

Fitzpatrick -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	8390	1	3	301A		Book Closet across from Classroom 300	Ceiling	Peeling paint and crack in ceiling	10	No			None	No	
2	8390	1	3	301B		Boy's Restroom next to Classroom 301	Ceiling	Severe peeling paint	200	No			None	No	
3	8390	1	3	300		Classroom 300	Ceiling	Peeling paint above ceiling in coat closet	10	No			None	No	
4	8390	1	3	300		Classroom 300	W1	Flaking paint	5	No			None	No	
5	8390	1	3	300		Classroom 300	W3	Peeling paint at columns	15	No			None	No	
6	8390	1	3	301		Classroom 301	Ceiling	Coat closet	10	No			None	No	
7	8390	1	3	301		Classroom 301	W1	Flaking paint	5	No			None	No	
8	8390	1	3	301		Classroom 301	W2	Peeling paint	5	No			None	No	
9	8390	1	3	301		Classroom 301	W3	Peeling paint along bottom course at columns	10	No			None	No	
10	8390	1	3	302		Classroom 302	Ceiling	Coat closet	15	No			None	No	
11	8390	1	3	302		Classroom 302	W1	Peeling paint on wall and columns	10	No			None	No	
12	8390	1	3	302		Classroom 302	W3	Peeling paint at columns	12	No			None	No	
13	8390	1	3	303		Classroom 303	Ceiling	Flaking paint along perimeter beams	70	No	No		None	No	
14	8390	1	3	303		Classroom 303	W1	Peeling paint at column and pipe, severe peeling paint on ductwork	30	No	No		None	No	
15	8390	1	3	303		Classroom 303	W3	Peeling paint at columns	6	No	No		None	No	
16	8390	1	3	304		Classroom 304	Ceiling	Severe peeling paint	200	No	No		None	No	
17	8390	1	3	304		Classroom 304	W1	peeling paint at column	5	No	No		None	No	
18	8390	1	3	304		Classroom 304	W3	Peeling paint at columns	12	No	No		None	No	
19	8390	1	3	305		Classroom 305	Ceiling	Peeling paint at some spots, and beam	15	No	No		None	No	
20	8390	1	3	305		Classroom 305	W1	Peeling paint at column	5	No	No		None	No	
21	8390	1	3	305		Classroom 305	W3	Peeling paint at columns	12	No	No		None	No	
22	8390	1	3	307		Classroom 307 (Special Education)	W1	Peeling paint	5	No	No		None	No	
23	8390	1	3	307		Classroom 307 (Special Education)	W3	Peeling paint at column	10	No	No		None	No	
24	8390	1	3	310		Classroom 310	Ceiling	Flaking paint - spreadout	20	No	No		None	No	
25	8390	1	3	310		Classroom 310	W1	Peeling paint on wall and pipe	20	No	No		None	No	
26	8390	1	3	310		Classroom 310	W3	Peeling paint at columns	15	No	No		None	No	
27	8390	1	3	310A		Classroom 310 Storage Room	Ceiling	No Access							Needs to be inspected
28	8390	1	3	310A		Classroom 310 Storage Room	Floor	No Access							Needs to be inspected
29	8390	1	3	310A		Classroom 310 Storage Room	W1	No Access							Needs to be inspected
30	8390	1	3	310A		Classroom 310 Storage Room	W2	No Access							Needs to be inspected
31	8390	1	3	310A		Classroom 310 Storage Room	W3	No Access							Needs to be inspected
32	8390	1	3	310A		Classroom 310 Storage Room	W4	No Access							Needs to be inspected
33	8390	1	3	312		Classroom 312	Ceiling	Peeling paint	200	No	No		None	No	

Fitzpatrick -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
34	8390	1	3	312		Classroom 312	W1	Peeling paint at column and pipe	8	No	No		None	No	
35	8390	1	3	312		Classroom 312	W3	Peeling paint at columns	25	No	No		None	No	
36	8390	1	3	314		Classroom 314	Ceiling	Peeling paint along perimeter beams	50	No	No		None	No	
37	8390	1	3	314		Classroom 314	W1	Peeling paint on wall and column	10	No	No		None	No	
38	8390	1	3	314		Classroom 314	W3	Peeling paint at columns	12	No	No		None	No	
39	8390	1	3	316		Classroom 316	Ceiling	Peeling paint at some spots	5	No	No		None	No	
40	8390	1	3	316		Classroom 316	W1	Peeling paint at columns	10	No	No		None	No	
41	8390	1	3	316		Classroom 316	W3	Peeling paint at columns	12	No	No		None	No	
42	8390	1	3	318		Classroom 318	Ceiling	Peeling paint along perimeter beam	20	No	No		None	No	
43	8390	1	3	318		Classroom 318	W1	Peeling paint on wall and columns	15	No	No		None	No	
44	8390	1	3	318		Classroom 318	W3	Peeling paint at columns	20	No	No		None	No	
45	8390	1	3	306		Computer Lab 306/308	Ceiling	Peeling paint on 306 side	15	No	No		None	No	
46	8390	1	3	306		Computer Lab 306/308	W1	Peeling paint at column by coat closet	6	No	No		None	No	
47	8390	1	3	306		Computer Lab 306/308	W3	Peeling paint at columns	20	No	No		None	No	
48	8390	1	3	303A		Girl's Restroom across from Classroom 312	Ceiling	Peeling paint	100	No	No		None	No	
49	8390	1	3	303A		Girl's Restroom across from Classroom 312	W1	Flaking paint	5	No	No		None	No	
50	8390	1	3	303A		Girl's Restroom across from Classroom 312	W2	Flaking paint	5	No	No		None	No	
51	8390	1	3	303A		Girl's Restroom across from Classroom 312	W3	Peeling paint at column	5	No	No		None	No	
52	8390	1	3	H31A		Hallway from Classroom 300 to Home and School Room 334	Ceiling	Peeling paint - spreadout	100	No	No		None	No	
53	8390	1	3	H31C		Hallway from Classrooms 310 to 318	Ceiling	Severe peeling paint	200	No	No		None	No	
54	8390	1	3	H31B		Hallway outside Computer Lab	Ceiling	Severe peeling paint - spreadout	300	No	No		None	No	
55	8390	1	3	H31B		Hallway outside Computer Lab	W1	Peeling paint	50	No	No		None	No	
56	8390	1	3	H31B		Hallway outside Computer Lab	W3	Peeling paint	50	No	No		None	No	
57	8390	1	3	304A		Home and School Room 334	Ceiling	No Access							Needs to be inspected
58	8390	1	3	304A		Home and School Room 334	Floor	No Access							Needs to be inspected
59	8390	1	3	304A		Home and School Room 334	W1	No Access							Needs to be inspected

Fitzpatrick -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
60	8390	1	3	304A		Home and School Room 334	W2	No Access							Needs to be inspected
61	8390	1	3	304A		Home and School Room 334	W3	No Access							Needs to be inspected
62	8390	1	3	304A		Home and School Room 334	W4	No Access							Needs to be inspected
63	8390	1	3	303D		Men's Restroom across from Classrooms 310	Ceiling	Flaking paint	10	No	No		None	No	
64	8390	1	3	303D		Men's Restroom across from Classrooms 310	W2	Flaking paint	20	No	No		None	No	
65	8390	1	3	303D		Men's Restroom across from Classrooms 310	W3	Flaking paint	20	No	No		None	No	
66	8390	1	3	S32		Stairwell across from Classroom 314	W2	Flaking paint	4	No	No		None	No	
67	8390	1	3	S32		Stairwell across from Classroom 314	W3	Flaking paint below radiator	10	No	No		None	No	
68	8390	1	3	S32		Stairwell across from Classroom 314	W4	Peeling paint on wall and column	5	No	No		None	No	
69	8390	1	3	S31		Stairwell near Classroom 300	W2	Peeling paint at column	5	No			None	No	
70	8390	1	3	S31		Stairwell near Classroom 300	W4	Peeling paint on horizontal beam	20	No			None	No	
71	8390	1	3	S33		Stairwell near Classrooms 307 and 318	Floor	Peeling paint on baseboard and stair risers	50	No	No		None	No	
72	8390	1	3	301C		Storage Room across from Classroom 304	Ceiling	Efflorescence, and debris on top of shelf	50	No	Shelf	20	None	No	
73	8390	1	3	301D		Storage Room across from Classroom 304 next to Elevator	Ceiling	No Access							Needs to be inspected
74	8390	1	3	301D		Storage Room across from Classroom 304 next to Elevator	Floor	No Access							Needs to be inspected
75	8390	1	3	301D		Storage Room across from Classroom 304 next to Elevator	W1	No Access							Needs to be inspected
76	8390	1	3	301D		Storage Room across from Classroom 304 next to Elevator	W2	No Access							Needs to be inspected
77	8390	1	3	301D		Storage Room across from Classroom 304 next to Elevator	W3	No Access							Needs to be inspected

Fitzpatrick -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
78	8390	1	3	301D		Storage Room across from Classroom 304 next to Elevator	W4	No Access							Needs to be inspected
79	8390	1	3	303CB		Teacher's Lounge Crawl Space on Right - Near Entrance	Ceiling	No Access							Needs to be inspected
80	8390	1	3	303CB		Teacher's Lounge Crawl Space on Right - Near Entrance	Floor	No Access							Needs to be inspected
81	8390	1	3	303CB		Teacher's Lounge Crawl Space on Right - Near Entrance	W1	No Access							Needs to be inspected
82	8390	1	3	303CB		Teacher's Lounge Crawl Space on Right - Near Entrance	W2	No Access							Needs to be inspected
83	8390	1	3	303CB		Teacher's Lounge Crawl Space on Right - Near Entrance	W3	No Access							Needs to be inspected
84	8390	1	3	303CB		Teacher's Lounge Crawl Space on Right - Near Entrance	W4	No Access							Needs to be inspected
85	8390	1	2	201B		Boy's Restroom next to Classroom 201	Ceiling	Peeling paint at some spots	3	No	No		None	No	
86	8390	1	2	200		Classroom 200	Ceiling	Peeling paint at perimeter beam	10	No	No		None	No	
87	8390	1	2	200		Classroom 200	W1	Peeling paint at column and pipe	10	No	No		None	No	
88	8390	1	2	200		Classroom 200	W3	Peeling paint at column and pipe	15	No	No		None	No	
89	8390	1	2	201		Classroom 201	W1	Peeling paint at columns	6	No	No		None	No	
90	8390	1	2	201		Classroom 201	W3	Peeling paint at column and pipe	15	No	No		None	No	
91	8390	1	2	202		Classroom 202	W1	Peeling paint at column and pipe	10	No	No		None	No	
92	8390	1	2	202		Classroom 202	W3	Peeling paint at column and pipes	15	No	No		None	No	
93	8390	1	2	203		Classroom 203	W1	Peeling paint at column, ductwork, and pipe	15	No			None	No	
94	8390	1	2	203		Classroom 203	W3	Peeling paint at columns and pipe	15	No			None	No	
95	8390	1	2	204		Classroom 204	W3	Peeling paint at middle column and pipe	4	No	No		None	No	
96	8390	1	2	205		Classroom 205	W3	Peeling paint at middle column	30	No			None	No	
97	8390	1	2	207		Classroom 207	W3	Peeling paint at columns and pipe	30	No			None	No	
98	8390	1	2	210		Classroom 210	Ceiling	Peeling paint along beam	30	No			None	No	

Fitzpatrick -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
99	8390	1	2	210		Classroom 210	W1	Peeling paint at column, pipe, and ductwork	15	No			None	No	
100	8390	1	2	210		Classroom 210	W3	Peeling paint at column and pipe	15	No			None	No	
101	8390	1	2	212		Classroom 212	W1	Peeling paint at column and pipe	8	No			None	No	
102	8390	1	2	212		Classroom 212	W3	Peeling paint at columns and pipes	10	No			None	No	
103	8390	1	2	214		Classroom 214	W1	Peeling paint at columns	5	No			None	No	
104	8390	1	2	214		Classroom 214	W3	Peeling paint at columns	15	No			None	No	
105	8390	1	2	216		Classroom 216	W1	Peeling paint at column	5	No			None	No	
106	8390	1	2	216		Classroom 216	W3	Peeling paint at columns and pipe	10	No			None	No	
107	8390	1	2	218		Classroom 218	W1	Peeling paint on fiberglass pipe insulation	4	No			None	No	
108	8390	1	2	218		Classroom 218	W3	Peeling paint at middle column	20	No			None	No	
109	8390	1	2	203A		Girl's Restroom across from Classroom 212	Ceiling	Peeling paint near the doorway	4	No			None	No	
110	8390	1	2	203A		Girl's Restroom across from Classroom 212	W3	Severe peeling paint at column	40	No			None	No	
111	8390	1	2	H21B		Hallway outside IMC 206/208	Ceiling	Flaking paint at light fixture	2	No			None	No	
112	8390	1	2	208		Library	W1	Peeling paint at columns	5	No			None	No	
113	8390	1	2	208		Library	W3	Peeling paint at columns	5	No			None	No	
114	8390	1	2	208A		Library Storage Room	Ceiling	Peeling paint	100	No			None	No	
115	8390	1	2	203D		Men's Restroom across from Classroom 210	W4	Peeling paint on pipe	10	No			None	No	
116	8390	1	2	201D		Room 204-A Speech Office	W4	Peeling paint on pipe	10	No			None	No	
117	8390	1	2	S21		Stairwell near Classroom 200	W1	Flaking paint	5	No	No		None	No	
118	8390	1	2	S21		Stairwell near Classroom 200	W2	Flaking paint	5	No	No		None	No	
119	8390	1	2	S21		Stairwell near Classroom 200	W3	Flaking paint	5	No	No		None	No	
120	8390	1	2	S21		Stairwell near Classroom 200	W4	Flaking paint	10	No	No		None	No	
121	8390	1	2	S23		Stairwell near Classrooms 207 and 218	W3	Peeling paint	5	No			None	No	
122	8390	1	2	S23		Stairwell near Classrooms 207 and 218	W4	Peeling paint at column	20	No			None	No	
123	8390	1	2	S22		Stairwell near Classrooms 212 and 214	W1	Peeling paint at door	2	No			None	No	
124	8390	1	2	S22		Stairwell near Classrooms 212 and 214	W3	Peeling paint on wall, radiator and pipe	4	No			None	No	

Fitzpatrick -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
125	8390	1	2	S22		Stairwell near Classrooms 212 and 214	W4	Peeling paint on wall and column	15	No			None	No	
126	8390	1	2	201C		Storage Room across from Classroom 204	Floor	Debris under window	3	No			None	No	
127	8390	1	2	203B		Women's Restroom across from Classroom 212	W1	Flaking paint above door	2	No			None	No	
128	8390	2	1	HA2		Annex Hallway from Classrooms 9 to 11	W2	Peeling paint on column at Classroom 12 entrance	10	No	No		None	No	
129	8390	2	1	HA2		Annex Hallway from Classrooms 9 to 11	W4	Peeling paint on column at Classroom 11 entrance	10	No	No		None	No	
130	8390	2	1	005G		Area 5 - Copy/Fax Area	W3	Chipping paint	1	No	No		None	No	
131	8390	2	1	005F		Area 5 - General Office Space between Storage and Copy Area	Ceiling	No Access							Needs to be inspected
132	8390	2	1	005F		Area 5 - General Office Space between Storage and Copy Area	Floor	No Access							Needs to be inspected
133	8390	2	1	005F		Area 5 - General Office Space between Storage and Copy Area	W1	No Access							Needs to be inspected
134	8390	2	1	005F		Area 5 - General Office Space between Storage and Copy Area	W2	No Access							Needs to be inspected
135	8390	2	1	005F		Area 5 - General Office Space between Storage and Copy Area	W3	No Access							Needs to be inspected
136	8390	2	1	005F		Area 5 - General Office Space between Storage and Copy Area	W4	No Access							Needs to be inspected
137	8390	2	1	005A		Area 5 - General Office Space in Center (Hallway Side)	W3	Chipping paint	1	No	No		None	No	
138	8390	2	1	5		Area 5 - General Office Space in Corner (Hallway Side)	Ceiling	No Access							Needs to be inspected
139	8390	2	1	5		Area 5 - General Office Space in Corner (Hallway Side)	Floor	No Access							Needs to be inspected

Fitzpatrick -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
140	8390	2	1	5		Area 5 - General Office Space in Corner (Hallway Side)	W1	No Access							Needs to be inspected
141	8390	2	1	5		Area 5 - General Office Space in Corner (Hallway Side)	W2	No Access							Needs to be inspected
142	8390	2	1	5		Area 5 - General Office Space in Corner (Hallway Side)	W3	No Access							Needs to be inspected
143	8390	2	1	5		Area 5 - General Office Space in Corner (Hallway Side)	W4	No Access							Needs to be inspected
144	8390	2	1	005H		Area 5 - General Office Space in Corner next to Copy Area	W4	Peeling paint	2	No	No		None	No	
145	8390	2	1	005I		Area 5 - Hallway	W1	Peeling paint	10	No	No		None	No	
146	8390	2	1	005I		Area 5 - Hallway	W3	Peeling paint	5	No	No		None	No	
147	8390	2	1	005D		Area 5 Restroom next to Storage	Ceiling	No Access							Needs to be inspected
148	8390	2	1	005D		Area 5 Restroom next to Storage	Floor	No Access							Needs to be inspected
149	8390	2	1	005D		Area 5 Restroom next to Storage	W1	No Access							Needs to be inspected
150	8390	2	1	005D		Area 5 Restroom next to Storage	W2	No Access							Needs to be inspected
151	8390	2	1	005D		Area 5 Restroom next to Storage	W3	No Access							Needs to be inspected
152	8390	2	1	005D		Area 5 Restroom next to Storage	W4	No Access							Needs to be inspected
153	8390	2	1	005E		Area 5 Storage	Ceiling	No Access							Needs to be inspected
154	8390	2	1	005E		Area 5 Storage	Floor	No Access							Needs to be inspected
155	8390	2	1	005E		Area 5 Storage	W1	No Access							Needs to be inspected
156	8390	2	1	005E		Area 5 Storage	W2	No Access							Needs to be inspected
157	8390	2	1	005E		Area 5 Storage	W3	No Access							Needs to be inspected
158	8390	2	1	005E		Area 5 Storage	W4	No Access							Needs to be inspected
159	8390	2	1	006A		Area 6 - Copy/Fax Area	W4	Chipping paint	1	No	No		None	No	
160	8390	2	1	006G		Area 6 - General Office Space in Corner (Hallway Side)	W3	Chipping paint to the right of door	1	No	No		None	No	
161	8390	2	1	006F		Area 6 - General Office Space next to Entrance	W3	Chipping paint	1	No	No		None	No	
162	8390	2	1	006I		Area 6 - Water heater room by entrance	W3	Peeling paint along the bottom of the wall	8	No	No		None	No	
163	8390	2	1	006C		Area 6 Storage with blue door	Floor	Peeling paint on metal floor hatch	4	No	No		None	No	

Fitzpatrick -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
164	8390	1	1	115		Auditorium	W1	Peeling paint on wall tiles	20	No	No		None	No	
165	8390	1	1	115		Auditorium	W4	Peeling paint near exit doors by stage	5	No	No		None	No	
166	8390	1	1	115 STAGE		Auditorium Stage	Ceiling	Peeling paint on ductwork	5	No	No		None	No	
167	8390	1	1	115 STAGE		Auditorium Stage	W1	Peeling paint on columns on either side	40	No	No		None	No	
168	8390	1	1	101A		Book Closet across from Classroom 109	Ceiling	No Access							Needs to be inspected
169	8390	1	1	101A		Book Closet across from Classroom 109	Floor	No Access							Needs to be inspected
170	8390	1	1	101A		Book Closet across from Classroom 109	W1	No Access							Needs to be inspected
171	8390	1	1	101A		Book Closet across from Classroom 109	W2	No Access							Needs to be inspected
172	8390	1	1	101A		Book Closet across from Classroom 109	W3	No Access							Needs to be inspected
173	8390	1	1	101A		Book Closet across from Classroom 109	W4	No Access							Needs to be inspected
174	8390	1	1	121		Boy's Restroom across from Classroom 106	Ceiling	Peeling paint at some spots and pipe	20	No	No		None	No	
175	8390	1	1	121		Boy's Restroom across from Classroom 106	Floor	Peeling paint	30	No	No		None	No	
176	8390	1	1	121		Boy's Restroom across from Classroom 106	W1	Flaking paint	5	No	No		None	No	
177	8390	1	1	121		Boy's Restroom across from Classroom 106	W3	Peeling paint at column	5	No	No		None	No	
178	8390	1	1	121		Boy's Restroom across from Classroom 106	W4	Flaking paint behind toilets	5	No	No		None	No	
179	8390	2	1	10		Classroom 10	W1	Peeling paint on wall and door	25	No	No		None	No	
180	8390	2	1	10		Classroom 10	W2	Peeling paint	5	No	No		None	No	
181	8390	2	1	10		Classroom 10	W3	Peeling paint on Univentilator	3	No	No		None	No	
182	8390	2	1	10		Classroom 10	W4	Peeling paint	10	No	No		None	No	
183	8390	2	1	010C		Classroom 10 Closet/Storage with blue door	Ceiling	No Access							Needs to be inspected
184	8390	2	1	010C		Classroom 10 Closet/Storage with blue door	Floor	No Access							Needs to be inspected
185	8390	2	1	010C		Classroom 10 Closet/Storage with blue door	W1	No Access							Needs to be inspected

Fitzpatrick -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
186	8390	2	1	010C		Classroom 10 Closet/Storage with blue door	W2	No Access							Needs to be inspected
187	8390	2	1	010C		Classroom 10 Closet/Storage with blue door	W3	No Access							Needs to be inspected
188	8390	2	1	010C		Classroom 10 Closet/Storage with blue door	W4	No Access							Needs to be inspected
189	8390	2	1	010A		Classroom 10 Restroom	W2	Peeling paint	2	No	No		None	No	
190	8390	2	1	010A		Classroom 10 Restroom	W4	Peeling paint	2	No	No		None	No	
191	8390	2	1	010B		Classroom 10 Storage/Computer Server Room	W2	Peeling paint	1	No	No		None	No	
192	8390	1	1	100		Classroom 100	Ceiling	Peeling paint at some spots and beam	23	No	No		None	No	
193	8390	1	1	100		Classroom 100	W3	Peeling paint at column and pipe	20	No	No		None	No	
194	8390	1	1	101		Classroom 101	W3	Peeling paint on column and pipes	15	No	No		None	No	
195	8390	1	1	102		Classroom 102	W1	Peeling paint at column	15	No	No		None	No	
196	8390	1	1	102		Classroom 102	W3	Peeling paint at column and pipe	15	No	No		None	No	
197	8390	1	1	102A		Classroom 102 Closet	Ceiling	No Access							Needs to be inspected
198	8390	1	1	102A		Classroom 102 Closet	Floor	No Access							Needs to be inspected
199	8390	1	1	102A		Classroom 102 Closet	W1	No Access							Needs to be inspected
200	8390	1	1	102A		Classroom 102 Closet	W2	No Access							Needs to be inspected
201	8390	1	1	102A		Classroom 102 Closet	W3	No Access							Needs to be inspected
202	8390	1	1	102A		Classroom 102 Closet	W4	No Access							Needs to be inspected
203	8390	1	1	103		Classroom 103	W1	Peeling paint on column, ductwork and pipe	35	No	No		None	No	
204	8390	1	1	103		Classroom 103	W3	Peeling paint at columns and pipes	50	No	No		None	No	
205	8390	1	1	104		Classroom 104	Ceiling	Flaking paint	10	No	No		None	No	
206	8390	1	1	104		Classroom 104	W1	Peeling paint on wall and ductwork	45	No	No		None	No	
207	8390	1	1	104		Classroom 104	W3	Peeling paint at columns and pipe	25	No	No		None	No	
208	8390	1	1	104A		Classroom 104 Storage	Ceiling	No Access							Needs to be inspected
209	8390	1	1	104A		Classroom 104 Storage	Floor	No Access							Needs to be inspected
210	8390	1	1	104A		Classroom 104 Storage	W1	No Access							Needs to be inspected
211	8390	1	1	104A		Classroom 104 Storage	W2	No Access							Needs to be inspected

Fitzpatrick -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
212	8390	1	1	104A		Classroom 104 Storage	W3	No Access							Needs to be inspected
213	8390	1	1	104A		Classroom 104 Storage	W4	No Access							Needs to be inspected
214	8390	1	1	105		Classroom 105	W1	Peeling paint at column and wall	12	No	No		None	No	
215	8390	1	1	105		Classroom 105	W3	Peeling paint at columns and pipes	60	No	No		None	No	
216	8390	1	1	106		Classroom 106	Ceiling	Peeling paint at couple of spots	2	No	No		None	No	
217	8390	1	1	106		Classroom 106	W1	Peeling paint on wall, pipe, and columns	20	No	No		None	No	
218	8390	1	1	106		Classroom 106	W3	Peeling paint at columns and pipe	20	No	No		None	No	
219	8390	1	1	107		Classroom 107	W3	Peeling paint at columns	40	No	No		None	No	
220	8390	1	1	108		Classroom 108	Ceiling	Peeling paint at some spots	6	No	No		None	No	
221	8390	1	1	108		Classroom 108	W1	Peeling paint on wall, column and pipe	20	No	No		None	No	
222	8390	1	1	108		Classroom 108	W3	Peeling paint at columns and pipe	30	No	No		None	No	
223	8390	1	1	109		Classroom 109	W3	Peeling paint on column and pipe	12	No	No		None	No	
224	8390	2	1	11A		Classroom 11	W2	Peeling paint	4	No	No		None	No	
225	8390	2	1	11A		Classroom 11	W3	Peeling paint on wall, control panel and Univentilator	10	No	No		None	No	
226	8390	2	1	11A		Classroom 11	W4	Peeling paint	1	No	No		None	No	
227	8390	2	1	011B		Classroom 11 Closet/Storage with blue door	Ceiling	No Access							Needs to be inspected
228	8390	2	1	011B		Classroom 11 Closet/Storage with blue door	Floor	No Access							Needs to be inspected
229	8390	2	1	011B		Classroom 11 Closet/Storage with blue door	W1	No Access							Needs to be inspected
230	8390	2	1	011B		Classroom 11 Closet/Storage with blue door	W2	No Access							Needs to be inspected
231	8390	2	1	011B		Classroom 11 Closet/Storage with blue door	W3	No Access							Needs to be inspected
232	8390	2	1	011B		Classroom 11 Closet/Storage with blue door	W4	No Access							Needs to be inspected
233	8390	2	1	011C		Classroom 11 Restroom	W2	Peeling paint behind toilets	4	No	No		None	No	
234	8390	2	1	011E		Classroom 11 Water heater room at entrance	W4	Peeling paint above heater	1	No	No		None	No	
235	8390	1	1	110		Classroom 110	W1	Peeling paint at column and pipe	10	No	No		None	No	
236	8390	1	1	110		Classroom 110	W3	Peeling paint at column and pipe	25	No	No		None	No	
237	8390	1	1	112		Classroom 112	W1	Peeling paint at column and pipe	10	No	No		None	No	

Fitzpatrick -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
238	8390	1	1	112		Classroom 112	W3	Peeling paint at columns and pipes	65	No	No		None	No	
239	8390	2	1	012A		Classroom 12A	W1	Peeling paint at restroom	3	No	No		None	No	
240	8390	2	1	012A		Classroom 12A	W2	Peeling paint -spreadout	10	No	No		None	No	
241	8390	2	1	012A		Classroom 12A	W3	Peeling paint -spreadout	3	No	No		None	No	
242	8390	2	1	9		Classroom 9	Ceiling	Cracking paint at beam	2	No	No		None	No	
243	8390	2	1	9		Classroom 9	W1	Peeling paint	1	No	No		None	No	
244	8390	2	1	9		Classroom 9	W3	Peeling paint on Univentilator	10	No	No		None	No	
245	8390	2	1	9		Classroom 9	W4	Peeling paint at left corner	2	No	No		None	No	
246	8390	2	1	009B		Classroom 9 Closet/Storage with blue door	Ceiling	Peeling paint	5	No	No		None	No	
247	8390	2	1	009B		Classroom 9 Closet/Storage with blue door	W1	Severe peeling paint, damaged drywall	10	No	No		None	No	
248	8390	2	1	009C		Classroom 9 Storage	Ceiling	No Access							Needs to be inspected
249	8390	2	1	009C		Classroom 9 Storage	Floor	No Access							Needs to be inspected
250	8390	2	1	009C		Classroom 9 Storage	W1	No Access							Needs to be inspected
251	8390	2	1	009C		Classroom 9 Storage	W2	No Access							Needs to be inspected
252	8390	2	1	009C		Classroom 9 Storage	W3	No Access							Needs to be inspected
253	8390	2	1	009C		Classroom 9 Storage	W4	No Access							Needs to be inspected
254	8390	1	1	101B		Closet across from Main Office next to Classroom 101	Ceiling	No Access							Needs to be inspected
255	8390	1	1	101B		Closet across from Main Office next to Classroom 101	Floor	No Access							Needs to be inspected
256	8390	1	1	101B		Closet across from Main Office next to Classroom 101	W1	No Access							Needs to be inspected
257	8390	1	1	101B		Closet across from Main Office next to Classroom 101	W2	No Access							Needs to be inspected
258	8390	1	1	101B		Closet across from Main Office next to Classroom 101	W3	No Access							Needs to be inspected
259	8390	1	1	101B		Closet across from Main Office next to Classroom 101	W4	No Access							Needs to be inspected
260	8390	1	1	101C		Girl's Restroom across from Main Office	Ceiling	Peeling paint at some spots	20	No	No		None	No	
261	8390	1	1	101C		Girl's Restroom across from Main Office	W3	Severe peeling paint at column	30	No	No		None	No	

Fitzpatrick -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
262	8390	1	1	H11E		Hallway along left side of Auditorium from across Main Office to Stage	Ceiling	Peeling paint along left side	5	No	No		None	No	
263	8390	1	1	H11D		Hallway along right side of Auditorium from across Classroom 104 to Stage	Ceiling	Peeling paint at drain pipe by stage	5	No	No		None	No	
264	8390	1	1	H11C		Hallway from Classroom 104 to Classroom 112	Ceiling	Peeling paint at divider - at Room 106	30	No	No		None	No	
265	8390	1	1	H11C		Hallway from Classroom 104 to Classroom 112	W2	Flaking paint on metal poster supports	20	No	No		None	No	
266	8390	1	1	H11C		Hallway from Classroom 104 to Classroom 112	W4	Flaking paint on metal poster supports	20	No	No		None	No	
267	8390	2	1	12		Lobby Entrance to Kitchen and Classroom 12A	W2	Peeling paint on drywall	1	No	No		None	No	
268	8390	2	1	12		Lobby Entrance to Kitchen and Classroom 12A	W3	Peeling paint at control panel	3	No	No		None	No	
269	8390	1	1	MEL		Main Entrance Lobby	W1	Peeling paint on doors	3	No	No		None	No	
270	8390	1	1	116		Nurse's Office	W2	Peeling paint on column and pipe	12	No	No		None	No	
271	8390	1	1	116B		Nurses' Office Closet	W2	Peeling paint at hook rack	1	No	No		None	No	
272	8390	2	1	008B		Parent Workshop Room Women's Restroom	W4	Peeling paint at soap dispenser	2	No	No		None	No	
273	8390	1	1	124		Principal's Office	W3	Peeling paint on pipe	1	No	No		None	No	
274	8390	1	1	117		Psychologist's Office 119	W2	Peeling paint on radiator cover	2	No	No		None	No	
275	8390	1	1	117		Psychologist's Office 119	W4	Peeling paint along bottom of the wall	10	No	No		None	No	
276	8390	1	1	S14		Stairwell from Hallway along left side of Auditorium near Stage to the Outdoors	W1	Peeling paint on door	5	No	No		None	No	
277	8390	1	1	S14		Stairwell from Hallway along left side of Auditorium near Stage to the Outdoors	W2	Peeling paint	20	No	No		None	No	
278	8390	1	1	S14		Stairwell from Hallway along left side of Auditorium near Stage to the Outdoors	W4	Peeling paint	50	No	No		None	No	

Fitzpatrick -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
279	8390	1	1	S11		Stairwell near Classroom 109	W2	Peeling paint on wall and column	30	No	No		None	No	
280	8390	1	1	S11		Stairwell near Classroom 109	W4	Peeling paint	5	No	No		None	No	
281	8390	1	1	S12		Stairwell near Classrooms 106 and 108	Ceiling	Peeling paint	50	No	No		None	No	
282	8390	1	1	S12		Stairwell near Classrooms 106 and 108	W1	Peeling paint on door	5	No	No		None	No	
283	8390	1	1	S12		Stairwell near Classrooms 106 and 108	W2	Flaking paint	10	No	No		None	No	
284	8390	1	1	S12		Stairwell near Classrooms 106 and 108	W4	Peeling paint on wall and column	30	No	No		None	No	
285	8390	1	1	S13		Stairwell near Classrooms 107 and 112	W1	Peeling paint at door	10	No	No		None	No	
286	8390	1	1	S13		Stairwell near Classrooms 107 and 112	W2	Flaking paint	5	No	No		None	No	
287	8390	1	1	S13		Stairwell near Classrooms 107 and 112	W3	Flaking paint	5	No	No		None	No	
288	8390	1	1	111		Storage and Mechanical Room in Hall for Auditorium	Floor	Needs repaint	50	No	No		None	No	
289	8390	1	1	100A		Storage Room adjacent to Main Entrance Lobby	Floor	Debris at pipe along left wall2	2	No	No		None	No	
290	8390	1	1	119		Women's Restroom near Classroom 106	Ceiling	Peeling paint at pipe penetration	2	No	No		None	No	
291	8390	1	0	018B		Boy's Restroom across from Kitchen	Ceiling	Peeling paint on ceiling and ductwork	30	No	No		None	No	
292	8390	1	0	018B		Boy's Restroom across from Kitchen	W1	Peeling paint at column	20	No	No		None	No	
293	8390	1	0	018B		Boy's Restroom across from Kitchen	W2	Peeling paint at toilets	20	No	No		None	No	
294	8390	1	0	018B		Boy's Restroom across from Kitchen	W3	Peeling paint at column	20	No	No		None	No	
295	8390	1	0	010B		Cafeteria	Ceiling	Peeling paint on ceiling and ductwork	100	No	No		None	No	
296	8390	1	0	010B		Cafeteria	W1	Peeling paint	5	No	No		None	No	
297	8390	1	0	010B		Cafeteria	W2	Peeling paint	5	No	No		None	No	
298	8390	1	0	010B		Cafeteria	W3	Peeling paint	5	No	No		None	No	
299	8390	1	0	010B		Cafeteria	W4	Peeling paint on wall and columns	65	No	No		None	No	

Fitzpatrick -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
300	8390	1	0	B-1		Classroom B1	W1	Peeling paint at columns	20	No	No		None	No	
301	8390	1	0	B-1		Classroom B1	W4	Peeling paint at columns	5	No	No		None	No	
302	8390	1	0	B-1A		Classroom B1 Closet/Storage	Ceiling	Peeling paint	10	No	No		None	No	
303	8390	1	0	B-1B		Classroom B1 Coatroom	W2	Peeling paint at the top, and pipe	5	No	No		None	No	
304	8390	1	0	005B		Classroom B1 Restroom	W2	Peeling paint on the back side of the pipe		No	No		None	No	
305	8390	1	0	005B		Classroom B1 Restroom	W3	Peeling paint behind pipe		No	No		None	No	
306	8390	1	0	005B		Classroom B1 Restroom	W4	peeling paint behind toilets		No	No		None	No	
307	8390	1	0	020B		Classroom B10 (Music Room)	W1	Peeling paint at column	50	No	No		None	No	
308	8390	1	0	020B		Classroom B10 (Music Room)	W2	Efflorescence	25	No	No		None	Yes	
309	8390	1	0	020B		Classroom B10 (Music Room)	W3	Peeling paint at column	20	No	No		None	No	
310	8390	1	0	B-2		Classroom B2	W1	Peeling paint at column & pipe	60	No	No		None	No	
311	8390	1	0	B-2		Classroom B2	W3	Peeling paint at column	50	No	No		None	No	
312	8390	1	0	B2B		Classroom B2 Closet/Storage	Ceiling	No Access							Inspection Required
313	8390	1	0	B2B		Classroom B2 Closet/Storage	Floor	No Access							Inspection Required
314	8390	1	0	B2B		Classroom B2 Closet/Storage	W1	No Access							Inspection Required
315	8390	1	0	B2B		Classroom B2 Closet/Storage	W2	No Access							Inspection Required
316	8390	1	0	B2B		Classroom B2 Closet/Storage	W3	No Access							Inspection Required
317	8390	1	0	B2B		Classroom B2 Closet/Storage	W4	No Access							Inspection Required
318	8390	1	0	B-4		Classroom B4	Ceiling	Flaking paint - spreadout	5	No	No		None	No	
319	8390	1	0	B-4		Classroom B4	W1	Peeling paint at column and pipe	30	No	No		None	No	
320	8390	1	0	B-4		Classroom B4	W3	Peeling paint at column	5	No	No		None	No	
321	8390	1	0	B-8		Classroom B8	W1	Peeling paint at door	5	No	No		None	No	
322	8390	1	0	B-8		Classroom B8	W3	Peeling paint at column	20	No	No		None	No	
323	8390	1	0	002C		Classrooms B2 and B4 Restroom	W4	Peeling paint on pipe	2	No	No		None	No	
324	8390	1	0	002C		Classrooms B2 and B4 Restroom	W2	Peeling paint behind toilets	8	No	No		None	No	
325	8390	1	0	022B		Girl's Restroom across from Classroom B10	Floor	Peeling paint at toilets	50	No	No		None	No	
326	8390	1	0	022B		Girl's Restroom across from Classroom B10	W2	Peeling paint behind toilets	25	No	No		None	No	
327	8390	1	0	022B		Girl's Restroom across from Classroom B10	W3	Peeling paint at column	20	No	No		None	No	
328	8390	1	0	022B		Girl's Restroom across from Classroom B10	W4	Peeling paint behind toilets	25	No	No		None	No	

Fitzpatrick -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
329	8390	1	0	023B		Gym	Ceiling	Peeling paint along perimeter and ductwork	35	No	No		None	No	
330	8390	1	0	023B		Gym	W2	Peeling paint at columns	20	No	No		None	No	
331	8390	1	0	023B		Gym	W4	Peeling paint at columns	10	No	No		None	No	
332	8390	1	0	024B		Gym Office	Ceiling	Peeling paint on ductwork	50	No	No		None	No	
333	8390	1	0	025B		Gym Storage Room adjacent to Gym Office	Ceiling	No Access							Needs to be inspected
334	8390	1	0	025B		Gym Storage Room adjacent to Gym Office	Floor	No Access							Needs to be inspected
335	8390	1	0	025B		Gym Storage Room adjacent to Gym Office	W1	No Access							Needs to be inspected
336	8390	1	0	025B		Gym Storage Room adjacent to Gym Office	W2	No Access							Needs to be inspected
337	8390	1	0	025B		Gym Storage Room adjacent to Gym Office	W3	No Access							Needs to be inspected
338	8390	1	0	025B		Gym Storage Room adjacent to Gym Office	W4	No Access							Needs to be inspected
339	8390	1	0	HGA		Hallway from Cafeteria to Classroom B2	Ceiling	Peeling paint at some spots	10	No	No		None	No	
340	8390	1	0	HGA		Hallway from Cafeteria to Classroom B2	W2	Peeling paint at cafeteria entrance	20	No	No		None	No	
341	8390	1	0	HGA		Hallway from Cafeteria to Classroom B2	W3	No Access							Needs to be inspected
342	8390	1	0	HGA		Hallway from Cafeteria to Classroom B2	W4	Peeling paint at cafeteria entrance	20	No	No		None	No	
343	8390	1	0	020B		Kindergarden Only Restroom across from Classroom B8	W3	peeling paint behind toilets	3	No	No		None	No	
344	8390	1	0	012B		Kitchen	W1	Peeling paint at column	2	No	No		None	No	
345	8390	1	0	012B		Kitchen	W3	Peeling paint at window frames	50	No	No		None	No	
346	8390	1	0	014C		Kitchen Storage Area/Formal Money Safe Room	Ceiling	No Access							Needs to be inspected
347	8390	1	0	014C		Kitchen Storage Area/Formal Money Safe Room	Floor	No Access							Needs to be inspected
348	8390	1	0	014C		Kitchen Storage Area/Formal Money Safe Room	W1	No Access							Needs to be inspected
349	8390	1	0	014C		Kitchen Storage Area/Formal Money Safe Room	W2	No Access							Needs to be inspected

Fitzpatrick -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
350	8390	1	0	014C		Kitchen Storage Area/Former Money Safe Room	W3	No Access							Needs to be inspected
351	8390	1	0	014C		Kitchen Storage Area/Former Money Safe Room	W4	No Access							Needs to be inspected
352	8390	1	0	007B		School Police Office	W2	Peeling paint at pipe	6	No	No		None	No	
353	8390	1	0	SG3		Stairwell from Gym to Schoolyard	W3	Peeling paint at right side column by exit door	20	No	No		None	No	
354	8390	1	0	SG1		Stairwell near Classroom B-2	Floor	Stair risers	20	No	No		None	No	
355	8390	1	0	SG1		Stairwell near Classroom B-2	W1	Flaking paint	5	No	No		None	No	
356	8390	1	0	SG1		Stairwell near Classroom B-2	W2	Flaking paint	10	No	No		None	No	
357	8390	1	0	SG1		Stairwell near Classroom B-2	W3	Flaking paint at column	20	No	No		None	No	
358	8390	1	0	SG1		Stairwell near Classroom B-2	W4	Flaking paint at door frame	8	No	No		None	No	
359	8390	1	0	SG2		Stairwell near Classroom B10 to Schoolyard	W3	Peeling paint door frame		No	No		None	No	
360	8390	1	0	014A		Storage Area in Cafeteria next to Food Service Restroom	Ceiling	No Access							Needs to be inspected
361	8390	1	0	014A		Storage Area in Cafeteria next to Food Service Restroom	Floor	No Access							Needs to be inspected
362	8390	1	0	014A		Storage Area in Cafeteria next to Food Service Restroom	W1	No Access							Needs to be inspected
363	8390	1	0	014A		Storage Area in Cafeteria next to Food Service Restroom	W2	No Access							Needs to be inspected
364	8390	1	0	014A		Storage Area in Cafeteria next to Food Service Restroom	W3	No Access							Needs to be inspected
365	8390	1	0	014A		Storage Area in Cafeteria next to Food Service Restroom	W4	No Access							Needs to be inspected
366	8390	1	0	007B2		Storage Room across from Classroom B6 (Telephone Mechanical Room)	W1	Flaking paint at front column and pipe	3	No	No		None	No	
367	8390	1	0	B-6		Storage Room B6	Ceiling	Peeling paint near left corner of wall 3	5	No	No		None	No	

Fitzpatrick -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
368	8390	1	0	B-6		Storage Room B6	W3	Peeling paint at columns and pipe	25	No	No		None	No	
369	8390	1	0	B-6A		Water Meter Room located in Storage Room B6	Floor	Debris at column	2	No	No		None	No	
370	8390	1	0	B-6A		Water Meter Room located in Storage Room B6	W3	Peeling paint at column	5	No	No		None	No	
371	8390	1	0	016B		Women's Restroom across from Kitchen	Floor	Peeling paint behind toilets	15	No	No		None	No	
372	8390	1	0	016B		Women's Restroom across from Kitchen	W2	Peeling paint	10	No	No		None	No	
373	8390	1	0	016B		Women's Restroom across from Kitchen	W3	Peeling paint	5	No	No		None	No	
374	8390	1	0	016B		Women's Restroom across from Kitchen	W4	Peeling paint at column	20	No	No		None	No	