

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	8260	1	2	208B		Boy's Restroom	W2	Flaking	2	No	No	N/A	N/A	No	
2	8260	1	2	208B		Boy's Restroom	W3	Chipping	1	No	No	N/A	N/A	No	
3	8260	1	2	208B		Boy's Restroom	W4	Flaking	17	No	No	N/A	N/A	No	
4	8260	1	2	201		Classroom 201	Floor	Chipping on cove base	32	No	No	N/A	N/A	No	Cove base is assumed asbestos
5	8260	1	2	201		Classroom 201	W1	Flaking on wall and sink	58	No	No	N/A	Posters	No	Limited inspection due to stored materials
6	8260	1	2	201		Classroom 201	W2	Flaking	15	No	No	N/A	Furniture, Stored Materials	No	Limited inspection due to stored materials
7	8260	1	2	201		Classroom 201	W3	Chipping on univent covers, Flaking	124	No	No	N/A	Furniture, Stored Materials	No	Limited inspection due to stored materials
8	8260	1	2	201		Classroom 201	W4	Flaking	49	No	No	N/A	Posters	No	Limited inspection due to stored materials
9	8260	1	2	201A		Classroom 201 Closet between Coat Area and Door	Ceiling	Flaking	3	No	No	N/A	N/A	No	
10	8260	1	2	201A		Classroom 201 Closet between Coat Area and Door	W3	Flaking	1	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
11	8260	1	2	201B		Classroom 201 Closet between Door and Side Wall	W2	Flaking	7	No	No	N/A	N/A	No	
12	8260	1	2	201B		Classroom 201 Closet between Door and Side Wall	W3	Chipping	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
13	8260	1	2	201B		Classroom 201 Closet between Door and Side Wall	W4	Hole	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
14	8260	1	2	202		Classroom 202	Floor	Chipping on cove base	38	No	No	N/A	N/A	No	Cove base is assumed asbestos
15	8260	1	2	202		Classroom 202	W1	Cracking, Chipping, Holes	26	No	No	N/A	Cabinets	No	Concrete block will need to be repaired
16	8260	1	2	202		Classroom 202	W2	Cracking, Chipping, Flaking	15	No	No	N/A	Furniture, Cabinets	No	Concrete block will need to be repaired
17	8260	1	2	202		Classroom 202	W3	Chipping on wall and univent covers, Flaking	61	No	No	N/A	Shelves, Cabinet	No	Limited inspection due to stored materials
18	8260	1	2	202		Classroom 202	W4	Chipping	16	No	No	N/A	N/A	No	
19	8260	1	2	202A		Classroom 202 Closet between Coat Area and Door	W3	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
20	8260	1	2	202A		Classroom 202 Closet between Coat Area and Door	W4	Cracking	14	No	No	N/A	N/A	No	Concrete block will need to be repaired
21	8260	1	2	202B		Classroom 202 Closet between Door and Side Wall	W2	Cracking, Chipping	14	No	No	N/A	N/A	No	Concrete block will need to be repaired
22	8260	1	2	202B		Classroom 202 Closet between Door and Side Wall	W3	Cracking	2	No	No	N/A	N/A	No	Concrete block will need to be repaired
23	8260	1	2	202B		Classroom 202 Closet between Door and Side Wall	W4	Cracking	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
24	8260	1	2	203		Classroom 203	Floor	Chipping on cove base	25	No	No	N/A	N/A	No	Cove base is assumed asbestos
25	8260	1	2	203		Classroom 203	W1	Chipping	25	No	No	N/A	N/A	No	
26	8260	1	2	203		Classroom 203	W2	Chipping, Flaking	3	No	No	N/A	N/A	No	

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
27	8260	1	2	203		Classroom 203	W3	Chipping, Flaking	48	No	No	N/A	N/A	No	
28	8260	1	2	203		Classroom 203	W4	Chipping, Flaking	29	No	No	N/A	N/A	No	
29	8260	1	2	203A		Classroom 203 Closet between Coat Area and Door	Ceiling	Flaking	2	No	No	N/A	N/A	No	
30	8260	1	2	203A		Classroom 203 Closet between Coat Area and Door	W1	Flaking	1	No	No	N/A	N/A	No	
31	8260	1	2	203A		Classroom 203 Closet between Coat Area and Door	W3	Flaking	2	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
32	8260	1	2	204		Classroom 204	Floor	Chipping on cove base	24	No	No	N/A	N/A	No	Cove base is assumed asbestos
33	8260	1	2	204		Classroom 204	W1	Cracking, Chipping, Flaking	14	No	No	N/A	Cabinet	No	Concrete block will need to be repaired
34	8260	1	2	204		Classroom 204	W2	Chipping	2	No	No	N/A	Furniture	No	Limited inspection due to stored materials
35	8260	1	2	204		Classroom 204	W3	Chipping on wall and univent cover	20	No	No	N/A	Shelf	No	
36	8260	1	2	204		Classroom 204	W4	Cracking, Chipping	20	No	No	N/A	N/A	No	Concrete block will need to be repaired
37	8260	1	2	204C		Classroom 204 Closet	Ceiling	Flaking	3	No	No	N/A	N/A	No	
38	8260	1	2	204C		Classroom 204 Closet	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
39	8260	1	2	204C		Classroom 204 Closet	W2	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
40	8260	1	2	204C		Classroom 204 Closet	W3	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
41	8260	1	2	204C		Classroom 204 Closet	W4	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
42	8260	1	2	205		Classroom 205	Floor	Chipping on cove base	25	No	No	N/A	N/A	No	Cove base is assumed asbestos
43	8260	1	2	205		Classroom 205	W1	Cracking, Chipping, Flaking	18	No	No	N/A	Posters, Shelves	No	Concrete block will need to be repaired
44	8260	1	2	205		Classroom 205	W2	Flaking	25	No	No	N/A	Cabinet, Furniture	No	Limited inspection due to stored materials
45	8260	1	2	205		Classroom 205	W3	Chipping on wall and univent covers, Flaking on metal pipe	42	No	No	N/A	Cabinet, Shelves	No	Limited inspection due to stored materials
46	8260	1	2	205		Classroom 205	W4	Chipping, Flaking	6	No	No	N/A	Shelves	No	Limited inspection due to stored materials
47	8260	1	2	205A		Classroom 205 Closet between Coat Area and Door	W3	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
48	8260	1	2	205A		Classroom 205 Closet between Coat Area and Door	W4	Cracking	5	No	No	N/A	N/A	No	Concrete block will need to be repaired
49	8260	1	2	205B		Classroom 205 Closet between Door and Side Wall	W2	Cracking, Chipping	5	No	No	N/A	N/A	No	Concrete block will need to be repaired
50	8260	1	2	206		Classroom 206	Floor	Chipping on cove base	9	No	No	N/A	N/A	No	Cove base is assumed asbestos
51	8260	1	2	206		Classroom 206	W1	Cracking, Chipping, Flaking on metal pipe	15	No	No	N/A	Posters	No	Concrete block will need to be repaired
52	8260	1	2	206		Classroom 206	W2	Cracking, Flaking	10	No	No	N/A	Posters	No	Concrete block will need to be repaired

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
53	8260	1	2	206		Classroom 206	W3	Chipping on wall and univent covers, Flaking	16	No	No	N/A	N/A	No	
54	8260	1	2	206		Classroom 206	W4	Flaking	3	No	No	N/A	Posters	No	
55	8260	1	2	206A		Classroom 206 Closet between Coat Area and Door	W3	Cracking	10	No	No	N/A	Shelves with stored materials	No	Concrete block will need to be repaired
56	8260	1	2	206A		Classroom 206 Closet between Coat Area and Door	W4	Cracking	12	No	No	N/A	N/A	No	Concrete block will need to be repaired
57	8260	1	2	206B		Classroom 206 Closet between Door and Side Wall	W3	Hole	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
58	8260	1	2	206B		Classroom 206 Closet between Door and Side Wall	W4	Hole	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
59	8260	1	2	207		Classroom 207	Ceiling	N/A	N/A	No	No	N/A	N/A	No	Cove base is assumed asbestos
60	8260	1	2	207		Classroom 207	Floor	Chipping on cove base	33	No	No	N/A	N/A	No	
61	8260	1	2	207		Classroom 207	W1	Cracking, Chipping, Flaking	55	No	No	N/A	Posters, Shelf	No	Concrete block will need to be repaired
62	8260	1	2	207		Classroom 207	W2	Chipping, Flaking	13	No	No	N/A	Furniture	No	Limited inspection due to stored materials
63	8260	1	2	207		Classroom 207	W3	Chipping, Flaking	23	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
64	8260	1	2	207		Classroom 207	W4	Chipping	10	No	No	N/A	Cabinet, Desk	No	Limited inspection due to stored materials
65	8260	1	2	207A		Classroom 207 Closet between Coat Area and Door	Ceiling	Flaking	5	No	No	N/A	N/A	No	
66	8260	1	2	207A		Classroom 207 Closet between Coat Area and Door	W3	Flaking	3	No	No	N/A	N/A	No	
67	8260	1	2	207A		Classroom 207 Closet between Coat Area and Door	W4	Flaking	1	No	No	N/A	N/A	No	
68	8260	1	2	207B		Classroom 207 Closet between Door and Side Wall	W2	Chipping, Holes	4	No	No	N/A	N/A	No	Concrete block will need to be repaired
69	8260	1	2	207B		Classroom 207 Closet between Door and Side Wall	W4	Cracking	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
70	8260	1	2	208		Classroom 208	Floor	Chipping on cove base	43	No	No	N/A	N/A	No	Cove base is assumed asbestos
71	8260	1	2	208		Classroom 208	W1	Cracking, Chipping, Flaking	17	No	No	N/A	Furniture, Posters	No	Concrete block will need to be repaired
72	8260	1	2	208		Classroom 208	W2	Chipping on wall and univent covers, Flaking	68	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
73	8260	1	2	208		Classroom 208	W3	Flaking	17	No	No	N/A	Cabinets	No	Limited inspection due to stored materials
74	8260	1	2	208		Classroom 208	W4	Cracking, Chipping, Flaking	22	No	No	N/A	Desks	No	Concrete block will need to be repaired
75	8260	1	2	208D		Classroom 208 Closet	W2	Cracking	8	No	No	N/A	N/A	No	Concrete block will need to be repaired
76	8260	1	2	208D		Classroom 208 Closet	W3	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
77	8260	1	2	204B		Closet adjacent Classroom 204	Ceiling	Flaking on duct support	3	No	No	N/A	N/A	No	

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
78	8260	1	2	204B		Closet adjacent Classroom 204	W2	Flaking	1	No	No	N/A	N/A	No	
79	8260	1	2	204B		Closet adjacent Classroom 204	W3	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
80	8260	1	2	208A		Copy Room next to Classroom 208	Ceiling	Flaking	9	No	No	N/A	N/A	No	
81	8260	1	2	208A		Copy Room next to Classroom 208	W2	Chipping	1	No	No	N/A	N/A	No	
82	8260	1	2	208A		Copy Room next to Classroom 208	W3	Chipping on radiator cover	2	No	No	N/A	N/A	No	
83	8260	1	2	208A		Copy Room next to Classroom 208	W4	Cracking, Holes	11	No	No	N/A	N/A	No	Concrete block will need to be repaired
84	8260	1	2	209		Girl's Restroom	Ceiling	Cracking	6	No	No	N/A	N/A	No	Concrete will need to be repaired
85	8260	1	2	209		Girl's Restroom	W2	Chipping on radiator cover	2	No	No	N/A	N/A	No	
86	8260	1	2	209		Girl's Restroom	W4	Cracking, hole	6	No	No	N/A	N/A	No	Concrete block will need to be repaired
87	8260	1	2	H201		Hallway between Classrooms 201 - 207	Floor	Chipping on cove base	21	No	No	N/A	N/A	No	Cove base is assumed asbestos
88	8260	1	2	H201		Hallway between Classrooms 201 - 207	W1	Cracking, Chipping on wall, electrical panel, and radiator covers, Flaking	41	No	No	N/A	N/A	No	Concrete block will need to be repaired
89	8260	1	2	H201		Hallway between Classrooms 201 - 207	W2	Cracking, Flaking	10	No	No	N/A	N/A	No	Concrete block will need to be repaired
90	8260	1	2	H201		Hallway between Classrooms 201 - 207	W3	Cracking, Chipping on wall and radiator covers, Flaking	56	No	No	N/A	N/A	No	Concrete block will need to be repaired
91	8260	1	2	204A		Staff Restroom	W1	Flaking	1	No	No	N/A	N/A	No	
92	8260	1	2	S201		Stairwell A adjacent to Classroom 207	Ceiling	Cracking, Flaking	15	No	No	N/A	N/A	No	Concrete will need to be repaired
93	8260	1	2	S201		Stairwell A adjacent to Classroom 207	Floor	Chipping on stairs and railings	92	No	No	N/A	N/A	No	
94	8260	1	2	S201		Stairwell A adjacent to Classroom 207	W1	Chipping on doors and doorframe, Flaking	23	No	No	N/A	N/A	No	
95	8260	1	2	S201		Stairwell A adjacent to Classroom 207	W2	Flaking	19	No	No	N/A	N/A	No	
96	8260	1	2	S201		Stairwell A adjacent to Classroom 207	W3	Chipping, Flaking	11	No	No	N/A	N/A	No	
97	8260	1	2	S201		Stairwell A adjacent to Classroom 207	W4	Cracking, Chipping, Flaking	35	No	No	N/A	N/A	No	Concrete block will need to be repaired
98	8260	1	2	S202		Stairwell C adjacent to Classroom 201	Ceiling	Flaking	5	No	No	N/A	N/A	No	
99	8260	1	2	S202		Stairwell C adjacent to Classroom 201	Floor	Chipping on stairs and railings	155	No	No	N/A	N/A	No	
100	8260	1	2	S202		Stairwell C adjacent to Classroom 201	W1	Chipping on doors and doorframe	30	No	No	N/A	N/A	No	
101	8260	1	2	S202		Stairwell C adjacent to Classroom 201	W3	Flaking	1	No	No	N/A	N/A	No	
102	8260	1	2	S202		Stairwell C adjacent to Classroom 201	W4	Flaking	1	No	No	N/A	N/A	No	
103	8260	1	2	S203		Stairwell to Classroom 208	Ceiling	Flaking	10	No	No	N/A	N/A	No	
104	8260	1	2	S203		Stairwell to Classroom 208	Floor	Chipping on floor and cove base	17	No	No	N/A	N/A	No	Cove base is assumed asbestos
105	8260	1	2	S203		Stairwell to Classroom 208	W1	Spalling, Flaking	3	Yes	No	N/A	N/A	No	

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
106	8260	1	2	S203		Stairwell to Classroom 208	W2	Chipping, Flaking	4	No	No	N/A	N/A	No	
107	8260	1	2	S203		Stairwell to Classroom 208	W3	Cracking, Flaking	6	No	No	N/A	N/A	No	Concrete block will need to be repaired
108	8260	1	2	S203		Stairwell to Classroom 208	W4	Cracking, Flaking	5	No	No	N/A	N/A	No	Concrete block will need to be repaired
109	8260	1	1	114		Auditorium	Ceiling	Efflorescence	19	Yes	No	N/A	N/A	Yes	Plaster is assumed asbestos
110	8260	1	1	114		Auditorium	W1	Chipping, Holes	17	No	No	N/A	N/A	Yes	
111	8260	1	1	114		Auditorium	W2	Chipping on wall and radiator covers	48	No	No	N/A	N/A	No	
112	8260	1	1	114		Auditorium	W3	Chipping, Holes	10	No	No	N/A	N/A	Yes	
113	8260	1	1	114		Auditorium	W4	Cracking, Chipping, Spalling, Efflorescence	27	Yes	No	N/A	N/A	Yes	
114	8260	1	1	114C		Auditorium Closet, Faculty Lounge Side	Ceiling	Cracking, Flaking	14	No	No	N/A	N/A	No	Concrete will need to be repaired
115	8260	1	1	114C		Auditorium Closet, Faculty Lounge Side	W3	Efflorescence	5	Yes	No	N/A	N/A	No	
116	8260	1	1	114B		Auditorium Closet, Main Office Side	W3	Hole	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
117	8260	1	1	114B		Auditorium Closet, Main Office Side	W4	Chipping on metal duct	20	No	No	N/A	N/A	No	
118	8260	1	1	114A		Auditorium Stage	Ceiling	Chipping, Holes, Significant Moisture Damage	6	Yes	No	N/A	N/A	No	Concrete will need to be repaired
119	8260	1	1	114A		Auditorium Stage	Floor	N/A	N/A	No	aint chips along wall	2	N/A	No	
120	8260	1	1	114A		Auditorium Stage	W1	Chipping, Holes	9	No	No	N/A	N/A	Yes	
121	8260	1	1	114A		Auditorium Stage	W2	Flaking on metal pipe and radiator cover	25	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
122	8260	1	1	114A		Auditorium Stage	W3	Chipping, Efflorescence	16	Yes	No	N/A	N/A	No	
123	8260	1	1	114A		Auditorium Stage	W4	Chipping on wall, door, and doorframe, Flaking, Efflorescence	47	Yes	No	N/A	N/A	No	
124	8260	1	1	112A		Boy's Restroom	W1	Flaking	7	No	No	N/A	N/A	No	
125	8260	1	1	112A		Boy's Restroom	W2	Flaking	23	No	No	N/A	N/A	No	
126	8260	1	1	112A		Boy's Restroom	W3	Flaking	3	No	No	N/A	N/A	No	
127	8260	1	1	112A		Boy's Restroom	W4	Flaking	28	No	No	N/A	N/A	No	
128	8260	1	1	101		Classroom 101	Floor	Chipping on cove base	22	No	No	N/A	N/A	No	Cove base is assumed asbestos
129	8260	1	1	101		Classroom 101	W1	Cracking, Chipping, Flaking	16	No	No	N/A	Posters	No	Concrete block will need to be repaired
130	8260	1	1	101		Classroom 101	W2	Chipping, Flaking	14	No	No	N/A	Posters, Cabinets, Stored Materials	No	Limited inspection due to stored materials
131	8260	1	1	101		Classroom 101	W3	Chipping on wall and univent cover, Flaking on wall and metal jackets	51	No	ips in corner of walls	1	Furniture	No	
132	8260	1	1	101		Classroom 101	W4	Chipping, Flaking	9	No	No	N/A	Furniture	No	Limited inspection due to stored materials
133	8260	1	1	102		Classroom 102	Floor	Chipping on cove base	18	No	No	N/A	N/A	No	Cove base is assumed asbestos
134	8260	1	1	102		Classroom 102	W1	Cracking, Chipping, Flaking, Efflorescence	31	Yes	No	N/A	N/A	No	Concrete block will need to be repaired
135	8260	1	1	102		Classroom 102	W2	Cracking	11	No	No	N/A	Posters, Shelves	No	Concrete block will need to be repaired
136	8260	1	1	102		Classroom 102	W3	Chipping on wall and univent covers, Flaking on wall and metal pipe	65	No	No	N/A	Cabinets, Stored Materials	No	Limited inspection due to stored materials
137	8260	1	1	102		Classroom 102	W4	Chipping, Flaking	14	No	No	N/A	Furniture	No	
138	8260	1	1	102C		Classroom 102 Closet with Sink	Ceiling	Chipping, Flaking	2	No	No	N/A	Cabinet, Stored Materials	No	Limited inspection due to stored materials

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
139	8260	1	1	102C		Classroom 102 Closet with Sink	Floor	Chipping on cove base	1	No	No	N/A	Cabinet, Stored Materials	No	Limited inspection due to stored materials. Cove base is assumed asbestos.
140	8260	1	1	102C		Classroom 102 Closet with Sink	W1	N/A	N/A	No	No	N/A	Cabinet, Stored Materials	No	Limited inspection due to stored materials
141	8260	1	1	102C		Classroom 102 Closet with Sink	W2	N/A	N/A	No	No	N/A	Cabinet, Stored Materials	No	Limited inspection due to stored materials
142	8260	1	1	102C		Classroom 102 Closet with Sink	W3	N/A	N/A	No	No	N/A	Cabinet, Stored Materials	No	Limited inspection due to stored materials
143	8260	1	1	102C		Classroom 102 Closet with Sink	W4	N/A	N/A	No	No	N/A	Cabinet, Stored Materials	No	Limited inspection due to stored materials
144	8260	1	1	103		Classroom 103	Floor	Chipping on cove base	32	No	No	N/A	N/A	No	Cove base is assumed asbestos
145	8260	1	1	103		Classroom 103	W1	Cracking, Chipping	14	No	No	N/A	N/A	No	Concrete block will need to be repaired
146	8260	1	1	103		Classroom 103	W2	Cracking, Chipping	5	No	No	N/A	N/A	No	Concrete block will need to be repaired
147	8260	1	1	103		Classroom 103	W3	Chipping on wall and univent covers, Flaking	26	No	No	N/A	N/A	No	
148	8260	1	1	103		Classroom 103	W4	Cracking, Chipping	6	No	No	N/A	N/A	No	Concrete block will need to be repaired
149	8260	1	1	103C		Classroom 103 Closet between Coat Area and Door	Ceiling	Flaking	5	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
150	8260	1	1	103C		Classroom 103 Closet between Coat Area and Door	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
151	8260	1	1	103C		Classroom 103 Closet between Coat Area and Door	W1	Chipping	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
152	8260	1	1	103C		Classroom 103 Closet between Coat Area and Door	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
153	8260	1	1	103C		Classroom 103 Closet between Coat Area and Door	W3	Flaking	5	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
154	8260	1	1	103C		Classroom 103 Closet between Coat Area and Door	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
155	8260	1	1	103D		Classroom 103 Closet between Door and Side Wall	Ceiling	Flaking	2	No	No	N/A	N/A	No	
156	8260	1	1	103D		Classroom 103 Closet between Door and Side Wall	W2	Chipping	1	No	No	N/A	N/A	No	
157	8260	1	1	103D		Classroom 103 Closet between Door and Side Wall	W3	Chipping	1	No	No	N/A	N/A	No	
158	8260	1	1	103A		Classroom 103 Girl's Restroom by Windows	W1	Chipping, Flaking	3	No	No	N/A	N/A	No	
159	8260	1	1	103A		Classroom 103 Girl's Restroom by Windows	W2	Chipping on radiator cover, Flaking	2	No	No	N/A	N/A	No	
160	8260	1	1	103B		Classroom 103 Restroom used as Closet (by door)	Ceiling	Flaking on metal duct	1	No	No	N/A	N/A	No	

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
161	8260	1	1	103B		Classroom 103 Restroom used as Closet (by door)	W1	Hole	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
162	8260	1	1	103B		Classroom 103 Restroom used as Closet (by door)	W3	Hole	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
163	8260	1	1	103B		Classroom 103 Restroom used as Closet (by door)	W4	Hole	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
164	8260	1	1	104		Classroom 104	Floor	Chipping on cove base	30	No	No	N/A	N/A	No	Cove base is assumed asbestos
165	8260	1	1	104		Classroom 104	W1	Cracking, Chipping	5	No	No	N/A	Posters	No	Concrete block will need to be repaired
166	8260	1	1	104		Classroom 104	W2	Chipping	2	No	No	N/A	Cabinets, Posters	No	Limited inspection due to stored materials
167	8260	1	1	104		Classroom 104	W3	Chipping on wall and univent covers	11	No	No	N/A	Cabinets, Posters	No	Limited inspection due to stored materials
168	8260	1	1	104		Classroom 104	W4	Chipping	1	No	No	N/A	Posters	No	
169	8260	1	1	104C		Classroom 104 Closet by Door	Ceiling	Chipping	1	No	No	N/A	N/A	No	
170	8260	1	1	104C		Classroom 104 Closet by Door	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
171	8260	1	1	104C		Classroom 104 Closet by Door	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
172	8260	1	1	104C		Classroom 104 Closet by Door	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
173	8260	1	1	104C		Classroom 104 Closet by Door	W4	Chipping	3	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
174	8260	1	1	104D		Classroom 104 Closet next to coat area	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
175	8260	1	1	104D		Classroom 104 Closet next to coat area	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
176	8260	1	1	104D		Classroom 104 Closet next to coat area	W3	Chipping	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
177	8260	1	1	104D		Classroom 104 Closet next to coat area	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
178	8260	1	1	105		Classroom 105	Floor	Chipping on cove base	15	No	No	N/A	N/A	No	Cove base is assumed asbestos
179	8260	1	1	105		Classroom 105	W1	Cracking, Chipping	5	No	No	N/A	N/A	No	Concrete block will need to be repaired
180	8260	1	1	105		Classroom 105	W2	Chipping	2	No	No	N/A	N/A	No	
181	8260	1	1	105		Classroom 105	W3	Chipping on metal jacket, Flaking	8	No	No	N/A	N/A	No	
182	8260	1	1	109		Classroom 109	Floor	Chipping on cove base	12	No	No	N/A	N/A	No	Cove base is assumed asbestos
183	8260	1	1	109		Classroom 109	W1	Cracking, Chipping, Flaking	48	No	No	N/A	Posters	No	Concrete block will need to be repaired
184	8260	1	1	109		Classroom 109	W2	Flaking	1	No	No	N/A	Stored Materials	No	
185	8260	1	1	109		Classroom 109	W3	Chipping, Flaking	12	No	No	N/A	Furniture, Stored Materials	No	Limited inspection due to stored materials
186	8260	1	1	109		Classroom 109	W4	Flaking	3	No	No	N/A	Cabinet, Stored Materials	No	

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
187	8260	1	1	109A		Classroom 109 Closet between Coat Area and Door	Ceiling	Flaking	4	No	No	N/A	N/A	No	
188	8260	1	1	109A		Classroom 109 Closet between Coat Area and Door	W1	Hole	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
189	8260	1	1	109A		Classroom 109 Closet between Coat Area and Door	W3	Hole, Flaking	2	No	No	N/A	N/A	No	Concrete block will need to be repaired
190	8260	1	1	109B		Classroom 109 Closet between Door and Side Wall	Ceiling	Flaking	1	No	No	N/A	N/A	No	
191	8260	1	1	109B		Classroom 109 Closet between Door and Side Wall	W2	Chipping	1	No	No	N/A	N/A	No	
192	8260	1	1	110		Classroom 110	Floor	Chipping on cove base	42	No	No	N/A	N/A	No	Cove base is assumed asbestos
193	8260	1	1	110		Classroom 110	W1	Cracking, Chipping, Hole, Flaking	18	No	No	N/A	Posters	No	Concrete block will need to be repaired
194	8260	1	1	110		Classroom 110	W2	Chipping	4	No	No	N/A	Posters	No	Limited inspection due to stored materials
195	8260	1	1	110		Classroom 110	W3	Chipping on wall and univent covers	25	No	No	N/A	Furniture, Stored Materials	No	Limited inspection due to stored materials
196	8260	1	1	110		Classroom 110	W4	Chipping, Flaking	6	No	No	N/A	Posters, Stored Materials	No	
197	8260	1	1	110A		Classroom 110 Closet between Coat Area and Door	Ceiling	Flaking	3	No	No	N/A	N/A	No	
198	8260	1	1	110A		Classroom 110 Closet between Coat Area and Door	W2	Flaking	2	No	No	N/A	N/A	No	
199	8260	1	1	110A		Classroom 110 Closet between Coat Area and Door	W3	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
200	8260	1	1	110A		Classroom 110 Closet between Coat Area and Door	W4	Cracking	5	No	No	N/A	N/A	No	Concrete block will need to be repaired
201	8260	1	1	110B		Classroom 110 Closet between Door and Side Wall	W1	Cracking	1	No	No	N/A	Stored Materials	No	Concrete block will need to be repaired
202	8260	1	1	110B		Classroom 110 Closet between Door and Side Wall	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
203	8260	1	1	110B		Classroom 110 Closet between Door and Side Wall	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
204	8260	1	1	110B		Classroom 110 Closet between Door and Side Wall	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
205	8260	1	1	111		Classroom 111	Floor	Chipping on cove base	50	No	No	N/A	N/A	No	
206	8260	1	1	111		Classroom 111	W1	Cracking, Chipping, Flaking	34	No	No	N/A	N/A	No	
207	8260	1	1	111		Classroom 111	W2	Chipping, Flaking	7	No	No	N/A	N/A	No	
208	8260	1	1	111		Classroom 111	W3	Chipping on univent covers, Flaking	58	No	ips between univent a	3	N/A	No	
209	8260	1	1	111		Classroom 111	W4	Chipping, Flaking	10	No	No	N/A	N/A	No	
210	8260	1	1	111A		Classroom 111 Closet between Coat Area and Door	W3	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
211	8260	1	1	111A		Classroom 111 Closet between Coat Area and Door	W4	Cracking, Chipping	6	No	No	N/A	N/A	No	Concrete block will need to be repaired
212	8260	1	1	111B		Classroom 111 Closet between Door and Side Wall	W2	Chipping	2	No	No	N/A	N/A	No	
213	8260	1	1	111B		Classroom 111 Closet between Door and Side Wall	W3	Chipping	2	No	No	N/A	N/A	No	
214	8260	1	1	112		Classroom 112	Ceiling	Chipping above missing ceiling tile	1	No	No	N/A	N/A	No	
215	8260	1	1	112		Classroom 112	Floor	Chipping on cove base	27	No	No	N/A	N/A	No	Cove base is assumed asbestos
216	8260	1	1	112		Classroom 112	W1	Cracking, Chipping, Flaking	23	No	No	N/A	Posters, Furniture	No	Concrete block will need to be repaired
217	8260	1	1	112		Classroom 112	W2	Cracking, Holes	7	No	No	N/A	Cabinets, Furniture	No	Concrete block will need to be repaired
218	8260	1	1	112		Classroom 112	W3	Chipping on univent covers and metal jackets, Flaking	71	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
219	8260	1	1	112		Classroom 112	W4	Chipping, Flaking	6	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
220	8260	1	1	112E		Classroom 112 Boy's Restroom	Ceiling	Flaking	1	No	No	N/A	N/A	No	
221	8260	1	1	112E		Classroom 112 Boy's Restroom	W3	Cracking	10	No	No	N/A	N/A	No	Concrete block will need to be repaired
222	8260	1	1	112B		Classroom 112 Closet between Coat Area and Door	W3	Hole	1	No	No	N/A	Shelves with stored materials	No	Concrete block will need to be repaired
223	8260	1	1	112D		Classroom 112 Girl's Restroom	Ceiling	Cracking	10	No	No	N/A	N/A	No	Concrete will need to be repaired
224	8260	1	1	112D		Classroom 112 Girl's Restroom	W4	Flaking	4	No	No	N/A	N/A	No	
225	8260	1	1	101A		Classrooms 101 & 102 Coat Room	Floor	Chipping on cove base	10	No	aint chips along wall	3	N/A	No	Cove base is assumed asbestos
226	8260	1	1	101A		Classrooms 101 & 102 Coat Room	W1	Cracking	5	No	No	N/A	N/A	No	Concrete block will need to be repaired
227	8260	1	1	101A		Classrooms 101 & 102 Coat Room	W2	Cracking, Chipping	6	No	No	N/A	N/A	No	Concrete block will need to be repaired
228	8260	1	1	101A		Classrooms 101 & 102 Coat Room	W3	Flaking	10	No	No	N/A	N/A	No	
229	8260	1	1	101A		Classrooms 101 & 102 Coat Room	W4	Chipping on radiator cover, Flaking	3	No	No	N/A	N/A	No	
230	8260	1	1	101B		Classrooms 101 & 102 Restroom	W1	Flaking	8	No	No	N/A	N/A	No	
231	8260	1	1	101B		Classrooms 101 & 102 Restroom	W2	Flaking	14	No	No	N/A	N/A	No	
232	8260	1	1	101B		Classrooms 101 & 102 Restroom	W3	Flaking	27	No	No	N/A	N/A	No	
233	8260	1	1	101B		Classrooms 101 & 102 Restroom	W4	Flaking	9	No	No	N/A	N/A	No	
234	8260	1	1	107B		CLI Office 107A	Floor	Chipping on cove base	10	No	No	N/A	N/A	No	Cove base is assumed asbestos
235	8260	1	1	107B		CLI Office 107A	W2	Chipping on wall and radiator cover	5	No	No	N/A	N/A	No	
236	8260	1	1	107B		CLI Office 107A	W3	Chipping on radiator cover	2	No	No	N/A	N/A	No	
237	8260	1	1	107D		CLI Office 107A Closet	Ceiling	Chipping	2	No	No	N/A	N/A	No	
238	8260	1	1	107D		CLI Office 107A Closet	W4	Chipping	1	No	No	N/A	N/A	No	

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
239	8260	1	1	107C		CLI Office 107A Restroom	Ceiling	Cracking	2	No	No	N/A	N/A	No	Concrete will need to be repaired
240	8260	1	1	105C		Counselor's Office	Floor	Chipping on cove base	21	No	No	N/A	N/A	No	Cove base is assumed asbestos
241	8260	1	1	105C		Counselor's Office	W1	Chipping, Flaking on radiator cover	15	No	No	N/A	Posters, Stored Materials	No	Limited inspection due to stored materials
242	8260	1	1	105C		Counselor's Office	W2	N/A	N/A	No	No	N/A	Posters	No	Limited inspection due to stored materials
243	8260	1	1	105C		Counselor's Office	W3	Efflorescence	7	Yes	No	N/A	Desk, Cabinet	No	
244	8260	1	1	105C		Counselor's Office	W4	Chipping on radiator cover	2	No	No	N/A	Cabinets	No	Limited inspection due to stored materials
245	8260	1	1	105E		Counselor's Office Closet	W1	Chipping	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
246	8260	1	1	105E		Counselor's Office Closet	W2	Chipping on metal pipe	7	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
247	8260	1	1	105E		Counselor's Office Closet	W3	Chipping	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
248	8260	1	1	105E		Counselor's Office Closet	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
249	8260	1	1	105B		Faculty Lounge	Ceiling	Flaking above missing ceiling tile	2	No	No	N/A	N/A	No	
250	8260	1	1	105B		Faculty Lounge	Floor	Chipping on cove base	14	No	No	N/A	N/A	No	Cove base is assumed asbestos
251	8260	1	1	105B		Faculty Lounge	W1	Chipping on conduit	2	No	No	N/A	N/A	No	
252	8260	1	1	105B		Faculty Lounge	W2	Chipping, Holes	6	No	No	N/A	N/A	No	Concrete block will need to be repaired
253	8260	1	1	105B		Faculty Lounge	W3	Chipping on wall and univent cover	5	No	No	N/A	N/A	No	
254	8260	1	1	105B		Faculty Lounge	W4	Chipping	4	No	No	N/A	N/A	No	
255	8260	1	1	105G		Faculty Lounge Closet adjacent Restroom	Ceiling	Cracking	1	No	No	N/A	N/A	No	Concrete will need to be repaired
256	8260	1	1	105G		Faculty Lounge Closet adjacent Restroom	W2	Chipping on pipe chase door	3	No	No	N/A	N/A	No	
257	8260	1	1	105G		Faculty Lounge Closet adjacent Restroom	W3	Cracking	4	No	No	N/A	N/A	No	Concrete block will need to be repaired
258	8260	1	1	105G		Faculty Lounge Closet adjacent Restroom	W4	Cracking	4	No	No	N/A	N/A	No	Concrete block will need to be repaired
259	8260	1	1	105H		Faculty Lounge Closet near Door	Ceiling	Cracking, Chipping, Flaking	6	No	No	N/A	N/A	No	Concrete will need to be repaired
260	8260	1	1	105H		Faculty Lounge Closet near Door	W1	Hole	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
261	8260	1	1	105H		Faculty Lounge Closet near Door	W3	Cracking	3	No	No	N/A	N/A	No	Concrete block will need to be repaired
262	8260	1	1	105F		Faculty Lounge Restroom	Ceiling	Cracking	5	No	No	N/A	N/A	No	Concrete will need to be repaired
263	8260	1	1	105F		Faculty Lounge Restroom	W2	Chipping on radiator cover	5	No	No	N/A	N/A	No	
264	8260	1	1	105F		Faculty Lounge Restroom	W3	Chipping on asbestos pipe insulation	2	No	No	N/A	N/A	No	
265	8260	1	1	108A		Girl's Restroom	Ceiling	Cracking, Flaking	6	No	No	N/A	N/A	No	Concrete will need to be repaired
266	8260	1	1	108A		Girl's Restroom	W1	Flaking	3	No	No	N/A	N/A	No	
267	8260	1	1	108A		Girl's Restroom	W2	Cracking	5	No	No	N/A	N/A	No	Concrete block will need to be repaired
268	8260	1	1	108A		Girl's Restroom	W4	Flaking	1	No	No	N/A	N/A	No	

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
269	8260	1	1	H102		Hallway adjacent to Auditorium leading to Stairwell B	Ceiling	Flaking	21	No	No	N/A	N/A	No	
270	8260	1	1	H102		Hallway adjacent to Auditorium leading to Stairwell B	Floor	Chipping on cove base	50	No	No	N/A	N/A	No	Cove base is assumed asbestos
271	8260	1	1	H102		Hallway adjacent to Auditorium leading to Stairwell B	W1	Chipping on doors and doorframe	25	No	No	N/A	N/A	No	
272	8260	1	1	H102		Hallway adjacent to Auditorium leading to Stairwell B	W2	Chipping, Flaking	52	No	No	N/A	N/A	No	
273	8260	1	1	H102		Hallway adjacent to Auditorium leading to Stairwell B	W4	Chipping on wall and radiator covers, Flaking on wall and metal pipe	71	No	No	N/A	N/A	No	
274	8260	1	1	H15		Hallway between Classrooms 102 - 104	Floor	Chipping on cove base	20	No	No	N/A	N/A	No	Cove base is assumed asbestos
275	8260	1	1	H15		Hallway between Classrooms 102 - 104	W1	Cracking, Chipping, Flaking	19	No	No	N/A	N/A	No	Concrete block will need to be repaired
276	8260	1	1	H15		Hallway between Classrooms 102 - 104	W3	Cracking, Chipping, Flaking	24	No	No	N/A	N/A	No	Concrete block will need to be repaired
277	8260	1	1	H17		Hallway between Classrooms 109 - 111	Ceiling	Chipping, Flaking	3	No	No	N/A	N/A	No	
278	8260	1	1	H17		Hallway between Classrooms 109 - 111	Floor	Chipping on cove base	24	No	No	N/A	N/A	No	
279	8260	1	1	H17		Hallway between Classrooms 109 - 111	W1	Chipping, Flaking	27	No	No	N/A	N/A	No	
280	8260	1	1	H17		Hallway between Classrooms 109 - 111	W2	Chipping on radiator cover, Flaking	4	No	No	N/A	N/A	No	
281	8260	1	1	H17		Hallway between Classrooms 109 - 111	W3	Cracking, Chipping, Flaking	19	No	No	N/A	N/A	No	Concrete block will need to be repaired
282	8260	1	1	H101		Hallway from Classroom 101 to Faculty Lounge	Floor	Chipping on cove base	21	No	No	N/A	N/A	No	Cove base is assumed asbestos
283	8260	1	1	H101		Hallway from Classroom 101 to Faculty Lounge	W1	Cracking, Chipping, Flaking	31	No	No	N/A	N/A	No	Concrete block will need to be repaired
284	8260	1	1	H101		Hallway from Classroom 101 to Faculty Lounge	W3	Cracking, Chipping, Flaking	86	No	No	N/A	N/A	No	Concrete block will need to be repaired
285	8260	1	1	H103		Hallway from Girl's Restroom to Main Office	W1	Cracking, Flaking	18	No	No	N/A	N/A	No	Concrete block will need to be repaired
286	8260	1	1	H103		Hallway from Girl's Restroom to Main Office	W3	Cracking, Chipping, Flaking	21	No	No	N/A	N/A	No	Concrete block will need to be repaired
287	8260	1	1	H103		Hallway from Girl's Restroom to Main Office	W4	Chipping	3	No	No	N/A	N/A	No	

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
288	8260	1	1	H105		Main Entrance Lobby	Ceiling	Efflorescence	5	Yes	No	N/A	N/A	No	Damage is on the assumed asbestos hard coat plaster adjacent to the asbestos textured plaster ceiling
289	8260	1	1	H105		Main Entrance Lobby	W1	Chipping	6	No	No	N/A	Posters	No	Limited inspection due to stored materials
290	8260	1	1	H105		Main Entrance Lobby	W2	Chipping, Flaking	7	No	No	N/A	Posters	No	Limited inspection due to stored materials
291	8260	1	1	H105		Main Entrance Lobby	W3	Chipping	1	No	No	N/A	Posters	No	Limited inspection due to stored materials
292	8260	1	1	H105		Main Entrance Lobby	W4	Cracking, Chipping	10	No	No	N/A	Posters	No	
293	8260	1	1	H104		Main Entrance Vestibule	Ceiling	Flaking	25	No	No	N/A	N/A	No	
294	8260	1	1	H104		Main Entrance Vestibule	W1	Chipping on doors and doorframe	50	No	No	N/A	N/A	No	
295	8260	1	1	H104		Main Entrance Vestibule	W2	Chipping on radiator cover	8	No	No	N/A	N/A	No	
296	8260	1	1	H104		Main Entrance Vestibule	W4	Chipping on radiator cover	7	No	No	N/A	N/A	No	
297	8260	1	1	106		Main Office	Floor	Chipping on cove base	5	No	No	N/A	N/A	No	Cove base is assumed asbestos
298	8260	1	1	106		Main Office	W2	Chipping on radiator cover	3	No	No	N/A	N/A	No	
299	8260	1	1	106		Main Office	W3	Chipping on radiator cover	3	No	No	N/A	N/A	No	
300	8260	1	1	106		Main Office	W4	Cracking, Chipping	4	No	No	N/A	N/A	No	Concrete block will need to be repaired
301	8260	1	1	106C		Main Office Closet	Ceiling	Flaking	10	No	No	N/A	N/A	No	
302	8260	1	1	106C		Main Office Closet	Floor	Chipping on cove base	1	No	No	N/A	N/A	No	Cove base is assumed asbestos
303	8260	1	1	106C		Main Office Closet	W2	Chipping	2	No	No	N/A	N/A	No	
304	8260	1	1	106C		Main Office Closet	W3	Flaking on wall and metal pipe	18	No	No	N/A	N/A	No	
305	8260	1	1	106C		Main Office Closet	W4	Chipping	1	No	No	N/A	N/A	No	
306	8260	1	1	107A		Nurse's Office	Floor	Chipping on cove base	25	No	No	N/A	N/A	No	Cove base is assumed asbestos
307	8260	1	1	107A		Nurse's Office	W1	N/A	N/A	No	No	N/A	Cabinets	No	Limited inspection due to stored materials
308	8260	1	1	107A		Nurse's Office	W2	Chipping	1	No	No	N/A	Posters	No	Limited inspection due to stored materials
309	8260	1	1	107A		Nurse's Office	W3	Chipping on radiator cover	2	No	No	N/A	Bed	No	Limited inspection due to stored materials
310	8260	1	1	107A		Nurse's Office	W4	Chipping on metal pipe and radiator cover	6	No	No	N/A	Posters, Refrigerator	No	Limited inspection due to stored materials
311	8260	1	1	106A		Principal's Office	W1	Cracking	7	No	No	N/A	N/A	No	Concrete block will need to be repaired
312	8260	1	1	106A		Principal's Office	W2	Chipping on radiator cover	3	No	No	N/A	N/A	No	
313	8260	1	1	106A		Principal's Office	W3	Chipping on radiator cover	4	No	No	N/A	N/A	No	
314	8260	1	1	106A		Principal's Office	W4	Chipping	3	No	No	N/A	N/A	No	
315	8260	1	1	106A2		Principal's Office Large Closet	Ceiling	Hole	1	No	No	N/A	N/A	No	Concrete will need to be repaired
316	8260	1	1	106A3		Principal's Office Restroom	W3	Chipping	1	No	No	N/A	N/A	No	
317	8260	1	1	107		Reading Intervention Office 107	Floor	Chipping on cove base	15	No	No	N/A	N/A	No	Cove base is assumed asbestos
318	8260	1	1	107		Reading Intervention Office 107	W1	Chipping	2	No	No	N/A	N/A	No	
319	8260	1	1	107		Reading Intervention Office 107	W2	Chipping, Holes	3	No	No	N/A	Shelves with stored materials	No	Concrete block will need to be repaired

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
320	8260	1	1	107		Reading Intervention Office 107	W3	Chipping on wall and radiator cover	2	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
321	8260	1	1	107		Reading Intervention Office 107	W4	Chipping on wall and radiator cover	6	No	No	N/A	Desk	No	Limited inspection due to stored materials
322	8260	1	1	105A		Reading Room 105A	W1	Cracking	4	No	No	N/A	Cabinet	No	Concrete block will need to be repaired
323	8260	1	1	105A		Reading Room 105A	W2	Chipping on metal jacket	3	No	No	N/A	Shelf, Cabinets	No	Limited inspection due to stored materials
324	8260	1	1	105A		Reading Room 105A	W3	Chipping on radiator cover	7	No	No	N/A	N/A	No	
325	8260	1	1	105A		Reading Room 105A	W4	Holes	11	No	No	N/A	N/A	No	Concrete block will need to be repaired
326	8260	1	1	116		School Police Office	Ceiling	Hole	1	No	No	N/A	N/A	No	Concrete will need to be repaired
327	8260	1	1	116		School Police Office	W3	Cracking	4	No	No	N/A	N/A	No	Concrete block will need to be repaired
328	8260	1	1	116		School Police Office	W4	Flaking	10	No	No	N/A	N/A	No	
329	8260	1	1	116A		School Police Office Restroom	Ceiling	Spalling	1	Yes	No	N/A	N/A	No	
330	8260	1	1	116A		School Police Office Restroom	W1	Flaking	17	No	No	N/A	N/A	No	
331	8260	1	1	116A		School Police Office Restroom	W2	Chipping on radiator cover, Flaking on wall and metal pipe	20	No	No	N/A	N/A	No	
332	8260	1	1	116A		School Police Office Restroom	W4	Flaking, Efflorescence	6	Yes	No	N/A	N/A	No	
333	8260	1	1	106B		Server Room adjacent Principal's Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
334	8260	1	1	106B		Server Room adjacent Principal's Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
335	8260	1	1	106B		Server Room adjacent Principal's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
336	8260	1	1	106B		Server Room adjacent Principal's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
337	8260	1	1	106B		Server Room adjacent Principal's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
338	8260	1	1	106B		Server Room adjacent Principal's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
339	8260	1	1	108		Special Education Liaison Office	W3	Chipping on radiator cover	4	No	No	N/A	Cabinets	No	Limited inspection due to stored materials
340	8260	1	1	108		Special Education Liaison Office	W4	Cracking	7	No	No	N/A	Shelves, Cabinets	No	Concrete block will need to be repaired
341	8260	1	1	108D		Special Education Liaison Office Waiting Area	W1	Hole	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
342	8260	1	1	117		Stage Music Room	Ceiling	Flaking, Significant Moisture Damage	11	Yes	No	N/A	N/A	No	Concrete will need to be repaired
343	8260	1	1	117		Stage Music Room	Floor	Debris	N/A	No	Debris around pipe	1	N/A	No	
344	8260	1	1	117		Stage Music Room	W1	Chipping on wood cove base	2	No	No	N/A	N/A	No	
345	8260	1	1	117		Stage Music Room	W2	Flaking on metal pipe	4	No	No	N/A	Cabinet	No	Limited inspection due to stored materials
346	8260	1	1	117		Stage Music Room	W3	Cracking, Chipping on wood cove base and radiator cover	13	No	No	N/A	Cabinet, Piano	No	Concrete block will need to be repaired
347	8260	1	1	115		Stage Restroom	Ceiling	Flaking	9	No	No	N/A	N/A	No	

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
348	8260	1	1	115		Stage Restroom	W1	Flaking	10	No	No	N/A	N/A	No	
349	8260	1	1	115		Stage Restroom	W2	Flaking	22	No	No	N/A	N/A	No	
350	8260	1	1	115		Stage Restroom	W3	Chipping on radiator cover, Flaking on wall and metal pipe	13	No	No	N/A	N/A	No	
351	8260	1	1	115		Stage Restroom	W4	Chipping	1	No	No	N/A	N/A	No	
352	8260	1	1	118		Stage Speech Room	Ceiling	Cracking	2	No	No	N/A	N/A	No	Concrete will need to be repaired
353	8260	1	1	118		Stage Speech Room	W1	N/A	N/A	No	No	N/A	Cabinet, Stored Materials	No	Limited inspection due to stored materials
354	8260	1	1	118		Stage Speech Room	W2	Chipping on wood cove base, Flaking	2	No	No	N/A	Shelf, Stored Materials	No	Limited inspection due to stored materials
355	8260	1	1	118		Stage Speech Room	W3	Chipping on radiator cover	5	No	No	N/A	Desk, Stored Materials	No	Limited inspection due to stored materials
356	8260	1	1	118		Stage Speech Room	W4	N/A	N/A	No	No	N/A	Cabinet, Desk	No	Limited inspection due to stored materials
357	8260	1	1	S12		Stairwell A adjacent to Classroom 112	Ceiling	Flaking	11	No	No	N/A	N/A	No	
358	8260	1	1	S12		Stairwell A adjacent to Classroom 112	Floor	Chipping on stairs and railings	125	No	No	N/A	N/A	No	
359	8260	1	1	S12		Stairwell A adjacent to Classroom 112	W1	Chipping on doors and doorframe, Flaking	24	No	No	N/A	N/A	No	
360	8260	1	1	S12		Stairwell A adjacent to Classroom 112	W2	Chipping, Flaking	3	No	No	N/A	N/A	No	
361	8260	1	1	S12		Stairwell A adjacent to Classroom 112	W4	Cracking, Chipping	25	No	No	N/A	N/A	No	Concrete block will need to be repaired
362	8260	1	1	S104		Stairwell B	Ceiling	Chipping, Flaking	4	No	No	N/A	N/A	No	
363	8260	1	1	S104		Stairwell B	Floor	Chipping on stairs, cove base, and railings	47	No	No	N/A	N/A	No	Cove base is assumed asbestos
364	8260	1	1	S104		Stairwell B	W1	Chipping on doors and doorframe	39	No	No	N/A	N/A	No	
365	8260	1	1	S104		Stairwell B	W2	Flaking	37	No	No	N/A	N/A	No	
366	8260	1	1	S104		Stairwell B	W3	Flaking	4	No	No	N/A	N/A	No	
367	8260	1	1	S104		Stairwell B	W4	Flaking on wall and metal pipe	46	No	No	N/A	N/A	No	
368	8260	1	1	S102		Stairwell C adjacent Classroom 101	Ceiling	Flaking	3	No	No	N/A	N/A	No	
369	8260	1	1	S102		Stairwell C adjacent Classroom 101	Floor	Chipping on stairs and railings	105	No	No	N/A	N/A	No	
370	8260	1	1	S102		Stairwell C adjacent Classroom 101	W1	Chipping on doors and doorframe	25	No	No	N/A	N/A	No	
371	8260	1	1	S102		Stairwell C adjacent Classroom 101	W2	Chipping on doors and doorframe, Flaking	29	No	No	N/A	N/A	No	
372	8260	1	1	S102		Stairwell C adjacent Classroom 101	W4	Cracking, Flaking	12	No	No	N/A	N/A	No	Concrete block will need to be repaired
373	8260	1	1	S107		Stairwell D adjacent Classroom 103	Ceiling	Flaking	9	No	No	N/A	N/A	No	
374	8260	1	1	S107		Stairwell D adjacent Classroom 103	Floor	Chipping	26	No	No	N/A	N/A	No	
375	8260	1	1	S107		Stairwell D adjacent Classroom 103	W1	Chipping on doors and doorframe	36	No	No	N/A	N/A	No	
376	8260	1	1	S107		Stairwell D adjacent Classroom 103	W2	Cracking, Chipping on wall and radiator cover, Flaking	22	No	No	N/A	N/A	No	Concrete block will need to be repaired
377	8260	1	1	S107		Stairwell D adjacent Classroom 103	W3	Chipping on doors and doorframe	18	No	No	N/A	N/A	No	
378	8260	1	1	S107		Stairwell D adjacent Classroom 103	W4	Chipping on door and doorframe	20	No	No	N/A	N/A	No	
379	8260	1	1	S107A		Stairwell D Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
380	8260	1	1	S107A		Stairwell D Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
381	8260	1	1	S107A		Stairwell D Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
382	8260	1	1	S107A		Stairwell D Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
383	8260	1	1	S107A		Stairwell D Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
384	8260	1	1	S107A		Stairwell D Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
385	8260	1	1	105J		Storage Closet adjacent Classroom 105	W1	Cracking	2	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials. Concrete block will need to be repaired
386	8260	1	1	105J		Storage Closet adjacent Classroom 105	W2	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
387	8260	1	1	105J		Storage Closet adjacent Classroom 105	W3	Holes	5	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials. Concrete block will need to be repaired
388	8260	1	1	105J		Storage Closet adjacent Classroom 105	W4	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
389	8260	1	1	108B		Storage Closet adjacent Classroom 109	Ceiling	Flaking	2	No	No	N/A	N/A	No	
390	8260	1	1	108B		Storage Closet adjacent Classroom 109	W1	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
391	8260	1	1	108B		Storage Closet adjacent Classroom 109	W2	N/A	N/A	No	No	N/A	Cabinet, Shelves with stored materials	No	Limited inspection due to stored materials
392	8260	1	1	108B		Storage Closet adjacent Classroom 109	W3	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
393	8260	1	1	108B		Storage Closet adjacent Classroom 109	W4	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
394	8260	1	1	111C		Storage Closet adjacent Classroom 111	Ceiling	Flaking	13	No	No	N/A	N/A	No	
395	8260	1	1	111C		Storage Closet adjacent Classroom 111	W1	Cracking	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
396	8260	1	1	111C		Storage Closet adjacent Classroom 111	W2	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
397	8260	1	1	111C		Storage Closet adjacent Classroom 111	W3	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
398	8260	1	1	111C		Storage Closet adjacent Classroom 111	W4	Chipping	1	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
399	8260	2	0	001B		Agriculture Classroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
400	8260	2	0	001B		Agriculture Classroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
401	8260	2	0	001B		Agriculture Classroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
402	8260	2	0	001B		Agriculture Classroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
403	8260	2	0	001B		Agriculture Classroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
404	8260	2	0	001B		Agriculture Classroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
405	8260	2	0	P03		Agriculture Classroom Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
406	8260	2	0	P03		Agriculture Classroom Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
407	8260	2	0	P03		Agriculture Classroom Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
408	8260	2	0	P03		Agriculture Classroom Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
409	8260	2	0	P03		Agriculture Classroom Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
410	8260	2	0	P03		Agriculture Classroom Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
411	8260	2	0	P02		Agriculture Classroom Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
412	8260	2	0	P02		Agriculture Classroom Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
413	8260	2	0	P02		Agriculture Classroom Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
414	8260	2	0	P02		Agriculture Classroom Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
415	8260	2	0	P02		Agriculture Classroom Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
416	8260	2	0	P02		Agriculture Classroom Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
417	8260	1	0	H02		A-Wing Hallway	Ceiling	Chipping on ceiling and metal pipe	27	No	No	N/A	N/A	No	
418	8260	1	0	H02		A-Wing Hallway	Floor	Debris	N/A	No	Debris near door	1	N/A	No	
419	8260	1	0	H02		A-Wing Hallway	W1	Chipping on wall, doors, doorframes, univent, and wood cove base	56	No	No	N/A	N/A	No	
420	8260	1	0	H02		A-Wing Hallway	W2	Chipping, Efflorescence	6	Yes	No	N/A	N/A	No	
421	8260	1	0	H02		A-Wing Hallway	W3	Cracking, Chipping on doors and doorframe	7	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos
422	8260	1	0	H02		A-Wing Hallway	W4	Chipping on wall, wood cove base, and univent	13	No	No	N/A	N/A	No	
423	8260	1	0	16		Boy's Restroom	Ceiling	Flaking	15	No	No	N/A	N/A	No	
424	8260	1	0	16		Boy's Restroom	W1	Chipping on radiator cover, Flaking	12	No	No	N/A	N/A	No	
425	8260	1	0	16		Boy's Restroom	W3	Cracking, Flaking on metal pipe	6	No	No	N/A	N/A	No	Concrete block will need to be repaired
426	8260	1	0	023 F		C1 Special Education Boy's Restroom	Floor	Chipping	15	No	No	N/A	N/A	No	
427	8260	1	0	023 F		C1 Special Education Boy's Restroom	W2	Chipping	1	No	No	N/A	N/A	No	
428	8260	1	0	023 F		C1 Special Education Boy's Restroom	W3	Efflorescence	5	Yes	No	N/A	N/A	Yes	

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
429	8260	1	0	023E		C1 Special Education Center Storage Room	Floor	Chipping on stairs	5	No	No	N/A	N/A	No	
430	8260	1	0	023E		C1 Special Education Center Storage Room	W1	Chipping on wall and doorframe	3	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos
431	8260	1	0	023E		C1 Special Education Center Storage Room	W2	Chipping	3	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos
432	8260	1	0	023E		C1 Special Education Center Storage Room	W3	Chipping, Flaking	3	No	No	N/A	N/A	No	
433	8260	1	0	023E		C1 Special Education Center Storage Room	W4	Flaking on wall and asbestos pipe insulation	1	No	No	N/A	N/A	No	
434	8260	1	0	2.30E+02		C1 Special Education Center Storage Room Emergency Medical Supplies	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
435	8260	1	0	2.30E+02		C1 Special Education Center Storage Room Emergency Medical Supplies	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
436	8260	1	0	2.30E+02		C1 Special Education Center Storage Room Emergency Medical Supplies	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
437	8260	1	0	2.30E+02		C1 Special Education Center Storage Room Emergency Medical Supplies	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
438	8260	1	0	2.30E+02		C1 Special Education Center Storage Room Emergency Medical Supplies	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
439	8260	1	0	2.30E+02		C1 Special Education Center Storage Room Emergency Medical Supplies	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
440	8260	1	0	26		C1 Special Education Classroom	Ceiling	Flaking on metal pipe	10	No	No	N/A	N/A	No	
441	8260	1	0	26		C1 Special Education Classroom	Floor	Chipping on metal grates	45	No	No	N/A	N/A	No	
442	8260	1	0	26		C1 Special Education Classroom	W1	Chipping, Hole, Flaking	13	No	No	N/A	N/A	No	Concrete block will need to be repaired
443	8260	1	0	26		C1 Special Education Classroom	W2	Chipping on doorframe and wood cove base	5	No	No	N/A	N/A	No	
444	8260	1	0	26		C1 Special Education Classroom	W3	Chipping, Flaking, Efflorescence	35	Yes	No	N/A	N/A	Yes	

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
445	8260	1	0	026A		C1 Special Education Classroom Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
446	8260	1	0	026A		C1 Special Education Classroom Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
447	8260	1	0	026A		C1 Special Education Classroom Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
448	8260	1	0	026A		C1 Special Education Classroom Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
449	8260	1	0	026A		C1 Special Education Classroom Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
450	8260	1	0	026A		C1 Special Education Classroom Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
451	8260	1	0	023A		C1 Special Education Girl's Restroom	Ceiling	Cracking, Flaking	12	No	No	N/A	N/A	No	Concrete will need to be repaired
452	8260	1	0	023A		C1 Special Education Girl's Restroom	Floor	Chipping	18	No	No	N/A	N/A	No	
453	8260	1	0	023A		C1 Special Education Girl's Restroom	W1	Flaking on asbestos pipe insulation	3	No	No	N/A	N/A	No	
454	8260	1	0	023A		C1 Special Education Girl's Restroom	W2	Flaking	1	No	No	N/A	N/A	No	
455	8260	1	0	023A		C1 Special Education Girl's Restroom	W3	Chipping on radiator cover, Efflorescence	9	Yes	No	N/A	N/A	Yes	
456	8260	1	0	023D		C1 Special Education Left Storage Room	Ceiling	Spalling	1	Yes	No	N/A	N/A	No	
457	8260	1	0	023D		C1 Special Education Left Storage Room	W1	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
458	8260	1	0	023D		C1 Special Education Left Storage Room	W2	Chipping	1	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
459	8260	1	0	023D		C1 Special Education Left Storage Room	W3	Chipping, Efflorescence	3	Yes	No	N/A	Shelves with stored materials	Yes	Limited inspection due to stored materials
460	8260	1	0	023D		C1 Special Education Left Storage Room	W4	Chipping	1	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
461	8260	1	0	023D1		C1 Special Education Left Storage Room Emergency Medical Supplies	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
462	8260	1	0	023D1		C1 Special Education Left Storage Room Emergency Medical Supplies	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
463	8260	1	0	023D1		C1 Special Education Left Storage Room Emergency Medical Supplies	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
464	8260	1	0	023D1		C1 Special Education Left Storage Room Emergency Medical Supplies	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
465	8260	1	0	023D1		C1 Special Education Left Storage Room Emergency Medical Supplies	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
466	8260	1	0	023D1		C1 Special Education Left Storage Room Emergency Medical Supplies	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
467	8260	1	0	23		C1 Special Education Physical Therapy Area	Floor	Chipping on metal grates	42	No	No	N/A	N/A	No	
468	8260	1	0	23		C1 Special Education Physical Therapy Area	W1	Chipping, Flaking	25	No	No	N/A	N/A	No	
469	8260	1	0	23		C1 Special Education Physical Therapy Area	W2	Chipping on wall and doorframe	5	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos
470	8260	1	0	23		C1 Special Education Physical Therapy Area	W3	Chipping, Hole, Flaking	5	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos
471	8260	1	0	23		C1 Special Education Physical Therapy Area	W4	Chipping	1	No	No	N/A	N/A	No	
472	8260	1	0	15		Cafeteria	Ceiling	Flaking	4	No	No	N/A	N/A	No	
473	8260	1	0	15		Cafeteria	Floor	Chipping on cove base	32	No	No	N/A	N/A	No	Cove base is assumed asbestos
474	8260	1	0	15		Cafeteria	W1	Flaking	4	No	No	N/A	N/A	No	
475	8260	1	0	15		Cafeteria	W2	Chipping	6	No	No	N/A	N/A	No	
476	8260	1	0	15		Cafeteria	W3	Chipping on wall, plastic jackets, metal pipe, and univent covers, Flaking on wall and metal pipe	71	No	No	N/A	N/A	No	
477	8260	1	0	15		Cafeteria	W4	Chipping on plastic jackets, univent covers, metal pipe, doors, and doorframe, Flaking	88	No	No	N/A	N/A	No	
478	8260	1	0	A1		Classroom A1	Ceiling	Flaking	11	No	No	N/A	N/A	No	
479	8260	1	0	A1		Classroom A1	W1	Chipping on wall, door, doorframe, and wood cove base	28	No	No	N/A	Furniture	No	Sheetrock is confirmed asbestos
480	8260	1	0	A1		Classroom A1	W2	Chipping on wall and wood cove base	9	No	No	N/A	Furniture	No	Sheetrock is confirmed asbestos
481	8260	1	0	A1		Classroom A1	W3	Cracking, Chipping on metal jacket, univent, windows, windowframes, radiator covers, and wood cove base	61	No	No	N/A	Furniture	No	Sheetrock is confirmed asbestos
482	8260	1	0	A1		Classroom A1	W4	N/A	N/A	No	No	N/A	Furniture	No	Limited inspection due to stored materials
483	8260	1	0	A1A		Classroom A1 Closet	Ceiling	Flaking	11	No	No	N/A	N/A	No	

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
484	8260	1	0	A1A		Classroom A1 Closet	W1	Chipping on wall, doorframes, and wood cove base, Flaking	54	No	No	N/A	Stored Materials	No	Sheetrock is confirmed asbestos
485	8260	1	0	A1A		Classroom A1 Closet	W2	Chipping on wall and wood cove base, Flaking	9	No	No	N/A	Cabinets	No	Sheetrock is confirmed asbestos
486	8260	1	0	A1A		Classroom A1 Closet	W3	Flaking	11	No	No	N/A	Cabinets, Stored Materials	No	Sheetrock is confirmed asbestos
487	8260	1	0	A1A		Classroom A1 Closet	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
488	8260	1	0	A2		Classroom A2	Ceiling	Chipping, Flaking	450	No	No	N/A	N/A	No	
489	8260	1	0	A2		Classroom A2	W1	Cracking, Chipping on wall, door, doorframe, and wood cove base, Flaking	63	No	No	N/A	Posters	No	Sheetrock is confirmed asbestos
490	8260	1	0	A2		Classroom A2	W2	Chipping, Holes, Flaking on metal jacket	5	No	No	N/A	Posters	No	Sheetrock is confirmed asbestos
491	8260	1	0	A2		Classroom A2	W3	Cracking, Chipping on wall, radiator cover, univent, windows, and windowframes, Flaking on metal jacket, windows, and windowframes	54	No	No	N/A	Furniture	No	Sheetrock is confirmed asbestos
492	8260	1	0	A2		Classroom A2	W4	Chipping on wall and wood cove base	17	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos
493	8260	1	0	A2A		Classroom A2 Closet	Ceiling	Flaking	3	No	No	N/A	N/A	No	
494	8260	1	0	A2A		Classroom A2 Closet	W1	Chipping on wall and doorframes, Flaking	18	No	No	N/A	Stored Materials	No	Sheetrock is confirmed asbestos
495	8260	1	0	A2A		Classroom A2 Closet	W2	Flaking	10	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos
496	8260	1	0	A2A		Classroom A2 Closet	W3	Chipping on wall and wood cove base, Flaking	20	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos
497	8260	1	0	A2A		Classroom A2 Closet	W4	Chipping	3	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos
498	8260	1	0	A3		Classroom A3	Ceiling	Chipping, Flaking	3	No	No	N/A	N/A	No	
499	8260	1	0	A3		Classroom A3	W1	Chipping on wall, door, doorframe, and wood cove base	35	No	No	N/A	Shelves, Furniture	No	Sheetrock is confirmed asbestos
500	8260	1	0	A3		Classroom A3	W2	Cracking, Chipping on wall and wood cove base	8	No	No	N/A	Shelves, Stored Materials	No	Sheetrock is confirmed asbestos
501	8260	1	0	A3		Classroom A3	W3	Cracking, Chipping on univent, radiator cover, wood cove base, windows, and windowframes, Flaking on wall, metal jacket, windows, and windowframes	49	No	No	N/A	Shelves, Stored Materials	No	Sheetrock is confirmed asbestos
502	8260	1	0	A3		Classroom A3	W4	Chipping on wall and wood cove base	9	No	No	N/A	Shelves, Stored Materials	No	Sheetrock is confirmed asbestos
503	8260	1	0	A3A		Classroom A3 Closet	W1	Chipping on wall and doorframes	16	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos
504	8260	1	0	A3A		Classroom A3 Closet	W2	Chipping on metal pipes, Flaking on fiberglass pipe insulation	7	No	No	N/A	Cabinets, Stored Materials	No	Limited inspection due to stored materials
505	8260	1	0	A3A		Classroom A3 Closet	W3	Chipping	4	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos
506	8260	1	0	A3A		Classroom A3 Closet	W4	N/A	N/A	No	No	N/A	Cabinets	No	Limited inspection due to stored materials
507	8260	1	0	A4		Classroom A4	Ceiling	Chipping	1	No	No	N/A	N/A	No	
508	8260	1	0	A4		Classroom A4	W1	Chipping on wall, door, doorframe, and wood cove base	29	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos
509	8260	1	0	A4		Classroom A4	W2	Chipping on wall and wood cove base	14	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
510	8260	1	0	A4		Classroom A4	W3	Cracking, Chipping on wall, metal jacket, radiator covers, and univent, Flaking on windows and windowframes	51	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos
511	8260	1	0	A4		Classroom A4	W4	Chipping on wall and wood cove base	7	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos
512	8260	1	0	A4A		Classroom A4 Closet	W1	Chipping on wall and doorframes	22	No	No	N/A	Stored Materials	No	Sheetrock is confirmed asbestos
513	8260	1	0	A4A		Classroom A4 Closet	W2	Flaking	1	No	No	N/A	Stored Materials	No	Sheetrock is confirmed asbestos
514	8260	1	0	A4A		Classroom A4 Closet	W3	Chipping on wall and wood cove base, Flaking	9	No	No	N/A	Stored Materials	No	Sheetrock is confirmed asbestos
515	8260	1	0	A4A		Classroom A4 Closet	W4	Chipping on wall and wood cove base	3	No	No	N/A	Stored Materials	No	Sheetrock is confirmed asbestos
516	8260	1	0	A5		Classroom A5	Ceiling	Flaking	3	No	No	N/A	N/A	No	
517	8260	1	0	A5		Classroom A5	W1	Cracking, Chipping on wall, door, doorframe, and wood cove base	46	No	No	N/A	N/A	No	Sheetrock is confirmed asbestos
518	8260	1	0	A5		Classroom A5	W2	Cracking, Chipping on wall and wood cove base	8	No	No	N/A	Shelves with stored materials	No	Sheetrock is confirmed asbestos
519	8260	1	0	A5		Classroom A5	W3	Cracking, Chipping on wall, univent, radiator covers, windows, and windowframes, Flaking on metal jacket, windows, and windowframes	30	No	No	N/A	Shelves with stored materials	No	Sheetrock is confirmed asbestos
520	8260	1	0	A5		Classroom A5	W4	Cracking, Chipping on wall and wood cove base	14	No	No	N/A	Shelves with stored materials	No	Sheetrock is confirmed asbestos
521	8260	1	0	A5A		Classroom A5 Closet	Ceiling	Flaking	3	No	No	N/A	N/A	No	
522	8260	1	0	A5A		Classroom A5 Closet	W1	Chipping on doorframes and wood cove base	18	No	No	N/A	N/A	No	
523	8260	1	0	A5A		Classroom A5 Closet	W2	Flaking	2	No	No	N/A	Stored Materials	No	Sheetrock is confirmed asbestos
524	8260	1	0	A5A		Classroom A5 Closet	W3	Cracking, Chipping on wall and wood cove base, Flaking	14	No	No	N/A	Cabinet, Stored Materials	No	Sheetrock is confirmed asbestos
525	8260	1	0	A5A		Classroom A5 Closet	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
526	8260	1	0	A6		Classroom A6	W1	Chipping on wall, door, and doorframe	15	No	No	N/A	Posters	No	Sheetrock is confirmed asbestos
527	8260	1	0	A6		Classroom A6	W2	Cracking, Chipping on wall and wood cove base	12	No	No	N/A	Posters, Furniture	No	Sheetrock is confirmed asbestos
528	8260	1	0	A6		Classroom A6	W3	Cracking, Chipping on wall, radiator covers, metal jacket, univent, windows, and windowframes, Flaking on wall, windows, and windowframes	54	No	No	N/A	Furniture	No	Sheetrock is confirmed asbestos
529	8260	1	0	A6		Classroom A6	W4	Chipping on wall and wood cove base	4	No	No	N/A	Furniture	No	Sheetrock is confirmed asbestos
530	8260	1	0	A6A		Classroom A6 Closet	Ceiling	Flaking	1	No	No	N/A	N/A	No	
531	8260	1	0	A6A		Classroom A6 Closet	W1	Chipping on doorframes, Flaking	16	No	No	N/A	Stored Materials	No	Sheetrock is confirmed asbestos
532	8260	1	0	A6A		Classroom A6 Closet	W2	Chipping on wall and wood cove base	2	No	No	N/A	Stored Materials	No	Sheetrock is confirmed asbestos
533	8260	1	0	A6A		Classroom A6 Closet	W3	Cracking, Chipping on wall and wood cove base	7	No	No	N/A	Stored Materials	No	Sheetrock is confirmed asbestos
534	8260	1	0	A6A		Classroom A6 Closet	W4	Chipping	1	No	No	N/A	Stored Materials	No	Sheetrock is confirmed asbestos
535	8260	1	0	24		Classroom C4	Floor	Chipping on cove base	9	No	No	N/A	N/A	No	

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
536	8260	1	0	24		Classroom C4	W1	Chipping on wall and metal pipe	8	No	No	N/A	N/A	No	
537	8260	1	0	24		Classroom C4	W2	Chipping on asbestos pipe insulation and metal pipe	9	No	No	N/A	N/A	No	
538	8260	1	0	24		Classroom C4	W3	Chipping on radiator cover and metal pipe	10	No	No	N/A	N/A	No	
539	8260	1	0	18		ESOL Classroom	Ceiling	Flaking	20	No	No	N/A	N/A	No	
540	8260	1	0	18		ESOL Classroom	Floor	Chipping on cove base	7	No	No	N/A	N/A	No	Cove base is assumed asbestos
541	8260	1	0	18		ESOL Classroom	W1	Chipping	2	No	No	N/A	N/A	No	
542	8260	1	0	18		ESOL Classroom	W3	Chipping, Flaking on asbestos pipe insulation	7	No	No	N/A	N/A	No	
543	8260	1	0	18		ESOL Classroom	W4	Chipping on wall and radiator covers	12	No	No	N/A	N/A	No	
544	8260	1	0	H06		ESOL Classroom / Women's Restroom Hallway	Ceiling	Flaking on ceiling and metal pipe	2	No	No	N/A	N/A	No	
545	8260	1	0	H06		ESOL Classroom / Women's Restroom Hallway	W1	Flaking	2	No	No	N/A	N/A	No	
546	8260	1	0	H06		ESOL Classroom / Women's Restroom Hallway	W2	Flaking	35	No	No	N/A	N/A	No	
547	8260	1	0	H06		ESOL Classroom / Women's Restroom Hallway	W3	Flaking	17	No	No	N/A	N/A	No	
548	8260	1	0	H06		ESOL Classroom / Women's Restroom Hallway	W4	Flaking	24	No	No	N/A	N/A	No	
549	8260	1	0	018A		ESOL Classroom Closet	Ceiling	Cracking	3	No	No	N/A	N/A	No	Concrete will need to be repaired
550	8260	1	0	018A		ESOL Classroom Closet	W2	Chipping	2	No	No	N/A	N/A	No	
551	8260	1	0	018A		ESOL Classroom Closet	W3	Chipping	4	No	No	N/A	N/A	No	
552	8260	1	0	018A		ESOL Classroom Closet	W4	Chipping	3	No	No	N/A	N/A	No	
553	8260	1	0	8		Girl's Restroom	Ceiling	Chipping	14	No	No	N/A	N/A	No	
554	8260	1	0	8		Girl's Restroom	W1	Chipping on wall and pipe chase door	12	No	No	N/A	N/A	No	
555	8260	1	0	8		Girl's Restroom	W2	Chipping on radiator cover	11	No	No	N/A	N/A	No	
556	8260	1	0	19		Gym	Ceiling	Cracking, Flaking	2	No	No	N/A	N/A	No	Plaster is assumed asbestos
557	8260	1	0	19		Gym	W1	Cracking, Chipping on wall and doorframe, Flaking	58	No	No	N/A	N/A	No	Concrete block will need to be repaired
558	8260	1	0	19		Gym	W2	Chipping, Flaking, Spalling	58	Yes	No	N/A	N/A	No	
559	8260	1	0	19		Gym	W3	Chipping, Flaking	9	No	No	N/A	N/A	No	
560	8260	1	0	19		Gym	W4	Chipping, Hole, Flaking	24	No	No	N/A	N/A	No	Concrete block will need to be repaired
561	8260	1	0	S106		Gym Back Exit Stairwell	Ceiling	Flaking	4	No	No	N/A	N/A	No	
562	8260	1	0	S106		Gym Back Exit Stairwell	Floor	Chipping on stairs, cove base, and railings	79	No	No	N/A	N/A	No	Cove base is assumed asbestos
563	8260	1	0	S106		Gym Back Exit Stairwell	W1	Cracking, Flaking	11	No	No	N/A	N/A	No	Concrete block will need to be repaired
564	8260	1	0	S106		Gym Back Exit Stairwell	W2	Cracking, Chipping, Flaking	35	No	No	N/A	N/A	No	Concrete block will need to be repaired
565	8260	1	0	S106		Gym Back Exit Stairwell	W3	Cracking, Chipping on doors and doorframe	27	No	No	N/A	N/A	No	Concrete block will need to be repaired

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
566	8260	1	0	S106		Gym Back Exit Stairwell	W4	Chipping on wall and asbestos pipe insulation, Flaking on metal pipes	10	No	No	N/A	N/A	No	
567	8260	1	0	019C		Gym Equipment Storage Room	Ceiling	Flaking	50	No	No	N/A	N/A	No	
568	8260	1	0	019C		Gym Equipment Storage Room	Floor	Flaking on metal pipe	9	No	Debris along wall 3	15	N/A	No	
569	8260	1	0	019C		Gym Equipment Storage Room	W1	Chipping on metal pipe	3	No	No	N/A	Gym Equipment	No	Limited inspection due to stored materials
570	8260	1	0	019C		Gym Equipment Storage Room	W2	Cracking, Flaking	11	No	No	N/A	Gym Equipment	No	Concrete block will need to be repaired
571	8260	1	0	019C		Gym Equipment Storage Room	W3	Efflorescence	150	Yes	No	N/A	Gym Equipment	Yes	
572	8260	1	0	019C		Gym Equipment Storage Room	W4	Flaking	10	No	No	N/A	Gym Equipment	No	Limited inspection due to stored materials
573	8260	1	0	019A		Gym Lobby and Hallway	Ceiling	Flaking	12	No	No	N/A	N/A	No	
574	8260	1	0	019A		Gym Lobby and Hallway	Floor	Chipping on cove base	29	No	Paint chips	11	N/A	No	Cove base is assumed asbestos
575	8260	1	0	019A		Gym Lobby and Hallway	W1	Chipping on wall and electrical panel, Flaking	12	No	No	N/A	N/A	No	
576	8260	1	0	019A		Gym Lobby and Hallway	W2	Chipping, Flaking	31	No	No	N/A	N/A	No	
577	8260	1	0	019A		Gym Lobby and Hallway	W3	Chipping, Flaking	31	No	No	N/A	N/A	No	
578	8260	1	0	019A		Gym Lobby and Hallway	W4	Flaking	18	No	No	N/A	N/A	No	
579	8260	1	0	2		Gym Lobby Boy's Restroom	Ceiling	Flaking	40	No	No	N/A	N/A	No	
580	8260	1	0	2		Gym Lobby Boy's Restroom	W1	Flaking	5	No	No	N/A	N/A	No	
581	8260	1	0	2		Gym Lobby Boy's Restroom	W2	Flaking on wall and windowsill	8	No	No	N/A	N/A	No	
582	8260	1	0	2		Gym Lobby Boy's Restroom	W4	Flaking	2	No	No	N/A	N/A	No	
583	8260	1	0	019B		Gym Lobby Custodial Closet	Ceiling	Chipping on asbestos pipe insulation, Flaking	21	No	No	N/A	N/A	No	
584	8260	1	0	019B		Gym Lobby Custodial Closet	Floor	Chipping	25	No	No	N/A	N/A	No	
585	8260	1	0	019B		Gym Lobby Custodial Closet	W1	Flaking	8	No	No	N/A	N/A	No	
586	8260	1	0	019B		Gym Lobby Custodial Closet	W2	Flaking	10	No	No	N/A	N/A	No	
587	8260	1	0	1		Gym Office	Ceiling	Flaking	16	No	No	N/A	N/A	No	
588	8260	1	0	1		Gym Office	Floor	Chipping on cove base	14	No	No	N/A	N/A	No	Cove base is assumed asbestos
589	8260	1	0	1		Gym Office	W1	Chipping	1	No	No	N/A	N/A	No	
590	8260	1	0	1		Gym Office	W2	Holes	2	No	No	N/A	N/A	No	Concrete block will need to be repaired
591	8260	1	0	1		Gym Office	W3	Chipping, Flaking	6	No	No	N/A	N/A	No	
592	8260	1	0	1		Gym Office	W4	Flaking	1	No	No	N/A	N/A	No	
593	8260	1	0	H01		Hallway between Gym Stair and Tank Room	Ceiling	Chipping on metal pipe and asbestos pipe insulation, Flaking on ceiling, asbestos pipe insulation, asbestos pipe fittings, and metal pipe	39	No	No	N/A	N/A	No	
594	8260	1	0	H01		Hallway between Gym Stair and Tank Room	Floor	Chipping on cove base	20	No	No	N/A	N/A	No	Cove base is assumed asbestos

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
595	8260	1	0	H01		Hallway between Gym Stair and Tank Room	W1	Chipping, Flaking	50	No	No	N/A	N/A	No	
596	8260	1	0	H01		Hallway between Gym Stair and Tank Room	W3	Chipping	1	No	No	N/A	N/A	No	
597	8260	1	0	H01		Hallway between Gym Stair and Tank Room	W4	Flaking	4	No	No	N/A	N/A	No	
598	8260	1	0	H04		Hallway from Stairwell C to Stairwell B	Ceiling	Flaking on ceiling and fiberglass pipe insulation	67	No	No	N/A	N/A	No	
599	8260	1	0	H04		Hallway from Stairwell C to Stairwell B	Floor	Chipping on cove base	20	No	No	N/A	N/A	No	Cove base is assumed asbestos
600	8260	1	0	H04		Hallway from Stairwell C to Stairwell B	W2	Chipping, Hole, Flaking	35	No	No	N/A	N/A	No	
601	8260	1	0	H04		Hallway from Stairwell C to Stairwell B	W3	Flaking	10	No	No	N/A	N/A	No	
602	8260	1	0	H04		Hallway from Stairwell C to Stairwell B	W4	Cracking, Chipping on wall, metal jackets, and radiator covers, Hole, Flaking on wall, metal pipes, and asbestos pipe fittings	87	No	No	N/A	N/A	No	Concrete block will need to be repaired
603	8260	1	0	H05		Hallway to Storage behind Kitchen	Floor	Chipping on cove base	9	No	No	N/A	N/A	No	Cove base is assumed asbestos
604	8260	1	0	H05		Hallway to Storage behind Kitchen	W1	Cracking	10	No	No	N/A	N/A	No	Concrete block will need to be repaired
605	8260	1	0	H05		Hallway to Storage behind Kitchen	W2	Chipping	4	No	No	N/A	N/A	No	
606	8260	1	0	H05		Hallway to Storage behind Kitchen	W3	Chipping	4	No	No	N/A	N/A	No	
607	8260	1	0	34		IMC	Ceiling	Chipping on metal duct, Flaking on ceiling and metal duct	12	No	No	N/A	N/A	No	
608	8260	1	0	34		IMC	W1	Chipping on door, doorframe, metal pipe, and conduit lines	20	No	No	N/A	N/A	No	
609	8260	1	0	34		IMC	W2	Chipping	8	No	No	N/A	N/A	No	
610	8260	1	0	34		IMC	W3	Chipping on wall, door, and doorframe, conduit, and metal pipe, Flaking on metal pipe	17	No	No	N/A	N/A	No	
611	8260	1	0	34		IMC	W4	Chipping, Flaking	2	No	No	N/A	N/A	No	
612	8260	1	0	H03		IMC Hallway	Ceiling	Flaking	2	No	No	N/A	N/A	No	
613	8260	1	0	H03		IMC Hallway	W1	Chipping on radiator covers	4	No	No	N/A	N/A	No	
614	8260	1	0	H03		IMC Hallway	W2	Chipping on doors and doorframe	14	No	No	N/A	N/A	No	
615	8260	1	0	H03		IMC Hallway	W3	Chipping on doorframe and radiator covers	4	No	No	N/A	N/A	No	
616	8260	1	0	14		Kitchen	Ceiling	Flaking	3	No	No	N/A	N/A	No	
617	8260	1	0	14		Kitchen	Floor	Chipping on cove base	20	No	No	N/A	N/A	No	
618	8260	1	0	14		Kitchen	W3	Chipping on wall and metal pipes	13	No	No	N/A	Ovens, Cabinets	No	
619	8260	1	0	14		Kitchen	W4	Chipping on wall and radiator cover	3	No	No	N/A	Cabinet	No	
620	8260	1	0	011A		Kitchen Staff Locker Room	Floor	Chipping on cove base	11	No	No	N/A	N/A	No	Cove base is assumed asbestos
621	8260	1	0	011A		Kitchen Staff Locker Room	W1	Flaking on wall and conduit	18	No	No	N/A	Lockers	No	
622	8260	1	0	011A		Kitchen Staff Locker Room	W2	Flaking on wall and fiberglass pipe insulation	24	No	No	N/A	N/A	No	

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
623	8260	1	0	011A		Kitchen Staff Locker Room	W3	Flaking	45	No	No	N/A	N/A	No	
624	8260	1	0	011A		Kitchen Staff Locker Room	W4	Flaking	32	No	No	N/A	N/A	No	
625	8260	1	0	014B		Kitchen Staff Locker Room / Storage Hallway	W1	Chipping, Flaking	43	No	No	N/A	N/A	No	
626	8260	1	0	014B		Kitchen Staff Locker Room / Storage Hallway	W2	Flaking	10	No	No	N/A	N/A	No	
627	8260	1	0	014B		Kitchen Staff Locker Room / Storage Hallway	W3	Chipping, Flaking	44	No	No	N/A	N/A	No	
628	8260	1	0	014B		Kitchen Staff Locker Room / Storage Hallway	W4	Flaking	6	No	No	N/A	N/A	No	
629	8260	1	0	011A1		Kitchen Staff Locker Room Restroom	Floor	Chipping on cove base	9	No	No	N/A	N/A	No	Cove base is assumed asbestos
630	8260	1	0	011A1		Kitchen Staff Locker Room Restroom	W2	Chipping on wall and asbestos pipe insulation	2	No	No	N/A	N/A	No	
631	8260	1	0	011A1		Kitchen Staff Locker Room Restroom	W3	Chipping	1	No	No	N/A	N/A	No	
632	8260	1	0	011A1		Kitchen Staff Locker Room Restroom	W4	Chipping	1	No	No	N/A	N/A	No	
633	8260	1	0	11		Kitchen Storage next to Staff Locker Room	Ceiling	Chipping	2	No	No	N/A	N/A	No	
634	8260	1	0	11		Kitchen Storage next to Staff Locker Room	Floor	Chipping on cove base	1	No	No	N/A	N/A	No	Cove base is assumed asbestos
635	8260	1	0	11		Kitchen Storage next to Staff Locker Room	W4	Hole	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
636	8260	1	0	17		Staff Restroom opposite ESOL Classroom	Ceiling	Flaking	1	No	No	N/A	N/A	No	
637	8260	1	0	17		Staff Restroom opposite ESOL Classroom	W1	Flaking	1	No	No	N/A	N/A	No	
638	8260	1	0	17		Staff Restroom opposite ESOL Classroom	W2	Chipping on radiator cover	1	No	No	N/A	N/A	No	
639	8260	1	0	17		Staff Restroom opposite ESOL Classroom	W3	Flaking	4	No	No	N/A	N/A	No	
640	8260	1	0	S02		Stairwell A adjacent to Fan Room	Ceiling	Flaking	30	No	No	N/A	N/A	No	
641	8260	1	0	S02		Stairwell A adjacent to Fan Room	Floor	Chipping on cove base	46	No	No	N/A	N/A	No	Cove base is assumed asbestos
642	8260	1	0	S02		Stairwell A adjacent to Fan Room	W1	Chipping on doors and doorframe, Flaking	44	No	No	N/A	N/A	No	
643	8260	1	0	S02		Stairwell A adjacent to Fan Room	W2	Chipping on wall and radiator cover, Holes, Flaking	19	No	No	N/A	N/A	No	Concrete block will need to be repaired
644	8260	1	0	S02		Stairwell A adjacent to Fan Room	W3	Chipping on doors and doorframe	16	No	No	N/A	N/A	No	
645	8260	1	0	S02		Stairwell A adjacent to Fan Room	W4	Cracking, Chipping	9	No	No	N/A	N/A	No	Concrete block will need to be repaired
646	8260	1	0	S105		Stairwell adjacent to Gym Office	Ceiling	Flaking	9	No	No	N/A	N/A	No	

Fox Chase -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
647	8260	1	0	S105		Stairwell adjacent to Gym Office	Floor	Chipping on cove base	1	No	No	N/A	N/A	No	Cove base is assumed asbestos
648	8260	1	0	S105		Stairwell adjacent to Gym Office	W1	Chipping	1	No	No	N/A	N/A	No	
649	8260	1	0	S105		Stairwell adjacent to Gym Office	W2	Chipping, Flaking	19	No	No	N/A	N/A	No	
650	8260	1	0	S105		Stairwell adjacent to Gym Office	W3	Chipping on doors and doorframe	18	No	No	N/A	N/A	No	
651	8260	1	0	S107		Stairwell B adjacent to Cafeteria	Ceiling	Chipping, Flaking on wall, fiberglass pipe insulation, and asbestos pipe fitting	30	No	No	N/A	N/A	No	
652	8260	1	0	S107		Stairwell B adjacent to Cafeteria	Floor	Chipping on cove base	24	No	No	N/A	N/A	No	Cove base is assumed asbestos
653	8260	1	0	S107		Stairwell B adjacent to Cafeteria	W1	Cracking, Chipping on door and doorframe, Flaking	22	No	No	N/A	N/A	No	Concrete block will need to be repaired
654	8260	1	0	S107		Stairwell B adjacent to Cafeteria	W2	Cracking, Chipping on wall, radiator cover, and conduit, Holes, Flaking on wall and conduit	29	No	No	N/A	N/A	No	Concrete block will need to be repaired
655	8260	1	0	S107		Stairwell B adjacent to Cafeteria	W3	Cracking, Flaking	4	No	No	N/A	N/A	No	Concrete block will need to be repaired
656	8260	1	0	S107		Stairwell B adjacent to Cafeteria	W4	Chipping	6	No	No	N/A	N/A	No	
657	8260	1	0	S102		Stairwell C adjacent to Cafeteria Hall	Ceiling	Flaking on ceiling and metal duct	2	No	No	N/A	N/A	No	
658	8260	1	0	S102		Stairwell C adjacent to Cafeteria Hall	Floor	Chipping on cove base	38	No	No	N/A	N/A	No	Cove base is assumed asbestos
659	8260	1	0	S102		Stairwell C adjacent to Cafeteria Hall	W1	Hole	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
660	8260	1	0	S102		Stairwell C adjacent to Cafeteria Hall	W2	Chipping on doors, doorframe, and radiator cover, Holes	37	No	No	N/A	N/A	No	Concrete block will need to be repaired
661	8260	1	0	S102		Stairwell C adjacent to Cafeteria Hall	W3	Chipping on doors and doorframe	20	No	No	N/A	N/A	No	
662	8260	1	0	S102		Stairwell C adjacent to Cafeteria Hall	W4	Chipping	5	No	No	N/A	N/A	No	
663	8260	1	0	S104		Stairwell to Gym	Ceiling	Chipping, Flaking	17	No	No	N/A	N/A	No	
664	8260	1	0	S104		Stairwell to Gym	Floor	Chipping on stairs, cove base, and railings	133	No	No	N/A	N/A	No	Cove base is assumed asbestos
665	8260	1	0	S104		Stairwell to Gym	W1	Cracking, Flaking	16	No	No	N/A	N/A	No	Concrete block will need to be repaired
666	8260	1	0	S104		Stairwell to Gym	W2	Chipping, Flaking	18	No	No	N/A	N/A	No	
667	8260	1	0	S104		Stairwell to Gym	W3	Chipping, Flaking	21	No	No	N/A	N/A	No	
668	8260	1	0	S104		Stairwell to Gym	W4	Chipping, Flaking	30	No	No	N/A	N/A	No	
669	8260	1	0	S104A		Stairwell to Gym Custodial Closet	Ceiling	Cracking, Chipping on metal duct	10	No	No	N/A	N/A	No	Concrete will need to be repaired
670	8260	1	0	S104A		Stairwell to Gym Custodial Closet	W3	Hole	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
671	8260	1	0	12		Storage Room behind Kitchen	Floor	Chipping on cove base	12	No	No	N/A	N/A	No	
672	8260	1	0	12		Storage Room behind Kitchen	W1	Chipping, Flaking	4	No	No	N/A	Refrigerator	No	Entrance from kitchen
673	8260	1	0	12		Storage Room behind Kitchen	W2	N/A	N/A	No	No	N/A	Shelf	No	Limited inspection due to stored materials
674	8260	1	0	12		Storage Room behind Kitchen	W3	Flaking	12	No	No	N/A	Refrigerator, Stored Materials	No	Limited inspection due to stored materials
675	8260	1	0	12		Storage Room behind Kitchen	W4	Chipping on radiator cover, Flaking	9	No	No	N/A	N/A	No	