

Franklin ES -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	7280	1	2	207A		Book Closet across from Classroom 202	W1	Cracking, Chipping, Efflorescence	13	Yes	No	N/A	Stored Materials	Yes	
2	7280	1	2	207A		Book Closet across from Classroom 202	W2	Cracking	2	No	No	N/A	Stored Materials	No	
3	7280	1	2	207A		Book Closet across from Classroom 202	W3	Cracking	6	No	No	N/A	Stored Materials	No	
4	7280	1	2	207A		Book Closet across from Classroom 202	W4	Cracking	14	No	No	N/A	Built in shelves with stored materials	No	
5	7280	1	2	201		Classroom 201	Ceiling	Holes, Flaking, Spalling	62	Yes	No	N/A	N/A	Yes	
6	7280	1	2	201		Classroom 201	Floor	Debris	N/A	No	Paint Chips	30	N/A	No	
7	7280	1	2	201		Classroom 201	W1	Cracking, Chipping, Holes	44	No	No	N/A	N/A	Yes	
8	7280	1	2	201		Classroom 201	W2	Flaking	1	No	No	N/A	N/A	No	
9	7280	1	2	201		Classroom 201	W3	Chipping on wall and metal pipes, Hole, Spalling	51	Yes	No	N/A	N/A	Yes	
10	7280	1	2	201		Classroom 201	W4	Cracking, Chipping	22	No	No	N/A	N/A	No	
11	7280	1	2	202		Classroom 202	Ceiling	Cracking, Flaking, Spalling	15	Yes	No	N/A	N/A	Yes	
12	7280	1	2	202		Classroom 202	W1	Chipping, Holes	19	No	No	N/A	N/A	Yes	
13	7280	1	2	202		Classroom 202	W2	Flaking, Spalling	2	Yes	No	N/A	N/A	Yes	
14	7280	1	2	202		Classroom 202	W3	Cracking, Chipping on wall and metal pipes, Holes, Efflorescence	210	Yes	No	N/A	N/A	Yes	
15	7280	1	2	202		Classroom 202	W4	Spalling	3	Yes	No	N/A	N/A	Yes	
16	7280	1	2	203		Classroom 203	Ceiling	Cracking	2	No	No	N/A	N/A	No	
17	7280	1	2	203		Classroom 203	Floor	Debris	N/A	No	Debris	30	N/A	No	
18	7280	1	2	203		Classroom 203	W1	Cracking, Chipping, Holes, Flaking, Spalling	18	Yes	No	N/A	N/A	Yes	
19	7280	1	2	203		Classroom 203	W2	Chipping, Holes, Flaking	5	No	No	N/A	N/A	Yes	
20	7280	1	2	203		Classroom 203	W3	Cracking, Chipping on wall and metal pipes, Holes	62	No	No	N/A	N/A	Yes	
21	7280	1	2	203		Classroom 203	W4	Cracking, Hole	2	No	No	N/A	N/A	Yes	
22	7280	1	2	204		Classroom 204	Ceiling	Flaking	80	No	No	N/A	N/A	No	
23	7280	1	2	204		Classroom 204	W1	Chipping, Staple Holes, Flaking	16	No	No	N/A	N/A	Yes	
24	7280	1	2	204		Classroom 204	W2	Cracking, Chipping on wall and radiator covers, Flaking	50	No	No	N/A	N/A	No	
25	7280	1	2	204		Classroom 204	W3	Cracking, Staples, Flaking	36	No	No	N/A	N/A	Yes	
26	7280	1	2	204		Classroom 204	W4	Cracking, Chipping, Holes, Staple Holes, Flaking, Spalling	44	Yes	No	N/A	N/A	Yes	
27	7280	1	2	204A		Classroom 204 - Coat Closet	Ceiling	Flaking	25	No	No	N/A	N/A	No	
28	7280	1	2	204A		Classroom 204 - Coat Closet	W1	Cracking, Chipping, Flaking	25	No	No	N/A	Stored Materials	No	
29	7280	1	2	204A		Classroom 204 - Coat Closet	W2	Cracking, Chipping, Flaking	5	No	No	N/A	Stored Materials	No	
30	7280	1	2	204A		Classroom 204 - Coat Closet	W3	Cracking, Flaking	28	No	No	N/A	Stored Materials	No	
31	7280	1	2	204A		Classroom 204 - Coat Closet	W4	Cracking, Chipping on radiator cover, Flaking	9	No	No	N/A	Stored Materials	No	
32	7280	1	2	205		Classroom 205	Ceiling	Flaking	9	No	No	N/A	N/A	No	
33	7280	1	2	205		Classroom 205	Floor	Debris	N/A	No	Debris	20	N/A	No	

Franklin ES -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
34	7280	1	2	205		Classroom 205	W1	Holes, Flaking	16	No	No	N/A	Posters	Yes	
35	7280	1	2	205		Classroom 205	W2	Chipping, Hole, Flaking	21	No	No	N/A	N/A	Yes	
36	7280	1	2	205		Classroom 205	W3	Cracking, Chipping	15	No	No	N/A	N/A	No	
37	7280	1	2	205		Classroom 205	W4	Cracking, Chipping on wall and radiator covers, Hole, Flaking	55	No	No	N/A	N/A	Yes	
38	7280	1	2	205A		Classroom 205 - Coat Closet	W1	Cracking, Chipping, Flaking	11	No	No	N/A	N/A	No	
39	7280	1	2	205A		Classroom 205 - Coat Closet	W2	Cracking, Chipping on radiator cover, Flaking	8	No	No	N/A	N/A	No	
40	7280	1	2	205A		Classroom 205 - Coat Closet	W3	Cracking, Chipping, Flaking	22	No	No	N/A	N/A	No	
41	7280	1	2	205A		Classroom 205 - Coat Closet	W4	Cracking, Chipping	4	No	No	N/A	N/A	No	
42	7280	1	2	206		Classroom 206	Ceiling	Hole, Flaking	12	No	No	N/A	N/A	Yes	
43	7280	1	2	206		Classroom 206	W1	Cracking, Chipping, Holes, Flaking	36	No	No	N/A	N/A	Yes	
44	7280	1	2	206		Classroom 206	W2	Cracking, Chipping, Flaking	33	No	No	N/A	N/A	No	
45	7280	1	2	206		Classroom 206	W3	Cracking, Chipping on wall and radiator covers, Hole	41	No	No	N/A	N/A	Yes	
46	7280	1	2	206		Classroom 206	W4	Cracking, Chipping, Hole, Flaking	17	No	No	N/A	N/A	Yes	
47	7280	1	2	206D		Classroom 206 - Coat Closet	W1	Cracking, Flaking	6	No	No	N/A	N/A	No	
48	7280	1	2	206D		Classroom 206 - Coat Closet	W2	Cracking, Chipping, Flaking	16	No	No	N/A	N/A	No	
49	7280	1	2	206D		Classroom 206 - Coat Closet	W3	Cracking, Chipping	17	No	No	N/A	N/A	No	
50	7280	1	2	206D		Classroom 206 - Coat Closet	W4	Cracking, Chipping, Flaking	18	No	No	N/A	N/A	No	
51	7280	1	2	206E		Classroom 206 - Teacher's Closet	W1	Flaking	1	No	No	N/A	N/A	No	
52	7280	1	2	206E		Classroom 206 - Teacher's Closet	W2	Flaking	2	No	No	N/A	N/A	No	
53	7280	1	2	206E		Classroom 206 - Teacher's Closet	W3	Cracking	7	No	No	N/A	Built in shelves with books	No	
54	7280	1	2	206E		Classroom 206 - Teacher's Closet	W4	Debris	N/A	No	No	N/A	Built in shelves with books	No	
55	7280	1	2	207		Classroom 207	Ceiling	Flaking	17	No	No	N/A	N/A	No	
56	7280	1	2	207		Classroom 207	Floor	Debris	N/A	No	Debris	10	N/A	No	
57	7280	1	2	207		Classroom 207	W1	Chipping, Hole	2	No	No	N/A	N/A	Yes	
58	7280	1	2	207		Classroom 207	W2	Cracking, Hole, Flaking	10	No	No	N/A	N/A	Yes	
59	7280	1	2	207		Classroom 207	W3	Cracking, Chipping	4	No	Debris on windowsill	1	N/A	No	
60	7280	1	2	207		Classroom 207	W4	Flaking, Efflorescence	6	Yes	No	N/A	N/A	Yes	
61	7280	1	2	208		Classroom 208	Ceiling	Flaking, Efflorescence	10	Yes	No	N/A	N/A	Yes	
62	7280	1	2	208		Classroom 208	W1	Chipping, Holes, Flaking	13	No	No	N/A	N/A	Yes	
63	7280	1	2	208		Classroom 208	W2	Holes, Spalling, Efflorescence	15	Yes	No	N/A	N/A	Yes	
64	7280	1	2	208		Classroom 208	W3	Cracking, Chipping on wall and metal pipes, Holes, Efflorescence	32	Yes	No	N/A	N/A	Yes	
65	7280	1	2	208		Classroom 208	W4	Spalling	4	Yes	No	N/A	N/A	Yes	

Franklin ES -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
66	7280	1	2	209		Classroom 209	Floor	Debris	N/A	No	Debris along wall 4	4	N/A	No	
67	7280	1	2	209		Classroom 209	W1	Chipping, Holes	9	No	No	N/A	N/A	Yes	
68	7280	1	2	209		Classroom 209	W2	Chipping	1	No	No	N/A	N/A	No	
69	7280	1	2	209		Classroom 209	W3	Flaking	2	No	No	N/A	N/A	No	
70	7280	1	2	209		Classroom 209	W4	Chipping	1	No	Debris inside radiator	5	N/A	No	
71	7280	1	2	209B		Classroom 209 Closet	Ceiling	Flaking, Spalling	4	Yes	No	N/A	N/A	Yes	
72	7280	1	2	209B		Classroom 209 Closet	W1	Cracking	3	No	No	N/A	N/A	No	
73	7280	1	2	209B		Classroom 209 Closet	W2	Cracking	6	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
74	7280	1	2	209B		Classroom 209 Closet	W3	Cracking, Spalling	15	Yes	No	N/A	Built in shelves with stored materials	Yes	Limited inspection due to stored materials
75	7280	1	2	209B		Classroom 209 Closet	W4	Cracking	2	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
76	7280	1	2	209D		Closet in Office 209A next to Book Closet	Ceiling	Efflorescence	3	Yes	No	N/A	N/A	Yes	
77	7280	1	2	209D		Closet in Office 209A next to Book Closet	W1	Cracking	1	No	No	N/A	N/A	No	
78	7280	1	2	209D		Closet in Office 209A next to Book Closet	W2	Cracking, Chipping	4	No	No	N/A	Built in shelves with stored materials	No	
79	7280	1	2	209D		Closet in Office 209A next to Book Closet	W3	Efflorescence	3	Yes	No	N/A	Built in shelves with stored materials	Yes	
80	7280	1	2	209D		Closet in Office 209A next to Book Closet	W4	Cracking	2	No	No	N/A	Built in shelves with stored materials	No	
81	7280	1	2	H26		Hallway between Classroom 205 and Nurse's Office	Ceiling	Hole, Flaking	23	No	No	N/A	N/A	Yes	
82	7280	1	2	H26		Hallway between Classroom 205 and Nurse's Office	W1	Chipping on metal pipes and radiator cover, Hole, Flaking, Spalling	35	Yes	No	N/A	N/A	Yes	
83	7280	1	2	H26		Hallway between Classroom 205 and Nurse's Office	W2	Cracking, Chipping	3	No	No	N/A	N/A	No	
84	7280	1	2	H26		Hallway between Classroom 205 and Nurse's Office	W3	Cracking, Chipping on wall and metal pipes, Hole, Flaking	43	No	No	N/A	N/A	Yes	

Franklin ES -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
85	7280	1	2	H27		Hallway between Classrooms 201 and 205	Ceiling	Flaking	19	No	No	N/A	N/A	No	
86	7280	1	2	H27		Hallway between Classrooms 201 and 205	W1	Chipping on radiator cover, Flaking	8	No	No	N/A	N/A	No	
87	7280	1	2	H27		Hallway between Classrooms 201 and 205	W2	Cracking, Chipping, Hole, Flaking, Spalling	20	Yes	No	N/A	N/A	Yes	
88	7280	1	2	H27		Hallway between Classrooms 201 and 205	W3	Chipping, Flaking	26	No	No	N/A	N/A	No	
89	7280	1	2	H27		Hallway between Classrooms 201 and 205	W4	Chipping, Holes	18	No	No	N/A	N/A	Yes	
90	7280	1	2	209A		Hallway from Main Hall to Classroom 209 Area	Ceiling	Flaking, Spalling	2	Yes	No	N/A	N/A	Yes	
91	7280	1	2	209A		Hallway from Main Hall to Classroom 209 Area	W1	Cracking, Chipping, Hole	12	No	No	N/A	N/A	Yes	
92	7280	1	2	209A		Hallway from Main Hall to Classroom 209 Area	W3	Chipping	5	No	No	N/A	N/A	No	
93	7280	1	2	209A		Hallway from Main Hall to Classroom 209 Area	W4	Flaking	3	No	No	N/A	N/A	No	
94	7280	1	2	206A		Nurse's Office	Ceiling	Flaking	180	No	No	N/A	N/A	No	
95	7280	1	2	206A		Nurse's Office	Floor	Debris	N/A	No	Debris	3	N/A	No	
96	7280	1	2	206A		Nurse's Office	W1	Cracking, Chipping on wood cove base, Flaking on wall, door, and doorframe	22	No	No	N/A	N/A	No	
97	7280	1	2	206A		Nurse's Office	W2	Cracking, Chipping on wall and wood cove base, Flaking on wall and radiator cover	24	No	No	N/A	N/A	No	
98	7280	1	2	206A		Nurse's Office	W3	Chipping	6	No	No	N/A	N/A	No	
99	7280	1	2	206A		Nurse's Office	W4	Chipping on built in wood cabinet, Flaking	13	No	No	N/A	N/A	No	
100	7280	1	2	206B		Nurse's Office - Closet	W1	Chipping on doorframe	7	No	No	N/A	N/A	No	
101	7280	1	2	206B		Nurse's Office - Closet	W3	Chipping	1	No	No	N/A	N/A	No	
102	7280	1	2	206B		Nurse's Office - Closet	W4	Chipping	2	No	No	N/A	N/A	No	
103	7280	1	2	206C		Nurse's Office - Restroom	W3	Chipping on radiator cover, Flaking on metal pipe	8	No	No	N/A	N/A	No	
104	7280	1	2	209C		Office 209A next to Book Closet	Ceiling	Cracking, Flaking	2	No	No	N/A	N/A	No	
105	7280	1	2	209C		Office 209A next to Book Closet	W1	Chipping, Holes, Flaking	23	No	No	N/A	N/A	Yes	
106	7280	1	2	209C		Office 209A next to Book Closet	W2	Chipping, Holes	20	No	No	N/A	Posters	Yes	
107	7280	1	2	209C		Office 209A next to Book Closet	W3	Chipping	9	No	No	N/A	Posters	No	

Franklin ES -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
108	7280	1	2	209C		Office 209A next to Book Closet	W4	Chipping on wall and radiator, Flaking	38	No	No	N/A	Posters	No	
109	7280	1	2	S25		Stairwell near Classroom 201	Ceiling	Cracking	1	No	No	N/A	N/A	No	
110	7280	1	2	S25		Stairwell near Classroom 201	Floor	Chipping on floor and railings	48	No	No	N/A	N/A	No	
111	7280	1	2	S25		Stairwell near Classroom 201	W1	Cracking, Hole, Flaking	141	No	No	N/A	N/A	Yes	
112	7280	1	2	S25		Stairwell near Classroom 201	W2	Chipping on doors and doorframe	50	No	No	N/A	N/A	No	
113	7280	1	2	S25		Stairwell near Classroom 201	W3	Chipping, Hole	9	No	No	N/A	N/A	Yes	
114	7280	1	2	S25		Stairwell near Classroom 201	W4	Cracking	10	No	No	N/A	N/A	No	
115	7280	1	1	108		Auditorium	Ceiling	Hole, Flaking, Efflorescence	56	Yes	No	N/A	N/A	Yes	Ceiling is assumed asbestos
116	7280	1	1	108		Auditorium	Floor	Debris	N/A	No	Paint Chips and Debris	45	N/A	No	
117	7280	1	1	108		Auditorium	W1	Cracking, Chipping, Holes	24	No	No	N/A	N/A	Yes	
118	7280	1	1	108		Auditorium	W2	Cracking, Chipping, Flaking, Efflorescence	31	Yes	Debris on windowsills	2	N/A	Yes	
119	7280	1	1	108		Auditorium	W3	Chipping, Hole	4	No	No	N/A	N/A	Yes	
120	7280	1	1	108		Auditorium	W4	Chipping, Efflorescence	23	Yes	Debris on windowsills	1	N/A	Yes	
121	7280	1	1	108A		Auditorium Stage	Ceiling	Flaking	1	No	No	N/A	N/A	No	Ceiling is assumed asbestos
122	7280	1	1	108A		Auditorium Stage	Floor	Debris	N/A	No	Paint Chips and Debris	10	N/A	No	
123	7280	1	1	108A		Auditorium Stage	W1	Holes	6	No	No	N/A	N/A	Yes	
124	7280	1	1	108A		Auditorium Stage	W2	Chipping on radiator cover, Hole	7	No	No	N/A	N/A	Yes	
125	7280	1	1	108A		Auditorium Stage	W4	Hole	1	No	No	N/A	N/A	Yes	
126	7280	1	1	101		Classroom 101	Ceiling	Flaking	16	No	No	N/A	N/A	No	
127	7280	1	1	101		Classroom 101	W1	Chipping, Holes	12	No	No	N/A	N/A	Yes	
128	7280	1	1	101		Classroom 101	W2	Cracking, Chipping	3	No	No	N/A	N/A	No	
129	7280	1	1	101		Classroom 101	W3	Chipping on wall and metal pipes	11	No	No	N/A	N/A	No	
130	7280	1	1	101		Classroom 101	W4	Chipping	7	No	No	N/A	N/A	No	
131	7280	1	1	102		Classroom 102	W1	Cracking, Chipping, Holes	8	No	No	N/A	N/A	Yes	
132	7280	1	1	102		Classroom 102	W3	Cracking, Chipping on metal pipes	22	No	No	N/A	N/A	No	
133	7280	1	1	102		Classroom 102	W4	Chipping, Flaking	3	No	No	N/A	N/A	No	
134	7280	1	1	103		Classroom 103	Ceiling	Hole	1	No	No	N/A	N/A	Yes	
135	7280	1	1	103		Classroom 103	Floor	Debris	N/A	No	Debris	10	N/A	No	
136	7280	1	1	103		Classroom 103	W1	Cracking, Chipping, Holes	8	No	No	N/A	N/A	Yes	
137	7280	1	1	103		Classroom 103	W2	Chipping, Flaking	3	No	No	N/A	N/A	No	
138	7280	1	1	103		Classroom 103	W3	Cracking, Chipping on wall and metal pipes	38	No	No	N/A	N/A	No	
139	7280	1	1	104		Classroom 104	Ceiling	Flaking	8	No	No	N/A	N/A	No	
140	7280	1	1	104		Classroom 104	Floor	Debris	N/A	No	Debris	5	N/A	No	
141	7280	1	1	104		Classroom 104	W1	Chipping, Holes, Flaking	10	No	No	N/A	N/A	Yes	
142	7280	1	1	104		Classroom 104	W2	Cracking, Chipping on wall, metal jackets, and radiator covers, Flaking	42	No	No	N/A	N/A	No	
143	7280	1	1	104		Classroom 104	W3	Cracking, Flaking	33	No	No	N/A	N/A	No	
144	7280	1	1	104		Classroom 104	W4	Cracking, Chipping, Flaking	13	No	No	N/A	N/A	No	

Franklin ES -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
145	7280	1	1	104A		Classroom 104 - Coat Closet	W1	Cracking	5	No	No	N/A	N/A	No	
146	7280	1	1	104A		Classroom 104 - Coat Closet	W2	Cracking, Flaking	4	No	No	N/A	N/A	No	
147	7280	1	1	104A		Classroom 104 - Coat Closet	W3	Chipping, Flaking	4	No	No	N/A	N/A	No	
148	7280	1	1	104A		Classroom 104 - Coat Closet	W4	Flaking	2	No	No	N/A	N/A	No	
149	7280	1	1	105		Classroom 105	Ceiling	Flaking	3	No	No	N/A	N/A	No	
150	7280	1	1	105		Classroom 105	Floor	Debris	N/A	No	Debris	10	N/A	No	
151	7280	1	1	105		Classroom 105	W1	Cracking	1	No	No	N/A	N/A	No	
152	7280	1	1	105		Classroom 105	W2	Cracking, Chipping, Holes	10	No	No	N/A	N/A	Yes	
153	7280	1	1	105		Classroom 105	W3	Cracking, Holes, Flaking	8	No	No	N/A	N/A	Yes	
154	7280	1	1	105		Classroom 105	W4	Chipping on wall, metal pipes, and radiator covers, Flaking	68	No	No	N/A	N/A	No	
155	7280	1	1	105A		Classroom 105 - Coat Closet	Ceiling	Flaking	1	No	No	N/A	N/A	No	
156	7280	1	1	105A		Classroom 105 - Coat Closet	W1	Cracking, Gouges, Flaking	11	No	No	N/A	N/A	Yes	
157	7280	1	1	105A		Classroom 105 - Coat Closet	W2	Cracking	2	No	No	N/A	Cabinet	No	Limited inspection due to cabinet
158	7280	1	1	105A		Classroom 105 - Coat Closet	W3	Flaking	2	No	No	N/A	Cabinet, Stored Materials	No	Limited inspection due to cabinet and stored materials
159	7280	1	1	105A		Classroom 105 - Coat Closet	W4	Cracking, Chipping, Flaking	5	No	No	N/A	N/A	No	
160	7280	1	1	106		Classroom 106	Ceiling	Flaking	6	No	No	N/A	N/A	No	
161	7280	1	1	106		Classroom 106	W1	Chipping, Holes, Staple Holes, Flaking	61	No	No	N/A	N/A	Yes	
162	7280	1	1	106		Classroom 106	W2	Chipping, Staple Holes, Flaking, Efflorescence	63	Yes	No	N/A	N/A	Yes	
163	7280	1	1	106		Classroom 106	W3	Cracking, Chipping on wall and radiator covers, Staple Holes, Flaking	78	No	No	N/A	N/A	Yes	
164	7280	1	1	106		Classroom 106	W4	Chipping, Hole, Staple Holes, Flaking	54	No	No	N/A	N/A	Yes	
165	7280	1	1	106B		Classroom 106 - Closet	Ceiling	Cracking, Flaking	4	No	No	N/A	N/A	No	
166	7280	1	1	106B		Classroom 106 - Closet	W1	Flaking	1	No	No	N/A	N/A	No	
167	7280	1	1	106B		Classroom 106 - Closet	W2	Cracking, Hole, Flaking	7	No	No	N/A	N/A	Yes	
168	7280	1	1	106B		Classroom 106 - Closet	W3	Flaking	12	No	No	N/A	Built in shelves with stored materials	No	
169	7280	1	1	106B		Classroom 106 - Closet	W4	Cracking, Holes, Flaking	16	No	No	N/A	N/A	Yes	
170	7280	1	1	107		Classroom 107	Ceiling	Flaking	11	No	No	N/A	N/A	No	
171	7280	1	1	107		Classroom 107	Floor	Debris	N/A	No	Paint Chips	5	N/A	No	
172	7280	1	1	107		Classroom 107	W1	Chipping, Hole	9	No	No	N/A	N/A	Yes	
173	7280	1	1	107		Classroom 107	W2	Chipping, Flaking	28	No	No	N/A	N/A	No	
174	7280	1	1	107		Classroom 107	W3	Chipping on wall and metal pipe	7	No	No	N/A	N/A	No	
175	7280	1	1	107		Classroom 107	W4	Chipping	6	No	No	N/A	N/A	No	

Franklin ES -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
176	7280	1	1	107A		Classroom 107 - Computer/Data Room	Ceiling	Cracking, Chipping	15	No	No	N/A	N/A	No	
177	7280	1	1	107A		Classroom 107 - Computer/Data Room	W3	Holes	2	No	No	N/A	N/A	Yes	
178	7280	1	1	107A		Classroom 107 - Computer/Data Room	W4	Cracking, Holes	3	No	No	N/A	N/A	Yes	
179	7280	1	1	H15		Hallway between Classrooms 101 and 105	Ceiling	Cracking, Flaking	39	No	No	N/A	N/A	No	
180	7280	1	1	H15		Hallway between Classrooms 101 and 105	W1	Cracking, Chipping on radiator covers, Hole, Flaking	10	No	No	N/A	N/A	Yes	
181	7280	1	1	H15		Hallway between Classrooms 101 and 105	W2	Chipping, Holes	13	No	No	N/A	N/A	Yes	
182	7280	1	1	H15		Hallway between Classrooms 101 and 105	W3	Cracking, Chipping, Flaking	7	No	No	N/A	N/A	No	
183	7280	1	1	H15		Hallway between Classrooms 101 and 105	W4	Cracking, Chipping, Hole	14	No	No	N/A	N/A	Yes	
184	7280	1	1	H14		Hallway between Classrooms 105 and 106	Ceiling	Cracking, Flaking	6	No	No	N/A	N/A	No	
185	7280	1	1	H14		Hallway between Classrooms 105 and 106	W1	Cracking, Chipping on wall, metal jackets, and radiator covers, Hole, Flaking	39	No	No	N/A	N/A	Yes	
186	7280	1	1	H14		Hallway between Classrooms 105 and 106	W3	Cracking, Chipping on wall, metal pipes, and metal lockers, Staple Holes, Flaking	70	No	No	N/A	N/A	Yes	
187	7280	1	1	H15A		Lobby Area next to Auditorium	Ceiling	Chipping, Spalling	2	Yes	No	N/A	N/A	No	
188	7280	1	1	H15A		Lobby Area next to Auditorium	W1	Chipping on wall, doors, doorframe, and radiator cover	17	No	No	N/A	N/A	No	
189	7280	1	1	H15A		Lobby Area next to Auditorium	W2	Cracking, Chipping	3	No	No	N/A	N/A	No	
190	7280	1	1	H15A		Lobby Area next to Auditorium	W3	Cracking, Chipping on doors, doorframe, and radiator cover	22	No	No	N/A	N/A	No	
191	7280	1	1	H15A		Lobby Area next to Auditorium	W4	Chipping	1	No	No	N/A	N/A	No	
192	7280	1	1	109		Main Office	Ceiling	Flaking	23	No	No	N/A	N/A	No	
193	7280	1	1	109		Main Office	W1	Cracking, Chipping	3	No	No	N/A	N/A	No	
194	7280	1	1	109		Main Office	W2	Cracking, Holes, paint has been stabilized, Flaking on wall and metal pipe	10	No	No	N/A	N/A	Yes	
195	7280	1	1	109		Main Office	W3	Chipping	1	No	No	N/A	N/A	No	
196	7280	1	1	109		Main Office	W4	Cracking, Chipping, Holes, Spalling	9	Yes	No	N/A	N/A	Yes	
197	7280	1	1	109A		Main Office - Storage Room	Ceiling	Cracking	2	No	No	N/A	N/A	No	

Franklin ES -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
198	7280	1	1	109A		Main Office - Storage Room	W1	Cracking, Gouge, Hole	6	No	No	N/A	Built in shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
199	7280	1	1	109A		Main Office - Storage Room	W2	Cracking, Hole	5	No	No	N/A	Built in shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
200	7280	1	1	109A		Main Office - Storage Room	W3	Cracking	3	No	No	N/A	Built in shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
201	7280	1	1	109A		Main Office - Storage Room	W4	Cracking	2	No	No	N/A	Built in shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
202	7280	1	1	110		Principal's Office	Ceiling	Cracking, Hole	2	No	No	N/A	N/A	Yes	
203	7280	1	1	110		Principal's Office	Floor	Debris	N/A	No	Debris	5	N/A	No	
204	7280	1	1	110		Principal's Office	W1	Cracking, Flaking	8	No	No	N/A	N/A	No	
205	7280	1	1	110		Principal's Office	W2	Cracking, Chipping on radiator cover, Flaking on wall and metal pipe	21	No	No	N/A	N/A	No	
206	7280	1	1	110		Principal's Office	W3	Cracking, Hole, Flaking	10	No	No	N/A	N/A	Yes	
207	7280	1	1	110		Principal's Office	W4	Cracking, Hole	2	No	No	N/A	N/A	Yes	
208	7280	1	1	110A		Principal's Office - Closet	Ceiling	Cracking	5	No	No	N/A	N/A	No	
209	7280	1	1	110A		Principal's Office - Closet	W1	Cracking, Hole	11	No	No	N/A	Shelves with stored materials	Yes	
210	7280	1	1	110A		Principal's Office - Closet	W2	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to shelves and stored materials
211	7280	1	1	110A		Principal's Office - Closet	W3	Cracking	20	No	No	N/A	Shelves with stored materials	No	Limited inspection due to shelves and stored materials
212	7280	1	1	110A		Principal's Office - Closet	W4	Cracking	20	No	No	N/A	Shelves with stored materials	No	Limited inspection due to shelves and stored materials
213	7280	1	1	110C		Principal's Office - Closet near Main Office Area	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
214	7280	1	1	110C		Principal's Office - Closet near Main Office Area	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
215	7280	1	1	110C		Principal's Office - Closet near Main Office Area	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
216	7280	1	1	110C		Principal's Office - Closet near Main Office Area	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
217	7280	1	1	110C		Principal's Office - Closet near Main Office Area	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Franklin ES -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
218	7280	1	1	110C		Principal's Office - Closet near Main Office Area	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
219	7280	1	1	111		Security Office - Stage Right Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
220	7280	1	1	111		Security Office - Stage Right Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
221	7280	1	1	111		Security Office - Stage Right Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
222	7280	1	1	111		Security Office - Stage Right Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
223	7280	1	1	111		Security Office - Stage Right Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
224	7280	1	1	111		Security Office - Stage Right Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
225	7280	1	1	112		Security Office - Stage Right Room - Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
226	7280	1	1	112		Security Office - Stage Right Room - Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
227	7280	1	1	112		Security Office - Stage Right Room - Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
228	7280	1	1	112		Security Office - Stage Right Room - Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
229	7280	1	1	112		Security Office - Stage Right Room - Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
230	7280	1	1	112		Security Office - Stage Right Room - Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
231	7280	1	1	108B		Stage Rear Hall (behind Stage)	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
232	7280	1	1	108B		Stage Rear Hall (behind Stage)	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
233	7280	1	1	108B		Stage Rear Hall (behind Stage)	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
234	7280	1	1	108B		Stage Rear Hall (behind Stage)	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
235	7280	1	1	108B		Stage Rear Hall (behind Stage)	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
236	7280	1	1	108B		Stage Rear Hall (behind Stage)	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
237	7280	1	1	S15		Stairwell near Classroom 101	Ceiling	Flaking	1	No	No	N/A	N/A	No	
238	7280	1	1	S15		Stairwell near Classroom 101	Floor	Chipping on floor and railings	43	No	No	N/A	N/A	No	
239	7280	1	1	S15		Stairwell near Classroom 101	W1	Cracking, Flaking	35	No	No	N/A	N/A	No	
240	7280	1	1	S15		Stairwell near Classroom 101	W2	Chipping on doors and doorframes	81	No	No	N/A	N/A	No	

Franklin ES -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
241	7280	1	1	S15		Stairwell near Classroom 101	W3	Cracking, Chipping, Flaking on wall and behind radiator	37	No	No	N/A	N/A	No	
242	7280	1	1	S15		Stairwell near Classroom 101	W4	Cracking, Chipping on doors and doorframe, Flaking, Significant Moisture Damage	54	Yes	No	N/A	N/A	Yes	Remove 15 LF ACPI
243	7280	1	1	S14		Stairwell near Classroom 103	Ceiling	Holes, Flaking	5	No	No	N/A	N/A	Yes	Remove 15 LF ACPI
244	7280	1	1	S14		Stairwell near Classroom 103	Floor	Chipping on floor and railings	45	No	No	N/A	N/A	No	
245	7280	1	1	S14		Stairwell near Classroom 103	W1	Cracking, Chipping	53	No	No	N/A	N/A	No	
246	7280	1	1	S14		Stairwell near Classroom 103	W2	Chipping on doors and doorframe	104	No	No	N/A	N/A	No	
247	7280	1	1	S14		Stairwell near Classroom 103	W3	Cracking, Chipping, Flaking	34	No	No	N/A	N/A	No	
248	7280	1	1	S14		Stairwell near Classroom 103	W4	Chipping on doors and doorframe, Significant Moisture Damage	52	Yes	No	N/A	N/A	Yes	
249	7280	1	1	S24		Stairwell near Classrooms 204 and 205	Ceiling	Cracking, Hole, paint has been stabilized, Flaking, Spalling	9	Yes	No	N/A	N/A	Yes	
250	7280	1	1	S24		Stairwell near Classrooms 204 and 205	Floor	Chipping on floor and railings	45	No	No	N/A	N/A	No	
251	7280	1	1	S24		Stairwell near Classrooms 204 and 205	W1	Cracking, Chipping	13	No	No	N/A	N/A	No	
252	7280	1	1	S24		Stairwell near Classrooms 204 and 205	W2	Chipping on doors and doorframe, Flaking	58	No	No	N/A	N/A	No	
253	7280	1	1	S24		Stairwell near Classrooms 204 and 205	W3	Cracking, Chipping, Gouges, Flaking, Spalling	20	Yes	No	N/A	N/A	Yes	
254	7280	1	1	S24		Stairwell near Classrooms 204 and 205	W4	Cracking, Chipping on wall and radiator cover, Flaking	15	No	No	N/A	N/A	No	
255	7280	1	1	S11		Stairwell next to Classroom 106	Floor	Chipping on floor and railings	38	No	No	N/A	N/A	No	
256	7280	1	1	S11		Stairwell next to Classroom 106	W3	Cracking, Chipping, Hole	17	No	No	N/A	N/A	Yes	
257	7280	1	1	113		Storage Room - Stage Left	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
258	7280	1	1	113		Storage Room - Stage Left	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
259	7280	1	1	106A		Storage Room near Classroom 106	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
260	7280	1	1	106A		Storage Room near Classroom 106	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
261	7280	1	1	106A		Storage Room near Classroom 106	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Franklin ES -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
262	7280	1	1	106A		Storage Room near Classroom 106	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
263	7280	1	1	106A		Storage Room near Classroom 106	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
264	7280	1	1	106A		Storage Room near Classroom 106	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
265	7280	1	1	113		Storage Room - Stage Left	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
266	7280	1	1	113		Storage Room - Stage Left	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
267	7280	1	1	113		Storage Room - Stage Left	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
268	7280	1	1	113		Storage Room - Stage Left	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
269	7280	1	0	2		Classroom 2	Ceiling	Cracking, Flaking	26	No	No	N/A	N/A	No	
270	7280	1	0	2		Classroom 2	W1	Chipping, Flaking	15	No	No	N/A	N/A	No	
271	7280	1	0	2		Classroom 2	W3	Flaking, Efflorescence	6	Yes	No	N/A	N/A	Yes	
272	7280	1	0	2		Classroom 2	W4	Cracking, Chipping, Flaking	17	No	No	N/A	N/A	No	
273	7280	1	0	002B		Classroom 2 - Storage Room	Ceiling	Cracking	2	No	No	N/A	N/A	No	
274	7280	1	0	002B		Classroom 2 - Storage Room	W1	Hole	1	No	No	N/A	N/A	No	
275	7280	1	0	002B		Classroom 2 - Storage Room	W2	Debris	N/A	No	No	N/A	Shelves, Stored Materials	No	
276	7280	1	0	002B		Classroom 2 - Storage Room	W3	Chipping, Flaking	10	No	No	N/A	Shelves, Stored Materials	No	
277	7280	1	0	001C		Conference Room in Room 1 Suite Area	Ceiling	Cracking, Holes, Spalling	11	Yes	No	N/A	N/A	Yes	
278	7280	1	0	001C		Conference Room in Room 1 Suite Area	Floor	Flaking	1	No	No	N/A	N/A	No	
279	7280	1	0	001C		Conference Room in Room 1 Suite Area	W1	Chipping	15	No	No	N/A	N/A	No	
280	7280	1	0	001C		Conference Room in Room 1 Suite Area	W2	Hole	2	No	No	N/A	N/A	Yes	
281	7280	1	0	001C		Conference Room in Room 1 Suite Area	W3	Flaking	2	No	No	N/A	N/A	No	
282	7280	1	0	001C		Conference Room in Room 1 Suite Area	W4	Chipping	3	No	No	N/A	N/A	No	
283	7280	1	0	001B		Counselor's Office at end of Hall in Room 1 Suite Area	W1	Chipping on wall and doorframe, Flaking	32	No	No	N/A	N/A	No	

Franklin ES -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
284	7280	1	0	001B		Counselor's Office at end of Hall in Room 1 Suite Area	W2	Cracking, Flaking	2	No	No	N/A	N/A	No	
285	7280	1	0	001B		Counselor's Office at end of Hall in Room 1 Suite Area	W3	Chipping, Hole, Flaking	4	No	No	N/A	N/A	No	
286	7280	1	0	001B		Counselor's Office at end of Hall in Room 1 Suite Area	W4	Chipping	4	No	No	N/A	N/A	No	
287	7280	1	0	1		Counselor's Office next to Conference Room in Room 1 Suite Area	Ceiling	Spalling	3	No	No	N/A	N/A	Yes	
288	7280	1	0	1		Counselor's Office next to Conference Room in Room 1 Suite Area	W1	Chipping on wall and doorframe	13	No	No	N/A	Posters	No	
289	7280	1	0	1		Counselor's Office next to Conference Room in Room 1 Suite Area	W2	Chipping, Gouge	4	No	No	N/A	N/A	Yes	
290	7280	1	0	1		Counselor's Office next to Conference Room in Room 1 Suite Area	W4	Chipping, Gouge	5	No	No	N/A	N/A	Yes	
291	7280	1	0	19		Former Boy's Restroom (used for Storage)	W1	Chipping on doorframe	10	No	No	N/A	N/A	No	
292	7280	1	0	10		Former Girl's Restroom now used for Storage	Ceiling	Holes, Flaking on ceiling and radiators	73	No	No	N/A	N/A	No	
293	7280	1	0	10		Former Girl's Restroom now used for Storage	W1	Chipping on doorframe	10	No	No	N/A	N/A	No	
294	7280	1	0	12		Gymnasium	Ceiling	Flaking	430	No	No	N/A	N/A	No	
295	7280	1	0	12		Gymnasium	Floor	Flaking on grates	282	No	Debris	30	N/A	No	
296	7280	1	0	12		Gymnasium	W1	Cracking, Hole, Spalling	15	Yes	No	N/A	N/A	Yes	
297	7280	1	0	12		Gymnasium	W2	Chipping, Flaking	10	No	No	N/A	N/A	No	
298	7280	1	0	12		Gymnasium	W4	Chipping on metal pipe and backboard, Flaking	24	No	No	N/A	N/A	No	
299	7280	1	0	13		Gymnasium Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
300	7280	1	0	13		Gymnasium Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
301	7280	1	0	13		Gymnasium Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
302	7280	1	0	13		Gymnasium Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
303	7280	1	0	13		Gymnasium Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
304	7280	1	0	13		Gymnasium Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Franklin ES -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
305	7280	1	0	14		Gymnasium Storage Room (leads to Stage Area)	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
306	7280	1	0	14		Gymnasium Storage Room (leads to Stage Area)	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
307	7280	1	0	14		Gymnasium Storage Room (leads to Stage Area)	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
308	7280	1	0	14		Gymnasium Storage Room (leads to Stage Area)	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
309	7280	1	0	14		Gymnasium Storage Room (leads to Stage Area)	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
310	7280	1	0	14		Gymnasium Storage Room (leads to Stage Area)	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
311	7280	1	0	H01		Hallway from Boiler Room Door to Stairwell past Fan Room	Ceiling	Flaking on ceiling and metal duct	101	No	No	N/A	N/A	No	1 SF ACM debris on duct across from Room 3
312	7280	1	0	H01		Hallway from Boiler Room Door to Stairwell past Fan Room	Floor	Chipping	1	No	No	N/A	N/A	No	
313	7280	1	0	H01		Hallway from Boiler Room Door to Stairwell past Fan Room	W1	Flaking on wall and metal jackets	20	No	No	N/A	N/A	No	
314	7280	1	0	H01		Hallway from Boiler Room Door to Stairwell past Fan Room	W2	Chipping, Holes, Flaking	15	No	No	N/A	N/A	No	
315	7280	1	0	H01		Hallway from Boiler Room Door to Stairwell past Fan Room	W4	Chipping, Holes, Flaking	40	No	No	N/A	N/A	No	
316	7280	1	0	H02A		Hallway from Hall near former Boy's Restroom (now used for storage) to Gymnasium	Ceiling	Flaking, Spalling, Significant Moisture Damage	17	Yes	No	N/A	N/A	Yes	
317	7280	1	0	H02A		Hallway from Hall near former Boy's Restroom (now used for storage) to Gymnasium	Floor	Chipping	52	No	No	N/A	N/A	No	

Franklin ES -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
318	7280	1	0	11		Hallway from Hall near Former Girl's Restroom to Gymnasium	Ceiling	Significant Moisture Damage	30	Yes	No	N/A	N/A	Yes	
319	7280	1	0	11		Hallway from Hall near Former Girl's Restroom to Gymnasium	W1	Cracking, Flaking	11	No	No	N/A	N/A	No	
320	7280	1	0	11		Hallway from Hall near Former Girl's Restroom to Gymnasium	W2	Efflorescence	4	Yes	No	N/A	N/A	Yes	
321	7280	1	0	11		Hallway from Hall near Former Girl's Restroom to Gymnasium	W4	Flaking	40	No	No	N/A	N/A	No	
322	7280	1	0	H02A		Hallway from Hall near former Boy's Restroom (now used for storage) to Gymnasium	W2	Flaking, Significant Moisture Damage	62	Yes	No	N/A	N/A	Yes	
323	7280	1	0	H02A		Hallway from Hall near former Boy's Restroom (now used for storage) to Gymnasium	W3	Flaking	8	No	No	N/A	N/A	No	
324	7280	1	0	H02A		Hallway from Hall near former Boy's Restroom (now used for storage) to Gymnasium	W4	Chipping, Efflorescence	3	Yes	No	N/A	N/A	Yes	
325	7280	1	0	H02		Hallway from Room 1 (Counselor Suite) to Former Boy's Restroom (Storage)	Ceiling	Cracking, Chipping on metal duct, Flaking on ceiling and metal duct	68	No	No	N/A	N/A	No	
326	7280	1	0	H02		Hallway from Room 1 (Counselor Suite) to Former Boy's Restroom (Storage)	W1	Chipping on metal pipe, Holes, Flaking on wall and asbestos pipe insulation	48	No	No	N/A	N/A	No	
327	7280	1	0	H02		Hallway from Room 1 (Counselor Suite) to Former Boy's Restroom (Storage)	W2	Chipping, Holes	3	No	No	N/A	N/A	No	

Franklin ES -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
328	7280	1	0	H02		Hallway from Room 1 (Counselor Suite) to Former Boy's Restroom (Storage)	W3	Holes, Flaking on wall and metal pipes	25	No	No	N/A	N/A	No	
329	7280	1	0	H02		Hallway from Room 1 (Counselor Suite) to Former Boy's Restroom (Storage)	W4	Cracking, Chipping on doors and doorframe, Hole	29	No	No	N/A	N/A	No	
330	7280	1	0	H03		Hallway from Stairwell next to Fan Room to Element 2	Ceiling	Holes, Flaking	26	No	No	N/A	N/A	No	
331	7280	1	0	H03		Hallway from Stairwell next to Fan Room to Element 2	W1	Chipping on metal jackets, Flaking	34	No	No	N/A	N/A	No	
332	7280	1	0	H03		Hallway from Stairwell next to Fan Room to Element 2	W3	Flaking	28	No	No	N/A	N/A	No	
333	7280	1	0	001E		Hallway in Room 1 Suite Area	Ceiling	Flaking on metal duct	4	No	No	N/A	N/A	No	
334	7280	1	0	001E		Hallway in Room 1 Suite Area	W3	Chipping	2	No	No	N/A	N/A	No	
335	7280	1	0	001E		Hallway in Room 1 Suite Area	W4	Gouge	1	No	No	N/A	N/A	Yes	
336	7280	1	0	001E		Hallway in Room 1 Suite Area	W1	Holes, Flaking	4	No	No	N/A	N/A	No	
337	7280	1	0	001E		Hallway in Room 1 Suite Area	W2	Chipping	1	No	No	N/A	N/A	No	
338	7280	1	0	3		Room 3 - Learning Support Office	Ceiling	Cracking, Flaking	11	No	No	N/A	N/A	No	
339	7280	1	0	3		Room 3 - Learning Support Office	Floor	Debris	N/A	No	Debris	5	N/A	No	
340	7280	1	0	3		Room 3 - Learning Support Office	W1	Cracking, Holes	6	No	No	N/A	N/A	Yes	
341	7280	1	0	3		Room 3 - Learning Support Office	W2	Chipping, Flaking	25	No	No	N/A	N/A	No	
342	7280	1	0	3		Room 3 - Learning Support Office	W3	Cracking, Chipping on wall and radiator, Holes	14	No	No	N/A	N/A	Yes	
343	7280	1	0	3		Room 3 - Learning Support Office	W4	Chipping, Coat hooks pulling off wall	14	No	No	N/A	N/A	Yes	
344	7280	1	0	001D		Speech Language Therapy Office next to Conference Room in Room 1 Suite Area	Ceiling	Cracking, Chipping	6	No	No	N/A	N/A	No	

Franklin ES -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
345	7280	1	0	001D		Speech Language Therapy Office next to Conference Room in Room 1 Suite Area	W1	Chipping, Hole, Flaking	3	No	No	N/A	N/A	No	
346	7280	1	0	001D		Speech Language Therapy Office next to Conference Room in Room 1 Suite Area	W2	Cracking	10	No	No	N/A	N/A	No	
347	7280	1	0	001D		Speech Language Therapy Office next to Conference Room in Room 1 Suite Area	W3	Chipping, Flaking	20	No	No	N/A	N/A	No	
348	7280	1	0	001D		Speech Language Therapy Office next to Conference Room in Room 1 Suite Area	W4	Chipping, Flaking	16	No	No	N/A	N/A	No	
349	7280	1	0	S01		Stairwell near former Boy's Restroom (now used for storage)	Ceiling	Cracking, Flaking	40	No	No	N/A	N/A	No	
350	7280	1	0	S01		Stairwell near former Boy's Restroom (now used for storage)	Floor	Debris	N/A	No	Debris	2	N/A	No	
351	7280	1	0	S01		Stairwell near former Boy's Restroom (now used for storage)	W1	Flaking on wall and railings	10	No	No	N/A	N/A	No	
352	7280	1	0	S01		Stairwell near former Boy's Restroom (now used for storage)	W2	Flaking	15	No	No	N/A	N/A	No	
353	7280	1	0	S01		Stairwell near former Boy's Restroom (now used for storage)	W3	Chipping, Flaking on railings	9	No	No	N/A	N/A	No	
354	7280	1	0	S03		Stairwell next to Fan Room	Ceiling	Cracking	2	No	No	N/A	N/A	No	
355	7280	1	0	S03		Stairwell next to Fan Room	W1	Hole	1	No	No	N/A	N/A	Yes	
356	7280	1	0	S03		Stairwell next to Fan Room	W2	Cracking	6	No	No	N/A	N/A	No	
357	7280	1	0	S03		Stairwell next to Fan Room	W4	Cracking	3	No	No	N/A	N/A	No	
358	7280	1	0	S02		Stairwell next to Room 1 (Counselor Suite)	Ceiling	Cracking, Flaking	3	No	No	N/A	N/A	No	
359	7280	1	0	S02		Stairwell next to Room 1 (Counselor Suite)	W1	Cracking, Holes, paint has been stabilized	5	No	No	N/A	N/A	Yes	

Franklin ES -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
360	7280	1	0	S02		Stairwell next to Room 1 (Counselor Suite)	W2	Chipping on doors and doorframe, Holes	27	No	No	N/A	N/A	Yes	
361	7280	1	0	S02		Stairwell next to Room 1 (Counselor Suite)	W3	Cracking	1	No	No	N/A	N/A	No	
362	7280	1	0	001F		Storage Closet in Hallway in Room 1 Suite Area	Ceiling	Cracking	5	No	No	N/A	Shelves, Stored Materials	No	
363	7280	1	0	001F		Storage Closet in Hallway in Room 1 Suite Area	Floor	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
364	7280	1	0	001F		Storage Closet in Hallway in Room 1 Suite Area	W1	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
365	7280	1	0	001F		Storage Closet in Hallway in Room 1 Suite Area	W2	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
366	7280	1	0	001F		Storage Closet in Hallway in Room 1 Suite Area	W3	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
367	7280	1	0	001F		Storage Closet in Hallway in Room 1 Suite Area	W4	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
368	7280	1	0	003A		Storage Closet in Hallway next to Room 3	W2	Chipping	1	No	No	N/A	Stored Materials	No	
369	7280	1	0	003A		Storage Closet in Hallway next to Room 3	W3	Cracking	5	No	No	N/A	Stored Materials	No	