

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	2160	1	4	CH		Center Hallway	Ceiling	Flaking	200	Y	Y - Floor	10			
2	2160	1	4	CH		Center Hallway	W1	Flaking	10	N					
3	2160	1	4	CH		Center Hallway	W3	Flaking	10	N	Y - Floor	10			
4	2160	1	4	400		Classroom 400	Ceiling	Flaking	225	Y	Y	225			
5	2160	1	4	400		Classroom 400	W2	Flaking	2	N					
6	2160	1	4	401		Classroom 401	Ceiling	Flaking	50	Y	Y - Floor	100	Supplies	Y	
7	2160	1	4	401		Classroom 401	W1	Flaking	2	Y					
8	2160	1	4	401		Classroom 401	W2	Flaking	2	Y					
9	2160	1	4	401		Classroom 401	W3	Flaking	2	Y					
10	2160	1	4	401		Classroom 401	W4	Flaking	2	Y					
11	2160	1	4	401C		Classroom 401 Closet	Ceiling	Flaking	10	Y					
12	2160	1	4	401C		Classroom 401 Closet	W1	Flaking	20	Y	Y - Floor	10	Many Supplies		
13	2160	1	4	401C		Classroom 401 Closet	W2	Flaking	20	Y					
14	2160	1	4	401C		Classroom 401 Closet	W3	Flaking	10	Y					
15	2160	1	4	401C		Classroom 401 Closet	W4	Flaking	10	Y					
16	2160	1	4	402		Classroom 402	Ceiling	Flaking, Significant Moisture Damage	200	Y	Y - Floor	500		Y	
17	2160	1	4	402		Classroom 402	W1	Flaking	10	Y					
18	2160	1	4	402		Classroom 402	W2	Flaking	10	Y					
19	2160	1	4	402		Classroom 402	W3	Flaking	20	Y					
20	2160	1	4	402		Classroom 402	W4	Flaking	10	Y					
21	2160	1	4	403		Classroom 403	Ceiling	Flaking, Significant Moisture Damage	50	Y	Y - Floor	50		Y	
22	2160	1	4	403		Classroom 403	W1	Flaking	10	Y					
23	2160	1	4	403		Classroom 403	W2	Flaking	10	Y					
24	2160	1	4	403		Classroom 403	W3	Flaking	10	Y					
25	2160	1	4	403		Classroom 403	W4	Flaking	10	Y					
26	2160	1	4	402B		Classroom 403 Closet	Ceiling	Flaking	5	N					
27	2160	1	4	402B		Classroom 403 Closet	W1	Flaking	5	N	Y - Floor	10	Supplies		
28	2160	1	4	402B		Classroom 403 Closet	W2	Flaking	5	N					
29	2160	1	4	402B		Classroom 403 Closet	W3	Flaking	5	N					
30	2160	1	4	402B		Classroom 403 Closet	W4	Flaking	5	N					
31	2160	1	4	H41 A, B, & C		Hallway in Front of Classroom 400	Ceiling	Flaking	500	Y				N	
32	2160	1	4	H41 A, B, & C		Hallway in Front of Classroom 400	W1	Flaking	200	Y	Y	500		N	
33	2160	1	4	H41 A, B, & C		Hallway in Front of Classroom 400	W3	Flaking, Efflorescence, Significant Moisture Damage	1000	Y				Y	
34	2160	1	4	H43E		Left Southeast Foyer Closet - Corner of 3rd and McKean Streets	Ceiling	Flaking	50	Y	Y - Floor	50		Y	
35	2160	1	4	H43E		Left Southeast Foyer Closet - Corner of 3rd and McKean Streets	W1	Flaking	50	Y				Y	

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
36	2160	1	4	H43E		Left Southeast Foyer Closet - Corner of 3rd and McKean Streets	W2	Flaking	50					Y	
37	2160	1	4	H43E		Left Southeast Foyer Closet - Corner of 3rd and McKean Streets	W3	Flaking	50					Y	
38	2160	1	4	H43E		Left Southeast Foyer Closet - Corner of 3rd and McKean Streets	W4	Flaking	50					Y	
39	2160	1	4	H41		North Hallway along Mifflin Street	Ceiling	Flaking	500	Y				Y	
40	2160	1	4	H41		North Hallway along Mifflin Street	W2	Flaking, Efflorescence, Significant Moisture Damage	1000	Y	Y - Floor	500		Y	
41	2160	1	4	H41		North Hallway along Mifflin Street	W4	Flaking	500	Y				Y	
42	2160	1	4	403A		Northeast Restroom - Corner of 3rd and Mifflin Streets	Ceiling	Flaking, Significant Moisture Damage	200	Y	Y	10		Y	
43	2160	1	4	403		Northeast Restroom - Corner of 3rd and Mifflin Streets	W1	Flaking, Efflorescence, Significant Moisture Damage	40	Y	Y	10		Y	
44	2160	1	4	403		Northeast Restroom - Corner of 3rd and Mifflin Streets	W2	Flaking	40	Y	Y	10		Y	
45	2160	1	4	403		Northeast Restroom - Corner of 3rd and Mifflin Streets	W3	Flaking	100	N	Y	5		Y	
46	2160	1	4	403A		Northeast Restroom - Corner of 3rd and Mifflin Streets	W4	Flaking	20	Y	Y	10		Y	
47	2160	1	4	H43D		Right Southeast Foyer Closet - Corner of 3rd and McKean Streets	Ceiling	Flaking	20	Y	Y - Floor	10	Many Supplies	Y	
48	2160	1	4	H43D		Right Southeast Foyer Closet - Corner of 3rd and McKean Streets	W1	Flaking	10					Y	
49	2160	1	4	H43D		Right Southeast Foyer Closet - Corner of 3rd and McKean Streets	W2	Flaking	10					Y	
50	2160	1	4	H43D		Right Southeast Foyer Closet - Corner of 3rd and McKean Streets	W3	Flaking	10					Y	
51	2160	1	4	H43D		Right Southeast Foyer Closet - Corner of 3rd and McKean Streets	W4	Flaking	10					Y	
52	2160	1	4	S44		South Fire Tower along McKean Street	Ceiling	Flaking, Holes, Significant Moisture Damage	310	Y					
53	2160	1	4	S44		South Fire Tower along McKean Street	Floor	Chipping	210	Y	Y	150			

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
54	2160	1	4	H43		South Hallway along McKean Street	Ceiling	Flaking, Significant Moisture Damage	1000	Y	Y	1000		Y	
55	2160	1	4	H43		South Hallway along McKean Street	W1	Flaking, Significant Moisture Damage	10	Y				Y	
56	2160	1	4	H43		South Hallway along McKean Street	W2	Flaking, Significant Moisture Damage	200	Y				Y	
57	2160	1	4	H43		South Hallway along McKean Street	W3	Flaking, Significant Moisture Damage	10	Y				Y	
58	2160	1	4	H43		South Hallway along McKean Street	W4	Flaking, Significant Moisture Damage	200	Y				Y	
59	2160	1	4	H43B		Southeast Foyer - Corner of 3rd and McKean Streets	Ceiling	Flaking	500	Y				Y	
60	2160	1	4	H43B		Southeast Foyer - Corner of 3rd and McKean Streets	W1	Flaking	5						
61	2160	1	4	H43B		Southeast Foyer - Corner of 3rd and McKean Streets	W2	Flaking	40	Y					
62	2160	1	4	H43B		Southeast Foyer - Corner of 3rd and McKean Streets	W3	Flaking	250						
63	2160	1	4	H43B		Southeast Foyer - Corner of 3rd and McKean Streets	W4	Flaking	5						
64	2160	1	4	402B		Southeast Restroom - Corner of 3rd and McKean Streets	Ceiling	Flaking	100	Y	Y - Floor	200		Y	
65	2160	1	4	402B		Southeast Restroom - Corner of 3rd and McKean Streets	W1	Flaking	20						
66	2160	1	4	402B		Southeast Restroom - Corner of 3rd and McKean Streets	W2	Flaking	20	Y					
67	2160	1	4	402B		Southeast Restroom - Corner of 3rd and McKean Streets	W3	Flaking	20						
68	2160	1	4	402B		Southeast Restroom - Corner of 3rd and McKean Streets	W4	Flaking	20						
69	2160	1	4	S43		Southeast Stairwell - Corner of 3rd and McKean Streets	Ceiling	Flaking	100	Y					
70	2160	1	4	S43		Southeast Stairwell - Corner of 3rd and McKean Streets	Floor	Flaking	100	Y					
71	2160	1	4	S43		Southeast Stairwell - Corner of 3rd and McKean Streets	W1	Flaking	300	Y	Y - Floor	100			
72	2160	1	4	S43		Southeast Stairwell - Corner of 3rd and McKean Streets	W2	Flaking	50						
73	2160	1	3	318C		Boy's Restroom	Ceiling	Flaking	50						
74	2160	1	3	318C		Boy's Restroom	W3	Flaking - Pipe	10						
75	2160	1	3	H32		Center Hallway	W1	Flaking	200	Y					
76	2160	1	3	H32		Center Hallway	W3	Flaking	200	Y	Y - Sills, Floors	10		Y	
77	2160	1	3	301		Classroom 301	W1	Flaking - Baseboard	10						
78	2160	1	3	301		Classroom 301	W2	Flaking	20						

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
79	2160	1	3	301		Classroom 301	W3	Flaking - Wall, Baseboard, Sill	15						
80	2160	1	3	301		Classroom 301	W4	Cracking - Below Blackboard	10						
81	2160	1	3	301A		Classroom 301 Closet	W2	Flaking, Spalling below Window	10	Y			Supplies		
82	2160	1	3	301B		Classroom 301 Closet	W4	Flaking	10						
83	2160	1	3	302		Classroom 302	W1	Flaking - Door Casing, Wall	20						
84	2160	1	3	302		Classroom 302	W2	Flaking - Door Casing, Wall	10						
85	2160	1	3	302		Classroom 302	W3	Flaking - Efflorescence - Wall and Sill	50	Y					
86	2160	1	3	302		Classroom 302	W4	Flaking - Efflorescence	100	Y			Computers, Desks		
87	2160	1	3	302A		Classroom 302 Closet	W1	Flaking	20						
88	2160	1	3	302A		Classroom 302 Closet	W2	Flaking, Efflorescence	50	Y	Y - on Contents	5	Many Supplies		
89	2160	1	3	302A		Classroom 302 Closet	W3	Flaking	10						
90	2160	1	3	302A		Classroom 302 Closet	W4	Flaking	20						
91	2160	1	3	303		Classroom 303	W1	Flaking - Wall, Doors, Door Casings	20						
92	2160	1	3	303		Classroom 303	W2	Flaking	40	Y					
93	2160	1	3	303		Classroom 303	W3	Flaking - Wall, Sill, Baseboard, Pipe	250	Y					
94	2160	1	3	303		Classroom 303	W4	Flaking	10						
95	2160	1	3	303A		Classroom 303 Closet	Ceiling	Flaking, Efflorescence	10	Y					
96	2160	1	3	303A		Classroom 303 Closet	W1	Flaking, Efflorescence	10	Y					
97	2160	1	3	303A		Classroom 303 Closet	W4	Flaking, Efflorescence	10	Y					
98	2160	1	3	304		Classroom 304	W1	Flaking - Wall, Door, Casing, Chalk Ledge, Baseboard	150	Y	Y - Floor	10			
99	2160	1	3	304		Classroom 304	W2	Flaking - Wall, Closet Doors	20						
100	2160	1	3	304		Classroom 304	W3	Flaking - Wall, Sill, Baseboard, Pipe	200	Y	Y - Floor, Sill	5		Y	
101	2160	1	3	304		Classroom 304	W4	Flaking - Wall	10						
102	2160	1	3	304B		Classroom 304 Closet	Ceiling	Flaking	20	Y	Y - Floor	5			
103	2160	1	3	304A		Classroom 304 Closet	W1	Flaking - Baseboard	5						
104	2160	1	3	304A		Classroom 304 Closet	W2	Flaking - Baseboard	5						
105	2160	1	3	304A		Classroom 304 Closet	W3	Flaking - Baseboard	5						
106	2160	1	3	304B		Classroom 304 Closet	W4	Flaking - Baseboard	5						
107	2160	1	3	305		Classroom 305	Ceiling	Flaking	5	Y					
108	2160	1	3	305A		Classroom 305 Closet	W1	Flaking	10						
109	2160	1	3	306		Classroom 306	W1	Flaking - Walls, Doors, Baseboards	40						
110	2160	1	3	306		Classroom 306	W2	Flaking	20						
111	2160	1	3	306		Classroom 306	W3	Flaking - Pipes, Windows	30						
112	2160	1	3	306		Classroom 306	W4	Flaking	10						
113	2160	1	3	306A		Classroom 306 Closet	W1	Flaking	30				Supplies		
114	2160	1	3	307		Classroom 307	W1	Flaking - Doors, and Below Cabinet by Wall 4	15						

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
115	2160	1	3	307A		Classroom 307 Closet	W1	Flaking	20						
116	2160	1	3	307A		Classroom 307 Closet	W4	Flaking	10				Supplies		
117	2160	1	3	308		Classroom 308	Ceiling	Flaking - on Drop Ceiling and Track	50	Y	Y - Desks, Floor,	30			
118	2160	1	3	308A		Classroom 308 Closet	W1	Flaking	10				Supplies		
119	2160	1	3	308A		Classroom 308 Closet	W2	Flaking	10						
120	2160		3	309		Classroom 309	W1	Flaking - Door, Below Cabinet, Closet Doors	10						
121	2160	1	3	309		Classroom 309	W2	Flaking - Chalk Ledge	5						
122	2160	1	3	309		Classroom 309	W3	Spalling by W4	10	Y					
123	2160	1	3	309B		Classroom 309 Closet	Ceiling	Flaking	10						
124	2160	1	3	309A		Classroom 309 Closet	W2	Flaking - Walls & Shelves	50		Y - Floor	20			
125	2160	1	3	309A		Classroom 309 Closet	W3	Flaking	10						
126	2160	1	3	309B		Classroom 309 Closet	W4	Flaking , Spalling	20	Y					
127	2160	1	3	310		Classroom 310	W1	Flaking - Walls, Doors	10						
128	2160	1	3	310		Classroom 310	W3	Flaking, Spalling	100	Y	Y - Floor	10			
129	2160	1	3	310C		Classroom 310 Closet	W1	Flaking	40						
130	2160	1	3	311		Classroom 311	W1	Flaking - Wall, Door	20						
131	2160	1	3	311		Classroom 311	W2	Flaking	10						
132	2160	1	3	311		Classroom 311	W3	Flaking - By Window and Sills	50		Y - Sills	10			
133	2160	1	3	311		Classroom 311	W4	Flaking	10						
134	2160	1	3	311A		Classroom 311 Closet	Ceiling	No Access							Inspection Needed
135	2160	1	3	311A		Classroom 311 Closet	Floor	No Access							Inspection Needed
136	2160	1	3	311A		Classroom 311 Closet	W1	No Access							Inspection Needed
137	2160	1	3	311A		Classroom 311 Closet	W2	No Access							Inspection Needed
138	2160	1	3	311A		Classroom 311 Closet	W3	No Access							Inspection Needed
139	2160	1	3	311A		Classroom 311 Closet	W4	No Access							Inspection Needed
140	2160	1	3	312		Classroom 312	W3	Flaking - Pipe	10						
141	2160	1	3	312C		Classroom 312 Closet	W2	Flaking	10						
142	2160	1	3	313		Classroom 313	Ceiling	Flaking, Efflorescence	50	Y					
143	2160	1	3	313		Classroom 313	W1	Flaking	20						
144	2160	1	3	313		Classroom 313	W2	Flaking	10						
145	2160	1	3	313		Classroom 313	W3	Flaking, Efflorescence	100	Y					
146	2160	1	3	313		Classroom 313	W4	Flaking	20						
147	2160	1	3	313A		Classroom 313 Closet	Ceiling	No Access							Inspection Needed
148	2160	1	3	313A		Classroom 313 Closet	Floor	No Access							Inspection Needed
149	2160	1	3	313B		Classroom 313 Closet	W1	Flaking	20				Supplies		
150	2160	1	3	313A		Classroom 313 Closet	W1	No Access							Inspection Needed

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
151	2160	1	3	313A		Classroom 313 Closet	W2	No Access							Inspection Needed
152	2160	1	3	313A		Classroom 313 Closet	W3	No Access							Inspection Needed
153	2160	1	3	313A		Classroom 313 Closet	W4	No Access							Inspection Needed
154	2160	1	3	314		Classroom 314	Ceiling	Flaking - By Windows	10	Y					
155	2160	1	3	315		Classroom 315	W1	Flaking - Wall and Doors	10						
156	2160	1	3	315		Classroom 315	W3	Flaking	20						
157	2160	1	3	315		Classroom 315	W4	Flaking	10						
158	2160	1	3	316		Classroom 316	Ceiling	Flaking - By Entrance	40	Y	Y - Floor	10			
159	2160	1	3	316		Classroom 316	W1	Flaking - Walls, Doors, Baseboard	50						
160	2160	1	3	316		Classroom 316	W2	Flaking - Wall, Chalk Ledge, Baseboard	50						
161	2160	1	3	316		Classroom 316	W3	Flaking - Wall, Pipe, Radiator	50						
162	2160	1	3	316		Classroom 316	W4	Flaking - Wall	50						
163	2160	1	3	316A		Classroom 316 Closet	Ceiling	Flaking	10						
164	2160	1	3	316A		Classroom 316 Closet	W2	Flaking	5						
165	2160	1	3	316A		Classroom 316 Closet	W3	Flaking	5						
166	2160	1	3	316A		Classroom 316 Closet	W4	Flaking	5						
167	2160	1	3	317		Classroom 317	Ceiling	Flaking, Efflorescence	100	Y					
168	2160	1	3	317		Classroom 317	W1	Flaking	100						
169	2160	1	3	317		Classroom 317	W2	Flaking - Chalk Ledge, Baseboard	100						
170	2160	1	3	317		Classroom 317	W3	Flaking, Efflorescence	200	Y	Y - floor	10			
171	2160	1	3	317		Classroom 317	W4	Flaking	100						
172	2160	1	3	317A		Classroom 317 Closet	W2	Flaking	10						
173	2160	1	3	317A		Classroom 317 Closet	W3	Flaking	10				Supplies		
174	2160	1	3	317A		Classroom 317 Closet	W4	Flaking	10						
175	2160	1	3	318		Classroom 318	Ceiling	Flaking	50	Y					
176	2160	1	3	318		Classroom 318	W1	Flaking	100		Y - Floor	10			
177	2160	1	3	318		Classroom 318	W2	Flaking	100						
178	2160	1	3	318		Classroom 318	W3	Flaking	200	Y					
179	2160	1	3	318		Classroom 318	W4	Flaking	100						
180	2160	1	3	318A		Classroom 318 Closet	W3	Flaking	10						
181	2160	1	3	319		Classroom 319	Ceiling	Flaking - By Window	10						
182	2160	1	3	319		Classroom 319	W1	Flaking	50						
183	2160	1	3	319		Classroom 319	W2	Flaking	50						
184	2160	1	3	319		Classroom 319	W3	Flaking - Wall, Radiator, Pipe	100						
185	2160	1	3	319		Classroom 319	W4	Flaking	50						
186	2160	1	3	319A		Classroom 319 Closet	W2	Flaking	10						
187	2160	1	3	319A		Classroom 319 Closet	W3	Flaking, Efflorescence - Wall, Pipe	50		Y - Floor	10	Many Supplies		
188	2160	1	3	319A		Classroom 319 Closet	W4	Flaking	10						
189	2160	1	3	320		Classroom 320	Ceiling	Flaking - By Windows	20						
190	2160	1	3	320		Classroom 320	W1	Flaking - Wall, Door	20						
191	2160	1	3	320		Classroom 320	W2	Flaking - Wall, Door	20						

Furness -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
192	2160	1	3	320		Classroom 320	W3	Flaking - Radiator, Sills, Walls	50	Y					
193	2160	1	3	320		Classroom 320	W4	Flaking - Doors	20						
194	2160	1	3	321		Classroom 321	W1	Flaking	100						
195	2160	1	3	321		Classroom 321	W2	Flaking	100						
196	2160	1	3	321		Classroom 321	W3	Flaking - Wall, Pipe, Radiator, Sills	100	Y					
197	2160	1	3	321		Classroom 321	W4	Flaking	50						
198	2160	1	3	304C		Girl's Restroom	Ceiling	Flaking	100	Y					
199	2160	1	3	304C		Girl's Restroom	W3	Flaking - Pipe and Radiator	20						
200	2160	1	3	S31		North Fire Tower	Ceiling	Holes, Gouges, Flaking, Significant Moisture Damage	310	Y					
201	2160	1	3	S31		North Fire Tower	Floor	Cracking, Chipping, Debris	210	Y	Y - Floor	200			
202	2160	1	3	H31		North Hallway along Mifflin Street	W2	Flaking	1,000	Y					
203	2160	1	3	H31		North Hallway along Mifflin Street	W4	Flaking	10						
204	2160	1	3	312A		Northeast Restroom - Corner of 3rd and Mifflin Streets	Ceiling	Flaking	50	Y					
205	2160	1	3	312B		Northeast Restroom Entrance Foyer - Corner of 3rd and Mifflin Streets	Ceiling	Flaking	50	Y					
206	2160	1	3	312B		Northeast Restroom Entrance Foyer - Corner of 3rd and Mifflin Streets	W1	Flaking - Door	10						
207	2160	1	3	312B		Northeast Restroom Entrance Foyer - Corner of 3rd and Mifflin Streets	W2	Flaking	10						
208	2160	1	3	312B		Northeast Restroom Entrance Foyer - Corner of 3rd and Mifflin Streets	W3	Flaking	10						
209	2160	1	3	312B		Northeast Restroom Entrance Foyer - Corner of 3rd and Mifflin Streets	W4	Flaking	10						
210	2160	1	3	S32		Northeast Stairwell - Corner of 3rd and Mifflin Streets	W1	Flaking	50	Y					
211	2160	1	3	311B		Room Between 311 & 312	W1	Flaking	10						
212	2160	1	3	311B		Room Between 311 & 312	W2	Flaking	10						
213	2160	1	3	311B		Room Between 311 & 312	W3	Flaking	50		Y - Floor	10			
214	2160	1	3	S34		South Fire Tower along McKean Street	Ceiling	Flaking, holes, Significant Moisture Damage	310	Y					
215	2160	1	3	S34		South Fire Tower along McKean Street	Floor	Chipping	210	Y	Y - Floor	210			
216	2160	1	3	H33		South Hallway along McKean Street	Ceiling	Flaking, Efflorescence on Ceiling Grid	100	Y					
217	2160	1	3	H33		South Hallway along McKean Street	W2	Flaking - Walls, Doors	100	Y					

Furness -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
218	2160	1	3	H33		South Hallway along McKean Street	W4	Flaking - Walls, Doors	400	Y				Y	
219	2160	1	3	310A		Southeast Restroom - Corner of 3rd and McKean Streets	Ceiling	Flaking	50	Y	Y - Floor	5			
220	2160	1	3	310B		Southeast Restroom Entrance Foyer - Corner of 3rd and McKean Streets	Ceiling	Flaking	50	Y					
221	2160	1	3	310B		Southeast Restroom Entrance Foyer - Corner of 3rd and McKean Streets	W1	Flaking - Walls, Doors	10						
222	2160	1	3	310B		Southeast Restroom Entrance Foyer - Corner of 3rd and McKean Streets	W2	Flaking	20						
223	2160	1	3	310B		Southeast Restroom Entrance Foyer - Corner of 3rd and McKean Streets	W3	Flaking	10						
224	2160	1	3	310B		Southeast Restroom Entrance Foyer - Corner of 3rd and McKean Streets	W4	Flaking	10						
225	2160	1	3	S33		Southeast Stairwell - Corner of 3rd and McKean Streets	W3	Flaking	200		Y - Floor	10			
226	2160	1	3	318B		Storage Room next to Boy's Restroom	W1	Flaking	1						
227	2160	1	2	224		Auditorium Balcony	Ceiling	Flaking	20						
228	2160	1	2	224		Auditorium Balcony	W1	Flaking	15						
229	2160	1	2	224		Auditorium Balcony	W2	Flaking, Efflorescence	200		Y	20		Y	
230	2160	1	2	224		Auditorium Balcony	W3	Flaking	20						
231	2160	1	2	224		Auditorium Balcony	W4	Flaking, Efflorescence	160		Y	20		Y	
232	2160	1	2	217		Boy's Restroom	Ceiling	Flaking, Efflorescence	150					Y	
233	2160	1	2	H22		Center Hallway	W3	Flaking	2					Y	
234	2160	1	2	201		Classroom 201	W1	Flaking - Door	2						
235	2160	1	2	201		Classroom 201	W2	Flaking - By Window	4						
236	2160	1	2	201		Classroom 201	W4	Flaking - Wall and By Window	10						
237	2160	1	2	201A		Classroom 201 Closet	W1	Flaking, Holes	2					Y	
238	2160	1	2	201A		Classroom 201 Closet	W3	Flaking, Holes	4					Y	
239	2160	1	2	203		Classroom 203	W1	Flaking, Cracking - Doors, Chalkboards	75						
240	2160	1	2	203		Classroom 203	W2	Flaking- Pipe	1						
241	2160	1	2	203		Classroom 203	W3	Cracking at Windows	35						
242	2160	1	2	203		Classroom 203	W4	Flaking at Chalkboard	4						
243	2160	1	2	203A		Classroom 203 Closet	W3	Flaking	2				Supplies		
244	2160	1	2	204		Classroom 204	Ceiling	Flaking - at Windows	16						
245	2160	1	2	204		Classroom 204	W1	Flaking - Doors, Chalkboard	85						
246	2160	1	2	204		Classroom 204	W2	Flaking	5						
247	2160	1	2	204		Classroom 204	W3	Flaking, Efflorescence, Flaking at Pipes	20						
248	2160	1	2	204		Classroom 204	W4	Flaking	20						



Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
249	2160	1	2	204D		Classroom 204 Closet	W2	Holes around Vent	2		Y	1	Supplies	Y	
250	2160	1	2	205		Classroom 205	W1	Flaking - Chipping on Doors	10						
251	2160	1	2	205		Classroom 205	W2	Flaking	160						
252	2160	1	2	205		Classroom 205	W3	Flaking on Windows	20						
253	2160	1	2	205		Classroom 205	W4	Flaking	20		Y	2			
254	2160	1	2	206		Classroom 206	W1	Flaking - Chipping on Doors	30						
255	2160	1	2	206		Classroom 206	W2	Flaking	10						
256	2160	1	2	206		Classroom 206	W3	Flaking on Windows	5						
257	2160	1	2	206		Classroom 206	W4	Flaking on Chalk Ledge	10						
258	2160	1	2	207		Classroom 207	W1	Flaking, Chipping (Doors)	100						
259	2160	1	2	207		Classroom 207	W2	Flaking	200						
260	2160	1	2	207		Classroom 207	W4	Flaking	200						
261	2160	1	2	208		Classroom 208	W1	Cracking	100						
262	2160	1	2	208		Classroom 208	W2	Flaking - chalk Ledge	20						
263	2160	1	2	208		Classroom 208	W3	Flaking, Chipping	15						
264	2160	1	2	208		Classroom 208	W4	Flaking, Chipping, Holes	30					Y	
265	2160	1	2	208A		Classroom 208 Closet	W1	Flaking	5				Supplies		
266	2160	1	2	208A		Classroom 208 Closet	W2	Flaking	10				Supplies		
267	2160	1	2	208A		Classroom 208 Closet	W3	Flaking	3				Supplies		
268	2160	1	2	209		Classroom 209	W1	Cracking, Flaking (Doors)	80						
269	2160	1	2	209		Classroom 209	W3	Flaking, Chipping	80						
270	2160	1	2	209		Classroom 209	W4	Flaking	60						
271	2160	1	2	209A		Classroom 209 Closet	Ceiling	Flaking, Efflorescence	2				Supplies		
272	2160	1	2	209A		Classroom 209 Closet	W1	Flaking, Cracking	5						
273	2160	1	2	209A		Classroom 209 Closet	W4	Flaking, Efflorescence	5				Supplies		
274	2160	1	2	210		Classroom 210	W2	Flaking	10						
275	2160	1	2	210		Classroom 210	W3	Flaking, Efflorescence	100					Y	
276	2160	1	2	211		Classroom 211	W1	Flaking, Chipping (Door)	100						
277	2160	1	2	211		Classroom 211	W2	Flaking	5				Supplies	Y	
278	2160	1	2	211		Classroom 211	W3	Flaking, Chipping	25						
279	2160	1	2	211		Classroom 211	W4	Flaking	10						
280	2160	1	2	211A		Classroom 211 Closet	Ceiling	Flaking	20						
281	2160	1	2	212		Classroom 212	W4	Flaking	20						
282	2160	1	2	213		Classroom 213	W1	Flaking, Chipping (Door)	120						
283	2160	1	2	213		Classroom 213	W2	Flaking	5						
284	2160	1	2	213		Classroom 213	W3	Flaking, Chipping	60					Y	
285	2160	1	2	213		Classroom 213	W4	Flaking	30						
286	2160	1	2	214		Classroom 214	W1	Chipping, Cracking (Doors)	15						
287	2160	1	2	214		Classroom 214	W2	Flaking - Chalk Ledge	10						
288	2160	1	2	214		Classroom 214	W3	Flaking, Efflorescence	60				Bookshelf	Y	
289	2160	1	2	214		Classroom 214	W4	Flaking	20						
290	2160	1	2	218		Classroom 218	W1	Flaking - Doors	5						
291	2160	1	2	218		Classroom 218	W2	Flaking - Chalk Ledge	10						
292	2160	1	2	218		Classroom 218	W3	Flaking - Windows	30						
293	2160	1	2	218		Classroom 218	W4	Flaking	10						
294	2160	1	2	219		Classroom 219	W1	Cracking, Flaking	40						
295	2160	1	2	219		Classroom 219	W2	Flaking	3						

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
296	2160	1	2	219		Classroom 219	W3	Flaking, Efflorescence	15					Y	
297	2160	1	2	219		Classroom 219	W4	Flaking	5						
298	2160	1	2	220		Classroom 220	W1	Cracking - Doors	20						
299	2160	1	2	220		Classroom 220	W2	Cracking	2						
300	2160	1	2	220		Classroom 220	W3	Flaking, Holes,	10					Y	
301	2160	1	2	220		Classroom 220	W4	Flaking, Efflorescence	150					Y	
302	2160	1	2	221		Classroom 221	W1	Chipping	2						
303	2160	1	2	221		Classroom 221	W4	Chipping	10						
304	2160	1	2	221D		Classroom 221 Closet	Ceiling	Flaking, Efflorescence	10				Supplies	Y	
305	2160	1	2	221E		Classroom 221 Closet	Ceiling	Flaking, Efflorescence	5				Supplies	Y	
306	2160	1	2	221E		Classroom 221 Closet	W2	Flaking	2						
307	2160	1	2	221D		Classroom 221 Closet	W3	Flaking	5						
308	2160	1	2	221E		Classroom 221 Closet	W3	Flaking	5						
309	2160	1	2	221E		Classroom 221 Closet	W4	Flaking	2						
310	2160	1	2	221B		Classroom 221B	Ceiling	Flaking, Efflorescence	3						
311	2160	1	2	221B		Classroom 221B	W4	Flaking	5						
312	2160	1	2	222		Classroom 222	W3	Flaking - by Pipe	8						
313	2160	1	2	206A		Girl's Restroom	Ceiling	Flaking, Cracking	200						
314	2160	1	2	206A		Girl's Restroom	W3	Flaking	2						
315	2160	1	2	215E		Music Department Closet in Music Room 215 Entrance Foyer	W2	Flaking	10				Supplies		
316	2160	1	2	215		Music Room 215	W3	Flaking	15						
317	2160	1	2	215		Music Room 215	W4	Flaking - on pipe	6						
318	2160	1	2	215G		Music Room 215 Storage Room	Ceiling	Flaking, Chipping	20		Y	2	Supplies		
319	2160	1	2	215G		Music Room 215 Storage Room	W1	Cracking	2				Supplies		
320	2160	1	2	215G		Music Room 215 Storage Room	W2	Flaking, Efflorescence	80		Y	2	Supplies	Y	
321	2160	1	2	215B		Music Teacher's Office	W3	Flaking, Efflorescence	40		Y	4			
322	2160	1	2	224C		No on-site description	Ceiling	Debris			Y	1			
323	2160	1	2	224C		No on-site description	Floor	Debris			Y	1			
324	2160	1	2	224C		No on-site description	W1	Debris			Y	1			
325	2160	1	2	224C		No on-site description	W2	Debris			Y	1			
326	2160	1	2	224C		No on-site description	W3	Debris			Y	1			
327	2160	1	2	224C		No on-site description	W4	Debris			Y	1			
328	2160	1	2	S224G		North Auditorium Stairwell	Ceiling	Flaking	10						
329	2160	1	2	S21		North Fire Tower along Mifflin Street	Ceiling	Flaking, Efflorescence	600		Y - Floor	10		Y	

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
330	2160	1	2	S22		Northeast Stairwell - Corner of 3rd and Mifflin Streets	Floor	Flaking	50	Y					
331	2160	1	2	S22		Northeast Stairwell - Corner of 3rd and Mifflin Streets	W3	Flaking	50						
332	2160	1	2	214A		Northeast Women's Restroom - Corner of 3rd and Mifflin Streets	W2	Flaking - Bookshelf	10						
333	2160	1	2	216		Nurse's Office	W3	Flaking	20						
334	2160	1	2	202		Office 202	W2	Flaking on Pipe, Holes	2					Y	
335	2160	1	2	202		Office 202	W3	Flaking	12						
336	2160	1	2	202		Office 202	W4	Flaking on Pipe	2						
337	2160	1	2	224A		Old Projector Room	Ceiling	No Access							Inspection Needed
338	2160	1	2	224A		Old Projector Room	W1	No Access							Inspection Needed
339	2160	1	2	224A		Old Projector Room	W2	No Access							Inspection Needed
340	2160	1	2	224A		Old Projector Room	W3	No Access							Inspection Needed
341	2160	1	2	224A		Old Projector Room	W4	No Access							Inspection Needed
342	2160	1	2	S224D		South Auditorium Stairwell	Ceiling	Debris			Y	1			
343	2160	1	2	S224D		South Auditorium Stairwell	Floor	Debris			Y	1			
344	2160	1	2	S224D		South Auditorium Stairwell	W1	Debris			Y	1			
345	2160	1	2	S224D		South Auditorium Stairwell	W2	Debris			Y	1			
346	2160	1	2	S224D		South Auditorium Stairwell	W3	Debris			Y	1			
347	2160	1	2	S224D		South Auditorium Stairwell	W4	Debris			Y	1			
348	2160	1	2	224B		South Auditorium Storage	Ceiling	Debris			Y	1			
349	2160	1	2	224B		South Auditorium Storage	Floor	Debris			Y	1			
350	2160	1	2	224B		South Auditorium Storage	W1	Debris			Y	1			
351	2160	1	2	224B		South Auditorium Storage	W2	Debris			Y	1			
352	2160	1	2	224B		South Auditorium Storage	W3	Debris			Y	1			
353	2160	1	2	224B		South Auditorium Storage	W4	Debris			Y	1			
354	2160	1	2	S24		South Fire Tower along McKean Street	Ceiling	Flaking, Holes	600						
355	2160	1	2	210A		Southeast Men's Restroom - Corner of 3rd and McKean Streets	Ceiling	Flaking	50						
356	2160	1	2	210B		Southeast Men's Restroom Entrance Foyer - Corner of 3rd and McKean Streets	W1	Flaking - Door	3						

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
357	2160	1	2	210B		Southeast Men's Restroom Entrance Foyer - Corner of 3rd and McKean Streets	W2	Flaking	2						
358	2160	1	2	S23		Southeast Stairwell - Corner of 3rd and McKean Streets	W1	Flaking	100	Y					
359	2160	1	2	S23		Southeast Stairwell - Corner of 3rd and McKean Streets	W2	Flaking	10						
360	2160	1	1	113		Assistant Principal's Office	Floor	Cracking, Chipping	15				Supplies		
361	2160	1	1	113		Assistant Principal's Office	W1	Cracking, Chipping, Flaking	10				Supplies		
362	2160	1	1	113		Assistant Principal's Office	W2	Chipping, Holes	5				Supplies	Y	
363	2160	1	1	118		Auditorium	Ceiling	Cracking, Chipping, Spalling - Drop Ceiling and Main Ceiling	100						
364	2160	1	1	118		Auditorium	W1	Cracks - Above Door	30						
365	2160	1	1	118		Auditorium	W2	Flaking, Cracking	50						
366	2160	1	1	118		Auditorium	W4	Flaking, Cracking	50						
367	2160	1	1	118E		Auditorium North Stage Hallway	Ceiling	Flaking	15						
368	2160	1	1	118E		Auditorium North Stage Hallway	Floor	Debris	50		Y - Floor	50	Stage supplies		
369	2160	1	1	118D		Auditorium North Stage Hallway	W2	Spalling, Efflorescence, Flaking	50	Y					
370	2160	1	1	118E		Auditorium North Stage Hallway	W4	Flaking - by Downstairs Doors	5						
371	2160	1	1	118F		Auditorium North Stage Restroom	Ceiling	No Access							Inspection Needed
372	2160	1	1	118F		Auditorium North Stage Restroom	Floor	No Access							Inspection Needed
373	2160	1	1	118F		Auditorium North Stage Restroom	W1	No Access							Inspection Needed
374	2160	1	1	118F		Auditorium North Stage Restroom	W2	No Access							Inspection Needed
375	2160	1	1	118F		Auditorium North Stage Restroom	W3	No Access							Inspection Needed
376	2160	1	1	118F		Auditorium North Stage Restroom	W4	No Access							Inspection Needed
377	2160	1	1	118C		Auditorium South Stage Hallway	Floor	Debris - Back Corner W3, W4	10		Y - Floor	10	Stage Supplies		
378	2160	1	1	118B		Auditorium South Stage Restroom	Ceiling	Flaking	8						
379	2160	1	1	STAGE		Auditorium Stage	Ceiling	Spalling	20						
380	2160	1	1	STAGE		Auditorium Stage	Floor	Debris - Along W2, W3, W4	75		Y - Floor	75	Supplies, Curtains		
381	2160	1	1	STAGE		Auditorium Stage	W2	Cracking, Chipping, Flaking, Efflorescence, Spalling	250				Supplies, Curtains		
382	2160	1	1	STAGE		Auditorium Stage	W3	Cracking, Chipping, Flaking, Efflorescence, Spalling	600				Supplies, Curtains		
383	2160	1	1	STAGE		Auditorium Stage	W4	Cracking, Chipping, Flaking, Efflorescence, Spalling	300				Supplies, Curtains		
384	2160	1	1	118G		Behind Stage Passage Hallway	Floor	Holes, gouges	90		Y - Floor	50			Floor not safe to walk on.

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
385	2160	1	1	121		Boy's Gym Upper Storage Room	W2	Efflorescence	10	Y					
386	2160	1	1	121		Boy's Gym Upper Storage Room	W3	Flaking, Chipping	10					Y	
387	2160	1	1	BALC2		Boy's Gymnasium Balcony	Ceiling	Spallign, Efflorescence, Flaking	800	Y			Supplies	Y	
388	2160	1	1	BALC2		Boy's Gymnasium Balcony	Floor	Debris	1,800		Y - Floor	1,800			
389	2160	1	1	BALC2		Boy's Gymnasium Balcony	W4	Spalling, Efflorescence, Flaking, Gouges	50	Y				Y	
390	2160	1	1	116		Boy's Restroom	Ceiling	Flaking	175						
391	2160	1	1	H12		Center Hallway	W1	Spalling - Above Stairwell to 2nd Floor	75						
392	2160	1	1	H12		Center Hallway	W2	Flaking, Spalling - By North Court Windows	180						
393	2160	1	1	H12		Center Hallway	W4	Spalling - by 106, 106A	15						
394	2160	1	1	101		Classroom 101	W1	Flaking	25						
395	2160	1	1	101		Classroom 101	W2	Flaking, Cracking	50						
396	2160	1	1	101		Classroom 101	W3	Chipping	25						
397	2160	1	1	101		Classroom 101	W4	Chipping	5						
398	2160	1	1	101A		Classroom 101 Closet	W1	Chipping	20				Supplies		
399	2160	1	1	101A		Classroom 101 Closet	W2	Chipping	10						
400	2160	1	1	101A		Classroom 101 Closet	W3	Chipping - Doors	10						
401	2160	1	1	102		Classroom 102	Ceiling	Flaking	4						
402	2160	1	1	102		Classroom 102	W1	Flaking	50						
403	2160	1	1	102		Classroom 102	W2	Flaking	50						
404	2160	1	1	102		Classroom 102	W3	Flaking	50						
405	2160	1	1	102		Classroom 102	W4	Flaking	50						
406	2160	1	1	102A		Classroom 102 Closet	W1	Flaking	5				Supplies		
407	2160	1	1	102A		Classroom 102 Closet	W2	Flaking	5						
408	2160	1	1	102A		Classroom 102 Closet	W3	Flaking	5						
409	2160	1	1	102A		Classroom 102 Closet	W4	Flaking	5						
410	2160	1	1	103		Classroom 103	W1	Flaking	20						
411	2160	1	1	103		Classroom 103	W2	Flaking	10						
412	2160	1	1	103		Classroom 103	W3	Flaking	20						
413	2160	1	1	103		Classroom 103	W4	Flaking, Chipping	100						
414	2160	1	1	103A		Classroom 103 Closet	W1	Cracking	5				Supplies		
415	2160	1	1	103A		Classroom 103 Closet	W3	Flaking - Doors	20						
416	2160	1	1	104		Classroom 104	Ceiling	Significant Moisture Damage	25						
417	2160	1	1	104		Classroom 104	W1	Flaking, Chipping, Cracking	75						
418	2160	1	1	104		Classroom 104	W2	Chipping	20						
419	2160	1	1	104		Classroom 104	W3	Chipping	10						
420	2160	1	1	104		Classroom 104	W4	Flaking, Chipping	10						
421	2160	1	1	104A		Classroom 104 Closet	W1	Flaking, Chipping	5				Supplies		
422	2160	1	1	104A		Classroom 104 Closet	W3	Flaking - Doors	15						

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
423	2160	1	1	104A		Classroom 104 Closet	W4	Flaking	2						
424	2160	1	1	105		Classroom 105	Floor	Holes - Under Center Window	2						
425	2160	1	1	105		Classroom 105	W1	Flaking	20						
426	2160	1	1	105		Classroom 105	W3	Chipping - Pipe under windows	40						
427	2160	1	1	105		Classroom 105	W4	Cracking - 3 Large Holes	25					Y	
428	2160	1	1	105B		Classroom 105 Closet	W1	Cracking	20						
429	2160	1	1	105B		Classroom 105 Closet	W2	Cracking	10						
430	2160	1	1	105B		Classroom 105 Closet	W3	Cracking	10						
431	2160	1	1	105A		Classroom 105 Storage Room	Ceiling	Cracking	10						
432	2160	1	1	105A		Classroom 105 Storage Room	Floor	Gouge, Significant Moisture Damage, Efflorescence	8	Y					
433	2160	1	1	105A		Classroom 105 Storage Room	W1	Cracking	50				Books, supplies, etc.		
434	2160	1	1	105A		Classroom 105 Storage Room	W2	Chipping, Cracking, Flaking, Efflorescence, Significant Moisture Damage	20	Y					
435	2160	1	1	105A		Classroom 105 Storage Room	W3	Chipping, Cracking, Flaking, Efflorescence, Significant Moisture Damage	20	Y					
436	2160	1	1	105A		Classroom 105 Storage Room	W4	Cracking	5						
437	2160	1	1	106		Classroom 106	Ceiling	Significant Moisture Damage - Corner by W2/W3	3						
438	2160	1	1	106		Classroom 106	W1	Cracking, Chipping, Significant Moisture Damage - Pipes, Pillars, and Walls	10						
439	2160	1	1	106		Classroom 106	W3	Efflorescence, Chipping, Spalling, Significant Water Damage	75	Y			Supplies	YES	
440	2160	1	1	106C		Classroom 106 Closet	Ceiling	Chipping, Cracking	10				Supplies		
441	2160	1	1	106C		Classroom 106 Closet	W1	Chipping, Cracking	10				Supplies		
442	2160	1	1	106C		Classroom 106 Closet	W2	Cracking	10				Supplies		
443	2160	1	1	106C		Classroom 106 Closet	W3	Cracking	10				Supplies		
444	2160	1	1	106C		Classroom 106 Closet	W4	Cracking	10				Supplies		
445	2160	1	1	114		Counselor's Office	W1	Cracking	5						
446	2160	1	1	111		Faculty Lounge	Ceiling	Significant Moisture Damage - 13 Panels	100						
447	2160	1	1	111		Faculty Lounge	W1	Flaking - Door	12						
448	2160	1	1	111		Faculty Lounge	W3	Flaking, Chipping	20						
449	2160	1	1	112		Family Welcome Center	W1	Flaking - On Door; Hole on Right	5					Y	
450	2160	1	1	112		Family Welcome Center	W2	Flaking, Cracking	40				Supplies		
451	2160	1	1	112		Family Welcome Center	W3	Cracking - Under Window, Radiator, Pipe	10				Supplies		
452	2160	1	1	112		Family Welcome Center	W4	Cracking - Corner by Window	10						
453	2160	1	1	120		Girl's Gym Upper Storage Room	Ceiling	Holes, Flaking, Spalling	200					Y	

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
454	2160	1	1	120		Girl's Gym Upper Storage Room	Floor	Holes	10						
455	2160	1	1	120		Girl's Gym Upper Storage Room	W2	Flaking, Cracking	35		Y - Floor	10			
456	2160	1	1	120		Girl's Gym Upper Storage Room	W3	Flaking	300		Y - Floor	5			
457	2160	1	1	120		Girl's Gym Upper Storage Room	W4	Flaking	35		Y - Floor	10			
458	2160	1	1	BALC1		Girl's Gymnasium Balcony	Ceiling	Chipping, Holes, Flaking, Gouges	400	Y				Y	
459	2160	1	1	BALC1		Girl's Gymnasium Balcony	Floor	Debris - Behind and Center Bleachers	-		Y - Floor	200			
460	2160	1	1	BALC1		Girl's Gymnasium Balcony	W2	Flaking	30						
461	2160	1	1	102A		Girl's Restroom	Ceiling	Flaking	40						
462	2160	1	1	102A		Girl's Restroom	Floor	Debris	-		Y - Floor	10			
463	2160	1	1	109		IMC (Library)	Floor	Debris - Back Corner of W3 & W4			Y - Floor	10	Supplies, Books		
464	2160	1	1	109		IMC (Library)	W1	Cracks - Length of Wall; Chipping - Doors	300		Y - Floor	10	Supplies, Books		
465	2160	1	1	109		IMC (Library)	W2	Cracking, Chipping, Gouges	10				Supplies, Books		
466	2160	1	1	109		IMC (Library)	W3	Chipping, Cracking, Significant Moisture Damage, Efflorescence - Pillars, Walls, Pipes, Windows	1,000	Y			Supplies, Books	Y	
467	2160	1	1	109		IMC (Library)	W4	Cracking, Chipping	50				Supplies, Books		
468	2160	1	1	108A		IMC (Library) Office	Ceiling	No Access							Inspection Needed
469	2160	1	1	108A		IMC (Library) Office	Floor	No Access							Inspection Needed
470	2160	1	1	108A		IMC (Library) Office	W1	No Access							Inspection Needed
471	2160	1	1	108A		IMC (Library) Office	W2	No Access							Inspection Needed
472	2160	1	1	108A		IMC (Library) Office	W3	No Access							Inspection Needed
473	2160	1	1	NP11		IMC (Library) Office	W3	Spalling - Above Door	8				Bookshelf		
474	2160	1	1	NP11		IMC (Library) Office	W4	Cracking - along Window	10				Desk		
475	2160	1	1	108A		IMC (Library) Office	W4	No Access							Inspection Needed
476	2160	1	1	NP10		IMC (Library) Office/Copy Room	Ceiling	Hole in Panel	8						
477	2160	1	1	NP10		IMC (Library) Office/Copy Room	W2	Cracking	5						
478	2160	1	1	NP10		IMC (Library) Office/Copy Room	W3	Spalling, Flaking	5						
479	2160	1	1	108B		IMC (Library) Storage Room	Ceiling	No Access							Inspection Needed
480	2160	1	1	108B		IMC (Library) Storage Room	Floor	No Access							Inspection Needed
481	2160	1	1	108B		IMC (Library) Storage Room	W1	No Access							Inspection Needed
482	2160	1	1	108B		IMC (Library) Storage Room	W2	No Access							Inspection Needed
483	2160	1	1	108B		IMC (Library) Storage Room	W3	No Access							Inspection Needed
484	2160	1	1	108B		IMC (Library) Storage Room	W4	No Access							Inspection Needed
485	2160	1	1	110		Main Office	W1	Cracking, Flaking	100				Filing cabinets		
486	2160	1	1	110		Main Office	W2	Cracking, Flaking	20				Bulletin board, bench		
487	2160	1	1	110		Main Office	W3	Flaking, Spalling - Behind Pipe in Corner by W2	20						

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
488	2160	1	1	115C		Main Office - Bilingual Counselor	W4	Cracking - Length of Wall in 2 Spots	100						
489	2160	1	1	NP9		Main Office Restroom	W1	Cracking - Above Door	5						
490	2160	1	1	NP9		Main Office Restroom	W3	Flaking, Spalling - in NP-9A	50				Supplies		
491	2160	1	1	S11		North Fire Tower along Mifflin Street	Ceiling	Efflorescence, Spalling, Flaking, Gouges, Significant Moisture Damage	500	Y	Y-Floor	500			
492	2160	1	1	S11		North Fire Tower along Mifflin Street	Floor	Gouges	200	Y					
493	2160	1	1	H11		North Hallway along Mifflin Street	W1	Flaking, Spalling	10						
494	2160	1	1	H11		North Hallway along Mifflin Street	W2	Flaking	2						
495	2160	1	1	H11		North Hallway along Mifflin Street	W4	Spalling - By Bilingual Conselor	2						
496	2160	1	1	S12		Northeast Stairwell - Corner of 3rd and Mifflin Streets	W2	Flaking	10						
497	2160	1	1	S12		Northeast Stairwell - Corner of 3rd and Mifflin Streets	W4	Flaking	10						
498	2160	1	1	106B		Northeast Women's Restroom - Corner of 3rd and McKean Streets	Ceiling	Cracking	20						
499	2160	1	1	106B		Northeast Women's Restroom - Corner of 3rd and McKean Streets	W1	Chipping	10						
500	2160	1	1	106B		Northeast Women's Restroom - Corner of 3rd and McKean Streets	W3	Cracking - Window	10						
501	2160	1	1	106A		Northeast Women's Restroom Entrance Vestibule - Corner of 3rd and McKean Streets	Ceiling	Cracking	10						
502	2160	1	1	106A		Northeast Women's Restroom Entrance Vestibule - Corner of 3rd and McKean Streets	W1	Chipping	20						
503	2160	1	1	106A		Northeast Women's Restroom Entrance Vestibule - Corner of 3rd and McKean Streets	W2	Chipping, Cracking	10						
504	2160	1	1	106A		Northeast Women's Restroom Entrance Vestibule - Corner of 3rd and McKean Streets	W3	Chipping	20						



Furness -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
505	2160	1	1	106A		Northeast Women's Restroom Entrance Vestibule - Corner of 3rd and McKean Streets	W4	Chipping, Cracking	50						
506	2160	1	1	H15		Northwest Hallway outside of Boys Gym	Ceiling	Spalling, Efflorescence	250						
507	2160	1	1	H15		Northwest Hallway outside of Boys Gym	W2	Spalling, Cracking - In Stairwell Closer to Balc2	10	Y	Y - Floor	10			
508	2160	1	1	H15		Northwest Hallway outside of Boys Gym	W3	Flaking - Wall with Gym Entrance	2						
509	2160	1	1	H15		Northwest Hallway outside of Boys Gym	W4	Flaking - by Firetower Door	10						
510	2160	1	1	NP7		Principal's Office Book Closet	W2	Cracking	10				Supplies		
511	2160	1	1	NP7		Principal's Office Book Closet	W3	Cracking	10				Supplies		
512	2160	1	1	NP7		Principal's Office Book Closet	W4	Cracking	10				Supplies		
513	2160	1	1	111A		School Police Office	W1	Cracking - Above Door, on Window	3	Y					
514	2160	1	1	111A		School Police Office	W2	Flaking, Spalling	10						
515	2160	1	1	111A		School Police Office	W3	Cracking, Gouge - Above Door	2						
516	2160	1	1	111A		School Police Office	W4	Chipping	10				Supplies		
517	2160	1	1	S14		South Fire Tower along McKean Street	Ceiling	Flaking, Significant Moisture Damage	500	Y					
518	2160	1	1	S14		South Fire Tower along McKean Street	Floor	Flaking, Holes	10						
519	2160	1	1	H13		South Hallway along McKean Street	W2	Flaking - Outside Doors to 102 & 104	20						
520	2160	1	1	S13		Southeast Stairwell - Corner of 3rd and McKean Streets	W3	Flaking - Near Windows	20	Y					
521	2160	1	1	H14		Southwest Hallway	Floor	Flaking	10						
522	2160	1	1	H14		Southwest Hallway	W1	Flaking	50						
523	2160	1	1	H14		Southwest Hallway	W2	Flaking - On Windows; Significant Moisture Damage, Efflorescence	40	Y					
524	2160	1	1	S15		Southwest Stairwell to Basement	Ceiling	Significant Moisture Damage - By Pipe	10	Y					
525	2160	1	1	S15		Southwest Stairwell to Basement	Floor	Flaking	20						
526	2160	1	1	S15		Southwest Stairwell to Basement	W4	Flaking	10						
527	2160	1	0	16A		Auditorium Fan Room	W1	Holes	10						
528	2160	1	0	16A		Auditorium Fan Room	W2	Flaking - on Fan	30						
529	2160	1	0	16A		Auditorium Fan Room	W4	Cracking, Flaking, Hole	20						
530	2160	1	0	16		Auditorium Supply Plenum	W1	Flaking	10						
531	2160	1	0	16		Auditorium Supply Plenum	W2	Cracking, Flaking	10						
532	2160	1	0	16		Auditorium Supply Plenum	W3	Cracking	5						
533	2160	1	0	16		Auditorium Supply Plenum	W4	Cracking, Flaking	50						

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
534	2160	1	0	17		Boy's and Girl's Gymnasium Fan Room	Ceiling	Flaking	50						
535	2160	1	0	17		Boy's and Girl's Gymnasium Fan Room	W1	Flaking, Cracking	50						
536	2160	1	0	17		Boy's and Girl's Gymnasium Fan Room	W2	Cracking	5						
537	2160	1	0	015G		Boy's Gym Storage Closet	Ceiling	Flaking	5						
538	2160	1	0	015G		Boy's Gym Storage Closet	W1	Flaking	5						
539	2160	1	0	015G		Boy's Gym Storage Closet	W2	Flaking - Window Sill	5						
540	2160	1	0	015G		Boy's Gym Storage Closet	W4	Flaking	5				Supplies		
541	2160	1	0	015E		Boy's Gym Teacher's Office	Ceiling	Flaking, Hole Above Pipes in Corner	20				Supplies		
542	2160	1	0	015E		Boy's Gym Teacher's Office	Floor	Flaking	50				Supplies		
543	2160	1	0	015D		Boy's Gym Teacher's Office	W1	Flaking	5				Desk		
544	2160	1	0	015D		Boy's Gym Teacher's Office	W2	Flaking	5						
545	2160	1	0	015F		Boy's Gym Teacher's Restroom	Ceiling	Holes, Flaking, Spalling,	20	Y					
546	2160	1	0	015A		Boy's Gym Weight Room	Ceiling	Flaking - Above Pipes/Fan; Cracking on Lights	360	Y				Y	
547	2160	1	0	015A		Boy's Gym Weight Room	Floor	Flaking	1,800				Supplies		
548	2160	1	0	015A		Boy's Gym Weight Room	W2	Flaking, Significant Moisture Damage from Pipe	5	Y					
549	2160	1	0	015A		Boy's Gym Weight Room	W3	Flaking - Along Windows	5						
550	2160	1	0	15		Boy's Gymnasium	Ceiling	Flaking, Spalling, Holes, Cracking	4,800					Y	
551	2160	1	0	EX		Boy's Gymnasium Entrance Vestibule	Ceiling	Flaking, Gouges, Efflorescence	100	Y			Supplies	Y	
552	2160	1	0	EX		Boy's Gymnasium Entrance Vestibule	W1	Efflorescence	10	Y			Supplies		
553	2160	1	0	EX		Boy's Gymnasium Entrance Vestibule	W2	Efflorescence	20	Y			Supplies		
554	2160	1	0	EX		Boy's Gymnasium Entrance Vestibule	W3	Flaking	20	Y			Supplies		
555	2160	1	0	EX		Boy's Gymnasium Entrance Vestibule	W4	Flaking on Doors, Efflorescence above doors	15	Y			Supplies		
556	2160	1	0	015B & C		Boy's Gymnasium Locker Room Restroom	Ceiling	Holes, Gouges, Flaking	170	Y				Y	
557	2160	1	0	015B & C		Boy's Gymnasium Locker Room Restroom	W3	Efflorescence, Flaking, Cracking	50	Y					
558	2160	1	0	015B & C		Boy's Gymnasium Locker Room Restroom	W4	Efflorescence, Flaking, Cracking	50	Y					
559	2160	1	0	13		Boy's Restroom	Ceiling	Flaking, Spalling	150						
560	2160	1	0	13		Boy's Restroom	W1	Flaking	2						
561	2160	1	0	9		Cafeteria	W3	Flaking - by Windows	30						

Furness -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
562	2160	1	0			Cafeteria Prep Room	W1	Cracking, Flaking, Spalling	100				Supplies		
563	2160	1	0			Cafeteria Prep Room	W2	Flaking	50				Supplies		
564	2160	1	0			Cafeteria Prep Room	W3	Holes, Flaking	25				Supplies	Y	
565	2160	1	0	NP10		Cafeteria Staff Restroom	Ceiling	Flaking, Efflorescence, Hole	15	Y					
566	2160	1	0	H02		Center Hallway	Ceiling	Flaking, Cracking	700					Y	
567	2160	1	0	H02		Center Hallway	Floor	Flaking, Chipping	200						
568	2160	1	0	H02		Center Hallway	W1	Flaking	10						
569	2160	1	0	H02		Center Hallway	W2	Flaking	20						
570	2160	1	0	H02		Center Hallway	W3	Flaking	10						
571	2160	1	0	H02		Center Hallway	W4	Flaking	35						
572	2160	1	0	4		Classroom 001 (Offices)	Ceiling	Ceiling Tile Damage - Significant Moisture Damage	80	Y					
573	2160	1	0	3		Classroom 003	W2	Flaking	10						
574	2160	1	0	3		Classroom 003	W4	Flaking	15						
575	2160	1	0	4		Classroom 004	W1	Cracking	6						
576	2160	1	0	5		Computer Lab 005	Ceiling	Flaking in Closet	30	Y			Supplies		
577	2160	1	0	5		Computer Lab 005	Floor	Debris	20		Y- Floor	20	Supplies		
578	2160	1	0	5		Computer Lab 005	W2	Flaking	5						
579	2160	1	0	NP5		Counselor Offices	Ceiling	Significant Moisture Damage	80	Y			Supplies		
580	2160	1	0	NP6		Counselor Offices	Ceiling	Significant Moisture Damage	16	Y			Supplies		
581	2160	1	0	NP5		Counselor Offices	Floor	Gouges	2				Supplies		
582	2160	1	0	NP3		Counselor Offices	W2	Flaking	10				Supplies		
583	2160	1	0	NP5		Counselor Offices	W2	Flaking	10				Supplies		
584	2160	1	0	NP2		Counselor Offices	W3	Cracking, Flaking	10				Supplies		
585	2160	1	0	NP3		Counselor Offices	W4	Flaking	10				Supplies		
586	2160	1	0	NP5		Counselor Offices	W4	Flaking	10				Supplies		
587	2160	1	0	NP2		Counselor Offices	W4	Flaking, Spalling by Window	15				Supplies		
588	2160	1	0	001E		Girl's Gym Teacher's Office	Ceiling	Flaking	25						
589	2160	1	0	001E		Girl's Gym Teacher's Office	Floor	Flaking	75						
590	2160	1	0	001D		Girl's Gym Teacher's Office	W1	Flaking, Cracking - by windows	15				Cabinet, desk		
591	2160	1	0	001D		Girl's Gym Teacher's Office	W2	Flaking	10				Supplies		
592	2160	1	0	001D		Girl's Gym Teacher's Office	W3	Flaking	10				Supplies		
593	2160	1	0	001E		Girl's Gym Teacher's Office	W4	Flaking	10						
594	2160	1	0	001F		Girl's Gym Teacher's Restroom	W4	Flaking - by Window	5						
595	2160	1	0	1		Girl's Gymnasium	Ceiling	Flaking, Holes	1,800						
596	2160	1	0	H05		Girl's Gymnasium Entrance Vestibule	Ceiling	Flaking	10						
597	2160	1	0	H05		Girl's Gymnasium Entrance Vestibule	W3	Flaking - On Window	10				Supplies		
598	2160	1	0	H05		Girl's Gymnasium Entrance Vestibule	W4	Cracking	5				Supplies		
599	2160	1	0	001A		Girl's Gymnasium Locker Room	Ceiling	Flaking	150				Supplies		
600	2160	1	0	001A		Girl's Gymnasium Locker Room	Floor	Flaking	1,800				Supplies		

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
601	2160	1	0	001A		Girl's Gymnasium Locker Room	W3	Flaking - by Windows	15						
602	2160	1	0	001C		Girl's Gymnasium Locker Room Restroom	Ceiling	Flaking	100						
603	2160	1	0	NP-2		Girl's Gymnasium Storage Closet	W1	Flaking, Cracking	10						
604	2160	1	0	NP-2		Girl's Gymnasium Storage Closet	W2	Flaking	10						
605	2160	1	0	NP-2		Girl's Gymnasium Storage Closet	W3	Flaking	10						
606	2160	1	0	NP-2		Girl's Gymnasium Storage Closet	W4	Flaking, Significant Moisture Damage	20	Y			Supplies		
607	2160	1	0	004D		Girl's Restroom	Ceiling	Flaking	25						
608	2160	1	0	004D		Girl's Restroom	W1	Cracking	1						
609	2160	1	0	004A		Hallway outside Classroom 001	Ceiling	Gouges, Cracking	5						
610	2160	1	0	004A		Hallway outside Classroom 001	Floor	Holes, Gouges	20						
611	2160	1	0	8		Kitchen	Ceiling	Flaking	10						
612	2160	1	0	8		Kitchen	W1	Flaking - on door above sink	10						
613	2160	1	0	8		Kitchen	W2	Cracking	5				Supplies		
614	2160	1	0	8		Kitchen	W3	Efflorescence, Flaking	30				Supplies		
615	2160	1	0	8		Kitchen	W4	Flaking	15				Grill/Cooktop		
616	2160	1	0	6		Kitchen Food Storage Room 006	Ceiling	Flaking	130						
617	2160	1	0	6		Kitchen Food Storage Room 006	W1	Flaking	10				Supplies		
618	2160	1	0	006B		Kitchen Manager's Office	Ceiling	Flaking	7						
619	2160	1	0	006B		Kitchen Manager's Office	Floor	Cracking	2						
620	2160	1	0	006B		Kitchen Manager's Office	W1	Flaking	5						
621	2160	1	0	006B		Kitchen Manager's Office	W2	Flaking	5				Desk		
622	2160	1	0	006B		Kitchen Manager's Office	W3	Flaking	10						
623	2160	1	0	006B		Kitchen Manager's Office	W4	Flaking	20						
624	2160	1	0	006B-A		Kitchen Manager's Office Restroom	Ceiling	Flaking, Spalling, Efflorescence	10	Y					
625	2160	1	0	006B-A		Kitchen Manager's Office Restroom	W1	Flaking	2						
626	2160	1	0	006B-A		Kitchen Manager's Office Restroom	W2	Flaking	10						
627	2160	1	0	006B-A		Kitchen Manager's Office Restroom	W3	Flaking	15						
628	2160	1	0	006B-A		Kitchen Manager's Office Restroom	W4	Flaking	5						
629	2160	1	0	S01		North Fire Tower along Mifflin Street	Ceiling	Flaking, Holes, Gouges, Significant Moisture Damage	250	Y					
630	2160	1	0	S01		North Fire Tower along Mifflin Street	Floor	Holes	5						
631	2160	1	0	H01		North Hallway along Mifflin Street	Ceiling	Flaking, Spalling, Efflorescence, Significant Moisture damage	850	Y				Y	
632	2160	1	0	H01		North Hallway along Mifflin Street	Floor	Flaking, Chipping	300						

Furness -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
633	2160	1	0	H01		North Hallway along Miffin Street	W1	Flaking	10						
634	2160	1	0	H01		North Hallway along Miffin Street	W2	Flaking	10						
635	2160	1	0	H01		North Hallway along Miffin Street	W3	Flaking	300						
636	2160	1	0	H01		North Hallway along Miffin Street	W4	Flaking	300						
637	2160	1	0	H02		Northwest Hallway outside of Boys Gym	Ceiling	Flaking, Spalling	50						
638	2160	1	0	H02		Northwest Hallway outside of Boys Gym	W3	Chipping, Flaking	10						
639	2160	1	0	12		Old Coal Storage Room	Ceiling	Cracking	10						
640	2160	1	0	002A		Restroom between Classroom 002 and Classroom 003	Ceiling	Hole	5				Supplies	Y	
641	2160	1	0	S04		South Fire Tower along McKean Street	Ceiling	Flaking, Holes, Significant Moisture Damage, Spalling	250	Y					
642	2160	1	0	S04		South Fire Tower along McKean Street	Floor	Holes	10	Y					
643	2160	1	0	H03		South Hallway along McKean Street	Ceiling	Flaking, Spalling - by Fire Tower	120						
644	2160	1	0	S03		Southeast Stairwell - Corner of 3rd and McKean Streets	W3	Flaking, Cracking, Efflorescence by Pipe	25	Y					
645	2160	1	0	S03		Southeast Stairwell - Corner of 3rd and McKean Streets	W4	Cracking	2						
646	2160	1	0	H04		Southwest Hallway outside of Girls Gym	Ceiling	Flaking	20						
647	2160	1	0	H04		Southwest Hallway outside of Girls Gym	Floor	Flaking	10						
648	2160	1	0	H04		Southwest Hallway outside of Girls Gym	W1	Flaking - by Windows	10						
649	2160	1	0	S05		Southwest Stairwell to First Floor outside of Girls Gym	W4	Flaking - Along Stairs	15						
650	2160	1	0	7		Special Education Classroom 007	Ceiling	Flaking	16				Supplies		
651	2160	1	0	7		Special Education Classroom 007	W1	Flaking	10				Supplies		
652	2160	1	0	7		Special Education Classroom 007	W2	Flaking	20				Supplies		
653	2160	1	0	7		Special Education Classroom 007	W3	Flaking	10				Supplies		
654	2160	1	0	7		Special Education Classroom 007	W4	Flaking	10				Supplies		
655	2160	1	0	7A		Special Education Classroom 007A	Ceiling	Holes, Flaking by Windows	50						
656	2160	1	0	7A		Special Education Classroom 007A	W1	Flaking	5				Supplies		
657	2160	1	0	7A		Special Education Classroom 007A	W3	Spalling, Holes	5						
658	2160	1	0	7A		Special Education Classroom 007A	W4	Flaking - Under Windows	100				Desks		

Furness -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
659	2160	1	0	7B		Special Education Classroom 007B	Ceiling	Flaking	12						
660	2160	1	0	7B		Special Education Classroom 007B	W2	Flaking	30						
661	2160	1	0	7B		Special Education Classroom 007B	W3	Spalling, Flaking	10						
662	2160	1	0	7B		Special Education Classroom 007B	W4	Flaking, Cracking	10						