

Harding -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	7110	1	3	H313		3rd Floor Hallways	Floor	Flaking paint along perimeter	20	No	None		No	N	
2	7110	1	3	H314		3rd Floor Hallways	Floor	Flaking paint along perimeter	20	No	None		No	N	
3	7110	1	3	H315		3rd Floor Hallways	Floor	Flaking paint along perimeter	20	No	None		No	N	
4	7110	1	3	H316		3rd Floor Hallways	Floor	Flaking paint along perimeter	20	No	None		No	N	
5	7110	1	3	H314		3rd Floor Hallways	W1	Flaking paint behind radiators and on tack boards	60	No	None		No	N	
6	7110	1	3	H315		3rd Floor Hallways	W2	Flaking paint on wall at column & stair#3	10	No	None		No	N	
7	7110	1	3	H316		3rd Floor Hallways	W3	Flaking paint behind radiators	60	No	None		No	N	
8	7110	1	3	H315		3rd Floor Hallways	W4	Damaged plaster at Room 316	5	No	None		No	Y	
9	7110	1	3	H313		3rd Floor Hallways	W4	Flaking paint	15	No	None		No	N	
10	7110	1	3	301A		Book Closet in Classroom 301	Ceiling	Flaking paint and Damaged plaster	5	No	None		No	Y	
11	7110	1	3	301A		Book Closet in Classroom 301	W1	Flaking paint	10	No	None		No	N	
12	7110	1	3	302		Classroom 302	W1	Flaking paint above whiteboard and door	40	No	None		No	N	
13	7110	1	3	302		Classroom 302	W2	Gouges on wood wall	60	No	None		No	N	
14	7110	1	3	302		Classroom 302	W3	Efflorescence above windows, debris on window sill, flaking paint behind radiators	60	No	Yes	6	No	Y	
15	7110	1	3	302		Classroom 302	W4	Gouges above blackboard at wooden dividers	20	No	None		No	N	
16	7110	1	3	304		Classroom 304	W1	Flaking paint around blackboard and at column near door	20	No	None		No	N	
17	7110	1	3	304		Classroom 304	W2	Gouges above blackboard at wooden dividers	20	No	None		No	N	
18	7110	1	3	304		Classroom 304	W3	Efflorescence above windows, debris on window sill, flaking paint behind radiators	50	No	Yes	10	No	Y	
19	7110	1	3	304		Classroom 304	W4	Gouges above blackboard at wooden dividers	20	No	None		No	N	
20	7110	1	3	305		Classroom 305	W1	Gouges above blackboard at wooden dividers	20	No	None		No	N	
21	7110	1	3	305		Classroom 305	W3	Efflorescence above windows, debris on window sill, flaking paint behind radiators	30	No	Yes	6	No	Y	
22	7110	1	3	305		Classroom 305	W4	Gouges on wooden wall	20	No	No		No	N	
23	7110	1	3	306		Classroom 306	W1	Gouges above blackboard at wooden dividers	20	No	None		No	N	
24	7110	1	3	306		Classroom 306	W2	Flaking paint above windows, debris on window sill, flaking paint on wall & behind radiators	50	No	Yes	30	Computers, Desks need to be moved. Projector screen and Tablets need to be moved from the sill	Y	
25	7110	1	3	306		Classroom 306	W3	Flaking paint above windows, debris on window sill, flaking paint on wall & behind radiators	50	No	Yes	30	No	Y	
26	7110	1	3	306		Classroom 306	W4	Gouges on the wood wall	20	No	None		No	N	
27	7110	1	3	307A		Classroom 307A and 307B	W3	Flaking paint behind radiators (20 SF), Damaged plaster and efflorescence above windows (30 SF), Debris on window sill	50	No	Yes	30	No	Y	
28	7110	1	3	307A		Classroom 307A and 307B	W4	Gouges above blackboard at wooden dividers	20	No	None		No	N	

Harding -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
29	7110	1	3	308A/308B		Classroom 308	W1	Chipping & Spalling paint	10	No	None		No	N	
30	7110	1	3	308A/308B		Classroom 308	W3	Efflorescence above windows, debris on window sill, flaking paint behind radiators	60	No	Yes	2	No	Y	
31	7110	1	3	308A/308B		Classroom 308	W4	Gouges above blackboard at wooden dividers	20	No	None		No	N	
32	7110	1	3	309		Classroom 309	W1	Gouges above blackboard at wooden dividers	20	No	None		No	N	
33	7110	1	3	309		Classroom 309	W3	Efflorescence and damaged plaster above windows	24	No	None		No	Y	
34	7110	1	3	309A		Classroom 309 Closet	Ceiling	No access							Inspection Needed
35	7110	1	3	309A		Classroom 309 Closet	Floor	No access							Inspection Needed
36	7110	1	3	309A		Classroom 309 Closet	W1	No access							Inspection Needed
37	7110	1	3	309A		Classroom 309 Closet	W2	No access							Inspection Needed
38	7110	1	3	309A		Classroom 309 Closet	W3	No access							Inspection Needed
39	7110	1	3	309A		Classroom 309 Closet	W4	No access							Inspection Needed
40	7110	1	3	310		Classroom 310	W1	Gouges above blackboard at wooden dividers, and flaking paint at edge of wall	35	No	None		No	N	
41	7110	1	3	310		Classroom 310	W2	Chipping at left corner	4	No	None		No	N	
42	7110	1	3	310		Classroom 310	W3	Flaking paint above windows, debris on window sill, flaking paint on wall & behind radiators	40	No	Yes	10	No	N	
43	7110	1	3	310		Classroom 310	W4	Gouges above blackboard at wooden dividers, and chipping paint on wall	30	No	None		No	N	
44	7110	1	3	311		Classroom 311	W1	Chipping	30	No	None		No	N	
45	7110	1	3	311		Classroom 311	W2	Chipping	10	No	None		No	N	
46	7110	1	3	311		Classroom 311	W3	Flaking paint behind radiators	20	No	None		No	N	
47	7110	1	3	311		Classroom 311	W4	Gouges above the blackboard at wooden dividers	20	No	None		No	N	
48	7110	1	3	312		Classroom 312	W1	Peeling paint and damaged drywall at column	5	No	None		No	N	
49	7110	1	3	312		Classroom 312	W2	Peeling paint and damaged plaster at door	5	No	None		No	Y	
50	7110	1	3	312		Classroom 312	W3	Flaking paint behind radiators	20	No	None		No	N	
51	7110	1	3	312		Classroom 312	W4	Flaking paint and Gouges above blackboard at wooden dividers	25	No	None		No	N	
52	7110	1	3	313		Classroom 313	W3	Damaged plaster above windows, flaking paint behind radiators	60	No	None		No	Y	
53	7110	1	3	313		Classroom 313	W4	Flaking paint behind radiator, and wall	15	No	None		No	N	
54	7110	1	3	314		Classroom 314	W1	Gouges above blackboard at wooden dividers, Flaking paint on wall	25	No	None		No	N	
55	7110	1	3	314		Classroom 314	W2	Peeling paint at door, Gouges on wooden wall	45	No	None		No	N	
56	7110	1	3	314		Classroom 314	W3	Flaking paint above windows, debris on window sill, flaking paint on wall & behind radiators	50	No	Yes	30	No	Y	
57	7110	1	3	314		Classroom 314	W4	Gouges above blackboard at wooden dividers	20	No	None		No	N	

Harding -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
58	7110	1	3	316		Classroom 316	Ceiling	Damaged plaster and flaking paint observed above drop ceiling through missing ceiling tile	20	No	None		No	Y	
59	7110	1	3	316		Classroom 316	W1	Flaking paint	5	No	None		No	N	
60	7110	1	3	316		Classroom 316	W2	Gouges on the wood wall	20	No	None		No	N	
61	7110	1	3	316		Classroom 316	W3	Efloroscence above windows, flaking paint behind radiators	50	No	None		No	Y	
62	7110	1	3	316		Classroom 316	W4	Gouges on the wood wall	20	No	None		No	N	
63	7110	1	3	318		Classroom 318	W1	Flaking paint and Gouges above blackboard at wooden dividers	25	No	None		No	N	
64	7110	1	3	318		Classroom 318	W3	Flaking paint and damaged plaster above windows, flaking paint on wall & behind radiators	50	No	None		No	Y	
65	7110	1	3	318		Classroom 318	W4	Gouges on Wooden wall	40	No	None		No	N	
66	7110	1	3	319		Classroom 319	W1	Gouges on blackboard at wooden dividers							
67	7110	1	3	319		Classroom 319	W2	Gouges on blackboard at wooden dividers							
68	7110	1	3	319		Classroom 319	W3	Severe peeling paint on wall, and behind radiators (20 SF), Damaged plaster (5 SF) above windows), Debris on window sill	60	No	Yes	30	Computers and furniture need to be moved	Y	
69	7110	1	3	319		Classroom 319	W4	Severe peeling paint on wall, and behind radiators (20 SF), Damaged plaster (5 SF) above windows), Debris on window sill	60	No	Yes	30	Computers and furniture need to be moved	Y	
70	7110	1	3	320		Classroom 320	W1	Gouges above blackboard at wooden dividers, Paint chipping	25	No	None		No	N	
71	7110	1	3	320		Classroom 320	W2	Damaged Plaster, Flaking paint	10	No	None		No	Y	
72	7110	1	3	320		Classroom 320	W3	Flaking paint on walls, and behind radiators (20 SF), Damaged plaster (5 SF), Debris on window sill	30	No	Yes	30	No	Y	
73	7110	1	3	320		Classroom 320	W4	Gouges on blackboard at wooden dividers	20	No	None		No	N	
74	7110	1	3	321		Classroom 321	W1	Gouges above blackboard at wooden dividers	20	No	None		No	N	
75	7110	1	3	321		Classroom 321	W2	Gouges above blackboard at wooden dividers	20	No	None		No	N	
76	7110	1	3	321		Classroom 321	W3	Flaking paint behind radiators (20 SF), Damaged plaster and efloroscence (30 SF), Debris on window sill	50	No	Yes	30	No	Y	
77	7110	1	3	321		Classroom 321	W4	Gouges above blackboard at wooden dividers, Flaking paint	25	No	None		No	N	
78	7110	1	3	322		Classroom 322	Ceiling	Flaking paint above drop ceiling exposed because of moved ceiling tile	16	No	None		No	N	
79	7110	1	3	322		Classroom 322	W3	Flaking paint behind radiators (20 SF), Damaged plaster and efloroscence above windows (30 SF), Debris on window sill	50	No	Yes	30	No	Y	
80	7110	1	3	322		Classroom 322	W4	Gouges above blackboard at wooden dividers	20	No	None		No	N	
81	7110	1	3	323		Classroom 323	W1	Gouges above blackboard at wooden dividers	20	No	None		No	N	
82	7110	1	3	323		Classroom 323	W3	Flaking paint behind radiators (20 SF), Damaged plaster and efloroscence above windows (30 SF)	50	No	None		No	Y	

Harding -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
83	7110	1	3	323		Classroom 323	W4	Gouges above blackboard at wooden dividers	20	No	None		No	N	
84	7110	1	3	324		Classroom 324	W1	Gouges above blackboard at wooden dividers	20	No	None		No	N	
85	7110	1	3	324		Classroom 324	W2	Flaking paint	5	No	None		No	N	
86	7110	1	3	324		Classroom 324	W3	Flaking paint behind radiators, and debris on window sill	20	No	Yes	20	No	N	
87	7110	1	3	324		Classroom 324	W4	Gouges above blackboard at wooden dividers	20	No	None		No	N	
88	7110	1	3	325		Classroom 325	W3	Flaking paint behind radiators (20 SF), Damaged plaster and efflorescence above windows (30 SF)	50	No	None		No	Y	
89	7110	1	3	325		Classroom 325	W4	Flaking paint at column	4	No	None		No	N	
90	7110	1	3	326		Classroom 326	W1	Flaking paint above and below the blackboard, door, Gouges above blackboard at wooden dividers	60	No	None		No	N	
91	7110	1	3	326		Classroom 326	W2	Flaking paint on walls and cracking paint behind radiators	40	No	None		No	N	
92	7110	1	3	326		Classroom 326	W3	Flaking paint behind radiators and above windows	40	No	None		No	N	
93	7110	1	3	311A		Large Storage Closet in Classroom 311	W2	Cracking and Peeling paint	10	No	None		No	N	
94	7110	1	3	311A		Large Storage Closet in Classroom 311	W3	Flaking Paint & peeling paint on pipe	25	No	None		No	N	
95	7110	1	3	311A		Large Storage Closet in Classroom 311	W4	Peeling paint and Damaged plaster	10	No	None		No	Y	
96	7110	1	3	326B		Men's Restroom (toilet area) next to Classroom 326	W4	Flaking paint behind radiator	5	No	None		No	N	
97	7110	1	3	326A		Men's Restroom next to Classroom 326	W3	Flaking paint behind radiator and debris on window sill	8	No	Yes	3	No	N	
98	7110	1	3	311B		Small Storage Closet in Classroom 311	W1	Flaking paint and Damaged Plaster	5	No	None		No	Y	
99	7110	1	3	311B		Small Storage Closet in Classroom 311	W4	Flaking paint and Damaged Plaster	5	No	None		No	Y	
100	7110	1	3	S34		Stairs across from Classroom 306	W2	Damaged Plaster	5	No	No		No	Y	
101	7110	1	3	S32		Stairs Next to Girls Restroom	W2	Efflorescence at column by door	5	No	None		No	Y	
102	7110	1	3	303		Vice Principal Office 303	Ceiling	Flaking paint	10	No	None		No	N	
103	7110	1	3	319C		Women's Restroom (toilet area) next to Classroom 319	Ceiling	Damaged Plaster, Flaking paint	10	No	None		No	Y	
104	7110	1	3	319C		Women's Restroom (toilet area) next to Classroom 319	W3	Damaged Plaster, Flaking paint	10	No	None		No	Y	
105	7110	1	3	319B		Women's Restroom next to Classroom 319	W3	Damaged Plaster (25 SF), Flaking paint behind radiators (10 SF)	35	No	None		No	Y	
106	7110	1	2	H210		2nd Floor Hallways	W1	Peeling paint on wall, and above windows, and behind radiators	120	No	None		No	N	

Harding -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
107	7110	1	2	H211		2nd Floor Hallways	W2	Peeling paint near S21, and behind radiators	30	No	None		No	N	
108	7110	1	2	H212		2nd Floor Hallways	W3	Flaking paint behind radiators	60	No	None		No	N	
109	7110	1	2	228		Auditorium Balcony	Ceiling	Peeling paint	10	No				N	
110	7110	1	2	228		Auditorium Balcony	Floor	Debris, Stair risers	400	No	Yes	100	No	N	
111	7110	1	2	228		Auditorium Balcony	W1	Severe peeling paint	100	No			No	N	
112	7110	1	2	228		Auditorium Balcony	W2	Severe peeling paint	100	No			No	N	
113	7110	1	2	228		Auditorium Balcony	W4	Debris on window sill	30	No	Yes	30	No	N	
114	7110	1	2	200		Boy's Restroom across from Classroom 204	W3	Damaged plaster at window	5	No	None		No	Y	
115	7110	1	2	202		Classroom 202	W1	Flaking paint on wall, Gouges above blackboard at wooden dividers	25	No	None		No	N	
116	7110	1	2	202		Classroom 202	W2	Gouges on wood wall	20	No	None		No	N	
117	7110	1	2	202		Classroom 202	W3	Flaking paint behind radiators, Debris on window sill, peeling paint above windows	50	No	Yes	10	No	N	
118	7110	1	2	204		Classroom 204	W1	Gouges above blackboard at wooden dividers	20	No	None		No	N	
119	7110	1	2	204		Classroom 204	W2	Gouges on wood wall	20	No	None		No	N	
120	7110	1	2	204		Classroom 204	W3	Flaking paint behind radiators, Spalling on wall, peeling paint above windows	50	No	None		No	N	
121	7110	1	2	204		Classroom 204	W4	Gouges on wood wall	20	No	None		No	N	
122	7110	1	2	205		Classroom 205	W1	Gouges above blackboard at wooden dividers	20	No	None		No	N	
123	7110	1	2	205		Classroom 205	W2	Gouges on wood wall	20	No	None		No	N	
124	7110	1	2	205		Classroom 205	W3	Flaking paint behind radiators, Debris on window sill, peeling paint above windows	50	No	Yes	10	No	N	
125	7110	1	2	205		Classroom 205	W4	Gouges on wood wall	20	No	None		No	N	
126	7110	1	2	211		Classroom 211	W1	Damaged plaster and flaking paint	15	No	None		No	Y	
127	7110	1	2	211		Classroom 211	W3	Flaking paint on wall & column, behind radiators	30	No	None		No	N	
128	7110	1	2	211		Classroom 211	W4	Flaking paint behind radiator	10	No	None		No	N	
129	7110	1	2	212		Classroom 212	Floor	Plaster/paint debris	5	No	Y	5	No	N	
130	7110	1	2	212		Classroom 212	W1	Flaking paint	5	No	None		No	N	
131	7110	1	2	212		Classroom 212	W3	Flaking paint and damaged plaster above windows, flaking paint on wall & behind radiators, debris on window sill	70	No	None		No	Y	
132	7110	1	2	214		Classroom 214	W3	Flaking paint above windows, flaking paint on wall & behind radiators	50	No	None		No	N	
133	7110	1	2	214		Classroom 214	W4	Peeling paint	5	No	None		No	N	
134	7110	1	2	214		Classroom 214	W1	Damaged Plaster near windows	5	No	None		No	Y	
135	7110	1	2	215		Classroom 215	W2	Flaking paint	5	No	None		No	N	
136	7110	1	2	216		Classroom 216	Ceiling	Damaged plaster, efflorescence, and peeling paint	20	No	None		No	N	
137	7110	1	2	216		Classroom 216	W1	Gouges above blackboard at wooden dividers	20	No	None		No	N	
138	7110	1	2	216		Classroom 216	W2	Peeling paint	5	No	None		No	N	
139	7110	1	2	216		Classroom 216	W3	Flaking paint behind radiators, Debris on window sill, Damaged plaster above windows	50	No	Yes	10	No	Y	
140	7110	1	2	216		Classroom 216	W4	Gouges on wood wall	20	No	None		No	N	

Harding -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
141	7110	1	2	217		Classroom 217	W1	Gouges above blackboard at wooden dividers, door & frame	40	No	None		No	N	
142	7110	1	2	217		Classroom 217	W2	Gouges above blackboard at wooden dividers	20	No	None		No	N	
143	7110	1	2	217		Classroom 217	W3	Flaking paint above windows, flaking paint on wall & behind radiators	50	No	None		No	N	
144	7110	1	2	217		Classroom 217	W4	Flaking paint and damaged plaster above windows, flaking paint on wall & behind radiators, damaged plaster at window sill	60	No	None		No	Y	
145	7110	1	2	218		Classroom 218	W1	Gouges above blackboard at wooden dividers, door	30	No	None		No	N	
146	7110	1	2	218		Classroom 218	W2	Flaking paint on wall	20	No	None		No	N	
147	7110	1	2	218		Classroom 218	W3	Flaking paint and damaged plaster above windows, flaking paint on wall & behind radiators, damaged plaster at window sill	60	No	None		No	Y	
148	7110	1	2	218		Classroom 218	W4	Gouges above blackboard at wooden dividers	20	No	None		No	N	
149	7110	1	2	219		Classroom 219	W1	Gouges above blackboard at wooden dividers, and wall	25	No	None		No	N	
150	7110	1	2	219		Classroom 219	W2	Flaking paint on wall and above windows	25	No	None		No	N	
151	7110	1	2	219		Classroom 219	W3	Flaking paint and damaged plaster above windows, flaking paint on wall & behind radiators	50	No	None		No	Y	
152	7110	1	2	219		Classroom 219	W4	Gouges above blackboard at wooden dividers	20	No	None		No	N	
153	7110	1	2	220		Classroom 220	Floor	Flaking paint on baseboard	70	No	None		No	N	
154	7110	1	2	220		Classroom 220	W1	Gouges above blackboard at wooden dividers	20	No	None		No	N	
155	7110	1	2	220		Classroom 220	W2	Flaking paint	10	No	None		No	N	
156	7110	1	2	220		Classroom 220	W3	Flaking paint behind radiators, Debris on window sill, Damaged plaster and efflorescence above windows	50	No	Yes	10	No	Y	
157	7110	1	2	220		Classroom 220	W4	Gouges above blackboard at wooden dividers	20	No	None		No	N	
158	7110	1	2	221		Classroom 221	W1	Gouges above blackboard at wooden dividers, and door	30	No	None		No	N	
159	7110	1	2	221		Classroom 221	W2	Flaking paint on wall	20	No	None		No	N	
160	7110	1	2	221		Classroom 221	W3	Flaking paint and efflorescence above windows, flaking paint on wall & behind radiators, debris on window sill (left corner), pipes	60	No	None		No	Y	
161	7110	1	2	221		Classroom 221	W4	Gouges above blackboard at wooden dividers, flaking paint on wall below blackboard	25	No	None		No	N	
162	7110	1	2	222		Classroom 222	W1	Gouges above blackboard at wooden dividers	20	No	None		No	N	
163	7110	1	2	222		Classroom 222	W2	Peeling paint on wall at door	5	No	None		No	N	
164	7110	1	2	222		Classroom 222	W3	Flaking paint and damaged plaster above windows, flaking paint on wall & behind radiators	50	No	None		No	Y	
165	7110	1	2	222		Classroom 222	W4	Gouges above blackboard at wooden dividers, and flaking paint at column at door	25	No	None		No	N	

Harding -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
166	7110	1	2	223		Classroom 223	W1	Gouges above blackboard at wooden dividers	20	No	None		No	N	
167	7110	1	2	223		Classroom 223	W2	Flaking paint on wall	5	No	None		No	N	
168	7110	1	2	223		Classroom 223	W3	Peeling paint above windows, flaking paint behind radiators	50	No	None		No	N	
169	7110	1	2	223		Classroom 223	W4	Gouges above blackboard at wooden dividers	20	No	None		No	N	
170	7110	1	2	224		Classroom 224	W1	Gouges above blackboard at wooden dividers	20	No	None		No	N	
171	7110	1	2	224		Classroom 224	W2	Flaking paint on wall and above windows	25	No	None		No	N	
172	7110	1	2	224		Classroom 224	W3	Flaking paint and damaged plaster above windows, flaking paint on wall & behind radiators	50	No	None		No	Y	
173	7110	1	2	224		Classroom 224	W4	Gouges above blackboard at wooden dividers	20	No	None		No	N	
174	7110	1	2	208G		Conference Room next to Conference Room 208 near Principal's Office	W4	Damaged plaster by the door	10	No	None		No	Y	
175	7110	1	2	206C		Corner Office Closet	W3	Damaged plaster & peeling paint	15	No	None		No	Y	
176	7110	1	2	206D		Corner office in Room 206 next to Nurse Office	W3	Peeling paint above windows	10	No	None		No	N	
177	7110	1	2	215A		Girl's Restroom next to Classroom 215	W3	Damaged Plaster near windows	10	No	None		No	Y	
178	7110	1	2	215A		Girl's Restroom next to Classroom 215	W4	Flaking & Spalling paint	20	No	None		No	Y	
179	7110	1	2	209		Library	W3	Flaking paint behind radiators, Debris on window sill, Damaged plaster above windows	150	No	Yes	40	No	Y	
180	7110	1	2	S27		Main Entrance Lobby and Stairs	Ceiling	Damaged plaster, Peeling paint	10	No	None		No	Y	
181	7110	1	2	208		Main Office	W2	Damaged plaster behind radiators, and above windows	50	No	None		No	Y	
182	7110	1	2	225		Men's Restroom next to Classroom 224	W3	Damaged plaster behind radiator	5	No	None		No	Y	
183	7110	1	2	206F		Nurse's Office Restroom	Ceiling	Efloroscence	2	No	None		No	Y	
184	7110	1	2	203		Office 203A	W3	Damaged plaster above windows, Debris on window sill	30	No	Yes	10	No	Y	
185	7110	1	2	207		Office 207	W2	Damaged plaster	2	No	None		No	N	
186	7110	1	2	207		Office 207	W3	Damaged plaster above windows	10	No	None		No	N	
187	7110	1	2	206E		Office at end of Room 206 Foyer next to Corner Office	Ceiling	Peeling paint on ceiling - seen through the missing ceiling tile	8	No	None		No	N	
188	7110	1	2	208E		Office in Center of Conference Room 208	W4	Damaged plaster	2	No	None		No	Y	
189	7110	1	2	208D		Office to Left of Conference Room 208	W3	Damaged plaster	10	No	None		No	Y	
190	7110	1	2	208D		Office to Left of Conference Room 208	W4	Damaged plaster	2	No	None		No	Y	
191	7110	1	2	208B		Office to Left of Principal's Conference Room	W3	Damaged plaster behind radiators, and efloroscence on wall	30	No	None		No	Y	

Harding -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
192	7110	1	2	208C		Office to Right side of Principal's Conference Room	W1	Damaged plaster by the door	10	No	None		No	Y	
193	7110	1	2	208C		Office to Right side of Principal's Conference Room	W3	Damaged plaster behind radiators, and efflorescence on wall	30	No	None		No	Y	
194	7110	1	2	208A		Principal's Office	W2	Damaged plaster behind radiators, and above windows	50	No	None		No	Y	
195	7110	1	2	208A		Principal's Office	W3	Peeling paint	10	No	None		No	N	
196	7110	1	2	208J		Principal's Office Restroom	W2	Peeling paint	15	No	None		No	N	
197	7110	1	2	208J		Principal's Office Restroom	W3	Flaking paint	5	No	None		No	N	
198	7110	1	2	208J		Principal's Office Restroom	W4	Flaking paint	5	No	None		No	N	
199	7110	1	2	S23		Stairs across from Classroom 202	Ceiling	Severe peeling paint at middle landing	16	No	None		No	N	
200	7110	1	2	S22		Stairs across from Classroom 216	Ceiling	Flaking paint along beam	50	No	None		No	N	
201	7110	1	2	S22		Stairs across from Classroom 216	W2	Flaking paint	50	No	None		No	N	
202	7110	1	2	S22		Stairs across from Classroom 216	W3	Flaking paint	5	No	None		No	N	
203	7110	1	2	S24		Stairs Next to Office 203A	Ceiling	Flaking paint	10	No	None		No	N	
204	7110	1	2	S21		Stairs Next to Office 213	W2	Flaking paint	15	No	None		No	N	
205	7110	1	2	S21		Stairs Next to Office 213	W3	Eflorescence at window	5	No	None		No	Y	
206	7110	1	2	229		Storage Closet across from Classroom 220	Ceiling	No access - padlocked							Inspection Needed
207	7110	1	2	229		Storage Closet across from Classroom 220	Floor	No access - padlocked							Inspection Needed
208	7110	1	2	229		Storage Closet across from Classroom 220	W1	No access - padlocked							Inspection Needed
209	7110	1	2	229		Storage Closet across from Classroom 220	W2	No access - padlocked							Inspection Needed
210	7110	1	2	229		Storage Closet across from Classroom 220	W3	No access - padlocked							Inspection Needed
211	7110	1	2	229		Storage Closet across from Classroom 220	W4	No access - padlocked							Inspection Needed
212	7110	1	2	230		Storage Closet across from Classroom 221	Ceiling	No access - padlocked							Inspection Needed
213	7110	1	2	230		Storage Closet across from Classroom 221	Floor	No access - padlocked							Inspection Needed
214	7110	1	2	230		Storage Closet across from Classroom 221	W1	No access - padlocked							Inspection Needed
215	7110	1	2	230		Storage Closet across from Classroom 221	W2	No access - padlocked							Inspection Needed

Harding -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
216	7110	1	2	230		Storage Closet across from Classroom 221	W3	No access - padlocked							Inspection Needed
217	7110	1	2	230		Storage Closet across from Classroom 221	W4	No access - padlocked							Inspection Needed
218	7110	1	2	209B		Storage Closet in Library near Main Lobby	W1	Peeling paint	10	No	None				
219	7110	1	2	209B		Storage Closet in Library near Main Lobby	W2	Severe Peeling paint	50	No	None				
220	7110	1	2	209B		Storage Closet in Library near Main Lobby	W3	Peeling paint	20	No	None				
221	7110	1	2	209A		Storage Room in Library Left Rear	W1	Peeling paint	20	No	None		No	N	
222	7110	1	2	209A		Storage Room in Library Left Rear	W3	Severe Peeling paint	150	No	None				
223	7110	1	2	216B		Women's Restroom (toilet area) next to Classroom 216	Ceiling	Flaking paint	60	No	None		No	N	
224	7110	1	2	216B		Women's Restroom (toilet area) next to Classroom 216	W1	Flaking paint	5	No	None		No	N	
225	7110	1	2	216B		Women's Restroom (toilet area) next to Classroom 216	W2	Flaking paint on Pipe	12	No	None		No	N	
226	7110	1	2	216B		Women's Restroom (toilet area) next to Classroom 216	W3	Flaking paint	25	No	None		No	N	
227	7110	1	2	216A		Women's Restroom next to Classroom 216	W2	Flaking paint	5	No	None		No	N	
228	7110	1	2	216A		Women's Restroom next to Classroom 216	W3	Flaking paint on wall and behind radiators	25	No	None		No	N	
229	7110	1	2	216A		Women's Restroom next to Classroom 216	W4	Flaking paint on wall and pipe	20	No	None		No	N	
230	7110	1	1	H19		1st Floor Hallways	Floor	peeling paint by water fountain	10						
231	7110	1	1	118		Auditorium	Ceiling	Peeling paint on ceiling under balcony and main ceiling	45	No	None		No	N	
232	7110	1	1	118		Auditorium	W1	Flaking paint	5	No	None		No	N	
233	7110	1	1	118		Auditorium	W2	Flaking paint	5	No	None		No	N	
234	7110	1	1	118		Auditorium	W3	Flaking paint	5	No	None		No	N	
235	7110	1	1	118		Auditorium	W4	Flaking paint	10	No	None		No	N	
236	7110	1	1	118B		Auditorium Stage Left Rear Storage Room	Ceiling	Severe Peeling paint	70	No	None		No	N	
237	7110	1	1	118B		Auditorium Stage Left Rear Storage Room	Floor	Debris	25	No	None		No	N	
238	7110	1	1	118B		Auditorium Stage Left Rear Storage Room	W1	Severe Peeling paint	50	No	None		No	N	
239	7110	1	1	118B		Auditorium Stage Left Rear Storage Room	W2	Severe Peeling paint	50	No	None		No	N	

Harding -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
240	7110	1	1	118B		Auditorium Stage Left Rear Storage Room	W3	Severe Peeling paint	50	No	None		No	N	
241	7110	1	1	118B		Auditorium Stage Left Rear Storage Room	W4	Severe Peeling paint on wall and pipe	60	No	None		No	N	
242	7110	1	1	118C		Auditorium Stage Right Rear Storage Room	Ceiling	Severe Peeling paint	70	No	None		No	N	
243	7110	1	1	118C		Auditorium Stage Right Rear Storage Room	Floor	Debris	25	No	None		No	N	
244	7110	1	1	118C		Auditorium Stage Right Rear Storage Room	W1	Severe Peeling paint	50	No	None		No	N	
245	7110	1	1	118C		Auditorium Stage Right Rear Storage Room	W2	Severe Peeling paint	50	No	None		No	N	
246	7110	1	1	118C		Auditorium Stage Right Rear Storage Room	W3	Severe Peeling paint	50	No	None		No	N	
247	7110	1	1	118C		Auditorium Stage Right Rear Storage Room	W4	Severe Peeling paint on wall and pipe	60	No	None		No	N	
248	7110	1	1	120		Boy's Cafeteria	Ceiling	Severe peeling paint on ceiling & Efflorescence near doors to hallway	35	No	None		No	Yes	
249	7110	1	1	120		Boy's Cafeteria	W1	Peeling paint on pipes (3)	18	No	None		No	N	
250	7110	1	1	120A		Boy's Cafeteria Food Counter Area	Ceiling	Severe peeling paint on ceiling and ductwork	35	No	None		No	N	
251	7110	1	1	120D		Boy's Cafeteria Storage Closet Near Entrance	Ceiling	Severe peeling paint	20	No	None		No	N	
252	7110	1	1	120D		Boy's Cafeteria Storage Closet Near Entrance	W1	Flaking paint	5	No	None		No	N	
253	7110	1	1	120D		Boy's Cafeteria Storage Closet Near Entrance	W2	Flaking paint	5	No	None		No	N	
254	7110	1	1	120D		Boy's Cafeteria Storage Closet Near Entrance	W3	Flaking paint	5	No	None		No	N	
255	7110	1	1	120D		Boy's Cafeteria Storage Closet Near Entrance	W4	Flaking paint	5	No	None		No	N	
256	7110	1	1	121A		Boy's Gym Teacher Office	Ceiling	Severe peeling paint on Pipes	40						
257	7110	1	1	121A		Boy's Gym Teacher Office	W1	Peeling paint	10						
258	7110	1	1	121A		Boy's Gym Teacher Office	W3	Peeling paint	10						
259	7110	1	1	121		Boy's Gymnasium	Ceiling	Peeling paint on ceiling, metal trusses, pipes	250	No	None		No	N	
260	7110	1	1	121		Boy's Gymnasium	Floor	Damaged floor	40	No	None		No	N	
261	7110	1	1	121		Boy's Gymnasium	W1	Peeling paint on wall and pipe	40	No	None		No	N	
262	7110	1	1	121D		Boy's Locker Room near Gym on Mezzanine	W1	Peeling paint on Pipe	12						

Harding -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
263	7110	1	1	121C		Boy's Locker Room Storage Room on Mezzanine	W1	Severe peeling paint	20						
264	7110	1	1	101A		Boy's Restroom across from Classroom 102	Ceiling	Damaged plaster	2	No	None		No	Y	
265	7110	1	1	101A		Boy's Restroom across from Classroom 102	Floor	Flaking paint	30	No	None		No	N	
266	7110	1	1	102		Classroom 102	Ceiling	Peeling paint	100	No	None		No	N	
267	7110	1	1	102		Classroom 102	W1	Gouges above blackboard at wooden dividers, and pipe	22	No	None		No	N	
268	7110	1	1	103		Classroom 103	W1	Flaking paint at closet (drywall)	5	No	None		No	N	
269	7110	1	1	104		Classroom 104	Ceiling	Damaged plaster and peeling paint above windows (visible through missing ceiling tile)	8	No	None		No	Y	
270	7110	1	1	104		Classroom 104	W3	Flaking paint behind radiator	10	No	None		No	N	
271	7110	1	1	104A		Classroom 104 Closet	W2	Flaking paint behind radiator	10	No	None		No	N	
272	7110	1	1	105		Classroom 105A	W1	Flaking paint above windows	2	No	None		No	N	
273	7110	1	1	105		Classroom 105A	W2	Damaged plaster and debris on sill	30	No	Yes	15	No	No	
274	7110	1	1	105		Classroom 105A	W3	Peeling paint above windows, and debris on sill		No	Yes	20	No	N	
275	7110	1	1	105A		Classroom 105B	W4	Peeling paint on wall, above windows, on pipe	30	No	None		No	N	
276	7110	1	1	106		Classroom 106A	W2	Peeling paint	20	No	None		No	N	
277	7110	1	1	106A		Classroom 106A Storage Closet with windows	Ceiling	No access							Inspection Needed
278	7110	1	1	106A		Classroom 106A Storage Closet with windows	Floor	No access							Inspection Needed
279	7110	1	1	106A		Classroom 106A Storage Closet with windows	W1	No access							Inspection Needed
280	7110	1	1	106A		Classroom 106A Storage Closet with windows	W2	No access							Inspection Needed
281	7110	1	1	106A		Classroom 106A Storage Closet with windows	W3	No access							Inspection Needed
282	7110	1	1	106A		Classroom 106A Storage Closet with windows	W4	No access							Inspection Needed
283	7110	1	1	106B		Classroom 106A Storage Closet without Windows	Ceiling	No access							Inspection Needed
284	7110	1	1	106B		Classroom 106A Storage Closet without Windows	Floor	No access							Inspection Needed
285	7110	1	1	106B		Classroom 106A Storage Closet without Windows	W1	No access							Inspection Needed
286	7110	1	1	106B		Classroom 106A Storage Closet without Windows	W2	No access							Inspection Needed
287	7110	1	1	106B		Classroom 106A Storage Closet without Windows	W3	No access							Inspection Needed

Harding -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
288	7110	1	1	106B		Classroom 106A Storage Closet without Windows	W4	No access							Inspection Needed
289	7110	1	1	107		Classroom 107	W3	Flaking paint above windows	20	No	None		No	N	
290	7110	1	1	107C		Classroom 107 Storage Closet left side	Ceiling	No access							Inspection Needed
291	7110	1	1	107C		Classroom 107 Storage Closet left side	Floor	No access							Inspection Needed
292	7110	1	1	107C		Classroom 107 Storage Closet left side	W1	No access							Inspection Needed
293	7110	1	1	107C		Classroom 107 Storage Closet left side	W2	No access							Inspection Needed
294	7110	1	1	107C		Classroom 107 Storage Closet left side	W3	No access							Inspection Needed
295	7110	1	1	107C		Classroom 107 Storage Closet left side	W4	No access							Inspection Needed
296	7110	1	1	107D		Classroom 107 Storage Closet on the right side	Ceiling	Peeling paint (lower ceiling)	20	No	None		No	N	
297	7110	1	1	107D		Classroom 107 Storage Closet on the right side	W2	Severe peeling paint	50	No	None		No	N	
298	7110	1	1	107D		Classroom 107 Storage Closet on the right side	W3	Severe peeling paint	50	No	None		No	N	
299	7110	1	1	107D		Classroom 107 Storage Closet on the right side	W4	Severe peeling paint	100	No	None		No	N	
300	7110	1	1	107B		Classroom 107 Storage Closet With Windows	Ceiling	No access							Inspection Needed
301	7110	1	1	107B		Classroom 107 Storage Closet With Windows	Floor	No access							Inspection Needed
302	7110	1	1	107B		Classroom 107 Storage Closet With Windows	W1	No access							Inspection Needed
303	7110	1	1	107B		Classroom 107 Storage Closet With Windows	W2	No access							Inspection Needed
304	7110	1	1	107B		Classroom 107 Storage Closet With Windows	W3	No access							Inspection Needed
305	7110	1	1	107B		Classroom 107 Storage Closet With Windows	W4	No access							Inspection Needed
306	7110	1	1	108		Classroom 108	W1	Control panel by door, drywall wall	10	No	None		No	N	
307	7110	1	1	108		Classroom 108	W3	Severe peeling paint above windows, Debris on window sill	100	No	Yes	50	No	N	
308	7110	1	1	108A		Classroom 108 Restroom	W4	Peeling paint on drywall next to mirror	4	No	None		No	N	

Harding -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
309	7110	1	1	108B		Classroom 108 Storage Closet With Windows	Ceiling	No access							Inspection Needed
310	7110	1	1	108B		Classroom 108 Storage Closet With Windows	Floor	No access							Inspection Needed
311	7110	1	1	108B		Classroom 108 Storage Closet With Windows	W1	No access							Inspection Needed
312	7110	1	1	108B		Classroom 108 Storage Closet With Windows	W2	No access							Inspection Needed
313	7110	1	1	108B		Classroom 108 Storage Closet With Windows	W3	No access							Inspection Needed
314	7110	1	1	108B		Classroom 108 Storage Closet With Windows	W4	No access							Inspection Needed
315	7110	1	1	108C		Classroom 108 Storage near front of class	Ceiling	No access							Inspection Needed
316	7110	1	1	108C		Classroom 108 Storage near front of class	Floor	No access							Inspection Needed
317	7110	1	1	108C		Classroom 108 Storage near front of class	W1	No access							Inspection Needed
318	7110	1	1	108C		Classroom 108 Storage near front of class	W2	No access							Inspection Needed
319	7110	1	1	108C		Classroom 108 Storage near front of class	W3	No access							Inspection Needed
320	7110	1	1	108C		Classroom 108 Storage near front of class	W4	No access							Inspection Needed
321	7110	1	1	109		Classroom 109	W2	Peeling paint on wall, and above windows, and debris on window sill	30	No	Yes	10	No	N	
322	7110	1	1	109		Classroom 109	W3	Peeling paint on wall, and above windows, and debris on window sill	30	No	Yes	10	No	N	
323	7110	1	1	110		Classroom 110	Ceiling	Severe peeling paint - visible through missing ceiling tile	20	No	None		No	N	
324	7110	1	1	110		Classroom 110	W3	Severe peeling paint above windows, Debris on window sill	50	No	Yes	20	No	N	
325	7110	1	1	110A		Classroom 110 Storage Closet	Ceiling	No access							Inspection Needed
326	7110	1	1	110A		Classroom 110 Storage Closet	Floor	No access							Inspection Needed
327	7110	1	1	110A		Classroom 110 Storage Closet	W1	No access							Inspection Needed
328	7110	1	1	110A		Classroom 110 Storage Closet	W2	No access							Inspection Needed
329	7110	1	1	110A		Classroom 110 Storage Closet	W3	No access							Inspection Needed
330	7110	1	1	110A		Classroom 110 Storage Closet	W4	No access							Inspection Needed
331	7110	1	1	111		Classroom 111	W1	Flaking paint (blue paint)	20	No	None		No	N	
332	7110	1	1	112		Classroom 112	Ceiling	Severe peeling paint - visible through missing ceiling tile	20	No	None		No	N	

Harding -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
333	7110	1	1	112		Classroom 112	Floor	Debris on floor, table, and books	30	No	Yes	30	No	N	
334	7110	1	1	112		Classroom 112	W3	Severe peeling paint on wall and flaking paint behind radiators	40	No	None		No	N	
335	7110	1	1	113		Classroom 113	Ceiling	Peeling paint along window wall (visible through missing ceiling tiles)	20	No	None		No	N	
336	7110	1	1	113		Classroom 113	W3	Peeling paint above windows	20	No	None		No	N	
337	7110	1	1	112A		Classroom 114	W3	Damaged plaster above windows, Peeling paint on wall and flaking paint behind radiators	60	No	None		No	Y	
338	7110	1	1	112A		Classroom 114	W4	Flaking paint	5	No	None		No	N	
339	7110	1	1	101B		Closet in Classroom 101/ Police Room	Ceiling	Severe peeling paint	10	No	None		No	N	
340	7110	1	1	102A		Closet in Classroom 102	W4	Peeling paint	5	No	None		No	N	
341	7110	1	1	106D		Closet in Office 106B	Ceiling	No access							Inspection Needed
342	7110	1	1	106D		Closet in Office 106B	Floor	No access							Inspection Needed
343	7110	1	1	106D		Closet in Office 106B	W1	No access							Inspection Needed
344	7110	1	1	106D		Closet in Office 106B	W2	No access							Inspection Needed
345	7110	1	1	106D		Closet in Office 106B	W3	No access							Inspection Needed
346	7110	1	1	106D		Closet in Office 106B	W4	No access							Inspection Needed
347	7110	1	1	100A		Corner Custodial Clock in and out Office	Ceiling	Severe peeling paint	200	No	None		No	N	
348	7110	1	1	100A		Corner Custodial Clock in and out Office	W1	Severe peeling paint	100	No	None		No	N	
349	7110	1	1	100A		Corner Custodial Clock in and out Office	W2	Severe peeling paint	60	No	None		No	N	
350	7110	1	1	100A		Corner Custodial Clock in and out Office	W3	Severe peeling paint	60	No	None		No	N	
351	7110	1	1	100A		Corner Custodial Clock in and out Office	W4	Severe peeling paint	100	No	None		No	N	
352	7110	1	1	S19-1		Fire Escape Stairs throughout near Margaret Street Side	Ceiling	Peeling and Flaking paint	100	No	None		N	N	
353	7110	1	1	S19-1		Fire Escape Stairs throughout near Margaret Street Side	W1	Peeling and Flaking paint	100	No	None		N	N	
354	7110	1	1	S19-1		Fire Escape Stairs throughout near Margaret Street Side	W2	Peeling and Flaking paint	100	No	None		N	N	
355	7110	1	1	S19-1		Fire Escape Stairs throughout near Margaret Street Side	W3	Peeling and Flaking paint on wall and window	150	No	None		N	N	
356	7110	1	1	S19-1		Fire Escape Stairs throughout near Margaret Street Side	W4	Peeling and Flaking paint	100	No	None		N	N	

Harding -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
357	7110	1	1	S19-1		Fire Escape Stairs throughout near Wakeling Street Side	Ceiling	Peeling and Flaking paint	10	No	None		N	N	
358	7110	1	1	S19-1		Fire Escape Stairs throughout near Wakeling Street Side	W1	Peeling and Flaking paint	20	No	None		N	N	
359	7110	1	1	S19-1		Fire Escape Stairs throughout near Wakeling Street Side	W2	Peeling and Flaking paint	20	No	None		N	N	
360	7110	1	1	S19-1		Fire Escape Stairs throughout near Wakeling Street Side	W3	Peeling and Flaking paint on wall and window	150	No	None		N	N	
361	7110	1	1	S19-1		Fire Escape Stairs throughout near Wakeling Street Side	W4	Peeling and Flaking paint	20	No	None		N	N	
362	7110	1	1	117B		Front Storage Closet in Gym next to Doors	W1	Peeling paint along bottom course of brick	20						
363	7110	1	1	116		Girl's Cafeteria	W1	Peeling paint on pipe at entrance door	4	No	None		No	N	
364	7110	1	1	116		Girl's Cafeteria	W3	Peeling paint on pipe at exit door	12	No	None		No	N	
365	7110	1	1	116A		Girl's Cafeteria Food Counter Area	Ceiling	Peeling paint	10	No	None		No	N	
366	7110	1	1	116D		Girl's Cafeteria Storage Closet Near Entrance	W1	Flaking paint	10	No	None		No	N	
367	7110	1	1	116D		Girl's Cafeteria Storage Closet Near Entrance	W2	Flaking paint	50	No	None		No	N	
368	7110	1	1	116D		Girl's Cafeteria Storage Closet Near Entrance	W3	Flaking paint	10	No	None		No	N	
369	7110	1	1	116D		Girl's Cafeteria Storage Closet Near Entrance	W4	Flaking paint	5	No	None		No	N	
370	7110	1	1	117A		Girl's Gym Locker Room on Mezzanine	W2	Peeling paint on window frames	30						
371	7110	1	1	117G		Girl's Gym Locker Room Rest Room on Mezzanine	Ceiling	Peeling paint	25						
372	7110	1	1	117F		Girl's Gym Locker Room Supply Room on Mezzanine	Ceiling	Peeling paint	20						
373	7110	1	1	117F		Girl's Gym Locker Room Supply Room on Mezzanine	W4	Peeling paint on pipe	12						
374	7110	1	1	S19		Girl's Gym Stairs	W2	Severe peeling paint	10						
375	7110	1	1	117		Girl's Gymnasium	Ceiling	Peeling paint on ceiling, metal trusses, pipes	250	No					
376	7110	1	1	117		Girl's Gymnasium	Floor	Damaged floor	40	No					
377	7110	1	1	117		Girl's Gymnasium	W1	Peeling paint on wall and pipe	40	No					
378	7110	1	1	H6		Hallway to Left of Auditorium	Floor	Debris	30	No	None		No	N	

Harding -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
379	7110	1	1	H6		Hallway to Left of Auditorium	W2	Efloroscence on wall and above windows	80	No	None		No	Y	
380	7110	1	1	H15		Hallway to Right of Auditorium	Floor	Debris on floor and chair	25	No	None		No	N	
381	7110	1	1	H15		Hallway to Right of Auditorium	W4	Efloroscence above windows	30	No	None		No	Y	
382	7110	1	1	119		Kitchen	Ceiling	Severe peeling paint on ceiling and ductwork	75	No	None		No	N	
383	7110	1	1	119		Kitchen	W1	Peeling paint in the middle of the room at the column, and on pipes	45	No	None		No	N	
384	7110	1	1	119		Kitchen	W3	Flaking paint on pipe	6	No	None		No	N	
385	7110	1	1	119		Kitchen	W4	Peeling paint	15	No	None		No	N	
386	7110	1	1	119A		Kitchen Large Center Storage Area	W1	Peeling paint on brick, and metal support at screen	10	No	None		No	N	
387	7110	1	1	119B		Kitchen Small Storage Room	W1	Severe Peeling paint	25	No	None		No	N	
388	7110	1	1	S17		Main Lobby Stairs	Ceiling	Peeling paint	5	No	None		No	N	
389	7110	1	1	106C		Men's Restroom in Main Lobby	W2	Cracking paint	5	No	None		No	N	
390	7110	1	1	119C		Office in Kitchen	Ceiling	No access							Inspection Needed
391	7110	1	1	119C		Office in Kitchen	Floor	No access							Inspection Needed
392	7110	1	1	119C		Office in Kitchen	W1	No access							Inspection Needed
393	7110	1	1	119C		Office in Kitchen	W2	No access							Inspection Needed
394	7110	1	1	119C		Office in Kitchen	W3	No access							Inspection Needed
395	7110	1	1	119C		Office in Kitchen	W4	No access							Inspection Needed
396	7110	1	1	114		Principal's Restroom near exit to Wakeling Street on 1st Floor	Ceiling	Severe peeling paint	200	No	None		No	N	
397	7110	1	1	114		Principal's Restroom near exit to Wakeling Street on 1st Floor	Floor	Debris	70	No	Yes	70	No	N	
398	7110	1	1	114		Principal's Restroom near exit to Wakeling Street on 1st Floor	W1	Severe peeling paint	50	No	None		No	N	
399	7110	1	1	114		Principal's Restroom near exit to Wakeling Street on 1st Floor	W2	Severe peeling paint	100	No	None		No	N	
400	7110	1	1	114		Principal's Restroom near exit to Wakeling Street on 1st Floor	W3	Severe peeling paint	50	No	None		No	N	
401	7110	1	1	114		Principal's Restroom near exit to Wakeling Street on 1st Floor	W4	Severe peeling paint	100	No	None		No	N	
402	7110	1	1	100B		Restroom in Corner Custodial Clock in and out Office	Ceiling	Severe peeling paint	Good						
403	7110	1	1	100B		Restroom in Corner Custodial Clock in and out Office	Floor	Severe peeling paint	30	No	None		No	N	
404	7110	1	1	100B		Restroom in Corner Custodial Clock in and out Office	W1	Severe peeling paint	10	No	None		No	N	

Harding -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
405	7110	1	1	100B		Restroom in Corner Custodial Clock in and out Office	W2	Severe peeling paint	30	No	None		No	N	
406	7110	1	1	100B		Restroom in Corner Custodial Clock in and out Office	W3	Severe peeling paint	50	No	None		No	N	
407	7110	1	1	100B		Restroom in Corner Custodial Clock in and out Office	W4	Severe peeling paint	30	No	None		No	N	
408	7110	1	1	119B		Restroom/lockers in Kitchen	Ceiling	No access							Inspection Needed
409	7110	1	1	119B		Restroom/lockers in Kitchen	Floor	No access							Inspection Needed
410	7110	1	1	119B		Restroom/lockers in Kitchen	W1	No access							Inspection Needed
411	7110	1	1	119B		Restroom/lockers in Kitchen	W2	No access							Inspection Needed
412	7110	1	1	119B		Restroom/lockers in Kitchen	W3	No access							Inspection Needed
413	7110	1	1	119B		Restroom/lockers in Kitchen	W4	No access							Inspection Needed
414	7110	1	1	118A		Stage	Ceiling	Peeling paint	30	No	None		No	N	
415	7110	1	1	118A		Stage	W1	Flaking paint and peeling paint on wall and front columns	30	No	None		No	N	
416	7110	1	1	S13		Stairs across from Classroom 102	Ceiling	Peeling paint	30	No	None		No	N	
417	7110	1	1	S14		Stairs across from Classroom 104	Ceiling	Peeling paint	5	No	None		No	N	
418	7110	1	1	S11		Stairs across from Classroom 110	Ceiling	Peeling paint	20	No	None		No	N	
419	7110	1	1	115		Storage Area to left of Walking Street Exit	Ceiling	Flaking paint	30	No	None		No	N	
420	7110	1	1	115		Storage Area to left of Walking Street Exit	W1	Flaking paint	10	No	None		No	N	
421	7110	1	1	115		Storage Area to left of Walking Street Exit	W2	Flaking paint	10	No	None		No	N	
422	7110	1	1	115		Storage Area to left of Walking Street Exit	W3	Flaking paint	30	No	None		No	N	
423	7110	1	1	115		Storage Area to left of Walking Street Exit	W4	Flaking paint	10	No	None		No	N	
424	7110	1	1	101B		Storage Closet across from Classroom 102	Ceiling	Severe peeling paint	25	No	None		No	N	
425	7110	1	1	101B		Storage Closet across from Classroom 102	W1	Severe peeling paint	10	No	None		No	N	
426	7110	1	1	101B		Storage Closet across from Classroom 102	W2	Peeling paint on pipe	12	No	None		No	N	
427	7110	1	1	101B		Storage Closet across from Classroom 102	W3	Severe peeling paint	20	No	None		No	N	

Harding -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
428	7110	1	1	101B		Storage Closet across from Classroom 102	W4	Severe peeling paint	20	No	None		No	N	
429	7110	1	1	117E		Storage Closet in Rear of Gym	Ceiling	Severe peeling paint on Pipes	40						
430	7110	1	1	117E		Storage Closet in Rear of Gym	W1	Peeling paint	10						
431	7110	1	1	113E		Storage Closet in Stairs across from Classroom 114	W3	Peeling paint	15						
432	7110	1	1	113E		Storage Closet in Stairs across from Classroom 114	W4	Peeling paint	15						
433	7110	1	1	109A		Storage in Classroom 109	Floor	Debris at window	6	No	Yes	6	No	N	
434	7110	1	1	109A		Storage in Classroom 109	W3	Peeling paint on wall, and above windows, and debris on window sill	30	No	Yes	10	No	N	
435	7110	1	1	109A		Storage in Classroom 109	W4	Cracking paint	5	No	None		No	N	
436	7110	1	1	121B		Storage in Front of Boy's Gym	Ceiling	Severe peeling paint	30						
437	7110	1	1	121B		Storage in Front of Boy's Gym	W1	Peeling paint & damaged plaster at door	30					Yes	
438	7110	1	1	121B		Storage in Front of Boy's Gym	W2	Severe peeling paint	20						
439	7110	1	1	121B		Storage in Front of Boy's Gym	W3	Severe peeling paint	40						
440	7110	1	1	121B		Storage in Front of Boy's Gym	W4	Severe peeling paint	20						
441	7110	1	1	NP5		Storage Room in Girl's Cafetorium Rear	Ceiling	No access							Inspection Needed
442	7110	1	1	NP5		Storage Room in Girl's Cafetorium Rear	Floor	No access							Inspection Needed
443	7110	1	1	NP5		Storage Room in Girl's Cafetorium Rear	W1	No access							Inspection Needed
444	7110	1	1	NP5		Storage Room in Girl's Cafetorium Rear	W2	No access							Inspection Needed
445	7110	1	1	NP5		Storage Room in Girl's Cafetorium Rear	W3	No access							Inspection Needed
446	7110	1	1	NP5		Storage Room in Girl's Cafetorium Rear	W4	No access							Inspection Needed