

Heston -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	4300	1	3	326		Book Closet near Elevator	W1	Partially Inaccessible	0	N	N	0	Y - 120 SF Bookcases, Books	N	
2	4300	1	3	326		Book Closet near Elevator	W2	Cracking	4	N	N	0	Y - 210 SF Bookcases, Books	N	
3	4300	1	3	326		Book Closet near Elevator	W3	Cracking	4	N	N	0	Y - 110 SF Bookcases, Books	N	
4	4300	1	3	326		Book Closet near Elevator	W4	Flaking	14	N	N	0	Y - 90 SF Books, Boxes, Contents	N	Additional Cracking, Chipping
5	4300	1	3	301		Classroom 301 - Science	W1	Partially Inaccessible	0	N	N	0	Y - 40 SF Bookcases, Contents	N	
6	4300	1	3	301A		Classroom 301 - Storage Room	W1	Cracking	5	N	N	0	Y - 96 SF Shelves, Boxes, Contents	N	
7	4300	1	3	301A		Classroom 301 - Storage Room	W2	Partially Inaccessible	0	N	N	0	Y - 60 SF Boxes, Contents	N	
8	4300	1	3	301A		Classroom 301 - Storage Room	W3	Cracking	16	N	N	0	Y - 60 SF Boxes, Contents	N	
9	4300	1	3	302		Classroom 302	W1	Cracking	5	N	N	0	N	N	3 Locations; Additional Chipping
10	4300	1	3	302		Classroom 302	W3	Flaking	10	N	N	0	N	N	3 Locations; Additional Cracking, Chipping
11	4300	1	3	302		Classroom 302	W4	Flaking	5	N	N	0	N	N	
12	4300	1	3	304		Classroom 304 - Computers	W3	Cracking	4	N	N	0	N	N	
13	4300	1	3	304		Classroom 304 - Computers	W4	Cracking	30	N	N	0	N	N	Cracking Near Ceiling
14	4300	1	3	306		Classroom 306	W1	Cracking	7	N	N	0	N	N	
15	4300	1	3	306		Classroom 306	W2	Chipping	2	N	N	0	N	N	
16	4300	1	3	306		Classroom 306	W3	Chipping	7	N	N	0	N	N	
17	4300	1	3	306		Classroom 306	W4	Chipping	2	N	N	0	N	N	
18	4300	1	3	308		Classroom 308	W3	Chipping	7	N	N	0	N	N	Chipping @ Air Unit
19	4300	1	3	308		Classroom 308	W4	Cracking	2	N	N	0	N	N	
20	4300	1	3	310		Classroom 310	W1	Flaking	3	N	N	0	N	N	2 Locations; Additional Chipping
21	4300	1	3	310		Classroom 310	W2	Faking	1	N	N	0	N	N	Flaking @ Conduit
22	4300	1	3	310		Classroom 310	W4	Flaking	2	N	N	0	N	N	2 Locations; Additional Chipping; Damage Near Floor
23	4300	1	3	312		Classroom 312	Ceiling	Cracking	2	N	N	0	N	N	
24	4300	1	3	312		Classroom 312	W1	Chipping	1	N	N	0	N	N	
25	4300	1	3	312		Classroom 312	W3	Flaking	7	N	N	0	N	N	Additional Chipping; Damage @ Air Unit
26	4300	1	3	312		Classroom 312	W4	Flaking	2	N	N	0	N	N	Additional Chipping; Damage @ Door Frame
27	4300	1	3	314		Classroom 314	W1	Cracking	5	N	N	0	N	N	3 Locations; Additional Chipping, Holes
28	4300	1	3	314		Classroom 314	W4	Cracking	2	N	N	0	N	N	
29	4300	1	3	318		Classroom 318	W2	Chipping	2	N	N	0	N	N	

Heston -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
30	4300	1	3	320		Classroom 320	W1	Partially Inaccessible	0	N	N	0	Y - 200 SF Desks, Tables, Posters, Contents	N	
31	4300	1	3	320		Classroom 320	W2	Flaking	6	N	N	0	N	N	Additional Cracking
32	4300	1	3	322		Classroom 322	W1	Cracking	3	N	N	0	N	N	2 Locations; Additional Chipping
33	4300	1	3	322		Classroom 322	W3	Cracking	3	N	N	0	Y - 84 SF Cabinets	N	
34	4300	1	3	328		Classroom 328	W1	Cracking	14	N	N	0	N	N	
35	4300	1	3	328		Classroom 328	W2	Partially Inaccessible	0	N	N	0	Y - 60 SF Desks, Boxes	N	
36	4300	1	3	328		Classroom 328	W3	Cracking	13	N	N	0	Y - 60 SF Boxes, Contents	N	
37	4300	1	3	328		Classroom 328	W4	Cracking	6	N	N	0	Y - 24 SF Boxes, Bookcases, Contents	N	
38	4300	1	3	309		Girl's Restroom	W3	Chipping	16	N	N	0	N	N	Chipping on Stall Doors
39	4300	1	3	H33		Hallway from Girl's Restroom to Stairwell S31	W4	Chipping	2	N	N	0	N	N	Chipping Near Floor
40	4300	1	3	H33		Hallway from Girl's Restroom to Stairwell S31	W1	Chipping	3	N	N	0	N	N	Chipping Near Floor; Wall 1 Facing IMC
41	4300	1	3	H33		Hallway from Girl's Restroom to Stairwell S31	W2	Chipping	2	N	N	0	N	N	Chipping Near Floor
42	4300	1	3	H33		Hallway from Girl's Restroom to Stairwell S31	W3	Flaking	8	N	N	0	N	N	Additional Chipping
43	4300	1	3	H31		Hallway from Stairwell S31 to Classroom 308	W1	Flaking	48	N	N	0	N	N	Additional Chipping; Damage Near Floor; Wall 1 300-308
44	4300	1	3	H31		Hallway from Stairwell S31 to Classroom 308	W2	Chipping	2	N	N	0	N	N	
45	4300	1	3	H31		Hallway from Stairwell S31 to Classroom 308	W3	Flaking	45	N	N	0	N	N	Additional Chipping
46	4300	1	3	H32		Hallway from Stairwell S32 to Stairwell S33	W2	Flaking	1	N	N	0	N	N	Additional Chipping; Damage Near Floor
47	4300	1	3	H32		Hallway from Stairwell S32 to Stairwell S33	W3	Flaking	15	N	N	0	N	N	Additional Chipping; Damage Near Floor
48	4300	1	3	305		Men's Restroom	Ceiling	Cracking	2	N	N	0	N	N	New Paint
49	4300	1	3	305		Men's Restroom	W4	Cracking	10	N	N	0	N	N	New Paint
50	4300	1	3	300		Room 300 Teacher's Lounge	W1	Cracking	1	N	N	0	N	N	
51	4300	1	3	300		Room 300 Teacher's Lounge	W3	Flaking	1	N	N	0	N	N	Additional Chipping
52	4300	1	3	300		Room 300 Teacher's Lounge	W4	Chipping	1	N	N	0	N	N	
53	4300	1	3	S31		Stairwell near Classroom 328	Center Banister	Chipping	7	N	N	0	N	N	
54	4300	1	3	S31		Stairwell near Classroom 328	Floor	Chipping	5	N	N	0	N	N	

Heston -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
55	4300	1	3	S31		Stairwell near Classroom 328	W2	Chipping	1	N	N	0	N	N	
56	4300	1	3	S31		Stairwell near Classroom 328	W3	Chipping	1	N	N	0	N	N	
57	4300	1	3	S31		Stairwell near Classroom 328	W4	Cracking	7	N	N	0	N	N	
58	4300	1	3	S32		Stairwell next to Classroom 308	Ceiling	Gouges	1	N	N	0	N	N	
59	4300	1	3	S32		Stairwell next to Classroom 308	Center Banister	Chipping	6	N	N	0	N	N	
60	4300	1	3	S32		Stairwell next to Classroom 308	Floor	Chipping	6	N	N	0	N	N	
61	4300	1	3	S32		Stairwell next to Classroom 308	W2	Holes	1	N	N	0	N	N	
62	4300	1	3	S32		Stairwell next to Classroom 308	W3	Flaking	4	N	N	0	N	N	
63	4300	1	3	S32		Stairwell next to Classroom 308	W4	Chipping	1	N	N	0	N	N	
64	4300	1	3	S33		Stairwell next to Classroom 322	Center Banister	Chipping	2	N	N	N	N	N	
65	4300	1	3	S33		Stairwell next to Classroom 322	Floor	Chipping	4	N	N	N	N	N	
66	4300	1	3	S33		Stairwell next to Classroom 322	W3	Cracking	5	N	N	N	N	N	
67	4300	1	3	318A		Storage Room between Classrooms 314 and 318	W1	Flaking	30	N	N	0	Y - 80 SF Books, Boxes, Contents	N	
68	4300	1	3	318A		Storage Room between Classrooms 314 and 318	W2	Flaking	40	N	N	0	Y - 54 SF Bookcases, Books	N	
69	4300	1	3	318A		Storage Room between Classrooms 314 and 318	W3	Flaking	35	N	N	0	Y - 21 SF Bookcases, Boxes, Contents	N	
70	4300	1	3	318A		Storage Room between Classrooms 314 and 318	W4	Flaking	40	N	N	0	Y - 24 SF Bookcases, File Cabinets, Boxes, Contents	N	
71	4300	1	3	316A		Storage Room between Classrooms 316 and 320	W1	Flaking	120	N	N	0	Y - 40 SF Contents	N	
72	4300	1	3	316A		Storage Room between Classrooms 316 and 320	W2	Flaking	36	N	N	0	Y - 36 SF Boxes, Contents	N	
73	4300	1	3	316A		Storage Room between Classrooms 316 and 320	W3	Flaking	120	N	N	0	Y - 80 SF Bookcases, Boxes	N	
74	4300	1	3	316A		Storage Room between Classrooms 316 and 320	W4	Flaking	150	N	N	0	Y - 70 SF Bookcases, Boxes, Contents	N	
75	4300	1	3	303		Women's Restroom	Ceiling	Flaking	1	N	N	0	N	N	Flaking Above Door
76	4300	1	2	223A		Boys' Restroom	W1	Chipping	2	N	N	0	N	N	Chipping @ Door Frame

Heston -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
77	4300	1	2	223A		Boys' Restroom	W2	Holes	1	N	N	0	N	N	
78	4300	1	2	202		Classroom 202	W1	Chipping	20	N	N	0	N	N	2 Locations; Chipping @ Corner & Near Floor
79	4300	1	2	202		Classroom 202	W2	Chipping	30	N	N	0	N	N	Chipping Near Floor
80	4300	1	2	204		Classroom 204	W1	Cracking	12	N	N	0	N	N	2 Locations; Additional Cracking; Damage @ Door Frame & Corner
81	4300	1	2	204		Classroom 204	W3	Chipping	8	N	N	0	N	N	3 Locations; Additional Chipping; Damage @ Corner, Top & Bottom of Wall
82	4300	1	2	204		Classroom 204	W4	Cracking	2	N	N	0	N	N	
83	4300	1	2	206		Classroom 206	Ceiling	Cracking	36	N	N	0	N	N	2 Locations
84	4300	1	2	206		Classroom 206	W2	Cracking	4	N	N	0	N	N	
85	4300	1	2	206		Classroom 206	W3	Cracking	2	N	N	0	N	N	
86	4300	1	2	206		Classroom 206	W4	Partially Inaccessible	0	N	N	0	Y - 90 SF Tables, Desks, Bookcases	N	
87	4300	1	2	206A		Classroom 206 - Closet	W2	Partially Inaccessible	0	N	N	0	Y - 7 SF Contents	N	
88	4300	1	2	206A		Classroom 206 - Closet	W3	Partially Inaccessible	0	N	N	0	Y - 14 SF Contents	N	
89	4300	1	2	206B		Classroom 206 - Closet	W4	Partially Inaccessible	0	N	N	0	Y - 7 SF Contents	N	
90	4300	1	2	208		Classroom 208	W2	Flaking	6	N	N	0	N	N	2 Locations; Additional Chipping
91	4300	1	2	208		Classroom 208	W3	Cracking	6	N	N	0	N	N	Additional Chipping
92	4300	1	2	208		Classroom 208	W4	Flaking	22	N	N	0	N	N	Additional Chipping; Damage Near Top of Wall
93	4300	1	2	208A		Classroom 208 - Closet	W2	Partially Inaccessible	0	N	N	0	Y - 7 SF Contents	N	
94	4300	1	2	208A		Classroom 208 - Closet	W3	Partially Inaccessible	0	N	N	0	Y - 14 SF Contents	N	
95	4300	1	2	208B		Classroom 208 - Closet	W4	Partially Inaccessible	0	N	N	0	Y - 7 SF Contents	N	
96	4300	1	2	210		Classroom 210	W2	Cracking	5	N	N	0	N	N	2 Locations; Additional Chipping
97	4300	1	2	210		Classroom 210	W3	Flaking	7	N	N	0	N	N	3 Locations; Additional Cracking, Chipping
98	4300	1	2	210		Classroom 210	W4	Cracking	5	N	N	0	N	N	
99	4300	1	2	212		Classroom 212	W2	Cracking	2	N	N	0	Y - 24 SF Bookcases	N	
100	4300	1	2	212		Classroom 212	W3	Chipping	2	N	N	0	N	N	Chipping @ Air Unit
101	4300	1	2	214		Classroom 214	W1	Cracking	2	N	N	0	N	N	
102	4300	1	2	214		Classroom 214	W2	Cracking	4	N	N	0	N	N	2 Locations; Additional Chipping; Damage @ Seam & Near Floor
103	4300	1	2	214		Classroom 214	W4	Partially Inaccessible	0	N	N	0	Y - 30 SF Bookcases, Contents	N	
104	4300	1	2	216		Classroom 216	W1	Cracking	7	N	N	0	N	N	
105	4300	1	2	216		Classroom 216	W3	Chipping	2	N	N	0	N	N	
106	4300	1	2	218		Classroom 218	W1	Chipping	3	N	N	0	N	N	
107	4300	1	2	218		Classroom 218	W2	Chipping	6	N	N	0	N	N	
108	4300	1	2	220		Classroom 220	W1	Chipping	2	N	N	0	N	N	Chipping @ Door
109	4300	1	2	220		Classroom 220	W3	Partially Inaccessible	0	N	N	0	Y - 40 SF File Cabinets, Contents	N	

Heston -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
110	4300	1	2	222		Classroom 222	Floor	Debris	0	N	Y - @ Pipes	1	N	N	
111	4300	1	2	222		Classroom 222	W1	Cracking	2	N	N	0	Y - 9 SF Contents	N	
112	4300	1	2	222		Classroom 222	W2	Cracking	28	N	N	0	N	N	
113	4300	1	2	222		Classroom 222	W3	Flaking	19	N	N	0	N	N	Additional Cracking, Chipping; Damage Includes Back Side of Pipe
114	4300	1	2	222		Classroom 222	W4	Partially Inaccessible	0	N	N	0	Y - 24 SF Bookcases	N	
115	4300	1	2	224		Classroom 224	W2	Cracking	4	N	N	0	N	N	
116	4300	1	2	224		Classroom 224	W4	Partially Inaccessible	0	N	N	0	Y - 60 SF Bookcases, Contents	N	
117	4300	1	2	224A		Classroom 224 - Closet	W2	Partially Inaccessible	0	N	N	0	Y - 7 SF Contents	N	
118	4300	1	2	224A		Classroom 224 - Closet	W3	Partially Inaccessible	0	N	N	0	Y - 14 SF Contents	N	
119	4300	1	2	224B		Classroom 224 - Closet	W4	Partially Inaccessible	0	N	N	0	Y - 7 SF Contents	N	
120	4300	1	2	207A		Computer Server Room near Room 228	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
121	4300	1	2	207A		Computer Server Room near Room 228	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
122	4300	1	2	207A		Computer Server Room near Room 228	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
123	4300	1	2	207A		Computer Server Room near Room 228	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
124	4300	1	2	207A		Computer Server Room near Room 228	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
125	4300	1	2	207A		Computer Server Room near Room 228	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
126	4300	1	2	H22		Hallway from Classroom 210 to Classroom 224	W2	Chipping	9	N	N	0	N	N	
127	4300	1	2	H22		Hallway from Classroom 210 to Classroom 224	W4	Chipping	7	N	N	0	N	N	
128	4300	1	2	H23		Hallway from Girl's Restroom to Stairwell near Classroom 200	W2	Chipping	3	N	N	0	N	N	
129	4300	1	2	H23		Hallway from Girl's Restroom to Stairwell near Classroom 200	W4	Chipping	4	N	N	0	N	N	
130	4300	1	2	H21		Hallway from Stairwell S21 to Classroom 208	W1	Chipping	7	N	N	0	N	N	
131	4300	1	2	H21		Hallway from Stairwell S21 to Classroom 208	W3	Cracking	6	N	N	0	N	N	
132	4300	1	2	205		IMC - Library	Floor	Debris	0	N	@ Corner of Wall 3 &	1	N	N	

Heston -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
133	4300	1	2	205		IMC - Library	W1	Flaking	6	N	N	0	Y - 25 SF Bookcases, Books	N	Additional Chipping; Damage Near Floor
134	4300	1	2	205		IMC - Library	W2	Cracking	10	N	N	0	Y - 72 SF Books	N	
135	4300	1	2	205		IMC - Library	W3	Partially Inaccessible	0	N	N	0	Y - 200 SF Bookcases, Books, Posters	N	
136	4300	1	2	205		IMC - Library	W4	Flaking	1	N	N	0	Y - 162 SF Bookcases, Books	N	
137	4300	1	2	207		IMC - Library Office 233	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
138	4300	1	2	207		IMC - Library Office 233	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
139	4300	1	2	207		IMC - Library Office 233	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
140	4300	1	2	207		IMC - Library Office 233	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
141	4300	1	2	207		IMC - Library Office 233	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
142	4300	1	2	207		IMC - Library Office 233	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
143	4300	1	2	225		Men's Restroom	W1	Chipping	2	N	N	0	N	N	Chipping @ Door Frame
144	4300	1	2	200		Room 200 Reading Office	W3	Chipping	0	N	N	0	N	N	Chipping @ Air Unit
145	4300	1	2	228		Room 232 Special Education Office	W2	Partially Inaccessible	0	N	N	0	Y - 22 SF Contents	N	
146	4300	1	2	228		Room 232 Special Education Office	W3	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents	N	
147	4300	1	2	226		Room 234 Maintenance Storage near Elevator	W2	Cracking	7	N	N	0	Y - 10 SF Contents	N	
148	4300	1	2	226		Room 234 Maintenance Storage near Elevator	W3	Cracking	8	N	N	0	Y - 20 SF Contents	N	
149	4300	1	2	226		Room 234 Maintenance Storage near Elevator	W4	Cracking	4	N	N	0	Y - 18 SF Contents	N	
150	4300	1	2	201		Staff Office across from Room 200	W2	Cracking	8	N	N	0	N	N	
151	4300	1	2	201		Staff Office across from Room 200	W3	Chipping	4	N	N	0	N	N	
152	4300	1	2	201		Staff Office across from Room 200	W4	Flaking	4	N	N	0	N	N	
153	4300	1	2	S22		Stairwell between Classrooms 208 and 210	Center Banister	Chipping	6	N	N	0	N	N	
154	4300	1	2	S22		Stairwell between Classrooms 208 and 210	Floor	Chipping	4	N	N	0	N	N	Chipping on Steps
155	4300	1	2	S22		Stairwell between Classrooms 208 and 210	W3	Chipping	1	N	N	0	N	N	Chipping @ Pipe
156	4300	1	2	S23		Stairwell next to Classroom 224	Center Banister	Chipping	12	N	N	0	N	N	

Heston -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
185	4300	1	1	101C		Classroom 101 Closet near Sink	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
186	4300	1	1	101C		Classroom 101 Closet near Sink	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
187	4300	1	1	101C		Classroom 101 Closet near Sink	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
188	4300	1	1	101C		Classroom 101 Closet near Sink	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
189	4300	1	1	106		Classroom 106 (Music)	W1	Flaking	200	N	N	0	Y - 75 SF Desks	N	
190	4300	1	1	106		Classroom 106 (Music)	W2	Flaking	75	N	N	0	Y - 200 SF Boxes, Bookcases, Contents	N	
191	4300	1	1	106		Classroom 106 (Music)	W3	Flaking	170	N	N	0	N	N	Additional Cracking
192	4300	1	1	106		Classroom 106 (Music)	W4	Flaking	200	N	N	0	N	N	Additional Cracking
193	4300	1	1	106A		Classroom 106 (Music) Rear Area with High Ceiling	W1	Flaking	200	N	N	0	Y - 75 SF Desks	N	Included with 106 Quantities
194	4300	1	1	106A		Classroom 106 (Music) Rear Area with High Ceiling	W2	Flaking	75	N	N	0	Y - 200 SF Boxes, Bookcases, Contents	N	Included with 106 Quantities
195	4300	1	1	106A		Classroom 106 (Music) Rear Area with High Ceiling	W3	Flaking	170	N	N	0	N	N	Included with 106 Quantities
196	4300	1	1	106A		Classroom 106 (Music) Rear Area with High Ceiling	W4	Flaking	200	N	N	0	N	N	Included with 106 Quantities
197	4300	1	1	106B		Classroom 106 (Music) Storage Room in Rear Area with High Ceiling	Ceiling	Efflorescence	64	Y	N	0	N	N	Water Stains on Ceiling
198	4300	1	1	106B		Classroom 106 (Music) Storage Room in Rear Area with High Ceiling	W1	Cracking	22	N	N	0	N	N	Cracking Near Top
199	4300	1	1	106B		Classroom 106 (Music) Storage Room in Rear Area with High Ceiling	W2	Cracking	3	N	N	0	Y - 36 SF Shelves, Contents	N	
200	4300	1	1	106B		Classroom 106 (Music) Storage Room in Rear Area with High Ceiling	W3	Partially Inaccessible	0	N	N	0	Y - 160 SF Shelves, Contents	N	
201	4300	1	1	106B		Classroom 106 (Music) Storage Room in Rear Area with High Ceiling	W4	Cracking	3	N	N	0	Y - 36 SF Shelves, Contents	N	
202	4300	1	1	108		Classroom 108	W2	Flaking	2	N	N	0	N	N	Flaking @ Window
203	4300	1	1	108		Classroom 108	W3	Partially Inaccessible	0	N	N	0	Y - 45 SF Fridge, Bookcases	N	
204	4300	1	1	108A		Classroom 108 Restroom	W1	Cracking	3	N	N	0	N	N	
205	4300	1	1	108A		Classroom 108 Restroom	W2	Cracking	7	N	N	0	N	N	

Heston -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
206	4300	1	1	108A		Classroom 108 Restroom	W4	Cracking	6	N	N	0	N	N	
207	4300	1	1	108D		Classroom 108 Storage Room	W1	Partially Inaccessible	0	N	N	0	Y - 18 SF Shelves, Contents	N	
208	4300	1	1	108D		Classroom 108 Storage Room	W2	Partially Inaccessible	0	N	N	0	Y - 24 SF Shelves, Contents	N	
209	4300	1	1	108D		Classroom 108 Storage Room	W3	Partially Inaccessible	0	N	N	0	Y - 20 SF Shelves, Contents	N	
210	4300	1	1	108D		Classroom 108 Storage Room	W4	Partially Inaccessible	0	N	N	0	Y - 16 SF Shelves, Contents	N	
211	4300	1	1	110		Classroom 110	Ceiling	Cracking	24	N	N	0	N	N	
212	4300	1	1	110		Classroom 110	W2	Cracking	20	N	N	0	N	N	Additional Chipping
213	4300	1	1	110		Classroom 110	W3	Cracking	8	N	N	0	N	N	Additional Chipping
214	4300	1	1	110		Classroom 110	W4	Cracking	4	N	N	0	N	N	
215	4300	1	1	112		Classroom 112	W1	Partially Inaccessible	0	N	N	0	Y - 100 SF Boxes, Contents	N	
216	4300	1	1	112		Classroom 112	W2	Partially Inaccessible	0	N	N	0	Y - 80 SF Boxes, Contents	N	
217	4300	1	1	112		Classroom 112	W3	Partially Inaccessible	0	N	N	0	Y - 48 SF Boxes, Contents, Posters	N	
218	4300	1	1	112		Classroom 112	W4	Partially Inaccessible	0	N	N	0	Y - 160 SF Boxes, Contents, Posters	N	
219	4300	1	1	112C		Classroom 112 Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
220	4300	1	1	112C		Classroom 112 Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
221	4300	1	1	112B		Classroom 112 Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
222	4300	1	1	112B		Classroom 112 Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
223	4300	1	1	112B		Classroom 112 Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
224	4300	1	1	112C		Classroom 112 Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
225	4300	1	1	112E		Classroom 112 Rear Door Lobby Area	W3	Cracking	8	N	N	0	N	N	N
226	4300	1	1	112E		Classroom 112 Rear Door Lobby Area	W4	Cracking	8	N	N	0	N	N	N
227	4300	1	1	112E		Classroom 112 Rear Door Lobby Area	W1	Cracking	8	N	N	0	N	N	N
228	4300	1	1	112E		Classroom 112 Rear Door Lobby Area	W2	Cracking	8	N	N	0	N	N	N
229	4300	1	1	112A		Classroom 112 Restroom	Floor	Flaking	30	N	N	0	N	N	Additional Chipping
230	4300	1	1	112A		Classroom 112 Restroom	W1	Cracking	1	N	N	0	N	N	
231	4300	1	1	112A		Classroom 112 Restroom	W2	Cracking	2	N	N	0	N	N	

Heston -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
264	4300	1	1	116B		Classroom 116 Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
265	4300	1	1	116B		Classroom 116 Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
266	4300	1	1	116B		Classroom 116 Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
267	4300	1	1	116C		Classroom 116 Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
268	4300	1	1	116A		Classroom 116 Restroom	Floor	Chipping	2	N	N	0	N	N	
269	4300	1	1	116A		Classroom 116 Restroom	W1	Cracking	1	N	N	0	N	N	
270	4300	1	1	116A		Classroom 116 Restroom	W4	Cracking	6	N	N	0	N	N	
271	4300	1	1	116D		Classroom 116 Storage Room	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
272	4300	1	1	116D		Classroom 116 Storage Room	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
273	4300	1	1	116D		Classroom 116 Storage Room	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
274	4300	1	1	116D		Classroom 116 Storage Room	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
275	4300	1	1	116D		Classroom 116 Storage Room	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
276	4300	1	1	116D		Classroom 116 Storage Room	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
277	4300	1	1	100BB		Conference Room Closet	W1	Chipping	3	N	N	0	N	N	Chipping @ Door
278	4300	1	1	100BB		Conference Room Closet	W3	Partially Inaccessible	0	N	N	0	Y - 10 SF Bookcases, Contents	N	
279	4300	1	1	100BB		Conference Room Closet	W4	Partially Inaccessible	0	N	N	0	Y - 40 SF Shelves, Contents	N	
280	4300	1	1	100B		Conference Room in Main Office	W1	Flaking	10	N	N	0	N	N	Additional Cracking, Chipping
281	4300	1	1	100B		Conference Room in Main Office	W2	Flaking	13	N	N	0	N	N	Additional Cracking
282	4300	1	1	100B		Conference Room in Main Office	W3	Flaking	4	N	N	0	N	N	Additional Cracking
283	4300	1	1	100B		Conference Room in Main Office	W4	Flaking	12	N	N	0	Y - 12 SF Bookcases, Books	N	Additional Cracking
284	4300	1	1	114E		Connecting Hall between Classrooms 114 and 116	W1	Cracking	8	N	N	0	N	N	Cracking @ Corner
285	4300	1	1	114E		Connecting Hall between Classrooms 114 and 116	W2	Cracking	8	N	N	0	N	N	Cracking @ Corner
286	4300	1	1	114E		Connecting Hall between Classrooms 114 and 116	W3	Cracking	8	N	N	0	N	N	Cracking @ Corner
287	4300	1	1	114E		Connecting Hall between Classrooms 114 and 116	W4	Cracking	8	N	N	0	N	N	Cracking @ Corner

Heston -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
288	4300	1	1	108E		Connection Hallway between Classrooms 108 and 110	W1	Cracking	9	N	N	0	N	N	
289	4300	1	1	108E		Connection Hallway between Classrooms 108 and 110	W2	Chipping	2	N	N	0	N	N	Chipping @ Door Frame
290	4300	1	1	108E		Connection Hallway between Classrooms 108 and 110	W3	Flaking	9	N	N	0	N	N	Additional Chipping; Damage @ Pipe & Door
291	4300	1	1	102B		Copy Room in Health Suite	W1	Flaking	20	N	N	0	N	N	
292	4300	1	1	102B		Copy Room in Health Suite	W2	Flaking	80	N	N	0	N	N	
293	4300	1	1	102B		Copy Room in Health Suite	W3	Flaking	16	N	N	0	N	N	
294	4300	1	1	102B		Copy Room in Health Suite	W4	Flaking	80	N	N	0	N	N	
295	4300	1	1	107B		Counselor Office	W1	Chipping	2	N	N	0	N	N	Chipping @ Door Frame
296	4300	1	1	107B		Counselor Office	W2	Chipping	4	N	N	0	N	N	Chipping @ Window Frame
297	4300	1	1	107B		Counselor Office	W4	Chipping	1	N	N	0	N	N	
298	4300	1	1	107C		Counselor Office Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
299	4300	1	1	107C		Counselor Office Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
300	4300	1	1	107C		Counselor Office Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
301	4300	1	1	107C		Counselor Office Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
302	4300	1	1	107C		Counselor Office Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
303	4300	1	1	107C		Counselor Office Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
304	4300	1	1	102C		File Room in Health Suite	W1	Flaking	4	N	N	0	Y - 10 SF File Cabinets, Contents	N	
305	4300	1	1	102C		File Room in Health Suite	W2	Flaking	40	N	N	0	Y - 60 SF File Cabinets, Contents	N	
306	4300	1	1	102C		File Room in Health Suite	W3	Partially Inaccessible	0	N	N	0	Y - 92 SF File Cabinets, Contents	N	
307	4300	1	1	102C		File Room in Health Suite	W4	Flaking	30	N	N	0	N	N	
308	4300	1	1	127		Former Staff Dining - Used for Storage	W1	Chipping	4	N	N	0	Y - 80 SF File Cabinets	N	Chipping @ Door Frame
309	4300	1	1	127		Former Staff Dining - Used for Storage	W2	Flaking	70	N	N	0	Y - 35 SF Cabinets, Tables	N	
310	4300	1	1	127		Former Staff Dining - Used for Storage	W3	Flaking	8	N	N	0	Y - 48 SF Cabinets	N	Additional Cracking
311	4300	1	1	127		Former Staff Dining - Used for Storage	W4	Flaking	80	N	N	0	Y - 30 SF Cabinets	N	
312	4300	1	1	119A		Girl's Locker Room	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Not in Use; Used for Storage
313	4300	1	1	119A		Girl's Locker Room	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Not in Use; Used for Storage
314	4300	1	1	119A		Girl's Locker Room	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Not in Use; Used for Storage

Heston -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
341	4300	1	1	119B		Gymnasium Storage Room next to Girl's Locker Room	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
342	4300	1	1	119B		Gymnasium Storage Room next to Girl's Locker Room	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
343	4300	1	1	119B		Gymnasium Storage Room next to Girl's Locker Room	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
344	4300	1	1	119B		Gymnasium Storage Room next to Girl's Locker Room	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
345	4300	1	1	119B		Gymnasium Storage Room next to Girl's Locker Room	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
346	4300	1	1	H16		Hallway between Custodial Closet and Hall by Female Maintenance Staff Locker Room	W1	Chipping	6	N	N	0	N	N	
347	4300	1	1	H16		Hallway between Custodial Closet and Hall by Female Maintenance Staff Locker Room	W2	Flaking	10	N	N	0	N	N	Additional Chipping
348	4300	1	1	H16		Hallway between Custodial Closet and Hall by Female Maintenance Staff Locker Room	W3	Chipping	4	N	N	0	N	N	
349	4300	1	1	104		Hallway between Psychologist's Office and Therapist's Office	W1	Flaking	40	N	N	0	N	N	Additional Chipping
350	4300	1	1	104		Hallway between Psychologist's Office and Therapist's Office	W2	Flaking	30	N	N	0	N	N	
351	4300	1	1	104		Hallway between Psychologist's Office and Therapist's Office	W3	Flaking	40	N	N	0	N	N	
352	4300	1	1	104		Hallway between Psychologist's Office and Therapist's Office	W4	Flaking	30	N	N	0	N	N	
353	4300	1	1	H12		Hallway from Classroom 108 to Classroom 116	W4	Chipping	13	N	N	0	N	N	Chipping Near Floor
354	4300	1	1	H12		Hallway from Classroom 108 to Classroom 116	W2	Chipping	12	N	N	0	N	N	Chipping Near Floor
355	4300	1	1	H14		Hallway from Classroom 109 to Cafetorium	W2	Chipping	4	N	N	0	N	N	
356	4300	1	1	H14		Hallway from Classroom 109 to Cafetorium	W4	Chipping	4	N	N	0	N	N	

Heston -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
357	4300	1	1	H13		Hallway from Classroom 109 to Gymnasium	W2	Chipping	4	N	N	0	N	N	Chipping Near Floor
358	4300	1	1	H13		Hallway from Classroom 109 to Gymnasium	W4	Flaking	14	N	N	0	N	N	Additional Chipping; Damage Near Floor
359	4300	1	1	H11		Hallway from Main Lobby to Classroom 106	W1	Chipping	13	N	N	0	N	N	Chipping Near Floor
360	4300	1	1	H11		Hallway from Main Lobby to Classroom 106	W3	Chipping	20	N	N	0	N	N	Chipping Near Floor
361	4300	1	1	H17		Hallway from Stage to Gymnasium	W1	Chipping	1	N	N	0	N	N	
362	4300	1	1	H17		Hallway from Stage to Gymnasium	W2	Chipping	3	N	N	0	N	N	
363	4300	1	1	H17		Hallway from Stage to Gymnasium	W4	Chipping	8	N	N	0	N	N	2 Locations; Chipping @ Door & Near Floor
364	4300	1	1	102		Health Suite Waiting Area	W1	Partially Inaccessible	0	N	N	0	Y - 60 SF Lockers	N	
365	4300	1	1	123		Kitchen	Floor	Chipping	12	N	N	0	N	N	
366	4300	1	1	123		Kitchen	W1	Chipping	7	N	N	0	N	N	2 Locations; Damage @ Pipe & Door Frame
367	4300	1	1	123		Kitchen	W2	Chipping	3	N	N	0	N	N	
368	4300	1	1	123		Kitchen	W3	Partially Inaccessible	0	N	N	0	Y - 60 SF Kitchen Appliances	N	
369	4300	1	1	123		Kitchen	W4	Chipping	4	N	N	0	N	N	
370	4300	1	1	123A		Kitchen Staff Locker Room	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
371	4300	1	1	123A		Kitchen Staff Locker Room	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
372	4300	1	1	123A		Kitchen Staff Locker Room	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
373	4300	1	1	123A		Kitchen Staff Locker Room	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
374	4300	1	1	123A		Kitchen Staff Locker Room	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
375	4300	1	1	123A		Kitchen Staff Locker Room	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
376	4300	1	1	130B		Kitchen Wash Area with Ovens	Ceiling	Partially Inaccessible	0	N	N	0	Y - 80 SF Ductwork	N	
377	4300	1	1	130B		Kitchen Wash Area with Ovens	Floor	Chipping	6	N	N	0	N	N	
378	4300	1	1	130B		Kitchen Wash Area with Ovens	W1	Partially Inaccessible	0	N	N	0	Y - 40 SF Kitchen Appliances, Contents	N	
379	4300	1	1	130B		Kitchen Wash Area with Ovens	W2	Flaking	4	N	N	0	Y - 52 SF Contents	N	
380	4300	1	1	130B		Kitchen Wash Area with Ovens	W3	Flaking	2	N	N	0	N	N	
381	4300	1	1	130B		Kitchen Wash Area with Ovens	W4	Partially Inaccessible	0	N	N	0	Y - 48 SF Contents	N	
382	4300	1	1	MEF		Main Entrance Foyer	Ceiling	Flaking	10	Y	N	0	N	N	Additional Efflorescence; Damage Above Doors
383	4300	1	1	MEF		Main Entrance Foyer	Floor	Debris	0	N	Y - @ Wall 1	2	N	N	
384	4300	1	1	MEF		Main Entrance Foyer	W1	Flaking	3	N	N	0	N	N	Additional Chipping

Heston -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
385	4300	1	1	MEF		Main Entrance Foyer	W3	Flaking	4	N	N	0	N	N	Additional Cracking, Chipping
386	4300	1	1	MEF		Main Entrance Foyer	W4	Chipping	3	N	N	0	N	N	
387	4300	1	1	ML		Main Lobby next to Main Office	Ceiling	Flaking	16	Y	N	0	N	N	Additional Efflorescence, Cracking
388	4300	1	1	ML		Main Lobby next to Main Office	W1	Chipping	4	N	N	0	Y - 36 SF Boxes	N	Chipping on Doors
389	4300	1	1	ML		Main Lobby next to Main Office	W2	Chipping	2	N	N	0	N	N	
390	4300	1	1	ML		Main Lobby next to Main Office	W3	Chipping	4	N	N	0	N	N	
391	4300	1	1	ML		Main Lobby next to Main Office	W4	Cracking	8	N	N	0	N	N	Additional Chipping
392	4300	1	1	100		Main Office	W2	Partially Inaccessible	0	N	N	0	Y - 36 SF Desks, File Cabinets	N	
393	4300	1	1	100		Main Office	W3	Cracking	12	N	N	0	Y - 64 SF Bookcases, Shelves, File Cabinets	N	Cracking @ Top of Wall
394	4300	1	1	100		Main Office	W4	Chipping	3	N	N	0	Y - 36 SF Bookcases, Contents	N	Chipping Beneath Mailboxes
395	4300	1	1	100C		Main Office Storage Room 159	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
396	4300	1	1	100C		Main Office Storage Room 159	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
397	4300	1	1	100C		Main Office Storage Room 159	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
398	4300	1	1	100C		Main Office Storage Room 159	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
399	4300	1	1	121		Men's Restroom	Floor	Flaking	4	N	N	0	N	N	
400	4300	2	1	MODULAR		Modular	Floor	Debris	0	N	Y - @ Perimeter	140	N	N	
401	4300	2	1	MODULAR		Modular	W1	Flaking	450	N	N	0	N	N	Entire Wall
402	4300	2	1	MODULAR		Modular	W2	Flaking	250	N	N	0	N	N	Entire Wall
403	4300	2	1	MODULAR		Modular	W3	Flaking	450	N	N	0	N	N	Entire Wall
404	4300	2	1	MODULAR		Modular	W4	Flaking	250	N	N	0	N	N	Entire Wall
405	4300	2	1	MODULAR		Modular Restroom	Floor	Debris	0	N	Y - @ Perimeter	30	N	N	
406	4300	2	1	MODULAR		Modular Restroom	W1	Flaking	49	N	N	0	N	N	Entire Wall
407	4300	2	1	MODULAR		Modular Restroom	W2	Flaking	90	N	N	0	N	N	Entire Wall
408	4300	2	1	MODULAR		Modular Restroom	W3	Flaking	60	N	N	0	N	N	Entire Wall
409	4300	2	1	MODULAR		Modular Restroom	W4	Flaking	90	N	N	0	N	N	Entire Wall
410	4300	1	1	102E		Nurse's Office	W1	Cracking	5	N	N	0	N	N	
411	4300	1	1	102E		Nurse's Office	W2	Cracking	1	N	N	0	N	N	
412	4300	1	1	102E		Nurse's Office	W3	Cracking	21	N	N	0	N	N	
413	4300	1	1	102E		Nurse's Office	W4	Cracking	2	N	N	0	N	N	
414	4300	1	1	102D		Nurse's Office Storage Room	W2	Cracking	4	N	N	0	N	N	
415	4300	1	1	102D		Nurse's Office Storage Room	W4	Cracking	3	N	N	0	Y - 15 SF Fridge	N	
416	4300	1	1	100A		Principal's Office	W1	Cracking	1	N	N	0	Y - 24 SF Bookcases, Books, Boxes	N	
417	4300	1	1	100A		Principal's Office	W2	Partially Inaccessible	0	N	N	0	Y - 40 SF Bookcases, Books	N	

Heston -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
418	4300	1	1	100A		Principal's Office	W3	Cracking	6	N	N	0	Y - 48 SF Desks, Computers, Contents	N	
419	4300	1	1	100CL		Principal's Office Closet	W3	Flaking	3	N	N	0	Y - 35 SF File Cabinets, Boxes, Contents	N	Additional Cracking; Damage on Fiberglass Pipe & Wall
420	4300	1	1	100CL		Principal's Office Closet	W4	Cracking	4	N	N	0	Y - 10 SF Contents	N	
421	4300	1	1	100RR		Principal's Office Restroom	Floor	Chipping	2	N	N	0	N	N	
422	4300	1	1	100RR		Principal's Office Restroom	W2	Cracking	1	N	N	0	N	N	
423	4300	1	1	100RR		Principal's Office Restroom	W3	Holes	1	N	N	0	N	N	
424	4300	1	1	103		Room 103 After School Program - Front Office Area	W1	Chipping	4	N	N	0	Y - 120 SF Contents	N	Chipping @ Door Frame
425	4300	1	1	103		Room 103 After School Program - Front Office Area	W2	Flaking	10	N	N	0	Y - 60 SF Bookcases, Kitchen Appliances, Contents	N	
426	4300	1	1	103		Room 103 After School Program - Front Office Area	W4	Chipping	4	N	N	0	Y - 28 SF Desks, Bookcases, Books, Contents	N	
427	4300	1	1	103A		Room 103 After School Program - Rear Office Area	W1	Flaking	7	N	N	0	N	N	Additional Chipping
428	4300	1	1	103A		Room 103 After School Program - Rear Office Area	W2	Flaking	1	N	N	0	N	N	
429	4300	1	1	103A		Room 103 After School Program - Rear Office Area	W3	Partially Inaccessible	0	N	N	0	Y - 36 SF File Cabinets, Desks, Tables, Posters	N	
430	4300	1	1	103A		Room 103 After School Program - Rear Office Area	W4	Chipping	10	N	N	0	Y - 32 SF Tables, Desks	N	
431	4300	1	1	103B		Room 103 After School Program - Rear Office Area Closet	W1	Chipping	5	N	N	0	N	N	
432	4300	1	1	103C		Room 103 After School Program - Rear Office Area Closet	W2	Cracking	2	N	N	0	N	N	
433	4300	1	1	103C		Room 103 After School Program - Rear Office Area Closet	W3	Flaking	10	N	N	0	Y - 9 SF Contents	N	
434	4300	1	1	103C		Room 103 After School Program - Rear Office Area Closet	W4	Flaking	4	N	N	0	Y - 12 SF Boxes	N	

Heston -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
435	4300	1	1	104A		Room 104A Physical Therapist's Office	W1	Flaking	50	N	N	0	N	N	
436	4300	1	1	104A		Room 104A Physical Therapist's Office	W2	Flaking	30	N	N	0	N	N	
437	4300	1	1	104A		Room 104A Physical Therapist's Office	W3	Flaking	80	N	N	0	N	N	
438	4300	1	1	104C		Room 104C Psychologist's Office	W1	Flaking	50	N	N	0	N	N	
439	4300	1	1	104C		Room 104C Psychologist's Office	W2	Flaking	70	N	N	0	N	N	Additional Cracking
440	4300	1	1	104C		Room 104C Psychologist's Office	W3	Flaking	80	N	N	0	Y - 32 SF Cabinets	N	Additional Cracking
441	4300	1	1	104C		Room 104C Psychologist's Office	W4	Flaking	20	N	N	0	N	N	
442	4300	1	1	105		Room 105 Office	W1	Partially Inaccessible	0	N	N	0	Y - 180 SF Shelves, Desks	N	
443	4300	1	1	105		Room 105 Office	W2	Flaking	75	N	N	0	Y - 240 SF Bookcases, Books	N	
444	4300	1	1	105		Room 105 Office	W3	Flaking	3	Y	N	0	Y - 260 SF Bookcases, Contents	N	
445	4300	1	1	107		Room 107 Counselor Suite Hallway	W3	Flaking	3	N	N	0	N	N	Additional Chipping
446	4300	1	1	104B		Security Office in Health Suite	Floor	Debris	0	N	@ Corner of Wall 3 &	2	N	N	
447	4300	1	1	104B		Security Office in Health Suite	W1	Flaking	40	N	N	0	N	N	
448	4300	1	1	104B		Security Office in Health Suite	W2	Flaking	90	N	N	0	N	N	
449	4300	1	1	104B		Security Office in Health Suite	W3	Flaking	40	N	N	0	N	N	
450	4300	1	1	104B		Security Office in Health Suite	W4	Flaking	10	N	N	0	Y - 30 SF Desks, File Cabinets	N	
451	4300	1	1	S14		Stairs near Gymnasium and Classroom 109	W1	Chipping	2	N	N	0	N	N	Chipping Near Floor
452	4300	1	1	S14		Stairs near Gymnasium and Classroom 109	W3	Chipping	1	N	N	0	N	N	Chipping Near Floor
453	4300	1	1	S12		Stairwell between Classrooms 106 and 108	Floor	Chipping	9	N	N	0	N	N	
454	4300	1	1	130C		Stairwell near Main Entrance and Main Office	Center Banister	Chipping	10	N	N	0	N	N	
455	4300	1	1	130C		Stairwell near Main Entrance and Main Office	Floor	Chipping	10	N	N	0	N	N	
456	4300	1	1	S13		Stairwell next to Classroom 116	Floor	Chipping	10	N	N	0	N	N	
457	4300	1	1	S13		Stairwell next to Classroom 116	W1	Chipping	10	N	N	0	N	N	Chipping @ Handrail
458	4300	1	1	S13		Stairwell next to Classroom 116	W2	Chipping	2	N	N	0	N	N	
459	4300	1	1	S13		Stairwell next to Classroom 116	W3	Cracking	4	N	N	0	N	N	

Heston -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
460	4300	1	1	S13		Stairwell next to Classroom 116	W4	Chipping	2	N	N	0	N	N	Chipping on Pipe
461	4300	1	1	129A		Storage Room between Boiler Room Stairs and Cafetorium	Ceiling	Flaking	6	N	N	0	N	N	Flaking on Pipes
462	4300	1	1	129A		Storage Room between Boiler Room Stairs and Cafetorium	Floor	Partially Inaccessible	0	N	N	0	Y - 60 SF Contents	N	
463	4300	1	1	129A		Storage Room between Boiler Room Stairs and Cafetorium	W1	Flaking	40	N	N	0	N	N	
464	4300	1	1	129A		Storage Room between Boiler Room Stairs and Cafetorium	W2	Flaking	60	N	N	0	N	N	
465	4300	1	1	129A		Storage Room between Boiler Room Stairs and Cafetorium	W3	Flaking	70	N	N	0	N	N	
466	4300	1	1	129A		Storage Room between Boiler Room Stairs and Cafetorium	W4	Faking	60	N	N	0	N	N	
467	4300	1	1	125A		Storage Room near Building Engineer's Office and Kitchen	Ceiling	Flaking	15	N	N	0	N	N	Flaking Includes Ductwork
468	4300	1	1	125A		Storage Room near Building Engineer's Office and Kitchen	W1	Flaking	8	N	N	0	N	N	
469	4300	1	1	125A		Storage Room near Building Engineer's Office and Kitchen	W2	Flaking	8	N	N	0	Y - 35 SF Shelves, Contents	N	Additional Cracking
470	4300	1	1	125A		Storage Room near Building Engineer's Office and Kitchen	W3	Flaking	2	N	N	0	Y - 21 SF Shelves, Contents	N	
471	4300	1	1	125A		Storage Room near Building Engineer's Office and Kitchen	W4	Flaking	2	N	N	0	Y - 24 SF Shelves, Contents	N	
472	4300	1	1	100D		Vice Principal's Office in Main Office	W1	Cracking	1	N	N	0	N	N	