

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	Ceiling	Cracking, holes	13	No	No	N/A	N/A	Yes	
2	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	Floor	N/A	N/A	No	No	N/A	Stored materials	No	Limited Inspection
3	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W1	Cracking, chipping wall and gate, holes	15	No	No	N/A	N/A	Yes	
4	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W2	Cracking, chipping, holes	16	No	No	N/A	N/A	Yes	
5	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W3	Cracking	3	No	No	N/A	N/A	No	
6	7320	1	3	325B		Book Storage Closet across from Classrooms 21 and 22	W4	N/A	N/A	No	No	N/A	Stored materials	No	Limited Inspection
7	7320	1	3	316		Classroom 16	Ceiling	Flaking windows	4	No	No	N/A	N/A	No	
8	7320	1	3	316		Classroom 16	Floor	Debris	N/A	No	Debris on floor by windows	5	N/A	No	
9	7320	1	3	316		Classroom 16	W1	Cracking, chipping, holes	20	No	No	N/A	N/A	Yes	
10	7320	1	3	316		Classroom 16	W2	Cracking	3	No	No	N/A	N/A	No	
11	7320	1	3	316		Classroom 16	W3	Flaking, Flaking wall and radiator, efflorescence	39	Yes	No	N/A	N/A	Yes	
12	7320	1	3	316		Classroom 16	W4	Flaking	3	No	No	N/A	N/A	No	
13	7320	1	3	316C		Classroom 16 Coat Closet	Ceiling	Flaking	3	No	No	N/A	N/A	No	
14	7320	1	3	316C		Classroom 16 Coat Closet	Floor	Debris	N/A	No	Debris on floor	6	N/A	No	
15	7320	1	3	316C		Classroom 16 Coat Closet	W3	Cracking, chipping, flaking	35	No	No	N/A	N/A	No	
16	7320	1	3	316C		Classroom 16 Coat Closet	W4	Flaking	4	No	No	N/A	N/A	No	
17	7320	1	3	317		Classroom 17	Ceiling	Flaking by windows	11	No	No	N/A	N/A	No	
18	7320	1	3	317		Classroom 17	W1	Chipping, staples holes, holes, flaking	16	No	No	N/A	N/A	Yes	
19	7320	1	3	317		Classroom 17	W2	Chipping	2	No	No	N/A	N/A	No	
20	7320	1	3	317		Classroom 17	W3	Flaking, holes, flaking, flaking radiators spalling	52	Yes	No	N/A	N/A	Yes	
21	7320	1	3	317		Classroom 17	W4	Cracking, staple holes	18	No	No	N/A	N/A	Yes	
22	7320	1	3	317B		Classroom 17 Coat Closet	W3	Cracking, chipping	6	No	No	N/A	N/A	No	
23	7320	1	3	318		Classroom 18	Ceiling	Flaking by windows	24	No	No	N/A	N/A	No	
24	7320	1	3	318		Classroom 18	Floor	Debris	N/A	No	Debris on floor under windows	8	N/A	No	
25	7320	1	3	318		Classroom 18	W1	Chipping door frame	4	no	no	NA	no	No	
26	7320	1	3	318		Classroom 18	W2	Efflorescence by partition pocket	2	yes	yes	2	cabinet	Yes	
27	7320	1	3	318		Classroom 18	W3	Chipping radiator, holes, spalling	7	Yes	Debris on floor under radiators	4	N/A	Yes	
28	7320	1	3	318		Classroom 18	W4	Cracking	6	No	No	N/A	N/A	No	
29	7320	1	3	318C		Classroom 18 Coat Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
30	7320	1	3	318C		Classroom 18 Coat Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
31	7320	1	3	318C		Classroom 18 Coat Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
32	7320	1	3	318C		Classroom 18 Coat Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
33	7320	1	3	318C		Classroom 18 Coat Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
34	7320	1	3	318C		Classroom 18 Coat Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
35	7320	1	3	318A		Classroom 18 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
36	7320	1	3	318B		Classroom 18 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
37	7320	1	3	318A		Classroom 18 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
38	7320	1	3	318A		Classroom 18 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
39	7320	1	3	318A		Classroom 18 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
40	7320	1	3	318A		Classroom 18 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
41	7320	1	3	319		Classroom 19	Ceiling	Flaking by windows	14	No	No	N/A	N/A	No	
42	7320	1	3	319		Classroom 19	Floor	Debris	N/A	No	Debris on floor by windows	4	N/A	No	
43	7320	1	3	319		Classroom 19	W1	Flaking	8	No	No	N/A	N/A	No	
44	7320	1	3	319		Classroom 19	W3	Cracking, staple holes, flaking	7	No	No	N/A	N/A	Yes	
45	7320	1	3	319		Classroom 19	W4	Cracking, flaking	6	No	No	N/A	N/A	No	
46	7320	1	3	319B		Classroom 19 Coat Closet	W3	Cracking	3	No	No	N/A	N/A	No	
47	7320	1	3	319B		Classroom 19 Coat Closet	W4	Cracking	1	No	No	N/A	N/A	No	
48	7320	1	3	320		Classroom 20	Ceiling	Holes, flaking	11	No	No	N/A	N/A	Yes	
49	7320	1	3	320		Classroom 20	Floor	Debris	N/A	No	Debris on floor under radiators	8	N/A	No	
50	7320	1	3	320		Classroom 20	W1	Gouges, flaking	6	No	No	N/A	N/A	Yes	
51	7320	1	3	320		Classroom 20	W3	Chipping, holes by radiators, flaking	10	No	No	N/A	N/A	Yes	
52	7320	1	3	320B		Classroom 20 Coat Closet	W3	Cracking	2	No	No	N/A	N/A	No	
53	7320	1	3	321		Classroom 21	Ceiling	Holes, flaking	12	No	No	N/A	N/A	Yes	
54	7320	1	3	321		Classroom 21	Floor	Debris	N/A	No	Debris on floor by windows	3	N/A	No	
55	7320	1	3	321		Classroom 21	W1	Chipping, flaking	10	No	No	N/A	N/A	No	
56	7320	1	3	321		Classroom 21	W3	Chipping radiators, flaking, efflorescence	6	Yes	No	N/A	N/A	Yes	
57	7320	1	3	321		Classroom 21	W4	Holes, flaking	7	No	No	N/A	N/A	Yes	
58	7320	1	3	321B		Classroom 21 Coat Closet	W3	Cracking	2	No	No	N/A	N/A	No	
59	7320	1	3	321A		Classroom 21 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
60	7320	1	3	321A		Classroom 21 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
61	7320	1	3	321A		Classroom 21 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
62	7320	1	3	321A		Classroom 21 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
63	7320	1	3	321A		Classroom 21 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
64	7320	1	3	321A		Classroom 21 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
65	7320	1	3	322		Classroom 22	Ceiling	Holes, flaking by windows	10	No	No	N/A	N/A	Yes	
66	7320	1	3	322		Classroom 22	Floor	Debris	N/A	No	Debris under radiators	6	N/A	No	
67	7320	1	3	322		Classroom 22	W1	Cracking, chipping, staple holes	7	No	No	N/A	N/A	Yes	
68	7320	1	3	322		Classroom 22	W2	Spalling, efflorescence	3	Yes	No	N/A	N/A	Yes	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
69	7320	1	3	322		Classroom 22	W3	Holes, spalling, efflorescence	11	Yes	No	N/A	N/A	Yes	
70	7320	1	3	322C		Classroom 22 Coat Closet	W2	Cracking	2	No	No	N/A	N/A	No	
71	7320	1	3	322C		Classroom 22 Coat Closet	W3	Cracking, chipping	5	No	No	N/A	N/A	No	
72	7320	1	3	325		Classroom 23	Ceiling	Flaking by windows	4	No	No	N/A	N/A	No	
73	7320	1	3	325		Classroom 23	Floor	Debris	N/A	No	Debris under radiators	5	N/A	No	
74	7320	1	3	325		Classroom 23	W1	Chipping, holes	5	No	No	N/A	N/A	Yes	
75	7320	1	3	325		Classroom 23	W3	Chipping radiators, flaking, holes above radiators	23	No	No	N/A	N/A	Yes	
76	7320	1	3	325C		Classroom 23 Coat Closet	Ceiling	Holes	1	No	No	N/A	N/A	Yes	
77	7320	1	3	325C		Classroom 23 Coat Closet	W3	Cracking, chipping, flaking	4	No	No	N/A	N/A	No	
78	7320	1	3	323		Classroom 24	Floor	Debris	N/A	No	Debris by windows	6	N/A	No	
79	7320	1	3	323		Classroom 24	W1	Chipping, Hole, Flaking	10	No	No	N/A	N/A	No	
80	7320	1	3	323		Classroom 24	W2	Chipping, Flaking	7	No	No	N/A	N/A	No	
81	7320	1	3	323		Classroom 24	W3	Cracking, flaking	18	No	No	N/A	N/A	No	
82	7320	1	3	323		Classroom 24	W4	Flaking wall, radiator, efflorescence	13	Yes	No	N/A	N/A	Yes	
83	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W2	Chipping, flaking	2	No	No	N/A	N/A	No	
84	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W3	Chipping radiators	3	No	No	N/A	N/A	No	
85	7320	1	3	H312		Hallway from Classroom 16 to Third Floor Main Hallway	W4	Cracking, flaking	5	No	No	N/A	N/A	No	
86	7320	1	3	H311		Hallway from Classrooms 23 and 24 to Third Floor Main Hallway	W3	Chipping	2	No	No	N/A	N/A	No	
87	7320	1	3	H311		Hallway from Classrooms 23 and 24 to Third Floor Main Hallway	W4	Chipping, flaking	3	No	No	N/A	N/A	No	
88	7320	1	3	316A		Men and Women's Staff Restroom	W2	Cracking, holes	6	No	No	N/A	N/A	Yes	
89	7320	1	3	316A		Men and Women's Staff Restroom	W4	Cracking, holes, flaking	3	No	No	N/A	N/A	Yes	
90	7320	1	3	323A		Office Next to Classroom 23	Ceiling	Cracking, flaking	8	No	No	N/A	N/A	No	
91	7320	1	3	323A		Office Next to Classroom 23	Floor	Debris	N/A	No	Debris under radiators	1	N/A	No	
92	7320	1	3	323A		Office Next to Classroom 23	W1	Cracking, holes	5	No	No	N/A	N/A	Yes	
93	7320	1	3	323A		Office Next to Classroom 23	W2	Cracking, flaking	9	No	No	N/A	N/A	No	
94	7320	1	3	323A		Office Next to Classroom 23	W3	Cracking, chipping radiators, holes	7	No	No	N/A	N/A	Yes	
95	7320	1	3	323A		Office Next to Classroom 23	W4	Flaking	3	No	No	N/A	N/A	No	
96	7320	1	3	S39		Stairwell from Third Floor Main Hallway to Storage Room 26 atop Third Floor Stairwell	Floor	Chipping stair face	60	No	No	N/A	N/A	No	
97	7320	1	3	S39		Stairwell from Third Floor Main Hallway to Storage Room 26 atop Third Floor Stairwell	W3	Chipping, flaking	26	No	No	N/A	N/A	No	
98	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	Floor	Debris	N/A	No	Debris on sill and floor under windows	6	N/A	No	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
99	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W1	Holes	1	No	No	N/A	N/A	Yes	
100	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W2	Cracking, holes	10	No	No	N/A	N/A	Yes	
101	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W3	Chipping radiators, holes by windows	4	No	No	N/A	N/A	Yes	
102	7320	1	3	26		Storage Room 26 atop Third Floor Stairwell	W4	Cracking, spalling	6	Yes	No	N/A	N/A	Yes	
103	7320	1	3	H314		Third Floor Hallway adjacent to Classroom 17 to Stairwell	W1	Chipping door	6	No	No	N/A	N/A	No	
104	7320	1	3	H314		Third Floor Hallway adjacent to Classroom 17 to Stairwell	W3	Flaking iron bars	30	No	No	N/A	N/A	No	
105	7320	1	3	H313		Third Floor Main Hallway	W1	Chipping, holes, flaking radiators	6	No	No	N/A	N/A	Yes	
106	7320	1	3	H313		Third Floor Main Hallway	W3	g wall and radiators, holes, staple holes,	10	No	No	N/A	N/A	Yes	
107	7320	1	3	S31		Third Floor Stairwell adjacent to Classroom 17	W3	Chipping door	3	No	No	N/A	N/A	No	
108	7320	1	3	S31		Third Floor Stairwell adjacent to Classroom 17	W4	Flaking window frame	14	No	No	N/A	N/A	No	
109	7320	1	3	324A		Women's Staff Restroom	W1	Chipping	1	No	No	N/A	N/A	No	
110	7320	1	3	324A		Women's Staff Restroom	W2	Flaking	10	No	No	N/A	N/A	No	
111	7320	1	3	324A		Women's Staff Restroom	W4	Cracking, flaking	27	No	No	N/A	N/A	No	
112	7320	1	2	210		Classroom 10	Ceiling	Holes, flaking	8	No	No	N/A	N/A	Yes	
113	7320	1	2	210		Classroom 10	Floor	Debris	N/A	No	Debris under radiators by windows	3	N/A	No	
114	7320	1	2	210		Classroom 10	W1	Cracking, chipping, staple holes, flaking	12	No	No	N/A	N/A	Yes	
115	7320	1	2	210		Classroom 10	W3	ipping radiators, holes, flaking, efflorescence	31	Yes	No	N/A	N/A	Yes	
116	7320	1	2	210		Classroom 10	W4	Cracking, holes, flaking	29	No	No	N/A	N/A	Yes	
117	7320	1	2	210C		Classroom 10 Coat Closet	W3	Cracking, chipping, flaking	11	No	No	N/A	N/A	No	
118	7320	1	2	211		Classroom 11	Ceiling	Holes, flaking	7	No	No	N/A	N/A	Yes	
119	7320	1	2	211		Classroom 11	W1	Cracking, chipping, holes, flaking	9	No	No	N/A	N/A	Yes	
120	7320	1	2	211		Classroom 11	W3	g, chipping wall, radiator and pipe, holes,	32	No	No	N/A	N/A	Yes	
121	7320	1	2	211		Classroom 11	W4	Chipping	4	No	No	N/A	N/A	No	
122	7320	1	2	211B		Classroom 11 Coat Closet	W3	Cracking, gouges	4	No	No	N/A	N/A	Yes	
123	7320	1	2	212		Classroom 12	Ceiling	Flaking	7	No	No	N/A	N/A	No	
124	7320	1	2	212		Classroom 12	Floor	Debris	N/A	No	Debris on floor by radiators	6	N/A	No	
125	7320	1	2	212		Classroom 12	W1	Cracking, chipping, holes, flaking	19	No	No	N/A	N/A	Yes	
126	7320	1	2	212		Classroom 12	W3	ipping radiator and pipe, flaking, efflorescence	22	Yes	No	N/A	N/A	Yes	
127	7320	1	2	212		Classroom 12	W4	Flaking	5	No	No	N/A	N/A	No	
128	7320	1	2	212B		Classroom 12 Coat Closet	W3	Cracking, flaking	12	No	No	N/A	N/A	No	
129	7320	1	2	15		Classroom 15	Ceiling	Flaking	9	No	No	N/A	N/A	No	
130	7320	1	2	15		Classroom 15	Floor	Debris	N/A	No	Debris on floor by windows	5	N/A	No	
131	7320	1	2	15		Classroom 15	W1	Cracking, chipping, staple holes, flaking	44	No	No	N/A	N/A	Yes	
132	7320	1	2	15		Classroom 15	W2	Cracking, staple holes	21	No	No	N/A	N/A	Yes	
133	7320	1	2	15		Classroom 15	W3	ipping raditors, holes, flaking, efflorescence	32	Yes	No	N/A	N/A	Yes	
134	7320	1	2	15		Classroom 15	W4	Gouges, staple holes	21	No	No	N/A	N/A	Yes	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
135	7320	1	2	15B		Classroom 15 Coat Closet	W2	Cracking	1	No	No	N/A	N/A	No	
136	7320	1	2	15B		Classroom 15 Coat Closet	W3	Cracking, holes, flaking	20	No	No	N/A	N/A	Yes	
137	7320	1	2	208		Classroom 8	Floor	Debris	N/A	No	Debris under radiators	2	N/A	No	
138	7320	1	2	208		Classroom 8	W1	Cracking, chipping, holes	12	No	No	N/A	N/A	Yes	
139	7320	1	2	208		Classroom 8	W2	Chipping, staples holes	7	No	No	N/A	N/A	Yes	
140	7320	1	2	208		Classroom 8	W3	Chipping pipe and radiator, holes, flaking	22	No	No	N/A	N/A	Yes	
141	7320	1	2	208		Classroom 8	W4	Flaking	8	No	No	N/A	N/A	No	
142	7320	1	2	208B		Classroom 8 Coat Closet	W2	Chipping, flaking	3	No	No	N/A	N/A	No	
143	7320	1	2	208B		Classroom 8 Coat Closet	W3	Chipping	2	No	No	N/A	N/A	No	
144	7320	1	2	206		Classroom 9	Ceiling	Chipping, flaking	5	No	No	N/A	N/A	No	
145	7320	1	2	206		Classroom 9	Floor	Debris	N/A	No	Debris on floor by radiators	5	N/A	No	
146	7320	1	2	206		Classroom 9	W1	Chipping, holes, staple holes, flaking	46	No	No	N/A	N/A	Yes	
147	7320	1	2	206		Classroom 9	W2	Staple holes	40	No	No	N/A	N/A	Yes	
148	7320	1	2	206		Classroom 9	W3	chipping wall and pipe, holes, flaking, efflorescence	49	Yes	No	N/A	N/A	Yes	
149	7320	1	2	206		Classroom 9	W4	Chipping, staples holes, flaking	18	No	No	N/A	N/A	Yes	
150	7320	1	2	206B		Classroom 9 Coat Closet	W3	Cracking	4	No	No	N/A	N/A	No	
151	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W2	Holes, staple holes, flaking	23	No	No	N/A	N/A	Yes	
152	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W3	Chipping	1	No	No	N/A	N/A	No	
153	7320	1	2	H28		Hallway from Classroom 15 to Second Floor Main Hallway	W4	Staple holes	6	No	No	N/A	N/A	Yes	
154	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	Ceiling	Cracking, flaking	4	No	No	N/A	N/A	No	
155	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	Floor	Debris	N/A	No	Debris on floor by wall	5	N/A	No	
156	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W2	Cracking, chipping, holes, flaking	11	No	No	N/A	N/A	Yes	
157	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W3	Chipping radiator, flaking pipe, flaking, efflorescence	10	Yes	No	N/A	N/A	Yes	
158	7320	1	2	H210		Hallway from Classroom 8 to Second Floor Main Hallway	W4	Cracking	4	No	No	N/A	N/A	No	
159	7320	1	2	213		IMC Library	Ceiling	Holes, flaking	14	No	No	N/A	N/A	Yes	
160	7320	1	2	213		IMC Library	Floor	Debris	N/A	No	Debris on floor by radiators	12	N/A	No	
161	7320	1	2	213		IMC Library	W1	Cracking, chipping, holes, flaking	39	No	No	N/A	N/A	Yes	
162	7320	1	2	213		IMC Library	W2	Cracking, flaking	11	No	No	N/A	N/A	No	
163	7320	1	2	213		IMC Library	W3	Chipping radiators, holes, spalling, efflorescence	23	Yes	No	N/A	N/A	Yes	
164	7320	1	2	213		IMC Library	W4	Chipping	2	No	No	N/A	N/A	No	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
165	7320	1	2	213B		IMC Library Book Storage Closet	W3	Cracking	2	No	No	N/A	N/A	No	
166	7320	1	2	213C		IMC Library Book Storage Closet	W4	N/A	N/A	No	No	N/A	Stored materials on shelves	No	Limited Inspection
167	7320	1	2	214B		Men's Staff Restroom	W4	Flaking	3	No	No	N/A	N/A	No	
168	7320	1	2	215C		Room within Teacher's Lounge	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
169	7320	1	2	215C		Room within Teacher's Lounge	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
170	7320	1	2	215C		Room within Teacher's Lounge	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
171	7320	1	2	215C		Room within Teacher's Lounge	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
172	7320	1	2	215C		Room within Teacher's Lounge	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
173	7320	1	2	215C		Room within Teacher's Lounge	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
174	7320	1	2	H29		Second Floor Main Hallway	W1	Chipping metal pipe, staple holes, flaking	18	No	No	N/A	N/A	Yes	
175	7320	1	2	H29		Second Floor Main Hallway	W3	g, chipping wall and radiator, holes, staple	26	No	No	N/A	N/A	Yes	
176	7320	1	2	S21		Second Floor Stairwell next to Classroom 9	W3	Chipping door and bars	92	No	No	N/A	N/A	No	
177	7320	1	2	S21		Second Floor Stairwell next to Classroom 9	W4	Chipping windows	12	No	No	N/A	N/A	No	
178	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
179	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
180	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
181	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
182	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
183	7320	1	2	215B		Storage Room next to the Teacher's Lounge and Classroom 15	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
184	7320	1	2	215A		Teacher's Lounge	Floor	Debris	N/A	No	Debris on floor	2	N/A	No	
185	7320	1	2	215A		Teacher's Lounge	W1	Chipping	2	No	No	N/A	N/A	No	
186	7320	1	2	215A		Teacher's Lounge	W2	Cracking	4	No	No	N/A	N/A	No	
187	7320	1	2	215A		Teacher's Lounge	W3	Cracking, flaking	7	No	No	N/A	N/A	No	
188	7320	1	2	215A		Teacher's Lounge	W4	Chipping radiators, flaking	5	No	No	N/A	N/A	No	
189	7320	1	2	215D		Teacher's Lounge Kitchen	W1	built-in shelves, chipping baseboard, holes	7	No	No	N/A	N/A	Yes	
190	7320	1	2	215D		Teacher's Lounge Kitchen	W2	Cracking, chipping baseboard, holes	4	No	No	N/A	N/A	Yes	
191	7320	1	2	215D		Teacher's Lounge Kitchen	W3	Chipping baseboard	4	No	No	N/A	N/A	No	
192	7320	1	2	215D		Teacher's Lounge Kitchen	W4	Chipping baseboard	4	No	No	N/A	N/A	No	
193	7320	1	2	214A		Women's Staff Restroom	W1	Chipping	1	No	No	N/A	N/A	No	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
194	7320	1	2	214A		Women's Staff Restroom	W2	Holes	1	No	No	N/A	N/A	Yes	
195	7320	1	2	214A		Women's Staff Restroom	W3	Chipping metal pipe	2	No	No	N/A	N/A	No	
196	7320	2	1	101C		Cafeteria	Ceiling	Flaking, efflorescence	5	Yes	No	N/A	N/A	Yes	
197	7320	2	1	101C		Cafeteria	W1	Cracking, chipping wall and door, flaking	29	No	No	N/A	N/A	No	
198	7320	2	1	101C		Cafeteria	W2	Cracking	30	No	No	N/A	N/A	No	
199	7320	2	1	101C		Cafeteria	W3	Chipping door	10	No	No	N/A	N/A	No	
200	7320	2	1	101C		Cafeteria	W4	Cracking	30	No	No	N/A	N/A	No	
201	7320	1	1	101		Classroom 1	Ceiling	Flaking	1	No	No	N/A	N/A	No	
202	7320	1	1	101		Classroom 1	W1	Cracking, chipping, chipping door, holes	21	No	No	N/A	N/A	Yes	
203	7320	1	1	101		Classroom 1	W2	Chipping	3	No	No	N/A	N/A	No	
204	7320	1	1	101		Classroom 1	W3	Chipping metal pipe, chipping, holes and efflorescence	19	Yes	No	N/A	N/A	Yes	
205	7320	1	1	101		Classroom 1	W4	Cracking and chipping	6	No	No	N/A	N/A	No	
206	7320	1	1	101D		Classroom 1 Coat Closet	W2	Chipping	3	No	No	N/A	N/A	No	
207	7320	1	1	101D		Classroom 1 Coat Closet	W3	Cracking and chipping	15	No	No	N/A	N/A	No	
208	7320	1	1	101A		Classroom 1 Restroom	W2	Flaking	2	No	No	N/A	N/A	No	
209	7320	1	1	101A		Classroom 1 Restroom	W4	Chipping wall and radiator	7	No	No	N/A	N/A	No	
210	7320	1	1	102		Classroom 2	W1	Cracking, chipping, holes, flaking	28	No	No	N/A	N/A	Yes	
211	7320	1	1	102		Classroom 2	W3	Chipping pipe and radiator, holes and efflorescence	18	Yes	No	N/A	N/A	Yes	
212	7320	1	1	102B		Classroom 2 Coat Closet	W3	Cracking and holes	12	No	No	N/A	N/A	Yes	
213	7320	1	1	103		Classroom 3	Ceiling	Flaking	2	No	No	N/A	N/A	No	
214	7320	1	1	103		Classroom 3	W1	Cracking, chipping door, flaking	20	No	No	N/A	N/A	No	
215	7320	1	1	103		Classroom 3	W2	Chipping and flaking	5	No	No	N/A	N/A	No	
216	7320	1	1	103		Classroom 3	W3	Cracking, chipping, chipping radiator, flaking	15	No	No	N/A	N/A	No	
217	7320	1	1	103		Classroom 3	W4	Chipping wall and metal pipe	4	No	No	N/A	N/A	No	
218	7320	1	1	103C		Classroom 3 Coat Closet	Ceiling	Chipping	1	No	No	N/A	N/A	No	
219	7320	1	1	103C		Classroom 3 Coat Closet	Floor	Debris	N/A	No	Debris on floor	2	N/A	No	
220	7320	1	1	103C		Classroom 3 Coat Closet	W3	Cracking, chipping, gouge, flaking	18	No	No	N/A	N/A	Yes	
221	7320	1	1	103C		Classroom 3 Coat Closet	W4	Chipping	1	No	No	N/A	N/A	No	
222	7320	1	1	103B		Classroom 3 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
223	7320	1	1	103B		Classroom 3 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
224	7320	1	1	103A		Classroom 3 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
225	7320	1	1	103A		Classroom 3 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
226	7320	1	1	103A		Classroom 3 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
227	7320	1	1	103B		Classroom 3 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
228	7320	1	1	104		Classroom 4	Ceiling	Holes, flaking	9	No	No	N/A	N/A	Yes	
229	7320	1	1	104		Classroom 4	Floor	Debris	N/A	No	Debris on floor by radiators	1	N/A	No	
230	7320	1	1	104		Classroom 4	W1	Cracking, chipping	11	No	No	N/A	N/A	No	
231	7320	1	1	104		Classroom 4	W2	Cracking, chipping, holes, chipping metal pipe	13	No	No	N/A	N/A	Yes	
232	7320	1	1	104		Classroom 4	W3	Cracking, chipping, holes, chipping radiator	15	No	No	N/A	N/A	Yes	
233	7320	1	1	104		Classroom 4	W4	Cracking, holes, flaking	16	No	No	N/A	N/A	Yes	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
234	7320	1	1	104E		Classroom 4 Coat Closet	W1	N/A	N/A	No	No	N/A	Stored materials	No	Limited Inspection
235	7320	1	1	104E		Classroom 4 Coat Closet	W2	Chipping	1	No	No	N/A	N/A	No	
236	7320	1	1	104E		Classroom 4 Coat Closet	W3	Cracking	12	No	No	N/A	N/A	No	
237	7320	1	1	104E		Classroom 4 Coat Closet	W4	Chipping	1	No	No	N/A	N/A	No	
238	7320	1	1	106		Classroom 6	Ceiling	Flaking	8	No	No	N/A	N/A	No	
239	7320	1	1	106		Classroom 6	W1	Chipping, flaking, chipping door	18	No	No	N/A	N/A	No	
240	7320	1	1	106		Classroom 6	W2	Chipping	2	No	No	N/A	N/A	No	
241	7320	1	1	106		Classroom 6	W3	Chipping wall, radiator, pipe and flaking	17	No	No	N/A	N/A	No	
242	7320	1	1	106		Classroom 6	W4	Staple holes	8	No	No	N/A	N/A	Yes	
243	7320	1	1	106C		Classroom 6 Coat Closet	W1	N/A	N/A	No	No	N/A	Shelves and stored materials	No	Limited Inspection
244	7320	1	1	106B		Classroom 6 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
245	7320	1	1	106B		Classroom 6 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
246	7320	1	1	106A		Classroom 6 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Computer desk blocking door. This space will need to be inspected
247	7320	1	1	106A		Classroom 6 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
248	7320	1	1	106A		Classroom 6 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
249	7320	1	1	106B		Classroom 6 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
250	7320	1	1	107E		Classroom 7	Ceiling	Holes, flaking	6	No	No	N/A	N/A	Yes	
251	7320	1	1	107E		Classroom 7	W1	Chipping, holes, staple holes, chipping door	26	No	No	N/A	N/A	Yes	
252	7320	1	1	107E		Classroom 7	W2	Cracking, chipping, holes, flaking	24	No	No	N/A	N/A	Yes	
253	7320	1	1	107E		Classroom 7	W3	Chipping, holes, flaking, spalling, chipping radiator	30	Yes	No	N/A	N/A	Yes	
254	7320	1	1	107E		Classroom 7	W4	Cracking, chipping, flaking, chipping cabinet	31	No	No	N/A	N/A	No	
255	7320	1	1	107D		Classroom 7 Coat Closet	W2	Flaking	3	No	No	N/A	N/A	No	
256	7320	1	1	107D		Classroom 7 Coat Closet	W3	Cracking, flaking	29	No	No	N/A	N/A	No	
257	7320	1	1	107C		Classroom 7 Restroom	W2	Chipping radiators	4	No	No	N/A	N/A	No	
258	7320	1	1	107F		Classroom 7 Storage Closet	Floor	Debris	N/A	No	Debris on floor	16	N/A	No	
259	7320	1	1	107F		Classroom 7 Storage Closet	W1	flaking	100	No	No	N/A	N/A	No	
260	7320	1	1	107B		Classroom 7 Storage Closet	W2	Cracking	3	No	No	N/A	N/A	No	
261	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W1	Chipping	4	No	No	N/A	N/A	No	
262	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W2	Chipping	7	No	No	N/A	N/A	No	
263	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W3	Chipping, holes	14	No	No	N/A	N/A	Yes	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
264	7320	1	1	105		Common Area for Counselor, Nurse, Special Education and Speech Offices	W4	Chipping	2	No	No	N/A	N/A	No	
265	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W1	Chipping	3	No	No	N/A	N/A	No	
266	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W2	Chipping	4	No	No	N/A	N/A	No	
267	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W3	Chipping	3	No	No	N/A	N/A	No	
268	7320	1	1	105E		Common Area for Counselor, Nurse, Special Education and Speech Offices Storage Closet	W4	Chipping	4	No	No	N/A	N/A	No	
269	7320	1	1	105A		Counselor's Office	Floor	Debris	N/A	No	Debris on floor by window	2	N/A	No	
270	7320	1	1	105A		Counselor's Office	W1	Chipping door	4	No	No	N/A	N/A	No	
271	7320	1	1	105A		Counselor's Office	W2	Chipping	5	No	No	N/A	N/A	No	
272	7320	1	1	105A		Counselor's Office	W3	Chipping radiator, flaking	13	No	No	N/A	N/A	No	
273	7320	1	1	105A		Counselor's Office	W4	Cracking, chipping	14	No	No	N/A	N/A	No	
274	7320	1	1	H19		First Floor Main Hallway	W1	Chipping wall and pipe, holes, flaking	26	No	No	N/A	N/A	Yes	
275	7320	1	1	H19		First Floor Main Hallway	W3	Chipping, chipping wall, metal pipe, radiator, flaking	56	No	No	N/A	N/A	No	
276	7320	1	1	S17		First Floor Stairwell Grange Avenue	Ceiling	Flaking	14	No	No	N/A	N/A	No	
277	7320	1	1	S17		First Floor Stairwell Grange Avenue	Floor	Chipping wall and rail	42	No	No	N/A	N/A	No	
278	7320	1	1	S17		First Floor Stairwell Grange Avenue	W1	Chipping, flaking, holes	35	No	No	N/A	N/A	Yes	
279	7320	1	1	S17		First Floor Stairwell Grange Avenue	W2	Chipping wall, radiator and pipe	9	No	No	N/A	N/A	No	
280	7320	1	1	S17		First Floor Stairwell Grange Avenue	W3	Chipping, holes, flaking	32	No	No	N/A	N/A	Yes	
281	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails	23	No	No	N/A	N/A	No	
282	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W1	Chipping wall and pipe	6	No	No	N/A	N/A	No	
283	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W3	Chipping, holes, flaking	26	No	No	N/A	N/A	Yes	
284	7320	1	1	S18		First Floor Stairwell opposite Grange Avenue	W4	Cracking, chipping radiators, flaking	17	No	No	N/A	N/A	No	
285	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	Ceiling	Cracking, flaking	6	No	No	N/A	N/A	No	
286	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	Floor	Debris	N/A	No	Debris on floor by wall	3	N/A	No	
287	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W2	Chipping, chipping metal pipe, holes, flaking	37	No	No	N/A	N/A	Yes	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
288	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W3	Chipping radiator, holes, flaking	8	No	No	N/A	N/A	Yes	
289	7320	1	1	H17		Hallway from Classroom 1 to First Floor Main Hallway	W4	Cracking, flaking	12	No	No	N/A	N/A	No	
290	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W2	Cracking, holes, flaking	14	No	No	N/A	N/A	Yes	
291	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W3	Chipping, cracking, holes	11	No	No	N/A	N/A	Yes	
292	7320	1	1	H15		Hallway from Classroom 7 to First Floor Main Hallway	W4	Cracking, chipping radiator, holes, flaking	36	No	No	N/A	N/A	Yes	
293	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W1	Chipping door and radiator	26	No	No	N/A	N/A	No	
294	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W2	Chipping radiator, door and metal pipe	13	No	No	N/A	N/A	No	
295	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W3	Cracking, chipping door and radiator, flaking	46	No	No	N/A	N/A	No	
296	7320	1	1	H14		Hallway from Classroom 7 to the Cafeteria	W4	Chipping metal pipe	2	No	No	N/A	N/A	No	
297	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W1	Cracking	1	No	No	N/A	N/A	No	
298	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W3	Cracking, chipping, holes	32	No	No	N/A	N/A	Yes	
299	7320	1	1	H20		Main Entrance Hallway to First Floor Main Hallway	W4	Chipping, holes	6	No	No	N/A	N/A	Yes	
300	7320	1	1	S19		Main Entrance Stairwell	W1	Cracking, chipping wall and door, flaking	26	No	No	N/A	N/A	No	
301	7320	1	1	107		Main Office	Ceiling	Holes, flaking	4	No	No	N/A	N/A	Yes	
302	7320	1	1	107		Main Office	W1	Chipping	7	No	No	N/A	N/A	No	
303	7320	1	1	107		Main Office	W2	Holes, flaking, spalling, efflorescence, chipping	27	Yes	No	N/A	N/A	Yes	
304	7320	1	1	107		Main Office	W3	Chipping, holes, chipping door	8	No	No	N/A	N/A	Yes	
305	7320	1	1	107		Main Office	W4	Chipping	6	No	No	N/A	N/A	No	
306	7320	1	1	105D		Nurse's Office	W1	Chipping, chipping door	7	No	No	N/A	N/A	No	
307	7320	1	1	105D		Nurse's Office	W2	Cracking, chipping, flaking	17	No	No	N/A	N/A	No	
308	7320	1	1	105D		Nurse's Office	W3	Chipping radiator, flaking	12	No	No	N/A	N/A	No	
309	7320	1	1	105D		Nurse's Office	W4	Chipping	10	No	No	N/A	N/A	No	
310	7320	1	1	107A		Principal's Office	W1	Cracking, chipping, chipping door	8	No	No	N/A	N/A	No	
311	7320	1	1	107A		Principal's Office	W4	Holes	4	No	No	N/A	N/A	Yes	
312	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W1	Chipping door	10	No	No	N/A	N/A	No	
313	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W2	Cracking and flaking	6	No	No	N/A	N/A	No	
314	7320	1	1	101B		Principal's Restroom adjacent to Classroom 1	W4	Cracking	3	No	No	N/A	N/A	No	
315	7320	1	1	S27		Second Floor Stairwell Grange Avenue	Floor	Chipping stairs and rails	22	No	No	N/A	N/A	No	
316	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W1	Cracking, chipping, staple holes, flaking	31	No	No	N/A	N/A	Yes	
317	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W2	Chipping, flaking	3	No	No	N/A	N/A	No	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
318	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W3	Cracking, flaking	24	No	No	N/A	N/A	No	
319	7320	1	1	S27		Second Floor Stairwell Grange Avenue	W4	Flaking	7	No	No	N/A	N/A	No	
320	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	Ceiling	Cracking, flaking	4	No	No	N/A	N/A	No	
321	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails	23	No	No	N/A	N/A	No	
322	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W1	Cracking, chipping, holes, staple holes	11	No	No	N/A	N/A	Yes	
323	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W2	Chipping door	4	No	No	N/A	N/A	No	
324	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W3	Chipping, flaking	9	No	No	N/A	N/A	No	
325	7320	1	1	S28		Second Floor Stairwell opposite Grange Avenue	W4	Flaking, spalling	4	Yes	No	N/A	N/A	Yes	
326	7320	1	1	105C		Special Education Office	Ceiling	Flaking	2	No	No	N/A	N/A	No	
327	7320	1	1	105C		Special Education Office	W2	Chipping	2	No	No	N/A	N/A	No	
328	7320	1	1	105C		Special Education Office	W3	Flaking	6	No	No	N/A	N/A	No	
329	7320	1	1	105B		Speech Office	W1	Cracking, flaking, holes, spalling	29	Yes	No	N/A	N/A	Yes	
330	7320	1	1	105B		Speech Office	W2	Cracking, chipping, gouges, holes	17	No	No	N/A	N/A	Yes	
331	7320	1	1	105B		Speech Office	W4	Chipping	4	No	No	N/A	N/A	No	
332	7320	1	1	S110		Stairwell next to Classroom 2	Floor	Chipping hand rail	20	No	No	N/A	N/A	No	
333	7320	1	1	S110		Stairwell next to Classroom 2	W1	Chipping door	8	No	No	N/A	N/A	No	
334	7320	1	1	S110		Stairwell next to Classroom 2	W3	Chipping door, flaking iron bars	30	No	No	N/A	N/A	No	
335	7320	1	1	S110		Stairwell next to Classroom 2	W4	Chipping door	14	No	No	N/A	N/A	No	
336	7320	1	1	S111		Stairwell next to Main Office	W1	Chipping door	10	No	No	N/A	N/A	No	
337	7320	1	1	S111		Stairwell next to Main Office	W2	Chipping door	6	No	No	N/A	N/A	No	
338	7320	1	1	S111		Stairwell next to Main Office	W3	Chipping door, flaking door, flaking iron bars	26	No	No	N/A	N/A	No	
339	7320	1	1	S111		Stairwell next to Main Office	W4	Flaking iron bars	90	No	No	N/A	N/A	No	
340	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	Ceiling	Cracking	5	No	No	N/A	N/A	No	
341	7320	1	1	104A		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W2	Cracking	4	No	No	N/A	N/A	No	
342	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W3	Cracking, chipping pipe	8	No	No	N/A	N/A	No	
343	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Classroom 4	W4	Cracking, holes	16	No	No	N/A	N/A	Yes	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
344	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	Ceiling	Cracking, holes, flaking	16	No	No	N/A	N/A	Yes	
345	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	Floor	Debris	N/A	No	Debris on floor	4	N/A	No	
346	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W1	Flaking	20	No	No	N/A	N/A	No	
347	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W2	Cracking, holes, flaking	30	No	No	N/A	N/A	Yes	
348	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W3	Flaking on wall and asbestos pipe	70	No	No	N/A	N/A	No	
349	7320	1	1	104C		Storage Room adjacent to Main Entrance Stairwell and Nurse's Office	W4	Flaking	5	No	No	N/A	N/A	No	
350	7320	1	1	S37		Third Floor Stairwell Grange Avenue	Ceiling	Holes	10	No	No	N/A	N/A	Yes	
351	7320	1	1	S37		Third Floor Stairwell Grange Avenue	Floor	Debris	N/A	No	Debris throughout	25	N/A	No	
352	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W1	Cracking, chipping wall and rails, flaking	55	No	No	N/A	N/A	No	
353	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W2	Flaking	7	No	No	N/A	N/A	No	
354	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W3	Cracking, holes, flaking	18	No	No	N/A	N/A	Yes	
355	7320	1	1	S37		Third Floor Stairwell Grange Avenue	W4	Cracking, holes, flaking	16	No	No	N/A	N/A	Yes	
356	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	Floor	Chipping rail and flaking	13	No	No	N/A	N/A	No	
357	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	W1	Chipping and flaking	3	No	No	N/A	N/A	No	
358	7320	1	1	S38		Third Floor Stairwell opposite Grange Avenue	W2	Chipping door	2	No	No	N/A	N/A	No	
359	7320	1	0	008B		Basement Boy's Restroom	Ceiling	Cracking, holes, flaking in concrete	36	No	No	N/A	N/A	Yes	
360	7320	1	0	008B		Basement Boy's Restroom	W1	Flaking	53	No	No	N/A	N/A	No	
361	7320	1	0	008B		Basement Boy's Restroom	W2	Flaking	51	No	No	N/A	N/A	No	
362	7320	1	0	008B		Basement Boy's Restroom	W3	Flaking	42	No	No	N/A	N/A	No	
363	7320	1	0	008B		Basement Boy's Restroom	W4	Flaking	47	No	No	N/A	N/A	No	
364	7320	1	0	003B		Basement Girl's Restroom	W1	Flaking duct and wall	30	No	No	N/A	N/A	No	
365	7320	1	0	003B		Basement Girl's Restroom	W2	Chipping pipe flaking wall	50	No	No	N/A	N/A	No	
366	7320	1	0	003B		Basement Girl's Restroom	W3	Cracked and flaking brick wall	59	No	No	N/A	N/A	No	
367	7320	1	0	003B		Basement Girl's Restroom	W4	Chipped pipe flaking wall	65	No	No	N/A	N/A	No	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
368	7320	1	0	H01		Basement Main Hallway	Ceiling	Flaking ceiling and duct	258	No	No	N/A	N/A	No	
369	7320	1	0	H01		Basement Main Hallway	Floor	Chipping floor grate	140	No	No	N/A	N/A	No	
370	7320	1	0	H01		Basement Main Hallway	W1	Chipping baseboard, flaking wall	130	No	No	N/A	N/A	No	
371	7320	1	0	H01		Basement Main Hallway	W2	Chipping, flaking	11	No	No	N/A	N/A	No	
372	7320	1	0	H01		Basement Main Hallway	W3	Chipping baseboard, flaking wall	70	No	No	N/A	N/A	No	
373	7320	1	0	H01		Basement Main Hallway	W4	Chipping baseboard, flaking wall	48	No	No	N/A	N/A	No	
374	7320	1	0	S09		Basement Stairwell Grange Avenue	Floor	Chipping stair and rails	58	No	No	N/A	N/A	No	
375	7320	1	0	S09		Basement Stairwell Grange Avenue	W1	Cracking, chipping wall and radiator, flaking	26	No	No	N/A	N/A	No	
376	7320	1	0	S09		Basement Stairwell Grange Avenue	W2	Cracking, chipping, chipping door, holes	37	No	No	N/A	N/A	Yes	
377	7320	1	0	S09		Basement Stairwell Grange Avenue	W3	Cracking, chipping radiators, staple holes	27	No	No	N/A	N/A	Yes	
378	7320	1	0	S09		Basement Stairwell Grange Avenue	W4	Chipping door	8	No	No	N/A	N/A	No	
379	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	Ceiling	Flaking	25	No	No	N/A	N/A	No	
380	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	Floor	Chipping stairs and rails	55	No	No	N/A	N/A	No	
381	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W1	Cracking, chipping, flaking	47	No	No	N/A	N/A	No	
382	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W2	Chipping door frame	10	No	No	N/A	N/A	No	
383	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W3	Chipping	14	No	No	N/A	N/A	No	
384	7320	1	0	S08		Basement Stairwell opposite Grange Avenue	W4	Chipping door and pipe, holes and flaking	39	No	No	N/A	N/A	Yes	
385	7320	1	0	001B		Classroom B-1	Ceiling	Chipping, flaking	9	No	No	N/A	N/A	No	
386	7320	1	0	001B		Classroom B-1	Floor	Chipping radiators	20	No	No	N/A	N/A	No	
387	7320	1	0	001B		Classroom B-1	W1	Cracking, chipping, chipping door	36	No	No	N/A	N/A	No	
388	7320	1	0	001B		Classroom B-1	W2	Cracking, flaking	11	No	No	N/A	N/A	No	
389	7320	1	0	001B		Classroom B-1	W3	Cracking, holes, flaking	7	No	No	N/A	N/A	Yes	
390	7320	1	0	001B		Classroom B-1	W4	Chipping fiberglass pipe	5	No	No	N/A	N/A	No	
391	7320	1	0	002B		Gymnasium	W1	Chipping on door, duct, pipe and backboard	75	No	No	N/A	N/A	No	
392	7320	1	0	002B		Gymnasium	W2	Chipping on door and backboard	30	No	No	N/A	N/A	No	
393	7320	1	0	002B		Gymnasium	W3	Cracking brick, chipping radiators	43	No	No	N/A	N/A	No	
394	7320	1	0	002B		Gymnasium	W4	Chipping radiator, pipe and door	41	No	No	N/A	N/A	No	
395	7320	1	0	002C		Gymnasium Storage Closet	W3	Chipping wall and shelf	30	No	No	N/A	Stored materials	No	
396	7320	1	0	H02		Hallway from Classroom B-1 to Basement Main Hallway	W2	Chipping brick wall	3	No	No	N/A	N/A	No	
397	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	Ceiling	Flaking ceiling and duct	225	No	No	N/A	N/A	No	

Howe -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
398	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	Floor	Debris	N/A	No	Debris at wall	4	N/A	No	
399	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	W2	Chipping baseboard, flaking brick	100	No	No	N/A	N/A	No	
400	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	W3	Chipping baseboard, flaking brick	10	No	No	N/A	N/A	No	
401	7320	1	0	H03		Hallway from Stairwell adjacent to the Boy's Restroom to Basement Main Hallway	W4	Chipping baseboard, flaking brick	29	No	No	N/A	N/A	No	
402	7320	1	0	S04		Stairwell adjacent to Classroom B-1	Ceiling	Flaking duct and ceiling	70	No	No	N/A	N/A	No	
403	7320	1	0	S04		Stairwell adjacent to Classroom B-1	Floor	Chipping hand rail	20	No	No	N/A	N/A	No	
404	7320	1	0	S04		Stairwell adjacent to Classroom B-1	W1	Chipping door, flaking wall	13	No	No	N/A	N/A	No	
405	7320	1	0	S04		Stairwell adjacent to Classroom B-1	W3	Chipping door	22	No	No	N/A	N/A	No	
406	7320	1	0	S03		Stairwell adjacent to the Boy's Restroom	Ceiling	Chipping door	10	No	No	N/A	N/A	No	
407	7320	1	0	S03		Stairwell adjacent to the Boy's Restroom	Floor	Chipping baseboard, stair face and hand rail	43	No	No	N/A	N/A	No	
408	7320	1	0	S03		Stairwell adjacent to the Boy's Restroom	W3	Chipping door	20	No	No	N/A	N/A	No	
409	7320	1	0	S03		Stairwell adjacent to the Boy's Restroom	W4	Chipping door	6	No	No	N/A	N/A	No	
410	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
411	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
412	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
413	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
414	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
415	7320	1	0	007A		Storage Room in Stairwell adjacent to the Boy's Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
416	7320	1	0	009B		Store Room #1	Ceiling	Flaking	20	No	No	N/A	Stored materials on shelves	No	
417	7320	1	0	009B		Store Room #1	Floor	N/A	N/A	No	No	N/A	Stored materials on shelves	No	Limited Inspection
418	7320	1	0	009B		Store Room #1	W1	N/A	N/A	No	No	N/A	Stored materials on shelves	No	Limited Inspection
419	7320	1	0	009B		Store Room #1	W2	Flaking metal pipe and wall	50	No	No	N/A	Stored materials on shelves	No	

Howe -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
420	7320	1	0	009B		Store Room #1	W3	Flaking	10	No	No	N/A	Stored materials on shelves	No	
421	7320	1	0	009B		Store Room #1	W4	N/A	N/A	No	No	N/A	Stored materials on shelves	No	Limited Inspection