

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	5060	1	7	701		Boys' Restroom in Recreation area near Stairwell #4	Ceiling	Flaking	16	N	N	0	N	N	
2	5060	1	7	701		Boys' Restroom in Recreation area near Stairwell #4	W1	Flaking	28	N	N	0	N	N	
3	5060	1	7	701		Boys' Restroom in Recreation area near Stairwell #4	W2	Flaking	40	N	N	0	N	N	
4	5060	1	7	701		Boys' Restroom in Recreation area near Stairwell #4	W3	Flaking	32	N	N	0	N	N	
5	5060	1	7	701		Boys' Restroom in Recreation area near Stairwell #4	W4	Flaking	8	N	N	0	N	N	
6	5060	1	7	703		Girls' Restroom	Ceiling	Flaking	30	N	N	0	N	N	
7	5060	1	7	708H		Hallway at the top of Stairwell #3	Ceiling	Flaking	18	N	N	0	N	N	
8	5060	1	7	708H		Hallway at the top of Stairwell #3	W1	Flaking	20	N	N	0	N	N	
9	5060	1	7	708H		Hallway at the top of Stairwell #3	W2	Flaking	15	N	N	0	N	N	
10	5060	1	7	708H		Hallway at the top of Stairwell #3	W3	Flaking	24	N	N	0	N	N	
11	5060	1	7	708H		Hallway at the top of Stairwell #3	W4	Flaking	10	N	N	0	N	N	
12	5060	1	7	702		Indoor Recreation area Room 702	Ceiling	Flaking	400	N	N	0	N	N	
13	5060	1	7	702		Indoor Recreation area Room 702	W1	Flaking	80	N	N	0	N	N	
14	5060	1	7	702		Indoor Recreation area Room 702	W2	Flaking	40	N	N	0	N	N	
15	5060	1	7	702		Indoor Recreation area Room 702	W3	Flaking	110	N	N	0	N	N	
16	5060	1	7	702		Indoor Recreation area Room 702	W4	Flaking	50	N	N	0	N	N	
17	5060	1	7	S75		Stairwell #1	Ceiling	Flaking	250	N	N	0	N	N	
18	5060	1	7	S75		Stairwell #1	Floor	Debris	0	N	Y - On Landing & Stairs	72	N	N	
19	5060	1	7	S75		Stairwell #1	W1	Flaking	45	N	N	0	N	N	
20	5060	1	7	S75		Stairwell #1	W2	Flaking	90	N	N	0	N	N	
21	5060	1	7	S75		Stairwell #1	W3	Flaking	120	N	N	0	N	N	
22	5060	1	7	S75		Stairwell #1	W4	Flaking	150	N	N	0	N	N	
23	5060	1	7	S73		Stairwell #2	Ceiling	Flaking	250	N	N	0	N	N	
24	5060	1	7	S73		Stairwell #2	Floor	Debris	0	N	Y - On Landing & Stairs	68	N	N	
25	5060	1	7	S73		Stairwell #2	W1	Flaking	45	N	N	0	N	N	
26	5060	1	7	S73		Stairwell #2	W2	Flaking	90	N	N	0	N	N	
27	5060	1	7	S73		Stairwell #2	W3	Flaking	120	N	N	0	N	N	
28	5060	1	7	S73		Stairwell #2	W4	Flaking	150	N	N	0	N	N	
29	5060	1	7	S74		Stairwell #3	Ceiling	Flaking	220	Y	N	0	N	Y - 80 SF	Additional Efflorescence
30	5060	1	7	S74		Stairwell #3	Floor	Debris	0	N	Y - On Landing & Stairs	84	N	N	
31	5060	1	7	S74		Stairwell #3	W1	Flaking	60	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
32	5060	1	7	S74		Stairwell #3	W2	Flaking	80	N	N	0	N	N	
33	5060	1	7	S74		Stairwell #3	W3	Flaking	120	N	N	0	N	N	
34	5060	1	7	S74		Stairwell #3	W4	Flaking	120	N	N	0	N	N	
35	5060	1	7	S71		Stairwell #4	Ceiling	Flaking	280	N	N	0	N	N	
36	5060	1	7	S71		Stairwell #4	Floor	Debris	0	N	Y - On Landing & Stairs	80	N	N	
37	5060	1	7	S71		Stairwell #4	W1	Flaking	60	N	N	0	N	N	
38	5060	1	7	S71		Stairwell #4	W2	Flaking	120	N	N	0	N	N	
39	5060	1	7	S71		Stairwell #4	W3	Flaking	100	N	N	0	N	N	
40	5060	1	7	S71		Stairwell #4	W4	Flaking	200	N	N	0	N	N	
41	5060	1	6	601		Classroom 601	W1	Partially Inaccessible	0	N	N	0	Y - 26 SF Desks, Contents	N	Limited Inspection
42	5060	1	6	601		Classroom 601	W3	Gouges	6	N	N	0	N	N	
43	5060	1	6	601		Classroom 601	W4	Partially Inaccessible	0	N	N	0	Y - 28 SF Contents	N	Limited Inspection
44	5060	1	6	602		Classroom 602	Ceiling	Efflorescence	8	Y	N	0	N	N	
45	5060	1	6	602		Classroom 602	W1	Chipping	7	N	N	0	N	N	
46	5060	1	6	602		Classroom 602	W2	Flaking	18	N	N	0	N	N	
47	5060	1	6	602		Classroom 602	W3	Flaking	12	N	N	0	N	N	
48	5060	1	6	602		Classroom 602	W4	Flaking	6	N	N	0	N	N	
49	5060	1	6	603		Classroom 603	W1	Flaking	16	N	N	0	N	N	Additional Cracking
50	5060	1	6	603		Classroom 603	W2	Flaking	20	N	N	0	N	N	
51	5060	1	6	603		Classroom 603	W3	Flaking	30	Y	N	0	N	Y - 8 SF	Additional Efflorescence
52	5060	1	6	603		Classroom 603	W4	Flaking	16	N	N	0	N	N	
53	5060	1	6	604		Classroom 604	W3	Flaking	14	N	N	0	N	N	
54	5060	1	6	604		Classroom 604	W4	Flaking	16	N	N	0	N	N	
55	5060	1	6	605/606		Classroom 605/606	W1	Chipping	4	N	N	0	Y - 20 SF Contents	N	
56	5060	1	6	605/606		Classroom 605/606	W2	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents	N	Limited Inspection
57	5060	1	6	605/606		Classroom 605/606	W3	Flaking	8	N	N	0	Y - 24 SF Contents	N	Additional Cracking
58	5060	1	6	605/606		Classroom 605/606	W4	Cracking	4	N	N	0	N	N	
59	5060	1	6	607/608		Classroom 607/608	W1	Chipping	4	N	N	0	Y - 28 SF Posters	N	
60	5060	1	6	607/608		Classroom 607/608	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks	N	Limited Inspection
61	5060	1	6	607/608		Classroom 607/608	W3	Flaking	3	N	N	0	Y - 16 SF Tables, Contents	N	
62	5060	1	6	609		Classroom 609	Floor	Debris	0	N	Y - @ Corner of Wall 3 & Wall 4	2	N	N	
63	5060	1	6	609		Classroom 609	W1	Flaking	16	N	N	0	N	N	
64	5060	1	6	609		Classroom 609	W2	Flaking	36	Y	N	0	N	Y - 36 SF	Additional Efflorescence
65	5060	1	6	609		Classroom 609	W3	Flaking	24	Y	N	0	N	Y - 24 SF	Additional Efflorescence
66	5060	1	6	609		Classroom 609	W4	Cracking	4	N	N	0	Y - 28 SF Contents	N	Additional Chipping
67	5060	1	6	610		Classroom 610	W1	Flaking	18	N	N	0	Y - 12 SF Posters	N	
68	5060	1	6	610		Classroom 610	W2	Chipping	10	N	N	0	Y - 10 SF Posters	N	
69	5060	1	6	610		Classroom 610	W3	Flaking	90	Y	N	0	N	Y - 40 SF	Additional Efflorescence



Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
103	5060	1	6	617A		Closet in Hall across Classroom 607	W3	Flaking	10	N	N	0	N	N	
104	5060	1	6	617A		Closet in Hall across Classroom 607	W4	Flaking	14	N	N	0	N	N	
105	5060	1	6	610A		Closet in Hall across Classroom 610	W2	Flaking	8	N	N	0	N	N	
106	5060	1	6	610A		Closet in Hall across Classroom 610	W3	Flaking	18	N	N	0	N	N	
107	5060	1	6	610A		Closet in Hall across Classroom 610	W4	Flaking	14	N	N	0	N	N	
108	5060	1	6	612C		Closet in Hall outside of the Girls' Restroom	Ceiling	Flaking	6	N	N	0	N	N	
109	5060	1	6	612C		Closet in Hall outside of the Girls' Restroom	W1	Cracking	3	N	N	0	N	N	
110	5060	1	6	612C		Closet in Hall outside of the Girls' Restroom	W2	Flaking	10	N	N	0	N	N	
111	5060	1	6	612C		Closet in Hall outside of the Girls' Restroom	W3	Flaking	10	N	N	0	N	N	
112	5060	1	6	612C		Closet in Hall outside of the Girls' Restroom	W4	Flaking	10	N	N	0	N	N	
113	5060	1	6	612B		Girls' Restroom across from Classroom 612	Ceiling	Cracking	6	N	N	0	N	N	
114	5060	1	6	H61		Hallway in front of Classroom 602	W3	Cracking	3	N	N	0	N	N	
115	5060	1	6	H63		Hallway in front of Classroom 611	W2	Efflorescence	20	Y	N	0	N	Y - 20 SF	
116	5060	1	6	H65		Hallway in front of Classroom 613	W1	Cracking	4	N	N	0	N	Y - 2 SF	Additional Cracking
117	5060	1	6	613		Room 613	W1	Partially Inaccessible	0	N	N	0	Y - 28 SF Cabinets, Contents	N	Limited Inspection
118	5060	1	6	613		Room 613	W2	Partially Inaccessible	0	N	N	0	Y - 18 SF Posters, Contents	N	Limited Inspection
119	5060	1	6	613		Room 613	W3	Partially Inaccessible	0	N	N	0	Y - 26 SF Contents	N	Limited Inspection
120	5060	1	6	613		Room 613	W4	Partially Inaccessible	0	N	N	0	Y - 24 SF Contents	N	Limited Inspection
121	5060	1	6	613A		Room 613 Kitchen area	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
122	5060	1	6	613A		Room 613 Kitchen area	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
123	5060	1	6	613A		Room 613 Kitchen area	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
124	5060	1	6	613A		Room 613 Kitchen area	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
125	5060	1	6	613A		Room 613 Kitchen area	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
126	5060	1	6	613A		Room 613 Kitchen area	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
127	5060	1	6	600		Room across from Classroom 601	Floor	Debris	0	N	Y - Beneath Windows	5	N	N	
128	5060	1	6	600		Room across from Classroom 601	W1	Flaking	21	N	N	0	N	N	Additional Chipping
129	5060	1	6	600		Room across from Classroom 601	W2	Flaking	60	Y	N	0	N	Y - 30 SF	Additional Efflorescence
130	5060	1	6	600		Room across from Classroom 601	W3	Flaking	6	N	N	0	N	N	Additional Chipping
131	5060	1	6	600A		Staff Restroom next to Classroom 601	Ceiling	Cracking	14	N	N	0	N	N	
132	5060	1	6	S63		Stairwell #2	Ceiling	Flaking	52	N	N	0	N	N	
133	5060	1	6	S63		Stairwell #2	W1	Flaking	18	N	N	0	N	N	
134	5060	1	6	S63		Stairwell #2	W2	Flaking	20	N	N	0	N	N	
135	5060	1	6	S63		Stairwell #2	W3	Flaking	40	N	N	0	N	N	
136	5060	1	6	S63		Stairwell #2	W4	Flaking	34	N	N	0	N	N	
137	5060	1	6	S64		Stairwell #3	W1	Flaking	12	Y	N	0	N	Y - 12 SF	Additional Efflorescence
138	5060	1	6	S64		Stairwell #3	W2	Cracking	3	N	N	0	N	N	
139	5060	1	6	S64		Stairwell #3	W3	Chipping	2	N	N	0	N	N	Chipping on Door
140	5060	1	6	S64		Stairwell #3	W4	Flaking	2	N	N	0	N	N	Additional Chipping
141	5060	1	6	S61		Stairwell #4	Ceiling	Flaking	50	N	N	0	N	N	
142	5060	1	6	S61		Stairwell #4	W1	Flaking	28	N	N	0	N	N	
143	5060	1	6	S61		Stairwell #4	W2	Flaking	16	N	N	0	N	N	Additional Chipping
144	5060	1	6	S61		Stairwell #4	W3	Flaking	36	N	N	0	N	N	Additional Cracking
145	5060	1	6	S61		Stairwell #4	W4	Chipping	30	N	N	0	N	N	Additional Cracking
146	5060	1	6	S62		Stairwell at Classroom 604	Ceiling	Flaking	60	N	N	0	N	N	
147	5060	1	6	S62		Stairwell at Classroom 604	W1	Flaking	20	N	N	0	N	N	
148	5060	1	6	S62		Stairwell at Classroom 604	W2	Flaking	42	N	N	0	N	N	
149	5060	1	6	S62		Stairwell at Classroom 604	W3	Flaking	36	N	N	0	N	N	
150	5060	1	6	S62		Stairwell at Classroom 604	W4	Flaking	28	N	N	0	N	N	
151	5060	1	6	600B		Storage Room outside of Staff Restroom next to Classroom 601	W1	Partially Inaccessible	0	N	N	0	Y - 28 SF Shelves, Contents	N	Limited Inspection
152	5060	1	6	600B		Storage Room outside of Staff Restroom next to Classroom 601	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Shelves, Contents	N	Limited Inspection

Mastbaum -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
153	5060	1	6	600B		Storage Room outside of Staff Restroom next to Classroom 601	W3	Partially Inaccessible	0	N	N	0	Y - 30 SF Shelves Contents	N	Limited Inspection
154	5060	1	6	600B		Storage Room outside of Staff Restroom next to Classroom 601	W4	Partially Inaccessible	0	N	N	0	Y - 48 SF Shelves, Contents	N	Limited Inspection
155	5060	1	6	612A		Women's Faculty Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
156	5060	1	6	612A		Women's Faculty Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
157	5060	1	6	612A		Women's Faculty Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
158	5060	1	6	612A		Women's Faculty Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
159	5060	1	6	612A		Women's Faculty Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
160	5060	1	6	612A		Women's Faculty Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
161	5060	1	5	515		Cafe Dining Area	W2	Flaking	20	Y	N	0	N	Y - 20 SF	Additional Cracking, Chipping
162	5060	1	5	515		Cafe Dining Area	W4	Flaking	26	Y	N	0	N	Y - 10 SF	Additional Efflorescence, Cracking, Chipping
163	5060	1	5	506A		Cafe Dining area between Classroom 506 and 510	W1	Flaking	32	N	N	0	N	N	Additional Chipping
164	5060	1	5	506A		Cafe Dining area between Classroom 506 and 510	W2	Flaking	16	N	N	0	N	N	Additional Cracking, Chipping
165	5060	1	5	506A		Cafe Dining area between Classroom 506 and 510	W4	Flaking	6	N	N	0	N	Y - 6 SF	Additional Cracking, Holes
166	5060	1	5	509		Cafeteria Staff Locker Room	W1	Chipping	4	N	N	0	N	N	
167	5060	1	5	509		Cafeteria Staff Locker Room	W2	Flaking	12	N	N	0	N	N	
168	5060	1	5	509		Cafeteria Staff Locker Room	W3	Flaking	28	N	N	0	N	N	
169	5060	1	5	509		Cafeteria Staff Locker Room	W4	Flaking	13	N	N	0	N	N	
170	5060	1	5	509A		Cafeteria Staff Locker Room Restroom	W1	Chipping	4	N	N	0	N	N	
171	5060	1	5	509A		Cafeteria Staff Locker Room Restroom	W2	Cracking	8	N	N	0	N	N	
172	5060	1	5	505		Classroom 505	Ceiling	None	0	Y	N	0	Y - 48 SF Contents	N	Suspended Ceiling; Water Stain on Ceiling Tile
173	5060	1	5	505		Classroom 505	Floor	Debris	0	N	Y - @ Perimeter	20	N	N	
174	5060	1	5	505		Classroom 505	W2	Flaking	52	N	N	0	N	N	Additional Chipping

Mastbaum -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
175	5060	1	5	505		Classroom 505	W3	Flaking	60	Y	N	0	N	Y - 4 SF	Additional Efflorescence
176	5060	1	5	505		Classroom 505	W4	Flaking	8	N	N	0	N	N	Additional Chipping
177	5060	1	5	510		Classroom 510 Kitchen	Ceiling	Flaking	26	N	N	0	N	N	Suspended Ceiling
178	5060	1	5	510		Classroom 510 Kitchen	W1	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks, Bookcases	N	Limited Inspection
179	5060	1	5	510		Classroom 510 Kitchen	W2	Flaking	12	N	N	0	N	N	
180	5060	1	5	510		Classroom 510 Kitchen	W3	Flaking	18	N	N	0	N	N	
181	5060	1	5	512		Classroom 512/Kitchen	W1	Chipping	8	N	N	0	Y - 20 SF Contents, Desks	N	
182	5060	1	5	512		Classroom 512/Kitchen	W2	Flaking	12	N	N	0	Y - 24 SF Desks	N	
183	5060	1	5	512		Classroom 512/Kitchen	W3	Flaking	20	N	N	0	Y - 24 SF Desks	N	
184	5060	1	5	512		Classroom 512/Kitchen	W4	Cracking	10	N	N	0	Y - 36 SF Desks, Posters	N	
185	5060	1	5	513		Classroom 513/Cafe	W1	Flaking	8	N	N	0	N	N	
186	5060	1	5	513		Classroom 513/Cafe	W2	Flaking	12	N	N	0	N	N	
187	5060	1	5	513		Classroom 513/Cafe	W3	Flaking	24	N	N	0	N	N	
188	5060	1	5	513		Classroom 513/Cafe	W4	Flaking	10	N	N	0	N	N	
189	5060	1	5	501B		Closet in Hallway across Room 501	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
190	5060	1	5	501B		Closet in Hallway across Room 501	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
191	5060	1	5	501B		Closet in Hallway across Room 501	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
192	5060	1	5	501B		Closet in Hallway across Room 501	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
193	5060	1	5	501B		Closet in Hallway across Room 501	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
194	5060	1	5	501B		Closet in Hallway across Room 501	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
195	5060	1	5	501A		Closet in Hallway adjacent to Room 501	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
196	5060	1	5	501A		Closet in Hallway adjacent to Room 501	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
197	5060	1	5	501A		Closet in Hallway adjacent to Room 501	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
198	5060	1	5	501A		Closet in Hallway adjacent to Room 501	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
199	5060	1	5	501A		Closet in Hallway adjacent to Room 501	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
200	5060	1	5	501A		Closet in Hallway adjacent to Room 501	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
201	5060	1	5	514		Food Storage Room next to Stairwell # 3	Ceiling	Flaking	240	N	N	0	N	N	
202	5060	1	5	514		Food Storage Room next to Stairwell # 3	W1	Cracking	18	N	N	0	Y - 120 SF Boxes, Contents	N	
203	5060	1	5	514		Food Storage Room next to Stairwell # 3	W2	Flaking	24	N	N	0	N	N	Additional Cracking
204	5060	1	5	514		Food Storage Room next to Stairwell # 3	W3	Flaking	62	Y	N	0	Y - 200 SF Boxes, Contents	N	Additional Efflorescence
205	5060	1	5	514		Food Storage Room next to Stairwell # 3	W4	Flaking	28	Y	N	0	N	Y - 10 SF	Additional Efflorescence
206	5060	1	5	508		Girls' Restroom next to Kitchen Staff Locker Room	Ceiling	Holes	2	N	N	0	N	N	
207	5060	1	5	508		Girls' Restroom next to Kitchen Staff Locker Room	Floor	Chipping	16	N	N	0	N	N	Chipping @ Perimeter
208	5060	1	5	508		Girls' Restroom next to Kitchen Staff Locker Room	W1	Flaking	50	N	N	0	N	N	
209	5060	1	5	508		Girls' Restroom next to Kitchen Staff Locker Room	W2	Flaking	8	N	N	0	N	N	Additional Cracking
210	5060	1	5	508		Girls' Restroom next to Kitchen Staff Locker Room	W3	Chipping	24	N	N	0	N	N	Additional Gouges
211	5060	1	5	508		Girls' Restroom next to Kitchen Staff Locker Room	W4	Chipping	3	N	N	0	N	N	
212	5060	1	5	H53		Hallway from Stairwell #2 to #3	Floor	Chipping	20	N	N	0	N	N	Chipping @ Perimeter
213	5060	1	5	H53		Hallway from Stairwell #2 to #3	W2	Cracking	2	N	N	0	N	N	Additional Chipping
214	5060	1	5	H52A		Hallway in front of Classroom 505	W1	Chipping	6	N	N	0	N	N	
215	5060	1	5	H52A		Hallway in front of Classroom 505	W2	Chipping	6	N	N	0	N	N	
216	5060	1	5	H52A		Hallway in front of Classroom 505	W3	Cracking	8	N	N	0	N	N	
217	5060	1	5	H52A		Hallway in front of Classroom 505	W4	Cracking	8	N	N	0	N	N	
218	5060	1	5	H51		Hallway in front of Stair #4	W2	Flaking	18	N	N	0	N	N	



Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
219	5060	1	5	H51		Hallway in front of Stair #4	W3	Chipping	1	N	N	0	N	N	
220	5060	1	5	H51		Hallway in front of Stair #4	W4	Cracking	2	N	N	0	N	N	Additional Chipping
221	5060	1	5	502		IMC	Ceiling	Flaking	128	N	N	0	N	N	
222	5060	1	5	502		IMC	Floor	Debris	0	N	Y - Beneath Windows	6	N	N	
223	5060	1	5	502		IMC	W2	Flaking	4	N	N	0	N	Y - 4 SF	Adicional Efflorescence
224	5060	1	5	502		IMC	W3	Partially Inaccessible	0	N	N	0	Y - 90 SF Bookcases, Books	N	Limited Inspection
225	5060	1	5	502		IMC	W4	Chipping	5	N	N	0	Y - 140 SF Bookcases, Books	N	
226	5060	1	5	507		Kitchen at the Northernmost wall	W1	Flaking	8	N	N	0	Y - 200 SF Kitchen Supplies	N	
227	5060	1	5	507		Kitchen at the Northernmost wall	W3	Flaking	32	N	N	0	N	Y - 8 SF	Additional Efflorescence; Damage on Wall & Radiator
228	5060	1	5	507		Kitchen at the Northernmost wall	W4	Chipping	32	N	N	0	N	N	
229	5060	1	5	H54		Long Narrow Kitchen Area former Hallway	W1	Cracking	6	N	N	0	Y - 170 SF Kitchen Appliances	N	
230	5060	1	5	H54		Long Narrow Kitchen Area former Hallway	W2	Cracking	4	N	N	0	N	N	Additional Chipping
231	5060	1	5	H54		Long Narrow Kitchen Area former Hallway	W3	Chipping	30	N	N	0	N	N	
232	5060	1	5	H54		Long Narrow Kitchen Area former Hallway	W4	Cracking	1	N	N	0	N	N	
233	5060	1	5	514B		Office next to Stairwell # 3	Ceiling	Flaking	30	Y	N	0	N	Y - 2 SF	Additional Efflorescence
234	5060	1	5	514B		Office next to Stairwell # 3	W2	Flaking	8	N	N	0	N	N	Additional Cracking
235	5060	1	5	514B		Office next to Stairwell # 3	W3	Flaking	24	Y	N	0	N	Y - 24 SF	Additional Efflorescence
236	5060	1	5	514B		Office next to Stairwell # 3	W4	Flaking	20	N	N	0	N	N	Additional Cracking
237	5060	1	5	514C		Restroom inside Office next to Stairwell # 3	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
238	5060	1	5	514C		Restroom inside Office next to Stairwell # 3	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
239	5060	1	5	514C		Restroom inside Office next to Stairwell # 3	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
240	5060	1	5	514C		Restroom inside Office next to Stairwell # 3	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
241	5060	1	5	514C		Restroom inside Office next to Stairwell # 3	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
242	5060	1	5	514C		Restroom inside Office next to Stairwell # 3	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
243	5060	1	5	501		Room 501	Ceiling	Flaking	98	Y	N	0	N	Y - 98 SF	Additional Efflorescence
244	5060	1	5	501		Room 501	W1	Partially Inaccessible	0	N	N	0	Y - 32 SF Contents	N	Limited Inspection
245	5060	1	5	501		Room 501	W2	Flaking	10	N	N	0	N	N	Additional Chipping
246	5060	1	5	501		Room 501	W3	Flaking	32	Y	N	0	N	Y - 32 SF	Additional Efflorescence
247	5060	1	5	501		Room 501	W4	Flaking	20	Y	N	0	N	Y - 20 SF	Additional Efflorescence
248	5060	1	5	506		Room 506	Floor	Debris	0	N	Y - Beneath Windows	16	N	N	
249	5060	1	5	506		Room 506	W2	Flaking	4	N	N	0	N	Y - 1 SF	Additional Efflorescence, Chipping
250	5060	1	5	506		Room 506	W3	Flaking	28	N	N	0	N	Y - 20 SF	Additional Efflorescence
251	5060	1	5	506		Room 506	W4	Flaking	3	N	N	0	N	Y - 3 SF	Additional Efflorescence, Chipping
252	5060	1	5	S53		Stair # 2	Ceiling	Flaking	32	N	N	0	N	N	
253	5060	1	5	S53		Stair # 2	W1	Flaking	80	N	N	0	N	N	
254	5060	1	5	S53		Stair # 2	W2	Flaking	12	N	N	0	N	N	
255	5060	1	5	S53		Stair # 2	W3	Flaking	80	N	N	0	N	N	
256	5060	1	5	S53		Stair # 2	W4	Flaking	16	N	N	0	N	N	
257	5060	1	5	S54		Stair # 3	W1	Flaking	72	Y	N	0	N	Y - 72 SF	Additional Efflorescence
258	5060	1	5	S54		Stair # 3	W4	Flaking	22	Y	N	0	N	Y - 18 SF	Additional Efflorescence
259	5060	1	5	S51		Stair # 4	Ceiling	Flaking	48	N	N	0	N	N	
260	5060	1	5	S51		Stair # 4	W1	Flaking	8	N	N	0	N	N	
261	5060	1	5	S51		Stair # 4	W2	Flaking	40	N	N	0	N	N	Additional Chipping
262	5060	1	5	S51		Stair # 4	W3	Flaking	26	N	N	0	N	N	Additional Chipping
263	5060	1	5	S51		Stair # 4	W4	Flaking	60	N	N	0	N	N	Additional Chipping
264	5060	1	5	S52		Stairwell at Classroom 505	W3	Flaking	6	N	N	0	N	Y - 6 SF	
265	5060	1	5	513A		Storage Closet in Hallway across from Classroom 513/Cafe	W1	Cracking	3	N	N	0	N	N	
266	5060	1	5	513A		Storage Closet in Hallway across from Classroom 513/Cafe	W2	Flaking	10	N	N	0	N	N	
267	5060	1	5	513A		Storage Closet in Hallway across from Classroom 513/Cafe	W3	Flaking	4	N	N	0	N	N	
268	5060	1	5	513A		Storage Closet in Hallway across from Classroom 513/Cafe	W4	Flaking	6	N	N	0	N	N	
269	5060	2	4	413A		Boys' Restroom	Ceiling	Flaking	3	N	N	0	N	N	
270	5060	1	4	401		Classroom 401	Ceiling	Flaking	6	Y	N	0	N	Y - 6 SF	Additional Efflorescence; Damage @ Window Lintels; Suspended Ceiling
271	5060	1	4	401		Classroom 401	W2	Partially Inaccessible	0	N	N	0	N	N	Limited Inspection

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
272	5060	1	4	401		Classroom 401	W3	Flaking	8	N	N	0	N	N	
273	5060	1	4	401		Classroom 401	W4	Efflorescence	8	Y	N	0	N	Y - 8 SF	
274	5060	1	4	402/403		Classroom 402/403	W1	Partially Inaccessible	0	N	N	0	Y - 36 SF Desks, Cabinets, Posters	N	Limited Inspection
275	5060	1	4	402/403		Classroom 402/403	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks, Cabinets, Posters	N	Limited Inspection
276	5060	1	4	402/403		Classroom 402/403	W3	Partially Inaccessible	0	N	N	0	Y - 32 SF Desks, Cabinets, Posters	N	Limited Inspection
277	5060	1	4	402/403		Classroom 402/403	W4	Chipping	9	N	N	0	N	N	
278	5060	1	4	404/405		Classroom 404/405	Ceiling	Efflorescence	8	Y	N	0	N	Y - 8 SF	Suspended Ceiling
279	5060	1	4	404/405		Classroom 404/405	W1	Flaking	30	N	N	0	N	N	Additional Chipping
280	5060	1	4	404/405		Classroom 404/405	W2	Flaking	18	Y	N	0	N	N	Additional Efflorescence
281	5060	1	4	404/405		Classroom 404/405	W3	Flaking	80	Y	Y - On Window Sills	4	N	Y - 10 SF	Additional Efflorescence
282	5060	1	4	404/405		Classroom 404/405	W4	Flaking	20	Y	N	0	N	N	Additional Efflorescence
283	5060	1	4	406		Classroom 406	Ceiling	Flaking	18	N	N	0	N	N	Suspended Ceiling; Flaking on Beam
284	5060	1	4	406		Classroom 406	W1	Partially Inaccessible	0	N	N	0	Y - 20 SF Desks, Bookcases, Contents	N	Limited Inspection
285	5060	1	4	406		Classroom 406	W2	Cracking	12	N	N	0	Y - 30 SF File Cabinets, Bookcases, Books	N	Additional Chipping
286	5060	1	4	406		Classroom 406	W3	Flaking	20	N	N	0	Y - 40 SF Desks	N	
287	5060	1	4	406		Classroom 406	W4	Flaking	22	N	N	0	Y - 60 SF Desks, Contents	N	
288	5060	1	4	407		Classroom 407	Ceiling	Efflorescence	48	Y	N	0	N	Y - 48 SF	Damage on Beam
289	5060	1	4	407		Classroom 407	W1	Chipping	20	N	N	0	N	N	
290	5060	1	4	407		Classroom 407	W2	Flaking	8	N	N	0	N	N	
291	5060	1	4	407		Classroom 407	W3	Flaking	14	Y	N	0	N	Y - 2 SF	Additional Efflorescence
292	5060	1	4	407		Classroom 407	W4	Chipping	16	N	N	0	N	Y - 16 SF	
293	5060	1	4	408		Classroom 408	W1	Partially Inaccessible	0	N	N	0	Y - 32 SF Contents	N	Limited Inspection
294	5060	1	4	408		Classroom 408	W2	Flaking	4	N	N	0	N	N	
295	5060	1	4	408		Classroom 408	W3	Flaking	18	N	N	0	N	N	
296	5060	1	4	408		Classroom 408	W4	Chipping	6	N	N	0	Y - 20 SF Posters	N	
297	5060	1	4	409		Classroom 409	W1	Partially Inaccessible	0	N	N	0	Y - 32 SF Contents	N	Limited Inspection

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
298	5060	1	4	409		Classroom 409	W2	Flaking	10	N	N	0	N	N	
299	5060	1	4	409		Classroom 409	W3	Flaking	15	N	N	0	N	N	
300	5060	1	4	409		Classroom 409	W4	Chipping	4	N	N	0	Y - 20 SF Posters	N	
301	5060	1	4	410		Classroom 410	W1	Partially Inaccessible	0	N	N	0	N	N	Limited Inspection
302	5060	1	4	410		Classroom 410	W2	Flaking	16	Y	N	0	N	Y - 8 SF	Additional Efflorescence
303	5060	1	4	410		Classroom 410	W3	Flaking	60	Y	N	0	N	Y - 20 SF	Additional Efflorescence
304	5060	1	4	410		Classroom 410	W4	Chipping	10	N	N	0	N	N	
305	5060	1	4	412/411		Classroom 412/411	Ceiling	Flaking	48	Y	N	0	N	N	Suspended Ceiling; Damage @ Missing Ceiling Tiles, Beam, Window Lintels
306	5060	1	4	412/411		Classroom 412/411	Floor	Debris	0	N	Y - Beneath Windows	10	N	N	
307	5060	1	4	412/411		Classroom 412/411	W1	Flaking	30	N	N	0	N	Y - 5 SF	
308	5060	1	4	412/411		Classroom 412/411	W2	Flaking	20	N	N	0	N	Y - 2 SF	Additional Chipping
309	5060	1	4	412/411		Classroom 412/411	W3	Flaking	8	Y	N	0	N	Y - 8 SF	Additional Efflorescence
310	5060	1	4	412/411		Classroom 412/411	W4	Chipping	24	N	N	0	N	N	
311	5060	1	4	413		Classroom 413	Floor	Debris	0	N	Y - @ Perimeter	5	N	N	Additional Efflorescence
312	5060	1	4	413		Classroom 413	W1	Flaking	32	N	N	0	N	N	Additional Cracking, Chipping
313	5060	1	4	413		Classroom 413	W2	Flaking	48	N	N	0	N	N	Additional Chipping
314	5060	1	4	413		Classroom 413	W3	Flaking	48	Y	N	0	N	Y - 20 SF	Additional Efflorescence
315	5060	1	4	413		Classroom 413	W4	Flaking	30	Y	N	0	N	Y - 10 SF	Additional Efflorescence
316	5060	1	4	414		Classroom 414	Floor	Debris	0	N	Y - @ Wall 3	4	N	N	
317	5060	1	4	414		Classroom 414	W1	Flaking	30	Y	N	0	N	Y - 8 SF	Additional Efflorescence
318	5060	1	4	414		Classroom 414	W2	Flaking	20	Y	N	0	N	Y - 20 SF	Additional Efflorescence
319	5060	1	4	414		Classroom 414	W3	Flaking	18	Y	Y - On Window Sill & Radiator	4	N	Y - 20 SF	
320	5060	1	4	414		Classroom 414	W4	Flaking	22	N	N	0	N	N	Additional Efflorescence
321	5060	1	4	415		Classroom 415	Ceiling	Flaking	4	Y	N	0	N	Y - 3 SF	
322	5060	1	4	415		Classroom 415	Floor	Debris	0	N	Y - @ Wall 3	4	N	N	
323	5060	1	4	415		Classroom 415	W1	Flaking	72	Y	N	0	N	Y - 8 SF	Additional Efflorescence
324	5060	1	4	415		Classroom 415	W2	Flaking	88	Y	N	0	N	Y - 20 SF	Additional Efflorescence
325	5060	1	4	415		Classroom 415	W3	Flaking	32	Y	Y - On Window Sill & Radiator	4	N	Y - 20 SF	
326	5060	1	4	415		Classroom 415	W4	Flaking	14	N	N	0	N	N	Additional Efflorescence
327	5060	2	4	420		Classroom 420	W1	Flaking	20	N	N	0	N	N	
328	5060	2	4	420		Classroom 420	W2	Flaking	16	N	N	0	N	N	Additional Cracking, Chipping
329	5060	2	4	420		Classroom 420	W3	Flaking	40	N	N	0	N	N	
330	5060	2	4	420		Classroom 420	W4	Cracking	20	N	N	0	N	N	
331	5060	2	4	420A		Classroom 420A	W1	Flaking	20	N	N	0	N	N	
332	5060	2	4	420A		Classroom 420A	W2	Flaking	30	N	N	0	N	N	
333	5060	2	4	420A		Classroom 420A	W3	Flaking	20	N	N	0	N	N	
334	5060	2	4	420A		Classroom 420A	W4	Flaking	40	N	N	0	N	N	
335	5060	2	4	420B		Classroom 420B	W1	Flaking	25	N	N	0	N	N	
336	5060	2	4	420B		Classroom 420B	W2	Flaking	40	N	N	0	N	N	
337	5060	2	4	420B		Classroom 420B	W3	Flaking	25	N	N	0	N	N	
338	5060	2	4	420B		Classroom 420B	W4	Flaking	40	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
339	5060	2	4	421		Classroom 421	W2	Flaking	65	Y	Y - On Window Sills	12	N	N	
340	5060	2	4	423		Classroom 423 Computer Room	W1	Chipping	4	N	N	0	Y - 120 SF Bookcases, Books, File Cabinets	N	Chipping @ Door Frame
341	5060	2	4	423		Classroom 423 Computer Room	W2	Partially Inaccessible	0	N	N	0	Y - 80 SF File Cabinets, Desks	N	Limited Inspection
342	5060	2	4	423		Classroom 423 Computer Room	W3	Flaking	210	Y	Y - On Window Sills	4	N	N	Additional Cracking, Chipping, Holes
343	5060	2	4	423C		Classroom 423 Server Room	W2	Partially Inaccessible	0	N	N	0	Y - 12 SF Contents	N	Limited Inspection
344	5060	2	4	423C		Classroom 423 Server Room	W3	Partially Inaccessible	0	N	N	0	Y - 18 SF Contents	N	Limited Inspection
345	5060	2	4	423C		Classroom 423 Server Room	W4	Partially Inaccessible	0	N	N	0	Y - 12 SF Contents	N	Limited Inspection
346	5060	2	4	424		Classroom 424	W1	Chipping	4	N	N	0	N	N	
347	5060	2	4	424		Classroom 424	W2	Cracking	10	N	N	0	N	N	
348	5060	2	4	424		Classroom 424	W3	Flaking	20	N	N	0	N	N	
349	5060	2	4	425		Classroom 425	W1	Cracking	12	N	N	0	N	N	Additional Chipping
350	5060	2	4	425		Classroom 425	W2	Flaking	80	N	N	0	N	N	
351	5060	2	4	425		Classroom 425	W3	Flaking	120	N	N	0	N	N	
352	5060	2	4	425		Classroom 425	W4	Flaking	36	N	Y - On Window Sills	3	N	N	
353	5060	2	4	426		Classroom 426 former Electrical Classroom used for storage	W3	Flaking	20	N	N	0	N	N	
354	5060	1	4	411B		Closet in Hallway across Classroom 411 closer to Classroom 409	W2	Flaking	4	N	N	0	Y - 20 SF Contents	N	
355	5060	1	4	411B		Closet in Hallway across Classroom 411 closer to Classroom 409	W3	Flaking	4	N	N	0	Y - 12 SF Contents	N	
356	5060	1	4	411B		Closet in Hallway across Classroom 411 closer to Classroom 409	W4	Flaking	8	N	N	0	Y - 16 SF Contents	N	
357	5060	1	4	405A		Closet in Hallway across from Classroom 405	W2	Flaking	10	N	N	0	Y - 16 SF Contents	N	
358	5060	1	4	405A		Closet in Hallway across from Classroom 405	W3	Flaking	14	N	N	0	Y - 8 SF Contents	N	
359	5060	1	4	405A		Closet in Hallway across from Classroom 405	W4	Flaking	10	N	N	0	Y - 16 SF Contents	N	
360	5060	1	4	407A		Closet in Hallway across from Classroom 407	W2	Flaking	9	N	N	0	Y - 24 SF Contents	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
361	5060	1	4	407A		Closet in Hallway across from Classroom 407	W3	Flaking	12	N	N	0	Y - 16 SF Contents	N	
362	5060	1	4	407A		Closet in Hallway across from Classroom 407	W4	Flaking	6	N	N	0	Y - 20 SF Contents	N	
363	5060	1	4	411A		Closet in Hallway across from Classroom 411	W2	Flaking	12	N	N	0	Y - 16 SF Contents	N	
364	5060	1	4	411A		Closet in Hallway across from Classroom 411	W3	Flaking	12	N	N	0	Y - 8 SF Contents	N	
365	5060	1	4	411A		Closet in Hallway across from Classroom 411	W4	Flaking	12	N	N	0	Y - 16 SF Contents	N	
366	5060	1	4	H45		Hallway at the Boys' and Girls' Restrooms	W1	Flaking	64	N	N	0	N	N	Additional Cracking, Chipping
367	5060	1	4	H45		Hallway at the Boys' and Girls' Restrooms	W3	Flaking	16	N	N	0	N	Y - 4 SF	Additional Cracking, Holes
368	5060	1	4	H50		Hallway behind the upper part of the Gym between Stairwell #3 and #4	Ceiling	Flaking	60	Y	N	0	N	Y - 20 SF	Additional Efflorescence
369	5060	1	4	H50		Hallway behind the upper part of the Gym between Stairwell #3 and #4	W2	Chipping	4	N	N	0	N	Y - 1 SF	Additional Holes
370	5060	1	4	H41		Hallway in front of Classroom 402-405	W2	Flaking	8	Y	N	0	N	Y - 4 SF	Additional Efflorescence, Chipping
371	5060	1	4	H41		Hallway in front of Classroom 402-405	W4	Chipping	4	N	N	0	N	N	
372	5060	1	4	H42		Hallway in front of Classroom 407-408	W1	Chipping	6	N	N	0	N	N	Chipping on Pipe
373	5060	1	4	H42		Hallway in front of Classroom 407-408	W3	Chipping	3	N	N	0	N	N	Additional Gouges, Holes
374	5060	2	4	H42		Hallway in front of Rooms 427 and 426	W2	Chipping	72	N	N	0	N	N	
375	5060	2	4	H42		Hallway in front of Rooms 427 and 426	W4	Chipping	72	N	N	0	N	N	
376	5060	1	4	H52		Hallway outside of IMC and Classroom 505	W1	Chipping	6	N	N	0	N	N	
377	5060	1	4	H52		Hallway outside of IMC and Classroom 505	W3	Chipping	5	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
378	5060	2	4	H41		Hallway running East to West along side Rooms 426 and 421	W1	Chipping	2	N	N	0	N	N	
379	5060	2	4	H41		Hallway running East to West along side Rooms 426 and 421	W3	Chipping	14	N	N	0	N	N	
380	5060	1	4	416		Office 416 up a small flight of Stairs across from Classroom 408	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
381	5060	1	4	416		Office 416 up a small flight of Stairs across from Classroom 408	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
382	5060	1	4	416		Office 416 up a small flight of Stairs across from Classroom 408	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Unoccupied by Students & Teachers
383	5060	1	4	416		Office 416 up a small flight of Stairs across from Classroom 408	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
384	5060	1	4	416		Office 416 up a small flight of Stairs across from Classroom 408	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
385	5060	1	4	416		Office 416 up a small flight of Stairs across from Classroom 408	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
386	5060	1	4	421		Office 416 up a small flight of Stairs across from Classroom 408 Office to the West	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
387	5060	1	4	421		Office 416 up a small flight of Stairs across from Classroom 408 Office to the West	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
388	5060	1	4	421		Office 416 up a small flight of Stairs across from Classroom 408 Office to the West	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Unoccupied by Students & Teachers
389	5060	1	4	421		Office 416 up a small flight of Stairs across from Classroom 408 Office to the West	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
390	5060	1	4	421		Office 416 up a small flight of Stairs across from Classroom 408 Office to the West	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
391	5060	1	4	421		Office 416 up a small flight of Stairs across from Classroom 408 Office to the West	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
392	5060	1	4	416A		Office 416 up a small flight of Stairs across from Classroom 408 Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
393	5060	1	4	416A		Office 416 up a small flight of Stairs across from Classroom 408 Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
394	5060	1	4	416A		Office 416 up a small flight of Stairs across from Classroom 408 Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Unoccupied by Students & Teachers
395	5060	1	4	416A		Office 416 up a small flight of Stairs across from Classroom 408 Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
396	5060	1	4	416A		Office 416 up a small flight of Stairs across from Classroom 408 Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
397	5060	1	4	416A		Office 416 up a small flight of Stairs across from Classroom 408 Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
398	5060	2	4	422		Room 422	W2	Partially Inaccessible	0	N	N	0	Y - 14 SF Desks, Contents	N	Limited Inspection
399	5060	2	4	422		Room 422	W3	Flaking	2	N	N	0	Y - 8 SF Desks	N	Additional Chipping
400	5060	2	4	422		Room 422	W4	Partially Inaccessible	0	N	N	0	Y - 16 SF Desks, Contents	N	Limited Inspection
401	5060	2	4	427		Room 427	Floor	Debris	0	N	Y - @ Perimeter	40	N	N	
402	5060	2	4	427		Room 427	W1	Flaking	240	N	N	0	N	N	
403	5060	2	4	427		Room 427	W2	Flaking	80	N	N	0	N	N	
404	5060	2	4	427		Room 427	W3	Flaking	64	Y	N	0	N	Y - 64 SF	Additional Efflorescence
405	5060	2	4	427		Room 427	W4	Flaking	20	N	N	0	N	N	



Mastbaum -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
406	5060	2	4	427B		Room 427 Hallway in front of 427B leading to Book Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
407	5060	2	4	427B		Room 427 Hallway in front of 427B leading to Book Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
408	5060	2	4	427B		Room 427 Hallway in front of 427B leading to Book Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
409	5060	2	4	427B		Room 427 Hallway in front of 427B leading to Book Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
410	5060	2	4	427B		Room 427 Hallway in front of 427B leading to Book Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
411	5060	2	4	427B		Room 427 Hallway in front of 427B leading to Book Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
412	5060	2	4	418/419		Room 427C	W1	Flaking	8	N	N	0	N	N	
413	5060	2	4	418/419		Room 427C	W2	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents	N	Limited Inspection
414	5060	2	4	418/419		Room 427C	W3	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents	N	Limited Inspection
415	5060	2	4	418/419		Room 427C	W4	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents	N	Limited Inspection
416	5060	1	4	S43		Stairwell # 2	Ceiling	Flaking	32	N	N	0	N	N	
417	5060	1	4	S43		Stairwell # 2	W1	Flaking	42	N	N	0	N	N	
418	5060	1	4	S43		Stairwell # 2	W2	Flaking	4	N	N	0	N	N	
419	5060	1	4	S43		Stairwell # 2	W3	Flaking	36	N	N	0	N	N	
420	5060	1	4	S43		Stairwell # 2	W4	Flaking	14	N	N	0	N	N	
421	5060	1	4	S44		Stairwell # 3	Ceiling	Flaking	5	N	N	0	N	N	Flaking on Ceiling & Pipe
422	5060	1	4	S44		Stairwell # 3	W1	Chipping	2	N	N	0	N	N	Chipping on Pipe
423	5060	1	4	S44		Stairwell # 3	W4	Flaking	8	Y	N	0	N	Y - 4 SF	Additional Efflorescence, Cracking, Chipping
424	5060	1	4	S41		Stairwell # 4	Ceiling	Flaking	32	N	N	0	N	N	
425	5060	1	4	S41		Stairwell # 4	W1	Flaking	10	N	N	0	N	N	
426	5060	1	4	S41		Stairwell # 4	W2	Flaking	18	N	N	0	N	N	
427	5060	1	4	S41		Stairwell # 4	W3	Flaking	42	N	N	0	N	N	
428	5060	1	4	S41		Stairwell # 4	W4	Flaking	32	N	N	0	N	N	
429	5060	1	4	S45		Stairwell # 9	Ceiling	Flaking	16	N	N	0	N	N	
430	5060	1	4	S45		Stairwell # 9	W2	Flaking	16	N	N	0	N	N	
431	5060	2	4	S43		Stairwell #7	Ceiling	Flaking	8	N	N	0	N	N	Additional Cracking
432	5060	2	4	S43		Stairwell #7	W3	Chipping	4	N	N	0	N	N	
433	5060	2	4	S43		Stairwell #7	W4	Flaking	40	N	N	0	N	N	Additional Chipping
434	5060	2	4	S44		Stairwell #8	W1	Flaking	16	N	N	0	N	N	Additional Chipping
435	5060	2	4	S44		Stairwell #8	W2	Flaking	5	N	N	0	N	N	
436	5060	2	4	S44		Stairwell #8	W4	Flaking	12	N	N	0	N	N	Additional Chipping
437	5060	2	4	S45		Stairwell #9	Ceiling	Flaking	16	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
438	5060	2	4	S45		Stairwell #9	W2	Flaking	16	N	N	0	N	N	
439	5060	1	4	S42		Stairwell at Classroom 406	W4	Chipping	2	N	N	0	N	N	Chipping on Door
440	5060	1	4	416		Storage area next to the Women's Faculty Area	W1	Partially Inaccessible	0	N	N	0	Y - 48 SF Contents	N	Limited Inspection
441	5060	1	4	416		Storage area next to the Women's Faculty Area	W2	Partially Inaccessible	0	N	N	0	Y - 32 SF Contents	N	Limited Inspection
442	5060	1	4	416		Storage area next to the Women's Faculty Area	W3	Partially Inaccessible	0	N	N	0	Y - 52 SF Contents	N	Limited Inspection
443	5060	1	4	416		Storage area next to the Women's Faculty Area	W4	Partially Inaccessible	0	N	N	0	Y - 36 SF Contents	N	Limited Inspection
444	5060	1	4	417		Women's Faculty Area	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
445	5060	1	4	417		Women's Faculty Area	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
446	5060	1	4	417		Women's Faculty Area	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
447	5060	1	4	417		Women's Faculty Area	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
448	5060	1	4	417		Women's Faculty Area	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
449	5060	1	4	417		Women's Faculty Area	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
450	5060	1	4	420		Women's Faculty Area Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
451	5060	1	4	420		Women's Faculty Area Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
452	5060	1	4	420		Women's Faculty Area Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
453	5060	1	4	420		Women's Faculty Area Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
454	5060	1	4	420		Women's Faculty Area Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
455	5060	1	4	420		Women's Faculty Area Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
456	5060	1	4	419/418		Women's Faculty Area Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
457	5060	1	4	419/418		Women's Faculty Area Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
458	5060	1	4	419/418		Women's Faculty Area Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
459	5060	1	4	419/418		Women's Faculty Area Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
460	5060	1	4	419/418		Women's Faculty Area Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
461	5060	1	4	419/418		Women's Faculty Area Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
462	5060	1	3	307		Biology Office between Classrooms 306 and 308	W1	Flaking	8	N	N	0	Y - 42 SF Cabinets	N	
463	5060	1	3	307		Biology Office between Classrooms 306 and 308	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Cabinets, Boxes	N	Limited Inspection
464	5060	2	3	318		Boys' Restroom	Ceiling	Flaking	10	N	N	0	N	N	
465	5060	1	3	301		Classroom 301	Ceiling	Flaking	36	Y	N	0	N	Y - 36 SF	Additional Efflorescence
466	5060	1	3	301		Classroom 301	W1	Chipping	4	N	N	0	N	Y - 1 SF	Additional Holes
467	5060	1	3	301		Classroom 301	W2	Flaking	80	N	N	0	N	N	
468	5060	1	3	301		Classroom 301	W4	Flaking	24	Y	N	0	N	Y - 24 SF	Additional Efflorescence
469	5060	1	3	302		Classroom 302/303	W1	Flaking	8	N	N	0	N	N	
470	5060	1	3	302		Classroom 302/303	W2	Flaking	26	Y	N	0	N	Y - 4 SF	Additional Efflorescence
471	5060	1	3	302		Classroom 302/303	W3	Flaking	6	Y	N	0	Y - 64 SF Desks, Posters, Contents	Y - 6 SF	Additional Efflorescence
472	5060	1	3	302		Classroom 302/303	W4	Chipping	12	N	N	0	N	N	
473	5060	1	3	305		Classroom 305/304	W1	Partially Inaccessible	0	N	N	0	Y - 32 SF Desks, Posters	N	Limited Inspection
474	5060	1	3	305		Classroom 305/304	W2	Partially Inaccessible	0	N	N	0	Y - 26 SF Desks, Posters	N	Limited Inspection
475	5060	1	3	305		Classroom 305/304	W3	Flaking	6	N	N	0	Y - 18 SF Desks	N	Additional Chipping
476	5060	1	3	305		Classroom 305/304	W4	Chipping	10	N	N	0	Y - 20 SF Posters	N	
477	5060	1	3	306		Classroom 306	Ceiling	Flaking	24	N	N	0	N	N	Suspended Ceiling; Flaking on Beam
478	5060	1	3	306		Classroom 306	W1	Flaking	16	N	N	0	Y - 18 SF Posters	N	
479	5060	1	3	306		Classroom 306	W2	Flaking	24	N	N	0	N	N	Additional Cracking, Chipping
480	5060	1	3	306		Classroom 306	W3	Flaking	42	N	N	0	N	Y - 12 SF	Additional Efflorescence, Cracking
481	5060	1	3	306		Classroom 306	W4	Flaking	8	Y	N	0	N	N	Additional Cracking
482	5060	1	3	308		Classroom 308	Ceiling	Flaking	52	Y	N	0	N	N	Suspended Ceiling; Flaking on Beam; Water Stain on Ceiling Tile
483	5060	1	3	308		Classroom 308	W1	Cracking	16	N	N	0	N	N	Additional Chipping
484	5060	1	3	308		Classroom 308	W2	Flaking	64	N	N	0	Y - 40 SF Posters	N	Additional Chipping
485	5060	1	3	308		Classroom 308	W3	Flaking	104	Y	N	0	N	Y - 16 SF	Additional Efflorescence
486	5060	1	3	308		Classroom 308	W4	Flaking	2	N	N	0	N	N	
487	5060	1	3	310		Classroom 310	Ceiling	Flaking	26	N	N	0	N	N	
488	5060	1	3	310		Classroom 310	W1	Flaking	8	N	N	0	N	N	Additional Chipping; Damage on Wall & Pipe
489	5060	1	3	310		Classroom 310	W3	Flaking	60	Y	N	0	N	Y - 20 SF	Additional Efflorescence

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
490	5060	1	3	310		Classroom 310	W4	Flaking	20	N	N	0	N	N	Additional Cracking
491	5060	1	3	311		Classroom 311	W1	Chipping	2	N	N	0	N	N	
492	5060	1	3	311		Classroom 311	W2	Flaking	2	N	N	0	N	N	
493	5060	1	3	311		Classroom 311	W3	Flaking	50	Y	N	0	N	Y - 50 SF	Additional Efflorescence
494	5060	1	3	311		Classroom 311	W4	Chipping	4	N	N	0	N	N	
495	5060	1	3	313		Classroom 313/312	W1	Chipping	2	N	N	0	N	N	
496	5060	1	3	313		Classroom 313/312	W2	Flaking	4	N	N	0	N	N	
497	5060	1	3	313		Classroom 313/312	W3	Flaking	40	N	N	0	N	N	
498	5060	1	3	313		Classroom 313/312	W4	Chipping	10	N	N	0	N	N	
499	5060	1	3	315		Classroom 315	W1	Partially Inaccessible	0	N	N	0	Y - 20 SF Desks, Posters	N	Limited Inspection
500	5060	1	3	315		Classroom 315	W2	Flaking	8	N	N	0	N	N	Additional Cracking, Chipping
501	5060	1	3	315		Classroom 315	W3	Flaking	8	Y	N	0	Y - 24 SF Desks	Y - 4 SF	Additional Efflorescence
502	5060	1	3	315		Classroom 315	W4	Chipping	6	N	N	0	Y - 11 SF Desks, Contents	N	Additional Gouges
503	5060	2	3	321		Classroom 321	Floor	Chipping	20	N	N	0	N	N	
504	5060	2	3	321		Classroom 321	W1	Partially Inaccessible	0	N	N	0	Y - 110 SF Cabinets, Contents	N	Limited Inspection
505	5060	2	3	321		Classroom 321	W2	Partially Inaccessible	0	N	N	0	Y - 210 SF Cabinets, Contents	N	Limited Inspection
506	5060	2	3	321		Classroom 321	W3	Chipping	4	N	N	0	N	N	
507	5060	2	3	323		Classroom 323	W1	Flaking	78	N	N	0	N	N	
508	5060	2	3	323		Classroom 323	W2	Flaking	90	N	N	0	N	N	
509	5060	2	3	323		Classroom 323	W3	Flaking	220	Y	N	0	N	Y - 30 SF	Additional Efflorescence
510	5060	2	3	323		Classroom 323	W4	Flaking	60	N	N	0	N	N	
511	5060	2	3	323A		Classroom 323 Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
512	5060	2	3	323A		Classroom 323 Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
513	5060	2	3	323A		Classroom 323 Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
514	5060	2	3	323A		Classroom 323 Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
515	5060	2	3	323A		Classroom 323 Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
516	5060	2	3	323A		Classroom 323 Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
517	5060	2	3	324		Classroom 324	W1	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
518	5060	2	3	324		Classroom 324	W2	Flaking	30	N	N	0	N	N	Additional Chipping
519	5060	2	3	324		Classroom 324	W3	Flaking	210	N	N	0	N	N	
520	5060	2	3	324		Classroom 324	W4	Flaking	12	N	N	0	N	N	Additional Cracking, Chipping
521	5060	2	3	325		Classroom 325	W1	Flaking	12	N	N	0	N	N	Additional Chipping

Mastbaum -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
522	5060	2	3	325		Classroom 325	W2	Flaking	10	N	N	0	N	N	Additional Chipping
523	5060	2	3	325		Classroom 325	W3	Flaking	28	Y	N	0	N	N	Additional Efflorescence
524	5060	2	3	325		Classroom 325	W4	Partially Inaccessible	0	N	N	0	Y - 28 SF Desks, Posters, Contents	Y - 14 SF	Limited Inspection
525	5060	2	3	325A		Classroom 325 Closet	W1	Partially Inaccessible	0	N	N	0	N	N	Limited Inspection
526	5060	2	3	325A		Classroom 325 Closet	W2	Partially Inaccessible	0	N	N	0	N	N	Limited Inspection
527	5060	2	3	325A		Classroom 325 Closet	W3	Partially Inaccessible	0	N	N	0	N	N	Limited Inspection
528	5060	2	3	326		Classroom 326	Ceiling	Flaking	100	Y	N	0	N	N	
529	5060	2	3	326		Classroom 326	W1	Flaking	140	N	N	0	N	N	
530	5060	2	3	326		Classroom 326	W2	Flaking	90	N	N	0	N	N	Additional Chipping
531	5060	2	3	326		Classroom 326	W3	Flaking	100	N	N	0	N	N	
532	5060	2	3	326		Classroom 326	W4	Flaking	160	N	N	0	N	N	
533	5060	1	3	314B		Closet in Hallway across Classroom 308	Ceiling	Cracking	4	N	N	0	N	N	
534	5060	1	3	314B		Closet in Hallway across Classroom 308	W1	Cracking	2	N	N	0	N	N	
535	5060	1	3	314B		Closet in Hallway across Classroom 308	W2	Flaking	8	N	N	0	Y - 16 SF Contents	N	
536	5060	1	3	314B		Closet in Hallway across Classroom 308	W3	Flaking	12	N	N	0	Y - 28 SF Contents	N	
537	5060	1	3	314B		Closet in Hallway across Classroom 308	W4	Flaking	10	N	N	0	Y - 22 SF Contents	N	
538	5060	1	3	311A		Closet in Hallway across Classroom 311	Ceiling	Cracking	10	N	N	0	N	N	
539	5060	1	3	311A		Closet in Hallway across Classroom 311	W2	Flaking	5	N	N	0	Y - 16 SF Contents	N	
540	5060	1	3	311A		Closet in Hallway across Classroom 311	W3	Flaking	5	N	N	0	Y - 20 SF Contents	N	
541	5060	1	3	311A		Closet in Hallway across Classroom 311	W4	Flaking	4	N	N	0	Y - 20 SF Contents	N	
542	5060	1	3	311B		Closet in Hallway across Classroom 311 closer to Classroom 308	Ceiling	Cracking	6	N	N	0	N	N	
543	5060	1	3	311B		Closet in Hallway across Classroom 311 closer to Classroom 308	W1	Cracking	2	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
544	5060	1	3	311B		Closet in Hallway across Classroom 311 closer to Classroom 308	W2	Flaking	2	N	N	0	Y - 24 SF Contents	N	
545	5060	1	3	311B		Closet in Hallway across Classroom 311 closer to Classroom 308	W3	Flaking	10	N	N	0	Y - 8 SF Contents	N	
546	5060	1	3	311B		Closet in Hallway across Classroom 311 closer to Classroom 308	W4	Flaking	9	N	N	0	Y - 24 SF Contents	N	
547	5060	1	3	316		Girls' Locker Room	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
548	5060	1	3	316		Girls' Locker Room	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
549	5060	1	3	316		Girls' Locker Room	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
550	5060	1	3	316		Girls' Locker Room	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
551	5060	1	3	316		Girls' Locker Room	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
552	5060	1	3	316		Girls' Locker Room	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
553	5060	1	3	316A		Girls' Locker Room Showers	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
554	5060	1	3	316A		Girls' Locker Room Showers	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
555	5060	1	3	316A		Girls' Locker Room Showers	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
556	5060	1	3	316A		Girls' Locker Room Showers	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
557	5060	1	3	316A		Girls' Locker Room Showers	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
558	5060	1	3	316A		Girls' Locker Room Showers	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
559	5060	2	3	319		Girls' Restroom	Ceiling	Flaking	10	N	N	0	N	N	
560	5060	1	3	314B		Gym Office	Ceiling	Flaking	20	N	N	0	N	N	
561	5060	1	3	314B		Gym Office	W1	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents	N	Limited Inspection
562	5060	1	3	314B		Gym Office	W2	Partially Inaccessible	0	N	N	0	Y - 28 SF Contents	N	Limited Inspection
563	5060	1	3	314B		Gym Office	W3	Partially Inaccessible	0	N	N	0	Y - 14 SF Contents	N	Limited Inspection
564	5060	1	3	314B		Gym Office	W4	Partially Inaccessible	0	N	N	0	Y - 18 SF Contents	N	Limited Inspection
565	5060	1	3	314		Gymnasium	Ceiling	Flaking	800	N	N	0	N	N	
566	5060	1	3	314		Gymnasium	W2	Flaking	30	N	N	0	N	N	Flaking Behind Radiators
567	5060	1	3	314		Gymnasium	W4	Flaking	30	N	N	0	N	N	Flaking Behind Radiators
568	5060	1	3	314A		Gymnasium Storage Closet to the West	W1	Partially Inaccessible	0	N	N	0	Y - 26 SF Contents	N	Limited Inspection

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
569	5060	1	3	314A		Gymnasium Storage Closet to the West	W2	Partially Inaccessible	0	N	N	0	Y - 32 SF Contents	N	Limited Inspection
570	5060	1	3	314A		Gymnasium Storage Closet to the West	W3	Partially Inaccessible	0	N	N	0	Y - 45 SF Contents	N	Limited Inspection
571	5060	1	3	314A		Gymnasium Storage Closet to the West	W4	Partially Inaccessible	0	N	N	0	N	N	Limited Inspection
572	5060	1	3	H31		Hallway at Classrooms 303-305	W2	Chipping	24	N	N	0	N	N	
573	5060	1	3	H31		Hallway at Classrooms 303-305	W4	Flaking	12	N	N	0	N	N	Additional Chipping, Holes
574	5060	1	3	H32A		Hallway at Classrooms 308	W1	Flaking	12	N	N	0	N	Y - 2 SF	Additional Chipping; Damage Includes Pipe
575	5060	1	3	H32A		Hallway at Classrooms 308	W3	Flaking	6	N	N	0	N	N	Additional Cracking
576	5060	1	3	H32		Hallway at Classrooms 311-315	W2	Cracking	7	N	N	0	N	N	
577	5060	1	3	H32		Hallway at Classrooms 311-315	W4	Flaking	6	N	N	0	N	N	
578	5060	1	3	H35		Hallway behind Girls' Locker Room	W1	Cracking	12	N	N	0	N	N	
579	5060	1	3	H35		Hallway behind Girls' Locker Room	W3	Flaking	50	N	N	0	N	N	
580	5060	2	3	H32		Hallway leading to Classroom 323	W2	Flaking	30	N	N	0	N	N	Additional Chipping
581	5060	2	3	H32		Hallway leading to Classroom 323	W4	Chipping	5	N	N	0	N	N	
582	5060	2	3	H33		Hallway leading to Classroom 324	W3	Chipping	2	N	N	0	N	N	
583	5060	1	3	305A		IT MDF Room across from Classroom 305/304	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
584	5060	1	3	305A		IT MDF Room across from Classroom 305/304	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
585	5060	1	3	305A		IT MDF Room across from Classroom 305/304	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
586	5060	1	3	305A		IT MDF Room across from Classroom 305/304	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
587	5060	1	3	305A		IT MDF Room across from Classroom 305/304	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
588	5060	1	3	305A		IT MDF Room across from Classroom 305/304	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
589	5060	1	3	309A		Laboratory Preparation area between Classrooms 308 and 310	W1	Flaking	40	N	N	0	N	N	
590	5060	1	3	309A		Laboratory Preparation area between Classrooms 308 and 310	W2	Flaking	24	N	N	0	Y - 40 SF Contents	N	
591	5060	1	3	309A		Laboratory Preparation area between Classrooms 308 and 310	W3	Partially Inaccessible	0	N	N	0	Y - 26 SF Contents	N	Limited Inspection
592	5060	1	3	309A		Laboratory Preparation area between Classrooms 308 and 310	W4	Flaking	12	N	N	0	Y - 60 SF Contents	N	
593	5060	2	3	327		Math Office Room 327	W1	Flaking	20	N	N	0	Y - 40 SF Bookcases, Books	N	
594	5060	2	3	327		Math Office Room 327	W2	Flaking	65	N	N	0	Y - 20 SF Posters	N	
595	5060	2	3	327		Math Office Room 327	W3	Flaking	48	N	N	0	N	N	
596	5060	2	3	327		Math Office Room 327	W4	Flaking	30	N	N	0	Y - 48 SF Desks, Bookcases, Books	N	
597	5060	2	3	322A		Men's and Women's Faculty Restroom	Ceiling	Cracking	6	N	N	0	N	N	
598	5060	2	3	322A		Men's and Women's Faculty Restroom	W1	Cracking	6	N	N	0	N	N	
599	5060	2	3	322		Room 322 Office behind Men's and Women's Faculty Restroom	W3	Flaking	8	N	N	0	N	N	
600	5060	1	3	S33		Stairwell #2 outside Classroom 310	Ceiling	Flaking	72	N	N	0	N	N	



Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
601	5060	1	3	S33		Stairwell #2 outside Classroom 310	W1	Chipping	5	N	N	0	N	N	
602	5060	1	3	S33		Stairwell #2 outside Classroom 310	W2	Flaking	40	N	N	0	N	N	Additional Chipping
603	5060	1	3	S33		Stairwell #2 outside Classroom 310	W3	Chipping	5	N	N	0	N	N	
604	5060	1	3	S33		Stairwell #2 outside Classroom 310	W4	Flaking	35	N	N	0	N	N	Additional Chipping
605	5060	1	3	S34		Stairwell #3 outside Classroom 313	Ceiling	Flaking	12	Y	N	0	N	Y - 12 SF	Additional Efflorescence
606	5060	1	3	S34		Stairwell #3 outside Classroom 313	Floor	Debris	0	N	Y - Near Wall 3	2	N	N	
607	5060	1	3	S34		Stairwell #3 outside Classroom 313	W1	Flaking	20	N	N	0	N	Y - 20 SF	Additional Efflorescence
608	5060	1	3	S34		Stairwell #3 outside Classroom 313	W3	Flaking	2	N	N	0	N	N	
609	5060	1	3	S34		Stairwell #3 outside Classroom 313	W4	Flaking	36	Y	Y - On Window Sill & Radiator	8	N	Y - 36 SF	Additional Efflorescence
610	5060	1	3	S31		Stairwell #4 outside Classroom 301	Ceiling	Flaking	48	N	N	0	N	Y - 48 SF	Additional Cracking
611	5060	1	3	S31		Stairwell #4 outside Classroom 301	W1	Flaking	30	N	N	0	N	N	Additional Chipping
612	5060	1	3	S31		Stairwell #4 outside Classroom 301	W2	Flaking	6	N	N	0	N	N	Additional Chipping
613	5060	1	3	S31		Stairwell #4 outside Classroom 301	W3	Flaking	30	N	N	0	N	N	Additional Chipping
614	5060	1	3	S31		Stairwell #4 outside Classroom 301	W4	Flaking	4	N	N	0	N	N	Additional Chipping
615	5060	2	3	S33		Stairwell #7	Ceiling	Flaking	2	N	N	0	N	N	
616	5060	2	3	S33		Stairwell #7	W1	Cracking	4	N	N	0	N	N	
617	5060	2	3	S33		Stairwell #7	W3	Flaking	10	N	N	0	N	N	
618	5060	2	3	S33		Stairwell #7	W4	Flaking	8	N	N	0	N	N	Additional Chipping
619	5060	2	3	S34		Stairwell #8	Ceiling	Flaking	9	N	N	0	N	N	
620	5060	2	3	S34		Stairwell #8	W2	Flaking	2	N	N	0	N	N	
621	5060	1	3	S25		Stairwell #9	W3	Flaking	8	N	N	0	N	N	
622	5060	2	3	S35		Stairwell #9	W3	Flaking	8	N	N	0	N	N	
623	5060	2	3	321D		Storage Room inside Classroom 321	W2	Partially Inaccessible	0	N	N	0	Y - 90 SF Shelves, Contents	N	Limited Inspection

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
624	5060	2	3	321D		Storage Room inside Classroom 321	W3	Partially Inaccessible	0	N	N	0	Y - 48 SF Shelves, Contents	N	Limited Inspection
625	5060	2	3	321D		Storage Room inside Classroom 321	W4	Partially Inaccessible	0	N	N	0	Y - 80 SF Shelves, Contents	N	Limited Inspection
626	5060	2	3	320C		Welding Classroom 320 Metal Closet	Ceiling	Chipping	8	N	N	0	N	N	
627	5060	2	3	320C		Welding Classroom 320 Metal Closet	Floor	Chipping	14	N	N	0	N	N	
628	5060	2	3	321C		Welding Classroom Teacher's Office	W3	Flaking	4	N	N	0	N	N	
629	5060	2	3	320A		Welding Classroom within Metal Shop 320	W3	Flaking	4	N	N	0	N	N	
630	5060	2	3	320		Welding Shop 320	Floor	Chipping	400	N	N	0	N	N	
631	5060	2	3	320		Welding Shop 320	W3	Chipping	4	N	N	0	N	N	Flaking @ Window Lintel
632	5060	2	3	320		Welding Shop 320	W4	Flaking	20	N	N	0	N	N	
633	5060	1	2	210		Auditorium Balcony	Ceiling	Flaking	400	N	N	0	N	N	Additional Cracking, Chipping
634	5060	1	2	210		Auditorium Balcony	W1	Flaking	28	N	N	0	N	N	Additional Cracking, Chipping
635	5060	1	2	210		Auditorium Balcony	W2	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
636	5060	1	2	210		Auditorium Balcony	W4	Flaking	18	N	N	0	N	N	Additional Cracking, Chipping
637	5060	2	2	223		Book Storage area next to Room 224	W1	Partially Inaccessible	0	N	N	0	Y - 14 SF Shelves, Contents	N	Limited Inspection
638	5060	2	2	223		Book Storage area next to Room 224	W2	Partially Inaccessible	0	N	N	0	Y - 28 SF Shelves, Contents	N	Limited Inspection
639	5060	2	2	223		Book Storage area next to Room 224	W3	Partially Inaccessible	0	N	N	0	Y - 21 SF Shelves, Contents	N	Limited Inspection
640	5060	2	2	223		Book Storage area next to Room 224	W4	Partially Inaccessible	0	N	N	0	Y - 35 SF Shelves, Contents	N	Limited Inspection
641	5060	2	2	223A		Book Storage area next to Room 224 Storage Closet	W2	Cracking	6	N	N	0	Y - 24 SF Books	N	
642	5060	2	2	223A		Book Storage area next to Room 224 Storage Closet	W3	None	0	N	N	0	Y - 20 SF Books	N	
643	5060	2	2	223A		Book Storage area next to Room 224 Storage Closet	W4	Cracking	10	N	N	0	Y - 30 SF Books	N	
644	5060	2	2	219		Boys' Restroom	Ceiling	Cracking	12	N	N	0	N	N	
645	5060	1	2	201		Classroom 201	W1	Cracking	8	N	N	0	Y - 22 SF Posters, Contents	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
646	5060	1	2	201		Classroom 201	W2	Chipping	4	N	N	0	Y - 36 SF Desks, Posters	N	
647	5060	1	2	201		Classroom 201	W3	Flaking	16	N	N	0	Y - 26 SF Desks, Posters, Contents	N	
648	5060	1	2	201		Classroom 201	W4	Chipping	10	N	N	0	Y - 10 SF Posters	N	
649	5060	1	2	206		Classroom 206	W1	Flaking	20	N	N	0	N	N	
650	5060	1	2	206		Classroom 206	W2	Flaking	6	N	N	0	N	N	
651	5060	1	2	206		Classroom 206	W3	Flaking	40	N	N	0	N	N	
652	5060	1	2	206		Classroom 206	W4	Flaking	8	N	N	0	N	N	
653	5060	1	2	206A		Classroom 206 back lab space/teacher's area	W1	Partially Inaccessible	0	N	N	0	Y - 22 SF Contents	N	Limited Inspection
654	5060	1	2	206A		Classroom 206 back lab space/teacher's area	W2	Flaking	4	N	N	0	N	N	
655	5060	1	2	206A		Classroom 206 back lab space/teacher's area	W3	Partially Inaccessible	0	N	N	0	Y - 28 SF Contents	N	Limited Inspection
656	5060	1	2	206B		Classroom 206 Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
657	5060	1	2	206C		Classroom 206 Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
658	5060	1	2	206B		Classroom 206 Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
659	5060	1	2	206C		Classroom 206 Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
660	5060	1	2	206B		Classroom 206 Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
661	5060	1	2	206C		Classroom 206 Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
662	5060	1	2	206B		Classroom 206 Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
663	5060	1	2	206C		Classroom 206 Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
664	5060	1	2	206B		Classroom 206 Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
665	5060	1	2	206C		Classroom 206 Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
666	5060	1	2	206B		Classroom 206 Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
667	5060	1	2	206C		Classroom 206 Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
668	5060	1	2	207		Classroom 207	W1	Partially Inaccessible	0	N	Y - On Window Sills	2	Y - 24 SF Posters	N	Limited Inspection
669	5060	1	2	207		Classroom 207	W2	Efflorescence	6	Y	N	0	N	Y - 6 SF	
670	5060	1	2	207		Classroom 207	W4	Chipping	2	N	N	0	Y - 14 SF Cabinets	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
671	5060	1	2	207A		Classroom 207 Closet to the left	Ceiling	Flaking	48	N	N	0	N	N	
672	5060	1	2	207A		Classroom 207 Closet to the left	Floor	Debris	0	N	Y	3	N	N	
673	5060	1	2	207A		Classroom 207 Closet to the left	W1	Gouges	4	N	N	0	N	N	
674	5060	1	2	207A		Classroom 207 Closet to the left	W2	Gouges	2	N	N	0	N	N	
675	5060	1	2	207A		Classroom 207 Closet to the left	W3	Chipping	1	N	N	0	N	N	
676	5060	1	2	207A		Classroom 207 Closet to the left	W4	Flaking	3	N	N	0	N	N	
677	5060	1	2	207B		Classroom 207 Small Conference Room	Floor	Debris	0	N	Y	4	N	N	
678	5060	1	2	207B		Classroom 207 Small Conference Room	W1	Flaking	6	Y	N	0	N	Y - 2 SF	Additional Efflorescence
679	5060	1	2	207B		Classroom 207 Small Conference Room	W2	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents	N	Limited Inspection
680	5060	1	2	207B		Classroom 207 Small Conference Room	W3	Chipping	1	N	N	0	N	N	
681	5060	1	2	207B		Classroom 207 Small Conference Room	W4	Flaking	15	Y	N	0	N	Y - 15 SF	Additional Efflorescence
682	5060	2	2	221		Classroom 221	W1	Flaking	12	N	N	0	N	N	
683	5060	2	2	221		Classroom 221	W2	Flaking	25	N	N	0	N	N	
684	5060	2	2	221		Classroom 221	W3	Flaking	24	N	N	0	N	N	
685	5060	2	2	221		Classroom 221	W4	Partially Inaccessible	0	N	N	0	Y - 100 SF Contents	N	Limited Inspection
686	5060	2	2	225		Classroom 225	Ceiling	Efflorescence	40	Y	N	N	N	Y - 40 SF	
687	5060	2	2	225		Classroom 225	W3	Flaking	16	N	N	N	Y - 40 SF Contents	N	Additional Cracking
688	5060	2	2	225		Classroom 225	W4	Partially Inaccessible	0	N	N	N	Y - 80 SF Desks, Posters, Contents	N	Limited Inspection
689	5060	2	2	226		Classroom 226	Ceiling	Efflorescence	10	Y	N	0	N	Y - 10 SF	
690	5060	2	2	226		Classroom 226	W3	Flaking	9	N	N	0	Y - 20 SF Desks	N	
691	5060	2	2	226B/225B		Classroom 226 and 225 Lab Prep Chemical Storage	W2	Partially Inaccessible	0	N	N	0	Y - 10 SF Contents	N	Limited Inspection
692	5060	2	2	226B/225B		Classroom 226 and 225 Lab Prep Chemical Storage	W3	Flaking	4	N	N	0	N	N	
693	5060	1	2	210A		Closet in Hallway across from Classroom 207	W1	Flaking	1	N	N	0	N	N	
694	5060	1	2	210A		Closet in Hallway across from Classroom 207	W2	Flaking	4	N	N	0	Y - 10 SF Contents	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
695	5060	1	2	210A		Closet in Hallway across from Classroom 207	W3	Flaking	12	N	N	0	Y - 12 SF Contents	N	
696	5060	1	2	210A		Closet in Hallway across from Classroom 207	W4	Flaking	6	N	N	0	Y - 20 SF Contents	N	
697	5060	1	2	210B		Closet in Hallway across from Classroom 207 closer to Classroom 206	W1	Flaking	5	N	N	0	N	N	
698	5060	1	2	210B		Closet in Hallway across from Classroom 207 closer to Classroom 206	W2	Flaking	4	N	N	0	Y - 20 SF Contents	N	
699	5060	1	2	210B		Closet in Hallway across from Classroom 207 closer to Classroom 206	W3	Flaking	10	N	N	0	Y - 12 SF Contents	N	
700	5060	1	2	210B		Closet in Hallway across from Classroom 207 closer to Classroom 206	W4	Flaking	10	N	N	0	Y - 24 SF Contents	N	
701	5060	1	2	213A		Closet in Hallway across from Classroom 209	W1	Flaking	2	N	N	0	N	N	
702	5060	1	2	213A		Closet in Hallway across from Classroom 209	W2	Flaking	8	N	N	0	Y - 20 SF Contents	N	
703	5060	1	2	213A		Closet in Hallway across from Classroom 209	W3	Flaking	8	N	N	0	Y - 30 SF Contents	N	
704	5060	1	2	213A		Closet in Hallway across from Classroom 209	W4	Flaking	10	N	N	0	Y - 12 SF Contents	N	
705	5060	2	2	220		Electrical Class Room 220	Floor	Chipping	300	N	N	0	N	N	Chipping on Entire Floor
706	5060	2	2	220		Electrical Class Room 220	W1	Flaking	12	N	N	0	N	N	
707	5060	2	2	220		Electrical Class Room 220	W2	Flaking	38	N	N	0	N	N	
708	5060	2	2	220		Electrical Class Room 220	W3	Flaking	24	Y	N	0	N	Y - 24 SF	Additional Efflorescence; Damage @ Window Lintels
709	5060	2	2	220		Electrical Class Room 220	W4	Partially Inaccessible	0	N	N	0	Y - 200 SF Wood, Ladders, Desks, Contents	N	Limited Inspection
710	5060	2	2	220A		Electrical Class Room 220 far Storage area	W1	Partially Inaccessible	0	N	N	0	Y - 60 SF Contents	N	Limited Inspection

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
711	5060	2	2	220A		Electrical Class Room 220 far Storage area	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Contents	N	Limited Inspection
712	5060	2	2	220A		Electrical Class Room 220 far Storage area	W3	Partially Inaccessible	0	N	N	0	Y - 80 SF Contents	N	Limited Inspection
713	5060	2	2	220A		Electrical Class Room 220 far Storage area	W4	Flaking	24	Y	N	0	Y - 28 SF Contents	Y - 16 SF	Additional Efflorescence
714	5060	2	2	221A/220C		Electrical Class Room 220 middle Storage area	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
715	5060	2	2	221A/220C		Electrical Class Room 220 middle Storage area	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
716	5060	2	2	221A/220C		Electrical Class Room 220 middle Storage area	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Padlock
717	5060	2	2	221A/220C		Electrical Class Room 220 middle Storage area	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
718	5060	2	2	221A/220C		Electrical Class Room 220 middle Storage area	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
719	5060	2	2	221A/220C		Electrical Class Room 220 middle Storage area	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
720	5060	2	2	220E/220B		Electrical Class Room 220 Storage Closet nearest to the Entrance	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
721	5060	2	2	220E/220B		Electrical Class Room 220 Storage Closet nearest to the Entrance	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
722	5060	2	2	220E/220B		Electrical Class Room 220 Storage Closet nearest to the Entrance	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Padlock
723	5060	2	2	220E/220B		Electrical Class Room 220 Storage Closet nearest to the Entrance	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
724	5060	2	2	220E/220B		Electrical Class Room 220 Storage Closet nearest to the Entrance	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
725	5060	2	2	220E/220B		Electrical Class Room 220 Storage Closet nearest to the Entrance	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
726	5060	2	2	217		Girls' Restroom	Ceiling	Cracking	8	N	N	0	N	N	
727	5060	1	2	H15		Hallway between Element 1 and Element 2	W3	Holes	4	N	N	0	N	Y - 2 SF	Additional Gouges; Damage Includes Column
728	5060	1	2	H17		Hallway in front of Classrooms 207-208	W4	Flaking	8	N	N	0	N	Y - 4 SF	Additional Gouges
729	5060	2	2	H21		Hallway in front of Classrooms 226 and 225	W1	Flaking	2	N	N	0	N	N	
730	5060	2	2	H21		Hallway in front of Classrooms 226 and 225	W2	Flaking	14	N	N	0	N	N	Additional Cracking; Damage Above Lockers
731	5060	1	2	H22B		Hallway in front of Main Office Room 205	W1	Flaking	6	N	N	0	N	N	
732	5060	1	2	H22		Hallway in front of Second Floor Auditorium Entrance	Ceiling	Flaking	8	N	N	0	N	N	Additional Cracking; Damage in Various Locations
733	5060	1	2	H22A		Hallway outside of Classroom 206	W1	Chipping	4	N	N	0	N	N	Chipping on Pipe
734	5060	1	2	H217		Hallway outside of Classrooms 207 - 209	Ceiling	Debris	0	N	N	0	N	Y - 4 SF	
735	5060	1	2	H217		Hallway outside of Classrooms 207 - 209	W4	Flaking	8	N	N	0	N	N	
736	5060	1	2	204A		Hallway Storage Closet across from Conference Room 204	Ceiling	Flaking	40	N	N	0	N	N	Additional Chipping, Holes
737	5060	1	2	204A		Hallway Storage Closet across from Conference Room 204	W3	Flaking	12	N	N	0	Y - 16 SF Contents	N	
738	5060	1	2	204A		Hallway Storage Closet across from Conference Room 204	W4	Chipping	60	N	N	0	Y - 14 SF Contents	N	
739	5060	1	2	H35B		Hallway/Stairs to Gymnasium across from Stairwell # 3	Ceiling	Flaking	30	N	N	0	N	N	
740	5060	1	2	H35B		Hallway/Stairs to Gymnasium across from Stairwell # 3	Floor	Debris	0	N	Y - @ Perimeter	4	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
741	5060	1	2	H35A		Hallway/Stairs to Gymnasium across from Stairwell # 4	Ceiling	Flaking	20	N	N	0	N	N	
742	5060	1	2	H35A		Hallway/Stairs to Gymnasium across from Stairwell # 4	Floor	Debris	0	N	Y - @ Perimeter	4	N	N	
743	5060	1	2	212A		IT MDF Room across from Stairwell # 4	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
744	5060	1	2	212A		IT MDF Room across from Stairwell # 4	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
745	5060	1	2	212A		IT MDF Room across from Stairwell # 4	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
746	5060	1	2	212A		IT MDF Room across from Stairwell # 4	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
747	5060	1	2	212A		IT MDF Room across from Stairwell # 4	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
748	5060	1	2	212A		IT MDF Room across from Stairwell # 4	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
749	5060	1	2	205		Main Office 205	W2	Gouges	2	N	N	0	Y - 40 SF Contents	N	
750	5060	1	2	205		Main Office 205	W3	Flaking	12	N	N	0	Y - 60 SF Desks, Cabinets, Copier	N	
751	5060	1	2	205B		Main Office Mail Room	W1	Partially Inaccessible	0	N	N	0	Y - 60 SF Cabinets, Contents	N	Limited Inspection
752	5060	1	2	205B		Main Office Mail Room	W4	Partially Inaccessible	0	N	N	0	Y - 28 SF Cabinets, Contents	N	Limited Inspection
753	5060	1	2	205F		Main Office Restroom	Ceiling	Flaking	3	N	N	0	N	N	
754	5060	1	2	205F		Main Office Restroom	W1	Flaking	2	N	N	0	N	N	
755	5060	1	2	205F		Main Office Restroom	W2	Holes	2	N	N	0	N	N	
756	5060	1	2	205F		Main Office Restroom	W3	Flaking	3	N	N	0	N	N	
757	5060	2	2	226		Men's Faculty Restroom	W2	Holes	1	N	N	0	N	N	
758	5060	2	2	218		Men's Restroom	Ceiling	Cracking	6	N	N	0	N	N	
759	5060	1	2	208		Nurse's Office	Floor	Flaking	32	N	N	0	N	N	Additional Chipping; Damage @ Perimeter on Baseboards



Mastbaum -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
760	5060	1	2	208		Nurse's Office	W1	Flaking	16	N	N	0	N	N	Additional Chipping; Damage on Wall & Door Frame
761	5060	1	2	208		Nurse's Office	W2	Flaking	22	Y	N	0	N	Y - 6 SF	Additional Efflorescence
762	5060	1	2	208		Nurse's Office	W3	Flaking	14	Y	N	0	N	Y - 3 SF	Additional Efflorescence
763	5060	1	2	208		Nurse's Office	W4	Cracking	12	N	N	0	N	N	
764	5060	1	2	208C		Nurse's Office Restroom	Ceiling	Flaking	12	Y	N	0	N	Y - 12 SF	Additional Efflorescence
765	5060	1	2	208C		Nurse's Office Restroom	W1	Flaking	2	N	N	0	N	N	
766	5060	1	2	208C		Nurse's Office Restroom	W3	Flaking	2	N	N	0	N	N	
767	5060	1	2	208C		Nurse's Office Restroom	W4	Flaking	28	Y	N	0	N	Y - 3 SF	Additional Efflorescence
768	5060	1	2	203A		Office 203A next to the Testing Room in the 203 Office Suites	W2	Efflorescence	4	Y	N	0	N	Y - 4 SF	
769	5060	1	2	203A		Office 203A next to the Testing Room in the 203 Office Suites	W3	Flaking	8	Y	N	0	N	Y - 4 SF	Additional Efflorescence; Damage on Wall & Radiator
770	5060	1	2	203C		Office 203C three doors to the left of the Testing Room in the 203 Office Suites	W3	Flaking	16	N	N	0	N	N	
771	5060	1	2	203E		Office 203E four doors to the left of the Testing Room in the 203 Office Suites	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
772	5060	1	2	203E		Office 203E four doors to the left of the Testing Room in the 203 Office Suites	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
773	5060	1	2	203E		Office 203E four doors to the left of the Testing Room in the 203 Office Suites	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
774	5060	1	2	203E		Office 203E four doors to the left of the Testing Room in the 203 Office Suites	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
775	5060	1	2	203E		Office 203E four doors to the left of the Testing Room in the 203 Office Suites	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
776	5060	1	2	203E		Office 203E four doors to the left of the Testing Room in the 203 Office Suites	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
777	5060	1	2	202A		Office within Room 202 to the left	Floor	Partially Inaccessible	0	N	Y - 28 SF Posters, Contents	0	N	N	Limited Inspection
778	5060	1	2	202A		Office within Room 202 to the left	W3	Flaking	3	Y	N	0	N	Y - 1 SF	Additional Efflorescence
779	5060	1	2	202A		Office within Room 202 to the left	W4	Partially Inaccessible	0	N	N	0	Y - 32 SF Desk, Posters, Contents	N	Limited Inspection
780	5060	1	2	202B		Office within Room 202 to the right	W4	Flaking	24	N	N	0	N	N	Additional Cracking
781	5060	1	2	205A		Principal's Office	W1	Partially Inaccessible	0	N	N	0	Y - 20 SF Posters, Contents	N	Limited Inspection
782	5060	1	2	205A		Principal's Office	W2	Partially Inaccessible	0	N	N	0	Y - 30 SF Contents	N	Limited Inspection
783	5060	1	2	205A		Principal's Office	W3	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks, Contents	N	Limited Inspection
784	5060	1	2	205A		Principal's Office	W4	Partially Inaccessible	0	N	N	0	Y - 18 SF Posters, Contents	N	Limited Inspection
785	5060	1	2	205E		Principal's Office Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
786	5060	1	2	205E		Principal's Office Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
787	5060	1	2	205E		Principal's Office Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
788	5060	1	2	205E		Principal's Office Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
789	5060	1	2	205E		Principal's Office Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
790	5060	1	2	205E		Principal's Office Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
791	5060	1	2	203D		Room 203 entrance to the 203 Suite of Offices	W1	Flaking	8	N	N	0	N	N	Additional Chipping
792	5060	1	2	208A		Room 208 Nurse's Administrative Area	W1	Partially Inaccessible	0	N	N	0	N	N	Limited Inspection
793	5060	1	2	208A		Room 208 Nurse's Administrative Area	W2	Partially Inaccessible	0	N	N	0	N	N	Limited Inspection
794	5060	1	2	208A		Room 208 Nurse's Administrative Area	W3	Partially Inaccessible	0	N	N	0	N	N	Limited Inspection
795	5060	1	2	208A		Room 208 Nurse's Administrative Area	W4	Flaking	6	Y	N	0	N	Y - 6 SF	Additional Efflorescence

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
796	5060	1	2	208B		Room 208 Nurse's Administrative Area Restroom	Ceiling	Flaking	4	N	N	0	N	N	
797	5060	1	2	208B		Room 208 Nurse's Administrative Area Restroom	W1	Flaking	8	N	N	0	N	N	
798	5060	1	2	208B		Room 208 Nurse's Administrative Area Restroom	W2	Flaking	12	N	N	0	N	N	
799	5060	1	2	208B		Room 208 Nurse's Administrative Area Restroom	W3	Flaking	12	N	N	0	N	N	
800	5060	1	2	208B		Room 208 Nurse's Administrative Area Restroom	W4	Flaking	10	N	N	0	N	N	
801	5060	2	2	222		Room 222 next to Men's Restroom	W1	Partially Inaccessible	0	N	N	0	Y - 15 SF Contents	N	Limited Inspection
802	5060	2	2	222		Room 222 next to Men's Restroom	W2	Debris	0	N	N	0	Y - 20 SF Contents	N	
803	5060	2	2	222		Room 222 next to Men's Restroom	W3	Flaking	4	N	N	0	N	N	
804	5060	2	2	222		Room 222 next to Men's Restroom	W4	Chipping	2	N	N	0	N	N	
805	5060	2	2	224		Room 224 used for storage and the School's Camera System	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
806	5060	2	2	224		Room 224 used for storage and the School's Camera System	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
807	5060	2	2	224		Room 224 used for storage and the School's Camera System	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
808	5060	2	2	224		Room 224 used for storage and the School's Camera System	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
809	5060	2	2	224		Room 224 used for storage and the School's Camera System	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
810	5060	2	2	224		Room 224 used for storage and the School's Camera System	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
811	5060	1	2	212		School Operation's Office 212 across from Stairwell # 4	Ceiling	Cracking	10	N	N	0	N	N	
812	5060	1	2	212		School Operation's Office 212 across from Stairwell # 4	W2	Flaking	2	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
813	5060	2	2	224C		School Police Office next to Room 224	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
814	5060	2	2	224C		School Police Office next to Room 224	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
815	5060	2	2	224C		School Police Office next to Room 224	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
816	5060	2	2	224C		School Police Office next to Room 224	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
817	5060	2	2	224C		School Police Office next to Room 224	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
818	5060	2	2	224C		School Police Office next to Room 224	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
819	5060	1	2	S21		Stairwell # 4 next to Classroom 201	Ceiling	Flaking	50	N	N	0	N	N	Additional Chipping
820	5060	1	2	S21		Stairwell # 4 next to Classroom 201	W1	Flaking	10	N	N	0	N	N	Additional Chipping
821	5060	1	2	S21		Stairwell # 4 next to Classroom 201	W2	Flaking	50	N	N	0	N	N	Additional Chipping
822	5060	1	2	S21		Stairwell # 4 next to Classroom 201	W3	Flaking	8	N	N	0	N	N	Additional Chipping
823	5060	1	2	S21		Stairwell # 4 next to Classroom 201	W4	Flaking	40	N	N	0	N	N	Additional Chipping
824	5060	1	2	S23		Stairwell #2 outside Classroom 206	Ceiling	Flaking	72	N	N	0	N	N	Additional Chipping
825	5060	1	2	S23		Stairwell #2 outside Classroom 206	W1	Flaking	12	N	N	0	N	N	Additional Chipping
826	5060	1	2	S23		Stairwell #2 outside Classroom 206	W2	Flaking	80	N	N	0	N	N	Additional Chipping
827	5060	1	2	S23		Stairwell #2 outside Classroom 206	W3	Flaking	20	N	N	0	N	N	Additional Chipping
828	5060	1	2	S23		Stairwell #2 outside Classroom 206	W4	Flaking	60	N	N	0	N	N	Additional Chipping
829	5060	1	2	S24		Stairwell #3 next to Nurse's Office	Ceiling	Flaking	12	Y	N	0	N	Y - 12 SF	Additional Efflorescence
830	5060	1	2	S24		Stairwell #3 next to Nurse's Office	W1	Chipping	2	N	N	0	N	N	Chipping on Pipe
831	5060	1	2	S24		Stairwell #3 next to Nurse's Office	W3	Holes	1	N	N	0	N	Y - 1 SF	
832	5060	1	2	S24		Stairwell #3 next to Nurse's Office	W4	Flaking	60	Y	N	0	N	Y - 16 SF	Additional Efflorescence
833	5060	2	2	S23		Stairwell #7	Ceiling	Flaking	30	N	N	0	N	N	Additional Chipping
834	5060	2	2	S23		Stairwell #7	W1	Flaking	48	N	N	0	N	N	Additional Cracking, Chipping

Mastbaum -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
835	5060	2	2	S23		Stairwell #7	W2	Flaking	4	N	N	0	N	N	
836	5060	2	2	S23		Stairwell #7	W3	Flaking	16	N	N	0	N	N	
837	5060	2	2	S23		Stairwell #7	W4	Flaking	36	N	N	0	N	N	
838	5060	2	2	S24		Stairwell #8	Ceiling	Chipping	18	N	N	0	N	N	
839	5060	2	2	S24		Stairwell #8	W1	Flaking	8	N	N	0	N	N	
840	5060	2	2	S24		Stairwell #8	W2	Flaking	14	N	N	0	N	N	
841	5060	2	2	S24		Stairwell #8	W3	Flaking	36	N	N	0	N	N	Additional Chipping
842	5060	2	2	S24		Stairwell #8	W4	Flaking	2	N	N	0	N	N	
843	5060	2	2	S25		Stairwell #9	W3	Flaking	8	N	N	0	N	N	
844	5060	1	2	S22		Stairwell next to Conference Room 204	W1	Flaking	9	N	N	0	N	N	Flaking on Pipe
845	5060	1	2	S22		Stairwell next to Conference Room 204	W2	Flaking	5	N	N	0	N	N	Additional Chipping
846	5060	1	2	203		Testing Room 203	W1	Flaking	8	N	N	0	Y - 40 SF Posters	N	
847	5060	1	2	203		Testing Room 203	W2	Partially Inaccessible	0	N	N	0	Y - 28 SF File Cabinets	N	Limited Inspection
848	5060	1	2	203		Testing Room 203	W3	Partially Inaccessible	0	N	N	0	Y - 60 SF Cabinets, Contents	N	Limited Inspection
849	5060	1	2	203		Testing Room 203	W4	Cracking	1	N	N	0	N	N	
850	5060	1	2	213		Women's Restroom across from Classroom 209	Ceiling	Cracking	9	N	N	0	N	N	
851	5060	1	2	213		Women's Restroom across from Classroom 209	W2	Cracking	3	N	N	0	N	N	
852	5060	1	2	213		Women's Restroom across from Classroom 209	W4	Cracking	5	N	N	0	N	N	
853	5060	1	1	106		Auditorium	Ceiling	Flaking	3,600	N	N	0	N	N	
854	5060	1	1	106		Auditorium	W1	Chipping	4	N	Y - @ Corner of Wall 1 & Wall 2	1	N	N	
855	5060	1	1	106		Auditorium	W2	Flaking	120	N	N	0	N	N	Additional Cracking, Chipping; Damage on Wall, Door, Window Sills
856	5060	1	1	106		Auditorium	W3	Flaking	210	N	N	0	N	N	
857	5060	1	1	106		Auditorium	W4	Flaking	200	N	N	0	N	N	Additional Chipping; Damage on Wall & Window Sills
858	5060	2	1	124		Auto Shop Garage on the West Classroom 124	Ceiling	Flaking	200	N	N	0	N	N	
859	5060	2	1	124		Auto Shop Garage on the West Classroom 124	W1	Flaking	700	N	N	0	N	N	
860	5060	2	1	124		Auto Shop Garage on the West Classroom 124	W2	Flaking	400	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
861	5060	2	1	124		Auto Shop Garage on the West Classroom 124	W3	Flaking	750	N	N	0	N	N	
862	5060	2	1	124		Auto Shop Garage on the West Classroom 124	W4	Flaking	200	N	N	0	N	N	
863	5060	2	1	124B		Auto Shop Mechanics Station Counter	Ceiling	Flaking	30	N	N	0	N	N	
864	5060	2	1	124B		Auto Shop Mechanics Station Counter	W1	Flaking	20	N	N	0	N	N	
865	5060	2	1	124B		Auto Shop Mechanics Station Counter	W2	Flaking	20	N	N	0	N	N	
866	5060	2	1	124B		Auto Shop Mechanics Station Counter	W3	Flaking	10	N	N	0	N	N	
867	5060	2	1	124B		Auto Shop Mechanics Station Counter	W4	Flaking	8	N	N	0	N	N	
868	5060	1	1	101T		Boys' Restroom next to Main Entrance	W3	Flaking	6	N	N	0	N	N	Flaking @ Window Frame
869	5060	2	1	116		Boys' Restroom outside of the Gym Entrance	Ceiling	Flaking	4	N	N	0	N	N	
870	5060	2	1	116		Boys' Restroom outside of the Gym Entrance	W1	Flaking	5	N	N	0	N	N	
871	5060	2	1	116		Boys' Restroom outside of the Gym Entrance	W2	Flaking	5	N	N	0	N	N	
872	5060	2	1	116		Boys' Restroom outside of the Gym Entrance	W3	Flaking	3	N	N	0	N	N	
873	5060	2	1	116		Boys' Restroom outside of the Gym Entrance	W4	Flaking	2	N	N	0	N	N	
874	5060	1	1	102		Classroom 101	W1	Partially Inaccessible	0	N	N	0	Y - 42 SF Desks, Posters	N	Limited Inspection
875	5060	1	1	102		Classroom 101	W2	Chipping	20	N	N	0	Y - 24 SF Posters	N	
876	5060	1	1	102		Classroom 101	W3	Flaking	12	Y	N	0	N	Y - 2 SF	Additional Efflorescence
877	5060	1	1	102A		Classroom 102	W1	Partially Inaccessible	0	N	N	0	Y - 42 SF Desks, Posters	N	Limited Inspection
878	5060	1	1	102A		Classroom 102	W2	Chipping	20	N	N	0	Y - 24 SF Posters	N	
879	5060	1	1	102A		Classroom 102	W3	Flaking	12	Y	N	0	N	Y - 2 SF	Additional Efflorescence
880	5060	1	1	103		Classroom 103	Floor	Chipping	40	N	N	0	N	N	Chipping @ Perimeter

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
881	5060	1	1	103		Classroom 103	W1	Flaking	3	N	N	0	Y - 40 SF Desks, Contents	N	Additional Chipping
882	5060	1	1	103		Classroom 103	W2	Flaking	16	N	N	0	Y - 40 SF Desks, Contents	N	Additional Chipping
883	5060	1	1	103		Classroom 103	W3	Flaking	32	N	N	0	N	N	Additional Cracking, Chipping
884	5060	1	1	103		Classroom 103	W4	Flaking	22	Y	N	0	N	Y - 8 SF	Additional Efflorescence, Chipping
885	5060	1	1	104		Classroom 104	Floor	Debris	0	N	Y - @ Wall 3	6	N	N	
886	5060	1	1	104		Classroom 104	W1	Chipping	14	N	N	0	Y - 30 SF Posters	N	
887	5060	1	1	104		Classroom 104	W2	Flaking	6	Y	N	0	N	Y - 6 SF	Additional Efflorescence
888	5060	1	1	104		Classroom 104	W3	Flaking	64	Y	Y - On Window Sills	6	Y - 60 SF Cabinets, Contents	Y - 64 SF	Additional Efflorescence
889	5060	1	1	104		Classroom 104	W4	Chipping	20	N	N	0	Y - 20 SF Posters	N	
890	5060	1	1	104B		Classroom 104 Closet	Ceiling	Chipping	6	N	N	0	N	Y - 2 SF	Additional Holes
891	5060	1	1	104B		Classroom 104 Closet	W1	Flaking	4	N	N	0	Y - 60 SF File Cabinets, Contents	Y - 2 SF	Additional Cracking, Holes
892	5060	1	1	104B		Classroom 104 Closet	W2	Cracking	6	N	N	0	Y - 40 SF Boxes, Contents	N	Additional Chipping
893	5060	1	1	104B		Classroom 104 Closet	W3	Flaking	80	N	N	0	Y - 150 SF Books, Boxes, Contents	N	Additional Cracking, Chipping
894	5060	1	1	104B		Classroom 104 Closet	W4	Flaking	32	N	N	0	Y - 32 SF Books, Tables, Contents	N	Additional Cracking
895	5060	1	1	101B		Girls' Restroom next to Main Entrance	W3	Flaking	8	N	N	0	N	N	
896	5060	2	1	117		Girls' Restroom outside of the Gym Entrance	Ceiling	Flaking	6	N	N	0	N	N	
897	5060	2	1	117		Girls' Restroom outside of the Gym Entrance	W1	Flaking	4	N	N	0	N	N	
898	5060	2	1	117		Girls' Restroom outside of the Gym Entrance	W2	Flaking	8	N	N	0	N	N	
899	5060	2	1	117		Girls' Restroom outside of the Gym Entrance	W3	Flaking	2	N	N	0	N	N	
900	5060	2	1	117		Girls' Restroom outside of the Gym Entrance	W4	Flaking	2	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
901	5060	2	1	122A		Gym Office to the East	W1	Chipping	2	N	Y - 18 SF Contents	0	N	N	Chipping @ Door
902	5060	2	1	122A		Gym Office to the East	W2	Partially Inaccessible	0	N	Y - 22 SF Shelves, Contents	0	N	N	Limited Inspection
903	5060	2	1	122A		Gym Office to the East	W3	Partially Inaccessible	0	N	Y - 40 SF Shelves, Contents	0	N	N	Limited Inspection
904	5060	2	1	122A		Gym Office to the East	W4	Partially Inaccessible	0	N	Y - 28 SF Shelves, Contents	0	N	N	Limited Inspection
905	5060	2	1	123		Gym Office to the West	W1	Chipping	6	N	N	0	Y - 20 SF Contents	N	
906	5060	2	1	123		Gym Office to the West	W2	Flaking	6	N	N	0	Y - 20 SF Contents	N	
907	5060	2	1	123		Gym Office to the West	W3	Chipping	10	N	N	0	N	N	
908	5060	2	1	123		Gym Office to the West	W4	Flaking	5	N	N	0	N	N	
909	5060	2	1	122		Gymnasium	Ceiling	Flaking	300	N	N	0	N	N	Flaking on Ductwork
910	5060	2	1	122		Gymnasium	Floor	Flaking	100	N	Y - @ Perimeter	40	N	N	Additional Chipping; Damage @ Perimeter
911	5060	2	1	122		Gymnasium	W1	Flaking	16	N	N	0	N	N	Additional Cracking, Chipping
912	5060	2	1	122		Gymnasium	W2	Flaking	400	N	N	0	N	N	Additional Chipping
913	5060	2	1	122		Gymnasium	W3	Flaking	80	N	N	0	N	N	Additional Chipping
914	5060	2	1	122		Gymnasium	W4	Flaking	250	N	N	0	N	N	Additional Chipping
915	5060	2	1	H11		Hallway at the Garage Classrooms 124 and 121	W1	Flaking	7	N	N	0	N	N	Additional Chipping
916	5060	2	1	H11		Hallway at the Garage Classrooms 124 and 121	W2	Chipping	20	N	N	0	N	N	
917	5060	1	1	H14		Hallway behind the Auditorium	Floor	Flaking	7	N	N	0	N	N	Additional Chipping
918	5060	1	1	H14		Hallway behind the Auditorium	Floor	Flaking	7	N	N	0	N	N	Additional Chipping
919	5060	1	1	H14		Hallway behind the Auditorium	W1	Flaking	6	N	N	0	N	N	Additional Chipping
920	5060	1	1	H14		Hallway behind the Auditorium	W1	Flaking	16	N	N	0	N	N	Additional Chipping
921	5060	1	1	H14		Hallway behind the Auditorium	W3	Flaking	10	N	N	0	N	N	Additional Chipping
922	5060	1	1	H14		Hallway behind the Auditorium	W3	Flaking	10	N	N	0	N	N	Additional Chipping
923	5060	1	1	H14		Hallway behind the Auditorium	W4	Cracking	12	N	N	0	N	N	2 Locations; Additional Holes
924	5060	1	1	H14		Hallway behind the Auditorium	W4	Cracking	12	N	N	0	N	N	2 Locations; Additional Holes



Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
925	5060	1	1	135B		Hallway Custodial Closet across from Storage Room next to Stairwell # 4	Ceiling	Flaking	16	N	N	0	N	N	
926	5060	1	1	135B		Hallway Custodial Closet across from Storage Room next to Stairwell # 4	W1	Flaking	4	N	N	0	N	N	
927	5060	1	1	135B		Hallway Custodial Closet across from Storage Room next to Stairwell # 4	W2	Flaking	20	N	N	0	N	N	
928	5060	1	1	135B		Hallway Custodial Closet across from Storage Room next to Stairwell # 4	W3	Flaking	18	N	N	0	N	N	
929	5060	1	1	135B		Hallway Custodial Closet across from Storage Room next to Stairwell # 4	W4	Flaking	22	N	N	0	N	N	
930	5060	1	1	H12		Hallway in front of Auditorium Entrance	Ceiling	Flaking	126	N	N	0	N	N	Additional Cracking, Chipping
931	5060	1	1	H12		Hallway in front of Auditorium Entrance	W2	Flaking	12	N	N	0	N	N	
932	5060	1	1	H12		Hallway in front of Auditorium Entrance	W3	Flaking	18	N	N	0	N	N	
933	5060	1	1	H12A		Hallway in front of Classroom 104	Floor	Debris	0	N	Y - Beneath Efflorescence	3	N	N	
934	5060	1	1	H12A		Hallway in front of Classroom 104	W1	Flaking	18	Y	Y	3	N	Y - 3 SF	Additional Efflorescence
935	5060	1	1	H13		Hallway in front of Classroom 104 A and 104C	W2	Flaking	2	N	N	0	N	N	Additional Cracking
936	5060	1	1	H13		Hallway in front of Classroom 104 A and 104C	W3	Cracking	4	N	N	0	N	Y - 4 SF	
937	5060	1	1	H11		Hallway in front of Classrooms 101 and 102	W1	Chipping	4	N	N	0	N	N	
938	5060	1	1	H11		Hallway in front of Classrooms 101 and 102	W2	Chipping	12	N	N	0	N	N	
939	5060	1	1	H11		Hallway in front of Classrooms 101 and 102	W4	Holes	2	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
940	5060	2	1	H12		Hallway in front of the Gym running East to West	W1	Chipping	20	N	N	0	N	N	
941	5060	2	1	H16		Hallway next to Office 123 leading Outside	W4	Chipping	12	N	N	0	N	N	
942	5060	1	1	135A		Hallway Storage Closet across from Equipment Storage Room 105	W1	Flaking	2	N	N	0	N	N	
943	5060	1	1	135A		Hallway Storage Closet across from Equipment Storage Room 105	W2	Flaking	8	N	N	0	N	N	
944	5060	1	1	135A		Hallway Storage Closet across from Equipment Storage Room 105	W3	Partially Inaccessible	0	N	N	0	N	N	Limited Inspection
945	5060	1	1	135A		Hallway Storage Closet across from Equipment Storage Room 105	W4	Partially Inaccessible	0	N	N	0	N	N	Limited Inspection
946	5060	1	1	H12		Hallway to the Northwest of Classroom 101	W1	Chipping	20	N	N	0	N	N	
947	5060	1	1	100H		Main Entrance Hallway	Ceiling	Flaking	60	Y	N	0	N	Y - 20 SF	Additional Efflorescence
948	5060	1	1	100H		Main Entrance Hallway	W1	Chipping	4	N	N	0	N	N	Chipping @ Doors
949	5060	1	1	100H		Main Entrance Hallway	W2	Flaking	4	N	N	0	N	N	
950	5060	2	1	121B		Male Faculty Restroom outside of the Gym	Ceiling	Cracking	10	N	N	0	N	N	
951	5060	1	1	104B		Office 104B	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
952	5060	1	1	104B		Office 104B	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
953	5060	1	1	104B		Office 104B	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
954	5060	1	1	104B		Office 104B	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
955	5060	1	1	104B		Office 104B	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
956	5060	1	1	104B		Office 104B	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
957	5060	1	1	104A		School Police Office across from Classroom 104	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
958	5060	1	1	104A		School Police Office across from Classroom 104	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
959	5060	1	1	104A		School Police Office across from Classroom 104	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
960	5060	1	1	104A		School Police Office across from Classroom 104	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
961	5060	1	1	104A		School Police Office across from Classroom 104	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
962	5060	1	1	104A		School Police Office across from Classroom 104	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
963	5060	1	1	106D		Side Room from Stage across Stairwell #4	Ceiling	Flaking	200	N	N	0	N	N	
964	5060	1	1	106D		Side Room from Stage across Stairwell #4	W1	Flaking	26	N	N	0	N	N	
965	5060	1	1	106D		Side Room from Stage across Stairwell #4	W2	Flaking	28	N	N	0	N	N	
966	5060	1	1	106D		Side Room from Stage across Stairwell #4	W3	Flaking	32	N	N	0	N	N	
967	5060	1	1	106D		Side Room from Stage across Stairwell #4	W4	Flaking	48	N	N	0	N	N	
968	5060	1	1	106F		Small Hallway leading to the Stage across from 105A	Ceiling	Flaking	48	N	N	0	N	N	
969	5060	1	1	106F		Small Hallway leading to the Stage across from 105A	W1	Flaking	14	N	N	0	N	N	
970	5060	1	1	106F		Small Hallway leading to the Stage across from 105A	W2	Flaking	40	N	N	0	N	N	
971	5060	1	1	106F		Small Hallway leading to the Stage across from 105A	W3	Flaking	20	N	N	0	N	N	
972	5060	1	1	106F		Small Hallway leading to the Stage across from 105A	W4	Flaking	24	N	N	0	N	N	
973	5060	1	1	106C		Stage	Ceiling	Flaking	120	N	N	0	N	N	
974	5060	1	1	106C		Stage	W2	Flaking	80	Y	N	0	N	Y - 2 SF	Additional Efflorescence
975	5060	1	1	106C		Stage	W3	Flaking	64	N	N	0	N	N	Flaking Includes Columns
976	5060	1	1	106C		Stage	W4	Flaking	90	N	N	0	N	Y - 4 SF	Additional Cracking
977	5060	2	1	S19		Stairs in the Gym leading to the Locker Room from the Northeast	Ceiling	Cracking	12	N	N	0	N	N	
978	5060	2	1	S19		Stairs in the Gym leading to the Locker Room from the Northeast	W1	Chipping	5	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
979	5060	2	1	S19		Stairs in the Gym leading to the Locker Room from the Northeast	W2	Chipping	2	N	N	0	N	N	
980	5060	2	1	S19		Stairs in the Gym leading to the Locker Room from the Northeast	W3	Chipping	9	N	N	0	N	N	
981	5060	2	1	S19		Stairs in the Gym leading to the Locker Room from the Northeast	W4	Chipping	5	N	N	0	N	N	
982	5060	2	1	S18		Stairs in the Gym leading to the Locker Room from the Northwest	Ceiling	Flaking	18	N	N	0	N	N	
983	5060	2	1	S18		Stairs in the Gym leading to the Locker Room from the Northwest	W1	Flaking	12	N	N	0	N	N	
984	5060	2	1	S18		Stairs in the Gym leading to the Locker Room from the Northwest	W2	Flaking	8	N	N	0	N	N	
985	5060	2	1	S18		Stairs in the Gym leading to the Locker Room from the Northwest	W3	Flaking	14	N	N	0	N	N	
986	5060	2	1	S18		Stairs in the Gym leading to the Locker Room from the Northwest	W4	Flaking	10	N	N	0	N	N	
987	5060	2	1	S11		Stairs leading from the Gym to the Locker Room to the Southeast	Ceiling	Flaking	20	N	N	0	N	N	
988	5060	2	1	S11		Stairs leading from the Gym to the Locker Room to the Southeast	W1	Flaking	80	N	N	0	N	N	
989	5060	2	1	S11		Stairs leading from the Gym to the Locker Room to the Southeast	W3	Flaking	28	N	N	0	N	N	
990	5060	2	1	S11		Stairs leading from the Gym to the Locker Room to the Southeast	W4	Flaking	40	N	N	0	N	N	
991	5060	2	1	S12A		Stairs leading from the Gym to the Locker Room to the Southwest	Ceiling	Flaking	20	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
992	5060	2	1	S12A		Stairs leading from the Gym to the Locker Room to the Southwest	W1	Flaking	10	N	N	0	N	N	
993	5060	2	1	S12A		Stairs leading from the Gym to the Locker Room to the Southwest	W2	Flaking	10	N	N	0	N	N	
994	5060	2	1	S12A		Stairs leading from the Gym to the Locker Room to the Southwest	W3	Flaking	18	N	N	0	N	N	
995	5060	2	1	S12A		Stairs leading from the Gym to the Locker Room to the Southwest	W4	Flaking	8	N	N	0	N	N	
996	5060	2	1	S15A		Stairs leading up into the Gym from the Main Hall	Ceiling	Flaking	10	N	N	0	N	N	
997	5060	1	1	S11		Stairwell # 4 next to Classroom 101	Ceiling	Flaking	8	Y	N	0	N	Y - 8 SF	Additional Efflorescence
998	5060	1	1	S11		Stairwell # 4 next to Classroom 101	Floor	Debris	0	N	Y - Beneath Efflorescence	2	N	N	
999	5060	1	1	S11		Stairwell # 4 next to Classroom 101	W1	Flaking	12	N	N	0	N	N	Additional Chipping
1000	5060	1	1	S11		Stairwell # 4 next to Classroom 101	W2	Cracking	4	N	N	0	N	N	
1001	5060	1	1	S11		Stairwell # 4 next to Classroom 101	W3	Flaking	36	N	N	0	N	N	
1002	5060	1	1	S11		Stairwell # 4 next to Classroom 101	W4	Flaking	4	N	N	0	N	N	Additional Holes
1003	5060	2	1	S14		Stairwell # 8	W1	Flaking	40	N	N	0	N	N	
1004	5060	2	1	S14		Stairwell # 8	W3	Flaking	4	N	N	0	N	N	
1005	5060	1	1	S13		Stairwell at Classroom 104	Ceiling	Flaking	120	N	N	0	N	N	Additional Chipping
1006	5060	1	1	S13		Stairwell at Classroom 104	W1	Flaking	30	N	N	0	N	N	Additional Chipping
1007	5060	1	1	S13		Stairwell at Classroom 104	W2	Flaking	50	N	N	0	N	N	Additional Chipping
1008	5060	1	1	S13		Stairwell at Classroom 104	W3	Flaking	60	N	N	0	N	N	Additional Chipping
1009	5060	1	1	S13		Stairwell at Classroom 104	W4	Flaking	40	N	N	0	N	N	Additional Chipping
1010	5060	2	1	S15		Stairwell next to Classroom 124	Ceiling	Chipping	20	N	N	0	N	N	
1011	5060	1	1	S14		Stairwell #3 next to Building Engineer's Room 105A	Ceiling	Flaking	4	Y	N	0	N	Y - 4 SF	Additional Efflorescence
1012	5060	1	1	S14		Stairwell #3 next to Building Engineer's Room 105A	W1	Flaking	10	N	N	0	N	N	Additional Cracking

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1013	5060	1	1	S14		Stairwell #3 next to Building Engineer's Room 105A	W4	Flaking	8	N	N	0	N	Y - 8 SF	Additional Efflorescence
1014	5060	1	1	105		Storage Closet 105	W1	Flaking	10	N	N	0	N	N	
1015	5060	1	1	105		Storage Closet 105	W2	Flaking	10	N	N	0	N	N	
1016	5060	1	1	105		Storage Closet 105	W3	Flaking	10	N	N	0	N	N	
1017	5060	1	1	105		Storage Closet 105	W4	Flaking	10	N	N	0	N	N	
1018	5060	1	1	102B		Storage Closet across the Hall from Classroom 102	Ceiling	Flaking	25	Y	N	0	N	Y - 25 SF	Additional Efflorescence
1019	5060	1	1	102B		Storage Closet across the Hall from Classroom 102	Floor	Debris	0	N	Y - Entire Floor	80	N	N	
1020	5060	1	1	102B		Storage Closet across the Hall from Classroom 102	W1	Flaking	8	N	N	0	N	N	
1021	5060	1	1	102B		Storage Closet across the Hall from Classroom 102	W2	Flaking	32	N	N	0	N	N	Additional Cracking
1022	5060	1	1	102B		Storage Closet across the Hall from Classroom 102	W3	Flaking	20	N	N	0	N	N	
1023	5060	1	1	102B		Storage Closet across the Hall from Classroom 102	W4	Flaking	45	N	N	0	N	Y - 30 SF	
1024	5060	1	1	106E		Storage Closet in Hallway across former Stair #4	Ceiling	Flaking	180	N	N	0	N	N	
1025	5060	1	1	106E		Storage Closet in Hallway across former Stair #4	W1	Flaking	28	N	N	0	N	N	
1026	5060	1	1	106E		Storage Closet in Hallway across former Stair #4	W2	Flaking	32	N	N	0	N	N	
1027	5060	1	1	106E		Storage Closet in Hallway across former Stair #4	W3	Flaking	40	N	N	0	N	N	
1028	5060	1	1	106E		Storage Closet in Hallway across former Stair #4	W4	Flaking	60	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1029	5060	1	1	135A		Storage Closet in Hallway across from 105 Storage Closet	W2	Flaking	16	N	N	0	Y - 16 SF Contents	N	
1030	5060	1	1	135A		Storage Closet in Hallway across from 105 Storage Closet	W3	Flaking	10	N	N	0	Y - 20 SF Contents	N	
1031	5060	1	1	135A		Storage Closet in Hallway across from 105 Storage Closet	W4	Flaking	16	N	N	0	Y - 16 SF Contents	N	
1032	5060	1	1	101		Storage Room next to Stair #4	W1	Chipping	20	N	N	0	Y - 16 SF Cabinets, Contents	N	
1033	5060	1	1	101		Storage Room next to Stair #4	W3	Flaking	26	Y	N	0	N	Y - 6 SF	Additional Efflorescence, Chipping
1034	5060	1	1	101		Storage Room next to Stair #4	W4	Chipping	14	N	N	0	Y - 32 SF Desks, Posters	N	
1035	5060	2	1	125		Wood Shop Carpentry	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1036	5060	2	1	125		Wood Shop Carpentry	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1037	5060	2	1	125		Wood Shop Carpentry	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Access to Wood Shop Area
1038	5060	2	1	125		Wood Shop Carpentry	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1039	5060	2	1	125		Wood Shop Carpentry	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1040	5060	2	1	125		Wood Shop Carpentry	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1041	5060	2	1	125B		Wood Shop Carpentry Office	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1042	5060	2	1	125B		Wood Shop Carpentry Office	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1043	5060	2	1	125B		Wood Shop Carpentry Office	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Access to Wood Shop Area
1044	5060	2	1	125B		Wood Shop Carpentry Office	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1045	5060	2	1	125B		Wood Shop Carpentry Office	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1046	5060	2	1	125B		Wood Shop Carpentry Office	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1047	5060	2	1	125A		Wood Shop Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1048	5060	2	1	125A		Wood Shop Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1049	5060	2	1	125A		Wood Shop Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Access to Wood Shop Area
1050	5060	2	1	125A		Wood Shop Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1051	5060	2	1	125A		Wood Shop Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1052	5060	2	1	125A		Wood Shop Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1053	5060	2	1	125E		Wood Shop Storage Closet to the Northwest behind Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1054	5060	2	1	125E		Wood Shop Storage Closet to the Northwest behind Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1055	5060	2	1	125E		Wood Shop Storage Closet to the Northwest behind Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Access to Wood Shop Area
1056	5060	2	1	125E		Wood Shop Storage Closet to the Northwest behind Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1057	5060	2	1	125E		Wood Shop Storage Closet to the Northwest behind Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1058	5060	2	1	125E		Wood Shop Storage Closet to the Northwest behind Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1059	5060	2	1	125D		Wood Shop Storage Closet in the Southwest corner by the Loading Dock	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1060	5060	2	1	125D		Wood Shop Storage Closet in the Southwest corner by the Loading Dock	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1061	5060	2	1	125D		Wood Shop Storage Closet in the Southwest corner by the Loading Dock	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Access to Wood Shop Area
1062	5060	2	1	125D		Wood Shop Storage Closet in the Southwest corner by the Loading Dock	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1063	5060	2	1	125D		Wood Shop Storage Closet in the Southwest corner by the Loading Dock	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required



Mastbaum -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1064	5060	2	1	125D		Wood Shop Storage Closet in the Southwest corner by the Loading Dock	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1065	5060	2	0	30T		Boys' Restroom near Room 25	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1066	5060	2	0	30T		Boys' Restroom near Room 25	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1067	5060	2	0	30T		Boys' Restroom near Room 25	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1068	5060	1	0	2		Classroom 2	Ceiling	Flaking	300	N	N	0	N	N	
1069	5060	1	0	2		Classroom 2	Floor	Debris	0	N	Y - Entire Floor	380	N	N	
1070	5060	1	0	2		Classroom 2	W1	Flaking	280	N	N	0	N	N	Unoccupied
1071	5060	1	0	2		Classroom 2	W2	Flaking	200	N	N	0	N	N	
1072	5060	1	0	2		Classroom 2	W3	Flaking	140	N	N	0	N	N	
1073	5060	1	0	2		Classroom 2	W4	Flaking	200	N	N	0	N	N	
1074	5060	2	0	25		Classroom 25	W1	Flaking	10	N	N	0	N	N	
1075	5060	2	0	25		Classroom 25	W2	Flaking	10	N	N	0	N	N	
1076	5060	2	0	25		Classroom 25	W3	Flaking	10	N	N	0	N	N	
1077	5060	2	0	25		Classroom 25	W4	Flaking	10	N	N	0	N	N	
1078	5060	2	0	26		Classroom 26	W1	Flaking	10	N	N	0	N	N	
1079	5060	2	0	26		Classroom 26	W2	Flaking	10	N	N	0	N	N	
1080	5060	2	0	26		Classroom 26	W3	Flaking	10	N	N	0	N	N	
1081	5060	2	0	26		Classroom 26	W4	Flaking	10	N	N	0	N	N	
1082	5060	1	0	008A		Closet in Hallway across from Classroom 2	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1083	5060	1	0	008A		Closet in Hallway across from Classroom 2	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1084	5060	1	0	008A		Closet in Hallway across from Classroom 2	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1085	5060	1	0	008A		Closet in Hallway across from Classroom 2	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1086	5060	1	0	008A		Closet in Hallway across from Classroom 2	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1087	5060	1	0	008A		Closet in Hallway across from Classroom 2	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1088	5060	1	0	10A		Electrical Closet that protrudes out into the Boiler Room by the Sump Pump Area	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1089	5060	1	0	10A		Electrical Closet that protrudes out into the Boiler Room by the Sump Pump Area	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1090	5060	1	0	10A		Electrical Closet that protrudes out into the Boiler Room by the Sump Pump Area	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1091	5060	1	0	10A		Electrical Closet that protrudes out into the Boiler Room by the Sump Pump Area	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1092	5060	1	0	10A		Electrical Closet that protrudes out into the Boiler Room by the Sump Pump Area	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1093	5060	1	0	10A		Electrical Closet that protrudes out into the Boiler Room by the Sump Pump Area	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1094	5060	1	0	5		Electrical Room next to Classroom 2	Floor	Debris	0	N	Y - Entire Floor	380	N	N	
1095	5060	2	0	17		Equipment Storage Room "D" is labeled on the door	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1096	5060	2	0	17		Equipment Storage Room "D" is labeled on the door	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1097	5060	2	0	17		Equipment Storage Room "D" is labeled on the door	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1098	5060	2	0	17		Equipment Storage Room "D" is labeled on the door	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1099	5060	2	0	17		Equipment Storage Room "D" is labeled on the door	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1100	5060	2	0	17		Equipment Storage Room "D" is labeled on the door	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1101	5060	1	0	008B		Former Woodshop Classroom 1	Ceiling	Flaking	300	N	N	0	N	N	
1102	5060	1	0	008B		Former Woodshop Classroom 1	Floor	Debris	0	N	Y - Entire Floor	300	N	N	
1103	5060	1	0	008B		Former Woodshop Classroom 1	W1	Flaking	280	N	N	0	N	N	Unoccupied

Mastbaum -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1104	5060	1	0	008B		Former Woodshop Classroom 1	W2	Flaking	200	N	N	0	N	N	
1105	5060	1	0	008B		Former Woodshop Classroom 1	W3	Flaking	140	N	N	0	N	N	
1106	5060	1	0	008B		Former Woodshop Classroom 1	W4	Flaking	200	N	N	0	N	N	
1107	5060	1	0	004A		Former Woodshop Classroom 1 Closet to the right of entrance	Ceiling	Flaking	300	N	N	0	N	N	
1108	5060	1	0	004A		Former Woodshop Classroom 1 Closet to the right of entrance	Floor	Debris	0	N	Y - Entire Floor	380	N	N	
1109	5060	1	0	004A		Former Woodshop Classroom 1 Closet to the right of entrance	W1	Flaking	200	N	N	0	N	N	Unoccupied
1110	5060	1	0	004A		Former Woodshop Classroom 1 Closet to the right of entrance	W2	Flaking	250	N	N	0	N	N	
1111	5060	1	0	004A		Former Woodshop Classroom 1 Closet to the right of entrance	W3	Flaking	200	N	N	0	N	N	
1112	5060	1	0	004A		Former Woodshop Classroom 1 Closet to the right of entrance	W4	Flaking	250	N	N	0	N	N	
1113	5060	1	0	4		Former Woodshop Classroom 1 Closet to the right of entrance behind Elevator	Ceiling	Flaking	16	N	N	0	N	N	
1114	5060	1	0	4		Former Woodshop Classroom 1 Closet to the right of entrance behind Elevator	Floor	Debris	0	N	Y - Entire Floor	16	N	N	
1115	5060	1	0	4		Former Woodshop Classroom 1 Closet to the right of entrance behind Elevator	W1	Flaking	20	N	N	0	N	N	Unoccupied
1116	5060	1	0	4		Former Woodshop Classroom 1 Closet to the right of entrance behind Elevator	W2	Flaking	25	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1117	5060	1	0	4		Former Woodshop Classroom 1 Closet to the right of entrance behind Elevator	W3	Flaking	18	N	N	0	N	N	
1118	5060	1	0	4		Former Woodshop Classroom 1 Closet to the right of entrance behind Elevator	W4	Flaking	20	N	N	0	N	N	
1119	5060	1	0	008C		Former Woodshop Classroom 1 Small Room to the left of Main Entrance	Ceiling	Flaking	300	N	N	0	N	N	
1120	5060	1	0	008C		Former Woodshop Classroom 1 Small Room to the left of Main Entrance	Floor	Debris	0	N	Y - Entire Floor	260	N	N	
1121	5060	1	0	008C		Former Woodshop Classroom 1 Small Room to the left of Main Entrance	W1	Flaking	120	N	N	0	N	N	Unoccupied
1122	5060	1	0	008C		Former Woodshop Classroom 1 Small Room to the left of Main Entrance	W2	Flaking	90	N	N	0	N	N	
1123	5060	1	0	008C		Former Woodshop Classroom 1 Small Room to the left of Main Entrance	W3	Flaking	100	N	N	0	N	N	
1124	5060	1	0	008C		Former Woodshop Classroom 1 Small Room to the left of Main Entrance	W4	Flaking	75	N	N	0	N	N	
1125	5060	1	0	008D		Former Woodshop Classroom 1 Small Room to the left of Main Entrance Closet	Ceiling	Flaking	80	N	N	0	N	N	
1126	5060	1	0	008D		Former Woodshop Classroom 1 Small Room to the left of Main Entrance Closet	Floor	Debris	0	N	Y - Entire Floor	40	N	N	
1127	5060	1	0	008D		Former Woodshop Classroom 1 Small Room to the left of Main Entrance Closet	W1	Flaking	250	N	N	0	N	N	Unoccupied
1128	5060	1	0	008D		Former Woodshop Classroom 1 Small Room to the left of Main Entrance Closet	W2	Flaking	40	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1129	5060	1	0	008D		Former Woodshop Classroom 1 Small Room to the left of Main Entrance Closet	W3	Flaking	80	N	N	0	N	N	
1130	5060	1	0	008D		Former Woodshop Classroom 1 Small Room to the left of Main Entrance Closet	W4	Flaking	100	N	N	0	N	N	
1131	5060	2	0	22		Girls' Restroom near Room 25	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
1132	5060	2	0	22		Girls' Restroom near Room 25	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1133	5060	2	0	22		Girls' Restroom near Room 25	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1134	5060	2	0	H04		Hallway along side Room 25 leading to the Weight Room	W2	Flaking	80	N	N	0	N	N	
1135	5060	2	0	H04		Hallway along side Room 25 leading to the Weight Room	W4	Flaking	80	N	N	0	N	N	
1136	5060	2	0	H02		Hallway along side Room 26 leading to the Weight Room	W2	Flaking	80	N	N	0	N	N	
1137	5060	2	0	H02		Hallway along side Room 26 leading to the Weight Room	W4	Flaking	80	N	N	0	N	N	
1138	5060	1	0	H02		Hallway in front of Classroom 1 and 2	W2	Flaking	20	N	N	0	N	N	
1139	5060	1	0	H02		Hallway in front of Classroom 1 and 2	W4	Flaking	18	N	N	0	N	N	
1140	5060	2	0	H07		Hallway in front of Elevator	W1	Chipping	4	N	N	0	N	N	
1141	5060	2	0	H07		Hallway in front of Elevator	W2	Cracking	16	N	N	0	N	N	
1142	5060	2	0	H07		Hallway in front of Elevator	W3	Chipping	2	N	N	0	N	N	
1143	5060	2	0	H07		Hallway in front of Elevator	W4	Cracking	20	N	N	0	N	N	
1144	5060	2	0	H01		Hallway in front of Room 25	W1	Flaking	60	N	N	0	N	N	
1145	5060	2	0	H01		Hallway in front of Room 25	W3	Flaking	60	N	N	0	N	N	
1146	5060	2	0	020A		Hallway leading from Storage Room 23 to the Locker Room along the West wall	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1147	5060	2	0	020A		Hallway leading from Storage Room 23 to the Locker Room along the West wall	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1148	5060	2	0	020A		Hallway leading from Storage Room 23 to the Locker Room along the West wall	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1149	5060	2	0	020A		Hallway leading from Storage Room 23 to the Locker Room along the West wall	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1150	5060	2	0	020A		Hallway leading from Storage Room 23 to the Locker Room along the West wall	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1151	5060	2	0	020A		Hallway leading from Storage Room 23 to the Locker Room along the West wall	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1152	5060	2	0	33		Locker area to the East (gated)	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1153	5060	2	0	33		Locker area to the East (gated)	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1154	5060	2	0	33		Locker area to the East (gated)	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1155	5060	2	0	33		Locker area to the East (gated)	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1156	5060	2	0	33		Locker area to the East (gated)	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1157	5060	2	0	33		Locker area to the East (gated)	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1158	5060	2	0	020C		Locker area to the West (gated)	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1159	5060	2	0	020C		Locker area to the West (gated)	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1160	5060	2	0	020C		Locker area to the West (gated)	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1161	5060	2	0	020C		Locker area to the West (gated)	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1162	5060	2	0	020C		Locker area to the West (gated)	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1163	5060	2	0	020C		Locker area to the West (gated)	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required

Mastbaum -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1164	5060	2	0	20		Locker Room	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1165	5060	2	0	20		Locker Room	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1166	5060	2	0	20		Locker Room	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1167	5060	2	0	20		Locker Room	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1168	5060	2	0	20		Locker Room	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1169	5060	2	0	20		Locker Room	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1170	5060	2	0	30		Locker Room Boys' Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1171	5060	2	0	30		Locker Room Boys' Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1172	5060	2	0	30		Locker Room Boys' Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1173	5060	2	0	30		Locker Room Boys' Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1174	5060	2	0	30		Locker Room Boys' Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1175	5060	2	0	30		Locker Room Boys' Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1176	5060	1	0	007A		Open Space/Hallway from the entrance to the Mechanical Rooms in front of the Building Engineer's Office and Electrical Room	W1	Chipping	4	N	N	0	N	N	
1177	5060	1	0	007A		Open Space/Hallway from the entrance to the Mechanical Rooms in front of the Building Engineer's Office and Electrical Room	W2	Flaking	6	N	N	0	N	N	
1178	5060	1	0	007A		Open Space/Hallway from the entrance to the Mechanical Rooms in front of the Building Engineer's Office and Electrical Room	W4	Flaking	10	N	N	0	N	N	
1179	5060	1	0	10D		Restroom up the metal Stairs in the Boiler Room past the Storage Closet	W1	Flaking	20	N	N	0	N	N	
1180	5060	1	0	10D		Restroom up the metal Stairs in the Boiler Room past the Storage Closet	W2	Flaking	18	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1181	5060	1	0	10D		Restroom up the metal Stairs in the Boiler Room past the Storage Closet	W3	Flaking	20	N	N	0	N	N	
1182	5060	1	0	10D		Restroom up the metal Stairs in the Boiler Room past the Storage Closet	W4	Flaking	18	N	N	0	N	N	
1183	5060	1	0	002B		Restrooms at the Northeast corner of the former Woodshop Classroom 1	Ceiling	Flaking	300	N	N	0	N	N	
1184	5060	1	0	002B		Restrooms at the Northeast corner of the former Woodshop Classroom 1	Floor	Debris	0	N	Y - Entire Floor	380	N	N	
1185	5060	1	0	002B		Restrooms at the Northeast corner of the former Woodshop Classroom 1	W1	Flaking	280	N	N	0	N	N	Unoccupied
1186	5060	1	0	002B		Restrooms at the Northeast corner of the former Woodshop Classroom 1	W2	Flaking	200	N	N	0	N	N	
1187	5060	1	0	002B		Restrooms at the Northeast corner of the former Woodshop Classroom 1	W3	Flaking	140	N	N	0	N	N	
1188	5060	1	0	002B		Restrooms at the Northeast corner of the former Woodshop Classroom 1	W4	Flaking	200	N	N	0	N	N	
1189	5060	2	0	23		Room 23	W1	Chipping	8	N	N	0	N	N	
1190	5060	2	0	23		Room 23	W2	Chipping	16	N	N	0	N	N	
1191	5060	2	0	23		Room 23	W3	Chipping	20	N	N	0	N	N	
1192	5060	2	0	23		Room 23	W4	Chipping	4	N	N	0	N	N	
1193	5060	2	0	27		Room 27	Ceiling	Flaking	40	N	N	0	N	N	
1194	5060	2	0	27		Room 27	W1	Flaking	20	N	N	0	N	N	
1195	5060	2	0	27		Room 27	W2	Flaking	18	N	N	0	N	N	
1196	5060	2	0	27		Room 27	W3	Flaking	28	N	N	0	N	N	
1197	5060	2	0	27		Room 27	W4	Flaking	32	N	N	0	N	N	
1198	5060	2	0	S09		Stairs leading from the Gym to the Locker Room to the Northeast	Ceiling	Flaking	18	N	N	0	N	N	



Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1199	5060	2	0	S09		Stairs leading from the Gym to the Locker Room to the Northeast	W1	Flaking	10	N	N	0	N	N	
1200	5060	2	0	S09		Stairs leading from the Gym to the Locker Room to the Northeast	W2	Flaking	10	N	N	0	N	N	
1201	5060	2	0	S09		Stairs leading from the Gym to the Locker Room to the Northeast	W3	Flaking	20	N	N	0	N	N	
1202	5060	2	0	S09		Stairs leading from the Gym to the Locker Room to the Northeast	W4	Flaking	24	N	N	0	N	N	
1203	5060	2	0	S08		Stairs leading from the Gym to the Locker Room to the Northwest	Ceiling	Flaking	16	N	N	0	N	N	
1204	5060	2	0	S08		Stairs leading from the Gym to the Locker Room to the Northwest	W1	Flaking	15	N	N	0	N	N	
1205	5060	2	0	S08		Stairs leading from the Gym to the Locker Room to the Northwest	W2	Flaking	12	N	N	0	N	N	
1206	5060	2	0	S08		Stairs leading from the Gym to the Locker Room to the Northwest	W3	Flaking	20	N	N	0	N	N	
1207	5060	2	0	S08		Stairs leading from the Gym to the Locker Room to the Northwest	W4	Flaking	26	N	N	0	N	N	
1208	5060	2	0	S07		Stairs leading to the Locker Room from the East	Ceiling	Flaking	16	N	N	0	N	N	
1209	5060	2	0	S07		Stairs leading to the Locker Room from the East	W1	Flaking	20	N	N	0	N	N	
1210	5060	2	0	S07		Stairs leading to the Locker Room from the East	W2	Flaking	14	N	N	0	N	N	
1211	5060	2	0	S07		Stairs leading to the Locker Room from the East	W3	Flaking	24	N	N	0	N	N	
1212	5060	2	0	S07		Stairs leading to the Locker Room from the East	W4	Flaking	18	N	N	0	N	N	
1213	5060	2	0	S06		Stairs leading to the Locker Room from the West	Ceiling	Flaking	15	N	N	0	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1214	5060	2	0	S06		Stairs leading to the Locker Room from the West	W1	Flaking	8	N	N	0	N	N	
1215	5060	2	0	S06		Stairs leading to the Locker Room from the West	W2	Flaking	20	N	N	0	N	N	
1216	5060	2	0	S06		Stairs leading to the Locker Room from the West	W3	Flaking	10	N	N	0	N	N	
1217	5060	2	0	S06		Stairs leading to the Locker Room from the West	W4	Flaking	25	N	N	0	N	N	
1218	5060	1	0	8		Stairwell #4 in Basement Level	Ceiling	Flaking	10	N	N	0	N	N	
1219	5060	1	0	8		Stairwell #4 in Basement Level	Floor	Debris	0	N	Y - Entire Floor	380	N	N	
1220	5060	2	0	S04		Stairwell at Girls' Restroom	Ceiling	Flaking	36	N	N	0	N	N	
1221	5060	2	0	S04		Stairwell at Girls' Restroom	Floor	Chipping	12	N	N	0	N	N	
1222	5060	2	0	S04		Stairwell at Girls' Restroom	W1	Flaking	24	N	N	0	N	N	
1223	5060	2	0	S04		Stairwell at Girls' Restroom	W2	Flaking	20	N	N	0	N	N	
1224	5060	2	0	S04		Stairwell at Girls' Restroom	W3	Flaking	24	N	N	0	N	N	
1225	5060	2	0	S04		Stairwell at Girls' Restroom	W4	Flaking	40	N	N	0	N	N	
1226	5060	2	0	S05		Stairwell at Room 27	Ceiling	Chipping	14	N	N	0	N	N	
1227	5060	2	0	S05		Stairwell at Room 27	W1	Flaking	10	N	N	0	N	N	
1228	5060	2	0	S05		Stairwell at Room 27	W2	Chipping	18	N	N	0	N	N	
1229	5060	2	0	S05		Stairwell at Room 27	W3	Flaking	22	N	N	0	N	N	
1230	5060	2	0	S05		Stairwell at Room 27	W4	Chipping	16	N	N	0	N	N	
1231	5060	2	0	23A		Storage Closet in the Hallway underneath the Stairs outside Room 23	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1232	5060	2	0	23A		Storage Closet in the Hallway underneath the Stairs outside Room 23	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1233	5060	2	0	23A		Storage Closet in the Hallway underneath the Stairs outside Room 23	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1234	5060	2	0	23A		Storage Closet in the Hallway underneath the Stairs outside Room 23	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1235	5060	2	0	23A		Storage Closet in the Hallway underneath the Stairs outside Room 23	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1236	5060	2	0	23A		Storage Closet in the Hallway underneath the Stairs outside Room 23	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1237	5060	1	0	10E		Storage Closet on the other side of the Restroom up the metal Stairs from the Boiler Room on the Emergency Exit Hallway	W1	Flaking	25	N	N	0	N	N	
1238	5060	1	0	10E		Storage Closet on the other side of the Restroom up the metal Stairs from the Boiler Room on the Emergency Exit Hallway	W2	Flaking	30	N	N	0	N	N	
1239	5060	1	0	10E		Storage Closet on the other side of the Restroom up the metal Stairs from the Boiler Room on the Emergency Exit Hallway	W3	Flaking	25	N	N	0	N	N	
1240	5060	1	0	10E		Storage Closet on the other side of the Restroom up the metal Stairs from the Boiler Room on the Emergency Exit Hallway	W4	Flaking	30	N	N	0	N	N	
1241	5060	2	0	31		Storage in Locker Room Former Showers (gated)	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1242	5060	2	0	31		Storage in Locker Room Former Showers (gated)	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1243	5060	2	0	31		Storage in Locker Room Former Showers (gated)	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1244	5060	2	0	31		Storage in Locker Room Former Showers (gated)	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1245	5060	2	0	31		Storage in Locker Room Former Showers (gated)	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1246	5060	2	0	31		Storage in Locker Room Former Showers (gated)	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1247	5060	2	0	32		Storage in Locker Room Former Showers to the East of the main showers	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1248	5060	2	0	32		Storage in Locker Room Former Showers to the East of the main showers	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1249	5060	2	0	32		Storage in Locker Room Former Showers to the East of the main showers	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1250	5060	2	0	32		Storage in Locker Room Former Showers to the East of the main showers	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1251	5060	2	0	32		Storage in Locker Room Former Showers to the East of the main showers	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1252	5060	2	0	32		Storage in Locker Room Former Showers to the East of the main showers	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1253	5060	1	0	002A		Storage/Workshop at the Northwest corner of the former Woodshop Classroom 1	Ceiling	Flaking	220	N	N	0	N	N	
1254	5060	1	0	002A		Storage/Workshop at the Northwest corner of the former Woodshop Classroom 1	Floor	Debris	0	N	Y - Entire Floor	380	N	N	

Mastbaum -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1255	5060	1	0	002A		Storage/Workshop at the Northwest corner of the former Woodshop Classroom 1	W1	Flaking	150	N	N	0	N	N	Unoccupied
1256	5060	1	0	002A		Storage/Workshop at the Northwest corner of the former Woodshop Classroom 1	W2	Flaking	180	N	N	0	N	N	
1257	5060	1	0	002A		Storage/Workshop at the Northwest corner of the former Woodshop Classroom 1	W3	Flaking	120	N	N	0	N	N	
1258	5060	1	0	002A		Storage/Workshop at the Northwest corner of the former Woodshop Classroom 1	W4	Flaking	140	N	N	0	N	N	
1259	5060	2	0	024A		Weight Room Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1260	5060	2	0	020B		Weight Room Office	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1261	5060	2	0	020B		Weight Room Office	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1262	5060	2	0	020B		Weight Room Office	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1263	5060	2	0	020B		Weight Room Office	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1264	5060	2	0	020B		Weight Room Office	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1265	5060	2	0	24		Weight Room Room 24/29	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1266	5060	2	0	24		Weight Room Room 24/29	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1267	5060	2	0	24		Weight Room Room 24/29	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1268	5060	2	0	24		Weight Room Room 24/29	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1269	5060	2	0	24		Weight Room Room 24/29	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required
1270	5060	2	0	24		Weight Room Room 24/29	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection required