

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	4570	1	3	H316		3rd Floor Hallway near Classrooms 301 through 305	Ceiling	Efflorescence	2	Y	N	0	N	N	
2	4570	1	3	H316		3rd Floor Hallway near Classrooms 301 through 305	W1	Flaking	7	N	N	0	N	Y - 2 SF	4 Locations; Additional Cracking
3	4570	1	3	H316		3rd Floor Hallway near Classrooms 301 through 305	W3	Cracking	8	N	N	0	N	N	2 Locations
4	4570	1	3	H315		3rd Floor Hallways near Classrooms 300 through 312	Ceiling	Flaking	9	N	N	0	N	N	Additional Chipping
5	4570	1	3	H315		3rd Floor Hallways near Classrooms 300 through 312	W2	Cracking	6	N	N	0	N	N	
6	4570	1	3	H315		3rd Floor Hallways near Classrooms 300 through 312	W4	Cracking	7	N	N	0	N	N	3 Locations; Additional Chipping
7	4570	1	3	312A		Boy's Restroom across from Classroom 310	Ceiling	Flaking	6	N	N	0	N	N	
8	4570	1	3	312A		Boy's Restroom across from Classroom 310	W4	Chipping	12	N	N	0	N	N	
9	4570	2	3	317B		Boy's Restroom next to Classroom 317	Ceiling	Chipping	7	N	N	0	N	N	
10	4570	2	3	317B		Boy's Restroom next to Classroom 317	W2	Chipping	12	N	N	0	N	N	
11	4570	2	3	317B		Boy's Restroom next to Classroom 317	W3	Chipping	4	N	N	0	N	N	
12	4570	1	3	300		Classroom 300	Ceiling	Cracking	3	N	N	0	N	N	2 Locations; Additional Cracking, Holes
13	4570	1	3	300		Classroom 300	W1	Cracking	4	N	N	0	N	N	2 Locations; Additional Holes
14	4570	1	3	300		Classroom 300	W2	Flaking	21	Y	N	0	N	Y - 2 SF	Additional Efflorescence, Cracking
15	4570	1	3	300		Classroom 300	W3	Flaking	10	N	N	0	N	N	2 Locations; Additional Cracking
16	4570	1	3	300		Classroom 300	W4	Flaking	4	N	N	0	Y - 24 SF Posters, Shelves	N	Additional Cracking
17	4570	1	3	304		Classroom 304	W1	Cracking	10	N	N	0	N	N	Additional Chipping
18	4570	1	3	304		Classroom 304	W2	Flaking	5	N	N	0	N	N	Additional Cracking, Holes
19	4570	1	3	304		Classroom 304	W3	Flaking	12	Y	N	0	N	Y - 6 SF	3 Locations; Additional Efflorescence, Chipping
20	4570	1	3	305		Classroom 305	W1	Partially Inaccessible	0	N	N	0	N	N	
21	4570	1	3	305		Classroom 305	W2	Efflorescence	2	Y	N	0	N	Y - 2 SF	
22	4570	1	3	305		Classroom 305	W3	Efflorescence	12	Y	N	0	N	Y - 12 SF	2 Locations
23	4570	1	3	306		Classroom 306	Ceiling	Flaking	4	N	N	0	N	N	
24	4570	1	3	306		Classroom 306	W1	Flaking	18	N	N	0	N	Y - 1 SF	Additional Cracking, Chipping
25	4570	1	3	306		Classroom 306	W2	Chipping	6	N	N	0	N	N	Additional Holes
26	4570	1	3	306		Classroom 306	W3	Flaking	26	N	N	0	N	N	Additional Cracking, Chipping
27	4570	1	3	306		Classroom 306	W4	Flaking	18	N	N	0	N	N	Additional Cracking, Chipping
28	4570	1	3	307		Classroom 307	Ceiling	Holes	1	N	N	0	N	Y - 1 SF	
29	4570	1	3	307		Classroom 307	W1	Cracking	2	N	N	0	N	N	Cracking in Closet
30	4570	1	3	308		Classroom 308	Ceiling	Efflorescence	1	Y	N	0	N	N	
31	4570	1	3	308		Classroom 308	W1	Cracking	4	N	N	0	N	N	Additional Chipping
32	4570	1	3	308		Classroom 308	W3	Flaking	4	N	N	0	N	N	Flaking @ Radiator Grate

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
33	4570	1	3	308		Classroom 308	W4	Chipping	1	N	N	0	N	N	
34	4570	1	3	309		Classroom 309	Ceiling	Flaking	3	Y	N	0	N	Y - 1 SF	Additional Efflorescence
35	4570	1	3	309		Classroom 309	W1	Flaking	1	N	N	0	N	N	Additional Chipping
36	4570	1	3	309		Classroom 309	W2	Flaking	6	N	N	0	N	Y - 1 SF	
37	4570	1	3	309		Classroom 309	W3	Flaking	9	N	Y - On Window Sills 3 & 4	6	Y - 48 SF Boxes, Contents	N	Additional Cracking, Chipping
38	4570	1	3	309		Classroom 309	W4	Cracking	12	N	N	0	Y - 36 SF Contents	N	
39	4570	1	3	310		Classroom 310	Ceiling	Flaking	2	N	N	0	N	N	2 Locations; Additional Cracking
40	4570	1	3	310		Classroom 310	W3	Flaking	4	Y	N	0	N	Y - 2 SF	2 Locations; Additional Efflorescence;
41	4570	1	3	311		Classroom 311	Ceiling	Flaking	28	Y	N	0	N	Y - 6 SF	4 Locations; Additional Efflorescence
42	4570	1	3	311		Classroom 311	W1	Flaking	8	N	N	0	N	N	2 Locations; Additional Cracking, Chipping; Damage Includes Closet
43	4570	1	3	311		Classroom 311	W2	Cracking	4	N	N	0	N	N	Additional Chipping
44	4570	1	3	311		Classroom 311	W3	Flaking	4	Y	Y - On Window Sill 5	2	N	Y - 2 SF	Additional Efflorescence, Cracking, Chipping
45	4570	1	3	311		Classroom 311	W4	Chipping	9	N	N	0	N	N	Additional Holes
46	4570	1	3	312		Classroom 312	Ceiling	Flaking	8	Y	N	0	N	Y - 6 SF	Additional Efflorescence
47	4570	1	3	312		Classroom 312	W1	Cracking	2	N	N	0	N	N	
48	4570	1	3	312		Classroom 312	W2	Cracking	5	N	N	0	N	N	Additional Chipping
49	4570	1	3	312		Classroom 312	W3	Flaking	8	Y	N	0	N	Y - 3 SF	Additional Efflorescence
50	4570	1	3	312		Classroom 312	W4	Cracking	12	N	N	0	N	N	Additional Chipping
51	4570	2	3	315		Classroom 315	Ceiling	Flaking	22	N	N	0	N	N	Additional Cracking, Chipping; Various Locations
52	4570	2	3	315		Classroom 315	W1	Cracking	6	N	N	0	N	N	
53	4570	2	3	315		Classroom 315	W2	Cracking	6	N	N	0	N	N	
54	4570	2	3	315		Classroom 315	W3	Flaking	30	N	N	0	N	N	Additional Cracking, Chipping
55	4570	2	3	316		Classroom 316	Ceiling	Flaking	75	N	N	0	N	N	Additional Cracking, Chipping
56	4570	2	3	316		Classroom 316	W1	Cracking	3	N	N	0	N	N	2 Locations; Additional Holes
57	4570	2	3	316		Classroom 316	W2	Cracking	4	N	N	0	N	N	
58	4570	2	3	316		Classroom 316	W3	Flaking	10	N	N	0	N	N	2 Locations; Damage on Walls & Radiator Grate; Additional Cracking, Chipping
59	4570	2	3	316		Classroom 316	W4	Holes	2	N	N	0	N	N	2 Locations
60	4570	2	3	317		Classroom 317	Ceiling	Flaking	12	N	N	0	N	N	2 Locations
61	4570	2	3	317		Classroom 317	W1	Cracking	12	N	N	0	N	N	Additional Chipping, Holes
62	4570	2	3	317		Classroom 317	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks, Posters	N	
63	4570	2	3	317		Classroom 317	W3	Chipping	6	N	N	0	N	N	Chipping on Cabinets
64	4570	2	3	318		Classroom 318	Ceiling	Flaking	38	N	N	0	N	N	2 Locations; Additional Chipping
65	4570	2	3	318		Classroom 318	W1	Flaking	20	N	N	0	N	N	Additional Cracking
66	4570	2	3	318		Classroom 318	W3	Cracking	14	N	N	0	N	N	2 Locations; Additional Chipping; Damage @ Comer & Cabinets
67	4570	1	3	308A		Girl's Restroom Across from IMC Library	Ceiling	Flaking	72	N	N	0	N	N	
68	4570	1	3	308A		Girl's Restroom Across from IMC Library	W3	Chipping	3	N	N	0	N	N	Chipping @ Pipe

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
69	4570	2	3	315B		Girl's Restroom next to Classroom 315	Ceiling	Cracking	40	N	N	0	N	N	Additional Chipping
70	4570	2	3	315B		Girl's Restroom next to Classroom 315	W3	Cracking	2	N	N	0	N	N	Cracking @ Window Lintel
71	4570	2	3	H318		Hallway between Classrooms 315 to 318	W3	Chipping	1	N	N	0	N	N	Chipping @ Doors
72	4570	1	3	303		IMC	Ceiling	Flaking	9	Y	N	0	N	N	Additional Efflorescence, Cracking
73	4570	1	3	303		IMC	W1	Flaking	44	N	N	0	N	N	7 Locations; Additional Cracking, Chipping
74	4570	1	3	303		IMC	W2	Flaking	4	N	N	0	N	N	Additional Cracking
75	4570	1	3	303		IMC	W3	Flaking	86	Y	Y - On Window Sills	18	N	Y - 12 SF	Additional Efflorescence, Cracking, Holes
76	4570	1	3	303		IMC	W4	Partially Inaccessible	0	N	N	0	Y - 120 SF Shelves, Books	N	
77	4570	1	3	309B		Office to Right of Classroom 309	Ceiling	Flaking	22	Y	N	0	N	N	Additional Efflorescence
78	4570	1	3	309B		Office to Right of Classroom 309	W1	Flaking	1	N	N	0	N	N	
79	4570	1	3	309B		Office to Right of Classroom 309	W2	Cracking	10	N	N	0	N	N	
80	4570	1	3	309B		Office to Right of Classroom 309	W3	Flaking	10	N	N	0	N	N	Additional Chipping
81	4570	1	3	309B		Office to Right of Classroom 309	W4	Cracking	3	N	N	0	N	N	2 Locations; Additional Chipping
82	4570	2	3	S36		Stairs across from Classroom 315	Ceiling	Flaking	7	N	N	0	N	N	Additional Cracking, Chipping; Damage @ 2 Locations
83	4570	2	3	S36		Stairs across from Classroom 315	W1	Cracking	8	N	N	0	N	N	
84	4570	2	3	S36		Stairs across from Classroom 315	W2	Cracking	6	N	N	0	N	N	
85	4570	2	3	S36		Stairs across from Classroom 315	W3	Flaking	8	N	N	0	N	N	Additional Cracking
86	4570	2	3	S36		Stairs across from Classroom 315	W4	Cracking	24	N	N	0	N	N	
87	4570	1	3	S34		Stairs across from Library	Center Banister	Chipping	2	N	N	0	N	N	
88	4570	1	3	S34		Stairs across from Library	W2	Cracking	20	N	N	0	N	N	
89	4570	1	3	S33		Stairs Next to Classroom 311	Ceiling	Flaking	20	N	N	0	N	N	Additional Chipping
90	4570	1	3	S33		Stairs Next to Classroom 311	W2	Flaking	20	N	N	0	N	Y - 1 SF	4 Locations; Additional Cracking, Chipping, Gouges
91	4570	1	3	S33		Stairs Next to Classroom 311	W3	Flaking	6	Y	N	0	N	Y - 2 SF	Additional Efflorescence, Cracking
92	4570	1	3	S33		Stairs Next to Classroom 311	W4	Flaking	17	N	N	0	N	N	3 Locations; Additional Cracking, Gouges
93	4570	2	3	S37		Stairs Next to Classroom 316	Ceiling	Flaking	120	N	N	0	N	N	Additional Cracking
94	4570	2	3	S37		Stairs Next to Classroom 316	Center Banister	Chipping	6	N	N	0	N	N	
95	4570	2	3	S37		Stairs Next to Classroom 316	W1	Cracking	4	N	N	0	N	N	
96	4570	2	3	S37		Stairs Next to Classroom 316	W2	Cracking	9	N	N	0	N	N	2 Locations
97	4570	2	3	S37		Stairs Next to Classroom 316	W3	Cracking	15	N	N	0	N	N	

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
98	4570	2	3	S37		Stairs Next to Classroom 316	W4	Cracking	15	N	N	0	N	N	
99	4570	1	3	308B		Storage Closet in Classroom 308 near Hallway	Ceiling	Flaking	6	N	N	0	N	Y - 2 SF	Additional Cracking
100	4570	1	3	308B		Storage Closet in Classroom 308 near Hallway	W1	Flaking	16	N	N	0	Y - 16 SF Boxes	N	Additional Cracking
101	4570	1	3	308B		Storage Closet in Classroom 308 near Hallway	W2	Partially Inaccessible	0	N	N	0	Y - 36 SF Boxes	N	
102	4570	1	3	308B		Storage Closet in Classroom 308 near Hallway	W3	Partially Inaccessible	0	N	N	0	Y - 40 SF Boxes	N	
103	4570	1	3	308B		Storage Closet in Classroom 308 near Hallway	W4	Flaking	24	N	N	0	N	Y - 16 SF	Additional Cracking
104	4570	1	3	308C		Storage Closet in Classroom 308 near Windows	W1	Cracking	1	N	N	0	N	N	
105	4570	1	3	308C		Storage Closet in Classroom 308 near Windows	W2	Chipping	2	N	N	0	N	N	
106	4570	2	3	317A		Storage Closet next to Custodial Closet	Ceiling	Flaking	14	Y	N	0	N	N	Additional Efflorescence
107	4570	2	3	317A		Storage Closet next to Custodial Closet	W1	Chipping	1	N	N	0	N	N	
108	4570	2	3	317A		Storage Closet next to Custodial Closet	W2	Cracking	2	N	N	0	N	N	
109	4570	2	3	317A		Storage Closet next to Custodial Closet	W3	Cracking	2	N	N	0	N	N	
110	4570	2	3	317A		Storage Closet next to Custodial Closet	W4	Flaking	12	N	N	0	N	N	3 Locations
111	4570	2	3	315A		Storage Closet to Right of Classroom 315	Ceiling	Flaking	42	N	N	0	N	N	
112	4570	2	3	315A		Storage Closet to Right of Classroom 315	W1	Cracking	6	N	N	0	N	N	
113	4570	2	3	315A		Storage Closet to Right of Classroom 315	W2	Cracking	5	N	N	0	N	N	
114	4570	2	3	315A		Storage Closet to Right of Classroom 315	W3	Cracking	1	N	N	0	N	N	Chipping @ Door
115	4570	2	3	315A		Storage Closet to Right of Classroom 315	W4	Cracking	12	N	N	0	N	N	2 Locations; Cracking @ Corners
116	4570	1	3	312B		Teacher Lounge across from Classroom 310	Ceiling	Efflorescence	4	Y	N	0	N	Y - 4 SF	
117	4570	1	3	312B		Teacher Lounge across from Classroom 310	W1	Cracking	5	N	N	0	N	N	2 Locations
118	4570	1	3	312B		Teacher Lounge across from Classroom 310	W2	Flaking	16	N	N	0	N	N	2 Locations; Additional Cracking

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
119	4570	1	3	312B		Teacher Lounge across from Classroom 310	W3	Flaking	10	N	N	0	N	N	Additional Chipping; Damage Includes Radiator Covers
120	4570	1	3	312C		Teacher Lounge Restroom	Ceiling	Flaking	3	Y	N	0	N	Y - 2 SF	2 Locations; Additional Efflorescence, Holes
121	4570	1	3	312C		Teacher Lounge Restroom	W1	Flaking	12	N	N	0	N	N	Additional Cracking
122	4570	1	3	312C		Teacher Lounge Restroom	W2	Efflorescence	2	Y	N	0	N	N	Damage @ Sink
123	4570	1	3	312C		Teacher Lounge Restroom	W3	Flaking	16	N	N	0	N	N	
124	4570	1	3	312C		Teacher Lounge Restroom	W4	Gouges	1	N	N	0	N	N	
125	4570	2	2	H213		2nd Floor Hallway near Classrooms 215 through 218	Ceiling	Flaking	10	N	N	0	N	N	Additional Cracking
126	4570	2	2	H213		2nd Floor Hallway near Classrooms 215 through 218	W2	Chipping	2	N	N	0	N	N	2 Locations; Chipping @ Radiator & Pipe
127	4570	2	2	H213		2nd Floor Hallway near Classrooms 215 through 218	W4	Chipping	2	N	N	0	N	N	Chipping @ Door
128	4570	1	2	209B		2nd Floor Men's Teacher Lounge	Ceiling	Flaking	17	Y	N	0	N	N	Additional Efflorescence
129	4570	1	2	209B		2nd Floor Men's Teacher Lounge	W1	Flaking	7	N	Y - On Moulding	1	N	Y - 7 SF	Additional Cracking
130	4570	1	2	209B		2nd Floor Men's Teacher Lounge	W2	Flaking	2	Y	N	0	N	Y - 2 SF	Additional Efflorescence
131	4570	1	2	209B		2nd Floor Men's Teacher Lounge	W3	Flaking	2	Y	Y - On Window Sill	2	N	Y - 2 SF	Additional Efflorescence
132	4570	1	2	212B		2nd Floor Women's Teacher Lounge next to Boy's Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
133	4570	1	2	212B		2nd Floor Women's Teacher Lounge next to Boy's Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
134	4570	1	2	212B		2nd Floor Women's Teacher Lounge next to Boy's Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
135	4570	1	2	212B		2nd Floor Women's Teacher Lounge next to Boy's Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
136	4570	1	2	212B		2nd Floor Women's Teacher Lounge next to Boy's Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
137	4570	1	2	212B		2nd Floor Women's Teacher Lounge next to Boy's Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
138	4570	1	2	212A		Boy's Restroom next to Classroom 212	Ceiling	Flaking	81	N	N	0	N	N	
139	4570	1	2	212A		Boy's Restroom next to Classroom 212	W4	Flaking	10	N	N	0	N	N	Flaking on Radiator

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
140	4570	2	2	217B		Boy's Restroom next to Classroom 217	Ceiling	Cracking	18	N	N	0	N	N	
141	4570	2	2	217B		Boy's Restroom next to Classroom 217	W1	Flaking	6	N	N	0	N	N	Additional Cracking
142	4570	2	2	217B		Boy's Restroom next to Classroom 217	W2	Flaking	9	N	N	0	N	N	Additional Cracking
143	4570	2	2	217B		Boy's Restroom next to Classroom 217	W3	Cracking	4	N	N	0	N	N	
144	4570	1	2	202		Classroom 202	Ceiling	Flaking	567	N	N	0	N	N	
145	4570	1	2	202		Classroom 202	W1	Flaking	42	N	N	0	N	Y - 1 SF	Additional Cracking, Chipping
146	4570	1	2	202		Classroom 202	W3	Flaking	22	N	Y - On Window Sills	4	N	N	2 Locations; Additional Chipping
147	4570	1	2	202		Classroom 202	W4	Chipping	210	N	N	0	N	N	Additional Cracking, Chipping
148	4570	1	2	203		Classroom 203	Ceiling	Flaking	480	N	N	0	N	N	Additional Cracking, Chipping
149	4570	1	2	203		Classroom 203	W3	Flaking	38	Y	Y - On Window Sills 1 & 2	2	N	Y - 8 SF	Additional Efflorescence, Cracking, Chipping
150	4570	1	2	203		Classroom 203	W4	Chipping	210	N	N	0	N	N	Sheetrock Wall
151	4570	1	2	203		Classroom 203	W1	Flaking	50	N	N	0	N	Y - 2 SF	3 Locations; Additional Cracking, Chipping; Damage Includes Entrance, Wall, Closet; Plastering @ Door Frame
152	4570	1	2	203		Classroom 203	W2	Flaking	6	N	N	0	N	N	Additional Cracking, Holes, Gouges
153	4570	1	2	204		Classroom 204	W1	Flaking	9	N	N	0	N	N	2 Locations; Additional Cracking, Chipping; Damage @ Door and Wall
154	4570	1	2	204		Classroom 204	W2	Holes	3	N	N	0	N	N	
155	4570	1	2	204		Classroom 204	W3	Flaking	3	N	N	0	N	N	Additional Cracking
156	4570	1	2	205		Classroom 205	W1	Cracking	15	N	N	0	N	N	2 Locations; Damage @ Wall & Closet
157	4570	1	2	205		Classroom 205	W2	Flaking	3	N	N	0	N	N	Additional Chipping, Gouges
158	4570	1	2	205		Classroom 205	W3	Flaking	18	Y	Y - On Window Sills	3	N	Y - 7 SF	Additional Efflorescence, Chipping
159	4570	1	2	205		Classroom 205	W4	Chipping	6	N	N	0	N	N	Additional Holes
160	4570	1	2	206		Classroom 206	W1	Flaking	10	N	N	0	N	Y - 5 SF	Additional Cracking, Chipping
161	4570	1	2	206		Classroom 206	W2	Chipping	4	N	N	0	N	N	
162	4570	1	2	206		Classroom 206	W4	Cracking	9	N	N	0	N	N	2 Locations; Additional Chipping; Damage Above and Below Bulletin Board
163	4570	1	2	207		Classroom 207	W1	Cracking	10	N	N	0	N	N	2 Locations
164	4570	1	2	207		Classroom 207	W2	Flaking	5	N	N	0	N	N	2 Locations
165	4570	1	2	207		Classroom 207	W3	Flaking	4	N	N	0	N	N	Additional Cracking, Chipping
166	4570	1	2	207		Classroom 207	W4	Cracking	2	N	N	0	N	N	
167	4570	1	2	208		Classroom 208	Ceiling	Flaking	756	Y	N	0	N	N	Water Stains on Ceiling
168	4570	1	2	208		Classroom 208	W1	Flaking	32	N	N	0	N	N	Additional Cracking, Chipping
169	4570	1	2	208		Classroom 208	W2	Flaking	24	Y	N	0	N	Y - 2 SF	Additional Efflorescence, Cracking, Chipping
170	4570	1	2	208		Classroom 208	W3	Chipping	4	N	N	0	N	N	
171	4570	1	2	208		Classroom 208	W4	Cracking	3	N	N	0	N	N	Additional Chipping, Holes
172	4570	1	2	209		Classroom 209	Ceiling	Flaking	21	Y	N	0	N	N	
173	4570	1	2	209		Classroom 209	W1	Flaking	1	N	N	0	N	Y - 7 SF	2 Locations; Additional Cracking, Gouges; Plastering @ Door Frame
174	4570	1	2	209		Classroom 209	W2	Partially Inaccessible	0	N	N	0	Y - 36 SF Desks, Bookcases	N	

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
175	4570	1	2	209		Classroom 209	W3	Flaking	25	N	N	0	N	N	2 Locations; Additional Chipping
176	4570	1	2	209		Classroom 209	W4	Efflorescence	9	Y	N	0	N	N	3 Locations; Additional Chipping
177	4570	1	2	210		Classroom 210	Ceiling	Flaking	13	Y	N	0	N	Y - 12 SF	2 Locations; Additional Efflorescence
178	4570	1	2	210		Classroom 210	W1	Flaking	14	N	N	0	N	Y - 7 SF	Additional Cracking, Chipping
179	4570	1	2	210		Classroom 210	W2	Flaking	5	N	N	0	N	N	Additional Holes
180	4570	1	2	210		Classroom 210	W3	Flaking	10	N	N	0	N	N	Additional Cracking, Chipping
181	4570	1	2	210		Classroom 210	W4	Cracking	20	N	N	0	N	N	Additional Chipping
182	4570	1	2	212		Classroom 212	Ceiling	Holes	1	N	N	0	N	N	
183	4570	1	2	212		Classroom 212	W1	Holes	1	N	N	0	N	N	
184	4570	1	2	212		Classroom 212	W2	Cracking	6	N	N	0	N	N	
185	4570	1	2	212		Classroom 212	W3	Cracking	3	N	N	0	N	N	3 Locations; Additional Chipping
186	4570	2	2	216		Classroom 216	Ceiling	Flaking	5	N	N	0	N	N	
187	4570	2	2	216		Classroom 216	W1	Chipping	2	N	N	0	N	N	Chipping @ Door Frame
188	4570	2	2	216		Classroom 216	W3	Flaking	5	N	N	0	N	Y - 40 SF Posters	Flaking @ Radiator Grate
189	4570	2	2	216		Classroom 216	W4	Cracking	2	N	N	0	N	N	2 Locations; Additional Chipping
190	4570	2	2	217		Classroom 217	Ceiling	Flaking	441	N	N	0	N	N	Additional Cracking
191	4570	2	2	217		Classroom 217	W1	Flaking	4	N	N	0	Y - 72 SF File Cabinets, Contents	N	Additional Cracking
192	4570	2	2	217		Classroom 217	W2	Holes	3	N	N	0	N	N	
193	4570	2	2	217		Classroom 217	W3	Flaking	6	N	N	0	N	N	Additional Cracking, Chipping; Damage @ Radiator, Window Lintel, Pipe
194	4570	2	2	218		Classroom 218	Ceiling	Flaking	148	N	N	0	N	N	
195	4570	2	2	218		Classroom 218	W1	Flaking	16	N	N	0	N	N	Additional Cracking; Damage @ Wall, Door Frame, Shelves
196	4570	2	2	218		Classroom 218	W2	Holes	4	N	N	0	N	N	
197	4570	2	2	218		Classroom 218	W3	Flaking	5	N	N	0	N	N	Locations; Flaking @ Radiator Grate & Wall
198	4570	2	2	218		Classroom 218	W4	Flaking	3	N	N	0	N	N	3 Locations; Additional Cracking
199	4570	1	2	209C		Closet across from Classroom 201	W1	Flaking	4	N	N	0	N	Y - 2 SF	Additional Cracking
200	4570	1	2	209C		Closet across from Classroom 201	W3	Partially Inaccessible	0	N	N	0	Y - 60 SF Contents	N	
201	4570	1	2	209C		Closet across from Classroom 201	W4	Gouges	8	N	N	0	N	N	
202	4570	1	2	208A		Girl's Restroom Across from Classroom 202	Ceiling	Flaking	160	N	N	0	N	N	
203	4570	1	2	208A		Girl's Restroom Across from Classroom 202	W3	Flaking	5	N	N	0	N	N	2 Locations; Additional Chipping; Damage on Radiator & Pipe
204	4570	2	2	215A		Girl's Restroom near Classroom 218	Ceiling	Flaking	70	N	N	0	N	N	Additional Cracking; 2 Locations
205	4570	2	2	215A		Girl's Restroom near Classroom 218	W2	Flaking	24	N	N	0	N	N	Additional Cracking, Chipping
206	4570	2	2	215A		Girl's Restroom near Classroom 218	W3	Flaking	10	N	N	0	N	N	Additional Cracking, Chipping
207	4570	2	2	215A		Girl's Restroom near Classroom 218	W4	Flaking	44	N	N	0	N	N	3 Locations; Additional Cracking Chipping; Damage @ Wall, Radiator & Pipes

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
231	4570	1	2	212C		Staff Restroom in Women's Lounge	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
232	4570	1	2	212C		Staff Restroom in Women's Lounge	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
233	4570	1	2	212C		Staff Restroom in Women's Lounge	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
234	4570	1	2	S23		Stairs across from Classroom 202	Center Banister	Chipping	10	N	N	0	N	N	
235	4570	1	2	S23		Stairs across from Classroom 202	W1	Flaking	3	N	N	0	N	N	Additional Chipping
236	4570	1	2	S23		Stairs across from Classroom 202	W2	Chipping	1	N	N	0	N	N	
237	4570	1	2	S23		Stairs across from Classroom 202	W4	Flaking	1	N	N	0	N	N	Additional Gouges
238	4570	1	2	S24		Stairs Next to Classroom 212	Ceiling	Flaking	10	N	N	0	N	N	Additional Chipping
239	4570	1	2	S24		Stairs Next to Classroom 212	W2	Cracking	5	N	N	0	N	N	2 Locations; Additional Gouges
240	4570	1	2	S24		Stairs Next to Classroom 212	W3	Flaking	8	Y	N	0	N	N	Additional Efflorescence
241	4570	1	2	S24		Stairs Next to Classroom 212	W4	Cracking	8	N	N	0	N	N	Additional Chipping
242	4570	2	2	S27		Stairs Next to Classroom 216	Ceiling	Flaking	48	N	N	0	N	N	Additional Chipping
243	4570	2	2	S27		Stairs Next to Classroom 216	Center Banister	Chipping	22	N	N	0	N	N	
244	4570	2	2	S27		Stairs Next to Classroom 216	Floor	Chipping	12	N	N	0	N	N	
245	4570	2	2	S27		Stairs Next to Classroom 216	W1	Chipping	1	N	N	0	N	N	Chipping @ Door
246	4570	2	2	S27		Stairs Next to Classroom 216	W3	Flaking	26	N	N	0	N	N	Additional Cracking
247	4570	2	2	S27		Stairs Next to Classroom 216	W4	Cracking	4	N	N	0	N	N	
248	4570	2	2	S26		Stairs Next to Classroom 218	Ceiling	Flaking	24	N	N	0	N	N	Additional Cracking; Damage @ Both Landings
249	4570	2	2	S26		Stairs Next to Classroom 218	Center Banister	Chipping	48	N	N	0	N	N	Chipping on Rail & Spindles
250	4570	2	2	S26		Stairs Next to Classroom 218	Floor	Chipping	48	N	N	0	N	N	
251	4570	2	2	S26		Stairs Next to Classroom 218	W1	Flaking	8	N	Y - On Window Sill	1	N	N	Additional Cracking
252	4570	2	2	S26		Stairs Next to Classroom 218	W2	Cracking	18	N	N	0	N	N	Cracking @ Seam Caulk
253	4570	2	2	S26		Stairs Next to Classroom 218	W3	Chipping	2	N	N	0	N	N	
254	4570	2	2	S26		Stairs Next to Classroom 218	W4	Flaking	27	N	N	0	N	N	Additional Cracking, Chipping
255	4570	1	2	205B		Storage Closet in Classroom 205	W3	Flaking	3	N	N	0	N	N	Additional Chipping
256	4570	1	2	209A		Storage Closet next to Classroom 209	Ceiling	Flaking	25	N	N	0	N	N	
257	4570	1	2	209A		Storage Closet next to Classroom 209	W1	Flaking	18	N	N	0	Y - 125 SF Bookcases, Contents	N	Additional Cracking
258	4570	1	2	209A		Storage Closet next to Classroom 209	W2	Flaking	8	N	N	0	Y - 200 SF Bookcases, Contents	N	

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
259	4570	1	2	209A		Storage Closet next to Classroom 209	W3	Flaking	20	N	N	0	Y - 80 SF Bookcases, Contents	N	
260	4570	1	2	209A		Storage Closet next to Classroom 209	W4	Cracking	5	N	N	0	Y - 200 SF Bookcases, Contents	N	
261	4570	1	2	211		Storage Room 211	Ceiling	Flaking	36	Y	N	0	N	Y - 36 SF	Additional Efflorescence
262	4570	1	2	211		Storage Room 211	W1	Flaking	22	N	N	0	N	Y - 2 SF	Additional Cracking, Chipping, Holes; Damage Includes Closet
263	4570	1	2	211		Storage Room 211	W2	Flaking	18	Y	N	0	N	Y - 2 SF	Additional Efflorescence
264	4570	1	2	211		Storage Room 211	W3	Flaking	180	Y	Y - On Window Sills	4	N	Y - 180 SF	Additional Efflorescence; Damage on Entire Wall
265	4570	1	2	211		Storage Room 211	W4	Flaking	18	N	N	0	N	N	Additional Cracking, Chipping
266	4570	1	2	201		Storage Room with Copy Machine	Ceiling	Flaking	128	Y	N	0	N	Y - 1 SF	Additional Efflorescence
267	4570	1	2	201		Storage Room with Copy Machine	W1	Flaking	27	N	N	0	N	N	4 Locations; Additional Cracking, Chipping; Damage Including Door Frame
268	4570	1	2	201		Storage Room with Copy Machine	W2	Flaking	1	N	N	0	N	N	Flaking Above Wooden Doors
269	4570	1	2	201		Storage Room with Copy Machine	W3	Flaking	55	Y	N	0	N	Y - 40 SF	Additional Efflorescence
270	4570	1	2	201		Storage Room with Copy Machine	W4	Flaking	5	N	N	0	N	Y - 1 SF	5 Locations; Additional Chipping
271	4570	2	2	217A		Teacher's Lounge / Restroom next to Classroom 217	Ceiling	Flaking	4	Y	N	0	N	N	Additional Efflorescence
272	4570	2	2	217A		Teacher's Lounge / Restroom next to Classroom 217	W1	Chipping	4	N	N	0	N	N	
273	4570	2	2	217A		Teacher's Lounge / Restroom next to Classroom 217	W3	Partially Inaccessible	0	N	N	0	N	N	
274	4570	2	2	217A		Teacher's Lounge / Restroom next to Classroom 217	W4	Flaking	8	Y	N	0	N	N	
275	4570	1	1	112		Auditorium	Ceiling	Flaking	13	Y	N	0	N	Y - 13 SF	2 Locations; Additional Efflorescence
276	4570	1	1	112		Auditorium	W1	Chipping	12	N	N	0	N	N	Chipping @ Door/Door Frames
277	4570	1	1	112		Auditorium	W2	Chipping	5	N	Y - On Air Shaft	3	N	N	Chipping @ Door Frame
278	4570	1	1	112		Auditorium	W3	Flaking	20	N	N	0	N	N	9 Locations; Additional Chipping
279	4570	1	1	113A		Book Storage Room across from Main Office	W2	Partially Inaccessible	0	N	N	0	Y - 60 SF Contents	N	
280	4570	1	1	113A		Book Storage Room across from Main Office	W3	Partially Inaccessible	0	N	N	0	Y - 60 SF Contents	N	
281	4570	1	1	113A		Book Storage Room across from Main Office	W4	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents	N	
282	4570	1	1	101		Classroom 101	Ceiling	Flaking	336	Y	N	0	N	Y - 4 SF	Additional Efflorescence
283	4570	1	1	101		Classroom 101	W1	Cracking	2	N	N	0	N	N	
284	4570	1	1	101		Classroom 101	W2	Cracking	5	N	N	0	N	N	3 Locations; Additional Chipping
285	4570	1	1	101		Classroom 101	W3	Hipping	3	N	N	0	N	N	3 Locations; Additional Holes, Gouges

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
286	4570	1	1	101		Classroom 101	W4	Cracking	7	N	N	0	N	Y - 1 SF	2 Locations; Additional Holes
287	4570	1	1	102		Classroom 102	Ceiling	Efflorescence	3	Y	N	0	N	N	Damage @ Window 3
288	4570	1	1	102		Classroom 102	W1	Chipping	2	N	N	0	N	N	
289	4570	1	1	102		Classroom 102	W2	Chipping	2	N	N	0	N	N	Chipping @ Corner
290	4570	1	1	102		Classroom 102	W3	Chipping	1	N	N	0	N	N	Chipping on Pipe
291	4570	1	1	103		Classroom 103	Ceiling	Cracking	2	N	N	0	N	N	
292	4570	1	1	103		Classroom 103	W1	Chipping	2	N	N	0	N	N	2 Locations; Damage in Closet
293	4570	1	1	103		Classroom 103	W3	Cracking	2	N	N	0	N	N	2 Locations; Additional Chipping; Damage On Wall & Pipe
294	4570	1	1	105		Classroom 105	Ceiling	Flaking	16	Y	N	0	N	N	Additional Efflorescence
295	4570	1	1	105		Classroom 105	W1	Cracking	11	N	N	0	N	N	4 Locations; Additional Chipping, Holes; Damage @ Door Frame, Corner, Wall, Closet
296	4570	1	1	105		Classroom 105	W2	Cracking	3	N	N	0	N	N	
297	4570	1	1	105		Classroom 105	W3	Flaking	5	N	Y - On Window Sills	3	N	N	Additional Chipping
298	4570	1	1	105		Classroom 105	W4	Cracking	7	N	N	0	N	N	2 Locations
299	4570	1	1	108		Classroom 108	Ceiling	Flaking	430	N	N	0	N	N	
300	4570	1	1	108		Classroom 108	W1	Flaking	32	N	N	0	N	N	Additional Cracking, Chipping
301	4570	1	1	108		Classroom 108	W2	Flaking	7	N	N	0	N	Y - 1 SF	Additional Cracking
302	4570	1	1	108		Classroom 108	W3	Chipping	2	N	N	0	N	N	
303	4570	1	1	108		Classroom 108	W4	Cracking	5	N	N	0	N	N	2 Locations
304	4570	1	1	109		Classroom 109	Ceiling	Flaking	567	N	N	0	N	N	
305	4570	1	1	109		Classroom 109	W1	Flaking	21	N	N	0	N	Y - 4 SF	Additional Cracking, Chipping
306	4570	1	1	109		Classroom 109	W2	Flaking	84	N	N	0	Y - 48 SF Fridge, Contents	N	Additional Chipping
307	4570	1	1	109		Classroom 109	W3	Flaking	210	Y	N	0	N	Y - 12 SF	Additional Efflorescence, Cracking; Damage on Entire Wall
308	4570	1	1	109		Classroom 109	W4	Flaking	16	N	N	0	N	N	Additional Cracking
309	4570	2	1	115		Classroom 115	W3	Flaking	4	N	N	0	N	N	New Paint; Flaking @ Radiator Grates
310	4570	2	1	116		Classroom 116	W3	Flaking	4	N	N	0	N	N	New Paint; Flaking @ Radiator Grates
311	4570	2	1	116A		Classroom 116 Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
312	4570	2	1	116A		Classroom 116 Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
313	4570	2	1	116A		Classroom 116 Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
314	4570	2	1	116A		Classroom 116 Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
315	4570	2	1	116A		Classroom 116 Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
316	4570	2	1	116A		Classroom 116 Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
317	4570	2	1	117		Classroom 117	W3	Flaking	5	N	N	0	N	N	New Paint; Additional Chipping; Damage @ Radiator Grates
318	4570	2	1	118		Classroom 118	Floor	Chipping	6	N	Y - Under Window	1	N	N	
319	4570	2	1	118		Classroom 118	W3	Flaking	4	N	N	0	N	N	Flaking @ Radiator Grates
320	4570	2	1	118A		Classroom 118 Restroom	W4	Chipping	1	N	N	0	N	N	Additional Holes
321	4570	1	1	110C		Clinic Employees' Restroom	W2	Holes	1	N	N	0	N	N	

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
322	4570	1	1	110C		Clinic Employees' Restroom	W3	Cracking	6	N	N	0	N	N	
323	4570	1	1	110C		Clinic Employees' Restroom	W4	Flaking	12	N	N	0	N	N	
324	4570	1	1	110A		Clinic Foyer	W2	Chipping	2	N	N	0	N	N	
325	4570	1	1	110A		Clinic Foyer	W3	Flaking	21	N	N	0	N	N	Additional Chipping; Damage @ Doors
326	4570	1	1	110A		Clinic Foyer	W4	Cracking	5	N	N	0	N	N	
327	4570	1	1	110B		Clinic Hallway	W1	Gouges	3	N	N	0	N	N	
328	4570	1	1	110B		Clinic Hallway	W3	Gouges	1	N	N	0	N	N	
329	4570	1	1	110E		Clinic Kitchen	W1	Partially Inaccessible	0	N	N	0	Y - 42 SF File Cabinets	N	
330	4570	1	1	110E		Clinic Kitchen	W2	Partially Inaccessible	0	N	N	0	Y - 32 SF File Cabinets	N	
331	4570	1	1	110E		Clinic Kitchen	W3	Partially Inaccessible	0	N	N	0	Y - 42 SF File Cabinets	N	
332	4570	1	1	110E		Clinic Kitchen	W4	Partially Inaccessible	0	N	N	0	Y - 32 SF File Cabinets	N	
333	4570	1	1	110		Clinic Lobby	W2	Chipping	7	N	N	0	N	N	Additional Gouges
334	4570	1	1	110		Clinic Lobby	W3	Flaking	8	N	N	0	N	N	2 Locations; Additional Chipping
335	4570	1	1	110		Clinic Lobby	W4	Partially Inaccessible	0	N	N	0	Y - 32 SF Cabinets	N	
336	4570	1	1	110D		Clinic Public Restroom	W2	Flaking	14	N	N	0	N	N	
337	4570	1	1	110K		Clinic Supply Room	W2	Chipping	2	N	N	0	N	N	Additional Gouges
338	4570	1	1	110K		Clinic Supply Room	W3	Partially Inaccessible	0	N	N	0	Y - 18 SF Cleaning Supplies	N	
339	4570	1	1	110I		Employee Lounge	W1	Partially Inaccessible	0	N	N	0	Y - SF Kitchen Appliances	N	
340	4570	1	1	110I		Employee Lounge	W2	Gouges	4	N	N	0	N	N	Additional Holes
341	4570	1	1	110I		Employee Lounge	W3	Gouges	2	N	N	0	N	N	
342	4570	1	1	110I		Employee Lounge	W4	Chipping	4	N	N	0	N	N	
343	4570	1	1	110F		Exam Room #1	W1	Chipping	1	N	N	0	Y - 6 SF Posters	N	
344	4570	1	1	110F		Exam Room #1	W2	Chipping	1	N	N	0	Y - 4 SF Posters	N	
345	4570	1	1	110F		Exam Room #1	W3	Chipping	1	N	N	0	Y - 7 SF Posters	N	
346	4570	1	1	110F		Exam Room #1	W4	Chipping	1	N	N	0	Y - 5 SF Posters	N	
347	4570	1	1	110G		Exam Room #2	W1	Chipping	3	N	N	0	N	N	Additional Gouges
348	4570	1	1	110G		Exam Room #2	W2	Chipping	1	N	N	0	N	N	
349	4570	1	1	110G		Exam Room #2	W3	Chipping	1	N	N	0	N	N	
350	4570	1	1	110H		Exam Room #3	W1	Gouges	2	N	N	0	N	N	Additional Holes
351	4570	1	1	110H		Exam Room #3	W2	Chipping	3	N	N	0	N	N	
352	4570	1	1	110H		Exam Room #3	W3	Chipping	3	N	N	0	N	N	Chipping @ Corner
353	4570	1	1	110M		File Room Behind Front Desk	W1	Partially Inaccessible	0	N	N	0	N	N	
354	4570	1	1	110M		File Room Behind Front Desk	W2	Partially Inaccessible	0	N	N	0	Y - 80 SF Files	N	
355	4570	1	1	110M		File Room Behind Front Desk	W3	Partially Inaccessible	0	N	N	0	Y - 60 SF Files	N	
356	4570	1	1	110M		File Room Behind Front Desk	W4	Partially Inaccessible	0	N	N	0	Y - 80 SF Files	N	

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
357	4570	2	1	H19		Hallway next to Classrooms 115 through 118	W4	Flaking	2	N	N	0	N	N	Flaking @ Radiator Grate
358	4570	1	1	110L		Laboratory	W1	Chipping	1	N	N	0	N	N	
359	4570	1	1	110L		Laboratory	W4	Holes	1	N	N	0	N	N	Suspended Ceiling
360	4570	1	1	113		Large Book Storage Room across from Auditorium	Ceiling	Efflorescence	36	Y	N	0	N	N	
361	4570	1	1	113		Large Book Storage Room across from Auditorium	W1	Holes	2	N	N	0	Y - 144 SF Shelves, Boxes, Contents	N	
362	4570	1	1	113		Large Book Storage Room across from Auditorium	W2	Partially Inaccessible	0	N	N	0	Y - 210 SF Shelves, Boxes, Contents	N	
363	4570	1	1	113		Large Book Storage Room across from Auditorium	W3	Flaking	4	N	N	0	Y - 210 SF Shelves, Boxes, Contents	N	2 Locations; Additional Cracking
364	4570	1	1	113		Large Book Storage Room across from Auditorium	W4	Cracking	3	N	N	0	Y - 180 SF Shelves, Boxes, Contents	N	Additional Chipping
365	4570	1	1	S15		Main Entrance Stair at Main Office	Ceiling	Flaking	12	N	N	0	N	N	
366	4570	1	1	S15		Main Entrance Stair at Main Office	W1	Flaking	7	N	N	0	N	N	
367	4570	1	1	114B		Nurse's Office	W2	Cracking	4	N	N	0	N	N	
368	4570	1	1	114B		Nurse's Office	W3	Flaking	3	N	N	0	N	N	Additional Chipping; Damage On Window Sill & Wall
369	4570	1	1	114C		Nurse's Office Restroom	Ceiling	Flaking	3	N	N	0	N	N	
370	4570	1	1	114C		Nurse's Office Restroom	Floor	Chipping	60	N	N	0	N	N	Chipping @ Perimeter
371	4570	1	1	110J		Office	W4	Chipping	3	N	N	0	N	N	Additional Gouges
372	4570	1	1	107		Parent Resources Room adjacent to Auditorium or Room 107	Ceiling	Flaking	648	Y	N	0	N	N	Additional Efflorescence; Damage on Entire Ceiling
373	4570	1	1	107		Parent Resources Room adjacent to Auditorium or Room 107	W4	Flaking	43	Y	Y - On Moulding	4	N	Y - 8 SF	Additional Efflorescence
374	4570	1	1	107		Parent Resources Room adjacent to Auditorium or Room 107	W1	Flaking	45	Y	N	0	Y - 38 SF Boxes, Contents	Y - 2 SF	Additional Efflorescence, Chipping, Holes
375	4570	1	1	107		Parent Resources Room adjacent to Auditorium or Room 107	W2	Flaking	84	N	N	0	Y - 120 SF Boxes, Posters, Contents	N	
376	4570	1	1	107		Parent Resources Room adjacent to Auditorium or Room 107	W3	Efflorescence	3	Y	Y - On Tables, Desks	4	Y - 96 SF Desks, Tables, Contents	Y - 2 SF	2 Locations; Additional Holes
377	4570	1	1	114A		Principal's Office	Ceiling	Holes	1	N	N	0	N	N	
378	4570	1	1	114A		Principal's Office	W3	Holes	1	N	N	0	N	N	
379	4570	1	1	114A		Principal's Office	W4	Holes	1	N	N	0	N	N	

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
380	4570	1	1	114A		Principal's Office Restroom	Ceiling	Chipping	1	N	N	0	N	N	
381	4570	1	1	114A		Principal's Office Restroom	W1	Holes	1	N	N	0	N	N	
382	4570	1	1	114A		Principal's Office Restroom	W3	Holes	3	N	N	0	N	N	
383	4570	1	1	114A		Principal's Office Storage Closet	W1	Cracking	1	N	N	0	N	N	
384	4570	1	1	114A		Principal's Office Storage Closet	W2	Chipping	1	N	N	0	N	N	
385	4570	1	1	114A		Principal's Office Storage Closet	W3	Partially Inaccessible	0	N	N	0	Y - 32 SF Shelves, Books, Contents	N	
386	4570	1	1	114A		Principal's Office Storage Closet	W4	Chipping	1	N	N	0	N	N	
387	4570	2	1	117B		Restroom next to Classroom 117	Ceiling	Flaking	1	N	N	0	N	N	
388	4570	2	1	117B		Restroom next to Classroom 117	W2	Cracking	3	N	N	0	N	N	
389	4570	2	1	117B		Restroom next to Classroom 117	W3	Flaking	16	N	N	0	N	N	Additional Cracking, Chipping
390	4570	2	1	117B		Restroom next to Classroom 117	W4	Cracking	12	N	N	0	N	N	2 Locations; Additional Chipping; Damage @ Pipes & Seam
391	4570	1	1	113B		Server Room across from Main Office	Ceiling	Flaking	6	N	N	0	N	N	Additional Cracking
392	4570	1	1	113B		Server Room across from Main Office	W2	Partially Inaccessible	0	N	N	0	Y - 60 SF Cables	N	
393	4570	1	1	113B		Server Room across from Main Office	W3	Partially Inaccessible	0	N	N	0	Y - 60 SF Cables	N	
394	4570	1	1	113B		Server Room across from Main Office	W4	Partially Inaccessible	0	N	N	0	Y - 60 SF Cables	N	
395	4570	1	1	S13		Stairs adjacent to Main Office	Center Banister	Chipping	8	N	N	0	N	N	
396	4570	1	1	S13		Stairs adjacent to Main Office	W1	Chipping	1	N	N	0	N	N	Chipping @ Door
397	4570	1	1	S13		Stairs adjacent to Main Office	W2	Gouges	1	N	N	0	N	N	
398	4570	1	1	S13		Stairs adjacent to Main Office	W3	Chipping	1	N	N	0	N	N	Chipping @ Door
399	4570	1	1	S13		Stairs adjacent to Main Office	W4	Flaking	2	N	N	0	N	N	Flaking @ Fiberglass Pipe
400	4570	1	1	S14		Stairs Next to Classroom 109	Ceiling	Flaking	12	N	N	0	N	N	
401	4570	1	1	S14		Stairs Next to Classroom 109	Center Banister	Chipping	2	N	N	0	N	N	
402	4570	1	1	S14		Stairs Next to Classroom 109	W2	Flaking	9	N	N	0	N	N	Additional Cracking, Chipping
403	4570	1	1	S14		Stairs Next to Classroom 109	W3	Flaking	8	N	N	0	N	N	Additional Cracking, Chipping
404	4570	1	1	S14		Stairs Next to Classroom 109	W4	Flaking	15	N	N	0	N	N	Additional Cracking, Chipping, Gouges
405	4570	2	1	S17		Stairs next to Classroom 116	Ceiling	Flaking	12	N	N	0	N	N	Additional Cracking
406	4570	2	1	S17		Stairs next to Classroom 116	Center Banister	Chipping	12	N	N	0	N	N	
407	4570	2	1	S17		Stairs next to Classroom 116	Floor	Chipping	7	N	N	0	N	N	

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
408	4570	2	1	S17		Stairs next to Classroom 116	W1	Flaking	1	N	N	0	N	N	Flaking @ Window Frame
409	4570	2	1	S17		Stairs next to Classroom 116	W2	Flaking	10	N	N	0	N	N	2 Locations; Additional Chipping; Damage on Both Landings
410	4570	2	1	S17		Stairs next to Classroom 116	W3	Chipping	1	N	N	0	N	N	Chipping @ Bottom of Door
411	4570	2	1	S17		Stairs next to Classroom 116	W4	Chipping	3	N	N	0	N	N	
412	4570	2	1	S26		Stairs Next to Classroom 118	Ceiling	Flaking	4	N	N	0	N	N	Additional Cracking
413	4570	2	1	S26		Stairs Next to Classroom 118	W1	Chipping	2	N	N	0	N	N	Chipping @ Door
414	4570	2	1	S26		Stairs Next to Classroom 118	W2	Flaking	14	N	N	0	N	N	Additional Cracking
415	4570	2	1	S26		Stairs Next to Classroom 118	W3	Flaking	10	N	N	0	N	N	
416	4570	2	1	S26		Stairs Next to Classroom 118	W4	Flaking	2	N	N	0	N	N	
417	4570	2	1	S06		Stairs Next to Classroom 15	Ceiling	Flaking	120	N	N	0	N	N	2 Locations; Additional Cracking
418	4570	2	1	117		Stairs Next to Classroom 15	Center Banister	Chipping	12	N	N	0	N	N	
419	4570	2	1	117		Stairs Next to Classroom 15	Floor	Chipping	10	N	N	0	N	N	Chipping @ Steps
420	4570	2	1	S06		Stairs Next to Classroom 15	W1	Flaking	20	N	N	0	N	N	Additional Cracking
421	4570	2	1	S06		Stairs Next to Classroom 15	W2	Flaking	18	N	N	0	N	N	3 Locations; Additional Cracking; Damage On Front & Back Walls and Radiator Grates
422	4570	2	1	S06		Stairs Next to Classroom 15	W3	Chipping	2	N	N	0	N	N	Chipping @ Door
423	4570	2	1	S06		Stairs Next to Classroom 15	W4	Flaking	21	N	N	0	N	N	Additional Cracking
424	4570	2	1	117A		Storage Closet next to Classroom 117	W1	Flaking	5	N	N	0	N	N	Additional Cracking
425	4570	2	1	117A		Storage Closet next to Classroom 117	W2	Partially Inaccessible	0	N	N	0	Y - 80 SF Books, Boxes	N	
426	4570	2	1	117A		Storage Closet next to Classroom 117	W3	Partially Inaccessible	0	N	N	0	Y - 30 SF Books, Boxes	N	
427	4570	1	1	110A		Storage Room across from Classroom 107 and next to Auditorium	Ceiling	Flaking	136	Y	N	0	N	N	Additional Efflorescence
428	4570	1	1	110A		Storage Room across from Classroom 107 and next to Auditorium	W1	Efflorescence	20	Y	N	0	N	N	
429	4570	1	1	110A		Storage Room across from Classroom 107 and next to Auditorium	W2	Flaking	42	Y	N	0	N	N	Additional Efflorescence
430	4570	1	1	110A		Storage Room across from Classroom 107 and next to Auditorium	W3	Flaking	3	Y	N	0	N	N	Additional Efflorescence

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
431	4570	1	1	110A		Storage Room across from Classroom 107 and next to Auditorium	W4	Flaking	48	Y	N	0	Y - 24 SF Cabinets	N	Additional Efflorescence
432	4570	2	1	115B		Storage Room to Right of Classroom 115	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
433	4570	2	1	115B		Storage Room to Right of Classroom 115	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
434	4570	2	1	115B		Storage Room to Right of Classroom 115	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
435	4570	2	1	115B		Storage Room to Right of Classroom 115	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
436	4570	2	1	115B		Storage Room to Right of Classroom 115	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
437	4570	2	1	115B		Storage Room to Right of Classroom 115	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
438	4570	1	1	106A		Women's Lounge on First Floor near Main Office	Ceiling	Flaking	72	Y	N	0	N	N	Additional Efflorescence
439	4570	1	1	106A		Women's Lounge on First Floor near Main Office	W1	Partially Inaccessible	0	N	N	0	Y - 72 SF Lockers	N	
440	4570	1	1	106A		Women's Lounge on First Floor near Main Office	W2	Flaking	3	N	N	0	N	N	Flaking @ Door
441	4570	1	1	106A		Women's Lounge on First Floor near Main Office	W4	Holes	1	N	N	0	N	N	
442	4570	1	1	106B		Women's Staff Restroom in Women's 1st Floor Staff Lounge	Ceiling	Flaking	1	N	N	0	N	N	
443	4570	1	1	106B		Women's Staff Restroom in Women's 1st Floor Staff Lounge	W1	Flaking	10	N	N	0	N	N	Additional Cracking
444	4570	1	1	106B		Women's Staff Restroom in Women's 1st Floor Staff Lounge	W2	Holes	8	N	N	0	N	N	Additional Gouges
445	4570	1	1	106B		Women's Staff Restroom in Women's 1st Floor Staff Lounge	W3	Holes	3	N	N	0	N	N	
446	4570	2	0	H06		Basement Hallway between Classrooms 16 and 15	W1	Holes	1	N	N	0	N	N	
447	4570	2	0	H06		Basement Hallway between Classrooms 16 and 15	W3	Chipping	2	N	N	0	N	N	

Meade -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
448	4570	1	0	H03		Basement Hallway from Boiler Room to Gym	W2	Chipping	1	N	N	0	N	N	Chipping @ Radiator
449	4570	1	0	H01		Basement Hallway from Cafeteria to Gym	W3	Flaking	2	N	N	0	N	N	Additional Chipping; Damage on Doors
450	4570	2	0	22		Boy's Restroom to Left of Classroom 16	Ceiling	Flaking	48	Y	N	0	N	N	Additional Efflorescence, Chipping
451	4570	2	0	22		Boy's Restroom to Left of Classroom 16	W1	Cracking	3	N	N	0	N	N	
452	4570	2	0	22		Boy's Restroom to Left of Classroom 16	W2	Flaking	42	N	N	0	N	N	Additional Cracking
453	4570	2	0	22		Boy's Restroom to Left of Classroom 16	W3	Flaking	1	N	N	0	N	N	Flaking @ Window Frame
454	4570	2	0	22		Boy's Restroom to Left of Classroom 16	W4	Flaking	18	N	N	0	N	N	Additional Chipping
455	4570	1	0	20		Cafeteria	Floor	Chipping	60	N	N	0	N	N	Chipping @ Perimeter
456	4570	1	0	20		Cafeteria	W1	Flaking	110	Y	N	0	N	N	CMU Wall; Additional Efflorescence, Spalling, Chipping
457	4570	1	0	20		Cafeteria	W2	Flaking	70	N	N	0	N	N	CMU Wall; Additional Chipping
458	4570	1	0	20		Cafeteria	W3	Flaking	22	N	N	0	N	N	CMU Wall; Additional Chipping
459	4570	1	0	20		Cafeteria	W4	Flaking	140	N	N	0	N	N	CMU Wall; Additional Cracking, Chipping
460	4570	2	0	15		Classroom 15	W3	Flaking	3	N	N	0	N	N	Flaking @ Radiator Grates
461	4570	2	0	15		Classroom 15	W4	Chipping	2	N	N	0	N	N	
462	4570	2	0	16		Classroom 16	W3	Flaking	3	N	N	0	N	N	Flaking @ Radiator Grates
463	4570	2	0	16		Classroom 16	W3	Flaking	4	N	N	0	N	N	Flaking @ Radiator
464	4570	2	0	16		Classroom 16	W4	Chipping	2	N	N	0	N	N	
465	4570	1	0	18		Closet to Right of Building Engineer's Office	Ceiling	Efflorescence	24	Y	N	0	N	Y - 24 SF	Additional Holes
466	4570	1	0	18		Closet to Right of Building Engineer's Office	W4	Partially Inaccessible	0	N	N	0	Y - 20 SF Boxes, Contents	N	
467	4570	2	0	16C		Corner Kitchen Room to Right of Classroom 16	W1	Cracking	9	N	N	0	N	N	Additional Chipping; Damage @ Door & Wall
468	4570	2	0	16C		Corner Kitchen Room to Right of Classroom 16	W2	Chipping	8	N	N	0	Y - 48 SF Kitchen Appliances	N	
469	4570	2	0	16C		Corner Kitchen Room to Right of Classroom 16	W3	Flaking	4	N	N	0	N	N	
470	4570	2	0	16C		Corner Kitchen Room to Right of Classroom 16	W4	Holes	3	N	N	0	N	N	
471	4570	1	0	13		Former Reading Adjustment Room to Right of Library	Ceiling	Flaking	120	Y	N	0	N	Y - 2 SF	Additional Efflorescence
472	4570	1	0	13		Former Reading Adjustment Room to Right of Library	W1	Flaking	20	N	N	0	N	N	Additional Cracking; Damage On/Behind Pipes
473	4570	1	0	13		Former Reading Adjustment Room to Right of Library	W3	Flaking	6	N	N	0	N	N	
474	4570	1	0	19		Girl's Restroom across from Library	Ceiling	Flaking	12	N	N	0	N	N	4 Locations; Additional Cracking, Chipping

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
475	4570	2	0	21		Girl's Restroom to Left of Classroom 16	Ceiling	Flaking	24	Y	N	0	N	Y	Additional Efflorescence
476	4570	2	0	21		Girl's Restroom to Left of Classroom 16	W1	Chipping	1	N	N	0	N	N	Chipping @ Door Frame
477	4570	2	0	21		Girl's Restroom to Left of Classroom 16	W2	Flaking	4	N	N	0	N	N	2 Locations; Additional Cracking
478	4570	2	0	21		Girl's Restroom to Left of Classroom 16	W3	Flaking	4	N	N	0	N	N	2 Locations; Additional Cracking; Damage @ Wall & Window Frame
479	4570	2	0	21		Girl's Restroom to Left of Classroom 16	W4	Flaking	36	Y	N	0	N	N	Additional Efflorescence; Damage @ Radiator & Wall
480	4570	1	0	9		Gym	Floor	Chipping	30	N	N	0	N	N	Chipping @ Perimeter
481	4570	1	0	9		Gym	W3	Flaking	11	N	N	0	N	N	2 Locations; Additional Chipping; Damage on Pipes & Radiator
482	4570	1	0	8		Gym Storage	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
483	4570	1	0	8		Gym Storage	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
484	4570	1	0	8		Gym Storage	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
485	4570	1	0	8		Gym Storage	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
486	4570	1	0	8		Gym Storage	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
487	4570	1	0	8		Gym Storage	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
488	4570	1	0	20A		Kitchen	Ceiling	Flaking	32	N	N	0	N	N	Additional Chipping
489	4570	1	0	20A		Kitchen	Floor	Chipping	96	N	N	0	N	N	
490	4570	1	0	20A		Kitchen	W2	Flaking	14	N	N	0	N	N	Additional Chipping
491	4570	1	0	20A		Kitchen	W3	Flaking	60	N	N	0	N	N	Additional Chipping
492	4570	1	0	20A		Kitchen	W4	Flaking	32	Y	N	0	N	N	Additional Efflorescence
493	4570	1	0	14		Library	Ceiling	Efflorescence	1	N	N	0	N	N	
494	4570	1	0	14		Library	Floor	Chipping	45	Y	N	0	N	N	
495	4570	1	0	14		Library	W3	Flaking	2	N	N	0	N	N	Additional Chipping
496	4570	2	0	15B		Office Space to Left of Classroom 15	Ceiling	Cracking	1	N	N	0	N	N	
497	4570	2	0	15B		Office Space to Left of Classroom 15	W1	Partially Inaccessible	0	N	N	0	Y - 40 SF Tables, Contents	N	
498	4570	2	0	15B		Office Space to Left of Classroom 15	W2	Cracking	16	N	N	0	N	N	
499	4570	2	0	15B		Office Space to Left of Classroom 15	W3	Cracking	2	N	N	0	N	N	Additional Chipping
500	4570	2	0	15B		Office Space to Left of Classroom 15	W4	Partially Inaccessible	0	N	N	0	Y - 24 SF Contents	N	
501	4570	2	0	16B		Restroom in Basement Corner Kitchen Room	Ceiling	Flaking	3	N	N	0	N	N	Additional Holes; Suspended Ceiling - Missing Ceiling Tile
502	4570	2	0	23		Staff Restroom to Right of Classroom 15	Ceiling	Flaking	12	N	N	0	N	N	
503	4570	2	0	23		Staff Restroom to Right of Classroom 15	W1	Flaking	7	N	N	0	N	N	Additional Cracking; Damage @ Door Frame
504	4570	2	0	23		Staff Restroom to Right of Classroom 15	W2	Flaking	6	N	N	0	N	N	Additional Chipping
505	4570	2	0	23		Staff Restroom to Right of Classroom 15	W3	Chipping	8	N	N	0	N	N	

Meade -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
506	4570	2	0	23		Staff Restroom to Right of Classroom 15	W4	Chipping	9	N	N	0	N	N	
507	4570	1	0	S03		Stairs across from Library	W1	Chipping	2	N	N	0	N	N	Chipping @ Door
508	4570	1	0	S03		Stairs across from Library	W3	Efflorescence	8	Y	N	0	N	N	
509	4570	1	0	S01		Stairs Next to Cafeteria	W4	Chipping	3	N	N	0	N	N	Chipping @ Brick Skirt
510	4570	2	0	S07		Stairs to Left of Classroom 15	Ceiling	Flaking	16	N	N	0	N	N	2 Locations; Additional Chipping
511	4570	2	0	S07		Stairs to Left of Classroom 15	Center Banister	Chipping	12	N	N	0	N	N	
512	4570	2	0	S07		Stairs to Left of Classroom 15	Floor	Chipping	14	N	N	0	N	N	
513	4570	2	0	S07		Stairs to Left of Classroom 15	W2	Flaking	46	Y	N	0	N	N	Additional Efflorescence, Chipping
514	4570	2	0	S07		Stairs to Left of Classroom 15	W3	Chipping	1	N	N	0	N	N	Chipping @ Door
515	4570	2	0	S07		Stairs to Left of Classroom 15	W4	Cracking	8	N	N	0	N	N	Additional Chipping; Damage @ Wall & Door