

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	4020	1	5	503A		Classroom 502, Closet at Top of Risers	W1	No Access						Inspection Needed	
2	4020	1	5	503A		Classroom 502, Closet at Top of Risers	W2	No Access						Inspection Needed	
3	4020	1	5	500		Classroom 502, Closet at Top of Risers	W3	No Access						Inspection Needed	
4	4020	1	5	500		Classroom 502, Closet at Top of Risers	W4	No Access						Inspection Needed	
5	4020	1	5	501A		Classroom 502, Closet to Left of Blackboard	Ceiling	Peeling paint	100	No	None	N/A	None	No	
6	4020	1	5	522A		Classroom 502, Closet to Left of Blackboard	Floor	Debris on floor and books	100	No	Books	100		No	
7	4020	1	5	501B		Classroom 502, Closet to Left of Blackboard	W1	Cracking paint	60	No	None	N/A	None	No	
8	4020	1	5	502		Classroom 502, Closet to Left of Blackboard	W2	Peeling paint and efflorescence on wall and peeling paint on pipe	100	No	None	N/A	None	No	
9	4020	1	5	502		Classroom 502, Closet to Left of Blackboard	W3	Peeling paint and efflorescence	80	No	None	N/A	None	No	
10	4020	1	5	502		Classroom 502, Closet to Left of Blackboard	W4	Cracking paint	20	No	None	N/A	None	No	
11	4020	1	5	502		Classroom 502, Closet to Right of Blackboard	Ceiling	Severe peeling paint	20	No	None	N/A	None	No	
12	4020	1	5	502		Classroom 502, Closet to Right of Blackboard	Floor	Debris	30	No	Debris	N/A	None	No	
13	4020	1	5	502		Classroom 502, Closet to Right of Blackboard	W1	Cracking paint	5	No	None	N/A	None	No	
14	4020	1	5	530		Classroom 502, Closet to Right of Blackboard	W3	Peeling paint	50	No	None	N/A	None	No	
15	4020	1	5	530		Classroom 502, Closet to Right of Blackboard	W4	Peeling and cracking paint	20	No	None	N/A	None	No	
16	4020	1	5	530		Classroom 505	W1	Damaged plaster/Crack	10	No	None	N/A	None	Yes	
17	4020	1	5	530		Classroom 505	W3	Damaged plaster	5	No	None	N/A	None	Yes	
18	4020	1	5	530		Classroom 506	W1	Damaged plaster and peeling paint	20	No	None	N/A	None	Yes	
19	4020	1	5	530		Classroom 506	W3	Damaged plaster and peeling paint	20	No	None	N/A	None	Yes	
20	4020	1	5	521A		Classroom 507	Ceiling	No Access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
21	4020	1	5	521A		Classroom 507	Floor	No Access						Inspection Needed	
22	4020	1	5	521A		Classroom 507	W1	No Access						Inspection Needed	
23	4020	1	5	521A		Classroom 507	W2	No Access						Inspection Needed	
24	4020	1	5	521A		Classroom 507	W3	No Access						Inspection Needed	
25	4020	1	5	521A		Classroom 507	W4	No Access						Inspection Needed	
26	4020	1	5	521B		Classroom 508	Ceiling	No Access						Inspection Needed	
27	4020	1	5	521B		Classroom 508	Floor	No Access						Inspection Needed	
28	4020	1	5	521B		Classroom 508	W1	No Access						Inspection Needed	
29	4020	1	5	521B		Classroom 508	W2	No Access						Inspection Needed	
30	4020	1	5	521B		Classroom 508	W3	No Access						Inspection Needed	
31	4020	1	5	505		Classroom 508	W4	No Access						Inspection Needed	
32	4020	1	5	505		Classroom 509	Ceiling	No Access						Inspection Needed	
33	4020	1	5	506		Classroom 509	Floor	No Access						Inspection Needed	
34	4020	1	5	506		Classroom 509	W1	No Access						Inspection Needed	
35	4020	1	5	507		Classroom 509	W2	No Access						Inspection Needed	
36	4020	1	5	507		Classroom 509	W3	No Access						Inspection Needed	
37	4020	1	5	507		Classroom 509	W4	No Access						Inspection Needed	
38	4020	1	5	507		Classroom 510	Floor	Debris	20	No	Debris	N/A	None	No	
39	4020	1	5	507		Classroom 510	W1	Severe peeling paint, cracking and flaking paint	35	No	None	N/A	None	No	
40	4020	1	5	507		Classroom 510	W3	Holes in plaster wall	10	No	None	N/A	None	Yes	
41	4020	1	5	508		Classroom 511	W3	Severe crack in the plaster wall	25	No	None	N/A	None	Yes	
42	4020	1	5	508		Classroom 512	Ceiling	Peeling paint	25	No	None	N/A	None	No	
43	4020	1	5	508		Classroom 512	Floor	Debris	10	No	Debris	N/A	None	No	
44	4020	1	5	508		Classroom 512	W1	Crack in plaster wall	10	No	None	N/A	None	Yes	
45	4020	1	5	508		Classroom 512	W2	Peeling and flaking paint	100	No	None	N/A	None	No	
46	4020	1	5	508		Classroom 512	W3	Damaged plaster	20	No	None	N/A	None	Yes	
47	4020	1	5	509		Classroom 512	W4	Peeling and cracking paint	15	No	None	N/A	None	No	
48	4020	1	5	509		Classroom 513	Ceiling	Peeling paint	20	No	None	N/A	None	No	
49	4020	1	5	509		Classroom 513	Floor	Debris	20	No	Debris	N/A	None	No	
50	4020	1	5	509		Classroom 513	W1	Crack in plaster wall	10	No	None	N/A	None	Yes	
51	4020	1	5	509		Classroom 513	W2	Peeling paint	20	No	None	N/A	None	No	
52	4020	1	5	509		Classroom 513	W3	Severe peeling and flaking paint	40	No	None	N/A	None	No	
53	4020	1	5	510		Classroom 514	Ceiling	Peeling paint	20	No	None	N/A	None	No	
54	4020	1	5	510		Classroom 514	Floor	Debris	10	No	Debris	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
55	4020	1	5	510		Classroom 514	W1	Peeling paint on wall and pipe	20	No	None	N/A	None	No	
56	4020	1	5	511		Classroom 514	W2	Cracking paint	5	No	None	N/A	None	No	
57	4020	1	5	512		Classroom 514	W3	Damaged plaster, efflorescence, debris on window sill	50	No	Window sill	10	None	Yes	
58	4020	1	5	512		Classroom 515	Ceiling	Peeling paint along window wall	20	No	None	N/A	None	No	
59	4020	1	5	512		Classroom 515	Floor	Debris	30	No	Debris	N/A	None	No	
60	4020	1	5	512		Classroom 515	W1	Cracking paint	20	No	None	N/A	None	No	
61	4020	1	5	512		Classroom 515	W2	Peeling paint by window	20	No	None	N/A	None	No	
62	4020	1	5	512		Classroom 515	W3	Severe peeling paint and efflorescence	60	No	None	N/A	None	No	
63	4020	1	5	513		Classroom 516	Floor	Peeling paint	5	No	None	N/A	None	No	
64	4020	1	5	513		Classroom 516	W1	Damaged plaster	3	No	None	N/A	None	Yes	
65	4020	1	5	513		Classroom 516	W2	Peeling paint	10	No	None	N/A	None	No	
66	4020	1	5	513		Classroom 516	W3	Peeling paint	10	No	None	N/A	None	No	
67	4020	1	5	513		Classroom 516	W4	Severe peeling paint and efflorescence	100	No	None	N/A	None	No	
68	4020	1	5	514		Classroom 517	W1	Hole in plaster wall	2	No	None	N/A	None	Yes	
69	4020	1	5	514		Classroom 517	W3	Peeling paint	10	No	None	N/A	None	No	
70	4020	1	5	514		Classroom 518	W1	Hole in plaster wall	1	No	None	N/A	None	Yes	
71	4020	1	5	514		Classroom 519	Floor	Debris by window	2	No	Debris	N/A	None	No	
72	4020	1	5	514		Classroom 519	W1	Hole in plaster wall at electrical box	1	No	None	N/A	None	Yes	
73	4020	1	5	515		Classroom 519	W3	Peeling paint	10	No	None	N/A	None	No	
74	4020	1	5	515		Classroom 520	W1	Hole in plaster wall	1	No	None	N/A	None	Yes	
75	4020	1	5	515		Classroom 520	W3	Peeling paint	5	No	None	N/A	None	No	
76	4020	1	5	515		Classroom 521	W1	Hole in plaster wall at electrical box	1	No	None	N/A	None	Yes	
77	4020	1	5	515		Classroom 521	W3	Peeling paint	5	No	None	N/A	None	No	
78	4020	1	5	516		Closet inside Storage Room with Double Doors inside Classroom 500	Ceiling	Peeling paint at ductwork	10	No	None	N/A	None	No	
79	4020	1	5	516		Closet inside Storage Room with Double Doors inside Classroom 500	Floor	Debris	20	No	Debris	N/A	None	No	
80	4020	1	5	516		Closet inside Storage Room with Double Doors inside Classroom 500	W1	Severe peeling paint at column	40	No	None	N/A	None	No	
81	4020	1	5	516		Closet inside Storage Room with Double Doors inside Classroom 500	W3	Peeling paint	5	No	None	N/A	None	No	
82	4020	1	5	516		Director's Room	Ceiling	Peeling paint and efflorescence	50	No	None	N/A	None	No	
83	4020	1	5	517		Director's Room	Floor	Debris	50	No	Debris	N/A	None	No	
84	4020	1	5	517		Director's Room	W1	Cracking paint	5	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
85	4020	1	5	518		Director's Room	W2	Peeling paint and efflorescence	30	No	None	N/A	None	No	
86	4020	1	5	519		Director's Room	W3	Peeling paint and efflorescence	50	No	None	N/A	None	No	
87	4020	1	5	519		Director's Room	W4	Peeling paint	20	No	None	N/A	None	No	
88	4020	1	5	519		Fire Tower near Classroom 511	Ceiling	No Access						Inspection Needed	
89	4020	1	5	520		Fire Tower near Classroom 511	Floor	No Access						Inspection Needed	
90	4020	1	5	520		Fire Tower near Classroom 511	W1	No Access						Inspection Needed	
91	4020	1	5	521		Fire Tower near Classroom 511	W2	No Access						Inspection Needed	
92	4020	1	5	521		Fire Tower near Classroom 511	W3	No Access						Inspection Needed	
93	4020	1	5	522A		Fire Tower near Classroom 511	W4	No Access						Inspection Needed	
94	4020	1	5	522A		Girl's Restroom	W2	Peeling paint	3	No	None	N/A	None	No	
95	4020	1	5	522A		Girl's Restroom	W3	Peeling paint	3	No	None	N/A	None	No	
96	4020	1	5	522A		Girl's Restroom	W4	Peeling paint	20	No	None	N/A	None	No	
97	4020	1	5	515A		Half Door by Stairs in Hallway near Classroom 501	Ceiling	No Access						Inspection Needed	
98	4020	1	5	515A		Half Door by Stairs in Hallway near Classroom 501	Floor	No Access						Inspection Needed	
99	4020	1	5	515A		Half Door by Stairs in Hallway near Classroom 501	W1	No Access						Inspection Needed	
100	4020	1	5	515A		Half Door by Stairs in Hallway near Classroom 501	W2	No Access						Inspection Needed	
101	4020	1	5	515A		Half Door by Stairs in Hallway near Classroom 501	W3	No Access						Inspection Needed	
102	4020	1	5	515A		Half Door by Stairs in Hallway near Classroom 501	W4	No Access						Inspection Needed	
103	4020	1	5	S55		Half Door by Stairs in Hallway near Classroom 504	Ceiling	No Access						Inspection Needed	
104	4020	1	5	S55		Half Door by Stairs in Hallway near Classroom 504	Floor	No Access						Inspection Needed	
105	4020	1	5	S55		Half Door by Stairs in Hallway near Classroom 504	W1	No Access						Inspection Needed	
106	4020	1	5	S55		Half Door by Stairs in Hallway near Classroom 504	W2	No Access						Inspection Needed	
107	4020	1	5	S55		Half Door by Stairs in Hallway near Classroom 504	W3	No Access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
108	4020	1	5	S55		Half Door by Stairs in Hallway near Classroom 504	W4	No Access						Inspection Needed	
109	4020	1	5	527A		Hallway between Classroom 517 and Stairwell	W1	Damaged plaster	10	No	None	N/A	None	Yes	
110	4020	1	5	527A		Hallway between Classroom 517 and Stairwell	W2	Peeling and cracking paint	10	No	None	N/A	None	No	
111	4020	1	5	527A		Hallway From Classroom 511 to Stairwell near Classroom 511	W2	Damaged plaster	5	No	None	N/A	None	Yes	
112	4020	1	5	502C		Hallway From Classroom 511 to Stairwell near Classroom 511	W4	Damaged plaster	6	No	None	N/A	None	Yes	
113	4020	1	5	502C		Hallway leading from Fan Room towards Classroom 511	Ceiling	Damaged plaster and efflorescence	30	No	None	N/A	None	Yes	
114	4020	1	5	502C		Hallway leading from Fan Room towards Classroom 511	Floor	Debris	80	No	Debris	N/A	None	No	
115	4020	1	5	502C		Hallway leading from Fan Room towards Classroom 511	W2	Severe peeling paint, efflorescence at stairs	10	No	None	N/A	None	No	
116	4020	1	5	502C		Hallway leading from Fan Room towards Classroom 511	W4	Severe peeling paint, efflorescence at stairs	30	No	None	N/A	None	No	
117	4020	1	5	502C		Hallway outside Classroom 502	Ceiling	Severe peeling paint	20	No	None	N/A	None	No	
118	4020	1	5	515B		Hallway outside Classroom 502	Floor	Debris	30	No	Debris	N/A	None	No	
119	4020	1	5	515B		Hallway outside Classroom 502	W2	Peeling paint	10	No	None	N/A	None	No	
120	4020	1	5	515B		Hallway outside Classroom 502	W4	Severe peeling paint	40	No	None	N/A	None	No	
121	4020	1	5	515B		Hallway outside Classroom 502, Janitorial Room Storage	Ceiling	No Access						Inspection Needed	
122	4020	1	5	515B		Hallway outside Classroom 502, Janitorial Room Storage	Floor	No Access						Inspection Needed	
123	4020	1	5	515B		Hallway outside Classroom 502, Janitorial Room Storage	W1	No Access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
124	4020	1	5	H509		Hallway outside Classroom 502, Janitorial Room Storage	W2	No Access						Inspection Needed	
125	4020	1	5	H509		Hallway outside Classroom 502, Janitorial Room Storage	W3	No Access						Inspection Needed	
126	4020	1	5	H505		Hallway outside Classroom 502, Janitorial Room Storage	W4	No Access						Inspection Needed	
127	4020	1	5	H505		Hallway outside Classrooms 500-501	Floor	Debris	5	No	Debris	N/A	None	No	
128	4020	1	5	H507		Hallway outside Classrooms 500-501	W2	Damaged plaster	20	No	None	N/A	None	Yes	
129	4020	1	5	H507		Hallway outside Classrooms 500-501	W4	Peeling paint on wall at windows	35	No	None	N/A	None	No	
130	4020	1	5	H507		Hallway outside Classrooms 504-505	W2	Peeling paint (includes walways to classrooms)	50	No	None	N/A	None	No	
131	4020	1	5	H507		Hallway outside Classrooms 504-505	W4	Peeling paint (includes windows)	50	No	None	N/A	None	No	
132	4020	1	5	H501		Hallway outside Classrooms 506-511	W2	Damaged plaster and peeling paint	20	No	None	N/A	None	Yes	
133	4020	1	5	H501		Hallway outside Classrooms 506-511	W4	Damaged plaster and peeling paint	50	No	None	N/A	None	Yes	
134	4020	1	5	H501		Hallway outside Classrooms 512-516	Ceiling	Peeling paint	20	No	None	N/A	None	No	
135	4020	1	5	H501		Hallway outside Classrooms 512-516	W2	Peeling and cracking paint	20	No	None	N/A	None	No	
136	4020	1	5	502B		Hallway outside Classrooms 512-516	W4	Peeling and cracking paint	20	No	None	N/A	None	No	
137	4020	1	5	502B		Hallway outside Classrooms 517-522	W2	Peeling paint	5	No	None	N/A	None	No	
138	4020	1	5	502B		Hallway outside Classrooms 517-522	W4	Peeling paint	5	No	None	N/A	None	No	
139	4020	1	5	502B		Large Practice Room near Classroom 505 Entrance closest to Classroom 504	W1	Peeling paint on wall near floor	10	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
140	4020	1	5	502B		Large Practice Room near Classroom 505 Entrance closest to Classroom 504	W2	Peeling paint on wall near floor	5	No	None	N/A	None	No	
141	4020	1	5	502B		Large Practice Room near Classroom 505 Entrance closest to Classroom 504	W3	Peeling paint on wall near floor	10	No	None	N/A	None	No	
142	4020	1	5	H500		Large Practice Room near Classroom 505 Entrance closest to Classroom 504	W4	Peeling paint on wall near floor	5	No	None	N/A	None	No	
143	4020	1	5	H500		Left Practice Room outside Classroom 505 Entrance closest to Classroom 506	Floor	Debris	5	No	Debris	N/A	None	No	
144	4020	1	5	H500		Left Practice Room outside Classroom 505 Entrance closest to Classroom 506	W3	Peeling paint and efflorescence	30	No	None	N/A	None	No	
145	4020	1	5	H502		Men's Restroom	Ceiling	Damaged plaster	10	No	None	N/A	None	Yes	
146	4020	1	5	H502		Men's Restroom	Floor	Debris	30	No	Debris	N/A	None	No	
147	4020	1	5	H504		Practice Room across from Classroom 516	W1	Debris	30	No	Debris	N/A	None	No	
148	4020	1	5	H504		Practice Room across from Classroom 516	W2	Peeling paint	5	No	None	N/A	None	No	
149	4020	1	5	H56		Practice Room across from Classroom 516	W3	Peeling paint	10	No	None	N/A	None	No	
150	4020	1	5	H56		Practice Room across from Classroom 516	W4	Damaged plaster above window and debris on window sill	30	No	Window Sill	10	None	Yes	
151	4020	1	5	H56		Practice Room adjacent to Classroom 504	Floor	Debris	10	Yes (appears to be leak from drain pipe)	Debris	10			
152	4020	1	5	H506		Practice Room adjacent to Classroom 504	W3	Severe peeling paint and efflorescence	40	No	None	N/A	None	No	
153	4020	1	5	H506		Practice Room adjacent to Classroom 504	W4	Severe peeling paint and efflorescence	40	No	None	N/A	None	No	
154	4020	1	5	511A		Prep Room between Classrooms 512 and 514	Ceiling	Damaged plaster, efflorescence, peeling paint	80	No	None	N/A	None	Yes	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
155	4020	1	5	511A		Prep Room between Classrooms 512 and 514	Floor	Debris	100	No	Debris	N/A	None	No	
156	4020	1	5	511A		Prep Room between Classrooms 512 and 514	W1	Severe peeling and flaking paint	100	No	None	N/A	None	No	
157	4020	1	5	511A		Prep Room between Classrooms 512 and 514	W4	Peeling paint on pipe	15	No	None	N/A	None	No	
158	4020	1	5	505A		Prep Room between Classrooms 513 and 515	W2	Peeling paint on pipe	15	No	None	N/A	None	No	
159	4020	1	5	505A		Small Practice Room near Classroom 505 Entrance closest to Classroom 504	W1	Peeling paint on wall near floor	5	No	None	N/A	None	No	
160	4020	1	5	514A		Small Practice Room near Classroom 505 Entrance closest to Classroom 504	W2	Peeling paint on wall near floor	8	No	None	N/A	None	No	
161	4020	1	5	514A		Small Practice Room near Classroom 505 Entrance closest to Classroom 504	W3	Damaged plaster	20	No	None	N/A	None	Yes	
162	4020	1	5	521C		Small Practice Room near Classroom 505 Entrance closest to Classroom 504	W4	Damaged plaster	2	No	None	N/A	None	Yes	
163	4020	1	5	521C		Stairwell adjacent Classroom 512	W2	Peeling paint	5	No	None	N/A	None	No	
164	4020	1	5	521C		Stairwell adjacent Classroom 512	W4	Peeling paint	5	No	None	N/A	None	No	
165	4020	1	5	521C		Stairwell near Classroom 500	W1	Damaged Plaster	20	No	None	N/A	None	Yes	
166	4020	1	5	513A		Stairwell near Classroom 500	W2	Peeling paint at window	10	No	None	N/A	None	No	
167	4020	1	5	513A		Stairwell near Classroom 505	Floor	Debris	5	No	Debris	N/A	None	No	
168	4020	1	5	513A		Stairwell near Classroom 505	W1	Cracking paint	3	No	None	N/A	None	No	
169	4020	1	5	517A		Stairwell near Classroom 505	W3	Cracking paint	3	No	None	N/A	None	No	
170	4020	1	5	517A		Stairwell near Classroom 505	W4	Peeling paint, efflorescence and debris on window sills	12	No	Window sills	8	None	No	
171	4020	1	5	517A		Stairwell near Classroom 511	Floor	Debris	10	No	Debris	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
172	4020	1	5	517A		Stairwell near Classroom 511	W1	Damaged plaster	20	No	None	N/A	None	Yes	
173	4020	1	5	516A		Stairwell near Classroom 511	W2	Damaged plaster and cracking paint	30	No	None	N/A	None	Yes	
174	4020	1	5	512A		Stairwell near Classroom 511	W3	Damaged plaster	10	No	None	N/A	None	Yes	
175	4020	1	5	512A		Stairwell near Classroom 516	Ceiling	Damaged plaster	30	No	None	N/A	None	Yes	
176	4020	1	5	512A		Stairwell near Classroom 516	Floor	Debris	30	No	Debris	N/A	None	No	
177	4020	1	5	512A		Stairwell near Classroom 516	W2	Peeling paint	30	No	None	N/A	None	No	
178	4020	1	5	S59		Stairwell near Classroom 516	W3	Peeling paint	30	No	None	N/A	None	No	
179	4020	1	5	S59		Stairwell near Classroom 516	W4	Peeling paint	30	No	None	N/A	None	No	
180	4020	1	5	S52		Stairwell near Classroom 517	Ceiling	Hole in plaster wall	2	No	None	N/A	None	Yes	
181	4020	1	5	S52		Stairwell near Classroom 517	Floor	Debris	10	No	Debris	N/A	None	No	
182	4020	1	5	S51		Stairwell near Classroom 517	W1	Damaged plaster	20	No	None	N/A	None	Yes	
183	4020	1	5	S51		Stairwell near Classroom 517	W2	Damaged plaster	30	No	None	N/A	None	Yes	
184	4020	1	5	S51		Stairwell near Classroom 517	W3	Cracking paint	10	No	None	N/A	None	No	
185	4020	1	5	S51		Stairwell near Classroom 517	W4	Peeling and flaking paint	10	No	None	N/A	None	No	
186	4020	1	5	S50		Storage Room Connected to Classroom 513, Prep Room between Classrooms 513 and 515, and Classroom 515	W1	Peeling paint	10	No	None	N/A	None	No	
187	4020	1	5	S50		Storage Room Connected to Classroom 513, Prep Room between Classrooms 513 and 515, and Classroom 515	W3	Peeling paint	10	No	None	N/A	None	No	
188	4020	1	5	S50		Storage Room Connected to Prep Room between Classrooms 512 and 514	Ceiling	Holes in plaster ceiling	5	No	None	N/A	None	Yes	
189	4020	1	5	S50		Storage Room Connected to Prep Room between Classrooms 512 and 514	W1	Peeling paint, crack in plaster wall	30	No	None	N/A	None	Yes	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
190	4020	1	5	S58		Storage Room Connected to Prep Room between Classrooms 512 and 514	W2	Peeling paint	10	No	None	N/A	None	No	
191	4020	1	5	S58		Storage Room Connected to Prep Room between Classrooms 512 and 514	W4	Peeling paint	10	No	None	N/A	None	No	
192	4020	1	5	S58		Storage Room Connected to Prep Room between Classrooms 513 and 515	Ceiling	No Access						Inspection Needed	
193	4020	1	5	S58		Storage Room Connected to Prep Room between Classrooms 513 and 515	Floor	No Access						Inspection Needed	
194	4020	1	5	S58		Storage Room Connected to Prep Room between Classrooms 513 and 515	W1	No Access						Inspection Needed	
195	4020	1	5	S53		Storage Room Connected to Prep Room between Classrooms 513 and 515	W2	No Access						Inspection Needed	
196	4020	1	5	S53		Storage Room Connected to Prep Room between Classrooms 513 and 515	W3	No Access						Inspection Needed	
197	4020	1	5	S53		Storage Room Connected to Prep Room between Classrooms 513 and 515	W4	No Access						Inspection Needed	
198	4020	1	5	S53		Storage Room in Stairwell near Classroom 500	W1	Peeling paint	2	No	None	N/A	None	No	
199	4020	1	5	S53		Storage Room in Stairwell near Classroom 500	W3	Peeling paint	5	No	None	N/A	None	No	
200	4020	1	5	S53		Storage Room in Stairwell near Classroom 500	W4	Peeling paint	2	No	None	N/A	None	No	
201	4020	1	5	513B		Women's Restroom	W4	Damaged plaster at door	12	No	None	N/A	None	Yes	
202	4020	1	5	513B		Boy's Restroom, Labeled Men's Restroom	W2	Efflorescence	8	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
203	4020	1	5	517B		Clasroom 416	Ceiling	Peeling paint	3	No	None	N/A	None	No	
204	4020	1	5	517B		Clasroom 416	W1	Peeling paint	5	No	None	N/A	None	No	
205	4020	1	5	517B		Clasroom 416	W2	Peeling paint	5	No	None	N/A	None	No	
206	4020	1	5	517B		Clasroom 416	W3	Peeling paint	5	No	None	N/A	None	No	
207	4020	1	5	516B		Classroom 400	W1	Peeling paint	2	No	None	N/A	None	No	
208	4020	1	5	516B		Classroom 400	W2	Peeling paint	5	No	None	N/A	None	No	
209	4020	1	5	516B		Classroom 400	W3	Peeling and Cracking paint on wall and pipe	40	No	None	N/A	None	No	
210	4020	1	5	516B		Classroom 401	Ceiling	Damaged plaster, Cracking paint, and efflorescence	120	No	None	N/A	None	Yes	
211	4020	1	5	516B		Classroom 401	Floor	Debris on floor and desks	100	No	Desks	20	None	No	
212	4020	1	5	516B		Classroom 401	W1	Severe peeling paint	25	No	None	N/A	None	No	
213	4020	1	5	523A		Classroom 401	W2	Peeling paint	10	No	None	N/A	None	No	
214	4020	1	5	523A		Classroom 401	W3	Severe peeling paint, cracking paint, and efflorescence	50	No	None	N/A	None	No	
215	4020	1	5	523A		Classroom 401	W4	Cracking paint	10	No	None	N/A	None	No	
216	4020	1	5	501C		Classroom 402	Ceiling	Peeling paint and efflorescence	10	No	None	N/A	None	No	
217	4020	1	4	413C		Classroom 402	Floor	Debris	10	No	Debris	N/A	None	No	
218	4020	1	4	416		Classroom 402	W1	Peeling and Cracking paint	20	No	None	N/A	None	No	
219	4020	1	4	416		Classroom 402	W3	Peeling paint on pipes, Cracking paint	30	No	None	N/A	None	No	
220	4020	1	4	416		Classroom 402	W4	Damaged plaster and cracking paint	10	No	None	N/A	None	Yes	
221	4020	1	4	416		Classroom 403	Ceiling	No Access						Inspection Needed	
222	4020	1	4	400		Classroom 403	Floor	No Access						Inspection Needed	
223	4020	1	4	400		Classroom 403	W1	No Access						Inspection Needed	
224	4020	1	4	400		Classroom 403	W2	No Access						Inspection Needed	
225	4020	1	4	401		Classroom 403	W3	No Access						Inspection Needed	
226	4020	1	4	401		Classroom 403	W4	No Access						Inspection Needed	
227	4020	1	4	401		Classroom 405	Ceiling	Peeling paint	20	No	None	N/A	None	No	
228	4020	1	4	401		Classroom 405	Floor	Debris on floor by door	6	No	Debris	N/A	None	No	
229	4020	1	4	401		Classroom 405	W1	Peeling and cracking paint	10	No	None	N/A	None	No	
230	4020	1	4	401		Classroom 405	W2	Peeling paint	5	No	None	N/A	None	No	
231	4020	1	4	402		Classroom 405	W3	Peeling paint and efflorescence	50	No	None	N/A	None	No	
232	4020	1	4	402		Classroom 405	W4	Peeling paint	5	No	None	N/A	None	No	
233	4020	1	4	402		Classroom 406	Ceiling	Peeling paint and efflorescence	10	No	None	N/A	None	No	
234	4020	1	4	402		Classroom 406	Floor	Debris on floor and chairs	20		Chairs	10			
235	4020	1	4	402		Classroom 406	W1	Spalling paint	10	No	None	N/A	None	No	
236	4020	1	4	403		Classroom 406	W3	Peeling paint on wall and pipes, Efflorescence, debris on window sill	50		Window Sill	5		No	
237	4020	1	4	403		Classroom 407	Ceiling	Peeling paint at left corner	6	No	None	N/A	None	No	
238	4020	1	4	403		Classroom 407	W1	Peeling paint	10	No	None	N/A	None	No	
239	4020	1	4	403		Classroom 407	W2	Damaged plaster and peeling paint at column	6	No	None	N/A	None	Yes	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
240	4020	1	4	403		Classroom 407	W3	Peeling and cracking paint	10	No	None	N/A	None	No	
241	4020	1	4	403		Classroom 407	W4	Peeling paint and efflorescence at window	30	No	None	N/A	None	No	
242	4020	1	4	405		Classroom 409	Ceiling	Peeling paint by windows	16	No	None	N/A	None	No	
243	4020	1	4	405		Classroom 409	W3	Peeling paint on wall and pipes, efflorescence	75	No	None	N/A	None	No	
244	4020	1	4	405		Classroom 410	W1	Peeling paint	2	No	None	N/A	None	No	
245	4020	1	4	405		Classroom 410	W3	Severe peeling paint, efflorescence on wall and column	30	No	None	N/A	None	No	
246	4020	1	4	405		Classroom 410	W4	Peeling paint	2	No	None	N/A	None	No	
247	4020	1	4	405		Classroom 412	Floor	Debris by window	6	No	Debris	N/A	None	No	
248	4020	1	4	406		Classroom 412	W3	Peeling paint and efflorescence	30	No	None	N/A	None	No	
249	4020	1	4	406		Classroom 414	Floor	Debris at window	4	No	Debris	N/A	None	No	
250	4020	1	4	406		Classroom 414	W1	Peeling paint	5	No	None	N/A	None	No	
251	4020	1	4	406		Classroom 414	W2	Peeling paint	10	No	None	N/A	None	No	
252	4020	1	4	407		Classroom 414	W3	Peeling paint, efflorescence and debris	50	No	None	N/A	None	No	
253	4020	1	4	407		Classroom 414 Dark Room	Ceiling	Peeling paint	20	No	None	N/A	None	No	
254	4020	1	4	407		Classroom 414 Dark Room	Floor	Debris	5	No	Debris	N/A	None	No	
255	4020	1	4	407		Classroom 414 Dark Room	W1	Peeling paint	10	No	None	N/A	None	No	
256	4020	1	4	407		Classroom 414 Dark Room	W2	Peeling paint	10	No	None	N/A	None	No	
257	4020	1	4	409		Classroom 415	W1	Peeling paint	10	No	None	N/A	None	No	
258	4020	1	4	409		Classroom 415	W2	Peeling paint	2	No	None	N/A	None	No	
259	4020	1	4	410		Classroom 415	W3	Peeling paint on wall and pipe	20	No	None	N/A	None	No	
260	4020	1	4	410		Classroom 415	W4	Peeling paint	20	No	None	N/A	None	No	
261	4020	1	4	410		Classroom 417	W3	Peeling paint	3	No	None	N/A	None	No	
262	4020	1	4	412		Classroom 418	Ceiling	No Access						Inspection Needed	
263	4020	1	4	412		Classroom 418	Floor	No Access						Inspection Needed	
264	4020	1	4	414		Classroom 418	W1	No Access						Inspection Needed	
265	4020	1	4	414		Classroom 418	W2	No Access						Inspection Needed	
266	4020	1	4	414		Classroom 418	W3	No Access						Inspection Needed	
267	4020	1	4	414		Classroom 418	W4	No Access						Inspection Needed	
268	4020	1	4	414B		Classroom 419	Ceiling	Severe peeling paint	150	No	None	N/A	None	No	
269	4020	1	4	414B		Classroom 419	Floor	Debris on floor and chairs	100		Chairs	35		No	
270	4020	1	4	414B		Classroom 419	W3	Peeling paint	3	No	None	N/A	None	No	
271	4020	1	4	414B		Classroom 420	Ceiling	Peeling paint	5	No	None	N/A	None	No	
272	4020	1	4	415		Classroom 420	W3	Peeling paint on wall and pipe	20	No	None	N/A	None	No	
273	4020	1	4	415		Classroom 420	W4	Efflorescence	5	No	None	N/A	None	No	
274	4020	1	4	415		Classroom 421	Ceiling	Peeling paint	15	No	None	N/A	None	No	
275	4020	1	4	415		Classroom 421	Floor	Debris	20	No	Debris	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
276	4020	1	4	417		Classroom 421	W1	Peeling paint and efflorescence	5	No	None	N/A	None	No	
277	4020	1	4	418		Classroom 421	W2	Peeling paint and damaged plaster	5	No	None	N/A	None	Yes	
278	4020	1	4	418		Classroom 421	W3	Peeling and cracking paint, Peeling paint on pipe	30	No	None	N/A	None	No	
279	4020	1	4	418		Classroom 422	W1	Peeling paint	2	No	None	N/A	None	No	
280	4020	1	4	418		Classroom 422	W2	Peeling paint and efflorescence	10	No	None	N/A	None	No	
281	4020	1	4	418		Classroom 422	W3	Peeling paint	2	No	None	N/A	None	No	
282	4020	1	4	418		Classroom 422	W4	Peeling paint	3	No	None	N/A	None	No	
283	4020	1	4	419		Classroom 425	Ceiling	Severe peeling paint and damaged plaster	120	No	None	N/A	None	Yes	
284	4020	1	4	419		Classroom 425	Floor	Debris	150	No	Debris	N/A	None	No	Warped wood floor
285	4020	1	4	419		Classroom 425	W3	Peeling paint on wall and pipes	25	No	None	N/A	None	No	
286	4020	1	4	420		Classroom 426	W3	Efflorescence at window, peeling paint on pipe	20	No	None	N/A	None	No	
287	4020	1	4	420		Classroom 427	Ceiling	Peeling paint, damaged plaster and efflorescence	150	No	None	N/A	None	Yes	
288	4020	1	4	420		Classroom 427	Floor	Debris	150	No	Debris	N/A	None	No	
289	4020	1	4	421		Classroom 427	W2	Damaged plaster	5	No	None	N/A	None	Yes	
290	4020	1	4	421		Classroom 427	W3	Peeling and cracking paint, efflorescence	50	No	None	N/A	None	No	
291	4020	1	4	421		Classroom 430	W1	Peeling paint	5	No	None	N/A	None	No	
292	4020	1	4	421		Classroom 430	W2	Peeling paint	10	No	None	N/A	None	No	
293	4020	1	4	421		Classroom 430	W3	Peeling paint on wall and pipes	40	No	None	N/A	None	No	
294	4020	1	4	422		Classroom 430	W4	Peeling paint	5	No	None	N/A	None	No	
295	4020	1	4	422		Classroom 431	Ceiling	Peeling paint and efflorescence	40	No	None	N/A	None	No	
296	4020	1	4	422		Classroom 431	Floor	Debris on carpet	40	No	Carpet	40	None	No	
297	4020	1	4	422		Classroom 431	W1	Peeling and cracking paint	10	No	None	N/A	None	No	
298	4020	1	4	425		Classroom 431	W2	Peeling paint	5	No	None	N/A	None	No	
299	4020	1	4	425		Classroom 431	W3	Peeling paint on wall and pipes, spalling	40	No	None	N/A	None	No	
300	4020	1	4	425		Classroom 431	W4	Cracking paint	5	No	None	N/A	None	No	
301	4020	1	4	426		Doorway Labeled 428 Left Office	Ceiling	No Access						Inspection Needed	
302	4020	1	4	427		Doorway Labeled 428 Left Office	Floor	No Access						Inspection Needed	
303	4020	1	4	427		Doorway Labeled 428 Left Office	W1	No Access						Inspection Needed	
304	4020	1	4	427		Doorway Labeled 428 Left Office	W2	No Access						Inspection Needed	
305	4020	1	4	427		Doorway Labeled 428 Left Office	W3	No Access						Inspection Needed	
306	4020	1	4	430		Doorway Labeled 428 Left Office	W4	No Access						Inspection Needed	
307	4020	1	4	430		Doorway Labeled 428 Right Office	Ceiling	No Access						Inspection Needed	
308	4020	1	4	430		Doorway Labeled 428 Right Office	Floor	No Access						Inspection Needed	
309	4020	1	4	430		Doorway Labeled 428 Right Office	W1	No Access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
310	4020	1	4	431		Doorway Labeled 428 Right Office	W2	No Access						Inspection Needed	
311	4020	1	4	431		Doorway Labeled 428 Right Office	W3	No Access						Inspection Needed	
312	4020	1	4	431		Doorway Labeled 428 Right Office	W4	No Access						Inspection Needed	
313	4020	1	4	431		Fire Tower adjacent Classroom 415	Ceiling	Severe peeling paint	200	No	None	N/A	None	No	
314	4020	1	4	431		Fire Tower adjacent Classroom 415	Floor	Debris	200	No	Debris	N/A	None	No	
315	4020	1	4	431		Fire Tower adjacent Classroom 415	W1	Peeling paint	30	No	None	N/A	None	No	
316	4020	1	4	428		Fire Tower adjacent Classroom 415	W2	Peeling paint	30	No	None	N/A	None	No	
317	4020	1	4	428		Fire Tower adjacent Classroom 415	W3	Peeling paint	30	No	None	N/A	None	No	
318	4020	1	4	428		Fire Tower adjacent Classroom 415	W4	Peeling paint	30	No	None	N/A	None	No	
319	4020	1	4	428		Fire Tower adjacent Classroom 422	Floor	Debris	50	No	Debris	N/A	None	No	
320	4020	1	4	428		Fire Tower adjacent Classroom 422	W1	Peeling paint	30	No	None	N/A	None	No	
321	4020	1	4	428		Fire Tower adjacent Classroom 422	W2	Peeling paint	30	No	None	N/A	None	No	
322	4020	1	4	428B		Fire Tower adjacent Classroom 422	W3	Peeling paint	30	No	None	N/A	None	No	
323	4020	1	4	428B		Fire Tower adjacent Classroom 422	W4	Peeling paint	30	No	None	N/A	None	No	
324	4020	1	4	428B		Hallway Outside Classrooms 400-407	Ceiling	Peeling paint	30	No	None	N/A	None	No	
325	4020	1	4	428B		Hallway Outside Classrooms 400-407	Floor	Debris	25	No	Debris	N/A	None	No	
326	4020	1	4	428B		Hallway Outside Classrooms 400-407	W1	Peeling paint and damaged plaster	20	No	None	N/A	None	Yes	
327	4020	1	4	428B		Hallway Outside Classrooms 400-407	W3	Peeling paint, damaged plaster and on pipes	40	No	None	N/A	None	Yes	
328	4020	1	4	S45		Hallway Outside Classrooms 409-414	W2	Peeling paint	15	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
329	4020	1	4	S45		Hallway Outside Classrooms 409-414	W4	Peeling paint	5	No	None	N/A	None	No	
330	4020	1	4	S45		Hallway Outside Classrooms 416-419	Ceiling	Efflorescence	25	No	None	N/A	None	No	
331	4020	1	4	S45		Hallway Outside Classrooms 416-419	Floor	Debris	20	No	Debris	N/A	None	No	
332	4020	1	4	S45		Hallway Outside Classrooms 416-419	W1	Peeling paint	5	No	None	N/A	None	No	
333	4020	1	4	S45		Hallway Outside Classrooms 416-419	W3	Peeling paint on wall and pipes	30	No	None	N/A	None	No	
334	4020	1	4	S43		Hallway Outside Classrooms 419-421	Ceiling	Severe peeling paint and efflorescence	100	No	None	N/A	None	No	
335	4020	1	4	S43		Hallway Outside Classrooms 419-421	Floor	Debris	60	No	Debris	N/A	None	No	
336	4020	1	4	S43		Hallway Outside Classrooms 419-421	W1	Peeling paint	10	No	None	N/A	None	No	
337	4020	1	4	S43		Hallway Outside Classrooms 419-421	W3	Peeling paint on Pipes	30	No	None	N/A	None	No	
338	4020	1	4	S43		Hallway Outside Classrooms 422-430	Ceiling	Peeling paint and efflorescence	50	No	None	N/A	None	No	
339	4020	1	4	H49		Hallway Outside Classrooms 422-430	Floor	Debris	30	No	Debris	N/A	None	No	
340	4020	1	4	H49		Hallway Outside Classrooms 422-430	W2	Peeling paint	5	No	None	N/A	None	No	
341	4020	1	4	H49		Hallway Outside Classrooms 422-430	W4	Peeling paint	5	No	None	N/A	None	No	
342	4020	1	4	H49		Men's Restroom Lounge Area	W1	Damaged plaster	2	No	None	N/A	None	Yes	
343	4020	1	4	H47		Men's Restroom Lounge Area	W2	Peeling paint and efflorescence above window	30	No	None	N/A	None	No	
344	4020	1	4	H47		Men's Restroom Lounge Area	W3	Cracking paint	5	No	None	N/A	None	No	
345	4020	1	4	H43		Men's Restroom Lounge Area	W4	Cracking paint	5	No	None	N/A	None	No	
346	4020	1	4	H43		Office 404	W3	Peeling paint on pipes, Cracking paint	40	No	None	N/A	None	No	
347	4020	1	4	H43		Office 408	Floor	Debris at window (behind cabinet)	6		Debris		Cabinet		
348	4020	1	4	H43		Office 408	W3	Peeling paint and efflorescence	25	No	None	N/A	None	No	
349	4020	1	4	H41		Office 408	W4	Damaged plaster	4	No	None	N/A	None	Yes	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
350	4020	1	4	H41		Office 411 Business Vocational Education Office	Ceiling	No Access						Inspection Needed	
351	4020	1	4	H41		Office 411 Business Vocational Education Office	Floor	No Access						Inspection Needed	
352	4020	1	4	H41		Office 411 Business Vocational Education Office	W1	No Access						Inspection Needed	
353	4020	1	4	H40		Office 411 Business Vocational Education Office	W2	No Access						Inspection Needed	
354	4020	1	4	H40		Office 411 Business Vocational Education Office	W3	No Access						Inspection Needed	
355	4020	1	4	H40		Office 411 Business Vocational Education Office	W4	No Access						Inspection Needed	
356	4020	1	4	H40		Office 411 Business Vocational Education Office Storage Room	Ceiling	No Access						Inspection Needed	
357	4020	1	4	406A		Office 411 Business Vocational Education Office Storage Room	Floor	No Access						Inspection Needed	
358	4020	1	4	406A		Office 411 Business Vocational Education Office Storage Room	W1	No Access						Inspection Needed	
359	4020	1	4	406A		Office 411 Business Vocational Education Office Storage Room	W2	No Access						Inspection Needed	
360	4020	1	4	406A		Office 411 Business Vocational Education Office Storage Room	W3	No Access						Inspection Needed	
361	4020	1	4	404		Office 411 Business Vocational Education Office Storage Room	W4	No Access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
362	4020	1	4	408		Office 413	W3	Peeling paint on pipe	6	No	None	N/A	None	No	
363	4020	1	4	408		Office 423	Ceiling	No Access						Inspection Needed	
364	4020	1	4	408		Office 423	Floor	No Access						Inspection Needed	
365	4020	1	4	411		Office 423	W1	No Access						Inspection Needed	
366	4020	1	4	411		Office 423	W2	No Access						Inspection Needed	
367	4020	1	4	411		Office 423	W3	No Access						Inspection Needed	
368	4020	1	4	411		Office 423	W4	No Access						Inspection Needed	
369	4020	1	4	411		Office 423 Left Closet	Ceiling	No Access						Inspection Needed	
370	4020	1	4	411		Office 423 Left Closet	Floor	No Access						Inspection Needed	
371	4020	1	4	414A		Office 423 Left Closet	W1	No Access						Inspection Needed	
372	4020	1	4	414A		Office 423 Left Closet	W2	No Access						Inspection Needed	
373	4020	1	4	414A		Office 423 Left Closet	W3	No Access						Inspection Needed	
374	4020	1	4	414A		Office 423 Left Closet	W4	No Access						Inspection Needed	
375	4020	1	4	414A		Office 423 Right Closet	Ceiling	No Access						Inspection Needed	
376	4020	1	4	414A		Office 423 Right Closet	Floor	No Access						Inspection Needed	
377	4020	1	4	413		Office 423 Right Closet	W1	No Access						Inspection Needed	
378	4020	1	4	423		Office 423 Right Closet	W2	No Access						Inspection Needed	
379	4020	1	4	423		Office 423 Right Closet	W3	No Access						Inspection Needed	
380	4020	1	4	423		Office 423 Right Closet	W4	No Access						Inspection Needed	
381	4020	1	4	423		Office 424	Floor	Debris	10	No	Debris	N/A	None	No	
382	4020	1	4	423		Office 424	W3	Peeling paint and efflorescence at window	20	No	None	N/A	None	No	
383	4020	1	4	423		Office 429	Ceiling	No Access						Inspection Needed	
384	4020	1	4	423A		Office 429	Floor	No Access						Inspection Needed	
385	4020	1	4	423A		Office 429	W1	No Access						Inspection Needed	
386	4020	1	4	423A		Office 429	W2	No Access						Inspection Needed	
387	4020	1	4	423A		Office 429	W3	No Access						Inspection Needed	
388	4020	1	4	423A		Office 429	W4	No Access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
389	4020	1	4	423A		Photographic Dark Room inside Door between Elevator and Office 408	Ceiling	Peeling paint	2	No	None	N/A	None	No	
390	4020	1	4	423B		Photographic Dark Room inside Door between Elevator and Office 408	W3	Peeling paint and efflorescence	20	No	None	N/A	None	No	
391	4020	1	4	423B		Small Office inside Office 404	Ceiling	No Access						Inspection Needed	
392	4020	1	4	423B		Small Office inside Office 404	Floor	No Access						Inspection Needed	
393	4020	1	4	423B		Small Office inside Office 404	W1	No Access						Inspection Needed	
394	4020	1	4	423B		Small Office inside Office 404	W2	No Access						Inspection Needed	
395	4020	1	4	423B		Small Office inside Office 404	W3	No Access						Inspection Needed	
396	4020	1	4	424		Small Office inside Office 404	W4	No Access						Inspection Needed	
397	4020	1	4	424		Stairwell A	Ceiling	Peeling paint	10	No	None	N/A	None	No	
398	4020	1	4	428A		Stairwell A	W2	Cracking paint	5	No	None	N/A	None	No	
399	4020	1	4	428A		Stairwell A	W4	Cracking paint	5	No	None	N/A	None	No	
400	4020	1	4	428A		Stairwell across From Classroom 418	Ceiling	No Access						Inspection Needed	
401	4020	1	4	428A		Stairwell across From Classroom 418	Floor	No Access						Inspection Needed	
402	4020	1	4	428A		Stairwell across From Classroom 418	W1	No Access						Inspection Needed	
403	4020	1	4	428A		Stairwell across From Classroom 418	W2	No Access						Inspection Needed	
404	4020	1	4	402F		Stairwell across From Classroom 418	W3	No Access						Inspection Needed	
405	4020	1	4	402F		Stairwell across From Classroom 418	W4	No Access						Inspection Needed	
406	4020	1	4	404A		Stairwell across From Classroom 419	Ceiling	Same as S58		No	None	N/A	None	No	
407	4020	1	4	404A		Stairwell across From Classroom 419	Floor	Same as S58		No	None	N/A	None	No	
408	4020	1	4	404A		Stairwell across From Classroom 419	W1	Same as S58		No	None	N/A	None	No	
409	4020	1	4	404A		Stairwell across From Classroom 419	W2	Same as S58		No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
410	4020	1	4	404A		Stairwell across From Classroom 419	W3	Same as S58		No	None	N/A	None	No	
411	4020	1	4	404A		Stairwell across From Classroom 419	W4	Same as S58		No	None	N/A	None	No	
412	4020	1	4	S40		Stairwell B	Floor	Debris on landing	20	No	Debris	N/A	None	No	
413	4020	1	4	S40		Stairwell B	W2	Severe peeling paint	100	No	None	N/A	None	No	
414	4020	1	4	S40		Stairwell B	W4	Cracking paint	20	No	None	N/A	None	No	
415	4020	1	4	S5		Stairwell C	Floor	Debris	15	No	Debris	N/A	None	No	
416	4020	1	4	S5		Stairwell C	W2	Severe peeling paint	70	No	None	N/A	None	No	
417	4020	1	4	S5		Stairwell C	W3	Severe peeling paint and damaged plaster	30	No	None	N/A	None	Yes	
418	4020	1	4	S5		Stairwell C	W4	Peeling paint	20	No	None	N/A	None	No	
419	4020	1	4	S5		Stairwell D	Ceiling	at door on beam	10	No	None	N/A	None	No	
420	4020	1	4	S5		Stairwell D	Floor	Peeling paint	20	No	None	N/A	None	No	
421	4020	1	4	S4		Stairwell D	W2	Peeling and cracking paint	30	No	None	N/A	None	No	
422	4020	1	4	S4		Stairwell D	W3	Peeling paint	20	No	None	N/A	None	No	
423	4020	1	4	S4		Stairwell D	W4	Severe peeling paint	40	No	None	N/A	None	No	
424	4020	1	4	S4		Storage Room across From Classroom 403	Ceiling	No Access						Inspection Needed	
425	4020	1	4	S4		Storage Room across From Classroom 403	Floor	No Access						Inspection Needed	
426	4020	1	4	S4		Storage Room across From Classroom 403	W1	No Access						Inspection Needed	
427	4020	1	4	S42		Storage Room across From Classroom 403	W2	No Access						Inspection Needed	
428	4020	1	4	S42		Storage Room across From Classroom 403	W3	No Access						Inspection Needed	
429	4020	1	4	S42		Storage Room across From Classroom 403	W4	No Access						Inspection Needed	
430	4020	1	4	S44		Storage Room adjacent Office 429	W4	Spalling	3	No	None	N/A	None	No	
431	4020	1	4	S44		Storage Room Inside Stairwell across From Classroom 418	Ceiling	No Access						Inspection Needed	
432	4020	1	4	S44		Storage Room Inside Stairwell across From Classroom 418	Floor	No Access						Inspection Needed	
433	4020	1	4	S44		Storage Room Inside Stairwell across From Classroom 418	W1	No Access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
434	4020	1	4	S41		Storage Room Inside Stairwell across From Classroom 418	W2	No Access						Inspection Needed	
435	4020	1	4	S41		Storage Room Inside Stairwell across From Classroom 418	W3	No Access						Inspection Needed	
436	4020	1	4	S41		Storage Room Inside Stairwell across From Classroom 418	W4	No Access						Inspection Needed	
437	4020	1	4	S41		Storage Room to Right inside Door between Elevator and Office 408	W2	Peeling paint on pipe	10	No	None	N/A	None	No	
438	4020	1	4	S41		Toilet Area in Women's Restroom	Ceiling	Cracking paint	4	No	None	N/A	None	No	
439	4020	1	4	403A		Toilet Area in Women's Restroom	W2	Cracking paint and efflorescence	15	No	None	N/A	None	No	
440	4020	1	4	403A		Toilet Area in Women's Restroom	W3	Efflorescence and peeling paint on pipes	35	No	None	N/A	None	No	
441	4020	1	4	403A		Toilets Area in Men's Restroom	W2	Peeling paint and spalling	5	No	None	N/A	None	No	
442	4020	1	4	403A		Toilets Area in Men's Restroom	W3	Peeling paint, efflorescence and debris on top of urinal	16		Top of urinal	2		No	
443	4020	1	4	403A		Women's Restroom Lounge Area	W3	Peeling paint above window on wall and pipe and debris on window sill	15		Window Sill	5			
444	4020	1	4	403A		Women's Restroom Lounge Area	W4	Damaged plaster	10	No	None	N/A	None	Yes	
445	4020	1	4	429		Auditorium Balcony	Ceiling	Severe peeling paint and efflorescence	200	No	None	N/A	None	No	
446	4020	1	4	418A		Auditorium Balcony	Floor	Debris	20	No	Debris	N/A	None	No	
447	4020	1	4	418A		Auditorium Projection Room across from Classroom 304	Ceiling	No Access						Inspection Needed	
448	4020	1	4	418A		Auditorium Projection Room across from Classroom 304	Floor	No Access						Inspection Needed	
449	4020	1	4	418A		Auditorium Projection Room across from Classroom 304	W1	No Access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
450	4020	1	4	418A		Auditorium Projection Room across from Classroom 304	W2	No Access						Inspection Needed	
451	4020	1	4	418A		Auditorium Projection Room across from Classroom 304	W3	No Access						Inspection Needed	
452	4020	1	4	402G		Auditorium Projection Room across from Classroom 304	W4	No Access						Inspection Needed	
453	4020	1	4	410B		Boy's Restroom	W2	Cracking paint	20	No	None	N/A	None	No	
454	4020	1	4	410B		Chemical Storage adjacent Storage Room 331	Ceiling	No Access						Inspection Needed	
455	4020	1	4	410B		Chemical Storage adjacent Storage Room 331	Floor	No Access						Inspection Needed	
456	4020	1	4	406B		Chemical Storage adjacent Storage Room 331	W1	No Access						Inspection Needed	
457	4020	1	4	406B		Chemical Storage adjacent Storage Room 331	W2	No Access						Inspection Needed	
458	4020	1	4	410A		Chemical Storage adjacent Storage Room 331	W3	No Access						Inspection Needed	
459	4020	1	4	410A		Chemical Storage adjacent Storage Room 331	W4	No Access						Inspection Needed	
460	4020	1	3	333A		Chemical Storage adjacent Storage Room 331 Rear Storage Room	Ceiling	No Access						Inspection Needed	
461	4020	1	3	333A		Chemical Storage adjacent Storage Room 331 Rear Storage Room	Floor	No Access						Inspection Needed	
462	4020	1	3	304A		Chemical Storage adjacent Storage Room 331 Rear Storage Room	W1	No Access						Inspection Needed	
463	4020	1	3	304A		Chemical Storage adjacent Storage Room 331 Rear Storage Room	W2	No Access						Inspection Needed	
464	4020	1	3	304A		Chemical Storage adjacent Storage Room 331 Rear Storage Room	W3	No Access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
465	4020	1	3	304A		Chemical Storage adjacent Storage Room 331 Rear Storage Room	W4	No Access						Inspection Needed	
466	4020	1	3	304A		Classroom 300	W3	Cracking paint and debris on window sill	10	No	Window sill	2	None	No	
467	4020	1	3	304A		Classroom 301	W3	Peeling paint and efflorescence	50	No	None	N/A	None	No	
468	4020	1	3	300A		Classroom 302	W3	Peeling paint behind radiators and top of window, efflorescence	30	No	None	N/A	None	No	
469	4020	1	3	315A		Classroom 303	W3	Peeling paint behind radiators and crack in plaster wall	10	No	None	N/A	None	Yes	
470	4020	1	3	315A		Classroom 304	Ceiling	Damaged plaster and efflorescence	20	No	None	N/A	None	Yes	
471	4020	1	3	315A		Classroom 304	Floor	Debris	10	No	Debris	N/A	None	No	
472	4020	1	3	315A		Classroom 304	W3	Cracking paint	5	No	None	N/A	None	No	
473	4020	1	3	315A		Classroom 304	W4	Efflorescence at window, debris on window sill	40	No	Window sill	5	None	No	
474	4020	1	3	315A		Classroom 305	Ceiling	Peeling paint at window	10	No	None	N/A	None	No	
475	4020	1	3	315H		Classroom 305	W3	Peeling paint on wall including behind radiators, efflorescence, debris on window sill	30	No	Window sill	4	None	No	
476	4020	1	3	315H		Classroom 305	W4	Damaged plaster at door	2	No	None	N/A	None	Yes	
477	4020	1	3	315H		Classroom 306	Floor	Debris by window	4	No	Debris	N/A	None	No	
478	4020	1	3	315H		Classroom 306	W1	Peeling paint	5	No	None	N/A	None	No	
479	4020	1	3	315H		Classroom 306	W3	Severe peeling paint and efflorescence	40	No	None	N/A	None	No	
480	4020	1	3	315H		Classroom 307	W3	Severe peeling paint and efflorescence	40	No	None	N/A	None	No	
481	4020	1	3	300		Classroom 308	Ceiling	Peeling paint by door, efflorescence by the left corner of the window wall	20	No	None	N/A	None	No	
482	4020	1	3	301		Classroom 308	W1	Peeling paint	5	No	None	N/A	None	No	
483	4020	1	3	302		Classroom 308	W2	Peeling and cracking paint, efflorescence, peeling paint on pipe	35	No	None	N/A	None	No	
484	4020	1	3	303		Classroom 308	W3	Peeling and cracking paint, efflorescence, peeling paint on pipe	30	No	None	N/A	None	No	
485	4020	1	3	304		Classroom 308	W4	Cracking paint	2	No	None	N/A	None	No	
486	4020	1	3	304		Classroom 309	Floor	Debris by window	2	No	Debris	N/A	None	No	
487	4020	1	3	304		Classroom 309	W1	Damaged plaster and peeling paint	3	No	None	N/A	None	Yes	
488	4020	1	3	304		Classroom 309	W3	Severe peeling paint and efflorescence	35	No	None	N/A	None	No	
489	4020	1	3	305		Classroom 311	Ceiling	Damaged plaster, peeling paint by window	10	No	None	N/A	None	Yes	
490	4020	1	3	305		Classroom 311	W3	Debris on window sill	2	No	Window sill	2	None	No	
491	4020	1	3	305		Classroom 312	W3	Peeling paint, efflorescence at top of window	5	No	None	N/A	None	No	
492	4020	1	3	306		Classroom 314	W2	Spalling and peeling paint	5	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
493	4020	1	3	306		Classroom 316	W3	Damaged plaster at top of window, debris on window sill	20	No	Window sill	3	None	Yes	
494	4020	1	3	306		Classroom 317	Ceiling	Peeling paint at window	3	No	None	N/A	None	No	
495	4020	1	3	307		Classroom 318	W2	Damaged plaster at column	1	No	None	N/A	None	No	
496	4020	1	3	308		Classroom 318	W3	Spalling at radiator	3	No	None	N/A	None	No	
497	4020	1	3	308		Classroom 319	W1	Peeling paint by door	1	No	None	N/A	None	No	
498	4020	1	3	308		Classroom 319	W4	Damaged plaster by door	1	No	None	N/A	None	Yes	
499	4020	1	3	308		Classroom 320	W1	Peeling paint	1	No	None	N/A	None	No	
500	4020	1	3	308		Classroom 320	W3	Efflorescence at left window, peeling paint on wall including behind radiators, debris on window sill	30	No	Window sill	2	None	No	
501	4020	1	3	309		Classroom 321	W1	Chipped plaster by window	3	No	None	N/A	None	Yes	
502	4020	1	3	309		Classroom 321	W3	Efflorescence at top of window, debris on window sill	4	No	Window sill	1	None	No	
503	4020	1	3	309		Classroom 324	W3	Flaking paint on wall and severe peeling paint behind radiators	25	No	None	N/A	None	No	
504	4020	1	3	311		Classroom 325	W3	Efflorescence, Peeling paint behind radiators	30	No	None	N/A	None	No	
505	4020	1	3	311		Classroom 326	Ceiling	Peeling paint	5	No	None	N/A	None	No	
506	4020	1	3	312		Classroom 326	W1	Peeling paint	10	No	None	N/A	None	No	
507	4020	1	3	314		Classroom 326	W2	Peeling paint	50	No	None	N/A	None	No	
508	4020	1	3	316		Classroom 326	W3	Peeling paint	20	No	None	N/A	None	No	
509	4020	1	3	317		Classroom 326	W4	Peeling paint	5	No	None	N/A	None	No	
510	4020	1	3	318		Classroom 328	W3	Peeling paint - Spreadout	10	No	None	N/A	None	No	
511	4020	1	3	318		Classroom 329	Ceiling	Peeling paint - Spreadout	10	No	None	N/A	None	No	
512	4020	1	3	319		Classroom 329	W3	Peeling paint behind radiators, Spalling and Cracking paint	40	No	None	N/A	None	No	
513	4020	1	3	319		Classroom 332	Ceiling	Peeling paint	40	No	None	N/A	None	No	
514	4020	1	3	320		Classroom 333	Ceiling	Damaged plaster at beam	3	No	None	N/A	None	Yes	
515	4020	1	3	320		Classroom 333	W3	Efflorescence	3	No	None	N/A	None	No	
516	4020	1	3	321		Classroom 334	W4	Efflorescence at top of window	5	No	None	N/A	None	No	
517	4020	1	3	321		Counselor's Office 323	W2	Peeling paint on wal including behind radiator, crack in plaster wall	30	No	None	N/A	None	Yes	
518	4020	1	3	324		Door between Stairwell and Office 310	Ceiling	No Access						Inspection Needed	
519	4020	1	3	325		Door between Stairwell and Office 310	Floor	No Access						Inspection Needed	
520	4020	1	3	326		Door between Stairwell and Office 310	W1	No Access						Inspection Needed	
521	4020	1	3	326		Door between Stairwell and Office 310	W2	No Access						Inspection Needed	
522	4020	1	3	326		Door between Stairwell and Office 310	W3	No Access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
523	4020	1	3	326		Door between Stairwell and Office 310	W4	No Access						Inspection Needed	
524	4020	1	3	326		Fire Tower adjacent Classroom 317	Ceiling	Severe peeling paint	500	No	None	N/A	None	No	
525	4020	1	3	328		Fire Tower adjacent Classroom 317	Floor	Debris	200	No	Debris	N/A	None	No	
526	4020	1	3	329		Fire Tower adjacent Classroom 317	W1	Severe peeling paint	200	No	None	N/A	None	No	
527	4020	1	3	329		Fire Tower adjacent Classroom 317	W2	Severe peeling paint	200	No	None	N/A	None	No	
528	4020	1	3	332		Fire Tower adjacent Classroom 317	W3	Severe peeling paint	200	No	None	N/A	None	No	
529	4020	1	3	333		Fire Tower adjacent Classroom 317	W4	Severe peeling paint	200	No	None	N/A	None	No	
530	4020	1	3	333		Fire Tower adjacent Classroom 325	Ceiling	Severe peeling paint	500	No	None	N/A	None	No	
531	4020	1	3	334		Fire Tower adjacent Classroom 325	Floor	Debris	200	No	Debris	N/A	None	No	
532	4020	1	3	323		Fire Tower adjacent Classroom 325	W1	Severe peeling paint	200	No	None	N/A	None	No	
533	4020	1	3	320D		Fire Tower adjacent Classroom 325	W2	Severe peeling paint	200	No	None	N/A	None	No	
534	4020	1	3	320D		Fire Tower adjacent Classroom 325	W3	Severe peeling paint	200	No	None	N/A	None	No	
535	4020	1	3	320D		Fire Tower adjacent Classroom 325	W4	Severe peeling paint	200	No	None	N/A	None	No	
536	4020	1	3	320D		First Storage Room inside Stairwell across from Classroom 319	Ceiling	No Access - Sealed off						Inspection Needed	
537	4020	1	3	320D		First Storage Room inside Stairwell across from Classroom 319	Floor	No Access - Sealed off						Inspection Needed	
538	4020	1	3	320D		First Storage Room inside Stairwell across from Classroom 319	W1	No Access - Sealed off						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
539	4020	1	3	S34		First Storage Room inside Stairwell across from Classroom 319	W2	No Access - Sealed off						Inspection Needed	
540	4020	1	3	S34		First Storage Room inside Stairwell across from Classroom 319	W3	No Access - Sealed off						Inspection Needed	
541	4020	1	3	S34		First Storage Room inside Stairwell across from Classroom 319	W4	No Access - Sealed off						Inspection Needed	
542	4020	1	3	S34		First Storage Room inside Stairwell across from Classroom 323	Ceiling	No Access - Sealed off						Inspection Needed	
543	4020	1	3	S34		First Storage Room inside Stairwell across from Classroom 323	Floor	No Access - Sealed off						Inspection Needed	
544	4020	1	3	S34		First Storage Room inside Stairwell across from Classroom 323	W1	No Access - Sealed off						Inspection Needed	
545	4020	1	3	S33		First Storage Room inside Stairwell across from Classroom 323	W2	No Access - Sealed off						Inspection Needed	
546	4020	1	3	S33		First Storage Room inside Stairwell across from Classroom 323	W3	No Access - Sealed off						Inspection Needed	
547	4020	1	3	S33		First Storage Room inside Stairwell across from Classroom 323	W4	No Access - Sealed off						Inspection Needed	
548	4020	1	3	S33		Girl's Restroom	Ceiling	Peeling paint and efflorescence	30	No	None	N/A	None	No	
549	4020	1	3	S33		Girl's Restroom	W3	Peeling paint and efflorescence	20	No	None	N/A	None	No	
550	4020	1	3	S33		Girl's Restroom	W4	Efflorescence	10	No	None	N/A	None	No	
551	4020	1	3	335		Hallway outside Classrooms 300-307	Ceiling	Peeling paint - Spreadout	5	No	None	N/A	None	No	
552	4020	1	3	335		Hallway outside Classrooms 300-307	W1	Peeling paint - Spreadout	5	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
553	4020	1	3	335		Hallway outside Classrooms 300-307	W3	Severe efflorescence on wall across from Classrooms 305 & 306, peeling paint on pipes	35	No	None	N/A	None	No	
554	4020	1	3	335		Hallway outside Classrooms 318-320	Ceiling	Damaged plaster, peeling paint	10	No	None	N/A	None	Yes	
555	4020	1	3	335		Men's Staff Restroom Lounge Area	W3	Efflorescence and damaged plaster at top of window	20	No	None	N/A	None	Yes	
556	4020	1	3	335		Nurse's Office	W1	Cracking paint	5	No	None	N/A	None	No	
557	4020	1	3	337		Nurse's Office	W2	Efflorescence at window by riser	2	No	None	N/A	None	No	
558	4020	1	3	337		Nurse's Office Closet	Ceiling	No Access (peeling paint is visible through door)						Inspection Needed	
559	4020	1	3	337		Nurse's Office Closet	Floor	No Access (peeling paint is visible through door)						Inspection Needed	
560	4020	1	3	337		Nurse's Office Closet	W1	No Access (peeling paint is visible through door)						Inspection Needed	
561	4020	1	3	337		Nurse's Office Closet	W2	No Access (peeling paint is visible through door)						Inspection Needed	
562	4020	1	3	337		Nurse's Office Closet	W3	No Access (peeling paint is visible through door)						Inspection Needed	
563	4020	1	3	318A		Nurse's Office Closet	W4	No Access (peeling paint is visible through door)						Inspection Needed	
564	4020	1	3	318A		Nurse's Office Left Patient Area	W3	Cracking paint on window sill	4	No	None	N/A	None	No	
565	4020	1	3	318A		Nurse's Office Right Patient Area	W2	Efflorescence by radiator	10	No	None	N/A	None	No	
566	4020	1	3	H34		Office 310	W2	Flaking paint	30	No	None	N/A	None	No	
567	4020	1	3	H34		Office 310	W4	Flaking paint	20	No	None	N/A	None	No	
568	4020	1	3	H34		Office 310 Storage Room	W2	Flaking paint	5	No	None	N/A	None	No	
569	4020	1	3	H32		Office 310 Storage Room	W3	Efflorescence at window	5	No	None	N/A	None	No	
570	4020	1	3	306A		Office 310 Storage Room	W4	Flaking paint	10	No	None	N/A	None	No	
571	4020	1	3	315		Office 313 Teacher's Rest Room	Ceiling	Damaged plaster and efflorescence	50	No	None	N/A	None	Yes	
572	4020	1	3	315		Office 313 Teacher's Rest Room	W1	Peeling paint	3	No	None	N/A	None	No	
573	4020	1	3	315D		Office 313 Teacher's Rest Room	W3	Damaged plaster and efflorescence	20	No	None	N/A	None	Yes	
574	4020	1	3	315D		Office 327 Science Book Room Closet	W3	Damaged plaster	5	No	None	N/A	None	Yes	
575	4020	1	3	315D		Office 327 Science Book Room Room on Left	Ceiling	Peeling paint	30	No	None	N/A	None	No	
576	4020	1	3	315D		Office 327 Science Book Room Room on Left	W4	Cracking paint	10	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
577	4020	1	3	315D		Office 327 Science Book Room Science Office Hallway	Ceiling	Peeling paint	5	No	None	N/A	None	No	
578	4020	1	3	315D		Office 327 Science Office Closet on Left	Ceiling	No Access						Inspection Needed	
579	4020	1	3	315G		Office 327 Science Office Closet on Left	Floor	No Access						Inspection Needed	
580	4020	1	3	315B		Office 327 Science Office Closet on Left	W1	No Access						Inspection Needed	
581	4020	1	3	310		Office 327 Science Office Closet on Left	W2	No Access						Inspection Needed	
582	4020	1	3	310		Office 327 Science Office Closet on Left	W3	No Access						Inspection Needed	
583	4020	1	3	310A		Office 327 Science Office Closet on Left	W4	No Access						Inspection Needed	
584	4020	1	3	310A		Office 327 Science Office Closet on Right	Ceiling	No Access						Inspection Needed	
585	4020	1	3	310A		Office 327 Science Office Closet on Right	Floor	No Access						Inspection Needed	
586	4020	1	3	313		Office 327 Science Office Closet on Right	W1	No Access						Inspection Needed	
587	4020	1	3	313		Office 327 Science Office Closet on Right	W2	No Access						Inspection Needed	
588	4020	1	3	313		Office 327 Science Office Closet on Right	W3	No Access						Inspection Needed	
589	4020	1	3	327E		Office 327 Science Office Closet on Right	W4	No Access						Inspection Needed	
590	4020	1	3	327B		Office 327 Science Office Room on Right	Ceiling	No Access						Inspection Needed	
591	4020	1	3	327B		Office 327 Science Office Room on Right	Floor	No Access						Inspection Needed	
592	4020	1	3	327		Office 327 Science Office Room on Right	W1	No Access						Inspection Needed	
593	4020	1	3	327D		Office 327 Science Office Room on Right	W2	No Access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
594	4020	1	3	327D		Office 327 Science Office Room on Right	W3	No Access						Inspection Needed	
595	4020	1	3	327D		Office 327 Science Office Room on Right	W4	No Access						Inspection Needed	
596	4020	1	3	327D		Stairwell A	W2	Cracking and peeling paint on control box	4	No	None	N/A	None	No	
597	4020	1	3	327D		Stairwell across from Classroom 319	Ceiling	No Access - Sealed off						Inspection Needed	
598	4020	1	3	327D		Stairwell across from Classroom 319	Floor	No Access - Sealed off						Inspection Needed	
599	4020	1	3	327C		Stairwell across from Classroom 319	W1	No Access - Sealed off						Inspection Needed	
600	4020	1	3	327C		Stairwell across from Classroom 319	W2	No Access - Sealed off						Inspection Needed	
601	4020	1	3	327C		Stairwell across from Classroom 319	W3	No Access - Sealed off						Inspection Needed	
602	4020	1	3	327C		Stairwell across from Classroom 319	W4	No Access - Sealed off						Inspection Needed	
603	4020	1	3	327C		Stairwell across from Classroom 323	Ceiling	No Access - Sealed off						Inspection Needed	
604	4020	1	3	327C		Stairwell across from Classroom 323	Floor	No Access - Sealed off						Inspection Needed	
605	4020	1	3	327A		Stairwell across from Classroom 323	W1	No Access - Sealed off						Inspection Needed	
606	4020	1	3	327A		Stairwell across from Classroom 323	W2	No Access - Sealed off						Inspection Needed	
607	4020	1	3	327A		Stairwell across from Classroom 323	W3	No Access - Sealed off						Inspection Needed	
608	4020	1	3	327A		Stairwell across from Classroom 323	W4	No Access - Sealed off						Inspection Needed	
609	4020	1	3	327A		Stairwell B	Ceiling	Peeling paint at middle landing	10	No	None	N/A	None	No	
610	4020	1	3	327A		Stairwell D	W2	Efflorescence on wall and peeling paint on pipe	20	No	None	N/A	None	No	
611	4020	1	3	S31		Stairwell D	W3	Efflorescence at top of window	5	No	None	N/A	None	No	
612	4020	1	3	S38		Storage Room 331	W2	Flaking and cracking paint	35	No	None	N/A	None	No	
613	4020	1	3	S38		Storage Room 331	W3	Peeling and cracking paint	15	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
614	4020	1	3	S38		Storage Room behind First Storage Room inside Stairwell across from Classroom 319	Ceiling	No Access - Sealed off						Inspection Needed	
615	4020	1	3	S38		Storage Room behind First Storage Room inside Stairwell across from Classroom 319	Floor	No Access - Sealed off						Inspection Needed	
616	4020	1	3	S38		Storage Room behind First Storage Room inside Stairwell across from Classroom 319	W1	No Access - Sealed off						Inspection Needed	
617	4020	1	3	S38		Storage Room behind First Storage Room inside Stairwell across from Classroom 319	W2	No Access - Sealed off						Inspection Needed	
618	4020	1	3	S37		Storage Room behind First Storage Room inside Stairwell across from Classroom 319	W3	No Access - Sealed off						Inspection Needed	
619	4020	1	3	S37		Storage Room behind First Storage Room inside Stairwell across from Classroom 319	W4	No Access - Sealed off						Inspection Needed	
620	4020	1	3	S37		Storage Room behind First Storage Room inside Stairwell across from Classroom 323	Ceiling	No Access - Sealed off						Inspection Needed	
621	4020	1	3	S37		Storage Room behind First Storage Room inside Stairwell across from Classroom 323	Floor	No Access - Sealed off						Inspection Needed	
622	4020	1	3	S37		Storage Room behind First Storage Room inside Stairwell across from Classroom 323	W1	No Access - Sealed off						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
623	4020	1	3	S37		Storage Room behind First Storage Room inside Stairwell across from Classroom 323	W2	No Access - Sealed off						Inspection Needed	
624	4020	1	3	S36		Storage Room behind First Storage Room inside Stairwell across from Classroom 323	W3	No Access - Sealed off						Inspection Needed	
625	4020	1	3	S32		Storage Room behind First Storage Room inside Stairwell across from Classroom 323	W4	No Access - Sealed off						Inspection Needed	
626	4020	1	3	S32		Storage Room between Classrooms 320 & 321	Ceiling	Peeling paint by door, and cracking paint in the middle	5	No	None	N/A	None	No	
627	4020	1	3	331		Storage Room between Classrooms 320 & 321	Floor	Debris by door	3	No	Debris	N/A	None	No	
628	4020	1	3	331		Storage Room between Classrooms 320 & 321	W3	Peeling paint behind radiators	10	No	None	N/A	None	No	
629	4020	1	3	336		Storage Room between Classrooms 320 & 321 Left Closet	Floor	Debris	4	No	Debris	N/A	None	No	
630	4020	1	3	336		Storage Room between Classrooms 320 & 321 Left Closet	W4	Damaged plaster and cracking paint	10	No	None	N/A	None	Yes	
631	4020	1	3	336		Storage Room between Classrooms 320 & 321 Right Closet	Ceiling	No Access						Inspection Needed	
632	4020	1	3	336		Storage Room between Classrooms 320 & 321 Right Closet	Floor	No Access						Inspection Needed	
633	4020	1	3	336		Storage Room between Classrooms 320 & 321 Right Closet	W1	No Access						Inspection Needed	
634	4020	1	3	336		Storage Room between Classrooms 320 & 321 Right Closet	W2	No Access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
635	4020	1	3	338		Storage Room between Classrooms 320 & 321 Right Closet	W3	No Access						Inspection Needed	
636	4020	1	3	338		Storage Room between Classrooms 320 & 321 Right Closet	W4	No Access						Inspection Needed	
637	4020	1	3	338		Toilet Area in Men's Staff Restroom	W3	Peeling paint	5	No	None	N/A	None	No	
638	4020	1	3	338		Toilet Area in Men's Staff Restroom	W4	Cracking paint and efflorescence	20	No	None	N/A	None	No	
639	4020	1	3	338		Toilet Area in Women's Restroom	Ceiling	Damaged plaster and efflorescence	60	No	None	N/A	None	Yes	
640	4020	1	3	338		Toilet Area in Women's Restroom	Floor	Debris	5	No	Debris	N/A	None	No	
641	4020	1	3	321A		Toilet Area in Women's Restroom	W1	Cracking paint	20	No	None	N/A	None	No	
642	4020	1	3	321A		Toilet Area in Women's Restroom	W2	Severe peeling paint, Cracking paint, efflorescence	20	No	None	N/A	None	No	
643	4020	1	3	321A		Toilet Area in Women's Restroom	W3	Severe peeling paint, Cracking paint, efflorescence	70	No	None	N/A	None	No	
644	4020	1	3	321C		Toilet Area in Women's Restroom	W4	Severe peeling paint and efflorescence	30	No	None	N/A	None	No	
645	4020	1	3	321C		Women's Restroom Lounge Area	W3	Damaged plaster above window, debris on window sill	6	No	Window sill	1	None	No	
646	4020	1	3	321D		Assistant Principal's Office	W3	Efflorescence above windows, debris on window sill	5	No	Window sill	1	None	No	
647	4020	1	3	321D		Boy's Restroom	W2	Efflorescence on wall and column at window	30	No	None	N/A	None	No	
648	4020	1	3	321D		Classroom 205	Ceiling	Peeling paint and efflorescence	5	No	None	N/A	None	No	
649	4020	1	3	321D		Classroom 205	W3	Peeling paint on wall and pipe	30	No	None	N/A	None	No	
650	4020	1	3	321D		Classroom 207	Ceiling	Peeling paint	10	No	None	N/A	None	No	
651	4020	1	3	321D		Classroom 207	W2	Peeling paint	5	No	None	N/A	None	No	
652	4020	1	3	306B		Classroom 207	W3	Peeling paint, efflorescence	30	No	None	N/A	None	No	
653	4020	1	3	306B		Classroom 210	W3	Peeling paint on pipes	10	No	None	N/A	None	No	
654	4020	1	3	313B		Classroom 211	Ceiling	Peeling paint	20	No	None	N/A	None	No	
655	4020	1	3	313B		Classroom 211	W3	Efflorescence at window	5	No	None	N/A	None	No	
656	4020	1	3	313B		Classroom 211	W4	Peeling paint	5	No	None	N/A	None	No	
657	4020	1	3	313B		Classroom 212	Ceiling	Peeling paint	10	No	None	N/A	None	No	
658	4020	1	3	313B		Classroom 212	W1	Peeling paint	30	No	None	N/A	None	No	
659	4020	1	3	313B		Classroom 212	W2	Peeling paint	25	No	None	N/A	None	No	
660	4020	1	3	313A		Classroom 212	W3	Damaged plaster, Peeling paint on wall and pipe	50	No	None	N/A	None	Yes	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
661	4020	1	2	201B		Classroom 212	W4	Peeling paint	2	No	None	N/A	None	No	
662	4020	1	2	200B		Classroom 213	Ceiling	Damaged plaster and peeling paint	60	No	None	N/A	None	Yes	
663	4020	1	2	205		Classroom 213	W1	Peeling paint	15	No	None	N/A	None	No	
664	4020	1	2	205		Classroom 213	W2	Peeling paint	5	No	None	N/A	None	No	
665	4020	1	2	207		Classroom 213	W3	Peeling paint and efflorescence	80	No	None	N/A	None	No	
666	4020	1	2	207		Classroom 213	W4	Peeling and cracking paint	10	No	None	N/A	None	No	
667	4020	1	2	207		Classroom 214	Ceiling	Severe peeling paint	15	No	None	N/A	None	No	
668	4020	1	2	210		Classroom 214	W1	Damaged plaster at door, Peeling and cracking paint	30	No	None	N/A	None	Yes	
669	4020	1	2	211		Classroom 214	W2	Damaged plaster at column	10	No	None	N/A	None	Yes	
670	4020	1	2	211		Classroom 214	W3	Peeling and cracking paint	35	No	None	N/A	None	No	
671	4020	1	2	211		Classroom 216	Ceiling	Severe peeling paint	60	No	None	N/A	None	No	
672	4020	1	2	212		Classroom 216	W3	Cracking paint	10	No	None	N/A	None	No	
673	4020	1	2	212		Classroom 217	W2	Cracking paint on wall and peeling paint on pipes	35	No	None	N/A	None	No	
674	4020	1	2	212		Classroom 217	W3	Peeling paint	10	No	None	N/A	None	No	
675	4020	1	2	212		Classroom 217	W4	Peeling paint	3	No	None	N/A	None	No	
676	4020	1	2	212		Classroom 219	Ceiling	Peeling paint	200	No	None	N/A	None	No	
677	4020	1	2	213		Classroom 219	W1	Damaged plaster and peeling paint	50	No	None	N/A	None	Yes	
678	4020	1	2	213		Classroom 219	W2	Peeling paint	50	No	None	N/A	None	No	
679	4020	1	2	213		Classroom 219	W3	Peeling and cracking paint	50	No	None	N/A	None	No	
680	4020	1	2	213		Classroom 219	W4	Damaged plaster and peeling paint	60	No	None	N/A	None	Yes	
681	4020	1	2	213		Classroom 222	W3	Spalling at air conditioner	5	No	None	N/A	None	No	
682	4020	1	2	215		Classroom 223	Ceiling	Severe peeling paint	120	No	None	N/A	None	No	
683	4020	1	2	215		Classroom 223	W1	Peeling paint on wall including plenum	30	No	None	N/A	None	No	
684	4020	1	2	215		Classroom 223	W3	Peeling paint behind radiator and peeling paint on pipes	30	No	None	N/A	None	No	
685	4020	1	2	215		Closet between Classrooms 224 & 225	Ceiling	No access						Inspection Needed	
686	4020	1	2	216		Closet between Classrooms 224 & 225	Floor	No access						Inspection Needed	
687	4020	1	2	216		Closet between Classrooms 224 & 225	W1	No access						Inspection Needed	
688	4020	1	2	217		Closet between Classrooms 224 & 225	W2	No access						Inspection Needed	
689	4020	1	2	217		Closet between Classrooms 224 & 225	W3	No access						Inspection Needed	
690	4020	1	2	217		Closet between Classrooms 224 & 225	W4	No access						Inspection Needed	
691	4020	1	2	219		Fire Tower adjacent Classroom 213	Ceiling	Severe peeling paint	400	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
692	4020	1	2	219		Fire Tower adjacent Classroom 213	Floor	Debris	100	No	Debris	N/A	None	No	
693	4020	1	2	219		Fire Tower adjacent Classroom 213	W1	Severe peeling paint	200	No	None	N/A	None	No	
694	4020	1	2	219		Fire Tower adjacent Classroom 213	W2	Severe peeling paint	200	No	None	N/A	None	No	
695	4020	1	2	219		Fire Tower adjacent Classroom 213	W3	Severe peeling paint	200	No	None	N/A	None	No	
696	4020	1	2	222		Fire Tower adjacent Classroom 213	W4	Severe peeling paint	200	No	None	N/A	None	No	
697	4020	1	2	223		Fire Tower adjacent Classroom 216	Ceiling	Severe peeling paint	400	No	None	N/A	None	No	
698	4020	1	2	223		Fire Tower adjacent Classroom 216	Floor	Debris	100	No	Debris	N/A	None	No	
699	4020	1	2	223		Fire Tower adjacent Classroom 216	W1	Severe peeling paint	200	No	None	N/A	None	No	
700	4020	1	2	225D		Fire Tower adjacent Classroom 216	W2	Severe peeling paint	200	No	None	N/A	None	No	
701	4020	1	2	225D		Fire Tower adjacent Classroom 216	W3	Severe peeling paint	200	No	None	N/A	None	No	
702	4020	1	2	225D		Fire Tower adjacent Classroom 216	W4	Severe peeling paint	200	No	None	N/A	None	No	
703	4020	1	2	225D		Girl's Restroom	Ceiling	Damaged plaster and efflorescence	50	No	None	N/A	None	Yes	
704	4020	1	2	225D		Girl's Restroom	W4	Peeling paint and efflorescence	15	No	None	N/A	None	No	
705	4020	1	2	225D		Hallway outside Classroom 213-IMC	W1	Peeling paint and efflorescence	10	No	None	N/A	None	No	
706	4020	1	2	S25		Hallway outside Classroom 225-Principal's Office	W3	Peeling paint at posters	15	No	None	N/A	None	No	
707	4020	1	2	S25		IMC	Ceiling	Damaged plaster above windows and peeling paint on pipes	50	No	None	N/A	None	Yes	
708	4020	1	2	S25		Main Office Supply Room	Ceiling	Damaged plaster and efflorescence	10	No	None	N/A	None	Yes	
709	4020	1	2	S25		Main Office Supply Room	W3	Efflorescence at window	20	No	None	N/A	None	No	
710	4020	1	2	S25		Office 201C Counselor's Office	W3	Damaged plaster above windows	10	No	None	N/A	None	Yes	
711	4020	1	2	S25		Office 201D	W3	Damaged plaster above windows	5	No	None	N/A	None	Yes	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
712	4020	1	2	S22		Office 202 Roster Office	W1	Peeling paint	5	No	None	N/A	None	No	
713	4020	1	2	S22		Office 202 Roster Office	W2	Peeling paint	25	No	None	N/A	None	No	
714	4020	1	2	S22		Office 202 Roster Office	W3	Peeling paint, efflorescence, debris on window sill	50	No	Window sill	5	None	No	
715	4020	1	2	S22		Office 203B	Floor	Debris	3	No	Debris	N/A	None	No	
716	4020	1	2	S22		Office 203B	W3	Severe efflorescence at column and above window, debris on window sill	20	No	Window sill	4	None	No	
717	4020	1	2	S22		Office 203C	W3	Efflorescence above window, debris on window sill	8	No	Window sill	2	None	No	
718	4020	1	2	210A		Office 203D	W2	Efflorescence above window, debris on window sill	6	No	Window sill	2	None	No	
719	4020	1	2	210A		Office 203D	W3	Peeling paint	10	No	None	N/A	None	No	
720	4020	1	2	H302		Office 203F Picture ID Room	W2	Peeling paint	2	No	None	N/A	None	No	
721	4020	1	2	H306		Office 203F Picture ID Room	W3	Peeling paint	2	No	None	N/A	None	No	
722	4020	1	2	214		Office 204, 1st Office from Left	Ceiling	No access						Inspection Needed	
723	4020	1	2	225B		Office 204, 1st Office from Left	Floor	No access						Inspection Needed	
724	4020	1	2	225B		Office 204, 1st Office from Left	W1	No access						Inspection Needed	
725	4020	1	2	201C		Office 204, 1st Office from Left	W2	No access						Inspection Needed	
726	4020	1	2	201G		Office 204, 1st Office from Left	W3	No access						Inspection Needed	
727	4020	1	2	202		Office 204, 1st Office from Left	W4	No access						Inspection Needed	
728	4020	1	2	202		Office 204, 2nd Office from Left	W4	Efflorescence, peeling and cracking paint, peeling paint on pipe, debris on window sill	40	No	Window sill	5	None	No	
729	4020	1	2	202		Office 204, 3rd Office from Left	W3	Severe peeling paint above window	10	No	None	N/A	None	No	
730	4020	1	2	203B		Office 204, Storage Room, 5th Room from Left	W3	Peeling paint on pipe	3	No	None	N/A	None	No	
731	4020	1	2	203B		Office 206 Special Education Suite Center Office	W3	Peeling paint	5	No	None	N/A	None	No	
732	4020	1	2	203C		Office 206 Special Education Suite Copy Room	W3	Peeling paint	5	No	None	N/A	None	No	
733	4020	1	2	203D		Office 206 Special Education Suite Large Left Office	W4	Severe peeling paint	5	No	None	N/A	None	No	
734	4020	1	2	203D		Office 206 Special Education Suite Left Office School Psychologist	W3	Severe peeling paint	25	No	None	N/A	None	No	
735	4020	1	2	203F		Office 208	Ceiling	No access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
736	4020	1	2	203F		Office 208	Floor	No access						Inspection Needed	
737	4020	1	2	204A		Office 208	W1	No access						Inspection Needed	
738	4020	1	2	204A		Office 208	W2	No access						Inspection Needed	
739	4020	1	2	204A		Office 208	W3	No access						Inspection Needed	
740	4020	1	2	204A		Office 208	W4	No access						Inspection Needed	
741	4020	1	2	204A		Office 209	Ceiling	Peeling paint	50	No	None	N/A	None	No	
742	4020	1	2	204A		Office 209	W1	Peeling paint	15	No	None	N/A	None	No	
743	4020	1	2	204B		Office 209	W2	Peeling paint	5	No	None	N/A	None	No	
744	4020	1	2	204C		Office 209	W3	Peeling paint	30	No	None	N/A	None	No	
745	4020	1	2	204E		Office 209	W4	Peeling paint	10	No	None	N/A	None	No	
746	4020	1	2	206B		Office 218 Educational Talent Search University of Pennsylvania Office	W4	Peeling paint at poster	5	No	None	N/A	None	No	
747	4020	1	2	206A		Office 221	W1	Peeling paint	10	No	None	N/A	None	No	
748	4020	1	2	206G		Office 221	W3	Peeling paint at top of window and debris on window sill	20	No	None	N/A	None	No	
749	4020	1	2	206F		Office 221	W4	Cracking paint	15	No	None	N/A	None	No	
750	4020	1	2	208		Office 221 Rear Office	Ceiling	No access						Inspection Needed	
751	4020	1	2	208		Office 221 Rear Office	Floor	No access						Inspection Needed	
752	4020	1	2	208		Office 221 Rear Office	W1	No access						Inspection Needed	
753	4020	1	2	208		Office 221 Rear Office	W2	No access						Inspection Needed	
754	4020	1	2	208		Office 221 Rear Office	W3	No access						Inspection Needed	
755	4020	1	2	208		Office 221 Rear Office	W4	No access						Inspection Needed	
756	4020	1	2	209		Office in Storage Room 203A	W3	Efflorescence above window, debris on window sill	10	No	Window sill	2	None	No	
757	4020	1	2	209		Principal's Conference Room	W2	Peeling paint on pipe	6	No	None	N/A	None	No	
758	4020	1	2	209		Stairwell A	W2	Peeling paint at control box	4	No	None	N/A	None	No	
759	4020	1	2	209		Stairwell across from Classroom 214	Ceiling	No access						Inspection Needed	
760	4020	1	2	209		Stairwell across from Classroom 214	Floor	No access						Inspection Needed	
761	4020	1	2	218		Stairwell across from Classroom 214	W1	No access						Inspection Needed	
762	4020	1	2	221		Stairwell across from Classroom 214	W2	No access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
763	4020	1	2	221		Stairwell across from Classroom 214	W3	No access						Inspection Needed	
764	4020	1	2	221		Stairwell across from Classroom 214	W4	No access						Inspection Needed	
765	4020	1	2	221A		Stairwell across from Classroom 214 Closet	Ceiling	No access						Inspection Needed	
766	4020	1	2	221A		Stairwell across from Classroom 214 Closet	Floor	No access						Inspection Needed	
767	4020	1	2	221A		Stairwell across from Classroom 214 Closet	W1	No access						Inspection Needed	
768	4020	1	2	221A		Stairwell across from Classroom 214 Closet	W2	No access						Inspection Needed	
769	4020	1	2	221A		Stairwell across from Classroom 214 Closet	W3	No access						Inspection Needed	
770	4020	1	2	221A		Stairwell across from Classroom 214 Closet	W4	No access						Inspection Needed	
771	4020	1	2	203G		Stairwell across from Classroom 214 Storage Room	Ceiling	No access						Inspection Needed	
772	4020	1	2	206D		Stairwell across from Classroom 214 Storage Room	Floor	No access						Inspection Needed	
773	4020	1	2	S20		Stairwell across from Classroom 214 Storage Room	W1	No access						Inspection Needed	
774	4020	1	2	S24		Stairwell across from Classroom 214 Storage Room	W2	No access						Inspection Needed	
775	4020	1	2	S24		Stairwell across from Classroom 214 Storage Room	W3	No access						Inspection Needed	
776	4020	1	2	S24		Stairwell across from Classroom 214 Storage Room	W4	No access						Inspection Needed	
777	4020	1	2	S24		Stairwell across from IMC	Ceiling	No access						Inspection Needed	
778	4020	1	2	S24		Stairwell across from IMC	Floor	No access						Inspection Needed	
779	4020	1	2	S24		Stairwell across from IMC	W1	No access						Inspection Needed	
780	4020	1	2	214D		Stairwell across from IMC	W2	No access						Inspection Needed	
781	4020	1	2	214D		Stairwell across from IMC	W3	No access						Inspection Needed	
782	4020	1	2	214D		Stairwell across from IMC	W4	No access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
783	4020	1	2	214D		Stairwell across from IMC Closet	Ceiling	No access						Inspection Needed	
784	4020	1	2	214D		Stairwell across from IMC Closet	Floor	No access						Inspection Needed	
785	4020	1	2	214D		Stairwell across from IMC Closet	W1	No access						Inspection Needed	
786	4020	1	2	214E		Stairwell across from IMC Closet	W2	No access						Inspection Needed	
787	4020	1	2	214E		Stairwell across from IMC Closet	W3	No access						Inspection Needed	
788	4020	1	2	214E		Stairwell across from IMC Closet	W4	No access						Inspection Needed	
789	4020	1	2	214E		Stairwell adjacent Principal's Office down to Main Entrance	W4	Peeling paint and efflorescence	20	No	None	N/A	None	No	
790	4020	1	2	214E		Stairwell C	Ceiling	Damaged plaster, Peeling paint, efflorescence	10	No	None	N/A	None	Yes	
791	4020	1	2	214E		Stairwell C	W4	Spalling and efflorescence	25	No	None	N/A	None	No	
792	4020	1	2	S23		Stairwell D	Ceiling	Severe peeling paint and efflorescence at middle landing	30	No	None	N/A	None	No	
793	4020	1	2	S23		Stairwell D	W2	Severe peeling paint and efflorescence	80	No	None	N/A	None	No	
794	4020	1	2	S23		Stairwell D	W3	Severe peeling paint and efflorescence	20	No	None	N/A	None	No	
795	4020	1	2	S23		Storage Room 201E	W3	Damaged plaster above windows	5	No	None	N/A	None	Yes	
796	4020	1	2	S23		Storage Room 203E	W1	Peeling paint	5	No	None	N/A	None	No	
797	4020	1	2	S23		Storage Room 203E	W2	Peeling paint	5	No	None	N/A	None	No	
798	4020	1	2	214F		Storage Room 203E	W3	Peeling paint	2	No	None	N/A	None	No	
799	4020	1	2	214F		Storage Room 203E	W4	Peeling paint	5	No	None	N/A	None	No	
800	4020	1	2	214F		Storage Room 220	W2	Severe peeling paint by copier	30	No	None	N/A	None	No	
801	4020	1	2	214F		Storage Room 220 Rear Office	W2	Severe peeling paint	50	No	None	N/A	None	No	
802	4020	1	2	214F		Storage Room 220 Rear Office	W3	Severe peeling paint	40	No	None	N/A	None	No	
803	4020	1	2	214F		Storage Room 220 Rear Office	W4	Severe peeling paint	20	No	None	N/A	None	No	
804	4020	1	2	S29		Storage Room adjacent Classroom 222	Ceiling	Damaged plaster	10	No	None	N/A	None	Yes	
805	4020	1	2	S26		Storage Room adjacent Classroom 222	Floor	Debris	20	No	Debris	N/A	None	No	
806	4020	1	2	S26		Storage Room between Elevator and Office 206	Ceiling	No access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
807	4020	1	2	S21		Storage Room between Elevator and Office 206	Floor	No access						Inspection Needed	
808	4020	1	2	S21		Storage Room between Elevator and Office 206	W1	No access						Inspection Needed	
809	4020	1	2	S21		Storage Room between Elevator and Office 206	W2	No access						Inspection Needed	
810	4020	1	2	201E		Storage Room between Elevator and Office 206	W3	No access						Inspection Needed	
811	4020	1	2	203E		Storage Room between Elevator and Office 206	W4	No access						Inspection Needed	
812	4020	1	2	203E		Storage Room between Office 206 and Classroom 210	W3	Crack in plaster wall	2	No	None	N/A	None	Yes	
813	4020	1	2	203E		Women's Restroom	Ceiling	Damaged plaster at the door, peeling paint on ceiling and ductwork	15	No	None	N/A	None	Yes	
814	4020	1	2	203E		Women's Restroom	W2	Peeling paint	10	No	None	N/A	None	No	
815	4020	1	2	220		Women's Restroom	W4	Cracking paint	15	No	None	N/A	None	No	
816	4020	1	2	220A		Women's Restroom Lounge Area	W3	Damaged plaster, Peeling paint, efflorescence at top of window	20	No	None	N/A	None	Yes	
817	4020	1	2	220A		Athletic Director's Office	Ceiling	Peeling paint	25	No	None	N/A	None	No	
818	4020	1	2	220A		Athletic Director's Office	W4	Peeling paint	3	No	None	N/A	None	No	
819	4020	1	2	222A		Athletic Director's Office Restroom	Ceiling	Severe peeling paint on ductwork	12	No	None	N/A	None	No	
820	4020	1	2	222A		Athletic Director's Office Storage Room	Ceiling	Peeling paint along back wall	10	No	None	N/A	None	No	
821	4020	1	2	201D		Auditorium	Ceiling	Efflorescence	20	No	None	N/A	None	No	
822	4020	1	2	201D		Auditorium	Floor	Debris by window near stage	15	No	Debris	N/A	None	No	
823	4020	1	2	201D		Auditorium	W2	Efflorescence	10	No	None	N/A	None	No	
824	4020	1	2	201D		Boy's Restroom	Ceiling	Efflorescence	30	No	None	N/A	None	No	
825	4020	1	2	201D		Boy's Restroom	W2	Efflorescence	25	No	None	N/A	None	No	
826	4020	1	2	201D		Boy's Restroom	W4	Peeling paint, efflorescence at window	10	No	None	N/A	None	No	
827	4020	1	2	210B		Boy's Restroom adjacent to Gym	W1	Peeling paint	50	No	None	N/A	None	No	
828	4020	1	2	225C		Boy's Restroom adjacent to Gym	W2	Peeling paint	150	No	None	N/A	None	No	
829	4020	1	2	225C		Boy's Restroom adjacent to Gym	W3	Peeling paint	50	No	None	N/A	None	No	
830	4020	1	2	225C		Boy's Restroom adjacent to Gym	W4	Peeling paint	100	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
831	4020	1	2	225A		Classroom 102	W1	Peeling paint on double doors and control box	30	No	None	N/A	None	No	
832	4020	2	1	020A		Classroom 103	W3	Peeling paint on pipes	10	No	None	N/A	None	No	
833	4020	2	1	020A		Classroom 105	Ceiling	Peeling paint, efflorescence at window	20	No	None	N/A	None	No	
834	4020	2	1	019A		Classroom 105	W2	Efflorescence at window	3	No	None	N/A	None	No	
835	4020	2	1	020B		Classroom 105 Closet	Ceiling	No Access						Inspection Needed	
836	4020	1	1	115		Classroom 105 Closet	Floor	No Access						Inspection Needed	
837	4020	1	1	115		Classroom 105 Closet	W1	No Access						Inspection Needed	
838	4020	1	1	115		Classroom 105 Closet	W2	No Access						Inspection Needed	
839	4020	1	1	116		Classroom 105 Closet	W3	No Access						Inspection Needed	
840	4020	1	1	116		Classroom 105 Closet	W4	No Access						Inspection Needed	
841	4020	1	1	116		Classroom 106 on Left	Ceiling	Peeling paint and efflorescence by window	10	No	None	N/A	None	No	
842	4020	2	1	010A		Classroom 106 on Left	W4	Peeling paint on pipe	12	No	None	N/A	None	No	
843	4020	2	1	010A		Classroom 106 on Right	Ceiling	Peeling paint	20	No	None	N/A	None	No	
844	4020	2	1	010A		Classroom 106 on Right	W1	Holes in plaster wall	3	No	None	N/A	None	Yes	
845	4020	2	1	010A		Classroom 106 on Right Closet	W3	Peeling paint	5	No	None	N/A	None	No	
846	4020	1	1	102		Classroom 107	W1	Peeling and cracking paint	30	No	None	N/A	None	No	
847	4020	1	1	102A		Classroom 107	W3	Peeling and cracking paint	50	No	None	N/A	None	No	
848	4020	1	1	103		Classroom 108	W1	Peeling paint on control panels	10	No	None	N/A	None	No	
849	4020	1	1	103		Classroom 108	W2	Peeling paint by window	3	No	None	N/A	None	No	
850	4020	1	1	105C		Classroom 108	W3	Efflorescence	30	No	None	N/A	None	No	
851	4020	1	1	105C		Classroom 109A	W1	Peeling paint	2	No	None	N/A	None	No	
852	4020	1	1	105C		Classroom 109A	W4	Efflorescence, Damaged plaster above windows, Debris on window sill	15	No	None	N/A	None	Yes	
853	4020	1	1	105C		Classroom 110	Floor	Stair components	25	No	None	N/A	None	No	
854	4020	1	1	105C		Classroom 110	W3	Peeling paint	3	No	None	N/A	None	No	
855	4020	1	1	105C		Classroom 110 Office	Ceiling	Severe peeling paint	60	No	None	N/A	None	No	
856	4020	1	1	106		Classroom 110 Office	W3	Efflorescence	25	No	None	N/A	None	No	
857	4020	1	1	106		Classroom 110 Office	W4	Peeling paint	20	No	None	N/A	None	No	
858	4020	1	1	106C		Classroom 117	Ceiling	Peeling paint	20	No	None	N/A	None	No	
859	4020	1	1	106C		Classroom 117	W2	Peeling and cracking paint	15	No	None	N/A	None	No	
860	4020	1	1	106E		Classroom 117	W4	Peeling and cracking paint on wall and peeling paint on pipe	40	No	None	N/A	None	No	
861	4020	1	1	107		Classroom 118	W2	Damaged plaster	10	No	None	N/A	None	Yes	
862	4020	1	1	107		Classroom 118	W3	Peeling paint	5	No	None	N/A	None	No	
863	4020	1	1	108		Classroom 118	W4	Peeling paint	5	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
864	4020	1	1	108		Classroom 119	W3	Severe peeling paint, efflorescence at window, debris on window sill	80	No	Window sill	10	None	No	
865	4020	1	1	108		Classroom 119	W4	Severe peeling paint, Efflorescence	150	No	None	N/A	None	No	
866	4020	1	1	109A		Classroom 121 Closet	Ceiling	No Access						Inspection Needed	
867	4020	1	1	109A		Classroom 121 Closet	Floor	No Access						Inspection Needed	
868	4020	1	1	110		Classroom 121 Closet	W1	No Access						Inspection Needed	
869	4020	1	1	110		Classroom 121 Closet	W2	No Access						Inspection Needed	
870	4020	1	1	109		Classroom 121 Closet	W3	No Access						Inspection Needed	
871	4020	1	1	109		Classroom 121 Closet	W4	No Access						Inspection Needed	
872	4020	1	1	109		Elevator adjacent Stairwell A	Ceiling	No access - Sealed off						Inspection Needed	
873	4020	1	1	117		Elevator adjacent Stairwell A	Floor	No access - Sealed off						Inspection Needed	
874	4020	1	1	117		Elevator adjacent Stairwell A	W1	No access - Sealed off						Inspection Needed	
875	4020	1	1	117		Elevator adjacent Stairwell A	W2	No access - Sealed off						Inspection Needed	
876	4020	1	1	118		Elevator adjacent Stairwell A	W3	No access - Sealed off						Inspection Needed	
877	4020	1	1	118		Elevator adjacent Stairwell A	W4	No access - Sealed off						Inspection Needed	
878	4020	1	1	118		Faculty Room adjacent to Men's Restroom	Ceiling	Peeling paint	10	No	None	N/A	None	No	
879	4020	1	1	119		Fire Tower adjacent Large Cafeteria	Ceiling	Severe peeling paint	400	No	None	N/A	None	No	
880	4020	1	1	119		Fire Tower adjacent Large Cafeteria	Floor	Debris	200	No	Debris	N/A	None	No	
881	4020	1	1	121A		Fire Tower adjacent Large Cafeteria	W1	Severe peeling paint	200	No	None	N/A	None	No	
882	4020	1	1	121A		Fire Tower adjacent Large Cafeteria	W2	Severe peeling paint	200	No	None	N/A	None	No	
883	4020	1	1	121A		Fire Tower adjacent Large Cafeteria	W3	Severe peeling paint	200	No	None	N/A	None	No	
884	4020	1	1	121A		Fire Tower adjacent Large Cafeteria	W4	Severe peeling paint	200	No	None	N/A	None	No	
885	4020	1	1	121A		Fire Tower adjacent Office 110	Ceiling	Severe peeling paint	400	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
886	4020	1	1	121A		Fire Tower adjacent Office 110	Floor	Derbis	200	No	Debris	N/A	None	No	
887	4020	1	1	110H		Fire Tower adjacent Office 110	W1	Severe peeling paint	200	No	None	N/A	None	No	
888	4020	1	1	110H		Fire Tower adjacent Office 110	W2	Severe peeling paint	200	No	None	N/A	None	No	
889	4020	1	1	110H		Fire Tower adjacent Office 110	W3	Severe peeling paint	200	No	None	N/A	None	No	
890	4020	1	1	110H		Fire Tower adjacent Office 110	W4	Severe peeling paint	200	No	None	N/A	None	No	
891	4020	1	1	110H		Girl's Restroom	Ceiling	Peeling paint and efflorescence	30	No	None	N/A	None	No	
892	4020	1	1	110H		Gym Office	Ceiling	Peeling paint	10	No	None	N/A	None	No	
893	4020	1	1	104		Gym Office Restroom	Ceiling	Peeling paint on ceiling and ductwork	30	No	None	N/A	None	No	
894	4020	1	1	S16		Gym over Boy's Locker Room	Ceiling	Peeling paint on ductwork	100	No	None	N/A	None	No	
895	4020	1	1	S16		Gym over Boy's Locker Room	W4	Peeling paint	10	No	None	N/A	None	No	
896	4020	1	1	S16		Gym over Girl's Locker Room	Ceiling	Peeling paint on ductwork	100	No	None	N/A	None	No	
897	4020	1	1	S16		Hallway between Classrooms 103 & 104	Ceiling	Peeling paint	25	No	None	N/A	None	No	
898	4020	1	1	S16		Hallway outside Classrooms 100-101	Ceiling	Peeling paint	100	No	None	N/A	None	No	
899	4020	1	1	S16		Hallway outside Classrooms 100-101	W3	Cracking paint	3	No	None	N/A	None	No	
900	4020	1	1	S12		Hallway outside Classrooms 102-104	Ceiling	Peeling paint	40	No	None	N/A	None	No	
901	4020	1	1	S12		Hallway outside Gym Offices	Ceiling	Peeling paint	10	No	None	N/A	None	No	
902	4020	1	1	S12		Hallway outside Restrooms adjacent to Gym	Ceiling	Peeling paint	20	No	None	N/A	None	No	
903	4020	1	1	S12		Hallway to Side Entrance adjacent Blower Room 3	Ceiling	Damaged plaster and efflorescence	20	No	None	N/A	None	Yes	
904	4020	1	1	S12		Hallway to Side Entrance adjacent Blower Room 3	W2	Cracking paint	5	No	None	N/A	None	No	
905	4020	1	1	S12		Hallway to Side Entrance adjacent Blower Room 3	W4	Cracking paint	5	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
906	4020	1	1	112A		Hallway to Side Entrance adjacent Classrooms 100 & 121	W3	Peeling paint and efflorescence	10	No	None	N/A	None	No	
907	4020	2	1	015A		Hallway to Side Entrance adjacent Classrooms 100 & 121	W4	Cracking paint	10	No	None	N/A	None	No	
908	4020	2	1	016A		Kitchen Restroom	W3	Peeling paint behind radiator	3	No	None	N/A	None	No	
909	4020	2	1	013A		Kitchen Storage Room closest to Small Cafeteria	W2	Severe peeling paint, cracking paint	25	No	None	N/A	None	No	
910	4020	2	1	013A		Kitchen Storage Room closest to Small Cafeteria	W3	Severe peeling paint, cracking paint	40	No	None	N/A	None	No	
911	4020	2	1	014A		Large Cafeteria	W4	Peeling paint on pipe by window	10	No	None	N/A	None	No	
912	4020	1	1	103C		Men's Restroom	Ceiling	Peeling and cracking paint	50	No	None	N/A	None	No	
913	4020	1	1	H102		Men's Restroom	W1	Peeling paint	30	No	None	N/A	None	No	
914	4020	1	1	H102		Men's Restroom	W2	Peeling paint	40	No	None	N/A	None	No	
915	4020	1	1	H100		Men's Restroom	W3	Peeling and cracking paint	50	No	None	N/A	None	No	
916	4020	2	1	H08		Men's Restroom	W4	Cracking paint	20	No	None	N/A	None	No	
917	4020	2	1	H09		Office 120 School Police Common Area	W4	Hole in drywall wall	1	No	None	N/A	None	No	
918	4020	1	1	H11		Office 120B School Police Office 2nd Office From Left	W4	Severe efflorescence	30	No	None	N/A	None	No	
919	4020	1	1	H11		Office 120C School Police Video Monitoring Room 3rd Office from Left	W3	Covered with paper and photos - Needs to be inspected		No	None	N/A	None	No	
920	4020	1	1	H11		Office 120D School Police Office 4th Office from Left	W3	Spalling, efflorescence	30	No	None	N/A	None	No	
921	4020	1	1	H12		Old Boy's Large Locker Room	Ceiling	Damaged plaster, Peeling paint, efflorescence	50	No	None	N/A	None	Yes	
922	4020	1	1	H12		Old Boy's Large Locker Room	Floor	Debris	40	No	Debris	N/A	None	No	
923	4020	1	1	114C		Old Boy's Large Locker Room	W1	Peeling paint	25	No	None	N/A	None	No	
924	4020	1	1	114E		Old Boy's Large Locker Room Closet	Ceiling	Severe efflorescence	25	No	None	N/A	None	No	
925	4020	1	1	114E		Old Boy's Large Locker Room Closet	Floor	Debris	25	No	Debris	N/A	None	No	
926	4020	1	1	114		Old Boy's Large Locker Room Closet	W1	Peeling paint	5	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
927	4020	1	1	102B		Old Boy's Large Locker Room Closet	W2	Peeling paint on wall and pipe	15	No	None	N/A	None	No	
928	4020	1	1	102B		Old Boy's Large Locker Room Closet	W3	Peeling paint	5	No	None	N/A	None	No	
929	4020	1	1	102B		Old Boy's Large Locker Room Closet	W4	Peeling paint	5	No	None	N/A	None	No	
930	4020	1	1	102B		Old Boy's Large Locker Room Restroom	Ceiling	Peeling paint on pipe	10	No	None	N/A	None	No	
931	4020	1	1	102B		Old Boy's Large Locker Room Restroom	Floor	Debris	10	No	Debris	N/A	None	No	
932	4020	1	1	120		Old Boy's Large Locker Room Restroom	W1	Peeling paint	30	No	None	N/A	None	No	
933	4020	1	1	120B		Old Boy's Large Locker Room Restroom	W2	Peeling paint on wall and pipe	20	No	None	N/A	None	No	
934	4020	1	1	120C		Old Boy's Large Locker Room Restroom	W3	Peeling paint	15	No	None	N/A	None	No	
935	4020	1	1	120D		Old Boy's Large Locker Room Showers	Ceiling	Peeling paint	100	No	None	N/A	None	No	
936	4020	1	1	199		Old Boy's Large Locker Room Showers	Floor	Debris	100	No	Debris	N/A	None	No	
937	4020	1	1	199		Old Boy's Small Upper Locker Room	Ceiling	Peeling paint	50	No	None	N/A	None	No	
938	4020	1	1	199		Old Boy's Small Upper Locker Room	Floor	Debris	50	No	Debris	N/A	None	No	
939	4020	1	1	199C		Old Boy's Small Upper Locker Room	W1	Peeling paint on wall and pipe	20	No	None	N/A	None	No	
940	4020	1	1	199C		Old Boy's Small Upper Locker Room	W4	Peeling paint	40	No	None	N/A	None	No	
941	4020	1	1	199C		Old Girl's Large Locker Room	Ceiling	Damaged plaster and peeling paint	60	No	None	N/A	None	Yes	
942	4020	1	1	199C		Old Girl's Large Locker Room	Floor	Debris	30	No	Debris	N/A	None	No	
943	4020	1	1	199C		Old Girl's Large Locker Room	W1	Peeling paint	5	No	None	N/A	None	No	
944	4020	1	1	199C		Old Girl's Large Locker Room	W2	Peeling paint and efflorescence	40	No	None	N/A	None	No	
945	4020	1	1	199B		Old Girl's Large Locker Room	W3	Peeling paint	10	No	None	N/A	None	No	
946	4020	1	1	199B		Old Girl's Large Locker Room	W4	Damaged plaster and peeling paint	10	No	None	N/A	None	Yes	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
947	4020	1	1	199B		Old Girl's Large Locker Room Closet	Floor	Debris	3	No	Debris	N/A	None	No	
948	4020	1	1	199B		Old Girl's Large Locker Room Closet	W3	Peeling paint	5	No	None	N/A	None	No	
949	4020	1	1	199B		Old Girl's Large Locker Room Closet	W4	Peeling paint on wall and pipe	15	No	None	N/A	None	No	
950	4020	1	1	199A		Old Girl's Large Locker Room Restroom	Ceiling	Peeling paint at window	10	No	None	N/A	None	No	
951	4020	1	1	199A		Old Girl's Large Locker Room Restroom	Floor	Debris	30	No	Debris	N/A	None	No	
952	4020	1	1	199D		Old Girl's Large Locker Room Showers	Ceiling	Severe peeling paint	120	No	None	N/A	None	No	
953	4020	1	1	199D		Old Girl's Large Locker Room Showers	Floor	Debris	100	No	Debris	N/A	None	No	
954	4020	1	1	199D		Old Girl's Small Upper Locker Room	Ceiling	Peeling paint - right corner	10	No	None	N/A	None	No	
955	4020	1	1	199D		Old Girl's Small Upper Locker Room	Floor	Debris	30	No	Debris	N/A	None	No	
956	4020	1	1	198		Old Girl's Small Upper Locker Room	W1	Peeling paint on pipe	10	No	None	N/A	None	No	
957	4020	1	1	198		Old Girl's Small Upper Locker Room	W3	Peeling paint - right corner	5	No	None	N/A	None	No	
958	4020	1	1	198		School Police Storage across from Blower Room 3	W1	Major crack in the plaster wall	20	No	None	N/A	None	Yes	
959	4020	1	1	198		School Police Storage across from Blower Room 3	W4	Damaged plaster	5	No	None	N/A	None	Yes	
960	4020	1	1	198		Stairwell C	W4	Severe efflorescence	100	No	None	N/A	None	No	
961	4020	1	1	198		Stairwell D	Floor	Debris	10	No	Debris	N/A	None	No	
962	4020	1	1	198C		Stairwell D	W2	Severe peeling paint, efflorescence, damaged plaster	150	No	None	N/A	None	Yes	
963	4020	1	1	198C		Stairwell from Kitchen to Boiler Room	Ceiling	Severe efflorescence	80	No	None	N/A	None	No	
964	4020	1	1	198C		Stairwell from Kitchen to Boiler Room	Floor	Debris	20	No	Debris	N/A	None	No	
965	4020	1	1	198B		Stairwell from Kitchen to Boiler Room	W1	Peeling paint	30	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
966	4020	1	1	198B		Stairwell from Kitchen to Boiler Room	W2	Peeling paint	35	No	None	N/A	None	No	
967	4020	1	1	198A		Stairwell from Kitchen to Boiler Room	W3	Peeling paint	25	No	None	N/A	None	No	
968	4020	1	1	198A		Stairwell from Kitchen to Boiler Room	W4	Peeling paint	30	No	None	N/A	None	No	
969	4020	1	1	198D		Stairwell to Cheerleading Gym	Ceiling	Severe peeling paint and efflorescence	100	No	None	N/A	None	No	
970	4020	1	1	198D		Stairwell to Cheerleading Gym	Floor	Debris	25	No	Debris	N/A	None	No	
971	4020	1	1	198D		Stairwell to Old Boy's Locker Room	Ceiling	Severe peeling paint and efflorescence	75	No	None	N/A	None	No	
972	4020	1	1	198D		Stairwell to Old Boy's Locker Room	Floor	Debris on floor and stairs	100	No	Debris	N/A	None	No	
973	4020	1	1	117A		Stairwell to Old Boy's Locker Room	W1	Peeling paint	10	No	None	N/A	None	No	
974	4020	1	1	117A		Stairwell to Old Boy's Locker Room	W2	Peeling paint on wall and pipe	20	No	None	N/A	None	No	
975	4020	1	1	S11		Stairwell to Old Boy's Locker Room	W3	Peeling paint	10	No	None	N/A	None	No	
976	4020	1	1	S17		Stairwell to Old Boy's Locker Room	W4	Peeling paint	10	No	None	N/A	None	No	
977	4020	1	1	S17		Stairwell to Old Girl's Locker Room	Ceiling	Damaged plaster and peeling paint	100	No	None	N/A	None	Yes	
978	4020	1	1	S02		Stairwell to Old Girl's Locker Room	Floor	Debris	100	No	Debris	N/A	None	No	
979	4020	1	1	S02		Stairwell to Old Girl's Locker Room	W1	Peeling paint	2	No	None	N/A	None	No	
980	4020	1	1	S02		Stairwell to Old Girl's Locker Room	W2	Peeling paint	2	No	None	N/A	None	No	
981	4020	1	1	S02		Stairwell to Old Girl's Locker Room	W3	Peeling paint	2	No	None	N/A	None	No	
982	4020	1	1	S02		Stairwell to Old Girl's Locker Room	W4	Peeling paint on wall and pipe	22	No	None	N/A	None	No	
983	4020	1	1	S02		Stairwell to Oxford Street Entrance	Ceiling	Peeling paint	40	No	None	N/A	None	No	
984	4020	1	1	S08		Stairwell to Oxford Street Entrance	W3	Peeling paint above exit doors	50	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
985	4020	1	1	S08		Storage Closet between Classroom 100 & Side Entrance	Ceiling	No Access						Inspection Needed	
986	4020	1	1	199E		Storage Closet between Classroom 100 & Side Entrance	Floor	No Access						Inspection Needed	
987	4020	1	1	199E		Storage Closet between Classroom 100 & Side Entrance	W1	No Access						Inspection Needed	
988	4020	1	1	199E		Storage Closet between Classroom 100 & Side Entrance	W2	No Access						Inspection Needed	
989	4020	1	1	199E		Storage Closet between Classroom 100 & Side Entrance	W3	No Access						Inspection Needed	
990	4020	1	1	199E		Storage Closet between Classroom 100 & Side Entrance	W4	No Access						Inspection Needed	
991	4020	1	1	199E		Storage Room adjacent Athletic Director's Office	Ceiling	Peeling paint on wall and ductwork	70	No	None	N/A	None	No	
992	4020	1	1	S01		Storage Room adjacent Athletic Director's Office	W1	Peeling paint	3	No	None	N/A	None	No	
993	4020	1	1	S01		Storage Room adjacent Gym Office	Ceiling	Severe peeling paint on ductwork	100	No	None	N/A	None	No	
994	4020	1	1	S01		Storage Room between Elevator and Office 105/105A/Old Boy's Locker Room	Ceiling	No Access						Inspection Needed	
995	4020	1	1	S01		Storage Room between Elevator and Office 105/105A/Old Boy's Locker Room	Floor	No Access						Inspection Needed	
996	4020	1	1	S01		Storage Room between Elevator and Office 105/105A/Old Boy's Locker Room	W1	No Access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
997	4020	1	1	S01		Storage Room between Elevator and Office 105/105A/Old Boy's Locker Room	W2	No Access						Inspection Needed	
998	4020	2	1	S88		Storage Room between Elevator and Office 105/105A/Old Boy's Locker Room	W3	No Access						Inspection Needed	
999	4020	2	1	S88		Storage Room between Elevator and Office 105/105A/Old Boy's Locker Room	W4	No Access						Inspection Needed	
1000	4020	1	1	122A		Storage Room between Elevator and Office 120	Ceiling	No Access						Inspection Needed	
1001	4020	1	1	122A		Storage Room between Elevator and Office 120	Floor	No Access						Inspection Needed	
1002	4020	1	1	122A		Storage Room between Elevator and Office 120	W1	No Access						Inspection Needed	
1003	4020	1	1	122A		Storage Room between Elevator and Office 120	W2	No Access						Inspection Needed	
1004	4020	1	1	122A		Storage Room between Elevator and Office 120	W3	No Access						Inspection Needed	
1005	4020	1	1	122A		Storage Room between Elevator and Office 120	W4	No Access						Inspection Needed	
1006	4020	2	1	018A		Ticket Booth near Cheerleading Gym	Ceiling	No Access						Inspection Needed	
1007	4020	2	1	018A		Ticket Booth near Cheerleading Gym	Floor	No Access						Inspection Needed	
1008	4020	2	1	017A		Ticket Booth near Cheerleading Gym	W1	No Access						Inspection Needed	
1009	4020	1	1	105		Ticket Booth near Cheerleading Gym	W2	No Access						Inspection Needed	
1010	4020	1	1	105		Ticket Booth near Cheerleading Gym	W3	No Access						Inspection Needed	
1011	4020	1	1	105		Ticket Booth near Cheerleading Gym	W4	No Access						Inspection Needed	
1012	4020	1	1	105		Ticket Booth near ROTC area	Ceiling	Peeling paint	5	No	None	N/A	None	No	
1013	4020	1	1	105		Ticket Booth near ROTC area	W4	Peeling paint	15	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1014	4020	1	1	105		Vestibule at Entrance to Classrooms 109A & 109B	W3	Damaged plaster	5	No	None	N/A	None	Yes	
1015	4020	1	1	110F		Vestibule at Entrance To Classrooms 117 & 118	W2	Damaged plaster, cracking paint	5	No	None	N/A	None	Yes	
1016	4020	1	1	110F		Vestibule at Entrance to two Storage Rooms adjacent to Classroom 100	W2	Peeling and cracking paint	10	No	None	N/A	None	No	
1017	4020	1	1	110F		Vestibule at Entrance to two Storage Rooms adjacent to Classroom 100	W4	Peeling and cracking paint	10	No	None	N/A	None	No	
1018	4020	1	1	110F		Women's Restroom near Main Entrance	W2	Cracking paint, hole in plaster wall	5	No	None	N/A	None	Yes	
1019	4020	1	1	110F		Women's Restroom near Main Entrance	W3	Cracking paint, hole in plaster wall	5	No	None	N/A	None	Yes	
1020	4020	1	1	110F		Women's Restroom near Main Entrance	W4	Cracking paint	20	No	None	N/A	None	No	
1021	4020	1	1	112B		1st Storage Room on Right in Hallway from Stairwell C to Cheerleading Gym	Ceiling	Severe peeling paint	60	No	None	N/A	None	No	
1022	4020	1	1	112B		1st Storage Room on Right in Hallway from Stairwell C to Cheerleading Gym	W1	Peeling paint	20	No	None	N/A	None	No	
1023	4020	1	1	112B		1st Storage Room on Right in Hallway from Stairwell C to Cheerleading Gym	W2	Severe peeling paint on wall and pipes	40	No	None	N/A	None	No	
1024	4020	1	1	112B		1st Storage Room on Right in Hallway from Stairwell C to Cheerleading Gym	W4	Peeling paint	10	No	None	N/A	None	No	
1025	4020	1	1	112B		2nd Storage Room on Right in Hallway from Stairwell C to Cheerleading Gym	Ceiling	No access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1026	4020	1	1	112B		2nd Storage Room on Right in Hallway from Stairwell C to Cheerleading Gym	Floor	No access						Inspection Needed	
1027	4020	1	1	114G		2nd Storage Room on Right in Hallway from Stairwell C to Cheerleading Gym	W1	No access						Inspection Needed	
1028	4020	1	1	114G		2nd Storage Room on Right in Hallway from Stairwell C to Cheerleading Gym	W2	No access						Inspection Needed	
1029	4020	1	1	109E		2nd Storage Room on Right in Hallway from Stairwell C to Cheerleading Gym	W3	No access						Inspection Needed	
1030	4020	1	1	118A		2nd Storage Room on Right in Hallway from Stairwell C to Cheerleading Gym	W4	No access						Inspection Needed	
1031	4020	1	1	122B		3rd Storage Room on Right with Gate in Hallway from Stairwell C to Cheerleading Gym	W1	Peeling paint on pipe	8	No	None	N/A	None	No	Floor appears to be collapsing
1032	4020	1	1	122B		Boy's Locker Room	Ceiling	Peeling paint on ceiling and ductwork	100	No	None	N/A	None	No	
1033	4020	1	1	106B		Boy's Locker Room Corner Equipment Room	Ceiling	Peeling paint	15	No	None	N/A	None	No	
1034	4020	1	1	106B		Boy's Locker Room Custodial Closet and Pipe Chase	Ceiling	No Access						Inspection Needed	
1035	4020	1	1	106B		Boy's Locker Room Custodial Closet and Pipe Chase	Floor	No Access						Inspection Needed	
1036	4020	1	0	22		Boy's Locker Room Custodial Closet and Pipe Chase	W1	No Access						Inspection Needed	
1037	4020	1	0	22		Boy's Locker Room Custodial Closet and Pipe Chase	W2	No Access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1038	4020	1	0	22		Boy's Locker Room Custodial Closet and Pipe Chase	W3	No Access						Inspection Needed	
1039	4020	1	0	22		Boy's Locker Room Custodial Closet and Pipe Chase	W4	No Access						Inspection Needed	
1040	4020	1	0	21		Boy's Locker Room Medium Locker Room to Right of Entrance	Ceiling	No Access						Inspection Needed	
1041	4020	1	0	21		Boy's Locker Room Medium Locker Room to Right of Entrance	Floor	No Access						Inspection Needed	
1042	4020	1	0	21		Boy's Locker Room Medium Locker Room to Right of Entrance	W1	No Access						Inspection Needed	
1043	4020	1	0	21		Boy's Locker Room Medium Locker Room to Right of Entrance	W2	No Access						Inspection Needed	
1044	4020	1	0	21		Boy's Locker Room Medium Locker Room to Right of Entrance	W3	No Access						Inspection Needed	
1045	4020	1	0	21		Boy's Locker Room Medium Locker Room to Right of Entrance	W4	No Access						Inspection Needed	
1046	4020	1	0	20		Boy's Locker Room Medium Locker Room to Right of Entrance Storage Room	Ceiling	No Access						Inspection Needed	
1047	4020	2	0	010B		Boy's Locker Room Medium Locker Room to Right of Entrance Storage Room	Floor	No Access						Inspection Needed	
1048	4020	2	0	010E		Boy's Locker Room Medium Locker Room to Right of Entrance Storage Room	W1	No Access						Inspection Needed	
1049	4020	2	0	007B		Boy's Locker Room Medium Locker Room to Right of Entrance Storage Room	W2	No Access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1050	4020	2	0	007B		Boy's Locker Room Medium Locker Room to Right of Entrance Storage Room	W3	No Access						Inspection Needed	
1051	4020	2	0	007B		Boy's Locker Room Medium Locker Room to Right of Entrance Storage Room	W4	No Access						Inspection Needed	
1052	4020	2	0	007B		Boy's Locker Room Small Locker Room to Left of Entrance	Ceiling	No Access						Inspection Needed	
1053	4020	2	0	007B		Boy's Locker Room Small Locker Room to Left of Entrance	Floor	No Access						Inspection Needed	
1054	4020	2	0	007B		Boy's Locker Room Small Locker Room to Left of Entrance	W1	No Access						Inspection Needed	
1055	4020	2	0	010C		Boy's Locker Room Small Locker Room to Left of Entrance	W2	No Access						Inspection Needed	
1056	4020	2	0	010C		Boy's Locker Room Small Locker Room to Left of Entrance	W3	No Access						Inspection Needed	
1057	4020	2	0	010C		Boy's Locker Room Small Locker Room to Left of Entrance	W4	No Access						Inspection Needed	
1058	4020	2	0	010C		Break Room in Stairwell from Boiler Room to Electrical Room	Ceiling	No access						Inspection Needed	
1059	4020	2	0	010C		Break Room in Stairwell from Boiler Room to Electrical Room	Floor	No access						Inspection Needed	
1060	4020	2	0	010C		Break Room in Stairwell from Boiler Room to Electrical Room	W1	No access						Inspection Needed	
1061	4020	2	0	010D		Break Room in Stairwell from Boiler Room to Electrical Room	W2	No access						Inspection Needed	
1062	4020	2	0	010D		Break Room in Stairwell from Boiler Room to Electrical Room	W3	No access						Inspection Needed	

Overbrook HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1063	4020	2	0	010D		Break Room in Stairwell from Boiler Room to Electrical Room	W4	No access						Inspection Needed	
1064	4020	2	0	010D		Cheerleading Gym	Ceiling	Metal components	150	No	None	N/A	None	No	
1065	4020	2	0	010D		Cheerleading Gym	W1	Peeling paint, spalling	40	No	None	N/A	None	No	
1066	4020	2	0	010D		Cheerleading Gym	W2	Peeling paint	20	No	None	N/A	None	No	
1067	4020	2	0	012A		Cheerleading Gym	W3	Peeling paint	20	No	None	N/A	None	No	
1068	4020	2	0	012A		Cheerleading Gym	W4	Peeling paint and efflorescence	40	No	None	N/A	None	No	
1069	4020	2	0	012A		Cheerleading Gym Storage Room with Door	Ceiling	Peeling paint	5	No	None	N/A	None	No	
1070	4020	2	0	012A		Cheerleading Gym Storage Room with Door	W1	Peeling paint at right corner column	40	No	None	N/A	None	No	
1071	4020	2	0	012A		Classroom 10	W3	Peeling paint, efflorescence	80	No	None	N/A	None	No	
1072	4020	2	0	012A		Classroom 10 Closet	W4	Peeling paint and efflorescence	10	No	None	N/A	None	No	
1073	4020	1	0	015D		Equipment Room outside Boy's Locker Room	Ceiling	No Access						Inspection Needed	
1074	4020	1	0	015D		Equipment Room outside Boy's Locker Room	Floor	No Access						Inspection Needed	
1075	4020	1	0	015D		Equipment Room outside Boy's Locker Room	W1	No Access						Inspection Needed	
1076	4020	1	0	015D		Equipment Room outside Boy's Locker Room	W2	No Access						Inspection Needed	
1077	4020	1	0	015D		Equipment Room outside Boy's Locker Room	W3	No Access						Inspection Needed	
1078	4020	1	0	015D		Equipment Room outside Boy's Locker Room	W4	No Access						Inspection Needed	
1079	4020	1	0	19		Former Auto Shop Storage Area adjacent Large Shop	Ceiling	Peeling paint	30	No	None	N/A	None	No	
1080	4020	1	0	19		Former Auto Shop Storage Area adjacent Large Shop	Floor	Debris	30	No	Debris	N/A	None	No	
1081	4020	1	0	19		Former Auto Shop Storage Area adjacent Large Shop	W1	Peeling paint	30	No	None	N/A	None	No	
1082	4020	1	0	19		Former Auto Shop Storage Area adjacent Large Shop	W2	Peeling paint	30	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1083	4020	1	0	19		Former Auto Shop Storage Area adjacent Large Shop	W3	Peeling paint	30	No	None	N/A	None	No	
1084	4020	1	0	019A		Former Auto Shop Storage Area adjacent Large Shop	W4	Peeling paint	30	No	None	N/A	None	No	
1085	4020	1	0	019A		Former Daycare Infants	W3	Peeling paint, spalling, efflorescence	50	No	None	N/A	None	No	
1086	4020	1	0	001A		Former Daycare Infants	W4	Peeling paint	20	No	None	N/A	None	No	
1087	4020	1	0	001D		Former Daycare Office adjacent to Kitchen	Floor	Debris at window	10	No	Debris	N/A	None	No	
1088	4020	2	0	012B		Former Daycare Office adjacent to Kitchen	W3	Peeling paint	20	No	None	N/A	None	No	
1089	4020	2	0	012B		Former Daycare Toddlers	Floor	Debris on floor and radiator casing tops	50	No	Radiator casing tops	25	None	No	
1090	4020	2	0	012B		Former Daycare Toddlers	W4	Severe efflorescence, peeling paint	150	No	None	N/A	None	No	
1091	4020	2	0	012B		Former Daycare Toddlers Closet	Ceiling	Peeling paint	40	No	None	N/A	None	No	
1092	4020	2	0	012B		Former Daycare Toddlers Closet	Floor	Debris	40	No	Debris	N/A	None	No	
1093	4020	2	0	012B		Former Daycare Toddlers Closet	W4	Severe peeling paint	120	No	None	N/A	None	No	
1094	4020	1	0	001B		Former Large Auto Shop	Ceiling	Severe peeling paint	20	No	None	N/A	None	No	
1095	4020	1	0	001B		Former Large Auto Shop	Floor	Debris	10	No	Debris	N/A	None	No	
1096	4020	1	0	001B		Former Large Auto Shop	W1	Peeling paint	10	No	None	N/A	None	No	
1097	4020	1	0	001B		Former Large Auto Shop	W2	Peeling paint	10	No	None	N/A	None	No	
1098	4020	1	0	001B		Former Large Auto Shop	W3	Peeling paint	10	No	None	N/A	None	No	
1099	4020	1	0	001B		Former Large Auto Shop	W4	Peeling paint	10	No	None	N/A	None	No	
1100	4020	1	0	3		Former Paint Shop	Ceiling	Severe peeling paint	80	No	None	N/A	None	No	
1101	4020	1	0	3		Former Paint Shop	Floor	Debris	40	No	Debris	N/A	None	No	
1102	4020	1	0	003E		Former Paint Shop	W1	Severe peeling paint	40	No	None	N/A	None	No	
1103	4020	1	0	003E		Former Paint Shop	W2	Severe peeling paint	40	No	None	N/A	None	No	
1104	4020	1	0	4		Former Paint Shop	W3	Severe peeling paint	40	No	None	N/A	None	No	
1105	4020	1	0	4		Former Paint Shop	W4	Severe peeling paint	40	No	None	N/A	None	No	
1106	4020	1	0	004A		Former Small Auto Shop	Ceiling	Severe peeling paint	120	No	None	N/A	None	No	
1107	4020	1	0	004A		Former Small Auto Shop	Floor	Debris	100	No	Debris	N/A	None	No	
1108	4020	1	0	004A		Former Small Auto Shop	W1	Severe peeling paint	50	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1109	4020	1	0	1		Former Small Auto Shop	W2	Severe peeling paint	50	No	None	N/A	None	No	
1110	4020	1	0	1		Former Small Auto Shop	W3	Severe peeling paint	50	No	None	N/A	None	No	
1111	4020	1	0	1		Former Small Auto Shop	W4	Severe peeling paint	50	No	None	N/A	None	No	
1112	4020	1	0	1		Girl's Locker Room	Ceiling	Peeling paint on ceiling and ductwork	200	No	None	N/A	None	No	
1113	4020	1	0	1		Girl's Locker Room	W2	Peeling paint	30	No	None	N/A	None	No	
1114	4020	1	0	1		Girl's Locker Room	W3	Peeling paint	30	No	None	N/A	None	No	
1115	4020	1	0	002A		Girl's Locker Room	W4	Peeling paint	30	No	None	N/A	None	No	
1116	4020	1	0	002A		Girl's Locker Room Custodial Closet	W2	Peeling paint by pump	5	No	None	N/A	None	No	
1117	4020	1	0	002A		Girl's Locker Room Showers	Ceiling	Peeling paint	10	No	None	N/A	None	No	
1118	4020	1	0	002A		Girl's Locker Room Varsity Room	Ceiling	Peeling paint on ductwork	50	No	None	N/A	None	No	
1119	4020	1	0	002A		Girl's Locker Room Visitor's Locker Room	Ceiling	Peeling paint on ductwork	50	No	None	N/A	None	No	
1120	4020	1	0	002A		Gym adjacent Cheerleading Gym	Ceiling	No Access - Sealed off - ACM concern						Inspection Needed	
1121	4020	1	0	2		Gym adjacent Cheerleading Gym	Floor	No Access - Sealed off - ACM concern						Inspection Needed	
1122	4020	1	0	2		Gym adjacent Cheerleading Gym	W1	No Access - Sealed off - ACM concern						Inspection Needed	
1123	4020	1	0	2		Gym adjacent Cheerleading Gym	W2	No Access - Sealed off - ACM concern						Inspection Needed	
1124	4020	1	0	2		Gym adjacent Cheerleading Gym	W3	No Access - Sealed off - ACM concern						Inspection Needed	
1125	4020	1	0	2		Gym adjacent Cheerleading Gym	W4	No Access - Sealed off - ACM concern						Inspection Needed	
1126	4020	1	0	2		Hallway outside Building Engineer's Office Area	Ceiling	Peeling paint on ceiling, ductwork, conduits and junction box	200	No	None	N/A	None	No	
1127	4020	2	0	001A		Hallway outside Building Engineer's Office Area	W1	Peeling paint on wall and pipes	20	No	None	N/A	None	No	
1128	4020	2	0	001A		Hallway outside Building Engineer's Office Area	W2	Peeling paint	5	No	None	N/A	None	No	
1129	4020	2	0	001A		Hallway outside Building Engineer's Office Area	W3	Peeling paint	40	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1130	4020	2	0	001A		Hallway outside Building Engineer's Office Area	W4	Peeling paint	5	No	None	N/A	None	No	
1131	4020	2	0	006C		Hallway to Blower Room 4	Ceiling	Peeling paint on ceilig and ductwork	100	No	None	N/A	None	No	
1132	4020	2	0	5		Hallway to Blower Room 4	Floor	Debris on floor and blackboard ledge	60	No	Blackboard ledge	20	None	No	
1133	4020	2	0	001B		Hallway to Blower Room 4	W2	Peeling paint	25	No	None	N/A	None	No	
1134	4020	2	0	001C		Hallway to Blower Room 4	W3	Peeling paint	10	No	None	N/A	None	No	
1135	4020	1	0	18		Hallway to Blower Room 4	W4	Peeling paint on wall and pipes	40	No	None	N/A	None	No	
1136	4020	1	0	18		ROTC Command Center	Ceiling	Peeling paint	50	No	None	N/A	None	No	
1137	4020	1	0	18		ROTC Gym	Ceiling	Peeling paint on ceiling and metal components	100	No	None	N/A	None	No	
1138	4020	1	0	18		ROTC Restroom	W3	Peeling paint	3	No	None	N/A	None	No	
1139	4020	1	0	18		ROTC Rifle Storage Room	Ceiling	Peeling paint	10	No	None	N/A	None	No	
1140	4020	1	0	18		ROTC Uniform Supply Room	Floor	Peeling paint	60	No	None	N/A	None	No	
1141	4020	1	0	H03		Shop Classroom 11	W3	Peeling paint, efflorescence	60	No	None	N/A	None	No	
1142	4020	1	0	H03		Shop Classroom 11	W4	Peeling paint, efflorescence	15	No	None	N/A	None	No	
1143	4020	1	0	H03		Shop Classroom 11 Closet	W2	Peeling paint, efflorescence	10	No	None	N/A	None	No	
1144	4020	1	0	H03		Small Room between Former Large and Small Auto Shops	Ceiling	Peeling paint	30	No	None	N/A	None	No	
1145	4020	1	0	H03		Small Room between Former Large and Small Auto Shops	Floor	Debris	10	No	Debris	N/A	None	No	
1146	4020	1	0	H06		Small Room between Former Large and Small Auto Shops	W1	Peeling paint	30	No	None	N/A	None	No	
1147	4020	1	0	H06		Small Room between Former Large and Small Auto Shops	W2	Peeling paint	20	No	None	N/A	None	No	
1148	4020	1	0	H06		Small Room between Former Large and Small Auto Shops	W3	Peeling paint	30	No	None	N/A	None	No	
1149	4020	1	0	H06		Small Room between Former Large and Small Auto Shops	W4	Peeling paint	20	No	None	N/A	None	No	
1150	4020	1	0	H06		Stairwell C Closet	Ceiling	Severe peeling paint	50	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1151	4020	1	0	010A		Stairwell C Restroom, Visiting Team Locker Boy's	W2	Peeling paint on pipe	10	No	None	N/A	None	No	
1152	4020	1	0	9		Stairwell from Basement to Former Large Auto Shop	Ceiling	Peeling paint	30	No	None	N/A	None	No	
1153	4020	1	0	11		Stairwell from Basement to Former Small Auto Shop	Ceiling	Peeling paint	30	No	None	N/A	None	No	
1154	4020	1	0	009B		Stairwell from Basement to Former Small Auto Shop	Floor	Debris	15	No	Debris	N/A	None	No	
1155	4020	1	0	009A		Stairwell from Basement to Former Small Auto Shop	W1	Peeling paint	10	No	None	N/A	None	No	
1156	4020	1	0	10		Stairwell from Basement to Former Small Auto Shop	W2	Peeling paint	20	No	None	N/A	None	No	
1157	4020	1	0	10		Stairwell from Basement to Former Small Auto Shop	W3	Peeling paint	10	No	None	N/A	None	No	
1158	4020	1	0	010A		Stairwell from Basement to Former Small Auto Shop	W4	Peeling paint	20	No	None	N/A	None	No	
1159	4020	1	0	25		Stairwell from Kitchen to Boiler Room Restroom for Female Cafeteria Staff	Ceiling	Peeling paint	35	No	None	N/A	None	No	
1160	4020	1	0	25		Stairwell from Kitchen to Boiler Room Restroom for Female Cafeteria Staff	Floor	Debris	10	No	Debris	N/A	None	No	
1161	4020	1	0	25		Stairwell from Kitchen to Boiler Room Restroom for Female Cafeteria Staff	W1	Peeling paint	25	No	None	N/A	None	No	
1162	4020	1	0	25		Stairwell from Kitchen to Boiler Room Restroom for Female Cafeteria Staff	W2	Peeling paint	35	No	None	N/A	None	No	

Overbrook HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1163	4020	1	0	25		Stairwell from Kitchen to Boiler Room Restroom for Female Cafeteria Staff	W3	Peeling paint	30	No	None	N/A	None	No	
1164	4020	1	0	25		Stairwell from Kitchen to Boiler Room Restroom for Female Cafeteria Staff	W4	Peeling paint	20	No	None	N/A	None	No	
1165	4020	1	0	017A		Stairwell to Boy's Locker Room	Ceiling	Peeling paint	300	No	None	N/A	None	No	
1166	4020	1	0	17		Stairwell to Girl's Locker Room	Ceiling	Peeling paint under the stairs	50	No	None	N/A	None	No	
1167	4020	1	0	S04		Stairwell to Girl's Locker Room	W2	Peeling paint at landing	20	No	None	N/A	None	No	
1168	4020	1	0	S09		Storage Room adjacent Blower Room 4	Ceiling	Peeling paint	20	No	None	N/A	None	No	
1169	4020	1	0	S09		Storage Room adjacent Blower Room 4	W1	Peeling paint	5	No	None	N/A	None	No	
1170	4020	1	0	S09		Storage Room adjacent Blower Room 4	W2	Peeling paint	10	No	None	N/A	None	No	
1171	4020	1	0	S09		Storage Room adjacent Blower Room 4	W3	Peeling paint	50	No	None	N/A	None	No	
1172	4020	1	0	S09		Storage Room on Left in Hallway from Stairwell C to Cheerleading Gym	Ceiling	Severe peeling paint, efflorescence	120	No	None	N/A	None	No	
1173	4020	1	0	S09		Stairwell from Basement to Former Small Auto Shop	W4	Peeling paint	20	No	None	N/A	No		
1174	4020	1	0	015H		Stairwell from Kitchen to Boiler Room Restroom for Female Cafeteria Staff	Ceiling	Peeling paint	35	No	None	N/A	No		
1175	4020	1	0	015H		Stairwell from Kitchen to Boiler Room Restroom for Female Cafeteria Staff	Floor	Debris	10	No	Debris	N/A	No		
1176	4020	1	0	015H		Stairwell from Kitchen to Boiler Room Restroom for Female Cafeteria Staff	W1	Peeling paint	25	No	None	N/A	No		

Overbrook HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1177	4020	1	0	015H		Stairwell from Kitchen to Boiler Room Restroom for Female Cafeteria Staff	W2	Peeling paint	35	No	None	N/A	No		
1178	4020	1	0	015H		Stairwell from Kitchen to Boiler Room Restroom for Female Cafeteria Staff	W3	Peeling paint	30	No	None	N/A	No		
1179	4020	1	0	015H		Stairwell from Kitchen to Boiler Room Restroom for Female Cafeteria Staff	W4	Peeling paint	20	No	None	N/A	No		
1180	4020	2	0	S81		Stairwell to Boy's Locker Room	Ceiling	Peeling paint	300	No	None	N/A	No		
1181	4020	2	0	S80		Stairwell to Girl's Locker Room	Ceiling	Peeling paint under the stairs	50	No	None	N/A	No		
1182	4020	2	0	S80		Stairwell to Girl's Locker Room	W2	Peeling paint at landing	20	No	None	N/A	No		
1183	4020	1	0	7		Storage Room adjacent Blower Room 4	Ceiling	Peeling paint	20	No	None	N/A	No		
1184	4020	1	0	7		Storage Room adjacent Blower Room 4	W1	Peeling paint	5	No	None	N/A	No		
1185	4020	1	0	7		Storage Room adjacent Blower Room 4	W2	Peeling paint	10	No	None	N/A	No		
1186	4020	1	0	7		Storage Room adjacent Blower Room 4	W3	Peeling paint	50	No	None	N/A	No		
1187	4020	1	0	018A		Storage Room on Left in Hallway from Stairwell C to Cheerleading Gym	Ceiling	Severe peeling paint, efflorescence	120	No	None	N/A	No		
1188	4020	1	0	018A		Storage Room on Left in Hallway from Stairwell C to Cheerleading Gym	Floor	Debris	120	No	Debris	N/A	No		
1189	4020	1	0	018A		Storage Room on Left in Hallway from Stairwell C to Cheerleading Gym	W1	Severe peeling paint	50	No	None	N/A	No		
1190	4020	1	0	018A		Storage Room on Left in Hallway from Stairwell C to Cheerleading Gym	W2	Peeling paint	5	No	None	N/A	No		
1191	4020	1	0	018A		Storage Room on Left in Hallway from Stairwell C to Cheerleading Gym	W3	Peeling paint	5	No	None	N/A	No		

Overbrook HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1192	4020	1	0	018A		Storage Room on Left in Hallway from Stairwell C to Cheerleading Gym	W4	Peeling paint	5	No	None	N/A	No		
1193	4020	2	0	4		Weight Room	Ceiling	Peeling paint on ceiling and ductwork	70	No	None	N/A	No		
1194	4020	2	0	004B		Weight Room Office	Ceiling	Peeling paint on ductwork	30	No	None	N/A	No		