

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	5150	1	4			Classroom 401	Ceiling	Flaking, Efflorescence	59	Yes	No	N/A	N/A	Yes	
2	5150	1	4			Classroom 401	W1	Cracking, Chipping, Flaking	44	No	No	N/A	N/A	No	
3	5150	1	4			Classroom 401	W2	Cracking	2	No	No	N/A	N/A	No	
4	5150	1	4			Classroom 401	W3	Chipping on wall and metal pipes, Flaking, Efflorescence	47	Yes	No	N/A	N/A	Yes	
5	5150	1	4			Classroom 401	W4	Cracking, Flaking	24	No	No	N/A	N/A	No	
6	5150	1	4			Classroom 401 Closet	Ceiling	Flaking, Efflorescence	4	Yes	No	N/A	N/A	Yes	
7	5150	1	4			Classroom 401 Closet	W1	Cracking, Flaking	2	No	No	N/A	N/A	No	
8	5150	1	4			Classroom 401 Closet	W2	Flaking	15	No	No	N/A	N/A	No	
9	5150	1	4			Classroom 401 Closet	W3	Holes, Flaking	10	No	No	N/A	Cabinet	Yes	Limited inspection due to stored materials
10	5150	1	4			Classroom 401 Closet	W4	Holes, Flaking, Efflorescence	25	Yes	No	N/A	Shelves with stored materials	Yes	Limited inspection due to stored materials
11	5150	1	4			Classroom 402	Ceiling	Cracking, Flaking	19	No	No	N/A	N/A	No	
12	5150	1	4			Classroom 402	W1	Cracking, Chipping, Flaking	27	No	No	N/A	N/A	No	
13	5150	1	4			Classroom 402	W2	Cracking, Flaking	22	No	No	N/A	N/A	No	
14	5150	1	4			Classroom 402	W3	Cracking, Chipping, Flaking, Efflorescence, Significant Moisture Damage behind radiators	72	Yes	No	N/A	N/A	Yes	
15	5150	1	4			Classroom 402	W4	Cracking	12	No	No	N/A	N/A	No	
16	5150	1	4			Classroom 402 Closet	Ceiling	Chipping, Flaking	5	No	No	N/A	N/A	No	
17	5150	1	4			Classroom 402 Closet	Floor	N/A	N/A	No	Paint chips and debris	10	N/A	No	
18	5150	1	4			Classroom 402 Closet	W1	Flaking, Efflorescence	150	Yes	No	N/A	N/A	Yes	
19	5150	1	4			Classroom 402 Closet	W3	Flaking	200	No	No	N/A	N/A	No	
20	5150	1	4			Classroom 402 Closet	W4	Flaking, Efflorescence	75	Yes	No	N/A	N/A	Yes	
21	5150	1	4			Classroom 403	Ceiling	Cracking, Flaking	28	No	No	N/A	N/A	No	
22	5150	1	4			Classroom 403	W1	Cracking, Flaking, Efflorescence	11	Yes	No	N/A	N/A	Yes	
23	5150	1	4			Classroom 403	W2	Flaking	4	No	No	N/A	Cabinets	No	Limited inspection due to cabinets
24	5150	1	4			Classroom 403	W3	Chipping, Flaking, Efflorescence	8	Yes	No	N/A	N/A	Yes	
25	5150	1	4			Classroom 403	W4	Cracking, Efflorescence	30	Yes	No	N/A	N/A	Yes	
26	5150	1	4			Classroom 403 Closet	Ceiling	Cracking	8	No	No	N/A	N/A	No	
27	5150	1	4			Classroom 403 Closet	Floor	N/A	N/A	No	Debris	5	N/A	No	
28	5150	1	4			Classroom 403 Closet	W2	Cracking, Flaking	19	No	No	N/A	N/A	No	
29	5150	1	4			Classroom 403 Closet	W3	Cracking, Flaking, Efflorescence	23	Yes	No	N/A	N/A	Yes	
30	5150	1	4			Classroom 403 Closet	W4	Cracking, Flaking	19	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
31	5150	1	4			Classroom 404	Ceiling	Holes, Flaking, Efflorescence	35	Yes	No	N/A	N/A	Yes	
32	5150	1	4			Classroom 404	W1	Cracking, Chipping	25	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
33	5150	1	4			Classroom 404	W2	Chipping, Hole, Flaking	9	No	No	N/A	N/A	Yes	
34	5150	1	4			Classroom 404	W3	Chipping, Hole behind radiator, Flaking behind radiator, Efflorescence	19	Yes	Debris on windowsills	2	N/A	Yes	
35	5150	1	4			Classroom 404	W4	Cracking, Chipping	7	No	No	N/A	N/A	No	
36	5150	1	4			Classroom 404 Closet	Ceiling	Cracking	1	No	No	N/A	N/A	No	
37	5150	1	4			Classroom 404 Closet	W1	Cracking, Flaking	4	No	No	N/A	N/A	No	
38	5150	1	4			Classroom 404 Closet	W2	Cracking, Chipping, Flaking	68	No	No	N/A	N/A	No	
39	5150	1	4			Classroom 404 Closet	W3	Cracking, Flaking	15	No	No	N/A	Shelf	No	Limited inspection due to stored materials
40	5150	1	4			Classroom 404 Closet	W4	Cracking, Chipping, Flaking	27	No	No	N/A	Cabinets, Shelves	No	Limited inspection due to stored materials
41	5150	1	4			Classroom 406	Ceiling	Cracking, Flaking, Efflorescence	21	Yes	No	N/A	N/A	Yes	
42	5150	1	4			Classroom 406	W1	Cracking, Chipping, Flaking	68	No	No	N/A	N/A	No	
43	5150	1	4			Classroom 406	W2	Cracking, Chipping	19	No	No	N/A	N/A	No	
44	5150	1	4			Classroom 406	W3	Cracking, Chipping, Flaking	62	No	No	N/A	N/A	No	
45	5150	1	4			Classroom 406	W4	Cracking, Chipping, Flaking	28	No	No	N/A	N/A	No	
46	5150	1	4			Classroom 406 Closet	Ceiling	Flaking	3	No	No	N/A	N/A	No	
47	5150	1	4			Classroom 406 Closet	W1	Cracking	2	No	No	N/A	N/A	No	
48	5150	1	4			Classroom 406 Closet	W2	Cracking, Flaking	27	No	No	N/A	N/A	No	
49	5150	1	4			Classroom 406 Closet	W3	Cracking	30	No	No	N/A	N/A	No	
50	5150	1	4			Classroom 406 Closet	W4	Cracking, Flaking	17	No	No	N/A	N/A	No	
51	5150	1	4			Classroom 407	Ceiling	Cracking, Flaking, Efflorescence	44	Yes	No	N/A	N/A	Yes	
52	5150	1	4			Classroom 407	W1	Cracking, Chipping, Flaking	45	No	No	N/A	Tables with computers	No	
53	5150	1	4			Classroom 407	W2	Cracking, Flaking	21	No	No	N/A	Tables with computers	No	
54	5150	1	4			Classroom 407	W3	Cracking, Chipping on wall and radiators, Hole, Flaking on wall and behind radiator, Efflorescence	66	Yes	No	N/A	Tables with computers	Yes	
55	5150	1	4			Classroom 407	W4	Cracking, Chipping, Flaking	28	No	No	N/A	Tables with computers	No	
56	5150	1	4			Classroom 407 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
57	5150	1	4			Classroom 407 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
58	5150	1	4			Classroom 407 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
59	5150	1	4			Classroom 407 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
60	5150	1	4			Classroom 407 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
61	5150	1	4			Classroom 407 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
62	5150	1	4			Classroom 408	Ceiling	Chipping, Hole, Flaking	40	No	No	N/A	N/A	Yes	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
63	5150	1	4			Classroom 408	W1	Cracking, Chipping, Flaking	31	No	No	N/A	Tables with computers	No	
64	5150	1	4			Classroom 408	W2	Cracking, Flaking	10	No	No	N/A	Tables with computers	No	
65	5150	1	4			Classroom 408	W3	Cracking, Flaking, Efflorescence	38	Yes	No	N/A	Tables with computers, Cabinets	Yes	
66	5150	1	4			Classroom 408	W4	Cracking	18	No	No	N/A	Furniture	No	
67	5150	1	4			Classroom 409	Ceiling	Flaking, Efflorescence	75	Yes	No	N/A	N/A	Yes	
68	5150	1	4			Classroom 409	W1	Cracking, Chipping, Flaking	44	No	No	N/A	N/A	No	
69	5150	1	4			Classroom 409	W2	Cracking, Chipping, Holes, Flaking	48	No	No	N/A	N/A	Yes	
70	5150	1	4			Classroom 409	W3	Cracking, Chipping, Holes behind radiators, Flaking	46	No	No	N/A	N/A	Yes	
71	5150	1	4			Classroom 409	W4	Chipping, Flaking	14	No	No	N/A	N/A	No	
72	5150	1	4			Classroom 409 Closet	Ceiling	Flaking	20	No	No	N/A	Shelves with stored materials	No	
73	5150	1	4			Classroom 409 Closet	Floor	Limited inspection due to stored materials	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
74	5150	1	4			Classroom 409 Closet	W1	Flaking	20	No	No	N/A	Shelves with stored materials	No	
75	5150	1	4			Classroom 409 Closet	W2	Flaking	200	No	No	N/A	Shelves with stored materials	No	
76	5150	1	4			Classroom 409 Closet	W3	Flaking	50	No	No	N/A	Shelves with stored materials	No	
77	5150	1	4			Classroom 409 Closet	W4	Flaking	75	No	No	N/A	Shelves with stored materials	No	
78	5150	1	4			Faculty Lounge 405	Ceiling	Cracking, Flaking	10	No	No	N/A	N/A	No	
79	5150	1	4			Faculty Lounge 405	W1	Cracking	8	No	No	N/A	N/A	No	
80	5150	1	4			Faculty Lounge 405	W2	Cracking, Chipping	14	No	No	N/A	N/A	No	
81	5150	1	4			Faculty Lounge 405	W3	Cracking	1	No	No	N/A	N/A	No	
82	5150	1	4			Faculty Lounge 405	W4	Cracking, Chipping, Flaking	15	No	No	N/A	N/A	No	
83	5150	1	4			Faculty Lounge Office adjacent to Classroom 404	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
84	5150	1	4			Faculty Lounge Office adjacent to Classroom 404	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
85	5150	1	4			Faculty Lounge Office adjacent to Classroom 404	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
86	5150	1	4			Faculty Lounge Office adjacent to Classroom 404	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
87	5150	1	4			Faculty Lounge Office adjacent to Classroom 404	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
88	5150	1	4			Faculty Lounge Office adjacent to Classroom 404	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
89	5150	1	4			Faculty Lounge Office adjacent to Restroom	Ceiling	Cracking, Flaking	7	No	No	N/A	N/A	No	
90	5150	1	4			Faculty Lounge Office adjacent to Restroom	W1	Chipping	9	No	No	N/A	N/A	No	
91	5150	1	4			Faculty Lounge Office adjacent to Restroom	W2	Cracking, Flaking	23	No	No	N/A	Cabinets	No	
92	5150	1	4			Faculty Lounge Office adjacent to Restroom	W3	Cracking, Flaking	48	No	No	N/A	N/A	No	
93	5150	1	4			Faculty Lounge Office adjacent to Restroom	W4	Cracking, Flaking, Efflorescence	32	No	No	N/A	N/A	No	
94	5150	1	4			Faculty Lounge Restroom	Ceiling	Cracking, Flaking	4	No	No	N/A	N/A	No	
95	5150	1	4			Faculty Lounge Restroom	W1	Cracking, Flaking	9	No	No	N/A	N/A	No	
96	5150	1	4			Faculty Lounge Restroom	W2	Cracking, Flaking	16	No	No	N/A	N/A	No	
97	5150	1	4			Faculty Lounge Restroom	W3	Cracking, Flaking	17	No	No	N/A	N/A	No	
98	5150	1	4			Faculty Lounge Restroom	W4	Cracking, Flaking	13	No	No	N/A	N/A	No	
99	5150	1	4			Fire Tower near Classroom 401	Ceiling	Cracking, Flaking	60	No	No	N/A	N/A	No	
100	5150	1	4			Fire Tower near Classroom 401	Floor	Flaking	105	No	No	N/A	N/A	No	
101	5150	1	4			Fire Tower near Classroom 401	W1	Flaking on wall, door, and windows	173	No	No	N/A	N/A	No	
102	5150	1	4			Fire Tower near Classroom 401	W2	Chipping, Flaking on wall and door	48	No	No	N/A	N/A	No	
103	5150	1	4			Fire Tower near Classroom 401	W3	Flaking on wall, windows, metal pipe, and metal bars	194	No	No	N/A	N/A	No	
104	5150	1	4			Fire Tower near Classroom 401	W4	Chipping, Flaking on wall, metal bars, and window	97	No	No	N/A	N/A	No	
105	5150	1	4			Fire Tower near Classroom 409	Ceiling	Cracking, Flaking, Efflorescence	33	Yes	No	N/A	N/A	Yes	
106	5150	1	4			Fire Tower near Classroom 409	Floor	Flaking	105	No	Debris	10	N/A	No	
107	5150	1	4			Fire Tower near Classroom 409	W1	Flaking on wall, door, and windows	150	No	No	N/A	N/A	No	
108	5150	1	4			Fire Tower near Classroom 409	W2	Flaking on wall, metal pipes, window, and metal bars	94	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
109	5150	1	4			Fire Tower near Classroom 409	W3	Flaking on wall, metal bars, and windows	182	No	No	N/A	N/A	No	
110	5150	1	4			Fire Tower near Classroom 409	W4	Flaking on wall, door, and windows	141	No	No	N/A	N/A	No	
111	5150	1	4			Girl's Restroom adjacent to Classroom 407	Ceiling	Cracking, Flaking, Spalling	9	Yes	No	N/A	N/A	Yes	
112	5150	1	4			Girl's Restroom adjacent to Classroom 407	Floor	Chipping	5	No	No	N/A	N/A	No	
113	5150	1	4			Girl's Restroom adjacent to Classroom 407	W1	Flaking	7	No	No	N/A	N/A	No	
114	5150	1	4			Girl's Restroom adjacent to Classroom 407	W2	Cracking, Chipping on metal pipes, Flaking	39	No	No	N/A	N/A	No	
115	5150	1	4			Girl's Restroom adjacent to Classroom 407	W3	Flaking	8	No	No	N/A	N/A	No	
116	5150	1	4			Girl's Restroom adjacent to Classroom 407	W4	Chipping, Flaking	108	No	No	N/A	N/A	No	
117	5150	1	4			Hallway from Classrooms 403-407	Ceiling	Cracking, Chipping, Flaking	13	No	No	N/A	N/A	No	
118	5150	1	4			Hallway from Classrooms 403-407	W1	Cracking, Chipping, Flaking	129	No	No	N/A	N/A	No	
119	5150	1	4			Hallway from Classrooms 403-407	W2	Cracking, Chipping, Flaking	16	No	No	N/A	N/A	No	
120	5150	1	4			Hallway from Classrooms 403-407	W3	Chipping, Flaking on wall and asbestos pipe insulation, Efflorescence	43	Yes	No	N/A	N/A	Yes	
121	5150	1	4			Hallway from Classrooms 403-407	W4	Cracking, Flaking	16	No	No	N/A	N/A	No	
122	5150	1	4			Hallway outside Classrooms 401-402	Ceiling	Cracking, Chipping on wall and radiators, Flaking	43	No	No	N/A	N/A	No	
123	5150	1	4			Hallway outside Classrooms 401-402	W2	Cracking, Chipping, Flaking	150	No	No	N/A	N/A	No	
124	5150	1	4			Hallway outside Classrooms 401-402	W3	Cracking, Flaking	20	No	No	N/A	N/A	No	
125	5150	1	4			Hallway outside Classrooms 401-402	W4	Cracking, Chipping, Flaking	100	No	No	N/A	N/A	No	
126	5150	1	4			Hallway outside Classrooms 408-409	Ceiling	Cracking, Chipping, Flaking, Efflorescence	14	Yes	No	N/A	N/A	Yes	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
127	5150	1	4			Hallway outside Classrooms 408-409	Floor	Chipping	5	No	No	N/A	N/A	No	
128	5150	1	4			Hallway outside Classrooms 408-409	W2	Cracking, Chipping on wall, radiators, and metal jackets, Holes, Flaking, Spalling, Efflorescence	150	Yes	No	N/A	N/A	Yes	
129	5150	1	4			Hallway outside Classrooms 408-409	W3	Cracking, Chipping, Flaking	28	No	No	N/A	N/A	No	
130	5150	1	4			Hallway outside Classrooms 408-409	W4	Cracking, Chipping, Flaking	95	No	No	N/A	N/A	No	
131	5150	1	4			Men's Restroom adjacent to Classroom 403	Ceiling	Flaking	18	No	No	N/A	N/A	No	
132	5150	1	4			Men's Restroom adjacent to Classroom 403	Floor	Chipping	4	No	Paint Chips	15	N/A	No	
133	5150	1	4			Men's Restroom adjacent to Classroom 403	W1	Cracking, Chipping, Flaking	8	No	No	N/A	N/A	No	
134	5150	1	4			Men's Restroom adjacent to Classroom 403	W2	Cracking, Flaking	26	No	No	N/A	N/A	No	
135	5150	1	4			Men's Restroom adjacent to Classroom 403	W3	Cracking, Efflorescence	48	Yes	Debris on windowsills	5	N/A	Yes	
136	5150	1	4			Men's Restroom adjacent to Classroom 403	W4	Cracking, Hole, Flaking	34	No	No	N/A	N/A	No	
137	5150	1	4			Stairwell across from Classroom 404	Ceiling	Flaking, Spalling, Efflorescence	33	Yes	No	N/A	N/A	Yes	
138	5150	1	4			Stairwell across from Classroom 404	Floor	Chipping on stairs and railings	76	No	No	N/A	N/A	No	
139	5150	1	4			Stairwell across from Classroom 404	W1	Chipping on doors and doorframe	41	No	No	N/A	N/A	No	
140	5150	1	4			Stairwell across from Classroom 404	W2	Cracking, Chipping, Flaking, Spalling, Efflorescence	39	Yes	No	N/A	N/A	Yes	
141	5150	1	4			Stairwell across from Classroom 404	W3	Cracking, Chipping on wall and radiator, Flaking	23	No	No	N/A	N/A	No	
142	5150	1	4			Stairwell across from Classroom 404	W4	Cracking, Chipping, Flaking	76	No	No	N/A	N/A	No	
143	5150	1	4			Stairwell across from Classroom 406	Ceiling	Flaking	9	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
144	5150	1	4			Stairwell across from Classroom 406	Floor	Chipping on stairs and railings	82	No	No	N/A	N/A	No	
145	5150	1	4			Stairwell across from Classroom 406	W1	Chipping on doors and doorframe	48	No	No	N/A	N/A	No	
146	5150	1	4			Stairwell across from Classroom 406	W2	Cracking, Flaking	31	No	No	N/A	N/A	No	
147	5150	1	4			Stairwell across from Classroom 406	W3	Cracking, Flaking, Efflorescence	32	Yes	No	N/A	N/A	Yes	
148	5150	1	4			Stairwell across from Classroom 406	W4	Cracking, Flaking	36	No	No	N/A	N/A	No	
149	5150	1	3			Boy's Restroom next to Classroom 303	Ceiling	Flaking, Efflorescence, Significant Moisture Damage	88	Yes	No	N/A	N/A	Yes	
150	5150	1	3			Boy's Restroom next to Classroom 303	Floor	Chipping	5	No	No	N/A	N/A	No	
151	5150	1	3			Boy's Restroom next to Classroom 303	W1	Flaking	20	No	No	N/A	N/A	No	
152	5150	1	3			Boy's Restroom next to Classroom 303	W2	Chipping on metal jackets, Flaking	34	No	No	N/A	N/A	No	
153	5150	1	3			Boy's Restroom next to Classroom 303	W3	Flaking, Efflorescence	14	Yes	No	N/A	N/A	Yes	
154	5150	1	3			Boy's Restroom next to Classroom 303	W4	Cracking, Chipping, Flaking on wall and metal pipe, Efflorescence	180	Yes	No	N/A	N/A	Yes	
155	5150	1	3			Classroom 301	Ceiling	Flaking, Efflorescence	69	Yes	No	N/A	N/A	Yes	
156	5150	1	3			Classroom 301	W1	Cracking, Chipping on wall and wood cove base, Flaking	15	No	No	N/A	Posters	No	
157	5150	1	3			Classroom 301	W2	Chipping, Flaking	13	No	No	N/A	Posters	No	
158	5150	1	3			Classroom 301	W3	Chipping on wall and wood cove base, Flaking, Spalling, Efflorescence	28	Yes	Debris on windowsills	2	Posters	Yes	Limited inspection
159	5150	1	3			Classroom 301	W4	Chipping on wall and wood cove base, Hole, Flaking	27	No	No	N/A	Posters	No	
160	5150	1	3			Classroom 301 Closet	Ceiling	Flaking, Significant Moisture Damage	96	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
161	5150	1	3			Classroom 301 Closet	Floor	Limited inspection due to stored materials	N/A	No	Debris	10	Stored Materials	No	Limited inspection due to stored materials
162	5150	1	3			Classroom 301 Closet	W1	Cracking	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
163	5150	1	3			Classroom 301 Closet	W2	Hole, Flaking	2	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
164	5150	1	3			Classroom 301 Closet	W3	Flaking on wall and metal pipe, Efflorescence	13	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
165	5150	1	3			Classroom 301 Closet	W4	Flaking, Significant Moisture Damage	70	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
166	5150	1	3			Classroom 302	Ceiling	Flaking	88	No	No	N/A	N/A	No	
167	5150	1	3			Classroom 302	Floor	N/A	N/A	No	Paint Chips	1	N/A	No	
168	5150	1	3			Classroom 302	W1	Cracking, Chipping on wall and wood cove base, Staple Holes, Flaking	38	No	No	N/A	Posters	Yes	
169	5150	1	3			Classroom 302	W2	Chipping on wall and wood cove base, Staples and Staple Holes	14	No	No	N/A	Posters	Yes	
170	5150	1	3			Classroom 302	W3	Chipping, Flaking, Spalling, Efflorescence	37	Yes	Debris on windowsills	9	N/A	Yes	
171	5150	1	3			Classroom 302	W4	Chipping, Flaking	24	No	No	N/A	Posters	No	
172	5150	1	3			Classroom 302 Closet	Ceiling	Efflorescence	10	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
173	5150	1	3			Classroom 302 Closet	Floor	Limited inspection due to stored materials	N/A	No	Debris on floor, windowsill, and stored materials	20	Stored Materials	No	Limited inspection due to stored materials
174	5150	1	3			Classroom 302 Closet	W1	Hole, Flaking, Efflorescence	7	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
175	5150	1	3			Classroom 302 Closet	W2	Chipping	3	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
176	5150	1	3			Classroom 302 Closet	W3	Efflorescence	25	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
177	5150	1	3			Classroom 302 Closet	W4	Efflorescence	75	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
178	5150	1	3			Classroom 303	Ceiling	Holes, Flaking	79	No	No	N/A	N/A	Yes	
179	5150	1	3			Classroom 303	W1	Cracking, Chipping	8	No	No	N/A	N/A	No	
180	5150	1	3			Classroom 303	W2	Cracking, Chipping	13	No	No	N/A	Furniture	No	
181	5150	1	3			Classroom 303	W3	Chipping, Hole, Flaking, Significant Moisture Damage behind radiator	25	Yes	No	N/A	N/A	Yes	
182	5150	1	3			Classroom 303	W4	Chipping, Flaking	30	No	No	N/A	N/A	No	
183	5150	1	3			Classroom 303 Closet	Ceiling	Flaking	48	No	No	N/A	N/A	No	
184	5150	1	3			Classroom 303 Closet	W1	Cracking, Flaking	6	No	No	N/A	N/A	No	
185	5150	1	3			Classroom 303 Closet	W2	Cracking, Flaking	60	No	No	N/A	N/A	No	
186	5150	1	3			Classroom 303 Closet	W3	Flaking, Spalling, Efflorescence	30	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
187	5150	1	3			Classroom 303 Closet	W4	Flaking	30	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
188	5150	1	3			Classroom 304	Ceiling	Flaking	42	No	No	N/A	N/A	No	
189	5150	1	3			Classroom 304	W1	Chipping, Staples and Staple Holes, Flaking	75	No	No	N/A	Posters	Yes	
190	5150	1	3			Classroom 304	W2	Chipping	4	No	No	N/A	Posters	No	
191	5150	1	3			Classroom 304	W3	Chipping, Holes behind radiators, Flaking	36	No	No	N/A	N/A	Yes	
192	5150	1	3			Classroom 304	W4	Cracking, Chipping, Staple Holes	16	No	No	N/A	Posters	Yes	
193	5150	1	3			Classroom 304 Closet	Ceiling	Flaking	5	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
194	5150	1	3			Classroom 304 Closet	Floor	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
195	5150	1	3			Classroom 304 Closet	W1	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
196	5150	1	3			Classroom 304 Closet	W2	Cracking, Chipping, Flaking	21	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
197	5150	1	3			Classroom 304 Closet	W3	Chipping, Flaking	8	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
198	5150	1	3			Classroom 304 Closet	W4	Cracking, Flaking	24	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
199	5150	1	3			Classroom 306	Ceiling	Flaking, Efflorescence	32	Yes	No	N/A	N/A	Yes	
200	5150	1	3			Classroom 306	W1	Cracking, Chipping, Flaking	80	No	No	N/A	N/A	No	
201	5150	1	3			Classroom 306	W2	Chipping, Flaking	17	No	No	N/A	N/A	No	
202	5150	1	3			Classroom 306	W3	Chipping, Flaking	36	No	No	N/A	N/A	No	
203	5150	1	3			Classroom 306	W4	Chipping, Flaking	6	No	No	N/A	N/A	No	
204	5150	1	3			Classroom 306 Closet	Ceiling	Flaking	5	No	No	N/A	N/A	No	
205	5150	1	3			Classroom 306 Closet	W2	Cracking, Flaking	28	No	No	N/A	N/A	No	
206	5150	1	3			Classroom 306 Closet	W3	Cracking, Chipping, Flaking	83	No	No	N/A	N/A	No	
207	5150	1	3			Classroom 306 Closet	W4	Cracking, Chipping, Flaking	11	No	No	N/A	N/A	No	
208	5150	1	3			Classroom 307	Ceiling	Flaking	50	No	No	N/A	N/A	No	
209	5150	1	3			Classroom 307	W1	Cracking, Chipping, Flaking	29	No	No	N/A	N/A	No	
210	5150	1	3			Classroom 307	W2	Cracking, Chipping, Flaking	16	No	No	N/A	N/A	No	
211	5150	1	3			Classroom 307	W3	Chipping on wall and radiators, Flaking, Significant Moisture Damage behind radiators	66	Yes	No	N/A	N/A	Yes	
212	5150	1	3			Classroom 307	W4	Chipping, Flaking	15	No	No	N/A	N/A	No	
213	5150	1	3			Classroom 307 Closet	Ceiling	Flaking, Spalling, Efflorescence	20	Yes	No	N/A	N/A	Yes	
214	5150	1	3			Classroom 307 Closet	W2	Cracking, Hole, Flaking	4	No	No	N/A	Shelves, Cabinets	Yes	Limited inspection due to stored materials
215	5150	1	3			Classroom 307 Closet	W3	Chipping on radiator, Flaking, Efflorescence	17	Yes	Debris on windowsill	3	N/A	Yes	
216	5150	1	3			Classroom 307 Closet	W4	Chipping, Flaking	10	No	No	N/A	N/A	No	
217	5150	1	3			Classroom 308	Ceiling	Flaking above windows	2	No	No	N/A	N/A	No	
218	5150	1	3			Classroom 308	W1	Cracking, Chipping, Flaking	13	No	No	N/A	N/A	No	
219	5150	1	3			Classroom 308	W2	Cracking, Chipping, Hole	5	No	No	N/A	N/A	Yes	
220	5150	1	3			Classroom 308	W3	Chipping on wall, radiators, and asbestos pipe insulation, Flaking, Spalling, Efflorescence	39	Yes	No	N/A	N/A	Yes	
221	5150	1	3			Classroom 308	W4	Chipping, Flaking	10	No	No	N/A	N/A	No	
222	5150	1	3			Classroom 308 Closet	Ceiling	Flaking	11	No	No	N/A	N/A	No	
223	5150	1	3			Classroom 308 Closet	Floor	N/A	N/A	No	Paint Chips	10	N/A	No	
224	5150	1	3			Classroom 308 Closet	W1	Hole, Flaking	50	No	No	N/A	N/A	Yes	
225	5150	1	3			Classroom 308 Closet	W2	Flaking, Efflorescence	10	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored amaterials
226	5150	1	3			Classroom 308 Closet	W3	Flaking	50	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored amaterials
227	5150	1	3			Classroom 308 Closet	W4	Flaking	30	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
228	5150	1	3			Classroom 309	Ceiling	Holes, Flaking, Efflorescence above windows	9	Yes	No	N/A	N/A	Yes	
229	5150	1	3			Classroom 309	W1	Cracking, Chipping on wall and wood cove base	37	No	No	N/A	N/A	No	
230	5150	1	3			Classroom 309	W2	Cracking, Chipping on wall and wood cove base, Flaking	29	No	No	N/A	N/A	No	
231	5150	1	3			Classroom 309	W3	Cracking, Chipping on wall and wood cove base, Flaking, Efflorescence	33	Yes	No	N/A	N/A	Yes	
232	5150	1	3			Classroom 309	W4	Chipping	9	No	No	N/A	N/A	No	
233	5150	1	3			Classroom 309 Closet	Ceiling	Flaking	96	No	No	N/A	N/A	No	
234	5150	1	3			Classroom 309 Closet	W1	Cracking	1	No	No	N/A	N/A	No	
235	5150	1	3			Classroom 309 Closet	W2	Cracking, Flaking, Efflorescence	18	Yes	No	N/A	Shelves with stored materials	Yes	Limited inspection due to stored materials
236	5150	1	3			Classroom 309 Closet	W3	Flaking, Spalling	4	Yes	No	N/A	Cabinet	Yes	Limited inspection due to stored materials
237	5150	1	3			Classroom 309 Closet	W4	Flaking	7	No	No	N/A	N/A	No	
238	5150	1	3			Fire Tower near Classroom 301	Ceiling	Chipping, Flaking, Spalling	50	Yes	No	N/A	N/A	Yes	
239	5150	1	3			Fire Tower near Classroom 301	Floor	Flaking	100	No	No	N/A	N/A	No	
240	5150	1	3			Fire Tower near Classroom 301	W1	Chipping, Flaking on wall, door, and windows	78	No	No	N/A	N/A	No	
241	5150	1	3			Fire Tower near Classroom 301	W2	Flaking on wall, door, and window	63	No	No	N/A	N/A	No	
242	5150	1	3			Fire Tower near Classroom 301	W3	Chipping on windows, Flaking on wall, metal pipe, and metal bars	121	No	No	N/A	N/A	No	
243	5150	1	3			Fire Tower near Classroom 301	W4	Flaking on wall, window, and metal bars	111	No	No	N/A	N/A	No	
244	5150	1	3			Fire Tower near Classroom 309	Ceiling	Flaking, Efflorescence	36	Yes	No	N/A	N/A	Yes	
245	5150	1	3			Fire Tower near Classroom 309	Floor	Flaking	105	No	Paint Chips	5	N/A	No	
246	5150	1	3			Fire Tower near Classroom 309	W1	Flaking on wall, door, and window	62	No	No	N/A	N/A	No	
247	5150	1	3			Fire Tower near Classroom 309	W2	Flaking on wall, metal bars, window, and metal pipe	89	No	No	N/A	N/A	No	
248	5150	1	3			Fire Tower near Classroom 309	W3	Flaking on wall, metal bars, and windows	86	No	No	N/A	N/A	No	
249	5150	1	3			Fire Tower near Classroom 309	W4	Flaking on wall and door	51	No	No	N/A	N/A	No	
250	5150	1	3			Girl's Restroom next to Classroom 307	Ceiling	Cracking, Flaking	7	No	No	N/A	N/A	No	
251	5150	1	3			Girl's Restroom next to Classroom 307	Floor	Chipping	26	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
252	5150	1	3			Girl's Restroom next to Classroom 307	W1	Flaking	6	No	No	N/A	N/A	No	
253	5150	1	3			Girl's Restroom next to Classroom 307	W2	Cracking, Chipping on metal jacket, Flaking	58	No	No	N/A	N/A	No	
254	5150	1	3			Girl's Restroom next to Classroom 307	W3	Cracking, Flaking on wall and metal pipe	12	No	No	N/A	N/A	No	
255	5150	1	3			Girl's Restroom next to Classroom 307	W4	Cracking, Flaking	50	No	No	N/A	N/A	No	
256	5150	1	3			Hallway from Classrooms 303-307	Ceiling	Chipping, Flaking	200	No	No	N/A	N/A	No	
257	5150	1	3			Hallway from Classrooms 303-307	Floor	Chipping	7	No	No	N/A	N/A	No	
258	5150	1	3			Hallway from Classrooms 303-307	W1	Cracking, Chipping, Flaking	225	No	No	N/A	N/A	No	
259	5150	1	3			Hallway from Classrooms 303-307	W2	Cracking, Chipping	26	No	No	N/A	N/A	No	
260	5150	1	3			Hallway from Classrooms 303-307	W3	Cracking, Chipping on wall, metal jackets, and asbestos pipe insulation, Flaking	100	No	No	N/A	N/A	No	
261	5150	1	3			Hallway from Classrooms 303-307	W4	Cracking, Chipping, Flaking	36	No	No	N/A	N/A	No	
262	5150	1	3			Hallway outside Classrooms 301-302	Ceiling	Holes, Flaking	35	No	No	N/A	N/A	Yes	
263	5150	1	3			Hallway outside Classrooms 301-302	Floor	Chipping	6	No	No	N/A	N/A	No	
264	5150	1	3			Hallway outside Classrooms 301-302	W2	Cracking, Chipping, Flaking	110	No	No	N/A	N/A	No	
265	5150	1	3			Hallway outside Classrooms 301-302	W3	Cracking, Flaking	8	No	No	N/A	N/A	No	
266	5150	1	3			Hallway outside Classrooms 301-302	W4	Cracking, Chipping, Flaking	69	No	No	N/A	N/A	No	
267	5150	1	3			Hallway outside Classrooms 308-309	Ceiling	Flaking, Spalling, Efflorescence	100	Yes	No	N/A	N/A	Yes	
268	5150	1	3			Hallway outside Classrooms 308-309	Floor	Chipping	3	No	No	N/A	N/A	No	
269	5150	1	3			Hallway outside Classrooms 308-309	W2	Cracking, Chipping on wall and metal jacket, Flaking, Efflorescence	163	Yes	No	N/A	N/A	Yes	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
270	5150	1	3			Hallway outside Classrooms 308-309	W3	Cracking, Holes, Flaking, Efflorescence	20	Yes	No	N/A	N/A	Yes	
271	5150	1	3			Hallway outside Classrooms 308-309	W4	Cracking, Chipping, Flaking	122	No	No	N/A	N/A	No	
272	5150	1	3			Stairwell across from Classroom 304	Ceiling	Flaking	36	No	No	N/A	N/A	No	
273	5150	1	3			Stairwell across from Classroom 304	Floor	Chipping on stairs and railings	87	No	No	N/A	N/A	No	
274	5150	1	3			Stairwell across from Classroom 304	W1	Chipping on doors and doorframe	62	No	No	N/A	N/A	No	
275	5150	1	3			Stairwell across from Classroom 304	W2	Cracking, Chipping, Flaking	60	No	No	N/A	N/A	No	
276	5150	1	3			Stairwell across from Classroom 304	W3	Cracking, Chipping	32	No	No	N/A	N/A	No	
277	5150	1	3			Stairwell across from Classroom 304	W4	Cracking, Chipping, Flaking	62	No	No	N/A	N/A	No	
278	5150	1	3			Stairwell across from Classroom 306	Ceiling	Chipping, Flaking	31	No	No	N/A	N/A	No	
279	5150	1	3			Stairwell across from Classroom 306	Floor	Chipping on stairs and railings	105	No	No	N/A	N/A	No	
280	5150	1	3			Stairwell across from Classroom 306	W1	Chipping on doors and doorframe	49	No	No	N/A	N/A	No	
281	5150	1	3			Stairwell across from Classroom 306	W2	Cracking, Chipping, Flaking, Spalling	61	Yes	No	N/A	N/A	Yes	
282	5150	1	3			Stairwell across from Classroom 306	W3	Cracking, Chipping, Flaking	30	No	No	N/A	N/A	No	
283	5150	1	3			Stairwell across from Classroom 306	W4	Cracking, Chipping, Holes, Flaking	44	No	No	N/A	N/A	Yes	
284	5150	1	3			Teacher's Lounge	Ceiling	Flaking	360	No	No	N/A	N/A	No	
285	5150	1	3			Teacher's Lounge	Floor	N/A	N/A	No	Debris along wall 3	5	N/A	No	
286	5150	1	3			Teacher's Lounge	W1	Hole, Flaking	11	No	No	N/A	N/A	No	
287	5150	1	3			Teacher's Lounge	W2	Cracking, Flaking	38	No	No	N/A	N/A	No	
288	5150	1	3			Teacher's Lounge	W3	Flaking, Spalling, Efflorescence	44	Yes	No	N/A	N/A	Yes	
289	5150	1	3			Teacher's Lounge	W4	Cracking, Chipping, Flaking	41	No	No	N/A	N/A	No	
290	5150	1	3			Teacher's Lounge Kitchen	Ceiling	Cracking, Flaking	17	No	No	N/A	N/A	No	
291	5150	1	3			Teacher's Lounge Kitchen	W1	Cracking, Flaking	6	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
292	5150	1	3			Teacher's Lounge Kitchen	W2	Cracking, Flaking	8	No	No	N/A	N/A	No	
293	5150	1	3			Teacher's Lounge Kitchen	W3	Cracking, Chipping, Flaking on wall and sink	15	No	No	N/A	N/A	No	
294	5150	1	3			Teacher's Lounge Kitchen	W4	Cracking, Flaking	7	No	No	N/A	N/A	No	
295	5150	1	2			Boy's Restroom adjacent to IMC	Ceiling	Flaking, Efflorescence	88	Yes	No	N/A	N/A	Yes	
296	5150	1	2			Boy's Restroom adjacent to IMC	Floor	Chipping	2	No	No	N/A	N/A	No	
297	5150	1	2			Boy's Restroom adjacent to IMC	W1	Cracking, Flaking	22	No	No	N/A	N/A	No	
298	5150	1	2			Boy's Restroom adjacent to IMC	W2	Cracking, Flaking	108	No	No	N/A	N/A	No	
299	5150	1	2			Boy's Restroom adjacent to IMC	W3	Flaking, Efflorescence	15	Yes	No	N/A	N/A	Yes	
300	5150	1	2			Boy's Restroom adjacent to IMC	W4	Cracking, Flaking	24	No	No	N/A	N/A	No	
301	5150	1	2			Classroom 201	Ceiling	Flaking	52	No	No	N/A	N/A	No	
302	5150	1	2			Classroom 201	W1	Cracking, Chipping, Flaking	37	No	No	N/A	N/A	No	
303	5150	1	2			Classroom 201	W3	Cracking, Chipping on wall, radiators, and metal pipe, Flaking	76	No	No	N/A	N/A	No	
304	5150	1	2			Classroom 201	W4	Cracking, Flaking	14	No	No	N/A	N/A	No	
305	5150	1	2			Classroom 201 Closet	Ceiling	Flaking	6	No	No	N/A	N/A	No	
306	5150	1	2			Classroom 201 Closet	Floor	N/A	N/A	No	Paint chips and debris	10	N/A	No	
307	5150	1	2			Classroom 201 Closet	W1	Cracking	2	No	No	N/A	N/A	No	
308	5150	1	2			Classroom 201 Closet	W2	Cracking	2	No	No	N/A	N/A	No	
309	5150	1	2			Classroom 201 Closet	W3	Cracking, Efflorescence	4	Yes	No	N/A	N/A	Yes	
310	5150	1	2			Classroom 201 Closet	W4	Chipping, Flaking on wall and metal pipe	23	No	No	N/A	N/A	No	
311	5150	1	2			Classroom 202	Ceiling	Chipping, Flaking, Efflorescence	155	Yes	No	N/A	N/A	Yes	
312	5150	1	2			Classroom 202	W1	Cracking, Chipping, Flaking	15	No	No	N/A	N/A	No	
313	5150	1	2			Classroom 202	W2	Cracking, Chipping, Flaking	15	No	No	N/A	N/A	No	
314	5150	1	2			Classroom 202	W3	Cracking, Chipping, Flaking on wall and behind radiator, Efflorescence	40	Yes	No	N/A	N/A	Yes	
315	5150	1	2			Classroom 202 Closet	Ceiling	Flaking	36	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
316	5150	1	2			Classroom 202 Closet	Floor	Limited inspection due to stored materials	N/A	No	Paint chips and debris	10	Stored Materials	No	Limited inspection due to stored materials
317	5150	1	2			Classroom 202 Closet	W1	Chipping, Flaking	37	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
318	5150	1	2			Classroom 202 Closet	W2	Chipping	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
319	5150	1	2			Classroom 202 Closet	W3	Flaking	28	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
320	5150	1	2			Classroom 202 Closet	W4	Flaking, Efflorescence	35	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
321	5150	1	2			Classroom 205	Ceiling	Flaking	34	No	No	N/A	N/A	No	
322	5150	1	2			Classroom 205	W1	Cracking, Chipping, Flaking	57	No	No	N/A	N/A	No	
323	5150	1	2			Classroom 205	W2	Chipping, Flaking	7	No	No	N/A	N/A	No	
324	5150	1	2			Classroom 205	W3	Chipping, Flaking, Significant Moisture Damage behind radiators	49	Yes	No	N/A	N/A	Yes	
325	5150	1	2			Classroom 205	W4	Cracking, Chipping, Flaking	15	No	No	N/A	N/A	No	
326	5150	1	2			Classroom 205 Closet	Ceiling	Flaking	2	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
327	5150	1	2			Classroom 205 Closet	Floor	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
328	5150	1	2			Classroom 205 Closet	W1	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
329	5150	1	2			Classroom 205 Closet	W2	Cracking	8	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
330	5150	1	2			Classroom 205 Closet	W3	Cracking	15	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
331	5150	1	2			Classroom 205 Closet	W4	Flaking	7	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
332	5150	1	2			Classroom 206	Ceiling	Cracking, Holes, Flaking	52	No	No	N/A	N/A	No	
333	5150	1	2			Classroom 206	W1	Cracking, Chipping, Holes, Flaking	27	No	No	N/A	N/A	No	
334	5150	1	2			Classroom 206	W2	Cracking, Chipping, Flaking	19	No	No	N/A	N/A	No	
335	5150	1	2			Classroom 206	W3	Cracking, Chipping on wall and radiators, Flaking behind radiator, Significant Moisture Damage behind radiator	54	Yes	No	N/A	N/A	Yes	
336	5150	1	2			Classroom 206	W4	Cracking, Chipping, Flaking	10	No	No	N/A	N/A	No	
337	5150	1	2			Classroom 206 Closet	Ceiling	Chipping, Flaking	2	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
338	5150	1	2			Classroom 206 Closet	Floor	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
339	5150	1	2			Classroom 206 Closet	W1	Flaking	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
340	5150	1	2			Classroom 206 Closet	W2	Cracking, Flaking	12	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
341	5150	1	2			Classroom 206 Closet	W3	Flaking	8	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
342	5150	1	2			Classroom 206 Closet	W4	Cracking, Chipping, Flaking	18	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
343	5150	1	2			Classroom 207	Ceiling	Flaking	48	No	No	N/A	N/A	No	
344	5150	1	2			Classroom 207	W1	Cracking, Chipping	21	No	No	N/A	N/A	No	
345	5150	1	2			Classroom 207	W2	Cracking, Chipping	4	No	No	N/A	N/A	No	
346	5150	1	2			Classroom 207	W3	Cracking, Chipping, Flaking on wall and behind radiator	29	No	No	N/A	N/A	No	
347	5150	1	2			Classroom 207	W4	Chipping, Flaking	7	No	No	N/A	N/A	No	
348	5150	1	2			Classroom 207 Closet	Ceiling	Flaking	9	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
349	5150	1	2			Classroom 207 Closet	Floor	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
350	5150	1	2			Classroom 207 Closet	W1	Flaking	2	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
351	5150	1	2			Classroom 207 Closet	W2	Flaking	8	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
352	5150	1	2			Classroom 207 Closet	W3	Cracking, Flaking	38	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
353	5150	1	2			Classroom 207 Closet	W4	Cracking, Chipping, Flaking	17	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
354	5150	1	2			Classroom 208	Ceiling	Flaking	35	No	No	N/A	N/A	No	
355	5150	1	2			Classroom 208	W1	Cracking, Chipping, Flaking	20	No	No	N/A	N/A	No	
356	5150	1	2			Classroom 208	W2	Cracking, Chipping, Flaking	8	No	No	N/A	Shelves with books	No	Limited inspection due to stored materials
357	5150	1	2			Classroom 208	W3	Cracking, Chipping, Hole, Flaking	24	No	No	N/A	N/A	Yes	
358	5150	1	2			Classroom 208	W4	Chipping, Flaking	14	No	No	N/A	N/A	No	
359	5150	1	2			Classroom 208 Closet	Ceiling	Flaking	96	No	No	N/A	N/A	No	
360	5150	1	2			Classroom 208 Closet	Floor	N/A	N/A	No	Paint Chips	10	N/A	No	
361	5150	1	2			Classroom 208 Closet	W1	Cracking, Flaking	6	No	No	N/A	N/A	No	
362	5150	1	2			Classroom 208 Closet	W2	Flaking	75	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
363	5150	1	2			Classroom 208 Closet	W3	Cracking, Efflorescence	6	Yes	No	N/A	N/A	Yes	
364	5150	1	2			Classroom 208 Closet	W4	Flaking	75	No	No	N/A	N/A	No	
365	5150	1	2			Elevator	Ceiling	Chipping	2	No	No	N/A	N/A	N/A	
366	5150	1	2			Elevator	W1	Chipping	2	No	No	N/A	N/A	N/A	
367	5150	1	2			Elevator	W2	Chipping	3	No	No	N/A	N/A	N/A	
368	5150	1	2			Elevator	W3	Chipping	3	No	No	N/A	N/A	N/A	
369	5150	1	2			Elevator	W4	Chipping	2	No	No	N/A	N/A	N/A	
370	5150	1	2			Fire Tower near Classroom 201	Ceiling	Chipping, Flaking	11	No	No	N/A	N/A	No	
371	5150	1	2			Fire Tower near Classroom 201	Floor	Chipping, Flaking	105	No	No	N/A	N/A	No	
372	5150	1	2			Fire Tower near Classroom 201	W1	Flaking on wall, door, doorframe, and windows	75	No	No	N/A	N/A	No	
373	5150	1	2			Fire Tower near Classroom 201	W2	Flaking on wall, door, and doorframe	44	No	No	N/A	N/A	No	
374	5150	1	2			Fire Tower near Classroom 201	W3	Chipping, Flaking on wall, windows, metal pipe, and metal bars	108	No	No	N/A	N/A	No	
375	5150	1	2			Fire Tower near Classroom 201	W4	Flaking on wall, metal bars and window	56	No	No	N/A	N/A	No	
376	5150	1	2			Fire Tower near Classroom 208	Ceiling	Chipping, Flaking	10	No	No	N/A	N/A	No	
377	5150	1	2			Fire Tower near Classroom 208	Floor	Chipping, Flaking	77	No	No	N/A	N/A	No	
378	5150	1	2			Fire Tower near Classroom 208	W1	Flaking on wall, door, and windows	38	No	No	N/A	N/A	No	
379	5150	1	2			Fire Tower near Classroom 208	W2	Flaking on door, windowframe, metal pipe, and metal bars	90	No	No	N/A	N/A	No	
380	5150	1	2			Fire Tower near Classroom 208	W3	Flaking on wall and windows	68	No	No	N/A	N/A	No	
381	5150	1	2			Fire Tower near Classroom 208	W4	Flaking	14	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
382	5150	1	2			Former Projection Room across from Nurse's Office	Ceiling	Flaking, Efflorescence	45	Yes	No	N/A	N/A	Yes	
383	5150	1	2			Former Projection Room across from Nurse's Office	Floor	Chipping	45	No	Debris	10	N/A	No	
384	5150	1	2			Former Projection Room across from Nurse's Office	W1	Cracking, Efflorescence	24	Yes	No	N/A	N/A	Yes	
385	5150	1	2			Former Projection Room across from Nurse's Office	W2	Cracking	3	No	No	N/A	N/A	No	
386	5150	1	2			Former Projection Room across from Nurse's Office	W3	Chipping	2	No	No	N/A	N/A	No	
387	5150	1	2			Former Projection Room across from Nurse's Office	W4	Efflorescence	16	Yes	No	N/A	N/A	Yes	
388	5150	1	2			Hallway from Library to Classroom 206	Ceiling	Chipping, Flaking	48	No	No	N/A	N/A	No	
389	5150	1	2			Hallway from Library to Classroom 206	Floor	Chipping	8	No	No	N/A	N/A	No	
390	5150	1	2			Hallway from Library to Classroom 206	W1	Cracking, Chipping	64	No	No	N/A	N/A	No	
391	5150	1	2			Hallway from Library to Classroom 206	W2	Cracking, Chipping, Hole	17	No	No	N/A	N/A	Yes	
392	5150	1	2			Hallway from Library to Classroom 206	W3	Cracking, Chipping, Hole, Flaking, Spalling	34	Yes	No	N/A	N/A	Yes	
393	5150	1	2			Hallway from Library to Classroom 206	W4	Cracking, Flaking	19	No	No	N/A	N/A	No	
394	5150	1	2			Hallway outside Classrooms 201-202	Ceiling	Chipping, Flaking	41	No	No	N/A	N/A	No	
395	5150	1	2			Hallway outside Classrooms 201-202	W2	Cracking, Chipping, Flaking Spalling	38	Yes	No	N/A	N/A	Yes	
396	5150	1	2			Hallway outside Classrooms 201-202	W3	Cracking	2	No	No	N/A	N/A	No	
397	5150	1	2			Hallway outside Classrooms 201-202	W4	Cracking, Chipping on wall and radiators, Flaking	43	No	No	N/A	N/A	No	
398	5150	1	2			Hallway outside Classrooms 207-208	Ceiling	Chipping, Flaking	14	No	No	N/A	N/A	No	
399	5150	1	2			Hallway outside Classrooms 207-208	W2	Cracking, Chipping on wall, radiators, and metal jackets, Flaking	56	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
400	5150	1	2			Hallway outside Classrooms 207-208	W3	Cracking, Chipping, Flaking	11	No	No	N/A	N/A	No	
401	5150	1	2			Hallway outside Classrooms 207-208	W4	Cracking, Chipping, Flaking	21	No	No	N/A	N/A	No	
402	5150	1	2			Large Library Closet closest to Boy's Restroom	Ceiling	Flaking, Efflorescence	10	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
403	5150	1	2			Large Library Closet closest to Boy's Restroom	Floor	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
404	5150	1	2			Large Library Closet closest to Boy's Restroom	W1	Cracking, Chipping, Flaking	8	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
405	5150	1	2			Large Library Closet closest to Boy's Restroom	W2	Efflorescence	50	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
406	5150	1	2			Large Library Closet closest to Boy's Restroom	W3	Flaking	5	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
407	5150	1	2			Large Library Closet closest to Boy's Restroom	W4	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
408	5150	1	2			Large Library Closet closest to Nurse's Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
409	5150	1	2			Large Library Closet closest to Nurse's Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
410	5150	1	2			Large Library Closet closest to Nurse's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
411	5150	1	2			Large Library Closet closest to Nurse's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
412	5150	1	2			Large Library Closet closest to Nurse's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
413	5150	1	2			Large Library Closet closest to Nurse's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
414	5150	1	2			Library 203	Ceiling	Flaking above missing ceiling tile	8	No	No	N/A	N/A	No	
415	5150	1	2			Library 203	W1	Cracking, Chipping, Flaking	65	No	No	N/A	N/A	No	
416	5150	1	2			Library 203	W2	Chipping, Flaking	5	No	No	N/A	N/A	No	
417	5150	1	2			Library 203	W3	Chipping, Holes, Flaking, Efflorescence on wall and behind radiator	63	Yes	No	N/A	N/A	Yes	
418	5150	1	2			Library 203	W4	Cracking	50	No	No	N/A	N/A	No	
419	5150	1	2			Library Office	Ceiling	Flaking above missing ceiling tile	8	No	No	N/A	N/A	No	
420	5150	1	2			Library Office	W3	Flaking	6	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
421	5150	1	2			Library Office	W4	Chipping on radiator, Flaking, Efflorescence	18	Yes	No	N/A	N/A	Yes	
422	5150	1	2			Nurse's Office	Ceiling	Flaking	18	No	No	N/A	N/A	No	
423	5150	1	2			Nurse's Office	W1	Cracking, Flaking	8	No	No	N/A	N/A	No	
424	5150	1	2			Nurse's Office	W2	Cracking, Chipping, Flaking	5	No	No	N/A	N/A	No	
425	5150	1	2			Nurse's Office	W3	Flaking, Efflorescence	15	Yes	No	N/A	N/A	Yes	
426	5150	1	2			Nurse's Office	W4	Cracking, Chipping, Flaking	9	No	No	N/A	N/A	No	
427	5150	1	2			Nurse's Office Restroom	Ceiling	Cracking	3	No	No	N/A	N/A	No	
428	5150	1	2			Nurse's Office Restroom	W1	Cracking	3	No	No	N/A	N/A	No	
429	5150	1	2			Nurse's Office Restroom	W2	Cracking	7	No	No	N/A	N/A	No	
430	5150	1	2			Nurse's Office Restroom	W3	Cracking, Chipping on wall and metal jacket, Flaking	4	No	No	N/A	N/A	No	
431	5150	1	2			Nurse's Office Restroom	W4	Cracking, Chipping on medicine cabinet	12	No	No	N/A	N/A	No	
432	5150	1	2			Nurse's Office Vestibule	Ceiling	Flaking on metal pipe	2	No	No	N/A	N/A	No	
433	5150	1	2			Nurse's Office Vestibule	W1	Cracking, Chipping on door	9	No	No	N/A	N/A	No	
434	5150	1	2			Nurse's Office Vestibule	W2	Cracking, Flaking	8	No	No	N/A	N/A	No	
435	5150	1	2			Nurse's Office Vestibule	W3	Chipping, Flaking	4	No	No	N/A	N/A	No	
436	5150	1	2			Nurse's Office Vestibule	W4	Cracking	9	No	No	N/A	N/A	No	
437	5150	1	2			Small Library Closet closest to Nurse's Office	Ceiling	Flaking	7	No	No	N/A	N/A	No	
438	5150	1	2			Small Library Closet closest to Nurse's Office	W1	Flaking	12	No	No	N/A	N/A	No	
439	5150	1	2			Small Library Closet closest to Nurse's Office	W2	Cracking	8	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
440	5150	1	2			Small Library Closet closest to Nurse's Office	W3	Cracking, Flaking	6	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
441	5150	1	2			Small Library Closet closest to Nurse's Office	W4	Flaking	4	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
442	5150	1	2			Stairwell across from Classroom 205	Ceiling	Chipping, Flaking	14	No	No	N/A	N/A	No	
443	5150	1	2			Stairwell across from Classroom 205	Floor	Chipping on stairs and railings	76	No	No	N/A	N/A	No	
444	5150	1	2			Stairwell across from Classroom 205	W1	Chipping on doors and doorframe	38	No	No	N/A	N/A	No	
445	5150	1	2			Stairwell across from Classroom 205	W2	Chipping, Flaking	14	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
446	5150	1	2			Stairwell across from Classroom 205	W3	Cracking, Chipping on wall and radiator, Flaking on wall and behind radiator	37	No	No	N/A	N/A	No	
447	5150	1	2			Stairwell across from Classroom 205	W4	Cracking, Chipping	13	No	No	N/A	N/A	No	
448	5150	1	2			Stairwell across from Library	Ceiling	Chipping, Flaking	46	No	No	N/A	N/A	No	
449	5150	1	2			Stairwell across from Library	Floor	Chipping	25	No	No	N/A	N/A	No	
450	5150	1	2			Stairwell across from Library	W1	Chipping on doors and doorframe	42	No	No	N/A	N/A	No	
451	5150	1	2			Stairwell across from Library	W2	Cracking, Chipping, Flaking	48	No	No	N/A	N/A	No	
452	5150	1	2			Stairwell across from Library	W3	Cracking, Chipping on wall and radiator, Flaking	46	No	No	N/A	N/A	No	
453	5150	1	2			Stairwell across from Library	W4	Cracking, Chipping, Flaking	50	No	No	N/A	N/A	No	
454	5150	1	2			Women's Restroom adjacent to Classroom 206	Ceiling	Flaking on ceiling and metal pipe, Significant Moisture Damage	183	Yes	No	N/A	N/A	Yes	
455	5150	1	2			Women's Restroom adjacent to Classroom 206	Floor	Chipping	1	No	No	N/A	N/A	No	
456	5150	1	2			Women's Restroom adjacent to Classroom 206	W1	Cracking, Chipping, Flaking	31	No	No	N/A	N/A	No	
457	5150	1	2			Women's Restroom adjacent to Classroom 206	W2	Cracking, Chipping on metal jackets, Flaking, Efflorescence	31	Yes	No	N/A	N/A	Yes	
458	5150	1	2			Women's Restroom adjacent to Classroom 206	W3	Chipping on radiator, Flaking on wall and metal pipe	22	No	No	N/A	N/A	No	
459	5150	1	2			Women's Restroom adjacent to Classroom 206	W4	Chipping, Flaking	22	No	No	N/A	N/A	No	
460	5150	1	1			Assistant Principal's Office	Ceiling	Flaking	25	No	No	N/A	N/A	No	
461	5150	1	1			Assistant Principal's Office	W1	Flaking	2	No	No	N/A	N/A	No	
462	5150	1	1			Assistant Principal's Office	W2	Chipping, Flaking	9	No	No	N/A	N/A	No	
463	5150	1	1			Assistant Principal's Office	W3	Chipping, Flaking, Significant Moisture Damage behind radiator	6	Yes	No	N/A	N/A	Yes	
464	5150	1	1			Assistant Principal's Office Entrance Area	W1	Cracking	1	No	No	N/A	N/A	No	
465	5150	1	1			Assistant Principal's Office Entrance Area	W2	Cracking	1	No	No	N/A	N/A	No	
466	5150	1	1			Assistant Principal's Office Entrance Area	W3	Flaking	8	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
467	5150	1	1			Assistant Principal's Office Entrance Area	W4	Flaking	4	No	No	N/A	N/A	No	
468	5150	1	1			Athletic Director's Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
469	5150	1	1			Athletic Director's Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
470	5150	1	1			Athletic Director's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
471	5150	1	1			Athletic Director's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
472	5150	1	1			Athletic Director's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
473	5150	1	1			Athletic Director's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
474	5150	1	1			Auditorium	Ceiling	Chipping, Flaking, Efflorescence	140	Yes	No	N/A	N/A	No	
475	5150	1	1			Auditorium	Floor	N/A	N/A	No	Paint Chips	50	N/A	No	
476	5150	1	1			Auditorium	W1	Cracking, Chipping	12	No	No	N/A	N/A	No	
477	5150	1	1			Auditorium	W2	Chipping on wall and doors	13	No	No	N/A	N/A	No	
478	5150	1	1			Auditorium	W3	Chipping, Hole	2	No	No	N/A	N/A	No	
479	5150	1	1			Auditorium	W4	Cracking, Chipping on wall and doors, Efflorescence	30	Yes	No	N/A	N/A	No	
480	5150	1	1			Classroom 102	Ceiling	Holes, Flaking	26	No	No	N/A	N/A	Yes	
481	5150	1	1			Classroom 102	W1	Cracking, Chipping, Holes, Flaking, Efflorescence	52	Yes	No	N/A	Posters, Stored Materials	Yes	
482	5150	1	1			Classroom 102	W2	Cracking, Chipping, Flaking	11	No	No	N/A	Posters, Stored Materials	No	
483	5150	1	1			Classroom 102	W3	Cracking, Chipping, Flaking, Efflorescence	34	Yes	No	N/A	Posters, Stored Materials	Yes	
484	5150	1	1			Classroom 102	W4	Cracking, Flaking	5	No	No	N/A	Posters, Stored Materials	No	
485	5150	1	1			Classroom 102 Closet	Ceiling	Chipping, Flaking	8	No	No	N/A	N/A	No	
486	5150	1	1			Classroom 102 Closet	Floor	Chipping	36	No	No	N/A	N/A	No	
487	5150	1	1			Classroom 102 Closet	W1	Flaking	2	No	No	N/A	N/A	No	
488	5150	1	1			Classroom 102 Closet	W3	Chipping, Flaking	8	No	No	N/A	N/A	No	
489	5150	1	1			Classroom 102 Closet	W4	Chipping on radiator and plastic jacket, Efflorescence	12	Yes	No	N/A	N/A	Yes	
490	5150	1	1			Classroom 108	Ceiling	Flaking	22	No	No	N/A	N/A	No	
491	5150	1	1			Classroom 108	W1	Cracking, Chipping	17	No	No	N/A	N/A	No	
492	5150	1	1			Classroom 108	W2	Cracking, Chipping	3	No	No	N/A	N/A	No	
493	5150	1	1			Classroom 108	W3	Chipping, Flaking on wall and behind radiator	14	No	No	N/A	N/A	No	
494	5150	1	1			Classroom 108	W4	Cracking, Chipping on built in wood cabinet, Flaking	12	No	No	N/A	Cabinets	No	

Bodine -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
495	5150	1	1			Classroom 108 Closet adjacent to Entrance	Ceiling	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
496	5150	1	1			Classroom 108 Closet adjacent to Entrance	Floor	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
497	5150	1	1			Classroom 108 Closet adjacent to Entrance	W1	Cracking, Chipping, Flaking	6	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
498	5150	1	1			Classroom 108 Closet adjacent to Entrance	W2	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
499	5150	1	1			Classroom 108 Closet adjacent to Entrance	W3	Cracking, Flaking	9	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
500	5150	1	1			Classroom 108 Closet adjacent to Entrance	W4	Cracking, Flaking	6	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
501	5150	1	1			Classroom 109	Ceiling	Cracking, Chipping, Flaking	27	No	No	N/A	N/A	No	
502	5150	1	1			Classroom 109	W1	Cracking, Chipping, Flaking	33	No	No	N/A	N/A	No	
503	5150	1	1			Classroom 109	W2	Cracking, Chipping, Flaking	16	No	No	N/A	N/A	No	
504	5150	1	1			Classroom 109	W3	Chipping on wall and radiator, Hole, Flaking on wall and behind radiator, Efflorescence	71	Yes	No	N/A	N/A	Yes	
505	5150	1	1			Classroom 109	W4	Flaking	11	No	No	N/A	Furniture	No	Limited inspection due to furniture
506	5150	1	1			Classroom 109 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
507	5150	1	1			Classroom 109 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
508	5150	1	1			Classroom 109 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
509	5150	1	1			Classroom 109 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
510	5150	1	1			Classroom 109 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
511	5150	1	1			Classroom 109 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
512	5150	1	1			Closet between Counselor's Office and Teacher's Lounge	Ceiling	Flaking	1	No	No	N/A	Stored Materials	No	
513	5150	1	1			Closet between Counselor's Office and Teacher's Lounge	Floor	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
514	5150	1	1			Closet between Counselor's Office and Teacher's Lounge	W1	Hole	1	No	No	N/A	Stored Materials	Yes	
515	5150	1	1			Closet between Counselor's Office and Teacher's Lounge	W2	Cracking	30	No	No	N/A	Stored Materials	No	

Bodine -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
516	5150	1	1			Closet between Counselor's Office and Teacher's Lounge	W3	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
517	5150	1	1			Closet between Counselor's Office and Teacher's Lounge	W4	Cracking, Hole	21	No	No	N/A	Stored Materials	Yes	
518	5150	1	1			Closet next to Classroom 108 (former Restroom)	Ceiling	Chipping	2	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
519	5150	1	1			Closet next to Classroom 108 (former Restroom)	Floor	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
520	5150	1	1			Closet next to Classroom 108 (former Restroom)	W1	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
521	5150	1	1			Closet next to Classroom 108 (former Restroom)	W2	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
522	5150	1	1			Closet next to Classroom 108 (former Restroom)	W3	Flaking	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
523	5150	1	1			Closet next to Classroom 108 (former Restroom)	W4	Limited inspection due to stored materials	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
524	5150	1	1			Counselor's Office	Ceiling	Cracking, Flaking, Spalling	5	Yes	No	N/A	N/A	Yes	
525	5150	1	1			Counselor's Office	W1	Chipping on door and doorframe	23	No	No	N/A	N/A	No	
526	5150	1	1			Counselor's Office	W2	Chipping on wall and metal jackets, Efflorescence	13	Yes	Debris on printer and cabinet	5	N/A	Yes	
527	5150	1	1			Counselor's Office	W3	Chipping on radiator	10	No	No	N/A	N/A	No	
528	5150	1	1			Counselor's Office	W4	Chipping on wall and wood cove base	30	No	No	N/A	N/A	No	
529	5150	1	1			Fire Tower near Classroom 102	Ceiling	Flaking	5	No	No	N/A	N/A	No	
530	5150	1	1			Fire Tower near Classroom 102	Floor	Chipping, Flaking	59	No	No	N/A	N/A	No	
531	5150	1	1			Fire Tower near Classroom 102	W1	Chipping on door and doorframe, Flaking on door and doorframe	8	No	No	N/A	N/A	No	
532	5150	1	1			Fire Tower near Classroom 102	W2	Chipping on door and doorframe, Flaking on wall, doors, and doorframe	32	No	No	N/A	N/A	No	
533	5150	1	1			Fire Tower near Classroom 102	W3	Flaking on windows, metal bars, and metal pipe	70	No	No	N/A	N/A	No	
534	5150	1	1			Fire Tower near Classroom 102	W4	Flaking on wall and metal bars	53	No	No	N/A	N/A	No	
535	5150	1	1			Fire Tower near Classroom 109	Ceiling	Flaking	3	No	No	N/A	N/A	No	
536	5150	1	1			Fire Tower near Classroom 109	Floor	Flaking	53	No	No	N/A	N/A	No	
537	5150	1	1			Fire Tower near Classroom 109	W1	Chipping on door, Flaking	6	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
538	5150	1	1			Fire Tower near Classroom 109	W2	Flaking on metal bars, windowframe, and metal pipe	71	No	No	N/A	N/A	No	
539	5150	1	1			Fire Tower near Classroom 109	W3	Flaking on wall and windows	11	No	No	N/A	N/A	No	
540	5150	1	1			Fire Tower near Classroom 109	W4	Chipping on doors and doorframe, Flaking on wall, door, and doorframe	57	No	No	N/A	N/A	No	
541	5150	1	1			Hallway by Classrooms 108-109	Ceiling	Flaking, Efflorescence	12	Yes	No	N/A	N/A	Yes	
542	5150	1	1			Hallway by Classrooms 108-109	Floor	Chipping	2	No	No	N/A	N/A	No	
543	5150	1	1			Hallway by Classrooms 108-109	W2	Cracking, Chipping on wall, radiators, and metal jackets, Flaking, Efflorescence	40	Yes	No	N/A	N/A	Yes	
544	5150	1	1			Hallway by Classrooms 108-109	W3	Cracking, Flaking	16	No	No	N/A	N/A	No	
545	5150	1	1			Hallway by Classrooms 108-109	W4	Cracking, Chipping	16	No	No	N/A	N/A	No	
546	5150	1	1			Hallway from Counselor's Office to Principal's Office	Ceiling	Cracking, Chipping, Flaking	87	No	No	N/A	N/A	No	
547	5150	1	1			Hallway from Counselor's Office to Principal's Office	Floor	Chipping	19	No	No	N/A	N/A	No	
548	5150	1	1			Hallway from Counselor's Office to Principal's Office	W1	Cracking, Chipping, Flaking	56	No	No	N/A	N/A	No	
549	5150	1	1			Hallway from Counselor's Office to Principal's Office	W2	Chipping	8	No	No	N/A	N/A	No	
550	5150	1	1			Hallway from Counselor's Office to Principal's Office	W3	Chipping, Flaking	73	No	No	N/A	N/A	No	
551	5150	1	1			Hallway from Counselor's Office to Principal's Office	W4	Cracking, Chipping	10	No	No	N/A	N/A	No	
552	5150	1	1			Hallway outside Classroom 102	Ceiling	Flaking, Efflorescence	32	No	No	N/A	N/A	No	
553	5150	1	1			Hallway outside Classroom 102	W2	Cracking, Chipping, Flaking	23	No	No	N/A	N/A	No	
554	5150	1	1			Hallway outside Classroom 102	W3	Cracking	19	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
555	5150	1	1			Hallway outside Classroom 102	W4	Cracking, Chipping on wall, radiator, and metal jackets, Flaking, Efflorescence	92	No	Debris on windowsills	9	N/A	No	
556	5150	1	1			Main Entrance Stairwell	Ceiling	Flaking	26	No	No	N/A	N/A	No	
557	5150	1	1			Main Entrance Stairwell	W1	Cracking, Chipping on doors and doorframe, Flaking	45	No	No	N/A	N/A	No	
558	5150	1	1			Main Entrance Stairwell	W2	Cracking, Flaking	24	No	No	N/A	N/A	No	
559	5150	1	1			Main Entrance Stairwell	W4	Cracking, Chipping, Flaking	50	No	No	N/A	N/A	No	
560	5150	1	1			Main Office	W1	Cracking, Chipping, Hole	5	No	No	N/A	N/A	Yes	
561	5150	1	1			Main Office	W3	Chipping	1	No	No	N/A	N/A	No	
562	5150	1	1			Main Office Closet adjacent to Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
563	5150	1	1			Main Office Closet adjacent to Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
564	5150	1	1			Main Office Closet adjacent to Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
565	5150	1	1			Main Office Closet adjacent to Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
566	5150	1	1			Main Office Closet adjacent to Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
567	5150	1	1			Main Office Closet adjacent to Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
568	5150	1	1			Main Office Hallway outside Restroom	Ceiling	Flaking	16	No	No	N/A	N/A	No	
569	5150	1	1			Main Office Hallway outside Restroom	W1	Chipping on wood cove base	2	No	No	N/A	N/A	No	
570	5150	1	1			Main Office Hallway outside Restroom	W4	Cracking, Chipping on wall and wood cove base	14	No	No	N/A	N/A	No	
571	5150	1	1			Main Office Large Closet	Ceiling	Flaking	4	No	No	N/A	N/A	No	
572	5150	1	1			Main Office Large Closet	W1	Cracking	3	No	No	N/A	N/A	No	
573	5150	1	1			Main Office Large Closet	W3	Cracking	3	No	No	N/A	N/A	No	
574	5150	1	1			Main Office Large Closet	W4	Cracking	5	No	No	N/A	N/A	No	
575	5150	1	1			Main Office Restroom	Ceiling	Hole	1	No	No	N/A	N/A	No	
576	5150	1	1			Main Office Restroom	W4	Cracking	3	No	No	N/A	N/A	No	
577	5150	1	1			Main Office Small Closet	Ceiling	Flaking	2	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
578	5150	1	1			Main Office Small Closet	W1	Cracking	1	No	No	N/A	N/A	No	
579	5150	1	1			Main Office Small Closet	W2	Cracking, Flaking	7	No	No	N/A	N/A	No	
580	5150	1	1			Main Office Small Closet	W3	Cracking	9	No	No	N/A	N/A	No	
581	5150	1	1			Main Office Small Closet	W4	Chipping	3	No	No	N/A	N/A	No	
582	5150	1	1			Office between Main Office and Principal's Office	Ceiling	Flaking	1	No	No	N/A	N/A	No	
583	5150	1	1			Office between Main Office and Principal's Office	W1	Cracking	1	No	No	N/A	N/A	No	
584	5150	1	1			Office between Main Office and Principal's Office	W3	Cracking, Holes	8	No	No	N/A	N/A	Yes	
585	5150	1	1			Office between Main Office and Principal's Office	W4	Chipping on radiator	10	No	No	N/A	N/A	No	
586	5150	1	1			Office Suite 105 Climate Support Office	Ceiling	Flaking	6	No	No	N/A	N/A	No	
587	5150	1	1			Office Suite 105 Climate Support Office	W1	Chipping	6	No	No	N/A	N/A	No	
588	5150	1	1			Office Suite 105 Climate Support Office	W2	Chipping	1	No	No	N/A	Cabinets	No	
589	5150	1	1			Office Suite 105 Climate Support Office	W3	Chipping	1	No	No	N/A	N/A	No	
590	5150	1	1			Office Suite 105 Climate Support Office	W4	Chipping, Flaking on wall and metal pipe	15	No	No	N/A	N/A	No	
591	5150	1	1			Office Suite 105 Common Area	Ceiling	Efflorescence	4	Yes	No	N/A	N/A	Yes	
592	5150	1	1			Office Suite 105 Common Area	W1	Chipping, Flaking	5	No	No	N/A	N/A	No	
593	5150	1	1			Office Suite 105 Common Area	W2	Chipping, Hole	8	No	No	N/A	N/A	No	
594	5150	1	1			Office Suite 105 Common Area	W4	Cracking, Chipping, Flaking, Efflorescence	45	Yes	No	N/A	N/A	Yes	
595	5150	1	1			Office Suite 105 Storage Room (labeled World Affairs Council)	Ceiling	Flaking	2	No	No	N/A	N/A	No	
596	5150	1	1			Office Suite 105 Storage Room (labeled World Affairs Council)	W1	Chipping on doorframe	5	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
597	5150	1	1			Office Suite 105 Storage Room (labeled World Affairs Council)	W2	Cracking, Hole	7	No	No	N/A	N/A	Yes	
598	5150	1	1			Office Suite 105 World Affairs Council Office	Ceiling	Flaking	3	No	No	N/A	N/A	No	
599	5150	1	1			Office Suite 105 World Affairs Council Office	W1	Chipping on doorframe	1	No	No	N/A	N/A	No	
600	5150	1	1			Office Suite 105 World Affairs Council Office	W2	Chipping	5	No	No	N/A	N/A	No	
601	5150	1	1			Office Suite 105 World Affairs Council Office	W3	Chipping, Flaking	2	No	No	N/A	N/A	No	
602	5150	1	1			Office Suite 105 World Affairs Council Office	W4	Flaking	2	No	No	N/A	N/A	No	
603	5150	1	1			Principal's Conference Room	Ceiling	Flaking	10	No	No	N/A	N/A	No	
604	5150	1	1			Principal's Conference Room	W1	Limited inspection due to stored materials	N/A	No	No	N/A	Cabinets	No	Limited inspection due to stored materials
605	5150	1	1			Principal's Conference Room	W2	Cracking, Efflorescence	11	Yes	No	N/A	N/A	Yes	
606	5150	1	1			Principal's Conference Room	W3	Chipping on radiator, Flaking, Spalling, Significant Moisture Damage behind radiator	21	Yes	No	N/A	N/A	Yes	
607	5150	1	1			Principal's Conference Room	W4	Cracking, Chipping	6	No	No	N/A	N/A	No	
608	5150	1	1			Principal's Conference Room Entrance Hallway	W1	Hole	1	No	No	N/A	N/A	Yes	
609	5150	1	1			Principal's Conference Room Entrance Hallway	W2	Cracking, Holes	5	No	No	N/A	N/A	Yes	
610	5150	1	1			Principal's Conference Room Entrance Hallway	W3	Chipping on asbestos pipe insulation, Hole	2	No	No	N/A	N/A	Yes	
611	5150	1	1			Principal's Conference Room Entrance Hallway	W4	Cracking, Chipping	7	No	No	N/A	N/A	No	
612	5150	1	1			Principal's Office	Ceiling	Flaking on ceiling and metal pipe	7	No	No	N/A	N/A	No	
613	5150	1	1			Principal's Office	W1	Cracking, Chipping	7	No	No	N/A	N/A	No	
614	5150	1	1			Principal's Office	W3	Flaking	18	No	No	N/A	N/A	No	
615	5150	1	1			Principal's Office	W4	Chipping, Flaking behind radiator	7	No	No	N/A	N/A	No	
616	5150	1	1			Stage	Ceiling	Chipping, Flaking	25	No	No	N/A	N/A	No	
617	5150	1	1			Stage	W1	Chipping, Flaking	25	No	No	N/A	N/A	No	
618	5150	1	1			Stage	W2	Cracking, Flaking	26	No	No	N/A	N/A	No	
619	5150	1	1			Stage	W3	Cracking, Chipping	19	No	No	N/A	N/A	No	
620	5150	1	1			Stage	W4	Cracking, Chipping	15	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
621	5150	1	1			Stairs to Left of Stairs	Ceiling	Flaking, Efflorescence	14	Yes	No	N/A	N/A	Yes	
622	5150	1	1			Stairs to Left of Stairs	Floor	N/A	N/A	No	Paint chips on floor and music stands	10	N/A	No	
623	5150	1	1			Stairs to Left of Stairs	W1	Chipping, Flaking	3	No	No	N/A	N/A	No	
624	5150	1	1			Stairs to Left of Stairs	W2	Cracking, Chipping on wall and door, Flaking, Efflorescence	70	Yes	No	N/A	N/A	Yes	
625	5150	1	1			Stairs to Left of Stairs	W3	Cracking, Chipping on wall and metal pipe, Flaking	44	No	No	N/A	N/A	No	
626	5150	1	1			Stairs to Left of Stairs	W4	Cracking, Chipping, Flaking	45	No	No	N/A	N/A	No	
627	5150	1	1			Stairs to Right of Stage	Ceiling	Flaking	12	No	No	N/A	N/A	No	
628	5150	1	1			Stairs to Right of Stage	Floor	N/A	N/A	No	Paint Chips	10	N/A	No	
629	5150	1	1			Stairs to Right of Stage	W1	Chipping	3	No	No	N/A	N/A	No	
630	5150	1	1			Stairs to Right of Stage	W2	Cracking, Chipping, Flaking, Spalling	11	Yes	No	N/A	N/A	Yes	
631	5150	1	1			Stairs to Right of Stage	W3	Cracking, Chipping, Flaking, Spalling	29	Yes	No	N/A	N/A	Yes	
632	5150	1	1			Stairs to Right of Stage	W4	Chipping on wall and metal pipes, Flaking, Efflorescence	37	Yes	Paint chips on windowsills	5	N/A	Yes	
633	5150	1	1			Stairwell by Counselor's Office	Ceiling	Flaking, Spalling	58	Yes	No	N/A	N/A	Yes	
634	5150	1	1			Stairwell by Counselor's Office	Floor	Chipping on stairs and railings	69	No	No	N/A	N/A	No	
635	5150	1	1			Stairwell by Counselor's Office	W1	Chipping on wall, doors, and doorframe, Flaking	46	No	No	N/A	N/A	No	
636	5150	1	1			Stairwell by Counselor's Office	W2	Cracking, Chipping on wall and metal pipes, Flaking, Efflorescence	47	Yes	No	N/A	N/A	Yes	
637	5150	1	1			Stairwell by Counselor's Office	W3	Chipping on wall, doors, and doorframe, Hole, Flaking	37	No	No	N/A	N/A	Yes	
638	5150	1	1			Stairwell by Counselor's Office	W4	Cracking, Chipping on wall and radiator, Flaking	45	No	No	N/A	N/A	No	
639	5150	1	1			Stairwell by Principal's Office	Ceiling	Flaking	33	No	No	N/A	N/A	No	
640	5150	1	1			Stairwell by Principal's Office	Floor	Chipping on stairs and railings	72	No	No	N/A	N/A	No	
641	5150	1	1			Stairwell by Principal's Office	W1	Chipping on doors and doorframe	46	No	No	N/A	N/A	No	
642	5150	1	1			Stairwell by Principal's Office	W2	Cracking, Chipping on wall and radiator	64	No	No	N/A	N/A	No	
643	5150	1	1			Stairwell by Principal's Office	W3	Chipping on wall, doors, and doorframe	23	No	No	N/A	N/A	No	
644	5150	1	1			Stairwell by Principal's Office	W4	Cracking, Chipping on wall and metal pipes	61	No	No	N/A	N/A	No	
645	5150	1	1			Storage Room 101	Ceiling	Chipping, Holes, Flaking	94	No	No	N/A	N/A	Yes	
646	5150	1	1			Storage Room 101	W1	Cracking	16	No	No	N/A	N/A	No	
647	5150	1	1			Storage Room 101	W2	Cracking, Chipping	3	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
648	5150	1	1			Storage Room 101	W3	Chipping on radiator, Spalling, Efflorescence behind radiator	15	Yes	No	N/A	N/A	Yes	
649	5150	1	1			Storage Room 101	W4	Flaking, Spalling	6	Yes	No	N/A	N/A	Yes	
650	5150	1	1			Teacher's Lounge	Ceiling	Flaking	4	No	No	N/A	N/A	No	
651	5150	1	1			Teacher's Lounge	W2	Chipping on plastic jacket, Flaking	20	No	No	N/A	N/A	No	
652	5150	1	1			Teacher's Lounge	W3	Cracking, Flaking	150	No	No	N/A	N/A	No	
653	5150	1	1			Teacher's Lounge	W4	Hole, Flaking	3	No	No	N/A	N/A	Yes	
654	5150	1	1			Teacher's Lounge Men's Restroom	Ceiling	Flaking	3	No	No	N/A	N/A	No	
655	5150	1	1			Teacher's Lounge Men's Restroom	Floor	Chipping	5	No	No	N/A	N/A	No	
656	5150	1	1			Teacher's Lounge Men's Restroom	W1	Cracking, Chipping on wall and doorframe, Flaking	35	No	No	N/A	N/A	No	
657	5150	1	1			Teacher's Lounge Men's Restroom	W2	Cracking, Chipping on radiator, Flaking	53	No	No	N/A	N/A	No	
658	5150	1	1			Teacher's Lounge Men's Restroom	W3	Cracking, Chipping, Flaking	75	No	No	N/A	N/A	No	
659	5150	1	1			Teacher's Lounge Men's Restroom	W4	Chipping	1	No	No	N/A	N/A	No	
660	5150	1	1			Teacher's Lounge Vestibule	Ceiling	Cracking	2	No	No	N/A	N/A	No	
661	5150	1	1			Teacher's Lounge Vestibule	W1	Cracking, Chipping	10	No	No	N/A	N/A	No	
662	5150	1	1			Teacher's Lounge Vestibule	W2	Cracking, Flaking	3	No	No	N/A	N/A	No	
663	5150	1	1			Teacher's Lounge Vestibule Closet	Ceiling	Hole	1	No	No	N/A	N/A	Yes	
664	5150	1	1			Teacher's Lounge Vestibule Closet	W1	Chipping on doorframe	1	No	No	N/A	N/A	No	
665	5150	1	1			Teacher's Lounge Vestibule Closet	W2	Chipping	3	No	No	N/A	N/A	No	
666	5150	1	1			Teacher's Lounge Vestibule Closet	W4	Chipping	3	No	No	N/A	N/A	No	
667	5150	1	1			Upper Storage Room to Left of Stage	Ceiling	Cracking, Flaking	18	No	No	N/A	Instruments	No	Limited inspection due to instruments
668	5150	1	1			Upper Storage Room to Left of Stage	Floor	Limited inspection due to instruments	N/A	No	Paint Chips	5	Instruments	No	Limited inspection due to instruments
669	5150	1	1			Upper Storage Room to Left of Stage	W1	Chipping, Flaking	9	No	No	N/A	Instruments	No	Limited inspection due to instruments
670	5150	1	1			Upper Storage Room to Left of Stage	W2	Chipping	1	No	No	N/A	Instruments	No	Limited inspection due to instruments
671	5150	1	1			Upper Storage Room to Left of Stage	W3	Cracking, Chipping, Flaking	17	No	No	N/A	Instruments	No	Limited inspection due to instruments
672	5150	1	1			Upper Storage Room to Left of Stage	W4	Cracking, Flaking	2	No	No	N/A	Instruments	No	Limited inspection due to instruments

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
673	5150	1	1			Upper Storage Room to Right of Stage	Ceiling	Flaking, Efflorescence	13	Yes	No	N/A	Instruments	Yes	Limited inspection due to instruments
674	5150	1	1			Upper Storage Room to Right of Stage	Floor	Limited inspection due to instruments	N/A	No	Paint Chips	20	Instruments	No	Limited inspection due to instruments
675	5150	1	1			Upper Storage Room to Right of Stage	W1	Cracking	4	No	No	N/A	Instruments	No	Limited inspection due to instruments
676	5150	1	1			Upper Storage Room to Right of Stage	W2	Cracking, Flaking	5	No	No	N/A	Instruments	No	Limited inspection due to instruments
677	5150	1	1			Upper Storage Room to Right of Stage	W3	Cracking, Chipping on metal pipe	7	No	No	N/A	Instruments	No	Limited inspection due to instruments
678	5150	1	1			Upper Storage Room to Right of Stage	W4	Cracking	4	No	No	N/A	Instruments	No	Limited inspection due to instruments
679	5150	1	1			Vestibule outside Assistant Principal's Office	W1	Cracking, Hole	2	No	No	N/A	N/A	Yes	
680	5150	1	1			Vestibule outside Assistant Principal's Office	W3	Cracking, Flaking	6	No	No	N/A	N/A	No	
681	5150	1	1			Vestibule outside Assistant Principal's Office	W4	Flaking	5	No	No	N/A	N/A	No	
682	5150	1	1			Women's Restroom adjacent to Classroom 108	Ceiling	Flaking on ceiling and metal pipes	193	No	No	N/A	N/A	No	
683	5150	1	1			Women's Restroom adjacent to Classroom 108	W1	Cracking, Chipping on doorframe, Flaking	72	No	No	N/A	N/A	No	
684	5150	1	1			Women's Restroom adjacent to Classroom 108	W2	Flaking on wall and metal jackets	82	No	No	N/A	N/A	No	
685	5150	1	1			Women's Restroom adjacent to Classroom 108	W3	Chipping on radiator, Flaking	18	No	No	N/A	N/A	No	
686	5150	1	1			Women's Restroom adjacent to Classroom 108	W4	Flaking	75	No	No	N/A	N/A	No	
687	5150	1	0			Art Room	Ceiling	Flaking, Efflorescence, Significant Moisture Damage	19	Yes	No	N/A	N/A	Yes	
688	5150	1	0			Art Room	Floor	Chipping	14	No	No	N/A	N/A	No	
689	5150	1	0			Art Room	W1	Chipping on wall and metal pipes	11	No	No	N/A	N/A	No	
690	5150	1	0			Art Room	W2	Chipping	1	No	No	N/A	N/A	No	
691	5150	1	0			Art Room	W3	Chipping, Flaking on wall and metal pipe, Efflorescence	15	Yes	No	N/A	N/A	Yes	
692	5150	1	0			Art Room	W4	Chipping, Flaking, Efflorescence	18	No	No	N/A	N/A	No	
693	5150	1	0			Art Room Closet adjacent to Hallway	Ceiling	Limited inspection due to stored materials	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
694	5150	1	0			Art Room Closet adjacent to Hallway	Floor	Limited inspection due to stored materials	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
695	5150	1	0			Art Room Closet adjacent to Hallway	W1	Limited inspection due to stored materials	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
696	5150	1	0			Art Room Closet adjacent to Hallway	W2	Chipping, Flaking	5	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
697	5150	1	0			Art Room Closet adjacent to Hallway	W3	Limited inspection due to stored materials	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
698	5150	1	0			Art Room Closet adjacent to Hallway	W4	Limited inspection due to stored materials	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
699	5150	1	0			Art Room Storage Room	Ceiling	Flaking on ceiling and metal pipe	7	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
700	5150	1	0			Art Room Storage Room	Floor	Limited inspection due to stored materials	N/A	No	Debris	3	Shelves with stored materials	No	Limited inspection due to stored materials
701	5150	1	0			Art Room Storage Room	W1	Cracking, Chipping, Flaking	12	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
702	5150	1	0			Art Room Storage Room	W2	Chipping, Hole, Flaking, Efflorescence	21	Yes	No	N/A	Shelves with stored materials	Yes	Limited inspection due to stored materials
703	5150	1	0			Art Room Storage Room	W3	Hole, Flaking	2	No	No	N/A	Shelves with stored materials	Yes	Limited inspection due to stored materials
704	5150	1	0			Art Room Storage Room	W4	Holes, Flaking	9	No	No	N/A	Shelves with stored materials	Yes	Limited inspection due to stored materials
705	5150	1	0			Art Room Storage Room Closet	Ceiling	Flaking on ceiling and metal pipes	11	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
706	5150	1	0			Art Room Storage Room Closet	Floor	Limited inspection due to stored materials	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
707	5150	1	0			Art Room Storage Room Closet	W1	Chipping, Flaking	2	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
708	5150	1	0			Art Room Storage Room Closet	W2	Flaking on wall and metal pipe	3	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
709	5150	1	0			Art Room Storage Room Closet	W3	Flaking, Efflorescence	6	Yes	No	N/A	Shelves with stored materials	Yes	Limited inspection due to stored materials
710	5150	1	0			Art Room Storage Room Closet	W4	Cracking, Hole, Flaking	8	No	No	N/A	Shelves with stored materials	Yes	Limited inspection due to stored materials
711	5150	1	0			Boy's Restroom	Ceiling	Cracking, Chipping on radiators, Flaking	80	No	No	N/A	N/A	No	
712	5150	1	0			Boy's Restroom	Floor	Chipping	14	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
713	5150	1	0			Boy's Restroom	W1	Chipping on door and doorframe	12	No	No	N/A	N/A	No	
714	5150	1	0			Boy's Restroom	W3	Chipping on urinal covers	6	No	No	N/A	N/A	No	
715	5150	1	0			Boy's Restroom	W4	Chipping on marble, Flaking on metal jackets	19	No	No	N/A	N/A	No	
716	5150	1	0			Boy's Side Stairwell Storage Room	Ceiling	Cracking, Flaking, Significant Moisture Damage	100	Yes	No	N/A	N/A	No	
717	5150	1	0			Boy's Side Stairwell Storage Room	Floor	N/A	N/A	No	Debris	350	N/A	No	
718	5150	1	0			Boy's Side Stairwell Storage Room	W1	Chipping on door and doorframe, Flaking, Efflorescence	27	Yes	No	N/A	N/A	No	
719	5150	1	0			Boy's Side Stairwell Storage Room	W2	Flaking, Efflorescence	75	Yes	No	N/A	N/A	No	
720	5150	1	0			Boy's Side Stairwell Storage Room	W3	Flaking, Efflorescence	70	Yes	No	N/A	N/A	No	
721	5150	1	0			Boy's Side Stairwell Storage Room	W4	Flaking, Efflorescence	50	Yes	No	N/A	N/A	No	
722	5150	1	0			Food Service Storage Room	Ceiling	Chipping, Holes, Flaking, Efflorescence	101	Yes	No	N/A	N/A	No	
723	5150	1	0			Food Service Storage Room	Floor	N/A	N/A	No	Paint chips and debris on floor and stored materials	123	N/A	No	
724	5150	1	0			Food Service Storage Room	W1	Chipping on door and doorframe, Efflorescence	28	Yes	No	N/A	N/A	No	
725	5150	1	0			Food Service Storage Room	W2	Chipping, Flaking on wall and windowframes, Efflorescence	105	Yes	No	N/A	Lockers, Stored Materials	No	
726	5150	1	0			Food Service Storage Room	W3	Chipping	70	Yes	No	N/A	N/A	No	
727	5150	1	0			Food Service Storage Room	W4	Chipping, Flaking, Efflorescence	67	Yes	No	N/A	Stored Materials	No	
728	5150	1	0			Girl's Restroom	Ceiling	Hole, Flaking, Efflorescence	110	Yes	No	N/A	N/A	Yes	
729	5150	1	0			Girl's Restroom	Floor	Chipping	12	No	Paint Chips	10	N/A	No	
730	5150	1	0			Girl's Restroom	W2	Chipping	9	No	No	N/A	N/A	No	
731	5150	1	0			Girl's Restroom	W3	Chipping on wall and metal pipe, Flaking	12	No	No	N/A	N/A	No	
732	5150	1	0			Girl's Side Stairwell Storage Room	Ceiling	Flaking	25	No	No	N/A	N/A	No	
733	5150	1	0			Girl's Side Stairwell Storage Room	Floor	Chipping	120	No	Debris on floor and stored materials	120	N/A	No	
734	5150	1	0			Girl's Side Stairwell Storage Room	W1	Flaking	20	No	No	N/A	N/A	No	
735	5150	1	0			Girl's Side Stairwell Storage Room	W2	Flaking	30	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
736	5150	1	0			Girl's Side Stairwell Storage Room	W3	Flaking	30	No	No	N/A	N/A	No	
737	5150	1	0			Girl's Side Stairwell Storage Room	W4	Flaking	10	No	No	N/A	N/A	No	
738	5150	1	0			Gym Office	Ceiling	Flaking	10	No	No	N/A	N/A	No	
739	5150	1	0			Gym Office	W4	Chipping	3	No	No	N/A	N/A	No	
740	5150	1	0			Gym Storage Room	Ceiling	Cracking, Flaking	14	No	No	N/A	N/A	No	
741	5150	1	0			Gym Storage Room	W1	Chipping on wall and conduit	11	No	No	N/A	N/A	No	
742	5150	1	0			Gym Storage Room	W2	Chipping	7	No	No	N/A	N/A	No	
743	5150	1	0			Gym Storage Room	W3	Chipping	7	No	No	N/A	N/A	No	
744	5150	1	0			Gym Storage Room	W4	Chipping	12	No	No	N/A	N/A	No	
745	5150	1	0			Gym/Cafeteria	Ceiling	Cracking, Flaking, Spalling	688	Yes	No	N/A	N/A	Yes	
746	5150	1	0			Gym/Cafeteria	Floor	Chipping	117	No	Paint Chips	3	N/A	No	
747	5150	1	0			Gym/Cafeteria	W1	Chipping, Flaking	16	No	No	N/A	N/A	No	
748	5150	1	0			Gym/Cafeteria	W2	Chipping on wall and metal pipe, Flaking, Efflorescence	68	Yes	No	N/A	N/A	No	
749	5150	1	0			Gym/Cafeteria	W3	Flaking, Efflorescence	34	Yes	No	N/A	N/A	No	
750	5150	1	0			Gym/Cafeteria	W4	Chipping on wall and metal pipe, Flaking, Efflorescence	40	Yes	No	N/A	N/A	No	
751	5150	1	0			Hallway from Fan Room to Boiler Room	Ceiling	Flaking	168	No	No	N/A	N/A	No	
752	5150	1	0			Hallway from Fan Room to Boiler Room	W1	Flaking	336	No	No	N/A	N/A	No	
753	5150	1	0			Hallway from Fan Room to Boiler Room	W2	Flaking	336	No	No	N/A	N/A	No	
754	5150	1	0			Hallway from Fan Room to Boiler Room	W3	Flaking	336	No	No	N/A	N/A	No	
755	5150	1	0			Hallway outside Boy's Restroom/Art Room	Ceiling	Flaking on ceiling and metal duct, Spalling, Significant Moisture Damage	34	No	No	N/A	N/A	Yes	
756	5150	1	0			Hallway outside Boy's Restroom/Art Room	Floor	Chipping	13	No	No	N/A	N/A	No	
757	5150	1	0			Hallway outside Boy's Restroom/Art Room	W2	Chipping on metal jackets, Flaking, Efflorescence	58	No	No	N/A	N/A	No	
758	5150	1	0			Hallway outside Boy's Restroom/Art Room	W3	Chipping on doors and doorframe, Flaking on wall, doors, and doorframe, Efflorescence	27	No	No	N/A	N/A	No	

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
759	5150	1	0			Hallway outside Boy's Restroom/Art Room	W4	Chipping, Hole	5	No	No	N/A	N/A	No	
760	5150	1	0			Hallway outside Girl's Restroom/Kitchen	Ceiling	Chipping, Holes, Flaking, Spalling, Efflorescence	116	Yes	No	N/A	N/A	Yes	
761	5150	1	0			Hallway outside Girl's Restroom/Kitchen	Floor	Chipping	27	No	No	N/A	N/A	No	
762	5150	1	0			Hallway outside Girl's Restroom/Kitchen	W2	Chipping, Flaking, Efflorescence	24	Yes	No	N/A	N/A	No	
763	5150	1	0			Hallway outside Girl's Restroom/Kitchen	W3	Chipping on wall, doors, and doorframe, Flaking on wall and doorframe	65	No	No	N/A	N/A	No	
764	5150	1	0			Hallway outside Girl's Restroom/Kitchen	W4	Chipping on wall and metal pipe, Flaking, Efflorescence	78	Yes	No	N/A	N/A	No	
765	5150	1	0			Kitchen	Ceiling	Hole, Flaking	280	No	No	N/A	N/A	Yes	
766	5150	1	0			Kitchen	W1	Chipping on wall, metal ducts, and metal pipes, Hole, Flaking on wall, metal ducts, and metal pipes	23	No	No	N/A	N/A	Yes	
767	5150	1	0			Kitchen	W2	Chipping, Flaking	2	No	No	N/A	N/A	No	
768	5150	1	0			Kitchen	W3	Chipping, Flaking, Efflorescence	12	Yes	No	N/A	N/A	Yes	
769	5150	1	0			Kitchen	W4	Chipping	1	No	No	N/A	Refrigerators	No	
770	5150	1	0			Kitchen Closet	Ceiling	Flaking	2	No	No	N/A	N/A	No	
771	5150	1	0			Kitchen Closet	Floor	Chipping	10	No	No	N/A	N/A	No	
772	5150	1	0			Kitchen Closet	W1	Efflorescence	5	Yes	No	N/A	N/A	No	
773	5150	1	0			Kitchen Closet	W4	Flaking	7	No	No	N/A	N/A	No	
774	5150	1	0			Men's Restroom	Ceiling	Flaking	77	No	No	N/A	N/A	No	
775	5150	1	0			Men's Restroom	Floor	N/A	N/A	No	Paint Chips	20	N/A	No	
776	5150	1	0			Men's Restroom	W1	Flaking	408	No	No	N/A	N/A	No	
777	5150	1	0			Men's Restroom	W2	Flaking	408	No	No	N/A	N/A	No	
778	5150	1	0			Men's Restroom	W3	Flaking	408	No	No	N/A	N/A	No	
779	5150	1	0			Men's Restroom	W4	Flaking	408	No	No	N/A	N/A	No	
780	5150	1	0			Men's Restroom Closet	W2	Flaking	10	No	No	N/A	N/A	No	
781	5150	1	0			Men's Restroom Closet	W3	Flaking	10	No	No	N/A	N/A	No	
782	5150	1	0			Men's Restroom Closet	W4	Flaking	5	No	No	N/A	N/A	No	
783	5150	1	0			School Store	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
784	5150	1	0			School Store	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
785	5150	1	0			School Store	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
786	5150	1	0			School Store	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
787	5150	1	0			School Store	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Bodine -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
788	5150	1	0			School Store	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
789	5150	1	0			Stairwell on Boy's Side	Ceiling	Flaking	20	No	No	N/A	N/A	No	
790	5150	1	0			Stairwell on Boy's Side	Floor	Chipping on stairs and railings	11	No	No	N/A	N/A	No	
791	5150	1	0			Stairwell on Boy's Side	W1	Cracking, Chipping, Holes, Flaking, Spalling	40	Yes	No	N/A	N/A	Yes	
792	5150	1	0			Stairwell on Boy's Side	W2	Cracking, Chipping, Flaking	46	No	No	N/A	N/A	No	
793	5150	1	0			Stairwell on Boy's Side	W3	Cracking, Flaking, Efflorescence	6	Yes	No	N/A	N/A	Yes	
794	5150	1	0			Stairwell on Boy's Side	W4	Chipping, Flaking	32	No	No	N/A	N/A	No	
795	5150	1	0			Stairwell on Girl's Side	Ceiling	Flaking	8	No	No	N/A	N/A	No	
796	5150	1	0			Stairwell on Girl's Side	Floor	Chipping on stairs and railings	14	No	No	N/A	N/A	No	
797	5150	1	0			Stairwell on Girl's Side	W1	Chipping, Flaking	13	No	No	N/A	N/A	No	
798	5150	1	0			Stairwell on Girl's Side	W2	Chipping on wall, doors, and doorframe, Flaking	57	No	No	N/A	N/A	No	
799	5150	1	0			Stairwell on Girl's Side	W3	Flaking on wall and metal pipe	30	No	No	N/A	N/A	No	
800	5150	1	0			Stairwell on Girl's Side	W4	Chipping, Flaking	16	No	No	N/A	N/A	No	
801	5150	1	0			Storage Closet adjacent to Boy's Restroom	W1	Chipping, Flaking	6	No	No	N/A	N/A	No	
802	5150	1	0			Storage Closet adjacent to Boy's Restroom	W2	Chipping, Flaking, Efflorescence	36	Yes	No	N/A	N/A	No	
803	5150	1	0			Storage Closet adjacent to Boy's Restroom	W3	Flaking	2	No	No	N/A	N/A	No	
804	5150	1	0			Storage Closet adjacent to Boy's Restroom	W4	Chipping, Flaking	17	No	No	N/A	N/A	No	
805	5150	1	0			Storage Closet adjacent to Girl's Restroom	W1	Chipping	10	No	No	N/A	N/A	No	
806	5150	1	0			Storage Closet adjacent to Girl's Restroom	W2	Chipping	1	No	No	N/A	N/A	No	
807	5150	1	0			Storage Closet adjacent to Girl's Restroom	W3	Chipping	20	No	No	N/A	N/A	No	