

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	5010	1	3			Boy's Locker Room	Ceiling	cracking, chipping, holes, flaking, chipping, flaking, duct	122	No	No	N/A	N/A	Yes	
2	5010	1	3			Boy's Locker Room	Floor	Debris	N/A	No	Yes	10	N/A	No	
3	5010	1	3			Boy's Locker Room	W1	chipping, flaking	20	No	No	N/A	N/A	No	
4	5010	1	3			Boy's Locker Room	W2	chipping, flaking	5	No	No	N/A	N/A	No	
5	5010	1	3			Boy's Locker Room	W3	cracking, chipping, flaking, chipping, pipe	22	No	No	N/A	N/A	No	
6	5010	1	3			Boy's Locker Room	W4	chipping	3	No	No	N/A	N/A	No	
7	5010	1	3			Classroom 300	Ceiling	chipping, holes	10	No	No	N/A	N/A	Yes	
8	5010	1	3			Classroom 300	Floor	chipping baseboard	4	No	Yes	10	N/A	No	
9	5010	1	3			Classroom 300	W1	cracking, chipping, holes, flaking	10	No	No	N/A	N/A	Yes	
10	5010	1	3			Classroom 300	W2	chipping, flaking	4	No	No	N/A	N/A	No	
11	5010	1	3			Classroom 300	W3	chipping, flaking, chipping radiators	62	No	No	N/A	N/A	No	
12	5010	1	3			Classroom 300	W4	cracking, chipping, flaking	7	No	No	N/A	N/A	No	
13	5010	1	3			Classroom 301	Ceiling	cracking, flaking	3	No	No	N/A	N/A	No	
14	5010	1	3			Classroom 301	W1	chipping, chipping door and frame	13	No	No	N/A	N/A	No	
15	5010	1	3			Classroom 301	W2	chipping, chipping door and frame	5	No	No	N/A	N/A	No	
16	5010	1	3			Classroom 301	W3	cracking, chipping, gouges, flaking	24	No	No	N/A	N/A	Yes	
17	5010	1	3			Classroom 301	W4	cracking, chipping, flaking	9	No	No	N/A	N/A	No	
18	5010	1	3			Classroom 302	W1	cracking, chipping, gouges, flaking, chipping door and frame	19	No	No	N/A	N/A	Yes	
19	5010	1	3			Classroom 302	W2	chipping	2	No	No	N/A	N/A	No	
20	5010	1	3			Classroom 302	W3	cracking, chipping, holes, flaking	11	No	No	N/A	N/A	Yes	
21	5010	1	3			Classroom 302	W4	chipping, holes, chipping door and frame	7	No	No	N/A	N/A	Yes	
22	5010	1	3			Classroom 303	Ceiling	flaking	5	No	No	N/A	N/A	No	
23	5010	1	3			Classroom 303	W1	chipping, gouges, flaking, chipping door and frame	11	No	No	N/A	N/A	Yes	
24	5010	1	3			Classroom 303	W2	holes, flaking	3	No	No	N/A	N/A	Yes	
25	5010	1	3			Classroom 303	W3	cracking, flaking, gouges, chipping radiators	45	No	No	N/A	N/A	Yes	
26	5010	1	3			Classroom 303	W4	cracking, chipping, gouges, holes, flaking	14	No	No	N/A	N/A	Yes	
27	5010	1	3			Classroom 304	Ceiling	flaking	2	No	No	N/A	N/A	No	
28	5010	1	3			Classroom 304	Floor	Debris	N/A	No	Yes	2	N/A	No	
29	5010	1	3			Classroom 304	W1	chipping, flaking, chipping door and frame	16	No	No	N/A	N/A	No	
30	5010	1	3			Classroom 304	W2	chipping, flaking, holes, chipping metal pipe	5	No	No	N/A	N/A	Yes	
31	5010	1	3			Classroom 304	W3	cracking, chipping, efflorescence, chipping radiators	52	Yes	No	N/A	N/A	Yes	
32	5010	1	3			Classroom 304	W4	chipping	3	No	No	N/A	N/A	No	
33	5010	1	3			Classroom 305	Ceiling	chipping, flaking	4	No	No	N/A	N/A	No	
34	5010	1	3			Classroom 305	Floor	Debris	N/A	No	Yes	25	N/A	No	
35	5010	1	3			Classroom 305	W1	cracking, holes	4	No	No	N/A	N/A	Yes	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
36	5010	1	3			Classroom 305	W2	chipping	7	No	No	N/A	N/A	No	
37	5010	1	3			Classroom 305	W3	cracking, chipping, holes, flaking, chipping radiators	70	No	No	N/A	N/A	Yes	
38	5010	1	3			Classroom 305	W4	cracking, chipping, holes, flaking, spalling efflorescence, significant moisture damage	22	Yes	No	N/A	N/A	Yes	
39	5010	1	3			Classroom 307	Floor	Debris	N/A	No	Yes	2	N/A	No	
40	5010	1	3			Classroom 307	W1	cracking, chipping, flaking	21	No	No	N/A	N/A	No	
41	5010	1	3			Classroom 307	W2	chipping, flaking	10	No	No	N/A	N/A	No	
42	5010	1	3			Classroom 307	W3	cracking, chipping, gouges, holes, flaking, spalling, efflorescence	30	Yes	No	N/A	N/A	Yes	
43	5010	1	3			Classroom 307	W4	cracking, flaking	11	No	No	N/A	N/A	No	
44	5010	1	3			Classroom 308	Ceiling	flaking	2	No	No	N/A	N/A	No	
45	5010	1	3			Classroom 308	W1	cracking, chipping, holes, flaking	20	No	No	N/A	N/A	Yes	
46	5010	1	3			Classroom 308	W2	cracking, chipping, holes, flaking	13	No	No	N/A	N/A	Yes	
47	5010	1	3			Classroom 308	W3	cracking, chipping, holes, flaking	10	No	No	N/A	N/A	Yes	
48	5010	1	3			Classroom 308	W4	holes, flaking	8	No	No	N/A	N/A	Yes	
49	5010	1	3			Classroom 309	Floor	Debris	N/A	No	Yes	2	N/A	No	
50	5010	1	3			Classroom 309	W1	chipping, holes, flaking	12	No	No	N/A	N/A	Yes	
51	5010	1	3			Classroom 309	W2	cracking, chipping, flaking	23	No	No	N/A	N/A	No	
52	5010	1	3			Classroom 309	W3	chipping	6	No	No	N/A	N/A	No	
53	5010	1	3			Classroom 309	W4	chipping	5	No	No	N/A	N/A	No	
54	5010	1	3			Classroom 310	W1	cracking, chipping, holes	4	No	No	N/A	Stored materials	Yes	
55	5010	1	3			Classroom 310	W2	cracking, chipping	6	No	No	N/A	Shelves	No	
56	5010	1	3			Classroom 310	W3	cracking, chipping, flaking, holes, chipping radiators	47	No	No	N/A	N/A	Yes	
57	5010	1	3			Classroom 310	W4	chipping, flaking	10	No	No	N/A	N/A	No	
58	5010	1	3			Classroom 311	Floor	chipping baseboard	50	No	No	N/A	N/A	No	
59	5010	1	3			Classroom 311	W1	cracking, chipping, holes, flaking	15	No	No	N/A	N/A	Yes	
60	5010	1	3			Classroom 311	W2	cracking, chipping, holes, flaking	8	No	No	N/A	N/A	Yes	
61	5010	1	3			Classroom 311	W3	cracking, chipping, flaking, chipping radiators	75	No	No	N/A	N/A	No	
62	5010	1	3			Classroom 311	W4	cracking	4	No	No	N/A	N/A	No	
63	5010	1	3			Classroom 314	W1	cracking, chipping, gouges, holes, flaking	20	No	No	N/A	N/A	Yes	
64	5010	1	3			Classroom 314	W2	cracking, chipping, gouges, holes, flaking	22	No	No	N/A	N/A	Yes	
65	5010	1	3			Classroom 314	W3	cracking, chipping, gouges, efflorescence, chipping radiators	72	Yes	No	N/A	N/A	Yes	
66	5010	1	3			Classroom 314	W4	chipping	3	No	No	N/A	N/A	No	
67	5010	1	3			Classroom 315	W1	chipping, gouges, holes	8	No	No	N/A	N/A	Yes	
68	5010	1	3			Classroom 315	W2	chipping, flaking	6	No	No	N/A	N/A	No	
69	5010	1	3			Classroom 315	W3	gouges, holes, efflorescence, chipping radiators	56	Yes	No	N/A	N/A	Yes	
70	5010	1	3			Classroom 315	W4	chipping, flaking, spalling	22	No	No	N/A	N/A	Yes	
71	5010	1	3			Classroom 316	W1	chipping, flaking, chipping door and frame	9	No	No	N/A	N/A	No	
72	5010	1	3			Classroom 316	W2	flaking	5	No	No	N/A	N/A	No	
73	5010	1	3			Classroom 316	W3	chipping, holes, flaking, chipping radiators	12	No	No	N/A	N/A	Yes	
74	5010	1	3			Classroom 318	Ceiling	cracking, chipping, flaking	4	No	No	N/A	N/A	No	
75	5010	1	3			Classroom 318	Floor	Debris	N/A	No	Yes	12	N/A	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
76	5010	1	3			Classroom 318	W1	cracking, chipping, gouges, chipping door and frame	10	No	No	N/A	N/A	Yes	
77	5010	1	3			Classroom 318	W2	cracking, chipping, holes, flaking	22	No	No	N/A	N/A	Yes	
78	5010	1	3			Classroom 318	W3	cracking, chipping, flaking, efflorescence,	58	Yes	No	N/A	N/A	Yes	
79	5010	1	3			Classroom 318	W4	cracking, chipping, holes, flaking	7	No	No	N/A	N/A	Yes	
80	5010	1	3			Counselor's Office 323	Ceiling	chipping, flaking	4	No	No	N/A	N/A	No	
81	5010	1	3			Counselor's Office 323	Floor	chipping baseboard	22	No	No	N/A	N/A	No	
82	5010	1	3			Counselor's Office 323	W1	cracking, chipping, holes	13	No	No	N/A	N/A	Yes	
83	5010	1	3			Counselor's Office 323	W2	chipping	4	No	No	N/A	N/A	No	
84	5010	1	3			Counselor's Office 323	W3	chipping, spalling	12	No	No	N/A	N/A	Yes	
85	5010	1	3			Counselor's Office 323	W4	cracking, chipping, flaking, chipping radiators	26	No	No	N/A	N/A	No	
86	5010	1	3			East Fire Tower	Ceiling	chipping, flaking	126	No	No	N/A	N/A	No	
87	5010	1	3			East Fire Tower	Floor	Debris	N/A	No	Yes	45	N/A	No	
88	5010	1	3			East Fire Tower	W1	chipping, flaking	20	No	No	N/A	N/A	No	
89	5010	1	3			East Fire Tower	W2	chipping, flaking	12	No	No	N/A	N/A	No	
90	5010	1	3			East Fire Tower	W3	chipping, flaking, iron bars	100	No	No	N/A	N/A	No	
91	5010	1	3			East Fire Tower	W4	chipping door and frame	2	No	No	N/A	N/A	No	
92	5010	1	3			East Stairwell	Ceiling	cracking, chipping, holes, flaking, efflorescence	52	Yes	No	N/A	N/A	Yes	
93	5010	1	3			East Stairwell	Floor	Debris	N/A	No	Yes	20	N/A	No	
94	5010	1	3			East Stairwell	W1	cracking, chipping, flaking, chipping radiators	160	No	No	N/A	N/A	No	
95	5010	1	3			East Stairwell	W2	cracking, chipping, flaking, holes, chipping door and frame	10	No	No	N/A	N/A	Yes	
96	5010	1	3			East Stairwell	W3	cracking, chipping, flaking	110	No	No	N/A	N/A	No	
97	5010	1	3			East Stairwell	W4	cracking, flaking, gouges, efflorescence	60	Yes	No	N/A	N/A	Yes	
98	5010	1	3			Foyer to Men's Restroom across from Classroom 304	Ceiling	chipping, efflorescence	10	Yes	No	N/A	N/A	Yes	
99	5010	1	3			Foyer to Men's Restroom across from Classroom 304	W1	chipping, chipping door and frame	8	No	No	N/A	N/A	No	
100	5010	1	3			Foyer to Men's Restroom across from Classroom 304	W2	cracking, chipping	16	No	No	N/A	N/A	No	
101	5010	1	3			Foyer to Men's Restroom across from Classroom 304	W3	chipping door and frame	6	No	No	N/A	N/A	No	
102	5010	1	3			Foyer to Men's Restroom across from Classroom 304	W4	chipping	6	No	No	N/A	Stored materials, shelves	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
103	5010	1	3			Girl's Locker Room Upper Level	Ceiling	chipping, flaking	12	No	No	N/A	N/A	No	
104	5010	1	3			Girl's Locker Room Upper Level	W1	chipping, flaking	12	No	No	N/A	Stored materials, lockers	No	
105	5010	1	3			Girl's Locker Room Upper Level	W2	cracking, chipping, flaking	10	No	No	N/A	N/A	No	
106	5010	1	3			Girl's Locker Room Upper Level	W3	cracking, chipping, flaking	14	No	No	N/A	N/A	No	
107	5010	1	3			Girl's Locker Room Upper Level	W4	chipping, flaking	2	No	No	N/A	N/A	No	
108	5010	1	3			Girl's Restroom across from Office 312	Ceiling	cracking, flaking	10	No	No	N/A	N/A	No	
109	5010	1	3			Gym	Ceiling	cracking, chipping, holes, flaking, efflorescence, significant moisture damage	150	Yes	No	N/A	N/A	Yes	
110	5010	1	3			Gym	Floor	Debris	N/A	No	Yes	50	N/A	No	
111	5010	1	3			Gym	W1	cracking, chipping, holes, flaking, efflorescence, significant moisture damage	350	Yes	No	N/A	N/A	Yes	
112	5010	1	3			Gym	W2	cracking, chipping, holes, flaking, efflorescence, significant moisture damage, chipping metal pipe	210	Yes	No	N/A	N/A	Yes	
113	5010	1	3			Gym	W3	cracking, chipping, holes, flaking, efflorescence, significant moisture damage, chipping metal pipe	250	Yes	No	N/A	N/A	Yes	
114	5010	1	3			Gym	W4	cracking, chipping, holes, flaking, efflorescence, significant moisture damage	205	Yes	No	N/A	N/A	Yes	
115	5010	1	3			Hallway at Gymnasium	Ceiling	holes, efflorescence, significant moisture damage	10	Yes	No	N/A	N/A	Yes	
116	5010	1	3			Hallway at Gymnasium	Floor	Debris	N/A	No	Yes	2	N/A	No	
117	5010	1	3			Hallway at Gymnasium	W1	cracking, chipping, holes, flaking	14	No	No	N/A	N/A	Yes	
118	5010	1	3			Hallway at Gymnasium	W2	cracking, chipping	3	No	No	N/A	N/A	No	
119	5010	1	3			Hallway at Gymnasium	W3	cracking, chipping, gouges	7	No	No	N/A	N/A	Yes	
120	5010	1	3			Hallway at Gymnasium	W4	chipping	2	No	No	N/A	N/A	No	
121	5010	1	3			Hallway from Classroom 300 to Office 312	W2	cracking, chipping, gouges, holes, flaking	62	No	No	N/A	N/A	Yes	
122	5010	1	3			Hallway from Classroom 300 to Office 312	W4	cracking, chipping, holes, flaking, chipping radiators, chipping metal pipe	42	No	No	N/A	N/A	Yes	
123	5010	1	3			Hallway from Classrooms 307 to 311	W1	cracking, chipping, gouges, flaking, chipping metal pipe, chipping door and frame	12	No	No	N/A	N/A	Yes	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
124	5010	1	3			Hallway from Classrooms 307 to 311	W2	cracking, chipping, holes	5	No	No	N/A	N/A	Yes	
125	5010	1	3			Hallway from Classrooms 307 to 311	W3	flaking, chipping door and frame	9	No	No	N/A	N/A	No	
126	5010	1	3			Hallway from Classrooms 307 to 311	W4	chipping door and frame	8	No	No	N/A	N/A	No	
127	5010	1	3			Lab Prep Room between Classrooms 302 and 301	Ceiling	holes, significant moisture damage	28	Yes	No	N/A	N/A	Yes	
128	5010	1	3			Lab Prep Room between Classrooms 302 and 301	Floor	Debris	N/A	No	Yes	10	N/A	No	
129	5010	1	3			Lab Prep Room between Classrooms 302 and 301	W1	chipping, chipping door and frame	5	No	No	N/A	N/A	No	
130	5010	1	3			Lab Prep Room between Classrooms 302 and 301	W2	cracking, chipping, flaking, efflorescence, significant moisture damage	21	Yes	No	N/A	N/A	Yes	
131	5010	1	3			Lab Prep Room between Classrooms 302 and 301	W3	chipping, flaking, efflorescence, chipping pipe	15	Yes	No	N/A	N/A	Yes	
132	5010	1	3			Lab Prep Room between Classrooms 302 and 301	W4	cracking, chipping, holes, flaking	12	No	No	N/A	N/A	Yes	
133	5010	1	3			Men's Restroom across Room 304	Ceiling	flaking, efflorescence	2	Yes	No	N/A	N/A	Yes	
134	5010	1	3			Men's Restroom across Room 304	W1	chipping door and frame	2	No	No	N/A	N/A	No	
135	5010	1	3			Office 306 in West Stairwell	Floor	Debris	N/A	No	Yes	15	N/A	No	
136	5010	1	3			Office 306 in West Stairwell	W1	cracking, holes, flaking, chipping radiators	10	No	No	N/A	N/A	Yes	
137	5010	1	3			Office 306 in West Stairwell	W2	cracking, holes	4	No	No	N/A	N/A	Yes	
138	5010	1	3			Office 306 in West Stairwell	W3	cracking, chipping, holes, flaking	12	No	No	N/A	N/A	Yes	
139	5010	1	3			Office 306 in West Stairwell	W4	cracking, chipping, flaking	12	No	No	N/A	N/A	No	
140	5010	1	3			Office 312	Ceiling	cracking, chipping, flaking, significant moisture damage	25	Yes	No	N/A	N/A	Yes	
141	5010	1	3			Office 312	Floor	Debris	N/A	No	Yes	10	N/A	No	
142	5010	1	3			Office 312	W1	chipping	3	No	No	N/A	N/A	No	
143	5010	1	3			Office 312	W2	cracking, chipping, holes, flaking	5	No	No	N/A	N/A	Yes	
144	5010	1	3			Office 312	W3	cracking, chipping, holes, flaking, chipping radiators	26	No	No	N/A	N/A	Yes	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
145	5010	1	3			Office 312	W4	cracking, chipping, flaking	11	No	No	N/A	N/A	No	
146	5010	1	3			Office 319	W1	chipping, holes, chipping door and frame	8	No	No	N/A	N/A	Yes	
147	5010	1	3			Office 319	W2	cracking, chipping, holes, flaking,	14	No	No	N/A	N/A	Yes	
148	5010	1	3			Office 319	W3	cracking, chipping, holes, flaking, chipping radiators	24	No	No	N/A	N/A	Yes	
149	5010	1	3			Office 319	W4	cracking, chipping, holes, flaking	12	No	No	N/A	N/A	Yes	
150	5010	1	3			Stairwell 1 adjacent to Office 312	W1	flaking	3	No	No	N/A	N/A	No	
151	5010	1	3			Stairwell 1 adjacent to Office 312	W3	flaking	2	No	No	N/A	N/A	No	
152	5010	1	3			Stairwell 1 adjacent to Office 312	W4	chipping door and frame	10	No	No	N/A	N/A	No	
153	5010	1	3			Stairwell 2 adjacent to Teacher's Lounge 320	Floor	Debris	N/A	No	Yes	3	N/A	No	
154	5010	1	3			Stairwell 2 adjacent to Teacher's Lounge 320	W1	chipping	2	No	No	N/A	N/A	No	
155	5010	1	3			Stairwell 2 adjacent to Teacher's Lounge 320	W4	chipping, flaking	16	No	No	N/A	N/A	No	
156	5010	1	3			Teacher's Lounge 320	W1	gouges, holes	2	No	No	N/A	N/A	Yes	
157	5010	1	3			Teacher's Lounge 320	W2	cracking, chipping, flaking	24	No	No	N/A	N/A	No	
158	5010	1	3			Teacher's Lounge 320	W3	cracking, chipping, holes, flaking	23	No	No	N/A	N/A	Yes	
159	5010	1	3			Teacher's Lounge 320	W4	cracking, chipping, holes, flaking	8	No	No	N/A	N/A	Yes	
160	5010	1	3			Teacher's Lounge 320 Back Room	Ceiling	cracking, chipping	4	No	No	N/A	N/A	No	
161	5010	1	3			Teacher's Lounge 320 Back Room	W1	cracking, chipping, holes, flaking	6	No	No	N/A	N/A	Yes	
162	5010	1	3			Teacher's Lounge 320 Back Room	W2	cracking, chipping, holes, flaking	17	No	No	N/A	N/A	Yes	
163	5010	1	3			Teacher's Lounge 320 Back Room	W3	cracking, chipping, flaking	6	No	No	N/A	Cabinets	No	
164	5010	1	3			Teacher's Lounge 320 Back Room	W4	cracking, chipping	7	No	No	N/A	N/A	No	
165	5010	1	3			Teacher's Lounge 320 Restroom	W1	chipping door and frame	10	No	No	N/A	N/A	No	
166	5010	1	3			West Fire Tower	Ceiling	cracking, chipping, flaking, efflorescence,	21	Yes	No	N/A	N/A	Yes	
167	5010	1	3			West Fire Tower	Floor	Debris	N/A	No	Yes	23	N/A	No	
168	5010	1	3			West Fire Tower	W1	flaking	175	No	No	N/A	N/A	No	
169	5010	1	3			West Fire Tower	W2	flaking, chipping door and frame	28	No	No	N/A	N/A	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
170	5010	1	3			West Fire Tower	W3	flaking	175	No	No	N/A	N/A	No	
171	5010	1	3			West Fire Tower	W4	flaking	18	No	No	N/A	N/A	No	
172	5010	1	3			West Stairwell	Ceiling	efflorescence, significant moisture damage	180	Yes	No	N/A	N/A	Yes	
173	5010	1	3			West Stairwell	Floor	Debris	N/A	No	Yes	30	N/A	No	
174	5010	1	3			West Stairwell	W1	flaking, efflorescence,	6	Yes	No	N/A	N/A	Yes	
175	5010	1	3			West Stairwell	W2	cracking, chipping, flaking, efflorescence, significant moisture damage, chipping metal pipe	24	Yes	No	N/A	N/A	Yes	
176	5010	1	3			West Stairwell	W3	cracking, chipping, flaking	10	No	No	N/A	N/A	No	
177	5010	1	2			Boy's Restroom across Elevator	Ceiling	chipping, holes, flaking	7	No	No	N/A	N/A	Yes	
178	5010	1	2			Boy's Restroom adjacent to Classroom 204	Ceiling	cracking, chipping, flaking	3	No	No	N/A	N/A	No	
179	5010	1	2			Boy's Restroom adjacent to Classroom 204	W1	chipping door and frame	10	No	No	N/A	N/A	No	actually female staff restroom
180	5010	1	2			Boy's Restroom adjacent to Classroom 204	W3	chipping radiators	8	No	No	N/A	N/A	No	
181	5010	1	2			Classroom 200	Ceiling	flaking	13	No	No	N/A	N/A	No	
182	5010	1	2			Classroom 200	Floor	chipping baseboard	13	No	No	N/A	N/A	No	
183	5010	1	2			Classroom 200	W1	cracking, chipping, holes, flaking	10	No	No	N/A	N/A	Yes	
184	5010	1	2			Classroom 200	W2	cracking, chipping, holes, flaking	12	No	No	N/A	N/A	Yes	
185	5010	1	2			Classroom 200	W3	cracking, chipping, chipping radiators	52	No	No	N/A	N/A	No	
186	5010	1	2			Classroom 200	W4	chipping, holes	3	No	No	N/A	N/A	Yes	
187	5010	1	2			Classroom 201	Ceiling	cracking, chipping, holes, flaking	10	No	No	N/A	N/A	Yes	
188	5010	1	2			Classroom 201	W1	cracking, chipping, gouges, holes, flaking	14	No	No	N/A	N/A	Yes	
189	5010	1	2			Classroom 201	W2	chipping	3	No	No	N/A	N/A	No	
190	5010	1	2			Classroom 201	W3	cracking, chipping, flaking	12	No	No	N/A	N/A	No	
191	5010	1	2			Classroom 201	W4	chipping	4	No	No	N/A	N/A	No	
192	5010	1	2			Classroom 202	Ceiling	chipping, holes, flaking	8	No	No	N/A	N/A	Yes	
193	5010	1	2			Classroom 202	W1	chipping, holes, flaking	12	No	No	N/A	N/A	Yes	
194	5010	1	2			Classroom 202	W2	N/A	N/A	No	No	N/A	Cabinets	No	Limited inspection due to stored materials
195	5010	1	2			Classroom 202	W3	cracking, chipping, holes, flaking, efflorescence,	22	Yes	No	N/A	N/A	Yes	
196	5010	1	2			Classroom 202	W4	cracking, chipping, holes, flaking	5	No	No	N/A	N/A	Yes	
197	5010	1	2			Classroom 203	Ceiling	chipping	5	No	No	N/A	N/A	No	
198	5010	1	2			Classroom 203	W1	cracking, chipping, gouges, holes, flaking	22	No	No	N/A	N/A	Yes	
199	5010	1	2			Classroom 203	W2	cracking, chipping, holes, flaking	14	No	No	N/A	N/A	Yes	
200	5010	1	2			Classroom 203	W3	cracking, chipping, chipping radiators	56	No	No	N/A	N/A	No	
201	5010	1	2			Classroom 203	W4	cracking, chipping, gouges, holes, flaking	22	No	No	N/A	N/A	Yes	
202	5010	1	2			Classroom 204	W1	cracking, chipping, holes, flaking	20	No	No	N/A	N/A	Yes	
203	5010	1	2			Classroom 204	W3	cracking, chipping, flaking, chipping radiators	48	No	No	N/A	N/A	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
204	5010	1	2			Classroom 204	W4	cracking, chipping, holes, staple holes, flaking	42	No	No	N/A	N/A	Yes	
205	5010	1	2			Classroom 205	Floor	chipping, baseboard	30	No	No	N/A	N/A	No	
206	5010	1	2			Classroom 205	W1	cracking, chipping, holes, flaking	13	No	No	N/A	N/A	Yes	
207	5010	1	2			Classroom 205	W2	chipping, flaking	15	No	No	N/A	N/A	No	
208	5010	1	2			Classroom 205	W3	chipping, chipping radiators	70	No	No	N/A	N/A	No	
209	5010	1	2			Classroom 205	W4	chipping	6	No	No	N/A	N/A	No	
210	5010	1	2			Classroom 207	Floor	chipping baseboard		No	No	N/A	N/A	No	
211	5010	1	2			Classroom 207	W1	chipping, flaking	10	No	No	N/A	N/A	No	
212	5010	1	2			Classroom 207	W2	chipping, flaking	14	No	No	N/A	N/A	No	
213	5010	1	2			Classroom 207	W3	cracking, chipping, holes, flaking, chipping radiators	84	No	No	N/A	N/A	Yes	
214	5010	1	2			Classroom 207	W4	cracking, chipping, flaking	18	No	No	N/A	N/A	No	
215	5010	1	2			Classroom 208	Ceiling	N/A	N/A	No	No	N/A	Computer desks	No	Limited inspection due to stored materials
216	5010	1	2			Classroom 208	W1	cracking, chipping, flaking	8	No	No	N/A	N/A	No	
217	5010	1	2			Classroom 208	W2	cracking, chipping, flaking	10	No	No	N/A	N/A	No	
218	5010	1	2			Classroom 208	W3	chipping, flaking	20	No	No	N/A	N/A	No	
219	5010	1	2			Classroom 208	W4	N/A	N/A	No	No	N/A	Cabinets	No	Limited inspection due to stored materials
220	5010	1	2			Classroom 209	Ceiling	chipping, flaking	5	No	No	N/A	N/A	No	
221	5010	1	2			Classroom 209	W1	chipping, holes, flaking	5	No	No	N/A	N/A	Yes	
222	5010	1	2			Classroom 209	W2	flaking	10	No	No	N/A	N/A	No	
223	5010	1	2			Classroom 209	W3	chipping, flaking, chipping radiators	35	No	No	N/A	N/A	No	
224	5010	1	2			Classroom 209	W4	chipping, flaking	12	No	No	N/A	N/A	No	
225	5010	1	2			Classroom 211	Ceiling	chipping baseboard	10	No	No	N/A	N/A	No	
226	5010	1	2			Classroom 211	W1	cracking, chipping, holes, flaking	22	No	No	N/A	N/A	Yes	
227	5010	1	2			Classroom 211	W2	cracking, chipping, holes, flaking	13	No	No	N/A	N/A	Yes	
228	5010	1	2			Classroom 211	W3	chipping, gouges flaking, chipping radiators	56	No	No	N/A	Desks	Yes	
229	5010	1	2			Classroom 211	W4	cracking, chipping, flaking	14	No	No	N/A	N/A	No	
230	5010	1	2			Classroom 214	Floor	chipping baseboard	4	No	No	N/A	N/A	No	
231	5010	1	2			Classroom 214	W1	cracking, chipping, holes, flaking	10	No	No	N/A	N/A	Yes	
232	5010	1	2			Classroom 214	W2	chipping, flaking	8	No	No	N/A	Posters	No	
233	5010	1	2			Classroom 214	W3	cracking, chipping, holes, flaking, chipping radiators	56	No	No	N/A	N/A	Yes	
234	5010	1	2			Classroom 214	W4	cracking, chipping, holes	8	No	No	N/A	N/A	Yes	
235	5010	1	2			Classroom 215	Floor	chipping baseboard	14	No	No	N/A	N/A	No	
236	5010	1	2			Classroom 215	W1	cracking, chipping, gouges, holes, flaking	20	No	No	N/A	N/A	Yes	
237	5010	1	2			Classroom 215	W2	cracking, chipping, flaking	3	No	No	N/A	N/A	No	
238	5010	1	2			Classroom 215	W3	cracking, chipping, holes, flaking, chipping radiators	58	No	No	N/A	N/A	Yes	
239	5010	1	2			Classroom 215	W4	cracking, chipping, gouges, holes, flaking,	60	No	No	N/A	N/A	Yes	
240	5010	1	2			Classroom 216	Ceiling	cracking	3	No	No	N/A	N/A	No	
241	5010	1	2			Classroom 216	Floor	chipping baseboard	10	No	No	N/A	N/A	No	
242	5010	1	2			Classroom 216	W1	cracking, chipping, flaking, chipping door and frame	25	No	No	N/A	N/A	No	
243	5010	1	2			Classroom 216	W3	cracking, chipping, holes, flaking, chipping radiators	20	No	No	N/A	N/A	Yes	
244	5010	1	2			Classroom 216	W4	cracking, flaking	3	No	No	N/A	N/A	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
245	5010	1	2			Classroom 221	Ceiling	cracking, chipping, flaking, significant moisture damage	10	Yes	No	N/A	N/A	Yes	
246	5010	1	2			Classroom 221	Floor	Debris	N/A	No	Yes	10	N/A	No	
247	5010	1	2			Classroom 221	W1	chipping, flaking	2	No	No	N/A	Cabinets	No	
248	5010	1	2			Classroom 221	W2	cracking, chipping, holes, chipping radiators, chipping metal pipe	28	No	No	N/A	N/A	Yes	
249	5010	1	2			Classroom 221	W3	chipping radiators	2	No	No	N/A	N/A	No	
250	5010	1	2			Classroom 221	W4	cracking, chipping, flaking, holes	13	No	No	N/A	N/A	Yes	
251	5010	1	2			Computer Classroom 218	Floor	chipping baseboard	10	No	No	N/A	N/A	No	
252	5010	1	2			Computer Classroom 218	W1	cracking, chipping, flaking	13	No	No	N/A	N/A	No	
253	5010	1	2			Computer Classroom 218	W2	cracking, chipping, holes, staple holes, flaking	22	No	No	N/A	N/A	Yes	
254	5010	1	2			Computer Classroom 218	W3	cracking, chipping, holes, flaking, chipping radiators	32	No	No	N/A	N/A	Yes	
255	5010	1	2			Computer Classroom 218	W4	cracking, chipping, holes, flaking	10	No	No	N/A	N/A	Yes	
256	5010	1	2			Dean's Office 212	W1	cracking, flaking	6	No	No	N/A	N/A	No	
257	5010	1	2			Dean's Office 212	W2	cracking, chipping, gouges, flaking	10	No	No	N/A	N/A	Yes	
258	5010	1	2			Dean's Office 212	W3	cracking, chipping, flaking, chipping radiators	5	No	No	N/A	N/A	No	
259	5010	1	2			Dean's Office 212	W4	cracking, chipping, flaking, holes	13	No	No	N/A	N/A	Yes	
260	5010	1	2			Dean's Office 223	Floor	Debris	N/A	No	Yes	10	N/A	No	
261	5010	1	2			Dean's Office 223	W1	cracking, chipping, holes, flaking, chipping door and frame	24	No	No	N/A	N/A	Yes	
262	5010	1	2			Dean's Office 223	W2	cracking, chipping, holes, flaking	7	No	No	N/A	N/A	Yes	
263	5010	1	2			Dean's Office 223	W3	chipping, chipping built in cabinets	12	No	No	N/A	N/A	No	
264	5010	1	2			Dean's Office 223	W4	chipping, flaking, chipping radiators	10	No	No	N/A	N/A	No	
265	5010	1	2			East Fire Tower	Ceiling	chipping, flaking	150	No	No	N/A	N/A	No	
266	5010	1	2			East Fire Tower	Floor	Debris	N/A	No	Yes	10	N/A	No	
267	5010	1	2			East Fire Tower	W2	chipping door and frame	8	No	No	N/A	N/A	No	
268	5010	1	2			East Fire Tower	W3	chipping flaking iron bars	110	No	No	N/A	N/A	No	
269	5010	1	2			East Fire Tower	W4	chipping door and frame	6	No	No	N/A	N/A	No	
270	5010	1	2			East Stairwell adjacent to Classroom 221	Ceiling	cracking, chipping, flaking, efflorescence	22	Yes	No	N/A	N/A	Yes	
271	5010	1	2			East Stairwell adjacent to Classroom 221	Floor	Debris	N/A	No	Yes	20	N/A	No	
272	5010	1	2			East Stairwell adjacent to Classroom 221	W1	cracking, chipping, holes, flaking, significant moisture damage, chipping radiators, chipping metal pipe	30	Yes	No	N/A	N/A	Yes	
273	5010	1	2			East Stairwell adjacent to Classroom 221	W2	cracking, chipping, holes, chipping door and frame	7	No	No	N/A	N/A	Yes	
274	5010	1	2			East Stairwell adjacent to Classroom 221	W3	cracking, chipping, flaking, efflorescence	20	Yes	No	N/A	N/A	Yes	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
275	5010	1	2			East Stairwell adjacent to Classroom 221	W4	cracking, chipping, flaking, efflorescence	34	Yes	No	N/A	N/A	Yes	
276	5010	1	2			Foyer leading to Girl's Restroom near Elevator	Ceiling	holes	2	No	No	N/A	N/A	Yes	
277	5010	1	2			Foyer leading to Girl's Restroom near Elevator	W1	cracking, chipping	3	No	No	N/A	N/A	No	
278	5010	1	2			Foyer leading to Girl's Restroom near Elevator	W3	chipping door and frame	4	No	No	N/A	N/A	No	
279	5010	1	2			Foyer leading to the Boy's Restroom across the Elevator	Ceiling	chipping, flaking	4	No	No	N/A	N/A	No	
280	5010	1	2			Foyer leading to the Boy's Restroom across the Elevator	W1	chipping	4	No	No	N/A	N/A	No	
281	5010	1	2			Foyer leading to the Boy's Restroom across the Elevator	W3	cracking, chipping door and frame	4	No	No	N/A	N/A	No	
282	5010	1	2			Foyer leading to the Boy's Restroom across the Elevator	W4	flaking	3	No	No	N/A	N/A	No	
283	5010	1	2			Foyer to the Men's Staff Restroom across from Classroom 204	Ceiling	cracking, flaking, holes	12	No	No	N/A	N/A	Yes	
284	5010	1	2			Foyer to the Men's Staff Restroom across from Classroom 204	Floor	chipping	15	No	No	N/A	N/A	No	
285	5010	1	2			Foyer to the Men's Staff Restroom across from Classroom 204	W1	cracking, chipping	6	No	No	N/A	N/A	No	
286	5010	1	2			Foyer to the Men's Staff Restroom across from Classroom 204	W2	cracking	16	No	No	N/A	Cabinets	No	
287	5010	1	2			Foyer to the Men's Staff Restroom across from Classroom 204	W3	cracking	4	No	No	N/A	N/A	No	
288	5010	1	2			Foyer to the Men's Staff Restroom across from Classroom 204	W4	chipping	2	No	No	N/A	Cabinets	No	
289	5010	1	2			Girl's Locker Room Lower Level	Ceiling	flaking	22	No	No	N/A	N/A	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
290	5010	1	2			Girl's Locker Room Lower Level	Floor	chipping stairs	3	No	Yes	42	N/A	No	
291	5010	1	2			Girl's Locker Room Lower Level	W2	chipping, metal pipe	3	No	No	N/A	N/A	No	
292	5010	1	2			Girl's Restroom near Elevator	Ceiling	flaking	2	No	No	N/A	N/A	No	
293	5010	1	2			Girl's Restroom near Elevator	W2	chipping, flaking	4	No	No	N/A	N/A	No	
294	5010	1	2			Hallway from Classroom 200 to Dean's Office 212	Floor	chipping	4	No	No	N/A	N/A	No	
295	5010	1	2			Hallway from Classroom 200 to Dean's Office 212	W2	cracking, chipping, holes, flaking, spalling	32	Yes	No	N/A	N/A	Yes	
296	5010	1	2			Hallway from Classroom 200 to Dean's Office 212	W4	cracking, chipping, staple holes, flaking, chipping radiators, chipping elevator door, chipping metal pipe	17	No	No	N/A	N/A	Yes	
297	5010	1	2			Hallway from Classroom 221 to Girl's Restroom	W1	cracking, spalling	60	Yes	No	N/A	N/A	Yes	
298	5010	1	2			Hallway from Classroom 221 to Girl's Restroom	W2	cracking	10	No	No	N/A	N/A	No	
299	5010	1	2			Hallway from Classroom 221 to Girl's Restroom	W3	cracking	8	No	No	N/A	N/A	No	
300	5010	1	2			Hallway from Classrooms 207 to 211	Floor	chipping baseboard	10	No	No	N/A	N/A	No	
301	5010	1	2			Hallway from Classrooms 207 to 211	W1	cracking, chipping, chipping radiators, chipping metal pipe	16	No	No	N/A	N/A	No	
302	5010	1	2			Hallway from Classrooms 207 to 211	W3	chipping, flaking	18	No	No	N/A	N/A	No	
303	5010	1	2			Hallway from Classrooms 207 to 211	W4	cracking, chipping, holes, flaking	5	No	No	N/A	N/A	Yes	
304	5010	1	2			Men's Staff Restroom across from Classroom 204	Ceiling	cracking, chipping, flaking, holes, spalling	14	No	No	N/A	N/A	Yes	
305	5010	1	2			Men's Staff Restroom across from Classroom 204	W4	chipping metal pipe	10	No	No	N/A	N/A	No	
306	5010	1	2			Nurse's Office	W1	chipping door and frame	5	No	No	N/A	N/A	No	
307	5010	1	2			Nurse's Office	W2	chipping door and frame	2	No	No	N/A	N/A	No	
308	5010	1	2			Office 206 in West Stairwell	W1	chipping, holes	6	No	No	N/A	N/A	Yes	
309	5010	1	2			Office 206 in West Stairwell	W2	chipping, flaking	6	No	No	N/A	N/A	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
310	5010	1	2			Office 206 in West Stairwell	W3	holes	4	No	No	N/A	N/A	Yes	
311	5010	1	2			Office 206 in West Stairwell	W4	holes, spalling	4	No	No	N/A	N/A	Yes	
312	5010	1	2			Office 210	Ceiling	chipping, flaking	8	No	No	N/A	N/A	No	
313	5010	1	2			Office 210	W1	chipping, holes	4	No	No	N/A	N/A	Yes	
314	5010	1	2			Office 210	W2	holes, flaking, gouges	7	No	No	N/A	N/A	Yes	
315	5010	1	2			Office 210	W3	flaking, chipping radiators	21	No	No	N/A	N/A	No	
316	5010	1	2			Office 210	W4	chipping, holes	4	No	No	N/A	N/A	Yes	
317	5010	1	2			Service Closet outside Classroom 207	Ceiling	holes	2	No	No	N/A	N/A	Yes	
318	5010	1	2			Stairs across the Elevator	Ceiling	spalling	3	No	No	N/A	N/A	Yes	
319	5010	1	2			Stairs across the Elevator	Floor	chipping, stair face and rail	30	No	No	N/A	N/A	No	
320	5010	1	2			Stairs across the Elevator	W1	cracking, chipping, flaking, chipping radiators, chipping metal pipe	15	No	No	N/A	N/A	No	
321	5010	1	2			Stairs across the Elevator	W2	chipping	2	No	No	N/A	N/A	No	
322	5010	1	2			Stairs across the Elevator	W3	chipping, chipping radiators	10	No	No	N/A	N/A	No	
323	5010	1	2			Stairs across the Elevator	W4	chipping door and frame, chipping, flaking	12	No	No	N/A	N/A	No	
324	5010	1	2			Stairs leading into Classroom 221	Floor	chipping stair face	2	No	No	N/A	N/A	No	
325	5010	1	2			Stairs leading into Classroom 221	W1	chipping, flaking	8	No	No	N/A	N/A	No	
326	5010	1	2			Stairs leading into Classroom 221	W3	chipping iron gate, chipping	14	No	No	N/A	N/A	No	
327	5010	1	2			Stairs leading into Classroom 221	W4	chipping, flaking	3	No	No	N/A	N/A	No	
328	5010	1	2			Stairwell 1 across from Classroom 204	Ceiling	chipping, flaking	2	No	No	N/A	N/A	No	
329	5010	1	2			Stairwell 1 across from Classroom 204	Floor	chipping railing, chipping stair face	70	No	No	N/A	N/A	No	
330	5010	1	2			Stairwell 1 across from Classroom 204	W1	cracking, chipping, flaking	15	No	No	N/A	N/A	No	
331	5010	1	2			Stairwell 1 across from Classroom 204	W2	cracking, chipping, flaking	4	No	No	N/A	N/A	No	
332	5010	1	2			Stairwell 1 across from Classroom 204	W3	cracking, chipping, flaking	5	No	No	N/A	N/A	No	
333	5010	1	2			Stairwell 1 across from Classroom 204	W4	cracking, chipping, gouges, holes, flaking, chipping door and frame	18	No	No	N/A	N/A	Yes	
334	5010	1	2			West Stairwell	Ceiling	cracking, chipping, holes, flaking	110	No	No	N/A	N/A	Yes	
335	5010	1	2			West Stairwell	Floor	Debris	N/A	No	Yes	20	N/A	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
336	5010	1	2			West Stairwell	W1	cracking, chipping, holes, flaking, chipping door and frame	18	No	No	N/A	N/A	Yes	
337	5010	1	2			West Stairwell	W2	chipping, chipping door and frame	14	No	No	N/A	N/A	No	
338	5010	1	2			West Stairwell	W3	cracking, chipping, holes, flaking,	10	No	No	N/A	N/A	Yes	
339	5010	1	2			West Stairwell	W4	cracking, chipping, gouges, holes, flaking,	14	No	No	N/A	N/A	Yes	
340	5010	1	2			West Stairwell Fire Tower	Ceiling	cracking, chipping, flaking, significant moisture damage	115	Yes	No	N/A	N/A	Yes	
341	5010	1	2			West Stairwell Fire Tower	Floor	Debris	N/A	No	Yes	43	N/A	No	
342	5010	1	2			West Stairwell Fire Tower	W1	chipping iron bars, chipping door and frame, chipping, flaking	155	No	No	N/A	N/A	No	
343	5010	1	2			West Stairwell Fire Tower	W2	cracking, chipping, flaking	90	No	No	N/A	N/A	No	
344	5010	1	2			West Stairwell Fire Tower	W3	cracking, chipping, flaking	76	No	No	N/A	N/A	No	
345	5010	1	2			West Stairwell Fire Tower	W4	cracking, chipping, flaking	190	No	No	N/A	N/A	No	
346	5010	1	1			Auditorium Balcony	Ceiling	cracking, chipping, holes, flaking	270	No	No	N/A	N/A	Yes	
347	5010	1	1			Auditorium Balcony	Floor	Debris	N/A	No	Yes	20	N/A	No	
348	5010	1	1			Auditorium Balcony	W2	chipping door and frame	6	No	No	N/A	N/A	No	
349	5010	1	1			Auditorium Balcony	W3	chipping, holes, flaking, chipping door and frame	20	No	No	N/A	N/A	Yes	
350	5010	1	1			Auditorium Balcony	W4	chipping, chipping, holes, flaking	18	No	No	N/A	N/A	Yes	
351	5010	1	1			Auditorium Projection Room	Ceiling	chipping, holes, flaking	5	No	No	N/A	N/A	Yes	
352	5010	1	1			Auditorium Projection Room	W1	cracking, holes, flaking	9	No	No	N/A	N/A	Yes	
353	5010	1	1			Auditorium Projection Room	W2	cracking, flaking	2	No	No	N/A	N/A	No	
354	5010	1	1			Auditorium Projection Room	W4	chipping, holes	8	No	No	N/A	N/A	Yes	
355	5010	1	1			Classroom 104	Ceiling	flaking	2	No	No	N/A	N/A	No	
356	5010	1	1			Classroom 104	Floor	chipping, baseboard	8	No	No	N/A	N/A	No	
357	5010	1	1			Classroom 104	W1	cracking, chipping, holes, flaking	12	No	No	N/A	N/A	Yes	
358	5010	1	1			Classroom 104	W2	holes	1	No	No	N/A	N/A	Yes	
359	5010	1	1			Classroom 104	W3	cracking, chipping, holes, flaking, chipping radiators	71	No	No	N/A	N/A	Yes	
360	5010	1	1			Classroom 104	W4	chipping, holes	9	No	No	N/A	N/A	Yes	
361	5010	1	1			Classroom 105	Ceiling	cracking, chipping, flaking	8	No	No	N/A	N/A	No	
362	5010	1	1			Classroom 105	W1	cracking, chipping, holes, flaking	12	No	No	N/A	N/A	Yes	
363	5010	1	1			Classroom 105	W3	cracking, chipping, holes, flaking, chipping radiators	50	No	No	N/A	N/A	Yes	
364	5010	1	1			Classroom 105	W4	cracking, chipping, holes, flaking	14	No	No	N/A	N/A	Yes	
365	5010	1	1			Classroom 107	Ceiling	flaking	3	No	No	N/A	N/A	No	
366	5010	1	1			Classroom 107	W1	chipping, holes, flaking	10	No	No	N/A	N/A	Yes	
367	5010	1	1			Classroom 107	W2	cracking, chipping, holes, flaking	12	No	No	N/A	N/A	Yes	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
368	5010	1	1			Classroom 107	W3	cracking, chipping, holes, flaking, chipping radiators	52	No	No	N/A	N/A	Yes	
369	5010	1	1			Classroom 107	W4	cracking, chipping, holes, flaking	13	No	No	N/A	N/A	Yes	
370	5010	1	1			Classroom 108	Floor	chipping baseboard	20	No	No	N/A	N/A	No	
371	5010	1	1			Classroom 108	W1	cracking, chipping, holes, flaking, chipping door and frame, chipping built in	22	No	No	N/A	N/A	Yes	
372	5010	1	1			Classroom 108	W2	chipping	3	No	No	N/A	N/A	No	
373	5010	1	1			Classroom 108	W3	cracking, chipping, holes, flaking, chipping radiators	31	No	No	N/A	N/A	Yes	
374	5010	1	1			Classroom 108	W4	cracking, chipping, holes, flaking, chipping door and frames	25	No	No	N/A	N/A	Yes	
375	5010	1	1			Classroom 108 Closet adjacent to Classroom 107 by Windows	Ceiling	cracking	10	No	No	N/A	N/A	No	
376	5010	1	1			Classroom 108 Closet adjacent to Classroom 107 by Windows	W1	chipping door and frame	4	No	No	N/A	N/A	No	
377	5010	1	1			Classroom 108 Closet adjacent to Classroom 107 by Windows	W2	cracking, holes	18	No	No	N/A	N/A	Yes	
378	5010	1	1			Classroom 108 Closet adjacent to Classroom 107 by Windows	W3	cracking, holes, flaking	15	No	No	N/A	Shelves with stored materials	Yes	
379	5010	1	1			Classroom 108 Closet adjacent to Classroom 107 by Windows	W4	cracking, holes	16	No	No	N/A	N/A	Yes	
380	5010	1	1			Classroom 108 Closet adjacent to Classroom 109	Ceiling	chipping, flaking	12	No	No	N/A	N/A	No	
381	5010	1	1			Classroom 108 Closet adjacent to Classroom 109	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
382	5010	1	1			Classroom 108 Closet adjacent to Classroom 109	Floor	Debris	N/A	No	Yes	5	N/A	No	
383	5010	1	1			Classroom 108 Closet adjacent to Classroom 109	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
384	5010	1	1			Classroom 108 Closet adjacent to Classroom 109	W1	cracking, chipping door and frame	28	No	No	N/A	N/A	No	
385	5010	1	1			Classroom 108 Closet adjacent to Classroom 109	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
386	5010	1	1			Classroom 108 Closet adjacent to Classroom 109	W2	cracking, chipping, holes, flaking	45	No	No	N/A	N/A	Yes	

Kensington HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
387	5010	1	1			Classroom 108 Closet adjacent to Classroom 109	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
388	5010	1	1			Classroom 108 Closet adjacent to Classroom 109	W3	cracking, chipping, flaking	12	No	No	N/A	N/A	No	
389	5010	1	1			Classroom 108 Closet adjacent to Classroom 109	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
390	5010	1	1			Classroom 108 Closet adjacent to Classroom 109	W4	chipping, holes, flaking	10	No	No	N/A	N/A	Yes	
391	5010	1	1			Classroom 108 Closet adjacent to Classroom 109	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
392	5010	1	1			Classroom 109	Ceiling	chipping, flaking	4	No	No	N/A	N/A	No	
393	5010	1	1			Classroom 109	Floor	chipping baseboard	12	No	No	N/A	N/A	No	
394	5010	1	1			Classroom 109	W1	cracking, chipping, holes	14	No	No	N/A	N/A	Yes	
395	5010	1	1			Classroom 109	W2	chipping, holes, flaking	4	No	No	N/A	N/A	Yes	
396	5010	1	1			Classroom 109	W3	chipping, holes, flaking, chipping radiators	47	No	No	N/A	N/A	Yes	
397	5010	1	1			Classroom 109	W4	cracking, chipping, holes, flaking	18	No	No	N/A	N/A	Yes	
398	5010	1	1			Classroom 111	W1	cracking, chipping, holes, flaking	32	No	No	N/A	N/A	Yes	
399	5010	1	1			Classroom 111	W2	cracking, chipping, holes, flaking	37	No	No	N/A	N/A	Yes	
400	5010	1	1			Classroom 111	W3	cracking, chipping, holes, flaking, chipping radiators	61	No	No	N/A	N/A	Yes	
401	5010	1	1			Classroom 111	W4	cracking, chipping, holes, flaking	10	No	No	N/A	N/A	Yes	
402	5010	1	1			Classroom 114	Floor	chipping, baseboard	14	No	No	N/A	N/A	No	
403	5010	1	1			Classroom 114	W1	cracking, chipping, holes, flaking,	13	No	No	N/A	N/A	Yes	
404	5010	1	1			Classroom 114	W2	chipping, holes	6	No	No	N/A	N/A	Yes	
405	5010	1	1			Classroom 114	W3	cracking, chipping, holes, flaking, chipping radiators	42	No	No	N/A	N/A	Yes	
406	5010	1	1			Classroom 114	W4	cracking, chipping, holes	12	No	No	N/A	N/A	Yes	
407	5010	1	1			Classroom 115	W1	cracking, chipping, holes, flaking	16	No	No	N/A	N/A	Yes	
408	5010	1	1			Classroom 115	W2	chipping	4	No	No	N/A	N/A	No	
409	5010	1	1			Classroom 115	W3	chipping, flaking, chipping radiators, chipping metal pipe	46	No	No	N/A	N/A	No	
410	5010	1	1			Classroom 115	W4	chipping	5	No	No	N/A	N/A	No	
411	5010	1	1			Classroom 116	W1	cracking, chipping, holes	8	No	No	N/A	N/A	Yes	
412	5010	1	1			Classroom 116	W2	cracking, chipping, holes, flaking	10	No	No	N/A	N/A	Yes	
413	5010	1	1			Classroom 116	W3	chipping, cracking, holes, flaking, chipping radiators	24	No	No	N/A	N/A	Yes	
414	5010	1	1			Classroom 116	W4	chipping, flaking	4	No	No	N/A	N/A	No	
415	5010	1	1			Classroom 116 Telecommunication Equipment Room	W1	chipping	1	No	No	N/A	N/A	No	
416	5010	1	1			Classroom 116 Telecommunication Equipment Room	W2	holes	1	No	No	N/A	N/A	Yes	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
417	5010	1	1			Classroom 116 Telecommunication Equipment Room	W4	holes	2	No	No	N/A	N/A	Yes	
418	5010	1	1			Classroom 117	Floor	chipping built in cabinets, chipping, baseboard	31	No	No	N/A	N/A	No	
419	5010	1	1			Classroom 117	W1	cracking, chipping, holes, flaking, chipping door and frame	18	No	No	N/A	N/A	Yes	
420	5010	1	1			Classroom 117	W2	cracking, chipping, holes	10	No	No	N/A	N/A	Yes	
421	5010	1	1			Classroom 117	W3	cracking, chipping, holes, flaking	10	No	No	N/A	N/A	Yes	
422	5010	1	1			Classroom 117	W4	cracking, chipping, holes, flaking	12	No	No	N/A	N/A	Yes	
423	5010	1	1			Classroom 118	W1	chipping, flaking, chipping door and frame	10	No	No	N/A	N/A	No	
424	5010	1	1			Classroom 118	W2	chipping, holes	7	No	No	N/A	N/A	Yes	
425	5010	1	1			Classroom 118	W3	cracking, chipping, flaking, chipping radiators	28	No	No	N/A	N/A	No	
426	5010	1	1			Department Office 112	W1	cracking, chipping, holes	6	No	No	N/A	N/A	Yes	
427	5010	1	1			Department Office 112	W2	chipping, holes, flaking	12	No	No	N/A	N/A	Yes	
428	5010	1	1			Department Office 112	W3	chipping radiators	7	No	No	N/A	N/A	No	
429	5010	1	1			Department Office 112	W4	chipping, holes, flaking	6	No	No	N/A	N/A	Yes	
430	5010	1	1			East Fire Tower	Ceiling	cracking, chipping, holes, flaking,	220	No	No	N/A	N/A	Yes	
431	5010	1	1			East Fire Tower	Floor	Debris	N/A	No	Yes	40	N/A	No	
432	5010	1	1			East Fire Tower	W1	chipping door and frame	8	No	No	N/A	N/A	No	
433	5010	1	1			East Fire Tower	W2	chipping wood	20	No	No	N/A	N/A	No	
434	5010	1	1			East Fire Tower	W3	chipping iron bars	120	No	No	N/A	N/A	No	
435	5010	1	1			East Fire Tower	W4	chipping door and frame	8	No	No	N/A	N/A	No	
436	5010	1	1			East Stairwell	Ceiling	cracking, chipping, flaking, efflorescence, significant moisture damage	190	Yes	No	N/A	N/A	Yes	
437	5010	1	1			East Stairwell	Floor	Debris	N/A	No	Yes	27	N/A	No	
438	5010	1	1			East Stairwell	W1	cracking, chipping, holes, flaking, chipping radiators	50	No	No	N/A	N/A	Yes	
439	5010	1	1			East Stairwell	W2	chipping door and frame	3	No	No	N/A	N/A	No	
440	5010	1	1			East Stairwell	W3	cracking, chipping, holes, flaking	45	No	No	N/A	N/A	Yes	
441	5010	1	1			East Stairwell	W4	cracking, chipping, holes, flaking, efflorescence,	25	Yes	No	N/A	N/A	Yes	
442	5010	1	1			Elevator	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
443	5010	1	1			Elevator	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
444	5010	1	1			Elevator	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
445	5010	1	1			Elevator	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
446	5010	1	1			Elevator	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
447	5010	1	1			Elevator	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
448	5010	1	1			Foyer outside Women's Restroom across from Classroom 104	Ceiling	chipping	2	No	No	N/A	N/A	No	
449	5010	1	1			Foyer outside Women's Restroom across from Classroom 104	W1	cracking, chipping, holes	12	No	No	N/A	N/A	Yes	
450	5010	1	1			Foyer outside Women's Restroom across from Classroom 104	W2	cracking, chipping, holes	10	No	No	N/A	Cabinets	Yes	
451	5010	1	1			Foyer outside Women's Restroom across from Classroom 104	W3	chipping, efflorescence, chipping door and frame	8	Yes	No	N/A	N/A	Yes	
452	5010	1	1			Foyer outside Women's Restroom across from Classroom 104	W4	cracking, chipping, flaking	3	No	No	N/A	N/A	No	
453	5010	1	1			Foyer/Stairwell to Right of Stage Balcony Level	Ceiling	chipping, flaking	3	No	No	N/A	N/A	No	
454	5010	1	1			Foyer/Stairwell to Right of Stage Balcony Level	W1	cracking, chipping, gouges, holes, chipping door and frame	10	No	No	N/A	N/A	Yes	
455	5010	1	1			Foyer/Stairwell to Right of Stage Balcony Level	W2	cracking, chipping, holes, flaking	48	No	No	N/A	N/A	Yes	
456	5010	1	1			Foyer/Stairwell to Right of Stage Balcony Level	W3	cracking, chipping, holes, flaking, chipping radiators	55	No	No	N/A	N/A	Yes	
457	5010	1	1			Foyer/Stairwell to Right of Stage Balcony Level	W4	chipping, holes, flaking, chipping door and frame	14	No	No	N/A	N/A	Yes	
458	5010	1	1			Girl's Restroom adjacent to Classroom 104	Ceiling	flaking, spalling	8	No	No	N/A	N/A	Yes	
459	5010	1	1			Girl's Restroom adjacent to Classroom 104	W1	chipping door and frame	4	No	No	N/A	N/A	No	
460	5010	1	1			Hallway from Classroom 111 to West Stairwell	Floor	chipping perimeter paint	34	No	No	N/A	N/A	No	
461	5010	1	1			Hallway from Classroom 111 to West Stairwell	W1	cracking, chipping, holes, flaking, spalling, chipping radiators, chipping metal pipe	26	No	No	N/A	N/A	Yes	
462	5010	1	1			Hallway from Classroom 111 to West Stairwell	W2	chipping, holes	3	No	No	N/A	N/A	Yes	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
463	5010	1	1			Hallway from Classroom 111 to West Stairwell	W3	chipping, holes, flaking	17	No	No	N/A	N/A	Yes	
464	5010	1	1			Hallway from Classroom 111 to West Stairwell	W4	chipping, holes	2	No	No	N/A	N/A	Yes	
465	5010	1	1			Hallway from the Elevator to Office 112	W1	chipping	10	No	No	N/A	N/A	No	
466	5010	1	1			Hallway from the Elevator to Office 112	W2	cracking, chipping, holes	13	No	No	N/A	N/A	Yes	
467	5010	1	1			Hallway from the Elevator to Office 112	W4	holes	2	No	No	N/A	N/A	Yes	
468	5010	1	1			Hallway outside Auditorium Balcony	W1	cracking, chipping	10	No	No	N/A	N/A	No	
469	5010	1	1			Hallway outside Auditorium Balcony	W2	cracking, spalling	2	No	No	N/A	N/A	Yes	
470	5010	1	1			Hallway outside Auditorium Balcony	W3	cracking, chipping, flaking, chipping metal pipe chipping radiators	6	No	No	N/A	N/A	No	
471	5010	1	1			Hallway outside Auditorium Balcony	W4	cracking, flaking	20	No	No	N/A	N/A	No	
472	5010	1	1			Main Office 1	Floor	chipping baseboard	44	No	No	N/A	N/A	No	
473	5010	1	1			Main Office 1	W1	chipping door and frame, chipping, flaking	19	No	No	N/A	N/A	No	
474	5010	1	1			Main Office 1	W2	chipping, holes, flaking	8	No	No	N/A	N/A	Yes	
475	5010	1	1			Main Office 1	W3	chipping, holes, flaking	15	No	No	N/A	N/A	Yes	
476	5010	1	1			Main Office 1	W4	chipping, holes, flaking	5	No	No	N/A	N/A	Yes	
477	5010	1	1			Main Office 1 Book Closet	Ceiling	holes	3	No	No	N/A	N/A	Yes	
478	5010	1	1			Main Office 1 Book Closet	W1	chipping	2	No	No	N/A	Shelving with stored materials	No	
479	5010	1	1			Main Office 1 Book Closet	W3	cracking	5	No	No	N/A	N/A	No	
480	5010	1	1			Main Office 1 Copy Room	Ceiling	chipping, flaking	1	No	No	N/A	N/A	No	
481	5010	1	1			Main Office 1 Copy Room	Floor	chipping, baseboard	13	No	No	N/A	N/A	No	
482	5010	1	1			Main Office 1 Copy Room	W1	cracking, chipping, holes, flaking,	5	No	No	N/A	N/A	Yes	
483	5010	1	1			Main Office 1 Copy Room	W2	cracking, chipping, holes, flaking,	9	No	No	N/A	N/A	Yes	
484	5010	1	1			Main Office 1 Copy Room	W3	cracking, chipping, holes, flaking, chipping radiators	9	No	No	N/A	N/A	Yes	
485	5010	1	1			Main Office 1 Copy Room	W4	chipping, holes, flaking	7	No	No	N/A	N/A	Yes	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
486	5010	1	1			Main Office 1 Telecommunication Equipment Room	W1	cracking, chipping, holes, flaking	5	No	No	N/A	N/A	Yes	
487	5010	1	1			Main Office 1 Telecommunication Equipment Room	W2	cracking, chipping, holes, flaking, chipping radiators	7	No	No	N/A	N/A	Yes	
488	5010	1	1			Main Office 1 Telecommunication Equipment Room	W3	cracking, flaking	6	No	No	N/A	N/A	No	
489	5010	1	1			Main Office 1 Telecommunication Equipment Room	W4	cracking, spalling	6	No	No	N/A	N/A	Yes	
490	5010	1	1			Main Office 2	Ceiling	chipping, flaking, holes	4	No	No	N/A	N/A	Yes	
491	5010	1	1			Main Office 2	W1	chipping, flaking	14	No	No	N/A	N/A	No	
492	5010	1	1			Main Office 2	W2	chipping, flaking	4	No	No	N/A	N/A	No	
493	5010	1	1			Main Office 2	W3	chipping, flaking, holes, chipping radiators	16	No	No	N/A	N/A	Yes	
494	5010	1	1			Main Office 2	W4	chipping, flaking	5	No	No	N/A	N/A	No	
495	5010	1	1			Main Office 2 Conference Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
496	5010	1	1			Main Office 2 Conference Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
497	5010	1	1			Main Office 2 Conference Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
498	5010	1	1			Main Office 2 Conference Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
499	5010	1	1			Main Office 2 Conference Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
500	5010	1	1			Main Office 2 Conference Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
501	5010	1	1			Main Office 2 Principal's Office	W1	chipping, holes	8	No	No	N/A	N/A	Yes	
502	5010	1	1			Main Office 2 Principal's Office	W2	chipping, holes	3	No	No	N/A	N/A	Yes	
503	5010	1	1			Main Office 2 Principal's Office	W3	cracking	2	No	No	N/A	N/A	No	
504	5010	1	1			Main Office 2 Principal's Office	W4	chipping	4	No	No	N/A	N/A	No	
505	5010	1	1			Office 106 in West Stairwell	W1	cracking, chipping, flaking, holes, chipping radiators	20	No	No	N/A	N/A	Yes	
506	5010	1	1			Office 106 in West Stairwell	W2	chipping, flaking	6	No	No	N/A	N/A	No	
507	5010	1	1			Office 106 in West Stairwell	W3	holes	4	No	No	N/A	N/A	Yes	
508	5010	1	1			Office 106 in West Stairwell	W4	cracking, flaking	5	No	No	N/A	N/A	No	
509	5010	1	1			Office to Left of Stage Balcony Level	W1	chipping, holes, flaking, chipping door and frame	21	No	No	N/A	N/A	Yes	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
510	5010	1	1			Office to Left of Stage Balcony Level	W2	chipping, holes, flaking	13	No	No	N/A	N/A	Yes	
511	5010	1	1			Office to Left of Stage Balcony Level	W3	cracking, chipping, holes, flaking	15	No	No	N/A	N/A	Yes	
512	5010	1	1			Office to Left of Stage Balcony Level	W4	cracking, chipping, holes, flaking	9	No	No	N/A	N/A	Yes	
513	5010	1	1			Office to Left of Stage Balcony Level Restroom	Ceiling	cracking, flaking	4	No	No	N/A	N/A	No	
514	5010	1	1			Office to Left of Stage Balcony Level Restroom	W4	chipping	4	No	No	N/A	N/A	No	
515	5010	1	1			Principal's Office	Ceiling	holes, significant moisture damage	5	Yes	No	N/A	N/A	Yes	
516	5010	1	1			Principal's Office	Floor	chipping, baseboard	3	No	No	N/A	N/A	No	
517	5010	1	1			Principal's Office	W1	cracking	10	No	No	N/A	N/A	No	
518	5010	1	1			Principal's Office	W3	cracking, flaking	17	No	No	N/A	N/A	No	
519	5010	1	1			Principal's Office 110	W1	cracking, chipping, holes, flaking	7	No	No	N/A	N/A	Yes	
520	5010	1	1			Principal's Office 110	W2	cracking, chipping, holes, flaking	6	No	No	N/A	N/A	Yes	
521	5010	1	1			Principal's Office 110	W3	chipping, chipping radiators	10	No	No	N/A	N/A	No	
522	5010	1	1			Principal's Office 110	W4	cracking	3	No	No	N/A	N/A	No	
523	5010	1	1			Principal's Storage Room 119	W3	cracking, chipping door and frame	8	No	No	N/A	N/A	No	
524	5010	1	1			Roster Office	Ceiling	chipping, flaking	3	No	No	N/A	N/A	No	
525	5010	1	1			Roster Office	Floor	Debris	N/A	No	Yes	4	N/A	No	
526	5010	1	1			Roster Office	W1	chipping	3	No	No	N/A	N/A	No	
527	5010	1	1			Roster Office	W2	chipping radiators	3	No	No	N/A	N/A	No	
528	5010	1	1			Roster Office	W3	cracking, chipping, flaking	4	No	No	N/A	N/A	No	
529	5010	1	1			Roster Office	W4	cracking, chipping, flaking, chipping radiators	6	No	No	N/A	N/A	No	
530	5010	1	1			School Police Office 120	Ceiling	cracking, flaking, flaking above missing ceiling tiles	24	No	No	N/A	N/A	No	
531	5010	1	1			School Police Office 120	W1	chipping, chipping door frame, holes, flaking	12	No	No	N/A	N/A	Yes	
532	5010	1	1			School Police Office 120	W2	cracking, chipping, holes, flaking	82	No	No	N/A	N/A	Yes	
533	5010	1	1			School Police Office 120	W3	hole, flaking	19	No	No	N/A	N/A	Yes	
534	5010	1	1			School Police Office 120	W4	cracking, chipping, holes, flaking, flaking metal pipe jackets	106	No	No	N/A	N/A	Yes	
535	5010	1	1			School Police Office 120 Stairwell	Ceiling	flaking, spalling	22	No	No	N/A	N/A	Yes	
536	5010	1	1			School Police Office 120 Stairwell	Floor	chipping railings	10	No	No	N/A	N/A	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
537	5010	1	1			School Police Office 120 Stairwell	W1	cracking, chipping, chipping door and frame	48	No	No	N/A	N/A	No	
538	5010	1	1			School Police Office 120 Stairwell	W2	cracking, chipping, flaking, spalling	56	No	No	N/A	N/A	Yes	
539	5010	1	1			School Police Office 120 Stairwell	W3	spalling	2	No	No	N/A	N/A	Yes	
540	5010	1	1			Stairs across from Classroom 104	Ceiling	chipping	2	No	No	N/A	N/A	No	
541	5010	1	1			Stairs across from Classroom 104	Floor	chipping, rail, chipping, stair face	45	No	No	N/A	N/A	No	
542	5010	1	1			Stairs across from Classroom 104	W1	cracking, chipping, chipping radiators	29	No	No	N/A	N/A	No	
543	5010	1	1			Stairs across from Classroom 104	W2	cracking, chipping railing	20	No	No	N/A	N/A	No	
544	5010	1	1			Stairs across from Classroom 104	W3	chipping, chipping radiators	10	No	No	N/A	N/A	No	
545	5010	1	1			Stairs across from Classroom 104	W4	chipping door and frame	8	No	No	N/A	N/A	No	
546	5010	1	1			Stairs next to 119 Principal Only Room	Ceiling	chipping, flaking	3	No	No	N/A	N/A	No	
547	5010	1	1			Stairs next to 119 Principal Only Room	Floor	chipping stair faces, chipping railings	41	No	No	N/A	N/A	No	
548	5010	1	1			Stairs next to 119 Principal Only Room	W1	chipping radiators	6	No	No	N/A	N/A	No	
549	5010	1	1			Stairs next to 119 Principal Only Room	W2	flaking	2	No	No	N/A	N/A	No	
550	5010	1	1			Stairs next to 119 Principal Only Room	W3	chipping radiators	6	No	No	N/A	N/A	No	
551	5010	1	1			Stairs next to 119 Principal Only Room	W4	flaking, chipping door and frame	10	No	No	N/A	N/A	No	
552	5010	1	1			Stairs to Assistant Principal's Office 110	Ceiling	holes	1	No	No	N/A	N/A	Yes	
553	5010	1	1			Stairs to Assistant Principal's Office 110	Floor	chipping railing	27	No	No	N/A	N/A	No	
554	5010	1	1			Stairs to Assistant Principal's Office 110	W2	cracking, flaking	6	No	No	N/A	N/A	No	
555	5010	1	1			Stairs to Assistant Principal's Office 110	W3	chipping, flaking	4	No	No	N/A	N/A	No	
556	5010	1	1			Stairs to Assistant Principal's Office 110	W4	cracking	8	No	No	N/A	N/A	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
557	5010	1	1			Teacher's Lounge 102	Ceiling	chipping, holes, flaking	10	No	No	N/A	N/A	Yes	
558	5010	1	1			Teacher's Lounge 102	Floor	Debris	N/A	No	Yes	3	N/A	No	
559	5010	1	1			Teacher's Lounge 102	W1	cracking, chipping, holes	16	No	No	N/A	N/A	Yes	
560	5010	1	1			Teacher's Lounge 102	W2	cracking, holes, flaking	3	No	No	N/A	N/A	Yes	
561	5010	1	1			Teacher's Lounge 102	W3	cracking, chipping, holes, flaking, chipping radiators	52	No	No	N/A	N/A	Yes	
562	5010	1	1			Teacher's Lounge 102	W4	cracking, flaking	5	No	No	N/A	N/A	No	
563	5010	1	1			Upper Hallway behind Stage	W1	cracking, chipping, flaking, chipping door and frame	14	No	No	N/A	N/A	No	
564	5010	1	1			Upper Hallway behind Stage	W2	cracking, chipping, flaking	60	No	No	N/A	N/A	No	
565	5010	1	1			Upper Hallway behind Stage	W3	chipping, flaking,	12	No	No	N/A	N/A	No	
566	5010	1	1			Upper Hallway behind Stage	W4	cracking, chipping, holes, flaking, chipping radiators	125	No	No	N/A	N/A	Yes	
567	5010	1	1			West Stairwell	Ceiling	cracking, chipping, holes, flaking	44	No	No	N/A	N/A	Yes	
568	5010	1	1			West Stairwell	Floor	Debris	N/A	No	Yes	16	N/A	No	
569	5010	1	1			West Stairwell	W1	cracking, chipping, holes, flaking	30	No	No	N/A	N/A	Yes	
570	5010	1	1			West Stairwell	W2	chipping door and frame	2	No	No	N/A	N/A	No	
571	5010	1	1			West Stairwell	W3	cracking, chipping, flaking	22	No	No	N/A	N/A	No	
572	5010	1	1			West Stairwell	W4	cracking, chipping, holes, flaking	35	No	No	N/A	N/A	Yes	
573	5010	1	1			West Stairwell Fire Tower	Ceiling	cracking, chipping, holes, flaking	122	No	No	N/A	N/A	Yes	
574	5010	1	1			West Stairwell Fire Tower	Floor	Debris	N/A	No	Yes	83	N/A	No	
575	5010	1	1			West Stairwell Fire Tower	W1	cracking, chipping, holes, flaking, chipping, iron bar chipping door and frame	156	No	No	N/A	N/A	Yes	
576	5010	1	1			West Stairwell Fire Tower	W2	cracking, chipping, holes, flaking	28	No	No	N/A	N/A	Yes	
577	5010	1	1			West Stairwell Fire Tower	W3	cracking, holes, flaking	7	No	No	N/A	N/A	Yes	
578	5010	1	1			West Stairwell Fire Tower	W4	cracking, chipping, holes, flaking	82	No	No	N/A	N/A	Yes	
579	5010	1	1			Women's Restroom across from Classroom 104	Ceiling	cracking, chipping, flaking	10	No	No	N/A	N/A	No	
580	5010	1	0			009 Suite Former Teacher's Lounge	W1	Chipping door and frame	11	No	No	N/A	N/A	No	
581	5010	1	0			009 Suite Former Teacher's Lounge	W2	Flaking metal duct	10	No	Debris is inside bottom of duct	3	N/A	No	
582	5010	1	0			009 Suite Former Teacher's Lounge	W3	Chipping	1	No	No	N/A	N/A	No	
583	5010	1	0			009 Suite Former Teacher's Lounge	W4	Chipping radiator cover, chipping window frame	2	No	No	N/A	N/A	No	
584	5010	1	0			009B Front Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
585	5010	1	0			009B Front Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
586	5010	1	0			009B Front Storage Room	W1	No Access	N/A	No	No	N/A	N/A	No	This space will need to be inspected
587	5010	1	0			009B Front Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
588	5010	1	0			009B Front Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
589	5010	1	0			009B Front Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
590	5010	1	0			009B Rear Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
591	5010	1	0			009B Rear Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
592	5010	1	0			009B Rear Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
593	5010	1	0			009B Rear Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
594	5010	1	0			009B Rear Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
595	5010	1	0			009B Rear Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
596	5010	1	0			Auditorium	Ceiling	Flaking, efflorescence	1869	Yes	No	N/A	N/A	Yes	
597	5010	1	0			Auditorium	W1	Cracking, flaking	12	No	No	N/A	N/A	No	
598	5010	1	0			Auditorium	W2	Holes, flaking	11	No	No	N/A	N/A	Yes	
599	5010	1	0			Auditorium	W3	Cracking, holes	4	No	No	N/A	N/A	Yes	
600	5010	1	0			Auditorium	W4	Cracking, chipping metal pipe jacket, holes, flaking, efflorescence	39	Yes	No	N/A	N/A	Yes	
601	5010	1	0			Boy's Restroom across from Classroom 5	Ceiling	Flaking metal duct	5	No	No	N/A	N/A	No	
602	5010	1	0			Boy's Restroom across from Classroom 5	W1	Chipping door and frame, flaking	24	No	No	N/A	N/A	No	
603	5010	1	0			Boy's Restroom across from Classroom 5	W3	Chipping window frames	6	No	No	N/A	N/A	No	
604	5010	1	0			Boy's Restroom across the Elevator	Ceiling	Flaking above missing ceiling tile	8	No	No	N/A	N/A	No	
605	5010	1	0			Boy's Restroom across the Elevator	W1	Chipping door and frame	6	No	No	N/A	N/A	No	
606	5010	1	0			Boy's Restroom across the Elevator	W4	Chipping window frame	4	No	No	N/A	N/A	No	
607	5010	1	0			Cafeteria	Ceiling	Chipping, flaking, flaking ducts, flaking metal pipes	409	No	No	N/A	N/A	No	
608	5010	1	0			Cafeteria	Floor	Chipping	146	No	No	N/A	N/A	No	
609	5010	1	0			Cafeteria	W1	Chipping door frame, chipping, holes	21	No	No	N/A	N/A	Yes	Wall 1 relative to auditorium side
610	5010	1	0			Cafeteria	W2	Chipping, chipping conduit, flaking, flaking metal pipes	26	No	No	N/A	N/A	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
611	5010	1	0			Cafeteria	W3	Chipping	16	No	No	N/A	N/A	No	
612	5010	1	0			Cafeteria	W4	Chipping, flaking, walls and columns	22	No	No	N/A	N/A	No	
613	5010	1	0			Classroom 1	Ceiling	chipping, flaking, duct	122	No	No	N/A	N/A	No	
614	5010	1	0			Classroom 1	W1	chipping, flaking, brick	12	No	No	N/A	N/A	No	
615	5010	1	0			Classroom 1	W2	cracking, chipping, holes, flaking, brick	35	No	No	N/A	N/A	Yes	
616	5010	1	0			Classroom 1	W3	chipping, flaking,	14	No	No	N/A	N/A	No	
617	5010	1	0			Classroom 1	W4	chipping, flaking, brick	15	No	No	N/A	N/A	No	
618	5010	1	0			Classroom 2	W1	chipping, holes, flaking	18	No	No	N/A	N/A	Yes	
619	5010	1	0			Classroom 2	W2	chipping door and frame	6	No	No	N/A	N/A	No	
620	5010	1	0			Classroom 2	W3	cracking, chipping, holes, chipping radiators	50	No	No	N/A	N/A	Yes	
621	5010	1	0			Classroom 2	W4	cracking, flaking	11	No	No	N/A	N/A	No	
622	5010	1	0			Classroom 2 Closet	W1	N/A	N/A	No	No	N/A	Stored materials	No	Limited inspection due to stored materials
623	5010	1	0			Classroom 2 Closet	W2	holes	1	No	No	N/A	N/A	Yes	
624	5010	1	0			Classroom 2 Closet	W3	holes	1	No	No	N/A	N/A	Yes	
625	5010	1	0			Classroom 2 Closet	W4	holes	2	No	No	N/A	N/A	Yes	
626	5010	1	0			Classroom 2 Restroom	Ceiling	holes	2	No	No	N/A	N/A	Yes	
627	5010	1	0			Classroom 2 Restroom	W1	chipping door and frame	8	No	No	N/A	N/A	No	
628	5010	1	0			Classroom 5	Ceiling	Flaking	5	No	No	N/A	N/A	No	
629	5010	1	0			Classroom 5	W1	Cracking, chipping, holes, flaking	29	No	No	N/A	N/A	Yes	
630	5010	1	0			Classroom 5	W2	Chipping, flaking	5	No	No	N/A	N/A	No	
631	5010	1	0			Classroom 5	W3	Holes	1	No	No	N/A	N/A	Yes	
632	5010	1	0			Classroom 5	W4	Holes	6	No	No	N/A	N/A	Yes	
633	5010	1	0			East Stairwell	Ceiling	Significant moisture damage	50	Yes	No	N/A	N/A	Yes	
634	5010	1	0			East Stairwell	W1	Flaking	10	No	No	N/A	N/A	No	
635	5010	1	0			East Stairwell	W2	Chipping door and frame, flaking	21	No	No	N/A	N/A	No	
636	5010	1	0			East Stairwell	W3	Flaking, efflorescence	17	Yes	No	N/A	N/A	Yes	
637	5010	1	0			Fire Exit by Classroom 2	Ceiling	chipping, holes, flaking, efflorescence, significant moisture damage	20	Yes	No	N/A	N/A	Yes	
638	5010	1	0			Fire Exit by Classroom 2	Floor	Debris	N/A	No	Yes	5	N/A	No	
639	5010	1	0			Fire Exit by Classroom 2	W1	chipping, flaking,	6	No	No	N/A	N/A	No	
640	5010	1	0			Fire Exit by Classroom 2	W2	cracking, chipping, holes, flaking, chipping door and frame	62	No	No	N/A	N/A	Yes	
641	5010	1	0			Fire Exit by Classroom 2	W3	cracking, chipping, holes, flaking,	55	No	No	N/A	N/A	Yes	
642	5010	1	0			Fire Exit by Classroom 2	W4	chipping door and frame	4	No	No	N/A	N/A	No	
643	5010	1	0			Foyer to Left of Stage	Ceiling	Holes, flaking	19	No	No	N/A	N/A	Yes	
644	5010	1	0			Foyer to Left of Stage	W1	Chipping, chipping door and frame, holes, flaking	26	No	No	N/A	N/A	Yes	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
645	5010	1	0			Foyer to Left of Stage	W2	Cracking, chipping, chipping radiators, holes, flaking	62	No	No	N/A	N/A	Yes	
646	5010	1	0			Foyer to Left of Stage	W3	Cracking, chipping, chipping door frame, flaking	25	No	No	N/A	N/A	No	
647	5010	1	0			Foyer to Left of Stage	W4	Cracking, chipping, flaking	84	No	No	N/A	N/A	No	
648	5010	1	0			Foyer to Left of Stage Restroom	Floor	Debris	N/A	No	Yes	1	N/A	No	
649	5010	1	0			Foyer to Left of Stage Restroom	W1	Chipping door and frame	16	No	No	N/A	N/A	No	
650	5010	1	0			Foyer to Left of Stage Restroom	W3	Efflorescence behind missing ceramic tiles	1	Yes	No	N/A	N/A	Yes	
651	5010	1	0			Foyer to the 009 Suite of Rooms	Ceiling	Flaking metal duct	1	No	No	N/A	N/A	No	
652	5010	1	0			Foyer to the 009 Suite of Rooms	W1	Cracking, chipping door frame, flaking, flaking vent cover, flaking baseboard	48	No	No	N/A	N/A	No	
653	5010	1	0			Foyer to the 009 Suite of Rooms	W3	Chipping	3	No	No	N/A	N/A	No	
654	5010	1	0			Foyer to the 009 Suite of Rooms	W4	Cracking	6	No	No	N/A	N/A	No	
655	5010	1	0			Gas Shut Off Room / Male and Female Restroom	Ceiling	cracking, chipping, holes, flaking, efflorescence, significant moisture damage	10	Yes	No	N/A	N/A	Yes	
656	5010	1	0			Girl's Restroom across the Elevator	W1	Chipping door and frame	6	No	No	N/A	N/A	No	
657	5010	1	0			Hallway along Auditorium	Ceiling	Hole, paint has been stabilized	1	No	No	N/A	N/A	Yes	
658	5010	1	0			Hallway along Auditorium	Floor	Chipping	6	No	No	N/A	N/A	No	
659	5010	1	0			Hallway along Auditorium	W1	Cracking, holes, flaking	8	No	No	N/A	N/A	Yes	
660	5010	1	0			Hallway along Auditorium	W2	Cracking	4	No	No	N/A	N/A	No	
661	5010	1	0			Hallway along Auditorium	W3	Cracking, chipping metal pipe jackets, chipping radiators	25	No	No	N/A	N/A	No	
662	5010	1	0			Hallway along Auditorium	W4	Chipping, stable holes	3	No	No	N/A	N/A	Yes	
663	5010	1	0			Hallway behind Stage	Ceiling	Hole	1	No	No	N/A	N/A	Yes	
664	5010	1	0			Hallway behind Stage	Floor	Debris	N/A	No	Yes	2	N/A	No	
665	5010	1	0			Hallway behind Stage	W1	Chipping door and frame	32	No	No	N/A	N/A	No	
666	5010	1	0			Hallway behind Stage	W2	Chipping, gouges, holes	24	No	No	N/A	N/A	Yes	
667	5010	1	0			Hallway behind Stage	W3	Chipping door and frame	8	No	No	N/A	N/A	No	
668	5010	1	0			Hallway behind Stage	W4	Chipping, chipping metal pipe jackets, chipping radiators, gouges, flaking	45	No	No	N/A	N/A	Yes	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
669	5010	1	0			Hallway from Classroom 2 to the Gas Shut Off Room	Floor	chipping and flaking baseboard	10	No	No	N/A	N/A	No	
670	5010	1	0			Hallway from Classroom 2 to the Gas Shut Off Room	W1	cracking, chipping, flaking	10	No	No	N/A	N/A	No	
671	5010	1	0			Hallway from Classroom 2 to the Gas Shut Off Room	W2	cracking, chipping, flaking	65	No	No	N/A	N/A	No	
672	5010	1	0			Hallway from Classroom 2 to the Gas Shut Off Room	W3	cracking, chipping, flaking, chipping radiators, chipping metal pipe	20	No	No	N/A	N/A	No	
673	5010	1	0			Hallway from Classroom 2 to the Gas Shut Off Room	W4	cracking, chipping, holes, flaking	24	No	No	N/A	N/A	Yes	
674	5010	1	0			Hallway from the Cafeteria Entrance to Classroom 5	Ceiling	cracking	6	No	No	N/A	N/A	No	
675	5010	1	0			Hallway from the Cafeteria Entrance to Classroom 5	W1	chipping	2	No	No	N/A	N/A	No	
676	5010	1	0			Hallway from the Cafeteria Entrance to Classroom 5	W2	cracking, chipping, flaking, chipping door and frame	16	No	No	N/A	N/A	No	
677	5010	1	0			Hallway from the Cafeteria Entrance to Classroom 5	W3	chipping	1	No	No	N/A	N/A	No	
678	5010	1	0			Hallway from the Cafeteria Entrance to Classroom 5	W4	chipping	6	No	No	N/A	N/A	No	
679	5010	1	0			Hallway from the Elevator to the Cafeteria Entrance	Floor	Chipping	10	No	No	N/A	N/A	No	
680	5010	1	0			Hallway from the Elevator to the Cafeteria Entrance	W2	Cracking, holes	7	No	No	N/A	N/A	Yes	
681	5010	1	0			Hallway from the Elevator to the Cafeteria Entrance	W3	Cracking	6	No	No	N/A	N/A	No	
682	5010	1	0			Hallway from the Elevator to the Cafeteria Entrance	W4	Cracking, chipping	9	No	No	N/A	N/A	No	
683	5010	1	0			Hallway outside Boy's and Girl's Restrooms	W2	Chipping window frame	3	No	No	N/A	N/A	No	
684	5010	1	0			Hallway outside Boy's and Girl's Restrooms	W3	Flaking above missing ceiling tile	6	No	No	N/A	N/A	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
685	5010	1	0			Hallway outside Classroom 1 to Office 4	Ceiling	chipping, holes, flaking, chipping, flaking, duct, chipping, flaking, metal pipe	205	No	No	N/A	N/A	Yes	
686	5010	1	0			Hallway outside Classroom 1 to Office 4	Floor	chipping, baseboard	20	No	No	N/A	N/A	No	
687	5010	1	0			Hallway outside Classroom 1 to Office 4	W1	cracking, chipping, holes, flaking,	36	No	No	N/A	N/A	Yes	
688	5010	1	0			Hallway outside Classroom 1 to Office 4	W2	cracking, chipping, holes, flaking, chipping door and frame	20	No	No	N/A	N/A	Yes	
689	5010	1	0			Hallway outside Classroom 1 to Office 4	W3	cracking, chipping, holes, flaking,	65	No	No	N/A	N/A	Yes	
690	5010	1	0			Hallway outside Classroom 1 to Office 4	W4	cracking, chipping, holes, flaking, chipping door and frame	28	No	No	N/A	N/A	Yes	
691	5010	1	0			Hallway outside Foyer to Left of Stage	Ceiling	Flaking, efflorescence	10	Yes	No	N/A	N/A	Yes	
692	5010	1	0			Hallway outside Foyer to Left of Stage	Floor	Chipping	30	No	Yes	10	N/A	No	
693	5010	1	0			Hallway outside Foyer to Left of Stage	W1	Holes, paint has been stabilized, efflorescence	11	Yes	No	N/A	N/A	Yes	
694	5010	1	0			Hallway outside Foyer to Left of Stage	W2	Cracking, chipping door and frame	30	No	No	N/A	N/A	No	
695	5010	1	0			Hallway outside Foyer to Left of Stage	W3	Chipping, flaking, spalling	7	Yes	No	N/A	N/A	Yes	
696	5010	1	0			Hallway outside Foyer to Left of Stage	W4	Chipping, efflorescence	13	Yes	No	N/A	N/A	Yes	
697	5010	1	0			Hallway to Building Engineer's Office	Floor	Chipping	4	No	No	N/A	N/A	No	
698	5010	1	0			Hallway to Building Engineer's Office	W1	Chipping door frame, flaking, flaking metal pipes	37	No	No	N/A	N/A	No	
699	5010	1	0			Hallway to Building Engineer's Office	W2	Cracking, holes, flaking	26	No	No	N/A	N/A	Yes	
700	5010	1	0			Hallway to Building Engineer's Office	W3	Chipping	1	No	No	N/A	N/A	No	
701	5010	1	0			Hallway to Building Engineer's Office	W4	Chipping, hole	8	No	No	N/A	N/A	Yes	
702	5010	1	0			Kitchen	Ceiling	Flaking	34	No	No	N/A	N/A	No	
703	5010	1	0			Kitchen	Floor	Chipping	73	No	No	N/A	N/A	No	
704	5010	1	0			Kitchen	W1	Chipping door and frame, chipping, flaking	26	No	No	N/A	N/A	No	
705	5010	1	0			Kitchen	W3	Chipping window frames, flaking	15	No	No	N/A	N/A	No	
706	5010	1	0			Kitchen	W4	Flaking, flaking metal pipes	6	No	No	N/A	N/A	No	
707	5010	1	0			Kitchen Freezer area	Floor	Chipping	11	No	No	N/A	N/A	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
708	5010	1	0			Kitchen Freezer area	W1	Chipping door frame, flaking	11	No	No	N/A	N/A	No	
709	5010	1	0			Kitchen Freezer area	W3	Chipping, flaking	3	No	No	N/A	N/A	No	
710	5010	1	0			Kitchen Loading Dock	Floor	Chipping	120	No	No	N/A	N/A	No	
711	5010	1	0			Kitchen Loading Dock	W2	Chipping	6	No	No	N/A	N/A	No	
712	5010	1	0			Kitchen Loading Dock	W4	Chipping door frame	6	No	No	N/A	N/A	No	
713	5010	1	0			Kitchen Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
714	5010	1	0			Kitchen Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
715	5010	1	0			Kitchen Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
716	5010	1	0			Kitchen Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
717	5010	1	0			Kitchen Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
718	5010	1	0			Kitchen Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
719	5010	1	0			Kitchen Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
720	5010	1	0			Kitchen Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
721	5010	1	0			Kitchen Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
722	5010	1	0			Kitchen Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
723	5010	1	0			Kitchen Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
724	5010	1	0			Kitchen Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
725	5010	1	0			Loading Dock	W1	Flaking doors and frame	60	No	No	N/A	N/A	No	
726	5010	1	0			Main Entrance Vestibule	Ceiling	Flaking	17	No	No	N/A	N/A	No	
727	5010	1	0			Main Entrance Vestibule	W1	Chipping doors and frame	12	No	No	N/A	N/A	No	
728	5010	1	0			Mechanical Room behind Building Engineer's Small Rear Storage Room	Floor	Debris	N/A	No	Paint Chips	225	N/A	No	
729	5010	1	0			Mechanical/Storage Room in Cafeteria	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
730	5010	1	0			Mechanical/Storage Room in Cafeteria	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
731	5010	1	0			Mechanical/Storage Room in Cafeteria	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
732	5010	1	0			Mechanical/Storage Room in Cafeteria	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
733	5010	1	0			Mechanical/Storage Room in Cafeteria	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
734	5010	1	0			Mechanical/Storage Room in Cafeteria	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
735	5010	1	0			Office 009A	Floor	Chipping	32	No	No	N/A	N/A	No	
736	5010	1	0			Office 009A	W1	Chipping door frame, chipping	32	No	No	N/A	N/A	No	
737	5010	1	0			Office 009A	W2	Chipping	13	No	No	N/A	N/A	No	
738	5010	1	0			Office 009A	W3	Cracking, flaking	28	No	No	N/A	N/A	No	
739	5010	1	0			Office 009A	W4	Chipping	13	No	No	N/A	N/A	No	
740	5010	1	0			Office 4	Ceiling	flaking	7	No	No	N/A	N/A	No	
741	5010	1	0			Office 4	Floor	chipping, metal pipe chipping, chipping baseboard	32	No	No	N/A	N/A	No	
742	5010	1	0			Office 4	W1	cracking, chipping, holes, flaking	21	No	No	N/A	N/A	Yes	
743	5010	1	0			Office 4	W2	cracking, chipping, holes, flaking	27	No	No	N/A	N/A	Yes	
744	5010	1	0			Office 4	W3	cracking, chipping, holes, flaking, chipping radiators	28	No	No	N/A	N/A	Yes	
745	5010	1	0			Office 4	W4	cracking, chipping, holes, flaking	36	No	No	N/A	N/A	Yes	
746	5010	1	0			Paint Room in Hallway outside Cafeteria	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
747	5010	1	0			Paint Room in Hallway outside Cafeteria	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
748	5010	1	0			Paint Room in Hallway outside Cafeteria	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
749	5010	1	0			Paint Room in Hallway outside Cafeteria	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
750	5010	1	0			Paint Room in Hallway outside Cafeteria	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
751	5010	1	0			Paint Room in Hallway outside Cafeteria	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
752	5010	1	0			Parent Resource Room 3	Ceiling	cracking, flaking	14	No	No	N/A	N/A	No	
753	5010	1	0			Parent Resource Room 3	W1	chipping, holes	6	No	No	N/A	N/A	Yes	
754	5010	1	0			Parent Resource Room 3	W2	cracking, chipping, holes, flaking	11	No	No	N/A	N/A	Yes	
755	5010	1	0			Parent Resource Room 3	W3	holes, flaking, chipping fiberglass pipe	13	No	No	N/A	N/A	Yes	
756	5010	1	0			Parent Resource Room 3	W4	cracking, chipping, flaking	12	No	No	N/A	N/A	No	
757	5010	1	0			Parent Resource Room 3 Closet	W2	flaking	1	No	No	N/A	N/A	No	
758	5010	1	0			Parent Resource Room 3 Closet	W4	holes	2	No	No	N/A	N/A	Yes	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
759	5010	1	0			Scholarship Office	Ceiling	chipping, flaking	18	No	No	N/A	N/A	No	
760	5010	1	0			Scholarship Office	W1	chipping, flaking, chipping door and frame	20	No	No	N/A	N/A	No	
761	5010	1	0			Scholarship Office	W2	chipping, flaking, efflorescence	60	Yes	No	N/A	N/A	Yes	
762	5010	1	0			Scholarship Office	W3	cracking, chipping, flaking	10	No	No	N/A	N/A	No	
763	5010	1	0			Scholarship Office	W4	cracking, chipping, holes, flaking	32	No	No	N/A	N/A	Yes	
764	5010	1	0			School Police Mini Office	Ceiling	Holes, flaking	12	No	No	N/A	N/A	Yes	
765	5010	1	0			School Police Mini Office	Floor	Chipping	15	No	No	N/A	N/A	No	
766	5010	1	0			School Police Mini Office	W1	Chipping, chipping metal pipes, efflorescence	11	Yes	No	N/A	N/A	Yes	
767	5010	1	0			School Police Mini Office	W2	Cracking	5	No	No	N/A	N/A	No	
768	5010	1	0			School Police Mini Office	W3	Cracking	6	No	No	N/A	N/A	No	
769	5010	1	0			School Police Mini Office	W4	Cracking, efflorescence	35	Yes	No	N/A	N/A	Yes	3 SF suspect mold growth
770	5010	1	0			School Police Mini Office Restroom	Ceiling	Flaking	26	No	No	N/A	N/A	No	
771	5010	1	0			School Police Mini Office Restroom	Floor	Chipping metal pipe	13	No	No	N/A	N/A	No	
772	5010	1	0			Service Closet adjacent to Elevator	W1	Chipping door and frame	4	No	No	N/A	N/A	No	
773	5010	1	0			Staff Lounge outside Staff Restroom across from Elevator	Floor	Chipping	5	No	No	N/A	N/A	No	
774	5010	1	0			Staff Lounge outside Staff Restroom across from Elevator	W1	Chipping, chipping door and frame	15	No	No	N/A	N/A	No	
775	5010	1	0			Staff Lounge outside Staff Restroom across from Elevator	W2	Cracking, flaking	17	No	No	N/A	N/A	No	
776	5010	1	0			Staff Lounge outside Staff Restroom across from Elevator	W4	Flaking	50	No	No	N/A	N/A	No	
777	5010	1	0			Stage	Ceiling	Chipping	50	No	No	N/A	N/A	No	
778	5010	1	0			Stage	W1	Chipping, holes, flaking	73	No	No	N/A	N/A	Yes	
779	5010	1	0			Stage	W2	Chipping, holes, flaking	81	No	No	N/A	N/A	Yes	
780	5010	1	0			Stage	W3	Chipping, flaking	100	No	No	N/A	N/A	No	
781	5010	1	0			Stage	W4	Chipping, flaking	75	No	No	N/A	N/A	No	
782	5010	1	0			Stairwell across from Elevator	Ceiling	Flaking	10	No	No	N/A	N/A	No	
783	5010	1	0			Stairwell across from Elevator	W1	Cracking, gouges	6	No	No	N/A	N/A	Yes	
784	5010	1	0			Stairwell across from Elevator	W2	Cracking	2	No	No	N/A	N/A	No	
785	5010	1	0			Stairwell across from Elevator	W3	Cracking, chipping, chipping doors and frame	17	No	No	N/A	N/A	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
786	5010	1	0			Stairwell across from Elevator	W4	Chipping doors and frame, holes	32	No	No	N/A	N/A	Yes	
787	5010	1	0			Stairwell across from Elevator Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
788	5010	1	0			Stairwell across from Elevator Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
789	5010	1	0			Stairwell across from Elevator Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
790	5010	1	0			Stairwell across from Elevator Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
791	5010	1	0			Stairwell across from Elevator Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
792	5010	1	0			Stairwell across from Elevator Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
793	5010	1	0			Stairwell across from Elevator Vestibule	Ceiling	Flaking, significant moisture damage	18	Yes	No	N/A	N/A	Yes	
794	5010	1	0			Stairwell across from Elevator Vestibule	Floor	Debris	N/A	No	Yes	5	N/A	No	
795	5010	1	0			Stairwell across from Elevator Vestibule	W1	Chipping vent cover	1	No	No	N/A	N/A	No	
796	5010	1	0			Stairwell across from Elevator Vestibule	W2	Chipping doors and frame	19	No	No	N/A	N/A	No	
797	5010	1	0			Stairwell across from Elevator Vestibule	W3	Chipping vent cover	1	No	No	N/A	N/A	No	
798	5010	1	0			Stairwell across from Elevator Vestibule	W4	Chipping doors and frame	14	No	No	N/A	N/A	No	
799	5010	1	0			Stairwell across from the Boy's and Girl's Restrooms	Ceiling	Cracking, chipping, flaking	21	No	No	N/A	N/A	No	
800	5010	1	0			Stairwell across from the Boy's and Girl's Restrooms	Floor	Chipping stair face, chipping railings	40	No	No	N/A	N/A	No	
801	5010	1	0			Stairwell across from the Boy's and Girl's Restrooms	W1	Cracking, chipping, holes	35	No	No	N/A	N/A	Yes	
802	5010	1	0			Stairwell across from the Boy's and Girl's Restrooms	W2	Flaking	2	No	No	N/A	N/A	No	
803	5010	1	0			Stairwell across from the Boy's and Girl's Restrooms	W3	Cracking, chipping	10	No	No	N/A	N/A	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
804	5010	1	0			Stairwell across from the Boy's and Girl's Restrooms	W4	Chipping, chipping doors, holes	7	No	No	N/A	N/A	Yes	
805	5010	1	0			Stairwell across from the Boy's and Girl's Restrooms Custodial Closet	Ceiling	Cracking, chipping, flaking	75	No	No	N/A	N/A	No	
806	5010	1	0			Stairwell across from the Boy's and Girl's Restrooms Custodial Closet	W1	Chipping doors	6	No	No	N/A	N/A	No	
807	5010	1	0			Stairwell across from the Boy's and Girl's Restrooms Vestibule	W1	Cracking	4	No	No	N/A	N/A	No	
808	5010	1	0			Stairwell across from the Boy's and Girl's Restrooms Vestibule	W2	Chipping doors, holes	11	No	No	N/A	N/A	Yes	
809	5010	1	0			Stairwell across from the Boy's and Girl's Restrooms Vestibule	W3	Cracking, flaking	7	No	No	N/A	N/A	No	
810	5010	1	0			Stairwell across from the Boy's and Girl's Restrooms Vestibule	W4	Cracking, flaking, chipping doors	12	No	No	N/A	N/A	No	
811	5010	1	0			Stairwell adjacent to Classroom 5	Ceiling	chipping	1	No	No	N/A	N/A	No	
812	5010	1	0			Stairwell adjacent to Classroom 5	Floor	chipping rail, chipping stair	9	No	No	N/A	N/A	No	
813	5010	1	0			Stairwell adjacent to Classroom 5	W1	chipping door and frame, flaking, duct	12	No	No	N/A	N/A	No	
814	5010	1	0			Stairwell adjacent to Classroom 5	W2	cracking, chipping, flaking	12	No	No	N/A	N/A	No	
815	5010	1	0			Stairwell adjacent to Classroom 5	W3	cracking, flaking, chipping door and frame	22	No	No	N/A	N/A	No	
816	5010	1	0			Stairwell adjacent to Classroom 5	W4	cracking	10	No	No	N/A	N/A	No	
817	5010	1	0			Stairwell adjacent to Classroom 5 Vestibule	Ceiling	chipping, flaking	2	No	No	N/A	N/A	No	
818	5010	1	0			Stairwell adjacent to Classroom 5 Vestibule	W2	cracking, chipping door and frame	8	No	No	N/A	N/A	No	
819	5010	1	0			Stairwell adjacent to Classroom 5 Vestibule	W3	cracking, chipping door and frame	8	No	No	N/A	N/A	No	
820	5010	1	0			Stairwell adjacent to Classroom 5 Vestibule	W4	cracking	4	No	No	N/A	N/A	No	
821	5010	1	0			Stairwell to Right of Stage	Ceiling	Flaking	16	No	No	N/A	N/A	No	

Kensington HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
822	5010	1	0			Stairwell to Right of Stage	W1	Chipping door and frame, chipping, holes, flaking	47	No	No	N/A	N/A	Yes	
823	5010	1	0			Stairwell to Right of Stage	W2	Chipping	8	No	No	N/A	N/A	No	
824	5010	1	0			Stairwell to Right of Stage	W3	Chipping, holes, flaking	24	No	No	N/A	N/A	Yes	
825	5010	1	0			Stairwell to Right of Stage	W4	Cracking, chipping door and frame, chipping, holes, flaking	40	No	No	N/A	N/A	Yes	
826	5010	1	0			Stairwell to Right of Stage Closet	Ceiling	Holes, flaking	7	No	No	N/A	N/A	Yes	
827	5010	1	0			Stairwell to Right of Stage Closet	Floor	Chipping railings	30	No	No	N/A	N/A	No	
828	5010	1	0			Stairwell to Right of Stage Closet	W1	Cracking, chipping door and frame, chipping, holes, flaking	12	No	No	N/A	N/A	Yes	
829	5010	1	0			Stairwell to Right of Stage Closet	W2	Cracking, chipping door and frame, chipping radiators, chipping, holes, flaking	22	No	No	N/A	N/A	Yes	
830	5010	1	0			Stairwell to Right of Stage Closet	W3	Cracking, chipping, holes flaking	20	No	No	N/A	N/A	Yes	
831	5010	1	0			Stairwell to Right of Stage Closet	W4	Chipping, chipping door and frame, flaking	14	No	No	N/A	N/A	No	
832	5010	1	0			Student Store under the stairs in front of the Auditorium	Ceiling	Chipping	1	No	No	N/A	N/A	No	
833	5010	1	0			Student Store under the stairs in front of the Auditorium	W1	Chipping, chipping door frame	3	No	No	N/A	N/A	No	
834	5010	1	0			Student Store under the stairs in front of the Auditorium	W2	Chipping	5	No	No	N/A	N/A	No	
835	5010	1	0			West Stairs at the Gas Shut Off Room	Ceiling	cracking, chipping, holes, flaking, significant moisture damage	140	Yes	No	N/A	N/A	Yes	
836	5010	1	0			West Stairs at the Gas Shut Off Room	Floor	Debris	N/A	No	Yes	80	N/A	No	