

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	2640	1	A	S46	Stairs	Stairs	Ceiling	Flaking	6	Y	N	0	N	Y - 6 SF	
2	2640	1	A	S46	Stairs	Stairs	Center Banister	Chipping	20	N	N	0	N	N	
3	2640	1	A	S46	Stairs	Stairs	W1	Inaccessible	0	N	N	0	N	N	Stairwell fenced in; All other walls visible from outside the gate
4	2640	1	A	S46	Stairs	Stairs	W2	Flaking	42	N	N	0	N	N	
5	2640	1	A	S46	Stairs	Stairs	W3	Cracking	80	N	N	0	N	N	
6	2640	1	A	S46	Stairs	Stairs	W4	Cracking	40	N	N	0	N	N	
7	2640	1	3	320	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Flaking	144	Y	N	0	N	Y - 6 SF	Additional Efflorescence
8	2640	1	3	320	Student Restrooms - Male (4-12)	Boy's Restroom	W1	Flaking	60	N	N	0	N	N	
9	2640	1	3	320	Student Restrooms - Male (4-12)	Boy's Restroom	W2	Flaking	125	N	N	0	N	N	Additional Cracking
10	2640	1	3	320	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Flaking	18	N	N	0	N	N	Additional Cracking
11	2640	1	3	301	Administrative Office	Classroom 301	W1	Flaking	28	N	N	0	Y - 46 SF Shelves, Contents	N	Additional Chipping; Damage in Closet
12	2640	1	3	301	Primary	Classroom 301	W3	Flaking	26	N	N	0	N	N	Additional Cracking, Chipping; Damage on Window Sill
13	2640	1	3	302	Primary	Classroom 302	Ceiling	Flaking	12	Y	N	0	N	N	Additional Efflorescence; Damage @ Window Lintels; Suspended Ceiling
14	2640	1	3	302	Primary	Classroom 302	W1	Flaking	32	N	N	0	Y - 96 SF Lockers	N	3 Locations; Additional Cracking, Chipping
15	2640	1	3	302	Primary	Classroom 302	W2	Flaking	20	N	N	0	y - 16 SF Posters	N	Additional Chipping
16	2640	1	3	302	Primary	Classroom 302	W3	Flaking	20	Y	N	0	N	Y - 1 SF	3 Locations; Additional Efflorescence, Chipping; Damage Includes Wall & Radiator Grates
17	2640	1	3	302	Primary	Classroom 302	W4	Flaking	8	N	N	0	Y - 28 SF Desks, Posters	N	2 Locations; Additional Chipping
18	2640	1	3	303	Primary	Classroom 303	W1	Flaking	48	N	N	0	Y - 110 SF Lockers, Posters	N	2 Locations; Additional Cracking, Chipping; Damage on Wall & Closet
19	2640	1	3	303	Primary	Classroom 303	W2	Flaking	60	Y	N	0	N	Y - 5 SF	Additional Efflorescence, Cracking, Chipping
20	2640	1	3	303	Primary	Classroom 303	W3	Flaking	64	Y	Y - @ Windows 1, 4	4	N	Y - 8 SF	Additional Efflorescence, Cracking, Chipping
21	2640	1	3	303	Primary	Classroom 303	W4	Flaking	16	Y	N	0	Y - 20 SF Bookcases, Posters	Y - 6 SF	Additional Efflorescence, Chipping
22	2640	1	3	304	Primary	Classroom 304	Ceiling	Flaking	16	Y	N	0	N	Y - 6 SF	Additional Efflorescence
23	2640	1	3	304	Primary	Classroom 304	W1	Flaking	20	N	N	0	Y - 96 SF Lockers	N	3 Locations; Additional Cracking, Chipping

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
24	2640	1	3	304	Primary	Classroom 304	W2	Flaking	24	N	N	0	Y - 16 SF Bookcases	N	
25	2640	1	3	304	Primary	Classroom 304	W3	Flaking	42	Y	N	0	N	Y - 4 SF	6 Locations; Additional Efflorescence, Cracking; Damage @ Radiator Grates, Wall
26	2640	1	3	305	Primary	Classroom 305	Ceiling	Flaking	16	N	N	0	N	N	Suspended Ceiling
27	2640	1	3	305	Primary	Classroom 305	W1	Flaking	8	N	N	0	Y - 96 SF Lockers	N	2 Locations; Additional Holes
28	2640	1	3	305	Primary	Classroom 305	W3	Flaking	30	Y	N	0	N	Y - 16 SF	4 Locations; Additional Efflorescence
29	2640	1	3	306	Primary	Classroom 306	W1	Flaking	90	N	N	0	Y - 160 SF Lockers, Contents	N	Additional Cracking, Chipping
30	2640	1	3	306	Primary	Classroom 306	W2	Flaking	120	N	N	0	Y - 48 SF Bookcases, Contents	N	Additional Cracking
31	2640	1	3	306	Primary	Classroom 306	W3	Flaking	68	N	N	0	Y - 48 SF Posters, Contents	N	Additional Cracking
32	2640	1	3	306	Primary	Classroom 306	W4	Chipping	2	N	N	0	Y - 40 SF Cabinets	N	
33	2640	1	3	307	Primary	Classroom 307	Ceiling	Flaking	12	Y	N	0	N	Y - 2 SF	Additional Efflorescence; Plastering Needed @ Window Lintel 3; Suspended Ceiling
34	2640	1	3	307	Primary	Classroom 307	W1	Flaking	240	N	N	0	Y - 70 SF Cabinets, Shelves	N	Additional Cracking
35	2640	1	3	307	Primary	Classroom 307	W3	Flaking	18	N	N	0	Y - 40 SF Posters, Contents	N	2 Locations; Additional Cracking
36	2640	1	3	307	Primary	Classroom 307	W4	Flaking	25	N	N	0	N	N	
37	2640	1	3	308	Primary	Classroom 308	W1	Flaking	10	N	N	0	N	N	
38	2640	1	3	308	Primary	Classroom 308	W2	Flaking	60	N	N	0	Y - 96 SF Lockers	N	3 Locations; Additional Cracking
39	2640	1	3	308	Primary	Classroom 308	W3	Flaking	24	N	N	0	N	N	Additional Cracking
40	2640	1	3	308	Primary	Classroom 308	W4	Flaking	3	N	N	0	N	N	Additional Cracking
41	2640	1	3	309	Primary	Classroom 309	Ceiling	Cracking	2	N	N	0	N	N	
42	2640	1	3	309	Primary	Classroom 309	W1	Flaking	80	N	N	0	Y - 96 SF Lockers	N	Flaking @ Wall & Closet Wall/Ceiling
43	2640	1	3	309	Primary	Classroom 309	W3	Cracking	8	N	N	0	N	N	2 Locations
44	2640	1	3	309	Primary	Classroom 309	W4	Flaking	36	N	N	0	Y - 84 SF Bookcases, Posters	N	
45	2640	1	3	310	Primary	Classroom 310	Ceiling	Flaking	20	N	N	0	N	N	Flaking @ Window Lintels; Suspended Ceiling
46	2640	1	3	310	Primary	Classroom 310	W1	Flaking	60	N	N	0	Y - 80 SF Posters, Contents	N	Additional Cracking; Flaking @ Wall & Closet Wall/Ceiling
47	2640	1	3	310	Primary	Classroom 310	W2	Partially Inaccessible	0	N	N	0	Y - 32 SF Posters	N	
48	2640	1	3	310	Primary	Classroom 310	W3	Cracking	28	N	N	0	N	N	3 Locations; Additional Chipping

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
49	2640	1	3	310	Primary	Classroom 310	W4	Partially Inaccessible	0	N	N	0	Y - 32 SF Posters	N	
50	2640	1	3	311	Primary	Classroom 311	Ceiling	Flaking	7	N	N	0	N	N	2 Locations; Flaking @ Window Lintels 1-3
51	2640	1	3	311	Primary	Classroom 311	W1	Flaking	65	N	N	0	Y - 96 SF Lockers, Posters	N	2 Locations; Flaking @ Wall & Closet Wall/Ceiling
52	2640	1	3	311	Primary	Classroom 311	W3	Flaking	4	N	N	0	Y - 36 SF Bookcases	N	Additional Cracking
53	2640	1	3	311	Primary	Classroom 311	W4	Partially Inaccessible	0	N	N	0	Y - 36 SF Desks, Posters	N	
54	2640	1	3	312	Primary	Classroom 312	W1	Partially Inaccessible	0	N	N	0	Y - 110 SF Lockers, Posters	N	
55	2640	1	3	312	Primary	Classroom 312	W2	Partially Inaccessible	0	N	N	0	Y - 40 SF Posters	N	
56	2640	1	3	312	Primary	Classroom 312	W3	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks, Posters	N	
57	2640	1	3	312	Primary	Classroom 312	W4	Partially Inaccessible	0	N	N	0	Y - 60 SF Bookcases, Desks, Posters	N	
58	2640	1	3	313	Primary	Classroom 313	W1	Flaking	66	N	N	0	Y - 106 SF Lockers, Posters	N	2 Locations; Additional Chipping; Damage @ Entrance & Closet
59	2640	1	3	313	Primary	Classroom 313	W2	Flaking	4	N	N	0	N	Y - > 1 SF	Additional Cracking
60	2640	1	3	313	Primary	Classroom 313	W3	Chipping	16	N	N	0	Y - 28 SF Posters	N	
61	2640	1	3	314	Primary	Classroom 314	W1	Partially Inaccessible	0	N	N	0	Y - 60 SF Bookcases, Contents	N	
62	2640	1	3	314	Primary	Classroom 314	W2	Chipping	20	N	N	0	N	N	Chipping on Window Sill
63	2640	1	3	314	Primary	Classroom 314	W3	Partially Inaccessible	0	N	N	0	Y - 90 SF Bookcases, Contents, Posters	N	
64	2640	1	3	314	Primary	Classroom 314	W4	Flaking	70	N	N	0	N	N	
65	2640	1	3	315	Primary	Classroom 315	Ceiling	Flaking	16	N	N	0	N	N	Flaking @ Window Lintel 1
66	2640	1	3	315	Primary	Classroom 315	W1	Flaking	32	N	N	0	N	N	2 Locations; Additional Cracking
67	2640	1	3	315	Primary	Classroom 315	W2	Flaking	48	Y	Y - On Contents	24	Y - 42 SF Posters	Y - 48 SF	Additional Efflorescence, Cracking
68	2640	1	3	315	Primary	Classroom 315	W3	Flaking	58	Y	N	0	N	Y - 32 SF	3 Locations; Additional Efflorescence, Cracking
69	2640	1	3	315	Primary	Classroom 315	W4	Partially Inaccessible	0	N	N	0	Y - 36 SF Desks, Tables	N	
70	2640	1	3	316	Primary	Classroom 316	Ceiling	Flaking	16	N	N	0	N	N	Additional Cracking; Damage @ Window Lintels

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
71	2640	1	3	316	Primary	Classroom 316	W1	Flaking	92	N	N	0	Y - 96 SF Lockers	Y - 1 SF	3 Locations; Additional Cracking, Chipping, Holes; Plastering Needed @ Entrance; Flaking in Closet Wall & Ceiling
72	2640	1	3	316	Primary	Classroom 316	W2	Cracking	4	N	N	0	N	N	
73	2640	1	3	316	Primary	Classroom 316	W3	Chipping	10	N	N	0	Y - 48 SF Desks	N	
74	2640	1	3	316	Primary	Classroom 316	W4	Flaking	1	N	N	0	Y - 20 SF Desks	N	Additional Chipping
75	2640	1	3	315A	Storage	Closet 315A	Ceiling	Flaking	40	N	N	0	N	N	2 Locations; Additional Cracking; Damage 2 Window Lintel
76	2640	1	3	315A		Closet 315A	W1	Chipping	3	N	N	0	N	N	
77	2640	1	3	315A	Storage	Closet 315A	W2	Flaking	12	N	N	0	N	N	
78	2640	1	3	315A	Storage	Closet 315A	W3	Flaking	5	N	N	0	N	N	2 Locations; Additional Cracking; Damage Including Radiator Grate
79	2640	1	3	315A	Storage	Closet 315A	W4	Flaking	6	N	N	0	N	N	
80	2640	1	3	315B	Storage	Closet 315B	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
81	2640	1	3	315B	Storage	Closet 315B	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
82	2640	1	3	315B	Storage	Closet 315B	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
83	2640	1	3	315B	Storage	Closet 315B	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
84	2640	1	3	315B	Storage	Closet 315B	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
85	2640	1	3	315B	Storage	Closet 315B	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
86	2640	1	3	3C	Storage	Closet adjacent to Classroom 304	Ceiling	Efflorescence	16	Y	N	0	N	Y - 16 SF	
87	2640	1	3	3C	Storage	Closet adjacent to Classroom 304	W2	Flaking	2	N	N	0	Y - 30 SF Contents	N	
88	2640	1	3	3C	Storage	Closet adjacent to Classroom 304	W3	Flaking	18	Y	N	0	Y - 24 SF Contents	Y - 18 SF	Additional Efflorescence; Damage on/under Window Frame
89	2640	1	3	3C	Storage	Closet adjacent to Classroom 304	W4	Flaking	2	Y	Y - On Contents	4	Y - 40 SF Contents	Y - 1 SF	2 Locations; Additional Efflorescence
90	2640	1	3	314A	Circulation (Hallway)	Custodial Closet Outside 314	W3	Flaking	56	N	N	0	N	Y - 1 SF	Additional Cracking
91	2640	1	3	314A	Circulation (Hallway)	Custodial Closet Outside 314	W4	Flaking	18	N	N	0	N	N	Additional Cracking
92	2640	1	3	S02-3	Stairs	Fire Tower adjacent to Hallway from Classrooms 208 to 314	Ceiling	Flaking	75	N	N	0	N	N	
93	2640	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 300 to 304	W1	Flaking	56	N	N	0	N	N	7 Locations; Additional Cracking, Chipping, Holes
94	2640	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 300 to 304	W3	Cracking	30	N	N	0	N	N	4 Locations; Additional Chipping
95	2640	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 308 to 314	W1	Chipping	2	N	N	0	N	N	

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
96	2640	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 308 to 314	W2	Flaking	364	N	N	0	N	N	6 Locations; Additional Cracking, Holes
97	2640	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 308 to 314	W3	Flaking	4	N	N	0	N	N	Additional Chipping
98	2640	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 308 to 314	W4	Flaking	156	N	N	0	N	N	Additional Cracking, Chipping
99	2640	1	3	H310	Hallway	Hallway from Classrooms 315 to 316	W1	Chipping	4	N	N	0	N	N	
100	2640	1	3	H310		Hallway from Classrooms 315 to 316	W3	Chipping	0	N	N	0	N	N	
101	2640	1	3	400	Primary	Meeting Room	Ceiling	Flaking	24	N	N	0	N	N	
102	2640	1	3	400	Primary	Meeting Room	W1	Flaking	16	N	N	0	N	N	
103	2640	1	3	400	Primary	Meeting Room	W2	Flaking	96	N	N	0	N	N	
104	2640	1	3	400	Primary	Meeting Room	W3	Flaking	80	N	N	0	N	N	
105	2640	1	3	400	Primary	Meeting Room	W4	Flaking	240	N	N	0	N	N	
106	2640	1	3	3E	Restrooms, Staff - Male	Men's Restroom	W2	Flaking	1	N	N	0	N	N	
107	2640	1	3	300	Administrative Office	Office 300	W2	Partially Inaccessible	0	N	N	0	Y - 116 SF Desks, Posters	N	
108	2640	1	3	300	Administrative Office	Office 300	W3	Chipping	4	N	N	0	N	N	
109	2640	1	3	300	Administrative Office	Office 300	W4	Cracking	6	N	N	0	Y - 84 SF Shelves	N	2 Locations; Additional Chipping
110	2640	1	3	308A	Administrative Office	Office 308A	Ceiling	Cracking	4	N	N	0	N	N	
111	2640	1	3	308A	Administrative Office	Office 308A	W1	Flaking	33	N	N	0	N	N	Additional Cracking
112	2640	1	3	308A	Administrative Office	Office 308A	W2	Flaking	98	N	N	0	N	N	Additional Cracking
113	2640	1	3	308A	Administrative Office	Office 308A	W3	Cracking	8	N	N	0	N	N	
114	2640	1	3	308A	Administrative Office	Office 308A	W4	Cracking	6	N	N	0	N	N	
115	2640	1	3	314A	Administrative Office	Office 314A	Ceiling	Cracking	8	N	N	0	N	N	
116	2640	1	3	314A	Administrative Office	Office 314A	W1	Flaking	35	N	N	0	N	N	Additional Cracking, Chipping
117	2640	1	3	314A	Administrative Office	Office 314A	W2	Flaking	72	N	N	0	Y - 28 Posters	N	Additional Cracking
118	2640	1	3	314A	Administrative Office	Office 314A	W3	Flaking	56	Y	N	0	N	Y - 3 SF	Additional Efflorescence, Spalling, Cracking
119	2640	1	3	314A	Administrative Office	Office 314A	W4	Flaking	86	N	N	0	N	N	Additional Cracking, Chipping
120	2640	1	3	401	Stairs	Stairwell adjacent to Classroom 303	Center Banister	Chipping	20	N	N	0	N	N	
121	2640	1	3	401	Stairs	Stairwell adjacent to Classroom 303	W1	Flaking	24	N	N	0	N	N	

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
122	2640	1	3	401	Stairs	Stairwell adjacent to Classroom 303	W2	Flaking	80	N	N	0	N	N	
123	2640	1	3	401	Stairs	Stairwell adjacent to Classroom 303	W4	Flaking	200	N	N	0	N	N	
124	2640	1	3	S03-3	Stairs	Stairwell adjacent to Classroom 308	Ceiling	Flaking	108	Y	N	0	N	Y - 12 SF	Additional Efflorescence, Cracking
125	2640	1	3	S03-3	Stairs	Stairwell adjacent to Classroom 308	Center Banister	Chipping	10	N	N	0	N	N	
126	2640	1	3	S03-3	Stairs	Stairwell adjacent to Classroom 308	Floor	Chipping	36	N	N	0	N	N	
127	2640	1	3	S03-3	Stairs	Stairwell adjacent to Classroom 308	W1	Flaking	6	Y	N	0	N	Y - 4 SF	2 Locations; Additional Efflorescence
128	2640	1	3	S03-3	Stairs	Stairwell adjacent to Classroom 308	W2	Flaking	140	Y	N	0	N	Y - 6 SF	Additional Efflorescence, Cracking
129	2640	1	3	S03-3	Stairs	Stairwell adjacent to Classroom 308	W3	Flaking	28	Y	N	0	N	Y - 12 SF	Additional Efflorescence, Cracking
130	2640	1	3	S03-3	Stairs	Stairwell adjacent to Classroom 308	W4	Flaking	80	Y	N	0	N	Y - 12 SF	Additional Efflorescence, Cracking
131	2640	1	3	S01	Stairs	Stairwell adjacent to Classroom 314	Ceiling	Flaking	36	Y	N	0	N	Y - 36 SF	Additional Efflorescence
132	2640	1	3	S01		Stairwell adjacent to Classroom 314	Center Banister	Chipping	20	N	N	0	N	N	
133	2640	1	3	S01	Stairs	Stairwell adjacent to Classroom 314	W1	Cracking	24	N	N	0	N	N	
134	2640	1	3	S01	Stairs	Stairwell adjacent to Classroom 314	W2	Flaking	20	Y	N	0	N	Y - 20 SF	Additional Efflorescence
135	2640	1	3	S01	Stairs	Stairwell adjacent to Classroom 314	W3	Flaking	80	Y	Y - @ Baseboard	5	N	Y - 4 SF	Additional Efflorescence
136	2640	1	3	S01	Stairs	Stairwell adjacent to Classroom 314	W4	Flaking	80	Y	Y - @ Baseboard	6	N	Y - 80 SF	Additional Efflorescence
137	2640	1	3	3B	Restrooms, Staff - Female	Women's Restroom	W1	Flaking	1	N	N	0	N	N	
138	2640	1	3	3B	Restrooms, Staff - Female	Women's Restroom	W2	Flaking	4	N	N	0	N	N	2 Locations
139	2640	1	3	3B	Restrooms, Staff - Female	Women's Restroom	W4	Flaking	16	Y	N	0	N	Y - 12 SF	Additional Efflorescence, Cracking
140	2640	1	2	200	Primary	Classroom 200	Ceiling	Chipping	1	N	N	0	N	N	
141	2640	1	2	200	Primary	Classroom 200	W1	Flaking	3	N	N	0	Y - 20 SF Tables, Cabinets, Desks	N	2 Locations; Additional Cracking, Chipping
142	2640	1	2	200	Primary	Classroom 200	W3	Flaking	7	Y	N	0	Y - 32 SF Desks, Posters, Carts	N	2 Locations; Additional Cracking, Chipping
143	2640	1	2	200	Primary	Classroom 200	W4	Flaking	3	N	N	0	N	N	3 Locations; Additional Chipping
144	2640	1	2	201	Primary	Classroom 201	W1	Flaking	62	N	N	0	Y - 144 SF Shelves	Y - 4 SF	5 Locations; Additional Cracking, Chipping, Holes
145	2640	1	2	201	Primary	Classroom 201	W2	Cracking	18	N	N	0	N	N	
146	2640	1	2	201	Primary	Classroom 201	W3	Flaking	12	N	N	0	Y - 48 SF Posters	N	12 Locations; Additional Cracking
147	2640	1	2	201	Primary	Classroom 201	W4	Cracking	24	N	N	0	Y - 40 SF Bookcases, Posters	N	2 Locations

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
148	2640	1	2	202	Primary	Classroom 202	Ceiling	Flaking	8	Y	N	0	N	Y - 8 SF	Additional Efflorescence; Suspended Ceiling
149	2640	1	2	202	Primary	Classroom 202	W1	Cracking	8	N	N	0	N	N	3 Locations; Additional Chipping
150	2640	1	2	202	Primary	Classroom 202	W2	Flaking	2	N	N	0	Y - 36 SF Bookcases, Cabinets	N	Additional Chipping
151	2640	1	2	202	Primary	Classroom 202	W3	Flaking	12	N	N	0	Y - 25 SF Bookcases, Cabinets	Y - 6 SF	3 Locations
152	2640	1	2	202	Primary	Classroom 202	W4	Cracking	6	N	N	0	N	N	Additional Chipping
153	2640	1	2	203	Primary	Classroom 203	Ceiling	Flaking	12	N	N	0	N	N	Additional Chipping; Damage @ Window Lintels
154	2640	1	2	203	Storage	Classroom 203	W1	Cracking	4	N	N	0	Y - 48 SF Lockers	N	Additional Chipping
155	2640	1	2	203	Storage	Classroom 203	W2	Chipping	1	N	N	0	Y - 53 SF Bookcases, Desks, Cabinets	N	
156	2640	1	2	203	Primary	Classroom 203	W3	Flaking	2	N	N	0	Y - 16 SF Cabinets	N	2 Locations; Additional Holes
157	2640	1	2	203	Primary	Classroom 203	W4	Partially Inaccessible	0	N	N	0	Y - 26 SF Bookcases, Contents	N	
158	2640	1	2	206	Primary	Classroom 206	Ceiling	Flaking	12	N	N	0	N	N	2 Locations; Additional Cracking
159	2640	1	2	206	Primary	Classroom 206	W1	Flaking	22	N	N	0	Y - 48 SF Lockers	N	3 Locations; Additional Cracking, Chipping
160	2640	1	2	206	Primary	Classroom 206	W2	Partially Inaccessible	0	N	N	0	Y - 32 SF Bookcases, Desks	N	
161	2640	1	2	206	Primary	Classroom 206	W3	Flaking	1	N	N	0	Y - 26 SF Cabinets, Posters	N	
162	2640	1	2	206	Primary	Classroom 206	W4	Chipping	4	N	N	0	Y - 18 SF Desks	N	
163	2640	1	2	207		Classroom 207	Ceiling	Cracking	2	N	N	0	N	N	Suspended Ceiling
164	2640	1	2	207	Primary	Classroom 207	W1	Flaking	80	N	N	0	Y - 60 SF Lockers, Contents	N	Additional Cracking
165	2640	1	2	207	Primary	Classroom 207	W2	Flaking	18	N	N	0	Y - 36 SF Contents	N	Additional Cracking; Damage Includes Forced Air Duct
166	2640	1	2	207	Primary	Classroom 207	W3	Flaking	4	N	N	0	Y - 56 SF Bookcases, Contents	N	
167	2640	1	2	207	Primary	Classroom 207	W4	Flaking	4	N	N	0	Y - 8 SF Bookcases	N	
168	2640	1	2	208	Primary	Classroom 208	W1	Cracking	4	N	N	0	Y - 16 SF Bulletin Board	N	Additional Chipping
169	2640	1	2	208	Primary	Classroom 208	W2	Flaking	96	N	N	0	Y - 120 SF Bookcases, Shelves, Contents	N	Additional Cracking

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
170	2640	1	2	208	Primary	Classroom 208	W3	Cracking	6	N	N	0	Y - 33 SF Cabinets, Desks, Posters	N	
171	2640	1	2	208	Primary	Classroom 208	W4	Cracking	4	N	N	0	N	N	
172	2640	1	2	209	Administrative Office	Classroom 209	W1	Flaking	50	N	N	0	N	N	Additional Cracking, Chipping
173	2640	1	2	209	Primary	Classroom 209	W3	Cracking	5	N	N	0	Y - 48 SF Bookcases, Desks, File Cabinets	N	2 Locations
174	2640	1	2	209	Primary	Classroom 209	W4	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks, Tables, Cabinets, Posters	N	
175	2640	1	2	210	Primary	Classroom 210	W1	Flaking	82	N	Y - On Closet Shelves	4	Y - 90 SF Lockers	N	Additional Cracking; Damage Includes Closet Walls & Ceiling
176	2640	1	2	210	Primary	Classroom 210	W3	Flaking	12	N	N	0	N	N	2 Locations; Additional Cracking, Chipping
177	2640	1	2	211	Primary	Classroom 211	W1	Flaking	24	N	N	0	Y - 72 SF Contents, Posters	N	Additional Cracking
178	2640	1	2	211	Primary	Classroom 211	W3	Cracking	2	N	N	0	Y - 48 SF Bookcases, Contents	N	Additional Holes
179	2640	1	2	212	Primary	Classroom 212	W1	Flaking	36	N	N	0	Y - 64 SF Cabinets	N	Additional Cracking, Chipping
180	2640	1	2	212	Primary	Classroom 212	W3	Flaking	4	N	N	0	Y - 14 SF Posters	Y - 14 SF	4 Locations; Additional Holes, Gouges
181	2640	1	2	213	Stairs	Classroom 213	W1	Flaking	24	N	N	0	Y - 72 SF Contents, Posters	N	Additional Cracking; Damage Includes Closet
182	2640	1	2	213	Stairs	Classroom 213	W2	Cracking	5	N	N	0	Y - 60 SF Bookcases, Posters	N	
183	2640	1	2	213	Primary	Classroom 213	W3	Cracking	36	N	N	0	N	N	
184	2640	1	2		Primary	Classroom 214	W1	Flaking	24	N	N	0	Y - 32 SF Posters	N	2 Locations; Additional Cracking
185	2640	1	2		Primary	Classroom 214	W2	Flaking	12	N	N	0	Y - 50 SF Cabinets, Boxes, Contents	N	2 Locations; Additional Cracking
186	2640	1	2	214	Primary	Classroom 214	W3	Flaking	26	N	N	0	Y - 48 SF Contents, Posters	N	
187	2640	1	2	214	Primary	Classroom 214	W4	Flaking	72	N	N	0	N	N	Additional Cracking; Damage Includes Forced Air Duct
188	2640	1	2	215	Primary	Classroom 215	Ceiling	Flaking	4	N	N	0	N	N	2 Locations; Additional Chipping; Damage @ Window Lintels 1, 4; Suspended Ceiling

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
189	2640	1	2	215	Circulation (Hallway)	Classroom 215	W1	Flaking	4	N	N	0	Y - 125 SF Contents	N	
190	2640	1	2	215	Primary	Classroom 215	W2	Partially Inaccessible	0	N	N	0	Y - 48 Sf Bookcases, File Cabinets	N	
191	2640	1	2	215		Classroom 215	W3	Cracking	6	N	N	0	Y - 36 SF Desks, Tables	N	
192	2640	1	2	216	Primary	Classroom 216	Ceiling	Flaking	6	N	N	0	N	N	Additional Chipping; Damage @ Window Lintel 2; Suspended Ceiling
193	2640	1	2	216	Primary	Classroom 216	W1	Flaking	80	N	N	0	Y - 125 SF File Cabinets, Cabinets, Contents	N	Additional Cracking; Damage in Closet Walls, Ceiling
194	2640	1	2	216	Primary	Classroom 216	W2	Flaking	18	N	N	0	Y - 25 SF Posters	N	3 Locations; Additional Cracking
195	2640	1	2	216	Primary	Classroom 216	W3	Flaking	48	N	N	0	N	N	Additional Cracking; Damage @ Bottom of Wall
196	2640	1	2	216	Primary	Classroom 216	W4	Flaking	16	N	N	0	N	N	Additional Cracking
197	2640	1	2	2C	Storage	Closet adjacent to Classroom 214	Ceiling	Flaking	9	N	N	0	N	N	2 Locations; Additional Chipping
198	2640	1	2	2C	Storage	Closet adjacent to Classroom 214	W1	Flaking	4	N	N	0	Y - 4 SF File Cabinet	N	Additional Chipping
199	2640	1	2	2C	Storage	Closet adjacent to Classroom 214	W2	Flaking	4	N	N	0	Y - 80 SF Posters	N	Additional Chipping
200	2640	1	2	2C	Storage	Closet adjacent to Classroom 214	W3	Flaking	4	N	N	0	Y - 16 SF Bookcases	N	Additional Chipping; Damage Includes Window Frame & Wall
201	2640	1	2	2C	Storage	Closet adjacent to Classroom 214	W4	Flaking	10	N	N	0	Y - 36 SF Desks	N	3 Locations; Additional Chipping
202	2640	1	2	2D	Storage	Closet adjacent to Library	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
203	2640	1	2	2D	Storage	Closet adjacent to Library	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
204	2640	1	2	2D	IMC (Library)	Closet adjacent to Library	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
205	2640	1	2	2D	IMC (Library)	Closet adjacent to Library	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
206	2640	1	2	2D	Storage	Closet adjacent to Library	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
207	2640	1	2	2D	Storage	Closet adjacent to Library	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
208	2640	1	2	214A		Custodial Closet Outside 214	Ceiling	Cracking	4	N	N	0	N	N	
209	2640	1	2	S-02	Primary	Fire Tower adjacent Hallway from Classrooms 208 to 214	Ceiling	Flaking	120	N	N	0	N	N	
210	2640	1	2	214A		Hallway	W3	Flaking	36	N	N	0	N	N	Additional Cracking
211	2640	1	2	209A		Hallway	W3	Flaking	8	N	N	0	Y - 16 SF Shelves, Contents	N	Additional Cracking
212	2640	1	2	214A		Hallway	W4	Flaking	12	N	N	0	N	N	Additional Cracking

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
213	2640	1	2	H212	Stairs	Hallway from Classrooms 200 to 205	W1	Flaking	28	N	N	0	N	N	Additional Cracking, Chipping
214	2640	1	2	H212	Stairs	Hallway from Classrooms 200 to 205	W2	Flaking	4	N	N	0	N	N	
215	2640	1	2	H212	Circulation (Hallway)	Hallway from Classrooms 200 to 205	W3	Flaking	25	N	N	0	N	N	3 Locations; Additional Cracking, Chipping
216	2640	1	2	H211	Hallway	Hallway from Classrooms 208 to 214	W2	Flaking	54	N	N	0	N	N	4 Locations; Additional Cracking, Chipping
217	2640	1	2	H211	Circulation (Hallway)	Hallway from Classrooms 208 to 214	W4	Flaking	540	N	N	0	N	N	Entire Wall; Additional Cracking
218	2640	1	2	H210	Circulation (Hallway)	Hallway from Classrooms 215 to 216	Ceiling	Flaking	4	N	N	0	N	N	
219	2640	1	2	H210	Restrooms, Staff - Female	Hallway from Classrooms 215 to 216	W1	Flaking	6	N	N	0	N	N	
220	2640	1	2	H210	Hallway	Hallway from Classrooms 215 to 216	W2	Flaking	12	N	N	0	N	N	
221	2640	1	2	H210	Hallway	Hallway from Classrooms 215 to 216	W3	Flaking	18	N	N	0	N	N	
222	2640	1	2	205	Primary	Library	W1	Partially Inaccessible	0	N	N	0	Y - 160 SF Bookcases	N	
223	2640	1	2	205	Primary	Library	W2	Partially Inaccessible	0	N	N	0	Y - 22 SF Bookcases	N	
224	2640	1	2	205	IMC (Library)	Library	W3	Flaking	20	N	N	0	Y - 16 SF Bookcases	N	4 Locations
225	2640	1	2	205	IMC (Library)	Library	W4	Flaking	46	N	Y - On Conduit	6	Y - 48 SF Bookcases	Y - 24 SF	3 Locations; Additional Efflorescence, Spalling
226	2640	1	2	2E	Restrooms, Staff - Male	Men's Restroom	Ceiling	Cracking	18	N	N	0	N	0	
227	2640	1	2	S04-2	Stairs	Men's Restroom	W1	Flaking	66	N	N	0	N	0	
228	2640	1	2	S04-2	Stairs	Men's Restroom	W2	Flaking	83	Y	N	0	N	Y - 3 SF	Additional Efflorescence
229	2640	1	2	2E	Restrooms, Staff - Male	Men's Restroom	W3	Flaking	42	Y	N	0	N	Y - 2 SF	Additional Efflorescence
230	2640	1	2	2E	Restrooms, Staff - Male	Men's Restroom	W4	Cracking	13	N	N	0	N	0	
231	2640	1	2	2B	Administrative Office	Office 2B	Ceiling	Flaking	14	N	N	0	N	N	3 Locations; Additional Cracking
232	2640	1	2	2B		Office 2B	Floor	Chipping	8	N	N	0	N	N	Chipping @ Perimeter
233	2640	1	2	2B	Administrative Office	Office 2B	W1	Flaking	3	N	N	0	N	N	2 Locations
234	2640	1	2	2B	Administrative Office	Office 2B	W2	Flaking	20	N	N	0	N	Y - 3 SF	4 Locations; Additional Cracking, Chipping, Holes
235	2640	1	2	2B	Administrative Office	Office 2B	W3	Flaking	3	N	N	0	N	N	Additional Cracking
236	2640	1	2	2B	Administrative Office	Office 2B	W4	Flaking	16	N	N	0	N	Y - 4 SF	2 Locations; Additional Cracking

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
237	2640	1	2	S21	Stairs	Stairwell adjacent Classroom 214	Ceiling	Efflorescence	4	Y	N	0	N	Y - 4 SF	2 Locations
238	2640	1	2	S21	Stairs	Stairwell adjacent Classroom 214	Center Banister	Chipping	12	N	N	0	N	N	
239	2640	1	2	S21	Stairs	Stairwell adjacent Classroom 214	W2	Flaking	36	N	N	0	N	N	Additional Cracking, Chipping
240	2640	1	2	S21	Stairs	Stairwell adjacent Classroom 214	W3	Flaking	16	Y	Y - Below Ceiling Efflorescence	1	N	Y - 13 SF	Additional Efflorescence, Cracking; Damage Above & Below Windows
241	2640	1	2	S21	Stairs	Stairwell adjacent Classroom 214	W4	Flaking	10	N	N	0	N	N	3 Locations; Additional Cracking, Chipping
242	2640	1	2	S04-1	Restrooms, Staff - Male	Stairwell adjacent to Classroom 103	Ceiling	Efflorescence	30	Y	N	0	N	Y - 30 SF	
243	2640	1	2	S04-1	Restrooms, Staff - Male	Stairwell adjacent to Classroom 103	Center Banister	Chipping	8	N	N	0	N	N	
244	2640	1	2	S04-1	Restrooms, Staff - Male	Stairwell adjacent to Classroom 103	W1	Flaking	30	N	N	0	N	N	Additional Cracking, Chipping
245	2640	1	2	S04-1	Restrooms, Staff - Male	Stairwell adjacent to Classroom 103	W2	Flaking	80	N	N	0	N	N	Additional Cracking, Chipping
246	2640	1	2	S03-2	Stairs	Stairwell adjacent to Classroom 203	Ceiling	Flaking	14	Y	N	0	N	Y - 14 SF	Additional Efflorescence
247	2640	1	2	S04-2	Stairs	Stairwell adjacent to Classroom 203	Center Banister	Chipping	20	N	N	0	N	N	
248	2640	1	2	S03-2	Stairs	Stairwell adjacent to Classroom 203	W1	Flaking	9	N	N	0	N	N	Additional Cracking
249	2640	1	2	S03-2	Stairs	Stairwell adjacent to Classroom 203	W2	Flaking	26	N	N	0	N	N	Additional Cracking, Chipping
250	2640	1	2	S03-2	Stairs	Stairwell adjacent to Classroom 208	Ceiling	Efflorescence	6	Y	N	0	N	Y - 6 SF	
251	2640	1	2	S03-2	Stairs	Stairwell adjacent to Classroom 208	Center Banister	Chipping	18	N	N	0	N	N	
252	2640	1	2	S03-2	Stairs	Stairwell adjacent to Classroom 208	Floor	Chipping	4	N	N	0	N	N	
253	2640	1	2	S03-2	Circulation (Hallway)	Stairwell adjacent to Classroom 208	W1	Flaking	10	N	N	0	N	N	2 Locations; Additional Cracking
254	2640	1	2	S03-2	Circulation (Hallway)	Stairwell adjacent to Classroom 208	W2	Flaking	26	N	N	0	N	N	Additional Cracking, Holes
255	2640	1	2	S03-2	Stairs	Stairwell adjacent to Classroom 208	W3	Chipping	6	N	N	0	N	N	Additional Chipping
256	2640	1	2	S03-2	Stairs	Stairwell adjacent to Classroom 208	W4	Flaking	28	N	N	0	N	N	Additional Cracking
257	2640	1	2	217B	Teacher Lounge/Dining	Teacher's Kitchen	Ceiling	Flaking	8	N	N	0	N	N	2 Locations; Damage @ Window Lintels
258	2640	1	2	217B	Teacher Lounge/Dining	Teacher's Kitchen	W1	Flaking	14	Y	Y - On Trim	1	Y - 12 SF Vending Machine	Y - 2 SF	
259	2640	1	2	217B		Teacher's Kitchen	W2	Cracking	3	N	N	0	N	N	4 Locations; Additional Cracking, Holes
260	2640	1	2	217B		Teacher's Kitchen	W3	Flaking	14	N	N	0	Y - 18 SF Kitchen Appliances	N	
261	2640	1	2	217B	Teacher Lounge/Dining	Teacher's Kitchen	W4	Flaking	10	N	Y - Behind Pipe	1	N	Y - 3 SF	2 Locations; Additional Spalling, Cracking

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
262	2640	1	2	217	Teacher Lounge/Dining	Teacher's Lounge	Ceiling	Flaking	4	Y	N	0	N	Y - 4 SF	Additional Efflorescence; Damage @ Window Lintel; Suspended Ceiling
263	2640	1	2	217	Teacher Lounge/Dining	Teacher's Lounge	W1	Flaking	6	N	N	0	N	N	2 Locations; Additional Cracking
264	2640	1	2	217	Teacher Lounge/Dining	Teacher's Lounge	W2	Flaking	10	N	N	0	Y - 10 SF Tables	N	4 Locations; Additional Cracking
265	2640	1	2	217	Teacher Lounge/Dining	Teacher's Lounge	W3	Flaking	46	N	N	0	N	N	2 Locations; Additional Cracking, Chipping
266	2640	1	2	217	Teacher Lounge/Dining	Teacher's Lounge	W4	Flaking	36	N	Y - Under Ceiling Efflorescence	4	N	N	3 Locations
267	2640	1	2	218	Restrooms, Staff - Female	Women's Restroom	Ceiling	Flaking	15	N	N	0	N	N	3 Locations; Additional Cracking
268	2640	1	2	218	Teacher Lounge/Dining	Women's Restroom	W1	Flaking	8	N	N	0	N	N	Additional Cracking
269	2640	1	2	218		Women's Restroom	W2	Flaking	16	N	N	0	N	N	2 Locations; Additional Cracking
270	2640	1	2	218	Restrooms, Staff - Female	Women's Restroom	W3	Flaking	10	N	N	0	N	N	Additional Cracking
271	2640	1	2	218	Restrooms, Staff - Female	Women's Restroom	W4	Flaking	20	N	N	0	N	N	3 Locations; Additional Cracking
272	2640	1	1	110	Auditorium	Auditorium	Ceiling	Flaking	20	N	N	0	N	N	Flaking @ Window Lintels 1-5
273	2640	1	1	110	Administrative Office	Auditorium	W1	Flaking	76	N	N	0	Y - 240 SF Cabinets, Contents	N	Additional Cracking, Chipping
274	2640	1	1	110	Administrative Office	Auditorium	W3	Partially Inaccessible	0	N	N	0	Y - 48 SF Contents	N	
275	2640	1	1	110	Auditorium	Auditorium	W4	Flaking	10	N	N	0	N	N	3 Locations; Additional Cracking
276	2640	1	1	102	Primary	Classroom 102	Ceiling	Flaking	16	N	N	0	N	N	Additional Chipping; Damage @ Window Lintels; Suspended Ceiling
277	2640	1	1	102	Administrative Office	Classroom 102	W1	Partially Inaccessible	0	N	N	0	Y - 80 SF Contents, Posters	N	
278	2640	1	1	102	Administrative Office	Classroom 102	W2	Cracking	32	N	N	0	Y - 48 SF Bookcases, Desks, Contents	N	
279	2640	1	1	102	Administrative Office	Classroom 102	W3	Cracking	32	N	N	0	Y - 64 SF Desks, Contents	N	2 Locations
280	2640	1	1	102	Primary	Classroom 102	W4	Flaking	20	N	N	0	Y - 20 SF Posters	N	2 Locations; Additional Cracking
281	2640	1	1	103	Primary	Classroom 103	Ceiling	Flaking	12	N	N	0	N	N	3 Locations; Additional Cracking; Damage @ Window Lintels 1, 2, 4
282	2640	1	1	103	Primary	Classroom 103	Floor	Flaking	60	N	N	0	Y - 90 SF Bookcases, Desks	N	Flaking @ Perimeter
283	2640	1	1	103	Primary	Classroom 103	W1	Flaking	28	N	N	0	N	N	3 Locations; Additional Cracking
284	2640	1	1	103	Primary	Classroom 103	W2	Flaking	24	N	N	0	N	N	Additional Cracking

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
285	2640	1	1	103	Primary	Classroom 103	W3	Flaking	64	N	N	0	Y - 78 SF Bookcases, Posters	N	3 Locations; Additional Cracking
286	2640	1	1	103	Primary	Classroom 103	W4	Flaking	13	N	N	0	Y - 24 SF Posters	N	3 Locations; Additional
287	2640	1	1	107	Primary	Classroom 107	Floor	Chipping	10	N	N	0	N	N	
288	2640	1	1	107	Stairs	Classroom 107	W1	Flaking	16	N	N	0	Y - 90 SF Contents, Posters	N	3 Locations; Additional Cracking, Chipping; Damage Includes Forced Air Duct
289	2640	1	1	107	Stairs	Classroom 107	W2	Flaking	4	N	N	0	N	N	2 Locations; Additional Chipping
290	2640	1	1	107	Stairs	Classroom 107	W3	Chipping	24	N	N	0	Y - 48 SF Contents, Posters	N	
291	2640	1	1	107	Primary	Classroom 107	W4	Cracking	6	N	N	0	N	N	
292	2640	1	1	112	Auditorium	Classroom 112	Ceiling	Flaking	2	N	N	0	N	N	
293	2640	1	1	112	Auditorium	Classroom 112	W1	Flaking	24	N	N	0	Y - Y - 256 SF Contents	N	2 Locations; Additional Chipping; Coat Closet Partially Inaccessible
294	2640	1	1	112	Auditorium	Classroom 112	W3	Flaking	4	N	N	0	N	Y - 4 SF	Additional Cracking
295	2640	1	1	113	Primary	Classroom 113	Ceiling	Flaking	6	N	N	0	N	N	3 Locations; Additional Cracking
296	2640	1	1	113	Primary	Classroom 113	W1	Flaking	60	N	N	0	Y - 256 Contents	N	Additional Cracking, Chipping; Coat Closet Partially Inaccessible
297	2640	1	1	113	Primary	Classroom 113	W2	Flaking	5	N	N	0	Y - 48 SF Bookcases	Y - 1 SF	2 Locations; Additional Cracking, Holes
298	2640	1	1	113	Primary	Classroom 113	W3	Flaking	3	N	N	0	N	N	2 Locations; Additional Cracking
299	2640	1	1	114	Primary	Classroom 114	W1	Partially Inaccessible	0	N	N	0	Y - 48 SF Bookcases, Cabinets, Contents	N	
300	2640	1	1	114	Primary	Classroom 114	W2	Flaking	5	N	N	0	N	Y - 1 SF	3 Locations; Additional Cracking
301	2640	1	1	114	Primary	Classroom 114	W3	Flaking	32	N	N	0	N	N	Additional Chipping
302	2640	1	1	114	Primary	Classroom 114	W4	Flaking	120	N	N	0	Y - 120 SF Shelves, Contents	N	Additional Cracking
303	2640	1	1	115	Primary	Classroom 115	Ceiling	Flaking	4	N	N	0	N	N	Flaking @ Window Lintel 2
304	2640	1	1	115	Primary	Classroom 115	Floor	Flaking	0	N	N	0	N	N	
305	2640	1	1	115	Primary	Classroom 115	W1	Flaking	18	N	N	0	Y - 90 SF Contents, Posters	N	2 Locations; Additional Cracking; Damage Includes Forced Air Duct
306	2640	1	1	115	Primary	Classroom 115	W3	Flaking	3	N	N	0	Y - 36 SF Bookcases, Desks	N	2 Locations; Additional Cracking, Chipping
307	2640	1	1	116	Primary	Classroom 116	Ceiling	Flaking	4	N	N	0	N	N	2 Locations; Additional Cracking
308	2640	1	1	116	Primary	Classroom 116	W1	Flaking	40	N	N	0	Y - 76 SF Contents	N	Additional Cracking; Coat Closet Partially Inaccessible
309	2640	1	1	116	Primary	Classroom 116	W2	Chipping	6	N	N	0	N	N	
310	2640	1	1	116	Primary	Classroom 116	W3	Flaking	4	N	N	0	N	Y - 1 SF	Additional Cracking, Holes

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
311	2640	1	1	117	Student Restrooms - Male (4-12)	Classroom 117	W1	Flaking	14	N	N	0	N	N	Flaking @ Fiberglass Pipe Insulation & Door Frame
312	2640	1	1	117	Student Restrooms - Male (4-12)	Classroom 117	W2	Flaking	6	N	N	0	N	N	Additional Cracking, Chipping
313	2640	1	1	117	Student Restrooms - Male (4-12)	Classroom 117	W3	Flaking	26	N	N	0	N	N	2 Locations
314	2640	1	1	117	Primary	Classroom 117	W4	Flaking	120	N	N	0	Y - 48 SF Bookcases, Desks	N	3 Locations
315	2640	1	1	1D	Restrooms, Staff - Male/Female	Closet adjacent to Classroom 114	W1	Partially Inaccessible	0	N	N	0	Y - 48 SF Cabinets, Bookcases, Contents	N	
316	2640	1	1	1D	Restrooms, Staff - Male/Female	Closet adjacent to Classroom 114	W2	Flaking	5	N	N	0	N	Y - 1 SF	3 Locations; Additional Cracking
317	2640	1	1	1D	Restrooms, Staff - Male/Female	Closet adjacent to Classroom 114	W3	Flaking	32	N	N	0	N	N	Additional Chipping
318	2640	1	1	1D	Restrooms, Staff - Male/Female	Closet adjacent to Classroom 114	W4	Flaking	120	N	N	0	Y - 90 SF Contents	N	Additional Cracking; Damage on Walls & Coat Closet Walls, Ceiling
319	2640	1	1	100	Administrative Office	Counselor's Office	W1	Cracking	8	N	N	0	Y - 56 SF Bookcases, File Cabinets	N	
320	2640	1	1	100	Administrative Office	Counselor's Office	W2	Flaking	2	N	N	0	N	N	
321	2640	1	1	100	Administrative Office	Counselor's Office	W3	Partially Inaccessible	0	N	N	0	Y - 60 SF Bookcases, Desks, Posters	N	
322	2640	1	1	100	Administrative Office	Counselor's Office	W4	Cracking	1	N	N	0	N	N	
323	2640	1	1	S02	Stairs	Fire Tower adjacent to Hallway from Classrooms 108 to 114	Ceiling	Flaking	120	N	N	0	N	N	
324	2640	1	1	105	Gymnasium - Intermediate Middle	Gym	Ceiling	Flaking	180	Y	N	0	N	Y - 24 SF	6 Locations; Additional Efflorescence, Cracking
325	2640	1	1	105	Administrative Office	Gym	W1	Flaking	64	Y	Y - Below Vents on Closet Trim	3	Y - 375 SF Contents	Y - 10 SF	7 Locations; Additional Efflorescence, Chipping, Holes
326	2640	1	1	105	Administrative Office	Gym	W2	Flaking	24	N	N	0	Y - 64 SF Wall Panels	N	3 Locations; Additional Cracking
327	2640	1	1	105	Administrative Office	Gym	W3	Flaking	80	N	N	0	N	N	5 Locations; Additional Cracking, Chipping
328	2640	1	1	105	Gymnasium - Intermediate Middle	Gym	W4	Flaking	75	Y	N	0	Y - 120 SF Wall Panels	Y - 32 SF	Additional Efflorescence, Cracking; Damage on Entire Wall

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
329	2640	1	1	H111	Circulation (Hallway)	Hallway from Classrooms 108 to 114	W2	Flaking	360	Y	N	0	N	Y - 4 SF	Additional Efflorescence, Cracking, Chipping
330	2640	1	1	H111	Circulation (Hallway)	Hallway from Classrooms 108 to 114	W4	Flaking	312	N	N	0	N	N	Additional Cracking
331	2640	1	1	H110	Circulation (Hallway)	Hallway from Classrooms 115 to 116	W1	Flaking	6	N	N	0	N	N	
332	2640	1	1	H110	Circulation (Hallway)	Hallway from Classrooms 115 to 116	W3	Flaking	36	N	N	0	N	N	
333	2640	1	1	H112	Primary	Hallway from Main Office to Gymnasium	W1	Flaking	38	N	N	0	Y - 120 SF Posters	N	Additional Cracking
334	2640	1	1	H112	Primary	Hallway from Main Office to Gymnasium	W2	Cracking	6	N	N	0	N	N	
335	2640	1	1	H112	Primary	Hallway from Main Office to Gymnasium	W3	Flaking	32	N	N	0	Y - 45 SF Posters	N	Additional Cracking
336	2640	1	1	100A	Restrooms, Staff - Male/Female	Main Office	W1	Chipping	2	N	N	0	Y - 42 SF Bookcases	N	
337	2640	1	1	100A	Restrooms, Staff - Male/Female	Main Office	W2	Flaking	8	N	N	0	Y = 75 SF File Cabinets	N	3 Locations; Additional Gouges, Holes
338	2640	1	1	100A	Storage	Main Office	W3	Chipping	1	N	N	0	N	N	Chipping @ Radiator
339	2640	1	1	100A	Administrative Office	Main Office	W4	Flaking	4	N	N	0	Y - 32 SF Bulletin Boards	N	
340	2640	1	1	100A	Administrative Office	Main Office Closet - Left	W2	Partially Inaccessible	0	N	N	0	Y - 7 SF Shelves, Contents	N	
341	2640	1	1	100A	Administrative Office	Main Office Closet - Left	W3	Partially Inaccessible	0	N	N	0	Y - 21 SF Shelves, Contents	N	
342	2640	1	1	100A	Administrative Office	Main Office Closet - Left	W4	Partially Inaccessible	0	N	N	0	Y - 7 SF Shelves, Contents	N	
343	2640	1	1	100A	Administrative Office	Main Office Closet - Right	W2	Partially Inaccessible	0	N	N	0	Y - 7 SF Shelves, Contents	N	
344	2640	1	1	100A	Administrative Office	Main Office Closet - Right	W3	Partially Inaccessible	0	N	N	0	Y - 21 SF Shelves, Contents	N	
345	2640	1	1	100A	Administrative Office	Main Office Closet - Right	W4	Partially Inaccessible	0	N	N	0	Y - 7 SF Shelves, Contents	N	
346	2640	1	1	115A	Primary	Male/Female Student Restroom	W1	Flaking	2	N	N	0	N	N	Flaking @ Door Frame
347	2640	1	1	115A	Primary	Male/Female Student Restroom	W3	Flaking	4	N	N	0	N	N	Flaking @ Door Frame
348	2640	1	1	1B	Restrooms, Staff - Male	Men's Restroom	Ceiling	Cracking	8	N	N	0	N	N	

Southwark -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
349	2640	1	1	1B	Restrooms, Staff - Female	Men's Restroom	W1	Flaking	3	N	N	0	N	N	Flaking @ Window
350	2640	1	1	1B	Restrooms, Staff - Female	Men's Restroom	W2	Flaking	10	N	N	0	N	N	Additional Chipping
351	2640	1	1	1B	Restrooms, Staff - Female	Men's Restroom	W3	Flaking	26	N	N	0	N	N	Additional Cracking
352	2640	1	1	1B	Restrooms, Staff - Male	Men's Restroom	W4	Flaking	16	N	N	0	N	N	Additional Cracking
353	2640	1	1	108	Primary	Nurse's Office 108	Ceiling	Flaking	3	N	N	0	N	N	Flaking @ Window 1; Suspended Ceiling
354	2640	1	1	108	Primary	Nurse's Office 108	W1	Flaking	13	N	N	0	N	N	3 Locations; Additional Cracking, Holes
355	2640	1	1	108	Primary	Nurse's Office 108	W2	Flaking	18	N	N	0	N	N	2 Locations; Additional Cracking, Holes
356	2640	1	1	108	Primary	Nurse's Office 108	W3	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks	N	
357	2640	1	1	108	Administrative Office	Nurse's Office 108	W4	Flaking	8	N	N	0	Y - 64 SF Bookcases, Desks, Contents	N	Additional Cracking, Holes
358	2640	1	1	101	Administrative Office	Office 101	Ceiling	Flaking	2	N	N	0	N	N	Additional Cracking, Chipping; Damage above Door
359	2640	1	1	101	Administrative Office	Office 101	W1	Flaking	16	N	N	0	N	N	Additional Cracking
360	2640	1	1	101		Office 101	W2	Cracking	8	N	N	0	Y - 28 SF Desks	N	
361	2640	1	1	101	Administrative Office	Office 101	W3	Flaking	6	N	N	0	Y - 8 SF Contents	N	Additional Cracking
362	2640	1	1	101	Administrative Office	Office 101	W4	Flaking	10	N	N	0	N	N	2 Locations; Additional Cracking, Gouges
363	2640	1	1	118	Administrative Office	Office 118	Ceiling	Flaking	6	N	N	0	N	N	
364	2640	1	1	118	Primary	Office 118	W1	Partially Inaccessible	0	N	N	0	Y - 32 SF Desks, Contents	N	
365	2640	1	1	118	Primary	Office 118	W2	Flaking	10	N	N	0	Y - 30 SF Desks, Contents	N	
366	2640	1	1	118	Primary	Office 118	W3	Flaking	4	N	N	0	Y - 16 SF File Cabinets, Desks, Contents	N	
367	2640	1	1	118	Administrative Office	Office 118	W4	Partially Inaccessible	0	N	N	0	Y - 72 SF Shelves, Contents	N	
368	2640	1	1	100B	Administrative Office	Principal's Office	W1	Cracking	4	N	N	0	N	N	
369	2640	1	1	100B	Administrative Office	Principal's Office	W2	Cracking	3	N	N	0	Y - 16 SF Desks	N	
370	2640	1	1	100B	Administrative Office	Principal's Office	W4	Partially Inaccessible	0	N	N	0	Y - 8 SF File Cabinets	N	
371	2640	1	1	100C	Storage	Server Room	W1	Flaking	8	N	N	0		N	Additional Cracking

Southwark -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
372	2640	1	1	100C	Storage	Server Room	W2	Gouges	2	N	N	0	Y - 20 SF IT Equipment	N	
373	2640	1	1	100C	Storage	Server Room	W3	Partially Inaccessible	0	N	N	0	Y - 12 SF Boxes, Contents	N	
374	2640	1	1	100C	Storage	Server Room	W4	Flaking	11	N	N	0	Y - 24 SF Contents	N	3 Locations; Additional Cracking, Chipping, Holes
375	2640	1	1	1C	Restrooms, Staff - Male	Staff Restroom	Ceiling	Flaking	11	N	N	0	N	N	2 Locations; Additional Cracking
376	2640	1	1	1C	Restrooms, Staff - Male	Staff Restroom	W1	Cracking	8	N	N	0	N	N	
377	2640	1	1	1C	Restrooms, Staff - Male	Staff Restroom	W2	Cracking	8	N	N	0	N	N	
378	2640	1	1	1C	Restrooms, Staff - Male	Staff Restroom	W3	Flaking	20	Y	N	0	N	Y - 2- SF	Additional Efflorescence
379	2640	1	1	1C	Restrooms, Staff - Male/Female	Staff Restroom	W4	Flaking	36	Y	N	0	N	Y - 36 SF	Additional Efflorescence
380	2640	1	1	S03	Stairs	Stairwell adjacent Classroom 108	Ceiling	Flaking	5	N	N	0	N	N	Additional Cracking
381	2640	1	1	S03	Stairs	Stairwell adjacent Classroom 108	Center Banister	Chipping	10	N	N	0	N	N	
382	2640	1	1	S03	Stairs	Stairwell adjacent Classroom 108	W1	Flaking	18	N	N	0	N	N	Additional Chipping
383	2640	1	1	S03	Stairs	Stairwell adjacent Classroom 108	W2	Flaking	60	N	N	0	N	N	Additional Cracking
384	2640	1	1	S03	Stairs	Stairwell adjacent Classroom 108	W3	Chipping	4	N	N	0	N	N	
385	2640	1	1	S03	Stairs	Stairwell adjacent Classroom 108	W4	Flaking	90	N	N	0	N	N	Additional Cracking
386	2640	1	1	S01	Gymnasium - Intermediate Middle	Stairwell adjacent to Classroom 114	Center Banister	Chipping	30	N	N	0	N	N	
387	2640	1	1	S01	Gymnasium - Intermediate Middle	Stairwell adjacent to Classroom 114	W1	Flaking	20	N	N	0	N	N	Additional Chipping
388	2640	1	1	S01	Gymnasium - Intermediate Middle	Stairwell adjacent to Classroom 114	W2	Flaking	6	N	N	0	N	N	
389	2640	1	1	1A	Restrooms, Staff - Female	Women's Restroom	Ceiling	Flaking	120	N	N	0	N	N	Additional Cracking
390	2640	1	1	1A	Circulation (Hallway)	Women's Restroom	W2	Flaking	30	N	N	0	N	N	Additional Cracking
391	2640	1	1	1A	Circulation (Hallway)	Women's Restroom	W3	Flaking	6	N	N	0	N	N	Additional Cracking
392	2640	1	1	1A	Restrooms, Staff - Female	Women's Restroom	W4	Flaking	16	N	N	0	N	N	Additional Cracking
393	2640	1	0	10		Boys' Restroom	Ceiling	Flaking	420	N	N	0	N	N	
394	2640	1	0	014	Administrative Office	Cafeteria	Ceiling	Flaking	200	N	N	0	N	N	6 Locations; Additional Chipping
395	2640	1	0	014	Administrative Office	Cafeteria	W2	Flaking	140	N	N	0	N	N	Additional Cracking, Chipping
396	2640	1	0	014	Administrative Office	Cafeteria	W3	Flaking	80	N	N	0	N	N	Additional Chipping

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
421	2640	1	0	020A	Primary	Classroom 020 Closet #2	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
422	2640	1	0	020A	Primary	Classroom 020 Closet #2	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
423	2640	1	0	020A	Primary	Classroom 020 Closet #2	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
424	2640	1	0	020A	Primary	Classroom 020 Closet #2	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
425	2640	1	0	021	Primary	Classroom 021	Ceiling	Flaking	400	N	N	0	N	N	6 Locations; Additional Cracking
426	2640	1	0	021	Storage	Classroom 021	W1	Flaking	120	N	N	0	Y - 60 SF Tables, Posters	N	2 Locations; Additional Cracking
427	2640	1	0	021	Storage	Classroom 021	W2	Flaking	14	N	N	0	Y - 72 SF Contents	N	2 Locations; Additional Cracking
428	2640	1	0	021	Storage	Classroom 021	W3	Flaking	30	N	N	0	Y - 180 SF Desks, Cabinets, Posters	N	Additional Cracking
429	2640	1	0	021	Primary	Classroom 021	W4	Flaking	50	N	N	0	N	N	Additional Cracking
430	2640	1	0	001	Primary	Closet adjacent Classroom 005	Ceiling	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping, Holes; Damage Includes Ductwork
431	2640	1	0	001	Primary	Closet adjacent Classroom 005	W1	Chipping	1	N	N	0	N	N	
432	2640	1	0	001	Primary	Closet adjacent Classroom 005	W3	Cracking	8	N	N	0	N	N	
433	2640	1	0	001	Primary	Closet adjacent Classroom 005	W4	Cracking	4	N	N	0	N	N	Additional Chipping
434	2640	1	0	024	Restrooms, Staff - Male/Female	Closet adjacent Hallway from Classroom 005 to Building Engineer's Office	W4	Efflorescence	140	N	N	0	N	Y - 140 SF	
435	2640	1	0	015	Stairs	Fan Room #1	W1	Flaking	150	N	N	0	N	N	
436	2640	1	0	015	Stairs	Fan Room #1	W2	Flaking	150	N	N	0	N	N	
437	2640	1	0	015	Stairs	Fan Room #1	W3	Flaking	150	N	N	0	N	N	
438	2640	1	0	S02	Circulation (Hallway)	Fire Tower adjacent to Cafeteria	Ceiling	Flaking	72	N	N	0	N	N	
439	2640	1	0	S02	Circulation (Hallway)	Fire Tower adjacent to Cafeteria	W1	Flaking	24	N	N	0	N	N	
440	2640	1	0	S02	Circulation (Hallway)	Fire Tower adjacent to Cafeteria	W2	Flaking	60	N	N	0	N	N	
441	2640	1	0	S02	Circulation (Hallway)	Fire Tower adjacent to Cafeteria	W3	Flaking	40	N	N	0	N	N	
442	2640	1	0	S02	Circulation (Hallway)	Fire Tower adjacent to Cafeteria	W4	Flaking	60	N	N	0	N	N	

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
443	2640	1	0	H013	Cafeteria (Dining Area)	Hallway	Ceiling	Flaking	8	N	N	0	Y - 160 SF Pipes, Ductwork	N	3 Locations; Additional Chipping
444	2640	1	0	H013	Cafeteria (Dining Area)	Hallway	W1	Flaking	28	N	N	0	N	N	Additional Chipping
445	2640	1	0	H013	Cafeteria (Dining Area)	Hallway	W2	Chipping	20	N	N	0	N	N	3 Locations
446	2640	1	0	H013	Cafeteria (Dining Area)	Hallway	W3	Flaking	16	N	N	0	N	N	Additional Chipping
447	2640	1	0	H013	Circulation (Hallway)	Hallway	W4	Flaking	24	N	N	0	N	N	4 Locations; Additional Chipping
448	2640	1	0	H011	Circulation (Hallway)	Hallway from Building Engineer's Office to Cafeteria	Ceiling	Flaking	26	N	N	0	N	N	6 Locations; Additional Chipping
449	2640	1	0	H011	Circulation (Hallway)	Hallway from Building Engineer's Office to Cafeteria	W1	Flaking	32	N	N	0	N	N	Additional Chipping
450	2640	1	0	H011	Circulation (Hallway)	Hallway from Building Engineer's Office to Cafeteria	W2	Flaking	80	N	N	0	N	N	Additional Chipping
451	2640	1	0	H011	Circulation (Hallway)	Hallway from Building Engineer's Office to Cafeteria	W3	Flaking	22	N	N	0	N	N	Additional Chipping
452	2640	1	0	H011	Circulation (Hallway)	Hallway from Building Engineer's Office to Cafeteria	W4	Flaking	110	N	N	0	N	N	
453	2640	1	0	H012	Administrative Office	Hallway from Classroom 005 to Stairwell adjacent to Building Engineer's Office	Ceiling	Flaking	720	N	N	0	N	N	Additional Chipping
454	2640	1	0	H012	Administrative Office	Hallway from Classroom 005 to Stairwell adjacent to Building Engineer's Office	W1	Flaking	720	N	N	0	N	N	Additional Chipping
455	2640	1	0	H012	Administrative Office	Hallway from Classroom 005 to Stairwell adjacent to Building Engineer's Office	W2	Flaking	48	N	N	0	N	N	Additional Chipping
456	2640	1	0	H012	Administrative Office	Hallway from Classroom 005 to Stairwell adjacent to Building Engineer's Office	W3	Flaking	774	N	N	0	N	N	Additional Chipping
457	2640	1	0	H010	Circulation (Hallway)	Hallway from Classrooms 020 to 021	Ceiling	Flaking	18	N	N	0	N	N	2 Locations; Additional Chipping

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
458	2640	1	0	H010	Storage	Hallway from Classrooms 020 to 021	W1	Flaking	28	N	N	0	N	N	Additional Chipping
459	2640	1	0	H010	Storage	Hallway from Classrooms 020 to 021	W2	Flaking	6	N	N	0	N	N	Additional Chipping
460	2640	1	0	H010	Storage	Hallway from Classrooms 020 to 021	W3	Flaking	60	N	N	0	N	N	Additional Chipping
461	2640	1	0	H010	Circulation (Hallway)	Hallway from Classrooms 020 to 021	W4	Flaking	74	N	N	0	N	N	Additional Chipping
462	2640	1	0	020C	Storage	Kitchen Closet	W1	Flaking	36	N	N	0	N	N	
463	2640	1	0	020C	Storage	Kitchen Closet	W2	Flaking	16	N	N	0	N	N	
464	2640	1	0	020C	Storage	Kitchen Closet	W3	Flaking	48	N	N	0	N	N	
465	2640	1	0	020C	Storage	Kitchen Closet	W4	Flaking	2	N	N	0	N	N	
466	2640	1	0	022A	Storage	Kitchen Storage	Ceiling	Flaking	48	N	N	0	N	N	3 Locations; Additional Cracking
467	2640	1	0	022A	Storage	Kitchen Storage	W1	Flaking	200	N	N	0	Y - 20 SF Contents	N	Additional Chipping
468	2640	1	0	022A	Storage	Kitchen Storage	W2	Flaking	30	N	N	0	Y - 30 SF Contents	N	
469	2640	1	0	022A	Storage	Kitchen Storage	W3	Flaking	150	N	N	0	Y - 60 SF Contents	N	
470	2640	1	0	022A	Storage	Kitchen Storage	W4	Flaking	320	N	N	0	N	N	Additional Chipping
471	2640	1	0	018	Student Restrooms - Female (4-12)	Old Girl's Restroom	Ceiling	Flaking	240	N	N	0	N	N	2 Locations; Additional Cracking
472	2640	1	0	018	Student Restrooms - Female (4-12)	Old Girl's Restroom	W2	Flaking	20	N	N	0	N	N	Additional Cracking
473	2640	1	0	012A	Stairs	Room 012	Ceiling	Flaking	23	N	N	0	N	N	4 Locations; Additional Chipping
474	2640	1	0	012A	Stairs	Room 012	W3	Partially Inaccessible	0	N	N	0	Y - 120 SF Cabinets	N	
475	2640	1	0	023	Circulation (Hallway)	Staff Restroom adjacent Building Engineer's Office	Ceiling	Flaking	70	N	N	0	N	N	
476	2640	1	0	023	Circulation (Hallway)	Staff Restroom adjacent Building Engineer's Office	W1	Flaking	28	N	N	0	N	N	
477	2640	1	0	023	Circulation (Hallway)	Staff Restroom adjacent Building Engineer's Office	W2	Flaking	60	N	N	0	N	N	
478	2640	1	0	023	Circulation (Hallway)	Staff Restroom adjacent Building Engineer's Office	W3	Flaking	32	N	N	0	N	N	
479	2640	1	0	023	Circulation (Hallway)	Staff Restroom adjacent Building Engineer's Office	W4	Flaking	8	N	N	0	Y - 40 SF Contents	N	Flaking Includes Radiator
480	2640	1	0	S01	Primary	Stairwell across from Classroom 021	Ceiling	Cracking	16	N	N	0	N	N	

Southwark -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
481	2640	1	0	S01	Primary	Stairwell across from Classroom 021	W1	Cracking	4	N	N	0	N	N	
482	2640	1	0	S01	Primary	Stairwell across from Classroom 021	W2	Holes	2	N	N	0	N	N	
483	2640	1	0	S01	Primary	Stairwell across from Classroom 021	W3	Chipping	4	N	N	0	N	N	Additional Chipping; Damage @ Door
484	2640	1	0	S01	Primary	Stairwell across from Classroom 021	W4	Flaking	64	N	N	0	N	N	
485	2640	1	0	S05	Storage	Stairwell adjacent to Building Engineer's Office	Ceiling	Flaking	32	N	N	0	N	N	
486	2640	1	0	S05	Storage	Stairwell adjacent to Building Engineer's Office	Center Banister	Chipping	10	N	N	0	N	N	
487	2640	1	0	S05	Storage	Stairwell adjacent to Building Engineer's Office	W1	Flaking	40	N	N	0	N	N	
488	2640	1	0	S05	Storage	Stairwell adjacent to Building Engineer's Office	W2	Flaking	210	N	N	0	N	N	
489	2640	1	0	S05	Storage	Stairwell adjacent to Building Engineer's Office	W3	Flaking	26	N	N	0	N	N	
490	2640	1	0	S05	Storage	Stairwell adjacent to Building Engineer's Office	W4	Flaking	240	N	N	0	N	N	
491	2640	1	0	S04	Storage	Stairwell adjacent to Fan Room	Floor	Chipping	40	N	N	0	N	N	
492	2640	1	0	S04	Primary	Stairwell adjacent to Fan Room	W1	Cracking	4	N	N	0	N	N	
493	2640	1	0	S04	Primary	Stairwell adjacent to Fan Room	W2	Chipping	3	N	N	0	N	N	