

Alcorn (Universal) -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	3424	1	3	304		Art Room 304	W2	Flaking paint	2	No	No	No	No	No	
2	3424	1	3	304		Art Room 304	W4	Flaking and cracking paint	5	No	No	No	No	No	
3	3424	1	3	301A		Assistant Principal's Office next to Classroom 301	Ceiling	Flaking and spalling paint	15	No	No	No	No	No	
4	3424	1	3	301A		Assistant Principal's Office next to Classroom 301	W1	Flaking paint	2	No	No	No	No	No	
5	3424	1	3	301A		Assistant Principal's Office next to Classroom 301	W4	Flaking paint	5	No	No	No	No	No	
6	3424	1	3	301C		Assistant Principal's Office Restroom	Ceiling	Flaking paint	6	No	No	No	No	No	
7	3424	1	3	301C		Assistant Principal's Office Restroom	Floor	Good	0	No	No	No	No	No	
8	3424	1	3	301C		Assistant Principal's Office Restroom	W2	Cracking paint	2	No	No	No	No	No	
9	3424	1	3	301C		Assistant Principal's Office Restroom	W4	Cracking paint	5	No	No	No	No	No	
10	3424	1	3	307A		Boy's Restroom next to Classroom 307	Ceiling	Efflorescence and flaking paint	20	No	No	No	No	No	
11	3424	1	3	307A		Boy's Restroom next to Classroom 307	W2	Cracking paint	10	No	No	No	No	No	
12	3424	1	3	307A		Boy's Restroom next to Classroom 307	W3	Cracking paint	5	No	No	No	No	No	
13	3424	1	3	301		Classroom 301	W1	Flaking paint	5	No	No	No	No	No	
14	3424	1	3	301		Classroom 301	W3	Flaking paint	5	No	No	No	No	No	
15	3424	1	3	301		Classroom 301	W4	Cracking paint by closet	3	No	No	No	No	No	
16	3424	1	3	302		Classroom 302	W1	Crack in plaster wall	2	No	No	No	No	No	
17	3424	1	3	302		Classroom 302	W2	Flaking paint	2	No	No	No	No	No	
18	3424	1	3	303		Classroom 303	Ceiling	Flaking paint	7	No	No	No	No	No	
19	3424	1	3	303		Classroom 303	W1	Flaking paint and hole in plaster wall	2	No	No	No	No	Yes	
20	3424	1	3	303		Classroom 303	W3	Flaking paint and efflorescence at top of window and columns	6	No	No	No	No	No	
21	3424	1	3	305		Classroom 305	W1	Flaking paint	2	No	No	No	No	No	
22	3424	1	3	305		Classroom 305	W2	Flaking paint	2	No	No	No	No	No	
23	3424	1	3	305		Classroom 305	W4	Flaking paint	2	No	No	No	No	No	
24	3424	1	3	306		Classroom 306	Ceiling	Flaking paint	2	No	No	No	No	No	
25	3424	1	3	306		Classroom 306	W1	Flaking paint	2	No	No	No	No	No	
26	3424	1	3	306		Classroom 306	W3	Spalling and efflorescence	10	No	No	No	No	No	
27	3424	1	3	306		Classroom 306	W4	Flaking paint	2	No	No	No	No	No	
28	3424	1	3	306A		Classroom 306 Coat Closet	Ceiling	Severe plaster damage	20	No	No	No	No	Yes	

Alcorn (Universal) -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
29	3424	1	3	306A		Classroom 306 Coat Closet	W1	Efflorescence	10	No	No	No	No	No	
30	3424	1	3	306A		Classroom 306 Coat Closet	W3	Flaking paint	2	No	No	No	No	No	
31	3424	1	3	306A		Classroom 306 Coat Closet	W4	Efflorescence	10	No	No	No	No	No	
32	3424	1	3	307		Classroom 307	Ceiling	Flaking paint and cracking paint	20	No	No	No	No	No	
33	3424	1	3	307		Classroom 307	W1	Cracking paint	2	No	No	No	No	No	
34	3424	1	3	307		Classroom 307	W2	Flaking paint, Efflorescence and debris on window sill	4	No	Window sill	3	No	No	
35	3424	1	3	307B		Classroom 307 Coat Closet	W1	Flaking paint	2	No	No	No	No	No	
36	3424	1	3	307B		Classroom 307 Coat Closet	W3	Spalling paint	3	No	No	No	No	No	
37	3424	1	3	307C		Classroom 307 Storage Closet	Ceiling	Flaking paint	10	No	No	No	No	No	
38	3424	1	3	307C		Classroom 307 Storage Closet	W2	Damaged plaster	1	No	No	No	No	Yes	
39	3424	1	3	307C		Classroom 307 Storage Closet	W3	Flaking paint	30	No	Shelves	8	Stationery	No	
40	3424	1	3	307C		Classroom 307 Storage Closet	W4	Flaking paint	10	No	No	No	No	No	
41	3424	1	3	308		Classroom 308	Ceiling	Flaking paint	5	No	No	No	No	No	
42	3424	1	3	308		Classroom 308	W3	Efflorescence and flaking paint	10	No	No	No	No	No	
43	3424	1	3	308		Classroom 308	W4	Flaking paint	5	No	No	No	No	No	
44	3424	1	3	309		Classroom 309	Ceiling	Flaking paint	5	No	No	No	No	No	
45	3424	1	3	309		Classroom 309	Floor	Debris on sill	3	No	Window sill	3	No	No	
46	3424	1	3	310		Classroom 310	Ceiling	Flaking paint by closet	5	No	No	No	No	No	
47	3424	1	3	302A		Girl's Restroom next to Classroom 302	Ceiling	Cracking paint	2	No	No	No	No	No	
48	3424	1	3	304A		GPHA Office	Ceiling	Significant Flaking paint, spalling and efflorescence	20	No	No	No	No	No	
49	3424	1	3	304A		GPHA Office	W3	Crack in plaster wall	3	No	No	No	No	No	
50	3424	1	3	304A		GPHA Office	W4	Flaking paint	10	No	No	No	No	No	
51	3424	1	3	310A		Hallway Closet outside of Classroom 310	Ceiling	Hole in plaster ceiling	3	No	No	No	No	No	
52	3424	1	3	310A		Hallway Closet outside of Classroom 310	Floor	Debris at pipe	2	No	No	No	No	No	
53	3424	1	3	310A		Hallway Closet outside of Classroom 310	W1	Crack in plaster wall	6	No	No	No	No	Yes	
54	3424	1	3	310A		Hallway Closet outside of Classroom 310	W2	Flaking and cracking paint	5	No	No	No	No	No	
55	3424	1	3	310A		Hallway Closet outside of Classroom 310	W4	Significant flaking paint on pipe	15	No	No	No	No	No	This pipe is next to ACM risers
56	3424	1	3	H311		Hallway from Girl's to Boy's Restroom	Ceiling	Flaking paint - Spread out	50	No	No	No	No	No	
57	3424	1	3	H311		Hallway from Girl's to Boy's Restroom	W1	Flaking paint	5	No	No	No	No	No	

Alcorn (Universal) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
58	3424	1	3	H311		Hallway from Girl's to Boy's Restroom	W3	Cracking paint	10	No	No	No	No	No	
59	3424	1	3	H311A		Hallway outside Classroom 301	Ceiling	Flaking paint	1	No	No	No	No	No	
60	3424	1	3	H311A		Hallway outside Classroom 301	W2	Flaking paint	2	No	No	No	No	No	
61	3424	1	3	H310		Hallway outside Classrooms 308 to 310	Ceiling	Flaking paint	5	No	No	No	No	No	
62	3424	1	3	H310		Hallway outside Classrooms 308 to 310	W2	Flaking and cracking paint	10	No	No	No	No	No	
63	3424	1	3	H310		Hallway outside Classrooms 308 to 310	W4	Flaking and cracking paint	10	No	No	No	No	No	
64	3424	1	3	S31		Stairwell across from Classroom 303	W2	Flaking paint	25	No	No	No	No	No	
65	3424	1	3	S32		Stairwell across from Classroom 306	Ceiling	Flaking and cracking paint	20	No	No	No	No	No	
66	3424	1	3	S32		Stairwell across from Classroom 306	W2	Flaking paint	5	No	No	No	No	No	
67	3424	1	3	S32		Stairwell across from Classroom 306	W3	Flaking paint	10	No	No	No	No	No	
68	3424	1	3	S32		Stairwell across from Classroom 306	W4	Efflorescence and flaking paint at window	10	No	No	No	No	No	
69	3424	1	3	S312		Stairwell to Upper Level outside of Classroom 305	Ceiling	Flaking paint	30	No	No	No	No	No	
70	3424	1	3	306C		Storage Closet across from Classroom 306	W2	Cracking paint, and debris on shelf	8	No	Debris on shelf	4	Stationery	No	
71	3424	1	3	311A		Upper Level Book Closet	Ceiling	Flaking paint	2	No	No	No	No	No	
72	3424	1	3	H312		Upper Level Hallway outside of Speech Classroom	Ceiling	Flaking paint	3	No	No	No	No	No	
73	3424	1	3	H312		Upper Level Hallway outside of Speech Classroom	W1	Flaking paint	5	No	No	No	No	No	
74	3424	1	3	H312		Upper Level Hallway outside of Speech Classroom	W3	Flaking paint and efflorescence	5	No	No	No	No	No	
75	3424	1	3	311		Upper Level Office - Right of Stairs	W1	Flaking paint at vent	2	No	No	No	No	No	
76	3424	1	3	311		Upper Level Office - Right of Stairs	W3	Flaking paint next to radiator	5	No	No	No	No	No	
77	3424	1	3	311		Upper Level Office - Right of Stairs	W4	Flaking paint	5	No	No	No	No	No	

Alcorn (Universal) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
78	3424	1	3	312		Upper Level Speech Classroom - Left of Stairs	Ceiling	Significant flaking paint	5	No	No	No	No	No	
79	3424	1	3	312		Upper Level Speech Classroom - Left of Stairs	W1	Efflorescence and spalling paint	10	No	No	No	No	No	
80	3424	1	3	312		Upper Level Speech Classroom - Left of Stairs	W4	Flaking paint by windows	2	No	No	No	No	No	
81	3424	1	2	207A		Boy's Restroom next to Classroom 207	Ceiling	Efflorescence, flaking paint and damaged plaster	20	No	No	No	No	Yes	
82	3424	1	2	207A		Boy's Restroom next to Classroom 207	W2	Spalling by window	10	No	No	No	No	No	
83	3424	1	2	207A		Boy's Restroom next to Classroom 207	W3	Efflorescence above windows and debris on window sill	10	No	Window sill	10	No	No	
84	3424	1	2	201		Classroom 201	Ceiling	Flaking paint	60	No	No	No	No	No	
85	3424	1	2	201		Classroom 201	W1	Flaking paint and cracking paint	30	No	No	No	No	No	
86	3424	1	2	201		Classroom 201	W2	Chipping paint	2	No	No	No	No	No	
87	3424	1	2	201		Classroom 201	W3	Flaking paint and spalling paint	10	No	No	No	No	No	
88	3424	1	2	201B		Classroom 201 Coat Closet	W1	Flaking paint and spalling paint	50	No	No	No	No	No	
89	3424	1	2	201D		Classroom 201 Storage Closet	W2	Cracking paint	2	No	No	No	No	No	
90	3424	1	2	201D		Classroom 201 Storage Closet	W3	Cracking paint	3	No	No	No	No	No	
91	3424	1	2	201D		Classroom 201 Storage Closet	W4	Flaking paint and cracking paint	10	No	No	No	No	No	
92	3424	1	2	202		Classroom 202	W1	Cracking paint	5	No	No	No	No	No	
93	3424	1	2	202		Classroom 202	W3	Chipping paint and cracking paint	5	No	No	No	No	No	
94	3424	1	2	202B		Classroom 202 Coat Closet	W3	Chipping paint	3	No	No	No	No	No	
95	3424	1	2	202C		Classroom 202 Storage Closet	W2	Flaking paint	5	No	No	No	No	No	
96	3424	1	2	202C		Classroom 202 Storage Closet	W3	Flaking paint	10	No	No	No	No	No	
97	3424	1	2	203		Classroom 203	Ceiling	Flaking paint and spalling paint	30	No	No	No	No	No	
98	3424	1	2	203		Classroom 203	W2	Flaking paint	5	No	No	No	No	No	
99	3424	1	2	203		Classroom 203	W3	Spalling paint	5	No	No	No	No	No	
100	3424	1	2	203A		Classroom 203 Coat Closet	Ceiling	Efflorescence	5	No	No	No	No	No	
101	3424	1	2	203A		Classroom 203 Coat Closet	W3	Efflorescence by window	5	No	No	No	No	No	
102	3424	1	2	203B		Classroom 203 Storage Closet	W2	Flaking paint	5	No	No	No	No	No	
103	3424	1	2	204		Classroom 204	W2	Cracking paint	1	No	No	No	No	No	
104	3424	1	2	204		Classroom 204	W3	Cracking paint, Damaged plaster at radiator	6	No	No	No	No	No	
105	3424	1	2	204E		Classroom 204 Coat Closet	W1	Holes in plaster wall (from shelf rack removal)	6	No	No	No	No	Yes	

Alcorn (Universal) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
106	3424	1	2	204F		Classroom 204 Storage Closet	W2	Damaged plaster	2	No	No	No	No	Yes	
107	3424	1	2	205		Classroom 205	Ceiling	Spalling paint and chipping paint	5	No	No	No	No	No	
108	3424	1	2	205A		Classroom 205 Coat Closet	W4	Flaking paint	2	No	No	No	No	No	
109	3424	1	2	206		Classroom 206	Ceiling	Flaking paint	10	No	No	No	No	No	
110	3424	1	2	206		Classroom 206	W3	Spalling paint	3	No	No	No	No	No	
111	3424	1	2	206A		Classroom 206 Coat Closet	Ceiling	Spalling paint	5	No	No	No	No	No	
112	3424	1	2	206A		Classroom 206 Coat Closet	W1	Flaking paint	8	No	No	No	No	No	
113	3424	1	2	206A		Classroom 206 Coat Closet	W3	Efflorescence	6	No	No	No	No	No	
114	3424	1	2	207		Classroom 207	Ceiling	Flaking paint	3	No	No	No	No	No	
115	3424	1	2	207		Classroom 207	W2	Spalling and cracking paint	10	No	No	No	No	No	
116	3424	1	2	207		Classroom 207	W4	Flaking paint at door	2	No	No	No	No	No	
117	3424	1	2	208		Classroom 208	Ceiling	Flaking paint	5	No	No	No	No	No	
118	3424	1	2	208A		Classroom 208 Coat Closet	Ceiling	Flaking paint at left corner	5	No	No	No	No	No	
119	3424	1	2	209		Computer Lab 209	Ceiling	Flaking paint	20	No	No	No	No	No	
120	3424	1	2	209		Computer Lab 209	W1	Flaking paint	1	No	No	No	No	No	
121	3424	1	2	209		Computer Lab 209	W3	Flaking paint and debris on window sill	5	No	Window sill	4	No	No	
122	3424	1	2	209A		Computer Lab 209 Storage Closet	Ceiling	No access - Needs to be inspected		No	No	No	No	No	No access
123	3424	1	2	209A		Computer Lab 209 Storage Closet	Floor	No access - Needs to be inspected		No	No	No	No	No	No access
124	3424	1	2	209A		Computer Lab 209 Storage Closet	W1	No access - Needs to be inspected		No	No	No	No	No	No access
125	3424	1	2	209A		Computer Lab 209 Storage Closet	W2	No access - Needs to be inspected		No	No	No	No	No	No access
126	3424	1	2	209A		Computer Lab 209 Storage Closet	W3	No access - Needs to be inspected		No	No	No	No	No	No access
127	3424	1	2	209A		Computer Lab 209 Storage Closet	W4	No access - Needs to be inspected		No	No	No	No	No	No access
128	3424	1	2	209B		Computer Lab 209 Storage Room	Ceiling	No access - Needs to be inspected		No	No	No	No	No	No access
129	3424	1	2	209B		Computer Lab 209 Storage Room	Floor	No access - Needs to be inspected		No	No	No	No	No	No access
130	3424	1	2	209B		Computer Lab 209 Storage Room	W1	No access - Needs to be inspected		No	No	No	No	No	No access
131	3424	1	2	209B		Computer Lab 209 Storage Room	W2	No access - Needs to be inspected		No	No	No	No	No	No access
132	3424	1	2	209B		Computer Lab 209 Storage Room	W3	No access - Needs to be inspected		No	No	No	No	No	No access
133	3424	1	2	209B		Computer Lab 209 Storage Room	W4	No access - Needs to be inspected		No	No	No	No	No	No access
134	3424	1	2	202A		Girl's Restroom next to Classroom 202	Ceiling	Spalling paint	20	No	No	No	No	No	
135	3424	1	2	202A		Girl's Restroom next to Classroom 202	W2	Flaking paint	10	No	No	No	No	No	

Alcorn (Universal) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
136	3424	1	2	202A		Girl's Restroom next to Classroom 202	W4	Flaking paint	10	No	No	No	No	No	
137	3424	1	2	H29		Hallway across from Classroom 206 to Men's Restroom	Ceiling	Flaking paint, Spalling paint, and efflorescence	30	No	No	No	No	No	
138	3424	1	2	H29		Hallway across from Classroom 206 to Men's Restroom	W2	Significant Flaking paint	30	No	No	No	No	No	
139	3424	1	2	H29		Hallway across from Classroom 206 to Men's Restroom	W4	Significant Flaking paint	30	No	No	No	No	No	
140	3424	1	2	H28		Hallway from Girl's to Boy's Restroom	Ceiling	Significant Flaking paint	30	No	No	No	No	No	
141	3424	1	2	H26		Hallway outside Classroom 201	W2	Cracking paint	2	No	No	No	No	No	
142	3424	1	2	H27		Hallway outside Classrooms 208 and 209	Ceiling	Flaking paint	2	No	No	No	No	No	
143	3424	1	2	H27		Hallway outside Classrooms 208 and 209	W1	Spalling at window	2	No	No	No	No	No	
144	3424	1	2	210		Men's Restroom in Hallway across from Classroom 206	Ceiling	Chipping paint	4	No	No	No	No	No	
145	3424	1	2	204D		Nurse's Office Closet	W2	Good	0	No	Debris on shelves and boxes	100	Stationery	No	
146	3424	1	2	204C		Nurse's Office Restroom	Ceiling	Flaking paint	20	No	No	No	No	No	
147	3424	1	2	204C		Nurse's Office Restroom	W1	Flaking paint	10	No	No	No	No	No	
148	3424	1	2	201A		Office next to Classroom 201	Ceiling	Flaking paint and efflorescence	10	No	No	No	No	No	
149	3424	1	2	201A		Office next to Classroom 201	W1	Flaking paint	10	No	No	No	No	No	
150	3424	1	2	201A		Office next to Classroom 201	W4	Flaking paint	2	No	No	No	No	No	
151	3424	1	2	S21		Stairwell across from Classroom 203	W1	Flaking paint and efflorescence at windows	10	No	No	No	No	No	
152	3424	1	2	S22		Stairwell across from Classroom 206	W3	Flaking paint	3	No	No	No	No	No	
153	3424	1	2	S22		Stairwell across from Classroom 206	W4	Efflorescence at window	5	No	No	No	No	No	
154	3424	1	2	211		Storage Room across from Classroom 205	W1	Flaking paint	2	No	No	No	No	No	

Alcorn (Universal) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
155	3424	1	2	211		Storage Room across from Classroom 205	W2	Crack in plaster wall	6	No	No	No	No	No	
156	3424	1	2	211		Storage Room across from Classroom 205	W3	Crack in plaster wall	20	No	No	No	No	No	
157	3424	1	2	211		Storage Room across from Classroom 205	W4	Crack in plaster wall	3	No	No	No	No	No	
158	3424	1	2	210A		Storage Room in Men's Restroom Hallway	W1	Efflorescence, damaged plaster	20	No	Shelves , Storage box	12	Stationery	No	
159	3424	1	2	201C		Women's Restroom inside Office next to Classroom 201	Ceiling	Flaking paint on pipe	40	No	No	No	No	No	
160	3424	1	2	201C		Women's Restroom inside Office next to Classroom 201	W2	Flaking and cracking paint	10	No	No	No	No	No	
161	3424	1	2	201C		Women's Restroom inside Office next to Classroom 201	W3	Flaking paint	10	No	No	No	No	No	
162	3424	1	1	109		Auditorium	Ceiling	Significant flaking paint and efflorescence	200	No	No	No	No	No	
163	3424	1	1	109		Auditorium	W1	Flaking paint	20	No	No	No	No	No	
164	3424	1	1	109		Auditorium	W3	Efflorescence and flaking paint	40	No	No	No	No	No	
165	3424	1	1	109		Auditorium	W4	Flaking paint	20	No	No	No	No	No	
166	3424	1	1	106A		Boy's Restroom next to Classroom 106	Ceiling	Spalling paint	20	No	No	No	No	No	
167	3424	1	1	106A		Boy's Restroom next to Classroom 106	W2	Efflorescence and spalling paint	40	No	No	No	No	No	
168	3424	1	1	106A		Boy's Restroom next to Classroom 106	W4	Flaking paint	10	No	No	No	No	No	
169	3424	1	1	101		Classroom 101	Ceiling	Flaking Paint	30	No	No	No	No	No	
170	3424	1	1	101		Classroom 101	Floor	Debris on window sill	4	No	No	No	No	No	
171	3424	1	1	101		Classroom 101	W1	Flaking Paint - Spread out	30	No	No	No	No	No	
172	3424	1	1	101		Classroom 101	W2	Flaking Paint	5	No	No	No	No	No	
173	3424	1	1	101		Classroom 101	W3	Flaking Paint by closet	5	No	Window sill	4		No	
174	3424	1	1	101		Classroom 101	W4	Flaking Paint	10	No	No	No	No	No	
175	3424	1	1	101B		Classroom 101 Closet	Ceiling	Efflorescence and flaking paint	20	No	No	No	No	No	
176	3424	1	1	101B		Classroom 101 Closet	W2	Efflorescence and flaking paint	20	No	No	No	No	No	
177	3424	1	1	101B		Classroom 101 Closet	W3	Efflorescence and flaking paint	15	No	No	No	No	No	
178	3424	1	1	101B		Classroom 101 Closet	W4	Efflorescence, flaking paint and spalling	30	No	No	No	No	No	
179	3424	1	1	H16		Classroom 101 Foyer	Ceiling	Flaking paint	15	No	No	No	No	No	

Alcorn (Universal) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
180	3424	1	1	H16		Classroom 101 Foyer	W1	Cracking paint	10	No	No	No	No	No	
181	3424	1	1	H16		Classroom 101 Foyer	W3	Flaking paint	10	No	No	No	No	No	
182	3424	1	1	H16		Classroom 101 Foyer	W4	Flaking paint	20	No	No	No	No	No	
183	3424	1	1	101A		Classroom 101 Restroom	Ceiling	Significant flaking paint and spalling	30	No	No	No	No	No	
184	3424	1	1	101A		Classroom 101 Restroom	W2	Flaking paint	30	No	No	No	No	No	
185	3424	1	1	101A		Classroom 101 Restroom	W3	Efflorescence	5	No	No	No	No	No	
186	3424	1	1	101A		Classroom 101 Restroom	W4	Significant flaking paint	30	No	No	No	No	No	
187	3424	1	1	102		Classroom 102	Ceiling	Flaking Paint at window and front wall soffit	6	No	No	No	No	No	
188	3424	1	1	102		Classroom 102	W1	Flaking paint	10	No	No	No	No	No	
189	3424	1	1	102B		Classroom 102 Coat Closet	W3	Spalling paint	5	No	No	No	No	No	
190	3424	1	1	102B		Classroom 102 Coat Closet	W4	Flaking paint	3	No	No	No	No	No	
191	3424	1	1	102C		Classroom 102 Storage Closet	W2	Flaking paint behind shelves	20	No	No	No	No	No	
192	3424	1	1	102C		Classroom 102 Storage Closet	W4	Cracking paint	30	No	No	No	No	No	
193	3424	1	1	103		Classroom 103	Ceiling	Flaking paint - spread out	20	No	No	No	No	No	
194	3424	1	1	103		Classroom 103	W1	Flaking paint	6	No	No	No	No	No	
195	3424	1	1	103		Classroom 103	W3	Flaking paint and cracking paint	5	No	No	No	No	No	
196	3424	1	1	103A		Classroom 103 Coat Closet	W1	Flaking paint	30	No	No	No	No	No	
197	3424	1	1	103A		Classroom 103 Coat Closet	W3	Cracking paint	3	No	No	No	No	No	
198	3424	1	1	103A		Classroom 103 Coat Closet	W4	Flaking paint	3	No	No	No	No	No	
199	3424	1	1	105		Classroom 105	W3	Efflorescence, flaking paint and cracking paint	15	No	No	No	No	No	
200	3424	1	1	105A		Classroom 105 Coat Closet	W2	Flaking paint and cracking paint, debris on window sill	10	No	Window sill	2	No	No	
201	3424	1	1	105B		Classroom 105 Storage Closet	W2	Cracking paint	5	No	Window sill	2		No	
202	3424	1	1	105B		Classroom 105 Storage Closet	W3	Flaking paint and cracking paint	15	No	No	No	No	No	
203	3424	1	1	105B		Classroom 105 Storage Closet	W4	Cracking paint	5	No	No	No	No	No	
204	3424	1	1	106		Classroom 106	Ceiling	Flaking paint	20	No	No	No	No	No	
205	3424	1	1	106		Classroom 106	W2	Flaking paint and efflorescence	10	No	No	No	No	No	
206	3424	1	1	106B		Classroom 106 Coat Closet	W3	Efflorescence	10	No	No	No	No	No	
207	3424	1	1	106B		Classroom 106 Coat Closet	W4	Flaking paint	5	No	No	No	No	No	
208	3424	1	1	106C		Classroom 106 Storage Closet	W1	Cracking paint	3	No	No	No	No	No	

Alcorn (Universal) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
209	3424	1	1	106C		Classroom 106 Storage Closet	W2	Cracking paint	3	No	No	No	No	No	
210	3424	1	1	106C		Classroom 106 Storage Closet	W3	Cracking paint	3	No	No	No	No	No	
211	3424	1	1	106C		Classroom 106 Storage Closet	W4	Cracking paint	3	No	No	No	No	No	
212	3424	1	1	107		Classroom 107	Ceiling	Flaking paint	2	No	No	No	No	No	
213	3424	1	1	107		Classroom 107	W3	Efflorescence	5	No	No	No	No	No	
214	3424	1	1	107A		Classroom 107 Coat Closet	Ceiling	Crack in plaster ceiling	2	No	No	No	No	No	
215	3424	1	1	107B		Classroom 107 Storage Closet	W1	Crack in plaster	3	No	No	No	No	No	
216	3424	1	1	107B		Classroom 107 Storage Closet	W2	Crack in plaster	3	No	No	No	No	No	
217	3424	1	1	108		Classroom 108	Ceiling	Flaking paint	3	No	No	No	No	No	
218	3424	1	1	108		Classroom 108	W3	Efflorescence, flaking paint and spalling paint	10	No	No	No	No	No	
219	3424	1	1	108B		Classroom 108 Restroom	Ceiling	Spalling paint	2	No	No	No	No	No	
220	3424	1	1	108B		Classroom 108 Restroom	W2	Flaking paint on cinderblock	5	No	No	No	No	No	
221	3424	1	1	108B		Classroom 108 Restroom	W3	Flaking paint	2	No	No	No	No	No	
222	3424	1	1	108A		Classroom 108 Storage Closet	W2	Flaking paint, crack in plaster	2	No	No	No	No	No	
223	3424	1	1	104		Family Student Resource Center	W1	Cracking paint	3	No	No	No	No	No	
224	3424	1	1	S17		Front Entrance Foyer/Stairwell	Ceiling	Efflorescence	10	No	No	No	No	No	
225	3424	1	1	S17		Front Entrance Foyer/Stairwell	W4	Efflorescence	5	No	No	No	No	No	
226	3424	1	1	102A		Girl's Restroom next to Classroom 102	Ceiling	Efflorescence	25	No	No	No	No	No	
227	3424	1	1	102A		Girl's Restroom next to Classroom 102	W4	Efflorescence	10	No	No	No	No	No	
228	3424	1	1	HALL1		Hallway behind Auditorium Stage	Ceiling	Flaking paint	20	No	No	No	No	No	
229	3424	1	1	HALL1		Hallway behind Auditorium Stage	W2	Significant flaking paint	50	No	No	No	No	No	
230	3424	1	1	HALL1		Hallway behind Auditorium Stage	W4	Flaking paint	5	No	No	No	No	No	
231	3424	1	1	H15		Hallway outside Auditorium	Ceiling	Flaking paint at main entrance	3	No	No	No	No	No	
232	3424	1	1	H15B		Hallway outside Classrooms 105 and 106	Ceiling	Flaking paint	3	No	No	No	No	No	
233	3424	1	1	H14		Hallway outside Classrooms 107 and 108	Ceiling	Flaking paint - spread out	10	No	No	No	No	No	
234	3424	1	1	100		Main Office	Ceiling	Flaking paint by window	5	No	No	No	No	No	
235	3424	1	1	100		Main Office	Floor	Debris on window sill	2	No	Window sill	2	No	No	
236	3424	1	1	100		Main Office	W1	Crack in plaster	10	No	No	No	No	No	

Alcorn (Universal) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
237	3424	1	1	100		Main Office	W3	Flaking paint on pipe	3	No	No	No	No	No	
238	3424	1	1	100B		Main Office Closet	W1	Cracking paint	5	No	No	No	No	No	
239	3424	1	1	100B		Main Office Closet	W3	Cracking paint	3	No	No	No	No	No	
240	3424	1	1	111		Office across from Teacher's Lounge 104	W2	Crack in plaster wall	6	No	No	No	No	No	
241	3424	1	1	100C		Principal's Office Restroom	Ceiling	Flaking paint	2	No	No	No	No	No	
242	3424	1	1	109 STAGE		Stage	Ceiling	Significant flaking paint and efflorescence	120	No	No	No	No	No	
243	3424	1	1	109 STAGE		Stage	Floor	Debris	100	No	No	No	No	No	
244	3424	1	1	109 STAGE		Stage	W1	Flaking paint at columns	40	No	No	No	No	No	
245	3424	1	1	109 STAGE		Stage	W3	Significant flaking paint and efflorescence behind curtains	200	No	No	No	No	No	
246	3424	1	1	S11		Stairwell across from Classroom 103	W2	Flaking paint and efflorescence	20	No	No	No	No	No	
247	3424	1	1	S11		Stairwell across from Classroom 103	W4	Flaking paint and efflorescence	10	No	No	No	No	No	
248	3424	1	1	S11A		Stairwell across from Classroom 103 to exit	Ceiling	Flaking paint	10	No	No	No	No	No	
249	3424	1	1	S11A		Stairwell across from Classroom 103 to exit	W2	Flaking paint and efflorescence	20	No	No	No	No	No	
250	3424	1	1	S12		Stairwell across from Classroom 105	Ceiling	Flaking paint and efflorescence	2	No	No	No	No	No	
251	3424	1	1	S12		Stairwell across from Classroom 105	W2	Flaking paint	2	No	No	No	No	No	
252	3424	1	1	S12A		Stairwell across from Classroom 105 to exit	W3	Efflorescence above exit doors	10	No	No	No	No	No	
253	3424	1	1	S12A		Stairwell across from Classroom 105 to exit	W4	Efflorescence	10	No	No	No	No	No	
254	3424	1	1	110		Storage Room across from Main Office	W1	Crack in plaster wall	3	No	No	No	No	No	
255	3424	1	1	110B		Storage/IT MDF Room next to Auditorium Stage	W1	Flaking paint and efflorescence	20	No	No	No	No	No	
256	3424	1	1	110B		Storage/IT MDF Room next to Auditorium Stage	W4	Flaking paint and efflorescence	20	No	No	No	No	No	
257	3424	1	1	104A		Teacher's Lounge Coat Closet	Ceiling	Flaking paint	10	No	No	No	No	No	
258	3424	1	1	104A		Teacher's Lounge Coat Closet	W1	Cracking paint	3	No	No	No	No	No	

Alcorn (Universal) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
259	3424	1	1	104A		Teacher's Lounge Coat Closet	W2	Cracking paint	3	No	No	No	No	No	
260	3424	1	1	104		Teacher's Lounge next to Classroom 103	W3	Cracking paint	3	No	No	No	No	No	
261	3424	1	1	112		Women's Restroom behind Auditorium Stage	Ceiling	Flaking paint and cracking paint	5	No	No	No	No	No	
262	3424	1	0	B-2		B-2 Head Start Office	W3	Significant Efflorescence and spalling	30	No	No	No	No	No	
263	3424	1	0	002A		B-2 Head Start Office Closet	Ceiling	Significant flaking paint at drain pipe	10	No	No	No	No	No	
264	3424	1	0	002A		B-2 Head Start Office Closet	W4	Flaking paint on radiator cover	2	No	No	No	No	No	
265	3424	1	0	12		Building Engineer's Office	Ceiling	Flaking paint	25	No	No	No	No	No	
266	3424	1	0	1		Cafetorium	Ceiling	Flaking paint and efflorescence including the lower ceiling	200	No	No	No	No	No	
267	3424	1	0	1		Cafetorium	W1	Efflorescence on brick wall	20	No	No	No	No	No	
268	3424	1	0	1		Cafetorium	W2	Efflorescence on brick wall	10	No	No	No	No	No	
269	3424	1	0	1		Cafetorium	W3	Efflorescence on brick wall	8	No	No	No	No	No	
270	3424	1	0	1		Cafetorium	W4	Efflorescence on brick wall, and flaking paint on plaster wall	20	No	No	No	No	No	
271	3424	1	0	016A		Girl's Restroom (Sinks)	Ceiling	Flaking paint and efflorescence	30	No	No	No	No	No	
272	3424	1	0	16		Girl's Restroom (Stalls)	Ceiling	Flaking paint	20	No	No	No	No	No	
273	3424	1	0	11		Gym Storage Room next to Kitchen	Ceiling	Flaking paint and Efflorescence	30	No	No	No	No	No	
274	3424	1	0	11		Gym Storage Room next to Kitchen	Floor	Debris on floor and chairs	20	No	Floor and chairs	20	Chairs	No	
275	3424	1	0	H03		Hallway on Girl's Restroom Side	Ceiling	Significant flaking paint	60	No	No	No	No	No	
276	3424	1	0	H03		Hallway on Girl's Restroom Side	W3	Flaking paint	10	No	No	No	No	No	
277	3424	1	0	002B		Hallway Storage Closet next to B-2 Head Start Office	Ceiling	Flaking paint on pipe	5	No	No	No	No	No	
278	3424	1	0	002B		Hallway Storage Closet next to B-2 Head Start Office	Floor	Good	0	No	Shelves	6		No	
279	3424	1	0	002B		Hallway Storage Closet next to B-2 Head Start Office	W2	Flaking paint on pipe	10	No	No	No	No	No	
280	3424	1	0	5		IMC (Library)	W1	Crack in plaster wall	8	No	No	No	No	No	
281	3424	1	0	5		IMC (Library)	W2	Flaking paint and Efflorescence	60	No	No	No	No	No	
282	3424	1	0	5		IMC (Library)	W3	Flaking paint and Efflorescence	60	No	No	No	No	No	
283	3424	1	0	10		Kitchen	Ceiling	Damaged plaster, flaking paint	20	No	No	No	No	Yes	
284	3424	1	0	9		Kitchen Dry Food Storage Room	Ceiling	Flaking paint	10	No	No	No	No	No	
285	3424	1	0	005A		Library Study Room	W3	Efflorescence at column	10	No	No	No	No	No	

Alcorn (Universal) -Scope of Work

Task ID	ULCS#	Element	Fl oor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
286	3424	1	0	005A		Library Study Room	W4	Efflorescence	10	No	No	No	No	No	
287	3424	1	0	H01		North Hallway on Boy's Restroom Side	Ceiling	Flaking paint - spread out	40	No	No	No	No	No	
288	3424	1	0	S06		North Stairs to Boiler/Fan Room	Floor	Stairs	12	No	No	No	No	No	
289	3424	1	0	S06		North Stairs to Boiler/Fan Room	W1	Flaking paint at column	3	No	No	No	No	No	
290	3424	1	0	S06		North Stairs to Boiler/Fan Room	W4	Flaking paint at column	10	No	No	No	No	No	
291	3424	1	0	002D		Restroom/Storage Room next to B-2 Head Start Office	Ceiling	Flaking paint on pipe	30	No	No	No	No	No	
292	3424	1	0	002D		Restroom/Storage Room next to B-2 Head Start Office	W1	Flaking paint	35	No	No	No	No	No	
293	3424	1	0	002D		Restroom/Storage Room next to B-2 Head Start Office	W2	Flaking paint	20	No	No	No	No	No	
294	3424	1	0	007B		Small Hallway to Boiler Room	Ceiling	Flaking paint	200	No	No	No	No	No	
295	3424	1	0	007B		Small Hallway to Boiler Room	W3	Flaking paint on pipe	10	No	No	No	No	No	
296	3424	1	0	S05		South Stairs to Boiler/Fan Room	Floor	Stairs	30	No	No	No	No	No	
297	3424	1	0	S05		South Stairs to Boiler/Fan Room	W1	Flaking paint at column	15	No	No	No	No	No	
298	3424	1	0	S05		South Stairs to Boiler/Fan Room	W4	Flaking paint at column	15	No	No	No	No	No	
299	3424	1	0	S01		South Stairwell across from Girl's Restroom	W2	Flaking paint	30	No	No	No	No	No	
300	3424	1	0	HB2		Southwest Vestibule to School Yard next to Girl's Restroom	Ceiling	Flaking paint and damaged plaster	20	No	No	No	No	Yes	
301	3424	1	0	HB2		Southwest Vestibule to School Yard next to Girl's Restroom	Floor	Debris	20	No	Floor	20		No	
302	3424	1	0	001B		Storage Closet in North Stairwell outside Gym	Ceiling	Flaking paint	10	No	No	No	No	No	
303	3424	1	0	001C		Storage Closet under stairs in North Stairwell outside Gym	Ceiling	Flaking paint	10	No	No	No	No	No	