

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	7020	1	5	507B		Back Room of Science Closet 509	Ceiling	Cracking paint	30	No	No	N/A	None	No	
2	7020	1	5	501G		Boy's Restroom in closed off area	Ceiling	Damaged plaster	20	No	No	N/A	None	Yes	
3	7020	1	5	501G		Boy's Restroom in closed off area	Floor	Debris	20	No	No	N/A	None	No	
4	7020	1	5	501G		Boy's Restroom in closed off area	W1	Flaking paint and efflorescence	20	No	No	N/A	None	No	
5	7020	1	5	501G		Boy's Restroom in closed off area	W2	Efflorescence	20	No	No	N/A	None	No	
6	7020	1	5	501G		Boy's Restroom in closed off area	W3	Efflorescence	20	No	No	N/A	None	No	
7	7020	1	5	501G		Boy's Restroom in closed off area	W4	Efflorescence	10	No	No	N/A	None	No	
8	7020	1	5	508		Classroom 501	W3	Flaking paint behind radiators	10	No	No	N/A	None	No	
9	7020	1	5	507		Classroom 502	W3	Flaking paint and efflorescence at radiators	45	No	No	N/A	None	No	
10	7020	1	5	505		Classroom 504	W2	Flaking paint	1	No	No	N/A	None	No	
11	7020	1	5	505		Classroom 504	W3	Efflorescence and flaking paint below windows	40	No	No	N/A	None	No	
12	7020	1	5	504		Classroom 505	W2	Damaged plaster at column	1	No	No	N/A	None	Yes	
13	7020	1	5	503		Classroom 506	W3	Flaking paint, efflorescence at radiators	30	No	No	N/A	None	No	
14	7020	1	5	503A		Classroom 506 Closet	Ceiling	No Access - None of the keys worked							Inspection Required
15	7020	1	5	503A		Classroom 506 Closet	Floor	No Access - None of the keys worked							Inspection Required
16	7020	1	5	503A		Classroom 506 Closet	W1	No Access - None of the keys worked							Inspection Required
17	7020	1	5	503A		Classroom 506 Closet	W2	No Access - None of the keys worked							Inspection Required
18	7020	1	5	503A		Classroom 506 Closet	W3	No Access - None of the keys worked							Inspection Required
19	7020	1	5	503A		Classroom 506 Closet	W4	No Access - None of the keys worked							Inspection Required
20	7020	1	5	504A		Closet between Classrooms 503/505	W2	Flaking paint	5	No	No	N/A	None	No	
21	7020	1	5	504A		Closet between Classrooms 503/505	W4	Flaking paint	2	No	No	N/A	None	No	
22	7020	1	5	501H		Girl's Room in closed off area	Ceiling	Spalling paint	25	No	No	N/A	None	No	
23	7020	1	5	501H		Girl's Room in closed off area	W2	Spalling paint	20	No	No	N/A	None	No	
24	7020	1	5	H519		Hallway in closed off area	Ceiling	Damaged plaster	20	No	No	N/A	None	Yes	
25	7020	1	5	H520		Hallway in closed off area	Ceiling	Damaged plaster	20	No	No	N/A	None	Yes	
26	7020	1	5	H519		Hallway in closed off area	Floor	Debris	10	No	No	N/A	None	No	
27	7020	1	5	H520		Hallway in closed off area	Floor	Debris	20	No	No	N/A	None	No	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
28	7020	1	5	H519		Hallway in closed off area	W1	Flaking paint	10	No	No	N/A	None	No	
29	7020	1	5	H520		Hallway in closed off area	W2	Flaking paint	10	No	No	N/A	None	No	
30	7020	1	5	H519		Hallway in closed off area	W2	Flaking paint	30	No	No	N/A	None	No	
31	7020	1	5	H519		Hallway in closed off area	W3	Flaking paint	10	No	No	N/A	None	No	
32	7020	1	5	H520		Hallway in closed off area	W4	Flaking paint and damaged plaster	80	No	No	N/A	None	Yes	
33	7020	1	5	H519		Hallway in closed off area	W4	Flaking paint and efflorescence	100	No	No	N/A	None	No	
34	7020	1	5	501		Music Room in closed off area	Ceiling	Flaking paint and efflorescence	10	No	No	N/A	None	No	
35	7020	1	5	501		Music Room in closed off area	W1	Flaking paint and efflorescence	40	No	No	N/A	None	No	
36	7020	1	5	501		Music Room in closed off area	W2	Flaking paint	10	No	No	N/A	None	No	
37	7020	1	5	501		Music Room in closed off area	W4	Flaking paint and efflorescence at windows	50	No	No	N/A	None	No	
38	7020	1	5	501B		Practice Room 1 in closed off area	W1	Flaking paint	5	No	No	N/A	None	No	
39	7020	1	5	501B		Practice Room 1 in closed off area	W2	Flaking paint and damaged plaster	50	No	No	N/A	None	Yes	
40	7020	1	5	501B		Practice Room 1 in closed off area	W3	Flaking paint and damaged plaster	20	No	No	N/A	None	No	
41	7020	1	5	507A		Science Storage Closet 509 adjacent Classroom 502	Ceiling	Flaking paint	5	No	No	N/A	None	No	
42	7020	1	5	507A		Science Storage Closet 509 adjacent Classroom 502	W3	Flaking paint at radiator	5	No	No	N/A	None	No	
43	7020	1	5	H518B		Secured Hallway 500 on door	Ceiling	Flaking paint and damaged plaster	100	No	No	N/A	None	Yes	
44	7020	1	5	H518B		Secured Hallway 500 on door	Floor	Debris	50	No	No	N/A	None	No	
45	7020	1	5	H518B		Secured Hallway 500 on door	W1	Flaking paint	10	No	No	N/A	None	No	
46	7020	1	5	H518B		Secured Hallway 500 on door	W2	Flaking paint and damaged plaster	50	No	No	N/A	None	Yes	
47	7020	1	5	H518B		Secured Hallway 500 on door	W3	Flaking paint	10	No	No	N/A	None	No	
48	7020	1	5	H518B		Secured Hallway 500 on door	W4	Flaking paint and damaged plaster	50	No	No	N/A	None	Yes	
49	7020	1	5	H520A		Small Hallway in closed off area	Ceiling	Damaged plaster	20	No	No	N/A	None	Yes	
50	7020	1	5	H519A		Small Hallway in closed off area	Floor	Debris	20	No	No	N/A	None	No	
51	7020	1	5	H519A		Small Hallway in closed off area	W1	Flaking paint	10	No	No	N/A	None	No	
52	7020	1	5	H520A		Small Hallway in closed off area	W1	Flaking paint, efflorescence, Damaged plaster	50	No	No	N/A	None	Yes	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
53	7020	1	5	H519A		Small Hallway in closed off area	W2	No wall	30	No	No	N/A	None	No	
54	7020	1	5	H520A		Small Hallway in closed off area	W2	Flaking paint and efflorescence	50	No	No	N/A	None	No	
55	7020	1	5	H519A		Small Hallway in closed off area	W4	Flaking paint and damaged plaster	50	No	No	N/A	None	Yes	
56	7020	1	5	S58		Stairwell by Boy's Restroom in closed off area	Ceiling	Flaking paint and Damaged plaster	20	No	No	N/A	None	Yes	
57	7020	1	5	S58		Stairwell by Boy's Restroom in closed off area	Floor	Debris on stairs	80	No	No	N/A	None	No	
58	7020	1	5	S58		Stairwell by Boy's Restroom in closed off area	W2	Flaking paint	10	No	No	N/A	None	No	
59	7020	1	5	S55		Stairwell by Girl's Restroom in closed off area	Ceiling	Efflorescence and damaged plaster	50	No	No	N/A	None	Yes	
60	7020	1	5	S55		Stairwell by Girl's Restroom in closed off area	Floor	Debris on stairs	30	No	No	N/A	None	No	
61	7020	1	5	S55		Stairwell by Girl's Restroom in closed off area	W3	Flaking paint	20	No	No	N/A	None	No	
62	7020	1	5	S55		Stairwell by Girl's Restroom in closed off area	W4	Flaking paint and Damaged plaster	100	No	No	N/A	None	Yes	
63	7020	1	5	S511		Stairwell leading to abandoned 5th Floor	Ceiling	Flaking paint	30	No	No	N/A	None	No	
64	7020	1	5	S511		Stairwell leading to abandoned 5th Floor	Floor	Debris	30	No	No	N/A	None	No	
65	7020	1	5	S511		Stairwell leading to abandoned 5th Floor	W1	Flaking and cracking paint	50	No	No	N/A	None	No	
66	7020	1	5	S511		Stairwell leading to abandoned 5th Floor	W2	Flaking paint	100	No	No	N/A	None	No	
67	7020	1	5	S511		Stairwell leading to abandoned 5th Floor	W3	Flaking paint	50	No	No	N/A	None	No	
68	7020	1	5	504B		Storage room inside Closet between Classrooms 503/505	W3	Flaking paint	2	No	No	N/A	None	No	
69	7020	1	5	501F		Women's Room in closed off area	Ceiling	Flaking paint	10	No	No	N/A	None	No	
70	7020	1	5	501F		Women's Room in closed off area	W1	Spalling paint	20	No	No	N/A	None	No	
71	7020	1	4	403A		Boy's Restroom	Ceiling	Cracking paint on ceiling above suspended radiator	30	No	No	N/A	None	No	
72	7020	1	4	408		Classroom 405	Ceiling	Efflorescence - front left corner	4	No	No	N/A	None	No	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
73	7020	1	4	407		Classroom 409	Ceiling	Efflorescence, damaged plaster	15	No	No	N/A	None	Yes	
74	7020	1	4	407		Classroom 409	W3	Flaking paint behind radiators	10	No	No	N/A	None	No	
75	7020	1	4	406		Classroom 411	Ceiling	Flaking paint and damaged plaster	25	No	No	N/A	None	Yes	
76	7020	1	4	406		Classroom 411	W3	Flaking paint and efflorescence	10	No	No	N/A	None	No	
77	7020	1	4	406		Classroom 411	W4	Efflorescence	6	No	No	N/A	None	No	
78	7020	1	4	403		Classroom 418	Ceiling	Flaking paint and damaged plaster	6	No	No	N/A	None	Yes	
79	7020	1	4	402		Classroom 421	Ceiling	Faking paint, efflorescence at window	20	No	No	N/A	None	No	
80	7020	1	4	402		Classroom 421	W3	Faking paint, efflorescence at window	10	No	No	N/A	None	No	
81	7020	1	4	401		Classroom 423	Ceiling	Efflorescence	4	No	No	N/A	None	No	
82	7020	1	4	401		Classroom 423	W1	Efflorescence	4	No	No	N/A	None	No	
83	7020	1	4	401		Classroom 423	W3	Efflorescence	4	No	No	N/A	None	No	
84	7020	1	4	426		Classroom 429	Ceiling	Flaking paint	20	No	No	N/A	None	No	
85	7020	1	4	425A		Classroom 431	Ceiling	Flaking paint	10	No	No	N/A	None	No	
86	7020	1	4	425A		Classroom 431	W3	Flaking paint behind radiators	10	No	No	N/A	None	No	
87	7020	1	4	425A		Classroom 431	W4	Damaged plaster by door	2	No	No	N/A	None	Yes	
88	7020	1	4	425		Classroom 433	Ceiling	Damaged plaster, spalling paint	16	No	No	N/A	None	Yes	
89	7020	1	4	422		Classroom 439	Ceiling	Flaking and cracking paint	6	No	No	N/A	None	No	
90	7020	1	4	421		Classroom 447	Ceiling	Flaking paint	10	No	No	N/A	None	No	
91	7020	1	4	421		Classroom 447	W1	Damaged plaster	1	No	No	N/A	None	Yes	
92	7020	1	4	420		Classroom 449	Ceiling	Flaking paint - spread out	10	No	No	N/A	None	No	
93	7020	1	4	419		Classroom 451	Ceiling	Efflorescence	4	No	No	N/A	None	No	
94	7020	1	4	419		Classroom 451	W3	Flaking paint	5	No	No	N/A	None	No	
95	7020	1	4	419		Classroom 451	W4	Flaking paint	3	No	No	N/A	None	No	
96	7020	1	4	414		Classroom 457	Ceiling	Flaking paint	40	No	No	N/A	None	No	
97	7020	1	4	414		Classroom 457	W1	Flaking paint, damaged plaster	3	No	No	N/A	None	Yes	
98	7020	1	4	414		Classroom 457	W2	Flaking paint	10	No	No	N/A	None	No	
99	7020	1	4	414		Classroom 457	W3	Flaking paint behind radiators	10	No	No	N/A	None	No	
100	7020	1	4	414		Classroom 457	W4	Severe efflorescence	40	No	No	N/A	None	No	
101	7020	1	4	413		Classroom 461	W3	Damaged plaster below window	4	No	No	N/A	None	Yes	
102	7020	1	4	412		Classroom 463	W2	Flaking paint	3	No	No	N/A	None	No	
103	7020	1	4	412		Classroom 463	W3	Flaking paint, damaged plaster behind radiators	10	No	No	N/A	None	Yes	
104	7020	1	4	411		Classroom 465	Ceiling	Flaking paint - spread out	5	No	No	N/A	None	No	
105	7020	1	4	424		Computer Room 435	Ceiling	Flaking paint	20	No	No	N/A	None	No	
106	7020	1	4	424		Computer Room 435	W2	Flaking paint on pipe	4	No	No	N/A	None	No	
107	7020	1	4	416		Computer Room 453	Ceiling	Flaking paint	12	No	No	N/A	None	No	
108	7020	1	4	416		Computer Room 453	W3	Flaking paint behind radiators and at window	25	No	Far right window sill	1	None	No	
109	7020	1	4	416		Computer Room 453	W4	Crack in plaster	10	No	No	N/A	None	Yes	
110	7020	1	4	421A		Dean's Office Room 445	Ceiling	Flaking paint	3	No	No	N/A	None	No	
111	7020	1	4	421A		Dean's Office Room 445	W3	Flaking paint	6	No	No	N/A	None	No	
112	7020	1	4	405		Drama Room 413	Ceiling	Efflorescence by door	4	No	No	N/A	None	No	
113	7020	1	4	405		Drama Room 413	W4	Efflorescence by door	4	No	No	N/A	None	No	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
114	7020	1	4	418E		Girl's Restroom	Ceiling	Flaking and cracking paint, efflorescence	100	No	No	N/A	None	No	
115	7020	1	4	404CB		Guidance Office Room 417 Closet Closest to Door	W2	Damaged plaster	2	No	No	N/A	None	Yes	
116	7020	1	4	H416		Hallway from Classrooms 429 to 439	W1	Flaking paint	5	No	No	N/A	None	No	
117	7020	1	4	H417		Hallway from Classrooms 461 to 409	W3	Flaking and spalling paint	20	No	No	N/A	None	No	
118	7020	1	4	410		Music Room 467	W2	Efflorescence at window	10	No	No	N/A	None	No	
119	7020	1	4	410		Music Room 467	W3	Efflorescence and spalling at window	20	No	No	N/A	None	No	
120	7020	1	4	410		Music Room 467	W4	Efflorescence at window	10	No	No	N/A	None	No	
121	7020	1	4	408A		Office 403	Ceiling	Severely damaged plaster ceiling - seen through missing tile	80	No	No	N/A	None	No	
122	7020	1	4	408A		Office 403	W3	Flaking paint on pipe	6	No	No	N/A	None	No	
123	7020	1	4	404B		Office 414	W2	Flaking and spalling paint	10	No	No	N/A	None	No	
124	7020	1	4	404A		Office Room 415	Ceiling	Flaking paint	4	No	No	N/A	None	No	
125	7020	1	4	404A		Office Room 415	W3	Flaking paint behind radiator	10	No	No	N/A	None	No	
126	7020	1	4	402B		Resource Room 419	Ceiling	Flaking paint, damaged plaster, efflorescence	40	No	No	N/A	None	Yes	
127	7020	1	4	409		Staff Lounge 401	Ceiling	Flaking paint and damaged plaster	10	No	No	N/A	None	Yes	
128	7020	1	4	409A		Staff Lounge 401 Closet	Ceiling	Damaged plaster and efflorescence	15	No	No	N/A	None	Yes	
129	7020	1	4	409A		Staff Lounge 401 Closet	Floor	Debris	4	No	No	N/A	None	No	
130	7020	1	4	409A		Staff Lounge 401 Closet	W2	Flaking paint and damaged plaster	10	No	Shelves	30	None	Yes	
131	7020	1	4	409A		Staff Lounge 401 Closet	W4	Flaking paint	15	No	Shelves	30	None	No	
132	7020	1	4	428		Staff Lounge 425	Ceiling	Flaking paint	2	No	No	N/A	None	No	
133	7020	1	4	401B		Staff Lounge 425 Restroom	Ceiling	Flaking paint	8	No	No	N/A	None	No	
134	7020	1	4	415B		Staff Restroom and Storage Room across from Office 455	Ceiling	Flaking paint	10	No	No	N/A	None	No	
135	7020	1	4	S414		Stairwell across from Classroom 449	W2	Flaking paint	10	No	No	N/A	None	No	
136	7020	1	4	S45		Stairwell across from Classroom 461	W2	Flaking paint	2	No	No	N/A	None	No	
137	7020	1	4	S411		Stairwell next to Boy's Restroom	W2	Cracking paint	100	No	No	N/A	None	No	
138	7020	1	4	S411		Stairwell next to Boy's Restroom	W4	Cracking paint	2	No	No	N/A	None	No	
139	7020	1	4	405A		Storage Closet 412 adjacent Elevator	Ceiling	Flaking paint	30	No	No	N/A	None	No	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
140	7020	1	4	405A		Storage Closet 412 adjacent Elevator	W4	Flaking paint	2	No	No	N/A	None	No	
141	7020	1	4	427		Storage Room 427	Ceiling	Flaking paint and damaged plaster	20	No	No	N/A	None	Yes	
142	7020	1	4	427		Storage Room 427	W2	Flaking paint	3	No	No	N/A	None	No	
143	7020	1	4	427		Storage Room 427	W3	Flaking paint	4	No	No	N/A	None	No	
144	7020	1	4	427		Storage Room 427	W4	Crack in plaster	5	No	No	N/A	None	Yes	
145	7020	1	4	421		Storage Room 443	W3	Flaking paint behind radiator	5	No	No	N/A	None	No	
146	7020	1	4	410C		Storage Room in Music Room 467	W1	Flaking paint	3	No	No	N/A	None	No	
147	7020	1	4	410C		Storage Room in Music Room 467	W4	Flaking and spalling paint	10	No	No	N/A	None	No	
148	7020	1	3	305A		Book Closet 314 adjacent Elevator	W1	Damaged plaster	8	No	No	N/A	None	Yes	
149	7020	1	3	305A		Book Closet 314 adjacent Elevator	W2	Damaged plaster	4	No	No	N/A	None	Yes	
150	7020	1	3	305A		Book Closet 314 adjacent Elevator	W3	Damaged plaster	3	No	No	N/A	None	Yes	
151	7020	1	3	305A		Book Closet 314 adjacent Elevator	W4	Damaged plaster	30	No	No	N/A	None	Yes	
152	7020	1	3	320B		Boy's Restroom	Ceiling	Flaking paint and efflorescence	20	No	No	N/A	None	No	
153	7020	1	3	320B		Boy's Restroom	W4	Spalling paint	10	No	No	N/A	None	No	
154	7020	1	3	318A		Chemical Storage in Classroom 355	W2	Flaking paint and efflorescence	10	No	Lab table	2	None	No	
155	7020	1	3	318A		Chemical Storage in Classroom 355	W3	Flaking paint and efflorescence	4	No	No	N/A	None	No	
156	7020	1	3	310		Classroom 303	W3	Flaking paint	4	No	No	N/A	None	No	
157	7020	1	3	310		Classroom 303	W4	Flaking paint at column by door	2	No	No	N/A	None	No	
158	7020	1	3	309		Classroom 305	W1	Flaking paint	2	No	No	N/A	None	No	
159	7020	1	3	309		Classroom 305	W3	Flaking paint	5	No	No	N/A	None	No	
160	7020	1	3	307		Classroom 311	Ceiling	Flaking paint, damaged plaster	20	No	No	N/A	None	Yes	
161	7020	1	3	307		Classroom 311	W1	Flaking paint	1	No	No	N/A	None	No	
162	7020	1	3	307		Classroom 311	W2	Flaking paint at top beam	2	No	No	N/A	None	No	
163	7020	1	3	307		Classroom 311	W3	Efflorescence and flaking paint	5	No	No	N/A	None	No	
164	7020	1	3	307		Classroom 311	W4	Flaking paint	1	No	No	N/A	None	No	
165	7020	1	3	306		Classroom 315	W3	Damaged plaster and flaking paint at radiator	8	No	No	N/A	None	Yes	
166	7020	1	3	306		Classroom 315	W4	Cracking and flaking paint at top beam	6	No	No	N/A	None	No	
167	7020	1	3	303		Classroom 321	Ceiling	Flaking paint	10	No	No	N/A	None	No	
168	7020	1	3	303		Classroom 321	W1	Flaking paint	3	No	No	N/A	None	No	
169	7020	1	3	303		Classroom 321	W2	Flaking paint	5	No	No	N/A	None	No	
170	7020	1	3	303		Classroom 321	W3	Flaking paint	5	No	No	N/A	None	No	
171	7020	1	3	303		Classroom 321	W4	Flaking paint	5	No	No	N/A	None	No	
172	7020	1	3	302		Classroom 323	Ceiling	Flaking paint	10	No	No	N/A	None	No	
173	7020	1	3	302		Classroom 323	W3	Flaking paint behind radiators	10	No	No	N/A	None	No	
174	7020	1	3	301		Classroom 325	W3	Flaking paint behind radiators	30	No	No	N/A	None	No	
175	7020	1	3	332		Classroom 331	W2	Flaking paint	6	No	No	N/A	None	No	
176	7020	1	3	331		Classroom 333	W3	Flaking paint behind radiators	10	No	No	N/A	None	No	
177	7020	1	3	329		Classroom 337	Ceiling	Flaking paint	15	No	No	N/A	None	No	
178	7020	1	3	329		Classroom 337	W1	Flaking paint	1	No	No	N/A	None	No	
179	7020	1	3	329		Classroom 337	W2	Flaking paint	10	No	No	N/A	None	No	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
180	7020	1	3	329		Classroom 337	W3	Flaking paint including behind radiators	15	No	No	N/A	None	No	
181	7020	1	3	328		Classroom 339	W3	Flaking paint behind radiators	10	No	No	N/A	None	No	
182	7020	1	3	327		Classroom 341	W2	Flaking paint at top beam	6	No	No	N/A	None	No	
183	7020	1	3	327		Classroom 341	W3	Flaking paint	4	No	No	N/A	None	No	
184	7020	1	3	327		Classroom 341	W4	Flaking paint at top beam	4	No	No	N/A	None	No	
185	7020	1	3	326		Classroom 343	W3	Flaking paint	3	No	No	N/A	None	No	
186	7020	1	3	325		Classroom 345	W1	Flaking paint	3	No	No	N/A	None	No	
187	7020	1	3	325		Classroom 345	W2	Flaking paint	5	No	No	N/A	None	No	
188	7020	1	3	325		Classroom 345	W3	Flaking paint	20	No	No	N/A	None	No	
189	7020	1	3	325		Classroom 345	W4	Flaking paint at front column by door	2	No	No	N/A	None	No	
190	7020	1	3	323		Classroom 349	Ceiling	Flaking paint at the door	10	No	No	N/A	None	No	
191	7020	1	3	323		Classroom 349	W2	Flaking paint	1	No	No	N/A	None	No	
192	7020	1	3	323		Classroom 349	W3	Flaking paint	30	No	No	N/A	None	No	
193	7020	1	3	322		Classroom 351	W3	Flaking paint	30	No	No	N/A	None	No	
194	7020	1	3	321		Classroom 353	Floor	Debris at left corner	1	No	No	N/A	None	No	
195	7020	1	3	321		Classroom 353	W3	Flaking paint	30	No	No	N/A	None	No	
196	7020	1	3	320		Classroom 354	W3	Flaking paint, efflorescence at window	10	No	No	N/A	None	No	
197	7020	1	3	318		Classroom 355	W3	Flaking paint behind radiators	10	No	No	N/A	None	No	
198	7020	1	3	357C		Classroom 357 Closet by the door	W3	Flaking paint	10	No	No	N/A	None	No	
199	7020	1	3	357B		Classroom 357 Closet on Right Side of Room	W3	Significant flaking paint	20	No	Shelves, clothing, binders, and boxes	20	None	No	
200	7020	1	3	316		Classroom 359	W1	Flaking paint on ductwork	4	No	No	N/A	None	No	
201	7020	1	3	315		Classroom 363	Ceiling	Flaking paint and cracking paint	30	No	No	N/A	None	No	
202	7020	1	3	315		Classroom 363	W3	Flaking paint behind radiators	10	No	No	N/A	None	No	
203	7020	1	3	314		Classroom 365	W3	Flaking paint behind radiators	10	No	No	N/A	None	No	
204	7020	1	3	314		Classroom 365	W4	Cracking paint on beam	6	No	No	N/A	None	No	
205	7020	1	3	313		Classroom 367	W1	Flaking paint	2	No	No	N/A	None	No	
206	7020	1	3	313		Classroom 367	W2	Flaking paint	6	No	No	N/A	None	No	
207	7020	1	3	313		Classroom 367	W3	Flaking paint	2	No	No	N/A	None	No	
208	7020	1	3	311		Classroom 371	W4	Efflorescence at window	10	No	Window sill and books	20	None	No	
209	7020	1	3	306B		Closet outside Office 317	Ceiling	No Access - None of the keys worked							Inspection Required
210	7020	1	3	306B		Closet outside Office 317	Floor	No Access - None of the keys worked							Inspection Required
211	7020	1	3	306B		Closet outside Office 317	W1	No Access - None of the keys worked							Inspection Required
212	7020	1	3	306B		Closet outside Office 317	W2	No Access - None of the keys worked							Inspection Required
213	7020	1	3	306B		Closet outside Office 317	W3	No Access - None of the keys worked							Inspection Required
214	7020	1	3	306B		Closet outside Office 317	W4	No Access - None of the keys worked							Inspection Required
215	7020	1	3	304B		Closet outside Office 319	Ceiling	No Access - None of the keys worked							Inspection Required
216	7020	1	3	304B		Closet outside Office 319	Floor	No Access - None of the keys worked							Inspection Required

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
217	7020	1	3	304B		Closet outside Office 319	W1	No Access - None of the keys worked							Inspection Required
218	7020	1	3	304B		Closet outside Office 319	W2	No Access - None of the keys worked							Inspection Required
219	7020	1	3	304B		Closet outside Office 319	W3	No Access - None of the keys worked							Inspection Required
220	7020	1	3	304B		Closet outside Office 319	W4	No Access - None of the keys worked							Inspection Required
221	7020	1	3	311A		Copy Room 301	W1	Flaking paint	5	No	No	N/A	None	No	
222	7020	1	3	311A		Copy Room 301	W2	Flaking paint	15	No	No	N/A	None	No	
223	7020	1	3	311A		Copy Room 301	W3	Flaking and spalling paint	10	No	No	N/A	None	No	
224	7020	1	3	311A1		Copy Room 301 Closet	Ceiling	Flaking paint on pipe	4	No	No	N/A	None	No	
225	7020	1	3	304B		Girl's Restroom	Ceiling	Cracking paint	5	No	No	N/A	None	No	
226	7020	1	3	304B		Girl's Restroom	W4	Flaking paint on pipe	4	No	No	N/A	None	No	
227	7020	1	3	H314		Hallway from Classrooms 363 to 307	W3	Flaking paint above sink across from Room 363	3	No	No	N/A	None	No	
228	7020	1	3	305C		Nurse's Office 320 next to Classroom 311	Ceiling	Flaking paint	20	No	No	N/A	None	No	
229	7020	1	3	304A		Office 319	Ceiling	Flaking paint	10	No	No	N/A	None	No	
230	7020	1	3	304A		Office 319	W3	Flaking paint	3	No	No	N/A	None	No	
231	7020	1	3	315A		Science Closet 361	W1	Flaking paint on pipe	12	No	No	N/A	None	No	
232	7020	1	3	333		Staff Lounge 327	Ceiling	Flaking paint	20	No	No	N/A	None	No	
233	7020	1	3	333B		Staff Lounge 327 Restroom	Ceiling	Flaking paint, damaged plaster, efflorescence	25	No	No	N/A	None	No	
234	7020	1	3	317B		Staff Restroom 360 across from Classroom 355	Ceiling	Flaking paint	5	No	No	N/A	None	No	
235	7020	1	3	S35		Stairwell across from Classroom 363	W4	Flaking paint	4	No	No	N/A	None	No	
236	7020	1	3	S314		Stairwell next to Boy's Restroom	W4	Cracking paint	4	No	No	N/A	None	No	
237	7020	1	3	S311		Stairwell next to Girl's Restroom	W2	Cracking paint	1	No	No	N/A	None	No	
238	7020	1	3	312A		Storage Closet between Classrooms 367 & 369	Ceiling	No Access							Inspection Required
239	7020	1	3	312A		Storage Closet between Classrooms 367 & 369	Floor	No Access							Inspection Required
240	7020	1	3	312A		Storage Closet between Classrooms 367 & 369	W1	No Access							Inspection Required
241	7020	1	3	312A		Storage Closet between Classrooms 367 & 369	W2	No Access							Inspection Required

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
242	7020	1	3	312A		Storage Closet between Classrooms 367 & 369	W3	No Access							Inspection Required
243	7020	1	3	312A		Storage Closet between Classrooms 367 & 369	W4	No Access							Inspection Required
244	7020	1	3	307A		Storage Room 309	Ceiling	Efflorescence and damaged plaster	10	No	No	N/A	None	Yes	
245	7020	1	3	307A		Storage Room 309	Floor	Debris at pipe	2	No	No	N/A	None	No	
246	7020	1	3	307A		Storage Room 309	W1	Flaking paint	4	No	No	N/A	None	No	
247	7020	1	3	307A		Storage Room 309	W4	Efflorescence, flaking paint on wall and pipe	20	No	Shelf	10	None	No	
248	7020	1	2	200		Balcony	Ceiling	Flaking paint, efflorescence and damaged plaster	200	No	No	N/A	None	Yes	
249	7020	1	2	200		Balcony	W2	Flaking paint and efflorescence	100	No	No	N/A	None	No	
250	7020	1	2	200		Balcony	W4	Efflorescence	20	No	No	N/A	None	No	
251	7020	1	2	207B		Boys Restroom next to Classroom 218	Ceiling	Flaking paint	20	No	No	N/A	None	No	
252	7020	1	2	207B		Boys Restroom next to Classroom 218	W2	Efflorescence	10	No	No	N/A	None	No	
253	7020	1	2	203		Classroom 221	W3	Flaking paint including behind the radiators	30	No	No	N/A	None	No	
254	7020	1	2	202		Classroom 223	W3	Flaking paint	10	No	No	N/A	None	No	
255	7020	1	2	201		Classroom 225	Ceiling	Flaking paint	6	No	No	N/A	None	No	
256	7020	1	2	201		Classroom 225	W3	Efflorescence and damaged plaster at window	5	No	No	N/A	None	Yes	
257	7020	1	2	229		Classroom 231	Ceiling	Cracking paint at beams and flaking paint at window	20	No	No	N/A	None	No	
258	7020	1	2	228		Classroom 233	Ceiling	Cracking paint	4	No	No	N/A	None	No	
259	7020	1	2	228		Classroom 233	W3	Spalling paint at window	10	No	No	N/A	None	No	
260	7020	1	2	227		Classroom 235	Ceiling	Flaking paint at middle column	4	No	No	N/A	None	No	
261	7020	1	2	226		Classroom 237	Ceiling	Flaking paint	3	No	No	N/A	None	No	
262	7020	1	2	226		Classroom 237	W1	Flaking paint	2	No	No	N/A	None	No	
263	7020	1	2	226		Classroom 237	W2	Flaking paint at top beam	6	No	No	N/A	None	No	
264	7020	1	2	225		Classroom 239	Ceiling	Flaking paint including beams	35	No	No	N/A	None	No	
265	7020	1	2	224		Classroom 241	Ceiling	Cracking paint at middle beam	8	No	No	N/A	None	No	
266	7020	1	2	224		Classroom 241	W4	Efflorescence	10	No	No	N/A	None	No	
267	7020	1	2	223		Classroom 243	Ceiling	Flaking paint and efflorescence	10	No	No	N/A	None	No	
268	7020	1	2	221		Classroom 249	Ceiling	Flaking paint	20	No	No	N/A	None	No	
269	7020	1	2	220		Classroom 251	Ceiling	Significant flaking paint	200	No	No	N/A	None	No	Teacher cleans paint debris from the desks and books every day
270	7020	1	2	217		Classroom 257	Ceiling	Flaking paint	20	No	No	N/A	None	No	
271	7020	1	2	217		Classroom 257	W2	Flaking paint	2	No	No	N/A	None	No	
272	7020	1	2	216		Classroom 265	Ceiling	Flaking paint	4	No	No	N/A	None	No	
273	7020	1	2	215		Classroom 269	W3	Flaking paint behind radiators	25	No	No	N/A	None	No	
274	7020	1	2	214		Classroom 271	W1	Flaking paint	4	No	No	N/A	None	No	
275	7020	1	2	219D		Closet outside Office 253	Ceiling	Damaged plaster	3	No	No	N/A	None	Yes	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
276	7020	1	2	219D		Closet outside Office 253	W2	Crack in plaster	4	No	No	N/A	None	Yes	
277	7020	1	2	222		Computer Graphics Room 247	Ceiling	Severe efflorescence	100	No	No	N/A	None	No	
278	7020	1	2	222		Computer Graphics Room 247	W1	Flaking paint	5	No	No	N/A	None	No	
279	7020	1	2	222		Computer Graphics Room 247	W3	Flaking paint behind radiators	20	No	No	N/A	None	No	
280	7020	1	2	219B		Girl's Restroom	Ceiling	Flaking and cracking paint, Efflorescence	20	No	No	N/A	None	No	
281	7020	1	2	219B		Girl's Restroom	W2	Flaking and cracking paint, Efflorescence	10	No	No	N/A	None	No	
282	7020	1	2	219B		Girl's Restroom	W4	Efflorescence	5	No	No	N/A	None	No	
283	7020	1	2	H27		Hallway from Classrooms 247 to 265	W4	Crack in plaster at Room 261	3	No	No	N/A	None	Yes	
284	7020	1	2	212B		Main Office Storage Room	Ceiling	Flaking paint	5	No	No	N/A	None	No	
285	7020	1	2	212C		Main Office Storage Room Closet	Ceiling	Flaking paint, crack in plaster	20	No	No	N/A	None	Yes	
286	7020	1	2	210		Office 207	W2	Flaking paint	2	No	No	N/A	None	No	
287	7020	1	2	209		Office 209	W4	Crack in plaster	2	No	No	N/A	None	Yes	
288	7020	1	2	208		Office 211	Ceiling	Flaking paint	20	No	No	N/A	None	No	
289	7020	1	2	207A		Office 214	W2	Flaking paint	3	No	No	N/A	None	No	
290	7020	1	2	207A		Office 214	W4	Flaking paint and damaged plaster	10	No	No	N/A	None	Yes	
291	7020	1	2	205		Office 217	W3	Flaking paint behind radiator	10	No	No	N/A	None	No	
292	7020	1	2	231		Office 227	Ceiling	Significant flaking paint	70	No	No	N/A	None	No	
293	7020	1	2	218A		Office 255	Ceiling	Flaking paint	20	No	No	N/A	None	No	
294	7020	1	2	216B		Office 261	Ceiling	Significant flaking paint	200	No	No	N/A	None	No	
295	7020	1	2	216A		Office 263	W1	Flaking paint	2	No	No	N/A	None	No	
296	7020	1	2	212D		Principal's Office	Ceiling	Spalling paint at window	1	No	No	N/A	None	No	
297	7020	1	2	212G		Principal's Office Conference Room	Ceiling	Flaking paint seen through missing tile	4	No	No	N/A	None	No	
298	7020	1	2	219A		School Psychologist Office 253	Ceiling	Flaking paint	4	No	No	N/A	None	No	
299	7020	1	2	219A		School Psychologist Office 253	W3	Flaking paint on pipe	6	No	No	N/A	None	No	
300	7020	1	2	213		Staff Lounge 273	W3	Efflorescence at window behind vending machine	5	No	No	N/A	None	No	
301	7020	1	2	S25		Stairwell across from Classroom 265	W2	Cracking paint	5	No	No	N/A	None	No	
302	7020	1	2	S25		Stairwell across from Classroom 265	W4	Flaking paint	4	No	No	N/A	None	No	
303	7020	1	2	S211		Stairwell next to Boy's Restroom	W2	Cracking paint	6	No	No	N/A	None	No	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
304	7020	1	2	S211		Stairwell next to Boy's Restroom	W4	Cracking paint	6	No	No	N/A	None	No	
305	7020	1	2	S214		Stairwell next to Girl's Restroom	W2	Cracking paint	3	No	No	N/A	None	No	
306	7020	1	2	S28		Stairwell next to Office 214	W4	Cracking paint	2	No	No	N/A	None	No	
307	7020	1	2	216C		Storage Room 259	Ceiling	Flaking paint	8	No	No	N/A	None	No	
308	7020	1	2	216C		Storage Room 259	Floor	Debris at window	1	No	No	N/A	None	No	
309	7020	1	2	216C		Storage Room 259	W2	Flaking paint	10	No	No	N/A	None	No	
310	7020	1	2	216C		Storage Room 259	W3	Efflorescence at window by shelf	3	No	Shelf	1	None	No	
311	7020	1	2	216C		Storage Room 259	W4	Flaking paint	5	No	No	N/A	None	No	
312	7020	1	2	217A		Storage Room 260	Ceiling	No Access - Keys did not work							Inspection Required
313	7020	1	2	217A		Storage Room 260	Floor	No Access - Keys did not work							Inspection Required
314	7020	1	2	217A		Storage Room 260	W1	No Access - Keys did not work							Inspection Required
315	7020	1	2	217A		Storage Room 260	W2	No Access - Keys did not work							Inspection Required
316	7020	1	2	217A		Storage Room 260	W3	No Access - Keys did not work							Inspection Required
317	7020	1	2	217A		Storage Room 260	W4	No Access - Keys did not work							Inspection Required
318	7020	1	2	215A		Storage Room 267	Ceiling	Damaged plaster	1	No	No	N/A	None	Yes	
319	7020	1	2	215A		Storage Room 267	W1	Flaking paint on pipe	1	No	No	N/A	None	No	
320	7020	1	2	204A		Storage Room outside Office 219	W1	Cracking paint	10	No	No	N/A	None	No	
321	7020	1	2	207G		Teacher's Lounge 213 Lobby Closet	Ceiling	Damaged plaster	10	No	No	N/A	None	Yes	
322	7020	1	2	207G		Teacher's Lounge 213 Lobby Closet	Floor	Debris	10	No	No	N/A	None	No	
323	7020	1	2	207G		Teacher's Lounge 213 Lobby Closet	W2	Good		No	Debris on top shelf	20	None	No	
324	7020	1	2	207G		Teacher's Lounge 213 Lobby Closet	W3	Crack in plaster	5	No	No	N/A	None	Yes	
325	7020	1	2	207G		Teacher's Lounge 213 Lobby Closet	W4	Crack in plaster	5	No	No	N/A	None	Yes	
326	7020	1	2	207D		Teacher's Lounge 213 Men's Restroom	Ceiling	Flaking paint and efflorescence	10	No	No	N/A	None	No	
327	7020	1	2	207		Teacher's Lounge 213, Main Lounge	Ceiling	Flaking paint and efflorescence	40	No	No	N/A	None	No	
328	7020	1	1	100		Auditorium	Ceiling	Flaking paint	200	No	No	N/A	None	No	
329	7020	1	1	100		Auditorium	W2	Severe efflorescence at window	100	No	No	N/A	None	No	
330	7020	1	1	100		Auditorium	W3	Flaking paint	6	No	No	N/A	None	No	
331	7020	1	1	100		Auditorium	W4	Efflorescence	20	No	No	N/A	None	No	
332	7020	3	1	130D		Boy's Restroom outside Main Gym	Ceiling	Flaking paint	4	No	No	N/A	None	No	
333	7020	1	1	153B		Canned Good Storage attached Office 153	Ceiling	Crack in plaster	4	No	No	N/A	None	Yes	
334	7020	1	1	153B		Canned Good Storage attached Office 153	W1	Crack in plaster	4	No	No	N/A	None	Yes	
335	7020	1	1	153B		Canned Good Storage attached Office 153	W3	Crack in plaster	10	No	No	N/A	None	Yes	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
336	7020	1	1	153B		Canned Good Storage attached Office 153	W4	Crack in plaster	6	No	No	N/A	None	Yes	
337	7020	1	1	112		Classroom 103	W3	Holes in plaster wall	4	No	No	N/A	None	Yes	
338	7020	1	1	110		Classroom 107	W1	Flaking paint	10	No	No	N/A	None	No	
339	7020	1	1	110		Classroom 107	W3	Flaking paint	20	No	No	N/A	None	No	
340	7020	1	1	110		Classroom 107	W4	Flaking paint	10	No	No	N/A	None	No	
341	7020	1	1	109		Classroom 111	Ceiling	Flaking paint	4	No	No	N/A	None	No	
342	7020	1	1	109		Classroom 111	W2	Flaking paint	3	No	No	N/A	None	No	
343	7020	1	1	109		Classroom 111	W3	Flaking paint	1	No	No	N/A	None	No	
344	7020	1	1	109		Classroom 111	W4	Efflorescence and flaking paint	10	No	No	N/A	None	No	
345	7020	1	1	106		Classroom 115	Ceiling	Cracking paint at middle column	10	No	No	N/A	None	No	
346	7020	1	1	104		Classroom 117	W3	Cracking paint at window	20	No	No	N/A	None	No	
347	7020	1	1	105		Classroom 118	Ceiling	Flaking paint at window	5	No	No	N/A	None	No	
348	7020	1	1	105		Classroom 118	W3	Spalling paint at window	20	No	No	N/A	None	No	
349	7020	1	1	103		Classroom 119	W3	Flaking paint on wall including behind radiators	10	No	No	N/A	None	No	
350	7020	1	1	104A		Classroom 120	W1	Flaking paint	3	No	No	N/A	None	No	
351	7020	1	1	104A		Classroom 120	W3	Efflorescence, flaking and spalling paint	25	No	No	N/A	None	No	
352	7020	1	1	120		Classroom 135	Ceiling	Significant flaking paint	150	No	No	N/A	None	No	
353	7020	1	1	120		Classroom 135	W1	Flaking paint	3	No	No	N/A	None	No	
354	7020	1	1	120		Classroom 135	W3	Flaking paint	3	No	No	N/A	None	No	
355	7020	1	1	119D		Classroom 139	W3	Flaking paint	1	No	No	N/A	None	No	
356	7020	1	1	119D		Classroom 139	W4	Flaking paint at column	2	No	No	N/A	None	No	
357	7020	1	1	119E		Classroom 141	W2	Flaking paint	5	No	No	N/A	None	No	
358	7020	1	1	119E		Classroom 141	W3	Flaking paint	5	No	No	N/A	None	No	
359	7020	1	1	118		Classroom 143	Ceiling	Flaking paint on pipe	10	No	No	N/A	None	No	
360	7020	1	1	118A		Classroom 143 Closet	W1	Crack in plaster	3	No	No	N/A	None	Yes	
361	7020	1	1	118A		Classroom 143 Closet	W2	Cracking paint and hole in plaster	15	No	No	N/A	None	No	
362	7020	1	1	118A		Classroom 143 Closet	W3	Cracking paint	20	No	No	N/A	None	No	
363	7020	1	1	118B		Classroom 143 Kitchen	W2	Flaking paint and crack in plaster	10	No	No	N/A	None	Yes	
364	7020	1	1	118B		Classroom 143 Kitchen	W3	Flaking paint	12	No	No	N/A	None	No	
365	7020	3	1	129		Classroom A102	W2	Flaking paint	5	No	No	N/A	None	No	
366	7020	3	1	121		Classroom A105	W4	Flaking paint near door (near ceiling)	4	No	No	N/A	None	No	
367	7020	3	1	121B		Classroom A105 Office	W4	Flaking paint	10	No	No	N/A	None	No	
368	7020	1	1	109A		Closet next to Classroom 107	W2	Severe crack in plaster wall	20	No	No	N/A	None	Yes	
369	7020	1	1	124		East Side Cafeteria	Ceiling	1'x1' ceiling tile		No	No	N/A	None	No	
370	7020	1	1	123		East Side Cafeteria Food Service Area	Ceiling	Crack in plaster at column	4	No	No	N/A	None	Yes	
371	7020	1	1	104L		Exit Lobby near Music Room 125	Ceiling	Flaking paint and efflorescence	5	No	No	N/A	None	No	
372	7020	1	1	104L		Exit Lobby near Music Room 125	W2	Flaking paint	5	No	No	N/A	None	No	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
373	7020	1	1	104B		Girl's Restroom next to Classroom 120	W1	Spalling paint	5	No	No	N/A	None	No	
374	7020	1	1	104B		Girl's Restroom next to Classroom 120	W2	Cracking paint	10	No	No	N/A	None	No	
375	7020	3	1	123R		Gym Teacher's Restroom	Ceiling	Damaged plaster	3	No	No	N/A	None	Yes	
376	7020	3	1	123/124		Gymnasium	Ceiling	Flaking paint on ductwork	15	No	No	N/A	None	No	
377	7020	3	1	123/124		Gymnasium	W1	Flaking paint	10	No	No	N/A	None	No	
378	7020	3	1	123/124		Gymnasium	W2	Flaking paint	10	No	No	N/A	None	No	
379	7020	3	1	123/124		Gymnasium	W3	Flaking paint	10	No	No	N/A	None	No	
380	7020	2	1	T4A		Hall Closet next to Storage Room T4	Ceiling	Flaking paint	2	No	No	N/A	None	No	
381	7020	1	1	116E		Laundry Room outside Special Education Kitchen Room 123/135	W3	Efflorescence	3	No	No	N/A	None	No	
382	7020	1	1	123C		Main Kitchen Dry Storage Room	Ceiling	Flaking paint	5	No	No	N/A	None	No	
383	7020	1	1	123C		Main Kitchen Dry Storage Room	W2	Efflorescence at window	10	No	No	N/A	None	No	
384	7020	1	1	122		Main Kitchen for both Cafeterias located on the 1st floor	Ceiling	Flaking paint and efflorescence near freight elevator and the front service area	25	No	No	N/A	None	No	
385	7020	1	1	122		Main Kitchen for both Cafeterias located on the 1st floor	W3	Efflorescence at window	15	No	No	N/A	None	No	
386	7020	1	1	ML		Main Lobby	Ceiling	Flaking paint at the entrance	3	No	No	N/A	None	No	
387	7020	2	1	T08		Men's Restroom near Custodial Closet T4	Ceiling	Flaking paint	3	No	No	N/A	None	No	
388	7020	1	1	108		Men's Restroom next to Classroom 111	Ceiling	Flaking paint	10	No	No	N/A	None	No	
389	7020	1	1	108		Men's Restroom next to Classroom 111	W1	Spalling near floor	3	No	No	N/A	None	No	
390	7020	1	1	108		Men's Restroom next to Classroom 111	W3	Flaking paint	5	No	No	N/A	None	No	
391	7020	1	1	113A		Men's Restroom next to Main Lobby	W4	Damaged plaster	1 SF	No	No	N/A	None	Yes	
392	7020	3	1	121E		Music Practice Room B attached to Classroom A105	Floor	Debris	10	No	No	N/A	None	No	
393	7020	3	1	121E		Music Practice Room B attached to Classroom A105	W1	Flaking paint	2	No	No	N/A	None	No	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
394	7020	3	1	121E		Music Practice Room B attached to Classroom A105	W2	Flaking paint	10	No	No	N/A	None	No	
395	7020	3	1	121E		Music Practice Room B attached to Classroom A105	W3	Flaking paint	15	No	No	N/A	None	No	
396	7020	3	1	121E		Music Practice Room B attached to Classroom A105	W4	Flaking paint	10	No	No	N/A	None	No	
397	7020	3	1	121C		Music Practice Room E attached to Classroom A105	W1	Flaking paint	10	No	No	N/A	None	No	
398	7020	3	1	121C		Music Practice Room E attached to Classroom A105	W4	Flaking paint	10	No	No	N/A	None	No	
399	7020	1	1	101		Music Room 125	Ceiling	Flaking paint	3	No	No	N/A	None	No	
400	7020	1	1	101		Music Room 125	Floor	Debris near right corner window	3	No	Floor	3	None	No	
401	7020	1	1	101		Music Room 125	W2	Efflorescence at right corner window			Window sill	2			
402	7020	1	1	106B		Office 114	Ceiling	Flaking paint and crack in plaster	10	No	No	N/A	None	Yes	
403	7020	1	1	106A		Office 116	W2	Spalling paint	30	No	No	N/A	None	No	
404	7020	1	1	120A		Office 136	Ceiling	Efflorescence at window	10	No	No	N/A	None	No	
405	7020	1	1	120A		Office 136	W1	Crack in plaster	8	No	No	N/A	None	Yes	
406	7020	1	1	120A		Office 136	W2	Crack in plaster	3	No	No	N/A	None	Yes	
407	7020	1	1	120A		Office 136	W3	Crack in plaster	3	No	No	N/A	None	Yes	
408	7020	1	1	117A		Office 145	Ceiling	Flaking paint by window	5	No	No	N/A	None	No	
409	7020	1	1	117A		Office 145	W1	Crack in plaster	8	No	No	N/A	None	Yes	
410	7020	1	1	117A		Office 145	W2	Damaged plaster	1	No	No	N/A	None	Yes	
411	7020	1	1	118C		Office 146	Ceiling	Flaking paint and efflorescence - spread out	20	No	No	N/A	None	No	
412	7020	1	1	118C		Office 146	W3	Spalling at air conditioner	3	No	No	N/A	None	No	
413	7020	1	1	153		Office 153	Ceiling	Efflorescence at curved part of ceiling	10	No	No	N/A	None	No	
414	7020	1	1	122A		Office in Main Kitchen for both Cafeterias located on the 1st floor	W4	Flaking paint by conduits	5	No	No	N/A	None	No	
415	7020	3	1	H122.3		Old Gym Lobby	W2	Significant flaking paint at the lower part of the Lobby	200	No	No	N/A	None	No	
416	7020	1	1	114		Parent meeting Room 151	W3	Spalling at column	10	No	No	N/A	None	No	
417	7020	1	1	103L		School Exit Lobby near Classroom 143	W1	Cracking and spalling paint at arch	5	No	No	N/A	None	No	
418	7020	1	1	102L		School Exit Lobby near Office 136	Ceiling	Flaking and spalling paint	10	No	No	N/A	None	No	
419	7020	1	1	102L		School Exit Lobby near Office 136	W1	Spalling paint at arch	3	No	No	N/A	None	No	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
420	7020	1	1	102L		School Exit Lobby near Office 136	W4	Spalling paint	5	No	No	N/A	None	No	
421	7020	1	1	113		School Police Office near Main Lobby	Ceiling	Cracking paint near window	10	No	No	N/A	None	No	
422	7020	1	1	113		School Police Office near Main Lobby	W4	Cracking paint	12	No	No	N/A	None	No	
423	7020	1	1	107		Security Office off exit lobby by Classroom 103	Ceiling	Cracking and flaking paint	10	No	No	N/A	None	No	
424	7020	1	1	107		Security Office off exit lobby by Classroom 103	W1	Cracking paint	5	No	No	N/A	None	No	
425	7020	1	1	119A		Special Ed Office 144	W3	Spalling paint at window	5	No	No	N/A	None	No	
426	7020	1	1	116A		Special Education Kitchen Room 123/135	W3	Damaged plaster at window	20	No	No	N/A	None	Yes	
427	7020	1	1	116B		Special Education Kitchen Room 123/135 Closet	W3	Crack in plaster	10	No	No	N/A	None	Yes	
428	7020	1	1	115		Special Education Room 121	W2	Severe efflorescence at far right window	30	No	No	N/A	None	No	
429	7020	1	1	115A		Special Education Room 121 Control Room	Ceiling	Efflorescence	2	No	No	N/A	None	No	
430	7020	1	1	115A		Special Education Room 121 Control Room	W2	Severe efflorescence at window	20	No	No	N/A	None	No	
431	7020	1	1	100 STAGE		Stage	W3	Cracking paint (behind curtains)	50	No	No	N/A	None	No	
432	7020	1	1	S18		Stairwell across from Classroom 111	W3	Cracking paint	5	No	No	N/A	None	No	
433	7020	1	1	S18		Stairwell across from Classroom 111	W4	Cracking paint	3	No	No	N/A	None	No	
434	7020	1	1	S114		Stairwell next to Boy's Restroom	W3	Cracking paint	2	No	No	N/A	None	No	
435	7020	1	1	S111		Stairwell next to Girl's Restroom	W3	Flaking and cracking paint	10	No	No	N/A	None	No	
436	7020	1	1	S16		Stairwell to the right of Main Entrance	Ceiling	Efflorescence	10	No	No	N/A	None	No	
437	7020	1	1	S16		Stairwell to the right of Main Entrance	W1	Efflorescence	10	No	No	N/A	None	No	
438	7020	1	1	S16		Stairwell to the right of Main Entrance	W4	Flaking paint	20	No	No	N/A	None	No	
439	7020	2	1	T2		STM Locker Room T2	W1	Flaking paint at window	1	No	No	N/A	None	No	
440	7020	1	1	101A		STM Lounge 123	W2	Cracking paint	3	No	No	N/A	None	No	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
441	7020	1	1	101D		STM Room next to East Side Cafeteria - Room 127	W3	Crack in plaster	3	No	No	N/A	None	Yes	
442	7020	1	1	101C		STM Storage next to Music Room 125	Ceiling	Flaking paint and damaged plaster	50	No	No	N/A	None	Yes	
443	7020	1	1	101C		STM Storage next to Music Room 125	W2	Flaking paint	15	No	No	N/A	None	No	
444	7020	1	1	101C		STM Storage next to Music Room 125	W4	Flaking paint	5	No	No	N/A	None	No	
445	7020	2	1	T1		Storage Room T1	Ceiling	Flaking paint on ductwork	3	No	No	N/A	None	No	
446	7020	2	1	T1		Storage Room T1	W1	Flaking paint at window	5	No	No	N/A	None	No	
447	7020	2	1	T1		Storage Room T1	W2	Flaking paint	10	No	No	N/A	None	No	
448	7020	1	1	153C		Uniform Storage Room attached to Office 153	Ceiling	Crack in plaster	2	No	No	N/A	None	Yes	
449	7020	1	1	153C		Uniform Storage Room attached to Office 153	W1	Crack in plaster	3	No	No	N/A	None	Yes	
450	7020	1	1	153C		Uniform Storage Room attached to Office 153	W2	Crack in plaster	6	No	No	N/A	None	Yes	
451	7020	1	1	153C		Uniform Storage Room attached to Office 153	W3	Crack in plaster	20	No	No	N/A	None	Yes	
452	7020	1	1	153C		Uniform Storage Room attached to Office 153	W4	Crack in plaster	20	No	No	N/A	None	Yes	
453	7020	1	1	121		West Side Cafeteria	W2	Flaking paint at column of mural	2	No	No	N/A	None	No	
454	7020	3	0	BB3		Basement Boy's Locker Room	Ceiling	Flaking paint on ductwork	25	No	No	N/A	None	No	
455	7020	3	0	BG1-4		Basement Girl's Locker Room and associated	Ceiling	Flaking paint on ductwork and drain pipes	20	No	No	N/A	None	No	
456	7020	1	0	22		Building Engineer's Office	Ceiling	Damaged plaster	20	No	No	N/A	None	Yes	
457	7020	1	0	21		Camelot Cafeteria	Ceiling	Flaking paint on ceiling and ductwork	250	No	No	N/A	None	No	
458	7020	1	0	21		Camelot Cafeteria	W1	Flaking paint and efflorescence	20	No	No	N/A	None	No	
459	7020	1	0	21		Camelot Cafeteria	W2	Flaking paint and efflorescence	20	No	No	N/A	None	No	
460	7020	1	0	21		Camelot Cafeteria	W3	Flaking paint on radiators	50	No	No	N/A	None	No	
461	7020	1	0	21		Camelot Cafeteria	W4	Efflorescence	10	No	No	N/A	None	No	
462	7020	1	0	20		Camelot Gym	Ceiling	Flaking paint on ceiling and ductwork	300	No	No	N/A	None	No	
463	7020	1	0	20		Camelot Gym	W1	Flaking paint and efflorescence	30	No	No	N/A	None	No	
464	7020	1	0	20		Camelot Gym	W2	Flaking paint and efflorescence	10	No	No	N/A	None	No	
465	7020	1	0	20		Camelot Gym	W3	Flaking paint and efflorescence	40	No	No	N/A	None	No	
466	7020	1	0	20		Camelot Gym	W4	Flaking paint and efflorescence	25	No	No	N/A	None	No	
467	7020	1	0	007B		Classroom 11 or E3	Ceiling	Flaking paint on ceiling, ductwork, and pipe	15	No	No	N/A	None	No	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
468	7020	1	0	002		Classroom 2 or T9	W3	Efflorescence by far left window	10	No	No	N/A	None	No	
469	7020	1	0	008A		Classroom E5	Ceiling	Flaking paint	3	No	No	N/A	None	No	
470	7020	1	0	008		Classroom E6	Ceiling	Flaking paint on ductwork	5	No	No	N/A	None	No	
471	7020	1	0	008		Classroom E6	W3	Flaking paint on pipes	10	No	No	N/A	None	No	
472	7020	1	0	004B		Classroom T12 or 8	Ceiling	Minor Flaking paint on ductwork and pipe	10	No	No	N/A	None	No	
473	7020	1	0	016G		Closet to the left of Special Education Gym Entrance	Ceiling	Efflorescence	10	No	No	N/A	None	No	
474	7020	1	0	016F		Closet to the right of Special Education Gym Entrance	Ceiling	Flaking paint	3	No	No	N/A	None	No	
475	7020	1	0	016F		Closet to the right of Special Education Gym Entrance	W1	Flaking paint	1	No	No	N/A	None	No	
476	7020	1	0	21C		Coat closet in stairwell at Camelot Cafeteria	Ceiling	Flaking paint	15	No	No	N/A	None	No	
477	7020	1	0	21C		Coat closet in stairwell at Camelot Cafeteria	W2	Flaking paint	20	No	No	N/A	None	No	
478	7020	1	0	21C		Coat closet in stairwell at Camelot Cafeteria	W4	Flaking paint	5	No	No	N/A	None	No	
479	7020	1	0	003B		Daycare Hall Closet - Stroller parking	Ceiling	Flaking paint	10	No	No	N/A	None	No	
480	7020	1	0	001A		Daycare Restroom near Office Suite T8 or 1	Ceiling	Flaking paint	10	No	No	N/A	None	No	
481	7020	1	0	13		Electrical Room	W2	Flaking paint on wall, pipe, and duct work	20	No	No	N/A	None	No	
482	7020	1	0	016E		Gym Office Storage Closet	Ceiling	Damaged plaster and flaking paint	25	No	No	N/A	None	Yes	
483	7020	1	0	016E		Gym Office Storage Closet	W4	Spalling paint	10	No	No	N/A	None	No	
484	7020	1	0	H04		Hallway outside Boiler Room Access Points	Ceiling	Ductwork	10	No	No	N/A	None	No	
485	7020	1	0	H02		Hallway outside Classroom 2	Ceiling	Ductwork	30	No	No	N/A	None	No	
486	7020	1	0	H03		Hallway outside Classroom E7	Ceiling	Ductwork	6	No	No	N/A	None	No	
487	7020	1	0	H03		Hallway outside Classroom E7	W3	Flaking paint on pipe	3	No	No	N/A	None	No	
488	7020	1	0	H01		Hallway outside Classroom G35	Ceiling	Ductwork	30	No	No	N/A	None	No	
489	7020	1	0	005		History Classroom T13	W1	Crack in plaster	2	No	No	N/A	None	Yes	
490	7020	1	0	005		History Classroom T13	W3	Flaking paint on pipes	20	No	No	N/A	None	No	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
491	7020	1	0	018		Library	Ceiling	Severe efflorescence and flaking paint in the rear part of the library	600	No	No	N/A	None	Yes	
492	7020	1	0	018		Library	Floor	Debris in the rear part of the library	20	No	No	N/A	None	No	
493	7020	1	0	018E		Library Storage Room 1	Ceiling	Cracking paint	20	No	No	N/A	None	No	
494	7020	1	0	018E		Library Storage Room 1	W1	Flaking paint on pipe	8	No	No	N/A	None	No	
495	7020	1	0	018E		Library Storage Room 1	W2	Flaking paint on brick wall	20	No	No	N/A	None	No	
496	7020	1	0	018E		Library Storage Room 1	W3	Efflorescence and flaking paint	30	No	No	N/A	None	No	
497	7020	1	0	018F		Library Storage Room 2	W3	Efflorescence	15	No	No	N/A	None	No	
498	7020	1	0	018D		Library Storage Room 3	W3	Efflorescence	40	No	No	N/A	None	No	
499	7020	1	0	018G		Library Storage Room 4	Ceiling	Damaged plaster and flaking paint	50	No	No	N/A	None	Yes	
500	7020	1	0	018B		Library Storage Room 5	Ceiling	Severe efflorescence	120	No	No	N/A	None	No	
501	7020	1	0	018C		Library Storage Room 5	W1	Flaking paint	4	No	Debris on top shelf	30	None	No	
502	7020	1	0	1		Office Suite T8 or 1	W3	Efflorescence at window in Ms. Vega's Office	15	No	No	N/A	None	No	
503	7020	1	0	17B		Restroom behind Special Education gym	Ceiling	Flaking paint	100	No	No	N/A	None	No	
504	7020	1	0	17B		Restroom behind Special Education gym	W1	Flaking paint	10	No	No	N/A	None	No	
505	7020	1	0	17B		Restroom behind Special Education gym	W2	Flaking paint	10	No	No	N/A	None	No	
506	7020	1	0	17B		Restroom behind Special Education gym	W3	Flaking paint	5	No	No	N/A	None	No	
507	7020	1	0	17B		Restroom behind Special Education gym	W4	Flaking paint	10	No	No	N/A	None	No	
508	7020	1	0	007		Science Classroom E2	Ceiling	Flaking paint on ductwork	3	No	No	N/A	None	No	
509	7020	1	0	016		Special Education Gym	Ceiling	Flaking paint on ceiling and ductwork	100	No	No	N/A	None	No	
510	7020	1	0	016		Special Education Gym	W3	Flaking paint	25	No	No	N/A	None	No	
511	7020	1	0	016		Special Education Gym	W4	Flaking paint	20	No	No	N/A	None	No	
512	7020	1	0	016A		Special Education Gym Locker Room	W3	Damaged plaster	2	No	No	N/A	None	Yes	
513	7020	1	0	016B		Special Education Gym Office	Ceiling	Flaking paint and efflorescence, damaged plaster	40	No	No	N/A	None	Yes	
514	7020	1	0	016B		Special Education Gym Office	W1	Flaking paint and efflorescence	20	No	No	N/A	None	No	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Fl oor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
515	7020	1	0	016B		Special Education Gym Office	W3	Flaking paint and efflorescence	20	No	No	N/A	None	No	
516	7020	1	0	016D		Special Education Gym Office Restroom	Ceiling	Flaking paint and damaged plaster	4	No	No	N/A	None	Yes	
517	7020	1	0	15		Storage Room	Ceiling	No Access - Outside contractor has this area							Inspection Required
518	7020	1	0	15		Storage Room	Floor	No Access - Outside contractor has this area							Inspection Required
519	7020	1	0	15		Storage Room	W1	No Access - Outside contractor has this area							Inspection Required
520	7020	1	0	15		Storage Room	W2	No Access - Outside contractor has this area							Inspection Required
521	7020	1	0	15		Storage Room	W3	No Access - Outside contractor has this area							Inspection Required
522	7020	1	0	15		Storage Room	W4	No Access - Outside contractor has this area							Inspection Required
523	7020	1	0	016C		Storage Room across from Classroom G35	Ceiling	Damaged plaster	10	No	No	N/A	None	Yes	
524	7020	1	0	016C		Storage Room across from Classroom G35	W2	Efflorescence	30	No	No	N/A	None	No	
525	7020	1	0	016C		Storage Room across from Classroom G35	W3	Efflorescence	30	No	No	N/A	None	No	
526	7020	1	0	19		Storage Room across from Fan Room #3 (006) - Inspected from the entrance, too much clutter	Ceiling	Flaking paint	250	No	No	N/A	None	No	
527	7020	1	0	19		Storage Room across from Fan Room #3 (006) - Inspected from the entrance, too much clutter	Floor	Debris	50	No	No	N/A	None	No	
528	7020	1	0	19		Storage Room across from Fan Room #3 (006) - Inspected from the entrance, too much clutter	W1	Flaking paint	40	No	No	N/A	None	No	
529	7020	1	0	19		Storage Room across from Fan Room #3 (006) - Inspected from the entrance, too much clutter	W2	Flaking paint	40	No	No	N/A	None	No	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	Element	Fl oor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
530	7020	1	0	19		Storage Room across from Fan Room #3 (006) - Inspected from the entrance, too much clutter	W3	Flaking paint	40	No	No	N/A	None	No	
531	7020	1	0	19		Storage Room across from Fan Room #3 (006) - Inspected from the entrance, too much clutter	W4	Flaking paint	40	No	No	N/A	None	No	
532	7020	1	0	17		Storage room behind Special Education gym	Ceiling	Flaking paint, damaged plaster, efflorescence	120	No	No	N/A	None	Yes	
533	7020	1	0	016F		Storage room inside Special Education Gym Locker Room	Ceiling	Damaged plaster and efflorescence	35	No	No	N/A	None	Yes	
534	7020	1	0	016F		Storage room inside Special Education Gym Locker Room	Floor	Debris on floor and gym balls	30	No	Floor, Gym balls	30	None	No	
535	7020	1	0	016F		Storage room inside Special Education Gym Locker Room	W2	Efflorescence	20	No	No	N/A	None	No	
536	7020	1	0	016F		Storage room inside Special Education Gym Locker Room	W3	Efflorescence and flaking paint	100	No	No	N/A	None	No	
537	7020	1	0	016F		Storage room inside Special Education Gym Locker Room	W4	Efflorescence and flaking paint	40	No	No	N/A	None	No	
538	7020	1	0	010C		Storage Room to the left of Women's Restroom	Ceiling	Flaking paint on suspended radiator	20	No	No	N/A	None	No	
539	7020	1	0	001B		Storage Room to the left of Women's Restroom	W2	Flaking paint	30	No	No	N/A	None	No	
540	7020	1	0	001B		Storage Room to the left of Women's Restroom	W3	Flaking paint	3	No	No	N/A	None	No	
541	7020	1	0	001B		Storage Room to the left of Women's Restroom	W4	Flaking paint	3	No	No	N/A	None	No	

Olney HS (ASPIRA) -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
542	7020	1	0	001B		Storage Room to the right of Women's Restroom	Ceiling	Flaking paint	5	No	No	N/A	None	No	
543	7020	1	0	001B		Storage Room to the right of Women's Restroom	W1	Flaking paint and cracking paint	20	No	No	N/A	None	No	
544	7020	1	0	008B		Student Restroom next to Classroom E6	Ceiling	Flaking paint	10	No	No	N/A	None	No	
545	7020	1	0	008C		Student Services Office E1	W1	Flaking paint	20	No	No	N/A	None	No	
546	7020	1	0	008C		Student Services Office E1	W4	Flaking paint	20	No	No	N/A	None	No	
547	7020	1	0	010B		Women's Restroom near Classroom G35	Ceiling	Flaking paint on ceiling, pipe and radiator	40	No	No	N/A	None	No	