

Penrose -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	1190	TB Reed/Motivation	2	206A		Boy's Restroom across from Classroom 203	W1	Cracking paint by toilet in first stall	5	No	None		No	No	
2	1190	TB Reed/Motivation	2	206A		Boy's Restroom across from Classroom 203	W3	Cracking paint at column and window	25	No	None		No	No	
3	1190	TB Reed/Motivation	2	201		Classroom 201	Floor	Debris at the corner of Walls 3 & 4	3	No	Floor	3	No	No	
4	1190	TB Reed/Motivation	2	201		Classroom 201	W1	Peeling paint on wall and blackboard dividers	20	No	None		No	No	
5	1190	TB Reed/Motivation	2	201		Classroom 201	W2	Severe peeling paint	50	No	None		No	No	
6	1190	TB Reed/Motivation	2	201		Classroom 201	W3	Efflorescence at right corner of the wall	10	No	None		No	No	
7	1190	TB Reed/Motivation	2	201A		Classroom 201 Storage Closet	Floor	Debris	25	No	Floor	25	No	No	
8	1190	TB Reed/Motivation	2	201A		Classroom 201 Storage Closet	W2	Severe peeling paint and efflorescence	50	No	None		No	No	
9	1190	TB Reed/Motivation	2	201A		Classroom 201 Storage Closet	W3	Severe peeling paint and efflorescence	50	No	None		No	No	
10	1190	TB Reed/Motivation	2	201A		Classroom 201 Storage Closet	W4	Spalling paint	5	No	None		No	No	
11	1190	TB Reed/Motivation	2	202		Classroom 202	W1	Damaged plaster by door, Peeling paint under paper dispenser	5	No	None		No	No	
12	1190	TB Reed/Motivation	2	202		Classroom 202	W2	Peeling paint and debris on blackboard ledge	20	No	Blackboard ledge	16	No	No	
13	1190	TB Reed/Motivation	2	202		Classroom 202	W3	Peeling paint on columns	10	No	None		No	No	
14	1190	TB Reed/Motivation	2	202A		Classroom 202 Storage Closet	W2	Chipping paint	20	No	None		No	No	
15	1190	TB Reed/Motivation	2	202A		Classroom 202 Storage Closet	W3	Chipping paint on wall and window sill	10	No	None		No	No	
16	1190	TB Reed/Motivation	2	203		Classroom 203	W1	Peeling paint on blackboard, damaged plaster	20	No	None		No	Yes	
17	1190	TB Reed/Motivation	2	203		Classroom 203	W2	Peeling paint on wood divider wall	40	No	None		No	No	
18	1190	TB Reed/Motivation	2	203		Classroom 203	W3	Peeling paint at column	3	No	None		No	No	
19	1190	TB Reed/Motivation	2	203		Classroom 203	W4	Peeling and Cracking paint	50	No	None		No	No	
20	1190	TB Reed/Motivation	2	203A		Classroom 203 Far Storage Closet	Floor	Debris	5	No	Floor	5	No	No	
21	1190	TB Reed/Motivation	2	203A		Classroom 203 Far Storage Closet	W1	Peeling paint on door frame	8	No	None		No	No	
22	1190	TB Reed/Motivation	2	203A		Classroom 203 Far Storage Closet	W2	Peeling paint on window sill	4	No	None		No	No	
23	1190	TB Reed/Motivation	2	203A		Classroom 203 Far Storage Closet	W3	Cracking paint and debris on table	10	No	Table	6	No	No	
24	1190	TB Reed/Motivation	2	203B		Classroom 203 Storage Closet near Entrance Door	W4	Peeling paint and crack in the wall	30	No	None		No	No	

Penrose -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
25	1190	TB Reed/Motivation	2	204		Classroom 204	W1	Cracking paint	5	No	None		No	No	
26	1190	TB Reed/Motivation	2	204		Classroom 204	W2	Cracking paint at plenum	10	No	None		No	No	
27	1190	TB Reed/Motivation	2	204		Classroom 204	W3	Cracking paint at column	8	No	None		No	No	
28	1190	TB Reed/Motivation	2	204		Classroom 204	W4	Peeling paint at spots	5	No	None		No	No	
29	1190	TB Reed/Motivation	2	204A		Classroom 204 Storage Closet	Ceiling	Peeling paint - above ceiling - visible through missing tile	4	No	None		No	No	
30	1190	TB Reed/Motivation	2	204A		Classroom 204 Storage Closet	Floor	Debris on floor and boxes	45	No	Boxes	45	No	No	
31	1190	TB Reed/Motivation	2	204A		Classroom 204 Storage Closet	W1	Severe peeling paint	50	No	None		No	No	
32	1190	TB Reed/Motivation	2	204A		Classroom 204 Storage Closet	W2	Severe peeling paint	30	No	None		No	No	
33	1190	TB Reed/Motivation	2	204A		Classroom 204 Storage Closet	W3	Severe peeling paint and efflorescence	50	No	None		No	No	
34	1190	TB Reed/Motivation	2	204A		Classroom 204 Storage Closet	W4	Cracking paint	20	No	None		No	No	
35	1190	TB Reed/Motivation	2	205		Classroom 205	W1	Peeling paint on walls and plenums	40	No	None		No	No	
36	1190	TB Reed/Motivation	2	205		Classroom 205	W2	Peeling paint at spots	5	No	None		No	No	
37	1190	TB Reed/Motivation	2	205		Classroom 205	W3	Peeling paint on wall and columns, Cracking paint at the top of window, Damaged plaster at closet entrance	40	No	None		No	Yes	
38	1190	TB Reed/Motivation	2	205		Classroom 205	W4	Peeling paint - Spread out	50	No	None		No	No	
39	1190	TB Reed/Motivation	2	205A		Classroom 205 Storage Closet	W3	Cracking and Spalling paint	20	No	None		No	No	
40	1190	TB Reed/Motivation	2	207		Girl's Restroom across from Classroom 203	W3	Peeling paint at column	10	No	None		No	No	
41	1190	TB Reed/Motivation	2	H21		Hallway from Classroom 201 to Classroom 205	W2	Cracking paint and efflorescence	70	No	None		No	No	
42	1190	TB Reed/Motivation	2	H21		Hallway from Classroom 201 to Classroom 205	W4	Cracking paint	50	No	None		No	No	
43	1190	TB Reed/Motivation	2	203A		Room 206 Teacher's Lounge next to Women's Restroom	W1	Peeling paint	5	No	None		No	No	
44	1190	TB Reed/Motivation	2	203A		Room 206 Teacher's Lounge next to Women's Restroom	W2	Peeling paint at window sill	8	No	None		No	No	
45	1190	TB Reed/Motivation	2	203A		Room 206 Teacher's Lounge next to Women's Restroom	W3	Peeling paint at window guard rail	5	No	None		No	No	

Penrose -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
46	1190	TB Reed/Motivation	2	203A		Room 206 Teacher's Lounge next to Women's Restroom	W4	Cracking paint	5	No	None		No	No	
47	1190	TB Reed/Motivation	2	206		Room 208 MDF	W1	Cracking paint	5	No	None		No	No	
48	1190	TB Reed/Motivation	2	206		Room 208 MDF	W3	Peeling and cracking paint at window	10	No	None		No	No	
49	1190	TB Reed/Motivation	2	206		Room 208 MDF	W4	Peeling paint at spots	4	No	None		No	No	
50	1190	TB Reed/Motivation	2	207A		Room 211 Storage across from Classroom 203	Ceiling	Peeling paint	30	No	None		No	No	
51	1190	TB Reed/Motivation	2	207A		Room 211 Storage across from Classroom 203	W1	Peeling paint and efflorescence	30	No	None		No	No	
52	1190	TB Reed/Motivation	2	207A		Room 211 Storage across from Classroom 203	W2	Peeling and cracking paint, Efflorescence	100	No	None		No	No	
53	1190	TB Reed/Motivation	2	207A		Room 211 Storage across from Classroom 203	W3	Cracking paint	30	No	None		No	No	
54	1190	TB Reed/Motivation	2	201A		Room between Elevator and Stairwell (Possible Attic Access)	Ceiling	Damaged plaster - Plaster was partially removed to install stairwell to attic	40	No	None		No	No	
55	1190	TB Reed/Motivation	2	S22		Stairwell near Classrooms 201 and 202	W3	Cracking paint	150	No	None		No	No	
56	1190	TB Reed/Motivation	2	S22		Stairwell near Classrooms 201 and 202	W4	Cracking paint	50	No	None		No	No	
57	1190	TB Reed/Motivation	2	S21		Stairwell near Room 206 Teacher's Lounge	W1	Peeling and Cracking paint	150	No	None		No	No	
58	1190	TB Reed/Motivation	2	S21		Stairwell near Room 206 Teacher's Lounge	W2	Peeling and Cracking paint	150	No	None		No	No	
59	1190	TB Reed/Motivation	2	S21		Stairwell near Room 206 Teacher's Lounge	W3	Peeling and Cracking paint	150	No	None		No	No	
60	1190	TB Reed/Motivation	2	S21		Stairwell near Room 206 Teacher's Lounge	W4	Peeling and Cracking paint	50	No	None		No	No	
61	1190	TB Reed/Motivation	2	S22		Stairwell near Classrooms 201 and 202	W1	Cracking paint	150	No	None		No	No	
62	1190	TB Reed/Motivation	2	S22		Stairwell near Classrooms 201 and 202	W2	Cracking paint	100	No	None		No	No	
63	1190	TB Reed/Motivation	2	204A		Women's Restroom	W1	Peeling and Cracking paint	30	No	None		No	No	
64	1190	TB Reed/Motivation	2	204A		Women's Restroom	W2	Peeling and Cracking paint	45	No	None		No	No	

Penrose -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
65	1190	TB Reed/Motivation	2	204A		Women's Restroom	W3	Peeling and Cracking paint	55	No	None		No	No	
66	1190	TB Reed/Motivation	1	100A		CASST Office in Middle	W4	Peeling paint on drywall wall	4	No	None		No	No	
67	1190	TB Reed/Motivation	1	100B		CASST Office on Left	W2	Peeling paint on drywall wall and window sill	20	No	None		No	No	
68	1190	TB Reed/Motivation	1	100		CASST Office on Right	W4	Peeling paint on drywall wall	6	No	None		No	No	
69	1190	TB Reed/Motivation	1	100Z		CASST Offices Waiting Area	W1	Peeling paint on drywall wall	5	No	None		No	No	
70	1190	TB Reed/Motivation	1	100Z		CASST Offices Waiting Area	W2	Peeling paint on drywall wall	10	No	None		No	No	
71	1190	TB Reed/Motivation	1	100Z		CASST Offices Waiting Area	W3	Peeling paint on drywall wall	2	No	None		No	No	
72	1190	TB Reed/Motivation	1	100Z		CASST Offices Waiting Area	W4	Peeling paint on drywall wall	4	No	None		No	No	
73	1190	TB Reed/Motivation	1	101		Classroom 101	W1	Peeling paint and spalling paint	10	No	None		No	No	
74	1190	TB Reed/Motivation	1	101		Classroom 101	W2	Peeling and cracking paint	30	No	None		No	No	
75	1190	TB Reed/Motivation	1	101		Classroom 101	W3	Chipping paint at columns	10	No	None		No	No	
76	1190	TB Reed/Motivation	1	101		Classroom 101	W4	Cracking paint	5	No	None		No	No	
77	1190	TB Reed/Motivation	1	101A		Classroom 101 Storage Closet	W1	Peeling paint by door	5	No	None		No	No	
78	1190	TB Reed/Motivation	1	101A		Classroom 101 Storage Closet	W2	Severe peeling paint and efflorescence	70	No	None		No	Yes	
79	1190	TB Reed/Motivation	1	101A		Classroom 101 Storage Closet	W3	Severe peeling paint, efflorescence, debris on window sill	50	No	Window sill	5	Shelves with DVDs	No	
80	1190	TB Reed/Motivation	1	102		Classroom 102	W1	Peeling and cracking paint	20	No	None		No	No	
81	1190	TB Reed/Motivation	1	102		Classroom 102	W2	Peeling paint on wood divider wall	30	No	None		No	No	
82	1190	TB Reed/Motivation	1	102		Classroom 102	W3	Peeling paint on columns and on wall below windows	10	No	None		No	No	
83	1190	TB Reed/Motivation	1	102		Classroom 102	W4	Cracking paint & Damaged plaster	8	No	None		No	Yes	
84	1190	TB Reed/Motivation	1	102A		Classroom 102 Storage Closet	Ceiling	No Access		No	None		No	No	Inspection Required
85	1190	TB Reed/Motivation	1	102A		Classroom 102 Storage Closet	Floor	No Access		No	None		No	No	Inspection Required
86	1190	TB Reed/Motivation	1	102A		Classroom 102 Storage Closet	W1	No Access		No	None		No	No	Inspection Required
87	1190	TB Reed/Motivation	1	102A		Classroom 102 Storage Closet	W2	No Access		No	None		No	No	Inspection Required
88	1190	TB Reed/Motivation	1	102A		Classroom 102 Storage Closet	W3	No Access		No	None		No	No	Inspection Required
89	1190	TB Reed/Motivation	1	102A		Classroom 102 Storage Closet	W4	No Access		No	None		No	No	Inspection Required
90	1190	TB Reed/Motivation	1	103		Classroom 103	W1	Peeling and cracking paint below the blackboard	40	No	None		No	No	

Penrose -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
91	1190	TB Reed/Motivation	1	103		Classroom 103	W2	Cracking paint, debris on blackboard ledge behind smart board	40	No	None		No	No	
92	1190	TB Reed/Motivation	1	103		Classroom 103	W3	Cracking paint at columns	20	No	None		No	No	
93	1190	TB Reed/Motivation	1	103		Classroom 103	W4	Peeling paint on wood divider wall	30	No	None		No	No	
94	1190	TB Reed/Motivation	1	103A		Classroom 103 Storage Closet	Ceiling	No Access		No	None		No	No	Inspection Required
95	1190	TB Reed/Motivation	1	103A		Classroom 103 Storage Closet	Floor	No Access		No	None		No	No	Inspection Required
96	1190	TB Reed/Motivation	1	103A		Classroom 103 Storage Closet	W1	No Access		No	None		No	No	Inspection Required
97	1190	TB Reed/Motivation	1	103A		Classroom 103 Storage Closet	W2	No Access		No	None		No	No	Inspection Required
98	1190	TB Reed/Motivation	1	103A		Classroom 103 Storage Closet	W3	No Access		No	None		No	No	Inspection Required
99	1190	TB Reed/Motivation	1	103A		Classroom 103 Storage Closet	W4	No Access		No	None		No	No	Inspection Required
100	1190	TB Reed/Motivation	1	104		Classroom 104	W1	Peeling paint & Damaged plaster at plenum grill	15	No	None		No	No	
101	1190	TB Reed/Motivation	1	104		Classroom 104	W2	Peeling paint at blackboard ledge & Efflorescence	25	No	None		No	No	
102	1190	TB Reed/Motivation	1	104		Classroom 104	W3	Cracking paint at columns	10	No	None		No	No	
103	1190	TB Reed/Motivation	1	104		Classroom 104	W4	Peeling paint on wall, holes in plaster wall behind smart board	25	No	None		No	No	
104	1190	TB Reed/Motivation	1	104Z		Classroom 104 Storage Closet	Ceiling	No Access		No	None		No	No	Inspection Required
105	1190	TB Reed/Motivation	1	104Z		Classroom 104 Storage Closet	Floor	No Access		No	None		No	No	Inspection Required
106	1190	TB Reed/Motivation	1	104Z		Classroom 104 Storage Closet	W1	No Access		No	None		No	No	Inspection Required
107	1190	TB Reed/Motivation	1	104Z		Classroom 104 Storage Closet	W2	No Access		No	None		No	No	Inspection Required
108	1190	TB Reed/Motivation	1	104Z		Classroom 104 Storage Closet	W3	No Access		No	None		No	No	Inspection Required
109	1190	TB Reed/Motivation	1	104Z		Classroom 104 Storage Closet	W4	No Access		No	None		No	No	Inspection Required
110	1190	TB Reed/Motivation	1	105		Classroom 105	Ceiling	Severe peeling paint above ceiling - visible through missing tile	8	No	None		No	No	
111	1190	TB Reed/Motivation	1	105		Classroom 105	W1	Peeling paint	10	No	None		No	No	
112	1190	TB Reed/Motivation	1	105		Classroom 105	W2	Severe peeling paint at front column and wall, damaged plaster	100	No	None		No	No	
113	1190	TB Reed/Motivation	1	105		Classroom 105	W3	Cracking paint on column, Efflorescence on wall	30	No	None		No	No	
114	1190	TB Reed/Motivation	1	105		Classroom 105	W4	Peeling and cracking paint, Efflorescence	100	No	None		No	No	
115	1190	TB Reed/Motivation	1	105B		Classroom 105 Storage Closet	Ceiling	No Access		No	None		No	No	Inspection Required

Penrose -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
116	1190	TB Reed/Motivation	1	105B		Classroom 105 Storage Closet	Floor	No Access		No	None		No	No	Inspection Required
117	1190	TB Reed/Motivation	1	105B		Classroom 105 Storage Closet	W1	No Access		No	None		No	No	Inspection Required
118	1190	TB Reed/Motivation	1	105B		Classroom 105 Storage Closet	W2	No Access		No	None		No	No	Inspection Required
119	1190	TB Reed/Motivation	1	105B		Classroom 105 Storage Closet	W3	No Access		No	None		No	No	Inspection Required
120	1190	TB Reed/Motivation	1	105B		Classroom 105 Storage Closet	W4	No Access		No	None		No	No	Inspection Required
121	1190	TB Reed/Motivation	1	100C		Classroom 106	W2	Cracking paint	3	No	None		No	No	
122	1190	TB Reed/Motivation	1	100C		Classroom 106	W4	Peeling paint on drywall wall	2	No	None		No	No	
123	1190	TB Reed/Motivation	1	105A		Elevator Lobby Area	W3	Severe peeling paint	8	No	None		No	No	
124	1190	TB Reed/Motivation	1	105A		Elevator Lobby Area	W4	Severe peeling paint	4	No	None		No	No	
125	1190	TB Reed/Motivation	1	H11		Hallway from Classroom 103 to Classroom 105	W2	Severe peeling paint and Cracking paint	400	No	None		No	No	
126	1190	TB Reed/Motivation	1	H11		Hallway from Classroom 103 to Classroom 105	W4	Severe peeling paint and Cracking paint	400	No	None		No	No	
127	1190	TB Reed/Motivation	1	104A		Men's Restroom	Ceiling	Peeling paint above ceiling - seen through missing tile	6	No	None		No	No	
128	1190	TB Reed/Motivation	1	104A		Men's Restroom	W1	Peeling and Cracking paint	30	No	None		No	No	
129	1190	TB Reed/Motivation	1	104A		Men's Restroom	W2	Peeling and Cracking paint	40	No	None		No	No	
130	1190	TB Reed/Motivation	1	104A		Men's Restroom	W3	Peeling and Cracking paint	25	No	None		No	No	
131	1190	TB Reed/Motivation	1	104A		Men's Restroom	W4	Peeling and Cracking paint including behind toilets	30	No	None		No	No	
132	1190	TB Reed/Motivation	1	S11		Stairwell near Classroom 103	W1	Peeling and Cracking paint	100	No	None		No	No	
133	1190	TB Reed/Motivation	1	S11		Stairwell near Classroom 103	W2	Peeling and Cracking paint	50	No	None		No	No	
134	1190	TB Reed/Motivation	1	S11		Stairwell near Classroom 103	W3	Peeling and Cracking paint	100	No	None		No	No	
135	1190	TB Reed/Motivation	1	S11		Stairwell near Classroom 103	W4	Peeling and Cracking paint	50	No	None		No	No	
136	1190	TB Reed/Motivation	1	S12		Stairwell near Classroom 105	W1	Peeling and Cracking paint	100	No	None		No	No	
137	1190	TB Reed/Motivation	1	S12		Stairwell near Classroom 105	W2	Peeling and Cracking paint	50	No	None		No	No	
138	1190	TB Reed/Motivation	1	S12		Stairwell near Classroom 105	W3	Peeling and Cracking paint	100	No	None		No	No	
139	1190	TB Reed/Motivation	1	S12		Stairwell near Classroom 105	W4	Peeling and Cracking paint	50	No	None		No	No	
140	1190	TB Reed/Motivation	1	103B		Storage Room next to Men's Restroom	Ceiling	Severe peeling paint above ceiling - visible through missing tile	6	No	None		No	No	

Penrose -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
141	1190	TB Reed/Motivation	1	103B		Storage Room next to Men's Restroom	W1	Severe peeling paint	100	No	None		No	No	
142	1190	TB Reed/Motivation	1	103B		Storage Room next to Men's Restroom	W2	Severe peeling paint and efflorescence	50	No	None		No	No	
143	1190	TB Reed/Motivation	1	103B		Storage Room next to Men's Restroom	W3	Severe peeling paint	100	No	None		Shelving	No	
144	1190	TB Reed/Motivation	1	103B		Storage Room next to Men's Restroom	W4	Peeling and Cracking paint	20	No	None		No	No	
145	1190	TB Reed/Motivation	0	001B		B-1 Music	Floor	Debris on carpet	10	No	None		No	No	
146	1190	TB Reed/Motivation	0	001B		B-1 Music	W1	Severe peeling paint, Efflorescence	15	No	None		No	No	
147	1190	TB Reed/Motivation	0	001B		B-1 Music	W2	Cracking paint	10	No	None		No	No	
148	1190	TB Reed/Motivation	0	001B		B-1 Music	W3	Severe peeling paint, Efflorescence, debris on radiator	150	No	None		No	No	
149	1190	TB Reed/Motivation	0	001B		B-1 Music	W4	Severe peeling paint, Efflorescence	50	No	None		No	No	
150	1190	TB Reed/Motivation	0	B10		B10 Storage Room under Stairwell	Floor	Debris	20	No	None		No	No	
151	1190	TB Reed/Motivation	0	B10		B10 Storage Room under Stairwell	W3	Severe peeling paint	60	No	None		No	No	
152	1190	TB Reed/Motivation	0	B10		B10 Storage Room under Stairwell	W4	Peeling paint	10	No	None		No	No	
153	1190	TB Reed/Motivation	0	B10A		B10A Elevator Mechanical Room	Floor	Debris along wall	20	No	None		No	No	
154	1190	TB Reed/Motivation	0	B10A		B10A Elevator Mechanical Room	W1	Peeling paint	10	No	None		No	No	
155	1190	TB Reed/Motivation	0	B10A		B10A Elevator Mechanical Room	W2	Severe peeling paint	70	No	None		No	No	
156	1190	TB Reed/Motivation	0	B10A		B10A Elevator Mechanical Room	W3	Peeling paint	30	No	None		No	No	
157	1190	TB Reed/Motivation	0	011B		B-14 Storage Room next to Boy's Restroom	Ceiling	Severe peeling paint	40	No	None		No	No	
158	1190	TB Reed/Motivation	0	011B		B-14 Storage Room next to Boy's Restroom	Floor	Debris	20	No	None		No	No	
159	1190	TB Reed/Motivation	0	011B		B-14 Storage Room next to Boy's Restroom	W2	Severe Efflorescence	40	No	None		No	No	
160	1190	TB Reed/Motivation	0	011B		B-14 Storage Room next to Boy's Restroom	W3	Severe Efflorescence	20	No	None		No	No	
161	1190	TB Reed/Motivation	0	011B		B-14 Storage Room next to Boy's Restroom	W4	Severe peeling paint on ductwork	40	No	None		No	No	

Penrose -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
162	1190	TB Reed/Motivation	0	009B		B-16 Custodial Closet and Gas Meter Room	Ceiling	Severe peeling paint	150	No	None		No	No	
163	1190	TB Reed/Motivation	0	009B		B-16 Custodial Closet and Gas Meter Room	Floor	Debris	50	No	None		No	No	
164	1190	TB Reed/Motivation	0	009B		B-16 Custodial Closet and Gas Meter Room	W1	Severe peeling paint	100	No	None		No	No	
165	1190	TB Reed/Motivation	0	009B		B-16 Custodial Closet and Gas Meter Room	W2	Severe peeling paint	100	No	None		No	No	
166	1190	TB Reed/Motivation	0	009B		B-16 Custodial Closet and Gas Meter Room	W3	Severe peeling paint on wall and pipe	150	No	None		No	No	
167	1190	TB Reed/Motivation	0	009B		B-16 Custodial Closet and Gas Meter Room	W4	Severe peeling paint	50	No	None		No	No	
168	1190	TB Reed/Motivation	0	010B		B-17 Storage Room	Ceiling	Severe peeling paint	40	No	None		No	No	
169	1190	TB Reed/Motivation	0	010B		B-17 Storage Room	Floor	Debris	30	No	None		No	No	
170	1190	TB Reed/Motivation	0	010B		B-17 Storage Room	W1	Severe peeling paint	15	No	None		No	No	
171	1190	TB Reed/Motivation	0	010B		B-17 Storage Room	W2	Severe peeling paint	60	No	None		No	No	
172	1190	TB Reed/Motivation	0	010B		B-17 Storage Room	W3	Severe peeling paint	100	No	None		No	No	
173	1190	TB Reed/Motivation	0	010B		B-17 Storage Room	W4	Severe peeling paint	30	No	None		No	No	
174	1190	TB Reed/Motivation	0	001BA		B-1A Storage Room	Ceiling	Severe peeling paint	40	No	None		No	No	
175	1190	TB Reed/Motivation	0	001BA		B-1A Storage Room	Floor	Debris	50	No	None		No	No	
176	1190	TB Reed/Motivation	0	001BA		B-1A Storage Room	W2	Severe peeling paint	40	No	None		No	No	
177	1190	TB Reed/Motivation	0	001BA		B-1A Storage Room	W3	Severe peeling paint	40	No	None		No	No	
178	1190	TB Reed/Motivation	0	002B		B-2 Computer Lab	Ceiling	Peeling paint	60	No	None		No	No	
179	1190	TB Reed/Motivation	0	002B		B-2 Computer Lab	Floor	Debris along left wall	30	No	None		No	No	
180	1190	TB Reed/Motivation	0	002B		B-2 Computer Lab	W1	Peeling paint and Efflorescence	30	No	None		No	No	
181	1190	TB Reed/Motivation	0	002B		B-2 Computer Lab	W2	Severe Efflorescence	220	No	None		No	No	
182	1190	TB Reed/Motivation	0	002B		B-2 Computer Lab	W3	Peeling paint and Severe Efflorescence	200	No	None		No	No	
183	1190	TB Reed/Motivation	0	002B		B-2 Computer Lab	W4	Peeling paint and Severe Efflorescence	50	No	None		No	No	
184	1190	TB Reed/Motivation	0	002BA		B-2 Computer Lab Storage Closet (B-15 Electrical)	Ceiling	Severe peeling paint and damaged plaster		No	None		No	No	

Penrose -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
185	1190	TB Reed/Motivation	0	002BA		B-2 Computer Lab Storage Closet (B-15 Electrical)	Floor	Debris on floor, boxes, and ductwork	35	No	None		No	No	
186	1190	TB Reed/Motivation	0	002BA		B-2 Computer Lab Storage Closet (B-15 Electrical)	W1	Peeling paint		No	None		No	No	
187	1190	TB Reed/Motivation	0	002BA		B-2 Computer Lab Storage Closet (B-15 Electrical)	W2	Peeling paint		No	None		No	No	
188	1190	TB Reed/Motivation	0	002BA		B-2 Computer Lab Storage Closet (B-15 Electrical)	W3	Severe peeling paint		No	None		No	No	
189	1190	TB Reed/Motivation	0	002BA		B-2 Computer Lab Storage Closet (B-15 Electrical)	W4	Severe peeling paint		No	None		No	No	
190	1190	TB Reed/Motivation	0	005BB		B-4 IMC Storage Room	W1	Peeling paint on door frame	3	No	None		No	No	
191	1190	TB Reed/Motivation	0	005BB		B-4 IMC Storage Room	W2	Peeling paint	2	No	None		No	No	
192	1190	TB Reed/Motivation	0	005BA		B-5 IMC Office	W1	Severe Efflorescence	10	No	None		No	No	
193	1190	TB Reed/Motivation	0	005BA		B-5 IMC Office	W4	Severe Efflorescence along window wall	60	No	None		No	No	
194	1190	TB Reed/Motivation	0	H02A		B-6 Security Office	W1	Peeling paint	2	No	None		No	No	
195	1190	TB Reed/Motivation	0	H02A		B-6 Security Office	W2	Peeling paint	2	No	None		No	No	
196	1190	TB Reed/Motivation	0	012B		Boy's Restroom	Ceiling	Peeling paint	5	No	None		No	No	
197	1190	TB Reed/Motivation	0	008B		Elevator Lobby Area	W2	Peeling paint	1	No	None		No	No	
198	1190	TB Reed/Motivation	0	008B		Elevator Lobby Area	W3	Peeling paint	2	No	None		No	No	
199	1190	TB Reed/Motivation	0	H01B		Former Building Engineer's Office	Ceiling	Severe peeling paint above ceiling - visible through missing tile	20	No	None		No	No	
200	1190	TB Reed/Motivation	0	H01B		Former Building Engineer's Office	Floor	Peeling paint on baseboard, debris on computer desk	30	No	None		No	No	
201	1190	TB Reed/Motivation	0	H01B		Former Building Engineer's Office	W1	Peeling paint at columns	20	No	None		No	No	
202	1190	TB Reed/Motivation	0	H01B		Former Building Engineer's Office	W2	Peeling paint	5	No	None		No	No	
203	1190	TB Reed/Motivation	0	H01B		Former Building Engineer's Office	W3	Peeling paint	15	No	None		No	No	
204	1190	TB Reed/Motivation	0	H01B		Former Building Engineer's Office	W4	Peeling paint	10	No	None		No	No	
205	1190	TB Reed/Motivation	0	006B		Girl's Restroom	Ceiling	Peeling paint	50	No	None		No	No	
206	1190	TB Reed/Motivation	0	H01		Hallway from B-1 Music to B-2 Computer Lab	W2	Efflorescence on brick wall	40	No	None		No	No	
207	1190	TB Reed/Motivation	0	005B		IMC/Library	Floor	Debris on carpet along window wall including behind book shelves	50	No	None		No	No	

Penrose -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
208	1190	TB Reed/Motivation	0	005B		IMC/Library	W2	Peeling paint	2	No	None		No	No	
209	1190	TB Reed/Motivation	0	005B		IMC/Library	W3	Severe Efflorescence along window wall	300	No	None		No	No	
210	1190	TB Reed/Motivation	0	S02		Stairwell near Elevator	Ceiling	Peeling paint	5	No	None		No	No	
211	1190	TB Reed/Motivation	0	S02		Stairwell near Elevator	W3	Peeling paint	20	No	None		No	No	
212	1190	TB Reed/Motivation	0	S02		Stairwell near Elevator	W4	Peeling paint	20	No	None		No	No	
213	1190	TB Reed/Motivation	0	S01		Stairwell near Gas Meter Room	Ceiling	Severe peeling paint	40	No	None		No	No	
214	1190	TB Reed/Motivation	0	S01		Stairwell near Gas Meter Room	Floor	Debris	10	No	None		No	No	
215	1190	TB Reed/Motivation	0	S01		Stairwell near Gas Meter Room	W2	Severe peeling paint	30	No	None		No	No	
216	1190	TB Reed/Motivation	0	S01		Stairwell near Gas Meter Room	W3	Severe peeling paint on wall including staircase wall	40	No	None		No	No	
217	1440	Penrose ES	2	203		Classroom 203	W2	Peeling paint	2	No	none		none	No	
218	1440	Penrose ES	2	203		Classroom 203	W3	Peeling paint	3	No	none		none	No	
219	1440	Penrose ES	2	204		Classroom 204	W2	Peeling paint	1	No	none		none	No	
220	1440	Penrose ES	2	204		Classroom 204	W3	Peeling paint at top of window	1	No	none		none	No	
221	1440	Penrose ES	2	204		Classroom 204	W4	Peeling paint	6	No	none		none	No	
222	1440	Penrose ES	2	211		Classroom 211	Ceiling	Peeling paint along left wall & window wall	10	No	none		none	No	
223	1440	Penrose ES	2	215		Classroom 215	Ceiling	Peeling paint by left corner	3	No	none		none	No	
224	1440	Penrose ES	2	215		Classroom 215	W3	Peeling paint	3	No	none		none	No	
225	1440	Penrose ES	2	217		Classroom 217	Ceiling	Peeling paint	10	No	none		none	No	
226	1440	Penrose ES	2	217		Classroom 217	W2	Peeling paint	3	No	none		none	No	
227	1440	Penrose ES	2	217		Classroom 217	W3	Efflorescence	35	No	none		none	No	
228	1440	Penrose ES	2	219		Classroom 219	Ceiling	Peeling paint	1	No	none		none	No	
229	1440	Penrose ES	2	219		Classroom 219	W3	Efflorescence on the right corner	5	No	none		none	No	
230	1440	Penrose ES	2	221		Classroom 221	Ceiling	Peeling paint and Efflorescence along seams and right wall	75	No	none		none	No	
231	1440	Penrose ES	2	221		Classroom 221	W3	Efflorescence on the left corner	3	No	none		none	No	
232	1440	Penrose ES	2	209A		Computer Server Room in Room 209	Ceiling	No Access		No	none		none	No	Inspection Required
233	1440	Penrose ES	2	209A		Computer Server Room in Room 209	Floor	No Access		No	none		none	No	Inspection Required
234	1440	Penrose ES	2	209A		Computer Server Room in Room 209	W1	No Access		No	none		none	No	Inspection Required
235	1440	Penrose ES	2	209A		Computer Server Room in Room 209	W2	No Access		No	none		none	No	Inspection Required
236	1440	Penrose ES	2	209A		Computer Server Room in Room 209	W3	No Access		No	none		none	No	Inspection Required
237	1440	Penrose ES	2	209A		Computer Server Room in Room 209	W4	No Access		No	none		none	No	Inspection Required

Penrose -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
238	1440	Penrose ES	2	210		Girl's Restroom near Classroom 207	W1	Efflorescence near ceiling behind ductwork	6	No	none		none	No	
239	1440	Penrose ES	2	216/218		IMC/Library	W3	Efflorescence on Classroom 218 side	4	No	none		none	No	
240	1440	Penrose ES	2	209		Room 209 Storage next to Classroom 207	W3	Efflorescence	4	No	none		none	No	
241	1440	Penrose ES	2	212		Storage Room next to Custodial Closet across from Classroom 213	W3	Peeling paint on pipe	1	No	none		none	No	
242	1440	Penrose ES	1	110A		Boy's Restroom across from Classroom 107	Ceiling	Peeling paint & Efflorescence	40	No	none		none	No	
243	1440	Penrose ES	1	102		Classroom 102	Ceiling	Efflorescence	2	No	none		none	No	
244	1440	Penrose ES	1	111		Classroom 111	Ceiling	Peeling paint	1	No	none		none	No	
245	1440	Penrose ES	1	113		Classroom 113	Ceiling	Peeling paint along window wall	40	No	none		none	No	
246	1440	Penrose ES	1	113		Classroom 113	W3	Efflorescence	30	No	none		none	No	
247	1440	Penrose ES	1	115		Classroom 115	Ceiling	Peeling paint	10	No	none		none	No	
248	1440	Penrose ES	1	115		Classroom 115	W3	Efflorescence	20	No	none		none	No	
249	1440	Penrose ES	1	117		Classroom 117	W3	Efflorescence	30	No	none		none	No	
250	1440	Penrose ES	1	117		Classroom 117	W4	Peeling paint	10	No	none		none	No	
251	1440	Penrose ES	1	119		Classroom 119	Ceiling	Peeling paint	10	No	none		none	No	
252	1440	Penrose ES	1	119		Classroom 119	W3	Efflorescence	50	No	none		none	No	
253	1440	Penrose ES	1	121		Classroom 121	W3	Efflorescence	30	No	none		none	No	
254	1440	Penrose ES	1	19		Elevator Lobby Area between Element 2 and Former Motivational High School	W1	Cracking paint	2	No	none		none	No	
255	1440	Penrose ES	1	24		G 107 Office in Main Office Area	W4	Peeling paint	2	No	none		none	No	
256	1440	Penrose ES	1	110		Girl's Restroom near Classroom 107	Ceiling	Peeling paint & Efflorescence	40	No	none		none	No	
257	1440	Penrose ES	1	106B		Principal's Office	W1	Peeling paint	1	No	none		none	No	
258	1440	Penrose ES	0	B004		B-4 Physical Education - Weight Lifting Room	W1	Peeling paint	50	No	none		none	No	
259	1440	Penrose ES	0	B004		B-4 Physical Education - Weight Lifting Room	W2	Peeling paint	35	No	none		none	No	
260	1440	Penrose ES	0	B004		B-4 Physical Education - Weight Lifting Room	W3	Peeling paint and efflorescence	75	No	none		none	No	
261	1440	Penrose ES	0	B004		B-4 Physical Education - Weight Lifting Room	W4	Peeling paint	25	No	none		none	No	
262	1440	Penrose ES	0	H01		Hallway from Corridor B-5 to Outside Exit	W2	Efflorescence	30	No	none		none	No	

Penrose -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
263	1440	Penrose ES	0	H01		Hallway from Corridor B-5 to Outside Exit	W3	Efflorescence	10	No	none		none	No	