

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	2360	Martin	B	BSMT		Basement Mechanical Room - Entrance in Hallway outside of Classroom 115	W1	Flaking	500	N	N	0	N	N	
2	2360	Martin	B	BSMT		Basement Mechanical Room - Entrance in Hallway outside of Classroom 115	W2	Flaking	700	N	N	0	N	N	
3	2360	Martin	B	BSMT		Basement Mechanical Room - Entrance in Hallway outside of Classroom 115	W3	Flaking	500	N	N	0	N	N	
4	2360	Martin	B	BSMT		Basement Mechanical Room - Entrance in Hallway outside of Classroom 115	W4	Flaking	700	N	N	0	N	N	
5	2360	Martin	B	BSMT		Basement Mechanical Room - Entrance in Hallway outside of Classroom 115	Ceiling	Flaking	875	N	N	0	N	N	
6	2360	Martin	1	100		Main Office	W3	Flaking	48	Y	N	0	N	Y - 20 SF	Additional Efflorescence
7	2360	Martin	1	100		Main Office	W4	Holes	2	N	N	0	Y - 40 SF Cabinets, Posters	N	
8	2360	Martin	1	100D		Principal's Office Restroom	Ceiling	Flaking	5	Y	N	0	N	Y - 5 SF	Damage Includes Window Lintel
9	2360	Martin	1	101		Classroom 101	W3	Efflorescence	3	N	Y - On Window Sill	1	N	Y - 3 SF	Efflorescence on Window Lintel
10	2360	Martin	1	119		Classroom 119	W1	Partially Inaccessible	0	N	N	0	Y - 30 SF Posters	N	
11	2360	Martin	1	119		Classroom 119	W2	Partially Inaccessible	0	N	N	0	Y - 42 SF Desks, Posters	N	
12	2360	Martin	1	119		Classroom 119	W3	Flaking	20	N	N	0	Y - 28 SF Desks, Posters	N	Additional Cracking, Chipping
13	2360	Martin	1	119		Classroom 119	W4	Partially Inaccessible	0	N	N	0	Y - 40 SF Desks, Posters	N	
14	2360	Martin	1	130A		Hallway Closet beside Classroom 119	W1	Partially Inaccessible	0	N	N	0	Y - 18 SF Contents	N	
15	2360	Martin	1	130A		Hallway Closet beside Classroom 119	W2	Partially Inaccessible	0	N	N	0	Y - 12 SF Contents	N	
16	2360	Martin	1	130A		Hallway Closet beside Classroom 119	W3	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
17	2360	Martin	1	130A		Hallway Closet beside Classroom 119	W4	Partially Inaccessible	0	N	N	0	Y - 18 SF Contents	N	
18	2360	Martin	1	130A		Hallway Closet beside Classroom 119	Ceiling	Partially Inaccessible	0	N	N	0	N	N	
19	2360	Martin	1	130A		Hallway Closet beside Classroom 119	Floor	Partially Inaccessible	0	N	N	0	N	N	
20	2360	Martin	1	120		Classroom 120	W1	Partially Inaccessible	0	N	N	0	Y - 30 SF Posters, Contents	N	
21	2360	Martin	1	120		Classroom 120	W2	Partially Inaccessible	0	N	N	0	Y - 18 SF Posters, Contents	N	
22	2360	Martin	1	120		Classroom 120	W3	Partially Inaccessible	0	N	N	0	Y - 36 SF Posters, Contents	N	
23	2360	Martin	1	120		Classroom 120	W4	Partially Inaccessible	0	N	N	0	Y - 36 SF Posters, Contents	N	
24	2360	Martin	1	120		Classroom 120	Ceiling	Partially Inaccessible	0	N	N	0	N	N	Suspended Ceiling
25	2360	Martin	1	120		Classroom 120	Floor	Partially Inaccessible	0	N	N	0	N	N	
26	2360	Martin	1	101D		Storage Closet beside Women's Restroom (in front of Auditorium)	Ceiling	Cracking	4	N	N	0	N	N	
27	2360	Martin	1	101B		Auditorium	W1	Flaking	45	N	N	0	N	N	
28	2360	Martin	1	101B		Auditorium	W2	Cracking	8	N	N	0	N	N	
29	2360	Martin	1	101B		Auditorium	W3	Flaking	70	N	N	0	N	N	Additional Cracking, Chipping; Damage Includes Windows
30	2360	Martin	1	101B		Auditorium	W4	Cracking	15	N	N	0	N	N	Additional Chipping
31	2360	Martin	1	101B		Auditorium	Ceiling	Flaking	200	N	N	0	N	N	Additional Cracking, Chipping; Decorative Plaster Ceiling
32	2360	Martin	1	101B		Auditorium	Floor	Chipping	150	N	N	0	N	N	Chipping on Auditorium Chairs
33	2360	Martin	1	101C		Auditorium Stage	W1	Flaking	30	N	N	0	N	N	Additional Chipping
34	2360	Martin	1	101C		Auditorium Stage	W2	Flaking	60	N	N	0	N	N	Additional Chipping
35	2360	Martin	1	101C		Auditorium Stage	W3	Flaking	150	N	N	0	N	N	Additional Chipping
36	2360	Martin	1	101C		Auditorium Stage	W4	Cracking	8	N	N	0	N	N	Additional Cracking
37	2360	Martin	1	101C		Auditorium Stage	Ceiling	Flaking	30	N	N	0	N	N	
38	2360	Martin	1	120A		Boys' Restroom across from Classroom 102	Ceiling	Cracking	10	N	N	0	N	N	
39	2360	Martin	1	102		Classroom 102	W1	Chipping	5	N	N	0	Y - 12 SF Posters, Contents	N	
40	2360	Martin	1	102		Classroom 102	W3	Flaking	10	N	N	0	Y - 30 SF Desks, Bookcases, Contents	N	Additional Chipping

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
41	2360	Martin	1	102		Classroom 102	W4	Chipping	12	N	N	0	Y - 20 SF Desks, Contents	N	
42	2360	Martin	1	102A		Classroom 102 Restroom	Ceiling	Holes	1	N	N	0	N	N	
43	2360	Martin	1	121		Classroom 121	W1	Flaking	12	N	N	0	N	N	
44	2360	Martin	1	121		Classroom 121	W2	Flaking	16	N	N	0	N	N	
45	2360	Martin	1	121		Classroom 121	W3	Flaking	12	Y	N	0	N	Y - 4 SF	Additional Efflorescence
46	2360	Martin	1	103		Classroom 103	W1	Chipping	2	N	N	0	N	N	
47	2360	Martin	1	103		Classroom 103	W2	Flaking	5	N	N	0	N	N	
48	2360	Martin	1	103		Classroom 103	W3	Flaking	12	N	N	0	Y - 24 Posters, Contents	N	
49	2360	Martin	1	103		Classroom 103	W4	Partially Inaccessible	0	N	N	0	Y - 36 SF Desks, Posters, Contents	N	
50	2360	Martin	1	122		Special Education Classroom 122	W2	Flaking	14	N	N	0	Y - 24 SF Desks, Shelves, Contents	N	Additional Chipping
51	2360	Martin	1	122		Special Education Classroom 122	W3	Flaking	16	N	N	0	Y - 28 SF Desks, Shelves, Contents	N	Additional Chipping
52	2360	Martin	1	122		Special Education Classroom 122	W4	Partially Inaccessible	0	N	N	0	Y - 20 SF Desks, Shelves, Contents	N	
53	2360	Martin	1	122A		Special Education Classroom 122 Restroom	Ceiling	Cracking	4	N	N	0	N	N	
54	2360	Martin	1	104		Classroom 104	W3	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents	N	
55	2360	Martin	1	104		Classroom 104	W4	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents	N	
56	2360	Martin	1	104A		Classroom 104 Closet	W2	Partially Inaccessible	0	N	N	0	Y - 14 SF Boxes, Contents	N	
57	2360	Martin	1	104A		Classroom 104 Closet	W3	Partially Inaccessible	0	N	N	0	Y - 21 SF Boxes, Contents	N	
58	2360	Martin	1	104A		Classroom 104 Closet	W4	Partially Inaccessible	0	N	N	0	Y - 14 SF Boxes, Contents	N	
59	2360	Martin	1	122B		Girls' Restroom across from Classroom 104	Ceiling	Cracking	5	N	N	0	N	N	
60	2360	Martin	1	104C		Kitchen Storage	W1	Flaking	6	N	N	0	Y - 20 SF Boxes, Contents	N	Additional Cracking
61	2360	Martin	1	104C		Kitchen Storage	W2	Partially Inaccessible	0	N	N	0	Y - 30 SF Boxes, Contents	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
62	2360	Martin	1	104C		Kitchen Storage	W3	Partially Inaccessible	0	N	N	0	Y - 28 SF Boxes, Contents	N	
63	2360	Martin	1	104C		Kitchen Storage	W4	Partially Inaccessible	0	N	N	0	Y - 32 SF Boxes, Contents	N	
64	2360	Martin	1	111A		Classroom 111A	W1	Chipping	3	N	N	0	N	N	
65	2360	Martin	1	111A		Classroom 111A	W2	Chipping	6	N	N	0	N	N	
66	2360	Martin	1	111A		Classroom 111A	W3	Flaking	36	N	N	0	N	Y - 16 SF	
67	2360	Martin	1	111A		Classroom 111A	Floor	Chipping	20	N	N	0	N	N	111
68	2360	Martin	1	111		Health Room 111	W2	Partially Inaccessible	0	N	N	0	Y - 40 SF Contents	N	
69	2360	Martin	1	111		Health Room 111	W3	Flaking	40	N	N	0	Y - 40 SF Posters, Desks, Contents	N	
70	2360	Martin	1	111		Health Room 111	W4	Partially Inaccessible	0	N	N	0	Y - 30 SF Posters, Desks, Contents	N	
71	2360	Martin	1	124		Classroom 124	W1	Chipping	20	N	N	0	N	N	
72	2360	Martin	1	124		Classroom 124	W3	Chipping	20	N	N	0	N	N	
73	2360	Martin	1	124A		Classroom 124 Closet	W1	Partially Inaccessible	0	N	N	0	Y - 10 SF Contents	N	
74	2360	Martin	1	124A		Classroom 124 Closet	W2	Partially Inaccessible	0	N	N	0	Y - 12 SF Contents	N	
75	2360	Martin	1	124A		Classroom 124 Closet	W3	Partially Inaccessible	0	N	N	0	Y - 16 SF Contents	N	
76	2360	Martin	1	124A		Classroom 124 Closet	W4	Partially Inaccessible	0	N	N	0	Y - 12 SF Contents	N	
77	2360	Martin	1	138		Conference Room in Center Hallway	W2	Flaking	6	N	N	0	Y - 38 SF Desks, Bookcases, Books	N	
78	2360	Martin	1	138		Conference Room in Center Hallway	W3	Flaking	14	N	N	0	Y - 28 SF Bookcases, Books, Contents	N	
79	2360	Martin	1	138		Conference Room in Center Hallway	W4	Flaking	10	N	N	0	Y - 48 SF Bookcases, Books, Posters, Contents	N	
80	2360	Martin	1	S1		Stairwell to Attic and Roof - East End of Center Hall	W1	Cracking	20	N	Y - On Contents	10	Y - 24 SF Boxes, Contents	N	
81	2360	Martin	1	S1		Stairwell to Attic and Roof - East End of Center Hall	W2	Flaking	108	Y	Y - On Contents	10	Y - 18 SF Boxes, Contents	Y - 100 SF	Additional Efflorescence
82	2360	Martin	1	S1		Stairwell to Attic and Roof - East End of Center Hall	W3	Flaking	120	Y	Y - On Contents	10	Y - 12 SF Boxes, Contents	Y - 120 SF	Additional Efflorescence

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
83	2360	Martin	1	S1		Stairwell to Attic and Roof - East End of Center Hall	W4	Flaking	200	Y	Y - On Contents	10	Y - 32 SF Cabinets, Boxes, Contents	Y - 200 SF	Additional Efflorescence
84	2360	Martin	1	S1		Stairwell to Attic and Roof - East End of Center Hall	Ceiling	Flaking	80	Y	N	0	N	Y -20 SF	Additional Efflorescence
85	2360	Martin	1	133		Classroom 133	W1	Cracking	6	N	N	0	N	N	Cinder Block Walls
86	2360	Martin	1	133		Classroom 133	W3	Cracking	6	N	N	0	N	N	Cinder Block Walls
87	2360	Martin	1	134		Classroom 134	W4	Cracking	4	N	N	0	N	N	Cinder Block Walls
88	2360	Martin	1	H4		Center Hallway	W2	Flaking	80	N	N	0	N	N	
89	2360	Martin	1	H4		Center Hallway	W4	Flaking	140	Y	N	0	N	Y - 24 SF	
90	2360	Martin	1	H4A		Center Hallway between Classrooms 106 and 107B	W2	Chipping	20	N	N	0	N	N	
91	2360	Martin	1	H4A		Center Hallway between Classrooms 106 and 107B	W3	Chipping	12	N	N	0	N	N	Chipping on Door
92	2360	Martin	1	H4A		Center Hallway between Classrooms 106 and 107B	W4	Chipping	20	N	N	0	N	N	
93	2360	Martin	1	105		Classroom 105	W1	Cracking	8	N	N	0	N	N	
94	2360	Martin	1	105		Classroom 105	W2	Cracking	8	N	N	0	N	N	
95	2360	Martin	1	106A		Classroom 106 Closet	W1	Flaking	8	N	N	0	N	N	
96	2360	Martin	1	106A		Classroom 106 Closet	W2	Flaking	16	N	N	0	N	N	
97	2360	Martin	1	106A		Classroom 106 Closet	W3	Flaking	12	N	N	0	N	N	
98	2360	Martin	1	106A		Classroom 106 Closet	W4	Flaking	16	N	N	0	N	N	
99	2360	Martin	1	106A		Classroom 106 Closet	Ceiling	Flaking	10	N	N	0	N	N	
100	2360	Martin	1	106B		Classroom 106 Storage Room	W1	Flaking	20	Y	N	0	N	Y - 6 SF	Additional Efflorescence
101	2360	Martin	1	106B		Classroom 106 Storage Room	W2	Flaking	40	Y	N	0	Y - 40 SF Boxes, Contents	Y - 6 SF	Additional Efflorescence
102	2360	Martin	1	106B		Classroom 106 Storage Room	W3	Flaking	60	Y	N	0	Y - 50 SF Boxes, Contents	Y - 6 SF	Additional Efflorescence
103	2360	Martin	1	106B		Classroom 106 Storage Room	W4	Flaking	40	Y	N	0	Y - 40 SF Boxes, Contents	Y - 8 SF	Additional Efflorescence
104	2360	Martin	1	106B		Classroom 106 Storage Room	Ceiling	Flaking	30	Y	N	0	N	Y - 8 SF	
105	2360	Martin	1	106C		Classroom 106 Restroom	Ceiling	Flaking	10	N	N	0	N	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
106	2360	Martin	1	107C		Storage Room between Classrooms 107A and 107B	W1	Flaking	15	N	N	0	N	N	
107	2360	Martin	1	107C		Storage Room between Classrooms 107A and 107B	W2	Flaking	20	N	N	0	Y - 25 SF Boxes, Contents	N	
108	2360	Martin	1	107C		Storage Room between Classrooms 107A and 107B	W3	Flaking	18	N	N	0	Y - 16 SF Boxes, Contents	N	
109	2360	Martin	1	107C		Storage Room between Classrooms 107A and 107B	W4	Flaking	22	N	N	0	Y - 30 SF Boxes, Contents	N	
110	2360	Martin	1	107C		Storage Room between Classrooms 107A and 107B	Ceiling	Flaking	10	N	N	0	N	N	
111	2360	Martin	1	107A		Classroom 107A	W2	Cracking	10	N	N	0	Y - 24 SF Boxes, Contents	N	
112	2360	Martin	1	107A		Classroom 107A	W3	Chipping	10	N	N	0	Y - 16 SF Boxes, Contents	N	
113	2360	Martin	1	107A		Classroom 107A	W4	Cracking	8	N	N	0	Y - 15 SF Boxes, Contents	N	
114	2360	Martin	1	107A-CL		Classroom 107A Closet	W1	Flaking	6	N	N	0	N	N	
115	2360	Martin	1	107A-CL		Classroom 107A Closet	W2	Flaking	6	N	N	0	Y - 18 SF Boxes, Contents	N	
116	2360	Martin	1	107A-CL		Classroom 107A Closet	W3	Flaking	5	N	N	0	Y - 12 SF Boxes, Contents	N	
117	2360	Martin	1	107A-CL		Classroom 107A Closet	W4	Flaking	3	N	N	0	Y - 10 SF Boxes, Contents	N	
118	2360	Martin	1	107A-CL		Classroom 107A Closet	Ceiling	Flaking	3	N	N	0	N	N	
119	2360	Martin	1	107A-DR		Classroom 107 Dark Room	W1	Flaking	20	N	N	0	N	N	
120	2360	Martin	1	107A-DR		Classroom 107 Dark Room	W2	Flaking	40	N	N	0	Y - 8 SF Boxes, Contents	N	
121	2360	Martin	1	107A-DR		Classroom 107 Dark Room	W3	Flaking	60	N	N	0	Y - 20 SF Boxes, Contents	N	
122	2360	Martin	1	107A-DR		Classroom 107 Dark Room	W4	Flaking	40	N	N	0	Y - 30 SF Boxes, Contents	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
123	2360	Martin	1	107A-DR		Classroom 107 Dark Room	Ceiling	Flaking	30	N	N	0	N	N	
124	2360	Martin	1	107B		Classroom 107B	W1	Flaking	30	N	N	0	N	N	Additional Cracking, Chipping
125	2360	Martin	1	107B		Classroom 107B	W2	Cracking	6	N	N	0	N	N	
126	2360	Martin	1	BEO		Building Engineer's Office	Ceiling	Cracking	4	N	N	0	N	Y - 4 SF	
127	2360	Martin	1	H1		Northeast Hallway	W1	Cracking	10	N	N	0	Y - 10 SF Posters	N	Additional Chipping
128	2360	Martin	1	H1		Northeast Hallway	W3	Flaking	24	N	N	0	N	Y - 8 SF	Additional Efflorescence
129	2360	Martin	1	H1		Northeast Hallway	W4	Flaking	20	N	N	0	N	Y - 4	Additional Efflorescence
130	2360	Martin	1	H1A		Hallway Vestibule Connecting Northeast and North Hallways	W1	Flaking	36	N	N	0	N	N	
131	2360	Martin	1	H1A		Hallway Vestibule Connecting Northeast and North Hallways	W4	Flaking	10	N	N	0	N	N	
132	2360	Martin	1	H1A		Hallway Vestibule Connecting Northeast and North Hallways	Ceiling	Flaking	16	N	N	0	N	N	Decorative Ceiling Plaster
133	2360	Martin	1	H1B		Entrance Vestibule outside Auditorium	W1	Flaking	40	N	N	0	N	N	
134	2360	Martin	1	H1B		Entrance Vestibule outside Auditorium	W4	Flaking	40	N	N	0	N	N	
135	2360	Martin	1	H1B		Entrance Vestibule outside Auditorium	Ceiling	Flaking	28	N	N	0	N	N	
136	2360	Martin	1	H2		North Hallway	W2	Cracking	6	N	N	0	Y - 20 SF Posters	N	
137	2360	Martin	1	H2		North Hallway	W4	Flaking	12	N	N	0	Y - 20 SF Posters	N	Additional Cracking
138	2360	Martin	1	H2A		Hallway Vestibule Connecting North and Northwest Hallways	W1	Flaking	10	N	N	0	N	N	
139	2360	Martin	1	H2A		Hallway Vestibule Connecting North and Northwest Hallways	W3	Flaking	8	N	N	0	N	N	
140	2360	Martin	1	H2A		Hallway Vestibule Connecting North and Northwest Hallways	Ceiling	Flaking	16	N	N	0	N	N	Decorative Ceiling Plaster
141	2360	Martin	1	H3		Northwest Hallway	W1	Flaking	60	N	N	0	N	N	
142	2360	Martin	1	H3		Northwest Hallway	W3	Flaking	110	N	N	0	N	N	
143	2360	Martin	1	MEV		Main Entrance Vestibule	W1	Flaking	20	N	N	0	N	N	
144	2360	Martin	1	MEV		Main Entrance Vestibule	W2	Flaking	28	N	N	0	N	N	
145	2360	Martin	1	MEV		Main Entrance Vestibule	W3	Flaking	18	N	N	0	N	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
146	2360	Martin	1	MEV		Main Entrance Vestibule	W4	Flaking	16	N	N	0	N	N	
147	2360	Martin	1	MEV		Main Entrance Vestibule	Ceiling	Flaking	15	N	N	0	N	N	
148	2360	Martin	1	131 A		Closet beside Classroom 131	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Padlocked
149	2360	Martin	1	131 A		Closet beside Classroom 131	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
150	2360	Martin	1	131 A		Closet beside Classroom 131	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
151	2360	Martin	1	131 A		Closet beside Classroom 131	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
152	2360	Martin	1	131 A		Closet beside Classroom 131	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
153	2360	Martin	1	131 A		Closet beside Classroom 131	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
154	2360	Martin	1	131		Classroom 131	W1	Partially Inaccessible	0	0	N	0	Y - 30 SF Desks, Poster, Contents	N	
155	2360	Martin	1	131		Classroom 131	W2	Partially Inaccessible	0	0	N	0	Y - 10 SF Posters	N	
156	2360	Martin	1	131		Classroom 131	W3	Flaking	60	Y	N	0	Y - 20 SF Posters, Contents	Y - 20 SF	Additional Efflorescence
157	2360	Martin	1	131		Classroom 131	W4	Cracking	12	N	N	0	N	N	Additional Holes
158	2360	Martin	1	117		Classroom 117	W1	Partially Inaccessible	0	N	N	0	Y - 26 SF Posters	N	
159	2360	Martin	1	117		Classroom 117	W2	Partially Inaccessible	0	N	N	0	Y - 24 SF Posters, Desks, Contents	N	
160	2360	Martin	1	117		Classroom 117	W3	Flaking	8	N	N	0	Y - 16 SF Posters, Contents	N	
161	2360	Martin	1	117		Classroom 117	W4	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents, Posters	N	
162	2360	Martin	1	130		Classroom 130	W2	Partially Inaccessible	0	N	N	0	N	N	
163	2360	Martin	1	130		Classroom 130	W3	Flaking	120	Y	Y - On Window Sill	2	N	N	
164	2360	Martin	1	130		Classroom 130	W4	Partially Inaccessible	0	N	N	0	N	N	
165	2360	Martin	1	115		Classroom 115	W2	Flaking	6	N	N	0	N	N	
166	2360	Martin	1	115		Classroom 115	W3	Flaking	14	N	N	0	N	N	
167	2360	Martin	1	H5		Southeast Hallway	W1	Flaking	50	N	N	0	N	N	
168	2360	Martin	1	H5		Southeast Hallway	W2	Cracking	24	N	N	0	Y - 16 SF Posters	N	Additional Chipping
169	2360	Martin	1	H5A		Hallway Vestibule Connecting Southeast and South Hallways	W1	Flaking	4	N	N	0	N	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
170	2360	Martin	1	H5A		Hallway Vestibule Connecting Southeast and South Hallways	W3	Flaking	2	N	N	0	N	N	
171	2360	Martin	1	H5A		Hallway Vestibule Connecting Southeast and South Hallways	W4	Flaking	8	N	N	0	N	N	
172	2360	Martin	1	H5A		Hallway Vestibule Connecting Southeast and South Hallways	Ceiling	Flaking	90	Y	N	0	N	Y - 90 SF	Decorative Ceiling Plaster
173	2360	Martin	1	H5B		Entrance Vestibule between Classrooms 112 & 113	W3	Chipping	5	N	N	0	N	N	
174	2360	Martin	1	H6		South Hallway	W2	Partially Inaccessible	0	N	N	0	Y - 20 SF Posters	N	
175	2360	Martin	1	H6		South Hallway	W4	Partially Inaccessible	0	N	N	0	Y - 20 SF Posters	N	
176	2360	Martin	1	H6		South Hallway	Ceiling	Flaking	16	N	N	0	N	N	Suspended Ceiling
177	2360	Martin	1	H6A		Hallway Vestibule Connecting South and Southwest Hallways	W1	Flaking	15	N	N	0	N	N	
178	2360	Martin	1	H6A		Hallway Vestibule Connecting South and Southwest Hallways	W2	Flaking	15	N	N	0	N	N	
179	2360	Martin	1	H6A		Hallway Vestibule Connecting South and Southwest Hallways	W3	Flaking	10	N	N	0	N	N	
180	2360	Martin	1	H6A		Hallway Vestibule Connecting South and Southwest Hallways	W4	Flaking	10	N	N	0	N	N	Additional Efflorescence
181	2360	Martin	1	H6A		Hallway Vestibule Connecting South and Southwest Hallways	Ceiling	Flaking	120	Y	N	0	N	Y - 120 SF	
182	2360	Martin	1	129		Classroom 129	W1	Chipping	10	N	N	0	Y - 16 SF Desks, Posters	N	
183	2360	Martin	1	129		Classroom 129	W3	Flaking	16	N	N	0	Y - 22 SF Bookcases, Contents	N	
184	2360	Martin	1	112		Classroom 112	W3	Flaking	20	N	N	0	N	N	
185	2360	Martin	1	TL1		Teacher's Lounge across from Classroom 111	Floor	Chipping	60	N	N	0	N	N	Chipping @ Perimeter

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
186	2360	Martin	1	TL1C		Closet inside Teacher's Lounge across from Classroom 111	W1	Flaking	8	Y	N	0	N	Y - 8 SF	
187	2360	Martin	1	TL1C		Closet inside Teacher's Lounge across from Classroom 111	W2	Flaking	18	Y	N	0	N	Y - 16 SF	
188	2360	Martin	1	TL1C		Closet inside Teacher's Lounge across from Classroom 111	Ceiling	Flaking	16	Y	N	0	N	Y - 16 SF	
189	2360	Martin	1	111		Classroom 111	W3	Flaking	40	N	N	0	N	N	
190	2360	Martin	1	128		Classroom 128	W3	Flaking	12	Y	N	0	Y - 20 SF Contents, Posters	N	
191	2360	Martin	1	128C		Classroom 128 Storage Closet C	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Padlocked
192	2360	Martin	1	128C		Classroom 128 Storage Closet C	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
193	2360	Martin	1	128C		Classroom 128 Storage Closet C	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
194	2360	Martin	1	128C		Classroom 128 Storage Closet C	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
195	2360	Martin	1	128C		Classroom 128 Storage Closet C	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
196	2360	Martin	1	128C		Classroom 128 Storage Closet C	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
197	2360	Martin	1	128B		Classroom 128 Storage Closet B	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Padlocked
198	2360	Martin	1	128B		Classroom 128 Storage Closet B	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
199	2360	Martin	1	128B		Classroom 128 Storage Closet B	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
200	2360	Martin	1	128B		Classroom 128 Storage Closet B	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
201	2360	Martin	1	128B		Classroom 128 Storage Closet B	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
202	2360	Martin	1	128B		Classroom 128 Storage Closet B	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
203	2360	Martin	1	110		Classroom 110	W3	Flaking	10	N	N	0	N	N	
204	2360	Martin	1	H7		Southwest Hallway	W1	Flaking	28	N	N	0	N	N	Additional Cracking
205	2360	Martin	1	H7		Southwest Hallway	W3	Flaking	40	N	N	0	N	N	Additional Chipping
206	2360	Martin	1	109		Gymnasium	Ceiling	Flaking	1,800	Y	Y - 20	0	N	Y - 30 SF	Ceiling Debris Continually Falls to Floor
207	2360	Martin	1	109A		Gym Teacher's Office	W2	Flaking	10	N	N	0	N	N	
208	2360	Martin	1	109A		Gym Teacher's Office	W3	Flaking	30	N	N	0	N	N	
209	2360	Martin	1	109A		Gym Teacher's Office	W4	Cracking	6	N	N	0	N	N	Additional Chipping
210	2360	Martin	1	109C		Gymnasium Closet	W1	Flaking	12	N	N	0	Y - 12 SF Gym Equipment	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
211	2360	Martin	1	109C		Gymnasium Closet	W2	Flaking	40	N	N	0	Y - 26 SF Gym Equipment	N	
212	2360	Martin	1	109C		Gymnasium Closet	W3	Flaking	110	N	N	0	Y - 28 SF Gym Equipment	N	
213	2360	Martin	1	109C		Gymnasium Closet	W4	Flaking	25	N	N	0	Y - 22 SF Gym Equipment	N	
214	2360	Martin	1	109C		Gymnasium Closet	Ceiling	Flaking	16	N	N	0	N	N	
215	2360	Martin	1	127		Classroom 127	W1	Chipping	12	N	N	0	N	N	Chipping @ Door
216	2360	Martin	1	127		Classroom 127	W2	Chipping	12	N	N	0	N	N	Chipping @ Door
217	2360	Martin	1	127A		Classroom 127 Closet	Ceiling	Flaking	4	N	N	0	N	N	Additional Chipping; Damage @ Window Lintel
218	2360	Martin	1	126		Computer Lab 126	W3	Efflorescence	12	Y	Y - On Radiator	2	Y - 48 SF Desks, Computers	N	
219	2360	Martin	1	126A		Closet inside Computer Lab 126	Ceiling	Cracking	4	N	N	0	N	N	
220	2360	Martin	1	108A		Women's Restroom across from Classroom 127	Ceiling	Flaking	8	Y	N	0	N	Y - 8 SF	
221	2360	Martin	1	108		Classroom 108	W1	Cracking	12	N	N	0	N	N	Additional Chipping
222	2360	Martin	1	108		Classroom 108	W4	Cracking	12	N	N	0	N	N	
223	2360	Martin	1	108B		Classroom 108 Closet	W1	Flaking	8	N	N	0	N	N	
224	2360	Martin	1	108B		Classroom 108 Closet	W4	Flaking	80	N	N	0	N	N	
225	2360	Martin	1	108B		Classroom 108 Closet	Ceiling	Flaking	80	N	N	0	N	N	
226	2360	Martin	A	S2		Stairwell across from Building Engineer's Office	W1	Flaking	40	Y	N	0	N	N	
227	2360	Martin	A	S2		Stairwell across from Building Engineer's Office	W2	Flaking	40	Y	Y - On Contents	4	Y - 20 SF Contents	N	
228	2360	Martin	A	S2		Stairwell across from Building Engineer's Office	W3	Flaking	50	N	Y - On Contents	3	Y - 20 SF Contents	N	
229	2360	Martin	A	S2		Stairwell across from Building Engineer's Office	W4	Flaking	16	N	N	0	N	N	
230	2360	Martin	A	S2		Stairwell across from Building Engineer's Office	Ceiling	Flaking	16	Y	N	0	N	N	
231	2360	Martin	A	S2		Stairwell across from Building Engineer's Office	Floor	Chipping	60	N	Y - Entire Floor	20	N	N	
232	2360	Martin	A	AH		Attic Hallway	W1	Flaking	4	N	N	0	N	N	
233	2360	Martin	A	AH		Attic Hallway	W2	Flaking	16	N	N	0	N	N	
234	2360	Martin	A	AH		Attic Hallway	W3	Flaking	2	N	N	0	N	N	
235	2360	Martin	A	AH		Attic Hallway	W4	Flaking	24	N	N	0	N	N	
236	2360	Martin	A	AH		Attic Hallway	Ceiling	Flaking	20	N	N	0	N	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
237	2360	Martin	A	130C		Left Attic Classroom	W1	Partially Inaccessible	0	N	N	0	N	N	
238	2360	Martin	A	130C		Left Attic Classroom	W3	Cracking	8	N	N	0	N	N	
239	2360	Martin	A	130C		Left Attic Classroom	W4	Chipping	12	N	N	0	N	N	
240	2360	Martin	A	MS		Music Storage Room	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
241	2360	Martin	A	MS		Music Storage Room	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock; No Key
242	2360	Martin	A	MS		Music Storage Room	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
243	2360	Martin	A	MS		Music Storage Room	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
244	2360	Martin	A	MS		Music Storage Room	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
245	2360	Martin	A	MS		Music Storage Room	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
246	2360	Martin	A	103B		Music Room Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock; No Key
247	2360	Martin	A	103B		Music Room Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
248	2360	Martin	A	103B		Music Room Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
249	2360	Martin	A	103B		Music Room Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
250	2360	Martin	A	103B		Music Room Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
251	2360	Martin	A	103B		Music Room Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
252	2360	Martin	A	138A		Right Attic Music Classroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock; No Key
253	2360	Martin	A	138A		Right Attic Music Classroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
254	2360	Martin	A	138A		Right Attic Music Classroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
255	2360	Martin	A	138A		Right Attic Music Classroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
256	2360	Martin	A	138A		Right Attic Music Classroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
257	2360	Martin	A	138A		Right Attic Music Classroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
258	2360	Bache	1	101	Primary	Classroom 1	W1	Flaking	100	N	N	0	N	N	Additional Cracking
259	2360	Bache	1	101	Primary	Classroom 1	W2	Flaking	150	N	N	0	Y - 60 SF Contents	N	Additional Cracking
260	2360	Bache	1	101	Primary	Classroom 1	W3	Flaking	105	N	N	0	Y - 40 SF Contents	N	Additional Cracking
261	2360	Bache	1	101	Primary	Classroom 1	W4	Flaking	170	N	N	0	Y - 60 SF Contents	N	Additional Cracking
262	2360	Bache	1	101	Primary	Classroom 1	Ceiling	Efflorescence	2	Y	N	0	N	Y - 2 SF	Suspended Ceiling; Water Stains on Ceiling Tiles
263	2360	Bache	1	101	Primary	Classroom 1	Floor	None	0	N	N	0	N	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
264	2360	Bache	1	101A	Storage	Classroom 1 Closet	W1	Chipping	4	N	N	0	N	N	
265	2360	Bache	1	101A	Storage	Classroom 1 Closet	W2	Flaking	80	N	N	0	N	N	
266	2360	Bache	1	101A	Storage	Classroom 1 Closet	W3	Flaking	20	N	N	0	Y - 16 SF Contents	N	
267	2360	Bache	1	101A	Storage	Classroom 1 Closet	W4	Flaking	60	Y	N	0	N	Y - 6 SF	Additional Efflorescence, Cracking, Chipping
268	2360	Bache	1	101A	Storage	Classroom 1 Closet	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
269	2360	Bache	1	101A	Storage	Classroom 1 Closet	Floor	Chipping	8	N	N	0	N	N	Additional Chipping
270	2360	Bache	1	S6	Stairs	Stairwell next to Classroom 1	W1	Flaking	12	N	N	0	N	N	Additional Chipping
271	2360	Bache	1	S6	Stairs	Stairwell next to Classroom 1	W2	Flaking	160	N	N	0	N	N	
272	2360	Bache	1	S6	Stairs	Stairwell next to Classroom 1	W3	Flaking	52	N	N	0	N	N	Additional Cracking
273	2360	Bache	1	S6	Stairs	Stairwell next to Classroom 1	W4	Flaking	160	N	N	0	N	N	Suspended Ceiling/ Water Stains on Ceiling Tiles
274	2360	Bache	1	S6	Stairs	Stairwell next to Classroom 1	Ceiling	None	0	Y	N	0	N	N	
275	2360	Bache	1	S6	Stairs	Stairwell next to Classroom 1	Floor	None	0	N	N	0	N	N	
276	2360	Bache	1	103	Primary	Classrooms 2 and 3	W1	Flaking	2	N	N	0	N	N	Additional Chipping
277	2360	Bache	1	103	Primary	Classrooms 2 and 3	W2	None	0	N	N	0	N	N	No Wall
278	2360	Bache	1	103	Primary	Classrooms 2 and 3	W3	Flaking	6	Y	N	0	Y - 40 SF Bookcases, Books	Y - 2 SF	Additional Efflorescence
279	2360	Bache	1	103	Primary	Classrooms 2 and 3	W4	Partially Inaccessible	0	N	N	0	Y - 90 SF Posters, Bookcases, Contents	N	
280	2360	Bache	1	103	Primary	Classrooms 2 and 3	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
281	2360	Bache	1	103	Primary	Classrooms 2 and 3	Floor	Chipping	40	N	N	0	N	N	Chipping @ Perimeter
282	2360	Bache	1	102	Primary	Classroom 2	W1	None	0	N	N	0	N	N	
283	2360	Bache	1	102	Primary	Classroom 2	W2	Flaking	5	N	N	0	Y - 60 SF Shelves, Contents	N	Additional Cracking, Chipping
284	2360	Bache	1	102	Primary	Classroom 2	W3	Flaking	20	Y	N	0	Y - 20 SF Contents	N	Additional Efflorescence, Cracking
285	2360	Bache	1	102	Primary	Classroom 2	W4	None	0	N	N	0	N	N	
286	2360	Bache	1	102	Primary	Classroom 2	Ceiling	None	0	Y	N	0	N	N	Suspended Ceiling; Water Stains on Ceiling Tiles
287	2360	Bache	1	102	Primary	Classroom 2	Floor	None	0	N	N	0	N	N	
288	2360	Bache	1	102B	Student Restrooms - Male/Female (Classroom)	Student Restroom inside Classroom 2	W1	Chipping	4	N	N	0	N	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
345	2360	Bache	1	105A	Storage	Classroom 5 Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
346	2360	Bache	1	105A	Storage	Classroom 5 Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
347	2360	Bache	1	105A	Storage	Classroom 5 Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
348	2360	Bache	1	S2	Stairs	Stairwell across to Classroom 5	W1	Cracking	30	N	N	0	N	N	Additional Chipping
349	2360	Bache	1	S2	Stairs	Stairwell across to Classroom 5	W2	Flaking	8	Y	Y - On Baseboard	4	N	Y - 4 SF	Additional Efflorescence, Cracking
350	2360	Bache	1	S2	Stairs	Stairwell across to Classroom 5	W3	Flaking	80	Y	Y - On Chair Rail & Baseboard	2	N	Y - 2 SF	Additional Efflorescence
351	2360	Bache	1	S2	Stairs	Stairwell across to Classroom 5	W4	Chipping	2	N	N	0	N	N	
352	2360	Bache	1	S2	Stairs	Stairwell across to Classroom 5	Ceiling	None	0	Y	N	0	N	N	Suspended Ceiling/ Water Stain on Ceiling Tile
353	2360	Bache	1	S2	Stairs	Stairwell across to Classroom 5	Floor	None	0	N	N	0	N	N	
354	2360	Bache	1	106	Primary	Classroom 6	W1	Flaking	70	N	N	0	N	N	Additional Cracking, Chipping
355	2360	Bache	1	106	Primary	Classroom 6	W2	Flaking	120	N	N	0	Y - 10 SF Posters	N	Additional Chipping
356	2360	Bache	1	106	Primary	Classroom 6	W3	Flaking	95	N	N	0	N	N	Additional Cracking, Chipping, Holes; Damage Includes Radiator Grille
357	2360	Bache	1	106	Primary	Classroom 6	W4	Flaking	220	Y	N	0	N	Y - 4 SF	Additional Efflorescence
358	2360	Bache	1	106	Primary	Classroom 6	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
359	2360	Bache	1	106	Primary	Classroom 6	Floor	Chipping	20	N	N	0	N	N	Chipping @ Perimeter
360	2360	Bache	1	106A	Storage	Classroom 6 Closet	W1	Flaking	25	N	N	0	N	N	
361	2360	Bache	1	106A	Storage	Classroom 6 Closet	W2	Partially Inaccessible	0	N	N	0	Y - 30 SF Contents	N	
362	2360	Bache	1	106A	Storage	Classroom 6 Closet	W3	Chipping	4	N	N	0	N	N	
363	2360	Bache	1	106A	Storage	Classroom 6 Closet	W4	Cracking	2	N	N	0	Y - 20 SF Contents	N	
364	2360	Bache	1	106A	Storage	Classroom 6 Closet	Ceiling	Flaking	4	Y	N	0	N	N	Suspended Ceiling; Water Stain on Ceiling Tile; Missing Ceiling Tile
365	2360	Bache	1	106A	Storage	Classroom 6 Closet	Floor	None	0	N	N	0	N	N	
366	2360	Bache	1	H10	Circulation (Hallway)	Hallway next to Classrooms 2 to 6	W1	Flaking	5	N	N	0	N	N	Additional Chipping
367	2360	Bache	1	H10	Circulation (Hallway)	Hallway next to Classrooms 2 to 6	W2	Flaking	32	N	N	0	N	N	Additional Cracking, Chipping
368	2360	Bache	1	H10	Circulation (Hallway)	Hallway next to Classrooms 2 to 6	W3	Flaking	12	N	N	0	N	N	Additional Cracking, Chipping
369	2360	Bache	1	H10	Circulation (Hallway)	Hallway next to Classrooms 2 to 6	W4	Cracking	120	N	N	0	N	N	Additional Chipping
370	2360	Bache	1	H10	Circulation (Hallway)	Hallway next to Classrooms 2 to 6	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
371	2360	Bache	1	H10	Circulation (Hallway)	Hallway next to Classrooms 2 to 6	Floor	None	0	N	N	0	N	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
372	2360	Bache	1	S7	Stairs	Stairwell next to Classroom 6	W1	Flaking	120	N	N	0	N	N	Additional Cracking
373	2360	Bache	1	S7	Stairs	Stairwell next to Classroom 6	W2	Flaking	130	N	N	0	N	N	
374	2360	Bache	1	S7	Stairs	Stairwell next to Classroom 6	W3	Chipping	12	N	N	0	N	N	
375	2360	Bache	1	S7	Stairs	Stairwell next to Classroom 6	W4	Flaking	16	Y	N	0	N	Y - 16 SF	Additional Efflorescence
376	2360	Bache	1	S7	Stairs	Stairwell next to Classroom 6	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
377	2360	Bache	1	S7	Stairs	Stairwell next to Classroom 6	Floor	None	0	N	N	0	N	N	
378	2360	Bache	1	107	Administrative Office	Copy Room 7	W1	Flaking	140	N	N	0	N	N	
379	2360	Bache	1	107	Administrative Office	Copy Room 7	W2	Flaking	45	N	N	0	N	N	Additional Cracking
380	2360	Bache	1	107	Administrative Office	Copy Room 7	W3	Chipping	8	N	N	0	N	N	Chipping @ Doors
381	2360	Bache	1	107	Administrative Office	Copy Room 7	W4	Chipping	12	N	N	0	N	N	
382	2360	Bache	1	107	Administrative Office	Copy Room 7	Ceiling	None	0	Y	N	0	N	N	Suspended Ceiling; Water Stains on Ceiling Tiles
383	2360	Bache	1	107	Administrative Office	Copy Room 7	Floor	Chipping	6	N	N	0	N	N	Chipping @ Perimeter
384	2360	Bache	1	107A	Teacher Lounge/Dining	Staff Lounge next to Classroom 8	W1	Chipping	4	N	N	0	N	N	Chipping @ Door
385	2360	Bache	1	107A	Teacher Lounge/Dining	Staff Lounge next to Classroom 8	W2	Chipping	12	N	N	0	Y - 150 SF Lockers	N	
386	2360	Bache	1	107A	Teacher Lounge/Dining	Staff Lounge next to Classroom 8	W3	Flaking	40	N	N	0	N	N	Additional Cracking
387	2360	Bache	1	107A	Teacher Lounge/Dining	Staff Lounge next to Classroom 8	W4	Chipping	20	N	N	0	Y - 20 SF Couch, Desks	N	
388	2360	Bache	1	107A	Teacher Lounge/Dining	Staff Lounge next to Classroom 8	Ceiling	Cracking	8	Y	N	0	N	N	Suspended Ceiling; Water Stain on Ceiling Tile
389	2360	Bache	1	107A	Teacher Lounge/Dining	Staff Lounge next to Classroom 8	Floor	Chipping	10	N	N	0	N	N	Chipping @ Perimeter
390	2360	Bache	1	107B	Circulation (Hallway)	Hallway to Staff Lounge	W1	Flaking	120	N	N	0	N	N	
391	2360	Bache	1	107B	Circulation (Hallway)	Hallway to Staff Lounge	W2	Cracking	30	N	N	0	N	N	Additional Chipping
392	2360	Bache	1	107B	Circulation (Hallway)	Hallway to Staff Lounge	W3	Flaking	110	N	N	0	N	N	
393	2360	Bache	1	107B	Circulation (Hallway)	Hallway to Staff Lounge	W4	Chipping	6	N	N	0	N	N	
394	2360	Bache	1	107B	Circulation (Hallway)	Hallway to Staff Lounge	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
395	2360	Bache	1	107B	Circulation (Hallway)	Hallway to Staff Lounge	Floor	None	0	N	Y - @ Perimeter	12	N	N	
396	2360	Bache	1	107C	Administrative Office	Office to the left behind Room 7	W1	Flaking	4	N	N	0	N	N	Additional Chipping
397	2360	Bache	1	107C	Administrative Office	Office to the left behind Room 7	W2	Flaking	60	Y	N	0	N	Y - 8 SF	Additional Efflorescence

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
398	2360	Bache	1	107C	Administrative Office	Office to the left behind Room 7	W3	Flaking	50	N	N	0	Y - 80 SF Contents	N	
399	2360	Bache	1	107C	Administrative Office	Office to the left behind Room 7	W4	Chipping	10	N	N	0	Y - 45 SF Contents	N	
400	2360	Bache	1	107C	Administrative Office	Office to the left behind Room 7	Ceiling	Flaking	4	Y	N	0	N	Y - 4 SF	Additional Efflorescence
401	2360	Bache	1	107C	Administrative Office	Office to the left behind Room 7	Floor	None	0	N	N	0	N	N	
402	2360	Bache	1	107D	Administrative Office	Right side office behind Room 7	W1	Chipping	5	N	N	0	N	N	
403	2360	Bache	1	107D	Administrative Office	Right side office behind Room 7	W2	Chipping	2	N	N	0	N	N	
404	2360	Bache	1	107D	Administrative Office	Right side office behind Room 7	W3	Flaking	32	N	N	0	N	Y - 1 SF	
405	2360	Bache	1	107D	Administrative Office	Right side office behind Room 7	W4	Chipping	2	N	N	0	Y - 14 SF Cabinets	N	
406	2360	Bache	1	107D	Administrative Office	Right side office behind Room 7	Ceiling	Efflorescence	4	Y	N	0	N	Y - 4 SF	
407	2360	Bache	1	107D	Administrative Office	Right side office behind Room 7	Floor	Chipping	15	N	N	0	N	N	Chipping @ Perimeter
408	2360	Bache	1	108	Primary	Classroom 8	W1	Flaking	400	N	N	0	N	N	Additional Cracking, Chipping
409	2360	Bache	1	108	Primary	Classroom 8	W2	Chipping	180	N	N	0	N	N	
410	2360	Bache	1	108	Primary	Classroom 8	W3	Flaking	175	N	N	0	Y - 48 SF Contents	N	
411	2360	Bache	1	108	Primary	Classroom 8	W4	Flaking	100	N	N	0	Y - 100 SF Bookcases, Contents	N	Additional Cracking, Chipping
412	2360	Bache	1	108	Primary	Classroom 8	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
413	2360	Bache	1	108	Primary	Classroom 8	Floor	Chipping	60	N	N	0	N	N	Chipping @ Perimeter
414	2360	Bache	1	108A	Storage	Classroom 8 Closet	W1	Flaking	45	N	N	0	N	N	
415	2360	Bache	1	108A	Storage	Classroom 8 Closet	W2	Partially Inaccessible	0	N	N	0	Y - 40 SF Contents	N	
416	2360	Bache	1	108A	Storage	Classroom 8 Closet	W3	Flaking	80	N	N	0	N	Y - 2 SF	
417	2360	Bache	1	108A	Storage	Classroom 8 Closet	W4	Cracking	18	N	N	0	Y - 18 SF Cabinets	N	Additional Chipping
418	2360	Bache	1	108A	Storage	Classroom 8 Closet	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
419	2360	Bache	1	108A	Storage	Classroom 8 Closet	Floor	None	0	N	Y - Perimeter	5	N	N	
420	2360	Bache	1	109	Primary	Classroom 9	W1	Flaking	310	N	N	0	Y - 100 SF Posters	N	Additional Cracking, Chipping
421	2360	Bache	1	109	Primary	Classroom 9	W2	Chipping	30	N	N	0	Y - 120 SF Posters, Bookcases, Contents	N	
422	2360	Bache	1	109	Primary	Classroom 9	W3	Flaking	360	N	N	0	N	Y - 5 SF	Additional Cracking
423	2360	Bache	1	109	Primary	Classroom 9	W4	Flaking	180	N	N	0	Y - 40 SF Posters, Contents	N	Additional Cracking

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
424	2360	Bache	1	109	Primary	Classroom 9	Ceiling	Flaking	30	N	N	0	N	N	Additional Cracking; Suspended Ceiling; Water Stains on Ceiling Tiles; Damage @ Window Lintels
425	2360	Bache	1	109	Primary	Classroom 9	Floor	Chipping	20	N	N	0	N	N	
426	2360	Bache	1	109A	Storage	Classroom 9 Closet	W1	Flaking	60	N	N	0	N	N	Additional Cracking
427	2360	Bache	1	109A	Storage	Classroom 9 Closet	W2	Flaking	60	N	N	0	Y - 21 SF Cabinets	N	Additional Cracking
428	2360	Bache	1	109A	Storage	Classroom 9 Closet	W3	Flaking	28	N	N	0	Y - 36 SF Contents	N	Additional Cracking
429	2360	Bache	1	109A	Storage	Classroom 9 Closet	W4	Cracking	12	N	N	0	N	N	Additional Chipping
430	2360	Bache	1	109A	Storage	Classroom 9 Closet	Ceiling	None	0	Y	N	0	N	N	Suspended Ceiling; Water Stain on Ceiling Tile
431	2360	Bache	1	109A	Storage	Classroom 9 Closet	Floor	None	0	N	N	0	N	N	
432	2360	Bache	1	H13	Circulation (Hallway)	Hallway near Classrooms 7 to 9	W1	Flaking	200	N	N	0	N	N	Additional Cracking, Chipping
433	2360	Bache	1	H13	Circulation (Hallway)	Hallway near Classrooms 7 to 9	W2	Flaking	10	N	N	0	N	N	Additional Cracking
434	2360	Bache	1	H13	Circulation (Hallway)	Hallway near Classrooms 7 to 9	W3	Flaking	510	N	N	0	N	N	Additional Cracking, Chipping
435	2360	Bache	1	H13	Circulation (Hallway)	Hallway near Classrooms 7 to 9	W4	None	0	N	N	0	N	N	No Wall
436	2360	Bache	1	H13	Circulation (Hallway)	Hallway near Classrooms 7 to 9	Ceiling	Flaking	24	Y	N	0	N	Y - 12 SF	Additional Efflorescence; Damage @ Window Lintels
437	2360	Bache	1	H13	Circulation (Hallway)	Hallway near Classrooms 7 to 9	Floor	None	0	N	N	0	N	N	
438	2360	Bache	1	S1	Stairs	Stairwell next to Classroom 9	W1	Flaking	160	N	N	0	N	N	
439	2360	Bache	1	S1	Stairs	Stairwell next to Classroom 9	W2	Flaking	12	Y	Y - On Baseboard	2	N	Y - 4 SF	Additional Efflorescence
440	2360	Bache	1	S1	Stairs	Stairwell next to Classroom 9	W3	Flaking	180	Y	N	0	N	Y - 8 SF	Additional Efflorescence
441	2360	Bache	1	S1	Stairs	Stairwell next to Classroom 9	W4	Cracking	8	N	N	0	N	N	Additional Chipping
442	2360	Bache	1	S1	Stairs	Stairwell next to Classroom 9	Ceiling	None	0	Y	N	0	N	N	Suspended Ceiling; Water Stains on Ceiling Tiles; Flaking Paint Exposed above Missing Ceiling Tiles
443	2360	Bache	1	S1	Stairs	Stairwell next to Classroom 9	Floor	None	0	N	N	0	N	N	
444	2360	Bache	2	210	Primary	Classroom 10	W1	Flaking	65	N	N	0	Y - 40 SF Contents	N	Additional Cracking, Chipping
445	2360	Bache	2	210	Primary	Classroom 10	W2	Flaking	180	N	N	0	Y - 60 SF Tables, Contents	N	
446	2360	Bache	2	210	Primary	Classroom 10	W3	Flaking	120	Y	Y	4	N	Y - 1 SF	Additional Efflorescence, Cracking
447	2360	Bache	2	210	Primary	Classroom 10	W4	Flaking	100	N	N	0	N	Y - 6 SF	Additional Cracking
448	2360	Bache	2	210	Primary	Classroom 10	Ceiling	Efflorescence	16	Y	N	0	N	Y - 16 SF	
449	2360	Bache	2	210	Primary	Classroom 10	Floor	Chipping	100	N	N	0	N	N	Chipping @ Perimeter

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
450	2360	Bache	2	210A	Storage	Classroom 10 Closet	W1	Partially Inaccessible	0	N	N	0	N	N	
451	2360	Bache	2	210A	Storage	Classroom 10 Closet	W2	Flaking	110	N	N	0	N	N	
452	2360	Bache	2	210A	Storage	Classroom 10 Closet	W3	Flaking	18	N	N	0	Y - 30 SF Contents	N	
453	2360	Bache	2	210A	Storage	Classroom 10 Closet	W4	Flaking	80	N	N	0	N	N	
454	2360	Bache	2	210A	Storage	Classroom 10 Closet	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
455	2360	Bache	2	210A	Storage	Classroom 10 Closet	Floor	None	0	N	N	0	N	N	
456	2360	Bache	2	211B	Primary	Women's Restroom next to Classroom 10	W1	None	0	N	N	0	N	N	
457	2360	Bache	2	211B	Primary	Women's Restroom next to Classroom 10	W2	None	0	N	N	0	N	N	
458	2360	Bache	2	211B	Primary	Women's Restroom next to Classroom 10	W3	Flaking	4	N	N	0	N	N	Flaking on Metal Box
459	2360	Bache	2	211B	Primary	Women's Restroom next to Classroom 10	W4	None	0	N	N	0	N	N	
460	2360	Bache	2	211B	Primary	Women's Restroom next to Classroom 10	Ceiling	None	0	N	N	0	N	N	
461	2360	Bache	2	211B	Primary	Women's Restroom next to Classroom 10	Floor	None	0	N	N	0	N	N	
462	2360	Bache	2	211	Primary	Classroom 11	W1	Flaking	260	N	N	0	N	N	Additional Cracking, Chipping
463	2360	Bache	2	211	Primary	Classroom 11	W2	Flaking	34	N	N	0	Y - 60 SF Desks, Contents	N	Additional Cracking, Chipping
464	2360	Bache	2	211	Primary	Classroom 11	W3	Flaking	160	Y	N	0	N	Y - 20 SF	Additional Efflorescence
465	2360	Bache	2	211	Primary	Classroom 11	W4	Cracking	120	N	N	0	N	N	
466	2360	Bache	2	211	Primary	Classroom 11	Ceiling	None	0	Y	N	0	N	N	Suspended Ceiling; Water Stains on Ceiling Tiles
467	2360	Bache	2	211	Primary	Classroom 11	Floor	None	0	N	N	0	N	N	
468	2360	Bache	2	211A	Storage	Classroom 11 Closet	W1	None	0	N	N	0	N	N	
469	2360	Bache	2	211A	Storage	Classroom 11 Closet	W2	Flaking	8	N	N	0	Y - 26 SF Contents	N	Additional Cracking
470	2360	Bache	2	211A	Storage	Classroom 11 Closet	W3	Flaking	20	N	N	0	N	N	
471	2360	Bache	2	211A	Storage	Classroom 11 Closet	W4	Flaking	4	N	N	0	Y - 28 SF Contents	Y - 1 SF	Additional Cracking
472	2360	Bache	2	211A	Storage	Classroom 11 Closet	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
473	2360	Bache	2	211A	Storage	Classroom 11 Closet	Floor	None	0	N	N	0	N	N	
474	2360	Bache	2	212	Primary	Classroom 12	W1	Flaking	480	N	N	0	N	N	Additional Cracking, Chipping

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
501	2360	Bache	2	213A	Storage	Classroom 13 Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
502	2360	Bache	2	213A	Storage	Classroom 13 Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
503	2360	Bache	2	213A	Storage	Classroom 13 Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
504	2360	Bache	2	S5A	Stairs	2nd Floor Fire Exit Stairwell	W1	Flaking	10	N	N	0	N	N	
505	2360	Bache	2	S5A	Stairs	2nd Floor Fire Exit Stairwell	W2	Flaking	40	N	N	0	N	N	
506	2360	Bache	2	S5A	Stairs	2nd Floor Fire Exit Stairwell	W3	Flaking	40	N	N	0	N	N	
507	2360	Bache	2	S5A	Stairs	2nd Floor Fire Exit Stairwell	W4	Flaking	40	N	N	0	N	N	
508	2360	Bache	2	S5A	Stairs	2nd Floor Fire Exit Stairwell	Ceiling	Flaking	40	N	N	0	N	N	
509	2360	Bache	2	S5A	Stairs	2nd Floor Fire Exit Stairwell	Floor	None	0	N	N	0	N	N	
510	2360	Bache	2	250	Service Closets	Custodial Closet across from Classroom 13	W1	Flaking	20	N	N	0	N	Y - 4 SF	Additional Efflorescence
511	2360	Bache	2	250	Service Closets	Custodial Closet across from Classroom 13	W2	Flaking	200	Y	N	0	Y - 160 SF Shelves, Contents	N	
512	2360	Bache	2	250	Service Closets	Custodial Closet across from Classroom 13	W3	Flaking	30	N	N	0	N	N	
513	2360	Bache	2	250	Service Closets	Custodial Closet across from Classroom 13	W4	Flaking	150	N	N	0	Y - 160 SF Shelves, Contents	N	
514	2360	Bache	2	250	Service Closets	Custodial Closet across from Classroom 13	Ceiling	Flaking	16	Y	N	0	N	N	
515	2360	Bache	2	250	Service Closets	Custodial Closet across from Classroom 13	Floor	None	0	N	Y - Perimeter	10	N	N	
516	2360	Bache	2	S2	Stairs	Stairwell across from Classroom 14	W1	Flaking	450	N	N	0	N	N	
517	2360	Bache	2	S2	Stairs	Stairwell across from Classroom 14	W2	Flaking	60	Y	N	0	N	Y - 30 SF	
518	2360	Bache	2	S2	Stairs	Stairwell across from Classroom 14	W3	Flaking	210	N	N	0	N	Y - 2 SF	
519	2360	Bache	2	S2	Stairs	Stairwell across from Classroom 14	W4	Chipping	4	N	N	0	N	N	
520	2360	Bache	2	S2	Stairs	Stairwell across from Classroom 14	Ceiling	Flaking	4	N	N	0	N	Y - 4 SF	
521	2360	Bache	2	S2	Stairs	Stairwell across from Classroom 14	Floor	None	0	N	N	0	N	N	
522	2360	Bache	2	214	Primary	Classroom 14	W1	Flaking	47	N	N	0	N	N	
523	2360	Bache	2	214	Primary	Classroom 14	W2	Flaking	180	N	N	0	N	N	
524	2360	Bache	2	214	Primary	Classroom 14	W3	Flaking	32	N	N	0	N	N	
525	2360	Bache	2	214	Primary	Classroom 14	W4	Flaking	120	N	N	0	N	N	
526	2360	Bache	2	214	Primary	Classroom 14	Ceiling	Efflorescence	8	Y	N	0	N	Y - 5 SF	
527	2360	Bache	2	214	Primary	Classroom 14	Floor	Chipping	8	N	N	0	N	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
528	2360	Bache	2	214A	Storage	Classroom 14 Closet	W1	None	0	N	N	0	48 SF Contents	N	
529	2360	Bache	2	214A	Storage	Classroom 14 Closet	W2	Flaking	12	N	N	0	N	N	
530	2360	Bache	2	214A	Storage	Classroom 14 Closet	W3	Flaking	12	N	N	0	N	N	
531	2360	Bache	2	214A	Storage	Classroom 14 Closet	W4	Partially Inaccessible	0	N	N	0	Y - 80 SF Contents	N	
532	2360	Bache	2	214A	Storage	Classroom 14 Closet	Ceiling	None	0	N	N	0	N	N	
533	2360	Bache	2	214A	Storage	Classroom 14 Closet	Floor	None	0	N	N	0	N	N	
534	2360	Bache	2	215	Primary	Classroom 15	W1	Flaking	120	N	N	0	N	N	Additional Cracking, Chipping
535	2360	Bache	2	215	Primary	Classroom 15	W2	Flaking	22	N	N	0	Y - 120 SF Contents	N	Additional Chipping
536	2360	Bache	2	215	Primary	Classroom 15	W3	Flaking	65	N	N	0	N	N	
537	2360	Bache	2	215	Primary	Classroom 15	W4	Flaking	45	N	N	0	Y - 45 Desks, Posters	N	
538	2360	Bache	2	215	Primary	Classroom 15	Ceiling	Efflorescence	12	Y	N	0	N	N	Suspended Ceiling; Water Stains on Ceiling Tiles
539	2360	Bache	2	215	Primary	Classroom 15	Floor	Chipping	30	N	N	0	N	N	
540	2360	Bache	2	215A	Storage	Classroom 15 Closet	W1	Flaking	36	N	N	0	N	N	Additional Cracking; Damage Includes Pipe
541	2360	Bache	2	215A	Storage	Classroom 15 Closet	W2	Flaking	140	N	N	0	Y - 120 SF Bookcases	N	Additional Cracking
542	2360	Bache	2	215A	Storage	Classroom 15 Closet	W3	None	0	N	N	0	N	N	
543	2360	Bache	2	215A	Storage	Classroom 15 Closet	W4	Flaking	120	N	N	0	N	Y - 2 SF	Additional Chipping, Holes; Plaster Might be Communist
544	2360	Bache	2	215A	Storage	Classroom 15 Closet	Ceiling	Flaking	16	N	N	0	N	Y - 16 SF	
545	2360	Bache	2	215A	Storage	Classroom 15 Closet	Floor	None	0	N	N	0	N	N	
546	2360	Bache	2	215B	Administrative Office	Office 14	W1	Flaking	110	N	N	0	N	N	Additional Cracking
547	2360	Bache	2	215B	Administrative Office	Office 14	W2	Flaking	180	N	N	0	N	N	Additional Cracking
548	2360	Bache	2	215B	Administrative Office	Office 14	W3	Flaking	90	N	N	0	N	N	Additional Cracking
549	2360	Bache	2	215B	Administrative Office	Office 14	W4	Flaking	40	N	N	0	N	N	
550	2360	Bache	2	215B	Administrative Office	Office 14	Ceiling	None	0	Y	N	0	N	N	
551	2360	Bache	2	215B	Administrative Office	Office 14	Floor	None	0	N	Y - @ Windows	5	N	N	
552	2360	Bache	2	H2	Circulation (Hallway)	Hallway near Classrooms 11 to 15	W1	None	0	N	N	0	N	N	No Wall
553	2360	Bache	2	H2	Circulation (Hallway)	Hallway near Classrooms 11 to 15	W2	Flaking	75	N	N	0	N	N	Additional Cracking

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
554	2360	Bache	2	H2	Circulation (Hallway)	Hallway near Classrooms 11 to 15	W3	Flaking	45	N	N	0	N	N	Additional Cracking
555	2360	Bache	2	H2	Circulation (Hallway)	Hallway near Classrooms 11 to 15	W4	Flaking	115	N	N	0	N	N	Additional Cracking
556	2360	Bache	2	H2	Circulation (Hallway)	Hallway near Classrooms 11 to 15	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling Tile
557	2360	Bache	2	H2	Circulation (Hallway)	Hallway near Classrooms 11 to 15	Floor	None	0	N	N	0	N	N	
558	2360	Bache	2	216	IMC (Library)	Library	W1	Chipping	6	N	N	0	N	N	
559	2360	Bache	2	216	IMC (Library)	Library	W2	Flaking	48	N	N	0	Y - 22 SF Desks	N	Additional Cracking
560	2360	Bache	2	216	IMC (Library)	Library	W3	Flaking	22	N	N	0	N	Y - 2 SF	Additional Cracking, Chipping
561	2360	Bache	2	216	IMC (Library)	Library	W4	Flaking	24	N	N	0	Y - 24 SF Bookcases	N	
562	2360	Bache	2	216	IMC (Library)	Library	Ceiling	Flaking	1	Y	N	0	N	Y - SF	Suspended Ceiling
563	2360	Bache	2	216	IMC (Library)	Library	Floor	None	0	N	N	0	N	N	
564	2360	Bache	2	216A	Storage	Library Closet	W1	Cracking	20	N	N	0	20 SF Desks, Contents	N	Classroom Recently Stabilized
565	2360	Bache	2	216A	Storage	Library Closet	W2	None	0	N	N	0	N	N	
566	2360	Bache	2	216A	Storage	Library Closet	W3	Flaking	16	N	N	0	N	N	
567	2360	Bache	2	216A	Storage	Library Closet	W4	None	0	N	N	0	N	N	
568	2360	Bache	2	216A	Storage	Library Closet	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
569	2360	Bache	2	216A	Storage	Library Closet	Floor	None	0	N	N	0	N	N	
570	2360	Bache	2	217A	Storage	Library Closet	W1	Flaking	12	N	N	0	Y - 60 SF Cabinets	N	Additional Cracking, Chipping
571	2360	Bache	2	217A	Storage	Library Closet	W2	Cracking	3	N	N	0	N	N	
572	2360	Bache	2	217A	Storage	Library Closet	W3	Flaking	15	N	Y - On Coat Rack	5	N	N	Additional Cracking
573	2360	Bache	2	217A	Storage	Library Closet	W4	Cracking	5	N	N	0	N	N	
574	2360	Bache	2	217A	Storage	Library Closet	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling Tile
575	2360	Bache	2	217A	Storage	Library Closet	Floor	Chipping	14	N	N	0	N	N	Chipping @ Perimeter
576	2360	Bache	2	218	Primary	Classroom 18	W1	Flaking	22	N	N	0	Y - 20 SF Posters	N	Additional Cracking, Chipping
577	2360	Bache	2	218	Primary	Classroom 18	W2	Flaking	20	N	N	0	N	Y - 4 SF	
578	2360	Bache	2	218	Primary	Classroom 18	W3	Flaking	12	Y	N	0	N	N	
579	2360	Bache	2	218	Primary	Classroom 18	W4	Flaking	89	Y	N	0	Y - 20 SF Posters	N	
580	2360	Bache	2	218	Primary	Classroom 18	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
581	2360	Bache	2	218	Primary	Classroom 18	Floor	Chipping	0	N	N	0	N	N	
582	2360	Bache	2	218A	Storage	Classroom 18 Closet	W1	Flaking	80	N	N	0	N	N	
583	2360	Bache	2	218A	Storage	Classroom 18 Closet	W2	Flaking	48	N	N	0	N	N	Additional Cracking
584	2360	Bache	2	218A	Storage	Classroom 18 Closet	W3	Flaking	120	N	N	0	Y - 120 SF Desks, Books	N	Additional Cracking
585	2360	Bache	2	218A	Storage	Classroom 18 Closet	W4	Partially Inaccessible	N/A	N	N	0	Y - 50 SF Contents	N	
586	2360	Bache	2	218A	Storage	Classroom 18 Closet	Ceiling	None	0	Y	N	0	N	N	Suspended Ceiling

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
587	2360	Bache	2	218A	Storage	Classroom 18 Closet	Floor	Chipping	10	N	N	0	N	N	
588	2360	Bache	2	H2A	Circulation (Hallway)	Hallway outside Library and Classroom 18	W1	Flaking	20	N	N	0	N	N	Additional Cracking
589	2360	Bache	2	H2A	Circulation (Hallway)	Hallway outside Library and Classroom 18	W2	None	0	N	N	0	N	N	
590	2360	Bache	2	H2A	Circulation (Hallway)	Hallway outside Library and Classroom 18	W3	Flaking	250	N	N	0	N	N	
591	2360	Bache	2	H2A	Circulation (Hallway)	Hallway outside Library and Classroom 18	W4	None	0	N	N	0	N	N	
592	2360	Bache	2	H2A	Circulation (Hallway)	Hallway outside Library and Classroom 18	Ceiling	None	0	Y	N	0	N	N	
593	2360	Bache	2	H2A	Circulation (Hallway)	Hallway outside Library and Classroom 18	Floor	None	0	N	N	0	N	N	
594	2360	Bache	2	S1	Stairs	Stairwell next to Classroom 18	W1	Flaking	180	N	N	0	N	N	
595	2360	Bache	2	S1	Stairs	Stairwell next to Classroom 18	W2	Flaking	60	Y	N	0	N	Y - 10 SF	
596	2360	Bache	2	S1	Stairs	Stairwell next to Classroom 18	W3	Flaking	160	N	N	0	N	N	
597	2360	Bache	2	S1	Stairs	Stairwell next to Classroom 18	W4	None	0	N	N	0	N	N	
598	2360	Bache	2	S1	Stairs	Stairwell next to Classroom 18	Ceiling	None	0	N	N	0	N	N	
599	2360	Bache	2	S1	Stairs	Stairwell next to Classroom 18	Floor	None	0	N	N	0	N	N	
600	2360	Bache	3	319	Primary	Classroom 19	W1	Flaking	150	N	N	0	N	N	Additional Chipping; Damage Includes Door
601	2360	Bache	3	319	Primary	Classroom 19	W2	Flaking	450	N	N	0	Y - 110 SF Desks, Contents	N	Additional Cracking, Chipping
602	2360	Bache	3	319	Primary	Classroom 19	W3	Flaking	240	N	N	0	N	N	Additional Cracking; Damage Includes Radiator Grille
603	2360	Bache	3	319	Primary	Classroom 19	W4	Flaking	380	N	N	0	N	N	Additional Cracking, Chipping
604	2360	Bache	3	319	Primary	Classroom 19	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
605	2360	Bache	3	319	Primary	Classroom 19	Floor	Cracking	18	N	N	0	N	N	Additional Chipping; Damage @ Baseboards
606	2360	Bache	3	319A	Storage	Classroom 19 Closet	W1	Flaking	300	N	N	0	N	N	
607	2360	Bache	3	319A	Storage	Classroom 19 Closet	W2	Flaking	30	N	N	0	N	Y - 1 SF	
608	2360	Bache	3	319A	Storage	Classroom 19 Closet	W3	Flaking	300	N	N	0	Y - 150 SF Boxes, Contents	N	
609	2360	Bache	3	319A	Storage	Classroom 19 Closet	W4	Cracking	6	N	N	0	N	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
610	2360	Bache	3	319A	Storage	Classroom 19 Closet	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
611	2360	Bache	3	319A	Storage	Classroom 19 Closet	Floor	Chipping	30	N	N	0	N	N	Chipping @ Perimeter
612	2360	Bache	3	320B	Restrooms, Staff - Male/Female	Staff restroom next to Classroom 20	W1	None	0	N	N	0	N	N	
613	2360	Bache	3	320B	Restrooms, Staff - Male/Female	Staff restroom next to Classroom 20	W2	None	0	N	N	0	N	N	
614	2360	Bache	3	320B	Restrooms, Staff - Male/Female	Staff restroom next to Classroom 20	W3	Cracking	8	N	N	0	N	N	
615	2360	Bache	3	320B	Restrooms, Staff - Male/Female	Staff restroom next to Classroom 20	W4	None	0	N	N	0	N	N	
616	2360	Bache	3	320B	Restrooms, Staff - Male/Female	Staff restroom next to Classroom 20	Ceiling	None	0	N	N	0	N	N	
617	2360	Bache	3	320B	Restrooms, Staff - Male/Female	Staff restroom next to Classroom 20	Floor	None	0	N	N	0	N	N	
618	2360	Bache	3	320	Primary	Classroom 20	W1	None	0	N	N	0	N	N	
619	2360	Bache	3	320	Primary	Classroom 20	W2	Partially Inaccessible	0	N	N	0	Y - 60 SF Bookcases, Books, Contents	N	
620	2360	Bache	3	320	Primary	Classroom 20	W3	Flaking	4	N	N	0	Y - 28 Bookcases, Contents	N	
621	2360	Bache	3	320	Primary	Classroom 20	W4	None	0	N	N	0	N	N	
622	2360	Bache	3	320	Primary	Classroom 20	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
623	2360	Bache	3	320	Primary	Classroom 20	Floor	None	0	N	N	0	N	N	
624	2360	Bache	3	320A	Storage	Classroom 20 Closet	W1	None	0	N	N	0	N	N	
625	2360	Bache	3	320A	Storage	Classroom 20 Closet	W2	None	0	N	N	0	N	N	
626	2360	Bache	3	320A	Storage	Classroom 20 Closet	W3	Flaking	14	N	N	0	N	N	Additional Cracking
627	2360	Bache	3	320A	Storage	Classroom 20 Closet	W4	Cracking	2	N	N	0	N	N	
628	2360	Bache	3	320A	Storage	Classroom 20 Closet	Ceiling	None	0	Y	N	0	N	N	Suspended Ceiling
629	2360	Bache	3	320A	Storage	Classroom 20 Closet	Floor	None	0	N	N	0	N	N	
630	2360	Bache	3	S3	Stairs	Stairwell across from Classroom 21	W1	Flaking	N	N	N	0	N	N	
631	2360	Bache	3	S3	Stairs	Stairwell across from Classroom 21	W2	Flaking	N	N	N	0	N	N	
632	2360	Bache	3	S3	Stairs	Stairwell across from Classroom 21	W3	Flaking	N	N	N	0	N	N	
633	2360	Bache	3	S3	Stairs	Stairwell across from Classroom 21	W4	Chipping	N	N	N	0	N	N	Chipping @ Door
634	2360	Bache	3	S3	Stairs	Stairwell across from Classroom 21	Ceiling	None	Y	N	N	0	N	N	Suspended Ceiling; Water Stains on Ceiling Tiles
635	2360	Bache	3	S3	Stairs	Stairwell across from Classroom 21	Floor	None	N	N	N	0	N	N	
636	2360	Bache	3	321	Primary	Classroom 21	W1	None	0	N	N	0	N	N	Recently Renovated
637	2360	Bache	3	321	Primary	Classroom 21	W2	Efflorescence	4	Y	N	0	N	Y - 4 SF	
638	2360	Bache	3	321	Primary	Classroom 21	W3	Flaking	16	Y	N	0	N	Y - 16 SF	Additional Efflorescence

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
639	2360	Bache	3	321	Primary	Classroom 21	W4	None	0	N	N	0	N	N	
640	2360	Bache	3	321	Primary	Classroom 21	Ceiling	None	0	Y	N	0	N	N	Suspended Ceiling; Water Stains on Ceiling Tiles
641	2360	Bache	3	321	Primary	Classroom 21	Floor	None	0	N	Y - Beneath Windows	1	N	N	
642	2360	Bache	3	321A	Storage	Classroom 21 Closet	W1	None	0	N	N	0	N	N	
643	2360	Bache	3	321A	Storage	Classroom 21 Closet	W2	None	0	N	N	0	N	N	
644	2360	Bache	3	321A	Storage	Classroom 21 Closet	W3	None	0	N	N	0	N	N	
645	2360	Bache	3	321A	Storage	Classroom 21 Closet	W4	None	0	N	N	0	N	N	
646	2360	Bache	3	321A	Storage	Classroom 21 Closet	Ceiling	Flaking	8	N	N	0	N	N	
647	2360	Bache	3	321A	Storage	Classroom 21 Closet	Floor	None	0	N	N	0	N	N	
648	2360	Bache	3	322	Primary	Classrooms 22 and 23	W1	None	0	N	N	0	N	N	Recently Renovated
649	2360	Bache	3	322	Primary	Classrooms 22 and 23	W2	None	0	N	N	0	N	N	
650	2360	Bache	3	322	Primary	Classrooms 22 and 23	W3	Flaking	12	N	N	0	N	N	Additional Chipping; Damage at Radiator Grille & Wall
651	2360	Bache	3	322	Primary	Classrooms 22 and 23	W4	None	0	N	N	0	N	N	
652	2360	Bache	3	322	Primary	Classrooms 22 and 23	Ceiling	None	0	N	N	0	N	N	
653	2360	Bache	3	322	Primary	Classrooms 22 and 23	Floor	None	0	N	N	0	N	N	
654	2360	Bache	3	322A	Storage	Classroom 22/23 Closet	W1	None	0	N	N	0	N	N	
655	2360	Bache	3	322A	Storage	Classroom 22/23 Closet	W2	None	0	N	N	0	N	N	
656	2360	Bache	3	322A	Storage	Classroom 22/23 Closet	W3	None	0	N	N	0	N	N	
657	2360	Bache	3	322A	Storage	Classroom 22/23 Closet	W4	None	0	N	N	0	N	N	
658	2360	Bache	3	322A	Storage	Classroom 22/23 Closet	Ceiling	Flaking	8	N	N	0	N	N	
659	2360	Bache	3	322A	Storage	Classroom 22/23 Closet	Floor	None	0	N	N	0	N	N	
660	2360	Bache	3	323A	Storage	Classroom 22/23 Left Side Closet	W1	None	0	N	N	0	N	N	
661	2360	Bache	3	323A	Storage	Classroom 22/23 Left Side Closet	W2	None	0	N	N	0	N	N	
662	2360	Bache	3	323A	Storage	Classroom 22/23 Left Side Closet	W3	None	0	N	N	0	N	N	
663	2360	Bache	3	323A	Storage	Classroom 22/23 Right Side Closet	W4	None	0	N	N	0	N	N	
664	2360	Bache	3	323A	Storage	Classroom 22/23 Right Side Closet	Ceiling	Flaking	8	N	N	0	N	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
665	2360	Bache	3	323A	Storage	Classroom 22/23 Right Side Closet	Floor	None	0	N	N	0	N	N	
666	2360	Bache	3	S5A	Stairs	3rd Floor Fire Exit Stairwell	W1	Flaking	10	N	N	0	N	N	
667	2360	Bache	3	S5A	Stairs	3rd Floor Fire Exit Stairwell	W2	Flaking	40	N	N	0	N	N	
668	2360	Bache	3	S5A	Stairs	3rd Floor Fire Exit Stairwell	W3	Flaking	20	N	N	0	N	N	
669	2360	Bache	3	S5A	Stairs	3rd Floor Fire Exit Stairwell	W4	Flaking	40	N	N	0	N	N	
670	2360	Bache	3	S5A	Stairs	3rd Floor Fire Exit Stairwell	Ceiling	Flaking	30	N	N	0	N	N	
671	2360	Bache	3	S5A	Stairs	3rd Floor Fire Exit Stairwell	Floor	None	0	N	N	0	N	N	
672	2360	Bache	3	322B	Service Closets	Custodial Closet across from Classroom 22/23	W1	Flaking	200	Y	N	0	N	Y - 200 SF	Additional Efflorescence
673	2360	Bache	3	322B	Service Closets	Custodial Closet across from Classroom 22/23	W2	Flaking	240	Y	N	0	Y - 60 SF Contents	Y - 30 SF	Additional Efflorescence
674	2360	Bache	3	322B	Service Closets	Custodial Closet across from Classroom 22/23	W3	Flaking	80	N	N	0	Y - 20 SF Boxes	N	
675	2360	Bache	3	322B	Service Closets	Custodial Closet across from Classroom 22/23	W4	Flaking	26	N	N	0	Y - 55 SF Boxes, Contents	N	
676	2360	Bache	3	322B	Service Closets	Custodial Closet across from Classroom 22/23	Ceiling	Flaking	4	N	N	0	N	N	Suspended Ceiling; Water Stains on Ceiling Tiles
677	2360	Bache	3	322B	Service Closets	Custodial Closet across from Classroom 22/23	Floor	None	0	N	Y - Entire Floor	180	N	N	
678	2360	Bache	3	S2	Stairs	Stairwell across from Classroom 22	W1	Flaking	75	Y	N	0	N	Y - 6 SF	Additional Efflorescence
679	2360	Bache	3	S2	Stairs	Stairwell across from Classroom 22	W2	Flaking	26	N	N	0	N	N	Additional Cracking
680	2360	Bache	3	S2	Stairs	Stairwell across from Classroom 22	W3	None	0	N	N	0	N	N	
681	2360	Bache	3	S2	Stairs	Stairwell across from Classroom 22	W4	Flaking	240	N	N	0	N	N	
682	2360	Bache	3	S2	Stairs	Stairwell across from Classroom 22	Ceiling	None	0	N	N	0	N	N	
683	2360	Bache	3	S2	Stairs	Stairwell across from Classroom 22	Floor	None	0	N	N	0	N	N	
684	2360	Bache	3	324	Primary	Classroom 24	W1	Flaking	180	N	N	0	Y - 22 SF Posters, Bulletin Boards	N	Additional Cracking, Chipping
685	2360	Bache	3	324	Primary	Classroom 24	W2	Partially Inaccessible	0	N	N	0	Y - 40 SF Bulletin Boards	N	
686	2360	Bache	3	324	Primary	Classroom 24	W3	Flaking	210	N	N	0	N	N	Additional Cracking, Chipping

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
687	2360	Bache	3	324	Primary	Classroom 24	W4	Flaking	145	N	N	0	N	Y - 4 SF	Additional Efflorescence, Cracking, Chipping
688	2360	Bache	3	324	Primary	Classroom 24	Ceiling	Flaking	12	Y	N	0	N	Y - 4 SF	Additional Efflorescence
689	2360	Bache	3	324	Primary	Classroom 24	Floor	Chipping	70	N	N	0	N	N	Chipping @ Baseboards
690	2360	Bache	3	324A	Storage	Classroom 24 Closet	W1	Flaking	36	N	N	0	Y - 20 SF Bookcases, Contents	N	Additional Cracking
691	2360	Bache	3	324A	Storage	Classroom 24 Closet	W2	Chipping	5	N	N	0	N	N	
692	2360	Bache	3	324A	Storage	Classroom 24 Closet	W3	Flaking	66	N	N	0	N	N	Additional Cracking, Chipping
693	2360	Bache	3	324A	Storage	Classroom 24 Closet	W4	Flaking	110	N	N	0	N	N	Additional Cracking
694	2360	Bache	3	324A	Storage	Classroom 24 Closet	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
695	2360	Bache	3	324A	Storage	Classroom 24 Closet	Floor	None	0	N	N	0	N	N	
696	2360	Bache	3	324B	Primary	Office to left of Classroom 25	W1	Flaking	48	N	N	0	Y - 12 SF Contents	N	Additional Cracking, Chipping; Damage Includes Door
697	2360	Bache	3	324B	Primary	Office to left of Classroom 25	W2	Flaking	112	N	N	0	Y - 8 SF Desks	N	Additional Cracking, Chipping
698	2360	Bache	3	324B	Primary	Office to left of Classroom 25	W3	Flaking	72	Y	N	0	N	Y - 2 SF	Additional Efflorescence, Cracking, Chipping
699	2360	Bache	3	324B	Primary	Office to left of Classroom 25	W4	Flaking	84	Y	N	0	Y - 32 SF File Cabinets, Boxes	Y - 16 SF	Additional Efflorescence, Cracking
700	2360	Bache	3	324B	Primary	Office to left of Classroom 25	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
701	2360	Bache	3	324B	Primary	Office to left of Classroom 25	Floor	None	0	N	N	0	N	N	None
702	2360	Bache	3	H3A	Circulation (Hallway)	Hallway near Classrooms 20 to 24	W1	Flaking	510	N	N	0	N	N	Additional Cracking, Chipping
703	2360	Bache	3	H3A	Circulation (Hallway)	Hallway near Classrooms 20 to 24	W2	Flaking	30	N	N	0	N	N	Additional Cracking
704	2360	Bache	3	H3A	Circulation (Hallway)	Hallway near Classrooms 20 to 24	W3	Flaking	260	N	N	0	N	N	Additional Cracking, Chipping
705	2360	Bache	3	H3A	Circulation (Hallway)	Hallway near Classrooms 20 to 24	W4	None	0	N	N	0	N	N	No Wall
706	2360	Bache	3	H3A	Circulation (Hallway)	Hallway near Classrooms 20 to 24	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
707	2360	Bache	3	H3A	Circulation (Hallway)	Hallway near Classrooms 20 to 24	Floor	None	0	N	N	0	N	N	
708	2360	Bache	3	325	Primary	Classroom 25	W1	Chipping	100	N	N	0	Additional Holes	N	
709	2360	Bache	3	325	Primary	Classroom 25	W2	Flaking	120	Y	Y - On Chair Rail	1	Additional Efflorescence, Chipping	Y - 8 SF	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
710	2360	Bache	3	325	Primary	Classroom 25	W3	Cracking	8	N	N	0	Damage Includes Radiator Grilles	N	
711	2360	Bache	3	325	Primary	Classroom 25	W4	None	140	N	N	0		N	
712	2360	Bache	3	325	Primary	Classroom 25	Ceiling	Flaking	30	Y	N	0	Additional Efflorescence; Suspended Ceiling	Y - 8 SF	
713	2360	Bache	3	325	Primary	Classroom 25	Floor	None	0	N	N	0		N	
714	2360	Bache	3	325A	Storage	Classroom 25 Closet	W1	None	0	N	N	0	N	N	Recently Stabilized
715	2360	Bache	3	325A	Storage	Classroom 25 Closet	W2	Partially Inaccessible	0	N	N	0	Y - 120 SF Desks, Chairs, Contents	N	
716	2360	Bache	3	325A	Storage	Classroom 25 Closet	W3	Chipping	3	N	N	0	N	N	Chipping on Door
717	2360	Bache	3	325A	Storage	Classroom 25 Closet	W4	Partially Inaccessible	0	N	N	0	Y - 24 SF Contents	N	
718	2360	Bache	3	325A	Storage	Classroom 25 Closet	Ceiling	None	0	Y	N	0	N	N	
719	2360	Bache	3	325A	Storage	Classroom 25 Closet	Floor	None	0	N	N	0	N	N	
720	2360	Bache	3	326	Primary	Classrooms 26 and 27	W1	None	0	N	N	0	N	N	Recently Stabilized
721	2360	Bache	3	326	Primary	Classrooms 26 and 27	W2	None	0	N	N	0	N	N	
722	2360	Bache	3	326	Primary	Classrooms 26 and 27	W3	Flaking	4	N	N	0	N	N	Flaking @ Radiator Grille
723	2360	Bache	3	326	Primary	Classrooms 26 and 27	W4	None	0	N	N	0	N	N	
724	2360	Bache	3	326	Primary	Classrooms 26 and 27	Ceiling	None	0	N	N	0	N	N	
725	2360	Bache	3	326	Primary	Classrooms 26 and 27	Floor	None	0	N	N	0	N	N	
726	2360	Bache	3	H3	Circulation (Hallway)	Hallway near Classrooms 25 to 27	W1	None	0	N	N	0	N	N	
727	2360	Bache	3	H3	Circulation (Hallway)	Hallway near Classrooms 25 to 27	W2	Flaking	600	Y	N	0	N	Y - 20 SF	Additional Efflorescence, Cracking, Chipping
728	2360	Bache	3	H3	Circulation (Hallway)	Hallway near Classrooms 25 to 27	W3	None	0	N	N	0	N	N	No Wall
729	2360	Bache	3	H3	Circulation (Hallway)	Hallway near Classrooms 25 to 27	W4	Flaking	440	N	N	0	N	N	Additional Cracking, Chipping
730	2360	Bache	3	H3	Circulation (Hallway)	Hallway near Classrooms 25 to 27	Ceiling	None	0	Y	N	0	N	N	Suspended Ceiling; Water Stains on Ceiling Tiles
731	2360	Bache	3	H3	Circulation (Hallway)	Hallway near Classrooms 25 to 27	Floor	None	0	N	N	0	N	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
751	2360	Bache	B	003C	Storage	Storage Area adjacent to Boy's Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
752	2360	Bache	B	003C	Storage	Storage Area adjacent to Boy's Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
753	2360	Bache	B	003C	Storage	Storage Area adjacent to Boy's Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
754	2360	Bache	B	003C	Storage	Storage Area adjacent to Boy's Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
755	2360	Bache	B	003C	Storage	Storage Area adjacent to Boy's Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
756	2360	Bache	B	003D	Storage	Storage Area adjacent to Girls' Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
757	2360	Bache	B	003D	Storage	Storage Area adjacent to Girls' Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
758	2360	Bache	B	003D	Storage	Storage Area adjacent to Girls' Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
759	2360	Bache	B	003D	Storage	Storage Area adjacent to Girls' Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
760	2360	Bache	B	003D	Storage	Storage Area adjacent to Girls' Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
761	2360	Bache	B	003D	Storage	Storage Area adjacent to Girls' Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
762	2360	Bache	B	S3	Stairs	Stairs to Right of Building Engineer's Office	W1	Chipping	10	N	N	0	N	N	Chipping on Handrail
763	2360	Bache	B	S3	Stairs	Stairs to Right of Building Engineer's Office	W2	None	0	N	N	0	N	N	
764	2360	Bache	B	S3	Stairs	Stairs to Right of Building Engineer's Office	W3	Flaking	25	N	N	0	N	N	
765	2360	Bache	B	S3	Stairs	Stairs to Right of Building Engineer's Office	W4	None	0	N	N	0	N	N	
766	2360	Bache	B	S3	Stairs	Stairs to Right of Building Engineer's Office	Ceiling	Flaking	40	N	N	0	N	N	Additional Chipping
767	2360	Bache	B	S3	Stairs	Stairs to Right of Building Engineer's Office	Floor	None	0	N	N	0	N	N	
768	2360	Bache	B	004B	Administrative Office	Building Engineer's Office	W1	Flaking	30	N	N	0	N	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
769	2360	Bache	B	004B	Administrative Office	Building Engineer's Office	W2	Flaking	90	Y	N	0	N	Y - 50 SF	Additional Efflorescence
770	2360	Bache	B	004B	Administrative Office	Building Engineer's Office	W3	Flaking	10	Y	N	0	N	Y - 2 SF	Additional Efflorescence
771	2360	Bache	B	004B	Administrative Office	Building Engineer's Office	W4	Flaking	20	Y	N	0	N	Y - 5 SF	Additional Efflorescence
772	2360	Bache	B	004B	Administrative Office	Building Engineer's Office	Ceiling	Flaking	40	Y	N	0	N	Y - 40 SF	Additional Efflorescence
773	2360	Bache	B	004B	Administrative Office	Building Engineer's Office	Floor	None	0	N	Y - @ Perimeter	20	N	N	
774	2360	Bache	B	004C	Restrooms, Staff - Male	Building Engineer's Restroom	W1	Cracking	4	N	N	0	N	N	
775	2360	Bache	B	004C	Restrooms, Staff - Male	Building Engineer's Restroom	W2	Flaking	4	N	N	0	N	N	
776	2360	Bache	B	004C	Restrooms, Staff - Male	Building Engineer's Restroom	W3	Flaking	2	N	N	0	N	N	
777	2360	Bache	B	004C	Restrooms, Staff - Male	Building Engineer's Restroom	W4	Flaking	6	N	N	0	N	N	
778	2360	Bache	B	004C	Restrooms, Staff - Male	Building Engineer's Restroom	Ceiling	Cracking	6	N	N	0	N	N	
779	2360	Bache	B	004C	Restrooms, Staff - Male	Building Engineer's Restroom	Floor	None	0	N	N	0	N	N	
780	2360	Bache	B	005B	Storage	Tool Closet to left of Building Engineer's Office	W1	Partially Inaccessible	0	N	N	0	Y - 70 SF Shelves, Contents	N	
781	2360	Bache	B	005B	Storage	Tool Closet to left of Building Engineer's Office	W2	Partially Inaccessible	0	N	N	0	Y - 120 SF Shelves, Contents	N	
782	2360	Bache	B	005B	Storage	Tool Closet to left of Building Engineer's Office	W3	Flaking	30	N	N	0	Y - 140 SF Shelves, Contents	N	
783	2360	Bache	B	005B	Storage	Tool Closet to left of Building Engineer's Office	W4	Flaking	30	N	N	0	Y - 60 SF Shelves, Contents	N	
784	2360	Bache	B	005B	Storage	Tool Closet to left of Building Engineer's Office	Ceiling	None	0	N	N	0	N	N	
785	2360	Bache	B	005B	Storage	Tool Closet to left of Building Engineer's Office	Floor	None	0	N	N	0	N	N	
786	2360	Bache	B	005C	Service Closets	Custodial Closet next to Stairwell 3	W1	Flaking	5	N	N	0	N	N	
787	2360	Bache	B	005C	Service Closets	Custodial Closet next to Stairwell 3	W2	Flaking	10	N	N	0	N	N	
788	2360	Bache	B	005C	Service Closets	Custodial Closet next to Stairwell 3	W3	Flaking	10	N	N	0	N	N	
789	2360	Bache	B	005C	Service Closets	Custodial Closet next to Stairwell 3	W4	Flaking	20	N	N	0	N	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
790	2360	Bache	B	005C	Service Closets	Custodial Closet next to Stairwell 3	Ceiling	Flaking	14	N	N	0	N	N	
791	2360	Bache	B	005C	Service Closets	Custodial Closet next to Stairwell 3	Floor	None	0	N	N	0	N	N	
792	2360	Bache	B	S2	Stairs	Stairs next to the Custodial Closet to Left of Building Engineer's Office	W1	None	0	N	N	0	N	N	
793	2360	Bache	B	S2	Stairs	Stairs next to the Custodial Closet to Left of Building Engineer's Office	W2	Chipping	3	N	N	0	N	N	
794	2360	Bache	B	S2	Stairs	Stairs next to the Custodial Closet to Left of Building Engineer's Office	W3	Chipping	10	N	N	0	N	N	Chipping on Handrail
795	2360	Bache	B	S2	Stairs	Stairs next to the Custodial Closet to Left of Building Engineer's Office	W4	None	0	N	N	0	N	N	
796	2360	Bache	B	S2	Stairs	Stairs next to the Custodial Closet to Left of Building Engineer's Office	Ceiling	Chipping	2	N	N	0	N	N	
797	2360	Bache	B	S2	Stairs	Stairs next to the Custodial Closet to Left of Building Engineer's Office	Floor	None	0	N	N	0	N	N	
798	2360	Bache	B	HB1	Circulation (Hallway)	Main Basement Hallway Next to Cafeteria	W1	Flaking	16	N	N	0	N	N	Additional Chipping
799	2360	Bache	B	HB1	Circulation (Hallway)	Main Basement Hallway Next to Cafeteria	W2	Flaking	45	N	N	0	N	N	Additional Chipping
800	2360	Bache	B	HB1	Circulation (Hallway)	Main Basement Hallway Next to Cafeteria	W3	Chipping	2	N	N	0	N	N	
801	2360	Bache	B	HB1	Circulation (Hallway)	Main Basement Hallway Next to Cafeteria	W4	Flaking	60	N	N	0	N	N	
802	2360	Bache	B	HB1	Circulation (Hallway)	Main Basement Hallway Next to Cafeteria	Ceiling	None	0	N	N	0	N	N	Suspended Ceiling
803	2360	Bache	B	HB1	Circulation (Hallway)	Main Basement Hallway Next to Cafeteria	Floor	Chipping	100	N	N	0	N	N	
804	2360	Bache	B	008B	Storage	Storage next to Boiler Room	W1	Flaking	20	N	N	0	N	N	
805	2360	Bache	B	008B	Storage	Storage next to Boiler Room	W2	Flaking	20	N	N	0	N	N	
806	2360	Bache	B	008B	Storage	Storage next to Boiler Room	W3	Flaking	20	N	N	0	N	N	
807	2360	Bache	B	008B	Storage	Storage next to Boiler Room	W4	Flaking	20	N	N	0	N	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
808	2360	Bache	B	008B	Storage	Storage next to Boiler Room	Ceiling	Flaking	20	N	N	0	N	N	
809	2360	Bache	B	008B	Storage	Storage next to Boiler Room	Floor	None	0	N	N	0	N	N	
810	2360	Bache	B	006B	Boiler Room	Boiler Room	W1	Flaking	400	N	N	0	N	N	
811	2360	Bache	B	006B	Boiler Room	Boiler Room	W2	Flaking	250	N	N	0	N	N	
812	2360	Bache	B	006B	Boiler Room	Boiler Room	W3	Flaking	400	N	N	0	N	N	
813	2360	Bache	B	006B	Boiler Room	Boiler Room	W4	Flaking	250	N	N	0	N	N	
814	2360	Bache	B	006B	Boiler Room	Boiler Room	Ceiling	Flaking	500	N	N	0	N	N	
815	2360	Bache	B	006B	Boiler Room	Boiler Room	Floor	None	0	N	Y - @ Perimeter	40	N	N	
816	2360	Bache	B	HB	Storage	Large Storage Area/Hallway adjacent to Boiler Room	W1	Flaking	200	N	N	0	N	N	
817	2360	Bache	B	HB	Storage	Large Storage Area/Hallway adjacent to Boiler Room	W2	Flaking	30	N	N	0	N	N	
818	2360	Bache	B	HB	Storage	Large Storage Area/Hallway adjacent to Boiler Room	W3	Flaking	260	N	N	0	N	N	
819	2360	Bache	B	HB	Storage	Large Storage Area/Hallway adjacent to Boiler Room	W4	Flaking	30	N	N	0	N	N	
820	2360	Bache	B	HB	Storage	Large Storage Area/Hallway adjacent to Boiler Room	Ceiling	Flaking	300	N	N	0	N	N	
821	2360	Bache	B	HB	Storage	Large Storage Area/Hallway adjacent to Boiler Room	Floor	Chipping	100	N	N	0	N	N	
822	2360	Bache	3	S1	Stairs	Stairwell next to Classroom 27	W1	Flaking	20	N	N	0	N	N	
823	2360	Bache	3	S1	Stairs	Stairwell next to Classroom 27	W2	Flaking	10	N	N	0	N	N	
824	2360	Bache	3	S1	Stairs	Stairwell next to Classroom 27	W3	Flaking	16	N	N	0	N	N	
825	2360	Bache	3	S1	Stairs	Stairwell next to Classroom 27	W4	Flaking	12	N	N	0	N	N	
826	2360	Bache	3	S1	Stairs	Stairwell next to Classroom 27	Ceiling	Flaking	20	N	N	0	N	N	
827	2360	Bache	3	S1	Stairs	Stairwell next to Classroom 27	Floor	None	0	N	N	0	N	N	
828	2360	Bache	2	S1	Stairs	Stairwell next to Classroom 18	W1	Flaking	10	N	N	0	N	N	
829	2360	Bache	2	S1	Stairs	Stairwell next to Classroom 18	W2	Flaking	14	N	N	0	N	N	
830	2360	Bache	2	S1	Stairs	Stairwell next to Classroom 18	W3	Flaking	25	N	N	0	N	N	
831	2360	Bache	2	S1	Stairs	Stairwell next to Classroom 18	W4	Flaking	6	N	N	0	N	N	

Bache-Martin -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
832	2360	Bache	2	S1	Stairs	Stairwell next to Classroom 18	Ceiling	Flaking	16	N	N	0	N	N	
833	2360	Bache	2	S1	Stairs	Stairwell next to Classroom 18	Floor	None	0	N	N	0	N	N	
834	2360	Bache	1	S1	Stairs	Stairwell next to Classroom 9	W1	Flaking	8	N	N	0	N	N	
835	2360	Bache	1	S1	Stairs	Stairwell next to Classroom 9	W2	Flaking	8	N	N	0	N	N	
836	2360	Bache	1	S1	Stairs	Stairwell next to Classroom 9	W3	Flaking	18	N	N	0	N	N	
837	2360	Bache	1	S1	Stairs	Stairwell next to Classroom 9	W4	Flaking	20	N	N	0	N	N	
838	2360	Bache	1	S1	Stairs	Stairwell next to Classroom 9	Ceiling	Flaking	20	N	N	0	N	N	
839	2360	Bache	1	S1	Stairs	Stairwell next to Classroom 9	Floor	None	0	N	N	0	N	N	