

CW Henry - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	6250	1	2	200	Primary	Boy's Restroom across from Classroom 208	Ceiling	flaking paint	25						
2	6250	1	2	201	Primary	Classroom 201	W1	flaking paint	24						
3	6250	1	2	201	Primary	Classroom 201	W3	flaking paint	20				posters		
4	6250	1	2	201	Primary	Classroom 201	W4	flaking paint	40						
5	6250	1	2	202	Primary	Classroom 202	W1	flaking paint	20				décor, posters		
6	6250	1	2	202	Primary	Classroom 202	W3	flaking paint	40				posters, bookshelf		
7	6250	1	2	203	Primary	Classroom 203	W1	flaking paint- door frame, closet	50						
8	6250	1	2	203	Primary	Classroom 203	W2	flaking paint	6						
9	6250	1	2	203	Primary	Classroom 203	W3	efflorescence- windows flaking paint	8						
10	6250	1	2	204	Primary	Classroom 204	Ceiling	flaking paint	300						
11	6250	1	2	204	Primary	Classroom 204	W1	flaking paint, chipping paint	40						
12	6250	1	2	204	Primary	Classroom 204	W2	flaking paint	100						
13	6250	1	2	204	Primary	Classroom 204	W3	flaking paint- radiator, above windows	20						
14	6250	1	2	204	Primary	Classroom 204	W4	flaking paint	100						
15	6250	1	2	204A	Storage	Classroom 204 Closet	Ceiling	flaking paint	5						
16	6250	1	2	204A	Storage	Classroom 204 Closet	W1	flaking paint- door jam	10						
17	6250	1	2	204A	Storage	Classroom 204 Closet	W2	flaking paint	80						
18	6250	1	2	204A	Storage	Classroom 204 Closet	W3	flaking paint	50						
19	6250	1	2	204A	Storage	Classroom 204 Closet	W4	flaking paint	105						
20	6250	1	2	206	Primary	Classroom 206	Ceiling	flaking paint	200						
21	6250	1	2	206	Primary	Classroom 206	W1	flaking paint	10						
22	6250	1	2	206	Primary	Classroom 206	W2	flaking paint	6						
23	6250	1	2	206	Primary	Classroom 206	W3	flaking paint- window wells	60						
24	6250	1	2	206	Primary	Classroom 206	W4	flaking paint- left side of wall	4				move file cabinet		
25	6250	1	2	207	Primary	Classroom 207	Floor	Debris under Window			debris below window	6			
26	6250	1	2	207	Primary	Classroom 207	W1	flaking paint- base board	15						
27	6250	1	2	207	Primary	Classroom 207	W2	flaking paint- above chalk board	10						
28	6250	1	2	207	Primary	Classroom 207	W3	flaking paint- window wells	250						
29	6250	1	2	207	Primary	Classroom 207	W4	flaking paint- above chalk board	100						
30	6250	1	2	207A	Storage	Classroom 207 Storage	Ceiling	flaking paint	50						
31	6250	1	2	207A	Storage	Classroom 207 Storage	W1	flaking paint- door jam	10						
32	6250	1	2	207A	Storage	Classroom 207 Storage	W2	flaking paint- above door	80						
33	6250	1	2	207A	Storage	Classroom 207 Storage	W3	efflorescence, flaking paint	35		below radiator	5			
34	6250	1	2	207A	Storage	Classroom 207 Storage	W4	efflorescence, flaking paint	116						
35	6250	1	2	208	Primary	Classroom 208	Ceiling	flaking paint	300						
36	6250	1	2	208	Primary	Classroom 208	W1	flaking paint- chalkboard	20						
37	6250	1	2	208	Primary	Classroom 208	W2	flaking paint- door frames	15						

CW Henry - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
38	6250	1	2	208	Primary	Classroom 208	W3	flaking paint- radiator, sills	75				posters		
39	6250	1	2	208A	Storage	Classroom 208 Storage	Ceiling	flaking paint	80						
40	6250	1	2	208A	Storage	Classroom 208 Storage	W1	flaking paint, chipping paint	60						
41	6250	1	2	208A	Storage	Classroom 208 Storage	W3	flaking paint	100						
42	6250	1	2	208A	Storage	Classroom 208 Storage	W4	flaking paint	10						
43	6250	1	2	209	Primary	Classroom 209	Ceiling	efflorescence, flaking paint	100						
44	6250	1	2	209	Primary	Classroom 209	W1	flaking paint- door jam, chalkboard	10						
45	6250	1	2	209	Primary	Classroom 209	W2	flaking paint	2						
46	6250	1	2	209	Primary	Classroom 209	W3	flaking paint- radiator, pillars	40				posters		
47	6250	1	2	209	Primary	Classroom 209	W4	flaking paint- door jam	10						
48	6250	1	2	210	Primary	Classroom 210	Ceiling	flaking paint	200						
49	6250	1	2	210	Primary	Classroom 210	W1	flaking paint- door jam, near ceiling, chalkboard	30						
50	6250	1	2	210	Primary	Classroom 210	W2	flaking paint	40						
51	6250	1	2	210	Primary	Classroom 210	W3	flaking paint- radiator, right corner	80						
52	6250	1	2	210	Primary	Classroom 210	W4	flaking paint	20						
53	6250	2	2	215	Primary	Classroom 215	Ceiling	flaking paint	40						
54	6250	2	2	215	Primary	Classroom 215	W3	flaking paint- radiator	6						
55	6250	2	2	216	Primary	Classroom 216	Ceiling	flaking paint- circles in ceiling	30						
56	6250	2	2	216	Primary	Classroom 216	W2	flaking paint- radiator	2						
57	6250	2	2	217	Primary	Classroom 217	Ceiling	flaking paint- circles in ceiling	25						
58	6250	2	2	218	Primary	Classroom 218	Ceiling	flaking paint- circles in ceiling	20						
59	6250	2	2	218	Primary	Classroom 218	W4	flaking paint- near door	4						
60	6250	1	2	200A	Student Restrooms - Female (4-12)	Girl's Restroom Across from Classroom 208	Ceiling	flaking paint	150						
61	6250	1	2	2H2	Circulation (Hallway)	Hallway next to Classrooms 201 through 203	Ceiling	flaking paint	150						
62	6250	1	2	2H2	Circulation (Hallway)	Hallway next to Classrooms 201 through 203	W1	flaking paint	150						
63	6250	1	2	2H2	Circulation (Hallway)	Hallway next to Classrooms 201 through 203	W2	flaking paint- corners of walls	15						
64	6250	1	2	2H2	Circulation (Hallway)	Hallway next to Classrooms 201 through 203	W3	flaking paint	100						
65	6250	1	2	H21	Circulation (Hallway)	Hallway next to Classrooms 204 through 207	W1	flaking paint	60				around lockers		
66	6250	1	2	H21	Circulation (Hallway)	Hallway next to Classrooms 204 through 207	W2	flaking paint	4						
67	6250	1	2	H21	Circulation (Hallway)	Hallway next to Classrooms 204 through 207	W3	flaking paint	400						

CW Henry - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
68	6250	1	2	H21	Circulation (Hallway)	Hallway next to Classrooms 204 through 207	W4	flaking paint	4						
69	6250	2	2	3H2	Circulation (Hallway)	Hallway next to Classrooms 214 through 217	W1	flaking paint	8					yes	
70	6250	2	2	3H2	Circulation (Hallway)	Hallway next to Classrooms 214 through 217	W2	flaking paint- next to room 215	2						
71	6250	2	2	3H2	Circulation (Hallway)	Hallway next to Classrooms 214 through 217	W4	flaking paint	10						
72	6250	1	2	205A	Restrooms, Staff - Male/Female	Staff Restroom in 2nd Floor Teacher's Lounge next to Classroom 204	Ceiling	chipped paint	35						
73	6250	1	2	S26	Stairs	Stairs Next to Classroom 201	Ceiling	flaking paint	6						
74	6250	1	2	S26	Stairs	Stairs Next to Classroom 201	W2	flaking paint	4						
75	6250	1	2	S26	Stairs	Stairs Next to Classroom 201	W3	flaking paint	4						
76	6250	1	2	S26	Stairs	Stairs Next to Classroom 201	W4	flaking paint	12						
77	6250	1	2	S21	Stairs	Stairs Next to Classroom 204	W1	efflorescence, flaking paint	68						
78	6250	1	2	S21	Stairs	Stairs Next to Classroom 204	W2	flaking paint	50					yes	plastering by handrail
79	6250	1	2	S21	Stairs	Stairs Next to Classroom 204	W4	flaking paint, chipping paint	54						
80	6250	1	2	S24	Stairs	Stairs Next to Classroom 208	W1	flaking paint, chipping paint	35						
81	6250	1	2	S24	Stairs	Stairs Next to Classroom 208	W2	flaking paint, chipping paint	40						
82	6250	1	2	S24	Stairs	Stairs Next to Classroom 208	W3	flaking paint	6						
83	6250	1	2	S24	Stairs	Stairs Next to Classroom 208	W4	flaking paint- door jams, walls	20						
84	6250	1	2	203A	Storage	Storage Closet outside Classroom 203	Ceiling	flaking paint	15						
85	6250	1	2	203A	Storage	Storage Closet outside Classroom 203	Floor	holes	2						
86	6250	1	2	203A	Storage	Storage Closet outside Classroom 203	W1	flaking paint	8						
87	6250	1	2	203A	Storage	Storage Closet outside Classroom 203	W2	flaking paint	15						
88	6250	1	2	203A	Storage	Storage Closet outside Classroom 203	W3	flaking paint	4						

CW Henry - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
89	6250	1	2	203A	Storage	Storage Closet outside Classroom 203	W4	flaking paint	12				pipes		
90	6250	1	2	205	Teacher Lounge/Dining	Teacher's Lounge Next to Classroom 204	Ceiling	efflorescence, flaking paint	22						
91	6250	1	2	205	Teacher Lounge/Dining	Teacher's Lounge Next to Classroom 204	W1	flaking paint- door jam, phone line box, top left corner	8						
92	6250	1	2	205	Teacher Lounge/Dining	Teacher's Lounge Next to Classroom 204	W2	flaking paint	2						
93	6250	1	2	205	Teacher Lounge/Dining	Teacher's Lounge Next to Classroom 204	W3	flaking paint	4						
94	6250	1	1	H11	Circulation (Hallway)	1st Floor Hallways next to Classrooms 103 through 105	W3	flaking paint	60				posters, blanket		
95	6250	1	1	H11	Circulation (Hallway)	1st Floor Hallways next to Classrooms 103 through 105	W4	flaking paint	2						
96	6250	1	1	105L	Teacher Lounge/Dining	1st Floor Teacher's Lounge next to Nurse's office	Ceiling	flaking paint- above lights by door	4						
97	6250	1	1	105L	Teacher Lounge/Dining	1st Floor Teacher's Lounge next to Nurse's office	W1	flaking paint- by outlets	10					yes	
98	6250	1	1	105L	Teacher Lounge/Dining	1st Floor Teacher's Lounge next to Nurse's office	W2	flaking paint	20						
99	6250	1	1	105L	Teacher Lounge/Dining	1st Floor Teacher's Lounge next to Nurse's office	W3	flaking paint	10						
100	6250	1	1	105L	Teacher Lounge/Dining	1st Floor Teacher's Lounge next to Nurse's office	W4	flaking paint	20				fridge		
101	6250	1	1	103C	Auditorium	Auditorium	Ceiling	flaking paint- above window	130						
102	6250	1	1	103C	Auditorium	Auditorium	Floor	flaking paint- stage	120						
103	6250	1	1	103C	Auditorium	Auditorium	W1	flaking paint	20						
104	6250	1	1	103C	Auditorium	Auditorium	W2	flaking paint	65						
105	6250	1	1	103C	Auditorium	Auditorium	W3	flaking paint	65						
106	6250	2	1	109A	Student Restrooms - Male (4-12)	Boy's Restroom 109A near Office 108A	Ceiling	flaking paint- corner of wall 1 + 2							
107	6250	1	1	100	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 105	Ceiling	flaking paint- by window	4						

CW Henry - Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
108	6250	1	1	101	Primary	Classroom 101	Ceiling	flaking paint- radiator pipes	10						
109	6250	1	1	101	Primary	Classroom 101	W1	flaking paint	8				wires		
110	6250	1	1	101	Primary	Classroom 101	W2	chipped paint- top left corner	40						
111	6250	1	1	101	Primary	Classroom 101	W3	flaking paint- radiator	50				school supplies poster		
112	6250	1	1	101	Primary	Classroom 101	W4	flaking paint	15				paper towel dispenser		
113	6250	1	1	101T	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	Ceiling	flaking paint	2						
114	6250	1	1	102	Primary	Classroom 102	Ceiling	flaking paint	30						
115	6250	1	1	102	Primary	Classroom 102	W1	flaking paint	250						
116	6250	1	1	102	Primary	Classroom 102	W2	flaking paint	25						
117	6250	1	1	102	Primary	Classroom 102	W3	flaking paint- above windows	30						
118	6250	1	1	102	Primary	Classroom 102	W4	flaking paint	2						
119	6250	1	1	103	Primary	Classroom 103	Ceiling	flaking paint- pipes near window	100	yes				yes	
120	6250	1	1	103	Primary	Classroom 103	Floor	flaking paint	250						wood floor needs new varnish
121	6250	1	1	103	Primary	Classroom 103	W1	flaking paint	60						
122	6250	1	1	103	Primary	Classroom 103	W2	flaking paint, efflorescence- corners	110	yes			bookshelf next to desk, file cabinet		
123	6250	1	1	103	Primary	Classroom 103	W3	flaking paint	120		on radiator	2	bookshelf	yes	
124	6250	1	1	103	Primary	Classroom 103	W4	flaking paint	80	yes			tables		corner of wall 3+4 has new moisture that started in summer of 2018
125	6250	1	1	103C	Storage	Classroom 103 Coat Closet	Floor	flaking paint	50						wood floor needs new varnish
126	6250	1	1	103C	Storage	Classroom 103 Coat Closet	W2	flaking paint, efflorescence	70						
127	6250	1	1	103C	Storage	Classroom 103 Coat Closet	W4	flaking paint	30						
128	6250	1	1	104	Primary	Classroom 104	Ceiling	flaking paint	150						
129	6250	1	1	104	Primary	Classroom 104	Floor	flaking paint	200						wood floor needs new varnish
130	6250	1	1	104	Primary	Classroom 104	W1	flaking paint	10						
131	6250	1	1	104	Primary	Classroom 104	W2	chipping paint	80						
132	6250	1	1	104	Primary	Classroom 104	W3	flaking paint	20						
133	6250	1	1	104	Primary	Classroom 104	W4	flaking paint	30						
134	6250	1	1	104A	Storage	Classroom 104 Coat Closet	Ceiling	flaking paint	50						
135	6250	1	1	104A	Storage	Classroom 104 Coat Closet	Floor	flaking paint	25						wood floor needs new varnish
136	6250	1	1	104A	Storage	Classroom 104 Coat Closet	W1	flaking paint	4						
137	6250	1	1	104A	Storage	Classroom 104 Coat Closet	W2	flaking paint	60						
138	6250	1	1	104A	Storage	Classroom 104 Coat Closet	W3	flaking paint	30						
139	6250	1	1	104A	Storage	Classroom 104 Coat Closet	W4	flaking paint	60						
140	6250	1	1	105	Primary	Classroom 105	Ceiling	flaking paint	300						

CW Henry - Scope of Work

Task ID	ULCS#	Element	Fl oor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
141	6250	1	1	105	Primary	Classroom 105	W3	flaking paint- window sills	4						
142	6250	1	1	105A	Storage	Classroom 105 Closet	Ceiling	flaking paint	60						
143	6250	1	1	105A	Storage	Classroom 105 Closet	W1	flaking paint	60						
144	6250	1	1	105A	Storage	Classroom 105 Closet	W2	flaking paint	8				storage on shelves		
145	6250	1	1	105A	Storage	Classroom 105 Closet	W3	flaking paint	90						
146	6250	1	1	105A	Storage	Classroom 105 Closet	W4	flaking paint	20						
147	6250	1	1	106	Primary	Classroom 106	Ceiling	flaking paint	350		dust on radiator	2			
148	6250	1	1	106	Primary	Classroom 106	W1	flaking paint, chipping paint- above chalk board	40						
149	6250	1	1	106	Primary	Classroom 106	W2	flaking paint- above doors	30				desks, school supplies		
150	6250	1	1	106	Primary	Classroom 106	W3	flaking paint- window wells, radiator	100				desks, shelves		
151	6250	1	1	106	Primary	Classroom 106	W4	flaking paint- doors	120						
152	6250	1	1	106A	Storage	Classroom 106 Closet	Ceiling	flaking paint- top of right door	50						
153	6250	1	1	106A	Storage	Classroom 106 Closet	W1	flaking paint	100						
154	6250	1	1	106A	Storage	Classroom 106 Closet	W3	flaking paint	30						
155	6250	1	1	106A	Storage	Classroom 106 Closet	W4	flaking paint	20						
156	6250	2	1	108	Primary	Classroom 108	Ceiling	flaking paint- circles in ceiling	20						
157	6250	2	1	108	Primary	Classroom 108	W2	flaking paint	8						
158	6250	2	1	108	Primary	Classroom 108	W4	flaking paint- above coat rack	20						
159	6250	2	1	109	Primary	Classroom 109	Ceiling	flaking paint- circles in ceiling	30						
160	6250	2	1	109	Primary	Classroom 109	W2	flaking paint	10						
161	6250	2	1	110	Primary	Classroom 110	Ceiling	flaking paint- circles in ceiling	45						
162	6250	2	1	110	Primary	Classroom 110	W1	flaking paint	6				posters		
163	6250	2	1	110	Primary	Classroom 110	W4	flaking paint	25				ABC posters		
164	6250	1	1	103B	Administrative Office	Counselor's Office across from Classroom 106	Ceiling	flaking paint	50						
165	6250	1	1	103B	Administrative Office	Counselor's Office across from Classroom 106	W2	flaking paint- corner of wall 1 + 2	2						
166	6250	1	1	103B	Administrative Office	Counselor's Office across from Classroom 106	W3	flaking paint	50		window sill, ground	4		yes	
167	6250	1	1	103B	Administrative Office	Counselor's Office across from Classroom 106	W4	flaking paint	15				chair		
168	6250	1	1	114	Lobby	Entrance Foyer/Exterior Stairs at Greene and Carpenter St Entrance	Ceiling	flaking paint	30						

CW Henry - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
169	6250	1	1	114	Lobby	Entrance Foyer/Exterior Stairs at Greene and Carpenter St Entrance	W1	flaking paint- around entrance door	40						
170	6250	1	1	114	Lobby	Entrance Foyer/Exterior Stairs at Greene and Carpenter St Entrance	W2	flaking paint- around stair door	40						
171	6250	1	1	114	Lobby	Entrance Foyer/Exterior Stairs at Greene and Carpenter St Entrance	W3	flaking paint- around radiator	80						
172	6250	1	1	114	Lobby	Entrance Foyer/Exterior Stairs at Greene and Carpenter St Entrance	W4	flaking paint	20						
173	6250	1	1	100A	Student Restrooms - Female (4-12)	Girl's Restroom Across from Classroom 105	Ceiling	flaking paint	4						
174	6250	1	1	1H2	Circulation (Hallway)	Hallway between Auditorium and Classroom 102	Ceiling	flaking paint- near pipes	80						
175	6250	1	1	1H2	Circulation (Hallway)	Hallway between Auditorium and Classroom 102	W1	flaking paint	100				posters		
176	6250	1	1	1H2	Circulation (Hallway)	Hallway between Auditorium and Classroom 102	W3	flaking paint	130				posters		
177	6250	2	1	3H1	Circulation (Hallway)	Hallway near Classroom 109 through Office 108A	W1	flaking paint	12						
178	6250	2	1	3H1	Circulation (Hallway)	Hallway near Classroom 109 through Office 108A	W2	flaking paint- next to room 108	4						
179	6250	2	1	3H1	Circulation (Hallway)	Hallway near Classroom 109 through Office 108A	W4	flaking paint- next to room 108	16						
180	6250	1	1	105B	Lockers - Female	Lockers outside of 1st Floor Counselor's Office	Ceiling	flaking paint	4						
181	6250	1	1	105B	Lockers - Female	Lockers outside of 1st Floor Counselor's Office	W1	flaking paint	4						
182	6250	1	1	105B	Lockers - Female	Lockers outside of 1st Floor Counselor's Office	W2	flaking paint	8					yes	

CW Henry - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
183	6250	1	1	105B	Lockers - Female	Lockers outside of 1st Floor Counselor's Office	W4	flaking paint	12						
184	6250	1	1	107	Administrative Office	Main Office	Ceiling	flaking paint- above window + wall 2	100						
185	6250	1	1	107	Administrative Office	Main Office	W1	holes	2						
186	6250	1	1	107	Administrative Office	Main Office	W2	chipped paint- above dutch door	8				book shelves	yes	
187	6250	1	1	107	Administrative Office	Main Office	W3	flaking paint- window sills	20						
188	6250	1	1	113T	Restrooms, Staff - Male	Men's Restroom in Stairwell near Classroom 104	Ceiling	flaking paint	10						
189	6250	1	1	103A	Administrative Office	Nurse's Front Office	Ceiling	flaking paint	10						
190	6250	1	1	104A	Restrooms, Staff - Male/Female	Nurse's Office Restroom	Ceiling	flaking paint	10					yes	plaster needed by pipes
191	6250	1	1	105A	Storage	Nurse's Office Storage Room	Ceiling	flaking paint	25						
192	6250	1	1	105A	Storage	Nurse's Office Storage Room	W1	flaking paint	5						
193	6250	1	1	105A	Storage	Nurse's Office Storage Room	W3	holes	2				shelf	yes	
194	6250	1	1	105A	Storage	Nurse's Office Storage Room	W4	flaking paint	10						
195	6250	2	1	108A	Administrative Office	Office 108-A	W3	flaking paint	10				instruments		
196	6250	1	1	113	Administrative Office	Office in Stairwell next to Classroom 104	Ceiling	flaking paint	25						
197	6250	1	1	113	Administrative Office	Office in Stairwell next to Classroom 104	W1	flaking paint	20						
198	6250	1	1	113	Administrative Office	Office in Stairwell next to Classroom 104	W2	flaking paint	8						
199	6250	1	1	113	Administrative Office	Office in Stairwell next to Classroom 104	W3	flaking paint	20						
200	6250	1	1	113	Administrative Office	Office in Stairwell next to Classroom 104	W4	flaking paint	25						
201	6250	1	1	107B	Restrooms, Staff - Male/Female	Principal's Office Restroom	W3	flaking paint- right of window	10						
202	6250	1	1	107A	Storage	Principal's Office Storage Closet	Ceiling	No Access							Inspection Required
203	6250	1	1	107A	Storage	Principal's Office Storage Closet	Floor	No Access							Inspection Required
204	6250	1	1	107A	Storage	Principal's Office Storage Closet	W1	No Access							Inspection Required
205	6250	1	1	107A	Storage	Principal's Office Storage Closet	W2	No Access							Inspection Required

CW Henry - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
206	6250	1	1	107A	Storage	Principal's Office Storage Closet	W3	No Access							Inspection Required
207	6250	1	1	107A	Storage	Principal's Office Storage Closet	W4	No Access							Inspection Required
208	6250	1	1	104	Administrative Office	Rear Nurse's Office with Windows	Ceiling	flaking paint	15						
209	6250	1	1	107B	Mechanical Room	Server Room Across from Classroom 102	Ceiling	flaking paint	50						
210	6250	1	1	107B	Mechanical Room	Server Room Across from Classroom 102	W1	flaking paint	10						
211	6250	1	1	107B	Mechanical Room	Server Room Across from Classroom 102	W2	flaking paint	20						
212	6250	1	1	107B	Mechanical Room	Server Room Across from Classroom 102	W3	flaking paint	15						
213	6250	1	1	107B	Mechanical Room	Server Room Across from Classroom 102	W4	flaking paint	20						
214	6250	1	1	112Z	Restrooms, Staff - Male/Female	Staff Restroom in 1st Floor Teacher's Lounge	Ceiling	flaking paint	10						
215	6250	1	1	S11	Stairs	Stairs /Foyer at Visitor Entrance	Floor	flaking paint- stairs up to the first floor	25						
216	6250	1	1	S11	Stairs	Stairs /Foyer at Visitor Entrance	W1	flaking paint	2						
217	6250	1	1	S11	Stairs	Stairs /Foyer at Visitor Entrance	W3	flaking paint- top of foyer near left door	15						
218	6250	1	1	S11	Stairs	Stairs /Foyer at Visitor Entrance	W4	flaking paint	25						
219	6250	1	1	S18	Stairs	Stairs Next to Addition	W2	flaking paint	15						
220	6250	1	1	S18	Stairs	Stairs Next to Addition	W4	flaking paint	10						
221	6250	1	1	S110	Stairs	Stairs to Left of Auditorium	W1	flaking paint	15						
222	6250	1	1	S110	Stairs	Stairs to Left of Auditorium	W2	flaking paint	35						
223	6250	1	1	S110	Stairs	Stairs to Left of Auditorium	W3	flaking paint	40						
224	6250	1	1	S110	Stairs	Stairs to Left of Auditorium	W4	flaking paint	30						
225	6250	2	1	108B	Storage	Storage Closet in Classroom 108	W1	flaking paint	4						
226	6250	1	1	103T	Student Restrooms - Male/Female	Student Restroom in Auditorium	Ceiling	flaking paint	6						
227	6250	1	1	103X	Restrooms, Staff - Female	Women's Restroom next to Auditorium	Ceiling	No Access							Inspection Required

CW Henry - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
228	6250	1	1	103X	Restrooms, Staff - Female	Women's Restroom next to Auditorium	Floor	No Access							Inspection Required
229	6250	1	1	103X	Restrooms, Staff - Female	Women's Restroom next to Auditorium	W1	No Access							Inspection Required
230	6250	1	1	103X	Restrooms, Staff - Female	Women's Restroom next to Auditorium	W2	No Access							Inspection Required
231	6250	1	1	103X	Restrooms, Staff - Female	Women's Restroom next to Auditorium	W3	No Access							Inspection Required
232	6250	1	1	103X	Restrooms, Staff - Female	Women's Restroom next to Auditorium	W4	No Access							Inspection Required
233	6250	1	0	12	Cafeteria	Cafeteria	Ceiling	holes- near pipe flaking paint- above windows	75						
234	6250	1	0	12	Cafeteria	Cafeteria	W1	flaking paint	40						
235	6250	1	0	12	Cafeteria	Cafeteria	W2	flaking paint	20						
236	6250	1	0	12	Cafeteria	Cafeteria	W3	flaking paint	100						
237	6250	1	0	12	Cafeteria	Cafeteria	W4	flaking paint	4						
238	6250	1	0	B4	Primary	Classroom B4	Ceiling	flaking paint, efflorescence	30						
239	6250	1	0	B4	Primary	Classroom B4	W1	flaking paint	10						
240	6250	1	0	B4	Primary	Classroom B4	W2	flaking paint- radiator, wall, pipes	30						
241	6250	1	0	B4	Primary	Classroom B4	W3	flaking paint, efflorescence	300			peg boards, tapestry	yes		
242	6250	1	0	B4	Primary	Classroom B4	W4	flaking paint	20						
243	6250	1	0	001B	Storage	Classroom B4 Storage	Ceiling	flaking paint	20						
244	6250	1	0	001B	Storage	Classroom B4 Storage	W1	flaking paint	60						
245	6250	1	0	001B	Storage	Classroom B4 Storage	W2	flaking paint- above window	30						
246	6250	1	0	001B	Storage	Classroom B4 Storage	W3	flaking paint	100						
247	6250	1	0	001B	Storage	Classroom B4 Storage	W4	flaking paint	5						
248	6250	1	0	6	Primary	Classroom B6 Music Room	W1	flaking paint- beam	40			behind posters			
249	6250	1	0	6	Primary	Classroom B6 Music Room	W2	flaking paint	20			behind posters			
250	6250	1	0	6	Primary	Classroom B6 Music Room	W3	flaking paint- near window	15						
251	6250	1	0	1C	Student Restrooms - Male (4-12)	Girl's Restroom next to Classroom B4	Ceiling	hole- near pipes	25						
252	6250	1	0	1A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom B4	Ceiling	flaking paint	45						
253	6250	1	0	8A	Administrative Office	Gym Teacher's Office in Gym	Ceiling	flaking paint, holes	45						
254	6250	1	0	8A	Administrative Office	Gym Teacher's Office in Gym	W1	flaking paint	10						

CW Henry - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
255	6250	1	0	8A	Administrative Office	Gym Teacher's Office in Gym	W2	flaking paint	20				shelf		
256	6250	1	0	8A	Administrative Office	Gym Teacher's Office in Gym	W3	flaking paint	30				shelves, equipment		
257	6250	1	0	8	Gymnasium - Intermediate Middle	Gymnasium	Ceiling	flaking paint	500						
258	6250	1	0	8	Gymnasium - Intermediate Middle	Gymnasium	W1	flaking paint	20						
259	6250	1	0	8	Gymnasium - Intermediate Middle	Gymnasium	W2	flaking paint- above windows	40						
260	6250	1	0	8	Gymnasium - Intermediate Middle	Gymnasium	W3	flaking paint	20						
261	6250	1	0	8	Gymnasium - Intermediate Middle	Gymnasium	W4	flaking paint	100						
262	6250	1	0	H01	Circulation (Hallway)	Hallway near Classroom B4 and Cafeteria areas	Ceiling	flaking paint- pipes and ceiling	200						
263	6250	1	0	H01	Circulation (Hallway)	Hallway near Classroom B4 and Cafeteria areas	W1	flaking paint	200						
264	6250	1	0	H01	Circulation (Hallway)	Hallway near Classroom B4 and Cafeteria areas	W2	flaking paint- near pipes	10						
265	6250	1	0	H01	Circulation (Hallway)	Hallway near Classroom B4 and Cafeteria areas	W3	flaking paint	600						
266	6250	1	0	H2	Circulation (Hallway)	Hallway next to Music Classroom and Gym	W1	flaking paint, holes- near pipe	25						
267	6250	1	0	H2	Circulation (Hallway)	Hallway next to Music Classroom and Gym	W3	flaking paint	200						
268	6250	1	0	H2	Circulation (Hallway)	Hallway next to Music Classroom and Gym	W4	flaking paint	20						
269	6250	1	0	5A	Storage	Home and School Storage Closet next to Gymnasium	Ceiling	No access							Inspection Required
270	6250	1	0	5A	Storage	Home and School Storage Closet next to Gymnasium	Floor	No access							Inspection Required
271	6250	1	0	5A	Storage	Home and School Storage Closet next to Gymnasium	W1	No access							Inspection Required

CW Henry - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
272	6250	1	0	5A	Storage	Home and School Storage Closet next to Gymnasium	W2	No access							Inspection Required
273	6250	1	0	5A	Storage	Home and School Storage Closet next to Gymnasium	W3	No access							Inspection Required
274	6250	1	0	5A	Storage	Home and School Storage Closet next to Gymnasium	W4	No access							Inspection Required
275	6250	1	0	6A	Kitchen	Kitchen	Ceiling	flaking paint- above pipes near window	20						
276	6250	1	0	6A	Kitchen	Kitchen	W1	flaking paint	20						
277	6250	1	0	6A	Kitchen	Kitchen	W3	flaking paint- near fridge	10						
278	6250	1	0	6A	Kitchen	Kitchen	W4	flaking paint- near duct	10						
279	6250	1	0	S06	Stairs	Stairs in front of Gym to exterior	Ceiling	holes- near pipes	4					yes	
280	6250	1	0	S06	Stairs	Stairs in front of Gym to exterior	Floor	flaking paint	50						
281	6250	1	0	S06	Stairs	Stairs in front of Gym to exterior	W1	flaking paint- above exit door	8						
282	6250	1	0	S06	Stairs	Stairs in front of Gym to exterior	W2	flaking paint	10						
283	6250	1	0	S06	Stairs	Stairs in front of Gym to exterior	W4	flaking paint- rail	40						
284	6250	1	0	S08	Stairs	Stairs in Gym adjacent to Gym Office	W1	flaking paint	20						
285	6250	1	0	S08	Stairs	Stairs in Gym adjacent to Gym Office	W3	flaking paint	8						
286	6250	1	0	S08	Stairs	Stairs in Gym adjacent to Gym Office	W4	flaking paint	8						
287	6250	1	0	S01	Stairs	Stairs Next to Cafeteria in Basement	Ceiling	flaking paint- below stairs	80						
288	6250	1	0	S01	Stairs	Stairs Next to Cafeteria in Basement	W2	flaking paint	20					yes	
289	6250	1	0	S01	Stairs	Stairs Next to Cafeteria in Basement	W3	flaking paint- behind pipes	20						
290	6250	1	0	S01	Stairs	Stairs Next to Cafeteria in Basement	W4	flaking paint	15						
291	6250	1	0	S4	Stairs	Stairs Next to Classroom B4	W1	flaking paint	25						
292	6250	1	0	S4	Stairs	Stairs Next to Classroom B4	W3	flaking paint	2						
293	6250	1	0	S4	Stairs	Stairs Next to Classroom B4	W4	flaking paint- handrail	20						

CW Henry - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
294	6250	1	0	S07	Stairs	Stairs to Left of Classroom B6 near rear of Gym	W1	flaking paint- handrail	10						
295	6250	1	0	S07	Stairs	Stairs to Left of Classroom B6 near rear of Gym	W3	flaking paint	8						
296	6250	1	0	4A	Storage	Storage Room next to Boiler Room Rear	Ceiling	flaking paint	50						
297	6250	1	0	4A	Storage	Storage Room next to Boiler Room Rear	W1	flaking paint	80						
298	6250	1	0	4A	Storage	Storage Room next to Boiler Room Rear	W2	flaking paint	60		dust on floor and boxes	10		yes	
299	6250	1	0	4A	Storage	Storage Room next to Boiler Room Rear	W3	flaking paint	10		dust on floor	20	storage items	yes	
300	6250	1	0	B5A	Storage	Storage Room next to Classroom B5	Ceiling	flaking paint	20						
301	6250	1	0	B5A	Storage	Storage Room next to Classroom B5	W2	flaking paint	50						
302	6250	1	0	B5A	Storage	Storage Room next to Classroom B5	W3	No access							Inspection Required
303	6250	1	0	B5A	Storage	Storage Room next to Classroom B5	W4	flaking paint	30						