

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	1	Store Room 8 - Fan Room next to Cafeteria (Fan Room # 1)	W1	Brick	White	Flaking	380	0.2	Negative
1	B	1	Store Room 8 - Fan Room next to Cafeteria (Fan Room # 1)	W2	Brick	White	Partially Inaccessible	N/A	N/A	N/A
1	B	1	Store Room 8 - Fan Room next to Cafeteria (Fan Room # 1)	W3	Brick	White	Flaking	30	0.1	Negative
1	B	1	Store Room 8 - Fan Room next to Cafeteria (Fan Room # 1)	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	1	Store Room 8 - Fan Room next to Cafeteria (Fan Room # 1)	W4	Brick	White	Flaking	30	0.1	Negative
1	B	1	Store Room 8 - Fan Room next to Cafeteria (Fan Room # 1)	Ceiling	Plaster	White	Flaking	190	0.5	Negative
1	B	1	Store Room 8 - Fan Room next to Cafeteria (Fan Room # 1)	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	B	2	Boy's Restroom outside of Cafeteria	W1	Brick	Tan	Chipping	4	0.4	Negative
1	B	2	Boy's Restroom outside of Cafeteria	W2	Concrete	Tan	Chipping	18	0.1	Negative
1	B	2	Boy's Restroom outside of Cafeteria	W3	Plaster	Tan	Chipping	65	0.2	Negative
1	B	2	Boy's Restroom outside of Cafeteria	W4	Brick	Tan	Cracking	20	0.5	Negative
1	B	2	Boy's Restroom outside of Cafeteria	Ceiling	Plaster	Tan	Chipping	130	0.5	Negative
1	B	2	Boy's Restroom outside of Cafeteria	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	B	3	Store Room 6	W1	Brick	White	Flaking	27	0.1	Negative
1	B	3	Store Room 6	W2	Brick	White	Flaking	30	0.1	Negative
1	B	3	Store Room 6	W3	Brick	White	Flaking	48	0.2	Negative
1	B	3	Store Room 6	W4	Brick	White	Flaking	130	0.1	Negative
1	B	3	Store Room 6	Ceiling	Plaster	White	Spalling	80	0.1	Negative
1	B	3	Store Room 6	Floor	Brick	White	None	N/A	N/A	N/A
1	B	003F	Store Room 5	W1	Brick	White	Flaking	1	0.1	Negative
1	B	003F	Store Room 5	W2	Brick	White	Flaking	25	0.1	Negative
1	B	003F	Store Room 5	W3	Brick	White	Flaking	20	-0.1	Negative
1	B	003F	Store Room 5	W4	Brick	White	Flaking	18	0.2	Negative
1	B	003F	Store Room 5	Ceiling	Plaster	White	Flaking	9	0.1	Negative
1	B	003F	Store Room 5	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	B	003E	Store Room 4	W1	Brick	White	Flaking	17	0.1	Negative
1	B	003E	Store Room 4	W2	Brick	White	Chipping	20	0.1	Negative
1	B	003E	Store Room 4	W3	Brick	White	Cracking	10	0.1	Negative
1	B	003E	Store Room 4	W4	Brick	White	Chipping	28	0.1	Negative
1	B	003E	Store Room 4	Ceiling	Plaster	White	Cracking	6	0.2	Negative
1	B	003E	Store Room 4	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	B	003D	Store Room 3	W1	Metal	Brown	None	N/A	N/A	N/A
1	B	003D	Store Room 3	W2	Brick	White	Flaking	70	0.3	Negative
1	B	003D	Store Room 3	W3	Brick	White	Flaking	30	0.5	Negative
1	B	003D	Store Room 3	W4	Brick	White	Flaking	10	0.1	Negative
1	B	003D	Store Room 3	Ceiling	Plaster	White	Flaking	6	-0.3	Negative
1	B	003D	Store Room 3	Floor	Concrete	Grey	None	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	003C	Store Room 2	W1	Brick	White	Flaking	2	0.2	Negative
1	B	003C	Store Room 2	W2	Brick	White	Spalling	30	0.3	Negative
1	B	003C	Store Room 2	W3	Brick	White	Flaking	17	0.1	Negative
1	B	003C	Store Room 2	W4	Brick	White	Spalling	60	0.1	Negative
1	B	003C	Store Room 2	Ceiling	Plaster	White	Spalling	24	0.2	Negative
1	B	003C	Store Room 2	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	B	003B	Staff Restroom next to Store Room 2	W1	Plaster	White	Cracking	8	0.2	Negative
1	B	003B	Staff Restroom next to Store Room 2	W2	Plaster	White	Flaking	24	0.2	Negative
1	B	003B	Staff Restroom next to Store Room 2	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	003B	Staff Restroom next to Store Room 2	W3	Plaster	White	Flaking	21	0.2	Negative
1	B	003B	Staff Restroom next to Store Room 2	W4	Plaster	White	Flaking	47	0.1	Negative
1	B	003B	Staff Restroom next to Store Room 2	Ceiling	Plaster	White	Flaking	60	0	Negative
1	B	003B	Staff Restroom next to Store Room 2	Floor	Concrete	Black	Chipping	13	1.2	Positive
1	B	001A	Store Room 7	W1	Metal	Brown	None	N/A	N/A	N/A
1	B	001A	Store Room 7	W2	Brick	White	Spalling	200	0.1	Negative
1	B	001A	Store Room 7	W3	Brick	White	Partially Inaccessible	N/A	N/A	N/A
1	B	001A	Store Room 7	W4	Brick	White	Flaking	120	0.2	Negative
1	B	001A	Store Room 7	Ceiling	Plaster	White	Flaking	36	-0.4	Negative
1	B	001A	Store Room 7	Floor	Concrete	Black	None	N/A	N/A	N/A
1	B	S01	Stairwell next to Boy's Restroom	W1	Metal	Brown	None	N/A	N/A	N/A
1	B	S01	Stairwell next to Boy's Restroom	W2	Wood	Tan	Chipping	1	0.3	Negative
1	B	S01	Stairwell next to Boy's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S01	Stairwell next to Boy's Restroom	W3	Plaster	Tan	Spalling	15	0.2	Negative
1	B	S01	Stairwell next to Boy's Restroom	W4	Plaster	Tan	Cracking	17	0.2	Negative
1	B	S01	Stairwell next to Boy's Restroom	Ceiling	Plaster	Tan	Cracking	3	-0.2	Negative
1	B	S01	Stairwell next to Boy's Restroom	Floor	Concrete	Black	Chipping	4	0.3	Negative
1	B	001C	Storage Area below Stairwell next to Boy's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001C	Storage Area below Stairwell next to Boy's Restroom	W2	Plaster	Tan	Flaking	180	0.1	Negative
1	B	001C	Storage Area below Stairwell next to Boy's Restroom	W3	Plaster	Tan	Spalling	30	0.1	Negative
1	B	001C	Storage Area below Stairwell next to Boy's Restroom	W4	Plaster	Tan	Flaking	190	0.2	Negative
1	B	001C	Storage Area below Stairwell next to Boy's Restroom	Ceiling	Plaster	Tan	Spalling	120	0.1	Negative
1	B	001C	Storage Area below Stairwell next to Boy's Restroom	Floor	Concrete	Tan	None	N/A	N/A	N/A
1	B	001B	Food Storage Room next to Cafeteria (labeled Elec MDP)	W1	Brick	White	Cracking	12	0.1	Negative
1	B	001B	Food Storage Room next to Cafeteria (labeled Elec MDP)	W2	Wood	White	Chipping	2	0	Negative
1	B	001B	Food Storage Room next to Cafeteria (labeled Elec MDP)	W3	Brick	White	Cracking	15	0.1	Negative
1	B	001B	Food Storage Room next to Cafeteria (labeled Elec MDP)	W4	Brick	White	Cracking	4	0	Negative
1	B	001B	Food Storage Room next to Cafeteria (labeled Elec MDP)	Ceiling	Plaster	White	Flaking	35	0	Negative

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	001B	Food Storage Room next to Cafeteria (labeled Elec MDP)	Floor	Concrete	White	None	N/A	N/A	N/A
1	B	004A	Storage Room next to Cafeteria	W1	Wood	White	None	N/A	N/A	N/A
1	B	004A	Storage Room next to Cafeteria	W2	Plaster	White	Cracking	50	0.1	Negative
1	B	004A	Storage Room next to Cafeteria	W3	Plaster	White	Cracking	4	0	Negative
1	B	004A	Storage Room next to Cafeteria	W4	Plaster	White	Cracking	22	0.3	Negative
1	B	004A	Storage Room next to Cafeteria	Ceiling	Plaster	White	Cracking	5	0.2	Negative
1	B	004A	Storage Room next to Cafeteria	Floor	Concrete	Black	Chipping	3	0.3	Negative
1	B	004B	Gas Main/Storage Room next to Cafeteria	W1	Wood	Brown	None	N/A	N/A	N/A
1	B	004B	Gas Main/Storage Room next to Cafeteria	W2	Plaster	White	Flaking	90	0.2	Negative
1	B	004B	Gas Main/Storage Room next to Cafeteria	W3	Plaster	White	Flaking	30	0	Negative
1	B	004B	Gas Main/Storage Room next to Cafeteria	W4	Plaster	White	Flaking	50	0.1	Negative
1	B	004B	Gas Main/Storage Room next to Cafeteria	Ceiling	Plaster	White	Flaking	34	0.2	Negative
1	B	004B	Gas Main/Storage Room next to Cafeteria	Floor	Concrete	Black	None	N/A	N/A	N/A
1	B	4	Cafeteria	W1	Plaster	Tan	Chipping	5	15.4	Positive
1	B	4	Cafeteria	W2	Plaster	Blue	Spalling	42	9.9	Positive
1	B	4	Cafeteria	W3	Plaster	Tan	Spalling	78	4.6	Positive
1	B	4	Cafeteria	W4	Brick	Tan	Flaking	54	11.1	Positive
1	B	4	Cafeteria	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	4	Cafeteria	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	4	Cafeteria	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	B	S02	Stairwell next to Cafeteria	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S02	Stairwell next to Cafeteria	W2	Plaster	Tan	Chipping	6	21.4	Positive
1	B	S02	Stairwell next to Cafeteria	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S02	Stairwell next to Cafeteria	W3	Brick	Tan	Chipping	3	40	Positive
1	B	S02	Stairwell next to Cafeteria	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S02	Stairwell next to Cafeteria	W4	Plaster	Tan	Chipping	12	0.1	Negative
1	B	S02	Stairwell next to Cafeteria	Ceiling	Plaster	Tan	Cracking	4	0.5	Negative
1	B	S02	Stairwell next to Cafeteria	Floor	Concrete	Black	None	N/A	N/A	N/A
1	B	H02	Hallway next to Cafeteria	W1	Plaster	Tan	Flaking	62	0.6	Negative
1	B	H02	Hallway next to Cafeteria	W2	Plaster	Tan	Chipping	18	0.1	Negative
1	B	H02	Hallway next to Cafeteria	W2	Wood	Tan	Chipping	12	0	Negative
1	B	H02	Hallway next to Cafeteria	W3	Plaster	Tan	Chipping	1	0.3	Negative
1	B	H02	Hallway next to Cafeteria	W4	Plaster	Tan	Chipping	6	0.3	Negative
1	B	H02	Hallway next to Cafeteria	Ceiling	Concrete	Tan	Flaking	500	-0.2	Negative
1	B	H02	Hallway next to Cafeteria	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H02	Hallway next to Cafeteria	Floor	Concrete	Black	Chipping	50	0.2	Negative
1	B	H01	Hallway from Store Room 1 to the Girl's Restroom	W1	Plaster	Tan	Chipping	2	0.3	Negative
1	B	H01	Hallway from Store Room 1 to the Girl's Restroom	W2	Plaster	Tan	Flaking	80	0.3	Negative

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	H01	Hallway from Store Room 1 to the Girl's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H01	Hallway from Store Room 1 to the Girl's Restroom	W3	Brick	Tan	Chipping	1	0.1	Negative
1	B	H01	Hallway from Store Room 1 to the Girl's Restroom	W4	Plaster	Tan	Cracking	25	0.5	Negative
1	B	H01	Hallway from Store Room 1 to the Girl's Restroom	Ceiling	Concrete	Tan	Chipping	500	-0.5	Negative
1	B	H01	Hallway from Store Room 1 to the Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H01	Hallway from Store Room 1 to the Girl's Restroom	Floor	Concrete	Black	Chipping	30	0.2	Negative
1	B	5	Store Room 1 (Fan Room across from Cafeteria)	W1	Plaster	Green	Flaking	110	0.4	Negative
1	B	5	Store Room 1 (Fan Room across from Cafeteria)	W2	Plaster	Green	Flaking	40	0.2	Negative
1	B	5	Store Room 1 (Fan Room across from Cafeteria)	W3	Plaster	Green	Partially Inaccessible	130	0.3	Negative
1	B	5	Store Room 1 (Fan Room across from Cafeteria)	W4	Plaster	Green	Partially Inaccessible	45	4.9	Positive
1	B	5	Store Room 1 (Fan Room across from Cafeteria)	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Store Room 1 (Fan Room across from Cafeteria)	Ceiling	Plaster	White	Flaking	110	-0.4	Negative
1	B	5	Store Room 1 (Fan Room across from Cafeteria)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5	Store Room 1 (Fan Room across from Cafeteria)	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	B	5B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	W1	Plaster	Green	Flaking	90	0.4	Negative
1	B	5B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	W2	Plaster	Green	Flaking	320	0.2	Negative
1	B	5B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	W3	Plaster	Green	Partially Inaccessible	35	0.3	Negative
1	B	5B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	W4	Plaster	Green	Partially Inaccessible	90	4.9	Positive
1	B	5B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	5B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	Ceiling	Plaster	White	Flaking	750	-0.4	Negative
1	B	5B	Store Room 1 (Fan Room across from Cafeteria) - Rear of Fan Unit	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	B	6	Mechanical Room/Building Engineers Office next to Old Boiler Room	W1	Concrete	Blue	Spalling	5	0.1	Negative
1	B	6	Mechanical Room/Building Engineers Office next to Old Boiler Room	W2	Brick	White	Chipping	4	0.2	Negative
1	B	6	Mechanical Room/Building Engineers Office next to Old Boiler Room	W3	Brick	Blue	Spalling	5	0.2	Negative
1	B	6	Mechanical Room/Building Engineers Office next to Old Boiler Room	W4	Brick	White	Spalling	36	0.3	Negative

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	6	Mechanical Room/Building Engineers Office next to Old Boiler Room	Ceiling	Concrete	White	None	N/A	N/A	N/A
1	B	6	Mechanical Room/Building Engineers Office next to Old Boiler Room	Floor	Concrete	Grey	Chipping	10	0.1	Negative
1	B	7	Old Boiler Room - Inactive Boilers	W1	Brick	White	Chipping	25	0.1	Negative
1	B	7	Old Boiler Room - Inactive Boilers	W2	Brick	White	Flaking	35	0.2	Negative
1	B	7	Old Boiler Room - Inactive Boilers	W3	Concrete	White	Spalling	200	0.3	Negative
1	B	7	Old Boiler Room - Inactive Boilers	W4	Brick	White	Spalling	10	20.4	Positive
1	B	7	Old Boiler Room - Inactive Boilers	Ceiling	Plaster	White	Partially Inaccessible	N/A	N/A	N/A
1	B	7	Old Boiler Room - Inactive Boilers	Floor	Concrete	Brown	None	N/A	N/A	N/A
1	B	8	Boiler Room - Active Boilers	W1	Brick	White	Chipping	3	0.2	Negative
1	B	8	Boiler Room - Active Boilers	W2	Brick	White	Chipping	5	0.2	Negative
1	B	8	Boiler Room - Active Boilers	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	8	Boiler Room - Active Boilers	W3	Concrete	White	Flaking	40	0.3	Negative
1	B	8	Boiler Room - Active Boilers	W4	Plaster	White	Flaking	35	0.2	Negative
1	B	8	Boiler Room - Active Boilers	Ceiling	Plaster	White	Flaking	N/A	0.4	Negative
1	B	8	Boiler Room - Active Boilers	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	8	Boiler Room - Active Boilers	Floor	Brick	Brown	Chipping	600	0.2	Negative
1	B	9	Basement Custodial Break Room beside Girls Restroom	W1	Brick	White	Spalling	1	0.1	Negative
1	B	9	Basement Custodial Break Room beside Girls Restroom	W2	Brick	White	Spalling	20	0.1	Negative
1	B	9	Basement Custodial Break Room beside Girls Restroom	W3	Brick	White	Spalling	6	0.3	Negative
1	B	9	Basement Custodial Break Room beside Girls Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	9	Basement Custodial Break Room beside Girls Restroom	W4	Brick	White	Spalling	1	0.1	Negative
1	B	9	Basement Custodial Break Room beside Girls Restroom	Ceiling	Concrete	White	Flaking	190	0.2	Negative
1	B	9	Basement Custodial Break Room beside Girls Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	9	Basement Custodial Break Room beside Girls Restroom	Floor	Concrete	Black	Flaking	45	0.2	Negative
1	B	10	Girl's Restroom	W1	Plaster	Tan	Cracking	8	-0.2	Negative
1	B	10	Girl's Restroom	W2	Plaster	Tan	Cracking	15	8.7	Positive
1	B	10	Girl's Restroom	W3	Plaster	Tan	Flaking	32	6.1	Positive
1	B	10	Girl's Restroom	W4	Plaster	Tan	Spalling	20	0.7	Positive
1	B	10	Girl's Restroom	Ceiling	Concrete	Tan	Chipping	160	0.7	Positive
1	B	10	Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	10	Girl's Restroom	Floor	Concrete	Grey	Chipping	7	0.2	Negative
1	B	010A	Storage Room across from Girl's Restroom	W1	Brick	Green	Flaking	5	0.1	Negative
1	B	010A	Storage Room across from Girl's Restroom	W2	Brick	Green	Flaking	40	0.3	Negative
1	B	010A	Storage Room across from Girl's Restroom	W3	Brick	Green	Partially Inaccessible	N/A	N/A	N/A
1	B	010A	Storage Room across from Girl's Restroom	W4	Plaster	Green	Spalling	320	0.2	Negative

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	010A	Storage Room across from Girl's Restroom	Ceiling	Concrete	Green	Flaking	80	0.3	Negative
1	B	010A	Storage Room across from Girl's Restroom	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	B	010B	Storage Closet outside of Girl's Restroom	W1	Brick	Green	Cracking	1	0.1	Negative
1	B	010B	Storage Closet outside of Girl's Restroom	W2	Brick	Green	Cracking	5	0.1	Negative
1	B	010B	Storage Closet outside of Girl's Restroom	W3	Brick	Green	Cracking	1	0.3	Negative
1	B	010B	Storage Closet outside of Girl's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010B	Storage Closet outside of Girl's Restroom	W4	Brick	Green	Cracking	1	-0.1	Negative
1	B	010B	Storage Closet outside of Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010B	Storage Closet outside of Girl's Restroom	Ceiling	Concrete	Grey	Cracking	1	0.2	Negative
1	B	010B	Storage Closet outside of Girl's Restroom	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	B	010C	Domestic Hot Water Heater Closet outside of Girl's Restroom	W1	Brick	Tan	Flaking	40	0.1	Negative
1	B	010C	Domestic Hot Water Heater Closet outside of Girl's Restroom	W2	Brick	Tan	Flaking	40	0.2	Negative
1	B	010C	Domestic Hot Water Heater Closet outside of Girl's Restroom	W3	Plaster	Tan	Flaking	30	0.2	Negative
1	B	010C	Domestic Hot Water Heater Closet outside of Girl's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010C	Domestic Hot Water Heater Closet outside of Girl's Restroom	W4	Brick	Tan	Flaking	65	0.1	Negative
1	B	010C	Domestic Hot Water Heater Closet outside of Girl's Restroom	Ceiling	Concrete	Tan	Flaking	75	0.3	Negative
1	B	010C	Domestic Hot Water Heater Closet outside of Girl's Restroom	Floor	Concrete	Tan	None	N/A	N/A	N/A
1	B	S03	Stairwell next to Girl's Restroom	W1	Brick	Tan	Cracking	40	13	Positive
1	B	S03	Stairwell next to Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S03	Stairwell next to Girl's Restroom	W2	Brick	Tan	Chipping	3	13.9	Positive
1	B	S03	Stairwell next to Girl's Restroom	W3	Brick	Tan	Cracking	25	13.4	Positive
1	B	S03	Stairwell next to Girl's Restroom	W4	Brick	Tan	Cracking	3	21.9	Positive
1	B	S03	Stairwell next to Girl's Restroom	Ceiling	Concrete	Tan	Flaking	5	1.1	Positive
1	B	S03	Stairwell next to Girl's Restroom	Floor	Concrete	Black	Cracking	16	0.2	Negative
1	1	S11	Stairwell next to Gym	W1	Wood	Tan	None	N/A	N/A	N/A
1	1	S11	Stairwell next to Gym	W2	Plaster	Tan	None	N/A	N/A	N/A
1	1	S11	Stairwell next to Gym	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S11	Stairwell next to Gym	W2	Brick	Tan	Chipping	3	17.6	Positive
1	1	S11	Stairwell next to Gym	W3	Plaster	Tan	None	N/A	N/A	N/A
1	1	S11	Stairwell next to Gym	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S11	Stairwell next to Gym	W3	Wood	Tan	Chipping	7	0.1	Negative
1	1	S11	Stairwell next to Gym	W4	Plaster	Tan	None	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	S11	Stairwell next to Gym	Ceiling	Plaster	Tan	None	N/A	N/A	N/A
1	1	S11	Stairwell next to Gym	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	1	S12	Stairwell next to Main Office	W1	Wood	Tan	None	N/A	N/A	N/A
1	1	S12	Stairwell next to Main Office	W2	Plaster	Tan	Chipping	1	32	Positive
1	1	S12	Stairwell next to Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S12	Stairwell next to Main Office	W3	Plaster	Red	None	N/A	N/A	N/A
1	1	S12	Stairwell next to Main Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S12	Stairwell next to Main Office	W4	Plaster	Tan	Chipping	7	30	Positive
1	1	S12	Stairwell next to Main Office	Ceiling	Plaster	Tan	None	N/A	N/A	N/A
1	1	S12	Stairwell next to Main Office	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	1	FT1	Fire Tower # 1	W1	Brick	White	Flaking	115	41	Positive
1	1	FT1	Fire Tower # 1	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	FT1	Fire Tower # 1	W2	Brick	White	Chipping	83	41	Positive
1	1	FT1	Fire Tower # 1	W3	Brick	White	Cracking	150	35	Positive
1	1	FT1	Fire Tower # 1	W4	Brick	White	Flaking	115	41	Positive
1	1	FT1	Fire Tower # 1	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	FT1	Fire Tower # 1	Ceiling	Plaster	White	Flaking	155	46	Positive
1	1	FT1	Fire Tower # 1	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	1	FT2	Fire Tower # 2	W1	Brick	White	Flaking	75	31	Positive
1	1	FT2	Fire Tower # 2	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	FT2	Fire Tower # 2	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	FT2	Fire Tower # 2	W2	Brick	White	Flaking	75	28.5	Positive
1	1	FT2	Fire Tower # 2	W3	Brick	White	Cracking	70	37	Positive
1	1	FT2	Fire Tower # 2	W4	Brick	White	Cracking	85	34	Positive
1	1	FT2	Fire Tower # 2	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	FT2	Fire Tower # 2	Ceiling	Plaster	White	Flaking	195	36	Positive
1	1	FT2	Fire Tower # 2	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	1	FT3	Fire Tower # 3	W1	Brick	White	Chipping	6	15.8	Positive
1	1	FT3	Fire Tower # 3	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	FT3	Fire Tower # 3	W2	Brick	White	Chipping	9	15.9	Positive
1	1	FT3	Fire Tower # 3	W3	Brick	White	Chipping	16	19	Positive
1	1	FT3	Fire Tower # 3	W4	Brick	White	Chipping	4	18.5	Positive
1	1	FT3	Fire Tower # 3	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	FT3	Fire Tower # 3	Ceiling	Plaster	White	Cracking	10	27.3	Positive
1	1	FT3	Fire Tower # 3	Floor	Concrete	Grey	N/A	N/A	N/A	N/A
1	1	FT4	Fire Tower # 4	W1	Brick	White	Chipping	10	16.6	Positive
1	1	FT4	Fire Tower # 4	W2	Brick	White	Chipping	5	14.4	Positive
1	1	FT4	Fire Tower # 4	W3	Brick	White	Chipping	14	18.7	Positive

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	FT4	Fire Tower # 4	W4	Brick	White	Chipping	14	17.2	Positive
1	1	FT4	Fire Tower # 4	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	FT4	Fire Tower # 4	Ceiling	Plaster	White	Flaking	54	28.9	Positive
1	1	FT4	Fire Tower # 4	Floor	Concrete	Grey	N/A	N/A	N/A	N/A
1	1	H13	Hallway outside Classrooms 2 -6	W1	Wood	Blue	Flaking	12	0.1	Negative
1	1	H13	Hallway outside Classrooms 2 -6	W2	Plaster	Tan	Flaking	8	26.4	Positive
1	1	H13	Hallway outside Classrooms 2 -6	W2	Brick	Blue	Chipping	16	21.8	Positive
1	1	H13	Hallway outside Classrooms 2 -6	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway outside Classrooms 2 -6	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway outside Classrooms 2 -6	W3	Metal	Red	Chipping	7	-0.2	Negative
1	1	H13	Hallway outside Classrooms 2 -6	W4	Plaster	Tan	Flaking	5	33	Positive
1	1	H13	Hallway outside Classrooms 2 -6	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway outside Classrooms 2 -6	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Hallway outside Classrooms 2 -6	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	Hallway outside Classrooms 8 -11	W1	Brick	Blue	Chipping	15	18	Positive
1	1	H14	Hallway outside Classrooms 8 -11	W2	Plaster	Tan	Flaking	27	29.5	Positive
1	1	H14	Hallway outside Classrooms 8 -11	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	Hallway outside Classrooms 8 -11	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	Hallway outside Classrooms 8 -11	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	Hallway outside Classrooms 8 -11	W3	Plaster	Tan	Flaking	10	26.9	Positive
1	1	H14	Hallway outside Classrooms 8 -11	W4	Plaster	Tan	Flaking	5	24	Positive
1	1	H14	Hallway outside Classrooms 8 -11	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	Hallway outside Classrooms 8 -11	Floor	Wood	Brown	Chipping	20	0.1	Negative
1	1	1	Gym	W1	Plaster	White	None	N/A	N/A	N/A
1	1	1	Gym	W2	Plaster	White	None	N/A	N/A	N/A
1	1	1	Gym	W3	Plaster	White	Flaking	4	0.3	Negative
1	1	1	Gym	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	1	Gym	W4	Plaster	White	None	N/A	N/A	N/A
1	1	1	Gym	Ceiling	Concrete	White	None	N/A	N/A	N/A
1	1	1	Gym	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	1A	Gym Storage Closet	W1	Brick	White	Partially Inaccessible	N/A	N/A	N/A
1	1	1A	Gym Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	1A	Gym Storage Closet	W2	Brick	White	Partially Inaccessible	N/A	N/A	N/A
1	1	1A	Gym Storage Closet	W3	Brick	White	Flaking	36	19.8	Positive
1	1	1A	Gym Storage Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	1A	Gym Storage Closet	W4	Brick	White	Partially Inaccessible	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	1A	Gym Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	1A	Gym Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	1A	Gym Storage Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	2	Classroom 2	W1	Plaster	White	Spalling	4	32	Positive
1	1	2	Classroom 2	W2	Wood	White	Cracking	56	0.4	Negative
1	1	2	Classroom 2	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	2	Classroom 2	W3	Brick	Blue	Flaking	22	21.2	Positive
1	1	2	Classroom 2	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	2	Classroom 2	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	2	Classroom 2	W4	Brick	Blue	Flaking	29	19.2	Positive
1	1	2	Classroom 2	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	2	Classroom 2	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	2	Classroom 2	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	2	Classroom 2	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	2	Classroom 2	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	2A	Classroom 2 Storage Closet	W1	Brick	Tan	Cracking	66	19.8	Positive
1	1	2A	Classroom 2 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	2A	Classroom 2 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	2A	Classroom 2 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	2A	Classroom 2 Storage Closet	W2	Brick	Tan	Chipping	51	21.7	Positive
1	1	2A	Classroom 2 Storage Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	2A	Classroom 2 Storage Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	2A	Classroom 2 Storage Closet	W3	Brick	Tan	Partially Inaccessible	N/A	N/A	N/A
1	1	2A	Classroom 2 Storage Closet	W4	Brick	Tan	Cracking	27	0.3	Negative
1	1	2A	Classroom 2 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	2A	Classroom 2 Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	3	Classroom 3	W1	Plaster	White	None	N/A	N/A	N/A
1	1	3	Classroom 3	W1	Brick	White	Chipping	27	0.4	Negative
1	1	3	Classroom 3	W2	Wood	White	Cracking	20	8.4	Positive
1	1	3	Classroom 3	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	3	Classroom 3	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	3	Classroom 3	W3	Brick	Tan	Flaking	24	22.6	Positive
1	1	3	Classroom 3	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	3	Classroom 3	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	3	Classroom 3	W4	Wood	White	Chipping	64	1.1	Positive
1	1	3	Classroom 3	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	3	Classroom 3	Floor	Wood	Brown	None	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	3A	Classroom 3 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	3A	Classroom 3 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	3A	Classroom 3 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	3A	Classroom 3 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	3A	Classroom 3 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	3A	Classroom 3 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	4	Classroom 4	W1	Plaster	Yellow	None	N/A	N/A	N/A
1	1	4	Classroom 4	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	4	Classroom 4	W2	Wood	Yellow	Chipping	4	0.3	Negative
1	1	4	Classroom 4	W3	Brick	Tan	Flaking	54	21.5	Positive
1	1	4	Classroom 4	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	4	Classroom 4	W4	Wood	Yellow	Chipping	12	8.4	Positive
1	1	4	Classroom 4	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	4	Classroom 4	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	4A	Classroom 4 Storage Closet	W1	Brick	White	Chipping	4	34	Positive
1	1	4A	Classroom 4 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	4A	Classroom 4 Storage Closet	W2	Wood	White	Partially Inaccessible	4	34	Positive
1	1	4A	Classroom 4 Storage Closet	W3	Brick	White	Partially Inaccessible	4	34	Positive
1	1	4A	Classroom 4 Storage Closet	W4	Wood	Brown	Partially Inaccessible	4	34	Positive
1	1	4A	Classroom 4 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	4A	Classroom 4 Storage Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	5	Classroom 5	W1	Plaster	Green	None	N/A	N/A	N/A
1	1	5	Classroom 5	W2	Wood	Tan	Chipping	11	0.2	Negative
1	1	5	Classroom 5	W3	Brick	Tan	Flaking	85	20.9	Positive
1	1	5	Classroom 5	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	5	Classroom 5	W4	Wood	White	Chipping	23	0.7	Negative
1	1	5	Classroom 5	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	5	Classroom 5	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	5A	Classroom 5 Storage Closet	W1	Brick	Green	Chipping	22	23.1	Positive
1	1	5A	Classroom 5 Storage Closet	W2	Wood	Green	Partially Inaccessible	N/A	N/A	N/A
1	1	5A	Classroom 5 Storage Closet	W3	Brick	Green	Partially Inaccessible	N/A	N/A	N/A
1	1	5A	Classroom 5 Storage Closet	W4	Wood	Green	Partially Inaccessible	N/A	N/A	N/A
1	1	5A	Classroom 5 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	5A	Classroom 5 Storage Closet	Floor	Wood	Brown	Partially Inaccessible	N/A	N/A	N/A
1	1	6	Classroom 6	W1	Brick	Tan	None	N/A	N/A	N/A
1	1	6	Classroom 6	W2	Brick	Tan	Cracking	15	18.4	Positive
1	1	6	Classroom 6	W3	Brick	Tan	Cracking	82	20.3	Positive
1	1	6	Classroom 6	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	6	Classroom 6	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	6	Classroom 6	W4	Brick	Tan	Cracking	29	0.3	Negative
1	1	6	Classroom 6	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	6	Classroom 6	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	6A	Classroom 6 Storage Closet	W1	Brick	Green	None	N/A	N/A	N/A
1	1	6A	Classroom 6 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	6A	Classroom 6 Storage Closet	W2	Brick	Green	Cracking	12	28.4	Positive
1	1	6A	Classroom 6 Storage Closet	W3	Brick	Green	Cracking	12	28.4	Positive
1	1	6A	Classroom 6 Storage Closet	W4	Brick	Green	Cracking	5	25	Positive
1	1	6A	Classroom 6 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	6A	Classroom 6 Storage Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	7	Counselor's Office - Front Area	W1	Plaster	Red	None	N/A	N/A	N/A
1	1	7	Counselor's Office - Front Area	W2	Plaster	Red	None	N/A	N/A	N/A
1	1	7	Counselor's Office - Front Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	7	Counselor's Office - Front Area	W3	Plaster	Red	Chipping	1	29.7	Positive
1	1	7	Counselor's Office - Front Area	W4	Plaster	Red	Chipping	2	30.1	Positive
1	1	7	Counselor's Office - Front Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	7	Counselor's Office - Front Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	7A	Counselor's Office - Left Rear Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7A	Counselor's Office - Left Rear Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7A	Counselor's Office - Left Rear Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7A	Counselor's Office - Left Rear Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7A	Counselor's Office - Left Rear Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7A	Counselor's Office - Left Rear Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7B	Counselor's Office - Right Rear Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7B	Counselor's Office - Right Rear Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7B	Counselor's Office - Right Rear Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7B	Counselor's Office - Right Rear Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7B	Counselor's Office - Right Rear Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7B	Counselor's Office - Right Rear Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7C	Staff Restroom across from Classroom 5	W1	Plaster	White	None	N/A	N/A	N/A
1	1	7C	Staff Restroom across from Classroom 5	W2	Plaster	White	None	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	7C	Staff Restroom across from Classroom 5	W3	Plaster	White	None	N/A	N/A	N/A
1	1	7C	Staff Restroom across from Classroom 5	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	7C	Staff Restroom across from Classroom 5	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	7C	Staff Restroom across from Classroom 5	W4	Plaster	White	None	N/A	N/A	N/A
1	1	7C	Staff Restroom across from Classroom 5	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	7C	Staff Restroom across from Classroom 5	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	7D	Custodial Closet next to Counselor's Office	W1	Brick	Tan	Chipping	4	16.4	Positive
1	1	7D	Custodial Closet next to Counselor's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	7D	Custodial Closet next to Counselor's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	7D	Custodial Closet next to Counselor's Office	W3	Brick	Tan	Chipping	N/A	N/A	N/A
1	1	7D	Custodial Closet next to Counselor's Office	W4	Brick	Tan	Chipping	N/A	N/A	N/A
1	1	7D	Custodial Closet next to Counselor's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	7D	Custodial Closet next to Counselor's Office	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	7E	Closet next to Staff Restroom across from Classroom 5	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7E	Closet next to Staff Restroom across from Classroom 5	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7E	Closet next to Staff Restroom across from Classroom 5	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7E	Closet next to Staff Restroom across from Classroom 5	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7E	Closet next to Staff Restroom across from Classroom 5	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7E	Closet next to Staff Restroom across from Classroom 5	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	12	Main Office	W1	Plaster	Tan	None	N/A	N/A	N/A
1	1	12	Main Office	W2	Plaster	Tan	None	N/A	N/A	N/A
1	1	12	Main Office	W3	Plaster	Tan	None	N/A	N/A	N/A
1	1	12	Main Office	W4	Plaster	Tan	Spalling	18	27.4	Positive
1	1	12	Main Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	12	Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	12	Main Office	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	1	12B	Main Office Storage Closet	W1	Brick				29.2	Positive
1	1	12B	Main Office Storage Closet	W2	Brick				33	Positive
1	1	12B	Main Office Storage Closet	W2	N/A	Tan	Spalling	N/A	N/A	N/A
1	1	12B	Main Office Storage Closet	W2	N/A	Tan	Spalling	N/A	N/A	N/A
1	1	12B	Main Office Storage Closet	W3	Brick				34	Positive
1	1	12B	Main Office Storage Closet	W4	Brick				0	Negative
1	1	12B	Main Office Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	12B	Main Office Storage Closet	Floor	Concrete			N/A	N/A	N/A
1	1	12A	Principal's Office	W1	Plaster	White	Cracking	5	29.9	Positive
1	1	12A	Principal's Office	W2	Plaster	White	Spalling	36	17.9	Positive
1	1	12A	Principal's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	12A	Principal's Office	W3	Plaster	White	None	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	12A	Principal's Office	W3	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	12A	Principal's Office	W3	Plaster	White	N/A	N/A	N/A	N/A
1	1	12A	Principal's Office	W4	Plaster	White	Cracking	1	29.1	Positive
1	1	12A	Principal's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	12A	Principal's Office	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	8	Classroom 8	W1	Plaster	Green	Cracking	3	27.4	Positive
1	1	8	Classroom 8	W2	Plaster	Purple	None	N/A	N/A	N/A
1	1	8	Classroom 8	W3	Plaster	White	Flaking	118	24.1	Positive
1	1	8	Classroom 8	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	8	Classroom 8	W4	Plaster	Purple	None	N/A	N/A	N/A
1	1	8	Classroom 8	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	8	Classroom 8	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	8	Classroom 8	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	8A	Classroom 8 Storage Closet	W1	Plaster	White	Flaking	230	23.2	Positive
1	1	8A	Classroom 8 Storage Closet	W2	Plaster	White	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible
1	1	8A	Classroom 8 Storage Closet	W3	Plaster	White	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible
1	1	8A	Classroom 8 Storage Closet	W4	Plaster	White	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible
1	1	8A	Classroom 8 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	8A	Classroom 8 Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	9	Music Classroom 9	W1	Plaster	White	Flaking	23	26.2	Positive
1	1	9	Music Classroom 9	W2	Plaster	White	None	N/A	N/A	N/A
1	1	9	Music Classroom 9	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	9	Music Classroom 9	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	9	Music Classroom 9	W3	Plaster	White	Flaking	85	28.1	Positive
1	1	9	Music Classroom 9	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	9	Music Classroom 9	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	9	Music Classroom 9	W4	Plaster	White	N/A	N/A	N/A	N/A
1	1	9	Music Classroom 9	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	9	Music Classroom 9	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	9	Music Classroom 9	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	9A	Music Classroom 9 Storage Closet	W1	Plaster	Tan	Chipping	17	24	Positive
1	1	9A	Music Classroom 9 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	9A	Music Classroom 9 Storage Closet	W2	Plaster	White	Cracking	24	9.3	Positive
1	1	9A	Music Classroom 9 Storage Closet	W3	Plaster	White	Cracking	24	9.3	Positive
1	1	9A	Music Classroom 9 Storage Closet	W4	Plaster	White	Flaking	32	23	Positive
1	1	9A	Music Classroom 9 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	9A	Music Classroom 9 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	9A	Music Classroom 9 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	9A	Music Classroom 9 Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	10	Classroom 10	W1	Plaster	Blue	None	N/A	N/A	N/A
1	1	10	Classroom 10	W2	Plaster	White	Cracking	3	24.8	Positive
1	1	10	Classroom 10	W3	Plaster	White	Cracking	4	25.4	Positive
1	1	10	Classroom 10	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	10	Classroom 10	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	10	Classroom 10	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	10	Classroom 10	W4	Plaster	White	Cracking	24	9.3	Positive
1	1	10	Classroom 10	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	10	Classroom 10	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	10	Classroom 10	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	10A	Classroom 10 Restroom	W1	Plaster	Tan	None	N/A	N/A	N/A
1	1	10A	Classroom 10 Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	10A	Classroom 10 Restroom	W2	Plaster	Tan	Cracking	6	6	Positive
1	1	10A	Classroom 10 Restroom	W3	Plaster	Tan	Cracking	8	23.7	Positive
1	1	10A	Classroom 10 Restroom	W3	Plaster	Brown	Flaking	26	6	Positive
1	1	10A	Classroom 10 Restroom	W4	Plaster	Tan	Flaking	1	6	Positive
1	1	10A	Classroom 10 Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	10A	Classroom 10 Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	10A	Classroom 10 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	10A	Classroom 10 Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	10B	Classroom 10 Storage Closet	W1	Plaster	Tan	N/A	N/A	N/A	N/A
1	1	10B	Classroom 10 Storage Closet	W2	Plaster	Tan	Cracking	42	23.3	Positive
1	1	10B	Classroom 10 Storage Closet	W3	Plaster	Tan	Cracking	6	6	Positive
1	1	10B	Classroom 10 Storage Closet	W4	Plaster	Tan	Cracking	78	28.1	Positive
1	1	10B	Classroom 10 Storage Closet	Ceiling	Plaster	Tan	N/A	N/A	N/A	N/A
1	1	10B	Classroom 10 Storage Closet	Floor	Wood	Tan	N/A	N/A	N/A	N/A
1	1	11	Classroom 11	W1	Plaster	White	Flaking	39	28.8338	Positive
1	1	11	Classroom 11	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	11	Classroom 11	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	11	Classroom 11	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	11	Classroom 11	W2	Plaster	White	Flaking	9	26.8	Positive
1	1	11	Classroom 11	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	11	Classroom 11	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	11	Classroom 11	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	11	Classroom 11	W3	Plaster	White	Cracking	4	27.6	Positive

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	11	Classroom 11	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	11	Classroom 11	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	11	Classroom 11	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	11	Classroom 11	W4	Plaster	Green	Flaking	32	24.9	Positive
1	1	11	Classroom 11	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	11	Classroom 11	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	11	Classroom 11	Floor	Wood	Tan	N/A	N/A	N/A	N/A
1	1	11A	Classroom 11 Restroom	W1	Plaster	White	Cracking	2	23.6	Positive
1	1	11A	Classroom 11 Restroom	W2	Plaster	White	Cracking	4	26.6	Positive
1	1	11A	Classroom 11 Restroom	W3	Plaster	White	Chipping	11	23.7	Positive
1	1	11A	Classroom 11 Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	11A	Classroom 11 Restroom	W4	Plaster	White	Cracking	9	23.4	Positive
1	1	11A	Classroom 11 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	11A	Classroom 11 Restroom	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	11C	Classroom 11 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	11C	Classroom 11 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	11C	Classroom 11 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	11C	Classroom 11 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	11C	Classroom 11 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	11C	Classroom 11 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H15	Vestibule to Exterior across from Music Classroom 9	W1	Brick	Red	None	N/A	N/A	N/A
1	1	H15	Vestibule to Exterior across from Music Classroom 9	W2	Brick	Red	None	N/A	N/A	N/A
1	1	H15	Vestibule to Exterior across from Music Classroom 9	W3	Brick	Red	None	N/A	N/A	N/A
1	1	H15	Vestibule to Exterior across from Music Classroom 9	W4	Brick	Red	None	N/A	N/A	N/A
1	1	H15	Vestibule to Exterior across from Music Classroom 9	Ceiling	Concrete	White	Partially Inaccessible	N/A	N/A	N/A
1	1	H15	Vestibule to Exterior across from Music Classroom 9	Floor	Concrete	Black	None	N/A	N/A	N/A
1	2	S21	Stairwell next to Classroom 12	W1	Wood	Tan	None	N/A	N/A	N/A
1	2	S21	Stairwell next to Classroom 12	W2	Wood	Tan	None	N/A	N/A	N/A
1	2	S21	Stairwell next to Classroom 12	W2	Brick	Tan	Chipping	2	11.3	Positive
1	2	S21	Stairwell next to Classroom 12	W3	Plaster	Tan	None	N/A	N/A	N/A
1	2	S21	Stairwell next to Classroom 12	W3	Brick	Tan	Cracking	3	25.8	Positive
1	2	S21	Stairwell next to Classroom 12	W4	Plaster	Tan	None	N/A	N/A	N/A
1	2	S21	Stairwell next to Classroom 12	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairwell next to Classroom 12	Ceiling	Plaster	Tan	None	N/A	N/A	N/A
1	2	S21	Stairwell next to Classroom 12	Floor	Wood	Tan	None	N/A	N/A	N/A
1	2	S22	Stairwell next to Classroom 18	W1	Wood	Tan	None	N/A	N/A	N/A
1	2	S22	Stairwell next to Classroom 18	W2	Plaster	Tan	Chipping	7	35	Positive
1	2	S22	Stairwell next to Classroom 18	W3	Plaster	Tan	Chipping	72	35	Positive

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	S22	Stairwell next to Classroom 18	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S22	Stairwell next to Classroom 18	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S22	Stairwell next to Classroom 18	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S22	Stairwell next to Classroom 18	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S22	Stairwell next to Classroom 18	Ceiling	Plaster	Tan	N/A	N/A	N/A	N/A
1	2	S22	Stairwell next to Classroom 18	Floor	Wood	Tan	N/A	N/A	N/A	N/A
1	2	FT1	Fire Tower # 1	W1	Brick	Tan	Flaking	189	44	Positive
1	2	FT1	Fire Tower # 1	W2	Brick	Tan	Cracking	154	42	Positive
1	2	FT1	Fire Tower # 1	W3	Brick	Tan	Flaking	155	38	Positive
1	2	FT1	Fire Tower # 1	W4	Brick	Tan	Cracking	45	39	Positive
1	2	FT1	Fire Tower # 1	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	FT1	Fire Tower # 1	Ceiling	Plaster	Tan	Alligatoring	74	37	Positive
1	2	FT1	Fire Tower # 1	Floor	Concrete	Tan	None	N/A	N/A	N/A
1	2	FT2	Fire Tower # 2	W1	Brick	Tan	Cracking	84	30	Positive
1	2	FT2	Fire Tower # 2	W2	Brick	Tan	Cracking	72	38	Positive
1	2	FT2	Fire Tower # 2	W3	Brick	Tan	Chipping	198	35	Positive
1	2	FT2	Fire Tower # 2	W4	Brick	Tan	Flaking	92	35	Positive
1	2	FT2	Fire Tower # 2	Ceiling	Plaster	Tan	Flaking	193	38	Positive
1	2	FT2	Fire Tower # 2	Floor	Concrete	Tan	N/A	N/A	N/A	N/A
1	2	FT3	Fire Tower # 3	W1	Brick	Tan	Cracking	7	16.4	Positive
1	2	FT3	Fire Tower # 3	W2	Brick	Tan	Chipping	1	13.7	Positive
1	2	FT3	Fire Tower # 3	W3	Brick	Tan	Flaking	25	18	Positive
1	2	FT3	Fire Tower # 3	W4	Brick	Tan	Chipping	12	12.8	Positive
1	2	FT3	Fire Tower # 3	Ceiling	Plaster	Tan	None	N/A	N/A	N/A
1	2	FT3	Fire Tower # 3	Floor	Concrete	Tan	None	N/A	N/A	N/A
1	2	FT4	Fire Tower # 4	W1	Brick	Tan	Cracking	4	13.3	Positive
1	2	FT4	Fire Tower # 4	W2	Brick	Tan	Chipping	5	14.3	Positive
1	2	FT4	Fire Tower # 4	W3	Brick	Tan	Chipping	68	15.9	Positive
1	2	FT4	Fire Tower # 4	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	FT4	Fire Tower # 4	W4	Brick	Tan	Cracking	4	15.5	Positive
1	2	FT4	Fire Tower # 4	Ceiling	Plaster	Tan	Flaking	5	29.3	Positive
1	2	FT4	Fire Tower # 4	Floor	Concrete	Tan	None	N/A	N/A	N/A
1	2	H23	Hallway outside Classrooms 12 - 17	W1	Plaster	Blue	None	N/A	N/A	N/A
1	2	H23	Hallway outside Classrooms 12 - 17	W2	Plaster	Blue	Chipping	19	33	Positive
1	2	H23	Hallway outside Classrooms 12 - 17	W2	Brick	Green	Chipping	9	20	Positive
1	2	H23	Hallway outside Classrooms 12 - 17	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Hallway outside Classrooms 12 - 17	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Hallway outside Classrooms 12 - 17	W2	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	H23	Hallway outside Classrooms 12 - 17	W3	Wood	Tan	None	N/A	N/A	N/A
1	2	H23	Hallway outside Classrooms 12 - 17	W4	Plaster	Blue	Chipping	4	33	Positive
1	2	H23	Hallway outside Classrooms 12 - 17	W4	Brick	Green	Chipping	3	22	Positive
1	2	H23	Hallway outside Classrooms 12 - 17	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Hallway outside Classrooms 12 - 17	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Hallway outside Classrooms 12 - 17	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Hallway outside Classrooms 12 - 17	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	H24	Hallway outside Classrooms 18 - 22	W1	Plaster	Blue	Chipping	1	29	Positive
1	2	H24	Hallway outside Classrooms 18 - 22	W2	Plaster	Blue	Flaking	25	28.6	Positive
1	2	H24	Hallway outside Classrooms 18 - 22	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H24	Hallway outside Classrooms 18 - 22	W3	Plaster	Blue	Flaking	13	29.2	Positive
1	2	H24	Hallway outside Classrooms 18 - 22	W4	Plaster	Blue	Chipping	9	23.6	Positive
1	2	H24	Hallway outside Classrooms 18 - 22	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H24	Hallway outside Classrooms 18 - 22	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W1	Plaster	Tan	Cracking	19	34	Positive
1	2	12	Classroom 12	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W2	Plaster	Tan	Cracking	96	16.6	Positive
1	2	12	Classroom 12	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W3	Plaster	Tan	Cracking	68	24.1	Positive
1	2	12	Classroom 12	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W4	Plaster	Tan	Chipping	43	12.3	Positive
1	2	12	Classroom 12	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12	Classroom 12	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	12A	Classroom 12 Storage Closet	W1	Brick	Tan	Cracking	64	27.6	Positive
1	2	12A	Classroom 12 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12A	Classroom 12 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	12A	Classroom 12 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12A	Classroom 12 Storage Closet	W2	Wood	Tan	Chipping	1	0.4	Negative
1	2	12A	Classroom 12 Storage Closet	W3	Brick	Tan	Cracking	103	23.6	Positive
1	2	12A	Classroom 12 Storage Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12A	Classroom 12 Storage Closet	W4	Brick	Tan	Flaking	24	25.5	Positive
1	2	12A	Classroom 12 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12A	Classroom 12 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	12A	Classroom 12 Storage Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	13	Classroom 13	W1	Plaster	Tan	Flaking	7	36	Positive
1	2	13	Classroom 13	W2	Plaster	Tan	Cracking	27	34	Positive
1	2	13	Classroom 13	W2	Plaster	Green	Chipping	14	0.1	Negative
1	2	13	Classroom 13	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	13	Classroom 13	W3	Brick	Tan	Flaking	15	21.1	Positive
1	2	13	Classroom 13	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	13	Classroom 13	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	13	Classroom 13	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	13	Classroom 13	W4	Plaster	Tan	Cracking	10	37	Positive
1	2	13	Classroom 13	W4	Brick	Tan	Cracking	60	26.2	Positive
1	2	13	Classroom 13	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	13	Classroom 13	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	13	Classroom 13	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	13	Classroom 13	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	13	Classroom 13	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	13A	Classroom 13 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	13A	Classroom 13 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	13A	Classroom 13 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	13A	Classroom 13 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	13A	Classroom 13 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	13A	Classroom 13 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	14	Library	W1	Plaster	Tan	Chipping	2	0.1	Negative
1	2	14	Library	W2	Plaster	Tan	Chipping	21	-0.1	Negative
1	2	14	Library	W3	Plaster	Tan	Chipping	2	36	Positive
1	2	14	Library	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	14	Library	W4	Plaster	Tan	Flaking	21	34	Positive
1	2	14	Library	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	14	Library	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	14A	Library Office	W1	Plaster			N/A	N/A	N/A
1	2	14A	Library Office	W2	Plaster			N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	14A	Library Office	W3	Plaster			N/A	N/A	N/A
1	2	14A	Library Office	W4	Plaster			N/A	N/A	N/A
1	2	14A	Library Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	14A	Library Office	Floor	Wood			N/A	N/A	N/A
1	2	14B	Library Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	14B	Library Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	14B	Library Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	14B	Library Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	14B	Library Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	14B	Library Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	15	Nurse's Office	W1	Plaster	Tan	Cracking	4	39	Positive
1	2	15	Nurse's Office	W2	Plaster	Tan	Chipping	5	39	Positive
1	2	15	Nurse's Office	W3	Plaster	Tan	None	N/A	N/A	N/A
1	2	15	Nurse's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	15	Nurse's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	15	Nurse's Office	W4	Plaster	Tan	Cracking	1	11.2	Positive
1	2	15	Nurse's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	15	Nurse's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	15	Nurse's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	15	Nurse's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	15A	Custodial Closet next to Nurse's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	15A	Custodial Closet next to Nurse's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	15A	Custodial Closet next to Nurse's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	15A	Custodial Closet next to Nurse's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	15A	Custodial Closet next to Nurse's Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	15A	Custodial Closet next to Nurse's Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	15B	Book Closet next to Staff Restroom across from Classroom 16	W1	Brick	Tan	Chipping	5	0.2	Negative
1	2	15B	Book Closet next to Staff Restroom across from Classroom 16	W2	Brick	Tan	Chipping	2	0.2	Negative
1	2	15B	Book Closet next to Staff Restroom across from Classroom 16	W3	Brick	Tan	Chipping	3	0.1	Negative
1	2	15B	Book Closet next to Staff Restroom across from Classroom 16	W4	Brick	Tan	Chipping	1	0.1	Negative
1	2	15B	Book Closet next to Staff Restroom across from Classroom 16	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	15B	Book Closet next to Staff Restroom across from Classroom 16	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	15B	Book Closet next to Staff Restroom across from Classroom 16	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	16	Classroom 16	W1	Plaster	Blue	None	N/A	N/A	N/A
1	2	16	Classroom 16	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	16	Classroom 16	W2	Wood	Tan	Chipping	34	0.6	Negative
1	2	16	Classroom 16	W3	Plaster	Blue	Flaking	5	35	Positive
1	2	16	Classroom 16	W3	Brick	Tan	Flaking	26	21.5	Positive
1	2	16	Classroom 16	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	16	Classroom 16	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	16	Classroom 16	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	16	Classroom 16	W4	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	16	Classroom 16	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	16	Classroom 16	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	16A	Classroom 16 Storage Closet	W1	Brick	Green	Cracking	4	27.2	Positive
1	2	16A	Classroom 16 Storage Closet	W2	Plaster	Green	None	N/A	N/A	N/A
1	2	16A	Classroom 16 Storage Closet	W3	Brick	Green	Cracking	17	22.4	Positive
1	2	16A	Classroom 16 Storage Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	16A	Classroom 16 Storage Closet	W4	Wood	Tan	Chipping	1	0.3	Negative
1	2	16A	Classroom 16 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	16A	Classroom 16 Storage Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	17	Classroom 17	W1	Plaster	Tan	N/A	N/A	N/A	N/A
1	2	17	Classroom 17	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	17	Classroom 17	W2	Brick	Tan	Flaking	30	33	Positive
1	2	17	Classroom 17	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	17	Classroom 17	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	17	Classroom 17	W3	Brick	Tan	Flaking	72	37.8	Positive
1	2	17	Classroom 17	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	17	Classroom 17	W4	Wood	Tan	Cracking	3	0.5	Negative
1	2	17	Classroom 17	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	17	Classroom 17	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	17A	Classroom 17 Storage Closet	W1	Brick	Tan	Chipping	3	25.9	Positive
1	2	17A	Classroom 17 Storage Closet	W2	Wood	Tan	None	N/A	N/A	N/A
1	2	17A	Classroom 17 Storage Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	17A	Classroom 17 Storage Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	17A	Classroom 17 Storage Closet	W3	Brick	Tan	Chipping	2	25.1	Positive
1	2	17A	Classroom 17 Storage Closet	W4	Brick	Tan	None	N/A	N/A	N/A
1	2	17A	Classroom 17 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	17A	Classroom 17 Storage Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	15A	Staff Restroom across from Classroom 16	W1	Plaster	Tan	Cracking	1	37	Positive
1	2	15A	Staff Restroom across from Classroom 16	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	15A	Staff Restroom across from Classroom 16	W2	Plaster	Tan	Spalling	3	36	Positive
1	2	15A	Staff Restroom across from Classroom 16	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	15A	Staff Restroom across from Classroom 16	W3	Plaster	Tan	Flaking	9	18.4	Positive
1	2	15A	Staff Restroom across from Classroom 16	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	15A	Staff Restroom across from Classroom 16	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	15A	Staff Restroom across from Classroom 16	W4	Plaster	Tan	Chipping	1	18.8	Positive
1	2	15A	Staff Restroom across from Classroom 16	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	15A	Staff Restroom across from Classroom 16	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	18	Classroom 18	W1	Plaster	Tan	Chipping	9	28.2	Positive
1	2	18	Classroom 18	W2	Plaster	Tan	Chipping	6	0.2	Negative
1	2	18	Classroom 18	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	18	Classroom 18	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	18	Classroom 18	W3	Plaster	Tan	Flaking	17	20.5	Positive
1	2	18	Classroom 18	W4	Plaster	Tan	Flaking	107	28.3	Positive
1	2	18	Classroom 18	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	18	Classroom 18	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	18	Classroom 18	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	18	Classroom 18	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	18A	Classroom 18 Storage Closet	W1	Brick	Tan	Flaking	25	24.9	Positive
1	2	18A	Classroom 18 Storage Closet	W2	Brick	Tan	Flaking	48	19.7	Positive
1	2	18A	Classroom 18 Storage Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	18A	Classroom 18 Storage Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	18A	Classroom 18 Storage Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	18A	Classroom 18 Storage Closet	W3	Brick	Tan	Cracking	3	21.2	Positive
1	2	18A	Classroom 18 Storage Closet	W4	Wood	Tan	Cracking	N/A	N/A	N/A
1	2	18A	Classroom 18 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	18A	Classroom 18 Storage Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	19	Classroom 19	W1	Plaster	Tan	Spalling	8	31	Positive
1	2	19	Classroom 19	W2	Plaster	Blue	Cracking	6	19.9	Positive
1	2	19	Classroom 19	W3	Plaster	Tan	Flaking	45	31	Positive
1	2	19	Classroom 19	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	19	Classroom 19	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	19	Classroom 19	W4	Plaster	Tan	Cracking	12	0.1	Negative
1	2	19	Classroom 19	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	19	Classroom 19	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	19	Classroom 19	Floor	Wood	Brown	N/A	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	19A	Classroom 19 Storage Closet	W1	Plaster	Tan	Cracking	24	24.5	Positive
1	2	19A	Classroom 19 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	19A	Classroom 19 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	19A	Classroom 19 Storage Closet	W2	Plaster	Tan	Cracking	6	22.7	Positive
1	2	19A	Classroom 19 Storage Closet	W3	Plaster	Tan	Cracking	7	23.2	Positive
1	2	19A	Classroom 19 Storage Closet	W4	Plaster	Tan	Cracking	1	1.8	Positive
1	2	19A	Classroom 19 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	19A	Classroom 19 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	19A	Classroom 19 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	19A	Classroom 19 Storage Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	20	Classroom 20	W1	Plaster	Tan	Chipping	16	29.6	Positive
1	2	20	Classroom 20	W2	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	20	Classroom 20	W3	Plaster	Tan	Flaking	86	22.4	Positive
1	2	20	Classroom 20	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	20	Classroom 20	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	20	Classroom 20	W4	Plaster	Tan	Alligatoring	21	26.6	Positive
1	2	20	Classroom 20	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	20	Classroom 20	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	20A	Classroom 20 Storage Closet	W1	Plaster	Tan	Chipping	45	25.5	Positive
1	2	20A	Classroom 20 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	20A	Classroom 20 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	20A	Classroom 20 Storage Closet	W2	Plaster	Tan	Cracking	12	27.6	Positive
1	2	20A	Classroom 20 Storage Closet	W3	Plaster	Tan	Cracking	54	27.2	Positive
1	2	20A	Classroom 20 Storage Closet	W4	Plaster	Tan	Cracking	28	24.7	Positive
1	2	20A	Classroom 20 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	20A	Classroom 20 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	20A	Classroom 20 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	20A	Classroom 20 Storage Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	22	Classroom 22	W1	Plaster	Tan	Cracking	1	23	Positive
1	2	22	Classroom 22	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	22	Classroom 22	W2	Plaster	Tan	Flaking	49	27.2	Positive
1	2	22	Classroom 22	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	22	Classroom 22	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	22	Classroom 22	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	22	Classroom 22	W3	Plaster	Tan	Cracking	98	34	Positive
1	2	22	Classroom 22	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	22	Classroom 22	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	22	Classroom 22	W4	Plaster	Tan	Flaking	43	24.8	Positive

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	22	Classroom 22	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	22	Classroom 22	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	22	Classroom 22	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	22A	Classroom 22 Storage Closet	W1	Plaster	Tan	Cracking	33	25.2	Positive
1	2	22A	Classroom 22 Storage Closet	W2	Plaster	Tan	Moisture Damage	33	27.6	Positive
1	2	22A	Classroom 22 Storage Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	22A	Classroom 22 Storage Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	22A	Classroom 22 Storage Closet	W3	Plaster	Tan	Chipping	8	28.8	Positive
1	2	22A	Classroom 22 Storage Closet	W4	Wood	Tan	Cracking	16	0.2	Negative
1	2	22A	Classroom 22 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	22A	Classroom 22 Storage Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	21	Classroom 21	W1	Plaster	Tan	Chipping	4	26.6	Positive
1	2	21	Classroom 21	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	21	Classroom 21	W2	Plaster	Tan	Chipping	2	30	Positive
1	2	21	Classroom 21	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	21	Classroom 21	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	21	Classroom 21	W3	Plaster	Tan	Flaking	20	24.4	Positive
1	2	21	Classroom 21	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	21	Classroom 21	W4	Plaster	Tan	Flaking	75	28.5	Positive
1	2	21	Classroom 21	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	21	Classroom 21	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	22	Classroom 22	Floor	Wood	Tan	Cracking	70	27.4	Positive
1	2	21A	Classroom 21 Storage Closet	W1	Plaster	Tan	None	N/A	N/A	N/A
1	2	21A	Classroom 21 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	21A	Classroom 21 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	21A	Classroom 21 Storage Closet	W2	Wood	Tan	Chipping	6	0.4	Negative
1	2	21A	Classroom 21 Storage Closet	W3	Plaster	Tan	Chipping	72	33	Positive
1	2	21A	Classroom 21 Storage Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	21A	Classroom 21 Storage Closet	W4	Plaster	Tan	Flaking	15	25.6	Positive
1	2	21A	Classroom 21 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	21A	Classroom 21 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	21A	Classroom 21 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	21A	Classroom 21 Storage Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	S31	Stairwell next to Classroom 23	W1	Wood	Brown	Chipping	2	0.2	Negative
1	3	S31	Stairwell next to Classroom 23	W2	Brick	Tan	None	N/A	N/A	N/A
1	3	S31	Stairwell next to Classroom 23	W3	Brick	Tan	Chipping	1	23.1	Positive
1	3	S31	Stairwell next to Classroom 23	W3	Brick	Tan	Chipping	1	35	Positive
1	3	S31	Stairwell next to Classroom 23	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	S31	Stairwell next to Classroom 23	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell next to Classroom 29	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell next to Classroom 29	W1	Wood	Brown	None	N/A	N/A	N/A
1	3	S32	Stairwell next to Classroom 29	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell next to Classroom 29	W2	Plaster	Tan	Chipping	1	32	Positive
1	3	S32	Stairwell next to Classroom 29	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell next to Classroom 29	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell next to Classroom 29	W3	Plaster	Tan	Cracking	48	36	Positive
1	3	S32	Stairwell next to Classroom 29	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell next to Classroom 29	W4	Brick	Tan	None	N/A	N/A	N/A
1	3	S32	Stairwell next to Classroom 29	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell next to Classroom 29	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell next to Classroom 29	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairwell next to Classroom 29	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	FT1	Fire Tower # 1	W1	Brick	Tan	Chipping	300	44	Positive
1	3	FT1	Fire Tower # 1	W2	Brick	Tan	Chipping	230	33	Positive
1	3	FT1	Fire Tower # 1	W3	Brick	Tan	Chipping	280	9.7	Positive
1	3	FT1	Fire Tower # 1	W4	Brick	Tan	Chipping	170	39	Positive
1	3	FT1	Fire Tower # 1	Ceiling	Concrete	White	N/A	N/A	N/A	N/A
1	3	FT1	Fire Tower # 1	Floor	Concrete	Brown	N/A	N/A	N/A	N/A
1	3	FT2	Fire Tower # 2	W1	Brick	Tan	Chipping	250	42	Positive
1	3	FT2	Fire Tower # 2	W2	Brick	Tan	Chipping	170	19.6	Positive
1	3	FT2	Fire Tower # 2	W3	Brick	Tan	Chipping	220	3.5	Positive
1	3	FT2	Fire Tower # 2	W4	Brick	Tan	Chipping	130	1.9	Positive
1	3	FT2	Fire Tower # 2	Ceiling	Concrete	White	N/A	N/A	N/A	N/A
1	3	FT2	Fire Tower # 2	Floor	Concrete	Brown	N/A	N/A	N/A	N/A
1	3	FT3	Fire Tower # 3	W1	Brick	Tan	Cracking	1	13.8	Positive
1	3	FT3	Fire Tower # 3	W2	Brick	Tan	Cracking	2	10.3	Positive
1	3	FT3	Fire Tower # 3	W3	Brick	Tan	Flaking	19	16.7	Positive
1	3	FT3	Fire Tower # 3	W4	Brick	Tan	Chipping	5	17.3	Positive
1	3	FT3	Fire Tower # 3	Ceiling	Concrete	White	N/A	N/A	N/A	N/A
1	3	FT3	Fire Tower # 3	Floor	Concrete	Brown	N/A	N/A	N/A	N/A
1	3	FT4	Fire Tower # 4	W1	Brick	Tan	Flaking	9	13.1	Positive
1	3	FT4	Fire Tower # 4	W2	Brick	Tan	Chipping	4	17.7	Positive
1	3	FT4	Fire Tower # 4	W3	Brick	Tan	Chipping	8	16	Positive
1	3	FT4	Fire Tower # 4	W4	Brick	Tan	Chipping	8	13.7	Positive
1	3	FT4	Fire Tower # 4	Ceiling	Concrete	White	N/A	N/A	N/A	N/A
1	3	FT4	Fire Tower # 4	Floor	Concrete	Brown	N/A	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	H38	Hallway outside Classrooms 23 - 28	W1	Plaster	Tan	None	N/A	N/A	N/A
1	3	H38	Hallway outside Classrooms 23 - 28	W2	Plaster	Tan	Chipping	7	37	Positive
1	3	H38	Hallway outside Classrooms 23 - 28	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H38	Hallway outside Classrooms 23 - 28	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H38	Hallway outside Classrooms 23 - 28	W3	Plaster	Tan	None	N/A	N/A	N/A
1	3	H38	Hallway outside Classrooms 23 - 28	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H38	Hallway outside Classrooms 23 - 28	W4	Plaster	Tan	Chipping	3	36	Positive
1	3	H38	Hallway outside Classrooms 23 - 28	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H38	Hallway outside Classrooms 23 - 28	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	H37	Hallway outside Classrooms 29 - 33	W1	Plaster	Tan	Chipping	1	35	Positive
1	3	H37	Hallway outside Classrooms 29 - 33	W2	Plaster	Tan	Chipping	36	14.4	Positive
1	3	H37	Hallway outside Classrooms 29 - 33	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H37	Hallway outside Classrooms 29 - 33	W3	Plaster	Tan	Chipping	5	12.2	Positive
1	3	H37	Hallway outside Classrooms 29 - 33	W4	Plaster	Tan	Chipping	20	13.3	Positive
1	3	H37	Hallway outside Classrooms 29 - 33	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H37	Hallway outside Classrooms 29 - 33	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	23	Classroom 23	W1	Plaster	Tan	Cracking	19	34	Positive
1	3	23	Classroom 23	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	23	Classroom 23	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	23	Classroom 23	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	23	Classroom 23	W2	Plaster	Tan	Flaking	148	8.6	Positive
1	3	23	Classroom 23	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	23	Classroom 23	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	23	Classroom 23	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	23	Classroom 23	W3	Plaster	Tan	Flaking	108	26.3	Positive
1	3	23	Classroom 23	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	23	Classroom 23	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	23	Classroom 23	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	23	Classroom 23	W4	Plaster	Tan	Chipping	83	28.5	Positive
1	3	23	Classroom 23	W4	Plaster	Pink	Cracking	21	19.3	Positive
1	3	23	Classroom 23	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	23	Classroom 23	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	23	Classroom 23	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	23A	Classroom 23 Storage Closet	W1	Brick	Black	Flaking	108	29.2	Positive
1	3	23A	Classroom 23 Storage Closet	W2	Wood	Tan	N/A	N/A	N/A	N/A
1	3	23A	Classroom 23 Storage Closet	W3	Brick	Tan	Flaking	240	35	Positive
1	3	23A	Classroom 23 Storage Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	23A	Classroom 23 Storage Closet	W4	Brick	Tan	Flaking	90	2.6	Positive

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	23A	Classroom 23 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	23A	Classroom 23 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	23A	Classroom 23 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	23A	Classroom 23 Storage Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	24	Classroom 24	W1	Plaster	Blue	None	0	N/A	N/A
1	3	24	Classroom 24	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	24	Classroom 24	W2	Wood	Purple	Flaking	33	0.2	Negative
1	3	24	Classroom 24	W3	Plaster	Blue	None	N/A	N/A	N/A
1	3	24	Classroom 24	W3	Brick	Tan	Flaking	54	23.2	Positive
1	3	24	Classroom 24	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	24	Classroom 24	W4	Plaster	Blue	None	N/A	N/A	N/A
1	3	24	Classroom 24	W4	Brick	Tan	Flaking	60	24.1	Positive
1	3	24	Classroom 24	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	24	Classroom 24	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	24	Classroom 24	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	24	Classroom 24	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	24	Classroom 24	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	24	Classroom 24	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	24A	Classroom 24 Storage Closet	W1	Brick	Green	Cracking	53	25.3	Positive
1	3	24A	Classroom 24 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	24A	Classroom 24 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	24A	Classroom 24 Storage Closet	W2	Brick	Green	Cracking	72	21.1	Positive
1	3	24A	Classroom 24 Storage Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	24A	Classroom 24 Storage Closet	W3	Brick	Green	Cracking	240	28.6	Positive
1	3	24A	Classroom 24 Storage Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	24A	Classroom 24 Storage Closet	W4	Brick	Green	Flaking	18	29.6	Positive
1	3	24A	Classroom 24 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	24A	Classroom 24 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	24A	Classroom 24 Storage Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	25	Classroom 25	W1	Plaster	White	Cracking	10	36	Positive
1	3	25	Classroom 25	W1	Brick	White	Flaking	5	20.8	Positive
1	3	25	Classroom 25	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	25	Classroom 25	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	25	Classroom 25	W2	Wood	White	Chipping	44	0.2	Negative
1	3	25	Classroom 25	W3	Plaster	White	Flaking	75	35	Positive
1	3	25	Classroom 25	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	25	Classroom 25	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	25	Classroom 25	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	25	Classroom 25	W3	Brick	White	Flaking	47	25.1	Positive

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	25	Classroom 25	W4	Wood	White	Cracking	92	0.2	Negative
1	3	25	Classroom 25	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	25	Classroom 25	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	25A	Classroom 25 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	25A	Classroom 25 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	25A	Classroom 25 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	25A	Classroom 25 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	25A	Classroom 25 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	25A	Classroom 25 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	26	Classroom 26	W1	Plaster	Tan	Chipping	5	34	Positive
1	3	26	Classroom 26	W2	Wood	Tan	Chipping	69	0.2	Negative
1	3	26	Classroom 26	W3	Plaster	Tan	Flaking	50	39	Positive
1	3	26	Classroom 26	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	26	Classroom 26	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	26	Classroom 26	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	26	Classroom 26	W3	Brick	Tan	Flaking	14	22.7	Positive
1	3	26	Classroom 26	W4	Wood	Brown	Chipping	54	1	Positive
1	3	26	Classroom 26	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	26	Classroom 26	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	26A	Classroom 26 Storage Closet	W1	Brick	Tan	Flaking	22	27.4	Positive
1	3	26A	Classroom 26 Storage Closet	W2	Wood	Tan	Cracking	43	0.2	Negative
1	3	26A	Classroom 26 Storage Closet	W3	Brick	Tan	Flaking	96	32	Positive
1	3	26A	Classroom 26 Storage Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	26A	Classroom 26 Storage Closet	W4	Brick	Tan	Cracking	5	24.8	Positive
1	3	26A	Classroom 26 Storage Closet	Ceiling	Plaster	Tan	Flaking	14	11.2	Positive
1	3	26A	Classroom 26 Storage Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	27	Classroom 27	W1	Plaster	Tan	None	N/A	N/A	N/A
1	3	27	Classroom 27	W2	Wood	Tan	Cracking	46	0.2	Negative
1	3	27	Classroom 27	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	27	Classroom 27	W3	Plaster	Tan	Cracking	38	30	Positive
1	3	27	Classroom 27	W3	Brick	Tan	Flaking	78	22.2	Positive
1	3	27	Classroom 27	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	27	Classroom 27	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	27	Classroom 27	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	27	Classroom 27	W4	Wood	Tan	Chipping	59	1.4	Positive
1	3	27	Classroom 27	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	27	Classroom 27	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	27A	Classroom 27 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	27A	Classroom 27 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	27A	Classroom 27 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	27A	Classroom 27 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	27A	Classroom 27 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	27A	Classroom 27 Storage Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	28	Classroom 28	W1	Plaster	Tan	N/A	N/A	N/A	N/A
1	3	28	Classroom 28	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	28	Classroom 28	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	28	Classroom 28	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	28	Classroom 28	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	28	Classroom 28	W1	Brick	Grey	None	N/A	N/A	N/A
1	3	28	Classroom 28	W2	Plaster	Tan	Flaking	14	33	Positive
1	3	28	Classroom 28	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	28	Classroom 28	W2	Brick	Grey	None	N/A	N/A	N/A
1	3	28	Classroom 28	W3	Plaster	Tan	Cracking	38	35	Positive
1	3	28	Classroom 28	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	28	Classroom 28	W3	Brick	Grey	None	N/A	N/A	N/A
1	3	28	Classroom 28	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	28	Classroom 28	W4	Wood	White	Cracking	52	0.2	Negative
1	3	28	Classroom 28	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	28	Classroom 28	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	28A	Classroom 28 Storage Closet	W1	Brick	Tan	Cracking	110	31	Positive
1	3	28A	Classroom 28 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	28A	Classroom 28 Storage Closet	W2	Brick	Tan	Cracking	72	23.4	Positive
1	3	28A	Classroom 28 Storage Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	28A	Classroom 28 Storage Closet	W3	Brick	Tan	Cracking	170	32	Positive
1	3	28A	Classroom 28 Storage Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	28A	Classroom 28 Storage Closet	W4	Brick	Tan	Cracking	68	20	Positive
1	3	28A	Classroom 28 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	28A	Classroom 28 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	28A	Classroom 28 Storage Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	27B	Faculty Lounge next to Classroom 23	W1	Plaster	White	Partially Inaccessible	N/A	N/A	N/A
1	3	27B	Faculty Lounge next to Classroom 23	W2	Plaster	White	Cracking	10	37	Positive
1	3	27B	Faculty Lounge next to Classroom 23	W3	Plaster	Pink	Flaking	16	13.6	Positive
1	3	27B	Faculty Lounge next to Classroom 23	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	27B	Faculty Lounge next to Classroom 23	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	27B	Faculty Lounge next to Classroom 23	W4	Plaster	White	Cracking	14	2.7	Positive

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	27B	Faculty Lounge next to Classroom 23	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	27B	Faculty Lounge next to Classroom 23	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	27C	Custodial Closet next to Faculty Lounge	W1	Brick	White	Cracking	1	0.1	Negative
1	3	27C	Custodial Closet next to Faculty Lounge	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	27C	Custodial Closet next to Faculty Lounge	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	27C	Custodial Closet next to Faculty Lounge	W2	Brick	White	Cracking	14	0.1	Negative
1	3	27C	Custodial Closet next to Faculty Lounge	W3	Brick	White	Cracking	15	0.1	Negative
1	3	27C	Custodial Closet next to Faculty Lounge	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	27C	Custodial Closet next to Faculty Lounge	W4	Brick	White	Efflorescence	23	0.1	Negative
1	3	27C	Custodial Closet next to Faculty Lounge	Ceiling	Plaster	White	N/A	N/A	N/A	N/A
1	3	27C	Custodial Closet next to Faculty Lounge	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	27B	Book Closet next to Staff Restroom across from Classroom 27	W1	Brick	White	Spalling	6	0	Negative
1	3	27B	Book Closet next to Staff Restroom across from Classroom 27	W2	Brick	White	Spalling	17	0.1	Negative
1	3	27B	Book Closet next to Staff Restroom across from Classroom 27	W3	Brick	White	Flaking	38	0.1	Negative
1	3	27B	Book Closet next to Staff Restroom across from Classroom 27	W4	Brick	White	Flaking	14	0.2	Negative
1	3	27B	Book Closet next to Staff Restroom across from Classroom 27	Ceiling	Plaster	White	N/A	N/A	N/A	N/A
1	3	27B	Book Closet next to Staff Restroom across from Classroom 27	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	27A	Staff Restroom across from Classroom 27	W1	Plaster	Tan	Chipping	1	30	Positive
1	3	27A	Staff Restroom across from Classroom 27	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	27A	Staff Restroom across from Classroom 27	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	27A	Staff Restroom across from Classroom 27	W2	Plaster	Tan	Chipping	1	28.6	Positive
1	3	27A	Staff Restroom across from Classroom 27	W3	Plaster	Tan	Chipping	1	36	Positive
1	3	27A	Staff Restroom across from Classroom 27	W4	Plaster	Tan	Chipping	1	0.3	Negative
1	3	27A	Staff Restroom across from Classroom 27	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	27A	Staff Restroom across from Classroom 27	Floor	Concrete	Tan	N/A	N/A	N/A	N/A
1	3	29	Art Classroom 29	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	29	Art Classroom 29	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	29	Art Classroom 29	W1	Plaster	Tan	Chipping	6	5.7	Positive
1	3	29	Art Classroom 29	W2	Plaster	Tan	Cracking	3	3.4	Positive
1	3	29	Art Classroom 29	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	29	Art Classroom 29	W3	Plaster	Tan	Cracking	3	0.1	Negative
1	3	29	Art Classroom 29	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	29	Art Classroom 29	W3	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	29	Art Classroom 29	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	29	Art Classroom 29	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	29	Art Classroom 29	W4	Plaster	Tan	Cracking	6	35	Positive
1	3	29	Art Classroom 29	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	29	Art Classroom 29	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	29	Art Classroom 29	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	29	Art Classroom 29	Floor	Concrete	Brown	N/A	N/A	N/A	N/A
1	3	30	Classroom 30	W1	Plaster	Tan	Cracking	16	27.8	Positive
1	3	30	Classroom 30	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	30	Classroom 30	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	30	Classroom 30	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	30	Classroom 30	W2	Plaster	Tan	N/A	N/A	N/A	N/A
1	3	30	Classroom 30	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	30	Classroom 30	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	30	Classroom 30	W3	Plaster	Tan	Efflorescence	12	16.7	Positive
1	3	30	Classroom 30	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	30	Classroom 30	W4	Plaster	Tan	Cracking	4	29.6	Positive
1	3	30	Classroom 30	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	30	Classroom 30	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	30A	Classroom 30 Storage Closet	W1	Plaster	Tan	Cracking	120	20.9	Positive
1	3	30A	Classroom 30 Storage Closet	W2	Plaster	Tan	Cracking	18	21.7	Positive
1	3	30A	Classroom 30 Storage Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	30A	Classroom 30 Storage Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	30A	Classroom 30 Storage Closet	W3	Plaster	Tan	Cracking	24	25.6	Positive
1	3	30A	Classroom 30 Storage Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	30A	Classroom 30 Storage Closet	W4	Plaster	Tan	Cracking	12	23.5	Positive
1	3	30A	Classroom 30 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	30A	Classroom 30 Storage Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W1	Plaster	Tan	Cracking	33	30	Positive
1	3	31	Classroom 31	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W2	Plaster	Tan	Cracking	4	28.3	Positive
1	3	31	Classroom 31	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W2	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	31	Classroom 31	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W3	Plaster	Tan	Flaking	47	2.8	Positive
1	3	31	Classroom 31	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W4	Plaster	Tan	Cracking	12	31	Positive
1	3	31	Classroom 31	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31	Classroom 31	Ceiling	N/A	N/A	N/A	n/a	N/A	N/A
1	3	31	Classroom 31	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	31A	Classroom 31 Storage Closet	W1	Plaster	Tan	Cracking	24	25	Positive
1	3	31A	Classroom 31 Storage Closet	W2	Plaster	Tan	Cracking	19	25.7	Positive
1	3	31A	Classroom 31 Storage Closet	W3	Plaster	Tan	Flaking	31	26.1	Positive
1	3	31A	Classroom 31 Storage Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31A	Classroom 31 Storage Closet	W4	Plaster	Tan	Chipping	15	1.5	Positive
1	3	31A	Classroom 31 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31A	Classroom 31 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31A	Classroom 31 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	31A	Classroom 31 Storage Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W1	Plaster	Tan	Chipping	23	26.8	Positive
1	3	32	Classroom 32	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W2	Plaster	Tan	Chipping	20	26.7	Positive
1	3	32	Classroom 32	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W3	Plaster	Tan	Cracking	42	1.8	Positive
1	3	32	Classroom 32	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W3	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	32	Classroom 32	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W4	Plaster	Tan	Cracking	24	30	Positive
1	3	32	Classroom 32	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32	Classroom 32	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	32A	Classroom 32 Storage Closet	W1	Plaster	Tan	Chipping	1	20.9	Positive
1	3	32A	Classroom 32 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32A	Classroom 32 Storage Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32A	Classroom 32 Storage Closet	W2	Plaster	Tan	Cracking	25	24.8	Positive
1	3	32A	Classroom 32 Storage Closet	W2	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	32A	Classroom 32 Storage Closet	W3	Plaster	Tan	Cracking	27	21.9	Positive
1	3	32A	Classroom 32 Storage Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32A	Classroom 32 Storage Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32A	Classroom 32 Storage Closet	W4	Plaster	Tan	Spalling	4	30	Positive
1	3	32A	Classroom 32 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32A	Classroom 32 Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32A	Classroom 32 Storage Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	32A	Classroom 32 Storage Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W1	Plaster	Tan	Chipping	1	29.8	Positive
1	3	33	Classroom 33	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W2	Plaster	Tan	Chipping	1	29.8	Positive
1	3	33	Classroom 33	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W3	Plaster	Tan	Flaking	11	14.5	Positive
1	3	33	Classroom 33	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W4	Plaster	Tan	Flaking	12	29.8	Positive
1	3	33	Classroom 33	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W4	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	33	Classroom 33	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W3	Plaster	Tan	Flaking	11	14.5	Positive
1	3	33	Classroom 33	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W4	Plaster	Tan	Flaking	12	29.8	Positive
1	3	33	Classroom 33	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33	Classroom 33	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33A	Classroom 33 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	33A	Classroom 33 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	33A	Classroom 33 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	33A	Classroom 33 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	33A	Classroom 33 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	33A	Classroom 33 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	010A	Storage Room across from Girl's Restroom	W3	Brick	Green	Chipping	30	0.3	Negative
1	1	1A	Gym Storage Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	2A	Classroom 2 Storage Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	2A	Classroom 2 Storage Closet	W3	Brick	Tan	Partially Inaccessible	Partially Inaccessable	24.8	Positive
1	1	3A	Classroom 3 Storage Closet	W1	Brick	No Access	No Access	0	24.4	Positive
1	1	3A	Classroom 3 Storage Closet	W2	N/A	No Access	No Access	N/A	N/A	N/A
1	1	3A	Classroom 3 Storage Closet	W3	Brick	No Access	No Access	Partially Inaccessable	34	Positive
1	1	3A	Classroom 3 Storage Closet	W4	Wood	No Access	No Access	0	0.2	Negative
1	1	5A	Classroom 5 Storage Closet	W2	Wood	Green	Chipping	10	0.2	Negative
1	1	5A	Classroom 5 Storage Closet	W3	Brick	Green	Chipping	25	20.5	Positive
1	1	5A	Classroom 5 Storage Closet	W4	Wood	Green	Chipping	4	0.2	Negative
1	1	7A	Counselor's Office - Left Rear Room	W1	Plaster	Tan	None	0	0.1	Positive
1	1	7A	Counselor's Office - Left Rear Room	W2	Plaster	Tan	None	0	37	Positive

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	7A	Counselor's Office - Left Rear Room	W4	Plaster	No Access	No Access	10	0	Negative
1	1	7B	Counselor's Office - Right Rear Room	W4	Plaster		Chipping	1	37	Positive
1	1	7E	Closet next to Staff Restroom across from Classroom 5	W1	Brick	Green	Chipping	5	12.7	Positive
1	1	7E	Closet next to Staff Restroom across from Classroom 5	W2	Brick	Green	Chipping	10	18	Positive
1	1	7E	Closet next to Staff Restroom across from Classroom 5	W3	Brick	Green	Chipping	18	21.7	Positive
1	1	7E	Closet next to Staff Restroom across from Classroom 5	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	7E	Closet next to Staff Restroom across from Classroom 5	W4	Brick	Green	Chipping	10	22.5	Positive
1	1	7E	Closet next to Staff Restroom across from Classroom 5	Ceiling	Plaster	Green	Cracking	2	10.2	Positive
1	1	8A	Classroom 8 Storage Closet	W2	Plaster	White	Partially Inaccessible	Partially Inaccessible	25.6	Positive
1	1	8A	Classroom 8 Storage Closet	W3	Plaster	White	Partially Inaccessible	Partially Inaccessible	23	Positive
1	1	8A	Classroom 8 Storage Closet	W4	Plaster	White	Partially Inaccessible	Partially Inaccessible	26.1	Positive
1	1	11C	Classroom 11 Storage Closet	W1	Plaster			6	10.5	Positive
1	1	11C	Classroom 11 Storage Closet	W2	Plaster			24	11.5	Positive
1	1	11C	Classroom 11 Storage Closet	W3	Plaster			28	16.9	Positive
1	1	11C	Classroom 11 Storage Closet	W4	Plaster			65	11.4	Positive
1	1	H15	Vestibule to Exterior across from Music Classroom 9	Ceiling	Concrete	White	Chipping	3	21.2	Positive
1	2	13A	Classroom 13 Storage Closet	W1	Brick			Partially Inaccessible	26.9	Positive
1	2	13A	Classroom 13 Storage Closet	W2	Brick			Partially Inaccessible	27.8	Positive
1	2	13A	Classroom 13 Storage Closet	W2	N/A	N/A	N/A	0	N/A	N/A
1	2	13A	Classroom 13 Storage Closet	W3	Brick			Partially Inaccessible	28	Positive
1	2	13A	Classroom 13 Storage Closet	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	13A	Classroom 13 Storage Closet	W4	N/A	N/A	N/A	0	N/A	N/A
1	2	14B	Library Storage Closet	W1	Brick			10	27	Positive
1	2	14B	Library Storage Closet	W2	Sheetrock			1	0.2	Negative
1	2	14B	Library Storage Closet	W3	Brick			7	26.4	Positive
1	2	14B	Library Storage Closet	W4	Sheetrock			2	0.2	Negative
1	2	15A	Custodial Closet next to Nurse's Office	W1	Brick			4	0.1	Negative
1	2	15A	Custodial Closet next to Nurse's Office	W2	Brick			5	0.1	Negative
1	2	15A	Custodial Closet next to Nurse's Office	W3	Brick			7	0.2	Negative
1	2	15A	Custodial Closet next to Nurse's Office	W4	Brick			6	0.1	Negative
1	2	15A	Custodial Closet next to Nurse's Office	Ceiling	Plaster			20	0.1	Negative
1	3	25A	Classroom 25 Storage Closet	W1	Brick			Partially Inaccessible	29.1	Positive

School District of Philadelphia										
Lead Safe Certification Inspection Report										
Francis Scott Key School										
			Name of Inspector: Charles Rhodes							
			Inspection Company: Batta							
E l e m e n t	F l o o r	Space #	On-Site Room Name	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	25A	Classroom 25 Storage Closet	W2	Brick			Partially Inaccessable	31	Positive
1	3	25A	Classroom 25 Storage Closet	W3	Brick			Partially Inaccessable	27.9	Positive
1	3	25A	Classroom 25 Storage Closet	W4	Wood			Partially Inaccessable	0.2	Negative
1	3	25A	Classroom 25 Storage Closet	Ceiling	Plaster			36	2.1	Positive
1	3	27A	Classroom 27 Storage Closet	W1	Brick			40	40	Positive
1	3	27A	Classroom 27 Storage Closet	W2	Wood			31	0	Negative
1	3	27A	Classroom 27 Storage Closet	W3	Brick			35	27.4	Positive
1	3	27A	Classroom 27 Storage Closet	W4	Plaster			9	23.2	Positive
1	3	27A	Classroom 27 Storage Closet	Ceiling	Plaster			29	23.2	Positive
1	3	27B	Faculty Lounge next to Classroom 23	W1	Plaster	Green	Cracking	5	40	Positive
1	3	27B	Faculty Lounge next to Classroom 23	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	33A	Classroom 33 Storage Closet	W1	Plaster			75	35	Positive
1	3	33A	Classroom 33 Storage Closet	W2	Plaster			22	0.9	Positive
1	3	33A	Classroom 33 Storage Closet	W3	Plaster			7	10.3	Positive
1	3	33A	Classroom 33 Storage Closet	W4	Plaster			4	27.8	Positive