

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	3	Faculty Lounge 300	W1	Plaster	White	Flaking	12	0.76	Positive
1	3	Faculty Lounge 300	W2	Plaster	White	Cracking	8	0.09	Negative
1	3	Faculty Lounge 300	W2	N/A	N/A	None	N/A	N/A	N/A
1	3	Faculty Lounge 300	W3	Metal	White	Chipping	3	0.3	Negative
1	3	Faculty Lounge 300	W4	Plaster	White	Moisture Damage	3	0.29	Negative
1	3	Faculty Lounge 300	W4	N/A	N/A	None	N/A	N/A	N/A
1	3	Faculty Lounge 300	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Faculty Lounge 300	Floor	Wood	Brown	None	N/A	N/A	N/A
1	3	Faculty Lounge 300 Back Area	W1	Metal	White	Cracking	6	0.4	Negative
1	3	Faculty Lounge 300 Back Area	W2	Plaster	White	Chipping	12	0.22	Negative
1	3	Faculty Lounge 300 Back Area	W3	Plaster	White	Cracking	40	0.15	Negative
1	3	Faculty Lounge 300 Back Area	W3	N/A	N/A	None	N/A	N/A	N/A
1	3	Faculty Lounge 300 Back Area	W4	Plaster	White	Cracking	5	0.08	Negative
1	3	Faculty Lounge 300 Back Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Faculty Lounge 300 Back Area	Floor	Wood	Brown	None	N/A	N/A	N/A
1	3	Faculty Lounge 300 Restroom	W1	Plaster	White	Cracking	40	0.02	Negative
1	3	Faculty Lounge 300 Restroom	W1	N/A	N/A	None	N/A	N/A	N/A
1	3	Faculty Lounge 300 Restroom	W2	Plaster	White	Moisture Damage	7	2.62	Positive
1	3	Faculty Lounge 300 Restroom	W3	Plaster	White	Flaking	35	0.02	Negative
1	3	Faculty Lounge 300 Restroom	W4	Plaster	White	Moisture Damage	20	0.07	Negative
1	3	Faculty Lounge 300 Restroom	W4	N/A	N/A	None	N/A	N/A	N/A
1	3	Faculty Lounge 300 Restroom	Ceiling	Plaster	White	Moisture Damage	20	0	Negative
1	3	Faculty Lounge 300 Restroom	Floor	Concrete	Grey	Friction	40	0.79	Positive
1	3	Fire Tower	W1	Metal	Brown	None	N/A	N/A	N/A
1	3	Fire Tower	W2	Brick	White	Alligatoring	48	5	Positive
1	3	Fire Tower	W3	Concrete	White	Cracking	10	4.95	Positive
1	3	Fire Tower	W3	N/A	N/A	None	N/A	N/A	N/A
1	3	Fire Tower	W3	N/A	N/A	None	N/A	N/A	N/A
1	3	Fire Tower	W4	Brick	White	Chipping	48	5	Positive
1	3	Fire Tower	Ceiling	Concrete	White	Flaking	96	16.3	Positive
1	3	Fire Tower	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	3	Hallway Closet adjacent to Classroom 303	W1	Plaster	White	Chipping	1	1	Positive
1	3	Hallway Closet adjacent to Classroom 303	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway Closet adjacent to Classroom 303	W3	Plaster	White	Chipping	5	1	Positive
1	3	Hallway Closet adjacent to Classroom 303	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway Closet adjacent to Classroom 303	Ceiling	N/A	N/A	Chipping	22	0.1	Negative
1	3	Hallway Closet adjacent to Classroom 303	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	Classroom 303	W1	Plaster	White	Flaking	11	0.14	Negative
1	3	Classroom 303	W2	Plaster	White	Flaking	7	1	Positive
1	3	Classroom 303	W3	Plaster	White	Chipping	27	1	Positive
1	3	Classroom 303	W4	Plaster	White	Flaking	2	1	Positive
1	3	Classroom 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 303	Floor	Wood	Brown	None	N/A	N/A	N/A
1	3	Classroom 303 Back Coat Closet	W1	Plaster	Tan	Cracking	5	5	Positive
1	3	Classroom 303 Back Coat Closet	W2	Plaster	Tan	Chipping	25	5	Positive
1	3	Classroom 303 Back Coat Closet	W3	Plaster	Tan	None	N/A	N/A	N/A

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	3	Classroom 303 Back Coat Closet	W4	Plaster	Tan	Cracking	7	5	Positive
1	3	Classroom 303 Back Coat Closet	Ceiling	Plaster	White	Cracking	16	20.2	Positive
1	3	Classroom 303 Back Coat Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	3	Classroom 303 Front Coat Closet	W1	Plaster	Tan	Cracking	6	5	Positive
1	3	Classroom 303 Front Coat Closet	W2	Plaster	Tan	Cracking	3	5	Positive
1	3	Classroom 303 Front Coat Closet	W3	Plaster	Tan	Cracking	2	5	Positive
1	3	Classroom 303 Front Coat Closet	W4	Plaster	Tan	Partially Inaccessible	0	N/A	N/A
1	3	Classroom 303 Front Coat Closet	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 303 Front Coat Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	3	Hallway from Fire Tower to Classroom 301	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Fire Tower to Classroom 301	W2	Plaster	White	Flaking	14	1	Positive
1	3	Hallway from Fire Tower to Classroom 301	W3	Metal	White	None	N/A	N/A	N/A
1	3	Hallway from Fire Tower to Classroom 301	W4	Plaster	White	Cracking	6	1	Positive
1	3	Hallway from Fire Tower to Classroom 301	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Fire Tower to Classroom 301	Floor	Concrete	No Access	None	N/A	N/A	N/A
1	3	Classroom 301	W1	Plaster	White	Flaking	2	0.3	Negative
1	3	Classroom 301	W1	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 301	W2	Plaster	White	Flaking	2	0.23	Negative
1	3	Classroom 301	W2	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 301	W3	Plaster	White	Flaking	11	0.36	Negative
1	3	Classroom 301	W3	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 301	W4	Plaster	White	Flaking	2	0.25	Negative
1	3	Classroom 301	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 301	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 301 Closet	W1	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 301 Closet	W2	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 301 Closet	W2	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 301 Closet	W3	Plaster	White	Moisture Damage	6	5	Positive
1	3	Classroom 301 Closet	W4	Plaster	White	Cracking	14	4.32	Positive
1	3	Classroom 301 Closet	Ceiling	Plaster	White	Chipping	30	22.3	Positive
1	3	Classroom 301 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairwell between Classrooms 301 and 302	W1	Plaster	White	None	N/A	N/A	N/A
1	3	Stairwell between Classrooms 301 and 302	W2	Plaster	White	None	N/A	N/A	N/A
1	3	Stairwell between Classrooms 301 and 302	W3	Plaster	White	None	N/A	N/A	N/A
1	3	Stairwell between Classrooms 301 and 302	W4	Plaster	White	Flaking	1	0	Negative
1	3	Stairwell between Classrooms 301 and 302	Ceiling	Plaster	White	None	N/A	N/A	N/A
1	3	Stairwell between Classrooms 301 and 302	Floor	Concrete	No Access	None	N/A	N/A	N/A
1	3	Classroom 302	W1	Plaster	White	Spalling	10	0.22	Negative
1	3	Classroom 302	W2	Plaster	White	Flaking	5	1	Positive
1	3	Classroom 302	W2	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 302	W3	Plaster	White	Cracking	25	1	Positive
1	3	Classroom 302	W4	Plaster	White	Chipping	11	1	Positive
1	3	Classroom 302	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 302	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	Classroom 302 Coat Closet	W1	Plaster	White	Alligatoring	46	5	Positive
1	3	Classroom 302 Coat Closet	W1	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 302 Coat Closet	W2	Plaster	White	Chipping	10	2.93	Positive

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	3	Classroom 302 Coat Closet	W3	Plaster	White	Moisture Damage	164	4.15	Positive
1	3	Classroom 302 Coat Closet	W3	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 302 Coat Closet	W4	Plaster	White	Chipping	15	3.22	Positive
1	3	Classroom 302 Coat Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 302 Coat Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	Custodial Closet adjacent to Classroom 302	W1	Plaster	Yellow	Moisture Damage	11	5	Positive
1	3	Custodial Closet adjacent to Classroom 302	W2	Plaster	Yellow	Moisture Damage	20	5	Positive
1	3	Custodial Closet adjacent to Classroom 302	W3	Plaster	Yellow	Moisture Damage	30	5	Positive
1	3	Custodial Closet adjacent to Classroom 302	W4	Plaster	Yellow	Moisture Damage	4	4.27	Positive
1	3	Custodial Closet adjacent to Classroom 302	Ceiling	Plaster	Yellow	Moisture Damage	15	0.2	Negative
1	3	Custodial Closet adjacent to Classroom 302	Floor	Concrete	Grey	Friction	5	0.08	Negative
1	3	Girl's Restroom	W1	Concrete	White	None	N/A	N/A	N/A
1	3	Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Girl's Restroom	W2	Concrete	White	None	N/A	N/A	N/A
1	3	Girl's Restroom	W3	Concrete	White	None	N/A	N/A	N/A
1	3	Girl's Restroom	W4	Concrete	White	None	N/A	N/A	N/A
1	3	Girl's Restroom	Ceiling	Plaster	White	Chipping	60	0.1	Negative
1	3	Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Music Room 304	W1	Plaster	White	Chipping	3	1	Positive
1	3	Music Room 304	W1	N/A	N/A	None	N/A	N/A	N/A
1	3	Music Room 304	W2	Plaster	White	Cracking	3	0.09	Negative
1	3	Music Room 304	W3	Plaster	White	Cracking	14	0	Negative
1	3	Music Room 304	W3	N/A	N/A	None	N/A	N/A	N/A
1	3	Music Room 304	W4	Plaster	White	Flaking	9	1	Positive
1	3	Music Room 304	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Music Room 304	Floor	Wood	Brown	None	N/A	N/A	N/A
1	3	Music Room 304 Coat Closet	W1	Plaster	White	None	0	N/A	N/A
1	3	Music Room 304 Coat Closet	W2	Plaster	White	Cracking	4	5	Positive
1	3	Music Room 304 Coat Closet	W2	N/A	N/A	None	N/A	N/A	N/A
1	3	Music Room 304 Coat Closet	W3	Plaster	White	Cracking	10	5	Positive
1	3	Music Room 304 Coat Closet	W4	Plaster	White	Spalling	9	5	Positive
1	3	Music Room 304 Coat Closet	W4	N/A	N/A	None	N/A	N/A	N/A
1	3	Music Room 304 Coat Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Music Room 304 Coat Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	3	Music Room 305	W1	Plaster	White	Chipping	3	1	Positive
1	3	Music Room 305	W1	N/A	N/A	None	N/A	N/A	N/A
1	3	Music Room 305	W2	Plaster	White	None	0	N/A	N/A
1	3	Music Room 305	W3	Plaster	White	Spalling	10	1	Positive
1	3	Music Room 305	W3	N/A	N/A	None	N/A	N/A	N/A
1	3	Music Room 305	W4	Plaster	White	Chipping	3	1	Positive
1	3	Music Room 305	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Music Room 305	Floor	Wood	Brown	None	N/A	N/A	N/A
1	3	Music Room 305 Coat Closet	W1	Plaster	White	Cracking	2	5	Positive
1	3	Music Room 305 Coat Closet	W2	Plaster	White	Cracking	3	5	Positive

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	3	Music Room 305 Coat Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Music Room 305 Coat Closet	W3	Plaster	White	Cracking	2	5	Positive
1	3	Music Room 305 Coat Closet	W4	Plaster	White	Cracking	9	5	Positive
1	3	Music Room 305 Coat Closet	W4	N/A	N/A	None	N/A	N/A	N/A
1	3	Music Room 305 Coat Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Music Room 305 Coat Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	3	Classroom 306	W1	Plaster	White	Spalling	2	1	Positive
1	3	Classroom 306	W2	Plaster	White	Cracking	7	0	Negative
1	3	Classroom 306	W3	Plaster	White	Cracking	3	0.07	Negative
1	3	Classroom 306	W3	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 306	W4	Plaster	White	Chipping	2	1	Positive
1	3	Classroom 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 306	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	Classroom 306 Coat Closet	W1	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 306 Coat Closet	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 306 Coat Closet	W2	Plaster	White	Alligatoring	10	5	Positive
1	3	Classroom 306 Coat Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 306 Coat Closet	W3	Plaster	White	Chipping	2	5	Positive
1	3	Classroom 306 Coat Closet	W3	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 306 Coat Closet	W4	Plaster	White	Cracking	5	5	Positive
1	3	Classroom 306 Coat Closet	W4	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 306 Coat Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 306 Coat Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	3	Boy's Restroom	W1	Concrete	Tan	None	N/A	N/A	N/A
1	3	Boy's Restroom	W2	Concrete	Tan	None	N/A	N/A	N/A
1	3	Boy's Restroom	W3	Concrete	Tan	None	N/A	N/A	N/A
1	3	Boy's Restroom	W4	Concrete	Tan	None	N/A	N/A	N/A
1	3	Boy's Restroom	Ceiling	Concrete	Tan	Chipping	6	0.1	Negative
1	3	Boy's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Boy's Restroom	Floor	Concrete	Tan	N/A	N/A	N/A	N/A
1	3	Custodial Closet adjacent Boy's Restroom	W1	Plaster	Tan	Cracking	30	5	N/A
1	3	Custodial Closet adjacent Boy's Restroom	W1	N/A	N/A	None	N/A	N/A	N/A
1	3	Custodial Closet adjacent Boy's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Custodial Closet adjacent Boy's Restroom	W2	Plaster	Tan	Cracking	48	5	Positive
1	3	Custodial Closet adjacent Boy's Restroom	W3	Plaster	Tan	Cracking	48	5	Positive
1	3	Custodial Closet adjacent Boy's Restroom	W4	Plaster	Tan	Cracking	48	5	Positive
1	3	Custodial Closet adjacent Boy's Restroom	Ceiling	Plaster	Tan	Cracking	20	50.1	Positive
1	3	Custodial Closet adjacent Boy's Restroom	Floor	Concrete	Tan	N/A	N/A	N/A	N/A
1	3	Classroom 307	W1	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 307	W1	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 307	W2	Plaster	White	Chipping	5	5	Positive
1	3	Classroom 307	W2	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 307	W3	Plaster	White	Chipping	5	0.09	Negative
1	3	Classroom 307	W3	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 307	W4	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 307	W4	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 307	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 307	Floor	Wood	N/A	None	N/A	N/A	N/A
1	3	Classroom 307 Coat Closet	W1	Plaster	White	Alligatoring	10	5	Positive
1	3	Classroom 307 Coat Closet	W1	N/A	N/A	None	N/A	N/A	N/A

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	3	Classroom 307 Coat Closet	W2	Plaster	White	Alligatoring	6	5	Positive
1	3	Classroom 307 Coat Closet	W3	Plaster	White	Chipping	40	5	Positive
1	3	Classroom 307 Coat Closet	W3	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 307 Coat Closet	W4	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 307 Coat Closet	W4	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 307 Coat Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 307 Coat Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Stairwell between Classrooms 307 and 308	W1	Metal	Grey	Flaking	3	0	Negative
1	3	Stairwell between Classrooms 307 and 308	W2	Plaster	White	Chipping	6	1	Positive
1	3	Stairwell between Classrooms 307 and 308	W3	Plaster	White	Chipping	12	0.25	Negative
1	3	Stairwell between Classrooms 307 and 308	W4	Plaster	White	Chipping	6	1	Positive
1	3	Stairwell between Classrooms 307 and 308	Ceiling	Plaster	White	Moisture Damage	4	0	Negative
1	3	Stairwell between Classrooms 307 and 308	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 302 to 307	W1	Metal	Grey	Flaking	6	0	Negative
1	3	Hallway from Classrooms 302 to 307	W2	Plaster	White	None	N/A	N/A	N/A
1	3	Hallway from Classrooms 302 to 307	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 302 to 307	W4	Plaster	White	None	8	1	Positive
1	3	Hallway from Classrooms 302 to 307	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 302 to 307	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 308	W1	Plaster	White	Spalling	2	1	Positive
1	3	Classroom 308	W2	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 308	W3	Plaster	White	Cracking	20	0.05	Negative
1	3	Classroom 308	W3	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 308	W4	Plaster	White	Flaking	6	0.1	Negative
1	3	Classroom 308	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 308	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 308	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 308 Coat Closet	W1	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 308 Coat Closet	W2	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 308 Coat Closet	W3	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 308 Coat Closet	W4	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 308 Coat Closet	Ceiling	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 308 Coat Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 309	W1	Plaster	White	None	3	1	Positive
1	3	Classroom 309	W2	Plaster	White	N/A	N/A	N/A	N/A
1	3	Classroom 309	W2	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 309	W3	Plaster	White	Chipping	7	0.32	Negative
1	3	Classroom 309	W3	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 309	W4	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 309	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 309	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 309 Coat Closet	W1	Plaster	White	Chipping	4	5	Positive
1	3	Classroom 309 Coat Closet	W2	Plaster	White	Partially Inaccessible	2	3.18	Positive
1	3	Classroom 309 Coat Closet	W3	Plaster	White	Partially Inaccessible	5	4.03	Positive
1	3	Classroom 309 Coat Closet	W4	Plaster	White	Partially Inaccessible	2	5	Positive
1	3	Classroom 309 Coat Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	Primary Component XRF (positive/negative)
1	3	Classroom 309 Coat Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 310	W1	Plaster	White	Spalling	4	1	Positive
1	3	Classroom 310	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 310	W2	Plaster	White	N/A	N/A	N/A	N/A
1	3	Classroom 310	W3	Plaster	White	Cracking	4	1	Positive
1	3	Classroom 310	W3	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 310	W4	Plaster	White	Chipping	12	1	Positive
1	3	Classroom 310	W4	N/A	N/A	None	N/A	N/A	N/A
1	3	Classroom 310	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 310	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 310 Coat Closet	W1	Plaster	White	Chipping	3	3.23	Positive
1	3	Classroom 310 Coat Closet	W2	Plaster	White	Alligating	16	5	Positive
1	3	Classroom 310 Coat Closet	W3	Plaster	White	Moisture Damage	10	5	Positive
1	3	Classroom 310 Coat Closet	W4	Plaster	White	Moisture Damage	5		No Access
1	3	Classroom 310 Coat Closet	Ceiling	Plaster	Tan	Moisture Damage	15	17.4	Positive
1	3	Classroom 310 Coat Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 311	W1	Plaster	Yellow	None	N/A	N/A	N/A
1	3	Classroom 311	W2	Plaster	Yellow	Spalling	14	0.18	Negative
1	3	Classroom 311	W3	Plaster	Yellow	None	N/A	N/A	N/A
1	3	Classroom 311	W4	Plaster	Yellow	None	N/A	N/A	N/A
1	3	Classroom 311	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 311	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 311 Closet on exterior side	W1	Plaster	White	Moisture Damage	2	5	Positive
1	3	Classroom 311 Closet on exterior side	W2	Plaster	White	Moisture Damage	6	5	Positive
1	3	Classroom 311 Closet on exterior side	W3	Plaster	White	Moisture Damage	6	5	Positive
1	3	Classroom 311 Closet on exterior side	W4	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 311 Closet on exterior side	Ceiling	Plaster	White	Moisture Damage	3	16.3	Positive
1	3	Classroom 311 Closet on exterior side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 311 Closet on Hall side	W1	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 311 Closet on Hall side	W2	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 311 Closet on Hall side	W3	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 311 Closet on Hall side	W4	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 311 Closet on Hall side	Ceiling	Plaster	White	None	N/A	N/A	N/A
1	3	Classroom 311 Closet on Hall side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classroom 310 to 308	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classroom 310 to 308	W2	Plaster	White	None	N/A	N/A	N/A
1	3	Hallway from Classroom 310 to 308	W3	Plaster	White	None	N/A	N/A	N/A
1	3	Hallway from Classroom 310 to 308	W4	Plaster	White	Chipping	3	0.15	Negative
1	3	Hallway from Classroom 310 to 308	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Hallway from Classroom 310 to 308	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200	W1	Plaster	White	Flaking	10	0.09	Negative
1	2	Classroom 200	W2	Plaster	White	Cracking	5	1	Positive
1	2	Classroom 200	W2	N/A	N/A	N/A	N/A	N/A	N/A

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	Primary Component XRF (positive/negative)
1	2	Classroom 200	W3	Plaster	White	Moisture Damage	42	0.15	Negative
1	2	Classroom 200	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200	W4	Plaster	White	Cracking	8	1	Positive
1	2	Classroom 200	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	Classroom 200 Closet	W1	Plaster	White	Cracking	6	1	Positive
1	2	Classroom 200 Closet	W2	Plaster	White	None	0	N/A	N/A
1	2	Classroom 200 Closet	W3	Plaster	White	Cracking	6	1	Positive
1	2	Classroom 200 Closet	W4	Plaster	White	Cracking	10	0.37	Negative
1	2	Classroom 200 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 200 Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	Fire Tower	W1	Metal	Brown	Flaking	1	0	Negative
1	2	Fire Tower	W2	Brick	White	Chipping	50	5	Positive
1	2	Fire Tower	W3	Concrete	White	Chipping	10	5	Positive
1	2	Fire Tower	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Fire Tower	W4	Brick	White	Chipping	45	5	Positive
1	2	Fire Tower	Ceiling	Concrete	White	Flaking	96	17.5	Positive
1	2	Fire Tower	Floor	Concrete	Grey	Partially Inaccessible	N/A	N/A	N/A
1	2	Hallway Closet adjacent to Classroom 203	W1	Plaster	Tan	Flaking	5	4.75	Positive
1	2	Hallway Closet adjacent to Classroom 203	W2	Plaster	Tan	Cracking	2	1	Positive
1	2	Hallway Closet adjacent to Classroom 203	W3	Plaster	Tan	Chipping	7	1	Positive
1	2	Hallway Closet adjacent to Classroom 203	W4	Plaster	Tan	Flaking	7	1	Positive
1	2	Hallway Closet adjacent to Classroom 203	Ceiling	Plaster	Tan	Chipping	12	13.3	Positive
1	2	Hallway Closet adjacent to Classroom 203	Floor	Concrete	Grey	Partially Inaccessible	N/A	N/A	N/A
1	2	Classroom 203	W1	Plaster	White	Flaking	5	1	Positive
1	2	Classroom 203	W2	Plaster	White	Flaking	10	0.37	Negative
1	2	Classroom 203	W3	Plaster	White	Spalling	30	1	Positive
1	2	Classroom 203	W3	N/A	N/A	None	N/A	N/A	N/A
1	2	Classroom 203	W4	Plaster	White	Cracking	2	1	Positive
1	2	Classroom 203	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	Classroom 203 Back Coat Closet	W1	Plaster	Grey	Cracking	6	5	Positive
1	2	Classroom 203 Back Coat Closet	W2	Plaster	Grey	Cracking	16	5	Positive
1	2	Classroom 203 Back Coat Closet	W3	Plaster	Grey	Flaking	6	5	Positive
1	2	Classroom 203 Back Coat Closet	W4	Plaster	Grey	Cracking	5	5	Positive
1	2	Classroom 203 Back Coat Closet	Ceiling	Plaster	White	Flaking	2	0.1	Negative
1	2	Classroom 203 Back Coat Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	Classroom 203 Front Coat Closet	W1	Plaster	White	None	0	5	Positive
1	2	Classroom 203 Front Coat Closet	W2	Plaster	White	None	0	5	Positive
1	2	Classroom 203 Front Coat Closet	W3	Plaster	White	Cracking	6	5	Positive
1	2	Classroom 203 Front Coat Closet	W4	Plaster	White	Cracking	4	5	Positive
1	2	Classroom 203 Front Coat Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 203 Front Coat Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	Hallway from Fire Tower to Classroom 201	W1	Metal	Grey	Flaking	9	0	Negative
1	2	Hallway from Fire Tower to Classroom 201	W2	Plaster	Tan	Cracking	7	1	Positive
1	2	Hallway from Fire Tower to Classroom 201	W2	N/A	N/A	N/A	N/A	N/A	N/A

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	2	Hallway from Fire Tower to Classroom 201	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Fire Tower to Classroom 201	W4	Plaster	Tan	Cracking	5	0.11	Negative
1	2	Hallway from Fire Tower to Classroom 201	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Fire Tower to Classroom 201	Floor	Concrete	Gray	None	N/A	N/A	N/A
1	2	Classroom 201	W1	Plaster	Tan	Chipping	9	0.31	Negative
1	2	Classroom 201	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 201	W2	Plaster	Tan	Chipping	10	0	Negative
1	2	Classroom 201	W3	Plaster	Tan	Cracking	36	0.21	Negative
1	2	Classroom 201	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 201	W4	Plaster	Tan	Cracking	6	0.06	Negative
1	2	Classroom 201	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 201	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 201 Closet	W1	Plaster	White	Cracking	40	5.00.	Positive
1	2	Classroom 201 Closet	W2	Plaster	White	Cracking	10	5.00.	Positive
1	2	Classroom 201 Closet	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 201 Closet	W3	Plaster	White	Cracking	30	5.00.	Positive
1	2	Classroom 201 Closet	W4	Plaster	White	Cracking	2	5.00.	Positive
1	2	Classroom 201 Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 201 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 201 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell between Classrooms 201 and 202	W1	Metal	Grey	N/A	N/A	N/A	N/A
1	2	Stairwell between Classrooms 201 and 202	W2	Plaster	Tan	None	N/A	N/A	N/A
1	2	Stairwell between Classrooms 201 and 202	W3	Plaster	Tan	Flaking	5	0.13	Negative
1	2	Stairwell between Classrooms 201 and 202	W4	Plaster	Tan	None	N/A	N/A	N/A
1	2	Stairwell between Classrooms 201 and 202	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell between Classrooms 201 and 202	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell between Classrooms 201 and 202	Ceiling	Plaster	White	Chipping	3	0.2	Negative
1	2	Stairwell between Classrooms 201 and 202	Floor	Concrete	Grey	Partially Inaccessible	N/A	N/A	N/A
1	2	Classroom 202	W1	Plaster	Tan	Chipping	8	1	Positive
1	2	Classroom 202	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	W2	Plaster	Tan	Chipping	5	1	Positive
1	2	Classroom 202	W3	Plaster	Tan	Cracking	20	1	Positive
1	2	Classroom 202	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	W4	Plaster	Tan	Chipping	12	1	Positive
1	2	Classroom 202	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	Classroom 202 Coat Closet	W1	Plaster	Blue	Cracking	2	5	Positive
1	2	Classroom 202 Coat Closet	W2	Plaster	Blue	Cracking	60	3.62	Positive
1	2	Classroom 202 Coat Closet	W3	Plaster	Blue	Cracking	20	5	Positive
1	2	Classroom 202 Coat Closet	W4	Plaster	Blue	Chipping	40	5	Positive
1	2	Classroom 202 Coat Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 202 Coat Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	Custodial Closet adjacent to Classroom 202	W1	Plaster	Yellow	None	N/A	N/A	N/A
1	2	Custodial Closet adjacent to Classroom 202	W2	Plaster	Yellow	None	N/A	N/A	N/A
1	2	Custodial Closet adjacent to Classroom 202	W3	Plaster	Yellow	Cracking	3	5	Positive
1	2	Custodial Closet adjacent to Classroom 202	W4	Plaster	Yellow	None	N/A	N/A	N/A
1	2	Custodial Closet adjacent to Classroom 202	Ceiling	Plaster	Yellow	None	N/A	N/A	N/A
1	2	Custodial Closet adjacent to Classroom 202	Floor	Concrete	Grey	Friction	15	1	Positive
1	2	Girl's Restroom	W1	Concrete	Pink	None	N/A	N/A	N/A

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	2	Girl's Restroom	W2	Concrete	Pink	None	N/A	N/A	N/A
1	2	Girl's Restroom	W3	Concrete	Pink	None	N/A	N/A	N/A
1	2	Girl's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Girl's Restroom	W4	Concrete	Pink	None	N/A	N/A	N/A
1	2	Girl's Restroom	Ceiling	Concrete	White	Chipping	30	0.2	Negative
1	2	Girl's Restroom	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	2	Classroom 204	W1	Plaster	Tan	Chipping	4	1	Positive
1	2	Classroom 204	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 204	W2	Wood	Brown	None	N/A	N/A	N/A
1	2	Classroom 204	W3	Plaster	Tan	Chipping	34	1	Positive
1	2	Classroom 204	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 204	W4	Plaster	Tan	Cracking	3	1	Positive
1	2	Classroom 204	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 204	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	Classroom 204 Coat Closet	W1	Plaster	White	None	N/A	N/A	N/A
1	2	Classroom 204 Coat Closet	W2	Plaster	White	Cracking	6	5	Positive
1	2	Classroom 204 Coat Closet	W3	Plaster	White	Chipping	2	5	Positive
1	2	Classroom 204 Coat Closet	W4	Plaster	White	Cracking	8	5	Positive
1	2	Classroom 204 Coat Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 204 Coat Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	IMC 206	W1	Plaster	White	Chipping	4	0	Negative
1	2	IMC 206	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	IMC 206	W2	Plaster	White	Chipping	3	0.04	Negative
1	2	IMC 206	W3	Plaster	White	Cracking	8	0.06	Negative
1	2	IMC 206	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	IMC 206	W4	Plaster	White	Chipping	1	0	Negative
1	2	IMC 206	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	IMC 206	Floor	Concrete	Gray	Partially Inaccessible	N/A	N/A	N/A
1	2	IMC 206 Closet on Classroom 207 side	W1	Plaster	Tan	None	N/A	N/A	N/A
1	2	IMC 206 Closet on Classroom 207 side	W2	Plaster	White	None	N/A	N/A	N/A
1	2	IMC 206 Closet on Classroom 207 side	W3	Plaster	White	None	N/A	N/A	N/A
1	2	IMC 206 Closet on Classroom 207 side	W4	Plaster	White	None	N/A	N/A	N/A
1	2	IMC 206 Closet on Classroom 207 side	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	IMC 206 Closet on Classroom 207 side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	IMC 206 Closet on Classroom 204 side	W1	Plaster	White	None	N/A	N/A	N/A
1	2	IMC 206 Closet on Classroom 204 side	W2	Plaster	White	Cracking	4	5	Positive
1	2	IMC 206 Closet on Classroom 204 side	W3	Plaster	White	None	N/A	N/A	N/A
1	2	IMC 206 Closet on Classroom 204 side	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	IMC 206 Closet on Classroom 204 side	W4	Plaster	White	Chipping	3	5	Positive
1	2	IMC 206 Closet on Classroom 204 side	Ceiling	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	N/A	N/A	N/A
1	2	IMC 206 Closet on Classroom 204 side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	IMC 206 Middle Closet next to door	W1	Plaster	Tan	Chipping	5	4.86	Positive
1	2	IMC 206 Middle Closet next to door	W2	Plaster	Tan	Chipping	6	5	Positive
1	2	IMC 206 Middle Closet next to door	W3	Plaster	Tan	None	N/A	N/A	N/A
1	2	IMC 206 Middle Closet next to door	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	IMC 206 Middle Closet next to door	W4	Plaster	Tan	Cracking	8	5	Positive
1	2	IMC 206 Middle Closet next to door	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	IMC 206 Middle Closet next to door	Floor	N/A	N/A	N/A	N/A	N/A	N/A

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	2	Boy's Restroom	W1	Concrete	Blue	None	N/A	N/A	N/A
1	2	Boy's Restroom	W2	Concrete	Blue	None	N/A	N/A	N/A
1	2	Boy's Restroom	W3	Concrete	Blue	None	N/A	N/A	N/A
1	2	Boy's Restroom	W4	Concrete	Blue	None	N/A	N/A	N/A
1	2	Boy's Restroom	Ceiling	Plaster	White	Cracking	30	2	Negative
1	2	Boy's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Boy's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Custodial Closet adjacent Classroom 206	W1	Plaster	Tan	Cracking	20	1	Positive
1	2	Custodial Closet adjacent Classroom 206	W2	Plaster	Tan	Chipping	64	3.06	Positive
1	2	Custodial Closet adjacent Classroom 206	W3	Plaster	Tan	Cracking	64	1	Positive
1	2	Custodial Closet adjacent Classroom 206	W4	Plaster	Tan	Cracking	64	1	Positive
1	2	Custodial Closet adjacent Classroom 206	Ceiling	Plaster	Tan	Chipping	20	no access	inconclusive
1	2	Custodial Closet adjacent Classroom 206	Floor	Concrete	Grey	Friction	20	1	Positive
1	2	Classroom 207	W1	Plaster	Tan	Spalling	7	1	Positive
1	2	Classroom 207	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 207	W2	Plaster	Tan	Chipping	20	1	Positive
1	2	Classroom 207	W3	Plaster	Tan	Chipping	24	1	Positive
1	2	Classroom 207	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 207	W4	Plaster	Tan	Chipping	8	1	Positive
1	2	Classroom 207	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 207	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	Classroom 207 Coat Closet	W1	Plaster	Tan	Chipping	30	5	Positive
1	2	Classroom 207 Coat Closet	W2	Plaster	Tan	Cracking	10	5	Positive
1	2	Classroom 207 Coat Closet	W3	Plaster	Tan	Cracking	15	5	Positive
1	2	Classroom 207 Coat Closet	W4	Plaster	Tan	Cracking	2	5	Positive
1	2	Classroom 207 Coat Closet	Ceiling	Plaster	Tan	Chipping	40	0	Negative
1	2	Classroom 207 Coat Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	Stairwell between Classrooms 207 and 208	W1	Plaster	Tan	None	N/A	N/A	N/A
1	2	Stairwell between Classrooms 207 and 208	W2	Plaster	Tan	Cracking	10	1	Positive
1	2	Stairwell between Classrooms 207 and 208	W3	Plaster	Tan	Chipping	4	0.27	Negative
1	2	Stairwell between Classrooms 207 and 208	W4	Plaster	Tan	Chipping	11	1	Positive
1	2	Stairwell between Classrooms 207 and 208	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairwell between Classrooms 207 and 208	Ceiling	Plaster	White	Flaking	7	0.1	Negative
1	2	Stairwell between Classrooms 207 and 208	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	2	Hallway from Classroom 202 to 207	W1	Metal	Grey	None	N/A	N/A	N/A
1	2	Hallway from Classroom 202 to 207	W2	Plaster	Tan	Cracking	32	1	Positive
1	2	Hallway from Classroom 202 to 207	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classroom 202 to 207	W3	Metal	Grey	None	N/A	N/A	N/A
1	2	Hallway from Classroom 202 to 207	W4	Plaster	Tan	Chipping	20	1	Positive
1	2	Hallway from Classroom 202 to 207	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classroom 202 to 207	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classroom 202 to 207	Floor	Concrete	Grey	Partially Inaccessible	N/A	N/A	N/A
1	2	Classroom 208	W1	Plaster	Tan	Chipping	8	1	Positive
1	2	Classroom 208	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208	W2	Plaster	Tan	Cracking	6	1	Positive
1	2	Classroom 208	W3	Plaster	Tan	Chipping	20	1	Positive
1	2	Classroom 208	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 208	W4	Plaster	Tan	Cracking	3	1	Positive
1	2	Classroom 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	2	Classroom 208	Floor	Wood	Brown	Partially Inaccessible	N/A	N/A	N/A
1	2	Classroom 208 Coat Closet	W1	Plaster	Blue	Chipping	10	5.5	Positive
1	2	Classroom 208 Coat Closet	W2	Plaster	Blue	Chipping	4	5.5	Positive
1	2	Classroom 208 Coat Closet	W3	Plaster	Blue	Cracking	50	5.5	Positive
1	2	Classroom 208 Coat Closet	W4	Plaster	Blue	Chipping	14	5.5	Positive
1	2	Classroom 208 Coat Closet	Ceiling	N/A	White	None	N/A	N/A	N/A
1	2	Classroom 208 Coat Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	Classroom 209	W1	Plaster	Tan	Chipping	2	1	Positive
1	2	Classroom 209	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 209	W2	Plaster	Tan	Chipping	3	1	Positive
1	2	Classroom 209	W3	Plaster	Tan	Chipping	5	1	Positive
1	2	Classroom 209	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 209	W4	Plaster	Tan	Chipping	2	1	Positive
1	2	Classroom 209	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 209	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	Classroom 209 Coat Closet	W1	Plaster	Tan	Chipping	10	5	Positive
1	2	Classroom 209 Coat Closet	W2	Plaster	Tan	Chipping	4	5	Positive
1	2	Classroom 209 Coat Closet	W3	Plaster	Tan	Chipping	15	0.98	Positive
1	2	Classroom 209 Coat Closet	W4	Plaster	Tan	Chipping	3	5	Positive
1	2	Classroom 209 Coat Closet	Ceiling	Plaster	White	Chipping	9	0.2	Negative
1	2	Classroom 209 Coat Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	Classroom 210	W1	Plaster	Tan	Chipping	2	1	Positive
1	2	Classroom 210	W2	Plaster	Tan	None	N/A	N/A	N/A
1	2	Classroom 210	W3	Plaster	Tan	Chipping	7	1	Positive
1	2	Classroom 210	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210	W4	Plaster	Tan	Chipping	11	0.26	Negative
1	2	Classroom 210	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	Classroom 210 Coat Closet	W1	Plaster	Tan	Chipping	2	5	Positive
1	2	Classroom 210 Coat Closet	W2	Plaster	Tan	Cracking	25	4.98	Positive
1	2	Classroom 210 Coat Closet	W3	Plaster	Tan	Cracking	60	5	Positive
1	2	Classroom 210 Coat Closet	W4	Plaster	Tan	Cracking	10	5	Positive
1	2	Classroom 210 Coat Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 210 Coat Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	2	Classroom 211	W1	Plaster	Tan	Chipping	7	1	Positive
1	2	Classroom 211	W2	Plaster	Tan	Chipping	18	1	Positive
1	2	Classroom 211	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211	W3	Plaster	Tan	Chipping	4	1	Positive
1	2	Classroom 211	W4	Plaster	Tan	Cracking	3	1	Positive
1	2	Classroom 211	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	Classroom 211 Closet on windows side	W1	Plaster	Blue	Cracking	2	5	Positive
1	2	Classroom 211 Closet on windows side	W2	Plaster	Blue	Cracking	16	3.7	Positive
1	2	Classroom 211 Closet on windows side	W3	Plaster	Blue	Cracking	6	5	Positive
1	2	Classroom 211 Closet on windows side	W4	Plaster	Blue	Cracking	3	5	Positive
1	2	Classroom 211 Closet on windows side	Ceiling	Plaster	Blue	Chipping	6	14.9	Positive
1	2	Classroom 211 Closet on windows side	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	Classroom 211 Closet on Hall side	W1	Plaster	Blue	None	N/A	N/A	N/A
1	2	Classroom 211 Closet on Hall side	W2	Plaster	Blue	Chipping	2	5	Positive

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	2	Classroom 211 Closet on Hall side	W3	Plaster	Blue	None	N/A	N/A	N/A
1	2	Classroom 211 Closet on Hall side	W4	Plaster	Blue	None	N/A	N/A	N/A
1	2	Classroom 211 Closet on Hall side	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Classroom 211 Closet on Hall side	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 210 to 208	W1	Concrete	Tan	Chipping	5	1	Positive
1	2	Hallway from Classrooms 210 to 208	W2	Plaster	Tan	Chipping	6	1	Positive
1	2	Hallway from Classrooms 210 to 208	W3	Plaster	Tan	Chipping	7	1	Positive
1	2	Hallway from Classrooms 210 to 208	W4	Plaster	Tan	Chipping	3	0.18	Negative
1	2	Hallway from Classrooms 210 to 208	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 210 to 208	Floor	Concrete	No Access	N/A	N/A	N/A	N/A
1	1	Entrance/Waiting Area for Office 100B	W1	Plaster	Blue	None	N/A	N/A	N/A
1	1	Entrance/Waiting Area for Office 100B	W2	Plaster	Blue	None	N/A	N/A	N/A
1	1	Entrance/Waiting Area for Office 100B	W3	Plaster	Blue	None	N/A	N/A	N/A
1	1	Entrance/Waiting Area for Office 100B	W4	Plaster	Blue	None	N/A	N/A	N/A
1	1	Entrance/Waiting Area for Office 100B	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Entrance/Waiting Area for Office 100B	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	Counselor's Office 100A	W1	Plaster	Blue	None	N/A	N/A	N/A
1	1	Counselor's Office 100A	W2	Plaster	Blue	None	N/A	N/A	N/A
1	1	Counselor's Office 100A	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Counselor's Office 100A	W3	Plaster	Blue	None	N/A	N/A	N/A
1	1	Counselor's Office 100A	W4	Plaster	Blue	None	N/A	N/A	N/A
1	1	Counselor's Office 100A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Counselor's Office 100A	Floor	Wood	Brown	Moisture Damage	N/A	N/A	N/A
1	1	Entrance/Waiting Area for Counselor's Office	W1	Plaster	Blue	None	N/A	N/A	N/A
1	1	Entrance/Waiting Area for Counselor's Office	W2	Plaster	Blue	None	N/A	N/A	N/A
1	1	Entrance/Waiting Area for Counselor's Office	W3	Plaster	Blue	None	N/A	N/A	N/A
1	1	Entrance/Waiting Area for Counselor's Office	W4	Plaster	Blue	None	N/A	N/A	N/A
1	1	Entrance/Waiting Area for Counselor's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Entrance/Waiting Area for Counselor's Office	Floor	Wood	Brown	Moisture Damage	N/A	N/A	N/A
1	1	Speech Office 100B	W1	Plaster	Blue	None	N/A	N/A	N/A
1	1	Speech Office 100B	W2	Plaster	Blue	None	N/A	N/A	N/A
1	1	Speech Office 100B	W3	Plaster	Blue	Cracking	6	1.23	Positive
1	1	Speech Office 100B	W4	Plaster	Blue	Cracking	15	1.3	Positive
1	1	Speech Office 100B	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Speech Office 100B	Floor	Wood	Brown	Moisture Damage	N/A	N/A	N/A
1	1	Counselor's Suite 100 Restroom	W1	Plaster	Blue	Chipping	1	1	Positive
1	1	Counselor's Suite 100 Restroom	W2	Plaster	Blue	Cracking	2	0.1	Negative
1	1	Counselor's Suite 100 Restroom	W3	Plaster	Blue	Flaking	15	1	Positive
1	1	Counselor's Suite 100 Restroom	W4	Plaster	Blue	Moisture Damage	6	1	Positive
1	1	Counselor's Suite 100 Restroom	Ceiling	Concrete	White	Chipping	3	0	Negative
1	1	Counselor's Suite 100 Restroom	Floor	Concrete	Brown	Friction	20	1	Positive
1	1	Dean's Office 101	W1	Plaster	Tan	Chipping	13	1	Positive
1	1	Dean's Office 101	W1	N/A	N/A	None	N/A	N/A	N/A
1	1	Dean's Office 101	W2	Plaster	Tan	Chipping	3	1	Positive
1	1	Dean's Office 101	W2	N/A	N/A	None	N/A	N/A	N/A
1	1	Dean's Office 101	W3	Plaster	Tan	Chipping	14	0.14	Negative

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Dean's Office 101	W4	Plaster	Tan	Chipping	10	1.001	Positive
1	1	Dean's Office 101	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Dean's Office 101	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	1	Dean's Office 101 Closet	W1	Plaster	Tan	None	N/A	N/A	N/A
1	1	Dean's Office 101 Closet	W2	Plaster	Tan	None	N/A	N/A	N/A
1	1	Dean's Office 101 Closet	W3	Plaster	Tan	None	N/A	N/A	N/A
1	1	Dean's Office 101 Closet	W4	Plaster	Tan	None	N/A	N/A	N/A
1	1	Dean's Office 101 Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Dean's Office 101 Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	Fire Tower	W1	Metal	Tan	None	N/A	N/A	N/A
1	1	Fire Tower	W2	Brick	Tan	Cracking	25	5	Positive
1	1	Fire Tower	W3	Metal	Tan	Cracking	5	4.2	Positive
1	1	Fire Tower	W4	Brick	Tan	Cracking	35	5	Positive
1	1	Fire Tower	Ceiling	Plaster	Tan	Chipping	40	0.3	Negative
1	1	Fire Tower	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Fire Tower	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	1	Hallway Closet adjacent to Classroom 103	W1	Plaster	Tan	Cracking	4	N/A	N/A
1	1	Hallway Closet adjacent to Classroom 103	W2	Plaster	Tan	None	N/A	N/A	N/A
1	1	Hallway Closet adjacent to Classroom 103	W3	Plaster	Tan	Cracking	3	N/A	N/A
1	1	Hallway Closet adjacent to Classroom 103	W4	Plaster	Tan	Alligatoring	2	N/A	N/A
1	1	Hallway Closet adjacent to Classroom 103	Ceiling	Plaster	Tan	Partially Inaccessible	2	N/A	N/A
1	1	Hallway Closet adjacent to Classroom 103	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	1	Classroom 103	W1	Plaster	Tan	Chipping	3	1	Positive
1	1	Classroom 103	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W2	Plaster	Tan	Chipping	15	1	Positive
1	1	Classroom 103	W3	Plaster	Tan	Chipping	24	1	Positive
1	1	Classroom 103	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	W4	Plaster	Tan	Chipping	4	1	Positive
1	1	Classroom 103	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	1	Classroom 103 Back Coat Closet	W1	Plaster	Tan	Chipping	10	5	Positive
1	1	Classroom 103 Back Coat Closet	W2	Plaster	Tan	Chipping	35	5	Positive
1	1	Classroom 103 Back Coat Closet	W3	Plaster	Tan	Chipping	10	5	Positive
1	1	Classroom 103 Back Coat Closet	W4	Plaster	Tan	Chipping	15	5	Positive
1	1	Classroom 103 Back Coat Closet	Ceiling	Plaster	Tan	Flaking	7	N/A	N/A
1	1	Classroom 103 Back Coat Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	Classroom 103 Front Coat Closet	W1	Plaster	White	Cracking	4	5	Positive
1	1	Classroom 103 Front Coat Closet	W2	Plaster	White	Cracking	4	5	Positive
1	1	Classroom 103 Front Coat Closet	W3	Plaster	White	Cracking	6	5	Positive
1	1	Classroom 103 Front Coat Closet	W4	Plaster	White	Cracking	5	5	Positive
1	1	Classroom 103 Front Coat Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 103 Front Coat Closet	Floor	Wood	Brown	N/A	N/A	N/A	N/A
1	1	Hallway from Fire Tower to Classroom 101	W1	Metal	Grey	None	N/A	N/A	N/A
1	1	Hallway from Fire Tower to Classroom 101	W2	Plaster	Tan	Chipping	5	1	Positive
1	1	Hallway from Fire Tower to Classroom 101	W2	N/A	N/A	None	N/A	N/A	N/A
1	1	Hallway from Fire Tower to Classroom 101	W3	Plaster	Tan	N/A	N/A	N/A	N/A
1	1	Hallway from Fire Tower to Classroom 101	W4	Plaster	Tan	Chipping	6	1	Positive
1	1	Hallway from Fire Tower to Classroom 101	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Fire Tower to Classroom 101	Floor	Concrete	Grey	N/A	N/A	N/A	N/A

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	Primary Component XRF (positive/negative)
1	1	Stairwell between Office 101 and Classroom 102	W1	Metal	Grey	None	N/A	N/A	N/A
1	1	Stairwell between Office 101 and Classroom 102	W2	Plaster	Tan	Cracking	6	0.11	Negative
1	1	Stairwell between Office 101 and Classroom 102	W3	Plaster	Tan	Cracking	8	0.11	Negative
1	1	Stairwell between Office 101 and Classroom 102	W4	Plaster	Tan	Cracking	5	1	Positive
1	1	Stairwell between Office 101 and Classroom 102	W4	N/A	N/A	None	N/A	N/A	N/A
1	1	Stairwell between Office 101 and Classroom 102	Ceiling	Plaster	White	Flaking	1	0	Negative
1	1	Stairwell between Office 101 and Classroom 102	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	1	Classroom 102	W1	Plaster	White	Chipping	8	1	Positive
1	1	Classroom 102	W2	Plaster	White	Chipping	1	1	Positive
1	1	Classroom 102	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102	W3	Plaster	White	Chipping	25	1	Positive
1	1	Classroom 102	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102	W4	Plaster	White	Chipping	10	1	Positive
1	1	Classroom 102	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102	Floor	Wood	Brown	Chipping	N/A	N/A	N/A
1	1	Classroom 102 Coat Closet	W1	Plaster	White	Chipping	10	5	Positive
1	1	Classroom 102 Coat Closet	W2	Plaster	White	Cracking	3	5	Positive
1	1	Classroom 102 Coat Closet	W3	Plaster	White	Chipping	35	5	Positive
1	1	Classroom 102 Coat Closet	W4	Plaster	White	Chipping	10	5	Positive
1	1	Classroom 102 Coat Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 102 Coat Closet	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	Custodial Closet adjacent to Classroom 102	W1	Plaster	Tan	Chipping	2	5	Positive
1	1	Custodial Closet adjacent to Classroom 102	W2	Plaster	Tan	Flaking	2	5	Positive
1	1	Custodial Closet adjacent to Classroom 102	W3	Plaster	Tan	Flaking	10	4.7	Positive
1	1	Custodial Closet adjacent to Classroom 102	W4	Plaster	Tan	Cracking	3	5	Positive
1	1	Custodial Closet adjacent to Classroom 102	Ceiling	N/A	N/A	None	N/A	N/A	N/A
1	1	Custodial Closet adjacent to Classroom 102	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	1	Girl's Restroom	W1	Brick	Tan	None	N/A	N/A	N/A
1	1	Girl's Restroom	W2	Brick	Tan	None	N/A	N/A	N/A
1	1	Girl's Restroom	W3	Brick	Tan	None	N/A	N/A	N/A
1	1	Girl's Restroom	W4	Brick	Tan	None	N/A	N/A	N/A
1	1	Girl's Restroom	Ceiling	Plaster	Tan	Flaking	9	0.2	Negative
1	1	Girl's Restroom	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	1	Hallway Closet adjacent Girl's Restroom	W1	Plaster	Tan	None	N/A	N/A	N/A
1	1	Hallway Closet adjacent Girl's Restroom	W2	Plaster	Tan	None	N/A	N/A	N/A
1	1	Hallway Closet adjacent Girl's Restroom	W3	Plaster	Tan	None	N/A	N/A	N/A
1	1	Hallway Closet adjacent Girl's Restroom	W4	Plaster	Tan	N/A	12	1	Positive
1	1	Hallway Closet adjacent Girl's Restroom	Ceiling	N/A	N/A	None	N/A	N/A	N/A
1	1	Hallway Closet adjacent Girl's Restroom	Floor	Wood	Brown	None	N/A	N/A	N/A
1	1	Principal's Office	W1	Plaster	Tan	Chipping	10	0.1	Negative
1	1	Principal's Office	W1	N/A	N/A	None	N/A	N/A	N/A
1	1	Principal's Office	W2	Plaster	Tan	Chipping	9	0.1	Negative
1	1	Principal's Office	W3	Plaster	Tan	None	N/A	N/A	N/A
1	1	Principal's Office	W3	N/A	N/A	None	N/A	N/A	N/A

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Principal's Office	W4	Plaster	Tan	Chipping	24	0	Negative
1	1	Principal's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Principal's Office Restroom	W1	Plaster	Tan	Cracking	3	0.7	Positive
1	1	Principal's Office Restroom	W2	Plaster	Tan	Cracking	3	1	Positive
1	1	Principal's Office Restroom	W3	Plaster	Tan	None	N/A	N/A	N/A
1	1	Principal's Office Restroom	W3	N/A	N/A	None	N/A	N/A	N/A
1	1	Principal's Office Restroom	W4	Plaster	Tan	Cracking	15	1.8	Positive
1	1	Principal's Office Restroom	Ceiling	Plaster	Tan	None	N/A	N/A	N/A
1	1	Principal's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Principal's Office Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Office Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Office Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Office Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Office Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Principal's Office Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office	W1	Plaster	Tan	Chipping	7	0.4	Negative
1	1	Main Office	W2	Plaster	Tan	Cracking	4	0.5	Negative
1	1	Main Office	W3	Plaster	Tan	Cracking	3	0.1	Negative
1	1	Main Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office	W4	Plaster	Tan	Chipping	3	0.4	Negative
1	1	Main Office	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office Server Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Main Office Server Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Main Office Server Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Main Office Server Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Main Office Server Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Main Office Server Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office Closet adjacent to Server Room	W1	Plaster	Blue	Chipping	5	1	Positive
1	1	Main Office Closet adjacent to Server Room	W2	Plaster	Blue	Chipping	12	8.3	Positive
1	1	Main Office Closet adjacent to Server Room	W3	Plaster	Blue	Chipping	2	1.2	Positive
1	1	Main Office Closet adjacent to Server Room	W4	Plaster	Blue	Chipping	4	1.5	Positive
1	1	Main Office Closet adjacent to Server Room	Ceiling	Plaster	White	Flaking	16		No Access
1	1	Main Office Closet adjacent to Server Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Office Closet on Copy Room side	W1	Plaster	Blue	Cracking	3	7.7	Positive
1	1	Main Office Closet on Copy Room side	W2	Plaster	Blue	Chipping	2	4.9	Positive
1	1	Main Office Closet on Copy Room side	W3	Plaster	Blue	Chipping	1	5.1	Positive
1	1	Main Office Closet on Copy Room side	W4	Plaster	Blue	Chipping	3	10.3	Positive
1	1	Main Office Closet on Copy Room side	Ceiling	Plaster	White	None	N/A	N/A	N/A
1	1	Main Office Closet on Copy Room side	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	Copy Room 110	W1	Plaster	Tan	Chipping	2	0.1	Negative
1	1	Copy Room 110	W2	Plaster	Tan	Cracking	3	0.1	Negative
1	1	Copy Room 110	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Copy Room 110	W3	Plaster	Tan	Chipping	9	0.1	Negative
1	1	Copy Room 110	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Copy Room 110	W4	Plaster	Tan	Chipping	10	0.2	Negative
1	1	Copy Room 110	Ceiling	Plaster	Tan	Flaking	13	0.5	Negative
1	1	Copy Room 110	Floor	Wood	N/A	N/A	N/A	N/A	N/A

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Copy Room Restroom	W1	Plaster	Tan	None	N/A	N/A	N/A
1	1	Copy Room Restroom	W2	Plaster	Tan	Chipping	2	0.3	Negative
1	1	Copy Room Restroom	W3	Plaster	Tan	None	N/A	N/A	N/A
1	1	Copy Room Restroom	W4	Plaster	Tan	None	N/A	N/A	N/A
1	1	Copy Room Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Copy Room Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	Main Entrance	W1	Plaster	Tan	N/A	N/A	N/A	N/A
1	1	Main Entrance	W2	Plaster	Tan	Cracking	18	0.3	Negative
1	1	Main Entrance	W3	Plaster	Tan	Moisture Damage	10	0.2	Negative
1	1	Main Entrance	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Main Entrance	W4	Plaster	Tan	Chipping	15	0.1	Negative
1	1	Main Entrance	Ceiling	Plaster	White	Flaking	35	0.4	Negative
1	1	Main Entrance	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	1	Nurse's Office	W1	Plaster	Yellow	None	N/A	N/A	N/A
1	1	Nurse's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Office	W2	Plaster	Yellow	None	N/A	N/A	N/A
1	1	Nurse's Office	W3	Plaster	Yellow	None	N/A	N/A	N/A
1	1	Nurse's Office	W4	Plaster	Yellow	None	N/A	N/A	N/A
1	1	Nurse's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Office	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Office Restroom	W1	Plaster	White	None	N/A	N/A	N/A
1	1	Nurse's Office Restroom	W2	Plaster	White	None	N/A	N/A	N/A
1	1	Nurse's Office Restroom	W3	Plaster	White	None	N/A	N/A	N/A
1	1	Nurse's Office Restroom	W4	Plaster	White	None	N/A	N/A	N/A
1	1	Nurse's Office Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Nurse's Office Restroom	Floor	Concrete	Grey	Friction	6	0.3	Negative
1	1	Classroom 104	W1	Plaster	Tan	Cracking	15	0	Negative
1	1	Classroom 104	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	W2	Plaster	Tan	Cracking	3	0.1	Negative
1	1	Classroom 104	W3	Plaster	Tan	Chipping	35	0.1	Negative
1	1	Classroom 104	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	W4	Plaster	Tan	Chipping	10	0	Negative
1	1	Classroom 104	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104 Coat Closet	W1	Plaster	White	None	N/A	N/A	N/A
1	1	Classroom 104 Coat Closet	W2	Plaster	White	None	N/A	N/A	N/A
1	1	Classroom 104 Coat Closet	W3	Plaster	White	Chipping	2	13.7	Positive
1	1	Classroom 104 Coat Closet	W4	Plaster	White	Chipping	3	16.8	Positive
1	1	Classroom 104 Coat Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 104 Coat Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Restroom	W1	Concrete	White	None	N/A	N/A	N/A
1	1	Boy's Restroom	W2	Concrete	White	Moisture Damage	16	0.1	Negative
1	1	Boy's Restroom	W3	Concrete	White	None	N/A	N/A	N/A
1	1	Boy's Restroom	W4	Concrete	White	None	N/A	N/A	N/A
1	1	Boy's Restroom	Ceiling	Concrete	White	Moisture Damage	30	2	Positive
1	1	Boy's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Boy's Restroom	Floor	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	N/A	N/A
1	1	Custodial Closet adjacent to Classroom 105	W1	Plaster	Yellow	Chipping	20	8.3	Positive
1	1	Custodial Closet adjacent to Classroom 105	W2	Plaster	Yellow	Chipping	50	7.7	Positive
1	1	Custodial Closet adjacent to Classroom 105	W3	Plaster	Yellow	Chipping	50	0	Negative
1	1	Custodial Closet adjacent to Classroom 105	W4	Plaster	Yellow	Chipping	50	10.5	Positive
1	1	Custodial Closet adjacent to Classroom 105	Ceiling	Plaster	Yellow	Chipping	18	4.5	Positive
1	1	Custodial Closet adjacent to Classroom 105	Floor	Concrete	Grey	Friction	15	0.4	Negative
1	1	Classroom 105	W1	Plaster	Blue	None	0	N/A	N/A
1	1	Classroom 105	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	W2	Plaster	Blue	Chipping	7	0.1	Negative
1	1	Classroom 105	W3	Plaster	Blue	Chipping	12	0.1	Negative
1	1	Classroom 105	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	W4	Plaster	Blue	Chipping	5	0	Negative
1	1	Classroom 105	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105 Restroom	W1	Plaster	White	Alligatoring	5	16.8	Positive
1	1	Classroom 105 Restroom	W2	Plaster	White	Chipping	20	11.9	Positive
1	1	Classroom 105 Restroom	W3	Plaster	White	None	N/A	N/A	N/A
1	1	Classroom 105 Restroom	W4	Plaster	White	Cracking	30	12.8	Positive
1	1	Classroom 105 Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105 Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105 Coat Closet	W1	Plaster	White	Alligatoring	4	17.3	Positive
1	1	Classroom 105 Coat Closet	W2	Plaster	White	Moisture Damage	20	6.3	Positive
1	1	Classroom 105 Coat Closet	W3	Plaster	White	Cracking	60	11.6	Positive
1	1	Classroom 105 Coat Closet	W4	Plaster	White	Partially Inaccessible	0	N/A	N/A
1	1	Classroom 105 Coat Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 105 Coat Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell between Classrooms 105 and 106	W1	Metal	Grey	None	N/A	N/A	N/A
1	1	Stairwell between Classrooms 105 and 106	W2	Plaster	Tan	Cracking	20	N/A	N/A
1	1	Stairwell between Classrooms 105 and 106	W3	Plaster	Tan	Flaking	5	0	Negative
1	1	Stairwell between Classrooms 105 and 106	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell between Classrooms 105 and 106	W4	Plaster	Tan	Flaking	26	0.1	Negative
1	1	Stairwell between Classrooms 105 and 106	Ceiling	Plaster	White	Flaking	2	0.2	Negative
1	1	Stairwell between Classrooms 105 and 106	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	1	Hallway from Classrooms 102 to 105	W1	Metal	Grey	None	N/A	N/A	N/A
1	1	Hallway from Classrooms 102 to 105	W2	Plaster	Tan	Chipping	10	4.9	Positive
1	1	Hallway from Classrooms 102 to 105	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 102 to 105	W3	Metal	Grey	None	N/A	N/A	N/A
1	1	Hallway from Classrooms 102 to 105	W4	Plaster	Tan	Chipping	11	0.1	Negative
1	1	Hallway from Classrooms 102 to 105	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 102 to 105	Floor	Concrete	Gray	None	N/A	N/A	N/A
1	1	Classroom 106	W1	Plaster	Tan	Chipping	8	0.1	Negative
1	1	Classroom 106	W2	Plaster	Tan	Cracking	7	0.3	Negative
1	1	Classroom 106	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	W3	Plaster	Tan	Chipping	15	0	Negative
1	1	Classroom 106	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	W4	Plaster	Tan	Chipping	6	0.1	Negative

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	Primary Component XRF (positive/negative)
1	1	Classroom 106	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 106 Coat Closet	W1	Plaster	Tan	Chipping	2	21.6	Positive
1	1	Classroom 106 Coat Closet	W2	Plaster	Tan	Chipping	4	17.1	Positive
1	1	Classroom 106 Coat Closet	W3	Plaster	Tan	Cracking	7	17.5	Positive
1	1	Classroom 106 Coat Closet	W4	Plaster	Tan	Partially Inaccessible	N/A	N/A	N/A
1	1	Classroom 106 Coat Closet	Ceiling	N/A	N/A	None	N/A	N/A	N/A
1	1	Classroom 106 Coat Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107	W1	Plaster	Blue	Chipping	2	0.1	Negative
1	1	Classroom 107	W2	Wood	Brown	None	N/A	N/A	N/A
1	1	Classroom 107	W3	Plaster	Blue	Moisture Damage	12	0.5	Negative
1	1	Classroom 107	W4	Plaster	Blue	Moisture Damage	15	0.2	Negative
1	1	Classroom 107	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 107 Restroom	W1	Plaster	Tan	Cracking	4	0.9	Positive
1	1	Classroom 107 Restroom	W2	Plaster	Tan	Moisture Damage	12	0.5	Negative
1	1	Classroom 107 Restroom	W3	Plaster	Tan	Cracking	5	0.2	Negative
1	1	Classroom 107 Restroom	W4	Plaster	Tan	None	0	0.3	Negative
1	1	Classroom 107 Restroom	Ceiling	Plaster	Tan	Flaking	12	0	Negative
1	1	Classroom 107 Restroom	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	1	Classroom 107 Coat Closet	W1	Plaster	Tan	Chipping	10	10.2	Positive
1	1	Classroom 107 Coat Closet	W2	Plaster	Tan	Chipping	3	16.6	Positive
1	1	Classroom 107 Coat Closet	W3	Plaster	Tan	Partially Inaccessible	4	15.3	Positive
1	1	Classroom 107 Coat Closet	W4	Plaster	Tan	Cracking	8	14.8	Positive
1	1	Classroom 107 Coat Closet	Ceiling	Plaster	N/A	Chipping	3		No Access
1	1	Classroom 107 Coat Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108	W1	Plaster	Pink	Chipping	3	6	Positive
1	1	Classroom 108	W2	Plaster	Pink	Chipping	1	0.3	Negative
1	1	Classroom 108	W3	Plaster	Pink	Chipping	12	0.2	Negative
1	1	Classroom 108	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108	W4	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108 Coat Closet	W1	Plaster	White	Cracking	7	16.2	Positive
1	1	Classroom 108 Coat Closet	W2	Concrete	White	None	0	20.1	Positive
1	1	Classroom 108 Coat Closet	W3	Plaster	White	Partially Inaccessible	24	0.1	Negative
1	1	Classroom 108 Coat Closet	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108 Coat Closet	W4	Plaster	White	Cracking	12	23.7	Positive
1	1	Classroom 108 Coat Closet	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108 Coat Closet	Ceiling	Plaster	White	None	N/A	N/A	N/A
1	1	Classroom 108 Coat Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 108 Restroom	W1	Plaster	White	Chipping	6	3.1	Positive
1	1	Classroom 108 Restroom	W2	Plaster	White	Cracking	9	0.2	Negative
1	1	Classroom 108 Restroom	W3	Plaster	White	Cracking	28	0.7	Positive

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Classroom 108 Restroom	W4	Concrete	White	Chipping	15	16.6	Positive
1	1	Classroom 108 Restroom	Ceiling	Plaster	White	None	N/A	N/A	N/A
1	1	Classroom 108 Restroom	Floor	Concrete	Grey	Friction	16	0.2	Negative
1	1	Classroom 109	W1	Plaster	White	Cracking	3	4.8	Positive
1	1	Classroom 109	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 109	W2	Plaster	White	Chipping	13	0.4	Negative
1	1	Classroom 109	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 109	W3	Plaster	White	Chipping	5	0.2	Negative
1	1	Classroom 109	W4	Plaster	White	None	N/A	N/A	N/A
1	1	Classroom 109	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 109	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 109 Closet on windows side	W1	No Access	White	No Access	N/A	N/A	N/A
1	1	Classroom 109 Closet on windows side	W2	No Access	White	No Access	No Access	No Access	No Access
1	1	Classroom 109 Closet on windows side	W3	No Access	White	No Access	No Access	No Access	No Access
1	1	Classroom 109 Closet on windows side	W4	No Access	White	No Access	No Access	No Access	No Access
1	1	Classroom 109 Closet on windows side	Ceiling	No Access	No Access	N/A	No Access	No Access	No Access
1	1	Classroom 109 Closet on windows side	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Classroom 109 Closet adjacent to Classroom 108	W1	Plaster	White	None	N/A	N/A	N/A
1	1	Classroom 109 Closet adjacent to Classroom 108	W2	Plaster	White	Chipping	2	17.2	Positive
1	1	Classroom 109 Closet adjacent to Classroom 108	W3	Plaster	White	None	N/A	N/A	N/A
1	1	Classroom 109 Closet adjacent to Classroom 108	W4	Plaster	White	None	N/A	N/A	N/A
1	1	Classroom 109 Closet adjacent to Classroom 108	Ceiling	Concrete	White	None	N/A	N/A	N/A
1	1	Classroom 109 Closet adjacent to Classroom 108	Floor	Concrete	White	None	N/A	N/A	N/A
1	BS	Stairwell between Boy's and Girl's Restrooms	W1	Metal	Grey	None	N/A	N/A	N/A
1	BS	Stairwell between Boy's and Girl's Restrooms	W2	Plaster	Tan	Cracking	30	0.1	Negative
1	BS	Stairwell between Boy's and Girl's Restrooms	W3	Plaster	Tan	Chipping	24	0.5	Negative
1	BS	Stairwell between Boy's and Girl's Restrooms	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Stairwell between Boy's and Girl's Restrooms	W4	Plaster	Tan	Chipping	48	0.3	Negative
1	BS	Stairwell between Boy's and Girl's Restrooms	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Stairwell between Boy's and Girl's Restrooms	Ceiling	Plaster	White	Cracking	6		No Access
1	BS	Stairwell between Boy's and Girl's Restrooms	Floor	Concrete	N/A	None	N/A	N/A	N/A
1	BS	Boy's Restroom	W1	Concrete	White	Moisture Damage	5	0	Negative
1	BS	Boy's Restroom	W2	Concrete	White	Moisture Damage	2	0.1	Negative
1	BS	Boy's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Boy's Restroom	W3	Concrete	White	None	N/A	N/A	N/A
1	BS	Boy's Restroom	W4	Concrete	White	None	N/A	N/A	N/A
1	BS	Boy's Restroom	Ceiling	Plaster	White	Chipping	75	6.6	Positive
1	BS	Boy's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Boy's Restroom	Floor	Concrete	White	None	N/A	N/A	N/A
1	BS	Boy's Restroom Custodial Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Boy's Restroom Custodial Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Boy's Restroom Custodial Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Boy's Restroom Custodial Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	BS	Boy's Restroom Custodial Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Boy's Restroom Custodial Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Hallway Closet adjacent to Cafeteria on Restroom side	W1	Concrete	White	Chipping	2	13.3	Positive
1	BS	Hallway Closet adjacent to Cafeteria on Restroom side	W1	Brick	White	Flaking	7	1.2	Positive
1	BS	Hallway Closet adjacent to Cafeteria on Restroom side	W2	Concrete	White	Cracking	4	19.2	Positive
1	BS	Hallway Closet adjacent to Cafeteria on Restroom side	W3	Concrete	White	Cracking	24	17.9	Positive
1	BS	Hallway Closet adjacent to Cafeteria on Restroom side	W4	Concrete	White	Cracking	5	10.5	Positive
1	BS	Hallway Closet adjacent to Cafeteria on Restroom side	Ceiling	Plaster	White	Flaking	22	8.8	Positive
1	BS	Hallway from Kitchen to Boy's Restroom	W1	Brick	White	Chipping	4	0.9	Positive
1	BS	Hallway from Kitchen to Boy's Restroom	W2	Brick	White	Cracking	9	1.2	Positive
1	BS	Hallway from Kitchen to Boy's Restroom	W3	Brick	White	Chipping	3	0.7	Positive
1	BS	Hallway from Kitchen to Boy's Restroom	W4	Brick	White	Chipping	18	0.8	Positive
1	BS	Hallway from Kitchen to Boy's Restroom	Ceiling	Concrete	White	Chipping	24		No Access
1	BS	Hallway from Kitchen to Boy's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Hallway from Kitchen to Boy's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	BS	Girl's Restroom	W1	Concrete	Tan	None	N/A	N/A	N/A
1	BS	Girl's Restroom	W2	Concrete	Tan	None	N/A	N/A	N/A
1	BS	Girl's Restroom	W3	Concrete	Tan	None	N/A	N/A	N/A
1	BS	Girl's Restroom	W4	Concrete	Tan	None	N/A	N/A	N/A
1	BS	Girl's Restroom	Ceiling	Concrete	Tan	Chipping	75	3.6	Positive
1	BS	Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Girl's Restroom	Floor	Concrete	Tan	None	N/A	N/A	N/A
1	BS	Girl's Restroom Custodial Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Girl's Restroom Custodial Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Girl's Restroom Custodial Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Girl's Restroom Custodial Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Girl's Restroom Custodial Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Girl's Restroom Custodial Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	BS	Kitchen	W1	Brick	White	None	N/A	N/A	N/A
1	BS	Kitchen	W2	Brick	White	Chipping	5	3.3	Positive
1	BS	Kitchen	W3	Brick	White	Chipping	8	4.5	Positive
1	BS	Kitchen	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Kitchen	W4	Brick	White	None	N/A	N/A	N/A
1	BS	Kitchen	Ceiling	Concrete	White	Moisture Damage	36	16.7	Positive
1	BS	Kitchen	Floor	Concrete	N/A	Partially Inaccessible	N/A	N/A	N/A
1	BS	Kitchen	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Kitchen Closet	W1	Brick	White	Chipping	6	16	Positive
1	BS	Kitchen Closet	W2	Brick	White	Partially Inaccessible	3	8.5	Positive
1	BS	Kitchen Closet	W3	Brick	White	Partially Inaccessible	6	11.3	Positive
1	BS	Kitchen Closet	W4	Brick	White	Partially Inaccessible	2	10.3	Positive

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	BS	Kitchen Closet	Ceiling	Concrete	White	None	N/A	N/A	N/A
1	BS	Kitchen Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	BS	Cafetorium	W1	Concrete	White	None	N/A	N/A	N/A
1	BS	Cafetorium	W2	Concrete	White	Cracking	30	4	Positive
1	BS	Cafetorium	W3	Concrete	White	Cracking	3	6.7	Positive
1	BS	Cafetorium	W4	Concrete	White	Chipping	3	10.4	Positive
1	BS	Cafetorium	Ceiling	Concrete	White	Flaking	100	8.8	Positive
1	BS	Cafetorium	Floor	Concrete	White	N/A	N/A	N/A	N/A
1	BS	Cafeteria Small Closet opposite Stage	W1	Brick	White	Chipping	50	0.9	Positive
1	BS	Cafeteria Small Closet opposite Stage	W2	Brick	White	Chipping	36	6.3	Positive
1	BS	Cafeteria Small Closet opposite Stage	W3	Brick	White	Chipping	54	9.7	Positive
1	BS	Cafeteria Small Closet opposite Stage	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Cafeteria Small Closet opposite Stage	W4	Brick	White	Chipping	40	8.7	Positive
1	BS	Cafeteria Small Closet opposite Stage	Ceiling	Concrete	White	Chipping	70	6.4	Positive
1	BS	Cafeteria Small Closet opposite Stage	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	BS	Cafeteria Large Closet behind Stage	W1	Brick	White	None	N/A	N/A	N/A
1	BS	Cafeteria Large Closet behind Stage	W2	Brick	White	Chipping	50	10.9	Positive
1	BS	Cafeteria Large Closet behind Stage	W3	Brick	White	Chipping	70	6.2	Positive
1	BS	Cafeteria Large Closet behind Stage	W4	Brick	White	None	N/A	N/A	N/A
1	BS	Cafeteria Large Closet behind Stage	Ceiling	Brick	White	Chipping	80	10.3	Positive
1	BS	Cafeteria Large Closet behind Stage	Floor	Concrete	N/A	Partially Inaccessible	N/A	N/A	N/A
1	BS	Cafeteria Large Closet by Stage	W1	Brick	White	Chipping	2	9.8	Positive
1	BS	Cafeteria Large Closet by Stage	W2	Brick	White	Chipping	22	5.8	Positive
1	BS	Cafeteria Large Closet by Stage	W3	Brick	White	None	N/A	N/A	N/A
1	BS	Cafeteria Large Closet by Stage	W4	Brick	White	Chipping	10	7.1	Positive
1	BS	Cafeteria Large Closet by Stage	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Cafeteria Large Closet by Stage	Ceiling	Concrete	White	Chipping	50	3.4	Positive
1	BS	Cafeteria Large Closet by Stage	Floor	Concrete	Gray	N/A	N/A	N/A	N/A
1	BS	Hallway from Cafeteria to Custodial Storage Room	W1	Brick	White	Chipping	6	0.5	Negative
1	BS	Hallway from Cafeteria to Custodial Storage Room	W2	Brick	White	Chipping	7	0.8	Positive
1	BS	Hallway from Cafeteria to Custodial Storage Room	W3	Brick	White	None	7	1.2	Positive
1	BS	Hallway from Cafeteria to Custodial Storage Room	W4	Brick	White	Chipping	8	0.9	Positive
1	BS	Hallway from Cafeteria to Custodial Storage Room	Ceiling	Concrete	White	Chipping	36	6.4	Positive
1	BS	Hallway from Cafeteria to Custodial Storage Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Classroom 003	W1	Plaster	Tan	Moisture Damage	3	11.2	Positive
1	BS	Classroom 003	W2	Plaster	Tan	None	N/A	N/A	N/A
1	BS	Classroom 003	W3	Plaster	Tan	Cracking	8	19.9	Positive
1	BS	Classroom 003	W4	Plaster	Tan	Moisture Damage	24	13.3	Positive
1	BS	Classroom 003	W4	Sheetrock	Tan	Cracking	8	10.8	Positive
1	BS	Classroom 003	Ceiling	Sheetrock	Tan	Chipping	4	10.2	Positive
1	BS	Classroom 003	Floor	Concrete	Tan	Cracking	5	0.4	Positive
1	BS	Classroom 003 Closet opposite entrance door	W1	Plaster	Tan	Chipping	32	10.5	Positive

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm <sup>2</sup> )	Primary Component XRF (positive/negative)
1	BS	Classroom 003 Closet opposite entrance door	W1	Sheetrock	Tan	Chipping	5	9.8	Positive
1	BS	Classroom 003 Closet opposite entrance door	W2	Plaster	Tan	Cracking	4	1.2	Positive
1	BS	Classroom 003 Closet opposite entrance door	W3	Plaster	Tan	Moisture Damage	30	11.8	Positive
1	BS	Classroom 003 Closet opposite entrance door	W3	Sheetrock	Tan	Chipping	10	11.2	Positive
1	BS	Classroom 003 Closet opposite entrance door	W4	Plaster	Tan	Cracking	30	15.4	Positive
1	BS	Classroom 003 Closet opposite entrance door	Ceiling	Plaster	Tan	Flaking	4	10.4	Positive
1	BS	Classroom 003 Closet opposite entrance door	Floor	Plaster	Tan	Cracking	3	0.5	Negative
1	BS	Classroom 003 Closet on exterior wall	W1	Plaster	Tan	Chipping	80	3.4	Positive
1	BS	Classroom 003 Closet on exterior wall	W2	Plaster	Tan	Chipping	60	4.8	Positive
1	BS	Classroom 003 Closet on exterior wall	W3	Plaster	Tan	Chipping	80	0.3	Negative
1	BS	Classroom 003 Closet on exterior wall	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Classroom 003 Closet on exterior wall	W4	Plaster	Tan	Flaking	50	0.5	Negative
1	BS	Classroom 003 Closet on exterior wall	Ceiling	Concrete	Tan	Chipping	50	7.4	Positive
1	BS	Classroom 003 Closet on exterior wall	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Stairwell adjacent to Classroom 003	W1	Plaster	Tan	N/A	N/A	N/A	N/A
1	BS	Stairwell adjacent to Classroom 003	W2	Plaster	Tan	N/A	N/A	N/A	N/A
1	BS	Stairwell adjacent to Classroom 003	W3	Plaster	Tan	N/A	N/A	N/A	N/A
1	BS	Stairwell adjacent to Classroom 003	W4	Plaster	Tan	Chipping	12	0.4	Negative
1	BS	Stairwell adjacent to Classroom 003	Ceiling	Concrete	White	None	N/A	N/A	N/A
1	BS	Stairwell adjacent to Classroom 003	Floor	Concrete	Grey	N/A	N/A	N/A	N/A
1	BS	BMT Office	W1	Brick	White	Chipping	3	6.8	Positive
1	BS	BMT Office	W2	Brick	White	Moisture Damage	4	0.2	Negative
1	BS	BMT Office	W3	Brick	White	None	N/A	N/A	N/A
1	BS	BMT Office	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	BMT Office	W4	Brick	White	None	N/A	N/A	N/A
1	BS	BMT Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	BMT Office	Floor	Concrete	Gray	Friction	8	0	Negative
1	BS	BMT Office Closet	W1	Brick	Yellow	Chipping	9	1.5	Positive
1	BS	BMT Office Closet	W2	Brick	Yellow	Chipping	15	0	Negative
1	BS	BMT Office Closet	W3	Brick	Yellow	Partially Inaccessible	4	0.7	Positive
1	BS	BMT Office Closet	W4	Brick	Yellow	Cracking	7	0.7	Positive
1	BS	BMT Office Closet	Ceiling	Brick	Yellow	Flaking	34		No Access
1	BS	BMT Office Closet	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	BS	Custodial Storage Room 001	W1	Brick	White	Chipping	3	8.6	Positive
1	BS	Custodial Storage Room 001	W2	Brick	White	Moisture Damage	5	0.2	Negative
1	BS	Custodial Storage Room 001	W3	Brick	White	Moisture Damage	25	12.4	Positive
1	BS	Custodial Storage Room 001	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Custodial Storage Room 001	W4	Brick	White	None	N/A	N/A	N/A
1	BS	Custodial Storage Room 001	Ceiling	Plaster	White	Partially Inaccessible	10	N/A	N/A
1	BS	Custodial Storage Room 001	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Hallway Closet across from Custodial Storage Room	W1	Metal	Tan	Chipping	18	2.1	Positive
1	BS	Hallway Closet across from Custodial Storage Room	W2	Plaster	Tan	Chipping	5	2	Positive

## Lead Safe Certification for James Ludlow School

Name of Inspector: Adam Prefer

Inspection Dates: 6-10 through 6-14-19

Inspection Company: Batta Environmental

ULCS# 5340

Element	Floor	On-Site Room Name	Primary Component (see terms)	Substrate Material	Color	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	BS	Hallway Closet across from Custodial Storage Room	W3	Plaster	Tan	Chipping	10	1.7	Positive
1	BS	Hallway Closet across from Custodial Storage Room	W4	Plaster	Tan	Chipping	6	1	Positive
1	BS	Hallway Closet across from Custodial Storage Room	Ceiling	Plaster	Tan	Flaking	60	1.1	Positive
1	BS	Boiler Room	W1	Brick	White	Chipping	800	2	Positive
1	BS	Boiler Room	W2	Brick	White	Chipping	500	0.8	Positive
1	BS	Boiler Room	W3	Brick	White	Chipping	600	0.1	Negative
1	BS	Boiler Room	W4	Brick	White	Chipping	400	22.4	Positive
1	BS	Boiler Room	Ceiling	Concrete	White	Flaking	1500	0.1	Negative
1	BS	Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Boiler Room Restroom	W1	Brick	White	Chipping	30	2	Positive
1	BS	Boiler Room Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Boiler Room Restroom	W2	Brick	White	Chipping	30	2	Positive
1	BS	Boiler Room Restroom	W3	Brick	White	Chipping	20	1.8	Positive
1	BS	Boiler Room Restroom	W4	Brick	White	Chipping	30	2.4	Positive
1	BS	Fan Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Boiler Room Restroom	Ceiling	Concrete	White	Flaking	50	1.3	Positive
1	BS	Boiler Room Restroom	Floor	Concrete	Gray	None	N/A	N/A	N/A
1	BS	Fan Room	W1	Brick	White	Chipping	400	0.4	Negative
1	BS	Fan Room	W2	Brick	White	Chipping	800	0.4	Negative
1	BS	Fan Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	BS	Fan Room	W3	Brick	White	Chipping	200	0.4	Negative
1	BS	Fan Room	W4	Brick	White	Chipping	200	3.9	Positive
1	BS	Fan Room	Ceiling	Concrete	White	Cracking	600		No Access
1	BS	Fan Room	Floor	Concrete	Grey	None	N/A	N/A	N/A
1	3	Classroom 303 Front Coat Closet	W4	Plaster	Tan	Cracking	1	13.1	Positive
1	3	Classroom 310 Coat Closet	W4	Concrete	White	Flaking	10	4.1	Positive
1	2	Hallway Closet adjacent to Classroom 203	Floor	Concrete	Grey	Cracking	5	0.3	Negative
1	2	Stairwell between Classrooms 201 and 202	Floor	Concrete	Grey	Cracking	3	0.5	Negative
1	2	IMC 206	Floor	Concrete	Gray	Cracking	2	0.4	Negative
1	2	IMC 206 Closet on Classroom 204 side	Ceiling	sheetock	gray	Cracking	5	1.9	Positive
1	2	Hallway from Classroom 202 to 207	Floor	Concrete	Grey	Cracking	2	0.2	Negative
1	2	Classroom 208	Floor	Wood	Brown	Friction	5	0.3	Negative
1	1	Hallway Closet adjacent to Classroom 103	Ceiling	Plaster	Tan	Cracking	2	1.2	Positive
1	1	Boy's Restroom	Floor	Cracking	tan	Cracking	4	0.4	negative
1	1	Classroom 105 Coat Closet	W4	Concrete	White	Flaking	5	7.2	Positive
1	1	Classroom 106 Coat Closet	W4	Plaster	Tan	Flaking	6	9.9	Positive
1	1	Main Office Closet adjacent to Server Room	Ceiling	Plaster	White	Flaking	16	9.8	Positive
1	1	Classroom 107 Coat Closet	Ceiling	Plaster	White	Chipping	3	4.2	Positive
1	BS	Kitchen	Floor	Concrete	Tan	Cracking	5	0.5	negative
1	BS	Stairwell between Boy's and Girl's Restrooms	Ceiling	Plaster	White	Cracking	10	5	Positive
1	BS	Hallway Closet adjacent to Cafeteria on Restroom side	Ceiling	Plaster	White	Flaking	22	8.8	Positive
1	BS	Hallway from Kitchen to Boy's Restroom	Ceiling	Concrete	Tan	Chipping	24	2.2	Positive
1	BS	Classroom 003	Floor	Concrete	White	Cracking	5	0.2	Negative
1	BS	Classroom 003 Closet opposite entrance door	Floor	Plaster	N/A	Cracking	4	0.1	Negative
1	1	Classroom 109 Closet on windows side	W1	Concrete	White	Flaking	4	9.1	Positive
1	1	Classroom 109 Closet on windows side	W2	Concrete	White	Flaking	5	10.2	Positive









