



City of Philadelphia - Department of Public Health
 Air Management Services, 2nd Fl. Asbestos Control Unit
 321 University Ave. Philadelphia, PA 19104

Office Use Only

Date Received L&I:

Date Received AMS:

Date Inspected

Inspector No.

Asbestos Inspection Report

1. Name of Building / Property: _____ Address _____

2. Name of Building / Property Owner: _____ Address _____ Phone No. _____

3. Name of Philadelphia Certified Investigator: _____ Certification No. _____ Contact Information / Email / Phone No. _____

L&I Commercial Activity No. (Former Business Privilege License No.) _____ Business Tax ID No. _____

4. Name of Philadelphia Licensed Laboratory: _____ License No. _____ Phone No. _____

5. Scope of Work: (Insert or attach a complete description of the portion of the subject property inspected and the anticipated work that will result in the disturbance of the identified Asbestos Containing Materials (ACMs) (e.g. demolition, asbestos abatement, and / or renovation activities.)

6. Property has been declared to be in imminent danger (ID) of failure or collapse by the City of Philadelphia Department of Licenses & Inspections. Attached is a copy of the L&I Notice of Violation declaring the property I.D. ****Note: INVESTIGATOR MUST BE ON SITE DURING DEMOLITION!**

7. (ACMs) identified? Yes (List Below) No (explain)

8. Suspected ACM's sampled? Yes (attached are copies of the laboratory chain of custody and bulk sample results.) No (Why?)

9. List all identified ACM's located in the planned renovation/demolition areas. Damaged ACM must be listed and then repaired or removed prior to renovation. You (Investigator) must label all ACM that may be left in the work area. (Attached are add'tl sheets)

Location	Description	Type (Code 1)	Amount		Condition (Code 2)	Action (Code 3)
			Square	Linear		

Code 1

FRI - Friable
 NF1 - Non-Friable, Cat. 1
 NF2 - Non-Friable, Cat. 2

Code 2

DD - Deteriorated or Delaminated
 ND - Non-Damaged

Code 3

REM - Removal necessary prior to Demo/Reno
 NRN - No removal necessary, label ACM
 REP - Repair & Label ACM, removal not necessary

10. I hereby certify that the foregoing statements are true and the information contained in this report is true. This certification is made subject to the penalties set forth in 18 PA. C.S. S4904 relating to unsworn falsification to authorities. Furthermore I certify that the inspection, sampling, and labeling requirements of section X of the Asbestos Control Regulation (ACR) have been met. The building owner has been notified of the ACR requirements and given a copy of this report. If the inspection has revealed ACM which will be disturbed by the proposed work or if it has revealed ACM in bad condition, the building owner has been notified to remove or repair the ACM in accordance with the ACR prior to renovation or demolition activity.

11. Signature of Certified Asbestos Investigator:  Date: _____ Signature of Building Owner: _____ Date: _____

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance							
		Robert Morris Elementary School (2390)	___ Three- Year Reinspection IX							
		Year Built: 1964	__X__ AIR/EIE							
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity							
		Prepared by: Bernard J. Bryson	___ Bulk Sampling Event							
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
F l o o r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
-	-	Throughout Classrooms 100, 101, 200, 203, 204, 213, 216 and 218	Wood Entry Doors	Non Suspect ACM	x	Q/U	EA	x	x	
-	-	Throughout Classrooms 100, 101, 200, 203, 204, 213, 216 and 218	Wood Closet and Restroom Doors	Non Suspect ACM	x	Q/U	EA	x	x	
1	110	Gym	Ceiling Tile 2' x 4'	NAD	x	680	SF	x	x	
1	110	Gym	Concrete Block Wall	Non Suspect ACM	x	3,904	SF	x	x	
1	110	Gym	12" x 12" Floor Tile and Mastic	Assumed	NF1	3,672	SF	ND	NRN	
1	110	Gym	Radiator Insulation	Assumed	FRI	66	SF	ND	NRN	
1	110	Gym	Metal Ceiling Tile 2' x 4'	Confirmed	FRI	3,500	SF	ND	NRN	
1	E1	Elevator	12" x 12" Floor Tile and Mastic	Assumed	NF1	99	SF	ND	NRN	
1	111	Fan Room between Stage and Gym	Fiberglass Pipe Insulation	Non Suspect ACM	x	50	LF	x	x	
1	111	Fan Room between Stage and Gym	Plaster Ceiling	NAD	x	300	SF	x	x	
1	111	Fan Room between Stage and Gym	Concrete Block Wall	Non Suspect ACM	x	1,200	SF	x	x	
1	111	Fan Room between Stage and Gym	Cement Floor	Non Suspect ACM	x	300	SF	x	x	
1	111	Fan Room between Stage and Gym	Vinyl Vibration Damper Cloth	Non Suspect ACM	x	20	SF	x	x	
1	S14	Stairwell behind Stage to Fan Room	Plaster Ceiling	NAD	x	72	SF	x	x	
1	S14	Stairwell behind Stage to Fan Room	Concrete Block Wall	Non Suspect ACM	x	308	SF	x	x	
1	S14	Stairwell behind Stage to Fan Room	Cement Floor	Non Suspect ACM	x	72	SF	x	x	
1	110D (lower level)	Storage below Fan Room in Gymnasium	Plaster Ceiling	NAD	x	288	SF	x	x	
1	110D (lower level)	Storage below Fan Room in Gymnasium	Concrete Block Wall	Non Suspect ACM	x	544	SF	x	x	

		School District of Philadelphia		Survey Type							Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9		___ 6 Month Surveillance							
		Robert Morris Elementary School (2390)		___ Three- Year Reinspection IX							
		Year Built: 1964		__X__ AIR/EIE							
		2600 W. Thompson Street, Philadelphia, PA 19121		__X__ Asbestos Abatement Activity							
		Prepared by: Bernard J. Bryson		___ Bulk Sampling Event							
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project		Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
<i>F l o o r</i>	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes	
1	110D (lower level)	Storage below Fan Room in Gymnasium	12" x 12" Floor Tile and Mastic	Assumed	NF1	288	SF	ND	NRN		
1	110D (upper level)	Fan Room (Upper Level) in Gymnasium	Fiberglass Pipe Insulation	Non Suspect ACM	x	80	LF	x	x		
1	110D (upper level)	Fan Room (Upper Level) in Gymnasium	Concrete Block Wall	Non Suspect ACM	x	840	SF	x	x		
1	110D (upper level)	Fan Room (Upper Level) in Gymnasium	Cement Floor	Non Suspect ACM	x	190	SF	x	x		
1	110D (upper level)	Fan Room (Upper Level) in Gymnasium	Fireproofing	Confirmed	FRI	200	SF	ND	NRN		
1	110D (upper level)	Fan Room (Upper Level) in Gymnasium	Vinyl Vibration Damper Cloth	Non Suspect ACM	x	6	SF	x	x		
1	110F	Coats Storage next to Boys Restroom in Gym	Plaster Ceiling	NAD	x	96	SF	x	x		
1	110F	Coats Storage next to Boys Restroom in Gym	Concrete Block Wall	Non Suspect ACM	x	352	SF	x	x		
1	110F	Coats Storage next to Boys Restroom in Gym	12" x 12" Floor Tile and Mastic	Assumed	NF1	96	SF	ND	NRN		
1	110E	Coats Storage next to Storage Room	Plaster Ceiling	NAD	x	96	SF	x	x	Pipe Chase in Room	
1	110E	Coats Storage next to Storage Room	Concrete Block Wall	Non Suspect ACM	x	352	SF	x	x	Pipe Chase in Room	
1	110E	Coats Storage next to Storage Room	12" x 12" Floor Tile and Mastic	Assumed	NF1	96	SF	ND	NRN	Pipe Chase in Room	

	School District of Philadelphia		Survey Type							
	Asbestos Inspection Report - Section 9		___ 6 Month Surveillance							
	Robert Morris Elementary School (2390)		___ Three- Year Reinspection IX							
	Year Built: 1964		__X__ AIR/EIE							
	2600 W. Thompson Street, Philadelphia, PA 19121		__X__ Asbestos Abatement Activity							
	Prepared by: Bernard J. Bryson		___ Bulk Sampling Event							
	Certification # 0437 Date: 1/28/2019 Classroom Modernization Project		Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
Q/U = Quantity Undetermined										
F l o o r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
1	PC110E	Pipe Chase in Coats Storage next to Storage Room	x	x	x	x	x	x	x	Not Accessed
1	110G	Boys Restroom in Gym	Plaster Ceiling	NAD	x	525	SF	x	x	
1	110G	Boys Restroom in Gym	Concrete Block Wall	Non Suspect ACM	x	1,400	SF	x	x	
1	110G	Boys Restroom in Gym	Radiator Insulation	Assumed	FRI	12	SF	ND	NRN	
1	110G	Boys Restroom in Gym	Cement Floor	Non Suspect ACM	x	525	SF	x	x	
1	110C	Girl's Restroom in Gym	Plaster Ceiling	NAD	x	100	SF	x	x	
1	110C	Girl's Restroom in Gym	Concrete Block Wall	Non Suspect ACM	x	320	SF	x	x	
1	110C	Girl's Restroom in Gym	Cement Floor	Non Suspect ACM	x	100	SF	x	x	
1	PC110C	Pipe Chase in Girl's Restroom in Gym	x	x	x	x	x	x	x	Not Accessed
1	110A	Gym Storage next to Gym Office (Old Kitchen)	Plaster Ceiling	NAD	x	136	SF	x	x	
1	110A	Gym Storage next to Gym Office (Old Kitchen)	Concrete Block Wall	Non Suspect ACM	x	400	SF	x	x	
1	110A	Gym Storage next to Gym Office (Old Kitchen)	Sink Undercoat Mastic	Confirmed	NF1	7	SF	ND	NRN	
1	110A	Gym Storage next to Gym Office (Old Kitchen)	9" x 9" Floor Tile and Mastic	Confirmed	NF1	136	SF	ND	NRN	
1	110B	Gym Office	Plaster Ceiling	NAD	x	50	SF	x	x	
1	110B	Gym Office	Concrete Block Wall	Non Suspect ACM	x	400	SF	x	x	
1	110B	Gym Office	9" x 9" Floor Tile and Mastic	Confirmed	NF1	136	SF	ND	NRN	
1	110B	Gym Office	Ceiling Tile 1' x 1'	NAD	x	70	SF	x	x	
1	110B	Gym Office	Ceiling Tile 1' x 1'	NAD	x	16	SF	x	x	
1	110C	Gym Office Restroom	Plaster Ceiling	NAD	x	68	SF	x	x	
1	110C	Gym Office Restroom	Concrete Block Wall	Non Suspect ACM	x	300	SF	x	x	
1	110C	Gym Office Restroom	9" x 9" Floor Tile and Mastic	Confirmed	NF1	68	SF	ND	NRN	

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance							
		Robert Morris Elementary School (2390) Year Built: 1964	___ Three- Year Reinspection IX							
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ AIR/EIE							
		Prepared by: Bernard J. Bryson	__X__ Asbestos Abatement Activity							
		Certification # 0437 Date: 1/28/2019	___ Bulk Sampling Event							
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
<i>F l o o r</i>	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
1	H19	Back Hallway from Auditorium to Gym	Concrete Block Wall	Non Suspect ACM	x	960	SF	x	x	
1	H19	Back Hallway from Auditorium to Gym	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN	
1	H19	Back Hallway from Auditorium to Gym	12" x 12" Floor Tile and Mastic	Assumed	NF1	175	SF	ND	NRN	
1	H19	Back Hallway from Auditorium to Gym	Spline Ceiling Tile 1' x 1'	NAD	x	145	SF	x	x	
1	H19	Back Hallway from Auditorium to Gym	Spline Ceiling Tile 1' x 1'	NAD	x	20	SF	x	x	
1	H19	Back Hallway from Auditorium to Gym	Spline Ceiling Tile 1' x 1'	NAD	x	10	SF	x	x	
1	Stage	Auditorium Stage	Fiberglass Pipe Insulation	Non Suspect ACM	x	150	LF	x	x	
1	Stage	Auditorium Stage	Metal Decking - Ceiling	Non Suspect ACM	x	1,320	SF	x	x	
1	Stage	Auditorium Stage	Concrete Block Wall	Non Suspect ACM	x	3,150	SF	x	x	
1	Stage	Auditorium Stage	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,320	SF	ND	NRN	
1	Stage	Auditorium Stage	Fireproofing	Confirmed	FRI	1,200	SF	ND	NRN	
1	109A	Stage Storage Room	Plaster Ceiling	NAD	x	54	SF	x	x	
1	109A	Stage Storage Room	Concrete Block Wall	Non Suspect ACM	x	210	SF	x	x	
1	109A	Stage Storage Room	9" x 9" Floor Tile and Mastic	Confirmed	NF1	54	SF	ND	NRN	
1	109	Auditorium	Plaster Ceiling	NAD	x	5,270	SF	x	x	
1	109	Auditorium	Concrete Block Wall	Non Suspect ACM	x	6,500	SF	x	x	
1	109	Auditorium	Radiator Insulation	Assumed	FRI	36	SF	ND	NRN	
1	109	Auditorium	9" x 9" Floor Tile and Mastic	Confirmed	NF1	4,092	SF	ND	NRN	
1	109	Auditorium	12" x 12" Floor Tile and Mastic	Assumed	NF1	1,178	SF	ND	NRN	
1	109B	Storage Room in Auditorium (near entrance)	Plaster Ceiling	NAD	x	68	SF	x	x	
1	109B	Storage Room in Auditorium (near entrance)	Concrete Block Wall	Non Suspect ACM	x	420	SF	x	x	

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	____ 6 Month Surveillance								
		Robert Morris Elementary School (2390) Year Built: 1964	____ Three- Year Reinspection IX								
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ AIR/EIE								
		Prepared by: Bernard J. Bryson	__X__ Asbestos Abatement Activity								
		Certification # 0437 Date: 1/28/2019	____ Bulk Sampling Event								
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218								
F l o o r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes	
1	109B	Storage Room in Auditorium (near entrance)	9" x 9" Floor Tile and Mastic	Confirmed	NF1	68	SF	ND	NRN		
1	108	Men's Restroom next to Principal's Office	Plaster Ceiling	NAD	x	340	SF	x	x		
1	108	Men's Restroom next to Principal's Office	Concrete Block Wall	Non Suspect ACM	x	600	SF	x	x		
1	108	Men's Restroom next to Principal's Office	Cement Floor	Non Suspect ACM	x	340	SF	x	x		
1	PC108	Pipe Chase in Men's Restroom next to Principal's Office	x	x	x	x	x	x	x	Not Accessed	
1	108A	Women's Restroom next to Principal's Office	Plaster Ceiling	NAD	x	140	SF	x	x		
1	108A	Women's Restroom next to Principal's Office	Concrete Block Wall	Non Suspect ACM	x	384	SF	x	x		
1	108A	Women's Restroom next to Principal's Office	Cement Floor	Non Suspect ACM	x	140	SF	x	x		
1	H15	Main Entrance Lobby (Includes Vestibule)	Plaster Ceiling	NAD	x	128	SF	x	x		
1	H15	Main Entrance Lobby (Includes Vestibule)	Brick Wall	Non Suspect ACM	x	1,700	SF	x	x		
1	H15	Main Entrance Lobby (Includes Vestibule)	Terrazzo Floor	Non Suspect ACM	x	1,188	SF	x	x		
1	H15	Main Entrance Lobby (Includes Vestibule)	Spline Ceiling Tile 1' x 1'	NAD	x	1,020	SF	x	x		
1	H15	Main Entrance Lobby (Includes Vestibule)	Spline Ceiling Tile 1' x 1'	NAD	x	20	SF	x	x		
1	H15	Main Entrance Lobby (Includes Vestibule)	Spline Ceiling Tile 1' x 1'	NAD	x	8	SF	x	x		
1	H15	Main Entrance Lobby (Includes Vestibule)	Ceiling Tile 2' x 4'	NAD	x	16	SF	x	x		
1	H15	Main Entrance Lobby (Includes Vestibule)	Radiator Insulation	Assumed	FRI	12	SF	ND	NRN		
1	107A1	Principal's Office Restroom	Plaster Ceiling	NAD	x	39	SF	x	x		
1	107A1	Principal's Office Restroom	Concrete Block Wall	Non Suspect ACM	x	300	SF	x	x		
1	107A1	Principal's Office Restroom	12" x 12" Floor Tile and Mastic	Assumed	NF1	39	SF	ND	NRN		
1	107A	Principal's Office	Concrete Block Wall	Non Suspect ACM	x	1,100	SF	x	x		
1	107A	Principal's Office	12" x 12" Floor Tile and Mastic	Assumed	NF1	450	SF	ND	NRN		

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined			
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance											
		Robert Morris Elementary School (2390)	___ Three- Year Reinspection IX											
		Year Built: 1964	__X__ AIR/EIE											
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity											
		Prepared by: Bernard J. Bryson	___ Bulk Sampling Event											
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218											
F	l	o	o	r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
1					107A	Principal's Office	Ceiling Tile 1' x 1'	NAD	x	428	SF	x	x	
1					107A	Principal's Office	Ceiling Tile 1' x 1'	NAD	x	15	SF	x	x	
1					107A	Principal's Office	Ceiling Tile 1' x 1'	NAD	x	7	SF	x	x	
1					107A2	Principal's Office Closet	Plaster Ceiling	NAD	x	15	SF	x	x	
1					107A2	Principal's Office Closet	Concrete Block Wall	Non Suspect ACM	x	90	SF	x	x	
1					107A2	Principal's Office Closet	12" x 12" Floor Tile and Mastic	Assumed	NF1	15	SF	ND	NRN	
1					107C	School Police next to Main Office	Plaster Ceiling	NAD	x	49	SF	x	x	
1					107C	School Police next to Main Office	Concrete Block Wall	Non Suspect ACM	x	336	SF	x	x	
1					107C	School Police next to Main Office	Cement Floor	Non Suspect ACM	x	49	SF	x	x	
1					107	Main Office	Concrete Block Wall	Non Suspect ACM	x	1,632	SF	x	x	
1					107	Main Office	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,107	SF	ND	NRN	
1					107	Main Office	Ceiling Tile 1' x 1'	NAD	x	1,025	SF	x	x	
1					107	Main Office	Ceiling Tile 1' x 1'	NAD	x	50	SF	x	x	
1					107	Main Office	Ceiling Tile 1' x 1'	NAD	x	32	SF	x	x	
1					107B	Main Office Closet	Plaster Ceiling	NAD	x	8	SF	x	x	
1					107B	Main Office Closet	Concrete Block Wall	Non Suspect ACM	x	90	SF	x	x	
1					107B	Main Office Closet	9" x 9" Floor Tile and Mastic	Confirmed	NF1	8	SF	ND	NRN	
1					106A	Main Office - Room Across from Mail Boxes	Concrete Block Wall	Non Suspect ACM	x	528	SF	x	x	
1					106A	Main Office - Room Across from Mail Boxes	9" x 9" Floor Tile and Mastic	Confirmed	NF1	120	SF	ND	NRN	
1					106A	Main Office - Room Across from Mail Boxes	Ceiling Tile 1' x 1'	NAD	x	88	SF	x	x	
1					106A	Main Office - Room Across from Mail Boxes	Ceiling Tile 1' x 1'	NAD	x	24	SF	x	x	
1					106A	Main Office - Room Across from Mail Boxes	Ceiling Tile 1' x 1'	NAD	x	8	SF	x	x	
1					106	Office/Copy Room in Main Office	Concrete Block Wall	Non Suspect ACM	x	528	SF	x	x	

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance								
		Robert Morris Elementary School (2390)	___ Three- Year Reinspection IX								
		Year Built: 1964	__X__ AIR/EIE								
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity								
		Prepared by: Bernard J. Bryson	___ Bulk Sampling Event								
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218								
<i>F l o o r</i>	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes	
1	106	Office/Copy Room in Main Office	9" x 9" Floor Tile and Mastic	Confirmed	NF1	120	SF	ND	NRN		
1	106	Office/Copy Room in Main Office	Ceiling Tile 1' x 1'	NAD	x	120	SF	x	x		
1	106C	Computer Server/Kitchenette in Main Office	Plaster Ceiling	NAD	x	108	SF	x	x		
1	106C	Computer Server/Kitchenette in Main Office	Concrete Block Wall	Non Suspect ACM	x	336	SF	x	x		
1	106C	Computer Server/Kitchenette in Main Office	9" x 9" Floor Tile and Mastic	Confirmed	NF1	108	SF	ND	NRN		
1	105A	Nurse's Office Restroom	Plaster Ceiling	NAD	x	36	SF	x	x		
1	105A	Nurse's Office Restroom	Concrete Block Wall	Non Suspect ACM	x	190	SF	x	x		
1	105A	Nurse's Office Restroom	9" x 9" Floor Tile and Mastic	Confirmed	NF1	36	SF	ND	NRN		
1	105	Nurse's Office	Concrete Block Wall	Non Suspect ACM	x	750	SF	x	x		
1	105	Nurse's Office	9" x 9" Floor Tile and Mastic	Confirmed	NF1	330	SF	ND	NRN		
1	105	Nurse's Office	Ceiling Tile 1' x 1'	NAD	x	332	SF	x	x		
1	105	Nurse's Office	Ceiling Tile 1' x 1'	NAD	x	22	SF	x	x		
1	105	Nurse's Office	Ceiling Tile 1' x 1'	NAD	x	6	SF	x	x		
1	105B	Nurse's Office Closet	Concrete Block Wall	Non Suspect ACM	x	144	SF	x	x		
1	105B	Nurse's Office Closet	9" x 9" Floor Tile and Mastic	Confirmed	NF1	18	SF	ND	NRN		
1	105B	Nurse's Office Closet	Plaster Ceiling	NAD	x	18	SF	x	x		
1	104	Counselor's Office	Concrete Block Wall	Non Suspect ACM	x	1,056	SF	x	x		
1	104	Counselor's Office	9" x 9" Floor Tile and Mastic	Confirmed	NF1	480	SF	ND	NRN		
1	104	Counselor's Office	Ceiling Tile 1' x 1'	NAD	x	448	SF	x	x		
1	104	Counselor's Office	Ceiling Tile 1' x 1'	NAD	x	24	SF	x	x		
1	104	Counselor's Office	Ceiling Tile 1' x 1'	NAD	x	8	SF	x	x		
1	104	Counselor's Office	Blackboard Glue Dots	Assumed	NF1	10	SF	ND	NRN		

		School District of Philadelphia		Survey Type							Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9		___ 6 Month Surveillance							
		Robert Morris Elementary School (2390)		___ Three- Year Reinspection IX							
		Year Built: 1964		__X__ AIR/EIE							
		2600 W. Thompson Street, Philadelphia, PA 19121		__X__ Asbestos Abatement Activity							
		Prepared by: Bernard J. Bryson		___ Bulk Sampling Event							
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project		Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
<i>F l o o r</i>	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes	
1	104A	Counselor's Office Large Closet	Plaster Ceiling	NAD	x	16	SF	x	x		
1	104A	Counselor's Office Large Closet	Concrete Block Wall	non Suspect ACM	x	96	SF	x	x		
1	104A	Counselor's Office Large Closet	9" x 9" Floor Tile and Mastic	Confirmed	NF1	16	SF	ND	NRN		
1	104B	Counselor's Office Small Closet	Plaster Ceiling	NAD	x	9	SF	x	x		
1	104B	Counselor's Office Small Closet	Concrete Block Wall	non Suspect ACM	x	72	SF	x	x		
1	104B	Counselor's Office Small Closet	9" x 9" Floor Tile and Mastic	Confirmed	NF1	9	SF	ND	NRN		
1	103A	Custodial Closet across from Main Office	Plaster Ceiling	NAD	x	36	SF	x	x		
1	103A	Custodial Closet across from Main Office	Concrete Block Wall	Non Suspect ACM	x	312	SF	x	x		
1	103A	Custodial Closet across from Main Office	9" x 9" Floor Tile and Mastic	Confirmed	NF1	36	SF	ND	NRN		
1	S11	Stairwell across from Main Office	Plaster Ceiling	NAD	x	210	SF	x	x		
1	S11	Stairwell across from Main Office	Concrete Block Wall	Non Suspect ACM	x	744	SF	x	x		
1	S11	Stairwell across from Main Office	Radiator Insulation	Assumed	FRI	12	SF	ND	NRN		
1	S11	Stairwell across from Main Office	12" x 12" Floor Tile and Mastic	Assumed	NF1	210	SF	ND	NRN		
1	H14	Hallway from Main Office to Gym	Ceiling Tile 2' x 4'	NAD	x	232	SF	x	x		
1	H14	Hallway from Main Office to Gym	Ceiling Tile 2' x 4'	NAD	x	8	SF	x	x		
1	H14	Hallway from Main Office to Gym	Plaster Ceiling	NAD	x	160	SF	x	x		
1	H14	Hallway from Main Office to Gym	Concrete Block Wall	Non Suspect ACM	x	2,400	SF	x	x		
1	H14	Hallway from Main Office to Gym	12" x 12" Floor Tile and Mastic	Assumed	NF1	173	SF	ND	NRN		
1	H14	Hallway from Main Office to Gym	12" x 12" Floor Tile and Mastic	Assumed	NF1	320	SF	ND	NRN		
1	H14	Hallway from Main Office to Gym	Radiator Insulation	Assumed	FRI	12	SF	ND	NRN		
1	H14	Hallway from Main Office to Gym	Spline Ceiling Tile 1' x 1'	NAD	x	597	SF	x	x		
1	H14	Hallway from Main Office to Gym	Spline Ceiling Tile 1' x 1'	NAD	x	16	SF	x	x		

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined			
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance											
		Robert Morris Elementary School (2390)	___ Three- Year Reinspection IX											
		Year Built: 1964	__X__ AIR/EIE											
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity											
		Prepared by: Bernard J. Bryson	___ Bulk Sampling Event											
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218											
F	l	o	o	r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
1					H14	Hallway from Main Office to Gym	Spline Ceiling Tile 1' x 1'	NAD	x	80	SF	x	x	
1					S14	Stairwell next to Gymnasium	Plaster Ceiling	NAD	x	240	SF	x	x	
1					S14	Stairwell next to Gymnasium	Concrete Block Wall	Non Suspect ACM	x	1000	SF	x	x	
1					S14	Stairwell next to Gymnasium	12" x 12" Floor Tile and Mastic	Assumed	NF1	50	SF	ND	NRN	
1					S14	Stairwell next to Gymnasium	Cement Floor	Non Suspect ACM	x	190	SF	x	x	
1					103	Storage across from Nurse's Office	Fiberglass Pipe Insulation	Non Suspect ACM	x	70	LF	x	x	
1					103	Storage across from Nurse's Office	Plaster Ceiling	NAD	x	372	SF	x	x	
1					103	Storage across from Nurse's Office	Concrete Block Wall	Non Suspect ACM	x	1,032	SF	x	x	
1					103	Storage across from Nurse's Office	9" x 9" Floor Tile and Mastic	Confirmed	NF1	372	SF	ND	NRN	
1					102	Girl's Restroom across from Nurse's Office	Plaster Ceiling	NAD	x	780	SF	x	x	
1					102	Girl's Restroom across from Nurse's Office	Concrete Block Wall	Non Suspect ACM	x	1,416	SF	x	x	
1					102	Girl's Restroom across from Nurse's Office	Radiator Insulation	Assumed	FRI	14	SF	ND	NRN	
1					102	Girl's Restroom across from Nurse's Office	Cement Floor	Non Suspect ACM	x	780	SF	x	x	
1					PC102	Pipe Chase in Girl's Restroom across from Nurse's Office	x	x	x	x	x	x	x	Not Accessed
1					H16	Hallway from Main Lobby to Classroom 100	Concrete Block Wall	Non Suspect ACM	x	3,312	SF	x	x	
1					H16	Hallway from Main Lobby to Classroom 100	Radiator Insulation	Assumed	FRI	8	SF	ND	NRN	
1					H16	Hallway from Main Lobby to Classroom 100	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,161	SF	ND	NRN	
1					H16	Hallway from Main Lobby to Classroom 100	Spline Ceiling Tile 1' x 1'	NAD	x	1,157	SF	x	x	
1					H16	Hallway from Main Lobby to Classroom 100	Spline Ceiling Tile 1' x 1'	NAD	x	4	SF	x	x	
1					PCH16	Pipe Chase in Hallway by Classroom 100	x	x	x	x	x	x	x	Not Accessed
1					101A	Classroom 101 Restroom	Plaster Ceiling	NAD	x	90	SF	x	x	
1					101A	Classroom 101 Restroom	Concrete Block Wall	Non Suspect ACM	x	280	SF	x	x	
1					101A	Classroom 101 Restroom	Wood Laminate & Metal Stall Partitions	Non Suspect ACM	x	Q/U	SF	x	x	

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	6 Month Surveillance							
		Robert Morris Elementary School (2390) Year Built: 1964	Three- Year Reinspection IX							
		2600 W. Thompson Street, Philadelphia, PA 19121	X AIR/EIE							
		Prepared by: Bernard J. Bryson	X Asbestos Abatement Activity							
		Certification # 0437 Date: 1/28/2019	Bulk Sampling Event							
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
Floor	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
1	101A	Classroom 101 Restroom	9" x 9" Floor Tile and Mastic	Confirmed	NF1	90	SF	ND	REM	Remove all 9" x 9" Floor Tile and associated Vinyl Cove Base - Remaining Mastic Adhered to Concrete Substrate to Remain
1	101B	Classroom 101 Coat and Storage Area	Plaster Ceiling	NAD	x	80	SF	x	x	
1	101B	Classroom 101 Coat and Storage Area	Concrete Block Wall	Non Suspect ACM	x	234	SF	x	x	
1	101B	Classroom 101 Coat and Storage Area	9" x 9" Floor Tile and Mastic	Confirmed	NF1	80	SF	ND	REM	Remove all 9" x 9" Floor Tile and associated Vinyl Cove Base - Remaining Mastic Adhered to Concrete Substrate to Remain
1	101C	Classroom 101 Storage Closet	Plaster Ceiling	NAD	x	60	SF	x	x	
1	101C	Classroom 101 Storage Closet	Concrete Block Wall	Non Suspect ACM	x	200	SF	x	x	
1	101C	Classroom 101 Storage Closet	Slate Window Sills	Non Suspect ACM	x	Q/U	SF	x	x	
1	101C	Classroom 101 Storage Closet	9" x 9" Floor Tile and Mastic	Confirmed	NF1	60	SF	ND	REM	Remove all 9" x 9" Floor Tile and associated Vinyl Cove Base - Remaining Mastic Adhered to Concrete Substrate to Remain
1	101	Classroom 101	Corrugated Metal Deck and Red Painted Trusses	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling
1	101	Classroom 101	Orange Foam Panels above Windows	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling
1	101	Classroom 101	Fiberglass Pipe Insulation	Non Suspect ACM	x	Q/U	LF	x	x	Above Suspended Ceiling; No Hard Fittings Identified
1	101	Classroom 101	Ceiling Tile 2' x 4'	NAD	x	1,250	SF	x	x	
1	101	Classroom 101	Concrete Block Wall	Non Suspect ACM	x	1,000	SF	x	x	
			Slate Window Sills	Non Suspect ACM	x	Q/U	SF	x	x	
1	101	Classroom 101	Slate Window Sills	Non Suspect ACM	x	Q/U	SF	x	x	

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	6 Month Surveillance								
		Robert Morris Elementary School (2390) Year Built: 1964	Three- Year Reinspection IX								
		2600 W. Thompson Street, Philadelphia, PA 19121	X AIR/EIE								
		Prepared by: Bernard J. Bryson	X Asbestos Abatement Activity								
		Certification # 0437 Date: 1/28/2019	Bulk Sampling Event								
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218								
Floor	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes	
1	101	Classroom 101	Unit Ventilator Insulation	Non Suspect ACM	x	Q/U	SF	x	x	Confirmed to be Comprised of Fiberglass	
1	101	Classroom 101	Sink Undercoat Mastic	Confirmed	NF1	6	SF	ND	REM	1 sink - 6 SF	
1	101	Classroom 101	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,250	SF	ND	REM	Remove all 9" x 9" Floor Tile and associated Vinyl Cove Base - Remaining Mastic Adhered to Concrete Substrate to Remain	
1	101	Classroom 101	Blackboard Glue Dots	Assumed	NF1	270	SF	ND	NRN	Blackboards/Tack boards to remain intact as per demolition note 16 on D1.1	
1	100	Classroom 100	Corrugated Metal Deck and Red Painted Trusses	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling	
1	100	Classroom 100	Orange Foam Panels above Windows	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling	
1	100	Classroom 100	Fiberglass Pipe Insulation	Non Suspect ACM	x	Q/U	LF	x	x	Above Suspended Ceiling; No Hard Fittings Identified	
1	100	Classroom 100	Ceiling Tile 2' x 4'	NAD	x	1,250	SF	x	x		
1	100	Classroom 100	Concrete Block Wall	Non Suspect ACM	x	1,422	SF	x	x		
1	100	Classroom 100	Slate Window Sills	Non Suspect ACM	x	Q/U	SF	x	x		
1	100	Classroom 100	Unit Ventilator Insulation	Non Suspect ACM	x	Q/U	SF	x	x	Confirmed to be Comprised of Fiberglass	
1	100	Classroom 100	Sink Undercoat Mastic	Confirmed	NF1	6	SF	ND	REM	1 sink - 6 SF	
1	100	Classroom 100	12" x 12" Floor Tile and Mastic	Assumed	NF1	1,250	SF	ND	REM	Remove all 12" x 12" Grey Floor Tile and associated Vinyl Cove Base - Remaining Mastic Adhered to Concrete Substrate to Remain	

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined				
		Asbestos Inspection Report - Section 9	____ 6 Month Surveillance											
		Robert Morris Elementary School (2390)	____ Three- Year Reinspection IX											
		Year Built: 1964	__X__ AIR/EIE											
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity											
		Prepared by: Bernard J. Bryson	____ Bulk Sampling Event											
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218											
F	l	o	o	r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
1					100	Classroom 100	Blackboard Glue Dots	Assumed	NF1	60	SF	ND	NRN	Blackboards/Tack boards to remain intact as per demolition note 16 on D1.1
1					100A	Classroom 100 Restroom	Plaster Ceiling	NAD	x	90	SF	x	x	
1					100A	Classroom 100 Restroom	Concrete Block Wall	Non Suspect ACM	x	304	SF	x	x	
1					100A	Classroom 100 Restroom	Wood Laminate & Metal Stall Partitions	Non Suspect ACM	x	Q/U	SF	x	x	
1					100A	Classroom 100 Restroom	12" x 12" Floor Tile and Mastic	Assumed	NF1	90	SF	ND	REM	Remove all 12" x 12" Grey Floor Tile and associated Vinyl Cove Base - Remaining Mastic Adhered to Concrete Substrate to Remain
1					100B	Classroom 100 Coat and Storage Area	Plaster Ceiling	NAD	x	80	SF	x	x	
1					100B	Classroom 100 Coat and Storage Area	Concrete Block Wall	Non Suspect ACM	x	270	SF	x	x	
1					100B	Classroom 100 Coat and Storage Area	12" x 12" Floor Tile and Mastic	Assumed	NF1	80	SF	ND	REM	Remove all 12" x 12" Grey Floor Tile and associated Vinyl Cove Base - Remaining Mastic Adhered to Concrete Substrate to Remain
1					100C	Classroom 100 Storage Closet	Plaster Ceiling	NAD	x	48	SF	x	x	
1					100C	Classroom 100 Storage Closet	Concrete Block Wall	Non Suspect ACM	x	200	SF	x	x	
1					100C	Classroom 100 Storage Closet	Slate Window Sills	Non Suspect ACM	x	Q/U	SF	x	x	
1					100C	Classroom 100 Storage Closet	12" x 12" Floor Tile and Mastic	Assumed	NF1	60	SF	ND	REM	Remove all 12" x 12" Grey Floor Tile and associated Vinyl Cove Base - Remaining Mastic Adhered to Concrete Substrate to Remain
1					S12	Stairwell across from Classroom 100	Pipe Fitting Insulation	Confirmed	FRI	2	EA	ND	NRN	
1					S12	Stairwell across from Classroom 100	Fiberglass Pipe Insulation	Non Suspect ACM	x	20	LF	x	x	
1					S12	Stairwell across from Classroom 100	Plaster Ceiling	NAD	x	160	SF	x	x	
1					S12	Stairwell across from Classroom 100	Concrete Block Wall	Non Suspect ACM	x	572	SF	x	x	

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance								
		Robert Morris Elementary School (2390)	___ Three- Year Reinspection IX								
		Year Built: 1964	__X__ AIR/EIE								
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity								
		Prepared by: Bernard J. Bryson	___ Bulk Sampling Event								
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218								
F l o o r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes	
1	S12	Stairwell across from Classroom 100	Radiator Insulation	Assumed	FRI	17	SF	ND	NRN		
1	S12	Stairwell across from Classroom 100	Cement Floor	Non Suspect ACM	x	160	SF	x	x		
2	S22	Stairwell next to Classroom 201	Plaster Ceiling	NAD	x	250	SF	x	x		
2	S22	Stairwell next to Classroom 201	Concrete Block Wall	Non Suspect ACM	x	910	SF	x	x		
2	S22	Stairwell next to Classroom 201	Radiator Insulation	Assumed	FRI	17	SF	ND	NRN		
2	S22	Stairwell next to Classroom 201	Cement Floor	Non Suspect ACM	x	250	SF	x	x		
2	H210	Hallway from Lunch Room to Classroom 200	Concrete Block Wall	Non Suspect ACM	x	2,716	SF	x	x		
2	H210	Hallway from Lunch Room to Classroom 200	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,278	SF	ND	NRN		
2	H210	Hallway from Lunch Room to Classroom 200	Radiator Insulation	Assumed	FRI	7	SF	ND	NRN		
2	H210	Hallway from Lunch Room to Classroom 200	Ceiling Tile 1' x 1'	NAD	x	1,244	SF	x	x		
2	H210	Hallway from Lunch Room to Classroom 200	Ceiling Tile 1' x 1'	NAD	x	34	SF	x	x		
2	S21	Stairwell across from Classroom 206	Plaster Ceiling	NAD	x	260	SF	x	x		
2	S21	Stairwell across from Classroom 206	Concrete Block Wall	Non Suspect ACM	x	720	SF	x	x		
2	S21	Stairwell across from Classroom 206	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN		
2	S21	Stairwell across from Classroom 206	Cement Floor	Non Suspect ACM	x	260	SF	x	x		
2	200	Classroom 200	Corrugated Metal Deck and Red Painted Trusses	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling	
2	200	Classroom 200	Orange Foam Panels above Windows	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling	
2	200	Classroom 200	Ceiling Tile 2' x 4'	NAD	x	1,000	SF	x	x	No Insulation above Suspended Ceiling	
2	200	Classroom 200	Plaster Ceiling	NAD	x	50	SF	x	x		
2	200	Classroom 200	Plaster Wall	NAD	x	150	SF	x	x	Plaster Wall above Coat Closet	

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance							
		Robert Morris Elementary School (2390) Year Built: 1964	___ Three- Year Reinspection IX							
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ AIR/EIE							
		Prepared by: Bernard J. Bryson	__X__ Asbestos Abatement Activity							
		Certification # 0437 Date: 1/28/2019	___ Bulk Sampling Event							
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
<i>F l o o r</i>	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
2	200	Classroom 200	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
2	200	Classroom 200	Slate Window Sills	Non Suspect ACM	x	Q/U	SF	x	x	
2	200	Classroom 200	Unit Ventilator Insulation	Non Suspect ACM	x	Q/U	SF	x	x	Confirmed to be Comprised of Fiberglass
2	200	Classroom 200	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,000	SF	ND	REM	Remove all 9" x 9" Floor Tile and associated Vinyl Cove Base - Remaining Mastic Adhered to Concrete Substrate to Remain
2	200	Classroom 200	Blackboard Glue Dots	Assumed	NF1	300	SF	ND	NRN	Blackboards/Tack boards to remain intact as per demolition note 16 on D1.1
2	201	Classroom 201	Ceiling Tile 2' x 4'	NAD	x	528	SF	x	x	
2	201	Classroom 201	Ceiling Tile 2' x 4'	NAD	x	48	SF	x	x	
2	201	Classroom 201	Concrete Block Wall	Non Suspect ACM	x	900	SF	x	x	
2	201	Classroom 201	9" x 9" Floor Tile and Mastic	Confirmed	NF1	576	SF	ND	NRN	
2	201	Classroom 201	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
2	202	Classroom 202	Ceiling Tile 2' x 4'	NAD	x	912	SF	x	x	
2	202	Classroom 202	Ceiling Tile 2' x 4'	NAD	x	24	SF	x	x	
2	202	Classroom 202	Plaster Ceiling	NAD	x	50	SF	x	x	
2	202	Classroom 202	Plaster Wall	NAD	x	100	SF	x	x	
2	202	Classroom 202	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
2	202	Classroom 202	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN	
2	202	Classroom 202	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
2	203	Classroom 203	Corrugated Metal Deck and Red Painted Trusses	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance								
		Robert Morris Elementary School (2390)	___ Three- Year Reinspection IX								
		Year Built: 1964	__X__ AIR/EIE								
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity								
		Prepared by: Bernard J. Bryson	___ Bulk Sampling Event								
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218								
F l o o r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes	
2	203	Classroom 203	Orange Foam Panels above Windows	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling	
2	203	Classroom 203	Ceiling Tile 2' x 4'	NAD	x	1,000	SF	x	x	No Insulation above Suspended Ceiling	
2	203	Classroom 203	Plaster Ceiling	NAD	x	50	SF	x	x		
2	203	Classroom 203	Plaster Wall	NAD	x	150	SF	x	x	Plaster Wall above Coat Closet	
2	203	Classroom 203	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x		
2	203	Classroom 203	Slate Window Sills	Non Suspect ACM	x	Q/U	SF	x	x		
2	203	Classroom 203	Unit Ventilator Insulation	Non Suspect ACM	x	Q/U	SF	x	x	Confirmed to be Comprised of Fiberglass	
2	203	Classroom 203	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,000	SF	ND	REM	Remove all 9" x 9" Floor Tile and associated Vinyl Cove Base - Remaining Mastic Adhered to Concrete Substrate to Remain	
2	203	Classroom 203	Blackboard Glue Dots	Assumed	NF1	300	SF	ND	NRN	Blackboards/Tack boards to remain intact as per demolition note 16 on D1.1	
2	204	Classroom 204	Corrugated Metal Deck and Red Painted Trusses	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling	
2	204	Classroom 204	Orange Foam Panels above Windows	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling	
2	204	Classroom 204	Ceiling Tile 2' x 4'	NAD	x	1,000	SF	x	x	No Insulation above Suspended Ceiling	
2	204	Classroom 204	Plaster Ceiling	NAD	x	50	SF	x	x		
2	204	Classroom 204	Plaster Wall	NAD	x	150	SF	x	x	Plaster Wall above Coat Closet	
2	204	Classroom 204	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x		
2	204	Classroom 204	Slate Window Sills	Non Suspect ACM	x	Q/U	SF	x	x		

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	6 Month Surveillance							
		Robert Morris Elementary School (2390)	Three- Year Reinspection IX							
		Year Built: 1964	X AIR/EIE							
		2600 W. Thompson Street, Philadelphia, PA 19121	X Asbestos Abatement Activity							
		Prepared by: Bernard J. Bryson	Bulk Sampling Event							
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
Floor	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
2	204	Classroom 204	Unit Ventilator Insulation	Non Suspect ACM	x	Q/U	SF	x	x	Confirmed to be Comprised of Fiberglass
2	204	Classroom 204	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,000	SF	ND	REM	Remove all 9" x 9" Floor Tile and associated Vinyl Cove Base - Remaining Mastic Adhered to Concrete Substrate to Remain
2	204	Classroom 204	Blackboard Glue Dots	Assumed	NF1	300	SF	ND	NRN	Blackboards/Tack boards to remain intact as per demolition note 16 on D1.1
2	220	Boys Restroom next to Classroom 203	Plaster Ceiling	NAD	x	208	SF	x	x	
2	220	Boys Restroom next to Classroom 203	Concrete Block Wall	Non Suspect ACM	x	680	SF	x	x	
2	220	Boys Restroom next to Classroom 203	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN	
2	220	Boys Restroom next to Classroom 203	Cement Floor	Non Suspect ACM	x	208	SF	x	x	
2	PC220	Pipe Chase in Boys Restroom next to Classroom 203	x	x	x	x	x	x	x	Not Accessed
2	221	Girl's Restroom across from Classroom 204	Plaster Ceiling	NAD	x	338	SF	x	x	
2	221	Girl's Restroom across from Classroom 204	Concrete Block Wall	Non Suspect ACM	x	780	SF	x	x	
2	221	Girl's Restroom across from Classroom 204	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN	
2	221	Girl's Restroom across from Classroom 204	Cement Floor	Non Suspect ACM	x	338	SF	x	x	
2	PC221	Pipe Chase in Girl's Restroom across from Classroom 204	x	x	x	x	x	x	x	Not Accessed
2	222	Women's Restroom across from Classroom 204	Plaster Ceiling	NAD	x	176	SF	x	x	
2	222	Women's Restroom across from Classroom 204	Concrete Block Wall	Non Suspect ACM	x	600	SF	x	x	
2	222	Women's Restroom across from Classroom 204	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN	

		School District of Philadelphia	Survey Type							
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance							
		Robert Morris Elementary School (2390)	___ Three- Year Reinspection IX							
		Year Built: 1964	__X__ AIR/EIE							
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity							
		Prepared by: Bernard J. Bryson	___ Bulk Sampling Event							
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
										Q/U = Quantity Undetermined
F l o o r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
2	222	Women's Restroom across from Classroom 204	Cement Floor	Non Suspect ACM	x	176	SF	x	x	
2	206	Classroom 206	Ceiling Tile 2' x 4'	NAD	x	896	SF	x	x	
2	206	Classroom 206	Ceiling Tile 2' x 4'	NAD	x	40	SF	x	x	
2	206	Classroom 206	Plaster Ceiling	NAD	x	50	SF	x	x	
2	206	Classroom 206	Plaster Wall	NAD	x	100	SF	x	x	
2	206	Classroom 206	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
2	206	Classroom 206	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN	
2	206	Classroom 206	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
2	224A	Custodial Closet next to Elevator	Fiberglass Pipe Insulation	Non Suspect ACM	x	24	LF	x	x	
2	224A	Custodial Closet next to Elevator	Plaster Ceiling	NAD	x	24	SF	x	x	
2	224A	Custodial Closet next to Elevator	Concrete Block Wall	Non Suspect ACM	x	220	SF	x	x	
2	224A	Custodial Closet next to Elevator	9" x 9" Floor Tile and Mastic	Confirmed	NF1	24	SF	ND	NRN	
2	208	Classroom 208	Fiberglass Pipe Insulation	Non Suspect ACM	x	10	LF	x	x	
2	208	Classroom 208	Ceiling Tile 2' x 4'	NAD	x	860	SF	x	x	
2	208	Classroom 208	Ceiling Tile 2' x 4'	NAD	x	20	SF	x	x	
2	208	Classroom 208	Ceiling Tile 2' x 4'	NAD	x	56	SF	x	x	
2	208	Classroom 208	Plaster Ceiling	NAD	x	50	SF	x	x	
2	208	Classroom 208	Plaster Wall	NAD	x	100	SF	x	x	
2	208	Classroom 208	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
2	208	Classroom 208	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN	
2	208	Classroom 208	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
2	224	Men's Restroom across from Lunch Room	Plaster Ceiling	NAD	x	44	SF	x	x	
2	224	Men's Restroom across from Lunch Room	Concrete Block Wall	Non Suspect ACM	x	240	SF	x	x	
2	224	Men's Restroom across from Lunch Room	Cement Floor	Non Suspect ACM	x	44	SF	x	x	

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance								
		Robert Morris Elementary School (2390) Year Built: 1964	___ Three- Year Reinspection IX								
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ AIR/EIE								
		Prepared by: Bernard J. Bryson	__X__ Asbestos Abatement Activity								
		Certification # 0437 Date: 1/28/2019	___ Bulk Sampling Event								
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218								
F l o o r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes	
2	PC224	Pipe Chase next to Men's Restroom Door	x	x	x	x	x	x	x	Not Accessed	
2	210	Cafeteria (210)	Ceiling Tile 2' x 4'	NAD	x	886	SF	x	x		
2	210	Cafeteria (210)	Ceiling Tile 2' x 4'	NAD	x	50	SF	x	x		
2	210	Cafeteria (210)	Plaster Ceiling	NAD	x	50	SF	x	x		
2	210	Cafeteria (210)	Plaster Wall	NAD	x	100	SF	x	x		
2	210	Cafeteria (210)	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x		
2	210	Cafeteria (210)	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN		
2	210	Cafeteria (210)	Blackboard Glue Dots	Assumed	NF1	10	SF	ND	NRN		
2	212	Cafeteria (212)	Ceiling Tile 2' x 4'	NAD	x	872	SF	x	x		
2	212	Cafeteria (212)	Ceiling Tile 2' x 4'	NAD	x	64	SF	x	x		
2	212	Cafeteria (212)	Plaster Ceiling	NAD	x	50	SF	x	x		
2	212	Cafeteria (212)	Plaster Wall	NAD	x	100	SF	x	x		
2	212	Cafeteria (212)	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x		
2	212	Cafeteria (212)	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN		
2	212	Cafeteria (212)	Blackboard Glue Dots	Assumed	NF1	10	SF	ND	NRN		
2	223	Storage next to Classroom 213	Plaster Ceiling	NAD	x	364	SF	x	x		
2	223	Storage next to Classroom 213	Concrete Block Wall	Non Suspect ACM	x	800	SF	x	x		
2	223	Storage next to Classroom 213	9" x 9" Floor Tile and Mastic	Confirmed	NF1	364	SF	ND	NRN		
2	223	Storage next to Classroom 213	Sheetrock Wall	NAD	x	418	SF	x	x		
2	223	Storage next to Classroom 213	Joint Compound	NAD	x	105	SF	x	x		
2	223A	Computer Server Room in Storage Room	x	x	x	x	x	x	x	Not Accessed	
2	213	Classroom 213	Corrugated Metal Deck and Red Painted Trusses	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling	
2	213	Classroom 213	Orange Foam Panels above Windows	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling	

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance							
		Robert Morris Elementary School (2390) Year Built: 1964	___ Three- Year Reinspection IX							
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ AIR/EIE							
		Prepared by: Bernard J. Bryson	__X__ Asbestos Abatement Activity							
		Certification # 0437 Date: 1/28/2019	Bulk Sampling Event							
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
<i>F l o o r</i>	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
2	213	Classroom 213	Ceiling Tile 2' x 4'	NAD	x	1,000	SF	x	x	No Insulation above Suspended Ceiling
2	213	Classroom 213	Plaster Ceiling	NAD	x	50	SF	x	x	
2	213	Classroom 213	Plaster Wall	NAD	x	150	SF	x	x	Plaster Wall above Coat Closet
2	213	Classroom 213	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
2	213	Classroom 213	Slate Window Sills	Non Suspect ACM	x	Q/U	SF	x	x	
2	213	Classroom 213	Unit Ventilator Insulation	Non Suspect ACM	x	Q/U	SF	x	x	Confirmed to be Comprised of Fiberglass
2	213	Classroom 213	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,000	SF	ND	REM	Remove all 9" x 9" Floor Tile and associated Vinyl Cove Base - Remaining Mastic Adhered to Concrete Substrate to Remain
2	213	Classroom 213	Blackboard Glue Dots	Assumed	NF1	300	SF	ND	NRN	Blackboards/Tack boards to remain intact as per demolition note 16 on D1.1
2	214	Classroom 214	Ceiling Tile 2' x 4'	NAD	x	910	SF	x	x	
2	214	Classroom 214	Ceiling Tile 2' x 4'	NAD	x	26	SF	x	x	
2	214	Classroom 214	Plaster Ceiling	NAD	x	50	SF	x	x	
2	214	Classroom 214	Plaster Wall	NAD	x	100	SF	x	x	
2	214	Classroom 214	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
2	214	Classroom 214	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN	
2	214	Classroom 214	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
2	216	Classroom 216	Corrugated Metal Deck and Red Painted Trusses	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling
2	216	Classroom 216	Orange Foam Panels above Windows	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance							
		Robert Morris Elementary School (2390) Year Built: 1964	___ Three- Year Reinspection IX							
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ AIR/EIE							
		Prepared by: Bernard J. Bryson	__X__ Asbestos Abatement Activity							
		Certification # 0437 Date: 1/28/2019	___ Bulk Sampling Event							
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
<i>F l o o r</i>	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
2	216	Classroom 216	Ceiling Tile 2' x 4'	NAD	x	1,000	SF	x	x	No Insulation above Suspended Ceiling
2	216	Classroom 216	Plaster Ceiling	NAD	x	50	SF	x	x	
2	216	Classroom 216	Plaster Wall	NAD	x	150	SF	x	x	Plaster Wall above Coat Closet
2	216	Classroom 216	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
2	216	Classroom 216	Slate Window Sills	Non Suspect ACM	x	Q/U	SF	x	x	
2	216	Classroom 216	Unit Ventilator Insulation	Non Suspect ACM	x	Q/U	SF	x	x	Confirmed to be Comprised of Fiberglass
2	216	Classroom 216	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,000	SF	ND	REM	Remove all 9" x 9" Floor Tile and associated Vinyl Cove Base - Remaining Mastic Adhered to Concrete Substrate to Remain
2	216	Classroom 216	Blackboard Glue Dots	Assumed	NF1	300	SF	ND	NRN	Blackboards/Tack boards to remain intact as per demolition note 16 on D1.1
2	S212	Stairwell next to Classroom 215	Plaster Ceiling	NAD	x	160	SF	x	x	
2	S212	Stairwell next to Classroom 215	Concrete Block Wall	Non Suspect ACM	x	572	SF	x	x	
2	S212	Stairwell next to Classroom 215	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN	
2	S212	Stairwell next to Classroom 215	Cement Floor	Non Suspect ACM	x	160	SF	x	x	
2	215	Classroom 215	Ceiling Tile 2' x 4'	NAD	x	868	SF	x	x	
2	215	Classroom 215	Ceiling Tile 2' x 4'	NAD	x	68	SF	x	x	
2	215	Classroom 215	Plaster Ceiling	NAD	x	50	SF	x	x	
2	215	Classroom 215	Plaster Wall	NAD	x	100	SF	x	x	
2	215	Classroom 215	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
2	215	Classroom 215	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN	
2	215	Classroom 215	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	____ 6 Month Surveillance								
		Robert Morris Elementary School (2390)	____ Three- Year Reinspection IX								
		Year Built: 1964	__X__ AIR/EIE								
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity								
		Prepared by: Bernard J. Bryson	____ Bulk Sampling Event								
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218								
<i>F l o o r</i>	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes	
2	218	Classroom 218	Corrugated Metal Deck and Red Painted Trusses	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling	
2	218	Classroom 218	Orange Foam Panels above Windows	Non Suspect ACM	x	Q/U	SF	x	x	Above Suspended Ceiling	
2	218	Classroom 218	Ceiling Tile 2' x 4'	NAD	x	1,200	SF	x	x	No Insulation above Suspended Ceiling	
2	218	Classroom 218	Plaster Ceiling	NAD	x	50	SF	x	x		
2	218	Classroom 218	Plaster Wall	NAD	x	150	SF	x	x	Plaster Wall above Coat Closet	
2	218	Classroom 218	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x		
2	218	Classroom 218	Slate Window Sills	Non Suspect ACM	x	Q/U	SF	x	x		
2	218	Classroom 218	Unit Ventilator Insulation	Non Suspect ACM	x	Q/U	SF	x	x	Confirmed to be Comprised of Fiberglass	
2	218	Classroom 218	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,200	SF	ND	REM	Remove all 9" x 9" Floor Tile and associated Vinyl Cove Base - Remaining Mastic Adhered to Concrete Substrate to Remain	
2	218	Classroom 218	Blackboard Glue Dots	Assumed	NF1	150	SF	ND	NRN	Blackboards/Tack boards to remain intact as per demolition note 16 on D1.1	
2	217	Office 217 across from Classroom 216	Ceiling Tile 2' x 4'	NAD	x	450	SF	x	x		
2	217	Office 217 across from Classroom 216	Concrete Block Wall	Non Suspect ACM	x	860	SF	x	x		
2	217	Office 217 across from Classroom 216	9" x 9" Floor Tile and Mastic	Confirmed	NF1	450	SF	ND	NRN		
2	217	Office 217 across from Classroom 216	Blackboard Glue Dots	Assumed	NF1	8	SF	ND	NRN		
2	217	Office 217 across from Classroom 216	Sheetrock Wall	NAD	x	400	SF	x	x		
2	217	Office 217 across from Classroom 216	Joint Compound	NAD	x	100	SF	x	x		
2	219	Room 219 Kitchen	Ceiling Tile 2' x 4'	NAD	x	860	SF	x	x		
2	219	Room 219 Kitchen	Ceiling Tile 2' x 4'	NAD	x	24	SF	x	x		

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance								
		Robert Morris Elementary School (2390) Year Built: 1964	___ Three- Year Reinspection IX								
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ AIR/EIE								
		Prepared by: Bernard J. Bryson	__X__ Asbestos Abatement Activity								
		Certification # 0437 Date: 1/28/2019	Bulk Sampling Event								
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218								
<i>F l o o r</i>	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes	
2	219	Room 219 Kitchen	Concrete Block Wall	Non Suspect ACM	x	1,200	SF	x	x		
2	219	Room 219 Kitchen	9" x 9" Floor Tile and Mastic	Confirmed	NF1	884	SF	ND	NRN		
2	219	Room 219 Kitchen	12" x 12" Floor Tile and Mastic	Assumed	NF1	33	SF	ND	NRN		
2	219	Room 219 Kitchen	Blackboard Glue Dots	Assumed	NF1	10	SF	ND	NRN		
2	219	Room 219 Kitchen	Sheetrock Wall	NAD	x	320	SF	x	x		
2	219	Room 219 Kitchen	Joint Compound	NAD	x	80	SF	x	x		
2	219A	Kitchen Office	Ceiling Tile 2' x 4'	NAD	x	256	SF	x	x		
2	219A	Kitchen Office	Concrete Block Wall	Non Suspect ACM	x	640	SF	x	x		
2	219A	Kitchen Office	12" x 12" Floor Tile and Mastic	Assumed	NF1	256	SF	ND	NRN		
2	219A	Kitchen Office	Sheetrock Wall	NAD	x	608	SF	x	x		
2	219A	Kitchen Office	Joint Compound	NAD	x	152	SF	x	x		
2	219A	Kitchen Office	Sink Undercoat Mastic	Confirmed	NF1	6	SF	ND	NRN		
2	218A	Storage outside Classroom 218 and at end of Hallway	Fiberglass Pipe Insulation	Non Suspect ACM	x	27	LF	x	x		
2	218A	Storage outside Classroom 218 and at end of Hallway	Fiberglass Pipe Fitting Insulation	Non Suspect ACM	x	2	EA	x	x		
2	218A	Storage outside Classroom 218 and at end of Hallway	Plaster Ceiling	NAD	x	180	SF	x	x		
2	218A	Storage outside Classroom 218 and at end of Hallway	Concrete Block Wall	Non Suspect ACM	x	486	SF	x	x		
2	218A	Storage outside Classroom 218 and at end of Hallway	9" x 9" Floor Tile and Mastic	Confirmed	NF1	159	SF	ND	NRN		
2	218A	Storage outside Classroom 218 and at end of Hallway	9" x 9" Floor Tile and Mastic	Confirmed	NF1	21	SF	ND	NRN		

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance							
		Robert Morris Elementary School (2390) Year Built: 1964	___ Three- Year Reinspection IX							
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ AIR/EIE							
		Prepared by: Bernard J. Bryson	__X__ Asbestos Abatement Activity							
		Certification # 0437 Date: 1/28/2019	___ Bulk Sampling Event							
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
F l o o r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
2	218B	Women's Restroom by Classroom 218	Fiberglass Pipe Fitting Insulation	Non Suspect ACM	x	2	EA	x	x	
2	218B	Women's Restroom by Classroom 218	Plaster Ceiling	NAD	x	225	SF	x	x	
2	218B	Women's Restroom by Classroom 218	Concrete Block Wall	Non Suspect ACM	x	600	SF	x	x	
2	218B	Women's Restroom by Classroom 218	12" x 12" Floor Tile and Mastic	Assumed	NF1	225	SF	ND	NRN	
2	H211	Hallway from Classroom 208 to 218	Concrete Block Wall	Non Suspect ACM	x	2,916	SF	x	x	
2	H211	Hallway from Classroom 208 to 218	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,372	SF	ND	NRN	
2	H211	Hallway from Classroom 208 to 218	Ceiling Tile 1' x 1'	NAD	x	1,372	SF	x	x	
3	319	Classroom 319	Ceiling Tile 2' x 4'	NAD	x	1,102	SF	x	x	
3	319	Classroom 319	Ceiling Tile 2' x 4'	NAD	x	16	SF	x	x	
3	319	Classroom 319	Concrete Block Wall	Non Suspect ACM	x	1,380	SF	x	x	
3	319	Classroom 319	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,118	SF	ND	NRN	
3	319	Classroom 319	Sink Undercoat Mastic	Confirmed	NF1	16	SF	ND	NRN	
3	319	Classroom 319	Blackboard Glue Dots	Assumed	NF1	10	SF	ND	NRN	
3	319A	Classroom 319 Storage	Plaster Ceiling	NAD	x	100	SF	x	x	
3	319A	Classroom 319 Storage	Concrete Block Wall	Non Suspect ACM	x	400	SF	x	x	
3	319A	Classroom 319 Storage	9" x 9" Floor Tile and Mastic	Confirmed	NF1	100	SF	ND	NRN	
3	318B	Storage Room next to Classroom 318	Fiberglass Pipe Insulation	Non Suspect ACM	x	42	LF	x	x	
3	318B	Storage Room next to Classroom 318	Plaster Ceiling	NAD	x	135	SF	x	x	
3	318B	Storage Room next to Classroom 318	Concrete Block Wall	Non Suspect ACM	x	400	SF	x	x	
3	318B	Storage Room next to Classroom 318	9" x 9" Floor Tile and Mastic	Confirmed	NF1	135	SF	ND	NRN	
3	318	Classroom 318	Ceiling Tile 2' x 4'	NAD	x	1,078	SF	x	x	
3	318	Classroom 318	Ceiling Tile 2' x 4'	NAD	x	40	SF	x	x	

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance								
		Robert Morris Elementary School (2390)	___ Three- Year Reinspection IX								
		Year Built: 1964	__X__ AIR/EIE								
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity								
		Prepared by: Bernard J. Bryson	___ Bulk Sampling Event								
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218								
F l o o r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes	
3	318	Classroom 318	Concrete Block Wall	Non Suspect ACM	x	1,380	SF	x	x		
3	318	Classroom 318	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,118	SF	ND	NRN		
3	318	Classroom 318	Blackboard Glue Dots	Assumed	NF1	10	SF	ND	NRN		
3	318A	Classroom 318 Storage	Ceiling Tile 2' x 4'	NAD	x	72	SF	x	x		
3	318A	Classroom 318 Storage	Concrete Block Wall	Non Suspect ACM	x	374	SF	x	x		
3	318A	Classroom 318 Storage	9" x 9" Floor Tile and Mastic	Confirmed	NF1	72	SF	ND	NRN		
3	317	Classroom 317	Ceiling Tile 2' x 4'	NAD	x	420	SF	x	x		
3	317	Classroom 317	Ceiling Tile 2' x 4'	NAD	x	30	SF	x	x		
3	317	Classroom 317	Concrete Block Wall	Non Suspect ACM	x	860	SF	x	x		
3	317	Classroom 317	9" x 9" Floor Tile and Mastic	Confirmed	NF1	450	SF	ND	NRN		
3	317	Classroom 317	Blackboard Glue Dots	Assumed	NF1	8	SF	ND	NRN		
3	315	Classroom 315	Ceiling Tile 2' x 4'	NAD	x	936	SF	x	x		
3	315	Classroom 315	Plaster Ceiling	NAD	x	50	SF	x	x		
3	315	Classroom 315	Plaster Wall	NAD	x	100	SF	x	x		
3	315	Classroom 315	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x		
3	315	Classroom 315	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN		
3	S33	Stairwell next to Classroom 315	Plaster Ceiling	NAD	x	260	SF	x	x		
3	S33	Stairwell next to Classroom 315	Concrete Block Wall	Non Suspect ACM	x	792	SF	x	x		
3	S33	Stairwell next to Classroom 315	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN		
3	S33	Stairwell next to Classroom 315	Cement Floor	Non Suspect ACM	x	260	SF	x	x		
3	316	Classroom 316	Ceiling Tile 2' x 4'	NAD	x	936	SF	x	x		
3	316	Classroom 316	Plaster Ceiling	NAD	x	50	SF	x	x		
3	316	Classroom 316	Plaster Wall	NAD	x	100	SF	x	x		
3	316	Classroom 316	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x		

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance							
		Robert Morris Elementary School (2390)	___ Three- Year Reinspection IX							
		Year Built: 1964	__X__ AIR/EIE							
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity							
		Prepared by: Bernard J. Bryson	___ Bulk Sampling Event							
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
F l o o r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
3	316	Classroom 316	12" x 12" Floor Tile and Mastic	Assumed	NF1	936	SF	ND	NRN	
3	313	Classroom 313	Ceiling Tile 2' x 4'	NAD	x	896	SF	x	x	
3	313	Classroom 313	Ceiling Tile 2' x 4'	NAD	x	40	SF	x	x	
3	313	Classroom 313	Plaster Ceiling	NAD	x	50	SF	x	x	
3	313	Classroom 313	Plaster Wall	NAD	x	100	SF	x	x	
3	313	Classroom 313	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
3	313	Classroom 313	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN	
3	313	Classroom 313	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
3	323	Storage next to Classroom 313	Fiberglass Pipe Insulation	Non Suspect ACM	x	30	LF	x	x	
3	323	Storage next to Classroom 313	Plaster Ceiling	NAD	x	364	SF	x	x	
3	323	Storage next to Classroom 313	Concrete Block Wall	Non Suspect ACM	x	800	SF	x	x	
3	323	Storage next to Classroom 313	9" x 9" Floor Tile and Mastic	Confirmed	NF1	364	SF	ND	NRN	
3	324	Men's Restroom across from Library	Plaster Ceiling	NAD	x	44	SF	x	x	
3	324	Men's Restroom across from Library	Concrete Block Wall	Non Suspect ACM	x	240	SF	x	x	
3	324	Men's Restroom across from Library	Cement Floor	Non Suspect ACM	x	44	SF	x	x	
3	PC324	Pipe Chase next to Men's Restroom Door	x	x	x	x	x	x	x	Not Accessed
3	314	Library (310, 312, & 314)	Ceiling Tile 2' x 4'	NAD	x	1,872	SF	x	x	
3	314	Library (310, 312, & 314)	Plaster Ceiling	NAD	x	100	SF	x	x	
3	314	Library (310, 312, & 314)	Sheetrock Wall	Non Suspect ACM	x	288	SF	x	x	
3	314	Library (310, 312, & 314)	Plaster Wall	NAD	x	200	SF	x	x	
3	314	Library (310, 312, & 314)	Concrete Block Wall	Non Suspect ACM	x	1,960	SF	x	x	
3	314	Library (310, 312, & 314)	Carpet	Non Suspect ACM	x	1,872	SF	x	x	
3	314A	Library Office	Ceiling Tile 2' x 4'	NAD	x	252	SF	x	x	
3	314A	Library Office	Sheetrock Wall	NAD	x	200	SF	x	x	
3	314A	Library Office	Joint Compound	NAD	x	50	SF	x	x	

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined			
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance										
		Robert Morris Elementary School (2390)	___ Three- Year Reinspection IX										
		Year Built: 1964	__X__ AIR/EIE										
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity										
		Prepared by: Bernard J. Bryson	___ Bulk Sampling Event										
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218										
F	l	o	r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
3				314A	Library Office	Carpet	Non Suspect ACM	x	252	SF	x	x	
3				314A	Library Office	Concrete Block Wall	Non Suspect ACM	x	120	SF	x	x	
3				314B	Library Storage	Ceiling Tile 2' x 4'	NAD	x	260	SF	x	x	
3				314B	Library Storage	Plaster Ceiling	NAD	x	50	SF	x	x	
3				314B	Library Storage	Sheetrock Wall	NAD	x	532	SF	x	x	
3				314B	Library Storage	Joint Compound	NAD	x	133	SF	x	x	
3				314B	Library Storage	Carpet	Non Suspect ACM	x	260	SF	x	x	
3				314B	Library Storage	Plaster Wall	NAD	x	100	SF	x	x	
3				308	Classroom 308	Ceiling Tile 2' x 4'	NAD	x	926	SF	x	x	
3				308	Classroom 308	Ceiling Tile 2' x 4'	NAD	x	10	SF	x	x	
3				308	Classroom 308	Plaster Ceiling	NAD	x	50	SF	x	x	
3				308	Classroom 308	Plaster Wall	NAD	x	100	SF	x	x	
3				308	Classroom 308	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
3				308	Classroom 308	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN	
3				308	Classroom 308	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
3				308	Classroom 308	Fiberglass Pipe Insulation	Non Suspect ACM	x	10	LF	x	x	
3				324A	Custodial Closet next to Elevator	Fiberglass Pipe Insulation	Non Suspect ACM	x	30	LF	x	x	
3				324A	Custodial Closet next to Elevator	Plaster Ceiling	NAD	x	24	SF	x	x	
3				324A	Custodial Closet next to Elevator	Concrete Block Wall	Non Suspect ACM	x	220	SF	x	x	
3				324A	Custodial Closet next to Elevator	9" x 9" Floor Tile and Mastic	Confirmed	NF1	24	SF	ND	NRN	
3				306	Classroom 306	Ceiling Tile 2' x 4'	NAD	x	880	SF	x	x	
3				306	Classroom 306	Ceiling Tile 2' x 4'	NAD	x	56	SF	x	x	
3				306	Classroom 306	Plaster Ceiling	NAD	x	50	SF	x	x	
3				306	Classroom 306	Plaster Wall	NAD	x	100	SF	x	x	
3				306	Classroom 306	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance							
		Robert Morris Elementary School (2390) Year Built: 1964	___ Three- Year Reinspection IX							
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ AIR/EIE							
		Prepared by: Bernard J. Bryson	___ Bulk Sampling Event							
		Certification # 0437 Date: 1/28/2019	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
		Classroom Modernization Project								
<i>F l o o r</i>	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
3	306	Classroom 306	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN	
3	306	Classroom 306	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
3	S31	Stairwell next to Elevator	Plaster Ceiling	NAD	x	260	SF	x	x	
3	S31	Stairwell next to Elevator	Concrete Block Wall	Non Suspect ACM	x	720	SF	x	x	
3	S31	Stairwell next to Elevator	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN	
3	S31	Stairwell next to Elevator	Cement Floor	Non Suspect ACM	x	260	SF	x	x	
3	322	Women's Restroom across from Classroom 304	Plaster Ceiling	NAD	x	176	SF	x	x	
3	322	Women's Restroom across from Classroom 304	Concrete Block Wall	Non Suspect ACM	x	540	SF	x	x	
3	322	Women's Restroom across from Classroom 304	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN	
3	322	Women's Restroom across from Classroom 304	Cement Floor	Non Suspect ACM	x	176	SF	x	x	
3	321	Girl's Restroom across from Classroom 304	Plaster Ceiling	NAD	x	338	SF	x	x	
3	321	Girl's Restroom across from Classroom 304	Concrete Block Wall	Non Suspect ACM	x	702	SF	x	x	
3	321	Girl's Restroom across from Classroom 304	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN	
3	321	Girl's Restroom across from Classroom 304	Cement Floor	Non Suspect ACM	x	338	SF	x	x	
3	PC321	Pipe Chase in Girl's Restroom across from Classroom 304	x	x	x	x	x	x	x	Not Accessed
3	320	Boys Restroom next to Classroom 303	Plaster Ceiling	NAD	x	208	SF	x	x	
3	320	Boys Restroom next to Classroom 303	Concrete Block Wall	Non Suspect ACM	x	612	SF	x	x	
3	320	Boys Restroom next to Classroom 303	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN	
3	320	Boys Restroom next to Classroom 303	Cement Floor	Non Suspect ACM	x	208	SF	x	x	
3	PC320	Pipe Chase in Boys Restroom next to Classroom 303	x	x	x	x	x	x	x	Not Accessed
3	304	Classroom 304	Ceiling Tile 2' x 4'	NAD	x	872	SF	x	x	

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined			
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance											
		Robert Morris Elementary School (2390)	___ Three- Year Reinspection IX											
		Year Built: 1964	__X__ AIR/EIE											
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity											
		Prepared by: Bernard J. Bryson	___ Bulk Sampling Event											
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218											
F	l	o	o	r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
3					304	Classroom 304	Ceiling Tile 2' x 4'	NAD	x	64	SF	x	x	
3					304	Classroom 304	Plaster Ceiling	NAD	x	50	SF	x	x	
3					304	Classroom 304	Plaster Wall	NAD	x	100	SF	x	x	
3					304	Classroom 304	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
3					304	Classroom 304	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN	
3					304	Classroom 304	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
3					302	Classroom 302	Ceiling Tile 2' x 4'	NAD	x	880	SF	x	x	
3					302	Classroom 302	Ceiling Tile 2' x 4'	NAD	x	56	SF	x	x	
3					302	Classroom 302	Plaster Ceiling	NAD	x	50	SF	x	x	
3					302	Classroom 302	Plaster Wall	NAD	x	100	SF	x	x	
3					302	Classroom 302	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
3					302	Classroom 302	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN	
3					302	Classroom 302	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
3					303	Classroom 303	Ceiling Tile 2' x 4'	NAD	x	916	SF	x	x	
3					303	Classroom 303	Ceiling Tile 2' x 4'	NAD	x	20	SF	x	x	
3					303	Classroom 303	Plaster Ceiling	NAD	x	50	SF	x	x	
3					303	Classroom 303	Plaster Wall	NAD	x	100	SF	x	x	
3					303	Classroom 303	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
3					303	Classroom 303	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN	
3					303	Classroom 303	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
3					301	Classroom 301	Ceiling Tile 2' x 4'	NAD	x	566	SF	x	x	
3					301	Classroom 301	Ceiling Tile 2' x 4'	NAD	x	10	SF	x	x	
3					301	Classroom 301	Concrete Block Wall	Non Suspect ACM	x	900	SF	x	x	
3					301	Classroom 301	9" x 9" Floor Tile and Mastic	Confirmed	NF1	576	SF	ND	NRN	

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance							
		Robert Morris Elementary School (2390)	___ Three- Year Reinspection IX							
		Year Built: 1964	__X__ AIR/EIE							
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity							
		Prepared by: Bernard J. Bryson	___ Bulk Sampling Event							
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
F l o o r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
3	301	Classroom 301	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
3	300	Classroom 300	Ceiling Tile 2' x 4'	NAD	x	886	SF	x	x	
3	300	Classroom 300	Ceiling Tile 2' x 4'	NAD	x	50	SF	x	x	
3	300	Classroom 300	Plaster Ceiling	NAD	x	50	SF	x	x	
3	300	Classroom 300	Plaster Wall	NAD	x	100	SF	x	x	
3	300	Classroom 300	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
3	300	Classroom 300	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN	
3	300	Classroom 300	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
3	S32	Stairwell next to Classroom 301	Plaster Ceiling	NAD	x	260	SF	x	x	
3	S32	Stairwell next to Classroom 301	Concrete Block Wall	Non Suspect ACM	x	792	SF	x	x	
3	S32	Stairwell next to Classroom 301	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN	
3	S32	Stairwell next to Classroom 301	Cement Floor	Non Suspect ACM	x	260	SF	x	x	
3	H315	Hallway from Library to Classroom 300	Concrete Block Wall	Non Suspect ACM	x	2,988	SF	x	x	
3	H315	Hallway from Library to Classroom 300	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,413	SF	ND	NRN	
3	H315	Hallway from Library to Classroom 300	Ceiling Tile 1' x 1'	NAD	x	1,399	SF	x	x	
3	H315	Hallway from Library to Classroom 300	Ceiling Tile 1' x 1'	NAD	x	14	SF	x	x	
3	H315	Hallway from Library to Classroom 300	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN	
3	H313	Hallway from Classroom 308 to 318	Concrete Block Wall	Non Suspect ACM	x	2,718	SF	x	x	
3	H313	Hallway from Classroom 308 to 318	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,144	SF	ND	NRN	
3	H313	Hallway from Classroom 308 to 318	Ceiling Tile 1' x 1'	NAD	x	1,142	SF	x	x	
3	H313	Hallway from Classroom 308 to 318	Ceiling Tile 1' x 1'	NAD	x	2	SF	x	x	
4	400	Classroom 400	Ceiling Tile 2' x 4'	NAD	x	912	SF	x	x	
4	400	Classroom 400	Ceiling Tile 2' x 4'	NAD	x	24	SF	x	x	
4	400	Classroom 400	Plaster Ceiling	NAD	x	50	SF	x	x	
4	400	Classroom 400	Plaster Wall	NAD	x	100	SF	x	x	

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	6 Month Surveillance								
		Robert Morris Elementary School (2390) Year Built: 1964	Three- Year Reinspection IX								
		2600 W. Thompson Street, Philadelphia, PA 19121	X AIR/EIE								
		Prepared by: Bernard J. Bryson	X Asbestos Abatement Activity								
		Certification # 0437 Date: 1/28/2019	Bulk Sampling Event								
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218								
F l o o r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes	
4	400	Classroom 400	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x		
4	400	Classroom 400	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN		
4	400	Classroom 400	Blackboard Glue Dots	Assumed	NF1	10	SF	ND	NRN		
4	S42	Stairwell next to Classroom 401	Plaster Ceiling	NAD	x	260	SF	x	x		
4	S42	Stairwell next to Classroom 401	Concrete Block Wall	Non Suspect ACM	x	720	SF	x	x		
4	S42	Stairwell next to Classroom 401	Radiator Insulation	Assumed	FRI	11	SF	ND	NRN		
4	S42	Stairwell next to Classroom 401	Cement Floor	Non Suspect ACM	x	260	SF	x	x		
4	401	Classroom 401	Ceiling Tile 2' x 4'	NAD	x	536	SF	x	x		
4	401	Classroom 401	Ceiling Tile 2' x 4'	NAD	x	40	SF	x	x		
4	401	Classroom 401	Concrete Block Wall	Non Suspect ACM	x	960	SF	x	x		
4	401	Classroom 401	9" x 9" Floor Tile and Mastic	Confirmed	NF1	576	SF	ND	NRN		
4	401	Classroom 401	Blackboard Glue Dots	Assumed	NF1	10	SF	ND	NRN		
4	402	Classroom 402	Ceiling Tile 2' x 4'	NAD	x	900	SF	x	x		
4	402	Classroom 402	Ceiling Tile 2' x 4'	NAD	x	36	SF	x	x		
4	402	Classroom 402	Plaster Ceiling	NAD	x	50	SF	x	x		
4	402	Classroom 402	Plaster Wall	NAD	x	100	SF	x	x		
4	402	Classroom 402	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x		
4	402	Classroom 402	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN		
4	402	Classroom 402	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN		
4	403	Classroom 403	Ceiling Tile 2' x 4'	NAD	x	856	SF	x	x		
4	403	Classroom 403	Plaster Ceiling	NAD	x	50	SF	x	x		
4	403	Classroom 403	Plaster Wall	NAD	x	100	SF	x	x		
4	403	Classroom 403	Concrete Block Wall	Non Suspect ACM	x	1240	SF	x	x		

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined				
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance											
		Robert Morris Elementary School (2390) Year Built: 1964	___ Three- Year Reinspection IX											
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ AIR/EIE											
		Prepared by: Bernard J. Bryson	__X__ Asbestos Abatement Activity											
		Certification # 0437 Date: 1/28/2019	___ Bulk Sampling Event											
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218											
F	l	o	o	r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
4					403	Classroom 403	9" x 9" Floor Tile and Mastic	Confirmed	NF1	0	SF	ND	NRN	ALL FLOOR TILES HAVE BEEN REMOVED; EXPOSED MASTIC REMAINS.
4					403	Classroom 403	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
4					404	Classroom 404	Ceiling Tile 2' x 4'	NAD	x	872	SF	x	x	
4					404	Classroom 404	Ceiling Tile 2' x 4'	NAD	x	64	SF	x	x	
4					404	Classroom 404	Plaster Ceiling	NAD	x	50	SF	x	x	
4					404	Classroom 404	Plaster Wall	NAD	x	100	SF	x	x	
4					404	Classroom 404	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
4					404	Classroom 404	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN	
4					404	Classroom 404	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
4					420	Boys Restroom next to Classroom 403	Plaster Ceiling	NAD	x	208	SF	x	x	
4					420	Boys Restroom next to Classroom 403	Concrete Block Wall	Non Suspect ACM	x	720	SF	x	x	
4					420	Boys Restroom next to Classroom 403	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN	
4					420	Boys Restroom next to Classroom 403	Cement Floor	Non Suspect ACM	x	208	SF	x	x	
4					PC420	Pipe Chase in Boys Restroom next to Classroom 403	x	x	x	x	x	x	x	Not Accessed
4					421	Girl's Restroom across from Classroom 404	Plaster Ceiling	NAD	x	338	SF	x	x	
4					421	Girl's Restroom across from Classroom 404	Concrete Block Wall	Non Suspect ACM	x	780	SF	x	x	
4					421	Girl's Restroom across from Classroom 404	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN	
4					421	Girl's Restroom across from Classroom 404	Cement Floor	Non Suspect ACM	x	338	SF	x	x	
4					PC421	Pipe Chase in Girl's Restroom across from Classroom 404	x	x	x	x	x	x	x	Not Accessed
4					422	Women's Restroom across from Classroom 404	Plaster Ceiling	NAD	x	176	SF	x	x	
4					422	Women's Restroom across from Classroom 404	Concrete Block Wall	Non Suspect ACM	x	480	SF	x	x	

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance								
		Robert Morris Elementary School (2390) Year Built: 1964	___ Three- Year Reinspection IX								
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ AIR/EIE								
		Prepared by: Bernard J. Bryson	__X__ Asbestos Abatement Activity								
		Certification # 0437 Date: 1/28/2019	___ Bulk Sampling Event								
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218								
<i>F l o o r</i>	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes	
4	422	Women's Restroom across from Classroom 404	Radiator Insulation	Assumed	FRI	6	SF	ND	NRN		
4	422	Women's Restroom across from Classroom 404	Cement Floor	Non Suspect ACM	x	176	SF	x	x		
4	406	Classroom 406	Ceiling Tile 2' x 4'	NAD	x	936	SF	x	x		
4	406	Classroom 406	Plaster Ceiling	NAD	x	50	SF	x	x		
4	406	Classroom 406	Plaster Wall	NAD	x	100	SF	x	x		
4	406	Classroom 406	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x		
4	406	Classroom 406	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN		
4	406	Classroom 406	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN		
4	S41	Stairwell next to Elevator	Plaster Ceiling	NAD	x	260	SF	x	x		
4	S41	Stairwell next to Elevator	Concrete Block Wall	Non Suspect ACM	x	792	SF	x	x		
4	S41	Stairwell next to Elevator	Cement Floor	Non Suspect ACM	x	260	SF	x	x		
4	444	Custodial Closet next to Elevator	Pipe Fitting Insulation	NAD	x	3	EA	x	x		
4	444	Custodial Closet next to Elevator	Fiberglass Pipe Insulation	Non Suspect ACM	x	20	LF	x	x		
4	444	Custodial Closet next to Elevator	Plaster Ceiling	NAD	x	24	SF	x	x		
4	444	Custodial Closet next to Elevator	Concrete Block Wall	Non Suspect ACM	x	220	SF	x	x		
4	444	Custodial Closet next to Elevator	9" x 9" Floor Tile and Mastic	Confirmed	NF1	24	SF	ND	NRN		
4	408	Classroom 408	Ceiling Tile 2' x 4'	NAD	x	900	SF	x	x		
4	408	Classroom 408	Ceiling Tile 2' x 4'	NAD	x	36	SF	x	x		
4	408	Classroom 408	Plaster Ceiling	NAD	x	50	SF	x	x		
4	408	Classroom 408	Plaster Wall	NAD	x	100	SF	x	x		
4	408	Classroom 408	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x		
4	408	Classroom 408	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN		
4	408	Classroom 408	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN		

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance							
		Robert Morris Elementary School (2390) Year Built: 1964	___ Three- Year Reinspection IX							
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ AIR/EIE							
		Prepared by: Bernard J. Bryson	__X__ Asbestos Abatement Activity							
		Certification # 0437 Date: 1/28/2019	___ Bulk Sampling Event							
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
<i>F l o o r</i>	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
4	410	Cafeteria (410)	Ceiling Tile 2' x 4'	NAD	x	920	SF	x	x	
4	410	Cafeteria (410)	Ceiling Tile 2' x 4'	NAD	x	16	SF	x	x	
4	410	Cafeteria (410)	Plaster Ceiling	NAD	x	50	SF	x	x	
4	410	Cafeteria (410)	Plaster Wall	NAD	x	100	SF	x	x	
4	410	Cafeteria (410)	Concrete Block Wall	Non Suspect ACM	x	1,000	SF	x	x	
4	410	Cafeteria (410)	Partition Room Dividers	Non Suspect ACM	x	240	SF	x	x	
4	410	Cafeteria (410)	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN	
4	410	Cafeteria (410)	Blackboard Glue Dots	Assumed	NF1	5	SF	ND	NRN	
4	412	Cafeteria (412)	Ceiling Tile 2' x 4'	NAD	x	920	SF	x	x	
4	412	Cafeteria (412)	Ceiling Tile 2' x 4'	NAD	x	16	SF	x	x	
4	412	Cafeteria (412)	Plaster Ceiling	NAD	x	50	SF	x	x	
4	412	Cafeteria (412)	Plaster Wall	NAD	x	100	SF	x	x	
4	412	Cafeteria (412)	Concrete Block Wall	Non Suspect ACM	x	1,000	SF	x	x	
4	412	Cafeteria (412)	Partition Room Dividers	Non Suspect ACM	x	240	SF	x	x	
4	412	Cafeteria (412)	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN	
4	412	Cafeteria (412)	Blackboard Glue Dots	Assumed	NF1	5	SF	ND	NRN	
4	424	Men's Restroom across from Classroom 410	Plaster Ceiling	NAD	x	44	SF	x	x	
4	424	Men's Restroom across from Classroom 410	Concrete Block Wall	Non Suspect ACM	x	300	SF	x	x	
4	424	Men's Restroom across from Classroom 410	Cement Floor	Non Suspect ACM	x	44	SF	x	x	
4	PC424	Pipe Chase next to Men's Restroom Door	x	x	x	x	x	x	x	Not Accessed
4	423	Storage next to Classroom 413	Fiberglass Pipe Insulation	Non Suspect ACM	x	20	LF	x	x	
4	423	Storage next to Classroom 413	Plaster Ceiling	NAD	x	364	SF	x	x	
4	423	Storage next to Classroom 413	Concrete Block Wall	Non Suspect ACM	x	800	SF	x	x	

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance								
		Robert Morris Elementary School (2390)	___ Three- Year Reinspection IX								
		Year Built: 1964	__X__ AIR/EIE								
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity								
		Prepared by: Bernard J. Bryson	___ Bulk Sampling Event								
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218								
F l o o r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes	
4	423	Storage next to Classroom 413	9" x 9" Floor Tile and Mastic	Confirmed	NF1	364	SF	ND	NRN		
4	413	Classroom 413	Ceiling Tile 2' x 4'	NAD	x	888	SF	x	x		
4	413	Classroom 413	Ceiling Tile 2' x 4'	NAD	x	48	SF	x	x	Limited Access in 413	
4	413	Classroom 413	Plaster Ceiling	NAD	x	50	SF	x	x		
4	413	Classroom 413	Plaster Wall	NAD	x	100	SF	x	x		
4	413	Classroom 413	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x		
4	413	Classroom 413	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN		
4	413	Classroom 413	Blackboard Glue Dots	Assumed	NF1	20	SF	ND	NRN		
4	414	Classroom 414	Ceiling Tile 2' x 4'	NAD	x	920	SF	x	x	older/faded tan	
4	414	Classroom 414	Ceiling Tile 2' x 4'	NAD	x	16	SF	x	x	newer, bright white	
4	414	Classroom 414	Plaster Ceiling	NAD	x	50	SF	x	x		
4	414	Classroom 414	Plaster Wall	NAD	x	100	SF	x	x		
4	414	Classroom 414	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x		
4	414	Classroom 414	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN		
4	414	Classroom 414	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN		
4	415	Classroom 415	Ceiling Tile 2' x 4'	NAD	x	856	SF	x	x	older/faded tan	
4	415	Classroom 415	Ceiling Tile 2' x 4'	NAD	x	80	SF	x	x	newer, bright white	
4	415	Classroom 415	Plaster Ceiling	NAD	x	50	SF	x	x		
4	415	Classroom 415	Plaster Wall	NAD	x	100	SF	x	x		
4	415	Classroom 415	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x		
4	415	Classroom 415	9" x 9" Floor Tile and Mastic	Confirmed	NF1	936	SF	ND	NRN		
4	415	Classroom 415	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN		
4	416	Classroom 416	Ceiling Tile 2' x 4'	NAD	x	936	SF	x	x	newer, bright white	
4	416	Classroom 416	Plaster Ceiling	NAD	x	50	SF	x	x		

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined			
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance										
		Robert Morris Elementary School (2390)	___ Three- Year Reinspection IX										
		Year Built: 1964	__X__ AIR/EIE										
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ Asbestos Abatement Activity										
		Prepared by: Bernard J. Bryson	___ Bulk Sampling Event										
		Certification # 0437 Date: 1/28/2019 Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218										
<i>F</i>	<i>l</i>	<i>o</i>	<i>r</i>	<i>Space #</i>	<i>On Site Room Name</i>	<i>Material Description</i>	<i>Confirmed, Assumed, NAD, Non Suspect ACM</i>	<i>Type (Code 1)</i>	<i>Amount of Material</i>	<i>SF LF EA</i>	<i>Condition (Code 2)</i>	<i>Action (Code 3)</i>	<i>Comments/Description/Notes</i>
4				416	Classroom 416	Plaster Wall	NAD	x	100	SF	x	x	
4				416	Classroom 416	Concrete Block Wall	Non Suspect ACM	x	1,240	SF	x	x	
4				416	Classroom 416	12" x 12" Floor Tile and Mastic	Assumed	NF1	936	SF	ND	NRN	
4				S43	Stairwell next to Classroom 415	Plaster Ceiling	NAD	x	260	SF	x	x	
4				S43	Stairwell next to Classroom 415	Concrete Block Wall	Non Suspect ACM	x	1,152	SF	x	x	
4				S43	Stairwell next to Classroom 415	Radiator Insulation	Assumed	FRI	10	SF	ND	NRN	
4				S43	Stairwell next to Classroom 415	Cement Floor	Non Suspect ACM	x	260	SF	x	x	
4				425	Storage next to Classroom 417	Plaster Ceiling	NAD	x	156	SF	x	x	
4				425	Storage next to Classroom 417	Concrete Block Wall	Non Suspect ACM	x	640	SF	x	x	
4				425	Storage next to Classroom 417	9" x 9" Floor Tile and Mastic	Confirmed	NF1	156	SF	ND	NRN	
4				417	Classroom 417	Ceiling Tile 2' x 4'	NAD	x	410	SF	x	x	older/faded tan
4				417	Classroom 417	Ceiling Tile 2' x 4'	NAD	x	40	SF	x	x	newer, bright white
4				417	Classroom 417	Concrete Block Wall	Non Suspect ACM	x	860	SF	x	x	
4				417	Classroom 417	9" x 9" Floor Tile and Mastic	Confirmed	NF1	450	SF	ND	NRN	
4				417	Classroom 417	Blackboard Glue Dots	Assumed	NF1	8	SF	ND	NRN	
4				418	Classroom 418	Fiberglass Pipe Insulation	Non Suspect ACM	x	4	LF	x	x	
4				418	Classroom 418	Ceiling Tile 2' x 4'	NAD	x	1,118	SF	x	x	newer, bright white
4				418	Classroom 418	Concrete Block Wall	Non Suspect ACM	x	1,380	SF	x	x	
4				418	Classroom 418	Sink Undercoat Mastic	Confirmed	NF1	7	SF	ND	NRN	
4				418	Classroom 418	12" x 12" Floor Tile and Mastic	Assumed	NF1	1,118	SF	ND	NRN	
4				419	Classroom 419	Ceiling Tile 2' x 4'	NAD	x	1,084	SF	x	x	
4				419	Classroom 419	Ceiling Tile 2' x 4'	NAD	x	60	SF	x	x	
4				419	Classroom 419	Plaster Ceiling	NAD	x	50	SF	x	x	

School District of Philadelphia Asbestos Inspection Report - Section 9 Robert Morris Elementary School (2390) Year Built: 1964 2600 W. Thompson Street, Philadelphia, PA 19121 Prepared by: Bernard J. Bryson Certification # 0437 Date: 1/28/2019 Classroom Modernization Project		Survey Type								Q/U = Quantity Undetermined				
		___ 6 Month Surveillance												
		___ Three- Year Reinspection IX												
		__X__ AIR/EIE												
		__X__ Asbestos Abatement Activity												
		___ Bulk Sampling Event												
		Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218												
F	l	o	o	r	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
4					419	Classroom 419	Plaster Wall	NAD	x	100	SF	x	x	Located above Closets in Classrooms
4					419	Classroom 419	Concrete Block Wall	Non Suspect ACM	x	1,400	SF	x	x	
4					419	Classroom 419	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,144	SF	ND	NRN	
4					419	Classroom 419	Blackboard Glue Dots	Assumed	NF1	40	SF	ND	NRN	
4					419A	Storage next to Classroom 419	Plaster Ceiling	NAD	x	280	SF	x	x	
4					419A	Storage next to Classroom 419	Concrete Block Wall	Non Suspect ACM	x	860	SF	x	x	
4					419A	Storage next to Classroom 419	9" x 9" Floor Tile and Mastic	Confirmed	NF1	280	SF	ND	NRN	
4					H418	Hallway from Classroom 408 to 419	Concrete Block Wall	Non Suspect ACM	x	3,060	SF	x	x	
4					H418	Hallway from Classroom 408 to 419	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,296	SF	ND	NRN	
4					H418	Hallway from Classroom 408 to 419	Radiator Insulation	Assumed	FRI	24	SF	ND	NRN	
4					H418	Hallway from Classroom 408 to 419	Ceiling Tile 1' x 1'	NAD	x	1,296	SF	x	x	older/faded tan, big dots
4					H420	Hallway from Custodial Closet to Classroom 400	Concrete Block Wall	Non Suspect ACM	x	3,180	SF	x	x	
4					H420	Hallway from Custodial Closet to Classroom 400	9" x 9" Floor Tile and Mastic	Confirmed	NF1	1,208	SF	ND	NRN	
4					H420	Hallway from Custodial Closet to Classroom 400	Radiator Insulation	Assumed	FRI	16	SF	ND	NRN	
4					H420	Hallway from Custodial Closet to Classroom 400	Ceiling Tile 1' x 1'	NAD	x	1,052	SF	x	x	
4					H420	Hallway from Custodial Closet to Classroom 400	Ceiling Tile 1' x 1'	NAD	x	100	SF	x	x	
4					H420	Hallway from Custodial Closet to Classroom 400	Ceiling Tile 1' x 1'	NAD	x	40	SF	x	x	newer/brighter white, big dots

		School District of Philadelphia	Survey Type								Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	6 Month Surveillance								
		Robert Morris Elementary School (2390) Year Built: 1964	Three- Year Reinspection IX								
		2600 W. Thompson Street, Philadelphia, PA 19121	X AIR/EIE								
		Prepared by: Bernard J. Bryson	X Asbestos Abatement Activity								
		Certification # 0437 Date: 1/28/2019	Bulk Sampling Event								
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218								
Floor	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes	
4	H420	Hallway from Custodial Closet to Classroom 400	Ceiling Tile 2' x 4'	NAD	x	16	SF	x	x		
B	S02	Stairwell by Building Engineer's Office	Plaster Ceiling	NAD	x	60	SF	x	x		
B	S02	Stairwell by Building Engineer's Office	Cement Floor	Non Suspect ACM	x	60	SF	x	x		
B	S02	Stairwell by Building Engineer's Office	Concrete Block Wall	Non Suspect ACM	x	240	SF	x	x		
B	4B	Pump Room behind Building Engineer's Office	Fiberglass Pipe Insulation	Non Suspect ACM	x	30	LF	x	x		
B	4B	Pump Room behind Building Engineer's Office	Concrete Ceiling	Non Suspect ACM	x	260	SF	x	x		
B	4B	Pump Room behind Building Engineer's Office	Concrete Block Wall	Non Suspect ACM	x	1000	SF	x	x		
B	4B	Pump Room behind Building Engineer's Office	Cement Floor	Non Suspect ACM	x	260	SF	x	x		
B	5B	Building Engineer's Office	Plaster Ceiling	NAD	x	60	SF	x	x	Pipe Chase access in Room	
B	5B	Building Engineer's Office	Concrete Block Wall	Non Suspect ACM	x	250	SF	x	x		
B	5B	Building Engineer's Office	Cement Floor	Non Suspect ACM	x	60	SF	x	x		
B	PC5B	Pipe Chase in Building Engineer's Office	x	x	x	x	x	x	x	Not Accessed	
B	5BB	Building Engineer's Office - Restroom	Plaster Ceiling	NAD	x	64	SF	x	x		
B	5BB	Building Engineer's Office - Restroom	Concrete Block Wall	Non Suspect ACM	x	250	SF	x	x		
B	5BB	Building Engineer's Office - Restroom	12" x 12" Floor Tile and Mastic	Assumed	NF1	64	SF	ND	NRN		
B	6B	Women's Staff Locker Room	Plaster Ceiling	NAD	x	60	SF	x	x		
B	6B	Women's Staff Locker Room	Concrete Block Wall	Non Suspect ACM	x	250	SF	x	x		
B	6B	Women's Staff Locker Room	Cement Floor	Non Suspect ACM	x	60	SF	x	x		
B	6BB	Maintenance Women's Locker Room - Restroom	Fiberglass Pipe Insulation	Non Suspect ACM	x	20	LF	x	x		
B	6BB	Maintenance Women's Locker Room - Restroom	Plaster Ceiling	NAD	x	70	SF	x	x		

		School District of Philadelphia	Survey Type							Q/U = Quantity Undetermined
		Asbestos Inspection Report - Section 9	___ 6 Month Surveillance							
		Robert Morris Elementary School (2390) Year Built: 1964	___ Three- Year Reinspection IX							
		2600 W. Thompson Street, Philadelphia, PA 19121	__X__ AIR/EIE							
		Prepared by: Bernard J. Bryson	__X__ Asbestos Abatement Activity							
		Certification # 0437 Date: 1/28/2019	___ Bulk Sampling Event							
		Classroom Modernization Project	Interior Renovations in Existing Classrooms 100, 101, 200, 203, 204, 213, 216 and 218							
<i>F l o o r</i>	Space #	On Site Room Name	Material Description	Confirmed, Assumed, NAD, Non Suspect ACM	Type (Code 1)	Amount of Material	SF LF EA	Condition (Code 2)	Action (Code 3)	Comments/Description/Notes
B	6BB	Maintenance Women's Locker Room - Restroom	Concrete Block Wall	Non Suspect ACM	x	275	SF	x	x	
B	6BB	Maintenance Women's Locker Room - Restroom	Cement Floor	Non Suspect ACM	x	70	SF	x	x	
B	6BB	Maintenance Women's Locker Room - Restroom	Pipe Fitting Insulation	Confirmed	FRI	1	EA	ND	NRN	
B	3B	Storage next to Boiler Room	Fiberglass Pipe Insulation	Non Suspect ACM	x	100	LF	x	x	
B	3B	Storage next to Boiler Room	Concrete Ceiling	Non Suspect ACM	x	500	SF	x	x	
B	3B	Storage next to Boiler Room	Concrete Block Wall	Non Suspect ACM	x	1000	SF	x	x	
B	3B	Storage next to Boiler Room	Cement Floor	Non Suspect ACM	x	500	SF	x	x	
B	2B	Boiler Room	Fiberglass Pipe Insulation	Non Suspect ACM	x	400	LF	x	x	
B	2B	Boiler Room	Concrete Ceiling	Non Suspect ACM	x	1500	SF	x	x	
B	2B	Boiler Room	Concrete Block Wall	Non Suspect ACM	x	2250	SF	x	x	
B	2B	Boiler Room	Cement Floor	Non Suspect ACM	x	1500	SF	x	x	
B	1B	Electrical Room	Vinyl Vibration Damper Cloth	Non Suspect ACM	x	1	SF	x	x	
B	1B	Electrical Room	Concrete Ceiling	Non Suspect ACM	x	100	SF	x	x	
B	1B	Electrical Room	Concrete Block Wall	Non Suspect ACM	x	400	SF	x	x	
B	1B	Electrical Room	Cement Floor	Non Suspect ACM	x	100	SF	x	x	
B	S01	Stairwell by Electrical Room	Concrete Ceiling	non Suspect ACM	x	250	SF	x	x	
B	S01	Stairwell by Electrical Room	Cement Floor	Non Suspect ACM	x	250	SF	x	x	
B	S01	Stairwell by Electrical Room	Concrete Block Wall	Non Suspect ACM	x	500	SF	x	x	
B	H02	Basement Hallway	Concrete Ceiling	non Suspect ACM	x	1400	SF	x	x	
B	H02	Basement Hallway	Cement Floor	Non Suspect ACM	x	1400	SF	x	x	
B	H02	Basement Hallway	Concrete Block Wall	Non Suspect ACM	x	4200	SF	x	x	
CS	C	Crawl Space Basement Pump Room	x	x	x	x	x	x	x	Fiberglass Pipe Insulation Throughout



Page 41 of 42

Morris Elementary School (2390) – Classroom Modernization Project

Project No. 010-4408

12. List all locations inspected that do **NOT** have asbestos containing material present: *Refer to Section 9*

13. List all materials assumed to be Asbestos Containing Materials that will not be disturbed by the Renovation/Demolition Activity. Note: If assumed materials will be impacted by the work, request a sampling strategy that meets OEMS approval. **(Bulk sampling data obtained in the Morris Elementary School's AHERA Management Plan)**

ASSUMED ASBESTOS CONTAINING MATERIALS			
12" x 12" floor tile & mastic throughout the building (various colors)	Metal Interior and Exterior Fire Doors (assumed asbestos-containing interior packing)	Glue dot adhesive behind blackboards and tack boards (concealed)	Radiator insulation throughout the building
Internal Materials associated with the Boilers	Interior/Exterior Window Glazing	Interior/Exterior Caulks (expansion seam, door, etc.)	Roofing (field & flashing)

Signature of Certified Asbestos Investigator:

Date:

1/28/2019

Signature of Building Owner:

Date:



Page 42 of 42

Morris Elementary School (2390) – Classroom Modernization Project

Project No. 010-4408

14. List all homogeneous materials present in this school (Only Positive or Negative Sampled Materials can be listed in box 14 below): **(Bulk sampling data obtained in the Morris Elementary School's AHERA Mgmt. Plan)**

CONFIRMED ASBESTOS CONTAINING MATERIALS	NON-ASBESTOS MATERIALS
Sink undercoat Mastic associated with Stainless Steel Sinks throughout the building	Terrazzo Floors, Concrete Floors and Ceilings, Brick Walls, Concrete Block Walls
9" x 9" floor tile & mastic throughout the building (various colors)	Plaster Walls and Ceilings Throughout the Building (including the Auditorium Plaster Ceiling and Plaster Walls above Coat Closets)
Fireproofing in the Gymnasium Upper Level Fan Room and Auditorium Stage	Fiberglass Pipe Insulation Throughout the Building
2' x 4' Metal Ceiling Tiles in the Gymnasium	2' x 4' Acoustical Ceiling Tiles Throughout the Building
Pipe Fitting Insulation in the Stairwell across from Classroom 100 and Maintenance Women's Locker Room Restroom	1' x 1' Ceiling Tiles Throughout the Building
	Vinyl Vibration Damper Cloth in the Fan Rooms and Electrical Room
	Slate Window Sills Throughout the Building
	Drywall/Joint Compound Walls and Ceilings Throughout the Building
	Corrugated Metal Deck and Red Painted Trusses above suspended ceilings Throughout the Building
	Orange Foam Panels above Windows above suspended ceilings Throughout the Building
	Unit Ventilator Insulation Throughout the Building (Confirmed to be Comprised of Fiberglass)
	Wood Entry, Closet and Restroom Doors throughout Classrooms 100, 101, 200, 203, 204, 213, 216 and 218
	Wood Laminate & Metal Stall Partitions in Classroom 100 and 101 Restrooms

15. Caution labels affixed to all ACM ? Yes No

All contractors' employees involved in the demolition or renovation activity must receive a copy or have access to this Asbestos Inspection Report.

Signature of Certified Asbestos Investigator:

Date:

1/28/2019

Signature of Building Owner:

Date: