AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report

ULCS# 5260

Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials ar Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage) Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS

			Year Built: 1973	sampled and Laboratory Analysis DETECTED or these materials are			SBESTUS			
E I e m e	F I o									Color
n t	o r	Space # (on Floor Plan)	On Site Room Name/Paint and Plaster Survery will be conducted @ this school	Material Description	Confirmed Assumed NAD Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	required f
1	3	301	Classroom 201	Concrete Ceiling	Non Suspect ACM	1490	SF	0	SF	
+	3	301	Classroom 201	Concrete Block Wall	Non Suspect ACM	940	SF	0	SF	-
	3	301	Classroom 201	Partition Room Dividers	Non Suspect ACM	320	SF	0	SF	
	3	301	Classroom 201	Floor Tile VAT 12" x 12"	Assumed	662	SF	0	SF	Tan
	3	301 301	Classroom 201 Classroom 201	Floor Tile VAT 12" x 12" Cement Floor	Assumed Non Suspect ACM	992	SF SF	0	SF SF	Brown Tan
\Box	3	301	Classroom 201	Blackboard Glue Dots	Assumed	130	SF	0	SF	
4	3	301	Classroom 201	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
	3	301 304	Classroom 201 Classroom 202	Acoustical Plaster Ceiling Concrete Ceiling	NAD Non Suspect ACM	1290 1250	SF SF	52 0	SF SF	
	3	304	Classroom 202	Concrete Block Wall	Non Suspect ACM	930	SF	0	SF	
+	3	304 304	Classroom 202 Classroom 202	Partition Room Dividers Brick Wall	Non Suspect ACM Non Suspect ACM	320 50	SF SF	0	SF SF	
Ť	3	202	Classroom 202	Floor Tile VAT 12" x 12"	Assumed	641	SF	0	SF	Tan
	3	202	Classroom 202	Floor Tile VAT 12" x 12"	Assumed	320	SF	0	SF	Brown
+	3	304 304	Classroom 202 Classroom 202	Cement Floor Blackboard Glue Dots	Non Suspect ACM Assumed	961 130	SF SF	0	SF SF	Tan
	3	304	Classroom 202	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
+	3	304 303	Classroom 202 Classroom 203	Acoustical Plaster Ceiling Concrete Ceiling	NAD Non Suspect ACM	1250 1250	SF SF	0	SF SF	
\pm	3	303	Classroom 203	Concrete Block Wall	Non Suspect ACM	930	SF	0	SF	
\dashv	3	303	Classroom 203	Partition Room Dividers	Non Suspect ACM	320	SF	0	SF	
+	3	303 303	Classroom 203 Classroom 203	Brick Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Assumed	50 641	SF SF	0	SF SF	Tan
\Box	3	303	Classroom 203	Floor Tile VAT 12" x 12"	Assumed	320	SF	0	SF	Brown
+	3	303	Classroom 203	Cement Floor	Non Suspect ACM	961 100	SF SF	0	SF SF	Tan
\pm	3	303 303	Classroom 203 Classroom 203	Blackboard Glue Dots Acoustical Plaster Ceiling	Assumed NAD	1250	SF	1	SF	
7	3	302	Classroom 204	Concrete Ceiling	Non Suspect ACM	1290	SF	0	SF	
+	3	302 302	Classroom 204 Classroom 204	Concrete Block Wall Partition Room Dividers	Non Suspect ACM Non Suspect ACM	940 320	SF SF	0	SF SF	
1	3	302	Classroom 204	Brick Wall	Non Suspect ACM	50	SF	0	SF	
+	3	302 302	Classroom 204 Classroom 204	Floor Tile VAT 12" x 12"	Assumed Assumed	662 330	SF SF	0	SF SF	Tan Brow
+	3	302	Classroom 204 Classroom 204	Floor Tile VAT 12" x 12" Cement Floor	Non Suspect ACM	992	SF	0	SF	Tan
1	3	302	Classroom 204	Blackboard Glue Dots	Assumed	100	SF	0	SF	
+	3	302 302	Classroom 204 Classroom 204	Sink Undercoat Mastic Acoustical Plaster Ceiling	Assumed NAD	1290	SF SF	0	SF SF	Black
\pm	3	302B	Classroom 204A	Concrete Ceiling	Non Suspect ACM	315	SF	0	SF	
1	3	302B	Classroom 204A	Concrete Block Wall	Non Suspect ACM	580	SF	0	SF	
+	3	302B 302B	Classroom 204A Classroom 204A	Brick Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Assumed	50 240	SF SF	0	SF SF	Brown
	3	302B	Classroom 204A	Cement Floor	Non Suspect ACM	240	SF	0	SF	Tan
+	3	302B 302B	Classroom 204A Classroom 204A	Blackboard Glue Dots Acoustical Plaster Ceiling	Assumed NAD	50 315	SF SF	3	SF SF	
\pm	3	308	Classroom 205	Concrete Ceiling	Non Suspect ACM	1290	SF	0	SF	
4	3	308	Classroom 205	Concrete Block Wall	Non Suspect ACM	1260	SF	0	SF	
+	3	308 308	Classroom 205 Classroom 205	Brick Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Assumed	50 662	SF SF	0	SF SF	Tan
#	3	308	Classroom 205	Floor Tile VAT 12" x 12"	Assumed	330	SF	0	SF	Brow
+	3	308 308	Classroom 205 Classroom 205	Cement Floor Blackboard Glue Dots	Non Suspect ACM Assumed	992 140	SF SF	0	SF SF	Tan
\pm	3	308	Classroom 205	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
4	3	308	Classroom 205	Acoustical Plaster Ceiling	NAD	1290	SF	3	SF	
+	3	305 305	Classroom 206 Classroom 206	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	1290 940	SF SF	0	SF SF	
#	3	305	Classroom 206	Partition Room Dividers	Non Suspect ACM	320	SF	0	SF	
+	3	305 305	Classroom 206 Classroom 206	Brick Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Assumed	50 842	SF SF	0	SF SF	Tan
#	3	305	Classroom 206	Floor Tile VAT 12 x 12" Floor Tile VAT 12" x 12"	Assumed	150	SF	0	SF	Brow
1	3	305	Classroom 206	Cement Floor	Non Suspect ACM	992	SF	0	SF	Tan
+	3	305 305	Classroom 206 Classroom 206	Blackboard Glue Dots Sink Undercoat Mastic	Assumed Assumed	130	SF SF	0	SF SF	Black
1	3	305	Classroom 206	Acoustical Plaster Ceiling	NAD	1290	SF	2	SF	
+	3	306 306	Classroom 207 Classroom 207	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	1290 940	SF SF	0	SF SF	-
1	3	306	Classroom 207	Partition Room Dividers	Non Suspect ACM	320	SF	0	SF	
Ţ	3	306	Classroom 207	Brick Wall	Non Suspect ACM	50	SF	0	SF	-
+	3	306 306	Classroom 207 Classroom 207	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Assumed Assumed	662 330	SF SF	0	SF SF	Tan Brow
#	3	306	Classroom 207	Cement Floor	Non Suspect ACM	992	SF	0	SF	Tan
+	3	306 306	Classroom 207 Classroom 207	Blackboard Glue Dots Sink Undercoat Mastic	Assumed Assumed	100	SF SF	0	SF SF	Black
†	3	306	Classroom 207	Acoustical Plaster Ceiling	NAD	1290	SF	1	SF	DiaCi
Ţ	3	303B	Classroom 207A	Concrete Ceiling	Non Suspect ACM	315	SF	0	SF	
+	3	303B 303B	Classroom 207A Classroom 207A	Concrete Block Wall Brick Wall	Non Suspect ACM Non Suspect ACM	580 50	SF SF	0	SF SF	
#	3	303B	Classroom 207A	Floor Tile VAT 12" x 12"	Assumed	240	SF	0	SF	Brow
f	3	303B	Classroom 207A	Cement Floor	Non Suspect ACM	240	SF	0	SF	Tan
+	3	303B 303B	Classroom 207A Classroom 207A	Blackboard Glue Dots Acoustical Plaster Ceiling	Assumed NAD	30 240	SF SF	0	SF SF	
#	3	307	Classroom 208	Concrete Ceiling	Non Suspect ACM	1490	SF	0	SF	
+	3	307	Classroom 208 Classroom 208	Concrete Block Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Assumed	1260	SF SF	0	SF SF	Tan
_	3	307 307	Classroom 208	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Assumed Assumed	662 330	SF	0	SF	Brow
1	3	307	Classroom 208	Cement Floor	Non Suspect ACM	992	SF	0	SF	Tan
+	3	307 307	Classroom 208 Classroom 208	Blackboard Glue Dots Sink Undercoat Mastic	Assumed Assumed	140 8	SF SF	0	SF SF	Black
\pm	3	307	Classroom 208	Acoustical Plaster Ceiling	NAD	1290	SF	20	SF	Diacr
T	3	309	Classroom 209	Concrete Ceiling	Non Suspect ACM	1330	SF	0	SF	

ULCS# 5260

AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report

Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials ar Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage)
Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED or these materials are not typically known to contain Asbestos)

Year Built: 1973

			Tear Built: 1973	DETECTED OF these materials are	Thoc cypically known to contain	Asbestos)				
E										
e e	F									
m	7									
e	o									Color
n	o	Space # (on	On Site Room Name/Paint and Plaster Survery will be		Confirmed Assumed NAD	Amount of		Amount of	SF LF	required for
"	,	Floor Plan)	conducted @ this school	Material Description	Non Suspect ACM	Material	SF LF EA	Damage	EA	VAT
1	3	309	Classroom 209	Concrete Block Wall	Non Suspect ACM	1280	SF EF EA	0	SF	VAI
-										T
1	3	309	Classroom 209	Floor Tile VAT 12" x 12"	Assumed	683	SF	0	SF	Tan
1	3	309	Classroom 209	Floor Tile VAT 12" x 12"	Assumed	340	SF	0	SF	Brown
1	3	309	Classroom 209	Cement Floor	Non Suspect ACM	1023	SF	0	SF	Tan
1	3	309	Classroom 209	Blackboard Glue Dots	Assumed	140	SF	0	SF	
1	3	309	Classroom 209	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
1	3	309	Classroom 209	Acoustical Plaster Ceiling	NAD	1330	SF	2	SF	Bidon
1	3	312	Classroom 210	Concrete Ceiling	Non Suspect ACM	1330	SF	0	SF	-
										-
1	3	312	Classroom 210	Concrete Block Wall	Non Suspect ACM	1280	SF	0	SF	-
1	3	312	Classroom 210	Brick Wall	Non Suspect ACM	50	SF	0	SF	
1	3	312	Classroom 210	Floor Tile VAT 12" x 12"	Assumed	683	SF	0	SF	Tan
1	3	312	Classroom 210	Floor Tile VAT 12" x 12"	Assumed	340	SF	0	SF	Brown
1	3	312	Classroom 210	Cement Floor	Non Suspect ACM	1023	SF	0	SF	Tan
1	3	312	Classroom 210	Blackboard Glue Dots	Assumed	140	SF	0	SF	
1	3	312	Classroom 210	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
					NAD		SF		SF	Diack
1	3	312	Classroom 210	Acoustical Plaster Ceiling		1330		5		
1	3	311	Classroom 211	Concrete Ceiling	Non Suspect ACM	1250	SF	0	SF	
1	3	311	Classroom 211	Concrete Block Wall	Non Suspect ACM	1250	SF	0	SF	
1 1	3	311	Classroom 211	Brick Wall	Non Suspect ACM	50	SF	0	SF	
1	3	311	Classroom 211	Floor Tile VAT 12" x 12"	Assumed	838	SF	0	SF	Tan
1	3	311	Classroom 211	Floor Tile VAT 12" x 12"	Assumed	120	SF	0	SF	Brown
1	3	311	Classroom 211	Floor Tile VAT 12 X 12"	Assumed	3	SF	0	SF	White
									SF	vville
1	3	311	Classroom 211	Cement Floor	Non Suspect ACM	961	SF	0		-
1	3	311	Classroom 211	Blackboard Glue Dots	Assumed	140	SF	0	SF	L
1	3	311	Classroom 211	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
1	3	311	Classroom 211	Acoustical Plaster Ceiling	NAD	1250	SF	1	SF	
1	3	307A	Classroom 211A	Concrete Ceiling	Non Suspect ACM	315	SF	0	SF	
1	3	307A	Classroom 211A	Concrete Block Wall	Non Suspect ACM	580	SF	0	SF	
1	3	307A	Classroom 211A	Brick Wall	Non Suspect ACM	50	SF	0	SF	
										Prou-
1	3	307A	Classroom 211A	Floor Tile VAT 12" x 12"	Assumed	240	SF	0	SF	Brown
1	3	307A	Classroom 211A	Cement Floor	Non Suspect ACM	240	SF	0	SF	-
1	3	307A	Classroom 211A	Blackboard Glue Dots	Assumed	30	SF	0	SF	
1	3	307A	Classroom 211A	Acoustical Plaster Ceiling	NAD	315	SF	0	SF	
1	3	310	Classroom 212	Concrete Ceiling	Non Suspect ACM	1490	SF	0	SF	
1	3	310	Classroom 212	Concrete Block Wall	Non Suspect ACM	1260	SF	0	SF	
1	3	310	Classroom 212	Floor Tile VAT 12" x 12"	Assumed	662	SF	0	SF	Tan
1	3	310	Classroom 212	Floor Tile VAT 12" x 12"		330	SF	0	SF	
					Assumed					Brown
1	3	310	Classroom 212	Cement Floor	Non Suspect ACM	992	SF	0	SF	Tan
1	3	310	Classroom 212	Blackboard Glue Dots	Assumed	140	SF	0	SF	
1	3	310	Classroom 212	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
1	3	310	Classroom 212	Acoustical Plaster Ceiling	NAD	1290	SF	47	SF	
1	3	318-1	Classroom 213	Concrete Ceiling	Non Suspect ACM	1490	SF	0	SF	
1	3	318-1	Classroom 213	Concrete Block Wall	Non Suspect ACM	940	SF	0	SF	
1	3	318-1	Classroom 213	Partition Room Dividers	Non Suspect ACM	320	SF	0	SF	
										T
1	3	318-1	Classroom 213	Floor Tile VAT 12" x 12"	Assumed	662	SF	0	SF	Tan
1	3	318-1	Classroom 213	Floor Tile VAT 12" x 12"	Assumed	330	SF	0	SF	Brown
1	3	318-1	Classroom 213	Cement Floor	Non Suspect ACM	992	SF	0	SF	Tan
1	3	318-1	Classroom 213	Blackboard Glue Dots	Assumed	100	SF	0	SF	
1	3	318-1	Classroom 213	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
1	3	318-1	Classroom 213	Acoustical Plaster Ceiling	NAD	1290	SF	65	SF	
1	3	NP-6	Classroom 214	Concrete Ceiling	Non Suspect ACM	1290	SF	0	SF	
1	3	NP-6	Classroom 214	Concrete Block Wall	Non Suspect ACM	940	SF	0	SF	
1	3	NP-6	Classroom 214	Partition Room Dividers	Non Suspect ACM	320	SF	0	SF	
1	3	NP-6	Classroom 214	Brick Wall	Non Suspect ACM	50	SF	0	SF	
1	3	NP-6	Classroom 214	Floor Tile VAT 12" x 12"	Assumed	662	SF	0	SF	Tan
1	3	NP-6	Classroom 214	Floor Tile VAT 12" x 12"	Assumed	330	SF	0	SF	Brown
1	3	NP-6	Classroom 214	Cement Floor	Non Suspect ACM	992	SF	0	SF	Tan
1	3	NP-6	Classroom 214	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
1	3	NP-6	Classroom 214	Acoustical Plaster Ceiling	NAD	1290	SF	0	SF	
1	3	NP-5	Classroom 215	Concrete Ceiling	Non Suspect ACM	1290	SF	0	SF	
1	3	NP-5	Classroom 215	Concrete Block Wall	Non Suspect ACM	940	SF	0	SF	
									SF	
1	3	NP-5	Classroom 215	Partition Room Dividers	Non Suspect ACM	320	SF	0		
1	3	NP-5	Classroom 215	Brick Wall	Non Suspect ACM	50	SF	0	SF	
1	3	NP-5	Classroom 215	Floor Tile VAT 12" x 12"	Assumed	662	SF	0	SF	Tan
1	3	NP-5	Classroom 215	Floor Tile VAT 12" x 12"	Assumed	330	SF	0	SF	Brown
1	3	NP-5	Classroom 215	Cement Floor	Non Suspect ACM	992	SF	0	SF	Tan
1	3	NP-5	Classroom 215	Blackboard Glue Dots	Assumed	130	SF	0	SF	
1	3	NP-5	Classroom 215	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
1	3	NP-5	Classroom 215	Acoustical Plaster Ceiling	NAD	1290	SF	4	SF	1
1	3	NP-4	Classroom 216	Concrete Ceiling	Non Suspect ACM	1290	SF	0	SF	
										-
1	3	NP-4	Classroom 216	Concrete Block Wall	Non Suspect ACM	940	SF	0	SF	
1	3	NP-4	Classroom 216	Partition Room Dividers	Non Suspect ACM	320	SF	0	SF	
1	3	NP-4	Classroom 216	Brick Wall	Non Suspect ACM	50	SF	0	SF	
1	3	NP-4	Classroom 216	Floor Tile VAT 12" x 12"	Assumed	662	SF	0	SF	Tan
1	3	NP-4	Classroom 216	Floor Tile VAT 12" x 12"	Assumed	330	SF	0	SF	Brown
1	3	NP-4	Classroom 216	Cement Floor	Non Suspect ACM	992	SF	0	SF	Tan
1	3	NP-4	Classroom 216	Blackboard Glue Dots	Assumed	130	SF	0	SF	Black
1	3	NP-4	Classroom 216	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
1	3	NP-4	Classroom 216	Acoustical Plaster Ceiling	NAD	1290	SF	10	SF	-
1	3	311B	Classroom 215A	Concrete Ceiling	Non Suspect ACM	315	SF	0	SF	
1	3	311B	Classroom 215A	Concrete Block Wall	Non Suspect ACM	580	SF	0	SF	
1	3	311B	Classroom 215A	Brick Wall	Non Suspect ACM	50	SF	0	SF	
	3	311B	Classroom 215A	Floor Tile VAT 12" x 12"	Assumed	238	SF	0	SF	Brown
1 1	3	311B	Classroom 215A	Floor Tile VAT 12" x 12"	Assumed	2	SF	0	SF	Tan
	3	311B	Classroom 215A	Cement Floor	Non Suspect ACM	240	SF	0	SF	Tan
1										1411
1		311B	Classroom 215A	Blackboard Glue Dots	Assumed	30	SF	0	SF	-
1 1 1	3		Classroom 215A	Acoustical Plaster Ceiling	NAD	315	SF	0	SF	1
1 1 1	3	311B	10.	Concrete Ceiling	N	1 4000	SF	0	SF	1
1 1 1		311B 314-1	Classroom 217	Concrete Celling	Non Suspect ACM	1690	5F			
1 1 1	3		Classroom 217 Classroom 217	Concrete Block Wall	Non Suspect ACM Non Suspect ACM	1460	SF	0	SF	
1 1 1 1 1	3 3 3	314-1 314-1	Classroom 217	Concrete Block Wall	Non Suspect ACM	1460	SF	0	SF	
1 1 1 1	3	314-1								

ULCS# 5260

AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report

Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials at Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage)

Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS

Fig.				Year Built: 1973	sampled and Laboratory Analysis DETECTED or these materials are			SBESTOS			
1											
Page											
Fig. Prince Pri	е	0									
1 2 314-1 Casenon 27	n t	o r			Material Description			SF LF EA			
1 2 314-1 Causer 277			314-1	Classroom 217	Floor Tile VAT 12" x 12"	Assumed	10	SF	0	SF	Tan
1 2 3944 Classoom 27											Brown
1 2 32 14 Cassers 21 Cooled Cooled											
1 2 31-4-1 Concern of 70 count Concern of Content of Con	-										
1 2 34.1 Classon 17 Greet Classon 17 Gree											
1 2 310 Gescond 128		3	314-1	Classroom 217 Closet	Cement Floor	Non Suspect ACM	210	SF	0	SF	Tan
1 3 313 Cassone 738 See											
1 2 323 Control											
1 3 333 Gasaron 218											
1 3 3 333 Classroom 218 Decktored Mark Dec	-										
1 3 333 Generor 28 Content Face Circle Sept Co. Sept Circle		3	313	Classroom 218	Blackboard Glue Dots	Assumed	140	SF	0	SF	
1 2 36C MC											Black
1 3 Rec. MoC. MoC. Moc. Res. Mos. Moc.											
1 3 MC MC MC MC MC MC MC											
1 3 MC MC MC MC MC MC MC											
1 3 Mo. Mo	1	3	IMC	IMC	Floor Tile VAT 12" x 12"	Assumed	3425	SF	0	SF	
1 3 3 304 MC											
1 3 3 321 A. M. O'Trice											Grey
1 3 321 A. M. Office		3	321A	IMC Office	Concrete Ceiling	Non Suspect ACM	145	SF	0	SF	
1 3 321A MC Office											
1 3 327A MAC Office		3	321A	IMC Office			110	SF		SF	Brown
1 3 321A MC Ckehen Shembar Well Non-Sepert ACM 336 SF 0 SF					Cement Floor						Tan
1 3 3 321 A MC Cebelen											
1 3 321A MC (Nithern From Ter VAT 12" Assumed 25 5 5 6 0 5 6 6 6 6 6 6 6 6 6	1	3	321A	IMC Kitchen	Sheetrock Wall	Non Suspect ACM	200	SF	0	SF	
1 3 321.4 MIC Kinthers											Brown
1 3 321A McKitchen											
1 3 3210 MC Copy Room				IMC Kitchen							Black
1 3 3210 M.C. Copy Room											
1 3 3210 MIC Copy Room			321D				405	SF		EA	
1 3 3210 MC Copy Room											
3 3210 MC Copy Room											Brown
1 3 321C MC Storage Room			321D	IMC Copy Room		Non Suspect ACM	445	SF		SF	
1 3 331C MC Storage Room											
1 3 321C MC Storage Room											
1 3 321C Mic Storage Room											
1 3 321C MC Storage Room											Brown
1 3 3 3 C	1	3	321C	IMC Storage Room	Cement Floor		320	SF	0	SF	Tan
1 3 314 Speech Pathologist Office, Former Mer's Lounge											Black
1 3 31 4 Speech Pathologist Office, Former Men's Lounge Concrete Block Wall Non Suspeet ACM 400 SF 0 SF 1 3 31 Speech Pathologist Office, Former Men's Lounge Floor Tile VAT 12' \$12' Assumed 100 SF 0 SF 1 3 31 Speech Pathologist Office, Former Men's Lounge Floor Tile VAT 12' \$12' Assumed 100 SF 0 SF 1 3 31 Speech Pathologist Office, Former Men's Lounge Comment Floor Non Suspeet ACM 100 SF 0 SF 1 3 31 Speech Pathologist Office, Former Men's Lounge Acoustical Plaster Ceiling NAD 130 SF 10 SF 1 3 31 Shorage Room adjacent to Classroom 218 Concrete Block Wall Non Suspeet ACM 186 SF 0 SF 1 3 31 Shorage Room adjacent to Classroom 218 Concrete Block Wall Non Suspeet ACM 140 SF 0 SF 1 3 31 Shorage Room adjacent to Classroom 218 Concrete Block Wall Non Suspeet ACM 140 SF 0 SF 1 3 320 Women's Lounge outside Restroom Ceiling Tile 2' x' NAD 95 SF 0 SF 1 3 320 Women's Lounge outside Restroom Concrete Block Wall Non Suspeet ACM 420 SF 0 SF 1 3 320 Women's Lounge outside Restroom Concrete Block Wall Non Suspeet ACM 420 SF 0 SF 1 3 320 Women's Lounge outside Restroom Concrete Block Wall Non Suspeet ACM 420 SF 0 SF 1 3 320 Women's Lounge outside Restroom Pie Chase Concrete Block Wall Non Suspeet ACM 420 SF 0 SF 3 3 320 Women's Lounge outside Restroom Pie Chase Concrete Block Wall Non Suspeet ACM 420 SF 0 SF 3 3 320 Women's Lounge outside Restroom Pie Chase Concrete Block Wall Non Suspeet ACM 45 SF 0 SF 3 3 320 Women's Restroom Pie Chase Concrete Block Wall Non Suspeet ACM 45 SF 0 SF 3 3 330 Women's Restroom Pie Chase Concrete Block Wall Non Suspeet ACM 45 SF 0 SF 3 3 318 Concrete Block Wall Non Suspeet ACM 45 SF 0 SF 4 3 3											
1 3 314 Speech Pathologist Office, Former Men's Lounge				Speech Pathologist Office, Former Men's Lounge		Non Suspect ACM					
1 3 314 Speech Pathologist Office, Former Men's Lounge Acoustical Plaster Celling NaD 130 SF 0 SF 10 SF 1 3 3134 Speech Pathologist Office, Former Men's Lounge Acoustical Plaster Celling NaD 130 SF 10 SF 1 3 3134 Storage Room adjacent to Classroom 218 Concrete Book Wall Non Suspect ACM 185 SF 0 SF 1 3 3134 Storage Room adjacent to Classroom 218 Concrete Blook Wall Non Suspect ACM 185 SF 0 SF 1 3 3134 Storage Room adjacent to Classroom 218 Concrete Blook Wall Non Suspect ACM 140 SF 0 SF SF 0 SF 1 3 320 Women's Lounge outside Restroom Celling Tile 2 x NaD 95 SF 0 SF SF 0 SF 1 3 320 Women's Lounge outside Restroom Concrete Blook Wall Non Suspect ACM 125 SF 0 SF SF 0 SF SF 0 SF SF											Brown
1 3 313A Storage Room adjacent to Classroom 218											Brown
1 3 313A Storage Room adjacent to Classroom 218 Cement Floor Non Suspect ACM 850 SF 0 SF 3 313A Storage Room adjacent to Classroom 218 Cement Floor Non Suspect ACM 140 SF 0 SF 4 3 320 Women's Lounge outside Restroom Cement Floor Non Suspect ACM 140 SF 0 SF 5 1 3 320 Women's Lounge outside Restroom Concrete Celling Non Suspect ACM 125 SF 0 SF 6 1 3 320 Women's Lounge outside Restroom Concrete Celling Non Suspect ACM 420 SF 0 SF 7 8 8 8 8 8 8 8 8 9 8 9 8 9 8 1 3 320 Women's Lounge outside Restroom Concrete Block Wall Non Suspect ACM 420 SF 0 SF 9 9 9 9 9 9 9 9 9											
1 3 313A Storage Room adjacent to Classroom 218 Cement Floor Non Suspect ACM 140 SF 0 SF 1 3 320 Women's Lounge outside Restroom Concrete Book Wall Non Suspect ACM 125 SF 0 SF 1 3 320 Women's Lounge outside Restroom Concrete Book Wall Non Suspect ACM 420 SF 0 SF 1 3 320 Women's Lounge outside Restroom Concrete Book Wall Non Suspect ACM 420 SF 0 SF 1 3 320 Women's Lounge outside Restroom Concrete Book Wall Non Suspect ACM 420 SF 0 SF 1 3 320 Women's Lounge outside Restroom Concrete Book Wall Non Suspect ACM 48 SF 0 SF 1 3 320 Women's Lounge outside Restroom Concrete Book Wall Non Suspect ACM 48 SF 0 SF 1 3 320 Women's Lounge outside Restroom Pipe Chase Concrete Book Wall Non Suspect ACM 48 SF 0 SF 1 3 320 Women's Lounge outside Restroom Pipe Chase Concrete Book Wall Non Suspect ACM 48 SF 0 SF 1 3 320 Women's Lounge outside Restroom Pipe Chase Concrete Book Wall Non Suspect ACM 48 SF 0 SF 1 3 320 Women's Lounge outside Restroom Pipe Chase Concrete Book Wall Non Suspect ACM 48 SF 0 SF 1 3 320 Women's Lounge outside Restroom Pipe Chase Concrete Book Wall Non Suspect ACM 48 SF 0 SF 1 3 320 Women's Restroom Concrete Book Wall Non Suspect ACM 50 SF SF 0 SF 1 3 320 Women's Restroom Concrete Book Wall Non Suspect ACM 50 SF 0 SF 1 3 320 Women's Restroom Concrete Book Wall Non Suspect ACM 50 SF 0 SF 1 3 319 Men's Restroom Concrete Book Wall Non Suspect ACM 50 SF 0 SF 1 3 318 Gir's Restroom Concrete Book Wall Non Suspect ACM 50 SF 0 SF 1 3 318 Gir's Restroom Concrete Book Wall Non Suspect ACM 50 SF 0 SF 1 3 318 Gir's Restroom Pipe Chase Concrete Book Wall Non Suspect ACM 48 SF 0 SF 1 3 318 Gir's Restroo											
1 3 320 Women's Lounge outside Restroom											
1 3 320 Women's Lounge outside Restroom	1 1	3									
1 3 320 Women's Lounge outside Restroom					Concrete Block Wall			SF		SF	
1 3 320 Women's Lounge outside Restroom Pipe Chase Concrete Ceiling		3	320	Women's Lounge outside Restroom	Floor Tile VAT 12" x 12"	Assumed	95		0		Brown
1 3 320 Women's Lounge outside Restroom Pipe Chase Center Block Wall Non Suspect ACM 48 SF 0 SF											
Plaster Ceiling	1	3	320	Women's Lounge outside Restroom Pipe Chase	Concrete Block Wall	Non Suspect ACM	320	SF	0	SF	
1 3 320 Women's Restroom											
1 3 320 Women's Restroom											
1 3 319	1	3	320	Women's Restroom	Ceramic Tile Floors	Non Suspect ACM	25	SF	0	SF	
1 3 319											
1 3 318 Girl's Restroom Plaster Ceiling NAD 170 SF 0 SF 1 3 318 Girl's Restroom Concrete Block Wall Non Suspect ACM 420 SF 0 SF 1 3 318 Girl's Restroom Ceramic Tile Floors Non Suspect ACM 170 SF 0 SF 1 3 318 Girl's Restroom Pipe Chase Fiberglass Pipe Insulation Non Suspect ACM 100 SF 0 SF 1 3 318 Girl's Restroom Pipe Chase Concrete Ceiling Non Suspect ACM 48 SF 0 SF 1 3 318 Girl's Restroom Pipe Chase Concrete Block Wall Non Suspect ACM 320 SF 0 SF 1 3 318 Girl's Restroom Pipe Chase Concrete Block Wall Non Suspect ACM 48 SF 0 SF 1 3 318 Boy's Restroom Pipe Chase Cement Floor Non Suspect ACM 48 SF 0 SF 1 3 318 Boy's Restroom Pipe Chase Cement Floor Non Suspect ACM 48 SF 0 SF 1 3 318 Boy's Restroom Pipe Chase Cement Floor Non Suspect ACM 48 SF 0 SF 1 3 318 Boy's Restroom Concrete Block Wall Non Suspect ACM 385 SF 0 SF 1 3 318 Boy's Restroom Ceramic Tile Floors Non Suspect ACM 150 SF 3 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Ceiling Non Suspect ACM 46 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Ceiling Non Suspect ACM 190 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Ceiling Non Suspect ACM 110 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Ceiling Non Suspect ACM 46 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Ceiling Non Suspect ACM 110 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Cement Floor Non Suspect ACM 50 SF	1	3			Ceramic Tile Floors						
1 3 318 Girl's Restroom Pipe Chase Fiberglass Pipe Insulation Non Suspect ACM 170 SF 0 SF 1 3 318 Girl's Restroom Pipe Chase Fiberglass Pipe Insulation Non Suspect ACM 100 SF 0 SF 1 3 318 Girl's Restroom Pipe Chase Concrete Celling Non Suspect ACM 48 SF 0 SF 1 3 318 Girl's Restroom Pipe Chase Concrete Block Wall Non Suspect ACM 320 SF 0 SF 1 3 318 Girl's Restroom Pipe Chase Concrete Block Wall Non Suspect ACM 48 SF 0 SF 1 3 318 Boy's Restroom Pipe Chase Concrete Block Wall Non Suspect ACM 48 SF 0 SF 1 3 318 Boy's Restroom Pipe Chase Concrete Block Wall Non Suspect ACM 385 SF 10 SF 1 3 318 Boy's Restroom Concrete Block Wall Non Suspect ACM 150 SF 3 SF 1 3 318 Boy's Restroom Concrete Block Wall Non Suspect ACM 150 SF 3 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Block Wall Non Suspect ACM 45 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Wall Non Suspect ACM 110 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Wall Non Suspect ACM 110 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Wall Non Suspect ACM 110 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Wall Non Suspect ACM 45 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Wall Non Suspect ACM 45 SF 0 SF 1 3 318 Custodial Closet Adjacent to Elevator Concrete Wall Non Suspect ACM 45 SF 0 SF 1 3 318 Custodial Closet Adjacent to Elevator Concrete Wall Non Suspect ACM 45 SF 0 SF 1 3 318 Custodial Closet Adjacent to Elevator Concrete Wall Non Suspect ACM 46 SF 0 SF 1 3 318 Custodial Closet Adjacent to Elevator Concrete Wall Non Suspect ACM 45 SF 0 SF 1 3 318		3	318	Girl's Restroom	Plaster Ceiling	NAD	170	SF		SF	
1 3 318 Girl's Restroom Pipe Chase Fiberglass Pipe Insulation Non Suspect ACM 100 SF 0 SF 1 3 318 Girl's Restroom Pipe Chase Concrete Block Wall Non Suspect ACM 48 SF 0 SF 1 3 318 Girl's Restroom Pipe Chase Concrete Block Wall Non Suspect ACM 48 SF 0 SF 1 3 318 Boy's Restroom Pipe Chase Cement Floor Non Suspect ACM 48 SF 0 SF 1 3 318 Boy's Restroom Plaster Ceiling NAD 150 SF 10 SF 1 3 318 Boy's Restroom Concrete Block Wall Non Suspect ACM 385 SF 0 SF 1 3 318 Boy's Restroom Ceramic Tile Floors Non Suspect ACM 150 SF 3 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Ceiling Non Suspect ACM											
1 3 318 Girl's Restroom Pipe Chase Concrete Block Wall Non Suspect ACM 320 SF 0 SF 1 3 318 Girl's Restroom Pipe Chase Cement Floor Non Suspect ACM 48 SF 0 SF 1 3 318 Boy's Restroom Plaster Ceiling NAD 150 SF 10 SF 1 3 318 Boy's Restroom Concrete Block Wall Non Suspect ACM 385 SF 0 SF 1 3 318 Boy's Restroom Ceramic Tile Floors Non Suspect ACM 150 SF 3 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Ceiling Non Suspect ACM 45 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Ceiling Non Suspect ACM 190 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Wall Non Suspect ACM <td>1</td> <td>3</td> <td>318</td> <td>Girl's Restroom Pipe Chase</td> <td>Fiberglass Pipe Insulation</td> <td>Non Suspect ACM</td> <td>100</td> <td>SF</td> <td>0</td> <td>SF</td> <td></td>	1	3	318	Girl's Restroom Pipe Chase	Fiberglass Pipe Insulation	Non Suspect ACM	100	SF	0	SF	
1 3 318 Girl's Restroom Pipe Chase Cement Floor Non Suspect ACM 48 SF 0 SF 1 3 318 Boy's Restroom Concrete Block Wall Non Suspect ACM 385 SF 0 SF 1 3 318 Boy's Restroom Concrete Block Wall Non Suspect ACM 150 SF 3 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Celling Non Suspect ACM 150 SF 3 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Celling Non Suspect ACM 46 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Celling Non Suspect ACM 190 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Celling Non Suspect ACM 110 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Cement					Concrete Ceiling						
1 3 318 Boy's Restroom Plaster Ceiling NAD 150 SF 10 SF 1 3 318 Boy's Restroom Concrete Block Wall Non Suspect ACM 385 SF 0 SF 1 3 318 Boy's Restroom Non Suspect ACM 150 SF 3 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Ceiling Non Suspect ACM 45 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Block Wall Non Suspect ACM 190 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Wall Non Suspect ACM 110 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Cement Floor Non Suspect ACM 45 SF 0 SF 1 3 310B Storage Room behind Elevator Cement Floor Non Suspect ACM 45											
1 3 318 Boy's Restroom Ceramic Tile Floors Non Suspect ACM 150 SF 3 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Celling Non Suspect ACM 45 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Block Wall Non Suspect ACM 190 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Wall Non Suspect ACM 110 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Cement Floor Non Suspect ACM 45 SF 0 SF 1 3 310B Storage Room behind Elevator Concrete Celling Non Suspect ACM 46 SF 0 SF	1	3	318	Boy's Restroom	Plaster Ceiling	NAD	150	SF	10	SF	
1 3 318 Custodial Closet adjacent to Elevator Concrete Ceiling Non Suspect ACM 45 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Block Wall Non Suspect ACM 190 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Wall Non Suspect ACM 110 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Cement Floor Non Suspect ACM 45 SF 0 SF 1 3 310B Storage Room behind Elevator Concrete Ceiling Non Suspect ACM 160 SF 0 SF											
1 3 318 Custodial Closet adjacent to Elevator Concrete Block Wall Non Suspect ACM 190 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Concrete Wall Non Suspect ACM 110 SF 0 SF 1 3 318 Custodial Closet adjacent to Elevator Cement Floor Non Suspect ACM 45 SF 0 SF 1 3 310B Storage Room behind Elevator Concrete Celing Non Suspect ACM 160 SF 0 SF											
1 3 318 Custodial Closet adjacent to Elevator Cement Floor Non Suspect ACM 45 SF 0 SF 1 3 310B Storage Room behind Elevator Concrete Ceiling Non Suspect ACM 160 SF 0 SF	1	3	318	Custodial Closet adjacent to Elevator	Concrete Block Wall	Non Suspect ACM	190	SF	0	SF	
1 3 310B Storage Room behind Elevator Concrete Ceiling Non Suspect ACM 160 SF 0 SF											

ULCS# 5260

AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report

Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials at Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage)

Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS

			Year Built: 1973	sampled and Laboratory Analysis DETECTED or these materials are			SBESTOS			
E I e	F									
m e n t	1 0 0 r	Space # (on Floor Plan)	On Site Room Name/Paint and Plaster Survery will be conducted @ this school	Material Description	Confirmed Assumed NAD Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	SF LF EA	Color required for VAT
1	3	310B	Storage Room behind Elevator	Cement Floor	Non Suspect ACM	120	SF SF	0	SF	
1	3	309A 309A	Storage Room across from Classroom 209 Storage Room across from Classroom 209	Ceiling Tile 2' x 2' Concrete Ceiling	NAD Non Suspect ACM	145 190	SF	0	EA SF	
1	3	309A	Storage Room across from Classroom 209	Concrete Block Wall	Non Suspect ACM	385	SF	0	SF	
1	3	309A 309A	Storage Room across from Classroom 209 Storage Room across from Classroom 209	Floor Tile VAT 12" x 12" Cement Floor	Assumed Non Suspect ACM	145 145	SF SF	0	SF SF	Brown
1	3	309A	Storage Room across from Classroom 209	Unit Ventilator Insulation	Confirmed	4	SF	0	SF	
1	3	H324 H324	Stairwell 2 Hallway Stairwell 2 Hallway	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	450 810	SF SF	0	SF SF	
1	3	H324	Stairwell 2 Hallway	Brick Wall	Non Suspect ACM	20	SF	0	SF	
1	3	H324	Stairwell 2 Hallway	Transite Sills	Assumed	1	SF	0	SF	
1	3	H324 H324	Stairwell 2 Hallway Stairwell 2 Hallway	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Assumed Assumed	293 7	SF SF	0	SF SF	Brown Tan
1	3	H324	Stairwell 2 Hallway	Cement Floor	Non Suspect ACM	300	SF	0	SF	Tan
1	3	H324	Stairwell 2 Hallway	Acoustical Plaster Ceiling	NAD	450	SF	40	SF	
1	3	S31 S31	Stairwell 2 Stairwell 2	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	100	SF SF	0	SF SF	
1	3	S31	Stairwell 2	Cement Floor	Non Suspect ACM	100	SF	0	SF	
1	3	S31	Stairwell 2	Acoustical Plaster Ceiling	NAD	100	SF	0	SF	
1	3	H325 H325	Lobby outside Stairwell 2 and 3 and IMC Lobby outside Stairwell 2 and 3 and IMC	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	1980 1560	SF SF	0	SF SF	
1	3	H325	Lobby outside Stairwell 2 and 3 and IMC	Floor Tile VAT 12" x 12"	Assumed	1520	SF	0	SF	Tan
1	3	H325	Lobby outside Stairwell 2 and 3 and IMC	Cement Floor	Non Suspect ACM	1520	SF	0	SF	Tan
1	3	H325 H321	Lobby outside Stairwell 2 and 3 and IMC Stairwell 3 Hallway	Acoustical Plaster Ceiling Concrete Ceiling	NAD Non Suspect ACM	1980 450	SF SF	0	SF SF	
1	3	H321	Stairwell 3 Hallway	Concrete Block Wall	Non Suspect ACM	810	SF	0	SF	
1	3	H321	Stairwell 3 Hallway	Brick Wall	Non Suspect ACM	20	SF	0	SF	
1	3	H321 H321	Stairwell 3 Hallway Stairwell 3 Hallway	Transite Sills Floor Tile VAT 12" x 12"	Assumed Assumed	300	SF SF	0	SF SF	Tan
1	3	H321	Stairwell 3 Hallway	Cement Floor	Non Suspect ACM	300	SF	0	SF	Tan
1	3	H321	Stairwell 3 Hallway	Acoustical Plaster Ceiling	NAD	450	SF	32	SF	
1	3	S33 S33	Stairwell 3 Stairwell 3	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	100	SF SF	0	SF SF	
1	3	S33	Stairwell 3	Cement Floor	Non Suspect ACM	100	SF	0	SF	
1	3	S33	Stairwell 3	Acoustical Plaster Ceiling	NAD	100	SF	0	SF	
1	3	H320 H320	Hallway outside Classrooms 209, 212, and 213 Hallway outside Classrooms 209, 212, and 213	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	1365 1850	SF SF	0	SF SF	
1	3	H320	Hallway outside Classrooms 209, 212, and 213	Transite Sills	Assumed	2	SF	0	SF	
1	3	H320	Hallway outside Classrooms 209, 212, and 213	Floor Tile VAT 12" x 12"	Assumed	4	SF	0	SF	Tan
1	3	H320 H320	Hallway outside Classrooms 209, 212, and 213 Hallway outside Classrooms 209, 212, and 213	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Assumed Assumed	11	SF SF	0	SF SF	White Pink
1	3	H320	Hallway outside Classrooms 209, 212, and 213	Floor Tile VAT 12" x 12"	Assumed	1025	SF	0	SF	Brown
1	3	H320 H320	Hallway outside Classrooms 209, 212, and 213 Hallway outside Classrooms 209, 212, and 213	Cement Floor Acoustical Plaster Ceiling	Non Suspect ACM NAD	1050 1365	SF SF	0 2	SF SF	
1	3	H323	Stairwell 4 Hallway	Concrete Ceiling	Non Suspect ACM	450	SF	0	SF	
1	3	H323	Stairwell 4 Hallway	Concrete Block Wall	Non Suspect ACM	810	SF	0	SF	
1	3	H323 H323	Stairwell 4 Hallway	Brick Wall	Non Suspect ACM	20	SF SF	0	SF SF	
1	3	H323	Stairwell 4 Hallway Stairwell 4 Hallway	Transite Sills Floor Tile VAT 12" x 12"	Assumed Assumed	14	SF	0	SF	Tan
1	3	H323	Stairwell 4 Hallway	Floor Tile VAT 12" x 12"	Assumed	111	SF	0	SF	White
1	3	H323 H323	Stairwell 4 Hallway Stairwell 4 Hallway	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Assumed Assumed	9 166	SF SF	0	SF SF	Tan Brown
1	3	H323	Stairwell 4 Hallway	Cement Floor	Non Suspect ACM	300	SF	0	SF	DIOWII
1	3	H323	Stairwell 4 Hallway	Acoustical Plaster Ceiling	NAD	450	SF	32	SF	
1	3	S34 S34	Stairwell 4 Stairwell 4	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	100	SF SF	0	SF SF	
1	3	S34	Stairwell 4	Cement Floor	Non Suspect ACM	100	SF	0	SF	
1	3	S34	Stairwell 4	Acoustical Plaster Ceiling	NAD	100	SF	0	SF	
1	3	H22 H22	Hallway outside Classrooms 217 and 218 Hallway outside Classrooms 217 and 218	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	835 1490	SF SF	0	SF SF	-
1	3	H22	Hallway outside Classrooms 217 and 218	Transite Sills	Assumed	1490	SF	0	SF	
1	3	H22	Hallway outside Classrooms 217 and 218	Floor Tile VAT 12" x 12"	Assumed	70	SF	0	SF	White
1	3	H22 H22	Hallway outside Classrooms 217 and 218 Hallway outside Classrooms 217 and 218	Floor Tile VAT 12" x 12" Cement Floor	Assumed Non Suspect ACM	570 640	SF SF	0	SF SF	Brown
1	3	H22	Hallway outside Classrooms 217 and 218	Acoustical Plaster Ceiling	NAD	835	SF	1	SF	
1	3	H22	Hallway outside Classrooms 217 and 218	Radiator Insulation	Assumed Non Suspect ACM	6	SF	0	SF	
1	3	S32 S32	Stairwell 1 Stairwell 1	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	153 835	SF SF	0	SF SF	
1	3	S32	Stairwell 1	Cement Floor	Non Suspect ACM	153	SF	0	SF	
1	3	S32	Stairwell 1	Acoustical Plaster Ceiling	NAD Non Support ACM	153	SF	1	SF	
1	2	202A 202A	Classroom 101 Classroom 101	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	550 810	SF SF	0	SF SF	
1	2	202A	Classroom 101	Floor Tile VAT 12" x 12"	Confirmed	420	SF	0	SF	Brown
1	2	202A	Classroom 101	Cement Floor	Non Suspect ACM	420	SF	0	SF	Tan
1	2	101 101	Classroom 101 Classroom 101	Blackboard Glue Dots Acoustical Plaster Ceiling	Assumed NAD	100 550	SF SF	0	SF SF	
1	2	201	Classroom 102	Concrete Ceiling	Non Suspect ACM	1820	SF	0	SF	
1	2	201	Classroom 102	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF	
1	2	201	Classroom 102 Classroom 102	Brick Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Assumed	70 45	SF SF	0	SF SF	White
1	2	201	Classroom 102	Floor Tile VAT 12" x 12"	Assumed	680	SF	0	SF	Tan
1	2	201	Classroom 102	Floor Tile VAT 12" x 12"	Confirmed	603	SF	0	SF	Brown
1	2	201	Classroom 102 Classroom 102	Floor Tile VAT 12" x 12" Cement Floor	Assumed Non Suspect ACM	77 1400	SF SF	0	SF SF	Pink Tan
1	2	201	Classroom 102	Blackboard Glue Dots	Assumed	105	SF	0	SF	
1	2	201	Classroom 102	Sink Undercoat Mastic	Assumed	6	SF	0	SF	
1	2	201 201	Classroom 102 Classroom 102 Restroom	Acoustical Plaster Ceiling Plaster Ceiling	NAD NAD	1820 50	SF SF	12 0	SF SF	
1	2	201	Classroom 102 Restroom	Concrete Block Wall	Non Suspect ACM	225	SF	0	SF	
1	2	201	Classroom 102 Restroom	Ceramic Tile Floors	Non Suspect ACM	50	SF	0	SF	
1	2	201	Classrooms 102 and 103 Staff Restroom Classrooms 102 and 103 Staff Restroom	Plaster Ceiling Concrete Block Wall	NAD Non Suspect ACM	25 160	SF SF	0	SF SF	
-	-		1 Total Tota	CONDICIO DIOCK TYDII			, Ji		, 51	-

ULCS# 5260

AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report

Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials ar Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage)
Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED or these materials are not typically known to contain Asbestos)

			Year Built: 1973
	F I o		
- 1	_	0	O., Cit. D /D.:t

-	_		Year Built: 1973	DETECTED or these materials are	Thou typically known to contain	ASDESIUS)			1	
E I e m e n	F I O	Space # (on	On Site Room Name/Paint and Plaster Survery will be		Confirmed Assumed NAD	Amount of		Amount of	SF LF	Color required for
1 1	2 2	Floor Plan) 201	conducted @ this school Classrooms 102 and 103 Staff Restroom	Material Description Ceramic Tile Floors	Non Suspect ACM Non Suspect ACM	Material 25	SF LF EA	Damage 0	<i>EA</i> SF	VAT
1	2	201A	Closet between Classrooms 102 and 103	Fiberglass Pipe Insulation	Non Suspect ACM	2	LF	0	LF	
1	2	201A	Closet between Classrooms 102 and 103	Concrete Ceiling	Non Suspect ACM	325	SF	0	SF	
1	2	201A	Closet between Classrooms 102 and 103	Concrete Block Wall	Non Suspect ACM	510	SF	0	SF	
1	2	201A	Closet between Classrooms 102 and 103	Cement Floor	Non Suspect ACM	250	SF	0	SF	
1	2	201D 201D	Classroom 102 Closet Classroom 102 Closet	Fiberglass Pipe Insulation Concrete Ceiling	Non Suspect ACM Non Suspect ACM	30 290	LF SF	0	LF SF	
1	2	201D	Classroom 102 Closet	Concrete Block Wall	Non Suspect ACM	620	SF	0	SF	
1	2	201D	Classroom 102 Closet	Cement Floor	Non Suspect ACM	220	SF	0	SF	
1	2	201	Classroom 102 Pipe Chase	Fiberglass Pipe Insulation	Non Suspect ACM	40	LF	0	LF	
1	2	201	Classroom 102 Pipe Chase	Concrete Ceiling	Non Suspect ACM	28	SF	0	SF	
1	2	201	Classroom 102 Pipe Chase	Concrete Block Wall	Non Suspect ACM	250	SF	0	SF	
1	2	201	Classroom 102 Pipe Chase Classroom 103	Cement Floor Concrete Ceiling	Non Suspect ACM Non Suspect ACM	28 1820	SF SF	0	SF SF	-
1	2	202	Classroom 103	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF	
1	2	202	Classroom 103	Brick Wall	Non Suspect ACM	70	SF	0	SF	
1	2	202	Classroom 103	Floor Tile VAT 12" x 12"	Assumed	36	SF	0	SF	Orange
1	2	202	Classroom 103	Floor Tile VAT 12" x 12"	Assumed	420	SF	0	SF	Tan
1	2	202	Classroom 103 Classroom 103	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Assumed Confirmed	90 854	SF SF	0	SF SF	Pink Brown
1	2	202	Classroom 103	Cement Floor	Non Suspect ACM	1400	SF	0	SF	Tan
1	2	202	Classroom 103	Blackboard Glue Dots	Assumed	105	SF	0	SF	
1	2	202	Classroom 103	Sink Undercoat Mastic	Assumed	6	SF	0	SF	\bot
1	2	202	Classroom 103	Acoustical Plaster Ceiling	NAD NAD	1820	SF	10	SF	
1	2	202	Classroom 103 Restroom Classroom 103 Restroom	Plaster Ceiling Concrete Block Wall	NAD Non Suspect ACM	50 225	SF SF	0	SF SF	
1	2	202	Classroom 103 Restroom Classroom 103 Restroom	Concrete Block Wall Ceramic Tile Floors	Non Suspect ACM Non Suspect ACM	50	SF	0	SF	
1	2	202B	Classroom 103 Closet	Fiberglass Pipe Insulation	Non Suspect ACM	35	LF	14	LF	
1	2	202B	Classroom 103 Closet	Concrete Ceiling	Non Suspect ACM	120	SF	0	SF	
1	2	202B	Classroom 103 Closet	Concrete Block Wall	Non Suspect ACM	420	SF	0	SF	
1	2	202B	Classroom 103 Closet	Cement Floor	Non Suspect ACM	90	SF	0	SF	
1	2	202B 204	Classroom 103 Closet Classroom 104	Unit Ventilator Insulation Concrete Ceiling	Assumed Non Suspect ACM	4 1820	SF SF	0	SF SF	
1	2	204	Classroom 104 Classroom 104	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF	
1	2	204	Classroom 104	Brick Wall	Non Suspect ACM	70	SF	0	SF	
1	2	204	Classroom 104	Floor Tile VAT 12" x 12"	Assumed	1400	SF	0	SF	Tan
1	2	204	Classroom 104	Cement Floor	Non Suspect ACM	1400	SF	0	SF	
1	2	204 204	Classroom 104 Classroom 104	Blackboard Glue Dots Sink Undercoat Mastic	Assumed Assumed	45 6	SF SF	0	SF SF	+
1	2	204	Classroom 104	Acoustical Plaster Ceiling	NAD	1820	SF	13	SF	+
1	2	204	Classroom 104 Restroom	Plaster Ceiling	NAD	50	SF	0	SF	<u> </u>
1	2	204	Classroom 104 Restroom	Concrete Block Wall	Non Suspect ACM	225	SF	0	SF	
1	2	204	Classroom 104 Restroom	Ceramic Tile Floors	Non Suspect ACM	50	SF	0	SF	
1	2	204	Classrooms 104 and 105 Staff Restroom	Plaster Ceiling	NAD Nan Suggest ACM	25	SF	0	SF	
1	2	204	Classrooms 104 and 105 Staff Restroom Classrooms 104 and 105 Staff Restroom	Concrete Block Wall Ceramic Tile Floors	Non Suspect ACM Non Suspect ACM	160 25	SF SF	0	SF SF	
1	2	203A	Closet between Classrooms 104 and 105	Fiberglass Pipe Insulation	Non Suspect ACM	1	LF	0	LF	+
1	2	203A	Closet between Classrooms 104 and 105	Concrete Ceiling	Non Suspect ACM	325	SF	0	SF	
1	2	203A	Closet between Classrooms 104 and 105	Concrete Block Wall	Non Suspect ACM	510	SF	0	SF	
1	2	203A	Closet between Classrooms 104 and 105	Cement Floor	Non Suspect ACM	250	SF	0	SF	
1	2	203B	Classroom 104 Closet	Concrete Ceiling	Non Suspect ACM	140 440	SF SF	0	SF SF	
1	2	203B 203B	Classroom 104 Closet Classroom 104 Closet	Concrete Block Wall Cement Floor	Non Suspect ACM Non Suspect ACM	105	SF	0	SF	-
1	2	203B	Classroom 104 Closet	Acoustical Plaster Ceiling	NAD	140	SF	0	SF	
1	2	204	Classroom 104 Pipe Chase	Fiberglass Pipe Insulation	Non Suspect ACM	40	LF	0	LF	
1	2	204	Classroom 104 Pipe Chase	Concrete Ceiling	Non Suspect ACM	28	SF	0	SF	
1	2	204	Classroom 104 Pipe Chase	Concrete Block Wall	Non Suspect ACM	250	SF	0	SF	
1	2	204 205	Classroom 104 Pipe Chase Classroom 105	Cement Floor Concrete Ceiling	Non Suspect ACM Non Suspect ACM	28 1820	SF SF	0	SF SF	
1	2	205	Classroom 105	Concrete Block Wall	Non Suspect ACM	1500	SF	0	SF	
1	2	205	Classroom 105	Brick Wall	Non Suspect ACM	70	SF	0	SF	
1	2	205	Classroom 105	Floor Tile VAT 12" x 12"	Confirmed	420	SF	0	SF	Tan
1	2	205	Classroom 105	Floor Tile VAT 12" x 12"	Confirmed	84	SF	0	SF	Pink
1	2	205 205	Classroom 105 Classroom 105	Floor Tile VAT 12" x 12" Cement Floor	Confirmed Non Suspect ACM	896 1400	SF SF	0	SF SF	Brown
1	2	205	Classroom 105	Blackboard Glue Dots	Assumed	1400	SF	0	SF	Tan
1	2	205	Classroom 105	Sink Undercoat Mastic	Assumed	6	SF	0	SF	<u> </u>
1	2	205	Classroom 105	Acoustical Plaster Ceiling	NAD	1820	SF	16	SF	
1	2	205	Classroom 105 Restroom	Plaster Ceiling	NAD	50	SF	0	SF	
1	2	205	Classroom 105 Restroom	Concrete Block Wall	Non Suspect ACM	225	SF	0	SF	
1	2	205 204B	Classroom 105 Restroom Classroom 105 Closet	Ceramic Tile Floors Concrete Ceiling	Non Suspect ACM Non Suspect ACM	50 290	SF SF	0	SF SF	
1	2	204B	Classroom 105 Closet	Concrete Block Wall	Non Suspect ACM	620	SF	0	SF	+
1	2	204B	Classroom 105 Closet	Cement Floor	Non Suspect ACM	220	SF	0	SF	
1	2	204B	Classroom 105 Closet	Unit Ventilator Insulation	Assumed	4	SF	0	SF	
1	2	206	Classroom 106	Concrete Ceiling	Non Suspect ACM	550	SF	0	SF	
1	2	206	Classroom 106	Concrete Block Wall	Non Suspect ACM	810	SF	0	SF	P
1	2	206 206	Classroom 106 Classroom 106	Floor Tile VAT 12" x 12" Cement Floor	Confirmed Non Suspect ACM	420 420	SF SF	0	SF SF	Brown Tan
1	2	206	Classroom 106	Blackboard Glue Dots	Assumed	100	SF	0	SF	Tall
1	2	206	Classroom 106	Acoustical Plaster Ceiling	NAD	550	SF	8	SF	
1	2	208	Classroom 107	Ceiling Tile 2' x 2'	NAD	30	SF	0	SF	
1	2	208	Classroom 107	Concrete Ceiling	Non Suspect ACM	1210	SF	0	SF	
1	2	208	Classroom 107	Concrete Block Wall	Non Suspect ACM	1220	SF	0	SF	T-1-1
1	2	208	Classroom 107 Classroom 107	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Assumed Confirmed	740 190	SF SF	0	SF SF	Tan Brown
1	2	208	Classroom 107 Classroom 107	Cement Floor	Non Suspect ACM	930	SF	0	SF	Tan
1	2	208	Classroom 107	Blackboard Glue Dots	Assumed	85	SF	0	SF	
1	2	208	Classroom 107	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
1	2	208	Classroom 107	Acoustical Plaster Ceiling	NAD	1210	SF	12	SF	
1	2	208A 208A	Classroom 107 Closet	Concrete Ceiling	Non Suspect ACM	55	SF	0	SF	+
1			Classroom 107 Closet	Concrete Block Wall	Non Suspect ACM	260	SF	0	SF	

AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report

Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials ar Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage)
Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED or these materials are not typically known to contain Asbestos)

ULCS# 5260 Year Built: 1973

-			Year Built: 1973	DETECTED or these materials are	not typically known to contain	ASDESTOS)				
E										
e	F									
m	1									
e n	0	Space # (on	On Site Room Name/Paint and Plaster Survery will be		Confirmed Assumed NAD	Amount of		Amount of	SF LF	Color required for
"	r	Floor Plan)	conducted @ this school	Material Description	Non Suspect ACM	Material	SF LF EA	Damage	EA	VAT
1	2	208A	Classroom 107 Closet	Cement Floor	Non Suspect ACM	42	SF	0	SF	
1	2	208B	Classroom 107 Restroom	Plaster Ceiling	NAD	30	SF	0	SF	
1	2	208B	Classroom 107 Restroom	Concrete Block Wall	Non Suspect ACM	220	SF	0	SF	
1	2	208B	Classroom 107 Restroom	Ceramic Tile Floors	Non Suspect ACM	30	SF	0	SF	
1	2	207	Classroom 108	Concrete Ceiling	Non Suspect ACM	1210	SF	0	SF	
1	2	207 207	Classroom 108 Classroom 108	Concrete Block Wall Brick Wall	Non Suspect ACM Non Suspect ACM	1220 50	SF SF	0	SF SF	
1	2	207	Classroom 108	Floor Tile VAT 12" x 12"	Assumed	620	SF	0	SF	Tan
1	2	207	Classroom 108	Floor Tile VAT 12" x 12"	Confirmed	310	SF.	0	SF	Brown
1	2	207	Classroom 108	Cement Floor	Non Suspect ACM	930	SF	0	SF	Tan
1	2	207	Classroom 108	Blackboard Glue Dots	Assumed	85	SF	0	SF	
1	2	207	Classroom 108	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
1	2	207	Classroom 108	Acoustical Plaster Ceiling	NAD	1210	SF	20	SF	
1	2	210	Classroom 109	Concrete Ceiling	Non Suspect ACM	1210	SF	0	SF	
1	2	210 210	Classroom 109 Classroom 109	Concrete Block Wall Brick Wall	Non Suspect ACM Non Suspect ACM	1220 50	SF SF	0	SF SF	
1	2	210	Classroom 109	Floor Tile VAT 12" x 12"	Assumed	930	SF	0	SF	Tan
1	2	210	Classroom 109	Cement Floor	Non Suspect ACM	930	SF	0	SF	Tan
1	2	210	Classroom 109	Blackboard Glue Dots	Assumed	85	SF	0	SF	
1	2	210	Classroom 109	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
1	2	210	Classroom 109	Acoustical Plaster Ceiling	NAD	1210	SF	10	SF	
1	2	209	Classroom 110	Ceiling Tile 2' x 2'	NAD	30	SF	1	EA	
1	2	209	Classroom 110	Concrete Ceiling	Non Suspect ACM	1210	SF	0	SF	
1	2	209	Classroom 110	Concrete Block Wall	Non Suspect ACM	1220	SF	0	SF	
1	2	209	Classroom 110	Floor Tile VAT 12" x 12"	Assumed	620	SF	0	SF	Tan
1 1	2	209 209	Classroom 110 Classroom 110	Floor Tile VAT 12" x 12" Cement Floor	Confirmed Non Suspect ACM	310 930	SF SF	0	SF SF	Brown Tan
1	2	209	Classroom 110	Cement Floor Blackboard Glue Dots	Assumed	85	SF	0	SF	ıdli
1	2	209	Classroom 110	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
1	2	209	Classroom 110	Acoustical Plaster Ceiling	NAD	1210	SF	10	SF	
1	2	209A	Classroom 110 Restroom	Plaster Ceiling	NAD	30	SF	0	SF	
1	2	209A	Classroom 110 Restroom	Concrete Block Wall	Non Suspect ACM	220	SF	0	SF	
1	2	209A	Classroom 110 Restroom	Ceramic Tile Floors	Non Suspect ACM	30	SF	1	SF	
1	2	209B	Classroom 110 Closet	Fiberglass Pipe Insulation	Non Suspect ACM	40	LF	0	LF	
1	2	209B 209B	Classroom 110 Closet Classroom 110 Closet	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	125 400	SF SF	0	SF SF	
1	2	209B 209B	Classroom 110 Closet	Cement Floor	Non Suspect ACM	95	SF	0	SF	
1	2	209B	Classroom 110 Closet	Unit Ventilator Insulation	Assumed	4	SF	0	SF	
1	2	211-1	Classroom 111	Concrete Ceiling	Non Suspect ACM	1290	SF	0	SF	
1	2	211-1	Classroom 111	Concrete Block Wall	Non Suspect ACM	940	SF	0	SF	
1	2	211-1	Classroom 111	Partition Room Dividers	Non Suspect ACM	320	SF	0	SF	
1	2	211-1	Classroom 111	Floor Tile VAT 12" x 12"	Assumed	992	SF	0	SF	Tan
1	2	211-1	Classroom 111	Cement Floor	Non Suspect ACM	992	SF	0	SF	Tan
1	2	211-1	Classroom 111	Blackboard Glue Dots	Assumed	140	SF	0	SF	Bl. I
1 1	2	211-1 211-1	Classroom 111	Sink Undercoat Mastic	Assumed NAD	8 1290	SF SF	0	SF SF	Black
1	2	214-1	Classroom 111 Classroom 112	Acoustical Plaster Ceiling Concrete Ceiling	Non Suspect ACM	1290	SF	12 0	SF	
1	2	214-1	Classroom 112	Concrete Block Wall	Non Suspect ACM	940	SF	0	SF	
1	2	214-1	Classroom 112	Partition Room Dividers	Non Suspect ACM	320	SF	0	SF	
1	2	214-1	Classroom 112	Brick Wall	Non Suspect ACM	50	SF	0	SF	
1	2	214-1	Classroom 112	Floor Tile VAT 12" x 12"	Assumed	662	SF	0	SF	Tan
1	2	214-1	Classroom 112	Floor Tile VAT 12" x 12"	Confirmed	330	SF	0	SF	Brown
1	2	214-1	Classroom 112	Cement Floor	Non Suspect ACM	992	SF	0	SF	Tan
1 1	2	214-1 214-1	Classroom 112 Classroom 112	Blackboard Glue Dots Sink Undercoat Mastic	Assumed Assumed	140	SF SF	0	SF SF	Black
1	2	214-1	Classroom 112	Acoustical Plaster Ceiling	NAD	1290	SF	8	SF	Diack
1	2	213-1	Classroom 113	Concrete Ceiling	Non Suspect ACM	1290	SF	0	SF	
1	2	213-1	Classroom 113	Concrete Block Wall	Non Suspect ACM	940	SF	0	SF	
1	2	213-1	Classroom 113	Partition Room Dividers	Non Suspect ACM	320	SF	0	SF	
1	2	213-1	Classroom 113	Brick Wall	Non Suspect ACM	50	SF	0	SF	
1	2	213-1	Classroom 113	Floor Tile VAT 12" x 12"	Assumed	992	SF	0	SF	Tan
1 1	2	213-1 213-1	Classroom 113 Classroom 113	Cement Floor Blackboard Glue Dots	Non Suspect ACM Assumed	992 140	SF SF	0	SF SF	Tan
1	2	213-1	Classroom 113	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
1	2	219-1	Classroom 113	Acoustical Plaster Ceiling	NAD	1290	SF	4	SF	
1	2	212-1	Classroom 114	Concrete Ceiling	Non Suspect ACM	1290	SF	0	SF	
1	2	212-1	Classroom 114	Concrete Block Wall	Non Suspect ACM	940	SF	0	SF	
1	2	212-1	Classroom 114	Partition Room Dividers	Non Suspect ACM	320	SF	0	SF	
1	2	212-1	Classroom 114	Brick Wall	Non Suspect ACM	50	SF	0	SF	T-1
1	2	213-1	Classroom 114	Floor Tile VAT 12" x 12" Cement Floor	Assumed Non Suspect ACM	992	SF SE	0	SF SF	Tan
1 1	2	212-1 212-1	Classroom 114 Classroom 114	Blackboard Glue Dots	Non Suspect ACM Assumed	992 140	SF SF	0	SF	Tan
1	2	212-1	Classroom 114	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
1	2	212-1	Classroom 114	Acoustical Plaster Ceiling	NAD	1290	SF	4	SF	
1	2	213	Classroom 115	Fiberglass Pipe Insulation	Non Suspect ACM	12	LF	0	LF	
1	2	213	Classroom 115	Concrete Ceiling	Non Suspect ACM	1525	SF	0	SF	
1	2	213	Classroom 115	Concrete Block Wall	Non Suspect ACM	1340	SF	0	SF	
1	2	213	Classroom 115	Brick Wall	Non Suspect ACM	50	SF	0	SF	
1	2	213	Classroom 115	Transite Sills	Assumed Assumed	12	SF	0	SF	T
1 1	2	213 213	Classroom 115 Classroom 115	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Assumed Confirmed	64 1106	SF SF	0	SF SF	Tan Brown
1	2	213	Classroom 115	Cement Floor	Non Suspect ACM	1170	SF	0	SF	Tan
1	2	213	Classroom 115	Blackboard Glue Dots	Assumed	125	SF	0	SF	ian
1	2	213	Classroom 115	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
1	2	213	Classroom 115	Acoustical Plaster Ceiling	NAD	1525	SF	20	SF	
1	2	213A	Storage Room adjacent to Classroom 115	Concrete Ceiling	Non Suspect ACM	340	SF	0	SF	
1	2	213A	Storage Room adjacent to Classroom 115	Concrete Block Wall	Non Suspect ACM	260	SF	0	SF	
1	2	213A	Storage Room adjacent to Classroom 115	Cement Floor	Non Suspect ACM	260	SF	0	SF	
1	2	216B	Classroom 116	Concrete Ceiling	Non Suspect ACM	465	SF	0	SF	
1	2	216B	Classroom 116	Concrete Block Wall	Non Suspect ACM	640	SF	0	SF	T
1 1	2	216B 216B	Classroom 116 Classroom 116	Floor Tile VAT 12" x 12" Cement Floor	Assumed Non Suspect ACM	355 355	SF SF	0	SF SF	Tan Tan
		L I U D	Olassi Colif 110	Cement Floor	INOTI GUSPECI ACIVI	1 333	<u> </u>		J OF	i dii

ULCS# 5260

AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report

Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials at Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage) Green= Non Asbestos Containing/Non Suspect Material (These materials have been

			Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS							
			Year Built: 1973	DETECTED or these materials are			JDE5105			
E										
e	F									
m	ı									0-1
e n	0	Space # (on	On Site Room Name/Paint and Plaster Survery will be		Confirmed Assumed NAD	Amount of		Amount of	SF LF	Color required for
t	r	Floor Plan)	conducted @ this school	Material Description	Non Suspect ACM	Material	SF LF EA	Damage	EA	VAT
1	2	216B	Classroom 116	Sink Undercoat Mastic	Assumed	8	SF	0	SF	
1	2	216B	Classroom 116 Former Principal's Conference Room adjacent to Classroom	Acoustical Plaster Ceiling	NAD	465	SF	10	SF	-
1	2	216A	116	Ceiling Tile 2' x 2'	NAD	100	SF	2	EA	
			Former Principal's Conference Room adjacent to Classroom							
1	2	216A	116 Former Principal's Conference Room adjacent to Classroom	Concrete Ceiling	Non Suspect ACM	130	SF	0	SF	-
1	2	216A	116	Concrete Block Wall	Non Suspect ACM	400	SF	0	SF	
			Former Principal's Conference Room adjacent to Classroom					_		_
1	2	216A	116 Former Principal's Conference Room adjacent to Classroom	Floor Tile VAT 12" x 12"	Confirmed	100	SF	0	SF	Brown
1	2	216A	116	Cement Floor	Non Suspect ACM	100	SF	0	SF	Tan
1	2	216C	Office behind Former Principal's Office Conference Room	Concrete Ceiling	Non Suspect ACM	300	SF	0	SF	
1	2	216C	Office behind Former Principal's Office Conference Room	Concrete Block Wall	Non Suspect ACM	520	SF	0	SF	
1	2	216C 216C	Office behind Former Principal's Office Conference Room Office behind Former Principal's Office Conference Room	Brick Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Assumed	50 230	SF SF	0	SF SF	Tan
1	2	216C	Office behind Former Principal's Office Conference Room	Cement Floor	Non Suspect ACM	230	SF	0	SF	Tan
1	2	216C	Office behind Former Principal's Office Conference Room	Sink Undercoat Mastic	Assumed	8	SF	0	SF	Black
1	2	216C	Office behind Former Principal's Office Conference Room	Acoustical Plaster Ceiling	NAD	300	SF	5	SF	
1	2	216	Counselor's Office	Ceiling Tile 2' x 2'	NAD Non Suspect ACM	150	SF SE	0	SF SF	-
1	2	216 216	Counselor's Office Counselor's Office	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	195 500	SF SF	0	SF	
1	2	216	Counselor's Office	Floor Tile VAT 12" x 12"	Confirmed	150	SF	0	SF	Brown
1	2	216	Counselor's Office	Cement Floor	Non Suspect ACM	150	SF	0	SF	Tan
1	2	119	Counselor's Office	Ceiling Tile 2' x 2'	NAD	180	SF	3	EA	
1	2	216D	Counselor's Office Counselor's Office	Concrete Ceiling	Non Suspect ACM	235	SF SE	0	SF	-
1	2	216D 216D	Counselor's Office Counselor's Office	Concrete Block Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Confirmed	275 180	SF SF	0	SF SF	Brown
1	2	216D	Counselor's Office	Cement Floor	Non Suspect ACM	180	SF	0	SF	Tan
1	2	216D	Counselor's Office	Unit Ventilator Insulation	Assumed	4	SF	0	SF	
1	2	216E	School Police Office	Fiberglass Pipe Insulation	Non Suspect ACM	24	LF	1	LF	
1	2	120 216E	School Police Office School Police Office	Ceiling Tile 2' x 2'	NAD Non Suspect ACM	120 160	SF SF	3 0	EA SF	-
1	2	216E	School Police Office School Police Office	Concrete Ceiling Concrete Block Wall	Non Suspect ACM	440	SF	0	SF	-
1	2	216E	School Police Office	Floor Tile VAT 12" x 12"	Confirmed	120	SF	0	SF	Brown
1	2	216E	School Police Office	Cement Floor	Non Suspect ACM	120	SF	0	SF	Tan
1	2	200	Main Office	Ceiling Tile 2' x 4'	Non Suspect ACM	30	SF	0	SF	
1	2	200	Main Office Main Office	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	900 660	SF SF	0	SF SF	-
1	2	200	Main Office	Sheetrock Wall	Non Suspect ACM	140	SF	0	SF	+
1	2	200	Main Office	Floor Tile VAT 12" x 12"	NAD	690	SF	0	SF	White
1	2	200	Main Office	Cement Floor	Non Suspect ACM	690	SF	0	SF	
1	2	200	Main Office	Acoustical Plaster Ceiling	NAD	900	SF	5	SF	-
1	2	200A 200A	Pupil Personnel Office Pupil Personnel Office	Fiberglass Pipe Insulation Ceiling Tile 2' x 2'	Non Suspect ACM NAD	10 90	LF SF	0	LF SF	-
1	2	200A	Pupil Personnel Office	Concrete Ceiling	Non Suspect ACM	120	SF	0	SF	1
1	2	200A	Pupil Personnel Office	Concrete Block Wall	Non Suspect ACM	380	SF	0	SF	
1	2	200A	Pupil Personnel Office	Floor Tile VAT 12" x 12"	Confirmed	90	SF	0	SF	Brown
1	2	200A 200B	Pupil Personnel Office Main Office Storage Room	Cement Floor	Non Suspect ACM NAD	90 170	SF SF	6	SF EA	Tan
1	2	200B	Main Office Storage Room	Ceiling Tile 2' x 2' Concrete Ceiling	Non Suspect ACM	225	SF	0	SF	<u> </u>
1	2	200B	Main Office Storage Room	Concrete Block Wall	Non Suspect ACM	500	SF	0	SF	
1	2	121B	Main Office Storage Room	Floor Tile VAT 12" x 12"	Confirmed	164	SF	0	SF	Brown
1	2	121B	Main Office Storage Room	Floor Tile VAT 12" x 12"	Assumed	6	SF	0	SF	Tan
1	2	200B 121B	Main Office Storage Room Main Office Storage Room	Cement Floor Sink Undercoat Mastic	Non Suspect ACM Assumed	170 12	SF SF	0	SF SF	Tan
1	2	200C	Main Office Storage Room Main Office Conference Room	Ceiling Tile 2' x 4'	Non Suspect ACM	195	SF	0	SF	
1	2	200C	Main Office Conference Room	Concrete Ceiling	Non Suspect ACM	255	SF	0	SF	
1	2	200C	Main Office Conference Room	Concrete Block Wall	Non Suspect ACM	290	SF	0	SF	
1	2	200C 200C	Main Office Conference Room Main Office Conference Room	Sheetrock Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Assumed	220 195	SF SF	0	SF SF	White
1	2	200C	Main Office Conference Room Main Office Conference Room	Cement Floor	Non Suspect ACM	195	SF	0	SF	White
1	2	200C	Main Office Conference Room	Blackboard Glue Dots	Assumed	40	SF	0	SF	
1	2	200C	Main Office Conference Room	Unit Ventilator Insulation	Assumed	4	SF	0	SF	
1	2	121D	Principal's Office	Ceiling Tile 2' x 2'	NAD Non Suggest ACM	170	SF SF	0	SF SF	
1	2	200D 200D	Principal's Office Principal's Office	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	225 500	SF	0	SF	
1	2	121D	Principal's Office	Floor Tile VAT 12" x 12"	Assumed	170	SF	0	SF	Tan
1	2	200D	Principal's Office	Cement Floor	Non Suspect ACM	170	SF	0	SF	Tan
1	2	200 E	Office across from Principal's Office	Ceiling Tile 2' x 2'	NAD	100	SF	0	SF	
1	2	200E	Office across from Principal's Office Office across from Principal's Office	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	130 400	SF SF	0	SF SF	-
1	2	200E 200E	Office across from Principal's Office Office across from Principal's Office	Floor Tile VAT 12" x 12"	Non Suspect ACM Confirmed	100	SF	0	SF	Brown
1	2	200E	Office across from Principal's Office	Cement Floor	Non Suspect ACM	100	SF	0	SF	
1	2	200F	Vice-Principal's Office	Ceiling Tile 2' x 2'	NAD	145	SF	4	EA	
1	2	200F	Vice-Principal's Office	Concrete Ceiling	Non Suspect ACM	190	SF	0	SF	-
1	2	200F 200F	Vice-Principal's Office Vice-Principal's Office	Concrete Block Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Confirmed	480 142	SF SF	0	SF SF	Brown
1	2	200F 200F	Vice-Principal's Office	Floor Tile VAT 12 x 12 Floor Tile VAT 12" x 12"	Assumed	3	SF	0	SF	White
1	2	200F	Vice-Principal's Office	Cement Floor	Non Suspect ACM	145	SF	0	SF	
1	2	200G	Principal's Office Large Closet	Ceiling Tile 2' x 2'	NAD	55	SF	1	EA	
1	2	200G	Principal's Office Large Closet	Concrete Ceiling	Non Suspect ACM	75	SF	0	SF	-
1	2	200G 200G	Principal's Office Large Closet Principal's Office Large Closet	Concrete Block Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Confirmed	300 55	SF SF	0	SF SF	Brown
1	2	200G 200G	Principal's Office Large Closet	Cement Floor	Non Suspect ACM	55	SF	0	SF	Tan
1	2	200H	Principal's Office Restroom	Plaster Ceiling	NAD	30	SF	0	SF	
1	2	200H	Principal's Office Restroom	Concrete Block Wall	Non Suspect ACM	180	SF	0	SF	
1	2	200H	Principal's Office Restroom	Ceramic Tile Floors	Non Suspect ACM	30	SF	0	SF	
1	2	200G 200G	Principal's Office Small Closet Principal's Office Small Closet	Ceiling Tile 2' x 2' Concrete Ceiling	NAD Non Suspect ACM	6 8	SF SF	0	SF SF	
				Concrete Block Wall	Non Suspect ACM	70	SF	0	SF	
1	2	200G	Principal's Office Small Closet							

ULCS# 5260

AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report

Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials ar Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage) Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED to these materials are not broadly known to contain Asbestos.

m e n t 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	F 1 0 0 r 2 2 2	Space # (on	Year Built: 1973	DETECTED or these materials and	The cypically known to contain	ASDESIOS)				
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Floor Plan) 200G	On Site Room Name/Paint and Plaster Survery will be conducted @ this school Principal's Office Small Closet	Material Description Cement Floor	Confirmed Assumed NAD Non Suspect ACM Non Suspect ACM	Amount of Material	SF LF EA	Amount of Damage	EA SF	Color required for VAT Tan
1 1 1 1 1 1 1 1 1 1 1		H224 200G	Main Office Hallway Main Office Hallway	Ceiling Tile 2' x 2'	NAD Non Suspect ACM	108 30	SF SF	0	EA SF	
1 1 1 1 1 1 1 1	2	H224	Main Office Hallway	Ceiling Tile 2' x 4' Concrete Ceiling	Non Suspect ACM	180	SF	0	SF	
1 1 1 1 1 1 1	2	H224	Main Office Hallway	Concrete Block Wall	Non Suspect ACM	370	SF	0	SF	
1 1 1 1 1	2	H224 H224	Main Office Hallway Main Office Hallway	Floor Tile VAT 12" x 12" Cement Floor	Assumed Non Suspect ACM	138 138	SF SF	0	SF SF	White Tan
1 1 1	2	211	Nurse's Office Waiting Area	Ceiling Tile 2' x 2'	NAD NAD	100	SF	0	SF	Tall
1 1 1	2	211	Nurse's Office Waiting Area	Concrete Ceiling	Non Suspect ACM	130	SF	0	SF	
1	2	211 211	Nurse's Office Waiting Area Nurse's Office Waiting Area	Concrete Block Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Assumed	310 100	SF SF	0	SF SF	Tan
	2	211	Nurse's Office Waiting Area	Cement Floor	Non Suspect ACM	100	SF	0	SF	Tan
	2	211A	Nurse's Office Restroom	Plaster Ceiling	NAD	50	SF	0	SF	
	2	211A 211A	Nurse's Office Restroom Nurse's Office Restroom	Concrete Block Wall Ceramic Tile Floors	Non Suspect ACM Non Suspect ACM	225 50	SF SF	0	SF SF	
	2	211B	Nurse's Office Storage Room	Ceiling Tile 2' x 2'	NAD	50	SF	0	SF	
	2	211B	Nurse's Office Storage Room	Concrete Ceiling	Non Suspect ACM	65	SF	0	SF	
	2	211B 211B	Nurse's Office Storage Room Nurse's Office Storage Room	Concrete Block Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Confirmed	225 30	SF SF	0	SF SF	Brown
_	2	211B	Nurse's Office Storage Room	Floor Tile VAT 12 X 12"	Assumed	20	SF	0	SF	Tan
1	2	211B	Nurse's Office Storage Room	Cement Floor	Non Suspect ACM	50	SF	0	SF	Tan
	2	211C	Nurse's Office Sink Area	Ceiling Tile 2' x 2' Concrete Ceiling	NAD Non Suspect ACM	110	SF SE	0	SF	-
	2	211C 211C	Nurse's Office Sink Area Nurse's Office Sink Area	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	145 420	SF SF	0	SF SF	
1	2	211C	Nurse's Office Sink Area	Floor Tile VAT 12" x 12"	Confirmed	70	SF	0	SF	Brown
	2	211C	Nurse's Office Sink Area	Floor Tile VAT 12" x 12"	Assumed	40	SF	0	SF	Tan
	2	211C 211C	Nurse's Office Sink Area Nurse's Office Sink Area	Cement Floor Sink Undercoat Mastic	Non Suspect ACM Assumed	110 8	SF SF	0	SF SF	Tan White
	2	211D	Nurse's Office	Ceiling Tile 2' x 2'	NAD	220	SF	0	SF	**IIIC
	2	211D	Nurse's Office	Concrete Ceiling	Non Suspect ACM	290	SF	0	SF	
	2	211D	Nurse's Office	Concrete Block Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Confirmed	660	SF	0	SF SF	Brown
	2	211D 211D	Nurse's Office Nurse's Office	Cement Floor	Non Suspect ACM	220 220	SF SF	0	SF	Brown Tan
1	2	211D	Nurses Office	Unit Ventilator Insulation	Assumed	4	SF	0	SF	
	2	122E	Nurse's Office Exam Room Nurse's Office Exam Room	Ceiling Tile 2' x 2'	NAD Non Suspect ACM	100	SF SF	0	SF SF	-
	2	211E 211E	Nurse's Office Exam Room Nurse's Office Exam Room	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	130 310	SF	0	SF	
	2	211E	Nurse's Office Exam Room	Floor Tile VAT 12" x 12"	Confirmed	100	SF	0	SF	Brown
	2	211E	Nurse's Office Exam Room	Cement Floor	Non Suspect ACM	100	SF	0	SF	Tan
	2	218 218	Women's Lounge outside Restroom Women's Lounge outside Restroom	Ceiling Tile 2' x 2' Concrete Ceiling	NAD Non Suspect ACM	95 125	SF SF	0	EA SF	-
	2	218	Women's Lounge outside Restroom	Concrete Block Wall	Non Suspect ACM	420	SF	0	SF	
	2	218	Women's Lounge outside Restroom	Floor Tile VAT 12" x 12"	Confirmed	95	SF	0	SF	Brown
	2	218 219B	Women's Lounge outside Restroom Women's Lounge outside Restroom Pipe Chase	Cement Floor Fiberglass Pipe Insulation	Non Suspect ACM Non Suspect ACM	95 75	SF LF	0	SF LF	
	2	219B	Women's Lounge outside Restroom Pipe Chase	Concrete Ceiling	Non Suspect ACM	48	SF	0	SF	
1	2	219B	Women's Lounge outside Restroom Pipe Chase	Concrete Block Wall	Non Suspect ACM	320	SF	0	SF	
	2	219B	Women's Lounge outside Restroom Pipe Chase	Cement Floor	Non Suspect ACM	48 25	SF SF	0	SF SF	
	2	218 218	2nd Floor Women's Restroom 2nd Floor Women's Restroom	Plaster Ceiling Concrete Block Wall	NAD Non Suspect ACM	160	SF	0	SF	
1	2	218	2nd Floor Women's Restroom	Ceramic Tile Floors	Non Suspect ACM	25	SF	0	SF	
	2	217	2nd Floor Men's Restroom	Plaster Ceiling	NAD	25	SF	0	SF	
	2	217 217	2nd Floor Men's Restroom 2nd Floor Men's Restroom	Concrete Block Wall Ceramic Tile Floors	Non Suspect ACM Non Suspect ACM	160 25	SF SF	0	SF SF	
	2	125	2nd Floor Girl's Restroom	Plaster Ceiling	NAD	170	SF	0	SF	
	2	215	2nd Floor Girl's Restroom	Concrete Block Wall	Non Suspect ACM	420	SF	0	SF	
	2	215 215	2nd Floor Girl's Restroom 2nd Floor Girl's Restroom Pipe Chase	Ceramic Tile Floors Fiberglass Pipe Insulation	Non Suspect ACM Non Suspect ACM	170 50	SF LF	0	SF LF	
	2	215	2nd Floor Girl's Restroom Pipe Chase	Concrete Ceiling	Non Suspect ACM	48	SF	0	SF	
1	2	215	2nd Floor Girl's Restroom Pipe Chase	Concrete Block Wall	Non Suspect ACM	320	SF	0	SF	
	2	215	2nd Floor Girl's Restroom Pipe Chase	Cement Floor	Non Suspect ACM	48	SF SE	0	SF	-
	2	214 214	2nd Floor Boy's Restroom 2nd Floor Boy's Restroom	Plaster Ceiling Concrete Block Wall	NAD Non Suspect ACM	150 385	SF SF	0	SF SF	
1	2	214	2nd Floor Boy's Restroom	Ceramic Tile Floors	Non Suspect ACM	150	SF	0	SF	
	2	214A	Custodial Closet adjacent to Elevator	Concrete Ceiling	Non Suspect ACM	36	SF	0	SF	
	2	214A 214A	Custodial Closet adjacent to Elevator Custodial Closet adjacent to Elevator	Concrete Block Wall Concrete Wall	Non Suspect ACM Non Suspect ACM	100 81	SF SF	0	SF SF	
	2	214A	Custodial Closet adjacent to Elevator	Cement Floor	Non Suspect ACM	36	SF	0	SF	
1	2	212	Storage Room behind Elevator	Fiberglass Pipe Insulation	Non Suspect ACM	15	LF	0	LF	
	2	212 212	Storage Room behind Elevator Storage Room behind Elevator	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	160 520	SF SF	0	SF SF	
	2	212	Storage Room behind Elevator Storage Room behind Elevator	Concrete Block Wall Cement Floor	Non Suspect ACM Non Suspect ACM	120	SF	0	SF	
1	2	222	Office adjacent to Nurse's Office	Ceiling Tile 2' x 2'	NAD	195	SF	2	EA	
	2	222	Office adjacent to Nurse's Office	Concrete Ceiling	Non Suspect ACM	255	SF	0	SF	-
	2	222 222	Office adjacent to Nurse's Office Office adjacent to Nurse's Office	Concrete Block Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Confirmed	560 195	SF SF	0	SF SF	Brown
	2	222	Office adjacent to Nurse's Office	Cement Floor	Non Suspect ACM	195	SF	0	SF	Tan
1	2	222	Office adjacent to Nurse's Office	Blackboard Glue Dots	Assumed	40	SF	0	SF	
	2	214-1 214	Book Closet across from Classroom 107 Book Closet across from Classroom 107	Fiberglass Pipe Insulation Concrete Ceiling	Non Suspect ACM Non Suspect ACM	30 430	LF SF	10	LF SF	-
	2	214	Book Closet across from Classroom 107 Book Closet across from Classroom 107	Concrete Block Wall	Non Suspect ACM	860	SF	0	SF	
1	2	214	Book Closet across from Classroom 107	Cement Floor	Non Suspect ACM	330	SF	0	SF	
	2	214	Book Closet across from Classroom 107	Unit Ventilator Insulation	Assumed	4	SF	0	SF	
	2	131 219	Telecommunication Equipment Room Mail Room	X Ceiling Tile 2' x 2'	X NAD	70	X SF	0 0	X SF	х
	2	219	Mail Room	X	Non Suspect ACM	95	SF	0	SF	
1	2	219	Mail Room	Concrete Block Wall	Non Suspect ACM	340	SF	0	SF	
	2	219 219	Mail Room Mail Room	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Confirmed Assumed	68	SF SF	0	SF SF	Brown
	2	219	Mail Room	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Assumed Assumed	1	SF	0	SF	Tan White
1	2	219 219A	Mail Room Office adjacent to Mail Room	Cement Floor Ceiling Tile 2' x 2'	Non Suspect ACM NAD	70 210	SF SF	0 2	SF EA	

ULCS# 5260

AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report

Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials ar Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage) Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS

			Year Built: 1973	sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED or these materials are not typically known to contain Asbestos)						
E I e m e n	F 1 0	Space # (on	On Site Room Name/Paint and Plaster Survery will be		Confirmed Assumed NAD	Amount of		Amount of	SF LF	Color required for
t	r	Floor Plan)	conducted @ this school	Material Description	Non Suspect ACM	Material	SF LF EA	Damage	EA	VAT
1	2	219A 219A	Office adjacent to Mail Room Office adjacent to Mail Room	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	275 825	SF SF	0	SF SF	
1	2	219A	Office adjacent to Mail Room	Floor Tile VAT 12" x 12"	Confirmed	210	SF	0	SF	Brown
1	2	219A	Office adjacent to Mail Room	Cement Floor	Non Suspect ACM	210	SF LF	0	SF LF	
1	2	219B 219B	Office adjacent to Mail Room Storage Room Office adjacent to Mail Room Storage Room	Fiberglass Pipe Insulation Ceiling Tile 2' x 2'	Non Suspect ACM NAD	5 65	SF	0	SF	
1	2	219B	Office adjacent to Mail Room Storage Room	Concrete Ceiling	Non Suspect ACM	85	SF	0	SF	
1	2	219B 219B	Office adjacent to Mail Room Storage Room Office adjacent to Mail Room Storage Room	Concrete Block Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Confirmed	320 65	SF SF	0	SF SF	Brown
1	2	219B	Office adjacent to Mail Room Storage Room	Cement Floor	Non Suspect ACM	65	SF	0	SF	Brown
1	2	219C	Office adjacent to Mail Room Closet at back of Office	Ceiling Tile 2' x 2'	NAD	30	SF	0	SF	
1	2	219C 219C	Office adjacent to Mail Room Closet at back of Office Office adjacent to Mail Room Closet at back of Office	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	40 220	SF SF	0	SF SF	
1	2	219C	Office adjacent to Mail Room Closet at back of Office	Floor Tile VAT 12" x 12"	Confirmed	30	SF	0	SF	Brown
1	2	219C 219C	Office adjacent to Mail Room Closet at back of Office Office adjacent to Mail Room Closet near Entrance	Cement Floor Ceiling Tile 2' x 2'	Non Suspect ACM NAD	30 25	SF SF	0	SF SF	
1	2	219C	Office adjacent to Mail Room Closet near Entrance	Concrete Ceiling	Non Suspect ACM	35	SF	0	SF	
1	2	219C	Office adjacent to Mail Room Closet near Entrance	Concrete Block Wall	Non Suspect ACM	200	SF	0	SF	
1	2	219C H17	Office adjacent to Mail Room Closet near Entrance Main Lobby	Cement Floor Concrete Ceiling	Non Suspect ACM Non Suspect ACM	25 705	SF SF	0	SF SF	
1	2	H17	Main Lobby	Concrete Block Wall	Non Suspect ACM	580	SF	0	SF	
1	2	H17	Main Lobby	Floor Tile VAT 12" x 12"	Assumed	20	SF	0	SF	White
1	2	H17	Main Lobby Main Lobby	Floor Tile VAT 12" x 12" Cement Floor	Confirmed Non Suspect ACM	520 540	SF SF	0	SF SF	Brown
1	2	H17	Main Lobby	Acoustical Plaster Ceiling	NAD	705	SF	2	SF	
1	2	H17 S22	Main Lobby	Radiator Insulation	Assumed NAD	15 153	SF SF	0	SF SF	-
1	2	S22 S22	Stairwell 1 Stairwell 1	Plaster Ceiling Concrete Block Wall	NAD Non Suspect ACM	835	SF	0	SF	
1	2	S22	Stairwell 1	Cement Floor	Non Suspect ACM	153	SF	0	SF	
1	2	H17	Hallway outside Stairwell 1 Hallway outside Stairwell 1	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	345 740	SF SF	0	SF SF	
1	2	H17A	Hallway outside Stairwell 1	Floor Tile VAT 12" x 12"	Assumed	14	SF	0	SF	White
1	2	H17A	Hallway outside Stairwell 1	Floor Tile VAT 12" x 12"	Assumed	91	SF	0	SF	Tan
1	2	H17A H17	Hallway outside Stairwell 1 Hallway outside Stairwell 1	Floor Tile VAT 12" x 12" Cement Floor	Confirmed Non Suspect ACM	160 265	SF SF	0	SF SF	Brown
1	2	H17A	Hallway outside Stairwell 1	Acoustical Plaster Ceiling	NAD	345	SF	0	SF	
1	2	H17A H223	Hallway outside Stairwell 1 Hallway outside Classroom 116 and Office 117	Radiator Insulation Concrete Ceiling	Assumed Non Suspect ACM	12 265	SF SF	0	SF SF	
1	2	H223	Hallway outside Classroom 116 and Office 117	Concrete Block Wall	Non Suspect ACM	740	SF	0	SF	
1	2	H223	Hallway outside Classroom 116 and Office 117	Floor Tile VAT 12" x 12"	Assumed	204	SF	0	SF	Tan
1	2	H223 H223	Hallway outside Classroom 116 and Office 117 Hallway outside Classroom 116 and Office 117	Cement Floor Acoustical Plaster Ceiling	Non Suspect ACM NAD	204 265	SF SF	0	SF SF	Tan
1	2	H216A	Hallway outside Offices 118-120	Concrete Ceiling	Non Suspect ACM	170	SF	0	SF	
1	2	H216A	Hallway outside Offices 118-120	Concrete Block Wall	Non Suspect ACM	230	SF SF	0	SF SF	Descrip
1	2	H216A H216A	Hallway outside Offices 118-120 Hallway outside Offices 118-120	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Confirmed Assumed	60 70	SF	0	SF	Brown Tan
1	2	H216A	Hallway outside Offices 118-120	Cement Floor	Non Suspect ACM	130	SF	0	SF	
1	2	H216A H216	Hallway outside Offices 118-120 Hallway from 2nd Floor Women's Restroom to Elevator	Acoustical Plaster Ceiling Concrete Ceiling	NAD Non Suspect ACM	170 760	SF SF	0	SF SF	
1	2	H216	Hallway from 2nd Floor Women's Restroom to Elevator	Concrete Block Wall	Non Suspect ACM	1220	SF	0	SF	
1	2	H216	Hallway from 2nd Floor Women's Restroom to Elevator	Transite Sills	Assumed	1	SF	0	SF	140.71
1	2	H216 H216	Hallway from 2nd Floor Women's Restroom to Elevator Hallway from 2nd Floor Women's Restroom to Elevator	Floor Tile VAT 12" x 12" Mastic a/w Floor Tile VAT 12" x 12"	Confirmed Confirmed	100	SF SF	0	SF SF	White Black
1	2	H216	Hallway from 2nd Floor Women's Restroom to Elevator	Floor Tile VAT 12" x 12"	Assumed	300	SF	0	SF	Tan
1	2	H216	Hallway from 2nd Floor Women's Restroom to Elevator	Floor Tile VAT 12" x 12"	Confirmed	185	SF SF	0	SF SF	Brown
1	2	H216 H216	Hallway from 2nd Floor Women's Restroom to Elevator Hallway from 2nd Floor Women's Restroom to Elevator	Cement Floor Acoustical Plaster Ceiling	Non Suspect ACM NAD	585 760	SF	10	SF	
1	2	H219	Hallway from Elevator to Stairwell 2	Concrete Ceiling	Non Suspect ACM	2080	SF	0	SF	
1	2	H219 H219	Hallway from Elevator to Stairwell 2 Hallway from Elevator to Stairwell 2	Concrete Block Wall Transite Sills	Non Suspect ACM Assumed	2000	SF SF	0	SF SF	
1	2	H219	Hallway from Elevator to Stairwell 2	Floor Tile VAT 12" x 12"	Assumed	138	SF	0	SF	Tan
1	2	H219 H216	Hallway from Elevator to Stairwell 2	Floor Tile VAT 12" x 12" Mastic a/w Floor Tile VAT 12" x 12"	Confirmed Confirmed	122	SF SF	0	SF SF	White Black
1	2	H216 H219	Hallway from 2nd Floor Women's Restroom to Elevator Hallway from Elevator to Stairwell 2	Mastic a/w Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Confirmed Confirmed	1340	SF SF	0	SF	Black Brown
1	2	H219	Hallway from Elevator to Stairwell 2	Cement Floor	Non Suspect ACM	1600	SF	0	SF	
1	2	H219 S24	Hallway from Elevator to Stairwell 2 Stairwell 4	Acoustical Plaster Ceiling Concrete Ceiling	NAD Non Suspect ACM	2080 120	SF SF	0	SF SF	-
1	2	S24 S24	Stairweil 4 Stairwell 4	Concrete Block Wall	Non Suspect ACM Non Suspect ACM	120	SF	0	SF	
1	2	S24	Stairwell 4	Cement Floor	Non Suspect ACM	120	SF	0	SF	
1	2	S24 S24	Stairwell 4 Hallway Stairwell 4 Hallway	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	445 880	SF SF	0	SF SF	-
1	2	S24A	Stairwell 4 Hallway	Transite Sills	Assumed	1	SF	0	SF	
1	2	S24A	Stairwell 4 Hallway	Floor Tile VAT 12" x 12"	Assumed	38	SF	0	SF	White
1	2	S24A S24	Stairwell 4 Hallway Stairwell 4 Hallway	Floor Tile VAT 12" x 12" Cement Floor	Confirmed Non Suspect ACM	302 340	SF SF	0	SF SF	Brown
1	2	S24A	Stairwell 4 Hallway	Acoustical Plaster Ceiling	NAD	445	SF	40	SF	
1	2	S24A	Stainwell 4 Hallway	Radiator Insulation Concrete Ceiling	Assumed Non Suspect ACM	15 120	SF SF	0	SF SF	-
1	2	S23 S23	Stairwell 3 Stairwell 3	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	120	SF	0	SF	
1	2	S23	Stairwell 3	Cement Floor	Non Suspect ACM	120	SF	0	SF	
1	2	H222	Stairwell 3 Hallway Stairwell 3 Hallway	Concrete Ceiling	Non Suspect ACM	445 880	SF	0	SF SF	-
1	2	H222 H222	Stairwell 3 Hallway Stairwell 3 Hallway	Concrete Block Wall Transite Sills	Non Suspect ACM Assumed	1	SF SF	0	SF	
1	2	H222	Stairwell 3 Hallway	Floor Tile VAT 12" x 12"	Assumed	38	SF	0	SF	White
1	2	H222	Stairwell 3 Hallway	Floor Tile VAT 12" x 12"	Assumed	96	SF SF	0	SF	Tan
1	2	H222 H222	Stairwell 3 Hallway Stairwell 3 Hallway	Floor Tile VAT 12" x 12" Cement Floor	Confirmed Non Suspect ACM	206 340	SF SF	0	SF SF	Brown
1	2	H222	Stairwell 3 Hallway	Radiator Insulation	Assumed	15	SF	0	SF	
1	2	H222 S21	Stairwell 3 Hallway Stairwell 2	Acoustical Plaster Ceiling Concrete Ceiling	NAD Non Suspect ACM	445 120	SF SF	30 0	SF SF	-
1	2	S21	Stairweil 2 Stairwell 2	Concrete Block Wall	Non Suspect ACM	240	SF	0	SF	
1	2	S21	Stairwell 2	Cement Floor	Non Suspect ACM	120	SF	0	SF	

AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report

Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials ar Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage) Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED or these materials are not typically known to contain Asbestos)

ULCS# 5260
Year Built: 1973

I e	F									
e n	0 0	Space # (on	On Site Room Name/Paint and Plaster Survery will be		Confirmed Assumed NAD	Amount of		Amount of	SF LF	Color required for
1 1	<u>r</u>	Floor Plan) S21	conducted @ this school Stairwell 2 Hallway	Material Description Concrete Ceiling	Non Suspect ACM Non Suspect ACM	Material 445	SF LF EA	Damage 0	<i>EA</i>	VAT
1	2	S21 S21A	Stairwell 2 Hallway Stairwell 2 Hallway	Concrete Block Wall Transite Sills	Non Suspect ACM Assumed	880 1	SF SF	0	SF SF	
1	2	S21A	Stairwell 2 Hallway	Floor Tile VAT 12" x 12"	Assumed	104	SF	0	SF	Tan
1	2	S21A S21	Stairwell 2 Hallway Stairwell 2 Hallway	Floor Tile VAT 12" x 12" Cement Floor	Confirmed Non Suspect ACM	236 340	SF SF	0	SF SF	Brown Tan
1	2	S21A S21A	Stairwell 2 Hallway Stairwell 2 Hallway	Radiator Insulation Acoustical Plaster Ceiling	Assumed NAD	15 445	SF SF	0 35	SF SF	
1	2	H218	Hallway outside Classrooms 101-102	Concrete Ceiling	Non Suspect ACM	890	SF	0	SF	
1	2	H218 H218	Hallway outside Classrooms 101-102 Hallway outside Classrooms 101-102	Concrete Block Wall Transite Sills	Non Suspect ACM Assumed	1350	SF SF	0	SF SF	
1	2	H218	Hallway outside Classrooms 101-102	Floor Tile VAT 12" x 12"	Assumed	49	SF	0	SF	White
1	2	H218 H218	Hallway outside Classrooms 101-102 Hallway outside Classrooms 101-102	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Assumed Assumed	8	SF SF	0	SF SF	Tan Tan
1	2	H218 H218	Hallway outside Classrooms 101-102 Hallway outside Classrooms 101-102	Floor Tile VAT 12" x 12"	Confirmed Non Suspect ACM	622 682	SF SF	0	SF SF	Brown Tan
1	2	H218	Hallway outside Classrooms 101-102	Cement Floor Acoustical Plaster Ceiling	NAD	890	SF	0	SF	Tall
1	2	219D 219D	Storage Room behind Women's Restroom Storage Room behind Women's Restroom	Fiberglass Pipe Insulation Concrete Ceiling	Non Suspect ACM Non Suspect ACM	40 160	LF SF	5	LF SF	
1	2	219D	Storage Room behind Women's Restroom	Concrete Block Wall	Non Suspect ACM	460	SF	0	SF	
1	1	219D 101	Storage Room behind Women's Restroom Art Room	Cement Floor Fiberglass Pipe Insulation	Non Suspect ACM Non Suspect ACM	120 300	SF LF	0	SF LF	
1	1	101 101	Art Room Art Room	Ceiling Tile 2' x 4'	Non Suspect ACM Non Suspect ACM	355 600	SF SF	6	EA SF	
1	1	101	Art Room	Fiberglass Ceiling Tile 2' x 4' Concrete Ceiling	Non Suspect ACM	2030	SF	0	SF	
1	1	101 101	Art Room Art Room	Concrete Wall Concrete Block Wall	Non Suspect ACM Non Suspect ACM	790 790	SF SF	0	SF SF	
1	1	101	Art Room	Floor Tile VAT 12" x 12"	Assumed	1560	SF	0	SF	Tan
1	1	101 101	Art Room Art Room	Cement Floor Blackboard Glue Dots	Non Suspect ACM Assumed	1560 65	SF SF	0	SF SF	Tan
1	1	101 101	Art Room Art Room	Acoustical Plaster Ceiling Kiln	NAD Assumed	2030 50	SF SF	0	SF SF	
1	1	101A	Art Room Closet by Entrance	Concrete Ceiling	Non Suspect ACM	175	SF	0	SF	
1	1	101A 101A	Art Room Closet by Entrance Art Room Closet by Entrance	Concrete Block Wall Cement Floor	Non Suspect ACM Non Suspect ACM	480 135	SF SF	0	SF SF	
1	1	101B	Art Room Closet by Kiln	Fiberglass Pipe Insulation	Non Suspect ACM	75	LF	0	LF	
1	1	101B 101B	Art Room Closet by Kiln Art Room Closet by Kiln	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	205 430	SF SF	0	SF SF	
1	1	101B 101B	Art Room Closet by Kiln Art Room Closet by Kiln	Concrete Wall Cement Floor	Non Suspect ACM Non Suspect ACM	90 155	SF SF	0	SF SF	
1	1	NP1	Crawlspace adjacent to Art Room	x	x	х	х	х	х	х
1	1	101B 102	Storage Room adjacent to Stairwell 2 Storage Room adjacent to Stairwell 2	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	235 900	SF SF	0	SF SF	
1	1	102	Storage Room adjacent to Stairwell 2	Cement Floor	Non Suspect ACM	235	SF	0	SF	
1	1	103 103A	Crawlspace between Stairwell 2 and Classroom B02 Closet across from Classroom B02	x Concrete Ceiling	Non Suspect ACM	35	X SF	0 0	X SF	х
1	1	103A 103A	Closet across from Classroom B02 Closet across from Classroom B02	Concrete Block Wall Cement Floor	Non Suspect ACM Non Suspect ACM	240 35	SF SF	0	SF SF	
1	1	104	Classroom B02	Fiberglass Pipe Insulation	Non Suspect ACM	80	LF	20	LF	
1	1	104 104	Classroom B02 Classroom B02	Ceiling Tile 2' x 4' Concrete Ceiling	Non Suspect ACM Non Suspect ACM	200 1345	SF SF	0	SF SF	
1	1	104 104	Classroom B02 Classroom B02	Concrete Block Wall Brick Wall	Non Suspect ACM Non Suspect ACM	1400 50	SF SF	0	SF SF	
1	1	104	Classroom B02	Floor Tile VAT 12" x 12"	NAD	1035	SF	0	SF	Tan/Marble
1	1	104 104	Classroom B02 Classroom B02	Cement Floor Blackboard Glue Dots	Non Suspect ACM Assumed	1035 60	SF SF	0	SF SF	
1	1	104	Classroom B02	Acoustical Plaster Ceiling	NAD	1345	SF	0	SF	
1	1	105 105	Classroom B03 Classroom B03	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	795 1000	SF SF	0	SF SF	
1	1	105 105	Classroom B03 Classroom B03	Floor Tile VAT 12" x 12" Cement Floor	Assumed Non Suspect ACM	610 610	SF SF	0	SF SF	Tan
1	1	105	Classroom B03	Blackboard Glue Dots	Assumed	60	SF	0	SF	
1	1	105 104A	Classroom B03 Classroom B02 Closet	Acoustical Plaster Ceiling Concrete Ceiling	NAD Non Suspect ACM	795 130	SF SF	0	SF SF	
1	1	104A 104A	Classroom B02 Closet Classroom B02 Closet	Concrete Block Wall Cement Floor	Non Suspect ACM Non Suspect ACM	400 100	SF SF	0	SF SF	
1	1	105A	Classroom B03 Closet adjacent to Hallway	Ceiling Tile 2' x 4'	Non Suspect ACM	100	SF	1	EA	
1	1	105A 105A	Classroom B03 Closet adjacent to Hallway Classroom B03 Closet adjacent to Hallway	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	130 400	SF SF	0	SF SF	
1	1	105A	Classroom B03 Closet adjacent to Hallway	Floor Tile VAT 12" x 12"	Assumed	100	SF	0	SF	Tan
1	1	105A 105B	Classroom B03 Closet adjacent to Hallway Classroom B03 Closet adjacent to Classroom B02	Cement Floor Ceiling Tile 2' x 4'	Non Suspect ACM Non Suspect ACM	100 100	SF SF	0	SF SF	
1	1	105B 105B	Classroom B03 Closet adjacent to Classroom B02 Classroom B03 Closet adjacent to Classroom B02	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	130 400	SF SF	0	SF SF	
1	1	105B	Classroom B03 Closet adjacent to Classroom B02	Floor Tile VAT 12" x 12"	Assumed	100	SF	0	SF	Tan
1	1	105B 106	Classroom B03 Closet adjacent to Classroom B02 Classroom B04	Cement Floor Ceiling Tile 2' x 4'	Non Suspect ACM Non Suspect ACM	100 140	SF SF	0 2	SF EA	
1	1	106	Classroom B04	Fiberglass Ceiling Tile 2' x 4'	Non Suspect ACM	140	SF	0	SF	
1	1	106 106	Classroom B04 Classroom B04	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	1145 720	SF SF	0	SF SF	
1	1	106	Classroom B04	Concrete Wall	Non Suspect ACM	140	SF SF	0	SF	
1	1	106 106	Classroom B04 Classroom B04	Brick Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Confirmed	50 870	SF	0	SF SF	Tan
1	1	106 106	Classroom B04 Classroom B04	Mastic a/w Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Confirmed Assumed	870 10	SF SF	0	SF SF	Black Tan
1	1	106	Classroom B04	Cement Floor	Non Suspect ACM	880	SF	0	SF	
1	1	106 106	Classroom B04 Classroom B04	Blackboard Glue Dots Acoustical Plaster Ceiling	Assumed NAD	50 1145	SF SF	0	SF SF	
1	1	106A	Classroom B04 Closet Classroom B04 Closet	Fiberglass Ceiling Tile 2' x 4'	Non Suspect ACM Non Suspect ACM	330	SF SF	0	SF SF	
1	1	106A 106A	Classroom B04 Closet	Concrete Ceiling Concrete Block Wall	Non Suspect ACM	430 740	SF	0	SF	
1	1	106A	Classroom B04 Closet	Floor Tile VAT 12" x 12"	Assumed	330	SF	0	SF	

AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report

Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials ar Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage)

Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED or these materials are not typically known to contain Asbestos)

ULCS# 5260 Year Built: 1973

			Year Built: 1973	DETECTED or these materials are	not typically known to contain	Asbestos)				
E										
é	F									
m	1									
e	0	Snoon # (on	On Site Room Name/Paint and Plaster Survery will be		Confirmed Assumed NAD	Amount of		Amount of	SF LF	Color required for
n t	o r	Space # (on Floor Plan)	conducted @ this school	Material Description	Non Suspect ACM	Material	SF LF EA	Damage	SF LF EA	VAT
1	1	106A	Classroom B04 Closet	Cement Floor	Non Suspect ACM	330	SF	0	SF	
1	1	100	Auditorium/Cafeteria	Fiberglass Ceiling Tile 2' x 2'	Non Suspect ACM	870	SF	0	SF	
1	1	100	Auditorium/Cafeteria	Ceiling Tile 2' x 2'	NAD	2030	SF	20	EA	
1	1	100	Auditorium/Cafeteria	Concrete Ceiling	Non Suspect ACM	9280	SF	0	SF	
1	11	100	Auditorium/Cafeteria	Concrete Block Wall	Non Suspect ACM	5410	SF	0	SF	-
1	1	100 100	Auditorium/Cafeteria Auditorium/Cafeteria	Transite Sills Floor Tile VAT 12" x 12"	Assumed Assumed	1 3965	SF SF	0	SF SF	Tan
1	1	100	Auditorium/Cafeteria Auditorium/Cafeteria	Floor Tile VAT 12 X 12"	Assumed	260	SF	0	SF	Grey
1	1	100	Auditorium/Cafeteria	Floor Tile VAT 12" x 12"	Assumed	660	SF	0	SF	Blue
1	1	100	Auditorium/Cafeteria	Cement Floor	Non Suspect ACM	7138	SF	0	SF	
1	1	100	Auditorium/Cafeteria	Acoustical Plaster Ceiling	NAD	5510	SF	50	SF	
1	1	100	Auditorium/Cafeteria	Unit Ventilator Insulation	Assumed	40	SF	0	SF	_
1	1	100 100	Auditorium Stage	Concrete Ceiling	Non Suspect ACM	795	SF SF	0	SF SF	
1	1	100	Auditorium Stage Auditorium Stage	Concrete Block Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Confirmed	465 610	SF	0	SF	Tan
1	1	100	Auditorium Stage	Cement Floor	Non Suspect ACM	610	SF	0	SF	Tan
1	1	100	Auditorium Stage	Acoustical Plaster Ceiling	NAD	795	SF	0	SF	
1	1	114	Teacher Lounge	Fiberglass Pipe Insulation	Non Suspect ACM	60	LF	0	LF	
1	1	114	Teacher Lounge	Ceiling Tile 2' x 4'	Non Suspect ACM	200	SF	0	SF	
1	1	114	Teacher Lounge	Fiberglass Ceiling Tile 2' x 4'	Non Suspect ACM	64	SF	0	SF	
1	11	114	Teacher Lounge	Concrete Ceiling	Non Suspect ACM	755	SF	0	SF	+
1	1	114 114	Teacher Lounge Teacher Lounge	Concrete Block Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Confirmed	900 523	SF SF	0	SF SF	Tan
1	1	114	Teacher Lounge	Floor Tile VAT 12 x 12 Floor Tile VAT 12" x 12"	Assumed	57	SF	0	SF	White
1	1	114	Teacher Lounge	Cement Floor	Non Suspect ACM	580	SF	0	SF	7******
1	1	114	Teacher Lounge	Acoustical Plaster Ceiling	NAD	410	SF	0	SF	
1	1	114	Teacher Lounge	Unit Ventilator Insulation	Assumed	4	SF	0	SF	
1	1	113A	Kitchen Serving Area	Ceiling Tile 2' x 2'	NAD	195	SF	3	EA	
1	11	113A	Kitchen Serving Area	Concrete Ceiling	Non Suspect ACM	255	SF	0	SF	-
1	1	113A 113A	Kitchen Serving Area Kitchen Serving Area	Concrete Block Wall Ceramic Tile Floors	Non Suspect ACM Non Suspect ACM	400 195	SF SF	0	SF SF	
1	1	113A 113	Kitchen Serving Area Kitchen	Ceiling Tile 2' x 2'	Non Suspect ACM NAD	245	SF	1	EA	
1	1	113	Kitchen	Concrete Ceiling	Non Suspect ACM	320	SF	0	SF	
1	1	113	Kitchen	Concrete Block Wall	Non Suspect ACM	660	SF	0	SF	
1	1	113	Kitchen	Ceramic Tile Floors	Non Suspect ACM	245	SF	0	SF	
1	1	108	Boy's Restroom	Plaster Ceiling	NAD	174	SF	10	SF	
1	1	108	Boy's Restroom	Sheetrock Ceiling	Non Suspect ACM	16	SF	1	SF	
1	1	108	Boy's Restroom	Concrete Block Wall	Non Suspect ACM	465	SF SF	0	SF SF	-
1	1	108 108A	Boy's Restroom Boy's Restroom Elevator Mechanical Room	Ceramic Tile Floors Ceiling Tile 2' x 2'	Non Suspect ACM NAD	190 75	SF	0	SF	
1	1	108A	Boy's Restroom Elevator Mechanical Room	Concrete Ceiling	Non Suspect ACM	100	SF	0	SF	+
1	1	108A	Boy's Restroom Elevator Mechanical Room	Concrete Block Wall	Non Suspect ACM	360	SF	0	SF	+
1	1	108A	Boy's Restroom Elevator Mechanical Room	Cement Floor	Non Suspect ACM	75	SF	0	SF	
1	1	107	Girl's Restroom	Plaster Ceiling	NAD	145	SF	0	SF	
1	1	107	Girl's Restroom	Concrete Block Wall	Non Suspect ACM	355	SF	0	SF	
1	1	107	Girl's Restroom	Ceramic Tile Floors	Non Suspect ACM	145	SF LF	0	SF	
1	1	110 110	Men's Restroom Men's Restroom	Fiberglass Pipe Insulation Plaster Ceiling	Non Suspect ACM NAD	55	SF	0	LF SF	
1	1	110	Men's Restroom	Concrete Block Wall	Non Suspect ACM	260	SF	0	SF	
1	1	110	Men's Restroom	Ceramic Tile Floors	Non Suspect ACM	55	SF	0	SF	
1	1	111	Women's Restroom	Plaster Ceiling	NAD	55	SF	0	SF	
1	1	111	Women's Restroom	Concrete Block Wall	Non Suspect ACM	260	SF	0	SF	
1	1	111	Women's Restroom	Ceramic Tile Floors	Non Suspect ACM	55	SF	0	SF	
1	1	112 112	Cafeteria Staff Locker Room Cafeteria Staff Locker Room	Ceiling Tile 2' x 2'	NAD Non Suspect ACM	42 42	SF SF	0	SF SF	-
1	1	112	Cafeteria Staff Locker Room Cafeteria Staff Locker Room	Concrete Ceiling Concrete Block Wall	Non Suspect ACM	210	SF	0	SF	-
1	1	112	Cafeteria Staff Locker Room	Floor Tile VAT 12" x 12"	Confirmed	42	SF	0	SF	Tan
1	1	112	Cafeteria Staff Locker Room	Cement Floor	Non Suspect ACM	42	SF	0	SF	
1	1	112A	Cafeteria Staff Locker Room Restroom	Plaster Ceiling	NAD	35	SF	0	SF	$\perp =$
1	1	112A	Cafeteria Staff Locker Room Restroom	Concrete Block Wall	Non Suspect ACM	195	SF	0	SF	
1	11	112A	Cafeteria Staff Locker Room Restroom	Ceramic Tile Floors	Non Suspect ACM	35	SF	0	SF	
1	1	112A 109	Cafeteria Staff Locker Room Restroom Gymnasium	Cement Floor Tectum Panels	Non Suspect ACM Non Suspect ACM	35 4740	SF SF	0	SF SF	
1	1	109	Gymnasium	Concrete Block Wall	Non Suspect ACM	9730	SF	0	SF	
1	1	109	Gymnasium	Floor Tile Mastic	Confirmed	4740	SF	0	SF	Black
1	1	109	Gymnasium	Cement Floor	Non Suspect ACM	4740	SF	0	SF	$\perp =$
1	1	109	Gymnasium	Vibration Damper Cloth	Assumed	40	SF	0	SF	
1	1	109B 109B	Gym Storage Room Gym Storage Room	Fiberglass Pipe Insulation Concrete Ceiling	Non Suspect ACM Non Suspect ACM	50 235	LF SF	5	LF SF	
1	1	109B 109B	Gym Storage Room Gym Storage Room	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	540	SF	0	SF	\vdash
1	1	109B	Gym Storage Room	Cement Floor	Non Suspect ACM	180	SF	0	SF	
1	1	109A	Vestibule outside Girl's Locker Room	Fiberglass Pipe Insulation	Non Suspect ACM	8	LF	0	LF	
1	1	109A	Vestibule outside Girl's Locker Room	Concrete Ceiling	Non Suspect ACM	55	SF	0	SF	
1	1	109A	Vestibule outside Girl's Locker Room	Concrete Block Wall	Non Suspect ACM	260	SF	0	SF	
1	1	109A	Vestibule outside Girl's Locker Room	Cement Floor	Non Suspect ACM	40	SF	0	SF	-
1	11	109A	Girl's Locker Room	Plaster Ceiling	NAD Nan Sugnest ACM	265	SF	20	SF	+
1	1	109A 109A	Girl's Locker Room Girl's Locker Room	Concrete Block Wall Cement Floor	Non Suspect ACM Non Suspect ACM	465 265	SF SF	0	SF SF	
1	1	109A 109A	Girl's Locker Room Showers	Plaster Ceiling	NOTI SUSPECT ACMI NAD	180	SF	0	SF	
1	1	109A	Girl's Locker Room Showers	Concrete Block Wall	Non Suspect ACM	465	SF	0	SF	
1	1	109A	Girl's Locker Room Showers	Ceramic Tile Walls	Non Suspect ACM	150	SF	0	SF	
1	1	109A	Girl's Locker Room Showers	Cement Floor	Non Suspect ACM	180	SF	0	SF	
1	1	109A	Girl's Locker Room Restroom	Plaster Ceiling	NAD	60	SF	0	SF	ļ
1	11	109A	Girl's Locker Room Restroom	Concrete Block Wall	Non Suspect ACM	180	SF	0	SF	-
1	1	109A 109A	Girl's Locker Room Restroom	Cement Floor Pipe Fitting Insulation	Non Suspect ACM	60 10	SF EA	0	SF EA	+
1	1	109A 109A	Girl's Locker Room Pipe Chase Girl's Locker Room Pipe Chase	Fiberglass Pipe Insulation	Assumed Non Suspect ACM	30	EA LF	0	LF	+
1	1	109A	Girl's Locker Room Pipe Chase	Concrete Ceiling	Non Suspect ACM	15	SF	0	SF	
1	1	109A	Girl's Locker Room Pipe Chase	Concrete Block Wall	Non Suspect ACM	160	SF	0	SF	
1	1	109A	Girl's Locker Room Pipe Chase	Cement Floor	Non Suspect ACM	15	SF	0	SF	
<u> </u>			Gym Office	Ceiling Tile 2' x 2'	NAD	120	SF	5	EA	1
1 1	1	109C 109C	Gym Office	Concrete Ceiling	Non Suspect ACM	160	SF	0	SF	

ULCS# 5260

AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report

Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials at Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage) Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED or these materials are not typically known to contain Asbestos)

Year Built: 1973

			Year Built: 1973	DETECTED or these materials are		Asbestos)				
F										
e	F									
m e	0									Color
n	0	Space # (on	On Site Room Name/Paint and Plaster Survery will be		Confirmed Assumed NAD	Amount of		Amount of	SF_LF	required for
1	<u>r</u>	Floor Plan) 109C	conducted @ this school Gym Office	Material Description Concrete Block Wall	Non Suspect ACM Non Suspect ACM	Material 285	SF LF EA	Damage 0	EA SF	VAT
1	1	109C	Gym Office	Floor Tile VAT 12" x 12"	Assumed	6	SF	0	SF	Tan
1	1	109C	Gym Office	Floor Tile VAT 12" x 12"	Assumed	26	SF	0	SF	Tan
1	1	109C 109C	Gym Office Gym Office	Floor Tile VAT 12" x 12" Cement Floor	Confirmed Non Suspect ACM	88 120	SF SF	0	SF SF	Tan
1	1	109C	Gym Office Restroom	Plaster Ceiling	NAD NAD	32	SF	0	SF	
1	1	109C	Gym Office Restroom	Sheetrock Ceiling	Non Suspect ACM	16	SF	0	SF	
1	1	109C	Gym Office Restroom	Concrete Block Wall	Non Suspect ACM	225	SF	0	SF	
1	1	109C 109D	Gym Office Restroom Vestibule outside Boy's Locker Room	Ceramic Tile Floors Concrete Ceiling	Non Suspect ACM Non Suspect ACM	48 55	SF SF	0	SF SF	
1	1	109D	Vestibule outside Boy's Locker Room Vestibule outside Boy's Locker Room	Concrete Block Wall	Non Suspect ACM	260	SF	0	SF	
1	1	109D	Vestibule outside Boy's Locker Room	Cement Floor	Non Suspect ACM	40	SF	0	SF	Tan
1	1	109D	Boy's Locker Room	Plaster Ceiling	NAD	400	SF	50	SF	
1	1	109D 109D	Boy's Locker Room Boy's Locker Room	Concrete Block Wall Cement Floor	Non Suspect ACM Non Suspect ACM	640 400	SF SF	0	SF SF	
1	1	109D	Boy's Locker Room Pipe Chase	Fiberglass Pipe Insulation	Non Suspect ACM	30	LF	0	LF	
1	1	109D	Boy's Locker Room Pipe Chase	Concrete Ceiling	Non Suspect ACM	30	SF	0	SF	
1	1	109D 109D	Boy's Locker Room Pipe Chase Boy's Locker Room Pipe Chase	Concrete Block Wall Cement Floor	Non Suspect ACM Non Suspect ACM	260 30	SF SF	0	SF SF	
1	1	109D	Boy's Locker Room former Shower Area	Plaster Ceiling	NAD NAD	100	SF	0	SF	
1	1	109E	Boy's Locker Room former Shower Area	Ceramic Tile Walls	Non Suspect ACM	320	SF	0	SF	
1	1	109E	Boy's Locker Room former Shower Area	Cement Floor	Non Suspect ACM	100	SF	0	SF	
1	1	109E 109E	Custodial Closet in Hallway to Gym Custodial Closet in Hallway to Gym	Fiberglass Pipe Insulation Concrete Ceiling	Non Suspect ACM Non Suspect ACM	8 54	LF SF	0	LF SF	
1	1	109E	Custodial Closet in Hallway to Gym	Concrete Block Wall	Non Suspect ACM Non Suspect ACM	216	SF	0	SF	
1	1	109E	Custodial Closet in Hallway to Gym	Cement Floor	Non Suspect ACM	54	SF	0	SF	
1	1	136A	Storage Room between Building Engineer's Office and Electrical Room	Concrete Ceiling	Non Suspect ACM	225	SF	0	SF	
+		130A	Storage Room between Building Engineer's Office and	Concrete Celling	INUIT SUSPECT ACM	223		0		
1	1	136A	Electrical Room	Concrete Block Wall	Non Suspect ACM	255	SF	0	SF	
1	1	136A	Storage Room between Building Engineer's Office and Electrical Room	Concrete Wall	Non Suspect ACM	255	SF	0	SF	
Ť			Storage Room between Building Engineer's Office and							
1	1	136A	Electrical Room	Cement Floor	Non Suspect ACM	170	SF	0	SF	
1	1	S15 142	Electrical Room Stairs Electrical Room	Metal Floor Concrete Ceiling	Non Suspect ACM Non Suspect ACM	40 224	SF SF	0	SF SF	
1	1	142	Electrical Room	Concrete Block Wall	Non Suspect ACM	660	SF	0	SF	
1	1	142	Electrical Room	Concrete Wall	Non Suspect ACM	240	SF	0	SF	
1	1	142 139	Electrical Room Storage Room adjacent to Building Engineer's Office	Cement Floor Concrete Ceiling	Non Suspect ACM Non Suspect ACM	224 225	SF SF	0	SF SF	
1	1	139	Storage Room adjacent to Building Engineer's Office	Concrete Block Wall	Non Suspect ACM	340	SF	0	SF	
1	1	139	Storage Room adjacent to Building Engineer's Office	Cement Floor	Non Suspect ACM	170	SF	0	SF	
1	1	136	Building Engineer's Office	Fiberglass Pipe Insulation	Non Suspect ACM	200	LF	50	LF	
1	1	136 136	Building Engineer's Office Building Engineer's Office	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	1405 3240	SF SF	0	SF SF	
1	1	136	Building Engineer's Office	Cement Floor	Non Suspect ACM	1080	SF	0	SF	
1	1	137	Vestibule outside Building Engineer's Restroom	Fiberglass Pipe Insulation	Non Suspect ACM	30	LF	0	LF	
1	1	137 137	Vestibule outside Building Engineer's Restroom	Concrete Ceiling	Non Suspect ACM	85 195	SF SF	0	SF SF	
1	1	137	Vestibule outside Building Engineer's Restroom Vestibule outside Building Engineer's Restroom	Concrete Block Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Assumed	65	SF	0	SF	Tan
1	1	137	Vestibule outside Building Engineer's Restroom	Cement Floor	Non Suspect ACM	65	SF	0	SF	Tan
1	1	139	Building Engineer's Restroom	Fiberglass Pipe Insulation	Non Suspect ACM	10	LF	0	LF	
1	1	139 139	Building Engineer's Restroom Building Engineer's Restroom	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	60 280	SF SF	0	SF SF	
1	1	139	Building Engineer's Restroom	Ceramic Tile Floors	Non Suspect ACM	45	SF	0	SF	
1	1	S17	Boiler Room Stairs	Metal Floor	Non Suspect ACM	40	SF	0	SF	
1	1	144	Boiler Room	Pipe Fitting Insulation	Assumed	6	EA	0	EA	
1	1	141 141	Boiler Room Boiler Room	Fiberglass Pipe Insulation Concrete Ceiling	Non Suspect ACM Non Suspect ACM	300 760	LF SF	10	LF SF	
1	1	141	Boiler Room	Concrete Block Wall	Non Suspect ACM Non Suspect ACM	1100	SF	0	SF	
1	1	141	Boiler Room	Concrete Wall	Non Suspect ACM	800	SF	0	SF	
1	1	144	Boiler Room	Boiler Breeching	Confirmed	250	SF	0	SF	
1	1	144 144	Boiler Room Boiler Room	Tank Insulation Acoustical Plaster Ceiling	Confirmed NAD	100 2500	SF SF	0	SF SF	
1	1	141	Boiler Room	Cement Floor	Non Suspect ACM	760	SF	0	SF	
1	1	H11	Hallway outside Art Room	Concrete Block Wall	Non Suspect ACM	1180	SF	0	SF	
1	1	H11 H11	Hallway outside Art Room Hallway outside Art Room	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Assumed Confirmed	472	SF SF	0	SF SF	Tan Tan
1	1	H11	Hallway outside Art Room Hallway outside Art Room	Transite Sills	Assumed	1	SF	0	SF	ıdfi
1	1	H11	Hallway outside Art Room	Cement Floor	Non Suspect ACM	472	SF	0	SF	Tan
1	1	S18	Stairs to back of Stage	Floor Tile VAT 12" x 12"	Confirmed	30	SF	0	SF	Tan
1	1	S18 S11	Stairs to back of Stage Stairwell 2	Cement Floor Concrete Ceiling	Non Suspect ACM Non Suspect ACM	40 65	SF SF	0	SF SF	
1	1	S11 S11	Stairweil 2 Stairwell 2	Concrete Celling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	150	SF	0	SF	
1	1	S11	Stairwell 2	Floor Tile VAT 12" x 12"	Confirmed	48	SF	0	SF	Tan
1	1	S11	Stairwell 2	Cement Floor	Non Suspect ACM	48	SF	0	SF	Tan
1	1	S11 S11	Stairwell 2 Stairwell 2	Acoustical Plaster Ceiling Radiator Insulation	NAD Assumed	65 12	SF SF	0	SF SF	
1	1	S13	Stairwell 3	Fiberglass Pipe Insulation	Non Suspect ACM	12	LF	0	LF	
1	1	S13	Stairwell 3	Concrete Ceiling	Non Suspect ACM	65	SF	0	SF	
1	1	S13	Stairwell 3	Concrete Block Wall	Non Suspect ACM	150	SF	0	SF	
1	1	S13 S13	Stairwell 3 Stairwell 3	Floor Tile VAT 12" x 12" Cement Floor	Confirmed Non Suspect ACM	48 48	SF SF	0	SF SF	Tan
1	1	S13 S13	Stairweii 3 Stairweii 3	Acoustical Plaster Ceiling	Non Suspect ACM NAD	65	SF	0	SF	
1	1	S13	Stairwell 3	Radiator Insulation	Assumed	12	SF	0	SF	
1	1	H12A	Hallway to Classroom B02	Ceiling Tile 2' x 4'	Non Suspect ACM	170	SF	0	SF	
1	1	H12A H12A	Hallway to Classroom B02 Hallway to Classroom B02	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	225 620	SF SF	0	SF SF	
1	1	H12A	Hallway to Classroom B02	Floor Tile VAT 12" x 12"	Confirmed	97	SF	0	SF	Tan
1	1	H12A	Hallway to Classroom B02	Floor Tile VAT 12" x 12"	Assumed	73	SF	0	SF	Tan
1	1	H12A	Hallway to Classroom B02	Cement Floor	Non Suspect ACM	170	SF	0	SF	
1	1	H12	Hallway outside Classroom B03	Concrete Ceiling	Non Suspect ACM	1785	SF	0	SF	I

ULCS# 5260 Year Built: 1973

AHERA Three-Year Reinspection 2018-2019 Room by Room Location Log Report

Red= Confirmed (Contact OEMS prior to the disturbance of any of the following materials ar Yellow= Assumed (Contact OEMS for assessment and sampling prior to the disturbance of these materials and report damage) Green= Non Asbestos Containing/Non Suspect Material (These materials have been sampled and Laboratory Analysis has indicated NO Asbestos present or NO ASBESTOS DETECTED or these materials are not typically known to contain Asbestos)

E I e	F									
m e n) 0 0	Space # (on	On Site Room Name/Paint and Plaster Survery will be		Confirmed Assumed NAD	Amount of		Amount of	SF LF	Color required for
1 1	<u>r</u>	Floor Plan) H12	conducted @ this school Hallway outside Classroom B03	Material Description	Non Suspect ACM Non Suspect ACM	Material 1960	SF LF EA	Damage 0	EA SF	VAT
1	1	H12	Hallway outside Classroom B03	Concrete Block Wall Floor Tile VAT 12" x 12"	Confirmed	240	SF	0	SF	Tan
1	1	H12	Hallway outside Classroom B03	Floor Tile VAT 12" x 12"	Assumed	1132	SF	0	SF	Tan
1	1	H12	Hallway outside Classroom B03	Transite Sills	Assumed	1	SF	0	SF	
1	1	H12	Hallway outside Classroom B03	Cement Floor	Non Suspect ACM	1372	SF	0	SF	Tan
1	1	H12	Hallway outside Classroom B03	Acoustical Plaster Ceiling	NAD Nac Support A CM	1785	SF	2	SF	
1	1	S14 S14	Stairwell 4 Stairwell 4	Concrete Ceiling Concrete Block Wall	Non Suspect ACM Non Suspect ACM	495 980	SF SF	0	SF SF	
1	1	S14	Stairwell 4	Transite Sills	Assumed	1	SF	0	SF	
1	1	S14	Stairwell 4	Floor Tile VAT 12" x 12"	Confirmed	380	SF	0	SF	Tan
1	1	S14	Stairwell 4	Cement Floor	Non Suspect ACM	380	SF	0	SF	
1	1	S14	Stairwell 4	Acoustical Plaster Ceiling	NAD	495	SF	0	SF	
1	1	S14	Stairwell 4	Radiator Insulation	Assumed	12	SF	0	SF	
1	1	H13	Hallway from Stairwell 4 to Cafeteria	Concrete Ceiling	Non Suspect ACM	450	SF	0	SF	
1	1	H13 H13	Hallway from Stairwell 4 to Cafeteria Hallway from Stairwell 4 to Cafeteria	Concrete Block Wall Transite Sills	Non Suspect ACM	835	SF SF	0	SF SF	
1	1	H13	Hallway from Stairwell 4 to Caleteria	Floor Tile VAT 12" x 12"	Assumed Assumed	6	SF	0	SF	Tan
1	1	H13	Hallway from Stairwell 4 to Cafeteria	Floor Tile VAT 12 X 12"	Assumed	4	SF	0	SF	Blue
<u> </u>		1110	Trainey non-stained rito salstona	1 1001 1110 1711 12 X 12	7100011100	-	<u> </u>		- U.	Mosaic/Marbl
1	1	H13	Hallway from Stairwell 4 to Cafeteria	Floor Tile VAT 12" x 12"	Assumed	1	SF	0	SF	е
1	1	H13	Hallway from Stairwell 4 to Cafeteria	Floor Tile VAT 12" x 12"	Confirmed	334	SF	0	SF	Tan
1	1	H13	Hallway from Stairwell 4 to Cafeteria	Cement Floor	Non Suspect ACM	345	SF	0	SF	-
1	1	H13 H13A	Hallway from Stairwell 4 to Cafeteria Hallway outside Elevator and Boy's Restroom	Acoustical Plaster Ceiling Fiberglass Ceiling Tile 2' x 4'	NAD Non Suspect ACM	450 100	SF SF	0	SF SF	
1	1	H13A	Hallway outside Elevator and Boy's Restroom Hallway outside Elevator and Boy's Restroom	Concrete Ceiling	Non Suspect ACM	130	SF	0	SF	
1	1	H13A	Hallway outside Elevator and Boy's Restroom	Concrete Block Wall	Non Suspect ACM	420	SF	0	SF	
1	1	H13A	Hallway outside Elevator and Boy's Restroom	Floor Tile VAT 12" x 12"	Assumed	100	SF	0	SF	Tan
1	1	H13	Hallway outside Elevator and Boy's Restroom	Cement Floor	Non Suspect ACM	100	SF	0	SF	
1	1	H13C	Hallway outside Elevator and Boy's Restroom Pipe Chase	Fiberglass Pipe Insulation	Non Suspect ACM	100	LF	0	LF	
1	1	H13C	Hallway outside Elevator and Boy's Restroom Pipe Chase	Concrete Ceiling	Non Suspect ACM	75	SF	0	SF	
1	1	H13C	Hallway outside Elevator and Boy's Restroom Pipe Chase	Concrete Block Wall	Non Suspect ACM	560	SF	0	SF	
1	1	H13C H13B	Hallway outside Elevator and Boy's Restroom Pipe Chase	Cement Floor Fiberglass Ceiling Tile 2' x 4'	Non Suspect ACM	75 86	SF SF	0	SF SF	
1	1	H13B	Hallway outside Building Engineer's Office Hallway outside Building Engineer's Office	Concrete Ceiling	Non Suspect ACM Non Suspect ACM	225	SF	0	SF	
1	1	H13B	Hallway outside Building Engineer's Office	Concrete Block Wall	Non Suspect ACM	500	SF	0	SF	
1	1	H13B	Hallway outside Building Engineer's Office	Floor Tile VAT 12" x 12"	Assumed	18	SF	0	SF	Tan
1	1	H13B	Hallway outside Building Engineer's Office	Floor Tile VAT 12" x 12"	Assumed	36	SF	0	SF	White
1	1	H13B	Hallway outside Building Engineer's Office	Floor Tile VAT 12" x 12"	Confirmed	116	SF	0	SF	Tan
1	1	H13B	Hallway outside Building Engineer's Office	Cement Floor	Non Suspect ACM	170	SF	0	SF	
1	1	H13B	Hallway outside Building Engineer's Office	Acoustical Plaster Ceiling	NAD	110	SF	2	SF	
1	1	H14A H14A	Hallway outside Schoolyard Entrance	Fiberglass Ceiling Tile 2' x 4'	Non Suspect ACM Non Suspect ACM	185 255	SF SF	0	SF SF	
1	1	H14A	Hallway outside Schoolyard Entrance Hallway outside Schoolyard Entrance	Ceiling Tile 2' x 4' Concrete Ceiling	Non Suspect ACM	575	SF	0	SF	
1	1	H14A	Hallway outside Schoolyard Entrance	Concrete Block Wall	Non Suspect ACM	420	SF	0	SF	
1	1	H14A	Hallway outside Schoolyard Entrance	Floor Tile VAT 12" x 12"	Assumed	36	SF	0	SF	Multi
1	1	H14A	Hallway outside Schoolyard Entrance	Floor Tile VAT 12" x 12"	Confirmed	404	SF	0	SF	Tan
1	1	H14A	Hallway outside Schoolyard Entrance	Cement Floor	Non Suspect ACM	440	SF	0	SF	
1	1	H14	Hallway from Building Engineer's Office to Loading Dock	Concrete Ceiling	Non Suspect ACM	425	SF	0	SF	
1	1	H14	Hallway from Building Engineer's Office to Loading Dock	Concrete Block Wall	Non Suspect ACM	710	SF	0	SF	
1	1	H14 H14	Hallway from Building Engineer's Office to Loading Dock	Floor Tile VAT 12" x 12"	Assumed	1	SF SF	0	SF SF	Black
1	1	H14	Hallway from Building Engineer's Office to Loading Dock Hallway from Building Engineer's Office to Loading Dock	Floor Tile VAT 12" x 12" Floor Tile VAT 12" x 12"	Assumed Assumed	3	SF	0	SF	Tan Blue
1	1	H14	Hallway from Building Engineer's Office to Loading Dock	Floor Tile VAT 12 x 12 Floor Tile VAT 12" x 12"	Assumed	3	SF	0	SF	Blue
1	1	H14	Hallway from Building Engineer's Office to Loading Dock	Floor Tile VAT 12" x 12"	Assumed	216	SF	0	SF	Tan
1	1	H14	Hallway from Building Engineer's Office to Loading Dock	Cement Floor	Non Suspect ACM	325	SF	0	SF	
1	1	H14	Hallway from Building Engineer's Office to Loading Dock	Acoustical Plaster Ceiling	NAD	425	SF	0	SF	
1	1	H15	Hallway to Gym	Concrete Ceiling	Non Suspect ACM	360	SF	0	SF	
1	1	H15	Hallway to Gym	Plaster Ceiling	NAD	50	SF	0	SF	
1	1_	H15	Hallway to Gym	Ceiling Tile 2' x 2'	NAD Nac Support A CM	65	SF	0	SF	
1	1	H15 H15	Hallway to Gym Hallway to Gym	Concrete Block Wall Floor Tile VAT 12" x 12"	Non Suspect ACM Confirmed	760 275	SF SF	0	SF SF	Tan
1	1	H15	Hallway to Gym	Transite Sills	Assumed	1	SF	0	SF	1411
1	1	H15	Hallway to Gym	Cement Floor	Non Suspect ACM	275	SF	0	SF	
1	1		Hallway to Gym	Acoustical Plaster Ceiling	NAD	360	SF	0	SF	
1	1	H14B	Hallway from Teacher's Lounge to Cafeteria	Plaster Ceiling	NAD	55	SF	5	SF	
1	1	H14B	Hallway from Teacher's Lounge to Cafeteria	Concrete Block Wall	Non Suspect ACM	150	SF	0	SF	
1	1	H14B	Hallway from Teacher's Lounge to Cafeteria	Floor Tile VAT 12" x 12"	Confirmed	7	SF	0	SF	Tan
1	1	H14B	Hallway from Teacher's Lounge to Cafeteria	Floor Tile VAT 12" x 12"	Assumed	48	SF	0	SF	Tan
1	1	H14B S12	Hallway from Teacher's Lounge to Cafeteria Stairwell 1	Cement Floor Plaster Ceiling	Non Suspect ACM NAD	55 130	SF SF	0 15	SF SF	
1	1	S12 S12	Stairwell 1	Concrete Block Wall	Non Suspect ACM	360	SF	0	SF	
1	1	S12	Stairwell 1	Floor Tile VAT 12" x 12"	Assumed	130	SF	0	SF	Tan
1	1	S12	Stairwell 1	Cement Floor	Non Suspect ACM	130	SF	0	SF	
1	1	S12	Stairwell 1	Radiator Insulation	Assumed	18	SF	0	SF	
1	1	EL1	Elevator	Metal Ceiling	Non Suspect ACM	35	SF	0	SF	
1	1	EL1	Elevator	Metal Walls	Non Suspect ACM	195	SF	0	SF	
1	1	EL1	Elevator	Floor Tile VAT 12" x 12"	Confirmed	35	SF	0	SF	Tan
1	1 A	EL1 AT	Elevator Attic across from Auditorium	Metal Floor	Non Suspect ACM	35	SF	0	SF	
	м	L AI		x	x	X	X	X	х	X
1	Α	AT	Attic 1st Floor	x	x	х	x	х	х	x