

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Long Hallway to Electrical Room next to Auditorium Supply Plenum	W1	Concrete	0	0	Negative
1	B	Long Hallway to Electrical Room next to Auditorium Supply Plenum	W2	Concrete	5	0.23	Negative
1	B	Long Hallway to Electrical Room next to Auditorium Supply Plenum	W2	Concrete	0	0	Negative
1	B	Long Hallway to Electrical Room next to Auditorium Supply Plenum	W3	Concrete	0	0	Negative
1	B	Long Hallway to Electrical Room next to Auditorium Supply Plenum	W4	Concrete	8	5.3	Positive
1	B	Long Hallway to Electrical Room next to Auditorium Supply Plenum	W4	Concrete	0	N/A	N/A
1	B	Long Hallway to Electrical Room next to Auditorium Supply Plenum	Ceiling	Concrete	0	0	Negative
1	B	Long Hallway to Electrical Room next to Auditorium Supply Plenum	Ceiling	Concrete	20	5.4	Positive
1	B	Long Hallway to Electrical Room next to Auditorium Supply Plenum	Floor	Concrete	N/A	N/A	N/A
1	B	Long Hallway to Electrical Room next to Auditorium Supply Plenum	Pipe	Metal	25	3.3	Positive
1	B	Electrical Room next to Auditorium Supply Plenum	W1	Concrete	0	0	Negative
1	B	Electrical Room next to Auditorium Supply Plenum	W2	Concrete	0	0	Negative
1	B	Electrical Room next to Auditorium Supply Plenum	W3	Concrete	0	0	Negative
1	B	Electrical Room next to Auditorium Supply Plenum	W4	Concrete	0	0	Negative
1	B	Electrical Room next to Auditorium Supply Plenum	Ceiling	Concrete	0	0	Negative
1	B	Electrical Room next to Auditorium Supply Plenum	Floor	Concrete	N/A	N/A	N/A
1	B	Storage Room in Long Hallway to Electrical Room next to Auditorium Supply Plenum	W1	No Access	No Access	No Access	No Access

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Storage Room in Long Hallway to Electrical Room next to Auditorium Supply Plenum	W2	No Access	No Access	No Access	No Access
1	B	Storage Room in Long Hallway to Electrical Room next to Auditorium Supply Plenum	W3	No Access	No Access	No Access	No Access
1	B	Storage Room in Long Hallway to Electrical Room next to Auditorium Supply Plenum	W4	No Access	No Access	No Access	No Access
1	B	Storage Room in Long Hallway to Electrical Room next to Auditorium Supply Plenum	Ceiling	No Access	No Access	No Access	No Access
1	B	Storage Room in Long Hallway to Electrical Room next to Auditorium Supply Plenum	Floor	No Access	No Access	No Access	No Access
1	B	Elevator Lobby	W1	Concrete	N/A	N/A	N/A
1	B	Elevator Lobby	W2	Concrete	N/A	N/A	N/A
1	B	Elevator Lobby	W3	Concrete	N/A	N/A	N/A
1	B	Elevator Lobby	W4	Concrete	N/A	N/A	N/A
1	B	Elevator Lobby	Ceiling	Plaster	100	20.6	Positive
1	B	Elevator Lobby	Floor	N/A	N/A	N/A	N/A
1	B	Elevator	W1	N/A	N/A	N/A	N/A
1	B	Elevator	W2	N/A	N/A	N/A	N/A
1	B	Elevator	W3	N/A	N/A	N/A	N/A
1	B	Elevator	W4	N/A	N/A	N/A	N/A
1	B	Elevator	Ceiling	N/A	N/A	N/A	N/A
1	B	Elevator	Floor	N/A	N/A	N/A	N/A
1	B	AHU Room behind the Multipurpose Room	W1	Concrete	N/A	N/A	N/A
1	B	AHU Room behind the Multipurpose Room	W1	Brick	0	0.01	Negative
1	B	AHU Room behind the Multipurpose Room	W2	Concrete	N/A	N/A	N/A
1	B	AHU Room behind the Multipurpose Room	W2	Brick	0	0	Negative
1	B	AHU Room behind the Multipurpose Room	W3	Concrete	N/A	N/A	N/A

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	AHU Room behind the Multipurpose Room	W4	Concrete	N/A	N/A	N/A
1	B	AHU Room behind the Multipurpose Room	Ceiling	No Access	No Access	No Access	No Access
1	B	AHU Room behind the Multipurpose Room	Floor	Concrete	N/A	N/A	N/A
1	B	Elevator Machine Room 006	W1	Sheetrock	0	0	Negative
1	B	Elevator Machine Room 006	W2	Sheetrock	0	0	Negative
1	B	Elevator Machine Room 006	W3	Sheetrock	0	0	Negative
1	B	Elevator Machine Room 006	W4	Sheetrock	0	0	Negative
1	B	Elevator Machine Room 006	Ceiling	Sheetrock	2	0	Negative
1	B	Elevator Machine Room 006	Floor	N/A	N/A	N/A	N/A
1	B	Hallway outside of Restrooms and Multipurpose Room	W1	Concrete	N/A	N/A	N/A
1	B	Hallway outside of Restrooms and Multipurpose Room	W2	Concrete	N/A	N/A	N/A
1	B	Hallway outside of Restrooms and Multipurpose Room	W3	Concrete	N/A	N/A	N/A
1	B	Hallway outside of Restrooms and Multipurpose Room	W4	Concrete	N/A	N/A	N/A
1	B	Hallway outside of Restrooms and Multipurpose Room	W4	Concrete	5	0.06	Negative
1	B	Hallway outside of Restrooms and Multipurpose Room	W4	Metal	5	0	Negative
1	B	Hallway outside of Restrooms and Multipurpose Room	W4	Metal	0	0	Negative
1	B	Hallway outside of Restrooms and Multipurpose Room	Ceiling	Plaster	500	18.1	Positive
1	B	Hallway outside of Restrooms and Multipurpose Room	Floor	N/A	N/A	N/A	N/A
1	B	Stairwell next to Auditorium Supply Plenum	W1	Plaster	5	12.2	Positive
1	B	Stairwell next to Auditorium Supply Plenum	W2	Concrete	0	0	Negative
1	B	Stairwell next to Auditorium Supply Plenum	W3	Plaster	5	13.4	Positive
1	B	Stairwell next to Auditorium Supply Plenum	W3	Concrete	0	N/A	N/A
1	B	Stairwell next to Auditorium Supply Plenum	W4	N/A	N/A	N/A	N/A
1	B	Stairwell next to Auditorium Supply Plenum	Ceiling	Plaster	20	13.9	Positive
1	B	Stairwell next to Auditorium Supply Plenum	Floor	N/A	N/A	N/A	N/A
1	B	Boy's Restroom	W1	Concrete	0	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
E l e m e n t	F l o o r	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Boy's Restroom	W2	Concrete	0	0	Negative
1	B	Boy's Restroom	W3	Concrete	0	0	Negative
1	B	Boy's Restroom	W4	Concrete	0	0	Negative
1	B	Boy's Restroom	Ceiling	Sheetrock	3	0	Negative
1	B	Boy's Restroom	Floor	Concrete	10	0	Negative
1	B	Girl's Restroom	W1	Concrete	0	0	Negative
1	B	Girl's Restroom	W2	Concrete	0	0	Negative
1	B	Girl's Restroom	W3	Concrete	0	0	Negative
1	B	Girl's Restroom	W4	Concrete	0	0	Negative
1	B	Girl's Restroom	Ceiling	Sheetrock	3	0	Negative
1	B	Girl's Restroom	Floor	Concrete	10	0.01	Negative
1	B	MDF Room 001	W1	Wood	0	0	Negative
1	B	MDF Room 001	W2	Wood	0	0	Negative
1	B	MDF Room 001	W3	Wood	0	0	Negative
1	B	MDF Room 001	W4	Wood	0	0	Negative
1	B	MDF Room 001	Ceiling	Sheetrock	5	0	Negative
1	B	MDF Room 001	Floor	N/A	N/A	N/A	N/A
1	B	Cafeteria 007	W1	Concrete	0	0	Negative
1	B	Cafeteria 007	W1	Brick	0	0	Negative
1	B	Cafeteria 007	W2	Concrete	0	0	Negative
1	B	Cafeteria 007	W2	Sheetrock	5	0	Negative
1	B	Cafeteria 007	W3	Concrete	0	0	Negative
1	B	Cafeteria 007	W4	Concrete	0	0	Negative
1	B	Cafeteria 007	W4	Sheetrock	5	0	Negative
1	B	Cafeteria 007	W4	Concrete	10	0	Negative
1	B	Cafeteria 007	W4	Metal	3	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Cafeteria 007	Ceiling	Plaster	800		
1	B	Cafeteria 007	Ceiling	Sheetrock	0	0	Negative
1	B	Cafeteria 007	Floor	N/A	N/A	N/A	N/A
1	B	Custodial Closet inside Cafeteria 007	W1	Concrete	0	0	Negative
1	B	Custodial Closet inside Cafeteria 007	W2	Brick	0	0.01	Negative
1	B	Custodial Closet inside Cafeteria 007	W2	Concrete	10	3.2	Positive
1	B	Custodial Closet inside Cafeteria 007	W3	Brick	3	0.04	Negative
1	B	Custodial Closet inside Cafeteria 007	W4	Concrete	0	0	Negative
1	B	Custodial Closet inside Cafeteria 007	Ceiling	Plaster	50	21.5	Positive
1	B	Custodial Closet inside Cafeteria 007	Floor	Concrete	N/A	N/A	N/A
1	B	AHU Room behind Auditorium Supply Plenum	W1	Plaster	40	5.7	Positive
1	B	AHU Room behind Auditorium Supply Plenum	W1	Brick	0	0.1	Negative
1	B	AHU Room behind Auditorium Supply Plenum	W2	Concrete	0	N/A	N/A
1	B	AHU Room behind Auditorium Supply Plenum	W2	Plaster	15	3.1	Positive
1	B	AHU Room behind Auditorium Supply Plenum	W3	Concrete	0	0	Negative
1	B	AHU Room behind Auditorium Supply Plenum	W3	Brick	0	0	Negative
1	B	AHU Room behind Auditorium Supply Plenum	W4	Concrete	0	0	Negative
1	B	AHU Room behind Auditorium Supply Plenum	W4	Brick	0	0	Negative
1	B	AHU Room behind Auditorium Supply Plenum	Ceiling	Concrete	200	1.2	Positive
1	B	AHU Room behind Auditorium Supply Plenum	Pillar	Concrete	85	2	Positive
1	B	AHU Room behind Auditorium Supply Plenum	Floor	Concrete	N/A	N/A	N/A
1	B	Staff Restroom outside of Multipurpose Room	W1	Concrete	0	N/A	N/A
1	B	Staff Restroom outside of Multipurpose Room	W2	Concrete	0	N/A	N/A
1	B	Staff Restroom outside of Multipurpose Room	W3	Concrete	0	N/A	N/A
1	B	Staff Restroom outside of Multipurpose Room	W4	Concrete	0	N/A	N/A
1	B	Staff Restroom outside of Multipurpose Room	Ceiling	Plaster	20	22.2	Positive

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Staff Restroom outside of Multipurpose Room	Floor	Concrete	20	0	Negative
1	B	Multipurpose Room 010	W1	Concrete	0	0	Negative
1	B	Multipurpose Room 010	W2	Concrete	0	0	Negative
1	B	Multipurpose Room 010	W3	Brick	0	0	Negative
1	B	Multipurpose Room 010	W3	Sheetrock	5	0	Negative
1	B	Multipurpose Room 010	W4	Brick	0	0	Negative
1	B	Multipurpose Room 010	Ceiling	Plaster	500	2	Positive
1	B	Multipurpose Room 010	Floor	N/A	N/A	N/A	N/A
1	B	Gym Teacher's Office 012	W1	Concrete	0	N/A	N/A
1	B	Gym Teacher's Office 012	W2	Concrete	0	N/A	N/A
1	B	Gym Teacher's Office 012	W3	Concrete	0	N/A	N/A
1	B	Gym Teacher's Office 012	W4	Concrete	0	N/A	N/A
1	B	Gym Teacher's Office 012	Ceiling	Plaster	30	19.3	Positive
1	B	Gym Teacher's Office 012	Floor	N/A	N/A	N/A	N/A
1	B	Small Storage Room inside Gym Teacher's Office 012	W1	Concrete	0	0	Negative
1	B	Small Storage Room inside Gym Teacher's Office 012	W2	Concrete	0	0	Negative
1	B	Small Storage Room inside Gym Teacher's Office 012	W3	Concrete	0	0	Negative
1	B	Small Storage Room inside Gym Teacher's Office 012	W4	Concrete	0	0	Negative
1	B	Small Storage Room inside Gym Teacher's Office 012	Ceiling	No Access	No Access	No Access	No Access
1	B	Small Storage Room inside Gym Teacher's Office 012	Floor	N/A	N/A	N/A	N/A
1	B	Large Storage Room inside Gym Teacher's Office 012	W1	Concrete	0	0	Negative
1	B	Large Storage Room inside Gym Teacher's Office 012	W2	Concrete	0	0	Negative
1	B	Large Storage Room inside Gym Teacher's Office 012	W3	Concrete	0	0	Negative
1	B	Large Storage Room inside Gym Teacher's Office 012	W4	Concrete	0	0	Negative
1	B	Large Storage Room inside Gym Teacher's Office 012	Ceiling	No Access	No Access	No Access	No Access
1	B	Large Storage Room inside Gym Teacher's Office 012	Floor	N/A	N/A	N/A	N/A

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm ²)	XRF (positive/negative)
1	B	Small Storage Room In Rear of Gym Teacher's Office	W1	Concrete	0	0	Negative
1	B	Small Storage Room In Rear of Gym Teacher's Office	W2	Concrete	0	0	Negative
1	B	Small Storage Room In Rear of Gym Teacher's Office	W3	Concrete	0	0	Negative
1	B	Small Storage Room In Rear of Gym Teacher's Office	W4	Concrete	0	0	Negative
1	B	Small Storage Room In Rear of Gym Teacher's Office	Ceiling	No Access	N/A	N/A	N/A
1	B	Small Storage Room In Rear of Gym Teacher's Office	Floor	N/A	N/A	N/A	N/A
1	B	Kitchen	W1	Concrete	0	0	Negative
1	B	Kitchen	W2	Concrete	0	0	Negative
1	B	Kitchen	W3	Concrete	0	0	Negative
1	B	Kitchen	W4	Concrete	0	0	Negative
1	B	Kitchen	Ceiling	Plaster	N/A	N/A	N/A
1	B	Kitchen	Floor	N/A	N/A	N/A	N/A
1	B	Kitchen Storage Room	W1	Concrete	0	0	Negative
1	B	Kitchen Storage Room	W2	Concrete	0	0	Negative
1	B	Kitchen Storage Room	W3	Concrete	0	0	Negative
1	B	Kitchen Storage Room	W4	Concrete	0	0	Negative
1	B	Kitchen Storage Room	Ceiling	Concrete	0	0	Negative
1	B	Kitchen Storage Room	Floor	N/A	N/A	N/A	N/A
1	B	Hallway outside of Multipurpose Room and Boiler Room	W1	Sheetrock	0	0	Negative
1	B	Hallway outside of Multipurpose Room and Boiler Room	W1	Concrete	0	0	Negative
1	B	Hallway outside of Multipurpose Room and Boiler Room	W1	Metal	3	0	Negative
1	B	Hallway outside of Multipurpose Room and Boiler Room	W2	Brick	15	12.5	Positive

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Hallway outside of Multipurpose Room and Boiler Room	W3	Concrete	0	0	Negative
1	B	Hallway outside of Multipurpose Room and Boiler Room	W3	Metal	0	0	Negative
1	B	Hallway outside of Multipurpose Room and Boiler Room	W4	Sheetrock	0	0	Negative
1	B	Hallway outside of Multipurpose Room and Boiler Room	Ceiling	Sheetrock	0	0	Negative
1	B	Hallway outside of Multipurpose Room and Boiler Room	Ceiling	Concrete	2	7.1	Positive
1	B	Hallway outside of Multipurpose Room and Boiler Room	Floor	Concrete	N/A	N/A	N/A
1	B	Stairwell next to Multipurpose Room	W1	Plaster	12	12	Positive
1	B	Stairwell next to Multipurpose Room	W1	Sheetrock	0	0	Negative
1	B	Stairwell next to Multipurpose Room	W1	Metal	20	0	Negative
1	B	Stairwell next to Multipurpose Room	W2	Brick	12	1.5	Positive
1	B	Stairwell next to Multipurpose Room	W3	Concrete	0	0	Negative
1	B	Stairwell next to Multipurpose Room	W3	Sheetrock	0	0	Negative
1	B	Stairwell next to Multipurpose Room	W3	Metal	20	0	Negative
1	B	Stairwell next to Multipurpose Room	W4	N/A	N/A	N/A	N/A
1	B	Stairwell next to Multipurpose Room	Ceiling	Concrete	10	9.3	Positive
1	B	Stairwell next to Multipurpose Room	Floor	Concrete	N/A	N/A	N/A
1	B	Building Engineer's Office	W1	Concrete	0	0	Negative
1	B	Building Engineer's Office	W1	Brick	0	0	Negative
1	B	Building Engineer's Office	W2	Brick	0	0	Negative
1	B	Building Engineer's Office	W2	Concrete	0	0	Negative
1	B	Building Engineer's Office	W3	Concrete	0	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm ²)	XRF (positive/negative)
1	B	Building Engineer's Office	W4	Concrete	0	0	Negative
1	B	Building Engineer's Office	Ceiling	Plaster	30	24.1	Positive
1	B	Building Engineer's Office	Floor	Concrete	N/A	N/A	N/A
1	B	AHU Room behind Building Engineer's Office	W1	Concrete	N/A	N/A	N/A
1	B	AHU Room behind Building Engineer's Office	W2	Brick	0	0	Negative
1	B	AHU Room behind Building Engineer's Office	W2	Concrete	30	12	Positive
1	B	AHU Room behind Building Engineer's Office	W3	Concrete	25	14	Positive
1	B	AHU Room behind Building Engineer's Office	W3	Brick	0	0	Negative
1	B	AHU Room behind Building Engineer's Office	W4	Brick	0	0	Negative
1	B	AHU Room behind Building Engineer's Office	Ceiling	Concrete	65	11.1	Positive
1	B	AHU Room behind Building Engineer's Office	Floor	Concrete	N/A	N/A	N/A
1	B	Stairwell outside of Building Engineer's Office	W1	Concrete	N/A	0	N/A
1	B	Stairwell outside of Building Engineer's Office	W2	Brick	0	0	Negative
1	B	Stairwell outside of Building Engineer's Office	W3	Concrete	0	0	Negative
1	B	Stairwell outside of Building Engineer's Office	W4	Concrete	0	0	Negative
1	B	Stairwell outside of Building Engineer's Office	Ceiling	Concrete	20	0	Negative
1	B	Stairwell outside of Building Engineer's Office	Floor	Concrete	N/A	N/A	N/A
1	B	Boiler Room	W1	Brick	150	10.1	Positive
1	B	Boiler Room	W1	Concrete	20	7.2	Positive
1	B	Boiler Room	W2	Concrete	200	10.5	Positive
1	B	Boiler Room	W3	Concrete	150	2.6	Positive
1	B	Boiler Room	W4	Brick	100	7.6	Positive
1	B	Boiler Room	W4	Concrete	20	9.7	Positive
1	B	Boiler Room	Ceiling	Concrete	200	11.2	Positive
1	B	Boiler Room	Floor	Concrete	N/A	N/A	N/A
1	B	Pump Room/Water Main	W1	Brick	150	9.4	Positive

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Pump Room/Water Main	W1	Concrete	20	9.7	Positive
1	B	Pump Room/Water Main	W2	Brick	100	11.9	Positive
1	B	Pump Room/Water Main	W2	Concrete	20	7.8	Positive
1	B	Pump Room/Water Main	W3	Brick	100	13.8	Positive
1	B	Pump Room/Water Main	W3	Concrete	100	11	Positive
1	B	Pump Room/Water Main	W4	Concrete	100	12.1	Positive
1	B	Pump Room/Water Main	Ceiling	Concrete	120	11.9	Positive
1	B	Pump Room/Water Main	Floor	Concrete	N/A	N/A	N/A
1	B	Fire Pump Room	W1	Sheetrock	0	0	Negative
1	B	Fire Pump Room	W1	Concrete	0	0	Negative
1	B	Fire Pump Room	W2	Brick	0	0.11	Negative
1	B	Fire Pump Room	W3	Concrete	0	0	Negative
1	B	Fire Pump Room	W4	Concrete	0	0.01	Negative
1	B	Fire Pump Room	Ceiling	Concrete	0	0.03	Negative
1	B	Fire Pump Room	Floor	N/A	N/A	N/A	N/A
1	B	Storage Room Behind Fire Pump Room	W1	Concrete	20	10.4	Positive
1	B	Storage Room Behind Fire Pump Room	W2	Concrete	0	7.4	Positive
1	B	Storage Room Behind Fire Pump Room	W3	Concrete	0	6.5	Positive
1	B	Storage Room Behind Fire Pump Room	W4	Brick	0	0.1	Negative
1	B	Storage Room Behind Fire Pump Room	Ceiling	Concrete	5	11.5	Positive
1	B	Storage Room Behind Fire Pump Room	Floor	Concrete	N/A	N/A	N/A
1	1	Front Entrance Vestibule	W1	Concrete	N/A	N/A	N/A
1	1	Front Entrance Vestibule	W2	Concrete	N/A	N/A	N/A
1	1	Front Entrance Vestibule	W3	Concrete	N/A	N/A	N/A
1	1	Front Entrance Vestibule	W4	Concrete	N/A	N/A	N/A
1	1	Front Entrance Vestibule	Ceiling	N/A	N/A	N/A	N/A

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Front Entrance Vestibule	Floor	N/A	N/A	N/A	N/A
1	1	Front Entrance Lobby	W1	Concrete	N/A	N/A	N/A
1	1	Front Entrance Lobby	W2	Concrete	N/A	N/A	N/A
1	1	Front Entrance Lobby	W3	Concrete	N/A	N/A	N/A
1	1	Front Entrance Lobby	W4	Concrete	N/A	N/A	N/A
1	1	Front Entrance Lobby	Ceiling	Metal	N/A	N/A	N/A
1	1	Front Entrance Lobby	Beam	Metal	100	0	Negative
1	1	Front Entrance Lobby	Floor	N/A	N/A	N/A	N/A
1	1	Front Entrance Hallway outside of Main Office	W1	Concrete	N/A	N/A	N/A
1	1	Front Entrance Hallway outside of Main Office	W2	Concrete	N/A	N/A	N/A
1	1	Front Entrance Hallway outside of Main Office	W3	Concrete	N/A	N/A	N/A
1	1	Front Entrance Hallway outside of Main Office	W4	Concrete	N/A	N/A	N/A
1	1	Front Entrance Hallway outside of Main Office	Ceiling	Metal	N/A	N/A	N/A
1	1	Front Entrance Hallway outside of Main Office	Floor	N/A	N/A	N/A	N/A
1	1	Hallway between Girl's Restroom and Auditorium	W1	Plaster	0	9.4	Positive
1	1	Hallway between Girl's Restroom and Auditorium	W2	Plaster	0	5.1	Positive
1	1	Hallway between Girl's Restroom and Auditorium	W3	Plaster	4	3.6	Positive
1	1	Hallway between Girl's Restroom and Auditorium	W4	Plaster	0	6.7	Positive
1	1	Hallway between Girl's Restroom and Auditorium	Ceiling	Plaster	150	15.8	Positive
1	1	Hallway between Girl's Restroom and Auditorium	Floor	N/A	N/A	N/A	N/A
1	1	Main Hallway	W1	N/A	N/A	N/A	N/A
1	1	Main Hallway	W2	Plaster	3	4.5	Positive
1	1	Main Hallway	W3	Plaster	0	6.7	Positive
1	1	Main Hallway	W4	Plaster	3	4.7	Positive
1	1	Main Hallway	W4	Plaster	3	5.9	Positive
1	1	Main Hallway	Ceiling	Plaster	250	19.6	Positive

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Main Hallway	Floor	N/A	N/A	N/A	N/A
1	1	Auditorium Stage	W1	Plaster	45	9.7	Positive
1	1	Auditorium Stage	W2	Plaster	25	9.1	Positive
1	1	Auditorium Stage	W3	Plaster	15	6.5	Positive
1	1	Auditorium Stage	W4	Plaster	10	7.4	Positive
1	1	Auditorium Stage	Ceiling	Plaster	N/A	N/A	N/A
1	1	Auditorium Stage	Floor	Wood	N/A	N/A	N/A
1	1	Auditorium	W1	Plaster	50	5.4	Positive
1	1	Auditorium	W1	Plaster	150	6.7	Positive
1	1	Auditorium	W1	Wood	0	0.11	Negative
1	1	Auditorium	W2	Plaster	30	6.5	Positive
1	1	Auditorium	W2	Plaster	30	4.5	Positive
1	1	Auditorium	W2	Wood	0	0.03	Negative
1	1	Auditorium	W3	Plaster	50	4.7	Positive
1	1	Auditorium	W3	Plaster	30	8.3	Positive
1	1	Auditorium	W3	Wood	20	1.1	Positive
1	1	Auditorium	W4	Plaster	40	6.7	Positive
1	1	Auditorium	W4	Plaster	90	4.3	Positive
1	1	Auditorium	W4	Wood	10	1.5	Positive
1	1	Auditorium	Ceiling	Plaster	300	see comment	Positive
1	1	Auditorium	Floor	Metal	400	4.3	Positive
1	1	Stairwell next to Auditorium Stage	W1	Concrete	0	0	Negative
1	1	Stairwell next to Auditorium Stage	W2	Plaster	5	12.2	Positive
1	1	Stairwell next to Auditorium Stage	W3	Plaster	0	11	Positive
1	1	Stairwell next to Auditorium Stage	W4	Plaster	5	9.1	Positive
1	1	Stairwell next to Auditorium Stage	Ceiling	Plaster	0	6.7	Positive

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Stairwell next to Auditorium Stage	Floor	N/A	N/A	N/A	N/A
1	1	Stairwell next to Auditorium Stage	Pipe	Metal	15	3.4	Positive
1	1	Stairwell between Classrooms 102 and 104	W1	Concrete	0	0	Negative
1	1	Stairwell between Classrooms 102 and 104	W2	Plaster	6	6.8	Positive
1	1	Stairwell between Classrooms 102 and 104	W3	Plaster	4	5.7	Positive
1	1	Stairwell between Classrooms 102 and 104	W4	Plaster	4	8.1	Positive
1	1	Stairwell between Classrooms 102 and 104	Ceiling	Plaster	0	N/A	N/A
1	1	Stairwell between Classrooms 102 and 104	Floor	N/A	N/A	N/A	N/A
1	1	Stairwell between Classrooms 102 and 104	Banister & Post	Metal	15	5.4	Positive
1	1	Hallway between Classrooms 107 and 109	W1	Plaster	0	4.1	Positive
1	1	Hallway between Classrooms 107 and 109	W2	Plaster	0	5.6	Positive
1	1	Hallway between Classrooms 107 and 109	W3	Plaster	0	8.7	Positive
1	1	Hallway between Classrooms 107 and 109	W4	N/A	N/A	N/A	N/A
1	1	Hallway between Classrooms 107 and 109	Ceiling	Plaster	800	12.3	Positive
1	1	Hallway between Classrooms 107 and 109	Floor	N/A	N/A	N/A	N/A
1	1	Custodial Closet outside of Girl's Restroom	W1	Plaster	0	11.4	Positive
1	1	Custodial Closet outside of Girl's Restroom	W2	Plaster	0	6.4	Positive
1	1	Custodial Closet outside of Girl's Restroom	W3	Plaster	10	9.5	Positive
1	1	Custodial Closet outside of Girl's Restroom	W4	Plaster	5	11.7	Positive
1	1	Custodial Closet outside of Girl's Restroom	Ceiling	Plaster	15	9.5	Positive
1	1	Custodial Closet outside of Girl's Restroom	Floor	Concrete	N/A	N/A	N/A
1	1	Main Office	W1	Sheetrock	0	0	Negative
1	1	Main Office	W2	Sheetrock	0	0	Negative
1	1	Main Office	W3	Sheetrock	0	0	Negative
1	1	Main Office	W4	Sheetrock	0	0	Negative
1	1	Main Office	Ceiling	Plaster	300	21.7	Positive

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Main Office	Floor	N/A	N/A	N/A	N/A
1	1	Hallway from Main Office to Main Hallway	W1	Concrete	N/A	N/A	N/A
1	1	Hallway from Main Office to Main Hallway	W2	Concrete	N/A	N/A	N/A
1	1	Hallway from Main Office to Main Hallway	W3	Concrete	N/A	N/A	N/A
1	1	Hallway from Main Office to Main Hallway	W4	Concrete	N/A	N/A	N/A
1	1	Hallway from Main Office to Main Hallway	Ceiling	Plaster	50	21.2	Positive
1	1	Hallway from Main Office to Main Hallway	Floor	N/A	N/A	N/A	N/A
1	1	Main Office Restroom	W1	Sheetrock	0	0	Negative
1	1	Main Office Restroom	W2	Sheetrock	0	0	Negative
1	1	Main Office Restroom	W3	Sheetrock	0	0	Negative
1	1	Main Office Restroom	W4	Sheetrock	0	0	Negative
1	1	Main Office Restroom	Ceiling	Sheetrock	0	0	Negative
1	1	Main Office Restroom	Floor	N/A	N/A	N/A	N/A
1	1	Office 100B	W1	Sheetrock	0	0	Negative
1	1	Office 100B	W2	Sheetrock	1	0	Negative
1	1	Office 100B	W3	Plaster	0	0	Negative
1	1	Office 100B	W4	Sheetrock	0	0	Negative
1	1	Office 100B	Ceiling	Plaster	45	14.1	Positive
1	1	Office 100B	Floor	N/A	N/A	N/A	N/A
1	1	Office 100C	W1	Sheetrock	0	0	Negative
1	1	Office 100C	W2	Sheetrock	0	0	Negative
1	1	Office 100C	W3	Plaster	4	0	Negative
1	1	Office 100C	W4	Sheetrock	0	0	Negative
1	1	Office 100C	Ceiling	Plaster	50	22.5	Positive
1	1	Office 100C	Floor	N/A	N/A	N/A	N/A
1	1	Office 100E	W1	Sheetrock	0	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Office 100E	W2	Sheetrock	0	0	Negative
1	1	Office 100E	W3	Sheetrock	0	0	Negative
1	1	Office 100E	W4	Sheetrock	0	0	Negative
1	1	Office 100E	Ceiling	Plaster	20	22.1	Positive
1	1	Office 100E	Floor	N/A	N/A	N/A	N/A
1	1	Office 100E Restroom	W1	Sheetrock	0	0	Negative
1	1	Office 100E Restroom	W2	Sheetrock	0	0	Negative
1	1	Office 100E Restroom	W3	Sheetrock	0	0	Negative
1	1	Office 100E Restroom	W4	Sheetrock	0	0	Negative
1	1	Office 100E Restroom	Ceiling	Plaster	10	21.6	Positive
1	1	Office 100E Restroom	Floor	N/A	N/A	N/A	N/A
1	1	Office 100F	W1	Sheetrock	0	0	Negative
1	1	Office 100F	W2	Sheetrock	0	0	Negative
1	1	Office 100F	W3	Sheetrock	0	0	Negative
1	1	Office 100F	W4	Sheetrock	0	0	Negative
1	1	Office 100F	Ceiling	Plaster	20	13.9	Positive
1	1	Office 100F	Floor	N/A	N/A	N/A	N/A
1	1	Office 100G	W1	Sheetrock	0	0	Negative
1	1	Office 100G	W2	Sheetrock	0	0	Negative
1	1	Office 100G	W3	Sheetrock	0	0	Negative
1	1	Office 100G	W4	Sheetrock	0	0	Negative
1	1	Office 100G	Ceiling	No Access	No Access	No Access	No Access
1	1	Office 100G	Floor	N/A	N/A	N/A	N/A
1	1	Nurse's Office	W1	Sheetrock	0	0	Negative
1	1	Nurse's Office	W2	Sheetrock	0	0	Negative
1	1	Nurse's Office	W3	Sheetrock	0	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Nurse's Office	W4	Sheetrock	0	0	Negative
1	1	Nurse's Office	Ceiling	Plaster	15	17.2	Positive
1	1	Nurse's Office	Floor	N/A	N/A	N/A	N/A
1	1	Nurse's Office Restroom	W1	Sheetrock	0	0	Negative
1	1	Nurse's Office Restroom	W2	Sheetrock	0	0	Negative
1	1	Nurse's Office Restroom	W3	Sheetrock	0	0	Negative
1	1	Nurse's Office Restroom	W4	Sheetrock	0	0	Negative
1	1	Nurse's Office Restroom	Ceiling	Sheetrock	0	0	Negative
1	1	Nurse's Office Restroom	Floor	N/A	N/A	N/A	N/A
1	1	Classroom 109	W1	Plaster	10	11.4	Positive
1	1	Classroom 109	W2	Plaster	5	10.2	Positive
1	1	Classroom 109	W3	Plaster	35	13.1	Positive
1	1	Classroom 109	W3	Wood	2	0.11	Negative
1	1	Classroom 109	W3	Wood	0	0.01	Negative
1	1	Classroom 109	W3	Wood	0	0.03	Negative
1	1	Classroom 109	W4	Plaster	0	N/A	N/A
1	1	Classroom 109	Ceiling	Plaster	400	14.4	Positive
1	1	Classroom 109	Floor	N/A	N/A	N/A	N/A
1	1	Classroom 109 Coat Closet	W1	Plaster	5	11.2	Positive
1	1	Classroom 109 Coat Closet	W2	Plaster	5	14.1	Positive
1	1	Classroom 109 Coat Closet	W3	Plaster	10	10	Positive
1	1	Classroom 109 Coat Closet	W4	Concrete	0	N/A	N/A
1	1	Classroom 109 Coat Closet	Ceiling	Plaster	15	13.7	Positive
1	1	Classroom 109 Coat Closet	Floor	N/A	N/A	N/A	N/A
1	1	Classroom 109 Corner Storage Closet	W1	Plaster	10	10.2	Positive
1	1	Classroom 109 Corner Storage Closet	W2	Plaster	2	11.2	Positive

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Classroom 109 Corner Storage Closet	W3	Plaster	0	N/A	N/A
1	1	Classroom 109 Corner Storage Closet	W4	Plaster	0	N/A	N/A
1	1	Classroom 109 Corner Storage Closet	Ceiling	No Access	No Access	No Access	No Access
1	1	Classroom 109 Corner Storage Closet	Floor	N/A	N/A	N/A	N/A
1	1	Classroom 109 Small Closet Near Entrance	W1	Plaster	0	N/A	N/A
1	1	Classroom 109 Small Closet Near Entrance	W2	Plaster	0	N/A	N/A
1	1	Classroom 109 Small Closet Near Entrance	W3	Plaster	0	N/A	N/A
1	1	Classroom 109 Small Closet Near Entrance	W4	Plaster	0	N/A	N/A
1	1	Classroom 109 Small Closet Near Entrance	Ceiling	No Access	No Access	No Access	No Access
1	1	Classroom 109 Small Closet Near Entrance	Floor	N/A	N/A	N/A	N/A
1	1	Electrical Room 111 outside Classroom 109	W1	Plaster	5	0	Negative
1	1	Electrical Room 111 outside Classroom 109	W2	Concrete	0	0	Negative
1	1	Electrical Room 111 outside Classroom 109	W3	Plaster	10	3.5	Positive
1	1	Electrical Room 111 outside Classroom 109	W4	Concrete	0	0	Negative
1	1	Electrical Room 111 outside Classroom 109	Ceiling	Plaster	40	12.4	Positive
1	1	Electrical Room 111 outside Classroom 109	Floor	Concrete	0	0	Negative
1	1	IT MDF Room outside Classroom 104	W1	Sheetrock	0	0.01	Negative
1	1	IT MDF Room outside Classroom 104	W2	Wood	0	0	Negative
1	1	IT MDF Room outside Classroom 104	W3	Wood	0	0	Negative
1	1	IT MDF Room outside Classroom 104	W4	Wood	0	0	Negative
1	1	IT MDF Room outside Classroom 104	Ceiling	No Access	No Access	No Access	No Access
1	1	IT MDF Room outside Classroom 104	Floor	N/A	N/A	N/A	N/A
1	1	Large Storage Room between Classrooms 104 and 109	W1	Sheetrock	0	0	Negative
1	1	Large Storage Room between Classrooms 104 and 109	W2	Sheetrock	0	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Large Storage Room between Classrooms 104 and 109	W3	Plaster	0	4.1	Positive
1	1	Large Storage Room between Classrooms 104 and 109	W4	Sheetrock	0	0.13	Negative
1	1	Large Storage Room between Classrooms 104 and 109	Ceiling	Plaster	250	15.5	Positive
1	1	Large Storage Room between Classrooms 104 and 109	Floor	N/A	N/A	N/A	N/A
1	1	Classroom 104	W1	Plaster	5	3.1	Positive
1	1	Classroom 104	W2	Concrete	0	0	Negative
1	1	Classroom 104	W3	Plaster	25	3.1	Positive
1	1	Classroom 104	W3	Wood	0	0	Negative
1	1	Classroom 104	W3	Wood	0	1.2	Positive
1	1	Classroom 104	W3	Wood	0	0.11	Negative
1	1	Classroom 104	W4	Plaster	2	6.1	Positive
1	1	Classroom 104	Ceiling	Plaster	250	9.2	Positive
1	1	Classroom 104	Ceiling	Plaster	5	4.1	Positive
1	1	Classroom 104	Floor	Wood	N/A	N/A	N/A
1	1	Classroom 104 Storage Closet	W1	Concrete	0	N/A	N/A
1	1	Classroom 104 Storage Closet	W2	Plaster	0	N/A	N/A
1	1	Classroom 104 Storage Closet	W3	Sheetrock	0	N/A	N/A
1	1	Classroom 104 Storage Closet	W4	Concrete	0	N/A	N/A
1	1	Classroom 104 Storage Closet	Ceiling	No Access	No Access	No Access	No Access
1	1	Classroom 104 Storage Closet	Floor	N/A	N/A	N/A	N/A
1	1	Classroom 104 Coat Closet	W1	Plaster	0	N/A	N/A
1	1	Classroom 104 Coat Closet	W2	Plaster	4	11.1	Positive
1	1	Classroom 104 Coat Closet	W3	Plaster	0	N/A	N/A

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Classroom 104 Coat Closet	W4	Plaster	5	12.3	Positive
1	1	Classroom 104 Coat Closet	Ceiling	No Access	No Access	No Access	No Access
1	1	Classroom 104 Coat Closet	Floor	N/A	N/A	N/A	N/A
1	1	Classroom 104 Corner Storage Nook	W1	Concrete	0	0	Negative
1	1	Classroom 104 Corner Storage Nook	W2	Concrete	0	0	Negative
1	1	Classroom 104 Corner Storage Nook	W3	Concrete	3	0	Negative
1	1	Classroom 104 Corner Storage Nook	W4	Plaster	0	3.1	Positive
1	1	Classroom 104 Corner Storage Nook	Ceiling	Plaster	5	10.1	Positive
1	1	Classroom 104 Corner Storage Nook	Floor	N/A	N/A	N/A	N/A
1	2	Stairwell next to Classroom 200	W1	Concrete	0	0	Negative
1	2	Stairwell next to Classroom 200	W2	Plaster	10	5.6	Positive
1	2	Stairwell next to Classroom 200	W3	Plaster	0	6.1	Positive
1	2	Stairwell next to Classroom 200	W4	Plaster	10	7	Positive
1	2	Stairwell next to Classroom 200	Ceiling	Plaster	0	9.1	Positive
1	2	Stairwell next to Classroom 200	Floor	N/A	N/A	N/A	N/A
1	2	Stairwell next to Classroom 200	Banister & Post	Metal	20	5.4	Positive
1	2	Stairwell between Classrooms 204 and 206	W1	Concrete	0	0	Negative
1	2	Stairwell between Classrooms 204 and 206	W2	Plaster	0	8.4	Positive
1	2	Stairwell between Classrooms 204 and 206	W3	Plaster	5	6.7	Positive
1	2	Stairwell between Classrooms 204 and 206	W4	Plaster	8	6.1	Positive
1	2	Stairwell between Classrooms 204 and 206	Ceiling	Plaster	0	11.1	Positive
1	2	Stairwell between Classrooms 204 and 206	Floor	N/A	N/A	N/A	N/A
1	2	Stairwell between Classrooms 204 and 206	Pipe	Metal	20	5.4	Positive
1	2	Girls Restroom Near 201	W1	Concrete	0	0	Negative
1	2	Girls Restroom Near 201	W2	Concrete	0	0	Negative
1	2	Girls Restroom Near 201	W3	Plaster	0	7.4	Positive

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Girls Restroom Near 201	W3	Wood	0	0	Negative
1	2	Girls Restroom Near 201	W3	Wood	0	0.11	Negative
1	2	Girls Restroom Near 201	W3	Wood	0	0.03	Negative
1	2	Girls Restroom Near 201	W4	Plaster	0	6.2	Positive
1	2	Girls Restroom Near 201	Ceiling	Plaster	3	5.4	Positive
1	2	Girls Restroom Near 201	Floor	Concrete	N/A	N/A	N/A
1	2	Classroom 200	W1	Plaster	1	9.4	Positive
1	2	Classroom 200	W1	Metal	12	10.6	Positive
1	2	Classroom 200	W2	Concrete	0	0	Negative
1	2	Classroom 200	W2	Plaster	1	9.3	Positive
1	2	Classroom 200	W3	Plaster	25	11	Positive
1	2	Classroom 200	W3	Wood	0	0.05	Negative
1	2	Classroom 200	W3	Wood	0	0.03	Negative
1	2	Classroom 200	W3	Wood	1	1.3	Positive
1	2	Classroom 200	W3	Metal	1	0	Negative
1	2	Classroom 200	W4	Plaster	4	0	Negative
1	2	Classroom 200	Ceiling	Plaster	300	7.9	Positive
1	2	Classroom 200	Floor	Wood	N/A	N/A	N/A
1	2	Classroom 200	Floor	Wood	10	0.01	Negative
1	2	Classroom 200 Small Closet	W1	Plaster	3	4.1	Positive
1	2	Classroom 200 Small Closet	W2	Plaster	5	3.9	Positive
1	2	Classroom 200 Small Closet	W3	Plaster	2	7.2	Positive
1	2	Classroom 200 Small Closet	W4	Plaster	8	7.5	Positive
1	2	Classroom 200 Small Closet	Ceiling	Plaster	20	6.1	Positive
1	2	Classroom 200 Small Closet	Floor	Wood	N/A	N/A	N/A
1	2	Classroom 200 Small Closet	Floor	Wood	5	0.03	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 200 Coat Closet	W1	Plaster	1	6.2	Positive
1	2	Classroom 200 Coat Closet	W2	Plaster	15	5.4	Positive
1	2	Classroom 200 Coat Closet	W3	Concrete	0	0	Negative
1	2	Classroom 200 Coat Closet	W4	Plaster	10	6.5	Positive
1	2	Classroom 200 Coat Closet	Ceiling	Plaster	60	4.2	Positive
1	2	Classroom 200 Coat Closet	Floor	Wood	N/A	N/A	N/A
1	2	Classroom 200 Coat Closet	Floor	Wood	5	0.04	Negative
1	2	Library 202	W1	Plaster	2	9.4	Positive
1	2	Library 202	W2	Concrete	0	N/A	N/A
1	2	Library 202	W2	Plaster	2	5.6	Positive
1	2	Library 202	W3	Plaster	20	14.5	Positive
1	2	Library 202	W3	Wood	20	0.14	Negative
1	2	Library 202	W3	Wood	0	0.02	Negative
1	2	Library 202	W3	Wood	0	1.2	Positive
1	2	Library 202	W4	Concrete	0	0	Negative
1	2	Library 202	Ceiling	Plaster	700	18.6	Positive
1	2	Library 202	Floor	Carpet	N/A	N/A	N/A
1	2	Library 202	Floor	Wood	10	0.01	Negative
1	2	Library 202 Small Closet Near Wall 4	W1	Plaster	0	4.2	Positive
1	2	Library 202 Small Closet Near Wall 4	W2	Plaster	3	3.1	Positive
1	2	Library 202 Small Closet Near Wall 4	W3	Plaster	0	5.7	Positive
1	2	Library 202 Small Closet Near Wall 4	W4	Plaster	6	0	Negative
1	2	Library 202 Small Closet Near Wall 4	Ceiling	Plaster	15	6.3	Positive
1	2	Library 202 Small Closet Near Wall 4	Floor	Carpet	N/A	N/A	N/A
1	2	Library 202 Small Closet Near Wall 2	W1	Plaster	0	4.3	Positive
1	2	Library 202 Small Closet Near Wall 2	W2	Plaster	1	3.8	Positive

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Library 202 Small Closet Near Wall 2	W3	Plaster	3	3.1	Positive
1	2	Library 202 Small Closet Near Wall 2	W4	Plaster	5	4.1	Positive
1	2	Library 202 Small Closet Near Wall 2	Ceiling	No Access	No Access	No Access	No Access
1	2	Library 202 Small Closet Near Wall 2	Floor	Carpet	N/A	N/A	N/A
1	2	Library 202 Coat Closet	W1	Plaster	8	7	Positive
1	2	Library 202 Coat Closet	W2	Plaster	20	6.7	Positive
1	2	Library 202 Coat Closet	W3	Plaster	100	8.4	Positive
1	2	Library 202 Coat Closet	W4	Plaster	40	8.6	Positive
1	2	Library 202 Coat Closet	Ceiling	No Access	No Access	No Access	No Access
1	2	Library 202 Coat Closet	Floor	Carpet	N/A	N/A	N/A
1	2	Library 202 Coat Closet	Floor	Wood	5	0.01	Negative
1	2	Classroom 206	W1	Plaster	4	2.4	Positive
1	2	Classroom 206	W2	Concrete	0	0	Negative
1	2	Classroom 206	W3	Plaster	4	17.3	Positive
1	2	Classroom 206	W3	Wood	0	0.02	Negative
1	2	Classroom 206	W3	Wood	0	0.04	Negative
1	2	Classroom 206	W3	Wood	0	1.1	Positive
1	2	Classroom 206	W4	Plaster	10	0	Negative
1	2	Classroom 206	Ceiling	Plaster	525	10.6	Positive
1	2	Classroom 206	Floor	Wood	N/A	N/A	N/A
1	2	Classroom 206	Floor	Wood	10	0.01	Negative
1	2	Classroom 206 Small Closet Near Entrance	W1	Plaster	0	5.4	Positive
1	2	Classroom 206 Small Closet Near Entrance	W2	Plaster	0	6.4	Positive
1	2	Classroom 206 Small Closet Near Entrance	W3	Plaster	0	5.3	Positive
1	2	Classroom 206 Small Closet Near Entrance	W4	Plaster	0	4.5	Positive
1	2	Classroom 206 Small Closet Near Entrance	Ceiling	No Access	N/A	N/A	N/A

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 206 Small Closet Near Entrance	Floor	Wood	N/A	N/A	N/A
1	2	Classroom 206 Small Closet Near Entrance	Floor	Wood	5	0	Negative
1	2	Classroom 206 Coat Closet	W1	Plaster	5	9.4	Positive
1	2	Classroom 206 Coat Closet	W2	Plaster	80	5.5	Positive
1	2	Classroom 206 Coat Closet	W2	Wood	0	0.18	Negative
1	2	Classroom 206 Coat Closet	W3	Sheetrock	0	0	Negative
1	2	Classroom 206 Coat Closet	W4	Plaster	30	7.1	Positive
1	2	Classroom 206 Coat Closet	W4	Wood	0	0.06	Negative
1	2	Classroom 206 Coat Closet	Ceiling	Plaster	50	19.3	Positive
1	2	Classroom 206 Coat Closet	Floor	Wood	N/A	N/A	N/A
1	2	Classroom 206 Coat Closet	Floor	Wood	8	0.01	Negative
1	2	Classroom 206 Rear Storage Closet	W1	Concrete	0	0	Negative
1	2	Classroom 206 Rear Storage Closet	W2	Plaster	1	17.7	Positive
1	2	Classroom 206 Rear Storage Closet	W3	Plaster	2	13.6	Positive
1	2	Classroom 206 Rear Storage Closet	W4	Concrete	0	0	Negative
1	2	Classroom 206 Rear Storage Closet	Ceiling	Plaster	40	21.4	Positive
1	2	Classroom 206 Rear Storage Closet	Floor	Wood	N/A	N/A	N/A
1	2	Classroom 206 Rear Storage Closet	Floor	Wood	5	0.04	Negative
1	2	Classroom 206 Corner Storage Nook	W1	Concrete	0	0	Negative
1	2	Classroom 206 Corner Storage Nook	W2	Concrete	0	0	Negative
1	2	Classroom 206 Corner Storage Nook	W3	Plaster	0	13.8	Positive
1	2	Classroom 206 Corner Storage Nook	W4	Plaster	0	19.9	Positive
1	2	Classroom 206 Corner Storage Nook	W4	Wood	0	0.13	Negative
1	2	Classroom 206 Corner Storage Nook	W4	Wood	0	0.1	Negative
1	2	Classroom 206 Corner Storage Nook	W4	Wood	0	0.03	Negative
1	2	Classroom 206 Corner Storage Nook	Ceiling	No Access	No Access	No Access	No Access

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 206 Corner Storage Nook	Floor	Wood	N/A	N/A	N/A
1	2	Classroom 206 Corner Storage Nook	Floor	Wood	5	0.06	Negative
1	2	Classroom 206 Mechanical Closet next to Coat Closet	W1	Plaster	0	N/A	N/A
1	2	Classroom 206 Mechanical Closet next to Coat Closet	W2	Plaster	4	9.6	Positive
1	2	Classroom 206 Mechanical Closet next to Coat Closet	W2	Sheetrock	0	0	Negative
1	2	Classroom 206 Mechanical Closet next to Coat Closet	W3	Plaster	10	5.7	Positive
1	2	Classroom 206 Mechanical Closet next to Coat Closet	W4	Concrete	0	N/A	N/A
1	2	Classroom 206 Mechanical Closet next to Coat Closet	Ceiling	No Access	No Access	No Access	No Access
1	2	Classroom 206 Mechanical Closet next to Coat Closet	Floor	Wood	N/A	N/A	N/A
1	2	Classroom 206 Mechanical Closet next to Coat Closet	Floor	Wood	5	0.04	Negative
1	2	IT MDF Room outside Classroom 206	W1	Wood	0	0	Negative
1	2	IT MDF Room outside Classroom 206	W2	Wood	0	0	Negative
1	2	IT MDF Room outside Classroom 206	W3	Wood	0	0	Negative
1	2	IT MDF Room outside Classroom 206	W4	Wood	0	0	Negative
1	2	IT MDF Room outside Classroom 206	Ceiling	Plaster	40	2.3	Positive
1	2	IT MDF Room outside Classroom 206	Floor	N/A	N/A	N/A	N/A
1	2	Faculty Lounge	W1	Sheetrock	1	0	Negative
1	2	Faculty Lounge	W2	Plaster	1	12	Positive
1	2	Faculty Lounge	W3	Plaster	12	19.3	Positive
1	2	Faculty Lounge	W3	Wood	0	0	Negative
1	2	Faculty Lounge	W3	Wood	0	0	Negative
1	2	Faculty Lounge	W3	Wood	0	0.11	Negative
1	2	Faculty Lounge	W4	Sheetrock	0	0	Negative
1	2	Faculty Lounge	Ceiling	N/A	N/A	N/A	N/A
1	2	Faculty Lounge	Floor	N/A	N/A	N/A	N/A
1	2	Faculty Lounge Restroom	W1	Sheetrock	0	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Faculty Lounge Restroom	W2	Sheetrock	10	0	Negative
1	2	Faculty Lounge Restroom	W3	Plaster	12	16.3	Positive
1	2	Faculty Lounge Restroom	W4	Sheetrock	6	0	Negative
1	2	Faculty Lounge Restroom	Ceiling	Sheetrock	5	0	Negative
1	2	Faculty Lounge Restroom	Floor	Concrete	0	0	Negative
1	2	Faculty Lounge Storage Closet	W1	Sheetrock	0	0	Negative
1	2	Faculty Lounge Storage Closet	W2	Sheetrock	0	N/A	N/A
1	2	Faculty Lounge Storage Closet	W2	Concrete	0	0.9	Positive
1	2	Faculty Lounge Storage Closet	W3	Concrete	0	0	Negative
1	2	Faculty Lounge Storage Closet	W3	Concrete	0	19.1	Positive
1	2	Faculty Lounge Storage Closet	W4	Concrete	0	18.6	Positive
1	2	Faculty Lounge Storage Closet	Ceiling	N/A	N/A	N/A	N/A
1	2	Faculty Lounge Storage Closet	Floor	N/A	N/A	N/A	N/A
1	2	Computer Classroom 204	W1	Plaster	10	13.5	Positive
1	2	Computer Classroom 204	W2	Concrete	0	0	Negative
1	2	Computer Classroom 204	W2	Plaster	2	2.4	Positive
1	2	Computer Classroom 204	W3	Plaster	14	15	Positive
1	2	Computer Classroom 204	W3	Wood	4	0.3	Negative
1	2	Computer Classroom 204	W3	Wood	0	0.03	Negative
1	2	Computer Classroom 204	W3	Wood	0	1.6	Positive
1	2	Computer Classroom 204	W4	Concrete	0	0	Negative
1	2	Computer Classroom 204	W4	Plaster	1	9.7	Positive
1	2	Computer Classroom 204	Ceiling	Plaster	100	19.2	Positive
1	2	Computer Classroom 204	Floor	Wood	N/A	N/A	N/A
1	2	Computer Classroom 204	Floor	Wood	10	0.1	Negative
1	2	Classroom 204 Small Computer Storage Closet Wall 2	W1	Concrete	0	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 204 Small Computer Storage Closet Wall 2	W2	Plaster	2	15.3	Positive
1	2	Classroom 204 Small Computer Storage Closet Wall 2	W3	Plaster	1	0.01	Negative
1	2	Classroom 204 Small Computer Storage Closet Wall 2	W4	Concrete	0	0	Negative
1	2	Classroom 204 Small Computer Storage Closet Wall 2	Ceiling	Plaster	0	N/A	N/A
1	2	Classroom 204 Small Computer Storage Closet Wall 2	Floor	Wood	N/A	N/A	N/A
1	2	Computer Classroom 204 Coat Closet - Library Side	W1	Plaster	20	10.1	Positive
1	2	Computer Classroom 204 Coat Closet - Library Side	W2	Plaster	4	9.6	Positive
1	2	Computer Classroom 204 Coat Closet - Library Side	W2	Concrete	0	0	Negative
1	2	Computer Classroom 204 Coat Closet - Library Side	W3	Plaster	15	8	Positive
1	2	Computer Classroom 204 Coat Closet - Library Side	W4	Plaster	10	12	Positive
1	2	Computer Classroom 204 Coat Closet - Library Side	Ceiling	Plaster	50	10.1	Positive
1	2	Computer Classroom 204 Coat Closet - Library Side	Floor	Wood	N/A	N/A	N/A
1	2	Computer Classroom 204 Coat Closet - Library Side	Floor	Wood	10	0.01	Negative
1	2	Classroom 204 Small Closet Near Entrance	W1	Plaster	1	3.8	Positive
1	2	Classroom 204 Small Closet Near Entrance	W2	Plaster	1	3.8	Positive
1	2	Classroom 204 Small Closet Near Entrance	W3	Plaster	0	2.5	Positive
1	2	Classroom 204 Small Closet Near Entrance	W4	Plaster	5	4.5	Positive
1	2	Classroom 204 Small Closet Near Entrance	Ceiling	No Access	No Access	No Access	No Access
1	2	Classroom 204 Small Closet Near Entrance	Floor	Wood	N/A	N/A	N/A
1	2	Computer Classroom 204 Coat Closet - Stairwell Side	W1	Plaster	2	15.1	Positive
1	2	Computer Classroom 204 Coat Closet - Stairwell Side	W2	Plaster	25	9.9	Positive
1	2	Computer Classroom 204 Coat Closet - Stairwell Side	W2	Wood	0	0.05	Negative
1	2	Computer Classroom 204 Coat Closet - Stairwell Side	W3	Plaster	8	6.7	Positive
1	2	Computer Classroom 204 Coat Closet - Stairwell Side	W4	Plaster	12	7.9	Positive
1	2	Computer Classroom 204 Coat Closet - Stairwell Side	Ceiling	Plaster	120	7.8	Positive
1	2	Computer Classroom 204 Coat Closet - Stairwell Side	Floor	Wood	N/A	N/A	N/A

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Computer Classroom 204 Coat Closet - Stairwell Side	Floor	Wood	6	0.03	Negative
1	2	Classroom 204 Small Storage Closet Along Wall 2 Near Wall 3	W1	No Access	No Access	No Access	No Access
1	2	Classroom 204 Small Storage Closet Along Wall 2 Near Wall 3	W2	No Access	No Access	No Access	No Access
1	2	Classroom 204 Small Storage Closet Along Wall 2 Near Wall 3	W3	No Access	No Access	No Access	No Access
1	2	Classroom 204 Small Storage Closet Along Wall 2 Near Wall 3	W4	No Access	No Access	No Access	No Access
1	2	Classroom 204 Small Storage Closet Along Wall 2 Near Wall 3	Ceiling	No Access	No Access	No Access	No Access
1	2	Classroom 204 Small Storage Closet Along Wall 2 Near Wall 3	Floor	No Access	No Access	No Access	No Access
1	2	Boys Restroom Near 207	W1	Concrete	0	0	Negative
1	2	Boys Restroom Near 207	W2	Concrete	0	0	Negative
1	2	Boys Restroom Near 207	W3	Concrete	0	0	Negative
1	2	Boys Restroom Near 207	W3	Plaster	4	10	Positive
1	2	Boys Restroom Near 207	W4	Plaster	4	0	Negative
1	2	Boys Restroom Near 207	W4	Wood	0	0	Negative
1	2	Boys Restroom Near 207	W4	Wood	0	0.03	Negative
1	2	Boys Restroom Near 207	W4	Wood	0	0	Negative
1	2	Boys Restroom Near 207	Ceiling	Sheetrock	0	0	Negative
1	2	Boys Restroom Near 207	Floor	Concrete	0	0	Negative
1	2	Classroom 209	W1	Plaster	20	12.6	Positive
1	2	Classroom 209	W2	Plaster	10	0	Negative
1	2	Classroom 209	W3	Plaster	15	0	Negative
1	2	Classroom 209	W3	Wood	0	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 209	W3	Wood	0	0	Negative
1	2	Classroom 209	W3	Wood	0	1	Positive
1	2	Classroom 209	W4	Plaster	1	0	Negative
1	2	Classroom 209	W4	Concrete	0	0	Negative
1	2	Classroom 209	Ceiling	Plaster	400	18.5	Positive
1	2	Classroom 209	Floor	Wood	N/A	N/A	N/A
1	2	Classroom 209	Floor	Wood	10	0.05	Negative
1	2	Classroom 209 Small Closet Near Entrance	W1	Plaster	3	3.5	Positive
1	2	Classroom 209 Small Closet Near Entrance	W2	Plaster	0	2.5	Positive
1	2	Classroom 209 Small Closet Near Entrance	W3	Plaster	0	2.7	Positive
1	2	Classroom 209 Small Closet Near Entrance	W4	Plaster	0	3.8	Positive
1	2	Classroom 209 Small Closet Near Entrance	Ceiling	N/A	N/A	N/A	N/A
1	2	Classroom 209 Small Closet Near Entrance	Floor	Wood	N/A	N/A	N/A
1	2	Classroom 209 Coat Closet	W1	Plaster	10	10	Positive
1	2	Classroom 209 Coat Closet	W2	Plaster	10	12.8	Positive
1	2	Classroom 209 Coat Closet	W3	Plaster	80	8.4	Positive
1	2	Classroom 209 Coat Closet	W4	Concrete	0	0	Negative
1	2	Classroom 209 Coat Closet	Ceiling	Plaster	100	20.1	Positive
1	2	Classroom 209 Coat Closet	Floor	Covebase	25	4.8	Positive
1	2	Classroom 209 Left Rear Storage Closet	W1	Plaster	18	5.4	Positive
1	2	Classroom 209 Left Rear Storage Closet	W2	Plaster	12	5.6	Positive
1	2	Classroom 209 Left Rear Storage Closet	W2	Wood	0	0.06	Negative
1	2	Classroom 209 Left Rear Storage Closet	W2	Wood	0	0.12	Negative
1	2	Classroom 209 Left Rear Storage Closet	W2	Wood	0	0.05	Negative
1	2	Classroom 209 Left Rear Storage Closet	W3	Plaster	0	4.7	Positive
1	2	Classroom 209 Left Rear Storage Closet	W4	Plaster	0	4.9	Positive

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 209 Left Rear Storage Closet	Ceiling	N/A	N/A	N/A	N/A
1	2	Classroom 209 Left Rear Storage Closet	Floor	Wood	N/A	N/A	N/A
1	2	Classroom 209 Left Rear Storage Closet	Floor	Wood	8	0.01	Negative
1	2	Classroom 209 Right Rear Storage Closet	W1	Plaster	13	2.9	Positive
1	2	Classroom 209 Right Rear Storage Closet	W2	Plaster	5	3.7	Positive
1	2	Classroom 209 Right Rear Storage Closet	W3	Plaster	1	5	Positive
1	2	Classroom 209 Right Rear Storage Closet	W4	Plaster	0	3.7	Positive
1	2	Classroom 209 Right Rear Storage Closet	Ceiling	N/A	N/A	N/A	N/A
1	2	Classroom 209 Right Rear Storage Closet	Floor	Wood	N/A	N/A	N/A
1	2	Classroom 209 Right Rear Storage Closet	Floor	Wood	2	0.06	Negative
1	2	Room 210 Main Area	W1	Sheetrock	0	0	Negative
1	2	Room 210 Main Area	W2	Plaster	3	4.1	Positive
1	2	Room 210 Main Area	W3	Plaster	15	4.8	Positive
1	2	Room 210 Main Area	W4	Sheetrock	0	0	Negative
1	2	Room 210 Main Area	Door Casing 1	Metal	0	0	Negative
1	2	Room 210 Main Area	Door Casing 4	Metal	0	0	Negative
1	2	Room 210 Main Area	Door Casing 4	Metal	0	0	Negative
1	2	Room 210 Main Area	Window Casing	Wood	0	1.2	Positive
1	2	Room 210 Main Area	Window Apron	Wood	0	0	Negative
1	2	Room 210 Main Area	Window Sill	Wood	0	0	Negative
1	2	Room 210 Main Area	Ceiling	Concrete	0	N/A	Negative
1	2	Room 210 Main Area	Floor	N/A	0	N/A	Negative
1	2	Room 210 Storage	W1	Sheetrock	0	0	Negative
1	2	Room 210 Storage	W2	Sheetrock	0	0	Negative
1	2	Room 210 Storage	W3	Plaster	0	28.7	Positive
1	2	Room 210 Storage	W4	Plaster	0	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Room 210 Storage	Ceiling	No Access	No Access	No Access	No Access
1	2	Room 210 Storage	Floor	N/A	N/A	N/A	N/A
1	2	Room 210 Bathroom	W1	Sheetrock	0	0	Negative
1	2	Room 210 Bathroom	W2	Sheetrock	0	0	Negative
1	2	Room 210 Bathroom	W3	Plaster	25	20.8	Positive
1	2	Room 210 Bathroom	W4	Sheetrock	0	0	Negative
1	2	Room 210 Bathroom	Ceiling	Sheetrock	0	0	Negative
1	2	Room 210 Bathroom	Floor	Concrete	0	0	N/A
1	2	Electrical Room 211 outside Classroom 209	W1	Plaster	40	0	Negative
1	2	Electrical Room 211 outside Classroom 209	W2	Concrete	0	0	Negative
1	2	Electrical Room 211 outside Classroom 209	W3	Plaster	0	2.4	Positive
1	2	Electrical Room 211 outside Classroom 209	W4	Concrete	0	0	Negative
1	2	Electrical Room 211 outside Classroom 209	Ceiling	Plaster	20	11.1	Positive
1	2	Electrical Room 211 outside Classroom 209	Floor	Concrete	0	0	Negative
1	2	2nd Floor Hallway	W1	Plaster	1	10.6	Positive
1	2	2nd Floor Hallway	W2	Plaster	15	11.7	Positive
1	2	2nd Floor Hallway	W3	Sheetrock	0	0	Negative
1	2	2nd Floor Hallway	W4	Plaster	20	14.4	Positive
1	2	2nd Floor Hallway	W4	Concrete	0	0	Negative
1	2	2nd Floor Hallway	Ceiling	Plaster	800	18.6	Positive
1	2	2nd Floor Hallway	Floor	N/A	N/A	N/A	N/A
1	3	Stairwell next to Classroom 300	W1	Concrete	0	0	Negative
1	3	Stairwell next to Classroom 300	W2	Plaster	3	11.7	Positive
1	3	Stairwell next to Classroom 300	W3	Plaster	30	10	Positive
1	3	Stairwell next to Classroom 300	W4	Plaster	10	11.2	Positive
1	3	Stairwell next to Classroom 300	Ceiling	Plaster	0	N/A	N/A

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Stairwell next to Classroom 300	Floor	N/A	N/A	N/A	N/A
1	3	Stairwell between Classrooms 308 and 310	W1	Concrete	0	0	Negative
1	3	Stairwell between Classrooms 308 and 310	W2	Plaster	0	4.1	Positive
1	3	Stairwell between Classrooms 308 and 310	W3	Plaster	1	9.8	Positive
1	3	Stairwell between Classrooms 308 and 310	W4	Plaster	7	8.9	Positive
1	3	Stairwell between Classrooms 308 and 310	Ceiling	Plaster	3	5.8	Positive
1	3	Stairwell between Classrooms 308 and 310	Floor	N/A	N/A	N/A	N/A
1	3	Classroom 300	Door Casing	Metal	2	0	Negative
1	3	Classroom 300	W1	Concrete	0	0	Negative
1	3	Classroom 300	W2	Concrete	0	0	Negative
1	3	Classroom 300	W2	Plaster	10	13.2	Positive
1	3	Classroom 300	W3	Plaster	25	12.1	Positive
1	3	Classroom 300	W3	Wood	10	0.01	Negative
1	3	Classroom 300	W3	Wood	0	0	Negative
1	3	Classroom 300	W3	Wood	0	1.1	Positive
1	3	Classroom 300	W3	Sheetrock	0	0	Negative
1	3	Classroom 300	W4	Plaster	10	7.4	Positive
1	3	Classroom 300	Ceiling	Sheetrock	0	N/A	N/A
1	3	Classroom 300	Floor	N/A	N/A	N/A	N/A
1	3	Classroom 300 Storage Closet	W1	Concrete	0	0	Negative
1	3	Classroom 300 Storage Closet	W2	Plaster	0	16.1	Positive
1	3	Classroom 300 Storage Closet	W3	Plaster	6	11.6	Positive
1	3	Classroom 300 Storage Closet	W3	Wood	0	0.11	Negative
1	3	Classroom 300 Storage Closet	W3	Wood	0	0.14	Negative
1	3	Classroom 300 Storage Closet	W3	Wood	0	0	Negative
1	3	Classroom 300 Storage Closet	W4	Concrete	0	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 300 Storage Closet	Ceiling	Sheetrock	0	N/A	N/A
1	3	Classroom 300 Storage Closet	Floor	N/A	N/A	N/A	N/A
1	3	Classroom 301	Door Casing	Metal	8	0	Negative
1	3	Classroom 301	W1	Concrete	0	0	Negative
1	3	Classroom 301	W2	Concrete	0	0	Negative
1	3	Classroom 301	W3	Plaster	2	7.1	Positive
1	3	Classroom 301	W3	Sheetrock	5	0	Negative
1	3	Classroom 301	W3	Wood	0	0.01	Negative
1	3	Classroom 301	W3	Wood	0	0.14	Negative
1	3	Classroom 301	W3	Wood	0	1.5	Positive
1	3	Classroom 301	W4	Concrete	0	0	Negative
1	3	Classroom 301	Ceiling	Sheetrock	0	N/A	N/A
1	3	Classroom 301	Floor	N/A	N/A	N/A	N/A
1	3	Classroom 301 Small Storage Closet	W1	Concrete	0	0	Negative
1	3	Classroom 301 Small Storage Closet	W2	Concrete	0	0	Negative
1	3	Classroom 301 Small Storage Closet	W3	Concrete	0	0	Negative
1	3	Classroom 301 Small Storage Closet	W4	Concrete	0	0	Negative
1	3	Classroom 301 Small Storage Closet	Ceiling	Sheetrock	0	N/A	N/A
1	3	Classroom 301 Small Storage Closet	Floor	N/A	0	N/A	N/A
1	3	Classroom 301 Large Storage Closet	W1	Concrete	0	0	Negative
1	3	Classroom 301 Large Storage Closet	W2	Concrete	0	0	Negative
1	3	Classroom 301 Large Storage Closet	W3	Concrete	0	0	Negative
1	3	Classroom 301 Large Storage Closet	W4	Concrete	0	0	Negative
1	3	Classroom 301 Large Storage Closet	Ceiling	Sheetrock	0	N/A	N/A
1	3	Classroom 301 Large Storage Closet	Floor	N/A	0	N/A	N/A
1	3	Classroom 303	W1	Concrete	0	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 303	W2	Plaster	20	16.9	Positive
1	3	Classroom 303	W3	Plaster	15	13.6	Positive
1	3	Classroom 303	W3	Wood	0	0	Negative
1	3	Classroom 303	W3	Wood	0	0	Negative
1	3	Classroom 303	W3	Wood	0	1.5	Positive
1	3	Classroom 303	W4	Concrete	0	0	Negative
1	3	Classroom 303	W4	Plaster	5	10.4	Positive
1	3	Classroom 303	Ceiling	Sheetrock	0	N/A	N/A
1	3	Classroom 303	Floor	N/A	0	N/A	N/A
1	3	Classroom 303 Storage Closet	W1	Concrete	0	0	Negative
1	3	Classroom 303 Storage Closet	W2	Concrete	0	0	Negative
1	3	Classroom 303 Storage Closet	W3	Plaster	0	2.4	Positive
1	3	Classroom 303 Storage Closet	W3	Wood	0	0	Negative
1	3	Classroom 303 Storage Closet	W3	Wood	0	0.11	Negative
1	3	Classroom 303 Storage Closet	W3	Wood	0	0.03	Negative
1	3	Classroom 303 Storage Closet	W4	Plaster	0	0	Negative
1	3	Classroom 303 Storage Closet	Ceiling	Sheetrock	0	N/A	N/A
1	3	Classroom 303 Storage Closet	Floor	N/A	0	N/A	N/A
1	3	Office 302	W1	Plaster	0	12.9	Positive
1	3	Office 302	W1	Plaster	0	11.1	Positive
1	3	Office 302	W2	Plaster	1	12.3	Positive
1	3	Office 302	W2	Concrete	0	0	Negative
1	3	Office 302	W3	Plaster	20	11.4	Positive
1	3	Office 302	W4	Plaster	5	13.1	Positive
1	3	Office 302	Ceiling	Plaster	150	3.3	Positive
1	3	Office 302	Floor	Wood	N/A	N/A	N/A

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Office 302 Coat Closet	W1	Plaster	2	9.8	Positive
1	3	Office 302 Coat Closet	W2	Plaster	0	7.1	Positive
1	3	Office 302 Coat Closet	W3	Concrete	0	0	Negative
1	3	Office 302 Coat Closet	W4	Plaster	0	9.2	Positive
1	3	Office 302 Coat Closet	Ceiling	Plaster	10	3.8	Positive
1	3	Office 302 Coat Closet	Floor	Wood	N/A	N/A	N/A
1	3	Office 302 Corner Closet	W1	Plaster	0	5.2	Positive
1	3	Office 302 Corner Closet	W2	Plaster	10	4.8	Positive
1	3	Office 302 Corner Closet	W3	Plaster	5	2.4	Positive
1	3	Office 302 Corner Closet	W4	Plaster	15	4.6	Positive
1	3	Office 302 Corner Closet	Ceiling	Plaster	10	3.1	Positive
1	3	Office 302 Corner Closet	Floor	N/A	N/A	N/A	N/A
1	3	Classroom 305	W1	Plaster	15	9.7	Positive
1	3	Classroom 305	W2	Plaster	8	7.5	Positive
1	3	Classroom 305	W3	Plaster	40	4.9	Positive
1	3	Classroom 305	W3	Wood	2	0.04	Negative
1	3	Classroom 305	W3	Wood	0	0.06	Negative
1	3	Classroom 305	W3	Wood	2	0.9	Positive
1	3	Classroom 305	W4	Plaster	12	5.6	Negative
1	3	Classroom 305	Ceiling	Plaster	450	4.6	Positive
1	3	Classroom 305	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 305	Floor	Wood	10	0.04	Negative
1	3	Classroom 305 Small Closet	W1	Plaster	0	5.2	Positive
1	3	Classroom 305 Small Closet	W2	Plaster	0	2.4	Positive
1	3	Classroom 305 Small Closet	W3	Plaster	0	3.8	Positive
1	3	Classroom 305 Small Closet	W3	Metal	1	5.9	Positive

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 305 Small Closet	W4	Plaster	4	3.4	Positive
1	3	Classroom 305 Small Closet	Ceiling	Plaster	10	5.4	Positive
1	3	Classroom 305 Small Closet	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 305 Small Closet	Floor	Wood	5	0.06	Negative
1	3	Classroom 305 Coat Closet	W1	Plaster	4	5.7	Positive
1	3	Classroom 305 Coat Closet	W2	Plaster	10	9.3	Positive
1	3	Classroom 305 Coat Closet	W2	Wood	0	0	Negative
1	3	Classroom 305 Coat Closet	W3	Concrete	0	0	Negative
1	3	Classroom 305 Coat Closet	W4	Plaster	1	5.3	Positive
1	3	Classroom 305 Coat Closet	W4	Wood	0	0	Negative
1	3	Classroom 305 Coat Closet	Ceiling	Plaster	15	6.2	Positive
1	3	Classroom 305 Coat Closet	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 305 Coat Closet	Floor	Wood	5	0.04	Negative
1	3	Classroom 305 Corner Storage Closet	W1	Plaster	0	4.2	Positive
1	3	Classroom 305 Corner Storage Closet	W2	Plaster	0	5.5	Positive
1	3	Classroom 305 Corner Storage Closet	W3	Plaster	15	6.2	Positive
1	3	Classroom 305 Corner Storage Closet	W4	Plaster	0	4.2	Positive
1	3	Classroom 305 Corner Storage Closet	Ceiling	Plaster	0	2.8	Positive
1	3	Classroom 305 Corner Storage Closet	Floor	N/A	N/A	N/A	N/A
1	3	Classroom 304	W1	Plaster	15	14	Positive
1	3	Classroom 304	W2	Concrete	0	0.02	Negative
1	3	Classroom 304	W3	Plaster	20	17.7	Positive
1	3	Classroom 304	W3	Wood	4	0.17	Negative
1	3	Classroom 304	W3	Wood	0	0.03	Negative
1	3	Classroom 304	W3	Wood	0	1.3	Positive
1	3	Classroom 304	W4	Plaster	0	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 304	Ceiling	Plaster	600	2.7	Positive
1	3	Classroom 304	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 304	Floor	Wood	10	0	Negative
1	3	Classroom 304 Small Closet	W1	Plaster	0	N/A	N/A
1	3	Classroom 304 Small Closet	W2	Plaster	0	0	Negative
1	3	Classroom 304 Small Closet	W3	Plaster	0	N/A	N/A
1	3	Classroom 304 Small Closet	W4	Plaster	0	4.5	Positive
1	3	Classroom 304 Small Closet	Ceiling	Plaster	0	3.9	Positive
1	3	Classroom 304 Small Closet	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 304 Small Closet	Floor	Wood	5	0.01	Negative
1	3	Classroom 304 Coat Closet	W1	Plaster	0	11.9	Positive
1	3	Classroom 304 Coat Closet	W2	Plaster	0	0	Negative
1	3	Classroom 304 Coat Closet	W2	Wood	0	1	Positive
1	3	Classroom 304 Coat Closet	W3	Plaster	2	5.5	Positive
1	3	Classroom 304 Coat Closet	W4	Plaster	6	17	Positive
1	3	Classroom 304 Coat Closet	Ceiling	No Access	No Access	No Access	No Access
1	3	Classroom 304 Coat Closet	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 304 Coat Closet	Floor	Wood	5	0.06	Negative
1	3	Classroom 307	W1	Plaster	2	0	Negative
1	3	Classroom 307	W1	Plaster	20	0	Negative
1	3	Classroom 307	W1	Wood	0	0	Negative
1	3	Classroom 307	W2	Plaster	2	11.1	Positive
1	3	Classroom 307	W3	Plaster	40	14.4	Positive
1	3	Classroom 307	W3	Wood	4	0.2	Negative
1	3	Classroom 307	W3	Wood	2	0.05	Negative
1	3	Classroom 307	W3	Wood	0	0.11	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 307	W4	Plaster	10	0.7	Positive
1	3	Classroom 307	Ceiling	Plaster	200	5.1	Positive
1	3	Classroom 307	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 307	Floor	Wood	10	0.01	Negative
1	3	Classroom 307 Small Closet	W1	Plaster	0	N/A	N/A
1	3	Classroom 307 Small Closet	W2	Plaster	0	6.8	Positive
1	3	Classroom 307 Small Closet	W3	Plaster	0	N/A	N/A
1	3	Classroom 307 Small Closet	W4	Plaster	0	5.5	Positive
1	3	Classroom 307 Small Closet	Ceiling	Plaster	0	N/A	N/A
1	3	Classroom 307 Small Closet	Floor	Wood	5	N/A	N/A
1	3	Classroom 307 Coat Closet	W1	Plaster	10	13.5	Positive
1	3	Classroom 307 Coat Closet	W2	Plaster	12	11.4	Positive
1	3	Classroom 307 Coat Closet	W2	Wood	0	1.2	Negative
1	3	Classroom 307 Coat Closet	W3	Plaster	15	7.7	Positive
1	3	Classroom 307 Coat Closet	W4	Plaster	15	7.9	Positive
1	3	Classroom 307 Coat Closet	Ceiling	Plaster	70	4.7	Positive
1	3	Classroom 307 Coat Closet	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 306	W1	Plaster	16	15.4	Positive
1	3	Classroom 306	W2	Concrete	0	0.02	Negative
1	3	Classroom 306	W3	Plaster	20	13.1	Positive
1	3	Classroom 306	W3	Wood	10	0.16	Negative
1	3	Classroom 306	W3	Wood	0	0.01	Negative
1	3	Classroom 306	W3	Wood	5	1.3	Positive
1	3	Classroom 306	W4	Concrete	0	0.01	Negative
1	3	Classroom 306	Ceiling	Plaster	650	7.3	Positive
1	3	Classroom 306	Floor	Wood	N/A	N/A	N/A

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 306	Floor	Wood	10	0.06	Negative
1	3	Classroom 306 Coat Closet	W1	Plaster	10	14.2	Positive
1	3	Classroom 306 Coat Closet	W2	Plaster	0	11.6	Positive
1	3	Classroom 306 Coat Closet	W2	Wood	0	0.03	Negative
1	3	Classroom 306 Coat Closet	W3	Plaster	0	12.9	Positive
1	3	Classroom 306 Coat Closet	W4	Plaster	10	12.2	Positive
1	3	Classroom 306 Coat Closet	Ceiling	Plaster	15	2.1	Positive
1	3	Classroom 306 Coat Closet	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 306	Floor	Wood	5	0.03	Negative
1	3	Classroom 309	W1	Plaster	20	18.1	Positive
1	3	Classroom 309	W2	Plaster	15	12.3	Positive
1	3	Classroom 309	W2	Concrete	0	0	Negative
1	3	Classroom 309	W3	Plaster	35	14.5	Positive
1	3	Classroom 309	W3	Wood	2	0	Negative
1	3	Classroom 309	W3	Wood	6	0.06	Negative
1	3	Classroom 309	W3	Wood	10	14.2	Positive
1	3	Classroom 309	W4	Plaster	5	16.1	Positive
1	3	Classroom 309	Ceiling	Plaster	375	2.3	Positive
1	3	Classroom 309	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 309	Floor	Wood	10	0.02	Negative
1	3	Classroom 309 Small Closet	W1	Plaster	4	4.8	Positive
1	3	Classroom 309 Small Closet	W2	Plaster	6	5.9	Positive
1	3	Classroom 309 Small Closet	W2	Wood	0	0.05	Negative
1	3	Classroom 309 Small Closet	W3	Plaster	0	5.6	Positive
1	3	Classroom 309 Small Closet	W3	Wood	0	0.17	Negative
1	3	Classroom 309 Small Closet	W4	Plaster	6	3.9	Positive

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 309 Small Closet	Ceiling	Plaster	0	4.3	Positive
1	3	Classroom 309 Small Closet	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 309 Small Closet	Floor	Wood	5	0.04	Negative
1	3	Classroom 309 Coat Closet	W1	Plaster	5	10.1	Positive
1	3	Classroom 309 Coat Closet	W2	Concrete	0	0	Negative
1	3	Classroom 309 Coat Closet	W2	Plaster	4	10.5	Positive
1	3	Classroom 309 Coat Closet	W3	Plaster	2	0	Negative
1	3	Classroom 309 Coat Closet	W3	Sheetrock	4	0	Negative
1	3	Classroom 309 Coat Closet	W4	Plaster	4	11.5	Positive
1	3	Classroom 309 Coat Closet	Ceiling	Plaster	5	4.5	Positive
1	3	Classroom 309 Coat Closet	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 309 Coat Closet	Floor	Wood	10	14.4	Positive
1	3	Classroom 308	W1	Plaster	12	16.9	Positive
1	3	Classroom 308	W2	Plaster	22	16.2	Positive
1	3	Classroom 308	W3	Plaster	35	20	Positive
1	3	Classroom 308	W3	Wood	10	0.04	Negative
1	3	Classroom 308	W3	Wood	0	0.08	Negative
1	3	Classroom 308	W3	Wood	0	0.12	Negative
1	3	Classroom 308	W4	Concrete	1	0	Negative
1	3	Classroom 308	W4	Plaster	1	17.1	Positive
1	3	Classroom 308	Ceiling	Plaster	500	19.2	Positive
1	3	Classroom 308	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 308	Floor	Wood	10	0.04	Negative
1	3	Classroom 308 Coat Closet	W1	Plaster	2	11.6	Positive
1	3	Classroom 308 Coat Closet	W2	Plaster	0	11.4	Positive
1	3	Classroom 308 Coat Closet	W2	Wood	0	0.3	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 308 Coat Closet	W3	Plaster	0	10.9	Positive
1	3	Classroom 308 Coat Closet	W4	Plaster	8	9.9	Positive
1	3	Classroom 308 Coat Closet	Ceiling	Plaster	100	4.5	Positive
1	3	Classroom 308 Coat Closet	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 308 Small Closet	W1	Plaster	0	2.9	Positive
1	3	Classroom 308 Small Closet	W2	Plaster	1	3.9	Positive
1	3	Classroom 308 Small Closet	W3	Plaster	1	0	Negative
1	3	Classroom 308 Small Closet	W4	Plaster	2	5.7	Positive
1	3	Classroom 308 Small Closet	Ceiling	Plaster	0	2.4	Positive
1	3	Classroom 308 Small Closet	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 308 Small Closet	Floor	Wood	5	0.01	Negative
1	3	Classroom 311	W1	Plaster	20	15.9	Positive
1	3	Classroom 311	W2	Plaster	10	0	Negative
1	3	Classroom 311	W3	Plaster	25	0.03	Negative
1	3	Classroom 311	W3	Wood	5	0.05	Negative
1	3	Classroom 311	W3	Wood	0	0.03	Negative
1	3	Classroom 311	W3	Wood	0	0.02	Negative
1	3	Classroom 311	W4	Plaster	8	0	Negative
1	3	Classroom 311	Ceiling	Plaster	400	3.1	Positive
1	3	Classroom 311	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 311	Floor	Wood	10	0.03	Negative
1	3	Classroom 311 Small Closet	W1	Plaster	0	2.9	Positive
1	3	Classroom 311 Small Closet	W2	Plaster	0	2.3	Positive
1	3	Classroom 311 Small Closet	W3	Plaster	0	3.5	Positive
1	3	Classroom 311 Small Closet	W4	Plaster	0	3	Positive
1	3	Classroom 311 Small Closet	Ceiling	Plaster	0	2.7	Positive

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 311 Small Closet	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 311 Coat Closet	W1	Plaster	3	10.5	Positive
1	3	Classroom 311 Coat Closet	W2	Plaster	10	12.9	Positive
1	3	Classroom 311 Coat Closet	W2	Wood	0	0	Negative
1	3	Classroom 311 Coat Closet	W3	Plaster	8	14.4	Positive
1	3	Classroom 311 Coat Closet	W4	Plaster	3	13.4	Positive
1	3	Classroom 311 Coat Closet	Ceiling	Plaster	100	9.7	Positive
1	3	Classroom 311 Coat Closet	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 310	W1	Plaster	8	20.1	Positive
1	3	Classroom 310	W2	Concrete	0	0	Negative
1	3	Classroom 310	W3	Plaster	10	18.9	Positive
1	3	Classroom 310	W4	Plaster	1	12.2	Positive
1	3	Classroom 310	Ceiling	Plaster	300	17.1	Positive
1	3	Classroom 310	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 310	Floor	Wood	10	0.06	Negative
1	3	Classroom 310 Coat Closet	W1	No Access	No Access	No Access	No Access
1	3	Classroom 310 Coat Closet	W2	No Access	No Access	No Access	No Access
1	3	Classroom 310 Coat Closet	W3	No Access	No Access	No Access	No Access
1	3	Classroom 310 Coat Closet	W4	No Access	No Access	No Access	No Access
1	3	Classroom 310 Coat Closet	Ceiling	No Access	No Access	No Access	No Access
1	3	Classroom 310 Coat Closet	Floor	No Access	No Access	No Access	No Access
1	3	Classroom 310 Rear Storage Closet	W1	Concrete	0	0	Negative
1	3	Classroom 310 Rear Storage Closet	W1	Metal	1	0	Negative
1	3	Classroom 310 Rear Storage Closet	W2	Plaster	0	0	Negative
1	3	Classroom 310 Rear Storage Closet	W3	Plaster	0	0	Negative
1	3	Classroom 310 Rear Storage Closet	W4	Plaster	0	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 310 Rear Storage Closet	Ceiling	Plaster	20	14.8	Positive
1	3	Classroom 310 Rear Storage Closet	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 310 Rear Storage Closet	Floor	Wood	5	0.03	Negative
1	3	Classroom 310 Corner Storage Nook	W1	Concrete	0	0	Negative
1	3	Classroom 310 Corner Storage Nook	W2	Plaster	0	0	Negative
1	3	Classroom 310 Corner Storage Nook	W3	Plaster	0	0	Negative
1	3	Classroom 310 Corner Storage Nook	W4	Plaster	3	8	Positive
1	3	Classroom 310 Corner Storage Nook	Ceiling	No Access	No Access	No Access	No Access
1	3	Classroom 310 Corner Storage Nook	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 310 Corner Storage Nook	Floor	Wood	5	0.04	Negative
1	3	Classroom 313 Coat Closet	W1	Plaster	1	10.1	Positive
1	3	Classroom 313 Coat Closet	W2	Plaster	2	12.2	Positive
1	3	Classroom 313 Coat Closet	W3	Plaster	0	13.1	Positive
1	3	Classroom 313 Coat Closet	W4	Concrete	0	0	Negative
1	3	Classroom 313 Coat Closet	Ceiling	Plaster	80	19.5	Positive
1	3	Classroom 313 Coat Closet	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 313 Coat Closet	Floor	Wood	10	0.08	Negative
1	3	Classroom 313	W1	Plaster	1	13.6	Positive
1	3	Classroom 313	W2	Plaster	0	16.1	Positive
1	3	Classroom 313	W2	Concrete	0	0	Negative
1	3	Classroom 313	W3	Plaster	20	15.1	Positive
1	3	Classroom 313	W3	Plaster	0	15.7	Positive
1	3	Classroom 313	W3	Wood	2	0.11	Negative
1	3	Classroom 313	W3	Wood	2	0.03	Negative
1	3	Classroom 313	W3	Wood	3	0.06	Negative
1	3	Classroom 313	W4	Plaster	0	13.7	Positive

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 313	W4	Concrete	0	0	Negative
1	3	Classroom 313	Ceiling	Plaster	250	14.6	Positive
1	3	Classroom 313	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 313	Floor	Wood	10	0.08	Negative
1	3	Classroom 313 Rear Storage Closet	W1	Plaster	0	12.2	Positive
1	3	Classroom 313 Rear Storage Closet	W2	Plaster	3	10.1	Positive
1	3	Classroom 313 Rear Storage Closet	W3	Plaster	0	11.2	Positive
1	3	Classroom 313 Rear Storage Closet	W4	Plaster	2	13.2	Positive
1	3	Classroom 313 Rear Storage Closet	Ceiling	Plaster	100	16.2	Positive
1	3	Classroom 313 Rear Storage Closet	Floor	Wood	N/A	N/A	N/A
1	3	Classroom 313 Small Closet Near Entrance	W1	Plaster	0	11.1	Positive
1	3	Classroom 313 Small Closet Near Entrance	W2	Plaster	0	12.4	Positive
1	3	Classroom 313 Small Closet Near Entrance	W3	Plaster	0	10.5	Positive
1	3	Classroom 313 Small Closet Near Entrance	W4	Plaster	0	10.3	Positive
1	3	Classroom 313 Small Closet Near Entrance	Ceiling	Plaster	0	11.3	Positive
1	3	Classroom 313 Small Closet Near Entrance	Floor	Wood	N/A	N/A	N/A
1	3	Electrical Room outside Classroom 313	W1	Plaster	0	0	Negative
1	3	Electrical Room outside Classroom 313	W2	Concrete	0	0	Negative
1	3	Electrical Room outside Classroom 313	W3	Plaster	0	10.1	Positive
1	3	Electrical Room outside Classroom 313	W4	Concrete	0	0	Negative
1	3	Electrical Room outside Classroom 313	Ceiling	Plaster	10	13.2	Positive
1	3	Electrical Room outside Classroom 313	Floor	Concrete	0	0	Negative
1	3	Staff Room Main Area	W1	Plaster	15	18.6	Positive
1	3	Staff Room Main Area	W2	Plaster	10	13.5	Positive
1	3	Staff Room Main Area	W3	Sheetrock	0	0	Negative
1	3	Staff Room Main Area	W4	Sheetrock	0	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Staff Room Main Area	Ceiling	Sheetrock	0	N/A	N/A
1	3	Staff Room Main Area	Floor	Floor Tile	N/A	N/A	N/A
1	3	Staff Room Main Area	Door Casing 1	Metal	0	0	Negative
1	3	Staff Room Main Area	Door Casing 4	Metal	0	0	Negative
1	3	Staff Room Main Area	Door Casing 4	Metal	0	0	Negative
1	3	Staff Room Main Area	Window Trim 3	Wood	3	0.13	Negative
1	3	Staff Room Main Area	Window Sill 3	Wood	0	0	Negative
1	3	Staff Room Main Area	Window Apron 3	Wood	0	0	Negative
1	3	Staff Room Closet	W1	Sheetrock	0	0	Negative
1	3	Staff Room Closet	W2	Sheetrock	0	0	Negative
1	3	Staff Room Closet	W3	Plaster	8	14	Positive
1	3	Staff Room Closet	W4	Concrete	0	0	Negative
1	3	Staff Room Closet	Ceiling	Sheetrock	0	N/A	N/A
1	3	Staff Room Closet	Floor	Floor Tile	N/A	N/A	N/A
1	3	Staff Room Bathroom	W1	Sheetrock	0	0	Negative
1	3	Staff Room Bathroom	W2	Sheetrock	0	0	Negative
1	3	Staff Room Bathroom	W3	Sheetrock	0	0	Negative
1	3	Staff Room Bathroom	W4	Sheetrock	0	0	Negative
1	3	Staff Room Bathroom	Ceiling	Sheetrock	0	0	Negative
1	3	Staff Room Bathroom	Floor	Concrete	N/A	N/A	N/A
1	3	IT MDF Room outside Classroom 310	W1	Sheetrock	0	0	Negative
1	3	IT MDF Room outside Classroom 310	W2	Sheetrock	0	0	Negative
1	3	IT MDF Room outside Classroom 310	W2	Wood	0	0	Negative
1	3	IT MDF Room outside Classroom 310	W3	Sheetrock	0	0	Negative
1	3	IT MDF Room outside Classroom 310	W3	Wood	0	0	Negative
1	3	IT MDF Room outside Classroom 310	W4	Sheetrock	0	0	Negative

		Inspection Dates: 10/12/20-10/19/20, 03/14-03/18/2022	School District of Philadelphia				
		Name of Inspector: Michael Barth, CJ Karoly	Lead Safe Certification Assessment Report				
		Inspection Company: Criterion Laboratories, Inc.	McDaniel School				
Element	Floor	On-site Room Name	Component	Substrate Material	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	IT MDF Room outside Classroom 310	W4	Wood	0	0	Negative
1	3	IT MDF Room outside Classroom 310	Ceiling	Sheetrock	0	N/A	N/A
1	3	IT MDF Room outside Classroom 310	Floor	N/A	N/A	N/A	N/A
1	3	3rd Floor Hallway	W1	Plaster	25	14.8	Positive
1	3	3rd Floor Hallway	W1	Concrete	0	0	Negative
1	3	3rd Floor Hallway	Door Casing	Metal	3	0.02	Negative
1	3	3rd Floor Hallway	W2	Plaster	1	10.3	Positive
1	3	3rd Floor Hallway	W3	Plaster	75	3.1	Positive
1	3	3rd Floor Hallway	W4	Sheetrock	0	0	Negative
1	3	3rd Floor Hallway	Ceiling	Plaster	1000	24.3	Positive
1	3	3rd Floor Hallway	Floor	N/A	N/A	N/A	N/A
1	A	Attic - 3rd Floor Stairwell	W1	Brick	N/A	N/A	N/A
1	A	Attic - 3rd Floor Stairwell	W2	Brick	N/A	N/A	N/A
1	A	Attic - 3rd Floor Stairwell	W3	Brick	N/A	N/A	N/A
1	A	Attic - 3rd Floor Stairwell	W4	Brick	N/A	N/A	N/A
1	A	Attic - 3rd Floor Stairwell	Ceiling	N/A	N/A	N/A	N/A
1	A	Attic - 3rd Floor Stairwell	Floor	Concrete	N/A	N/A	N/A
1	C	Auditorium Supply Plenum	W1	No Access	No Access	No Access	No Access
1	C	Auditorium Supply Plenum	W2	No Access	No Access	No Access	No Access
1	C	Auditorium Supply Plenum	W3	No Access	No Access	No Access	No Access
1	C	Auditorium Supply Plenum	W4	No Access	No Access	No Access	No Access
1	C	Auditorium Supply Plenum	Ceiling	No Access	No Access	No Access	No Access
1	C	Auditorium Supply Plenum	Floor	No Access	No Access	No Access	No Access