

LEAD SAFE ASSESSMENT REPORT



Gilbert Spruance Elementary School

**6401 Horrocks Street
Philadelphia, Pennsylvania**

August 12, 2021

Prepared For:



**440 N. Broad Street
Philadelphia, PA 19130**

Prepared by:



**1012 Industrial Drive
West Berlin, NJ 08091**

ACER Project Number: SDP038



TABLE OF CONTENTS

1.0 INTRODUCTION

2.0 SCOPE OF WORK

2.1 Building Description

3.0 FINDINGS & RECOMMENDATIONS

3.1 Inspection Findings

3.2 Recommendations

4.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

5.0 APPENDICES

Appendix A Lead Safe Certification Assessment



I.0 INTRODUCTION

Acer Associates, LLC (ACER) has prepared this report to summarize the findings of the Lead Safe Assessment at the Gilbert Spruance Elementary School, located at 6401 Horrocks Street in Philadelphia, Pennsylvania. The purpose of the inspection was to identify and assess painted surfaces within the school.

The inspection was completed on April 16, April 19 – April 22, April 28, and May 5, 2021, by Ms. Kristen Masotes of ACER. Ms. Masotes is a licensed Commonwealth of Pennsylvania Lead Risk Assessor (058358).

The lead survey was conducted in accordance with the requirements of Federal, State and local regulations pertaining to lead paint, including the U.S. Department of Housing and Urban Development (HUD) Guidelines for the Evaluation of Lead-Based Paint Hazards in Housing. The findings in this report are consistent with accepted principles and practices established and prescribed by the City of Philadelphia, Commonwealth of Pennsylvania, EPA, and HUD.

This report, and the supporting data, findings, conclusions, opinions, and the recommendations it contains, represents the result of ACER's efforts. This report is not an abatement specification and should not be used for specifying removal methods or techniques. The results, assessments, conclusions, and recommendations stated in this report are factually representative of the conditions observed at this location on the dates of the inspection. ACER cannot assume responsibility for any change in conditions that occurred after the inspection.

Any reliance on this report by a party other than The School District of Philadelphia shall be at the party's sole risk unless that party has written authorization from ACER to use this document. The purpose of this restriction is to attempt to protect the interest of parties to whom the report may not be appropriately directed.

END OF SECTION



2.0 INSPECTION

2.1 Building Description

Gilbert Spruance Elementary School is a two (2) story building with a basement. Interior finishes surveyed included CMU walls, concrete ceilings, and a combination of wood, tile, and concrete floors.

Please Note: Direction “W1” corresponds to the entry wall of each room/location. Direction “W2” corresponds to the next adjacent wall in the clockwise directions and so forth for directions “W3” and “W4”.

A Niton model XLP-703A X-ray fluorescence lead paint analyzer was used for determination of lead content in paint. Calibration checks of the Niton XLP-703A were done in accordance with Performance Characteristic Sheets (PCS). A copy of the PCS has been provided in Appendix B. Calibration checks were performed on this XRF instrument using a National Institute of Standards and Technology (NIST) Standard Reference Material (SRM) sheet supplied by Niton at the beginning and end of each day's testing and at intervals of every four (4) hours during the testing. Calibration checks consist of the average of three (3) readings taken of the nominal 1.0 mg/cm² paint film (SRM 2573). If for any reason the instrument does not maintain a consistent reproducible calibration, it is immediately removed from active service and sent back to the manufacturer for examination, service and/or recalibration.

The inspection consisted of collecting test readings of all substrate types in a room as depicted above and described as follows. One (1) test point (reading) was taken for each testing combination, except for the walls where at least four (4) were tested, to determine the amount of lead contained in the paint for that substrate. A testing combination is characterized by the room equivalent (Room 102, Main Office, etc.), component type (door, window, wall, etc.) and substrate (metal, sheetrock, etc.). The resulting test readings are then classified as POSITIVE OR NEGATIVE according to the action level, which is set in accordance with the applicable action level of the governing municipality, county, or state. Substrate corrections were not performed since the XLP 703A was used in the *Standard Mode* setting, no substrate corrections are necessary according to the PCS. The lead safe certification assessment report for this inspection is provided in Appendix A.

END OF SECTION



3.0 FINDINGS & RECOMMENDATIONS

On April 16, April 19 – April 22, April 28, and May 5, 2021, ACER conducted an inspection for lead-based paint at Gilbert Spruance Elementary School, located at 6401 Horrocks Street in Philadelphia, Pennsylvania.

3.1 Findings

In accordance with The Philadelphia Code, Chapter 6-800, lead-based paint is defined as greater than 0.7 mg/cm². ACER's inspection identified lead-based paint associated with the following building components:

Component	Substrate	Color	Location(s)
Pipe Jacket	Metal	Blue	Classroom 100
Wall Baseboard	Transite	Black	Office 100B
Pipe Jacket	Metal	Gray	Classroom 101
		Red	
		Green	Classroom 102
		Yellow	Classroom 103
		Blue	Classroom 104
			Classroom 105
		Green	Classroom 106
			Wall Baseboard
Pipe Jacket	Metal	Blue	Classroom 108
		Green	Classroom 109
			Classroom 110
Wall Baseboard	Transite	Black	Classroom 111
Pipe Jacket	Metal	Blue	
Column	Concrete		
Pipe Jacket	Metal	Green	Classroom 114
Wall 3	CMU	Yellow	Classroom 115
Wall Baseboard	Ceramic Tile	Tan	Classroom 119
Wall Baseboard	Transite	Black	Boys Restroom 110T
			Girls Restroom 111T
		Pipe Cover	Metal
Classroom 118			
Wall Baseboard	Transite	Black	Office 118A



Component	Substrate	Color	Location(s)
Wall Baseboard	Transite	Black	Classroom 120
Wall 3	CMU	Beige	Book Storage 124A
Wall 4	CMU	Blue	
Wall Baseboard	Transite	Black	Boys Restroom at Gym
W2	CMU	Beige	Hallway at Boys Restroom at Gym
Wall Baseboard	Transite	Black	Girls Restroom at Gym
W4	CMU	Black	Stage
Univent	Metal	Beige	Women's Restroom to the left of the Auditorium
Wall Baseboard	Transite	Black	Waiting Room at Nurse's Office
			Teacher Dining Area
Door Panel	Metal	Red	Kitchen
Wall Baseboard	Transite	Black	Cafeteria
Door	Metal	Red	Kitchen Office
Wall Baseboard	Transite	Black	Hallway next to Classroom 111
Pipe Jacket	Metal	Beige	Hallway at Classrooms 108 to 115
W2	CMU	Beige	Walkway at Boy's Restroom by Gym
Pipe Jacket	Metal	Beige	Hallway at Classrooms 100 to 107
Wall Baseboard	Transite	Black	Hallway at Classrooms 118 & 120
			Stairwell next to Classroom 110
W3	CMU	Beige	Stairwell next to 119
Wall Baseboard	Transite	Black	
Stair Riser	Concrete	Black	Stairwell next to Classroom 115
Wall Baseboard	Transite	Black	Stairwell near Classroom 101
Pipe Jacket	Metal	Beige	
Ceiling	Concrete	White	Classroom 202
W2	CMU	Blue	Classroom 203
Wall Baseboard	Transite	Black	
Ceiling	Concrete	White	Classroom 205
			Classroom 207
			Girls Restroom across from Stairwell C
Wall Baseboard	Transite	Black	Boy's Restroom across from Stairwell C
W2	CMU	Green	214L Student Assistance Room
Wall Baseboard	Transite	Black	
W2	CMU	Beige	Girls Restroom next to Asst Principal Office
Ceiling	Concrete	White	Classroom 216



Component	Substrate	Color	Location(s)
W4	CMU	Blue	Classroom 216 Closet
W	CMU	Beige	Boys Restroom across from Stairwell C
Ceiling	Concrete	White	
Stall Wall	Transite	Beige	
W3	CMU	Beige	Stairwell next to Classroom 207
Wall Baseboard	Transite	Tan	Stairwell next to Library
Pipe Cover	Metal	Beige	
Ceiling	Concrete	White	
Stair Riser	Concrete	Black	Stairwell near Classroom 201
W3	CMU	White	Boiler Room
Panel Box	Metal	Green	

3.2 Limitations

The inspection and sample procedures used to complete this inspection are consistent with prevalent environmental and industrial hygiene standards for lead-based paint. All reasonable efforts were made to identify the presence of lead-based paint within the inspected areas. Materials not identified in this report should be considered as not sampled. ACER cannot assume responsibility for any change in conditions that occurred after the inspection.

END OF SECTION



4.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONAL

Sincerely,
Acer Associates, LLC

Prepared By:

Kristen Masotes
Project Manager
PA Lead Risk Assessor #058358

Reviewed By:

Matthew J. DePalma
Vice President



5.0 APPENDICES



Appendix A

Lead Safe Certification Assessment Report

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	100	Primary	Classroom 100	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative			Negative					
8350	1	B835001-1	1	100	Primary	Classroom 100	Yes	W1	CMU	BLUE	None	0	0.02	Negative	None		Positive			no		
8350	1	B835001-1	1	100	Primary	Classroom 100	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative			N/A			no		
8350	1	B835001-1	1	100	Primary	Classroom 100 Closet	Yes	CEILING	TRANSITE	BLUE	None	0	0.03	Negative			N/A					
8350	1	B835001-1	1	100	Primary	Classroom 100	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.01	Negative			N/A					
8350	1	B835001-1	1	100	Primary	Classroom 100	Yes	W4	CMU	BLUE	None	0	0.04	Negative			Positive					
8350	1	B835001-1	1	100	Primary	Classroom 100	Yes	W3	CMU	BLUE	None	0	0.04	Negative			Positive					
8350	1	B835001-1	1	100	Primary	Classroom 100	Yes	W2	CMU	BLUE	None	0	0.04	Negative			Positive					
8350	1	B835001-1	1	100	Primary	Classroom 100	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.01	Negative			N/A					
8350	1	B835001-1	1	100	Primary	Classroom 100	Yes	PIPE JACKET	METAL	BLUE	None	0	2.6	Positive			N/A					
8350	1	B835001-1	1	100A	Administrative Office	Adjustment Room 101A	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative			Negative					
8350	1	B835001-1	1	100A	Administrative Office	Adjustment Room 101A	Yes	W1	CMU	BEIGE	None	0	0.05	Negative			Positive					
8350	1	B835001-1	1	100A	Administrative Office	Adjustment Room 101A	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.02	Negative			N/A					
8350	1	B835001-1	1	100A	Administrative Office	Adjustment Room 101A Closet	Yes	CEILING	TRANSITE	BLUE	None	0	0.05	Negative			N/A					
8350	1	B835001-1	1	100A	Administrative Office	Adjustment Room 101A	Yes	W1	CMU	BLUE	None	0	0	Negative			Positive					
8350	1	B835001-1	1	100A	Administrative Office	Adjustment Room 101A	Yes	W2	CMU	BEIGE	None	0	0.03	Negative			Positive					
8350	1	B835001-1	1	100A	Administrative Office	Adjustment Room 101A	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.03	Negative			N/A					
8350	1	B835001-1	1	100A	Administrative Office	Adjustment Room 101A	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.03	Negative			N/A					
8350	1	B835001-1	1	100A	Administrative Office	Adjustment Room 101A	Yes	W3	CMU	BEIGE	None	0	0.03	Negative			Positive					
8350	1	B835001-1	1	100A	Administrative Office	Adjustment Room 101A	Yes	UNIVENT	METAL	BEIGE	None	0	0.06	Negative			Negative					
8350	1	B835001-1	1	100A	Administrative Office	Adjustment Room 101A	Yes	W4	CMU	BEIGE	None	0	0.03	Negative			Positive					
8350	1	B835001-1	1	100A	Administrative Office	Adjustment Room 101A	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.02	Negative			N/A					
8350	1	B835001-1	1	100B	Administrative Office	Office 100B	Yes	W1	CMU	GREEN	None	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	100B	Administrative Office	Office 100B	Yes	W2	CMU	GREEN	None	0	0.05	Negative			Positive					
8350	1	B835001-1	1	100B	Administrative Office	Office 100B	Yes	W3	CMU	GREEN	None	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	100B	Administrative Office	Office 100B	Yes	CEILING	CONCRETE	WHITE	None	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	100B	Administrative Office	Office 100B	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	1.1	Positive			N/A					
8350	1	B835001-1	1	100B	Administrative Office	Office 100B	Yes	UNIVENT	METAL	TAN	None	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	101	Primary	Classroom 101	Yes	W1	CMU	GRAY	Flaking	5	< LOD	Negative	None		Positive	No	No	No	yes	
8350	1	B835001-1	1	101	Primary	Classroom 101	Yes	W2	CMU	GRAY	None	0	0.07	Negative			Positive					
8350	1	B835001-1	1	101	Primary	Classroom 101	Yes	W2	CMU	WHITE	None	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	101	Primary	Classroom 101	Yes	W3	CMU	WHITE	None	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	101	Primary	Classroom 101	Yes	W3	CMU	GRAY	None	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	101	Primary	Classroom 101	Yes	PIPE JACKET	METAL	GRAY	None	0	1.8	Positive			N/A					
8350	1	B835001-1	1	101	Primary	Classroom 101	Yes	PIPE JACKET	METAL	RED	None	0	3.5	Positive			N/A					
8350	1	B835001-1	1	101	Primary	Classroom 101	Yes	WALL	BRICK	BLACK	PEELING	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	101	Primary	Classroom 101	Yes	UNIVENT	METAL	TAN	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	101	Primary	Classroom 101	Yes	UNIVENT CABINE	METAL	TAN	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	101	Primary	Classroom 101	Yes	W4	CMU	GRAY	None	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	101	Primary	Classroom 101	Yes	W4	CMU	WHITE	None	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	101	Primary	Classroom 101	Yes	W1	CMU	WHITE	None	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	101	Primary	Classroom 101	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	101	Primary	Classroom 101	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	101	Primary	Classroom 101 Closet	Yes	CEILING	TRANSITE	WHITE	None	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	100C	Administrative Office	Building Engineer's Office 100C	No	W1	CMU	BEIGE	None	0	0.05	Negative			Positive					
8350	1	B835001-1	1	100C	Administrative Office	Building Engineer's Office 100C	No	W4	CMU	BEIGE	None	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	100C	Administrative Office	Building Engineer's Office 100C	No	W3</														

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	102	Primary	Classroom 102	Yes	WALL BASEBOAR	CMU	GREEN	None	0	0.01	Negative			N/A					
8350	1	B835001-1	1	102	Primary	Classroom 102	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.02	Negative			N/A					
8350	1	B835001-1	1	102	Primary	Classroom 102	Yes	PIPE COVER	METAL	GREEN	None	0	1.8	Positive			N/A					
8350	1	B835001-1	1	102	Primary	Classroom 102	Yes	UNIVENT	METAL	TAN	None	0	0.04	Negative			Negative					
8350	1	B835001-1	1	102	Primary	Classroom 102	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative			Negative					
8350	1	B835001-1	1	103	Primary	Classroom 103	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative			Negative					
8350	1	B835001-1	1	103	Primary	Classroom 103	Yes	W1	CMU	YELLOW	None	0	0.03	Negative			Positive					
8350	1	B835001-1	1	103	Primary	Classroom 103	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative			N/A					
8350	1	B835001-1	1	103	Primary	Classroom 103 Closet	Yes	CEILING	TRANSITE	YELLOW	None	0	0.03	Negative			N/A					
8350	1	B835001-1	1	103	Primary	Classroom 103	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative			N/A					
8350	1	B835001-1	1	103	Primary	Classroom 103	Yes	W4	CMU	YELLOW	None	0	0.02	Negative			Positive					
8350	1	B835001-1	1	103	Primary	Classroom 103	Yes	W3	CMU	YELLOW	None	0	0.04	Negative			Positive					
8350	1	B835001-1	1	103	Primary	Classroom 103	Yes	PIPE JACKET	METAL	YELLOW	None	0	4	Positive			N/A					
8350	1	B835001-1	1	103	Primary	Classroom 103	Yes	UNIVENT	METAL	TAN	None	0	0.04	Negative			Negative					
8350	1	B835001-1	1	103	Primary	Classroom 103	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative			N/A					
8350	1	B835001-1	1	103	Primary	Classroom 103	Yes	W2	CMU	YELLOW	None	0	0.06	Negative			Positive					
8350	1	B835001-1	1	101A	Administrative Office	Vice Principal's Office 101A	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A			Positive					Room was always occupied
8350	1	B835001-1	1	101A	Administrative Office	Vice Principal's Office 101A	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A			Positive					
8350	1	B835001-1	1	101A	Administrative Office	Vice Principal's Office 101A	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A			Positive					Room was always occupied
8350	1	B835001-1	1	101A	Administrative Office	Vice Principal's Office 101A	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A			Positive					Room was always occupied
8350	1	B835001-1	1	101A	Administrative Office	Vice Principal's Office 101A	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			Negative					Room was always occupied
8350	1	B835001-1	1	101A	Administrative Office	Vice Principal's Office 101A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Room was always occupied
8350	1	B835001-1	1	104	Primary	Classroom 104	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative			Negative					
8350	1	B835001-1	1	104	Primary	Classroom 104	Yes	W1	CMU	BLUE	None	0	0.02	Negative			Positive					
8350	1	B835001-1	1	104	Primary	Classroom 104	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative			N/A					
8350	1	B835001-1	1	104	Primary	Classroom 104 Closet	Yes	CEILING	TRANSITE	BLUE	None	0	0.03	Negative			N/A					
8350	1	B835001-1	1	104	Primary	Classroom 104	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative			N/A					
8350	1	B835001-1	1	104	Primary	Classroom 104	Yes	W2	CMU	BLUE	None	0	0.05	Negative			Positive					
8350	1	B835001-1	1	104	Primary	Classroom 104	Yes	W3	CMU	BLUE	None	0	0.06	Negative			Positive					
8350	1	B835001-1	1	104	Primary	Classroom 104	Yes	PIPE JACKET	METAL	BLUE	None	0	3.2	Positive			N/A					
8350	1	B835001-1	1	104	Primary	Classroom 104	Yes	UNIVENT	METAL	TAN	None	0	0.05	Negative			Negative					
8350	1	B835001-1	1	104	Primary	Classroom 104	Yes	W4	CMU	BLUE	None	0	0.06	Negative			Positive					
8350	1	B835001-1	1	104	Primary	Classroom 104	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative			N/A					
8350	1	B835001-1	1	101ACL	Storage	Vice Principal's Office - Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	101ACL	Storage	Vice Principal's Office - Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	101ACL	Storage	Vice Principal's Office - Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	101ACL	Storage	Vice Principal's Office - Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	101ACL	Storage	Vice Principal's Office - Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	101ACL	Storage	Vice Principal's Office - Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	101B	Storage	Storage 101B across from Building Engineer's Office	Yes	CEILING	CONCRETE	WHITE	None	0	0.03	Negative			Negative					
8350	1	B835001-1	1	101L	Administrative Office	Office 101L	Yes	W1	CMU	BEIGE	None	0	0.02	Negative			Positive					
8350	1	B835001-1	1	101L	Administrative Office	Office 101L	Yes	W2	CMU	BEIGE	None	0	0	Negative			Positive					
8350	1	B835001-1	1	101L	Administrative Office	Office 101L	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.03	Negative			N/A					
8350	1	B835001-1	1	101L	Administrative Office	Office 101L	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.02	Negative			N/A					
8350	1	B835001-1	1	101L	Administrative Office	Office 101L	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.1	Negative			N/A					
8350	1	B835001-1	1	101L	Administrative Office	Office 101L	Yes	W4	CMU	BEIGE	None	0	0.02	Negative			Positive					
8350	1	B835001-1	1	101L	Administrative Office	Office 101L	Yes	W3	CMU	BEIGE	None	0	0	Negative			Positive					
8350	1	B835001-1	1	101L	Administrative Office	Office 101L	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.03	Negative			N/A					
8350	1	B835001-1	1	101L	Administrative Office	Office 101L	Yes	UNIVENT	METAL	BEIGE	None	0	0.11	Negative			Negative					
8350	1	B835001-1	1	101LR	Restrooms, Staff - Male/Female	Office 101L Restroom	Yes	W1	CMU	WHITE	None	0	0.02	Negative			Positive					
8350	1	B835001-1	1	101LR	Restrooms, Staff - Male/Female	Office 101L Restroom	Yes	W2	CMU	WHITE	None	0	0.01	Negative			Positive					
8350	1	B835001-1	1	101LR	Restrooms, Staff - Male/Female	Office 101L Restroom	Yes	W3	CMU	WHITE	None	0	0.01	Negative			Positive					
8350	1	B835001-1	1	101LR	Restrooms, Staff - Male/Female	Office 101L Restroom	Yes	W4	CMU	WHITE	None	0	0.03	Negative			Positive					
8350	1	B835001-1	1	101LR	Restrooms, Staff - Male/Female	Office 101L Restroom	Yes	CEILING	CONCRETE	WHITE	None	0	0.03	Negative			Negative					
8350	1	B835001-1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative			Negative					
8350	1	B835001-1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	W1	CMU	BEIGE	None	0	0	Negative			Positive					
8350	1	B835001-1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	W2	CMU	BEIGE	None	0	0	Negative			Positive					
8350	1	B835001-1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	W3	CMU	BEIGE	None	0	0	Negative			Positive					
8350	1	B835001-1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	W4	CMU	BEIGE	None	0	0	Negative			Positive					
8350	1	B835001-1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	PIPE	METAL	BEIGE	None	0	0.22	Negative			Negative					
8350	1	B835001-1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	PIPE JACKET	METAL	BEIGE	None	0	0.04	Negative			N/A					
8350	1	B835001-1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	UNIVENT	METAL	BEIGE	None	0	0.1	Negative			Negative					
8350	1	B835001-1	1	105	Primary	Classroom 105	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative			Negative					
8350	1	B835001-1	1	105	Primary	Classroom 105	Yes	W1	CMU	BLUE	None	0	0.02	Negative			Positive					
8350	1	B835001-1	1	105	Primary	Classroom 105	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative			N/A					
8350	1	B835001-1	1	105	Primary	Classroom 105 Closet	Yes	CEILING	TRANSITE	BLUE	None	0	0	Negative			N/A					
8350	1	B835001-1	1	105	Primary	Classroom 105	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.01	Negative			N/A					
8350	1	B835001-1	1	105	Primary	Classroom 105	Yes	W4	CMU	BLUE	None	0	0.03	Negative			Positive					
8350	1	B835001-1	1	105	Primary	Classroom 105	Yes	W3	CMU	BLUE	None	0	0.03	Negative			Positive					
8350	1	B835001-1	1	105	Primary	Classroom 105	Yes	PIPE JACKET	METAL	BLUE	None	0	3.7	Positive			N/A					
8350	1	B835001-1	1	105	Primary	Classroom 105	Yes	UNIVENT	METAL	TAN	None	0	0.04	Negative			Negative					
8350	1	B835001-1	1	105	Primary	Classroom 105	Yes	W2	CMU	BLUE	None	0	0.06	Negative			Positive					

					School District of Philadelphia																					
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report											Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School											ULCS# 8350							
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
8350	1	B835001-1	1	105	Primary	Classroom 105	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative			N/A									
8350	1	B835001-1	1	106	Primary	Classroom 106	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative			Negative									
8350	1	B835001-1	1	106	Primary	Classroom 106	Yes	W1	CMU	GREEN	None	0	0.03	Negative			Positive									
8350	1	B835001-1	1	106	Primary	Classroom 106	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.01	Negative			N/A									
8350	1	B835001-1	1	106	Primary	Classroom 106	Yes	W1	CMU	BLUE	None	0	0.12	Negative			Positive									
8350	1	B835001-1	1	106	Primary	Classroom 106 Closet	Yes	CEILING	TRANSITE	GREEN	None	0	0.04	Negative			N/A									
8350	1	B835001-1	1	106	Primary	Classroom 106	Yes	W2	CMU	GREEN	None	0	0.03	Negative			Positive									
8350	1	B835001-1	1	106	Primary	Classroom 106	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.01	Negative			N/A									
8350	1	B835001-1	1	106	Primary	Classroom 106	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.07	Negative			N/A									
8350	1	B835001-1	1	106	Primary	Classroom 106	Yes	W4	CMU	GREEN	None	0	0.04	Negative			Positive									
8350	1	B835001-1	1	106	Primary	Classroom 106	Yes	PIPE JACKET	METAL	GREEN	None	0	2.5	Positive			N/A									
8350	1	B835001-1	1	106	Primary	Classroom 106	Yes	UNIVENT	METAL	TAN	None	0	0.14	Negative			Negative									
8350	1	B835001-1	1	106	Primary	Classroom 106	Yes	PIPE JACKET	METAL	BLUE	None	0	2.9	Positive			N/A									
8350	1	B835001-1	1	106	Primary	Classroom 106	Yes	W3	CMU	Green	Flaking	2	0.05	Negative	None		Positive	No	No	No	Yes					
8350	1	B835001-1	1	107	Primary	Classroom 107	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative			Negative									
8350	1	B835001-1	1	107	Primary	Classroom 107	Yes	W1	CMU	YELLOW	INTACT	0	0.07	Negative			Positive									
8350	1	B835001-1	1	107	Primary	Classroom 107	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	1	Positive			N/A									
8350	1	B835001-1	1	107	Primary	Classroom 107	Yes	W2	CMU	YELLOW	INTACT	0	0	Negative			Positive									
8350	1	B835001-1	1	107	Primary	Classroom 107 Closet	Yes	CEILING	TRANSITE	YELLOW	INTACT	0	0.01	Negative			N/A									
8350	1	B835001-1	1	107	Primary	Classroom 107	Yes	W3	CMU	YELLOW	INTACT	0	0.04	Negative			Positive									
8350	1	B835001-1	1	107	Primary	Classroom 107	Yes	UNIVENT	METAL	TAN	INTACT	0	0.28	Negative			Negative									
8350	1	B835001-1	1	107	Primary	Classroom 107	Yes	W4	CMU	YELLOW	INTACT	0	0.05	Negative			Positive									
8350	1	B835001-1	1	108	Primary	Classroom 108	Yes	W1	CMU	Blue	Flaking	7	0.02	Negative	None		Positive	No	No	No	Yes					
8350	1	B835001-1	1	108	Primary	Classroom 108	Yes	W2	CMU	BLUE	INTACT	0	0.02	Negative			Positive									
8350	1	B835001-1	1	108	Primary	Classroom 108	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.05	Negative			N/A									
8350	1	B835001-1	1	108	Primary	Classroom 108	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative			N/A									
8350	1	B835001-1	1	108	Primary	Classroom 108	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative			Negative									
8350	1	B835001-1	1	108	Primary	Classroom 108	Yes	W3	CMU	Blue	Flaking	3	0.13	Negative	None		Positive	No	No	No	Yes					
8350	1	B835001-1	1	108	Primary	Classroom 108	Yes	PIPE JACKET	METAL	BLUE	INTACT	0	2	Positive			N/A									
8350	1	B835001-1	1	108	Primary	Classroom 108	Yes	UNIVENT	METAL	TAN	INTACT	0	0.05	Negative			Negative									
8350	1	B835001-1	1	108	Primary	Classroom 108	Yes	W4	CMU	BLUE	INTACT	0	0.02	Negative			Positive									
8350	1	B835001-1	1	108	Primary	Classroom 108	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative			N/A									
8350	1	B835001-1	1	108	Primary	Classroom 108 Closet	Yes	CEILING	TRANSITE	BLUE	INTACT	0	0	Negative			N/A									
8350	1	B835001-1	1	109	Primary	Classroom 109 Closet	Yes	Ceiling	TRANSITE	White	INTACT	0	0.01	Negative			Negative									
8350	1	B835001-1	1	109	Primary	Classroom 109	Yes	W1	CMU	PURPLE	INTACT	0	0.04	Negative			Positive									
8350	1	B835001-1	1	109	Primary	Classroom 109	Yes	W2	CMU	PURPLE	INTACT	0	0.02	Negative			Positive									
8350	1	B835001-1	1	109	Primary	Classroom 109	Yes	W3	CMU	BEIGE	Flaking	2	0.06	Negative	None		Positive	No	No	No	yes					
8350	1	B835001-1	1	109	Primary	Classroom 109	Yes	W4	CMU	BEIGE	INTACT	0	0.01	Negative			Positive									
8350	1	B835001-1	1	109	Primary	Classroom 109	Yes	Ceiling	Concrete	White	Flaking	1	0	Negative	None		Negative	No	No	No	No					
8350	1	B835001-1	1	109	Primary	Classroom 109	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0	Negative			N/A									
8350	1	B835001-1	1	109	Primary	Classroom 109	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative			N/A									
8350	1	B835001-1	1	109	Primary	Classroom 109	Yes	PIPE JACKET	METAL	GREEN	INTACT	0	3.2	Positive			N/A									
8350	1	B835001-1	1	109	Primary	Classroom 109	Yes	UNIVENT	METAL	TAN	INTACT	0	0.1	Negative			Negative									
8350	1	B835001-1	1	109	Primary	Classroom 109	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative			N/A									
8350	1	B835001-1	1	110	Primary	Classroom 110	Yes	Ceiling	Concrete	WHITE	INTACT	0	0	Negative			Negative									
8350	1	B835001-1	1	110	Primary	Classroom 110	Yes	W1	CMU	PURPLE	INTACT	0	0.06	Negative			Positive									
8350	1	B835001-1	1	110	Primary	Classroom 110	Yes	W2	CMU	PURPLE	INTACT	0	0.05	Negative			Positive									
8350	1	B835001-1	1	110	Primary	Classroom 110	Yes	W3	CMU	PURPLE	INTACT	0	0.04	Negative			Positive									
8350																										

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	112	Primary	Classroom 112	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative			N/A					
8350	1	B835001-1	1	112	Primary	Classroom 112	Yes	PIPE COVER	METAL	BLUE	INTACT	0	0.3	Negative			N/A					
8350	1	B835001-1	1	112	Primary	Classroom 112	Yes	UNIVENT	METAL	TAN	INTACT	0	0.07	Negative			Negative					
8350	1	B835001-1	1	112	Primary	Classroom 112 Closet	Yes	CEILING	TRANSITE	BLUE	INTACT	0	0.03	Negative			N/A					
8350	1	B835001-1	1	113	Primary	Classroom 113	Yes	CEILING	TRANSITE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	113	Primary	Classroom 113	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	113	Primary	Classroom 113	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	113	Primary	Classroom 113	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	113	Primary	Classroom 113	Yes	W4	CMU	WHITE	INTACT	0	0.07	Negative			Positive					
8350	1	B835001-1	1	113	Primary	Classroom 113	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	113	Primary	Classroom 113	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	113	Primary	Classroom 113	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	113	Primary	Classroom 113	Yes	UNIVENT,	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	113	Primary	Classroom 113	Yes	UNIVENT,CABINE	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	113	Primary	Classroom 113	Yes	PIPE JACKET	METAL	BLUE	INTACT	0	< LOD	Negaive			N/A					
8350	1	B835001-1	1	113	Primary	Classroom 113	Yes	CONDUIT	METAL	BLUE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	114	Primary	Classroom 114	Yes	W1	CMU	GREEN	INTACT	0	0.05	Negative			Positive					
8350	1	B835001-1	1	114	Primary	Classroom 114	Yes	W2	CMU	GREEN	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	114	Primary	Classroom 114	Yes	W3	CMU	GREEN	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	114	Primary	Classroom 114	Yes	W4	CMU	GREEN	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	114	Primary	Classroom 114	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	114	Primary	Classroom 114	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	114	Primary	Classroom 114	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	114	Primary	Classroom 114	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative								
8350	1	B835001-1	1	114	Primary	Classroom 114	Yes	PIPE COVER	METAL	GREEN	INTACT	0	2.1	Positive			N/A					
8350	1	B835001-1	1	114	Primary	Classroom 114	Yes	Ceiling	Concrete	White	INTACT	0	0.07	Negative			Negative					
8350	1	B835001-1	1	115	Primary	Classroom 115	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.02	Negative			Negative					
8350	1	B835001-1	1	115	Primary	Classroom 115	Yes	W1	CMU	YELLOW	INTACT	0	0.05	Negative			Positive					
8350	1	B835001-1	1	115	Primary	Classroom 115	Yes	W2	CMU	YELLOW	INTACT	0	0.02	Negative			Positive					
8350	1	B835001-1	1	115	Primary	Classroom 115	Yes	W3	CMU	YELLOW	INTACT	0	0.8	Positive			Positive					
8350	1	B835001-1	1	115	Primary	Classroom 115	Yes	W4	CMU	YELLOW	INTACT	0	0.02	Negative			Positive					
8350	1	B835001-1	1	115	Primary	Classroom 115	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative			N/A					
8350	1	B835001-1	1	115	Primary	Classroom 115	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative			N/A					
8350	1	B835001-1	1	115	Primary	Classroom 115	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative			N/A					
8350	1	B835001-1	1	115	Primary	Classroom 115	Yes	UNIVENT	METAL	TAN	INTACT	0	0.06	Negative			Negative					
8350	1	B835001-1	1	115	Primary	Classroom 115	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	0.07	Negative			Negative					
8350	1	B835001-1	1	115	Primary	Classroom 115	Yes	PIPE COVER	METAL	YELLOW	INTACT	0	2.7	Positive			Negative					
8350	1	B835001-1	1	115	Primary	Classroom 115 Closet	Yes	CEILING	TRANSITE	YELLOW	INTACT	0	0.02	Negative			N/A					
8350	1	B835001-1	1	117	Primary	Classroom 117 Closet	Yes	CEILING	TRANSITE	WHITE	INTACT	0	0.07	Negative			N/A					
8350	1	B835001-1	1	117	Primary	Classroom 117	Yes	W1	CMU	GREEN	INTACT	0	0.05	Negative			Positive					
8350	1	B835001-1	1	117	Primary	Classroom 117	Yes	W1	CMU	YELLOW	Flaking	10	0.05	Negative	None		Positive	No	No	No	Yes	
8350	1	B835001-1	1	117	Primary	Classroom 117	Yes	W2	DRYWALL	GREEN	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	117	Primary	Classroom 117	Yes	W3	CMU	GREEN	INTACT	0	0.03	Negative			Positive					
8350	1	B835001-1	1	117	Primary	Classroom 117	Yes	W3	CMU	GREEN	INTACT	0	0.05	Negative			Positive					
8350	1	B835001-1	1	117	Primary	Classroom 117	Yes	W4	CMU	YELLOW	INTACT	0	0.06	Negative			Positive					
8350	1	B835001-1	1	117	Primary	Classroom 117	Yes	W4	CMU	GREEN	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	117	Primary	Classroom 117	Yes	UNIVENT	METAL	TAN	INTACT	0	0.09	Negative			Negative					
8350	1	B835001-1	1	117	Primary	Classroom 117	Yes	PIPE COVER	METAL	GREEN	INTACT	0	0.08	Negative			N/A					
8350	1	B835001-1	1	117	Primary	Classroom 117	Yes	CEILING	TRANSITE	GREEN	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	119	Primary	Classroom 119	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	1	119	Primary	Classroom 119	Yes	W1	CMU	YELLOW	INTACT	0	0.02	Negative			Positive					
8350	1	B835001-1	1	119	Primary	Classroom 119	Yes	W2	CMU	YELLOW	INTACT	0	0.02	Negative			Positive					
8350	1	B835001-1	1	119	Primary	Classroom 119	Yes	W3	CMU	YELLOW	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	119	Primary	Classroom 119	Yes	W4	CMU	YELLOW	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	119	Primary	Classroom 119	Yes	PIPE JACKET	METAL	GREEN	PEELING	0	0.11	Negative			N/A					
8350	1	B835001-1	1	119	Primary	Classroom 119	Yes	UNIVENT	METAL	TAN	PEELING	0	0.05	Negative			Negative					
8350	1	B835001-1	1	119	Primary	Classroom 119	Yes	UNIVENT CABINE	METAL	TAN	PEELING	0	0.09	Negative			Negative					
8350	1	B835001-1	1	119	Primary	Classroom 119	Yes	WALL BASEBOAR	Ceramic Tile	TAN	PEELING	0	1.6	Positive			N/A					
8350	1	B835001-1	1	119	Primary	Classroom 119 Closet	Yes	CEILING	TRANSITE	GREEN	INTACT	0	0	Negative			N/A					
8350	1	B835001-1	1	122	Primary	Classroom 122	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	1	122	Primary	Classroom 122	Yes	W1	CMU	BEIGE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	122	Primary	Classroom 122	Yes	W2	DRYWALL	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	122	Primary	Classroom 122	Yes	W3	CMU	BEIGE	INTACT	0	0.02	Negative			Positive					
8350	1	B835001-1	1	122	Primary	Classroom 122	Yes	W4	CMU	BLUE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	122	Primary	Classroom 122	Yes	PIPE COVER	METAL	BEIGE	INTACT	0	0.09	Negative			N/A					
8350	1	B835001-1	1	122	Primary	Classroom 122	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.12	Negative			Negative					
8350	1	B835001-1	1	122	Primary	Classroom 122	Yes	UNIVENT CABINE	METAL	BEIGE	INTACT	0	0.02	Negative			Negative					
8350	1	B835001-1	1	122	Primary	Classroom 122	Yes	DOOR CASING	METAL	BEIGE	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	1	122	Primary	Classroom 122 Closet	Yes	CEILING	TRANSITE	BEIGE	INTACT	0	0	Negative			N/A					
8350	1	B835001-1	1	122	Primary	Classroom 122	Yes	PIPE	METAL	BEIGE	INTACT	0	0.02	Negative			Negative					
8350	1	B835001-1	1	122	Primary	Classroom 122	Yes	PIPE	METAL	BLUE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	1	124	Primary	Classroom 124	Yes	DOOR CASING	METAL	WHITE	Flaking	5	0.15	Negative	None		Negative	No	No	No	No	
8350	1	B835001-1	1	124	Primary	Classroom 124	Yes	W1	CMU	WHITE	INTACT	0	0.01	Negative			Positive					
8350	1	B835001-1	1	124	Primary	Classroom 124	Yes	W2	DRYWALL	WHITE	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	124	Primary	Classroom 124	Yes	W4	DRYWALL	WHITE	Flaking	5	0	Negative	None		Negative	No	No	No	No	

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	124	Primary	Classroom 124	Yes	WALL BASEBOAR	WOOD	WHITE	INTACT	0	0	Negative			N/A					
8350	1	B835001-1	1	124	Primary	Classroom 124	Yes	WALL BASEBOAR	CMU	WHITE	PEELING	0	0.04	Negative			N/A					
8350	1	B835001-1	1	124	Primary	Classroom 124	Yes	PIPE COVER	METAL	WHITE	PEELING	0	0.05	Negative			N/A					
8350	1	B835001-1	1	124	Primary	Classroom 124	Yes	UNIVENT COVER	METAL	TAN	INTACT	0	0.16	Negative			Negative					
8350	1	B835001-1	1	124	Primary	Classroom 124	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	0.02	Negative			Negative					
8350	1	B835001-1	1	124	Primary	Classroom 124	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.01	Negative			Negative					
8350	1	B835001-1	1	124	Primary	Classroom 124 Closet	Yes	CEILING	TRANSITE	WHITE	INTACT	0	0.01	Negative			N/A					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	2.3	Positive			N/A					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	FLOOR	CONCRETE	GRAY	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	DOOR CASING	WOOD	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	STALL WALL	TRANSITE	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	DOOR PANEL	WOOD	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	Ceiling	Concrete	White	Flaking	10	<LOD	Negative	None		Negative	No	No	No	No	
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	CEILING	CONCRETE	WHITE	PEELING	0	0.02	Negative			Negative					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W2	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	4.1	Positive			N/A					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.35	Negative			Negative					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	STALL WALL	TRANSITE	BEIGE	INTACT	0	0	Negative			N/A					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	DOOR CASING	WOOD	BEIGE	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	DOOR	WOOD	BEIGE	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	DOOR	WOOD	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	DOOR CASING	WOOD	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	1.6	Positive			N/A					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	COLUMN	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	FLOOR	CONCRETE	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	Ceiling	Concrete	White	Flaking	15	< LOD	Negative	None		Negative	No	No	No	No	
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T Foyer	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T Foyer	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T Foyer	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T Foyer	Yes	DOOR CASING	WOOD	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T Foyer	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	W1	CMU	BEIGE	INTACT	0	0.09	Negative			Positive					
8350	1	B835001-1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	W2	CMU	BEIGE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	PIPE	METAL	BEIGE	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	SINK	CERAMIC	BEIGE	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	PIPE	METAL	BEIGE	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W2	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W1	CMU	RED	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W2	CMU	RED	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W3	CMU	RED	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W4	CMU	RED	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	WALL BASEBOAR	CMU	BLACK	INTACT	0	0	Negative			N/A					
8350	1	B835001-1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	WALL BASEBOAR	CMU	BLACK	INTACT	0	0	Negative			N/A					
8350	1	B835001-1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.07	Negative			Negative					
8350	1	B835001-1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	2.5	Positive			N/A					
8350	1	B835001-1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	W1	CMU	BEIGE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	W2	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	PIPE COVER	METAL	BEIGE	INTACT	0	2	Positive			N/A					
8350	1	B835001-1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.12	Negative			Negative					
8350	1	B835001-1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.9	Positive			N/A					
8350	1	B835001-1	1	111LRR	Restrooms, Staff - Male/Female	Teacher Lounge 111L - Restroom	Yes	W1	CMU	BEIGE	INTACT	0	0.06	Negative			Positive					
8350	1	B835001-1	1	111LRR	Restrooms, Staff - Male/Female	Teacher Lounge 111L - Restroom	Yes	W2	CMU	BEIGE	INTACT	0	0.02	Negative			Positive					
8350	1	B835001-1	1	111LRR	Restrooms, Staff - Male/Female	Teacher Lounge 111L - Restroom	Yes	W3	CMU	BEIGE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	111LRR	Restrooms, Staff - Male/Female	Teacher Lounge 111L - Restroom	Yes	W4	CMU	BEIGE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	111LRR	Restrooms, Staff - Male/Female	Teacher Lounge 111L - Restroom	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.07	Negative			Negative					
8350	1	B835001-1	1	114S	Storage	Book Storage 114S	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	114S	Storage	Book Storage 114S	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	114S	Storage	Book Storage 114S	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	114S	Storage	Book Storage 114S	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	114S	Storage	Book Storage 114S	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	114S	Storage	Book Storage 114S	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	116	ESE Full Time	Classroom 116	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	116	ESE Full Time	Classroom 116	Yes	W1	CMU	BLUE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	116	ESE Full Time	Classroom 116	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	116	ESE Full Time	Classroom 116	Yes	W3	DRYWALL	BLUE	PEELING	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	116	ESE Full Time	Classroom 116	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	116	ESE Full Time	Classroom 116	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	116	ESE Full Time	Classroom 116	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	116	ESE Full Time	Classroom 116	Yes	W3	CMU	BLUE	INTACT	0	0.08	Negative			Positive					
8350	1	B835001-1	1	116	ESE Full Time	Classroom 116	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	116B	Student Restrooms - Male/Female (Classroom)	Classroom 116 Restroom	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	116B	Student Restrooms - Male/Female (Classroom)	Classroom 116 Restroom	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	116B	Student Restrooms - Male/Female (Classroom)	Classroom 116 Restroom	Yes	W3	CMU	BLUE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	116B	Student Restrooms - Male/Female (Classroom)	Classroom 116 Restroom	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative			Positive					

								School District of Philadelphia														
								Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	116B	Student Restrooms - Male/Female (Classroom)	Classroom 116 Restroom	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	116B	Student Restrooms - Male/Female (Classroom)	Classroom 116 Restroom	Yes	CEILING	CONCRETE	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	116B	Student Restrooms - Male/Female (Classroom)	Classroom 116 Restroom	Yes	PIPE	METAL	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	117CL	Storage	Classroom 117 Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117CL	Storage	Classroom 117 Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117CL	Storage	Classroom 117 Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117CL	Storage	Classroom 117 Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117CL	Storage	Classroom 117 Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117CL	Storage	Classroom 117 Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117T	Student Restrooms - Male/Female (Classroom)	Classroom 117 Restroom	Yes	W1	CMU	YELLOW	INTACT	No Access	0.03	Negative			Positive					
8350	1	B835001-1	1	117T	Student Restrooms - Male/Female (Classroom)	Classroom 117 Restroom	Yes	W2	CMU	YELLOW	INTACT	No Access	0.05	Negative			Positive					
8350	1	B835001-1	1	117T	Student Restrooms - Male/Female (Classroom)	Classroom 117 Restroom	Yes	W3	CMU	YELLOW	INTACT	No Access	0.04	Negative			Positive					
8350	1	B835001-1	1	117T	Student Restrooms - Male/Female (Classroom)	Classroom 117 Restroom	Yes	W4	CMU	YELLOW	INTACT	No Access	0.07	Negative			Positive					
8350	1	B835001-1	1	117T	Student Restrooms - Male/Female (Classroom)	Classroom 117 Restroom	Yes	PIPE	METAL	YELLOW	INTACT	No Access	0.01	Negative			N/A					
8350	1	B835001-1	1	117T	Student Restrooms - Male/Female (Classroom)	Classroom 117 Restroom	Yes	DOOR CASING	METAL	TAN	INTACT	No Access	0.05	Negative			Negative					
8350	1	B835001-1	1	117T	Student Restrooms - Male/Female (Classroom)	Classroom 117 Restroom	Yes	CEILING	CONCRETE	WHITE	INTACT	No Access	0.04	Negative			Negative					
8350	1	B835001-1	1	117B	Storage	Classroom 117 Storage	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117B	Storage	Classroom 117 Storage	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117B	Storage	Classroom 117 Storage	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117B	Storage	Classroom 117 Storage	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117B	Storage	Classroom 117 Storage	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117B	Storage	Classroom 117 Storage	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117A	Storage	Stationery Storage 117A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117A	Storage	Stationery Storage 117A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117A	Storage	Stationery Storage 117A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117A	Storage	Stationery Storage 117A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117A	Storage	Stationery Storage 117A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117A	Storage	Stationery Storage 117A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	117	Circulation (Hallway)	Hallway near Classroom 17 Restroom	Yes	WALL	CMU	BLUE	INTACT	No Access	0.05	Negative			Positive					
8350	1	B835001-1	1	117	Circulation (Hallway)	Hallway near Classroom 17 Restroom	Yes	WALL	CMU	BLUE	INTACT	No Access	0	Negative			Positive					
8350	1	B835001-1	1	117	Circulation (Hallway)	Hallway near Classroom 17 Restroom	Yes	WALL	DRYWALL	BLUE	INTACT	No Access	0	Negative			Positive					
8350	1	B835001-1	1	117	Circulation (Hallway)	Hallway near Classroom 17 Restroom	Yes	CEILING	CONCRETE	WHITE	INTACT	No Access	0	Negative			Negative					
8350	1	B835001-1	1	117	Circulation (Hallway)	Hallway near Classroom 17 Restroom	Yes	DOOR CASING	METAL	TAN	INTACT	No Access	0	Negative			Negative					
8350	1	B835001-1	1	117	Circulation (Hallway)	Hallway near Classroom 17 Restroom	Yes	DOOR CASING	METAL	TAN	INTACT	No Access	0.04	Negative			Negative					
8350	1	B835001-1	1	117	Circulation (Hallway)	Hallway near Classroom 17 Restroom	Yes	SHELF	WOOD	BLUE	INTACT	No Access	0	Negative			N/A					
8350	1	B835001-1	1	118	ESE Full Time	Classroom 118	Yes	CEILING COLUMN	CONCRETE	WHITE	INTACT	No Access	< LOD	Negative			Negative					
8350	1	B835001-1	1	118	ESE Full Time	Classroom 118	Yes	W1	CMU	BEIGE	INTACT	No Access	< LOD	Negative			Positive					
8350	1	B835001-1	1	118	ESE Full Time	Classroom 118	Yes	W2	CMU	BEIGE	INTACT	No Access	< LOD	Negative			Positive					
8350	1	B835001-1	1	118	ESE Full Time	Classroom 118	Yes	W3	DRYWALL	BEIGE	INTACT	No Access	< LOD	Negative			Positive					
8350	1	B835001-1	1	118	ESE Full Time	Classroom 118	Yes	W4	CMU	BEIGE	INTACT	No Access	< LOD	Negative			Positive					
8350	1	B835001-1	1	118	ESE Full Time	Classroom 118	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	No Access	0.3	Negative			N/A					
8350	1	B835001-1	1	118	ESE Full Time	Classroom 118	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	1.3	Positive			N/A					
8350	1	B835001-1	1	118	ESE Full Time	Classroom 118	Yes	UNIVENT	METAL	TAN	INTACT	No Access	< LOD	Negative			Negative					
8350	1	B835001-1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	W1	DRYWALL	BEIGE	INTACT	No Access	< LOD	Negative			Positive					
8350	1	B835001-1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	W2	CMU	BEIGE	INTACT	No Access	< LOD	Negative			Positive					
8350	1	B835001-1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	W3	CMU	BEIGE	INTACT	No Access	< LOD	Negative			Positive					
8350	1	B835001-1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	W3	DRYWALL	BEIGE	INTACT	No Access	< LOD	Negative			Positive					
8350	1	B835001-1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	W2	DRYWALL	BEIGE	INTACT	No Access	< LOD	Negative			Positive					
8350	1	B835001-1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	W3	CMU	BEIGE	INTACT	No Access	0.06	Negative			Positive					
8350	1	B835001-1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	W4	CMU	BEIGE	INTACT	No Access	0.08	Negative			Positive					
8350	1	B835001-1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	1.2	Positive			N/A					
8350	1	B835001-1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	CEILING COLUMN	CONCRETE	BEIGE	INTACT	No Access	< LOD	Negative			Negative					
8350	1	B835001-1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	1.4	Positive			N/A					
8350	1	B835001-1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	UNIVENT	METAL	TAN	INTACT	No Access	< LOD	Negative			Negative					
8350	1	B835001-1	1	118B	Student Restrooms - Male/Female (Classroom)	Classroom 118 Restroom	Yes	W1	CMU	BEIGE	Flaking	2	0.04	Negative	None		Positive	No	No	No	Yes	
8350	1	B835001-1	1	118B	Student Restrooms - Male/Female (Classroom)	Classroom 118 Restroom	Yes	W2	CMU	BEIGE	Flaking	2	0.09	Negative	None		Positive	No	No	No	Yes	

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	118B	Student Restrooms - Male/Female (Classroom)	Classroom 118 Restroom	Yes	W3	CMU	BEIGE	Flaking	2	< LOD	Negative	None		Positive	No	No	No	Yes	
8350	1	B835001-1	1	118B	Student Restrooms - Male/Female (Classroom)	Classroom 118 Restroom	Yes	W4	CMU	BEIGE	Flaking	2	< LOD	Negative	None		Positive	No	No	No	Yes	
8350	1	B835001-1	1	118B	Student Restrooms - Male/Female (Classroom)	Classroom 118 Restroom	Yes	CEILING	CONCRETE	BEIGE	INTACT	0	0.04	Negative			Negative	No	No	No	Yes	
8350	1	B835001-1	1	118C	Storage	Classroom 118 Closet	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	118C	Storage	Classroom 118 Closet	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	118C	Storage	Classroom 118 Closet	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	119CL	Storage	Classroom 119 Closet	Yes	W4	CMU	GREEN	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	119CL	Storage	Classroom 119 Closet	Yes	W1	CMU	GREEN	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	119CL	Storage	Classroom 119 Closet	Yes	W2	CMU	GREEN	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	119CL	Storage	Classroom 119 Closet	Yes	DOOR CASING	METAL	TAN	PEELING	0	0.06	Negative			Negative					
8350	1	B835001-1	1	119CL	Storage	Classroom 119 Closet	Yes	DOOR CASING	METAL	TAN	PEELING	0	0.05	Negative			Negative					
8350	1	B835001-1	1	120	Primary	Classroom 120	Yes	CEILING COLUMN	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	120	Primary	Classroom 120	Yes	W1	CMU	BEIGE	INTACT	0	0.05	Negative			Positive					
8350	1	B835001-1	1	120	Primary	Classroom 120	Yes	W2	CMU	BEIGE	INTACT	0	0.07	Negative			Positive					
8350	1	B835001-1	1	120	Primary	Classroom 120	Yes	W3	CMU	BEIGE	INTACT	0	0.13	Negative			Positive					
8350	1	B835001-1	1	120	Primary	Classroom 120	Yes	W4	CMU	BEIGE	INTACT	0	0.05	Negative			Positive					
8350	1	B835001-1	1	120	Primary	Classroom 120	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	1.1	Positive			N/A					
8350	1	B835001-1	1	120	Primary	Classroom 120	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	120A	Administrative Office	Office 120A next to Classroom 120	Yes	W1	CMU	YELLOW	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	120A	Administrative Office	Office 120A next to Classroom 120	Yes	W2	CMU	YELLOW	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	120A	Administrative Office	Office 120A next to Classroom 120	Yes	W3	CMU	YELLOW	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	120A	Administrative Office	Office 120A next to Classroom 120	Yes	W4	CMU	YELLOW	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	120A	Administrative Office	Office 120A next to Classroom 120	Yes	PIPE	METAL	YELLOW	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	120B	Student Restrooms - Male/Female (Classroom)	Classroom 120 Restroom	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.08	Negative			Negative					
8350	1	B835001-1	1	120B	Student Restrooms - Male/Female (Classroom)	Classroom 120 Restroom	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	120B	Student Restrooms - Male/Female (Classroom)	Classroom 120 Restroom	Yes	W2	CMU	BEIGE	INTACT	0	0.08	Negative			Positive					
8350	1	B835001-1	1	120B	Student Restrooms - Male/Female (Classroom)	Classroom 120 Restroom	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	120B	Student Restrooms - Male/Female (Classroom)	Classroom 120 Restroom	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	120S	Storage	Storage 120S in Hallway	Yes	DOOR CASING	METAL	TAN	INTACT	0	0.07	Negative			Negative					
8350	1	B835001-1	1	120S	Storage	Storage 120S in Hallway	Yes	W1	CMU	WHITE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	120S	Storage	Storage 120S in Hallway	Yes	W4	CMU	WHITE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	120S	Storage	Storage 120S in Hallway	Yes	W2	CMU	WHITE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	W1	CMU	BLUE	Flaking	5	0.04	Negative	None		Positive	No	No	No	Yes	
8350	1	B835001-1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	W2	CMU	BLUE	INTACT	0	0.07	Negative			Positive					
8350	1	B835001-1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	W3	CMU	BLUE	INTACT	0	0.06	Negative			Positive					
8350	1	B835001-1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	W4	CMU	BLUE	INTACT	0	0.05	Negative			Positive					
8350	1	B835001-1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	FLOOR	CONCRETE	GREEN	INTACT	0	0.03	Negative	None		N/A					
8350	1	B835001-1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	UNIVENT	METAL	TAN	INTACT	0	0.08	Negative			Negative					
8350	1	B835001-1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	DOOR CASING	METAL	TAN	INTACT	0	0.11	Negative			Negative					
8350	1	B835001-1	1	122S	Storage	Storage 122S across from Restrooms	Yes	W1	CMU	WHITE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	122S	Storage	Storage 122S across from Restrooms	Yes	W2	CMU	WHITE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	122S	Storage	Storage 122S across from Restrooms	Yes	W3	CMU	WHITE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	122S	Storage	Storage 122S across from Restrooms	Yes	W4	CMU	WHITE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	122S	Storage	Storage 122S across from Restrooms	Yes	DOOR CASING	METAL	TAN	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	1	124A	Storage	Book Storage 124A	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	124A	Storage	Book Storage 124A	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	124A	Storage	Book Storage 124A	Yes	W3	CMU	Beige	Flaking	5	< LOD	Negative	None		Positive	No	No	No	Yes	
8350	1	B835001-1	1	124A	Storage	Book Storage 124A	Yes	W3	CMU	BEIGE	INTACT	0	1.1	Positive			Positive					
8350	1	B835001-1	1	124A	Storage	Book Storage 124A	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	124A	Storage	Book Storage 124A	Yes	W4	DRYWALL	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	124A	Storage	Book Storage 124A	Yes	DOOR	METAL	RED	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	124A	Storage	Book Storage 124A	Yes	DOOR CASING	METAL	RED	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	124A	Storage	Book Storage 124A	Yes	DOOR CENTER PANEL	METAL	RED	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	124A	Storage	Book Storage 124A	Yes	W4	CMU	Blue	Flaking	5	< LOD	Negative	None		Positive	No	No	No	Yes	
8350	1	B835001-1	1	124A	Storage	Book Storage 124A	Yes	DOOR CASING	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	124A	Storage	Book Storage 124A	Yes	W4	CMU	BLUE	INTACT	0	1.1	Positive			Positive					
8350	1	B835001-1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	W1	CMU	BEIGE	INTACT	0	0.03	Negative			Positive					
8350	1	B835001-1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	W2	CMU	BEIGE	INTACT	0	0.03	Negative			Positive					
8350	1	B835001-1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	W3	CMU	BEIGE	INTACT	0	0.02	Negative			Positive					

ULCS#ElementBldgElmt IDFloorSpace #								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	W4	CMU	BEIGE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	STALL WALL	TRANSITE	BROWN	INTACT	0	0	Negative			N/A					
8350	1	B835001-1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	STALL WALL	TRANSITE	BROWN	INTACT	0	0	Negative			N/A					
8350	1	B835001-1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	DOOR CASING	METAL	RED	INTACT	0	0.01	Negative			Negative					
8350	1	B835001-1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	DOOR	METAL	RED	INTACT	0	0.08	Negative			Negative					
8350	1	B835001-1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	PIPE COVER	METAL	BEIGE	INTACT	0	0.16	Negative			N/A					
8350	1	B835001-1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	UNIVENT	METAL	WHITE	INTACT	0	0.12	Negative			Negative					
8350	1	B835001-1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	PIPE	METAL	WHITE	INTACT	0	0.16	Negative			Negative					
8350	1	B835001-1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	VENT COVER	METAL	WHITE	INTACT	0	0.01	Negative			Negative					
8350	1	B835001-1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.01	Negative			Negative					
8350	1	B835001-1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	W1	CMU	BEIGE	INTACT	0	0.01	Negative			Positive					
8350	1	B835001-1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	W2	CMU	BEIGE	INTACT	0	0.02	Negative			Positive					
8350	1	B835001-1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	W3	CMU	BEIGE	INTACT	0	0.07	Negative			Positive					
8350	1	B835001-1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	W4	CMU	BEIGE	INTACT	0	0.1	Negative			Positive					
8350	1	B835001-1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	VENT COVER	METAL	BEIGE	INTACT	0	0.01	Negative			N/A					
8350	1	B835001-1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	DOOR CASING	METAL	TAN	INTACT	0	0.12	Negative			Negative					
8350	1	B835001-1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	PIPE COVER	METAL	BLACK	INTACT	0	0.1	Negative			N/A					
8350	1	B835001-1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	STALL WALL	TRANSITE	BROWN	INTACT	0	0	Negative			N/A					
8350	1	B835001-1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	DOOR	METAL	RED	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	DOOR CASING	METAL	RED	INTACT	0	0.01	Negative			Negative					
8350	1	B835001-1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	UNIVENT	METAL	WHITE	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	PIPE	METAL	WHITE	INTACT	0	0.25	Negative			Negative					
8350	1	B835001-1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	FLOOR	CONCRETE	GRAY	INTACT	0	0	Negative			N/A					
8350	1	B835001-1	1	138A	Storage	Gym Storage	Yes	W4	BRICK	WHITE	PEELING	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	138A	Storage	Gym Storage	Yes	W1	CMU	WHITE	PEELING	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	138A	Storage	Gym Storage	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	138A	Storage	Gym Storage	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	138A	Storage	Gym Storage	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	138A	Storage	Gym Storage	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	138A	Storage	Gym Storage	Yes	PIPE	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	138A	Storage	Gym Storage	Yes	CEILING	TRANSITE	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W1	CMU	WHITE	Flaking	12	0.05	Negative	None		Positive	No	No	No	Yes	
8350	1	B835001-1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W2	CMU	WHITE	Flaking	12	< LOD	Negative	None		Positive	No	No	No	Yes	
8350	1	B835001-1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W3	CMU	WHITE	Flaking	12	0.05	Negative	None		Positive	No	No	No	Yes	
8350	1	B835001-1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W4	CMU	WHITE	Flaking	12	0.08	Negative	None		Positive	No	No	No	Yes	
8350	1	B835001-1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W1	CMU	RED	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W2	CMU	RED	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W3	CMU	RED	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W4	CMU	RED	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	VENT COVER	METAL	BLACK	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	BACK BOARD SURF	PLASTER	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	UNIVENT COVER	METAL	RED	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	UNIVENT COVER	METAL	RED	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	PULL UP BAR SURF	WOOD	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	VENT COVER	METAL	RED	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	BULLETIN BOARD	CORK	RED	PEELING	0	< LOD	Negative			N/A					

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	W1	CMU	CLEAR	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	W2	CMU	CLEAR	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	W3	CMU	CLEAR	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	W4	CMU	CLEAR	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	FLOOR	CONCRETE	GRAY	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	2.2	Positive			N/A					
8350	1	B835001-1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	HAND DRYER	METAL	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	DOOR	WOOD	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	W1	CMU	CLEAR	INTACT	0	< LOD	Negative								
8350	1	B835001-1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	W2	CMU	Beige	INTACT	0	1.3	Positive								
8350	1	B835001-1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	FLOOR	CONCRETE	GRAY	INTACT	0	< LOD	Negative								
8350	1	B835001-1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	UNIVENT COVER	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	DOOR CASING	METAL	RED	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	W4	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139T PC	Pipe Chase	Boy's Restroom at Gym Pipe Chase	No	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	139T PC	Pipe Chase	Boy's Restroom at Gym Pipe Chase	No	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	139T PC	Pipe Chase	Boy's Restroom at Gym Pipe Chase	No	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	139T PC	Pipe Chase	Boy's Restroom at Gym Pipe Chase	No	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	139T PC	Pipe Chase	Boy's Restroom at Gym Pipe Chase	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	139T PC	Pipe Chase	Boy's Restroom at Gym Pipe Chase	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	139C	Service Closets	Custodial Storage in Boy's Restroom at Gym	No	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139C	Service Closets	Custodial Storage in Boy's Restroom at Gym	No	W3	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	FLOOR	CONCRETE	GRAY	INTACT	0	< LOD	Negative								
8350	1	B835001-1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	2.6	Positive			N/A					
8350	1	B835001-1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	DOOR	WOOD	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	DOOR CASING	WOOD	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	HAND DRYER	METAL	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	DOOR	WOOD	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	PIPE	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	DOOR	METAL	RED	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	DOOR CASING	METAL	RED	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	UNIVENT	METAL	BEIGE	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	DOOR	WOOD	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	DUCT	METAL	BEIGE	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350</																						

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	PIPE	METAL	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	151	Auditorium	Auditorium	Yes	W1	CMU	RED	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	151	Auditorium	Auditorium	Yes	W2	CMU	RED	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	151	Auditorium	Auditorium	Yes	W3	CMU	BEIGE	INTACT	0	0.05	Negative			Positive					
8350	1	B835001-1	1	151	Auditorium	Auditorium	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	DOOR	METAL	RED	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	DOOR CASING	METAL	RED	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	DOOR CENTER PANEL	METAL	RED	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	WALL BASEBOARD	CONCRETE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	WALL BASEBOARD	CONCRETE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	STAIRS RAILING	METAL	BLACK	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	UNIVENT COVER	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	151S	Stage	Stage	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	151S	Stage	Stage	Yes	W1	CMU	BEIGE	INTACT	0	0.03	Negative			Positive					
8350	1	B835001-1	1	151S	Stage	Stage	Yes	W4	CMU	BLACK	INTACT	0	1	Positive			Positive					
8350	1	B835001-1	1	152/153	Administrative Office	Music practice Room to the right of Stage	Yes	W1	CMU	GREEN	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	152/153	Administrative Office	Music practice Room to the right of Stage	Yes	W2	CMU	GREEN	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	152/153	Administrative Office	Music practice Room to the right of Stage	Yes	W3	CMU	GREEN	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	P.1	Principal/Directors Office	Principal's Office	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	P.1	Principal/Directors Office	Principal's Office	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0.05	Negative			N/A					
8350	1	B835001-1	1	P.1	Principal/Directors Office	Principal's Office	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0.03	Negative			N/A					
8350	1	B835001-1	1	P.1	Principal/Directors Office	Principal's Office	Yes	W4	CMU	BEIGE	INTACT	0	0.01	Negative			Positive					
8350	1	B835001-1	1	P.1	Principal/Directors Office	Principal's Office	Yes	UNIVENT	METAL	BLUE	INTACT	0	0.25	Negative								
8350	1	B835001-1	1	P.1	Principal/Directors Office	Principal's Office	Yes	W2	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	P.1	Principal/Directors Office	Principal's Office	Yes	W3	CMU	BEIGE	INTACT	0	0.23	Negative			Positive					
8350	1	B835001-1	1	P.1	Principal/Directors Office	Principal's Office	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0.03	Negative			N/A					
8350	1	B835001-1	1	P.1	Principal/Directors Office	Principal's Office	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0	Negative			N/A					
8350	1	B835001-1	1	P2	Storage	Principal's Office Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	P2	Storage	Principal's Office Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	P2	Storage	Principal's Office Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	P2	Storage	Principal's Office Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	P2	Storage	Principal's Office Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	P2	Storage	Principal's Office Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	P3	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	1	P3	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	W1	CMU	BEIGE	INTACT	0	0.15	Negative			Positive					
8350	1	B835001-1	1	P3	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	W2	CMU	BEIGE	INTACT	0	0.15	Negative			Positive					
8350	1	B835001-1	1	P3	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	W3	CMU	BEIGE	INTACT	0	0.05	Negative			Positive					
8350	1	B835001-1	1	P3	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	W4	CMU	BEIGE	INTACT	0	0.03	Negative			Positive					
8350	1	B835001-1	1	P3	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.22	Negative								
8350	1	B835001-1	1	2	Administrative Office	Main Office	Yes	W1	CMU	WHITE	INTACT	0	0.06	Negative			Positive					
8350	1	B835001-1	1	2	Administrative Office	Main Office	Yes	W2	CMU	WHITE	INTACT	0	0.03	Negative			Positive					
8350	1	B835001-1	1	2	Administrative Office	Main Office	Yes	W3	CMU	WHITE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	2	Administrative Office	Main Office	Yes	W4	CMU	WHITE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	2	Administrative Office	Main Office	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0.01	Negative			N/A					
8350	1	B835001-1	1	2	Administrative Office	Main Office	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0.03	Negative			N/A					
8350	1	B835001-1	1	2	Administrative Office	Main Office	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0.17	Negative			N/A					
8350	1	B835001-1	1	2	Administrative Office	Main Office	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0	Negative			N/A					
8350	1	B835001-1	1	2	Administrative Office	Main Office	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.07	Negative			Negative					
8350	1	B835001-1	1	2	Administrative Office	Main Office	Yes	UNIVENT	METAL	WHITE	INTACT	0	0.3	Negative			Negative					
8350	1	B835001-1	1	2CL1	Storage	Main Office Closet 1 to the right of entrance	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Only Office Staff have the keys
8350	1	B835001-1	1	2CL1	Storage	Main Office Closet 1 to the right of entrance	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Only Office Staff have the keys
8350	1	B835001-1	1	2CL1	Storage	Main Office Closet 1 to the right of entrance	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Only Office Staff have the keys
8350	1	B835001-1	1	2CL1	Storage	Main Office Closet 1 to the right of entrance	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Only Office Staff have the keys
8350	1	B835001-1	1	2CL1	Storage	Main Office Closet 1 to the right of entrance	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Only Office Staff have the keys
8350	1	B835001-1	1	2CL1	Storage	Main Office Closet 1 to the right of entrance	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Only Office Staff have the keys

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	2CL2	Storage	Main Office Closet to the left of doorway to Principal's Office from Main Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Only Office Staff have the keys
8350	1	B835001-1	1	2CL2	Storage	Main Office Closet to the left of doorway to Principal's Office from Main Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Only Office Staff have the keys
8350	1	B835001-1	1	2A	Administrative Office	Control Room next to Main Office	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Never Left the office during the inspection time frame
8350	1	B835001-1	1	2A	Administrative Office	Control Room next to Main Office	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Never Left the office during the inspection time frame
8350	1	B835001-1	1	2A	Administrative Office	Control Room next to Main Office	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Never Left the office during the inspection time frame
8350	1	B835001-1	1	2A	Administrative Office	Control Room next to Main Office	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Never Left the office during the inspection time frame
8350	1	B835001-1	1	2A	Administrative Office	Control Room next to Main Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Never Left the office during the inspection time frame
8350	1	B835001-1	1	2A	Administrative Office	Control Room next to Main Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Never Left the office during the inspection time frame
8350	1	B835001-1	1	3	Administrative Office	Vice Principal's Office - Room 3	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Never Left the office during the inspection time frame
8350	1	B835001-1	1	3	Administrative Office	Vice Principal's Office - Room 3	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Never Left the office during the inspection time frame
8350	1	B835001-1	1	3	Administrative Office	Vice Principal's Office - Room 3	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Never Left the office during the inspection time frame
8350	1	B835001-1	1	3	Administrative Office	Vice Principal's Office - Room 3	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Never Left the office during the inspection time frame
8350	1	B835001-1	1	3	Administrative Office	Vice Principal's Office - Room 3	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Never Left the office during the inspection time frame
8350	1	B835001-1	1	3	Administrative Office	Vice Principal's Office - Room 3	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Never Left the office during the inspection time frame
8350	1	B835001-1	1	4	Restrooms, Staff - Male	Men's Restroom to the right of Auditorium Entrance	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W4	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	UNIVENT	METAL	BEIGE	INTACT	0	2.4	Positive			Negative					
8350	1	B835001-1	1	5	Administrative Office	Counselor's Office 5	Yes	W1	CMU	BEIGE	INTACT	0	0.05	Negative			Positive					
8350	1	B835001-1	1	5	Administrative Office	Counselor's Office 5	Yes	W2	CMU	BEIGE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	5	Administrative Office	Counselor's Office 5	Yes	W3	CMU	BEIGE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	5	Administrative Office	Counselor's Office 5	Yes	W4	CMU	BEIGE	INTACT	0	0.05	Negative			Positive					
8350	1	B835001-1	1	5	Administrative Office	Counselor's Office 5	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.18	Negative			N/A					
8350	1	B835001-1	1	5	Administrative Office	Counselor's Office 5	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.16	Negative			N/A					
8350	1	B835001-1	1	5	Administrative Office	Counselor's Office 5	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.1	Negative			N/A					
8350	1	B835001-1	1	5	Administrative Office	Counselor's Office 5	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.04	Negative			N/A					
8350	1	B835001-1	1	5	Administrative Office	Counselor's Office 5	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.17	Negative			Negative					
8350	1	B835001-1	1	5.5T	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Only counselor has the key
8350	1	B835001-1	1	5.5T	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Only counselor has the key
8350	1	B835001-1	1	5.5T	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Only counselor has the key
8350	1	B835001-1	1	5.5T	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Only counselor has the key
8350	1	B835001-1	1	5.5T	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Only counselor has the key
8350	1	B835001-1	1	5.5T	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Only counselor has the key
8350	1	B835001-1	1	5W	Circulation (Hallway)	Waiting Room at Nurse's Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	1	Positive			N/A					
8350	1	B835001-1	1	5W	Circulation (Hallway)	Waiting Room at Nurse's Office	Yes	W4	CMU	BLACK	INTACT	0	0.03	Negative			Positive					
8350	1	B835001-1	1	5W	Circulation (Hallway)	Waiting Room at Nurse's Office	Yes	W3	CMU	BLACK	INTACT	0	0.06	Negative			Positive					
8350	1	B835001-1	1	5W	Circulation (Hallway)	Waiting Room at Nurse's Office	Yes	W2	CMU	BLACK	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	5W	Circulation (Hallway)	Waiting Room at Nurse's Office	Yes	W1	CMU	BLACK	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	6	Health Service Room	Nurse's Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative			N/A					
8350	1	B835001-1	1	6	Health Service Room	Nurse's Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative			N/A					

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	6	Health Service Room	Nurse's Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative			N/A					
8350	1	B835001-1	1	6	Health Service Room	Nurse's Office	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	6	Health Service Room	Nurse's Office	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	6	Health Service Room	Nurse's Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0	Negative			N/A					
8350	1	B835001-1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.07	Negative			Negative					
8350	1	B835001-1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	W2	CMU	BEIGE	INTACT	0	0.01	Negative			Positive					
8350	1	B835001-1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative			N/A					
8350	1	B835001-1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative			N/A					
8350	1	B835001-1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative			N/A					
8350	1	B835001-1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.04	Negative			N/A					
8350	1	B835001-1	1	6.5	Student Restrooms - Male/Female	Nurse's Office Restroom	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	1	6.5	Student Restrooms - Male/Female	Nurse's Office Restroom	Yes	W1	CMU	BEIGE	INTACT	0	0.08	Negative			Positive					
8350	1	B835001-1	1	6.5	Student Restrooms - Male/Female	Nurse's Office Restroom	Yes	W4	CMU	BEIGE	INTACT	0	0.05	Negative			Positive					
8350	1	B835001-1	1	6.5	Student Restrooms - Male/Female	Nurse's Office Restroom	Yes	W3	CMU	BEIGE	INTACT	0	0.02	Negative			Positive					
8350	1	B835001-1	1	6.5	Student Restrooms - Male/Female	Nurse's Office Restroom	Yes	W4	CMU	BEIGE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	6.5	Student Restrooms - Male/Female	Nurse's Office Restroom	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W1	CMU	YELLOW	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W2	CMU	YELLOW	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W3	CMU	YELLOW	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W4	CMU	YELLOW	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	SHELF	WOOD	YELLOW	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	SHELF SUPPORT	WOOD	YELLOW	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	CABINET	METAL	YELLOW	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	SINK	CERAMIC	YELLOW	INTACT	0	< LOD	Negaive			N/A					
8350	1	B835001-1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	FLOOR	CONCRETE	GRAY	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	Ceiling	CONCRETE	WHITE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W1	CMU	BLUE	INTACT	0	0.11	Negative			Positive					
8350	1	B835001-1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W3	CMU	BLUE	INTACT	0	0.06	Negative			Positive					
8350	1	B835001-1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W4	CMU	WHITE	INTACT	0	0.1	Negative			Positive					
8350	1	B835001-1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	WINDOW SILL	SLATE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W1	CMU	WHITE	INTACT	0	0.04	Negative								
8350	1	B835001-1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	1.4	Positive			N/A					
8350	1	B835001-1	1	9	Kitchen	Kitchen	Yes	Ceiling	CONCRETE	BEIGE	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	9	Kitchen	Kitchen	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	9	Kitchen	Kitchen	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	9	Kitchen	Kitchen	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	9	Kitchen	Kitchen	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	9	Kitchen	Kitchen	Yes	DOOR PANEL	METAL	RED	INTACT	0	1.1	Positive			N/A					
8350	1	B835001-1	1	9	Kitchen	Kitchen	Yes	DOOR PANEL	METAL	RED	INTACT	0	1.7	Positive			N/A					

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	9	Kitchen	Kitchen	Yes	WALL BASEBOAR	TRANSITE	GRAY	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	9	Kitchen	Kitchen	Yes	WALL BASEBOAR	TRANSITE	GRAY	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	1.4	Positive			N/A					
8350	1	B835001-1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	WINDOW CASING	METAL	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	10A	Administrative Office	Kitchen Office	Yes	Ceiling	CONCRETE	BEIGE	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	10A	Administrative Office	Kitchen Office	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	10A	Administrative Office	Kitchen Office	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	10A	Administrative Office	Kitchen Office	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	10A	Administrative Office	Kitchen Office	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	10A	Administrative Office	Kitchen Office	Yes	DOOR	METAL	RED	INTACT	0	0.8	Positive			N/A					
8350	1	B835001-1	1	10A	Administrative Office	Kitchen Office	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	10A	Administrative Office	Kitchen Office	Yes	COLUMN	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	11	Administrative Office	Gym Office	Yes	W1	CMU	BEIGE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	11	Administrative Office	Gym Office	Yes	W4	CMU	BEIGE	INTACT	0	0.03	Negative			Positive					
8350	1	B835001-1	1	11	Administrative Office	Gym Office	Yes	W3	CMU	BEIGE	INTACT	0	0.03	Negative			Positive					
8350	1	B835001-1	1	11	Administrative Office	Gym Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative			N/A					
8350	1	B835001-1	1	11	Administrative Office	Gym Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative			N/A					
8350	1	B835001-1	1	11	Administrative Office	Gym Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.06	Negative			N/A					
8350	1	B835001-1	1	11	Administrative Office	Gym Office	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.07	Negative			Negative					
8350	1	B835001-1	1	11	Administrative Office	Gym Office	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.06	Negative			Negative					
8350	1	B835001-1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	CEILING	CONCRETE	BEIGE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	W1	CMU	BEIGE	INTACT	0	0.03	Negative			Positive					
8350	1	B835001-1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	W2	CMU	BEIGE	INTACT	0	0.03	Negative			Positive					
8350	1	B835001-1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	W3	CMU	BEIGE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	W4	CMU	BEIGE	INTACT	0	0.05	Negative			Positive					
8350	1	B835001-1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative			N/A					
8350	1	B835001-1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative			N/A					
8350	1	B835001-1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative			N/A					
8350	1	B835001-1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative			N/A					
8350	1	B835001-1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	W1	CMU	BEIGE	INTACT	0	0.06	Negative			Positive					
8350	1	B835001-1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	W3	CMU	BEIGE	INTACT	0	0.05	Negative			Positive					
8350	1	B835001-1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.07	Negative			N/A					
8350	1	B835001-1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	WALL BASEBOAR	TRANSITE	TAN	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	WALL BASEBOAR	TRANSITE	TAN	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	UNIVENT	METAL	TAN	PEELING	0	< LOD	Negaive			Negative					
8350	1	B835001-1	1	13	Storage	Freezer Room by Kitchen	Yes	W1	BRICK	BEIGE	INTACT	0	0.2	Negative			Positive					
8350	1	B835001-1	1	13	Storage	Freezer Room by Kitchen	Yes	W2	CMU	BEIGE	INTACT	0	0.23	Negative			Positive					
8350	1	B835001-1	1	13	Storage	Freezer Room by Kitchen	Yes	W4	CMU	BEIGE	PEELING	0	0.26	Negative			Positive					
8350	1	B835001-1	1	13	Storage	Freezer Room by Kitchen	Yes	W3	CMU	BEIGE	PEELING	0	0.28	Negative			Positive					
8350	1	B835001-1	1	13	Storage	Freezer Room by Kitchen	Yes	FLOOR	CONCRETE	GRAY	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	13	Storage	Freezer Room by Kitchen	Yes	WALL BASEBOAR	CMU	GRAY	PEELING	0	0.3	Negative			N/A					
8350	1	B835001-1	1	13	Storage	Freezer Room by Kitchen	Yes	WALL BASEBOAR	CMU	GRAY	PEELING	0	0.3	Negative			N/A					
8350	1	B835001-1	1	13	Storage	Freezer Room by Kitchen	Yes	DOOR	METAL	BROWN	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	13	Storage	Freezer Room by Kitchen	Yes	DOOR CASING	METAL	BROWN	PEELING	0	< LOD	Negaive			Negative					
8350	1	B835001-1	1	13	Storage	Freezer Room by Kitchen	Yes	DOOR STOP	METAL	BROWN	INTACT	0	< LOD	Negaive			Negative					
8350	1	B835001-1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	W1	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	W4	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	W3	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	COLUMN	CONCRETE	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	COLUMN	CONCRETE	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	COLUMN	CONCRETE	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	CEILING	CONCRETE	WHITE	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	15	Administrative Office	Home & School Office along Auditorium Hallway	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Custodial Staff Didn't have the Key
8350	1	B835001-1	1	15	Administrative Office	Home & School Office along Auditorium Hallway	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Custodial Staff Didn't have the Key
8350	1	B835001-1	1	15	Administrative Office	Home & School Office along Auditorium Hallway	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Custodial Staff Didn't have the Key
8350	1	B835001-1	1	15	Administrative Office	Home & School Office along Auditorium Hallway	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Custodial Staff Didn't have the Key
8350	1	B835001-1	1	15	Administrative Office	Home & School Office along Auditorium Hallway	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Custodial Staff Didn't have the Key
8350	1	B835001-1	1	15	Administrative Office	Home & School Office along Auditorium Hallway	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Custodial Staff Didn't have the Key
8350	1	B835001-1	1	15R	Restrooms, Staff - Male/Female	Home & School Office Restroom	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Custodial Staff Didn't have the Key
8350	1	B835001-1	1	15R	Restrooms, Staff - Male/Female	Home & School Office Restroom	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Custodial Staff Didn't have the Key
8350	1	B835001-1	1	15R	Restrooms, Staff - Male/Female	Home & School Office Restroom	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Custodial Staff Didn't have the Key
8350	1	B835001-1	1	15R	Restrooms, Staff - Male/Female	Home & School Office Restroom	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	Custodial Staff Didn't have the Key
8350	1	B835001-1	1	15R	Restrooms, Staff - Male/Female	Home & School Office Restroom	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	Custodial Staff Didn't have the Key
8350	1	B835001-1	1	15R	Restrooms, Staff - Male/Female	Home & School Office Restroom	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Custodial Staff Didn't have the Key
8350	1	B835001-1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	Ceiling	CONCRETE	WHITE	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	DOOR	METAL	RED	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	DOOR CASING	METAL	RED	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	DOOR CENTER PANEL	METAL	RED	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	WALL BASEBOARD	TRANSITE	BLACK	PEELING	0	0.3	Positive			N/A					
8350	1	B835001-1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	WALL BASEBOARD	TRANSITE	BLACK	PEELING	0	1.4	Positive			N/A					
8350	1	B835001-1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	W1	CMU	BEIGE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	W2	CMU	BEIGE	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	W3	CMU	BEIGE	INTACT	0	0.02	Negative			Positive					
8350	1	B835001-1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	W4	CMU	BEIGE	INTACT	0	0.02	Negative			Positive					
8350	1	B835001-1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	UNIVENT	METAL	BROWN	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	DOOR	METAL	TAN	INTACT	0	0.14	Negative			N/A					
8350	1	B835001-1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	DOOR CASING	METAL	TAN	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	ELEC PANEL COVER	METAL	BEIGE	INTACT	0	0.09	Negative			N/A					
8350	1	B835001-1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	UNIVENT	METAL	BROWN	INTACT	0	0.01	Negative			Negative					
8350	1	B835001-1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	PIPE COVER	METAL	BEIGE	INTACT	0	0.06	Negative			N/A					
8350	1	B835001-1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	DOOR	METAL	RED	INTACT	0	0.11	Negative			N/A					
8350	1	B835001-1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	DOOR CENTER PANEL	METAL	RED	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	DOOR CASING	METAL	RED	INTACT	0	0.01	Negative			Negative					
8350	1	B835001-1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	CEILING	CONCRETE	BEIGE	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative			Positive					
8350	1	B835001-1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	W3	CMU	BEIGE	INTACT	0	0.02	Negative			Positive					
8350	1	B835001-1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0.01	Negative			N/A					
8350	1	B835001-1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0.02	Negative			N/A					
8350	1	B835001-1	1	H12																		

							School District of Philadelphia																		
							Lead Safe Certification Assessment Report										Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21								
					Inspection Company: Acer Associates		Spruance School										ULCS# 8350								
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes			
8350	1	B835001-1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative			N/A								
8350	1	B835001-1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative			N/A								
8350	1	B835001-1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative			N/A								
8350	1	B835001-1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative			N/A								
8350	1	B835001-1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	DOOR	METAL	RED	PEELING	0	< LOD	Negative			N/A								
8350	1	B835001-1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	DOOR CASING	METAL	RED	PEELING	0	< LOD	Negative			Negative								
8350	1	B835001-1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	UNIVENT	METAL	BEIGE	PEELING	0	< LOD	Negative			Negative								
8350	1	B835001-1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	DOOR	WOOD	BEIGE	INTACT	0	< LOD	Negative			N/A								
8350	1	B835001-1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	DUCT	METAL	BEIGE	PEELING	0	< LOD	Negative			Negative								
8350	1	B835001-1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative			Positive								
8350	1	B835001-1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Positive								
8350	1	B835001-1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative			Positive								
8350	1	B835001-1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	W4	CMU	WHITE	INTACT	0	< LOD	Negative			Positive								
8350	1	B835001-1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	PIPE	METAL	WHITE	INTACT	0	< LOD	Negative			Negative								
8350	1	B835001-1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative	Negative	#REF!	Positive	#REF!	#REF!	#REF!	#REF!				
8350	1	B835001-1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative	Negative	#REF!	Positive	#REF!	#REF!	#REF!	#REF!				
8350	1	B835001-1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative	Negative	#REF!	Positive	#REF!	#REF!	#REF!	#REF!				
8350	1	B835001-1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative	Negative	#REF!	Positive	#REF!	#REF!	#REF!	#REF!				
8350	1	B835001-1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	Ceiling	CONCRETE	WHITE	INTACT	0	< LOD	Negative	Negative	#REF!	Negative	#REF!	#REF!	#REF!	#REF!				
8350	1	B835001-1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative	Negative		N/A								
8350	1	B835001-1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative	Negative		N/A								
8350	1	B835001-1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.04	Negative	Negative		N/A								
8350	1	B835001-1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	PIPE	METAL	WHITE	INTACT	0	0.12	Negative	Negative		Negative								
8350	1	B835001-1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	DOOR	METAL	GREEN	INTACT	0	0.03	Negative	Negative		N/A								
8350	1	B835001-1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	DOOR CENTER P	METAL	GREEN	INTACT	0	0.01	Negative	Negative		Negative								
8350	1	B835001-1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	DOOR CASING	METAL	GREEN	INTACT	0	0	Negative	Negative		Negative								
8350	1	B835001-1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.08	Negative	Negative		Negative								
8350	1	B835001-1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative			Positive								
8350	1	B835001-1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	W2	CMU	BEIGE	INTACT	0	0	Negative			Positive								
8350	1	B835001-1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative			Positive								
8350	1	B835001-1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative			Positive								
8350	1	B835001-1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative			Negative								
8350	1	B835001-1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative			N/A								
8350	1	B835001-1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative			N/A								
8350	1	B835001-1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	PIPE	METAL	WHITE	INTACT	0	0.12	Negative			Negative								
8350	1	B835001-1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	DOOR	METAL	GREEN	INTACT	0	0.03	Negative			N/A								
8350	1	B835001-1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	DOOR CENTER P	METAL	GREEN	INTACT	0	0.01	Negative			Negative								
8350	1	B835001-1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	DOOR CASING	METAL	GREEN	INTACT	0	0	Negative			Negative								
8350	1	B835001-1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.08	Negative			Negative								
8350	1	B835001-1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative			Positive								
8350	1	B835001-1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	W2	CMU	BEIGE	INTACT	0	0	Negative			Positive								
8350	1	B835001-1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative			Positive								
8350	1	B835001-1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative			Positive								
8350	1	B835001-1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative			Negative								
8350	1	B835001-1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative			N/A								
8350	1	B835001-1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative			N/A								
8350	1	B835001-1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.04	Negative			N/A								
8350	1	B835001-1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	PIPE	METAL	WHITE	INTACT	0	0.12	Negative			Negative								
8350	1	B835001-1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	DOOR	METAL	GREEN	INTACT	0	0.03	Negative			N/A								
8350	1	B835001-1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	DOOR CENTER P	METAL	GREEN	INTACT	0	0.01	Negative			Negative								
8350	1	B835001-1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	DOOR CASING	METAL	GREEN	INTACT	0	0	Negative			Negative								
8350	1	B835001-1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.08	Negative			Negative								
8350	1	B835001-1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	W1	CMU	YELLOW	INTACT	0	0	Negative			Positive								
8350	1	B835001-1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	W3	CMU	YELLOW	INTACT	0	0.03	Negative			Positive								
8350	1	B835001-1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	W2	CMU	YELLOW	INTACT	0	0	Negative			Positive								
8350	1	B835001-1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative			Positive								
8350	1	B835001-1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.05	Negative			N/A								
8350	1	B835001-1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative			N/A								
8350	1	B835001-1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.05	Negative			N/A								
8350	1	B835001-1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.04	Negative			N/A								
8350	1	B835001-1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	UNIVENT	METAL	BROWN	INTACT	0	0.03	Negative			Negative								
8350	1	B835001-1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.09	Negative			Negative								
8350	1	B835001-1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative			Positive								
8350	1	B835001-1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	W2	CMU	BEIGE	INTACT	0	0	Negative			Positive								
8350	1	B835001-1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative			Positive								
8350	1	B835001-1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative			N/A								
8350	1	B835001-1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative			N/A								
8350	1	B835001-1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.05	Negative			N/A								
8350	1	B835001-1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	DOOR CASING	METAL	BROWN	INTACT	0	0.11	Negative			Negative								
8350	1	B835001-1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	UNIVENT	METAL	BROWN	INTACT	0	0.02	Negative			Negative								
8350	1	B835001-1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	PIPE JACKET	METAL	BEIGE	INTACT	0	3.8	Positive			N/A								
8350	1	B835001-1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	ELEC PANEL	METAL	BEIGE	INTACT	0	0.23	Negative			N/A								
8350	1	B835001-1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	CEILING	CONCRETE	BEIGE	INTACT	0	0	Negative			Negative								
8350	1	B835001-1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive								

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	CEILING COLUMN	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	W1	TRANSITE	BLACK	INTACT	0	0.04	Negative			Positive					
8350	1	B835001-1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	W2	TRANSITE	BLACK	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	1.1	Positive			Positive					
8350	1	B835001-1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S11	Stairs	Stairwell at Gym	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	S11	Stairs	Stairwell at Gym	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	S11	Stairs	Stairwell at Gym	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	#REF!	#REF!	#REF!	#REF!	
8350	1	B835001-1	1	S11	Stairs	Stairwell at Gym	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	S11	Stairs	Stairwell at Gym	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	S11	Stairs	Stairwell at Gym	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive	#REF!	#REF!	#REF!	#REF!	
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive	#REF!	#REF!	#REF!	#REF!	
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0.12	Negative			N/A					
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0.11	Negative			N/A					
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	HALF WALL	TRANSITE	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W4	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W2	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	STAIRS STRINGER	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	WALL BASEBOARD	CONCRETE	BLACK	INTACT	0	0.08	Negative			N/A					
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	STAIRS RISER	CONCRETE	BLACK	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	STAIRS RISER	CONCRETE	BLACK	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	1	Positive			N/A					
8350	1	B835001-1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	W1	BRICK	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	W3	CMU	BEIGE	INTACT	0	1	Positive			Positive					
8350	1	B835001-1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	WALL BASEBOARD	CONCRETE	TAN	PEELING	0	0.04	Negative			N/A					
8350	1	B835001-1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	WALL BASEBOARD	CONCRETE	TAN	PEELING	0	1.1	Positive			N/A					
8350	1	B835001-1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	DOOR	METAL	TAN	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	DOOR CASING	METAL	TAN	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	DOOR CASING	METAL	TAN	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	DOOR	METAL	TAN	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	DOOR	METAL	TAN	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	DOOR CASING	METAL	TAN	PEELING	0	< LOD	Negative			Negative					

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	CEILING	CONCRETE	WHITE	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0		1.1	Positive		N/A					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	DOOR	METAL	TAN	PEELING	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	DOOR CASING	METAL	TAN	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	PIPE JACKET	METAL	BEIGE	INTACT	0		2.2	Positive		N/A					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	DOOR	METAL	GREEN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	DOOR CASING	METAL	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	DOOR	WOOD	BROWN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	DOOR CASING	METAL	BROWN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	STAIRS RISER	CONCRETE	BLACK	INTACT	0		0.05	Negative		Negative					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	STAIRS STRINGER	CONCRETE	BLACK	INTACT	0		0.09	Negative		Negative					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	STAIRS HALFVAL	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	STAIRS HALFVAL	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0		0.07	Negative		N/A					
8350	1	B835001-1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	STAIRS RISER	CONCRETE	BLACK	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	STAIRS STRINGER	TRANSITE	BLACK	INTACT	0		0.13	Negative		Negative					
8350	1	B835001-1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	STAIR HALFWALL	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	DOOR	METAL	TAN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	CEILING	CONCRETE	WHITE	PEELING	0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	W1	CMU	BEIGE		0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	W2	CMU	BEIGE		0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	W3	CMU	BEIGE		0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	W4	CMU	BEIGE		0	< LOD	Negative			Positive					
8350	1	B835001-1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	DOOR	METAL	RED		0	< LOD	Negative			N/A					
8350	1	B835001-1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	DOOR CENTER P	METAL	RED		0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	DOOR CASING	METAL	RED		0	< LOD	Negative			Negative					
8350	1	B835001-1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	UNIVENT COVER	METAL	BROWN		0	< LOD	Negative			Negative					
8350	1	B835001-1	2	200	Primary	Classroom 200	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	200	Primary	Classroom 200	Yes	UNIVENT	METAL	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	200	Primary	Classroom 200	Yes	W1	CMU	ORANGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	200	Primary	Classroom 200	Yes	W1	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	200	Primary	Classroom 200	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	200	Primary	Classroom 200	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	200	Primary	Classroom 200	Yes	W2	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	200	Primary	Classroom 200	Yes	W3	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	200	Primary																	

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	2	201S	Primary	Classroom 201S	Yes	W1	CMU	GRAY	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	201S	Primary	Classroom 201S	Yes	W2	CMU	GRAY	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	201S	Primary	Classroom 201S	Yes	W4	CMU	GRAY	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	201S	Primary	Classroom 201S	Yes	W3	CMU	GRAY	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	201S	Primary	Classroom 201S	Yes	COLUMN	CONCRETE	BLUE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	202	Primary	Classroom 202	Yes	CEILING	CONCRETE	WHITE	INTACT	0	1.2	Positive			Negative					
8350	1	B835001-1	2	202	Primary	Classroom 202	Yes	W1	CMU	GREEN	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	202	Primary	Classroom 202	Yes	W2	CMU	GREEN	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	2	202	Primary	Classroom 202	Yes	W3	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	202	Primary	Classroom 202	Yes	W4	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	202	Primary	Classroom 202	Yes	CHALKBOARD FR	WOOD	CLEAR	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	202	Primary	Classroom 202	Yes	DOOR CASING	WOOD	CLEAR	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	202	Primary	Classroom 202	Yes	DOOR	WOOD	CLEAR	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	202	Primary	Classroom 202	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	202	Primary	Classroom 202	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	202	Primary	Classroom 202	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative			N/A					
8350	1	B835001-1	2	202	Primary	Classroom 202	Yes	CHALKBOARD FR	TRANSITE	CLEAR	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	202	Primary	Classroom 202	Yes	UNIVENT	METAL	INTACT	Flaking	0	< LOD	Negative	None		Negative					
8350	1	B835001-1	2	202	Primary	Classroom 202 Closet	Yes	CEILING	TRANSITE	GREEN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	203	Primary	Classroom 203	Yes	W1	CMU	BLUE	INTACT	0	0.08	Negative			Negative					
8350	1	B835001-1	2	203	Primary	Classroom 203	Yes	W2	CMU	BLUE	INTACT	0	1	Positive			Negative					
8350	1	B835001-1	2	203	Primary	Classroom 203	Yes	W4 BASEBOARD	TRANSITE	BLACK	INTACT	0	1	Positive			N/A					
8350	1	B835001-1	2	203	Primary	Classroom 203	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	203	Primary	Classroom 203	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	203	Storage	Classroom 203	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	204	Primary	Classroom 204	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	204	Primary	Classroom 204	Yes	W1	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	204	Primary	Classroom 204	Yes	W2	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	204	Primary	Classroom 204	Yes	W3	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	204	Primary	Classroom 204	Yes	W4	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	204	Primary	Classroom 204	Yes	W4	CMU	DARK GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	204	Primary	Classroom 204	Yes	W3	CMU	DARK GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	204	Primary	Classroom 204	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	204	Primary	Classroom 204	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	204	Primary	Classroom 204	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	204	Primary	Classroom 204	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	204	Primary	Classroom 204	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	204	Primary	Classroom 204	Yes	CHALKBOARD FR	WOOD	CLEAR	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	204	Primary	Classroom 204	Yes	DOOR CASING	WOOD	CLEAR	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	204	Primary	Classroom 204 Closet	Yes	CEILING	TRANSITE	GREEN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	205	Primary	Classroom 205	Yes	W1	CMU	YELLOW	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	205	Primary	Classroom 205	Yes	W2	CMU	YELLOW	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	205	Primary	Classroom 205	Yes	W3	CMU	YELLOW	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	205	Primary	Classroom 205	Yes	W4	CMU	YELLOW	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	2	205	Primary	Classroom 205	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	205	Primary	Classroom 205	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	205	Primary	Classroom 205	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative								

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	2	207	Primary	Classroom 207	Yes	CEILING	CONCRETE	WHITE	INTACT	0	1	Positive			Negative					
8350	1	B835001-1	2	207CL	Storage	Classroom 207 Closet	Yes	CEILING	TRANSITE	BLUE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	208	Primary	Classroom 208	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	208	Primary	Classroom 208	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	208	Primary	Classroom 208	Yes	W3	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	208	Primary	Classroom 208	Yes	W4	CMU	BLUE	INTACT	0	0.06	Negative			Negative					
8350	1	B835001-1	2	208	Primary	Classroom 208	Yes	W4	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	208	Primary	Classroom 208	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	208	Primary	Classroom 208	Yes	W1	CMU	GREEN	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	208	Primary	Classroom 208	Yes	W2	CMU	GREEN	INTACT	0	0.09	Negative			Negative					
8350	1	B835001-1	2	208	Primary	Classroom 208	Yes	W3	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	208	Primary	Classroom 208	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	208	Primary	Classroom 208	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	208	Primary	Classroom 208	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	208	Primary	Classroom 208	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	208	Primary	Classroom 208	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	208CL	Storage	Classroom 208 Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	208CL	Storage	Classroom 208 Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	208CL	Storage	Classroom 208 Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	208CL	Storage	Classroom 208 Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	208CL	Storage	Classroom 208 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
8350	1	B835001-1	2	208CL	Storage	Classroom 208 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
8350	1	B835001-1	2	209	Primary	Classroom 209	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	209	Primary	Classroom 209	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	209	Primary	Classroom 209	Yes	W3	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	209	Primary	Classroom 209	Yes	W3	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	209	Primary	Classroom 209	Yes	W4	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	209	Primary	Classroom 209	Yes	W1	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	209	Primary	Classroom 209	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	209	Primary	Classroom 209	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.04	Negative			N/A					
8350	1	B835001-1	2	209	Primary	Classroom 209	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	209CL	Storage	Classroom 209 Closet	Yes	CEILING	TRANSITE	GREEN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	209CL	Storage	Classroom 209	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	209CL	Storage	Classroom 209	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	210	Primary	Classroom 210	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	210	Primary	Classroom 210	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	210	Primary	Classroom 210	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	210	Primary	Classroom 210	Yes	CHALKBOARD FR	WOOD	CLEAR	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	210	Primary	Classroom 210	Yes	DOOR CASING	WOOD	CLEAR	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	210	Primary	Classroom 210	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	210	Primary	Classroom 210	Yes	W3	CMU	BLUE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	210	Primary	Classroom 210	Yes	COLUMN	CONCRETE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	210	Primary	Classroom 210	Yes	UNIVENT	METAL	BLACK	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	210	Primary	Classroom 210	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	210	Primary	Classroom 210	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	210	Primary	Classroom 210	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	210	Primary	Classroom 210 Closet	Yes	CEILING	TRANSITE	GREEN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	210	Primary	Classroom 210	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	211	Primary	Classroom 211	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	211	Primary	Classroom 211	Yes	W1	CMU	BLUE	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	2	211	Primary	Classroom 211	Yes	DOOR CASING	PLASTER	CLEAR	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	211	Primary	Classroom 211	Yes	DOOR	WOOD	CLEAR	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	211	Primary	Classroom 211	Yes	CHALKBOARD FR	WOOD	CLEAR	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	211	Primary	Classroom 211	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	211	Primary	Classroom 211	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	211	Primary	Classroom 211	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	211	Primary	Classroom 211 Closet	Yes	CEILING	TRANSITE	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	211	Primary	Classroom 211	Yes	W2	CMU	BLUE	INTACT	0	0.06	Negative			Negative					
8350	1	B835001-1	2	211	Primary	Classroom 211	Yes	CHALKBOARD FR	WOOD	CLEAR	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	211	Primary	Classroom 211	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.04	Negative			N/A					
8350	1	B835001-1	2	211	Primary	Classroom 211	Yes	W3	CMU	GREEN	INTACT	0	0.07	Negative			Negative					
8350	1	B835001-1	2	211	Primary	Classroom 211	Yes	COLUMN	CONCRETE	BLUE	INTACT	0	0.06	Negative			N/A					
8350	1	B835001-1	2	211	Primary	Classroom 211	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	211S	Administrative Office	Office 211S next to Classroom 211	Yes	CEILING	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	211S	Administrative Office	Office 211S next to Classroom 211	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	211S	Administrative Office	Office 211S next to Classroom 211	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	211S	Administrative Office	Office 211S next to Classroom 211	Yes	W4	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	211S	Administrative Office	Office 211S next to Classroom 211	Yes	CHALKBOARD FR	METAL	PURPLE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	211S	Administrative Office	Office 211S next to Classroom 211	Yes	LOCKER	METAL	PURPLE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	CEILING	CONCRETE	WHITE	INTACT	0	1.1	Positive			Negative					
8350	1	B835001-1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	DOOR CASING	WOOD	BEIGE	INTACT	0	< LOD	Negative			Negative					

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	1.9	Positive			N/A					
8350	1	B835001-1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	DOOR PANEL	WOOD	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	W3	CMU	BEIGE	Flaking	70	< LOD	Negative	Floor	10	Negative	No	No	No	No	
8350	1	B835001-1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	UNIVENT COVER	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	211TPC	Pipe Chase	Girl's Restroom Pipe Chase	No	W1	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	211TPC	Pipe Chase	Girl's Restroom Pipe Chase	No	W2	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	211TPC	Pipe Chase	Girl's Restroom Pipe Chase	No	W3	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	211TPC	Pipe Chase	Girl's Restroom Pipe Chase	No	W4	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	211TPC	Pipe Chase	Girl's Restroom Pipe Chase	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	211TPC	Pipe Chase	Girl's Restroom Pipe Chase	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
8350	1	B835001-1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	UNIVENT COVER	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	FLOOR	CONCRETE	GRAY	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	2.3	Positive			N/A					
8350	1	B835001-1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	DOOR	WOOD	BROWN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	DOOR CASING	WOOD	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	STALL WALL	TRANSITE	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	COLUMN	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	212A	Storage	Custodial Closet near Stairwell C	No	W1	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	212A	Storage	Custodial Closet near Stairwell C	No	W2	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	212A	Storage	Custodial Closet near Stairwell C	No	W3	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	212A	Storage	Custodial Closet near Stairwell C	No	W4	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	212A	Storage	Custodial Closet near Stairwell C	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	212A	Storage	Custodial Closet near Stairwell C	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
8350	1	B835001-1	2	212TPC	Pipe Chase	Boy's Restroom Pipe Chase	No	W1	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	212TPC	Pipe Chase	Boy's Restroom Pipe Chase	No	W2	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	212TPC	Pipe Chase	Boy's Restroom Pipe Chase	No	W3	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	212TPC	Pipe Chase	Boy's Restroom Pipe Chase	No	W4	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	212TPC	Pipe Chase	Boy's Restroom Pipe Chase	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	212TPC	Pipe Chase	Boy's Restroom Pipe Chase	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
8350	1	B835001-1	2	212	Primary	Classroom 212	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	212	Primary	Classroom 212	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	212	Primary	Classroom 212	Yes	W1	CMU	YELLOW	INTACT	0	0.08	Negative			Negative					
8350	1	B835001-1	2	212	Primary	Classroom 212	Yes	CEILING	TRANSITE	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	212	Primary	Classroom 212	Yes	W2	DRYWALL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	212	Primary	Classroom 212	Yes	W3	CMU	BLUE	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	2	212	Primary	Classroom 212	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	212	Primary	Classroom 212	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	212	Primary	Classroom 212	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	212	Primary	Classroom 212	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	212	Primary	Classroom 212	Yes	UNIVENT	METAL	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	212	Primary	Classroom 212	Yes	UNIVENT CABINE	METAL	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	207LL	Primary	Classroom 213A	Yes	W1	CMU	GREEN	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	207LL	Primary	Classroom 213A	Yes	W4	DRYWALL	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	207LL	Primary	Classroom 213A	Yes	W3	CMU	GREEN	INTACT	0	0.09	Negative			Negative					
8350	1	B835001-1	2	207LL	Primary	Classroom 213A	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	207LL	Primary	Classroom 213A	Yes	W2	CMU	YELLOW	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	207LL	Primary	Classroom 213A	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	207N	Storage	Library Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
8350	1	B835001-1	2	207N	Storage	Library Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
8350	1	B835001-1	2	207N	Storage	Library Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
8350	1	B835001-1	2	207N	Storage	Library Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
8350	1	B835001-1	2	207N	Storage	Library Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
8350	1	B835001-1	2	207N	Storage	Library Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
8350	1	B835001-1	2	207L	IMC (Library)	Library	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	207L	IMC (Library)	Library	Yes	W1	CMU	BLUE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	207L	IMC (Library)	Library	Yes	W2	DRYWALL	WHITE	INTACT	0	< LOD	Negative			Negative					

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	2	207L	IMC (Library)	Library	Yes	W3	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	207L	IMC (Library)	Library	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	207L	IMC (Library)	Library	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	207L	IMC (Library)	Library	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	207L	IMC (Library)	Library	Yes	WALL BASEBOAR	WOOD	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	207L	IMC (Library)	Library	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	207M	Administrative Office	Library Work Room	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	207M	Administrative Office	Library Work Room	Yes	W1	CMU	GRAY	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	207M	Administrative Office	Library Work Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	207M	Administrative Office	Library Work Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	207M	Administrative Office	Library Work Room	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	207M	Administrative Office	Library Work Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	207M	Administrative Office	Library Work Room	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214	Primary	Classroom 214	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214	Primary	Classroom 214	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214	Primary	Classroom 214	Yes	W1	CMU	YELLOW	INTACT	0	0.08	Negative			Negative					
8350	1	B835001-1	2	214	Primary	Classroom 214	Yes	CEILING	TRANSITE	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214	Primary	Classroom 214	Yes	W2	DRYWALL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214	Primary	Classroom 214	Yes	W3	CMU	BLUE	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	2	214	Primary	Classroom 214	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214	Primary	Classroom 214	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	214	Primary	Classroom 214	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	214	Primary	Classroom 214	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	214	Primary	Classroom 214	Yes	UNIVENT	METAL	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214	Primary	Classroom 214	Yes	UNIVENT CABINE	METAL	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214B	Primary	Classroom 214B - Music Room	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214B	Primary	Classroom 214B - Music Room	Yes	W1	CMU	LIGHT BLUE	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	2	214B	Primary	Classroom 214B - Music Room	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214B	Primary	Classroom 214B - Music Room	Yes	W2	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214B	Primary	Classroom 214B - Music Room	Yes	W3	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214B	Primary	Classroom 214B - Music Room	Yes	W4	DRYWALL	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214B	Primary	Classroom 214B - Music Room	Yes	CEILING	TRANSITE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214B	Primary	Classroom 214B - Music Room	Yes	CEILING	TRANSITE	BLACK	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214B	Primary	Classroom 214B - Music Room	Yes	UNIVENT	METAL	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214B	Primary	Classroom 214B - Music Room	Yes	UNIVENT CABINT	METAL	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214L	Administrative Office	Student Assistance Room at the end of the Hallway	Yes	W1	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214L	Administrative Office	Student Assistance Room at the end of the Hallway	Yes	W2	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214L	Administrative Office	Student Assistance Room at the end of the Hallway	Yes	W2	CMU	GREEN	INTACT	0	1	Positive			Negative					
8350	1	B835001-1	2	214L	Administrative Office	Student Assistance Room at the end of the Hallway	Yes	W4 BASEBOARD	TRANSITE	BLACK	INTACT	0	1.2	Positive			N/A					
8350	1	B835001-1	2	214L	Administrative Office	Student Assistance Room at the end of the Hallway	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214L	Administrative Office	Student Assistance Room at the end of the Hallway	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214L	Administrative Office	Student Assistance Room at the end of the Hallway	Yes	SOFFIT	CONCRETE	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	214L	Administrative Office	Student Assistance Room Bathroom	Yes	W1	CMU	BEIGE	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	2	214L	Administrative Office	Student Assistance Room Bathroom	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214L	Administrative Office	Student Assistance Room Bathroom	Yes	W3	CMU	BEIGE	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	2	214L	Administrative Office	Student Assistance Room Bathroom	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214L	Administrative Office	Student Assistance Room Bathroom	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214Y	Restrooms, Staff - Male/Female	Student Assistance Room Restroom	Yes	W1	CMU	BEIGE	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	2	214Y	Restrooms, Staff - Male/Female	Student Assistance Room Restroom	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214Y	Restrooms, Staff - Male/Female	Student Assistance Room Restroom	Yes	W3	CMU	BEIGE	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	2	214Y	Restrooms, Staff - Male/Female	Student Assistance Room Restroom	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	214Y	Restrooms, Staff - Male/Female	Student Assistance Room Restroom	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	215	Primary	Classroom 215	Yes	W1	CMU	LIGHT BLUE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	215	Primary	Classroom 215	Yes	W2	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	215	Primary	Classroom 215	Yes	W3	CMU	LIGHT BLUE	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	2	215	Primary	Classroom 215	Yes	W4	CMU	LIGHT BLUE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	215	Primary	Classroom 215	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	215	Primary	Classroom 215	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	215	Primary	Classroom 215	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	215	Primary	Classroom 215	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W1	CMU	BEIGE	INTACT	0	0.08	Negative			Negative					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W2	CMU	BEIGE	INTACT	0	0.07	Negative			Negative					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W4	CMU	BEIGE	INTACT	0	0.09	Negative			Negative					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W3	CMU	BEIGE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W3	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W4	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W4	CMU	ORANGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	PIPE	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative			Negative					

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	FAN SUPPORT	WOOD	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	FAN	METAL	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	SOFFIT	CONCRETE	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	SOFFIT	CONCRETE	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	SOFFIT	CONCRETE	WHITE	INTACT	0	0.04	Negative			N/A					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	COLUMN	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	COLUMN	CONCRETE	BEIGE	INTACT	0	0.04	Negative			N/A					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	COLUMN	CONCRETE	ORANGE	INTACT	0	0.04	Negative			N/A					
8350	1	B835001-1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W1	CMU	BEIGE	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W1	CMU	BEIGE	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W2	CMU	BEIGE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W3	CMU	BEIGE	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W4	CMU	BEIGE	INTACT	0	0.07	Negative			Negative					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W1	CMU	ORANGE	INTACT	0	0.06	Negative			Negative					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W2	CMU	GREEN	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	DUCT	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	FAN SUPPORT	WOOD	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	CEILING	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	SOFFIT	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	223PC	Pipe Chase	Assistant Principal's Office Pipe Chase	No	W1	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	223PC	Pipe Chase	Assistant Principal's Office Pipe Chase	No	W2	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	223PC	Pipe Chase	Assistant Principal's Office Pipe Chase	No	W3	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	223PC	Pipe Chase	Assistant Principal's Office Pipe Chase	No	W4	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	223PC	Pipe Chase	Assistant Principal's Office Pipe Chase	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	2	223PC	Pipe Chase	Assistant Principal's Office Pipe Chase	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
8350	1	B835001-1	2	224	Student Restrooms - Female (4-12)	Girl's Restroom next to Assistant Principal's Office	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	224	Student Restrooms - Female (4-12)	Girl's Restroom next to Assistant Principal's Office	Yes	W4	CMU	BEIGE	INTACT	0	0.06	Negative			Negative					
8350	1	B835001-1	2	224	Student Restrooms - Female (4-12)	Girl's Restroom next to Assistant Principal's Office	Yes	W2	CMU	BEIGE	INTACT	0	1.6	Positive			Negative					
8350	1	B835001-1	2	224	Student Restrooms - Female (4-12)	Girl's Restroom next to Assistant Principal's Office	Yes	CEILING	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	224	Student Restrooms - Female (4-12)	Girl's Restroom next to Assistant Principal's Office	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	224	Student Restrooms - Female (4-12)	Girl's Restroom next to Assistant Principal's Office	Yes	PIPE JACKET	METAL	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	225	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	W1	CMU	BLUE	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	W2	CMU	BLUE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	W3	CMU	BLUE	Flaking	5	< LOD	Negative	None		Negative	No	No	No	No	
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	W4	CMU	BLUE	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	W4	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	W3	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	W2	CMU	LIGHT BLUE	INTACT	0	0.06	Negative			Negative					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	W1	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	DOOR STOP	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	CLOSET DOOR CA	METAL	TAN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	CLOSET DOOR CA	METAL	TAN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	BATHROOM DOOR	METAL	TAN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	CEILING	CONCRETE	WHITE	INTACT	0	1.9	Positive			Negative					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	COLUMN	CONCRETE	BLUE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	COLUMN	CONCRETE	LIGHT BLUE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	216	Primary	Classroom 216	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	216A	Primary	Classroom 216 Bathroom	Yes	PIPE	METAL	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	216A	Primary	Classroom 216 Bathroom	Yes	W1	CMU	BLUE	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	2	216A	Primary	Classroom 216 Bathroom	Yes	W2	CMU	BLUE	INTACT	0	0.04	Negative			Negative					

					School District of Philadelphia																	
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
ULCS#	1	B835001-1	2	216A	Primary	Classroom 216 Bathroom	Yes	W3	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	216CL	Storage	Classroom 216 Closet	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	216CL	Storage	Classroom 216 Closet	Yes	W4	CMU	BLUE	INTACT	0	0.9	Positive			Negative					
8350	1	B835001-1	2	216CL	Storage	Classroom 216 Closet	Yes	COLUMN	CONCRETE	BLUE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	216CL	Storage	Classroom 216 Closet	Yes	CEILING	TRANSITE	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	216CL	Storage	Classroom 216 Closet	Yes	CEILING GRATE	METAL	BLUE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	217	Primary	Classroom 217	Yes	CEILING	CONCRETE	YELLOW	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	217	Primary	Classroom 217	Yes	W1	CMU	BLUE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	217	Primary	Classroom 217	Yes	W2	CMU	BLUE	INTACT	0	0.1	Negative			Negative					
8350	1	B835001-1	2	217	Primary	Classroom 217	Yes	W3	CMU	BLUE	INTACT	0	0.08	Negative			Negative					
8350	1	B835001-1	2	217	Primary	Classroom 217	Yes	W4	CMU	BLUE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	217	Primary	Classroom 217	Yes	W4	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	217	Primary	Classroom 217	Yes	W1	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	217	Primary	Classroom 217	Yes	W2	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	217	Primary	Classroom 217	Yes	W3	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	217	Primary	Classroom 217	Yes	WALL BASEBOAR	CMU	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	217	Primary	Classroom 217	Yes	DOOR CASING	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	217	Primary	Classroom 217 Closet	Yes	CEILING	TRANSITE	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	217	Primary	Classroom 217	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	217	Primary	Classroom 217	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	218	Primary	Classroom 218	Yes	W1	CMU	BLUE	INTACT	0	0.07	Negative			Negative					
8350	1	B835001-1	2	218	Primary	Classroom 218	Yes	W2	CMU	BLUE	INTACT	0	0.06	Negative			Negative					
8350	1	B835001-1	2	218	Primary	Classroom 218	Yes	W3	CMU	BLUE	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	2	218	Primary	Classroom 218	Yes	W4	CMU	BLUE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	218	Primary	Classroom 218	Yes	W4	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	218	Primary	Classroom 218	Yes	W2	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	218	Primary	Classroom 218	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	220	Primary	Classroom 220	Yes	W1	CMU	LIGHT BEIGE	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	2	220	Primary	Classroom 220	Yes	W2	CMU	LIGHT BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	220	Primary	Classroom 220	Yes	W3	CMU	LIGHT BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	220	Primary	Classroom 220	Yes	W4	CMU	LIGHT BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	220	Primary	Classroom 220	Yes	DOOR CASING	METAL	RED	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	220	Primary	Classroom 220	Yes	DOOR	WOOD	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	220	Primary	Classroom 220	Yes	DOOR	WOOD	LIGHT BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	220	Primary	Classroom 220	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	220CL	Storage	Classroom 220 Closet	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	220CL	Storage	Classroom 220 Closet	Yes	COLUMN	CONCRETE	BLUE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	220CL	Storage	Classroom 220 Closet	Yes	COLUMN	CONCRETE	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	220CL	Storage	Classroom 220 Closet	Yes	CEILING	TRANSITE	BLUE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	220CL	Storage	Classroom 220 Closet	Yes	DOOR CASING	METAL	RED	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	FLOOR	CONCRETE	GRAY	INTACT	0	< LOD	Negative								
8350	1	B835001-1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	WALL	CMU	BEIGE	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	WALL	CMU	BEIGE	INTACT	0	0.9	Positive			Negative					
8350	1	B835001-1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	CEILING	CONCRETE	WHITE	INTACT	0	1.8	Positive			Negative					
8350	1	B835001-1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	SHELF	WOOD	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	STALL WALL	TRANSITE	BEIGE	INTACT	0	1	Positive			N/A					
8350	1	B835001-1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	PIPE JACKET	METAL	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	H23	Circulation (Hallway)	Hallway at Classrooms 215 to 220	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	H23	Circulation (Hallway)	Hallway at Classrooms 215 to 220	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	H23	Circulation (Hallway)	Hallway at Classrooms 215 to 220	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350																						

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	E l e m e n t	BldgElmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	WINDOW SILL	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.07	Negative			N/A					
8350	1	B835001-1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	STAIRS RISER	CONCRETE	BLACK	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	STAIRS STRINGER	TRANSITE	BLACK	INTACT	0	0.13	Negative			Negative					
8350	1	B835001-1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	STAIR HALF WALL	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	DOOR	METAL	TAN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W1	BRICK	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W3	CMU	BEIGE	INTACT	0	1	Positive			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	WALL BASEBOAR	CONCRETE	TAN	INTACT	0	0.04	Negative			N/A					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	WALL BASEBOAR	TRANSITE	TAN	INTACT	0	1.1	Positive			N/A					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR	METAL	TAN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR	METAL	TAN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR	METAL	TAN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR CASING	METAL	RED	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR CENTER PANEL	METAL	RED	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR	METAL	RED	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	STAIRS STRINGER	CONCRETE	TAN	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	2	S24	Stairs	Stairwell next to Library	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	2	S24	Stairs	Stairwell next to																

								School District of Philadelphia														
					Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Inspection Company: Acer Associates			Spruance School							ULCS# 8350							
ULCS#	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	STAIRS RISER	TRANSITE	BLACK	INTACT	0	0.03	Negative			Negative					
8350	1	B835001-1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	HALF WALL	CONCRETE	BEIGE	INTACT	0	0.02	Negative			N/A					
8350	1	B835001-1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	STAIRS RISER	CONCRETE	BLACK	INTACT	0	1	Positive			Negative					
8350	1	B835001-1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	STAIRS STRINGER	TRANSITE	BLACK	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	HALF WALL	CONCRETE	BEIGE	INTACT	0	0.01	Negative			N/A					
8350	1	B835001-1	B	1	Mechanical Room	Water Main Room	No	W1	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	1	Mechanical Room	Water Main Room	No	W2	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	1	Mechanical Room	Water Main Room	No	W3	CONCRETE	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	1	Mechanical Room	Water Main Room	No	W4	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	1	Mechanical Room	Water Main Room	No	WALL BASEBOAR	TRANSITE	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	1	Mechanical Room	Water Main Room	No	WALL BASEBOAR	TRANSITE	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	1	Mechanical Room	Water Main Room	No	WALL BASEBOAR	TRANSITE	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	1	Mechanical Room	Water Main Room	No	WALL BASEBOAR	TRANSITE	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	1	Mechanical Room	Water Main Room	No	DOOR CASING	METAL	GREEN	INTACT	0	< LOD	Negaive			Negative					
8350	1	B835001-1	B	1	Mechanical Room	Water Main Room	No	DOOR	WOOD	GREEN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	1	Mechanical Room	Water Main Room	No	DOOR STOP	METAL	GREEN	INTACT	0	< LOD	Negaive			Negative					
8350	1	B835001-1	B	1	Mechanical Room	Water Main Room	No	DOOR	METAL	BLUE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	1	Mechanical Room	Water Main Room	No	DOOR CASING	METAL	BLUE	INTACT	0	< LOD	Negaive			Negative					
8350	1	B835001-1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	CEILING	CONCRETE	BEIGE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	W1	CMU	GREEN	INTACT	0	0.04	Negative			Negative					
8350	1	B835001-1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	W4	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	W2	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	W4	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	W1	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	DOOR CASING	METAL	SILVER	INTACT	0	< LOD	Negaive			Negative					
8350	1	B835001-1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	DOOR CASING	METAL	SILVER	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	S03	Stairs	Basement Stairwell	No	W4	CONCRETE	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	S03	Stairs	Basement Stairwell	No	W2	CONCRETE	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	S03	Stairs	Basement Stairwell	No	W1	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	S03	Stairs	Basement Stairwell	No	DOOR	METAL	TAN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	S03	Stairs	Basement Stairwell	No	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	S03	Stairs	Basement Stairwell	No	STAIRS RAILING	METAL	TAN	INTACT	0	< LOD	Negaive			Negative					
8350	1	B835001-1	B	S03	Stairs	Basement Stairwell	No	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negaive			Negative					
8350	1	B835001-1	B	S03	Stairs	Basement Stairwell	No	DOOR	METAL	TAN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	S03	Stairs	Basement Stairwell	No	STAIRS RISER	CONCRETE	GRAY	INTACT	0	< LOD	Negaive			Negative					
8350	1	B835001-1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	W1	CMU	BLUE	INTACT	0	0.09	Negative			Negative					
8350	1	B835001-1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	W2	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	W3	CMU	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	W4	CMU	BLUE	INTACT	0	0.06	Negative			Negative					
8350	1	B835001-1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	PIPE	METAL	BLUE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	COLUMN	CONCRETE	BLUE	INTACT	0	0.06	Negative			N/A					
8350	1	B835001-1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	STALL DOOR	WOOD	GRAY	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	W2	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	W3	CMU	GREEN	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	W4	CMU	GREEN	INTACT	0	0.09	Negative			Negative					
8350	1	B835001-1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	W3	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	W4	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	ELECTRICAL PAN	METAL	GREEN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	ELECTRICAL PAN	METAL	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	ALARM SWITCH	METAL	RED	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	CONDOIT	METAL	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	3	Storage	Storage Room at Boiler Room	No	W4	CMU	WHITE	INTACT	0	N/A	N/A			Negative					
8350	1	B835001-1	B	3	Storage	Storage Room at Boiler Room	No	W1	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	3	Storage	Storage Room at Boiler Room	No	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	3	Storage	Storage Room at Boiler Room	No	COLUMN	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	3	Storage	Storage Room at Boiler Room	No	PIPING	METAL	GREEN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	4	Mechanical Room	Pump Room next to Boiler Room	No	W1	CONCRETE	WHITE	INTACT	0	0.4	Negative			Negative					
8350	1	B835001-1	B	4	Mechanical Room	Pump Room next to Boiler Room	No	W2	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					

								School District of Philadelphia														
								Lead Safe Certification Assessment Report							Inspection Dates: 4/19/21 - 4/21/21 & 4/28/21 & 5/5/21							
					Name of Inspector: Kristen Masotes			Spruance School							ULCS# 8350							
					Inspection Company: Acer Associates																	
ULCS#	Element	BldgElmt ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
8350	1	B835001-1	B	4	Mechanical Room	Pump Room next to Boiler Room	No	W3	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	4	Mechanical Room	Pump Room next to Boiler Room	No	W4	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	4	Mechanical Room	Pump Room next to Boiler Room	No	TANK	METAL	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	4	Mechanical Room	Pump Room next to Boiler Room	No	COLUMN	CONCRETE	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	W1	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	W3	CMU	WHITE	INTACT	0	1.2	Positive			Negative					
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	W4	CMU	WHITE	INTACT	0	0.5	Negative			Negative					
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	COLUMN	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	PIPE	METAL	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	DOOR	METAL	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	PANEL BOX	METAL	WHITE	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	PANEL BOX	METAL	GREEN	INTACT	0	0.8	Positive			N/A					
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	PAD	CONCRETE	BLACK	INTACT	0	0.17	Negative			N/A					
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	SUMP PUMP PIP	METAL	SILVER	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	ELEC PANEL BOX	METAL	BLACK	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	DOOR	METAL	GREEN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	DOOR	METAL	GREEN	INTACT	0	< LOD	Negaive			N/A					
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	DOOR CENTER P	METAL	GREEN	INTACT	0	< LOD	Negative								
8350	1	B835001-1	B	5	Boiler Room	Boiler Room	No	WINDOW PANEL	METAL	GREEN	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	6	Mechanical Room	Incinerator Room	No	DOOR	METAL	SILVER	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	6	Mechanical Room	Incinerator Room	No	DOOR CASING	METAL	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	6	Mechanical Room	Incinerator Room	No	W1	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	6	Mechanical Room	Incinerator Room	No	W2	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	6	Mechanical Room	Incinerator Room	No	W3	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	6	Mechanical Room	Incinerator Room	No	W4	CMU	GREEN	INTACT	0	0.05	Negative			Negative					
8350	1	B835001-1	B	6	Mechanical Room	Incinerator Room	No	W1	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	6	Mechanical Room	Incinerator Room	No	W2	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	6	Mechanical Room	Incinerator Room	No	W3	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	6	Mechanical Room	Incinerator Room	No	W4	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	6	Mechanical Room	Incinerator Room	No	CEILING	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	6	Mechanical Room	Incinerator Room	No	COLUMN	CMU	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	6	Mechanical Room	Incinerator Room	No	PIPE	CMU	SILVER	INTACT	0	< LOD	Negative			N/A					
8350	1	B835001-1	B	7	Storage	Storage next to the Front Stairwell	No	W1	CMU	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	7	Storage	Storage next to the Front Stairwell	No	COLUMN	CONCRETE	GREEN	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	7	Storage	Storage next to the Front Stairwell	No	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative			Negative					
8350	1	B835001-1	B	8	Circulation (Hallway)	Crawlspace/Hallway to Boiler Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	B	8	Circulation (Hallway)	Crawlspace/Hallway to Boiler Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	B	8	Circulation (Hallway)	Crawlspace/Hallway to Boiler Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	B	8	Circulation (Hallway)	Crawlspace/Hallway to Boiler Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	B	8	Circulation (Hallway)	Crawlspace/Hallway to Boiler Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	B	8	Circulation (Hallway)	Crawlspace/Hallway to Boiler Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
8350	1	B835001-1	A	AT	Attic	Attic- Auditorium	No	W1	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	A	AT	Attic	Attic- Auditorium	No	W2	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	C	CS	Crawl Space	Crawl Space-Basement	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			Negative					
8350	1	B835001-1	C	CS	Crawl Space	Crawl Space-Basement	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
8350	1	B835001-1	1	L1	Circulation (Hallway)	Main Entrance Lobby	Yes	W1	CMU	YELLOW	INTACT	0	0.16	Negative			Negative					
8350	1	B835001-1	1	L1	Circulation (Hallway)	Main Entrance Lobby	Yes	W2	CMU	YELLOW	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	L1	Circulation (Hallway)	Main Entrance Lobby	Yes	W4	CMU	YELLOW	INTACT	0	0.01	Negative			Negative					
8350	1	B835001-1	1	L1	Circulation (Hallway)	Main Entrance Lobby	Yes	DOOR	METAL	RED	INTACT	0	0.06	Negative			N/A					
8350	1	B835001-1	1	L1	Circulation (Hallway)	Main Entrance Lobby	Yes	DOOR CENTER P	METAL	RED	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	L1	Circulation (Hallway)	Main Entrance Lobby	Yes	DOOR CASING	METAL	RED	INTACT	0	0	Negative			Negative					
8350	1	B835001-1	1	L1	Circulation (Hallway)	Main Entrance Lobby	Yes	UNIVENT	METAL	BROWN	INTACT	0	0.11	Negative			Negative					