

						School District of Philadelphia						
						Lead Safe Certification Assessment Report						
			Name of Inspector: Kristen Masotes									
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	100	Primary	Classroom 100	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative
1	1	100	Primary	Classroom 100	Yes	W1	CMU	BLUE	None	0	0.02	Negative
1	1	100	Primary	Classroom 100	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative
1	1	100	Primary	Classroom 100 Closet	Yes	CEILING	TRANSITE	BLUE	None	0	0.03	Negative
1	1	100	Primary	Classroom 100	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.01	Negative
1	1	100	Primary	Classroom 100	Yes	W4	CMU	BLUE	None	0	0.04	Negative
1	1	100	Primary	Classroom 100	Yes	W3	CMU	BLUE	None	0	0.04	Negative
1	1	100	Primary	Classroom 100	Yes	W2	CMU	BLUE	None	0	0.04	Negative
1	1	100	Primary	Classroom 100	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.01	Negative
1	1	100	Primary	Classroom 100	Yes	PIPE JACKET	METAL	BLUE	None	0	2.6	Positive
1	1	100A	Administrative Office	Adjustment Room 101A	Yes	CEILING	CONCRETE	WHITE	None	0	0.4	Negative
1	1	100A	Administrative Office	Adjustment Room 101A	Yes	W1	CMU	BEIGE	None	0	0.4	Negative
1	1	100A	Administrative Office	Adjustment Room 101A	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.02	Negative
1	1	100A	Administrative Office	Adjustment Room 101A Closet	Yes	CEILING	TRANSITE	BLUE	None	0	0.05	Negative
1	1	100A	Administrative Office	Adjustment Room 101A	Yes	W1	CMU	BLUE	None	0	0	Negative
1	1	100A	Administrative Office	Adjustment Room 101A	Yes	W2	CMU	BEIGE	None	0	0.03	Negative
1	1	100A	Administrative Office	Adjustment Room 101A	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.03	Negative
1	1	100A	Administrative Office	Adjustment Room 101A	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.03	Negative
1	1	100A	Administrative Office	Adjustment Room 101A	Yes	W3	CMU	BEIGE	None	0	0.03	Negative
1	1	100A	Administrative Office	Adjustment Room 101A	Yes	UNIVENT	METAL	BEIGE	None	0	0.06	Negative
1	1	100A	Administrative Office	Adjustment Room 101A	Yes	W4	CMU	BEIGE	None	0	0.03	Negative
1	1	100A	Administrative Office	Adjustment Room 101A	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.02	Negative
1	1	100B	Administrative Office	Office 100B	Yes	W1	CMU	GREEN	None	0	0.3	Negative
1	1	100B	Administrative Office	Office 100B	Yes	W2	CMU	GREEN	None	0	0.05	Negative
1	1	100B	Administrative Office	Office 100B	Yes	W3	CMU	GREEN	None	0	< LOD	Negative
1	1	100B	Administrative Office	Office 100B	Yes	CEILING	CONCRETE	WHITE	None	0	< LOD	Negative
1	1	100B	Administrative Office	Office 100B	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	1.1	Positive
1	1	100B	Administrative Office	Office 100B	Yes	UNIVENT	METAL	TAN	None	0	< LOD	Negative
1	1	101	Primary	Classroom 101	Yes	W1	CMU	GRAY	Flaking	5	< LOD	Negative
1	1	101	Primary	Classroom 101	Yes	W2	CMU	GRAY	None	0	0.07	Negative
1	1	101	Primary	Classroom 101	Yes	W2	CMU	WHITE	None	0	< LOD	Negative
1	1	101	Primary	Classroom 101	Yes	W3	CMU	WHITE	None	0	< LOD	Negative
1	1	101	Primary	Classroom 101	Yes	W3	CMU	GRAY	None	0	< LOD	Negative
1	1	101	Primary	Classroom 101	Yes	PIPE JACKET	METAL	GRAY	None	0	1.8	Positive
1	1	101	Primary	Classroom 101	Yes	PIPE JACKET	METAL	RED	None	0	3.5	Positive
1	1	101	Primary	Classroom 101	Yes	WALL	BRICK	BLACK	PEELING	0	< LOD	Negative
1	1	101	Primary	Classroom 101	Yes	UNIVENT	METAL	TAN	PEELING	0	< LOD	Negative
1	1	101	Primary	Classroom 101	Yes	UNIVENT CABINE	METAL	TAN	PEELING	0	< LOD	Negative
1	1	101	Primary	Classroom 101	Yes	W4	CMU	GRAY	None	0	< LOD	Negative
1	1	101	Primary	Classroom 101	Yes	W4	CMU	WHITE	None	0	< LOD	Negative
1	1	101	Primary	Classroom 101	Yes	W1	CMU	WHITE	None	0	< LOD	Negative
1	1	101	Primary	Classroom 101	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	< LOD	Negative
1	1	101	Primary	Classroom 101	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	< LOD	Negative
1	1	101	Primary	Classroom 101	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	< LOD	Negative
1	1	101	Primary	Classroom 101 Closet	Yes	CEILING	TRANSITE	WHITE	None	0	< LOD	Negative

						School District of Philadelphia						
						Lead Safe Certification Assessment Report						
			Name of Inspector: Kristen Masotes									
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	100C	Administrative Office	Building Engineer's Office 100C	No	W1	CMU	BEIGE	None	0	0.05	Negative
1	1	100C	Administrative Office	Building Engineer's Office 100C	No	W4	CMU	BEIGE	None	0	< LOD	Negative
1	1	100C	Administrative Office	Building Engineer's Office 100C	No	W3	CMU	BEIGE	None	0	< LOD	Negative
1	1	100C	Administrative Office	Building Engineer's Office 100C	No	W3	CMU	GRAY	None	0	< LOD	Negative
1	1	100C	Administrative Office	Building Engineer's Office 100C	No	W2	CMU	BEIGE	None	0	0.05	Negative
1	1	100C	Administrative Office	Building Engineer's Office 100C	No	WALL BASEBOAR	TRANSITE	BLACK	None	0	< LOD	Negative
1	1	100C	Administrative Office	Building Engineer's Office 100C	No	WALL BASEBOAR	TRANSITE	BLACK	None	0	< LOD	Negative
1	1	100C	Administrative Office	Building Engineer's Office 100C	No	UNIVENT	PLASTER	BEIGE	None	0	< LOD	Negative
1	1	100C	Administrative Office	Building Engineer's Office 100C	No	CABINET	METAL	BEIGE	None	0	< LOD	Negative
1	1	100C	Administrative Office	Building Engineer's Office 100C	No	CONDUIT	METAL	BEIGE	None	0	< LOD	Negative
1	1	100C	Administrative Office	Building Engineer's Office 100C	No	CONDUIT	METAL	BEIGE	None	0	< LOD	Negative
1	1	100S	Storage	Storage 100S next to Classroom 100	Yes	W1	CMU	BEIGE	None	0	0	Negative
1	1	100S	Storage	Storage 100S next to Classroom 100	Yes	W2	CMU	BEIGE	None	0	0	Negative
1	1	100S	Storage	Storage 100S next to Classroom 100	Yes	W3	CMU	BEIGE	None	0	0	Negative
1	1	100S	Storage	Storage 100S next to Classroom 100	Yes	W4	CMU	BEIGE	None	0	0	Negative
1	1	100S	Storage	Storage 100S next to Classroom 100	Yes	W4	CMU	WHITE	None	0	< LOD	Negative
1	1	100S	Storage	Storage 100S next to Classroom 100	Yes	W2	CMU	WHITE	None	0	< LOD	Negative
1	1	100S	Storage	Storage 100S next to Classroom 100	Yes	W1	CMU	WHITE	None	0	< LOD	Negative
1	1	100S	Storage	Storage 100S next to Classroom 100	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative
1	1	100S	Storage	Storage 100S next to Classroom 100	Yes	UNIVENT	METAL	BEIGE	None	0	0.08	Negative
1	1	100S	Storage	Storage 100S next to Classroom 100	Yes	PIPE COVER	METAL	BEIGE	None	0	0.12	Negative
1	1	100S	Storage	Storage 100S next to Classroom 100	Yes	WALL BASEBOAR	CMU	BLACK	None	0	0	Negative
1	1	100S	Storage	Storage 100S next to Classroom 100	Yes	WALL BASEBOAR	CMU	BLACK	None	0	0	Negative
1	1	100S	Storage	Storage 100S next to Classroom 100	Yes	WALL BASEBOAR	CMU	BLACK	None	0	0	Negative
1	1	102	Primary	Classroom 102	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.01	Negative
1	1	102	Primary	Classroom 102	Yes	W1	CMU	GREEN	None	0	0.03	Negative
1	1	102	Primary	Classroom 102	Yes	W3	CMU	GREEN	None	0	0.03	Negative
1	1	102	Primary	Classroom 102	Yes	W4	CMU	GREEN	Flaking	5	0.02	Negative
1	1	102	Primary	Classroom 102	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.01	Negative
1	1	102	Primary	Classroom 102 Closet	Yes	CEILING	TRANSITE	GREEN	None	0	0.01	Negative
1	1	102	Primary	Classroom 102	Yes	WALL BASEBOAR	CMU	GREEN	None	0	0.01	Negative
1	1	102	Primary	Classroom 102	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.02	Negative
1	1	102	Primary	Classroom 102	Yes	PIPE COVER	METAL	GREEN	None	0	1.8	Positive
1	1	102	Primary	Classroom 102	Yes	UNIVENT	METAL	TAN	None	0	0.04	Negative
1	1	102	Primary	Classroom 102	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative
1	1	103	Primary	Classroom 103	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative
1	1	103	Primary	Classroom 103	Yes	W1	CMU	YELLOW	None	0	0.03	Negative
1	1	103	Primary	Classroom 103	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative
1	1	103	Primary	Classroom 103 Closet	Yes	CEILING	TRANSITE	YELLOW	None	0	0.03	Negative
1	1	103	Primary	Classroom 103	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative
1	1	103	Primary	Classroom 103	Yes	W4	CMU	YELLOW	None	0	0.02	Negative
1	1	103	Primary	Classroom 103	Yes	W3	CMU	YELLOW	None	0	0.04	Negative
1	1	103	Primary	Classroom 103	Yes	PIPE JACKET	METAL	YELLOW	None	0	4	Positive
1	1	103	Primary	Classroom 103	Yes	UNIVENT	METAL	TAN	None	0	0.04	Negative
1	1	103	Primary	Classroom 103	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative

						School District of Philadelphia						
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	103	Primary	Classroom 103	Yes	W2	CMU	YELLOW	None	0	0.06	Negative
1	1	101A	Administrative Office	Vice Principal's Office 101A	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101A	Administrative Office	Vice Principal's Office 101A	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101A	Administrative Office	Vice Principal's Office 101A	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101A	Administrative Office	Vice Principal's Office 101A	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101A	Administrative Office	Vice Principal's Office 101A	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101A	Administrative Office	Vice Principal's Office 101A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Primary	Classroom 104	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative
1	1	104	Primary	Classroom 104	Yes	W1	CMU	BLUE	None	0	0.02	Negative
1	1	104	Primary	Classroom 104	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative
1	1	104	Primary	Classroom 104 Closet	Yes	CEILING	TRANSITE	BLUE	None	0	0.03	Negative
1	1	104	Primary	Classroom 104	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative
1	1	104	Primary	Classroom 104	Yes	W2	CMU	BLUE	None	0	0.05	Negative
1	1	104	Primary	Classroom 104	Yes	W3	CMU	BLUE	None	0	0.06	Negative
1	1	104	Primary	Classroom 104	Yes	PIPE JACKET	METAL	BLUE	None	0	3.2	Positive
1	1	104	Primary	Classroom 104	Yes	UNIVENT	METAL	TAN	None	0	0.05	Negative
1	1	104	Primary	Classroom 104	Yes	W4	CMU	BLUE	None	0	0.06	Negative
1	1	104	Primary	Classroom 104	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative
1	1	101ACL	Storage	Vice Principal's Office - Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	101ACL	Storage	Vice Principal's Office - Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	101ACL	Storage	Vice Principal's Office - Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	101ACL	Storage	Vice Principal's Office - Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	101ACL	Storage	Vice Principal's Office - Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	101ACL	Storage	Vice Principal's Office - Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	101B	Storage	Storage 101B across from Building Engineer's Office	Yes	CEILING	CONCRETE	WHITE	None	0	0.03	Negative
1	1	101L	Administrative Office	Office 101L	Yes	W1	CMU	BEIGE	None	0	0.02	Negative
1	1	101L	Administrative Office	Office 101L	Yes	W2	CMU	BEIGE	None	0	0	Negative
1	1	101L	Administrative Office	Office 101L	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.03	Negative
1	1	101L	Administrative Office	Office 101L	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.02	Negative
1	1	101L	Administrative Office	Office 101L	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.1	Negative
1	1	101L	Administrative Office	Office 101L	Yes	W4	CMU	BEIGE	None	0	0.02	Negative
1	1	101L	Administrative Office	Office 101L	Yes	W3	CMU	BEIGE	None	0	0	Negative
1	1	101L	Administrative Office	Office 101L	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.03	Negative
1	1	101L	Administrative Office	Office 101L	Yes	UNIVENT	METAL	BEIGE	None	0	0.11	Negative
1	1	101LR	Restrooms, Staff - Male/Female	Office 101L Restroom	Yes	W1	CMU	WHITE	None	0	0.02	Negative
1	1	101LR	Restrooms, Staff - Male/Female	Office 101L Restroom	Yes	W2	CMU	WHITE	None	0	0.01	Negative
1	1	101LR	Restrooms, Staff - Male/Female	Office 101L Restroom	Yes	W3	CMU	WHITE	None	0	0.01	Negative
1	1	101LR	Restrooms, Staff - Male/Female	Office 101L Restroom	Yes	W4	CMU	WHITE	None	0	0.03	Negative
1	1	101LR	Restrooms, Staff - Male/Female	Office 101L Restroom	Yes	CEILING	CONCRETE	WHITE	None	0	0.03	Negative
1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative
1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	W1	CMU	BEIGE	None	0	0	Negative
1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	W2	CMU	BEIGE	None	0	0	Negative

						School District of Philadelphia						
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	W3	CMU	BEIGE	None	0	0	Negative
1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	W4	CMU	BEIGE	None	0	0	Negative
1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	PIPE	METAL	BEIGE	None	0	0.22	Negative
1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	PIPE JACKET	METAL	BEIGE	None	0	0.04	Negative
1	1	101S	Storage	Storage 101S next to Classroom 101	Yes	UNIVENT	METAL	BEIGE	None	0	0.1	Negative
1	1	105	Primary	Classroom 105	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative
1	1	105	Primary	Classroom 105	Yes	W1	CMU	BLUE	None	0	0.02	Negative
1	1	105	Primary	Classroom 105	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative
1	1	105	Primary	Classroom 105 Closet	Yes	CEILING	TRANSITE	BLUE	None	0	0	Negative
1	1	105	Primary	Classroom 105	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.01	Negative
1	1	105	Primary	Classroom 105	Yes	W4	CMU	BLUE	None	0	0.03	Negative
1	1	105	Primary	Classroom 105	Yes	W3	CMU	BLUE	None	0	0.03	Negative
1	1	105	Primary	Classroom 105	Yes	PIPE JACKET	METAL	BLUE	None	0	3.7	Positive
1	1	105	Primary	Classroom 105	Yes	UNIVENT	METAL	TAN	None	0	0.04	Negative
1	1	105	Primary	Classroom 105	Yes	W2	CMU	BLUE	None	0	0.06	Negative
1	1	105	Primary	Classroom 105	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0	Negative
1	1	106	Primary	Classroom 106	Yes	CEILING	CONCRETE	WHITE	None	0	0	Negative
1	1	106	Primary	Classroom 106	Yes	W1	CMU	GREEN	None	0	0.03	Negative
1	1	106	Primary	Classroom 106	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.01	Negative
1	1	106	Primary	Classroom 106	Yes	W1	CMU	BLUE	None	0	0.12	Negative
1	1	106	Primary	Classroom 106 Closet	Yes	CEILING	TRANSITE	GREEN	None	0	0.04	Negative
1	1	106	Primary	Classroom 106	Yes	W2	CMU	GREEN	None	0	0.03	Negative
1	1	106	Primary	Classroom 106	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.01	Negative
1	1	106	Primary	Classroom 106	Yes	WALL BASEBOAR	TRANSITE	BLACK	None	0	0.07	Negative
1	1	106	Primary	Classroom 106	Yes	W4	CMU	GREEN	None	0	0.04	Negative
1	1	106	Primary	Classroom 106	Yes	PIPE JACKET	METAL	GREEN	None	0	2.5	Positive
1	1	106	Primary	Classroom 106	Yes	UNIVENT	METAL	TAN	None	0	0.14	Negative
1	1	106	Primary	Classroom 106	Yes	PIPE JACKET	METAL	BLUE	None	0	2.9	Positive
1	1	106	Primary	Classroom 106	Yes	W3	CMU	Green	Flaking	2	0.05	Negative
1	1	107	Primary	Classroom 107	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	107	Primary	Classroom 107	Yes	W1	CMU	YELLOW	INTACT	0	0.07	Negative
1	1	107	Primary	Classroom 107	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	1	Positive
1	1	107	Primary	Classroom 107	Yes	W2	CMU	YELLOW	INTACT	0	0	Negative
1	1	107	Primary	Classroom 107 Closet	Yes	CEILING	TRANSITE	YELLOW	INTACT	0	0.01	Negative
1	1	107	Primary	Classroom 107	Yes	W3	CMU	YELLOW	INTACT	0	0.04	Negative
1	1	107	Primary	Classroom 107	Yes	UNIVENT	METAL	TAN	INTACT	0	0.28	Negative
1	1	107	Primary	Classroom 107	Yes	W4	CMU	YELLOW	INTACT	0	0.05	Negative
1	1	108	Primary	Classroom 108	Yes	W1	CMU	Blue	Flaking	7	0.02	Negative
1	1	108	Primary	Classroom 108	Yes	W2	CMU	BLUE	INTACT	0	0.02	Negative
1	1	108	Primary	Classroom 108	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.05	Negative
1	1	108	Primary	Classroom 108	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	1	108	Primary	Classroom 108	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	108	Primary	Classroom 108	Yes	W3	CMU	Blue	Flaking	3	0.13	Negative
1	1	108	Primary	Classroom 108	Yes	PIPE JACKET	METAL	BLUE	INTACT	0	2	Positive
1	1	108	Primary	Classroom 108	Yes	UNIVENT	METAL	TAN	INTACT	0	0.05	Negative

						School District of Philadelphia						
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	108	Primary	Classroom 108	Yes	W4	CMU	BLUE	INTACT	0	0.02	Negative
1	1	108	Primary	Classroom 108	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	1	108	Primary	Classroom 108 Closet	Yes	CEILING	TRANSITE	BLUE	INTACT	0	0	Negative
1	1	109	Primary	Classroom 109 Closet	Yes	Ceiling	TRANSITE	White	INTACT	0	0.01	Negative
1	1	109	Primary	Classroom 109	Yes	W1	CMU	PURPLE	INTACT	0	0.04	Negative
1	1	109	Primary	Classroom 109	Yes	W2	CMU	PURPLE	INTACT	0	0.02	Negative
1	1	109	Primary	Classroom 109	Yes	W3	CMU	BEIGE	Flaking	2	0.06	Negative
1	1	109	Primary	Classroom 109	Yes	W4	CMU	BEIGE	INTACT	0	0.01	Negative
1	1	109	Primary	Classroom 109	Yes	Ceiling	Concrete	White	Flaking	1	0	Negative
1	1	109	Primary	Classroom 109	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0	Negative
1	1	109	Primary	Classroom 109	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative
1	1	109	Primary	Classroom 109	Yes	PIPE JACKET	METAL	GREEN	INTACT	0	3.2	Positive
1	1	109	Primary	Classroom 109	Yes	UNIVENT	METAL	TAN	INTACT	0	0.1	Negative
1	1	109	Primary	Classroom 109	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative
1	1	110	Primary	Classroom 110	Yes	Ceiling	Concrete	WHITE	INTACT	0	0	Negative
1	1	110	Primary	Classroom 110	Yes	W1	CMU	PURPLE	INTACT	0	0.06	Negative
1	1	110	Primary	Classroom 110	Yes	W2	CMU	PURPLE	INTACT	0	0.05	Negative
1	1	110	Primary	Classroom 110	Yes	W3	CMU	PURPLE	INTACT	0	0.04	Negative
1	1	110	Primary	Classroom 110	Yes	W4	CMU	PURPLE	INTACT	0	0.05	Negative
1	1	110	Primary	Classroom 110	Yes	CHALKBOARD FR	Wood	CLEAR	INTACT	0	0.04	Negative
1	1	110	Primary	Classroom 110	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0	Negative
1	1	110	Primary	Classroom 110	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative
1	1	110	Primary	Classroom 110	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative
1	1	110	Primary	Classroom 110	Yes	PIPE JACKET	Metal	GREEN	INTACT	0	3.8	Positive
1	1	110	Primary	Classroom 110 Closet	Yes	Ceiling	TRANSITE	GREEN	INTACT	0	0	Negative
1	1	110	Primary	Classroom 110	Yes	UNIVENT	Metal	TAN	INTACT	0	0.03	Negative
1	1	111	Primary	Classroom 111	Yes	W1	CMU	BEIGE	INTACT	0	0.03	Negative
1	1	111	Primary	Classroom 111	Yes	W1	CMU	BLUE	INTACT	0	0.07	Negative
1	1	111	Primary	Classroom 111	Yes	W2	CMU	BEIGE	Flaking	5	< LOD	Negative
1	1	111	Primary	Classroom 111	Yes	W3	CMU	BEIGE	Flaking	5	< LOD	Negative
1	1	111	Primary	Classroom 111	Yes	W4	CMU	BEIGE	INTACT	0	0.06	Negative
1	1	111	Primary	Classroom 111	Yes	W4 BASEBOARD	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	111	Primary	Classroom 111	Yes	W1 BASEBOARD	TRANSITE	BLACK	INTACT	0	1.7	Positive
1	1	111	Primary	Classroom 111	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	1	111	Primary	Classroom 111	Yes	UNIVENT CABINE	METAL	BLUE	INTACT	0	< LOD	Negative
1	1	111	Primary	Classroom 111	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative
1	1	111	Primary	Classroom 111	Yes	PIPE JACKET	METAL	BLUE	INTACT	0	2.6	Positive
1	1	111	Primary	Classroom 111	Yes	COLUMN	CONCRETE	BLUE	INTACT	0	1.2	Positive
1	1	111	Primary	Classroom 111	Yes	Ceiling	Concrete	White	INTACT	0	0	Negative
1	1	112	Primary	Classroom 112	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	112	Primary	Classroom 112	Yes	W1	CMU	BLUE	INTACT	0	0.04	Negative
1	1	112	Primary	Classroom 112	Yes	W2	CMU	BLUE	INTACT	0	0.03	Negative
1	1	112	Primary	Classroom 112	Yes	W4	CMU	BLUE	INTACT	0	0.05	Negative
1	1	112	Primary	Classroom 112	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0	Negative
1	1	112	Primary	Classroom 112	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative

						School District of Philadelphia						
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	112	Primary	Classroom 112	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative
1	1	112	Primary	Classroom 112	Yes	PIPE COVER	METAL	BLUE	INTACT	0	0.3	Negative
1	1	112	Primary	Classroom 112	Yes	UNIVENT	METAL	TAN	INTACT	0	0.07	Negative
1	1	112	Primary	Classroom 112 Closet	Yes	CEILING	TRANSITE	BLUE	INTACT	0	0.03	Negative
1	1	113	Primary	Classroom 113	Yes	CEILING	TRANSITE	WHITE	INTACT	0	< LOD	Negative
1	1	113	Primary	Classroom 113	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	113	Primary	Classroom 113	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	113	Primary	Classroom 113	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	113	Primary	Classroom 113	Yes	W4	CMU	WHITE	INTACT	0	0.07	Negative
	1	113	Primary	Classroom 113		CEILING	Concrete	WHITE	INTACT	0	0.4	Negative
1	1	113	Primary	Classroom 113	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	113	Primary	Classroom 113	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	113	Primary	Classroom 113	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	113	Primary	Classroom 113	Yes	UNIVENT,	METAL	TAN	INTACT	0	< LOD	Negative
1	1	113	Primary	Classroom 113	Yes	UNIVENT,CABINE	METAL	TAN	INTACT	0	< LOD	Negative
1	1	113	Primary	Classroom 113	Yes	PIPE JACKET	METAL	BLUE	INTACT	0	< LOD	Negaive
1	1	113	Primary	Classroom 113	Yes	CONDUIT	METAL	BLUE	INTACT	0	< LOD	Negative
1	1	114	Primary	Classroom 114	Yes	W1	CMU	GREEN	INTACT	0	0.05	Negative
1	1	114	Primary	Classroom 114	Yes	W2	CMU	GREEN	INTACT	0	< LOD	Negative
1	1	114	Primary	Classroom 114	Yes	W3	CMU	GREEN	INTACT	0	< LOD	Negative
1	1	114	Primary	Classroom 114	Yes	W4	CMU	GREEN	INTACT	0	< LOD	Negative
1	1	114	Primary	Classroom 114	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	114	Primary	Classroom 114	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	114	Primary	Classroom 114	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	1	114	Primary	Classroom 114	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative
1	1	114	Primary	Classroom 114	Yes	PIPE COVER	METAL	GREEN	INTACT	0	2.1	Positive
1	1	114	Primary	Classroom 114	Yes	Ceiling	Concrete	White	INTACT	0	0.07	Negative
1	1	115	Primary	Classroom 115	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.02	Negative
1	1	115	Primary	Classroom 115	Yes	W1	CMU	YELLOW	INTACT	0	0.05	Negative
1	1	115	Primary	Classroom 115	Yes	W2	CMU	YELLOW	INTACT	0	0.02	Negative
1	1	115	Primary	Classroom 115	Yes	W3	CMU	YELLOW	INTACT	0	0.8	Positive
1	1	115	Primary	Classroom 115	Yes	W4	CMU	YELLOW	INTACT	0	0.02	Negative
1	1	115	Primary	Classroom 115	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative
1	1	115	Primary	Classroom 115	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative
1	1	115	Primary	Classroom 115	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative
1	1	115	Primary	Classroom 115	Yes	UNIVENT	METAL	TAN	INTACT	0	0.06	Negative
1	1	115	Primary	Classroom 115	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	0.07	Negative
1	1	115	Primary	Classroom 115	Yes	PIPE COVER	METAL	YELLOW	INTACT	0	2.7	Positive
1	1	115	Primary	Classroom 115 Closet	Yes	CEILING	TRANSITE	YELLOW	INTACT	0	0.02	Negative
1	1	117	Primary	Classroom 117 Closet	Yes	CEILING	TRANSITE	WHITE	INTACT	0	0.07	Negative
1	1	117	Primary	Classroom 117	Yes	W1	CMU	GREEN	INTACT	0	0.05	Negative
1	1	117	Primary	Classroom 117	Yes	W1	CMU	YELLOW	Flaking	10	0.05	Negative
1	1	117	Primary	Classroom 117	Yes	W2	DRYWALL	GREEN	INTACT	0	0	Negative
1	1	117	Primary	Classroom 117	Yes	W3	CMU	GREEN	INTACT	0	0.03	Negative
1	1	117	Primary	Classroom 117	Yes	W3	CMU	GREEN	INTACT	0	0.05	Negative

						School District of Philadelphia						
						Lead Safe Certification Assessment Report						
			Name of Inspector: Kristen Masotes			Spruance School						
			Inspection Company: Acer Associates									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	117	Primary	Classroom 117	Yes	W4	CMU	YELLOW	INTACT	0	0.06	Negative
1	1	117	Primary	Classroom 117	Yes	W4	CMU	GREEN	INTACT	0	0	Negative
1	1	117	Primary	Classroom 117	Yes	UNIVENT	METAL	TAN	INTACT	0	0.09	Negative
1	1	117	Primary	Classroom 117	Yes	PIPE COVER	METAL	GREEN	INTACT	0	0.08	Negative
	1	117	Primary	Classroom 117	Yes	CEILING	Concrete	White	INTACT	0	0.3	Negative
1	1	117	Primary	Classroom 117	Yes	CEILING	TRANSITE	GREEN	INTACT	0	0	Negative
1	1	119	Primary	Classroom 119	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.03	Negative
1	1	119	Primary	Classroom 119	Yes	W1	CMU	YELLOW	INTACT	0	0.02	Negative
1	1	119	Primary	Classroom 119	Yes	W2	CMU	YELLOW	INTACT	0	0.02	Negative
1	1	119	Primary	Classroom 119	Yes	W3	CMU	YELLOW	INTACT	0	0	Negative
1	1	119	Primary	Classroom 119	Yes	W4	CMU	YELLOW	INTACT	0	0.04	Negative
1	1	119	Primary	Classroom 119	Yes	PIPE JACKET	METAL	GREEN	PEELING	0	0.11	Negative
1	1	119	Primary	Classroom 119	Yes	UNIVENT	METAL	TAN	PEELING	0	0.05	Negative
1	1	119	Primary	Classroom 119	Yes	UNIVENT CABINE	METAL	TAN	PEELING	0	0.09	Negative
1	1	119	Primary	Classroom 119	Yes	WALL BASEBOAR	Ceramic Tile	TAN	PEELING	0	1.6	Positive
1	1	119	Primary	Classroom 119 Closet	Yes	CEILING	TRANSITE	GREEN	INTACT	0	0	Negative
1	1	122	Primary	Classroom 122	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.04	Negative
1	1	122	Primary	Classroom 122	Yes	W1	CMU	BEIGE	INTACT	0	0.04	Negative
1	1	122	Primary	Classroom 122	Yes	W2	DRYWALL	BEIGE	INTACT	0	0	Negative
1	1	122	Primary	Classroom 122	Yes	W3	CMU	BEIGE	INTACT	0	0.02	Negative
1	1	122	Primary	Classroom 122	Yes	W4	CMU	BLUE	INTACT	0	0	Negative
1	1	122	Primary	Classroom 122	Yes	PIPE COVER	METAL	BEIGE	INTACT	0	0.09	Negative
1	1	122	Primary	Classroom 122	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.12	Negative
1	1	122	Primary	Classroom 122	Yes	UNIVENT CABINE	METAL	BEIGE	INTACT	0	0.02	Negative
1	1	122	Primary	Classroom 122	Yes	DOOR CASING	METAL	BEIGE	INTACT	0	0.03	Negative
1	1	122	Primary	Classroom 122 Closet	Yes	CEILING	TRANSITE	BEIGE	INTACT	0	0	Negative
1	1	122	Primary	Classroom 122	Yes	PIPE	METAL	BEIGE	INTACT	0	0.02	Negative
1	1	122	Primary	Classroom 122	Yes	PIPE	METAL	BLUE	INTACT	0	0.04	Negative
1	1	124	Primary	Classroom 124	Yes	DOOR CASING	METAL	WHITE	Flaking	5	0.15	Negative
1	1	124	Primary	Classroom 124	Yes	W1	CMU	WHITE	INTACT	0	0.01	Negative
1	1	124	Primary	Classroom 124	Yes	W2	DRYWALL	WHITE	INTACT	0	0	Negative
1	1	124	Primary	Classroom 124	Yes	W4	DRYWALL	WHITE	Flaking	5	0	Negative
1	1	124	Primary	Classroom 124	Yes	WALL BASEBOAR	WOOD	WHITE	INTACT	0	0	Negative
1	1	124	Primary	Classroom 124	Yes	WALL BASEBOAR	CMU	WHITE	PEELING	0	0.04	Negative
1	1	124	Primary	Classroom 124	Yes	PIPE COVER	METAL	WHITE	PEELING	0	0.05	Negative
1	1	124	Primary	Classroom 124	Yes	UNIVENT COVER	METAL	TAN	INTACT	0	0.16	Negative
1	1	124	Primary	Classroom 124	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	0.02	Negative
1	1	124	Primary	Classroom 124	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.01	Negative
1	1	124	Primary	Classroom 124 Closet	Yes	CEILING	TRANSITE	WHITE	INTACT	0	0.01	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative

			School District of Philadelphia									
			Name of Inspector: Kristen Masotes					Lead Safe Certification Assessment Report				
			Inspection Company: Acer Associates					Spruance School				
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	2.3	Positive
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	FLOOR	CONCRETE	GRAY	INTACT	0	< LOD	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	DOOR CASING	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	STALL WALL	TRANSITE	BEIGE	INTACT	0	< LOD	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	DOOR PANEL	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	Ceiling	Concrete	White	Flaking	10	<LOD	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	CEILING	CONCRETE	WHITE	PEELING	0	0.02	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W2	CMU	BEIGE	INTACT	0	0	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	4.1	Positive
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.35	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	STALL WALL	TRANSITE	BEIGE	INTACT	0	0	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	DOOR CASING	WOOD	BEIGE	INTACT	0	0	Negative
1	1	110J	Student Restrooms - Male (4-12)	Boy's Restroom 110T	Yes	DOOR	WOOD	BEIGE	INTACT	0	0.03	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	DOOR	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	DOOR CASING	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	1.6	Positive
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative

			School District of Philadelphia									
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	COLUMN	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	FLOOR	CONCRETE	BLUE	INTACT	0	< LOD	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	Ceiling	Concrete	White	Flaking	15	< LOD	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T Foyer	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T Foyer	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T Foyer	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T Foyer	Yes	DOOR CASING	WOOD	WHITE	INTACT	0	< LOD	Negative
1	1	111T	Student Restrooms - Female (4-12)	Girl's Restroom 111T Foyer	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	W1	CMU	BEIGE	INTACT	0	0.09	Negative
1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	W2	CMU	BEIGE	INTACT	0	0.04	Negative
1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	PIPE	METAL	BEIGE	PEELING	0	< LOD	Negative
1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative
1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	SINK	CERAMIC	BEIGE	PEELING	0	< LOD	Negative
1	1	111C	Service Closets	Custodial Storage next to Girl's Restroom by Classroom 113	No	PIPE	METAL	BEIGE	PEELING	0	< LOD	Negative
1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W2	CMU	BEIGE	INTACT	0	0	Negative
1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative
1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative
1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W1	CMU	RED	INTACT	0	0	Negative
1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W2	CMU	RED	INTACT	0	0	Negative
1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W3	CMU	RED	INTACT	0	0	Negative
1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	W4	CMU	RED	INTACT	0	0	Negative
1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	WALL BASEBOAR	CMU	BLACK	INTACT	0	0	Negative
1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	WALL BASEBOAR	CMU	BLACK	INTACT	0	0	Negative
1	1	110A	Administrative Office	Office 110A next to Room 112	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.07	Negative
1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative

			School District of Philadelphia									
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	2.5	Positive
1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	W1	CMU	BEIGE	INTACT	0	0.04	Negative
1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	W2	CMU	BEIGE	INTACT	0	0	Negative
1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative
1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative
1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	PIPE COVER	METAL	BEIGE	INTACT	0	2	Positive
1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.12	Negative
1	1	111L	Teacher Lounge/Dining	Teacher Lounge 111L	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.9	Positive
1	1	111LRR	Restrooms, Staff - Male/Female	Teacher Lounge 111L - Restroom	Yes	W1	CMU	BEIGE	INTACT	0	0.06	Negative
1	1	111LRR	Restrooms, Staff - Male/Female	Teacher Lounge 111L - Restroom	Yes	W2	CMU	BEIGE	INTACT	0	0.02	Negative
1	1	111LRR	Restrooms, Staff - Male/Female	Teacher Lounge 111L - Restroom	Yes	W3	CMU	BEIGE	INTACT	0	0.04	Negative
1	1	111LRR	Restrooms, Staff - Male/Female	Teacher Lounge 111L - Restroom	Yes	W4	CMU	BEIGE	INTACT	0	0.04	Negative
1	1	111LRR	Restrooms, Staff - Male/Female	Teacher Lounge 111L - Restroom	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.07	Negative
1	1	114S	Storage	Book Storage 114S	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114S	Storage	Book Storage 114S	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114S	Storage	Book Storage 114S	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114S	Storage	Book Storage 114S	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114S	Storage	Book Storage 114S	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114S	Storage	Book Storage 114S	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114S	Storage	Book Storage 114S	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	116	ESE Full Time	Classroom 116	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	1	116	ESE Full Time	Classroom 116	Yes	W1	CMU	BLUE	INTACT	0	0.04	Negative
1	1	116	ESE Full Time	Classroom 116	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative
1	1	116	ESE Full Time	Classroom 116	Yes	W3	DRYWALL	BLUE	PEELING	0	< LOD	Negative
1	1	116	ESE Full Time	Classroom 116	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	116	ESE Full Time	Classroom 116	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	116	ESE Full Time	Classroom 116	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative
1	1	116	ESE Full Time	Classroom 116	Yes	W3	CMU	BLUE	INTACT	0	0.08	Negative
1	1	116	ESE Full Time	Classroom 116	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	1	116B	Student Restrooms - Male/Female (Classroom)	Classroom 116 Restroom	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative
1	1	116B	Student Restrooms - Male/Female (Classroom)	Classroom 116 Restroom	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative
1	1	116B	Student Restrooms - Male/Female (Classroom)	Classroom 116 Restroom	Yes	W3	CMU	BLUE	INTACT	0	< LOD	Negative

						School District of Philadelphia						
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	116B	Student Restrooms - Male/Female (Classroom)	Classroom 116 Restroom	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative
1	1	116B	Student Restrooms - Male/Female (Classroom)	Classroom 116 Restroom	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative
1	1	116B	Student Restrooms - Male/Female (Classroom)	Classroom 116 Restroom	Yes	CEILING	CONCRETE	BLUE	INTACT	0	< LOD	Negative
1	1	116B	Student Restrooms - Male/Female (Classroom)	Classroom 116 Restroom	Yes	PIPE	METAL	BLUE	INTACT	0	< LOD	Negative
1	1	117CL	Storage	Classroom 117 Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117CL	Storage	Classroom 117 Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117CL	Storage	Classroom 117 Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117CL	Storage	Classroom 117 Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117CL	Storage	Classroom 117 Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117CL	Storage	Classroom 117 Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117T	Student Restrooms - Male/Female (Classroom)	Classroom 117 Restroom	Yes	W1	CMU	YELLOW	INTACT	No Access	0.03	Negative
1	1	117T	Student Restrooms - Male/Female (Classroom)	Classroom 117 Restroom	Yes	W2	CMU	YELLOW	INTACT	No Access	0.05	Negative
1	1	117T	Student Restrooms - Male/Female (Classroom)	Classroom 117 Restroom	Yes	W3	CMU	YELLOW	INTACT	No Access	0.04	Negative
1	1	117T	Student Restrooms - Male/Female (Classroom)	Classroom 117 Restroom	Yes	W4	CMU	YELLOW	INTACT	No Access	0.07	Negative
1	1	117T	Student Restrooms - Male/Female (Classroom)	Classroom 117 Restroom	Yes	PIPE	METAL	YELLOW	INTACT	No Access	0.01	Negative
1	1	117T	Student Restrooms - Male/Female (Classroom)	Classroom 117 Restroom	Yes	DOOR CASING	METAL	TAN	INTACT	No Access	0.05	Negative
1	1	117T	Student Restrooms - Male/Female (Classroom)	Classroom 117 Restroom	Yes	CEILING	CONCRETE	WHITE	INTACT	No Access	0.04	Negative
1	1	117B	Storage	Classroom 117 Storage	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117B	Storage	Classroom 117 Storage	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117B	Storage	Classroom 117 Storage	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117B	Storage	Classroom 117 Storage	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117B	Storage	Classroom 117 Storage	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117B	Storage	Classroom 117 Storage	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117A	Storage	Stationery Storage 117A	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117A	Storage	Stationery Storage 117A	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117A	Storage	Stationery Storage 117A	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117A	Storage	Stationery Storage 117A	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117A	Storage	Stationery Storage 117A	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	117A	Storage	Stationery Storage 117A	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access

			School District of Philadelphia									
			Lead Safe Certification Assessment Report									
			Spruance School									
			Name of Inspector: Kristen Masotes									
			Inspection Company: Acer Associates									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	117	Circulation (Hallway)	Hallway near Classroom 17 Restroom	Yes	WALL	CMU	BLUE	INTACT	No Access	0.05	Negative
1	1	117	Circulation (Hallway)	Hallway near Classroom 17 Restroom	Yes	WALL	CMU	BLUE	INTACT	No Access	0	Negative
1	1	117	Circulation (Hallway)	Hallway near Classroom 17 Restroom	Yes	WALL	DRYWALL	BLUE	INTACT	No Access	0	Negative
1	1	117	Circulation (Hallway)	Hallway near Classroom 17 Restroom	Yes	CEILING	CONCRETE	WHITE	INTACT	No Access	0	Negative
1	1	117	Circulation (Hallway)	Hallway near Classroom 17 Restroom	Yes	DOOR CASING	METAL	TAN	INTACT	No Access	0	Negative
1	1	117	Circulation (Hallway)	Hallway near Classroom 17 Restroom	Yes	DOOR CASING	METAL	TAN	INTACT	No Access	0.04	Negative
1	1	117	Circulation (Hallway)	Hallway near Classroom 17 Restroom	Yes	SHELF	WOOD	BLUE	INTACT	No Access	0	Negative
1	1	118	ESE Full Time	Classroom 118	Yes	CEILING COLUMN	CONCRETE	WHITE	INTACT	No Access	< LOD	Negative
1	1	118	ESE Full Time	Classroom 118	Yes	W1	CMU	BEIGE	INTACT	No Access	< LOD	Negative
1	1	118	ESE Full Time	Classroom 118	Yes	W2	CMU	BEIGE	INTACT	No Access	< LOD	Negative
1	1	118	ESE Full Time	Classroom 118	Yes	W3	DRYWALL	BEIGE	INTACT	No Access	< LOD	Negative
1	1	118	ESE Full Time	Classroom 118	Yes	W4	CMU	BEIGE	INTACT	No Access	< LOD	Negative
1	1	118	ESE Full Time	Classroom 118	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	No Access	0.3	Negative
1	1	118	ESE Full Time	Classroom 118	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	1.3	Positive
1	1	118	ESE Full Time	Classroom 118	Yes	UNIVENT	METAL	TAN	INTACT	No Access	< LOD	Negative
1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	W1	DRYWALL	BEIGE	INTACT	No Access	< LOD	Negative
1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	W2	CMU	BEIGE	INTACT	No Access	< LOD	Negative
1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	W3	CMU	BEIGE	INTACT	No Access	< LOD	Negative
1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	W3	DRYWALL	BEIGE	INTACT	No Access	< LOD	Negative
1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	W2	DRYWALL	BEIGE	INTACT	No Access	< LOD	Negative
1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	W3	CMU	BEIGE	INTACT	No Access	0.06	Negative
1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	W4	CMU	BEIGE	INTACT	No Access	0.08	Negative
1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	1.2	Positive
1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	CEILING COLUMN	CONCRETE	BEIGE	INTACT	No Access	< LOD	Negative
1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	1.4	Positive
1	1	118A	Administrative Office	Office 118A next to Classroom 118	Yes	UNIVENT	METAL	TAN	INTACT	No Access	< LOD	Negative
1	1	118B	Student Restrooms - Male/Female (Classroom)	Classroom 118 Restroom	Yes	W1	CMU	BEIGE	Flaking	2	0.04	Negative
1	1	118B	Student Restrooms - Male/Female (Classroom)	Classroom 118 Restroom	Yes	W2	CMU	BEIGE	Flaking	2	0.09	Negative
1	1	118B	Student Restrooms - Male/Female (Classroom)	Classroom 118 Restroom	Yes	W3	CMU	BEIGE	Flaking	2	< LOD	Negative
1	1	118B	Student Restrooms - Male/Female (Classroom)	Classroom 118 Restroom	Yes	W4	CMU	BEIGE	Flaking	2	< LOD	Negative
1	1	118B	Student Restrooms - Male/Female (Classroom)	Classroom 118 Restroom	Yes	CEILING	CONCRETE	BEIGE	INTACT	0	0.04	Negative
1	1	118C	Storage	Classroom 118 Closet	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative
1	1	118C	Storage	Classroom 118 Closet	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative
1	1	118C	Storage	Classroom 118 Closet	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative
1	1	119CL	Storage	Classroom 119 Closet	Yes	W4	CMU	GREEN	INTACT	0	0	Negative
1	1	119CL	Storage	Classroom 119 Closet	Yes	W1	CMU	GREEN	INTACT	0	0	Negative
1	1	119CL	Storage	Classroom 119 Closet	Yes	W2	CMU	GREEN	INTACT	0	0	Negative

						School District of Philadelphia						
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	119CL	Storage	Classroom 119 Closet	Yes	DOOR CASING	METAL	TAN	PEELING	0	0.06	Negative
1	1	119CL	Storage	Classroom 119 Closet	Yes	DOOR CASING	METAL	TAN	PEELING	0	0.05	Negative
1	1	120	Primary	Classroom 120	Yes	CEILING COLUMN	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	1	120	Primary	Classroom 120	Yes	W1	CMU	BEIGE	INTACT	0	0.05	Negative
1	1	120	Primary	Classroom 120	Yes	W2	CMU	BEIGE	INTACT	0	0.07	Negative
1	1	120	Primary	Classroom 120	Yes	W3	CMU	BEIGE	INTACT	0	0.13	Negative
1	1	120	Primary	Classroom 120	Yes	W4	CMU	BEIGE	INTACT	0	0.05	Negative
1	1	120	Primary	Classroom 120	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	1.1	Positive
	1	120	Primary	Classroom 120		CEILING	CONCRETE	WHITE	INTACT	0	0.4	Negative
1	1	120	Primary	Classroom 120	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	1	120A	Administrative Office	Office 120A next to Classroom 120	Yes	W1	CMU	YELLOW	INTACT	0	< LOD	Negative
1	1	120A	Administrative Office	Office 120A next to Classroom 120	Yes	W2	CMU	YELLOW	INTACT	0	< LOD	Negative
1	1	120A	Administrative Office	Office 120A next to Classroom 120	Yes	W3	CMU	YELLOW	INTACT	0	< LOD	Negative
1	1	120A	Administrative Office	Office 120A next to Classroom 120	Yes	W4	CMU	YELLOW	INTACT	0	< LOD	Negative
1	1	120A	Administrative Office	Office 120A next to Classroom 120	Yes	PIPE	METAL	YELLOW	INTACT	0	< LOD	Negative
1	1	120B	Student Restrooms - Male/Female (Classroom)	Classroom 120 Restroom	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.08	Negative
1	1	120B	Student Restrooms - Male/Female (Classroom)	Classroom 120 Restroom	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	120B	Student Restrooms - Male/Female (Classroom)	Classroom 120 Restroom	Yes	W2	CMU	BEIGE	INTACT	0	0.08	Negative
1	1	120B	Student Restrooms - Male/Female (Classroom)	Classroom 120 Restroom	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	120B	Student Restrooms - Male/Female (Classroom)	Classroom 120 Restroom	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	120S	Storage	Storage 120S in Hallway	Yes	DOOR CASING	METAL	TAN	INTACT	0	0.07	Negative
1	1	120S	Storage	Storage 120S in Hallway	Yes	W1	CMU	WHITE	INTACT	0	0	Negative
1	1	120S	Storage	Storage 120S in Hallway	Yes	W4	CMU	WHITE	INTACT	0	0	Negative
1	1	120S	Storage	Storage 120S in Hallway	Yes	W2	CMU	WHITE	INTACT	0	0	Negative
1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	W1	CMU	BLUE	Flaking	5	0.04	Negative
1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	W2	CMU	BLUE	INTACT	0	0.07	Negative
1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	W3	CMU	BLUE	INTACT	0	0.06	Negative
1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	W4	CMU	BLUE	INTACT	0	0.05	Negative
1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	FLOOR	CONCRETE	GREEN	INTACT	0	0.03	Negative
1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	UNIVENT	METAL	TAN	INTACT	0	0.08	Negative
1	1	122A	Administrative Office	Speech & Language Therapy Office 122A	Yes	DOOR CASING	METAL	TAN	INTACT	0	0.11	Negative
1	1	122S	Storage	Storage 122S across from Restrooms	Yes	W1	CMU	WHITE	INTACT	0	0	Negative
1	1	122S	Storage	Storage 122S across from Restrooms	Yes	W2	CMU	WHITE	INTACT	0	0	Negative
1	1	122S	Storage	Storage 122S across from Restrooms	Yes	W3	CMU	WHITE	INTACT	0	0	Negative
1	1	122S	Storage	Storage 122S across from Restrooms	Yes	W4	CMU	WHITE	INTACT	0	0	Negative
	1	122S	Storage	Storage 122S across from Restrooms		Ceiling	Concrete	White	None	0	0.4	Negative

						School District of Philadelphia						
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	122S	Storage	Storage 122S across from Restrooms	Yes	DOOR CASING	METAL	TAN	INTACT	0	0.03	Negative
1	1	124A	Storage	Book Storage 124A	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	124A	Storage	Book Storage 124A	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	124A	Storage	Book Storage 124A	Yes	W3	CMU	Beige	Flaking	5	< LOD	Negative
1	1	124A	Storage	Book Storage 124A	Yes	W3	CMU	BEIGE	INTACT	0	1.1	Positive
1	1	124A	Storage	Book Storage 124A	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative
1	1	124A	Storage	Book Storage 124A	Yes	W4	DRYWALL	BEIGE	INTACT	0	< LOD	Negative
1	1	124A	Storage	Book Storage 124A	Yes	DOOR	METAL	RED	INTACT	0	< LOD	Negative
1	1	124A	Storage	Book Storage 124A	Yes	DOOR CASING	METAL	RED	INTACT	0	< LOD	Negative
1	1	124A	Storage	Book Storage 124A	Yes	DOOR CENTER PANEL	METAL	RED	INTACT	0	< LOD	Negative
1	1	124A	Storage	Book Storage 124A	Yes	W4	CMU	Blue	Flaking	5	< LOD	Negative
1	1	124A	Storage	Book Storage 124A	Yes	DOOR CASING	METAL	BEIGE	INTACT	0	< LOD	Negative
	1	124A	Storage	Book Storage 124A	Yes	Ceiling	Concrete	White	INTACT	0	0.3	Negative
1	1	124A	Storage	Book Storage 124A	Yes	W4	CMU	BLUE	INTACT	0	1.1	Positive
1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	W1	CMU	BEIGE	INTACT	0	0.03	Negative
1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	W2	CMU	BEIGE	INTACT	0	0.03	Negative
1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	W3	CMU	BEIGE	INTACT	0	0.02	Negative
1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	W4	CMU	BEIGE	INTACT	0	0.04	Negative
1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.04	Negative
1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	STALL WALL	TRANSITE	BROWN	INTACT	0	0	Negative
1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	STALL WALL	TRANSITE	BROWN	INTACT	0	0	Negative
1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	DOOR CASING	METAL	RED	INTACT	0	0.01	Negative
1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	DOOR	METAL	RED	INTACT	0	0.08	Negative
1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	PIPE COVER	METAL	BEIGE	INTACT	0	0.16	Negative
1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	UNIVENT	METAL	WHITE	INTACT	0	0.12	Negative
1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	PIPE	METAL	WHITE	INTACT	0	0.16	Negative
1	1	125T	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 117	Yes	VENT COVER	METAL	WHITE	INTACT	0	0.01	Negative
1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.01	Negative
1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	W1	CMU	BEIGE	INTACT	0	0.01	Negative
1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	W2	CMU	BEIGE	INTACT	0	0.02	Negative
1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	W3	CMU	BEIGE	INTACT	0	0.07	Negative
1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	W4	CMU	BEIGE	INTACT	0	0.1	Negative

			School District of Philadelphia									
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	VENT COVER	METAL	BEIGE	INTACT	0	0.01	Negative
1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	DOOR CASING	METAL	TAN	INTACT	0	0.12	Negative
1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	PIPE COVER	METAL	BLACK	INTACT	0	0.1	Negative
1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	STALL WALL	TRANSITE	BROWN	INTACT	0	0	Negative
1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	DOOR	METAL	RED	INTACT	0	0.04	Negative
1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	DOOR CASING	METAL	RED	INTACT	0	0.01	Negative
1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	UNIVENT	METAL	WHITE	INTACT	0	0	Negative
1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	PIPE	METAL	WHITE	INTACT	0	0.25	Negative
1	1	126T	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 117	Yes	FLOOR	CONCRETE	GRAY	INTACT	0	0	Negative
1	1	138A	Storage	Gym Storage	Yes	W4	BRICK	WHITE	PEELING	0	< LOD	Negative
1	1	138A	Storage	Gym Storage	Yes	W1	CMU	WHITE	PEELING	0	< LOD	Negative
1	1	138A	Storage	Gym Storage	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	138A	Storage	Gym Storage	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	138A	Storage	Gym Storage	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	138A	Storage	Gym Storage	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	138A	Storage	Gym Storage	Yes	PIPE	METAL	BEIGE	INTACT	0	< LOD	Negative
1	1	138A	Storage	Gym Storage	Yes	CEILING	TRANSITE	BEIGE	INTACT	0	< LOD	Negative
1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W1	CMU	WHITE	Flaking	12	0.05	Negative
1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W2	CMU	WHITE	Flaking	12	< LOD	Negative
1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W3	CMU	WHITE	Flaking	12	0.05	Negative
1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W4	CMU	WHITE	Flaking	12	0.08	Negative
1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W1	CMU	RED	INTACT	0	< LOD	Negative
1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W2	CMU	RED	INTACT	0	< LOD	Negative
1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W3	CMU	RED	INTACT	0	< LOD	Negative
1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	W4	CMU	RED	INTACT	0	< LOD	Negative
	1	139	Gymnasium - Intermediate Middle	Gym	Yes	Ceiling	Concrete	White	INTACT	0	0.3	Negative
1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	VENT COVER	METAL	BLACK	INTACT	0	< LOD	Negative
1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	BACK BOARD SU	PLASTER	BLACK	INTACT	0	< LOD	Negative
1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	UNIVENT COVER	METAL	RED	INTACT	0	< LOD	Negative

						School District of Philadelphia						
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	UNIVENT COVER	METAL	RED	INTACT	0	< LOD	Negative
1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	PULL UP BAR SUR	WOOD	BLACK	INTACT	0	< LOD	Negative
1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	VENT COVER	METAL	RED	INTACT	0	< LOD	Negative
1	1	139	Gymnasium - Intermediate Middle	Gym	Yes	BULLETIN BOARD	CORK	RED	PEELING	0	< LOD	Negative
1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	W1	CMU	CLEAR	INTACT	0	< LOD	Negative
1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	W2	CMU	CLEAR	INTACT	0	< LOD	Negative
1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	W3	CMU	CLEAR	INTACT	0	< LOD	Negative
1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	W4	CMU	CLEAR	INTACT	0	< LOD	Negative
1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	FLOOR	CONCRETE	GRAY	INTACT	0	< LOD	Negative
1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	2.2	Positive
1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative
1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	HAND DRYER	METAL	BEIGE	INTACT	0	< LOD	Negative
1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	DOOR	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	1	139T	Student Restrooms - Male (4-12)	Boy's Restroom at Gym	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	W1	CMU	CLEAR	INTACT	0	< LOD	Negative
1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	W2	CMU	Beige	INTACT	0	1.3	Positive
1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	FLOOR	CONCRETE	GRAY	INTACT	0	< LOD	Negative
1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	UNIVENT COVER	METAL	BEIGE	INTACT	0	< LOD	Negative
1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	DOOR CASING	METAL	RED	INTACT	0	< LOD	Negative
1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	139T	Circulation (Hallway)	Hallway at Boy's Restroom at Gym	Yes	W4	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	139T PC	Pipe Chase	Boy's Restroom at Gym Pipe Chase	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	139T PC	Pipe Chase	Boy's Restroom at Gym Pipe Chase	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	139T PC	Pipe Chase	Boy's Restroom at Gym Pipe Chase	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	139T PC	Pipe Chase	Boy's Restroom at Gym Pipe Chase	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	139T PC	Pipe Chase	Boy's Restroom at Gym Pipe Chase	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	139T PC	Pipe Chase	Boy's Restroom at Gym Pipe Chase	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	139C	Service Closets	Custodial Storage in Boy's Restroom at Gym	No	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	139C	Service Closets	Custodial Storage in Boy's Restroom at Gym	No	W3	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	FLOOR	CONCRETE	GRAY	INTACT	0	< LOD	Negative

						School District of Philadelphia						
						Lead Safe Certification Assessment Report						
			Name of Inspector: Kristen Masotes									
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	2.6	Positive
1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	DOOR	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	DOOR CASING	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	HAND DRYER	METAL	BEIGE	INTACT	0	< LOD	Negative
1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative
1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	DOOR	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	PIPE	METAL	BEIGE	INTACT	0	< LOD	Negative
1	1	139G	Student Restrooms - Female (4-12)	Girl's Restroom at Gym	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	DOOR	METAL	RED	PEELING	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	DOOR CASING	METAL	RED	PEELING	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	UNIVENT	METAL	BEIGE	PEELING	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	DOOR	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	DUCT	METAL	BEIGE	PEELING	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	W4	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	139G	Circulation (Hallway)	Hallway at Girl's Restroom at Gym	Yes	PIPE	METAL	WHITE	INTACT	0	< LOD	Negative
1	1	151	Auditorium	Auditorium	Yes	W1	CMU	RED	INTACT	0	0.04	Negative
1	1	151	Auditorium	Auditorium	Yes	W2	CMU	RED	INTACT	0	< LOD	Negative
1	1	151	Auditorium	Auditorium	Yes	W3	CMU	BEIGE	INTACT	0	0.05	Negative
1	1	151	Auditorium	Auditorium	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	DOOR	METAL	RED	INTACT	0	< LOD	Negative
1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	DOOR CASING	METAL	RED	INTACT	0	< LOD	Negative

			School District of Philadelphia									
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	DOOR CENTER PANEL	METAL	RED	INTACT	0	< LOD	Negative
1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	WALL BASEBOARD	CONCRETE	BLACK	INTACT	0	< LOD	Negative
1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	WALL BASEBOARD	CONCRETE	BLACK	INTACT	0	< LOD	Negative
1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	STAIRS RAILING	METAL	BLACK	INTACT	0	< LOD	Negative
1	1	151	Auditorium	Auditorium Exit to Parking Lot	Yes	UNIVENT COVER	METAL	BEIGE	INTACT	0	< LOD	Negative
1	1	151S	Stage	Stage	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	151S	Stage	Stage	Yes	W1	CMU	BEIGE	INTACT	0	0.03	Negative
1	1	151S	Stage	Stage	Yes	W4	CMU	BLACK	INTACT	0	1	Positive
1	1	152/153	Administrative Office	Music practice Room to the right of Stage	Yes	W1	CMU	GREEN	INTACT	0	< LOD	Negative
1	1	152/153	Administrative Office	Music practice Room to the right of Stage	Yes	W2	CMU	GREEN	INTACT	0	< LOD	Negative
1	1	152/153	Administrative Office	Music practice Room to the right of Stage	Yes	W3	CMU	GREEN	INTACT	0	< LOD	Negative
1	1	P.1	Principal/Directors Office	Principal's Office	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	P.1	Principal/Directors Office	Principal's Office	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0.05	Negative
1	1	P.1	Principal/Directors Office	Principal's Office	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	1	P.1	Principal/Directors Office	Principal's Office	Yes	W4	CMU	BEIGE	INTACT	0	0.01	Negative
1	1	P.1	Principal/Directors Office	Principal's Office	Yes	UNIVENT	METAL	BLUE	INTACT	0	0.25	Negative
1	1	P.1	Principal/Directors Office	Principal's Office	Yes	W2	CMU	BEIGE	INTACT	0	0	Negative
1	1	P.1	Principal/Directors Office	Principal's Office	Yes	W3	CMU	BEIGE	INTACT	0	0.23	Negative
1	1	P.1	Principal/Directors Office	Principal's Office	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	1	P.1	Principal/Directors Office	Principal's Office	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0	Negative
1	1	P2	Storage	Principal's Office Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	P2	Storage	Principal's Office Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	P2	Storage	Principal's Office Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	P2	Storage	Principal's Office Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	P2	Storage	Principal's Office Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	P2	Storage	Principal's Office Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	P3	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.05	Negative
1	1	P3	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	W1	CMU	BEIGE	INTACT	0	0.15	Negative
1	1	P3	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	W2	CMU	BEIGE	INTACT	0	0.15	Negative
1	1	P3	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	W3	CMU	BEIGE	INTACT	0	0.05	Negative
1	1	P3	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	W4	CMU	BEIGE	INTACT	0	0.03	Negative

						School District of Philadelphia						
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	P3	Restrooms, Staff - Male/Female	Principal's Office Restroom	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.22	Negative
1	1	2	Administrative Office	Main Office	Yes	W1	CMU	WHITE	INTACT	0	0.06	Negative
1	1	2	Administrative Office	Main Office	Yes	W2	CMU	WHITE	INTACT	0	0.03	Negative
1	1	2	Administrative Office	Main Office	Yes	W3	CMU	WHITE	INTACT	0	0.04	Negative
1	1	2	Administrative Office	Main Office	Yes	W4	CMU	WHITE	INTACT	0	0.04	Negative
1	1	2	Administrative Office	Main Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative
1	1	2	Administrative Office	Main Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	1	2	Administrative Office	Main Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.17	Negative
1	1	2	Administrative Office	Main Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0	Negative
1	1	2	Administrative Office	Main Office	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.07	Negative
1	1	2	Administrative Office	Main Office	Yes	UNIVENT	METAL	WHITE	INTACT	0	0.3	Negative
1	1	2CL1	Storage	Main Office Closet 1 to the right of entrance	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2CL1	Storage	Main Office Closet 1 to the right of entrance	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2CL1	Storage	Main Office Closet 1 to the right of entrance	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2CL1	Storage	Main Office Closet 1 to the right of entrance	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2CL1	Storage	Main Office Closet 1 to the right of entrance	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2CL1	Storage	Main Office Closet 1 to the right of entrance	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2CL2	Storage	Main Office Closet to the left of doorway to Principal's Office from Main Office	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2CL2	Storage	Main Office Closet to the left of doorway to Principal's Office from Main Office	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2CL2	Storage	Main Office Closet to the left of doorway to Principal's Office from Main Office	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2CL2	Storage	Main Office Closet to the left of doorway to Principal's Office from Main Office	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2CL2	Storage	Main Office Closet to the left of doorway to Principal's Office from Main Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2CL2	Storage	Main Office Closet to the left of doorway to Principal's Office from Main Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2A	Administrative Office	Control Room next to Main Office	Yes	W1	CMU	Tan	Intact	0	0.5	Negative
1	1	2A	Administrative Office	Control Room next to Main Office	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2A	Administrative Office	Control Room next to Main Office	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2A	Administrative Office	Control Room next to Main Office	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2A	Administrative Office	Control Room next to Main Office	Yes	Ceiling Beam	Concrete	White	Intact	0	0.4	Negative
1	1	2A	Administrative Office	Control Room next to Main Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	3	Administrative Office	Vice Principal's Office - Room 3	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	3	Administrative Office	Vice Principal's Office - Room 3	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	3	Administrative Office	Vice Principal's Office - Room 3	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	3	Administrative Office	Vice Principal's Office - Room 3	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	3	Administrative Office	Vice Principal's Office - Room 3	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	3	Administrative Office	Vice Principal's Office - Room 3	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	4	Restrooms, Staff - Male	Men's Restroom to the right of Auditorium Entrance	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.03	Negative
1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.03	Negative
1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative

			School District of Philadelphia									
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W4	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	4.5	Restrooms, Staff - Female	Women's Restroom to the left of Auditorium Entrance	Yes	UNIVENT	METAL	BEIGE	INTACT	0	2.4	Positive
1	1	5	Administrative Office	Counselor's Office 5	Yes	W1	CMU	BEIGE	INTACT	0	0.05	Negative
1	1	5	Administrative Office	Counselor's Office 5	Yes	W2	CMU	BEIGE	INTACT	0	0.04	Negative
1	1	5	Administrative Office	Counselor's Office 5	Yes	W3	CMU	BEIGE	INTACT	0	0.04	Negative
1	1	5	Administrative Office	Counselor's Office 5	Yes	W4	CMU	BEIGE	INTACT	0	0.05	Negative
1	1	5	Administrative Office	Counselor's Office 5	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.18	Negative
1	1	5	Administrative Office	Counselor's Office 5	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.16	Negative
1	1	5	Administrative Office	Counselor's Office 5	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.1	Negative
1	1	5	Administrative Office	Counselor's Office 5	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.04	Negative
1	1	5	Administrative Office	Counselor's Office 5	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.17	Negative
1	1	5.5T	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Yes	W1	CMU	TAN	INTACT	0	0.3	Negative
1	1	5.5T	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	5.5T	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	5.5T	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	5.5T	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	5.5T	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	5W	Circulation (Hallway)	Waiting Room at Nurse's Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	1	Positive
1	1	5W	Circulation (Hallway)	Waiting Room at Nurse's Office	Yes	W4	CMU	BLACK	INTACT	0	0.03	Negative
1	1	5W	Circulation (Hallway)	Waiting Room at Nurse's Office	Yes	W3	CMU	BLACK	INTACT	0	0.06	Negative
1	1	5W	Circulation (Hallway)	Waiting Room at Nurse's Office	Yes	W2	CMU	BLACK	INTACT	0	0	Negative
1	1	5W	Circulation (Hallway)	Waiting Room at Nurse's Office	Yes	W1	CMU	BLACK	INTACT	0	0	Negative
1	1	6	Health Service Room	Nurse's Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	1	6	Health Service Room	Nurse's Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative

			School District of Philadelphia									
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	6	Health Service Room	Nurse's Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative
	1	6	Health Service Room	Nurse's Office	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	6	Health Service Room	Nurse's Office	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative
1	1	6	Health Service Room	Nurse's Office	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative
1	1	6	Health Service Room	Nurse's Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0	Negative
1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.07	Negative
1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative
1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative
1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	W2	CMU	BEIGE	INTACT	0	0.01	Negative
1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative
1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative
1	1	6B	Health Service Room	Nurse's Office - Exam Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.04	Negative
1	1	6.5	Student Restrooms - Male/Female	Nurse's Office Restroom	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.03	Negative
1	1	6.5	Student Restrooms - Male/Female	Nurse's Office Restroom	Yes	W1	CMU	BEIGE	INTACT	0	0.08	Negative
1	1	6.5	Student Restrooms - Male/Female	Nurse's Office Restroom	Yes	W4	CMU	BEIGE	INTACT	0	0.05	Negative
1	1	6.5	Student Restrooms - Male/Female	Nurse's Office Restroom	Yes	W3	CMU	BEIGE	INTACT	0	0.02	Negative
1	1	6.5	Student Restrooms - Male/Female	Nurse's Office Restroom	Yes	W4	CMU	BEIGE	INTACT	0	0.04	Negative
1	1	6.5	Student Restrooms - Male/Female	Nurse's Office Restroom	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.05	Negative
1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W1	CMU	YELLOW	INTACT	0	< LOD	Negative
1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W2	CMU	YELLOW	INTACT	0	< LOD	Negative
1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W3	CMU	YELLOW	INTACT	0	< LOD	Negative
1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W4	CMU	YELLOW	INTACT	0	< LOD	Negative
1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	W1	CMU	BEIGE	INTACT	0	0.4	Negative
1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	SHELF	WOOD	YELLOW	INTACT	0	< LOD	Negative
1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	SHELF SUPPORT	WOOD	YELLOW	INTACT	0	< LOD	Negative
1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	CABINET	METAL	YELLOW	INTACT	0	< LOD	Negative
1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	SINK	CERAMIC	YELLOW	INTACT	0	< LOD	Negaive

			School District of Philadelphia									
			Name of Inspector: Kristen Masotes				Lead Safe Certification Assessment Report					
			Inspection Company: Acer Associates				Spruance School					
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	FLOOR	CONCRETE	GRAY	INTACT	0	< LOD	Negative
	1	7	Service Closets	Custodial Storage next to Women's Restroom in Hallway	No	Ceiling	CONCRETE	White	INTACT	0	0.4	Negative
1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	Ceiling	CONCRETE	WHITE	INTACT	0	0.04	Negative
1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W1	CMU	BLUE	INTACT	0	0.11	Negative
1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative
1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W3	CMU	BLUE	INTACT	0	0.06	Negative
1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative
1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W4	CMU	WHITE	INTACT	0	0.1	Negative
1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	WINDOW SILL	SLATE	BLACK	INTACT	0	< LOD	Negative
1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	W1	CMU	WHITE	INTACT	0	0.04	Negative
1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	8	Teacher Lounge/Dining	Teacher Dining Area	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	1.4	Positive
1	1	9	Kitchen	Kitchen	Yes	Ceiling	CONCRETE	BEIGE	INTACT	0	0	Negative
1	1	9	Kitchen	Kitchen	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	9	Kitchen	Kitchen	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	9	Kitchen	Kitchen	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	9	Kitchen	Kitchen	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	9	Kitchen	Kitchen	Yes	DOOR PANEL	METAL	RED	INTACT	0	1.1	Positive
1	1	9	Kitchen	Kitchen	Yes	DOOR PANEL	METAL	RED	INTACT	0	1.7	Positive
1	1	9	Kitchen	Kitchen	Yes	WALL BASEBOAR	TRANSITE	GRAY	PEELING	0	< LOD	Negative
1	1	9	Kitchen	Kitchen	Yes	WALL BASEBOAR	TRANSITE	GRAY	PEELING	0	< LOD	Negative
1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	1.4	Positive
1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative
1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative
1	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	WINDOW CASING	METAL	BEIGE	INTACT	0	< LOD	Negative
	1	10	Cafeteria (Dining Area)	Cafeteria	Yes	Ceiling	CONCRETE	White	INTACT	0	0.4	Negative
1	1	10A	Administrative Office	Kitchen Office	Yes	Ceiling	CONCRETE	BEIGE	INTACT	0	0	Negative

			School District of Philadelphia									
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	10A	Administrative Office	Kitchen Office	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	10A	Administrative Office	Kitchen Office	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	10A	Administrative Office	Kitchen Office	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	10A	Administrative Office	Kitchen Office	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	10A	Administrative Office	Kitchen Office	Yes	DOOR	METAL	RED	INTACT	0	0.8	Positive
1	1	10A	Administrative Office	Kitchen Office	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	1	10A	Administrative Office	Kitchen Office	Yes	COLUMN	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	1	11	Administrative Office	Gym Office	Yes	W1	CMU	BEIGE	INTACT	0	0.04	Negative
1	1	11	Administrative Office	Gym Office	Yes	W4	CMU	BEIGE	INTACT	0	0.03	Negative
1	1	11	Administrative Office	Gym Office	Yes	W3	CMU	BEIGE	INTACT	0	0.03	Negative
1	1	11	Administrative Office	Gym Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative
1	1	11	Administrative Office	Gym Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	1	11	Administrative Office	Gym Office	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.06	Negative
1	1	11	Administrative Office	Gym Office	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.07	Negative
1	1	11	Administrative Office	Gym Office	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.06	Negative
1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	CEILING	CONCRETE	BEIGE	INTACT	0	0.04	Negative
1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	W1	CMU	BEIGE	INTACT	0	0.03	Negative
1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	W2	CMU	BEIGE	INTACT	0	0.03	Negative
1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	W3	CMU	BEIGE	INTACT	0	0.04	Negative
1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	W4	CMU	BEIGE	INTACT	0	0.05	Negative
1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative
1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative
1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative
1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	1	16A	Restrooms, Staff - Male/Female	Gym Office Restroom	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.03	Negative
1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	W1	CMU	BEIGE	INTACT	0	0.06	Negative
1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	W3	CMU	BEIGE	INTACT	0	0.05	Negative
1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.07	Negative
1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	WALL BASEBOAR	TRANSITE	TAN	PEELING	0	< LOD	Negative

			School District of Philadelphia									
			Lead Safe Certification Assessment Report									
			Spruance School									
			Name of Inspector: Kristen Masotes									
			Inspection Company: Acer Associates									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	WALL BASEBOAR	TRANSITE	TAN	PEELING	0	< LOD	Negative
	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	Ceiling	Concrete	White	Intact	0	0.4	Negative
1	1	12	Restrooms, Staff - Male/Female	Kitchen Area Locker Room	Yes	UNIVENT	METAL	TAN	PEELING	0	< LOD	Negaive
1	1	13	Storage	Freezer Room by Kitchen	Yes	W1	BRICK	BEIGE	INTACT	0	0.2	Negative
1	1	13	Storage	Freezer Room by Kitchen	Yes	W2	CMU	BEIGE	INTACT	0	0.23	Negative
1	1	13	Storage	Freezer Room by Kitchen	Yes	W4	CMU	BEIGE	PEELING	0	0.26	Negative
1	1	13	Storage	Freezer Room by Kitchen	Yes	W3	CMU	BEIGE	PEELING	0	0.28	Negative
1	1	13	Storage	Freezer Room by Kitchen	Yes	FLOOR	CONCRETE	GRAY	PEELING	0	< LOD	Negative
1	1	13	Storage	Freezer Room by Kitchen	Yes	WALL BASEBOAR	CMU	GRAY	PEELING	0	0.3	Negative
1	1	13	Storage	Freezer Room by Kitchen	Yes	WALL BASEBOAR	CMU	GRAY	PEELING	0	0.3	Negative
1	1	13	Storage	Freezer Room by Kitchen	Yes	DOOR	METAL	BROWN	PEELING	0	< LOD	Negative
1	1	13	Storage	Freezer Room by Kitchen	Yes	DOOR CASING	METAL	BROWN	PEELING	0	< LOD	Negaive
1	1	13	Storage	Freezer Room by Kitchen	Yes	DOOR STOP	METAL	BROWN	INTACT	0	< LOD	Negaive
1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	W4	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	W3	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	COLUMN	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	COLUMN	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	COLUMN	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	1	14	Mechanical Room	Air Handler Room across from Gym and along the Auditorium Hallway	No	CEILING	CONCRETE	WHITE	PEELING	0	< LOD	Negative
1	1	15	Administrative Office	Home & School Office along Auditorium Hallway	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15	Administrative Office	Home & School Office along Auditorium Hallway	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15	Administrative Office	Home & School Office along Auditorium Hallway	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15	Administrative Office	Home & School Office along Auditorium Hallway	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15	Administrative Office	Home & School Office along Auditorium Hallway	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15	Administrative Office	Home & School Office along Auditorium Hallway	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15R	Restrooms, Staff - Male/Female	Home & School Office Restroom	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15R	Restrooms, Staff - Male/Female	Home & School Office Restroom	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15R	Restrooms, Staff - Male/Female	Home & School Office Restroom	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15R	Restrooms, Staff - Male/Female	Home & School Office Restroom	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15R	Restrooms, Staff - Male/Female	Home & School Office Restroom	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15R	Restrooms, Staff - Male/Female	Home & School Office Restroom	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access

						School District of Philadelphia						
						Lead Safe Certification Assessment Report						
			Name of Inspector: Kristen Masotes									
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	Ceiling	CONCRETE	WHITE	INTACT	0	0.03	Negative
1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	DOOR	METAL	RED	PEELING	0	< LOD	Negative
1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	DOOR CASING	METAL	RED	PEELING	0	< LOD	Negative
1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	DOOR CENTER PO	METAL	RED	PEELING	0	< LOD	Negative
1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	0.3	Positive
1	1	H106	Circulation (Hallway)	Hallway next to Classroom 111	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	1.4	Positive
1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	W1	CMU	BEIGE	INTACT	0	0.04	Negative
1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	W2	CMU	BEIGE	INTACT	0	0.04	Negative
1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	W3	CMU	BEIGE	INTACT	0	0.02	Negative
1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	W4	CMU	BEIGE	INTACT	0	0.02	Negative
1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	UNIVENT	METAL	BROWN	INTACT	0	0.04	Negative
1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	DOOR	METAL	TAN	INTACT	0	0.14	Negative
1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	DOOR CASING	METAL	TAN	INTACT	0	0.03	Negative
1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	ELEC PANEL COV	METAL	BEIGE	INTACT	0	0.09	Negative
1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	UNIVENT	METAL	BROWN	INTACT	0	0.01	Negative
1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	PIPE COVER	METAL	BEIGE	INTACT	0	0.06	Negative
1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	DOOR	METAL	RED	INTACT	0	0.11	Negative
1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	DOOR CENTER PO	METAL	RED	INTACT	0	0	Negative
1	1	H11	Circulation (Hallway)	Hallway at Classrooms 117 to 124	Yes	DOOR CASING	METAL	RED	INTACT	0	0.01	Negative
1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	CEILING	CONCRETE	BEIGE	INTACT	0	0	Negative
1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	W3	CMU	BEIGE	INTACT	0	0.02	Negative
1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative
1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative
1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	DOOR CASING	METAL	TAN	INTACT	0	0.13	Negative
1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	UNIVENT	METAL	BROWN	INTACT	0	0.01	Negative
1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	PIPE JACKET	METAL	BEIGE	INTACT	0	3.3	Positive
1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative
1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.07	Negative
1	1	H12	Circulation (Hallway)	Hallway at Classrooms 108 to 115	Yes	CONDUIT	METAL	BEIGE	INTACT	0	0	Negative
1	1	H139	Circulation (Hallway)	Walkway at Boy's Restroom by Gym	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	H139	Circulation (Hallway)	Walkway at Boy's Restroom by Gym	Yes	W2	CMU	WHITE	Flaking	5	< LOD	Negative
1	1	H139	Circulation (Hallway)	Walkway at Boy's Restroom by Gym	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	H139	Circulation (Hallway)	Walkway at Boy's Restroom by Gym	Yes	W4	CMU	WHITE	Flaking	5	< LOD	Negative
1	1	H139	Circulation (Hallway)	Walkway at Boy's Restroom by Gym	Yes	W1	CMU	CLEAR	INTACT	0	< LOD	Negative
1	1	H139	Circulation (Hallway)	Walkway at Boy's Restroom by Gym	Yes	W2	CMU	BEIGE	INTACT	0	1.3	Positive
	1	H139	Circulation (Hallway)	Walkway at Boy's Restroom by Gym		Ceiling	Concrete	White	None	0	0.4	Negative
1	1	H139	Circulation (Hallway)	Walkway at Boy's Restroom by Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	H139	Circulation (Hallway)	Walkway at Boy's Restroom by Gym	Yes	FLOOR	CONCRETE	GRAY	INTACT	0	< LOD	Negative
1	1	H139	Circulation (Hallway)	Walkway at Boy's Restroom by Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative

						School District of Philadelphia						
						Lead Safe Certification Assessment Report						
			Name of Inspector: Kristen Masotes									
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	H139	Circulation (Hallway)	Walkway at Boy's Restroom by Gym	Yes	UNIVENT COVER	METAL	BEIGE	INTACT	0	< LOD	Negative
1	1	H139	Circulation (Hallway)	Walkway at Boy's Restroom by Gym	Yes	DOOR CASING	METAL	RED	INTACT	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	W2	CMU	BEIGE	Flaking	5	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	W4	CMU	BEIGE	Flaking	5	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	WALL BASEBOAR	TRANSITE	BLACK	PEELING	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym		Ceiling	Concrete	White	None	0	0.4	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	DOOR	METAL	RED	PEELING	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	DOOR CASING	METAL	RED	PEELING	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	UNIVENT	METAL	BEIGE	PEELING	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	DOOR	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	DUCT	METAL	BEIGE	PEELING	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	W4	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	H139.5	Circulation (Hallway)	Walkway at Girl's Restroom by Gym	Yes	PIPE	METAL	WHITE	INTACT	0	< LOD	Negative
1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	Ceiling	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative
1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.04	Negative
1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	PIPE	METAL	WHITE	INTACT	0	0.12	Negative
1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	DOOR	METAL	GREEN	INTACT	0	0.03	Negative
1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	DOOR CENTER PC	METAL	GREEN	INTACT	0	0.01	Negative
1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	DOOR CASING	METAL	GREEN	INTACT	0	0	Negative
1	1	H151	Circulation (Hallway)	Hallway along left side of Auditorium	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.08	Negative
1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	W2	CMU	BEIGE	INTACT	0	0	Negative
1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative
1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative
1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative
1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.04	Negative
1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	PIPE	METAL	WHITE	INTACT	0	0.12	Negative
1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	DOOR	METAL	GREEN	INTACT	0	0.03	Negative
1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	DOOR CENTER PC	METAL	GREEN	INTACT	0	0.01	Negative

						School District of Philadelphia						
						Lead Safe Certification Assessment Report						
			Name of Inspector: Kristen Masotes									
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	DOOR CASING	METAL	GREEN	INTACT	0	0	Negative
1	1	H151.A	Circulation (Hallway)	Hallway across from Kitchen along Auditorium	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.08	Negative
1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	W2	CMU	BEIGE	INTACT	0	0	Negative
1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative
1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative
1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.01	Negative
1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.04	Negative
1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	PIPE	METAL	WHITE	INTACT	0	0.12	Negative
1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	DOOR	METAL	GREEN	INTACT	0	0.03	Negative
1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	DOOR CENTER PC	METAL	GREEN	INTACT	0	0.01	Negative
1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	DOOR CASING	METAL	GREEN	INTACT	0	0	Negative
1	1	H14	Circulation (Hallway)	Hallway at Kitchen and Cafeteria	Yes	UNIVENT	METAL	BEIGE	INTACT	0	0.08	Negative
1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	W1	CMU	YELLOW	INTACT	0	0	Negative
1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	W3	CMU	YELLOW	INTACT	0	0.03	Negative
1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	W2	CMU	YELLOW	INTACT	0	0	Negative
1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative
1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.05	Negative
1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.05	Negative
1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.04	Negative
1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	UNIVENT	METAL	BROWN	INTACT	0	0.03	Negative
1	1	H15	Circulation (Hallway)	Hallway at Main Entrance	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.09	Negative
1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	W1	CMU	BEIGE	INTACT	0	0	Negative
1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	W2	CMU	BEIGE	INTACT	0	0	Negative
1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative
1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.02	Negative
1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.05	Negative
1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	DOOR CASING	METAL	BROWN	INTACT	0	0.11	Negative
1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	UNIVENT	METAL	BROWN	INTACT	0	0.02	Negative
1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	PIPE JACKET	METAL	BEIGE	INTACT	0	3.8	Positive
1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	ELEC PANEL	METAL	BEIGE	INTACT	0	0.23	Negative
1	1	H16	Circulation (Hallway)	Hallway at Classrooms 100 to 107	Yes	CEILING	CONCRETE	BEIGE	INTACT	0	0	Negative
1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	CEILING COLUMN	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120		Ceiling Beam	Concrete	White	Intact	0	0.2	Negative
1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	W1	TRANSITE	BLACK	INTACT	0	0.04	Negative
1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	W2	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	1.1	Positive

			School District of Philadelphia									
			Lead Safe Certification Assessment Report									
			Spruance School									
			Name of Inspector: Kristen Masotes									
			Inspection Company: Acer Associates									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	H19	Circulation (Hallway)	Hallway at Classrooms 118 & 120	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative
1	1	S11	Stairs	Stairwell at Gym	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S11	Stairs	Stairwell at Gym	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S11	Stairs	Stairwell at Gym	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S11	Stairs	Stairwell at Gym	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S11	Stairs	Stairwell at Gym	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S11	Stairs	Stairwell at Gym	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.12	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.11	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	HALF WALL	TRANSITE	BEIGE	INTACT	0	< LOD	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W4	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	W2	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	STAIRS STRINGER	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	WALL BASEBOAR	CONCRETE	BLACK	INTACT	0	0.08	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	STAIRS RISER	CONCRETE	BLACK	INTACT	0	0.04	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	STAIRS RISER	CONCRETE	BLACK	INTACT	0	< LOD	Negative
1	1	S12	Stairs	Stairwell next to Classroom 110	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	1	Positive
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	W1	BRICK	BEIGE	INTACT	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	W3	CMU	BEIGE	INTACT	0	1	Positive
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	WALL BASEBOAR	CONCRETE	TAN	PEELING	0	0.04	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	WALL BASEBOAR	CONCRETE	TAN	PEELING	0	1.1	Positive
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	DOOR	METAL	TAN	PEELING	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	DOOR CASING	METAL	TAN	PEELING	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	DOOR CASING	METAL	TAN	PEELING	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	DOOR	METAL	TAN	PEELING	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	DOOR CASING	METAL	TAN	PEELING	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	DOOR CASING	METAL	RED	PEELING	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	DOOR CENTER P	METAL	RED	PEELING	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	DOOR	METAL	RED	PEELING	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	UNIVENT	METAL	BROWN	PEELING	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative

							School District of Philadelphia					
							Lead Safe Certification Assessment Report					
			Name of Inspector: Kristen Masotes				Spruance School					
			Inspection Company: Acer Associates									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S13	Stairs	Stairwell next to Classroom 119	Yes	STAIRS STRINGER	CONCRETE	TAN	INTACT	0	0.03	Negative
1	1	S14	Stairs	Stairwell next to Classroom 115	Yes	DOOR CASING	METAL	TAN	INTACT	0	0.09	Negative
1	1	S14	Stairs	Stairwell next to Classroom 115	Yes	DOOR	METAL	TAN	INTACT	0	0.09	Negative
1	1	S14	Stairs	Stairwell next to Classroom 115	Yes	W1	CMU	BEIGE	INTACT	0	0.01	Negative
1	1	S14	Stairs	Stairwell next to Classroom 115	Yes	W2	CMU	BEIGE	INTACT	0	0.04	Negative
1	1	S14	Stairs	Stairwell next to Classroom 115	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative
1	1	S14	Stairs	Stairwell next to Classroom 115	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.07	Negative
1	1	S14	Stairs	Stairwell next to Classroom 115	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.07	Negative
1	1	S14	Stairs	Stairwell next to Classroom 115	Yes	STAIRS STRINGER	TRANSITE	BLACK	INTACT	0	0.07	Negative
1	1	S14	Stairs	Stairwell next to Classroom 115	Yes	STAIRS RISER	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	1	S14	Stairs	Stairwell next to Classroom 115	Yes	HALF WALL	CONCRETE	BEIGE	INTACT	0	0.02	Negative
1	1	S14	Stairs	Stairwell next to Classroom 115	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative
1	1	S14	Stairs	Stairwell next to Classroom 115	Yes	STAIRS RISER	CONCRETE	BLACK	INTACT	0	1	Positive
1	1	S14	Stairs	Stairwell next to Classroom 115	Yes	STAIRS STRINGER	TRANSITE	BLACK	INTACT	0	0.05	Negative
1	1	S14	Stairs	Stairwell next to Classroom 115	Yes	HALF WALL	CONCRETE	BEIGE	INTACT	0	0.01	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	CEILING	CONCRETE	WHITE	PEELING	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	1.1	Positive
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	DOOR	METAL	TAN	PEELING	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	DOOR CASING	METAL	TAN	PEELING	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	PIPE JACKET	METAL	BEIGE	INTACT	0	2.2	Positive
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	DOOR	METAL	GREEN	INTACT	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	DOOR CASING	METAL	GREEN	INTACT	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	DOOR	WOOD	BROWN	INTACT	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	DOOR CASING	METAL	BROWN	INTACT	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	STAIRS RISER	CONCRETE	BLACK	INTACT	0	0.05	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	STAIRS STRINGER	CONCRETE	BLACK	INTACT	0	0.09	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	STAIRS HALFVAL	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	1	S14X	Stairs	Stairwell near Classroom 101	Yes	STAIRS HALFVAL	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative

						School District of Philadelphia						
						Lead Safe Certification Assessment Report						
			Name of Inspector: Kristen Masotes			Spruance School						
			Inspection Company: Acer Associates									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.07	Negative
1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	STAIRS RISER	CONCRETE	BLACK	INTACT	0	< LOD	Negative
1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	STAIRS STRINGER	TRANSITE	BLACK	INTACT	0	0.13	Negative
1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	STAIR HALF WALL	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	DOOR	METAL	TAN	INTACT	0	< LOD	Negative
1	1	S15	Stairs	Stairwell near Restrooms by Classroom 117	Yes	CEILING	CONCRETE	WHITE	PEELING	0	< LOD	Negative
1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	W1	CMU	BEIGE		0	< LOD	Negative
1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	W2	CMU	BEIGE		0	< LOD	Negative
1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	W3	CMU	BEIGE		0	< LOD	Negative
1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	W4	CMU	BEIGE		0	< LOD	Negative
	1	S16	Stairs	Stairwell between Classrooms 118 & 120		CEILING	CONCRETE	WHITE	None	0	0.3	Negative
1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	DOOR	METAL	RED		0	< LOD	Negative
1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	DOOR CENTER PANEL	METAL	RED		0	< LOD	Negative
1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	DOOR CASING	METAL	RED		0	< LOD	Negative
1	1	S16	Stairs	Stairwell between Classrooms 118 & 120	Yes	UNIVENT COVER	METAL	BROWN		0	< LOD	Negative
1	2	200	Primary	Classroom 200	Yes	UNIVENT CABINET	METAL	TAN	INTACT	0	< LOD	Negative
1	2	200	Primary	Classroom 200	Yes	UNIVENT	METAL	BLUE	INTACT	0	< LOD	Negative
1	2	200	Primary	Classroom 200	Yes	W1	CMU	ORANGE	INTACT	0	< LOD	Negative
1	2	200	Primary	Classroom 200	Yes	W1	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	200	Primary	Classroom 200	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	200	Primary	Classroom 200	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	200	Primary	Classroom 200	Yes	W2	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	200	Primary	Classroom 200	Yes	W3	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	200	Primary	Classroom 200	Yes	W3	CMU	ORANGE	INTACT	0	< LOD	Negative
1	2	200	Primary	Classroom 200	Yes	W4	CMU	ORANGE	INTACT	0	< LOD	Negative
1	2	200	Primary	Classroom 200	Yes	W4	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	200	Primary	Classroom 200	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	200	Primary	Classroom 200	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	200	Primary	Classroom 200	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	< LOD	Negative
	2	200	Primary	Classroom 200	Yes	Ceiling	Concrete	White	INTACT	0	0.4	Negative
1	2	200S	Primary	Classroom 200S	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	200S	Primary	Classroom 200S	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	200S	Primary	Classroom 200S	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	200S	Primary	Classroom 200S	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	200S	Primary	Classroom 200S	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	2	201	Primary	Classroom 201	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	201	Primary	Classroom 201	Yes	W1	CMU	YELLOW	INTACT	0	< LOD	Negative
1	2	201	Primary	Classroom 201	Yes	W2	CMU	YELLOW	INTACT	0	< LOD	Negative
1	2	201	Primary	Classroom 201	Yes	W4	CMU	YELLOW	INTACT	0	0.04	Negative
1	2	201	Primary	Classroom 201	Yes	W3	CMU	YELLOW	INTACT	0	< LOD	Negative
1	2	201	Primary	Classroom 201	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	201	Primary	Classroom 201	Yes	CHALKBOARD FRAME	WOOD	CLEAR	INTACT	0	< LOD	Negative
1	2	201	Primary	Classroom 201	Yes	DOOR CASING	WOOD	CLEAR	INTACT	0	< LOD	Negative
1	2	201	Primary	Classroom 201	Yes	DOOR	WOOD	CLEAR	INTACT	0	< LOD	Negative

						School District of Philadelphia						
						Lead Safe Certification Assessment Report						
			Name of Inspector: Kristen Masotes									
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	201	Primary	Classroom 201 Closet	Yes	CEILING	TRANSITE	YELLOW	INTACT	0	0.03	Negative
1	2	201	Primary	Classroom 201	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	201	Primary	Classroom 201	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	201	Primary	Classroom 201	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	2	201	Primary	Classroom 201	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative
1	2	201S	Primary	Classroom 201S	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	201S	Primary	Classroom 201S	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	2	201S	Primary	Classroom 201S	Yes	W4	CMU	WHITE	INTACT	0	< LOD	Negative
1	2	201S	Primary	Classroom 201S	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	2	201S	Primary	Classroom 201S	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative
1	2	201S	Primary	Classroom 201S	Yes	W1	CMU	GRAY	INTACT	0	< LOD	Negative
1	2	201S	Primary	Classroom 201S	Yes	W2	CMU	GRAY	INTACT	0	< LOD	Negative
1	2	201S	Primary	Classroom 201S	Yes	W4	CMU	GRAY	INTACT	0	< LOD	Negative
1	2	201S	Primary	Classroom 201S	Yes	W3	CMU	GRAY	INTACT	0	< LOD	Negative
1	2	201S	Primary	Classroom 201S	Yes	COLUMN	CONCRETE	BLUE	INTACT	0	< LOD	Negative
1	2	202	Primary	Classroom 202	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.4	Negative
	2	202	Primary	Classroom 202	Yes	CEILING BEAM	CONCRETE	WHITE	INTACT	0	0.4	Negative
1	2	202	Primary	Classroom 202	Yes	W1	CMU	GREEN	INTACT	0	0.04	Negative
1	2	202	Primary	Classroom 202	Yes	W2	CMU	GREEN	INTACT	0	0.05	Negative
1	2	202	Primary	Classroom 202	Yes	W3	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	202	Primary	Classroom 202	Yes	W4	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	202	Primary	Classroom 202	Yes	CHALKBOARD FR	WOOD	CLEAR	INTACT	0	< LOD	Negative
1	2	202	Primary	Classroom 202	Yes	DOOR CASING	WOOD	CLEAR	INTACT	0	< LOD	Negative
1	2	202	Primary	Classroom 202	Yes	DOOR	WOOD	CLEAR	INTACT	0	< LOD	Negative
1	2	202	Primary	Classroom 202	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	202	Primary	Classroom 202	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	202	Primary	Classroom 202	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	2	202	Primary	Classroom 202	Yes	CHALKBOARD FR	TRANSITE	CLEAR	INTACT	0	< LOD	Negative
1	2	202	Primary	Classroom 202	Yes	UNIVENT	METAL	INTACT	Flaking	0	< LOD	Negative
1	2	202	Primary	Classroom 202 Closet	Yes	CEILING	TRANSITE	GREEN	INTACT	0	< LOD	Negative
1	2	203	Primary	Classroom 203	Yes	W1	CMU	BLUE	INTACT	0	0.08	Negative
1	2	203	Primary	Classroom 203	Yes	W2	CMU	BLUE	INTACT	0	0.5	Negative
1	2	203	Primary	Classroom 203	Yes	W4 BASEBOARD	TRANSITE	BLACK	INTACT	0	1	Positive
1	2	203	Primary	Classroom 203	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	2	203	Primary	Classroom 203	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative
1	2	203	Storage	Classroom 203	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	204	Primary	Classroom 204	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	204	Primary	Classroom 204	Yes	W1	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	204	Primary	Classroom 204	Yes	W2	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	204	Primary	Classroom 204	Yes	W3	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	204	Primary	Classroom 204	Yes	W4	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	204	Primary	Classroom 204	Yes	W4	CMU	DARK GREEN	INTACT	0	< LOD	Negative
1	2	204	Primary	Classroom 204	Yes	W3	CMU	DARK GREEN	INTACT	0	< LOD	Negative
1	2	204	Primary	Classroom 204	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	2	204	Primary	Classroom 204	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative

							School District of Philadelphia					
			Name of Inspector: Kristen Masotes				Lead Safe Certification Assessment Report					
			Inspection Company: Acer Associates				Spruance School					
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	204	Primary	Classroom 204	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	204	Primary	Classroom 204	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	204	Primary	Classroom 204	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	204	Primary	Classroom 204	Yes	CHALKBOARD FR	WOOD	CLEAR	INTACT	0	< LOD	Negative
1	2	204	Primary	Classroom 204	Yes	DOOR CASING	WOOD	CLEAR	INTACT	0	< LOD	Negative
1	2	204	Primary	Classroom 204 Closet	Yes	CEILING	TRANSITE	GREEN	INTACT	0	< LOD	Negative
1	2	205	Primary	Classroom 205	Yes	W1	CMU	YELLOW	INTACT	0	< LOD	Negative
1	2	205	Primary	Classroom 205	Yes	W2	CMU	YELLOW	INTACT	0	< LOD	Negative
1	2	205	Primary	Classroom 205	Yes	W3	CMU	YELLOW	INTACT	0	0.04	Negative
1	2	205	Primary	Classroom 205	Yes	W4	CMU	YELLOW	INTACT	0	0.05	Negative
1	2	205	Primary	Classroom 205	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	205	Primary	Classroom 205	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	205	Primary	Classroom 205	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	205	Primary	Classroom 205	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	2	205	Primary	Classroom 205	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative
1	2	205	Primary	Classroom 205	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.3	Negative
1	2	206	Primary	Classroom 206	Yes	UNIVENT CABINE	METAL	GRAY	INTACT	0	< LOD	Negative
1	2	206	Primary	Classroom 206	Yes	UNIVENT	METAL	GRAY	INTACT	0	< LOD	Negative
1	2	206	Primary	Classroom 206	Yes	W3	CMU	GRAY	INTACT	0	0.05	Negative
1	2	206	Primary	Classroom 206	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	206	Primary	Classroom 206	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	206	Primary	Classroom 206	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	206	Primary	Classroom 206	Yes	W2	CMU	GRAY	INTACT	0	< LOD	Negative
1	2	206	Primary	Classroom 206	Yes	W1	CMU	GRAY	INTACT	0	< LOD	Negative
1	2	206	Primary	Classroom 206	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	206	Primary	Classroom 206	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	206	Primary	Classroom 206	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	206	Primary	Classroom 206	Yes	W1	CMU	GREEN	INTACT	0	0.1	Negative
1	2	206	Primary	Classroom 206	Yes	W2	CMU	GREEN	INTACT	0	0.1	Negative
1	2	206	Primary	Classroom 206	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	207	Primary	Classroom 207	Yes	W1	CMU	PURPLE	INTACT	0	0.4	Negative
1	2	207	Primary	Classroom 207	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	207	Primary	Classroom 207	Yes	W3	CMU	PURPLE	INTACT	0	< LOD	Negative
1	2	207	Primary	Classroom 207	Yes	W4	CMU	PURPLE	INTACT	0	0.06	Negative
1	2	207	Primary	Classroom 207	Yes	W4	CMU	GRAY	INTACT	0	0.04	Negative
1	2	207	Primary	Classroom 207	Yes	W1	CMU	GRAY	INTACT	0	0.05	Negative
1	2	207	Primary	Classroom 207	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	207	Primary	Classroom 207	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	207	Primary	Classroom 207	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	207	Primary	Classroom 207	Yes	UNIVENT	METAL	BLUE	INTACT	0	< LOD	Negative
1	2	207	Primary	Classroom 207	Yes	UNIVENT CABINE	METAL	BLUE	INTACT	0	< LOD	Negative
1	2	207	Primary	Classroom 207	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.3	Negative
1	2	207CL	Storage	Classroom 207 Closet	Yes	CEILING	TRANSITE	BLUE	INTACT	0	< LOD	Negative
1	2	208	Primary	Classroom 208	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	208	Primary	Classroom 208	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative

						School District of Philadelphia						
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	208	Primary	Classroom 208	Yes	W3	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	208	Primary	Classroom 208	Yes	W4	CMU	BLUE	INTACT	0	0.06	Negative
1	2	208	Primary	Classroom 208	Yes	W4	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	208	Primary	Classroom 208	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	208	Primary	Classroom 208	Yes	W1	CMU	GREEN	INTACT	0	0.04	Negative
1	2	208	Primary	Classroom 208	Yes	W2	CMU	GREEN	INTACT	0	0.09	Negative
1	2	208	Primary	Classroom 208	Yes	W3	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	208	Primary	Classroom 208	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	208	Primary	Classroom 208	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	208	Primary	Classroom 208	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	2	208	Primary	Classroom 208	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative
1	2	208	Primary	Classroom 208	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	208CL	Storage	Classroom 208 Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208CL	Storage	Classroom 208 Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208CL	Storage	Classroom 208 Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208CL	Storage	Classroom 208 Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208CL	Storage	Classroom 208 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208CL	Storage	Classroom 208 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	209	Primary	Classroom 209	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	209	Primary	Classroom 209	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	209	Primary	Classroom 209	Yes	W3	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	209	Primary	Classroom 209	Yes	W3	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	209	Primary	Classroom 209	Yes	W4	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	209	Primary	Classroom 209	Yes	W1	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	209	Primary	Classroom 209	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	209	Primary	Classroom 209	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.04	Negative
1	2	209	Primary	Classroom 209	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	209CL	Storage	Classroom 209 Closet	Yes	CEILING	TRANSITE	GREEN	INTACT	0	< LOD	Negative
1	2	209CL	Storage	Classroom 209	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	2	209CL	Storage	Classroom 209	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative
1	2	210	Primary	Classroom 210	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	210	Primary	Classroom 210	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	210	Primary	Classroom 210	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	210	Primary	Classroom 210	Yes	CHALKBOARD FR	WOOD	CLEAR	INTACT	0	< LOD	Negative
1	2	210	Primary	Classroom 210	Yes	DOOR CASING	WOOD	CLEAR	INTACT	0	< LOD	Negative
1	2	210	Primary	Classroom 210	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	210	Primary	Classroom 210	Yes	W3	CMU	BLUE	INTACT	0	0.04	Negative
1	2	210	Primary	Classroom 210	Yes	COLUMN	CONCRETE	BLACK	INTACT	0	< LOD	Negative
1	2	210	Primary	Classroom 210	Yes	UNIVENT	METAL	BLACK	INTACT	0	< LOD	Negative
1	2	210	Primary	Classroom 210	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative
1	2	210	Primary	Classroom 210	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	210	Primary	Classroom 210	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	210	Primary	Classroom 210 Closet	Yes	CEILING	TRANSITE	GREEN	INTACT	0	< LOD	Negative
1	2	210	Primary	Classroom 210	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	211	Primary	Classroom 211	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative

							School District of Philadelphia					
			Name of Inspector: Kristen Masotes				Lead Safe Certification Assessment Report					
			Inspection Company: Acer Associates				Spruance School					
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	211	Primary	Classroom 211	Yes	W1	CMU	BLUE	INTACT	0	0.03	Negative
1	2	211	Primary	Classroom 211	Yes	DOOR CASING	PLASTER	CLEAR	INTACT	0	< LOD	Negative
1	2	211	Primary	Classroom 211	Yes	DOOR	WOOD	CLEAR	INTACT	0	< LOD	Negative
1	2	211	Primary	Classroom 211	Yes	CHALKBOARD FR	WOOD	CLEAR	INTACT	0	< LOD	Negative
1	2	211	Primary	Classroom 211	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	211	Primary	Classroom 211	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	211	Primary	Classroom 211	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	211	Primary	Classroom 211 Closet	Yes	CEILING	TRANSITE	WHITE	INTACT	0	< LOD	Negative
1	2	211	Primary	Classroom 211	Yes	W2	CMU	BLUE	INTACT	0	0.06	Negative
1	2	211	Primary	Classroom 211	Yes	CHALKBOARD FR	WOOD	CLEAR	INTACT	0	< LOD	Negative
1	2	211	Primary	Classroom 211	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.04	Negative
1	2	211	Primary	Classroom 211	Yes	W3	CMU	GREEN	INTACT	0	0.07	Negative
1	2	211	Primary	Classroom 211	Yes	COLUMN	CONCRETE	BLUE	INTACT	0	0.06	Negative
1	2	211	Primary	Classroom 211	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	2	211S	Administrative Office	Office 211S next to Classroom 211	Yes	CEILING	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	2	211S	Administrative Office	Office 211S next to Classroom 211	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	2	211S	Administrative Office	Office 211S next to Classroom 211	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	2	211S	Administrative Office	Office 211S next to Classroom 211	Yes	W4	CMU	WHITE	INTACT	0	< LOD	Negative
1	2	211S	Administrative Office	Office 211S next to Classroom 211	Yes	CHALKBOARD FR	METAL	PURPLE	INTACT	0	< LOD	Negative
1	2	211S	Administrative Office	Office 211S next to Classroom 211	Yes	LOCKER	METAL	PURPLE	INTACT	0	< LOD	Negative
1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.2	Negative
1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	DOOR CASING	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	1.9	Positive
1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	DOOR PANEL	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	W3	CMU	BEIGE	Flaking	70	< LOD	Negative
1	2	211T	Student Restrooms - Female (4-12)	Girl's Restroom across from Stairwell C	Yes	UNIVENT COVER	METAL	BEIGE	INTACT	0	< LOD	Negative
1	2	211TPC	Pipe Chase	Girl's Restroom Pipe Chase	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211TPC	Pipe Chase	Girl's Restroom Pipe Chase	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211TPC	Pipe Chase	Girl's Restroom Pipe Chase	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211TPC	Pipe Chase	Girl's Restroom Pipe Chase	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211TPC	Pipe Chase	Girl's Restroom Pipe Chase	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	211TPC	Pipe Chase	Girl's Restroom Pipe Chase	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative

			School District of Philadelphia									
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	UNIVENT COVER	METAL	BEIGE	INTACT	0	< LOD	Negative
1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	FLOOR	CONCRETE	GRAY	INTACT	0	< LOD	Negative
1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	2.3	Positive
1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	DOOR	WOOD	BROWN	INTACT	0	< LOD	Negative
1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	DOOR CASING	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	STALL WALL	TRANSITE	BEIGE	INTACT	0	< LOD	Negative
1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	212T	Student Restrooms - Male (4-12)	Boy's Restroom across from Stairwell C	Yes	COLUMN	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	2	212A	Storage	Custodial Closet near Stairwell C	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212A	Storage	Custodial Closet near Stairwell C	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212A	Storage	Custodial Closet near Stairwell C	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212A	Storage	Custodial Closet near Stairwell C	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212A	Storage	Custodial Closet near Stairwell C	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212A	Storage	Custodial Closet near Stairwell C	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212TPC	Pipe Chase	Boy's Restroom Pipe Chase	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212TPC	Pipe Chase	Boy's Restroom Pipe Chase	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212TPC	Pipe Chase	Boy's Restroom Pipe Chase	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212TPC	Pipe Chase	Boy's Restroom Pipe Chase	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212TPC	Pipe Chase	Boy's Restroom Pipe Chase	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212TPC	Pipe Chase	Boy's Restroom Pipe Chase	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212	Primary	Classroom 212	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	212	Primary	Classroom 212	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	212	Primary	Classroom 212	Yes	W1	CMU	YELLOW	INTACT	0	0.08	Negative
1	2	212	Primary	Classroom 212	Yes	CEILING	TRANSITE	BLUE	INTACT	0	< LOD	Negative
1	2	212	Primary	Classroom 212	Yes	W2	DRYWALL	BEIGE	INTACT	0	< LOD	Negative
1	2	212	Primary	Classroom 212	Yes	W3	CMU	BLUE	INTACT	0	0.05	Negative
1	2	212	Primary	Classroom 212	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	212	Primary	Classroom 212	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	212	Primary	Classroom 212	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	212	Primary	Classroom 212	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	212	Primary	Classroom 212	Yes	UNIVENT	METAL	BLUE	INTACT	0	< LOD	Negative
1	2	212	Primary	Classroom 212	Yes	UNIVENT CABINE	METAL	BLUE	INTACT	0	< LOD	Negative
1	2	207LL	Primary	Classroom 213A	Yes	W1	CMU	GREEN	INTACT	0	0.04	Negative
1	2	207LL	Primary	Classroom 213A	Yes	W4	DRYWALL	WHITE	INTACT	0	< LOD	Negative
1	2	207LL	Primary	Classroom 213A	Yes	W3	CMU	GREEN	INTACT	0	0.09	Negative
1	2	207LL	Primary	Classroom 213A	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative

							School District of Philadelphia						
			Name of Inspector: Kristen Masotes				Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates				Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	2	207LL	Primary	Classroom 213A	Yes	W2	CMU	YELLOW	INTACT	0	< LOD	Negative	
1	2	207LL	Primary	Classroom 213A	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative	
1	2	207N	Storage	Library Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	2	207N	Storage	Library Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	2	207N	Storage	Library Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	2	207N	Storage	Library Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	2	207N	Storage	Library Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	2	207N	Storage	Library Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	2	207L	IMC (Library)	Library	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative	
1	2	207L	IMC (Library)	Library	Yes	W1	CMU	BLUE	INTACT	0	0.04	Negative	
1	2	207L	IMC (Library)	Library	Yes	W2	DRYWALL	WHITE	INTACT	0	< LOD	Negative	
1	2	207L	IMC (Library)	Library	Yes	W3	CMU	BLUE	INTACT	0	< LOD	Negative	
1	2	207L	IMC (Library)	Library	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative	
1	2	207L	IMC (Library)	Library	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative	
1	2	207L	IMC (Library)	Library	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative	
1	2	207L	IMC (Library)	Library	Yes	WALL BASEBOAR	WOOD	WHITE	INTACT	0	< LOD	Negative	
1	2	207L	IMC (Library)	Library	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative	
1	2	207M	Administrative Office	Library Work Room	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative	
1	2	207M	Administrative Office	Library Work Room	Yes	W1	CMU	GRAY	INTACT	0	< LOD	Negative	
1	2	207M	Administrative Office	Library Work Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative	
1	2	207M	Administrative Office	Library Work Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative	
1	2	207M	Administrative Office	Library Work Room	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative	
1	2	207M	Administrative Office	Library Work Room	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative	
1	2	207M	Administrative Office	Library Work Room	Yes	W2	CMU	BLUE	INTACT	0	< LOD	Negative	
1	2	214	Primary	Classroom 214	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative	
1	2	214	Primary	Classroom 214	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative	
1	2	214	Primary	Classroom 214	Yes	W1	CMU	YELLOW	INTACT	0	0.08	Negative	
1	2	214	Primary	Classroom 214	Yes	CEILING	TRANSITE	BLUE	INTACT	0	< LOD	Negative	
1	2	214	Primary	Classroom 214	Yes	W2	DRYWALL	BEIGE	INTACT	0	< LOD	Negative	
1	2	214	Primary	Classroom 214	Yes	W3	CMU	BLUE	INTACT	0	0.05	Negative	
1	2	214	Primary	Classroom 214	Yes	W4	CMU	BLUE	INTACT	0	< LOD	Negative	
1	2	214	Primary	Classroom 214	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative	
1	2	214	Primary	Classroom 214	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative	
1	2	214	Primary	Classroom 214	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	< LOD	Negative	
1	2	214	Primary	Classroom 214	Yes	UNIVENT	METAL	BLUE	INTACT	0	< LOD	Negative	
1	2	214	Primary	Classroom 214	Yes	UNIVENT CABINE	METAL	BLUE	INTACT	0	< LOD	Negative	
1	2	214B	Primary	Classroom 214B - Music Room	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative	
1	2	214B	Primary	Classroom 214B - Music Room	Yes	W1	CMU	LIGHT BLUE	INTACT	0	0.03	Negative	
1	2	214B	Primary	Classroom 214B - Music Room	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative	
1	2	214B	Primary	Classroom 214B - Music Room	Yes	W2	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative	
1	2	214B	Primary	Classroom 214B - Music Room	Yes	W3	CMU	BLUE	INTACT	0	< LOD	Negative	
1	2	214B	Primary	Classroom 214B - Music Room	Yes	W4	DRYWALL	WHITE	INTACT	0	< LOD	Negative	
1	2	214B	Primary	Classroom 214B - Music Room	Yes	CEILING	TRANSITE	WHITE	INTACT	0	< LOD	Negative	
1	2	214B	Primary	Classroom 214B - Music Room	Yes	CEILING	TRANSITE	BLACK	INTACT	0	< LOD	Negative	
1	2	214B	Primary	Classroom 214B - Music Room	Yes	UNIVENT	METAL	BLUE	INTACT	0	< LOD	Negative	

						School District of Philadelphia						
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	214B	Primary	Classroom 214B - Music Room	Yes	UNIVENT CABINET	METAL	BLUE	INTACT	0	< LOD	Negative
1	2	214L	Administrative Office	Student Assistance Room at the end of the Hallway	Yes	W1	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	214L	Administrative Office	Student Assistance Room at the end of the Hallway	Yes	W2	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	214L	Administrative Office	Student Assistance Room at the end of the Hallway	Yes	W2	CMU	GREEN	INTACT	0	0.1	Negative
1	2	214L	Administrative Office	Student Assistance Room at the end of the Hallway	Yes	W4 BASEBOARD	TRANSITE	BLACK	INTACT	0	1.2	Positive
1	2	214L	Administrative Office	Student Assistance Room at the end of the Hallway	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	2	214L	Administrative Office	Student Assistance Room at the end of the Hallway	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	214L	Administrative Office	Student Assistance Room at the end of the Hallway	Yes	SOFFIT	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	214L	Administrative Office	Student Assistance Room Bathroom	Yes	W1	CMU	BEIGE	INTACT	0	0.05	Negative
1	2	214L	Administrative Office	Student Assistance Room Bathroom	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	214L	Administrative Office	Student Assistance Room Bathroom	Yes	W3	CMU	BEIGE	INTACT	0	0.05	Negative
1	2	214L	Administrative Office	Student Assistance Room Bathroom	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	214L	Administrative Office	Student Assistance Room Bathroom	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	214Y	Restrooms, Staff - Male/Female	Student Assistance Room Restroom	Yes	W1	CMU	BEIGE	INTACT	0	0.05	Negative
1	2	214Y	Restrooms, Staff - Male/Female	Student Assistance Room Restroom	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	214Y	Restrooms, Staff - Male/Female	Student Assistance Room Restroom	Yes	W3	CMU	BEIGE	INTACT	0	0.05	Negative
1	2	214Y	Restrooms, Staff - Male/Female	Student Assistance Room Restroom	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	214Y	Restrooms, Staff - Male/Female	Student Assistance Room Restroom	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	215	Primary	Classroom 215	Yes	W1	CMU	LIGHT BLUE	INTACT	0	0.04	Negative
1	2	215	Primary	Classroom 215	Yes	W2	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative
1	2	215	Primary	Classroom 215	Yes	W3	CMU	LIGHT BLUE	INTACT	0	0.05	Negative
1	2	215	Primary	Classroom 215	Yes	W4	CMU	LIGHT BLUE	INTACT	0	0.04	Negative
1	2	215	Primary	Classroom 215	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	2	215	Primary	Classroom 215	Yes	UNIVENT CABINET	METAL	TAN	INTACT	0	< LOD	Negative
1	2	215	Primary	Classroom 215	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	2	215	Primary	Classroom 215	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W1	CMU	BEIGE	INTACT	0	0.08	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W2	CMU	BEIGE	INTACT	0	0.07	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W4	CMU	BEIGE	INTACT	0	0.09	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W3	CMU	BEIGE	INTACT	0	0.04	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W3	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W4	CMU	GREEN	INTACT	0	< LOD	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W4	CMU	ORANGE	INTACT	0	< LOD	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	PIPE	METAL	BEIGE	INTACT	0	< LOD	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	FAN SUPPORT	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	FAN	METAL	WHITE	INTACT	0	< LOD	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	SOFFIT	CONCRETE	WHITE	INTACT	0	< LOD	Negative

			School District of Philadelphia									
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	SOFFIT	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	SOFFIT	CONCRETE	WHITE	INTACT	0	0.04	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	COLUMN	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	COLUMN	CONCRETE	BEIGE	INTACT	0	0.04	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	COLUMN	CONCRETE	ORANGE	INTACT	0	0.04	Negative
1	2	215A	Administrative Office	Office 215A next to Stairwell by Restrooms	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W1	CMU	BEIGE	INTACT	0	0.05	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W1	CMU	BEIGE	INTACT	0	0.05	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W2	CMU	BEIGE	INTACT	0	0.04	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W3	CMU	BEIGE	INTACT	0	0.05	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W4	CMU	BEIGE	INTACT	0	0.07	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W1	CMU	ORANGE	INTACT	0	0.06	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	W2	CMU	GREEN	INTACT	0	0.04	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	DUCT	METAL	BEIGE	INTACT	0	< LOD	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	FAN SUPPORT	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	CEILING	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	2	223	Principal/Directors Office	Assistant Principal's Office 215C	Yes	SOFFIT	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	2	223PC	Pipe Chase	Assistant Principal's Office Pipe Chase	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	223PC	Pipe Chase	Assistant Principal's Office Pipe Chase	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	223PC	Pipe Chase	Assistant Principal's Office Pipe Chase	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	223PC	Pipe Chase	Assistant Principal's Office Pipe Chase	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	223PC	Pipe Chase	Assistant Principal's Office Pipe Chase	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	223PC	Pipe Chase	Assistant Principal's Office Pipe Chase	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	224	Student Restrooms - Female (4-12)	Girl's Restroom next to Assistant Principal's Office	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	224	Student Restrooms - Female (4-12)	Girl's Restroom next to Assistant Principal's Office	Yes	W4	CMU	BEIGE	INTACT	0	0.06	Negative
1	2	224	Student Restrooms - Female (4-12)	Girl's Restroom next to Assistant Principal's Office	Yes	W2	CMU	BEIGE	INTACT	0	0.5	Negative

			School District of Philadelphia									
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	224	Student Restrooms - Female (4-12)	Girl's Restroom next to Assistant Principal's Office	Yes	CEILING	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	2	224	Student Restrooms - Female (4-12)	Girl's Restroom next to Assistant Principal's Office	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative
1	2	224	Student Restrooms - Female (4-12)	Girl's Restroom next to Assistant Principal's Office	Yes	PIPE JACKET	METAL	BLACK	INTACT	0	< LOD	Negative
1	2	225	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	2	216	Primary	Classroom 216	Yes	W1	CMU	BLUE	INTACT	0	0.03	Negative
1	2	216	Primary	Classroom 216	Yes	W2	CMU	BLUE	INTACT	0	0.04	Negative
1	2	216	Primary	Classroom 216	Yes	W3	CMU	BLUE	Flaking	5	< LOD	Negative
1	2	216	Primary	Classroom 216	Yes	W4	CMU	BLUE	INTACT	0	0.03	Negative
1	2	216	Primary	Classroom 216	Yes	W4	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative
1	2	216	Primary	Classroom 216	Yes	W3	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative
1	2	216	Primary	Classroom 216	Yes	W2	CMU	LIGHT BLUE	INTACT	0	0.06	Negative
1	2	216	Primary	Classroom 216	Yes	W1	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative
1	2	216	Primary	Classroom 216	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	2	216	Primary	Classroom 216	Yes	DOOR STOP	METAL	TAN	INTACT	0	< LOD	Negative
1	2	216	Primary	Classroom 216	Yes	CLOSET DOOR CA	METAL	TAN	INTACT	0	< LOD	Negative
1	2	216	Primary	Classroom 216	Yes	CLOSET DOOR CA	METAL	TAN	INTACT	0	< LOD	Negative
1	2	216	Primary	Classroom 216	Yes	BATHROOM DOOR	METAL	TAN	INTACT	0	< LOD	Negative
1	2	216	Primary	Classroom 216	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.3	Negative
1	2	216	Primary	Classroom 216	Yes	COLUMN	CONCRETE	BLUE	INTACT	0	< LOD	Negative
1	2	216	Primary	Classroom 216	Yes	COLUMN	CONCRETE	LIGHT BLUE	INTACT	0	< LOD	Negative
1	2	216	Primary	Classroom 216	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative
1	2	216A	Primary	Classroom 216 Bathroom	Yes	PIPE	METAL	WHITE	INTACT	0	< LOD	Negative
1	2	216A	Primary	Classroom 216 Bathroom	Yes	W1	CMU	BLUE	INTACT	0	0.03	Negative
1	2	216A	Primary	Classroom 216 Bathroom	Yes	W2	CMU	BLUE	INTACT	0	0.04	Negative
1	2	216A	Primary	Classroom 216 Bathroom	Yes	W3	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	216CL	Storage	Classroom 216 Closet	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	216CL	Storage	Classroom 216 Closet	Yes	W4	CMU	BLUE	INTACT	0	0.9	Positive
1	2	216CL	Storage	Classroom 216 Closet	Yes	COLUMN	CONCRETE	BLUE	INTACT	0	< LOD	Negative
1	2	216CL	Storage	Classroom 216 Closet	Yes	CEILING	TRANSITE	BLUE	INTACT	0	< LOD	Negative
1	2	216CL	Storage	Classroom 216 Closet	Yes	CEILING GRATE	METAL	BLUE	INTACT	0	< LOD	Negative
1	2	217	Primary	Classroom 217	Yes	CEILING	CONCRETE	YELLOW	INTACT	0	0.4	Negative
1	2	217	Primary	Classroom 217	Yes	W1	CMU	BLUE	INTACT	0	0.04	Negative
1	2	217	Primary	Classroom 217	Yes	W2	CMU	BLUE	INTACT	0	0.1	Negative
1	2	217	Primary	Classroom 217	Yes	W3	CMU	BLUE	INTACT	0	0.08	Negative
1	2	217	Primary	Classroom 217	Yes	W4	CMU	BLUE	INTACT	0	0.04	Negative
1	2	217	Primary	Classroom 217	Yes	W4	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative
1	2	217	Primary	Classroom 217	Yes	W1	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative
1	2	217	Primary	Classroom 217	Yes	W2	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative
1	2	217	Primary	Classroom 217	Yes	W3	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative
1	2	217	Primary	Classroom 217	Yes	WALL BASEBOAR	CMU	BLACK	INTACT	0	< LOD	Negative
1	2	217	Primary	Classroom 217	Yes	DOOR CASING	METAL	BEIGE	INTACT	0	< LOD	Negative
1	2	217	Primary	Classroom 217 Closet	Yes	CEILING	TRANSITE	BLUE	INTACT	0	< LOD	Negative

							School District of Philadelphia					
			Name of Inspector: Kristen Masotes				Lead Safe Certification Assessment Report					
			Inspection Company: Acer Associates				Spruance School					
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	217	Primary	Classroom 217	Yes	UNIVENT	METAL	TAN	INTACT	0	< LOD	Negative
1	2	217	Primary	Classroom 217	Yes	UNIVENT CABINE	METAL	TAN	INTACT	0	< LOD	Negative
1	2	218	Primary	Classroom 218	Yes	W1	CMU	BLUE	INTACT	0	0.07	Negative
1	2	218	Primary	Classroom 218	Yes	W2	CMU	BLUE	INTACT	0	0.06	Negative
1	2	218	Primary	Classroom 218	Yes	W3	CMU	BLUE	INTACT	0	0.05	Negative
1	2	218	Primary	Classroom 218	Yes	W4	CMU	BLUE	INTACT	0	0.04	Negative
1	2	218	Primary	Classroom 218	Yes	W4	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative
1	2	218	Primary	Classroom 218	Yes	W2	CMU	LIGHT BLUE	INTACT	0	< LOD	Negative
1	2	218	Primary	Classroom 218	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	220	Primary	Classroom 220	Yes	W1	CMU	LIGHT BEIGE	INTACT	0	0.04	Negative
1	2	220	Primary	Classroom 220	Yes	W2	CMU	LIGHT BEIGE	INTACT	0	< LOD	Negative
1	2	220	Primary	Classroom 220	Yes	W3	CMU	LIGHT BEIGE	INTACT	0	< LOD	Negative
1	2	220	Primary	Classroom 220	Yes	W4	CMU	LIGHT BEIGE	INTACT	0	< LOD	Negative
1	2	220	Primary	Classroom 220	Yes	DOOR CASING	METAL	RED	INTACT	0	< LOD	Negative
1	2	220	Primary	Classroom 220	Yes	DOOR	WOOD	BLACK	INTACT	0	< LOD	Negative
1	2	220	Primary	Classroom 220	Yes	DOOR	WOOD	LIGHT BEIGE	INTACT	0	< LOD	Negative
1	2	220	Primary	Classroom 220	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	220CL	Storage	Classroom 220 Closet	Yes	W1	CMU	BLUE	INTACT	0	< LOD	Negative
1	2	220CL	Storage	Classroom 220 Closet	Yes	COLUMN	CONCRETE	BLUE	INTACT	0	< LOD	Negative
1	2	220CL	Storage	Classroom 220 Closet	Yes	COLUMN	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	220CL	Storage	Classroom 220 Closet	Yes	CEILING	TRANSITE	BLUE	INTACT	0	< LOD	Negative
1	2	220CL	Storage	Classroom 220 Closet	Yes	DOOR CASING	METAL	RED	INTACT	0	< LOD	Negative
1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	FLOOR	CONCRETE	GRAY	INTACT	0	< LOD	Negative
1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	W1	CMU	Tan	INTACT	0	0.1	Negative
1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	W2	CMU	Tan	INTACT	0	0.5	Negative
	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office		W3	CMU	Tan	INTACT	0	0.5	Negative
	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office		W4	CMU	Tan	INTACT	0	0.4	Negative
1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0.5	Negative
1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	SHELF	WOOD	BEIGE	INTACT	0	< LOD	Negative
1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative
1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	STALL WALL	TRANSITE	BEIGE	INTACT	0	1	Positive
1	2	226	Student Restrooms - Male (4-12)	Boy's Restroom next to Assistant Principal's Office	Yes	PIPE JACKET	METAL	BLACK	INTACT	0	< LOD	Negative
1	2	H23	Circulation (Hallway)	Hallway at Classrooms 215 to 220	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	H23	Circulation (Hallway)	Hallway at Classrooms 215 to 220	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	H23	Circulation (Hallway)	Hallway at Classrooms 215 to 220	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	H23	Circulation (Hallway)	Hallway at Classrooms 215 to 220	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative

			School District of Philadelphia									
			Lead Safe Certification Assessment Report									
			Spruance School									
			Name of Inspector: Kristen Masotes									
			Inspection Company: Acer Associates									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	H23	Circulation (Hallway)	Hallway at Classrooms 215 to 220	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative
1	2	H23	Circulation (Hallway)	Hallway at Classrooms 215 to 220	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative
1	2	H23	Circulation (Hallway)	Hallway at Classrooms 215 to 220	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative
1	2	H23	Circulation (Hallway)	Hallway at Classrooms 215 to 220	Yes	DOOR	METAL	TAN	INTACT	0	< LOD	Negative
	2	H23	Circulation (Hallway)	Hallway at Classrooms 215 to 220		CEILING BEAM	CONCRETE	WHITE	INTACT	0	0.4	Negative
1	2	H23	Circulation (Hallway)	Hallway at Classrooms 215 to 220	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	2	H24	Circulation (Hallway)	Hallway at Classrooms 208 to 214	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	H24	Circulation (Hallway)	Hallway at Classrooms 208 to 214	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	H24	Circulation (Hallway)	Hallway at Classrooms 208 to 214	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
	2	H24	Circulation (Hallway)	Hallway at Classrooms 208 to 214		CEILING BEAM	CONCRETE	WHITE	INTACT	0	0.4	Negative
1	2	H24	Circulation (Hallway)	Hallway at Classrooms 208 to 214	Yes	UNIVENT COVER	METAL	BEIGE	INTACT	0	< LOD	Negative
1	2	H24	Circulation (Hallway)	Hallway at Classrooms 208 to 214	Yes	UNIVENT	METAL	BEIGE	INTACT	0	< LOD	Negative
1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	DOOR	METAL	TAN	INTACT	0	< LOD	Negative
1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative
1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	WINDOW SILL	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	< LOD	Negative
	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207		CEILING BEAM	CONCRETE	WHITE	INTACT	0	0.4	Negative
1	2	H27	Circulation (Hallway)	Hallway at Classrooms 200 to 207	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative
1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	0.07	Negative
1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	STAIRS RISER	CONCRETE	BLACK	INTACT	0	< LOD	Negative
1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	STAIRS STRINGER	TRANSITE	BLACK	INTACT	0	0.13	Negative
1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	STAIR HALF WALL	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	DOOR	METAL	TAN	INTACT	0	< LOD	Negative
1	2	S22	Stairs	Stairwell next to Classroom 210	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W1	BRICK	BEIGE	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W3	CMU	BEIGE	INTACT	0	0	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	WALL BASEBOARD	CONCRETE	TAN	INTACT	0	0.04	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	WALL BASEBOARD	TRANSITE	TAN	INTACT	0	1.1	Positive

						School District of Philadelphia						
						Lead Safe Certification Assessment Report						
			Name of Inspector: Kristen Masotes									
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR	METAL	TAN	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR	METAL	TAN	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR	METAL	TAN	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR CASING	METAL	RED	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR CASING	METAL	RED	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	DOOR	METAL	RED	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S23	Stairs	Stairwell next to Classroom 207	Yes	STAIRS STRINGER	CONCRETE	TAN	INTACT	0	0.03	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	W2	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	W4	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	W3	CMU	WHITE	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	W3	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	W1	CMU	BEIGE	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	CEILING	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	WALL BASEBOARD	TRANSITE	WHITE	INTACT	0	1.1	Positive
1	2	S24	Stairs	Stairwell next to Library	Yes	DOOR	METAL	TAN	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	PIPE COVER	METAL	BEIGE	INTACT	0	2.2	Positive
1	2	S24	Stairs	Stairwell next to Library	Yes	DOOR	METAL	GREEN	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	DOOR CASING	METAL	GREEN	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	UNIVENT	METAL	BROWN	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	DOOR	WOOD	BROWN	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	DOOR CASING	METAL	BROWN	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	STAIRS RISER	CONCRETE	BLACK	INTACT	0	0.05	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	STAIRS STRINGER	CONCRETE	BLACK	INTACT	0	0.09	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	STAIRS HALFWALL	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	STAIRS HALFWALL	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	2	S24	Stairs	Stairwell next to Library	Yes	CEILING	CONCRETE	WHITE	Flaking	3	0.2	Negative
1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	DOOR CASING	METAL	TAN	INTACT	0	0.09	Negative
1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	DOOR	METAL	TAN	INTACT	0	0.09	Negative
1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	W1	CMU	BEIGE	INTACT	0	0.01	Negative
1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	W2	CMU	BEIGE	INTACT	0	0.04	Negative
1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	W4	CMU	BEIGE	INTACT	0	0	Negative

			<div>School District of Philadelphia</div> <div>Lead Safe Certification Assessment Report</div> <div>Spruance School</div>									
			Name of Inspector: Kristen Masotes									
			Inspection Company: Acer Associates									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.07	Negative
1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	WALL BASEBOAR	TRANSITE	BLACK	INTACT	0	0.07	Negative
1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	STAIRS STRINGER	TRANSITE	BLACK	INTACT	0	0.07	Negative
1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	STAIRS RISER	TRANSITE	BLACK	INTACT	0	0.03	Negative
1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	HALF WALL	CONCRETE	BEIGE	INTACT	0	0.02	Negative
1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative
1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	STAIRS RISER	CONCRETE	BLACK	INTACT	0	0.3	Negative
1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	STAIRS STRINGER	TRANSITE	BLACK	INTACT	0	0.05	Negative
1	2	S24A	Stairs	Stairwell near Classroom 201	Yes	HALF WALL	CONCRETE	BEIGE	INTACT	0	0.01	Negative
1	B	1	Mechanical Room	Water Main Room	No	W1	CMU	BLUE	INTACT	0	< LOD	Negative
1	B	1	Mechanical Room	Water Main Room	No	W2	CMU	BLUE	INTACT	0	< LOD	Negative
1	B	1	Mechanical Room	Water Main Room	No	W3	CONCRETE	BLUE	INTACT	0	< LOD	Negative
1	B	1	Mechanical Room	Water Main Room	No	W4	CMU	BLUE	INTACT	0	< LOD	Negative
1	B	1	Mechanical Room	Water Main Room	No	WALL BASEBOAR	TRANSITE	WHITE	INTACT	0	< LOD	Negative
1	B	1	Mechanical Room	Water Main Room	No	WALL BASEBOAR	TRANSITE	WHITE	INTACT	0	< LOD	Negative
1	B	1	Mechanical Room	Water Main Room	No	WALL BASEBOAR	TRANSITE	WHITE	INTACT	0	< LOD	Negative
1	B	1	Mechanical Room	Water Main Room	No	WALL BASEBOAR	TRANSITE	WHITE	INTACT	0	< LOD	Negative
1	B	1	Mechanical Room	Water Main Room	No	DOOR CASING	METAL	GREEN	INTACT	0	< LOD	Negative
1	B	1	Mechanical Room	Water Main Room	No	DOOR	WOOD	GREEN	INTACT	0	< LOD	Negative
1	B	1	Mechanical Room	Water Main Room	No	DOOR STOP	METAL	GREEN	INTACT	0	< LOD	Negative
1	B	1	Mechanical Room	Water Main Room	No	DOOR	METAL	BLUE	INTACT	0	< LOD	Negative
1	B	1	Mechanical Room	Water Main Room	No	DOOR CASING	METAL	BLUE	INTACT	0	< LOD	Negative
1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	CEILING	CONCRETE	BEIGE	INTACT	0	< LOD	Negative
1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	W1	CMU	GREEN	INTACT	0	0.04	Negative
1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	W4	CMU	GREEN	INTACT	0	< LOD	Negative
1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	W2	CMU	GREEN	INTACT	0	< LOD	Negative
1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	W4	CMU	WHITE	INTACT	0	< LOD	Negative
1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	DOOR CASING	METAL	SILVER	INTACT	0	< LOD	Negative
1	B	S02	Stairs	Hallway from Basement Stairwell to Restroom	No	DOOR CASING	METAL	SILVER	INTACT	0	< LOD	Negative
1	B	S03	Stairs	Basement Stairwell	No	W4	CONCRETE	BLUE	INTACT	0	< LOD	Negative
1	B	S03	Stairs	Basement Stairwell	No	W2	CONCRETE	BLUE	INTACT	0	< LOD	Negative
1	B	S03	Stairs	Basement Stairwell	No	W1	CMU	BLUE	INTACT	0	< LOD	Negative
1	B	S03	Stairs	Basement Stairwell	No	DOOR	METAL	TAN	INTACT	0	< LOD	Negative
1	B	S03	Stairs	Basement Stairwell	No	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	B	S03	Stairs	Basement Stairwell	No	STAIRS RAILING	METAL	TAN	INTACT	0	< LOD	Negative
1	B	S03	Stairs	Basement Stairwell	No	DOOR CASING	METAL	TAN	INTACT	0	< LOD	Negative
1	B	S03	Stairs	Basement Stairwell	No	DOOR	METAL	TAN	INTACT	0	< LOD	Negative
1	B	S03	Stairs	Basement Stairwell	No	STAIRS RISER	CONCRETE	GRAY	INTACT	0	< LOD	Negative
1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	W1	CMU	BLUE	INTACT	0	0.09	Negative
1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	W2	CMU	BLUE	INTACT	0	< LOD	Negative
1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	W3	CMU	BLUE	INTACT	0	< LOD	Negative

			School District of Philadelphia									
			Name of Inspector: Kristen Masotes					Lead Safe Certification Assessment Report				
			Inspection Company: Acer Associates					Spruance School				
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	W4	CMU	BLUE	INTACT	0	0.06	Negative
1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	PIPE	METAL	BLUE	INTACT	0	< LOD	Negative
1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	COLUMN	CONCRETE	BLUE	INTACT	0	0.06	Negative
1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	CEILING	CONCRETE	WHITE	Flaking	15	0.4	Negative
1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	STALL DOOR	WOOD	GRAY	INTACT	0	< LOD	Negative
1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	B	1A	Restrooms, Staff - Male/Female	Restroom in Water Main Room	No	WALL BASEBOARD	TRANSITE	BLACK	INTACT	0	< LOD	Negative
1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	W2	CMU	GREEN	INTACT	0	< LOD	Negative
1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	W3	CMU	GREEN	INTACT	0	0.05	Negative
1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	W4	CMU	GREEN	INTACT	0	0.09	Negative
1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	W3	CMU	WHITE	INTACT	0	< LOD	Negative
1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	W4	CMU	WHITE	INTACT	0	< LOD	Negative
1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	ELECTRICAL PANEL	METAL	GREEN	INTACT	0	< LOD	Negative
1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	ELECTRICAL PANEL	METAL	WHITE	INTACT	0	< LOD	Negative
1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	ALARM SWITCH	METAL	RED	INTACT	0	< LOD	Negative
1	B	2	Mechanical Room	Mechanical room area in front of Boiler Room	No	CONDOIT	METAL	WHITE	INTACT	0	< LOD	Negative
1	B	3	Storage	Storage Room at Boiler Room	No	W4	CMU	WHITE	INTACT	0	N/A	N/A
1	B	3	Storage	Storage Room at Boiler Room	No	W1	CMU	WHITE	INTACT	0	0.5	Negative
1	B	3	Storage	Storage Room at Boiler Room	No	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	B	3	Storage	Storage Room at Boiler Room	No	COLUMN	CONCRETE	WHITE	INTACT	0	< LOD	Negative
	B	3	Storage	Storage Room at Boiler Room	No	Ceiling	CONCRETE	WHITE	Flaking	400	0.4	Negative
1	B	3	Storage	Storage Room at Boiler Room	No	PIPING	METAL	GREEN	INTACT	0	< LOD	Negative
1	B	4	Mechanical Room	Pump Room next to Boiler Room	No	W1	CONCRETE	WHITE	INTACT	0	0.1	Negative
1	B	4	Mechanical Room	Pump Room next to Boiler Room	No	W2	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	B	4	Mechanical Room	Pump Room next to Boiler Room	No	W3	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	B	4	Mechanical Room	Pump Room next to Boiler Room	No	W4	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	B	4	Mechanical Room	Pump Room next to Boiler Room	No	TANK	METAL	WHITE	INTACT	0	< LOD	Negative
1	B	4	Mechanical Room	Pump Room next to Boiler Room	No	COLUMN	CONCRETE	WHITE	INTACT	0	< LOD	Negative
1	B	5	Boiler Room	Boiler Room	No	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	B	5	Boiler Room	Boiler Room	No	W2	CMU	WHITE	INTACT	0	0.2	Negative
1	B	5	Boiler Room	Boiler Room	No	W3	CMU	WHITE	INTACT	0	1.2	Positive
1	B	5	Boiler Room	Boiler Room	No	W4	CMU	WHITE	INTACT	0	0.5	Negative
1	B	5	Boiler Room	Boiler Room	No	COLUMN	CMU	WHITE	INTACT	0	< LOD	Negative
1	B	5	Boiler Room	Boiler Room	No	PIPE	METAL	WHITE	INTACT	0	< LOD	Negative
1	B	5	Boiler Room	Boiler Room	No	DOOR	METAL	WHITE	INTACT	0	< LOD	Negative

						School District of Philadelphia						
			Name of Inspector: Kristen Masotes			Lead Safe Certification Assessment Report						
			Inspection Company: Acer Associates			Spruance School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	5	Boiler Room	Boiler Room	No	PANEL BOX	METAL	WHITE	INTACT	0	< LOD	Negative
1	B	5	Boiler Room	Boiler Room	No	PANEL BOX	METAL	GREEN	INTACT	0	0.8	Positive
1	B	5	Boiler Room	Boiler Room	No	PAD	CONCRETE	BLACK	INTACT	0	0.17	Negative
1	B	5	Boiler Room	Boiler Room	No	SUMP PUMP PIP	METAL	SILVER	INTACT	0	< LOD	Negative
1	B	5	Boiler Room	Boiler Room	No	ELEC PANEL BOX	METAL	BLACK	INTACT	0	< LOD	Negative
1	B	5	Boiler Room	Boiler Room	No	DOOR	METAL	GREEN	INTACT	0	< LOD	Negative
1	B	5	Boiler Room	Boiler Room	No	DOOR	METAL	GREEN	INTACT	0	< LOD	Negaive
1	B	5	Boiler Room	Boiler Room	No	DOOR CENTER PC	METAL	GREEN	INTACT	0	< LOD	Negative
1	B	5	Boiler Room	Boiler Room	No	WINDOW PANEL	METAL	GREEN	INTACT	0	< LOD	Negative
1	B	6	Mechanical Room	Incinerator Room	No	DOOR	METAL	SILVER	INTACT	0	< LOD	Negative
1	B	6	Mechanical Room	Incinerator Room	No	DOOR CASING	METAL	GREEN	INTACT	0	< LOD	Negative
1	B	6	Mechanical Room	Incinerator Room	No	W1	CMU	GREEN	INTACT	0	< LOD	Negative
1	B	6	Mechanical Room	Incinerator Room	No	W2	CMU	GREEN	INTACT	0	< LOD	Negative
1	B	6	Mechanical Room	Incinerator Room	No	W3	CMU	GREEN	INTACT	0	< LOD	Negative
1	B	6	Mechanical Room	Incinerator Room	No	W4	CMU	GREEN	INTACT	0	0.05	Negative
1	B	6	Mechanical Room	Incinerator Room	No	W1	CMU	WHITE	INTACT	0	< LOD	Negative
1	B	6	Mechanical Room	Incinerator Room	No	W2	CMU	WHITE	INTACT	0	< LOD	Negative
1	B	6	Mechanical Room	Incinerator Room	No	W3	CMU	WHITE	INTACT	0	< LOD	Negative
1	B	6	Mechanical Room	Incinerator Room	No	W4	CMU	WHITE	INTACT	0	< LOD	Negative
1	B	6	Mechanical Room	Incinerator Room	No	CEILING	CMU	WHITE	INTACT	0	< LOD	Negative
1	B	6	Mechanical Room	Incinerator Room	No	COLUMN	CMU	WHITE	INTACT	0	< LOD	Negative
1	B	6	Mechanical Room	Incinerator Room	No	PIPE	CMU	SILVER	INTACT	0	< LOD	Negative
1	B	7	Storage	Storage next to the Front Stairwell	No	W1	CMU	GREEN	INTACT	0	0.4	Negative
1	B	7	Storage	Storage next to the Front Stairwell	No	COLUMN	CONCRETE	GREEN	INTACT	0	< LOD	Negative
1	B	7	Storage	Storage next to the Front Stairwell	No	CEILING	CONCRETE	WHITE	INTACT	0	0.1	Negative
1	B	8	Circulation (Hallway)	Crawlspace/Hallway to Boiler Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	8	Circulation (Hallway)	Crawlspace/Hallway to Boiler Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	8	Circulation (Hallway)	Crawlspace/Hallway to Boiler Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	8	Circulation (Hallway)	Crawlspace/Hallway to Boiler Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	8	Circulation (Hallway)	Crawlspace/Hallway to Boiler Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	8	Circulation (Hallway)	Crawlspace/Hallway to Boiler Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Attic- Auditorium	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Attic- Auditorium	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS	Crawl Space	Crawl Space-Basement	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS	Crawl Space	Crawl Space-Basement	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	L1	Circulation (Hallway)	Main Entrance Lobby	Yes	W1	CMU	YELLOW	INTACT	0	0.16	Negative
1	1	L1	Circulation (Hallway)	Main Entrance Lobby	Yes	W2	CMU	YELLOW	INTACT	0	0	Negative
1	1	L1	Circulation (Hallway)	Main Entrance Lobby	Yes	W4	CMU	YELLOW	INTACT	0	0.01	Negative
1	1	L1	Circulation (Hallway)	Main Entrance Lobby	Yes	DOOR	METAL	RED	INTACT	0	0.06	Negative
1	1	L1	Circulation (Hallway)	Main Entrance Lobby	Yes	DOOR CENTER PC	METAL	RED	INTACT	0	0	Negative
1	1	L1	Circulation (Hallway)	Main Entrance Lobby	Yes	DOOR CASING	METAL	RED	INTACT	0	0	Negative
1	1	L1	Circulation (Hallway)	Main Entrance Lobby	Yes	UNIVENT	METAL	BROWN	INTACT	0	0.11	Negative