

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Administrative Office	Main Office	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	Administrative Office	Main Office	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	Administrative Office	Main Office	yes	W3	Plaster	Beige	Damaged plaster	3	31.2	Positive
1	1	Administrative Office	Main Office	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	Administrative Office	Main Office	yes	Ceiling	Plaster	Beige	N/A	N/A	N/A	N/A
1	1	Administrative Office	Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Main Office Closet by the entrance	yes	W1	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
1	1	Storage	Main Office Closet by the entrance	yes	W2	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
1	1	Storage	Main Office Closet by the entrance	yes	W3	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
1	1	Storage	Main Office Closet by the entrance	yes	W4	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
1	1	Storage	Main Office Closet by the entrance	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	Storage	Main Office Closet by the entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Administrative Office	Principal's Office	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	Administrative Office	Principal's Office	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	Administrative Office	Principal's Office	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	Administrative Office	Principal's Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Administrative Office	Principal's Office	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	Administrative Office	Principal's Office	yes	Ceiling	Plaster	Beige	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Administrative Office	Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	W2	Plaster	Beige	Chipping	3	20.3	Positive
1	1	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	W4	Plaster	Beige	Chipping	4	16.2	Positive
1	1	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	1	Restrooms, Staff - Male/Female	Principal's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 101	yes	W1	Plaster	Beige	Efflorescence, Flaking, Chipping	12	17.5	Positive
1	1	Primary	Classroom 101	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 101	yes	W2	Plaster	Beige	Chipping	10	11.6	Positive
1	1	Primary	Classroom 101	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 101	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 101	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 101	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 101	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 101	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 101	yes	W3	Plaster	Beige	Flaking, Efflorescence	8	11.3	Positive
1	1	Primary	Classroom 101	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 101	yes	W4	Plaster	Beige	Efflorescence, Flaking, Chipping	10	13.6	Positive
1	1	Primary	Classroom 101	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 101	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 101	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	1	Primary	Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W1	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W2	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W3	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W4	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	Storage	Locker Storage outside Classroom 101	yes	W1	Plaster	Purple	None	0	N/A	N/A
1	1	Storage	Locker Storage outside Classroom 101	yes	W2	Plaster	Beige	Partially Inaccessible	0	21.4	Positive
1	1	Storage	Locker Storage outside Classroom 101	yes	W3	Plaster	Purple	Flaking	4	10.4	Positive
1	1	Storage	Locker Storage outside Classroom 101	yes	W4	Plaster	Beige	Partially Inaccessible	0	15.2	Positive
1	1	Storage	Locker Storage outside Classroom 101	yes	Ceiling	Plaster	Beige	Flaking	2	8.2	Positive
1	1	Storage	Locker Storage outside Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Restrooms, Staff - Male/Female	Staff Restroom inside Locker Storage outside Classroom 101	yes	W1	Plaster	Purple	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Restrooms, Staff - Male/Female	Staff Restroom inside Locker Storage outside Classroom 101	yes	W2	Plaster	Purple	None	0	N/A	N/A
1	1	Restrooms, Staff - Male/Female	Staff Restroom inside Locker Storage outside Classroom 101	yes	W3	Plaster	Purple	None	0	N/A	N/A
1	1	Restrooms, Staff - Male/Female	Staff Restroom inside Locker Storage outside Classroom 101	yes	W4	Plaster	Purple	Efflorescence	6	18.2	Positive
1	1	Restrooms, Staff - Male/Female	Staff Restroom inside Locker Storage outside Classroom 101	yes	Ceiling	Plaster	Beige	Flaking	5	3	Positive
1	1	Restrooms, Staff - Male/Female	Staff Restroom inside Locker Storage outside Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 102	yes	W1	Plaster	Beige	Chipping	3	10.2	Positive
1	1	Primary	Classroom 102	yes	W2	Plaster	Beige	Chipping	10	18.2	Positive
1	1	Primary	Classroom 102	yes	W3	Plaster	Beige	Chipping, Cracking, Efflorescence	35	11.3	Positive
1	1	Primary	Classroom 102	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	Primary	Classroom 102	yes	Ceiling	Plaster	Beige	Flaking	10	3.6	Positive
1	1	Primary	Classroom 102	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Classroom 102 Coat Closet	yes	W1	Plaster	Beige	Spalling	5	14	Positive
1	1	Storage	Classroom 102 Coat Closet	yes	W2	Plaster	Beige	Cracking	5	16.7	Positive
1	1	Storage	Classroom 102 Coat Closet	yes	W3	Plaster	Beige	Flaking	10	14.3	Positive
1	1	Storage	Classroom 102 Coat Closet	yes	W4	Plaster	Beige	Cracking	8	20.2	Positive
1	1	Storage	Classroom 102 Coat Closet	yes	Ceiling	Plaster	Beige	Flaking	40	12.8	Positive
1	1	Storage	Classroom 102 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	W1	Plaster	Pink	Chipping	10	18.9	Positive
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	W2	Plaster	Blue	Cracking	30	22	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	W3	Plaster	Pink/Blue	Cracking	30	2.8	Positive
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	W4	Plaster	Pink	Cracking	3	17.7	Positive
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	Ceiling	Plaster	Pink	Cracking, Flaking, Damaged plaster	40	0.06	Negative
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Classroom 102 Small Storage	yes	W1	Plaster	Beige	Flaking	10	10.1	Positive
1	1	Storage	Classroom 102 Small Storage	yes	W2	Plaster	Beige	Flaking, Crack in Plaster	30	9.3	Positive
1	1	Storage	Classroom 102 Small Storage	yes	W3	Plaster	Beige	Flaking, Crack in Plaster	20	9.4	Positive
1	1	Storage	Classroom 102 Small Storage	yes	W4	Plaster	Beige	Flaking, Crack in Plaster	20	20.9	Positive
1	1	Storage	Classroom 102 Small Storage	yes	Ceiling	Plaster	Beige	Flaking	20	9.8	Positive
1	1	Storage	Classroom 102 Small Storage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 103	yes	W1	Plaster	Beige	Chipping	4	12.1	Positive
1	1	Primary	Classroom 103	yes	W2	Plaster	Beige	Chipping, Flaking	18	3.7	Positive
1	1	Primary	Classroom 103	yes	W3	Plaster	Beige	Flaking	5	10.1	Positive
1	1	Primary	Classroom 103	yes	W4	Plaster	Beige	Spalling, Flaking, Chipping	30	3.4	Positive
1	1	Primary	Classroom 103	yes	Ceiling	Plaster	Beige	Flaking	2	14.2	Positive
1	1	Primary	Classroom 103	yes	Floor	Wood/Carpet	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	yes	W2	Plaster	Beige	Efflorescence	10	22.9	Positive
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	yes	W3	Plaster	Beige	Efflorescence , Spalling	30	15.6	Positive
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	yes	Ceiling	Plaster	Beige	Flaking	3	No test	Positive
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Classroom 103 Instrument Storage	yes	W1	Plaster	Beige	Partially Inaccessible	0	17.5	Positive
1	1	Storage	Classroom 103 Instrument Storage	yes	W2	Sheetrock	Beige	Partially Inaccessible	0	0	Negative
1	1	Storage	Classroom 103 Instrument Storage	yes	W3	Plaster	Beige	Partially Inaccessible	4	16.2	Positive
1	1	Storage	Classroom 103 Instrument Storage	yes	W4	Plaster	Beige	None	0	17	Positive
1	1	Storage	Classroom 103 Instrument Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Classroom 103 Instrument Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Classroom 103 Closet by entrance	yes	W1	Plaster	Beige	Flaking	8	6.9	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Storage	Classroom 103 Closet by entrance	yes	W2	Plaster	Beige	Flaking	15	5	Positive
1	1	Storage	Classroom 103 Closet by entrance	yes	W3	Plaster	Beige	Flaking	25	7.9	Positive
1	1	Storage	Classroom 103 Closet by entrance	yes	W4	Plaster	Beige	Flaking	20	10.1	Positive
1	1	Storage	Classroom 103 Closet by entrance	yes	Ceiling	Plaster	Beige	Flaking	15	8.4	Positive
1	1	Storage	Classroom 103 Closet by entrance	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Teacher Lounge/Dining	Teacher Lounge/Dining	yes	W1	Plaster	Beige	Chipping, Crack in Plaster, Spalling	16	17.9	Positive
1	1	Teacher Lounge/Dining	Teacher Lounge/Dining	yes	W2	Plaster	Beige	Chipping	2	19.8	Positive
1	1	Teacher Lounge/Dining	Teacher Lounge/Dining	yes	W3	Plaster	Beige	Chipping	8	10.9	Positive
1	1	Teacher Lounge/Dining	Teacher Lounge/Dining	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	Teacher Lounge/Dining	Teacher Lounge/Dining	yes	Ceiling	Plaster	Beige	Flaking	8	10.7	Positive
1	1	Teacher Lounge/Dining	Teacher Lounge/Dining	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Teacher Lounge Left side Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage	Teacher Lounge Left side Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage	Teacher Lounge Left side Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage	Teacher Lounge Left side Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage	Teacher Lounge Left side Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage	Teacher Lounge Left side Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage	Teacher Lounge Right side Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage	Teacher Lounge Right side Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage	Teacher Lounge Right side Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage	Teacher Lounge Right side Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage	Teacher Lounge Right side Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Storage	Teacher Lounge Right side Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Primary	Classroom 106	yes	W1	Plaster	Beige	Chipping	3	1.7	Positive
1	1	Primary	Classroom 106	yes	W2	Plaster	Beige	Chipping, Flaking	7	15	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	Primary	Classroom 106	yes	W3	Plaster	Beige	Efflorescence, Flaking	15	12.5	Positive
1	1	Primary	Classroom 106	yes	W4	Plaster	Beige	Flaking	6	3.4	Positive
1	1	Primary	Classroom 106	yes	Ceiling	Plaster	Beige	Efflorescence, Flaking	8	10.8	Positive
1	1	Primary	Classroom 106	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Classroom 106 Coat Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	Storage	Classroom 106 Coat Closet	yes	W2	Plaster	Beige	Flaking	25	12.4	Positive
1	1	Storage	Classroom 106 Coat Closet	yes	W3	Plaster	Beige	Flaking, Efflorescence	20	15.5	Positive
1	1	Storage	Classroom 106 Coat Closet	yes	W4	Plaster	Beige	Cracking	30	10.6	Positive
1	1	Storage	Classroom 106 Coat Closet	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	1	Storage	Classroom 106 Coat Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Classroom 103 Closet by entrance	yes	W1	Plaster	Beige	Flaking	2	10.3	Positive
1	1	Storage	Classroom 103 Closet by entrance	yes	W2	Plaster	Beige	Flaking	15	10.1	Positive
1	1	Storage	Classroom 103 Closet by entrance	yes	W3	Plaster	Beige	Flaking	15	21.4	Positive
1	1	Storage	Classroom 103 Closet by entrance	yes	W4	Plaster	Beige	Flaking	15	7.1	Positive
1	1	Storage	Classroom 103 Closet by entrance	yes	Ceiling	Plaster	Beige	Flaking	20	7.7	Positive
1	1	Storage	Classroom 103 Closet by entrance	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Administrative Office	Nurse's Office	yes	W1	Plaster	Pink	Flaking	10	26.7	Positive
1	1	Administrative Office	Nurse's Office	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Administrative Office	Nurse's Office	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Administrative Office	Nurse's Office	yes	W2	Plaster	Pink	Cracking, Friction	15	18.9	Positive
1	1	Administrative Office	Nurse's Office	yes	W3	Plaster	Pink	Cracking, Efflorescence	12	34.8	Positive
1	1	Administrative Office	Nurse's Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Administrative Office	Nurse's Office	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A



School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Administrative Office	Nurse's Office	yes	W4	Plaster	Pink	Friction	4	20.2	Positive
1	1	Administrative Office	Nurse's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Administrative Office	Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	restrooms, Staff - Male/Female	Nurse's Office Restroom	yes	W1	Plaster	Pink	None	0	N/A	N/A
1	1	restrooms, Staff - Male/Female	Nurse's Office Restroom	yes	W2	Plaster	Pink	Cracking	3	18	Positive
1	1	restrooms, Staff - Male/Female	Nurse's Office Restroom	yes	W3	Plaster	Pink	Flaking	5	15.8	Positive
1	1	restrooms, Staff - Male/Female	Nurse's Office Restroom	yes	W4	Plaster	Pink	Holes in plaster	2	18.7	Positive
1	1	restrooms, Staff - Male/Female	Nurse's Office Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	restrooms, Staff - Male/Female	Nurse's Office Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Service Closets	Custodial Closet in hallway outside Classroom 107	no	W1	Plaster	Beige	None	0	N/A	N/A
1	1	Service Closets	Custodial Closet in hallway outside Classroom 107	no	W2	Plaster	Beige	Cracking	20	12.9	Positive
1	1	Service Closets	Custodial Closet in hallway outside Classroom 107	no	W3	Plaster	Beige	Cracking	25	9.5	Positive
1	1	Service Closets	Custodial Closet in hallway outside Classroom 107	no	W4	Plaster	Beige	None	0	N/A	N/A
1	1	Service Closets	Custodial Closet in hallway outside Classroom 107	no	Ceiling	Plaster	Beige	Damaged Plaster	16	9.3	Positive
1	1	Service Closets	Custodial Closet in hallway outside Classroom 107	no	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	Primary	Classroom 107	yes	W1	Plaster	Beige	Chipping	3	14.6	Positive
1	1	Primary	Classroom 107	yes	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 107	yes	W3	Plaster	Beige	Flaking, Cracking	10	14.3	Positive
1	1	Primary	Classroom 107	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	Primary	Classroom 107	yes	W4	Plaster	Beige	Chipping	2	9.6	Positive
1	1	Primary	Classroom 107	yes	Ceiling	Plaster	Beige	Flaking	4	15.5	Positive
1	1	Primary	Classroom 107	yes	Floor	Carpet/Floor Tile	N/A	N/A	N/A	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	W1	Plaster	Beige	Cracking	10	9.1	Positive
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	W2	Plaster	Beige	Spalling	6	6.9	Positive
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	W3	Plaster	Beige	Cracking, holes in plaster	5	1.5	Positive
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	Ceiling	Plaster	Beige	Efflorescence	4	No Test	Positive
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Classroom 107 Closet	yes	W1	Plaster	Beige	None	0	10.4	Positive
1	1	Storage	Classroom 107 Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	10.1	Positive
1	1	Storage	Classroom 107 Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	10.1	Positive
1	1	Storage	Classroom 107 Closet	yes	W4	Plaster	Beige	Partially Inaccessible	0	11.5	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	Storage	Classroom 107 Closet	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	1	Storage	Classroom 107 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 108	yes	W1	Plaster	Beige	Chipping	6	17.4	Positive
1	1	Primary	Classroom 108	yes	W2	Plaster	Beige	Chipping	2	17.2	Positive
1	1	Primary	Classroom 108	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 108	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 108	yes	W3	Plaster	Beige	Spalling, Cracking	4	10.6	Positive
1	1	Primary	Classroom 108	yes	W4	Plaster	Beige	Crack in plaster	3	10.5	Positive
1	1	Primary	Classroom 108	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Primary	Classroom 108	yes	Ceiling	Plaster	Beige	Efflorescence	4	2.8	Positive
1	1	Primary	Classroom 108	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W3	Plaster	Beige	Chipping	2	1.5	Positive
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	W4	Plaster	Beige	Cracking	2	14.3	Positive
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	Ceiling	Plaster	Beige	Flaking	3	4.1	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Classroom 108 Closet	yes	W1	Plaster	Beige	No Access	No Access	No Access	No Access
1	1	Storage	Classroom 108 Closet	yes	W2	Plaster	Beige	No Access	No Access	No Access	No Access
1	1	Storage	Classroom 108 Closet	yes	W3	Plaster	Beige	No Access	No Access	No Access	No Access
1	1	Storage	Classroom 108 Closet	yes	W4	Plaster	Beige	No Access	No Access	No Access	No Access
1	1	Storage	Classroom 108 Closet	yes	Ceiling	Plaster	Beige	No Access	No Access	No Access	No Access
1	1	Storage	Classroom 108 Closet	yes	Floor	Plaster	Beige	No Access	No Access	No Access	No Access
1	1	Primary	Classroom 109	yes	W1	Plaster	Beige	Chipping	3	17.6	Positive
1	1	Primary	Classroom 109	yes	W2	Plaster	Beige	Chipping	5	20.5	Positive
1	1	Primary	Classroom 109	yes	W3	Plaster	Beige	Efflorescence, Chipping, flaking	12	1	Positive
1	1	Primary	Classroom 109	yes	W4	Plaster	Beige	Cracking	10	3.7	Positive
1	1	Primary	Classroom 109	yes	Ceiling	Plaster	Beige	Efflorescence	20	2.9	Positive
1	1	Primary	Classroom 109	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 109 Restroom (common to Classroom 108)	yes	W1	Plaster	Purple	Damaged plaster	3	1.2	Positive
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 109 Restroom (common to Classroom 108)	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 109 Restroom (common to Classroom 108)	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 109 Restroom (common to Classroom 108)	yes	W2	Sheetrock	Beige	Hole	1	0	Negative

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 109 Restroom (common to Classroom 108)	yes	W3	Plaster	Purple	Flaking	2	13.2	Positive
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 109 Restroom (common to Classroom 108)	yes	W4	Plaster	Purple	Flaking	2	13.9	Positive
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 109 Restroom (common to Classroom 108)	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	Student Restrooms - Male/Female (Classroom)	Classroom 109 Restroom (common to Classroom 108)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Classroom 109 Coat Closet	yes	W1	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
1	1	Storage	Classroom 109 Coat Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
1	1	Storage	Classroom 109 Coat Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	Storage	Classroom 109 Coat Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	Storage	Classroom 109 Coat Closet	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Classroom 109 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Classroom 109 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	Storage	Classroom 109 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	Storage	Classroom 109 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	Storage	Classroom 109 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	Storage	Classroom 109 Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	Storage	Classroom 109 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Auditorium	Auditorium	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	Auditorium	Auditorium	yes	W2	Plaster	Beige	none	0	N/A	N/A
1	1	Auditorium	Auditorium	yes	W3	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Auditorium	Auditorium	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	Auditorium	Auditorium	yes	Ceiling	Plaster	White	Efflorescence, Flaking	45	No Test	Positive
1	1	Auditorium	Auditorium	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Stage	Auditorium Stage	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	Stage	Auditorium Stage	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	Stage	Auditorium Stage	yes	W3	Plaster	Beige	Friction	4	0.06	Negative
1	1	Stage	Auditorium Stage	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	Stage	Auditorium Stage	yes	Ceiling	Plaster	Beige	Flaking	8	No Test	Positive
1	1	Stage	Auditorium Stage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Storage to the left of Stage	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	Storage	Storage to the left of Stage	yes	W2	Plaster	Beige	Spalling, Efflorescence	6	8.8	Positive
1	1	Storage	Storage to the left of Stage	yes	W3	Plaster	Beige	Efflorescence	3	7.5	Positive
1	1	Storage	Storage to the left of Stage	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	Storage	Storage to the left of Stage	yes	Ceiling	Plaster	Beige	Efflorescence, Flaking	4	12.4	Positive
1	1	Storage	Storage to the left of Stage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Storage to the right of Stage	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	Storage	Storage to the right of Stage	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	Storage	Storage to the right of Stage	yes	W3	Plaster	Beige	Spalling, Efflorescence, Cracking	4	0.04	Negative
1	1	Storage	Storage to the right of Stage	yes	W4	Plaster	Beige	Spalling, Efflorescence, Cracking	12	0.14	Negative
1	1	Storage	Storage to the right of Stage	yes	Ceiling	Plaster	Beige	Efflorescence	2	11.5	Positive
1	1	Storage	Storage to the right of Stage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	Circulation (Hallway)	Hallway at Classrooms 107 to 109	yes	W1	No Wall	N/A	N/A	N/A	N/A	N/A
1	1	Circulation (Hallway)	Hallway at Classrooms 107 to 109	yes	W2	Plaster	Yellow	Chipping	6	30.2	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Circulation (Hallway)	Hallway at Classrooms 107 to 109	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	1	Circulation (Hallway)	Hallway at Classrooms 107 to 109	yes	W4	Plaster	Yellow	Chipping	3	23.1	Positive
1	1	Circulation (Hallway)	Hallway at Classrooms 107 to 109	yes	Ceiling	Plaster	Beige	Flaking	6	13.5	Positive
1	1	Circulation (Hallway)	Hallway at Classrooms 107 to 109	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	Circulation (Hallway)	Hallway at Main Office	yes	W1	Plaster	Yellow	Chipping	2	24.2	Positive
1	1	Circulation (Hallway)	Hallway at Main Office	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	1	Circulation (Hallway)	Hallway at Main Office	yes	W3	Plaster	Yellow	Chipping	2	25	Positive
1	1	Circulation (Hallway)	Hallway at Main Office	yes	W4	Plaster	Yellow	Chipping	2	22.4	Positive
1	1	Circulation (Hallway)	Hallway at Main Office	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	1	Circulation (Hallway)	Hallway at Main Office	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	Circulation (Hallway)	Hallway at Classrooms 101 and 102	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	1	Circulation (Hallway)	Hallway at Classrooms 101 and 102	yes	W2	Plaster	Yellow	Chipping	2	24.7	Positive
1	1	Circulation (Hallway)	Hallway at Classrooms 101 and 102	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	1	Circulation (Hallway)	Hallway at Classrooms 101 and 102	yes	W4	Plaster	Yellow	Chipping	2	24.1	Positive
1	1	Circulation (Hallway)	Hallway at Classrooms 101 and 102	yes	Ceiling	Plaster	Beige	Flaking	6	No Test	Positive
1	1	Circulation (Hallway)	Hallway at Classrooms 101 and 102	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	Stairs	Stairwell across from Room 104	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	Stairs	Stairwell across from Room 104	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	1	Stairs	Stairwell across from Room 104	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	Stairs	Stairwell across from Room 104	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	Stairs	Stairwell across from Room 104	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairs	Stairwell across from Room 104	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairs	Stairwell across from Room 104	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	Stairs	Stairwell across from Room 104	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	1	Stairs	Stairwell across from Room 104	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	Stairs	Stairwell across from Room 107	yes	W1	Plaster	Beige	Cracking	8	19.3	Positive
1	1	Stairs	Stairwell across from Room 107	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairs	Stairwell across from Room 107	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairs	Stairwell across from Room 107	yes	W2	Plaster	Beige	Cracking	30	20.8	Positive
1	1	Stairs	Stairwell across from Room 107	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairs	Stairwell across from Room 107	yes	W3	Plaster	Beige	Cracking, Flaking	20	20.5	Positive
1	1	Stairs	Stairwell across from Room 107	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairs	Stairwell across from Room 107	yes	W4	Plaster	Beige	Cracking, Damaged plaster	35	17.6	Positive
1	1	Stairs	Stairwell across from Room 107	yes	Ceiling	Concrete	White	Flaking	5	19.3	Positive
1	1	Stairs	Stairwell across from Room 107	yes	Ceiling	Plaster	White	Cracking	6	1.5	Positive
1	1	Stairs	Stairwell across from Room 107	yes	Floor	Concrete	Black	Friction	10	0.04	Negative
1	1	Stairs	Stairwell across from Room 107	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairs	Stairwell across from Room 107	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairs	Stairwell next to Classroom 109	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	Stairs	Stairwell next to Classroom 109	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	Stairs	Stairwell next to Classroom 109	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairs	Stairwell next to Classroom 109	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	Stairs	Stairwell next to Classroom 109	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	Stairs	Stairwell next to Classroom 109	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	1	Stairs	Stairwell next to Classroom 109	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	Stairs	Main Entrance Lobby	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	1	Stairs	Main Entrance Lobby	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	1	Stairs	Main Entrance Lobby	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A



School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	1	Stairs	Main Entrance Lobby	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	1	Stairs	Main Entrance Lobby	yes	W4	Plaster	Blue	Flaking	1	21.4	Positive
1	1	Stairs	Main Entrance Lobby	yes	Ceiling	Plaster	Blue	Efflorescence, Cracking	6	19.3	Positive
1	1	Stairs	Main Entrance Lobby	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairs	Main Entrance Lobby	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairs	Main Entrance Lobby	yes	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 201	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Primary	Classroom 201	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Primary	Classroom 201	yes	W3	Plaster	Beige	Efflorescence, Cracking, Chipping	7	12	Positive
1	2	Primary	Classroom 201	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Primary	Classroom 201	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 201	yes	Ceiling	Plaster	White	Efflorescence, Flaking	6	5.4	Positive
1	2	Primary	Classroom 201	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 201 Coat Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 201 Coat Closet	yes	W2	Plaster	Beige	Cracking, Flaking	4	16.3	Positive
1	2	Storage	Classroom 201 Coat Closet	yes	W3	Plaster	Beige	Efflorescence, Flaking, Cracking	40	16.3	Positive
1	2	Storage	Classroom 201 Coat Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 201 Coat Closet	yes	Ceiling	Plaster	White	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 201 Coat Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 201 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 201 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 201 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 201 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 201 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 201 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Restrooms, Staff - Male/Female	Restroom outside Classroom 201	yes	W1	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	2	Restrooms, Staff - Male/Female	Restroom outside Classroom 201	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Restroom outside Classroom 201	yes	W3	Plaster	Beige	Peeling, Cracking, Damage	4	20.5	Positive
1	2	Restrooms, Staff - Male/Female	Restroom outside Classroom 201	yes	W4	Plaster	Beige	Crack in plaster	2	23.6	Positive
1	2	Restrooms, Staff - Male/Female	Restroom outside Classroom 201	yes	Ceiling	Concrete	White	Crack	4	5.8	Positive
1	2	Restrooms, Staff - Male/Female	Restroom outside Classroom 201	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Room 200 - Storage outside Classroom 201	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Room 200 - Storage outside Classroom 201	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Room 200 - Storage outside Classroom 201	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Room 200 - Storage outside Classroom 201	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Room 200 - Storage outside Classroom 201	yes	Ceiling	Concrete	White	Flaking	4	12.8	Positive
1	2	Storage	Room 200 - Storage outside Classroom 201	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 202	yes	W1	Plaster	Beige	Flaking	2	20.7	Positive
1	2	Primary	Classroom 202	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 202	yes	W2	Plaster	Beige	Flaking	2	20.6	Positive
1	2	Primary	Classroom 202	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 202	yes	W3	Plaster	Beige	Flaking	2	0.03	Negative
1	2	Primary	Classroom 202	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 202	yes	W4	Plaster	Beige	Flaking	2	14.1	Positive
1	2	Primary	Classroom 202	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 202	yes	Ceiling	Plaster	White	Efflorescence	6	1.5	Positive
1	2	Primary	Classroom 202	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 202 Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 202 Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 202 Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 202 Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 202 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 202 Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	2	Storage	Classroom 202 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 202 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 202 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 202 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 202 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 202 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 202	yes	W1	Plaster	Beige	Damaged plaster	2	0	Negative
1	2	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 202	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 202	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 202	yes	W4	Plaster	Beige	Flaking	10	1	Positive
1	2	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 202	yes	Ceiling	Plaster	White	fluorescence, Flaking	15	1	Positive
1	2	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 202	yes	Floor	Concrete	Grey	Friction	20	0.08	Negative
1	2	Storage	Book Closet near Boy's Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Book Closet near Boy's Restroom	yes	W2	Plaster	Beige	Flaking	2	10.6	Positive
1	2	Storage	Book Closet near Boy's Restroom	yes	W3	Plaster	Beige	Flaking	3	10.1	Positive
1	2	Storage	Book Closet near Boy's Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Book Closet near Boy's Restroom	yes	Ceiling	Plaster	White	Flaking	3	10.4	Positive
1	2	Storage	Book Closet near Boy's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	Primary	Classroom 203	yes	W1	Plaster	Beige	Chipping	2	21.4	Positive
1	2	Primary	Classroom 203	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Primary	Classroom 203	yes	W3	Plaster	Beige	Chipping	2	26.5	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	Primary	Classroom 203	yes	W4	Plaster	Beige	Chipping	2	19.5	Positive
1	2	Primary	Classroom 203	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	Primary	Classroom 203	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 203 Storage	yes	W1	Plaster	Beige	Chipping	2	16.9	Positive
1	2	Storage	Classroom 203 Storage	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 203 Storage	yes	W3	Plaster	Beige	Spalling	15	2.9	Positive
1	2	Storage	Classroom 203 Storage	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 203 Storage	yes	Ceiling	Plaster	White	Efflorescence	3	14.6	Positive
1	2	Storage	Classroom 203 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 203 Closet to the left of entrance	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 203 Closet to the left of entrance	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 203 Closet to the left of entrance	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 203 Closet to the left of entrance	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 203 Closet to the left of entrance	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 203 Closet to the left of entrance	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 203 Closet to the right of entrance	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 203 Closet to the right of entrance	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 203 Closet to the right of entrance	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 203 Closet to the right of entrance	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 203 Closet to the right of entrance	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 203 Closet to the right of entrance	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Administrative Office	School Psychologist's Office next to Room 203	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Administrative Office	School Psychologist's Office next to Room 203	yes	W2	Plaster	Beige	Cracking	2	1.4	Positive
1	2	Administrative Office	School Psychologist's Office next to Room 203	yes	W3	Plaster	Beige	Cracking	2	1.9	Positive
1	2	Administrative Office	School Psychologist's Office next to Room 203	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Administrative Office	School Psychologist's Office next to Room 203	yes	W4	Plaster	Beige	Cracking	2	1.4	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	2	Administrative Office	School Psychologist's Office next to Room 203	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Administrative Office	School Psychologist's Office next to Room 203	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Storage in Room 203A -School Psychologist's Office next to Room 203	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Storage in Room 203A -School Psychologist's Office next to Room 203	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Storage in Room 203A -School Psychologist's Office next to Room 203	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Storage in Room 203A -School Psychologist's Office next to Room 203	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Storage in Room 203A -School Psychologist's Office next to Room 203	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Storage in Room 203A -School Psychologist's Office next to Room 203	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Primary	Classroom 204	yes	W1	Plaster	Beige	Flaking	5	23.6	Positive
1	2	Primary	Classroom 204	yes	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 204	yes	W3	Plaster	Beige	Flaking	8	0	Negative
1	2	Primary	Classroom 204	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 204	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 204	yes	W4	Plaster	Beige	Flaking	5	21	Positive
1	2	Primary	Classroom 204	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	Primary	Classroom 204	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 204 Storage	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 204 Storage	yes	W2	Plaster	Beige	Friction	2	8.3	Positive
1	2	Storage	Classroom 204 Storage	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 204 Storage	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 204 Storage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	Storage	Classroom 204 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 204 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 204 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	Storage	Classroom 204 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 204 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 204 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 204 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Primary	Classroom 205	yes	W1	Plaster	Beige	Cracking	2	26.6	Positive
1	2	Primary	Classroom 205	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 205	yes	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 205	yes	W3	Plaster	Beige	Flaking, Spalling	5	16.1	Positive
1	2	Primary	Classroom 205	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 205	yes	W4	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 205	yes	Ceiling	Plaster	White	Efflorescence	4	1.4	Positive
1	2	Primary	Classroom 205	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 205 Storage	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 205 Storage	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 205 Storage	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 205 Storage	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 205 Storage	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 205 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 205 Closet to the left of entrance	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 205 Closet to the left of entrance	yes	W2	Plaster	Beige	Crack in plaster	5	11.3	Positive
1	2	Storage	Classroom 205 Closet to the left of entrance	yes	W3	Plaster	Beige	Partially Inaccessible	0	9.5	Positive
1	2	Storage	Classroom 205 Closet to the left of entrance	yes	W4	Plaster	Beige	Partially Inaccessible	0	10.2	Positive
1	2	Storage	Classroom 205 Closet to the left of entrance	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	Storage	Classroom 205 Closet to the left of entrance	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 206	yes	W1	Plaster	Beige	Chipping	2	13.3	Positive
1	2	Primary	Classroom 206	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 206	yes	W2	Plaster	Beige	Chipping, Spalling	10	25	Positive
1	2	Primary	Classroom 206	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 206	yes	W3	Plaster	Beige	Spalling, Damage	6	14.6	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	2	Primary	Classroom 206	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 206	yes	W4	Wood/Plaster	Beige	None	0	N/A	N/A
1	2	Primary	Classroom 206	yes	Ceiling	Plaster	White	ing, Damaged pla	4	1.3	Positive
1	2	Primary	Classroom 206	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 206 Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 206 Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 206 Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 206 Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 206 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 206 Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 206 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 206 Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
1	2	Storage	Classroom 206 Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
1	2	Storage		yes	W4	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
1	2	Storage	Classroom 206 Closet	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 206 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Student Restrooms - Female (4-12)	Girl's Restroom next to Room 206	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Student Restrooms - Female (4-12)	Girl's Restroom next to Room 206	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Student Restrooms - Female (4-12)	Girl's Restroom next to Room 206	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	Student Restrooms - Female (4-12)	Girl's Restroom next to Room 206	yes	W4	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	2	Student Restrooms - Female (4-12)	Girl's Restroom next to Room 206	yes	Ceiling	Plaster	White	Flaking	2	7.3	Positive
1	2	Student Restrooms - Female (4-12)	Girl's Restroom next to Room 206	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	Storage	Book Closet near Girl's Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Book Closet near Girl's Restroom	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Book Closet near Girl's Restroom	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Book Closet near Girl's Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Book Closet near Girl's Restroom	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Book Closet near Girl's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	Service Closets	Custodial Closet in hallway outside Classroom 207	no	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Service Closets	Custodial Closet in hallway outside Classroom 207	no	W2	Plaster	Beige	Cracking	20	14	Positive
1	2	Service Closets	Custodial Closet in hallway outside Classroom 207	no	W3	Plaster	Beige	Cracking	40	13.5	Positive
1	2	Service Closets	Custodial Closet in hallway outside Classroom 207	no	W4	Plaster	Beige	Cracking	40	13.9	Positive
1	2	Service Closets	Custodial Closet in hallway outside Classroom 207	no	Ceiling	Plaster	White	Chipping, Damaged Plaster	16	20.7	Positive
1	2	Service Closets	Custodial Closet in hallway outside Classroom 207	no	Floor	Concrete	Grey	Friction	4	0.07	Negative
1	2	Primary	Classroom 207	yes	W1	Plaster	Beige	Chipping	2	21	Positive
1	2	Primary	Classroom 207	yes	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 207	yes	W3	Plaster	Beige	Spalling, Cracking	2	8.1	Positive
1	2	Primary	Classroom 207	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 207	yes	W4	Plaster	Beige	Spalling, Chipping	10	8.2	Positive
1	2	Primary	Classroom 207	yes	Ceiling	Plaster	White	Chipping, Damaged plaster	6	4.8	Positive
1	2	Primary	Classroom 207	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 207 Storage	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 207 Storage	yes	W2	Plaster	Beige	Spalling	6	1.1	Positive



School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	Storage	Classroom 207 Storage	yes	W3	Plaster	Beige	Partially Inaccessible	0	11.4	Positive
1	2	Storage	Classroom 207 Storage	yes	W4	Plaster	Beige	None	0	12.9	Positive
1	2	Storage	Classroom 207 Storage	yes	Ceiling	Plaster	White	Efflorescence	4	No test	Positive
1	2	Storage	Classroom 207 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 207 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 207 Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	10.1	Positive
1	2	Storage	Classroom 207 Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	5.8	Positive
1	2	Storage	Classroom 207 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 207 Closet	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 207 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 208	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Primary	Classroom 208	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Primary	Classroom 208	yes	W3	Plaster	Beige	Spalling, Cracking	8	10.7	Positive
1	2	Primary	Classroom 208	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 208	yes	W4	Plaster/Wood	Beige	None	0	N/A	N/A
1	2	Primary	Classroom 208	yes	Ceiling	Plaster	White	scence, Damaged	8	19.8	Positive
1	2	Primary	Classroom 208	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 208 Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 208 Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 208 Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 208 Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 208 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 208 Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 208 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 208 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 208 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 208 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 208 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage	Classroom 208 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	2	Primary	Classroom 209	yes	W1	Plaster	Beige	Flaking	1	20.7	Positive
1	2	Primary	Classroom 209	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Primary	Classroom 209	yes	W3	Plaster	Beige	Efflorescence, Spalling	50	0.01	Negative
1	2	Primary	Classroom 209	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Primary	Classroom 209	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Primary	Classroom 209	yes	Ceiling	Plaster	White	Flaking	3	1.4	Positive
1	2	Primary	Classroom 209	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 209 Storage	yes	W1	Plaster	Beige	Spalling, Damaged plaster	4	14.9	Positive
1	2	Storage	Classroom 209 Storage	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 209 Storage	yes	W3	Plaster	Beige	Cracking	2	11.9	Positive
1	2	Storage	Classroom 209 Storage	yes	W4	Plaster	Beige	Efflorescence, Flaking, Spalling	30	0	Negative
1	2	Storage	Classroom 209 Storage	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 209 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Storage	Classroom 209 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 209 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 209 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 209 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 209 Closet	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Classroom 209 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Restroom above Storage to the right of Stage	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Restroom above Storage to the right of Stage	yes	W2	Plaster	Beige	Flaking	3	13	Positive
1	2	Restrooms, Staff - Male/Female	Restroom above Storage to the right of Stage	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Restroom above Storage to the right of Stage	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Restroom above Storage to the right of Stage	yes	W4	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	Restrooms, Staff - Male/Female	Restroom above Storage to the right of Stage	yes	Ceiling	Plaster	Beige	Spalling, Damaged plaster	2	5.2	Positive
1	2	Restrooms, Staff - Male/Female	Restroom above Storage to the right of Stage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Toilet area of Restroom above Storage to the right of Stage	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Toilet area of Restroom above Storage to the right of Stage	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Toilet area of Restroom above Storage to the right of Stage	yes	W3	Plaster	Beige	Spalling, Flaking	2	7.7	Positive
1	2	Restrooms, Staff - Male/Female	Toilet area of Restroom above Storage to the right of Stage	yes	W4	Plaster	Beige	Flaking	2	1.6	Positive
1	2	Restrooms, Staff - Male/Female	Toilet area of Restroom above Storage to the right of Stage	yes	Ceiling	Plaster	Beige	Spalling	2	11.7	Positive
1	2	Restrooms, Staff - Male/Female	Toilet area of Restroom above Storage to the right of Stage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Restroom above Storage to the left of Stage	yes	W1	Plaster	Beige	Alligating, Cracking	12	10.2	Positive
1	2	Restrooms, Staff - Male/Female	Restroom above Storage to the left of Stage	yes	W2	Plaster	Beige	Cracking	1	11	Positive
1	2	Restrooms, Staff - Male/Female	Restroom above Storage to the left of Stage	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Restroom above Storage to the left of Stage	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Restroom above Storage to the left of Stage	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Restroom above Storage to the left of Stage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Toilet area of Restroom above Storage to the left of Stage	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Toilet area of Restroom above Storage to the left of Stage	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Toilet area of Restroom above Storage to the left of Stage	yes	W3	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	2	Restrooms, Staff - Male/Female	Toilet area of Restroom above Storage to the left of Stage	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Toilet area of Restroom above Storage to the left of Stage	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	2	Restrooms, Staff - Male/Female	Toilet area of Restroom above Storage to the left of Stage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	Circulation (Hallway)	Hallway at Classrooms 207 to 209	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	Circulation (Hallway)	Hallway at Classrooms 207 to 209	yes	W2	Plaster	Yellow	Cracking, Damaged plaster	2	0.11	Negative
1	2	Circulation (Hallway)	Hallway at Classrooms 207 to 209	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Circulation (Hallway)	Hallway at Classrooms 207 to 209	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	2	Circulation (Hallway)	Hallway at Classrooms 207 to 209	yes	W4	Plaster	Yellow	Cracking, hole in plaster	2	21.9	Positive
1	2	Circulation (Hallway)	Hallway at Classrooms 207 to 209	yes	Ceiling	Plaster	Beige	Cracking, Damaged plaster	6	No test	Positive
1	2	Circulation (Hallway)	Hallway at Classrooms 207 to 209	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	Circulation (Hallway)	Hallway at Classrooms 203 to 206	yes	W1	Plaster	Yellow	Flaking	10	25.1	Positive
1	2	Circulation (Hallway)	Hallway at Classrooms 203 to 206	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Circulation (Hallway)	Hallway at Classrooms 203 to 206	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	2	Circulation (Hallway)	Hallway at Classrooms 203 to 206	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	2	Circulation (Hallway)	Hallway at Classrooms 203 to 206	yes	W4	Plaster	Yellow	Flaking	10	21.1	Positive
1	2	Circulation (Hallway)	Hallway at Classrooms 203 to 206	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	2	Circulation (Hallway)	Hallway at Classrooms 203 to 206	yes	Floor	Concrete	Grey	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	2	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	2	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	2	Circulation (Hallway)	Hallway at Classrooms 201 and 202	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	Stairs	Stairwell across from Room 204	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Stairs	Stairwell across from Room 204	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairs	Stairwell across from Room 204	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Stairs	Stairwell across from Room 204	yes	W3	Plaster	Beige	Cracking	1	20.8	Positive
1	2	Stairs	Stairwell across from Room 204	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Stairs	Stairwell across from Room 204	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	Stairs	Stairwell across from Room 204	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	Stairs	Stairwell across from Room 207	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Stairs	Stairwell across from Room 207	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairs	Stairwell across from Room 207	yes	W2	Plaster	Beige	Chipping	10	19.4	Positive
1	2	Stairs	Stairwell across from Room 207	yes	W3	Plaster	Beige	Chipping, Flaking	14	21.8	Positive
1	2	Stairs	Stairwell across from Room 207	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairs	Stairwell across from Room 207	yes	W4	Plaster	Beige	Chipping	6	19.7	Positive
1	2	Stairs	Stairwell across from Room 207	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	Stairs	Stairwell across from Room 207	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	Stairs	Stairwell across from Room 207	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairs	Stairwell at the end of the Hallway by Room 209	yes	W1	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	2	Stairs	Stairwell at the end of the Hallway by Room 209	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	Stairs	Stairwell at the end of the Hallway by Room 209	yes	W3	Plaster	Beige	Discoloration, Cracking, Flaking	8	26.4	Positive
1	2	Stairs	Stairwell at the end of the Hallway by Room 209	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	Stairs	Stairwell at the end of the Hallway by Room 209	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	Stairs	Stairwell at the end of the Hallway by Room 209	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	Stairs	Stairwell at the end of the Hallway by Room 209	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	Storage	Storage/Projection Room across from Classroom 204	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Storage/Projection Room across from Classroom 204	yes	W2	Plaster	Beige	Cracking, Crack in plaster	5	23.7	Positive
1	2	Storage	Storage/Projection Room across from Classroom 204	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	Storage	Storage/Projection Room across from Classroom 204	yes	W4	Plaster	Beige	Crack in plaster	8	30.1	Positive
1	2	Storage	Storage/Projection Room across from Classroom 204	yes	Ceiling	Plaster	White	Crack in plaster	3	22.4	Positive
1	2	Storage	Storage/Projection Room across from Classroom 204	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	Storage	Storage Room at the end of the Hallway near Room 301	yes	W1	Plaster	Orange	None	0	N/A	N/A
1	3	Storage	Storage Room at the end of the Hallway near Room 301	yes	W2	Plaster	Orange	Friction	5	30.2	Positive
1	3	Storage	Storage Room at the end of the Hallway near Room 301	yes	W3	Plaster	Beige	Partially Inaccessible	5	23.4	Positive
1	3	Storage	Storage Room at the end of the Hallway near Room 301	yes	W4	Plaster	Orange	Efflorescence, Flaking, Damaged plaster	50	40.8	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	Storage	Storage Room at the end of the Hallway near Room 301	yes	Ceiling	Plaster	White	Efflorescence	12	23.1	Positive
1	3	Storage	Storage Room at the end of the Hallway near Room 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Art - Elementary	Classroom 301	yes	W1	Plaster	Orange	Chipping	20	21.9	Positive
1	3	Art - Elementary	Classroom 301	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Art - Elementary	Classroom 301	yes	W2	Plaster	Orange	Chipping	25	23.1	Positive
1	3	Art - Elementary	Classroom 301	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Art - Elementary	Classroom 301	yes	W3	Plaster	Orange	Chipping	10	19.9	Positive
1	3	Art - Elementary	Classroom 301	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Art - Elementary	Classroom 301	yes	W4	Plaster	Orange	Chipping	10	22.7	Positive
1	3	Art - Elementary	Classroom 301	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Art - Elementary	Classroom 301	yes	Ceiling	Plaster	White	Efflorescence, Flaking	12	22.4	Positive
1	3	Art - Elementary	Classroom 301	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 301 Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 301 Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 301 Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 301 Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 301 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 301 Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Art - Elementary	Classroom 302	yes	W1	Plaster	Orange	Chipping	15	22.8	Positive
1	3	Art - Elementary	Classroom 302	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Art - Elementary	Classroom 302	yes	W2	Plaster	Orange	Chipping	20	17.6	Positive
1	3	Art - Elementary	Classroom 302	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Art - Elementary	Classroom 302	yes	W3	Plaster	Orange	Chipping	10	17.7	Positive
1	3	Art - Elementary	Classroom 302	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Art - Elementary	Classroom 302	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Art - Elementary	Classroom 302	yes	W4	Plaster	Orange	Chipping	20	19.7	Positive
1	3	Art - Elementary	Classroom 302	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Art - Elementary	Classroom 302	yes	Ceiling	Plaster	White	Efflorescence, Flaking	12	19.4	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	3	Art - Elementary	Classroom 302	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 302 Storage	yes	W1	Plaster	White	Cracking, Damaged plaster	5	18.5	Positive
1	3	Storage	Classroom 302 Storage	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	Storage	Classroom 302 Storage	yes	W3	Plaster	White	Chipping, Crack in plaster wall	8	2.4	Positive
1	3	Storage	Classroom 302 Storage	yes	W4	Plaster	White	Efflorescence, Cracking	10	1.7	Positive
1	3	Storage	Classroom 302 Storage	yes	Ceiling	Plaster	White	Efflorescence	2	No test	Positive
1	3	Storage	Classroom 302 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 302 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 302 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 302 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 302 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 302 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 302 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Student Restrooms - Male (4-12)	Boy's Restroom next to Room 302	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	Student Restrooms - Male (4-12)	Boy's Restroom next to Room 302	yes	W2	Plaster	Beige	Cracking, Damaged plaster	4	19.5	Positive
1	3	Student Restrooms - Male (4-12)	Boy's Restroom next to Room 302	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	Student Restrooms - Male (4-12)	Boy's Restroom next to Room 302	yes	W4	Plaster	Beige	Flaking	10	0.06	Negative
1	3	Student Restrooms - Male (4-12)	Boy's Restroom next to Room 302	yes	Ceiling	Plaster	White	Efflorescence	5	14.8	Positive



School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	3	Student Restrooms - Male (4-12)	Boy's Restroom next to Room 302	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	Storage	Book Closet by Boy's Restroom next to Room 302	yes	W1	Plaster	Green	None	0	N/A	N/A
1	3	Storage	Book Closet by Boy's Restroom next to Room 302	yes	W2	Plaster	Green	Partially Inaccessible	2	4.8	Positive
1	3	Storage	Book Closet by Boy's Restroom next to Room 302	yes	W3	Plaster	Green	Partially Inaccessible	3	9.5	Positive
1	3	Storage	Book Closet by Boy's Restroom next to Room 302	yes	W4	Plaster	Green	None	0	N/A	N/A
1	3	Storage	Book Closet by Boy's Restroom next to Room 302	yes	Ceiling	Plaster	White	Flaking	5	10.1	Positive
1	3	Storage	Book Closet by Boy's Restroom next to Room 302	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	Computer Room	Classroom 303	yes	W1	Plaster	Beige	Chipping	3	19.5	Positive
1	3	Computer Room	Classroom 303	yes	W2	Plaster	Beige	Chipping	4	20	Positive
1	3	Computer Room	Classroom 303	yes	W3	Plaster	Beige	Efflorescence, Chipping, Damaged plaster	25	14.7	Positive
1	3	Computer Room	Classroom 303	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Computer Room	Classroom 303	yes	W4	Plaster	Beige	Flaking	45	16.8	Positive
1	3	Computer Room	Classroom 303	yes	Ceiling	Plaster	White	Flaking	15	26.8	Positive
1	3	Computer Room	Classroom 303	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 303 Storage	yes	W1	Plaster	Beige	Cracking	5	17.6	Positive
1	3	Storage	Classroom 303 Storage	yes	W2	Plaster	Beige	Efflorescence	15	10.9	Positive
1	3	Storage	Classroom 303 Storage	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 303 Storage	yes	W3	Plaster	Beige	Flaking	6	18.3	Positive
1	3	Storage	Classroom 303 Storage	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	Storage	Classroom 303 Storage	yes	Ceiling	Plaster	White	Efflorescence	6	16.3	Positive
1	3	Storage	Classroom 303 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 303 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 303 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	Storage	Classroom 303 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 303 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 303 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 303 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Primary	Classroom 304	yes	W1	Plaster	Beige	Chipping, Damaged Plaster	5	16	Positive
1	3	Primary	Classroom 304	yes	W2	Sheetrock	Beige	Scraped	3	0.01	Negative
1	3	Primary	Classroom 304	yes	W3	Plaster	Beige	Cracking, Damaged Plaster	15	25.8	Positive
1	3	Primary	Classroom 304	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 304	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	Primary	Classroom 304	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 304	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 304 Storage 1	yes	W1	Plaster	Beige	None	0	18.5	Positive
1	3	Storage	Classroom 304 Storage 1	yes	W2	Plaster	Beige	Partially Inaccessible	0	14.9	Positive
1	3	Storage	Classroom 304 Storage 1	yes	W3	Plaster	Beige	Partially Inaccessible	0	18.2	Positive
1	3	Storage	Classroom 304 Storage 1	yes	W4	Plaster	Beige	Partially Inaccessible	0	12.8	Positive
1	3	Storage	Classroom 304 Storage 1	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 304 Storage 1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 304 Storage 2	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	Storage	Classroom 304 Storage 2	yes	W2	Plaster	Beige	Chipping	4	12.2	Positive
1	3	Storage	Classroom 304 Storage 2	yes	W3	Plaster	Beige	Chipping	5	12.7	Positive
1	3	Storage	Classroom 304 Storage 2	yes	W4	Plaster	Beige	Chipping	4	9.9	Positive
1	3	Storage	Classroom 304 Storage 2	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 304 Storage 2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 304 Closet	yes	W1	Plaster	Green	None	0	N/A	N/A
1	3	Storage	Classroom 304 Closet	yes	W2	Plaster	Green	Partially Inaccessible	0	7.2	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	Storage	Classroom 304 Closet	yes	W3	Plaster	Green	Partially Inaccessible	0	6.2	Positive
1	3	Storage	Classroom 304 Closet	yes	W4	Plaster	Green	Crack in Plaster	8	1.8	Positive
1	3	Storage	Classroom 304 Closet	yes	Ceiling	Plaster	Green	Damaged Plaster	1	10.1	Positive
1	3	Storage	Classroom 304 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 305	yes	W1	Plaster	Orange	Chipping, Damaged Plaster	10	19.5	Positive
1	3	Primary	Classroom 305	yes	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 305	yes	W3	Plaster	Orange	Spalling, Damaged Plaster	5	20.8	Positive
1	3	Primary	Classroom 305	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 305	yes	W4	Sheetrock	White	Scratched	2	0	Negative
1	3	Primary	Classroom 305	yes	Ceiling	Plaster	White	Efflorescence, Damaged Plaster	10	19.1	Positive
1	3	Primary	Classroom 305	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 305 Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 305 Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 305 Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 305 Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 305 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 305 Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 305 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 305 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 305 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 305 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 305 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 305 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Primary	Classroom 306	yes	W1	Plaster	Beige	Flaking	6	22.3	Positive
1	3	Primary	Classroom 306	yes	W2	Plaster	Beige	Efflorescence, Spalling	100	1.1	Positive
1	3	Primary	Classroom 306	yes	W3	Plaster	Beige	Efflorescence, Flaking	22	24	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	3	Primary	Classroom 306	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 306	yes	W4	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 306	yes	Ceiling	Plaster	Beige	Efflorescence	8	4.2	Positive
1	3	Primary	Classroom 306	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 306 Storage	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	Storage	Classroom 306 Storage	yes	W2	Plaster	Beige	Cracking	2	7.9	Positive
1	3	Storage	Classroom 306 Storage	yes	W3	Plaster	Beige	Cracking	5	No test	Positive
1	3	Storage	Classroom 306 Storage	yes	W4	Plaster	Beige	Spalling	20	12.5	Positive
1	3	Storage	Classroom 306 Storage	yes	Ceiling	Plaster	Beige	Spalling	6	No Test	Positive
1	3	Storage	Classroom 306 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 306 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 306 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 306 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 306 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 306 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 306 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Student Restrooms - Female (4-12)	Girl's Restroom next to Room 306	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	Student Restrooms - Female (4-12)	Girl's Restroom next to Room 306	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	Student Restrooms - Female (4-12)	Girl's Restroom next to Room 306	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	Student Restrooms - Female (4-12)	Girl's Restroom next to Room 306	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	Student Restrooms - Female (4-12)	Girl's Restroom next to Room 306	yes	Ceiling	Plaster	White	Flaking	3	19.4	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	3	Student Restrooms - Female (4-12)	Girl's Restroom next to Room 306	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	Storage	Book Closet next to Girl's Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	Storage	Book Closet next to Girl's Restroom	yes	W2	Plaster	Beige	Flaking	20	0.02	Negative
1	3	Storage	Book Closet next to Girl's Restroom	yes	W3	Plaster	Beige	Flaking, Crack in plaster	12	0.01	Negative
1	3	Storage	Book Closet next to Girl's Restroom	yes	W4	Plaster	Beige	Crack in plaster	8	0.02	Negative
1	3	Storage	Book Closet next to Girl's Restroom	yes	Ceiling	Plaster	Beige	Flaking, Crack in plaster	8	0.02	Negative
1	3	Storage	Book Closet next to Girl's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	Service Closets	Custodial Closet in hallway outside Classroom 307	no	W1	Plaster	Beige	None	0	N/A	N/A
1	3	Service Closets	Custodial Closet in hallway outside Classroom 307	no	W2	Plaster	Beige	Cracking	30	17.5	Positive
1	3	Service Closets	Custodial Closet in hallway outside Classroom 307	no	W3	Plaster	Beige	Cracking	30	15.2	Positive
1	3	Service Closets	Custodial Closet in hallway outside Classroom 307	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Service Closets	Custodial Closet in hallway outside Classroom 307	no	W4	Plaster	Beige	Cracking	30	22.6	Positive
1	3	Service Closets	Custodial Closet in hallway outside Classroom 307	no	Ceiling	Plaster	Beige	Flaking	16	16.5	Positive
1	3	Service Closets	Custodial Closet in hallway outside Classroom 307	no	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	Primary	Classroom 307	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	Primary	Classroom 307	yes	W2	Sheetrock	Beige	Scraped	10	0	Negative
1	3	Primary	Classroom 307	yes	W3	Plaster	Beige	Efflorescence, Flaking, Cracking, Spalling	55	16.1	Positive
1	3	Primary	Classroom 307	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 307	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 307	yes	W4	Plaster	Beige	Cracking	2	14.9	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	Primary	Classroom 307	yes	Ceiling	Plaster	Beige	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 307	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 307 Storage	yes	W1	Plaster	Beige	Damaged plaster	2	0.9	Positive
1	3	Storage	Classroom 307 Storage	yes	W2	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
1	3	Storage	Classroom 307 Storage	yes	W3	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
1	3	Storage	Classroom 307 Storage	yes	W4	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
1	3	Storage	Classroom 307 Storage	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 307 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 307 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	Storage	Classroom 307 Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
1	3	Storage	Classroom 307 Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
1	3	Storage	Classroom 307 Closet	yes	W4	Plaster	Beige	Partially Inaccessible	0	N/A	N/A
1	3	Storage	Classroom 307 Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	Storage	Classroom 307 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 308	yes	W1	Plaster	Beige	Cracking, Damaged plaster	10	17.7	Positive
1	3	Primary	Classroom 308	yes	W2	Plaster	Beige	Chipping	15	17.5	Positive
1	3	Primary	Classroom 308	yes	W3	Plaster	Beige	Efflorescence, Flaking	40	16.8	Positive
1	3	Primary	Classroom 308	yes	W4	Plaster	Beige	Cracking	2	14.8	Positive
1	3	Primary	Classroom 308	yes	W4	Sheetrock	Beige	Scraped	10	0	Negative
1	3	Primary	Classroom 308	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 308	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 308 Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 308 Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 308 Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	Storage	Classroom 308 Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 308 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 308 Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 308 Closet	yes	W1	Plaster	Beige	Partially Inaccessible	0	6.3	Positive
1	3	Storage	Classroom 308 Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	8.3	Positive
1	3	Storage	Classroom 308 Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	10.1	Positive
1	3	Storage	Classroom 308 Closet	yes	W4	Plaster	Beige	Partially Inaccessible	0	6.7	Positive
1	3	Storage	Classroom 308 Closet	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	3	Storage	Classroom 308 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 309	yes	W1	Plaster	White	Chipping	5	14.3	Positive
1	3	Primary	Classroom 309	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	Primary	Classroom 309	yes	W3	Plaster	White	Efflorescence, Flaking	50	18.5	Positive
1	3	Primary	Classroom 309	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 309	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	Primary	Classroom 309	yes	Ceiling	Plaster	White	Efflorescence, Damaged plaster	24	21.6	Positive
1	3	Primary	Classroom 309	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 309 Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 309 Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 309 Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 309 Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 309 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 309 Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 309 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 309 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 309 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 309 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	Storage	Classroom 309 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 309 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Teacher Lounge/Dining	Teacher Lounge	yes	W1	Plaster	Purple	none	0	N/A	N/A
1	3	Teacher Lounge/Dining	Teacher Lounge	yes	W2	Plaster	Purple	Crack in plaster	3	26.7	Positive
1	3	Teacher Lounge/Dining	Teacher Lounge	yes	W3	Plaster	Purple	Efflorescence, Spalling	8	22.2	Positive
1	3	Teacher Lounge/Dining	Teacher Lounge	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Teacher Lounge/Dining	Teacher Lounge	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Teacher Lounge/Dining	Teacher Lounge	yes	W4	Plaster	Purple	Flaking	3	18.8	Positive
1	3	Teacher Lounge/Dining	Teacher Lounge	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	Teacher Lounge/Dining	Teacher Lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Restrooms, Staff - Male/Female	Restroom in Teacher Lounge	yes	W1	Plaster	Beige	Efflorescence	3	28.1	Positive
1	3	Restrooms, Staff - Male/Female	Restroom in Teacher Lounge	yes	W2	Plaster	Beige	Cracking	2	26.3	Positive
1	3	Restrooms, Staff - Male/Female	Restroom in Teacher Lounge	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	Restrooms, Staff - Male/Female	Restroom in Teacher Lounge	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	Restrooms, Staff - Male/Female	Restroom in Teacher Lounge	yes	Ceiling	Plaster	Beige	Flaking	4	30.7	Positive
1	3	Restrooms, Staff - Male/Female	Restroom in Teacher Lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 310	yes	W1	Plaster	Beige	Chipping	4	19.1	Positive
1	3	Primary	Classroom 310	yes	W2	Plaster	Beige	Chipping, Damaged plaster	5	18.3	Positive



School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	Primary	Classroom 310	yes	W3	Plaster	Beige	Efflorescence, Cracking paint	25	1.4	Positive
1	3	Primary	Classroom 310	yes	W4	Plaster	Beige	Chipping	3	21.2	Positive
1	3	Primary	Classroom 310	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 310	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 310 Storage	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	Storage	Classroom 310 Storage	yes	W2	Plaster	Beige	Crack in plaster	3	21.2	Positive
1	3	Storage	Classroom 310 Storage	yes	W3	Plaster	Beige	Flaking, Cracking	10	17.7	Positive
1	3	Storage	Classroom 310 Storage	yes	W4	Plaster	Beige	Efflorescence, Flaking	30	1.5	Positive
1	3	Storage	Classroom 310 Storage	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 310 Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	Storage	Classroom 310 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 310 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 310 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 310 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 310 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Storage	Classroom 310 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Circulation (Hallway)	Hallway at Classrooms 307, 308 and 310	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	3	Circulation (Hallway)	Hallway at Classrooms 307, 308 and 310	yes	W2	Plaster	Yellow	Flaking, Cracking, Spalling	5	27.9	Positive
1	3	Circulation (Hallway)	Hallway at Classrooms 307, 308 and 310	yes	W3	Plaster	Yellow	Spalling, Damaged plaster	25	0.7	Positive
1	3	Circulation (Hallway)	Hallway at Classrooms 307, 308 and 310	yes	W4	Plaster	Yellow	Flaking, Cracking	5	13.6	Positive
1	3	Circulation (Hallway)	Hallway at Classrooms 307, 308 and 310	yes	Ceiling	Plaster	White	Flaking, Damaged plaster	30	16.5	Positive
1	3	Circulation (Hallway)	Hallway at Classrooms 307, 308 and 310	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	Circulation (Hallway)	Hallway at Classrooms 303 to 306	yes	W1	Plaster	Yellow	Flaking	2	25.2	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	3	Circulation (Hallway)	Hallway at Classrooms 303 to 306	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	3	Circulation (Hallway)	Hallway at Classrooms 303 to 306	yes	W3	Plaster	Yellow	Chipping	4	3.3	Positive
1	3	Circulation (Hallway)	Hallway at Classrooms 303 to 306	yes	W4	Plaster	Yellow	Chipping	5	16.9	Positive
1	3	Circulation (Hallway)	Hallway at Classrooms 303 to 306	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	Circulation (Hallway)	Hallway at Classrooms 303 to 306	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	Circulation (Hallway)	Hallway at Classrooms 301 and 302	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	3	Circulation (Hallway)	Hallway at Classrooms 301 and 302	yes	W2	Plaster	Yellow	Chipping	1	24.8	Positive
1	3	Circulation (Hallway)	Hallway at Classrooms 301 and 302	yes	W3	Plaster	Yellow	Efflorescence, Cracking	6	0.01	Negative
1	3	Circulation (Hallway)	Hallway at Classrooms 301 and 302	yes	W4	Plaster	Yellow	Efflorescence, Cracking	5	0.01	Negative
1	3	Circulation (Hallway)	Hallway at Classrooms 301 and 302	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Circulation (Hallway)	Hallway at Classrooms 301 and 302	yes	Ceiling	Plaster	White	Efflorescence, Flaking, Damage	12	17.1	Positive
1	3	Circulation (Hallway)	Hallway at Classrooms 301 and 302	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	Stairs	Stairwell across from Room 304	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	Stairs	Stairwell across from Room 304	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairs	Stairwell across from Room 304	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairs	Stairwell across from Room 304	yes	W2	Plaster	Beige	Efflorescence, Flaking	6	19	Positive
1	3	Stairs	Stairwell across from Room 304	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	Stairs	Stairwell across from Room 304	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	Stairs	Stairwell across from Room 304	yes	Ceiling	Plaster	White	Efflorescence, Cracking, Damaged Plaster	8	21.2	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	3	Stairs	Stairwell across from Room 304	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	Stairs	Stairwell across from Room 307	yes	W1	Plaster	Beige	Cracking	2	21.6	Positive
1	3	Stairs	Stairwell across from Room 307	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairs	Stairwell across from Room 307	yes	W2	Plaster	Beige	Cracking	10	21.7	Positive
1	3	Stairs	Stairwell across from Room 307	yes	W3	Plaster	Beige	Flaking, Cracking	30	25.5	Positive
1	3	Stairs	Stairwell across from Room 307	yes	W4	Plaster	Beige	Cracking	5	23.1	Positive
1	3	Stairs	Stairwell across from Room 307	yes	Ceiling	Plaster	White	Flaking, Cracking	5	29.1	Positive
1	3	Stairs	Stairwell across from Room 307	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	Stairs	Stairwell across from Room 307	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairs	Stairwell at the end of the Hallway by Room 310	yes	W1	Plaster	Beige	Efflorescence	10	21.7	Positive
1	3	Stairs	Stairwell at the end of the Hallway by Room 310	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	Stairs	Stairwell at the end of the Hallway by Room 310	yes	W3	Plaster	Beige	Spalling	30	1.1	Positive
1	3	Stairs	Stairwell at the end of the Hallway by Room 310	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairs	Stairwell at the end of the Hallway by Room 310	yes	W4	Plaster	Beige	Efflorescence, Spalling, Damaged plaster	15	1.2	Positive
1	3	Stairs	Stairwell at the end of the Hallway by Room 310	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Stairs	Stairwell at the end of the Hallway by Room 310	yes	Ceiling	Plaster	White	Efflorescence	25	2	Positive
1	3	Stairs	Stairwell at the end of the Hallway by Room 310	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	Stairs	Stairwell at the end of the Hallway by Room 310	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Administrative Office	Building Engineer's Office	no	W1	Plaster	Beige	Flaking	6	16.7	Positive
1	B	Administrative Office	Building Engineer's Office	no	W2	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	B	Administrative Office	Building Engineer's Office	no	W3	Plaster	Beige	Flaking	10	19.4	Positive
1	B	Administrative Office	Building Engineer's Office	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Administrative Office	Building Engineer's Office	no	W4	Plaster	Beige	Cracking, Flaking, Efflorescence, Damaged Plaster	125	17.7	Positive
1	B	Administrative Office	Building Engineer's Office	no	Ceiling	Plaster	Beige	Cracking, Flaking	16	17.5	Positive
1	B	Administrative Office	Building Engineer's Office	no	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	Storage	Building Engineer's Office Storage on the right side	no	W1	Plaster	Beige	Flaking, Efflorescence	200	13.9	Positive
1	B	Storage	Building Engineer's Office Storage on the right side	no	W2	Plaster	Beige	Flaking, Efflorescence	30	2.5	Positive
1	B	Storage	Building Engineer's Office Storage on the right side	no	W3	Plaster	Beige	Flaking, Efflorescence	10	15.6	Positive
1	B	Storage	Building Engineer's Office Storage on the right side	no	W4	Plaster	Beige	Cracking	40	14.4	Positive
1	B	Storage	Building Engineer's Office Storage on the right side	no	Ceiling	Plaster	Beige	Flaking, Cracking, Damaged Plaster	80	8.9	Positive
1	B	Storage	Building Engineer's Office Storage on the right side	no	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	Storage	Building Engineer's Office Storage A on the left by window	no	W1	Brick	Yellow	Flaking	10	0.17	Negative
1	B	Storage	Building Engineer's Office Storage A on the left by window	no	W2	Brick	Yellow	Flaking	15	0.13	Negative
1	B	Storage	Building Engineer's Office Storage A on the left by window	no	W3	Brick	Yellow	Flaking	20	0.3	Negative
1	B	Storage	Building Engineer's Office Storage A on the left by window	no	W4	Brick	Yellow	Flaking	15	0.4	Negative
1	B	Storage	Building Engineer's Office Storage A on the left by window	no	Ceiling	Concrete	Beige	Flaking	20	0.37	Negative

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	Storage	Building Engineer's Office Storage A on the left by window	no	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	Storage	Building Engineer's Office Storage B in the front	no	W1	Brick	Yellow	None	0	N/A	N/A
1	B	Storage	Building Engineer's Office Storage B in the front	no	W2	Brick	Yellow	None	0	N/A	N/A
1	B	Storage	Building Engineer's Office Storage B in the front	no	W3	Brick	Yellow	None	0	N/A	N/A
1	B	Storage	Building Engineer's Office Storage B in the front	no	W4	Brick	Yellow	None	0	N/A	N/A
1	B	Storage	Building Engineer's Office Storage B in the front	no	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	Storage	Building Engineer's Office Storage B in the front	no	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	Cafeteria (Dining Area)	Lunch Room next to Boy's Restroom	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	B	Cafeteria (Dining Area)	Lunch Room next to Boy's Restroom	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	B	Cafeteria (Dining Area)	Lunch Room next to Boy's Restroom	yes	W3	Plaster	Yellow	Spalling	15	0.02	Negative
1	B	Cafeteria (Dining Area)	Lunch Room next to Boy's Restroom	yes	W4	Plaster	Yellow	Flaking	10	22.1	Positive
1	B	Cafeteria (Dining Area)	Lunch Room next to Boy's Restroom	yes	Ceiling	Plaster	Beige	Flaking, Efflorescence	12	0.08	Negative
1	B	Cafeteria (Dining Area)	Lunch Room next to Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Student Restrooms - Male (4-12)	Boy's Restroom next to Building Engineer's Office	yes	W1	Brick	Yellow	Flaking	30	0.29	Negative
1	B	Student Restrooms - Male (4-12)	Boy's Restroom next to Building Engineer's Office	yes	W2	Brick	Yellow	Flaking	25	0.4	Negative

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	Student Restrooms - Male (4-12)	Boy's Restroom next to Building Engineer's Office	yes	W3	Brick	Yellow	Flaking	25	0.16	Negative
1	B	Student Restrooms - Male (4-12)	Boy's Restroom next to Building Engineer's Office	yes	W4	Brick	Yellow	None	0	N/A	N/A
1	B	Student Restrooms - Male (4-12)	Boy's Restroom next to Building Engineer's Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	Student Restrooms - Male (4-12)	Boy's Restroom next to Building Engineer's Office	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	Mechanical Room	Pump Room next to Boiler Room	no	W1	Concrete	White	Cracking	15	0.05	Negative
1	B	Mechanical Room	Pump Room next to Boiler Room	no	W1	Concrete	Beige	Cracking	20	1.2	Positive
1	B	Mechanical Room	Pump Room next to Boiler Room	no	W2	Concrete	White/Beige	Cracking	12	0.07	Negative
1	B	Mechanical Room	Pump Room next to Boiler Room	no	W2	Concrete	Beige	Cracking	10	0.12	Negative
1	B	Mechanical Room	Pump Room next to Boiler Room	no	W3	Brick	White	Cracking	15	0.09	Negative
1	B	Mechanical Room	Pump Room next to Boiler Room	no	W3	Concrete	Beige	Cracking	8	0.06	Negative
1	B	Mechanical Room	Pump Room next to Boiler Room	no	W4	Concrete	White	Cracking	10	0.02	Negative
1	B	Mechanical Room	Pump Room next to Boiler Room	no	W4	Concrete	Beige	Cracking	6	0.05	Negative
1	B	Mechanical Room	Pump Room next to Boiler Room	no	Ceiling	Concrete	White	Flaking	10	0.22	Negative
1	B	Mechanical Room	Pump Room next to Boiler Room	no	Ceiling	Concrete	White	Flaking	10	No Test	Positive
1	B	Mechanical Room	Pump Room next to Boiler Room	no	Floor	Concrete	Grey	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	Mechanical Room	Boiler Room	no	W1	Brick	White/Beige	Cracking	30	2.6	Positive
1	B	Mechanical Room	Boiler Room	no	W1	Concrete	Beige	Cracking	30	12.1	Positive
1	B	Mechanical Room	Boiler Room	no	W2	Brick	White/Beige	Cracking	20	2.9	Positive
1	B	Mechanical Room	Boiler Room	no	W2	Concrete	White/Beige	Cracking	25	0.18	Negative
1	B	Mechanical Room	Boiler Room	no	W3	Brick	White	Cracking	25	0.23	Negative
1	B	Mechanical Room	Boiler Room	no	W3	Concrete	Beige	Cracking	15	0.17	Negative
1	B	Mechanical Room	Boiler Room	no	W4	Concrete	White	Cracking	25	0.35	Negative
1	B	Mechanical Room	Boiler Room	no	W4	Concrete	Beige	Cracking	20	0.11	Negative
1	B	Mechanical Room	Boiler Room	no	Ceiling	Concrete	White	Flaking	30	No Test	Positive
1	B	Mechanical Room	Boiler Room	no	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	Cafeteria (Dining Area)	Cafeteria	yes	W1	Concrete	Yellow	None	0	N/A	N/A
1	B	Cafeteria (Dining Area)	Cafeteria	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Cafeteria (Dining Area)	Cafeteria	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Cafeteria (Dining Area)	Cafeteria	yes	W2	Concrete	Yellow	None	0	N/A	N/A
1	B	Cafeteria (Dining Area)	Cafeteria	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
1	B	Cafeteria (Dining Area)	Cafeteria	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Cafeteria (Dining Area)	Cafeteria	yes	W4	Concrete	Yellow	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	Cafeteria (Dining Area)	Cafeteria	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	Cafeteria (Dining Area)	Cafeteria	yes	Floor	Concrete	Grey	Cracking, Friction	20	0.06	Negative
1	B	Cafeteria (Dining Area)	Cafeteria	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Mechanical Room	Fan Room next to Boiler Room	no	W1	Brick	White	Cracking, Flaking	50	2.7	Positive
1	B	Mechanical Room	Fan Room next to Boiler Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Mechanical Room	Fan Room next to Boiler Room	no	W2	Concrete	White/Beige	Flaking	20	2.2	Positive
1	B	Mechanical Room	Fan Room next to Boiler Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Mechanical Room	Fan Room next to Boiler Room	no	W3	Brick/Concrete	White/Beige	Cracking	10	2.1	Positive
1	B	Mechanical Room	Fan Room next to Boiler Room	no	W4	Brick/Concrete	White/Beige	Cracking, Flaking	50	5.5	Positive
1	B	Mechanical Room	Fan Room next to Boiler Room	no	Ceiling	Concrete	White	Flaking	120	0.14	Negative
1	B	Mechanical Room	Fan Room next to Boiler Room	no	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	Cafeteria (Dining Area)	Small Lunch Room next to Girl's Restroom	yes	W1	Brick	Multi Colored	None	0	N/A	N/A
1	B	Cafeteria (Dining Area)	Small Lunch Room next to Girl's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Cafeteria (Dining Area)	Small Lunch Room next to Girl's Restroom	yes	W2	Brick	Multi Colored	None	0	N/A	N/A
1	B	Cafeteria (Dining Area)	Small Lunch Room next to Girl's Restroom	yes	W3	Brick	Multi Colored	None	0	N/A	N/A
1	B	Cafeteria (Dining Area)	Small Lunch Room next to Girl's Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Cafeteria (Dining Area)	Small Lunch Room next to Girl's Restroom	y	W4	Brick	Multi Colored	None	0	N/A	N/A



School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	B	Cafeteria (Dining Area)	Small Lunch Room next to Girl's Restroom	yes	Ceiling	Plaster	White	Flaking	8	10.7	Positive
1	B	Cafeteria (Dining Area)	Small Lunch Room next to Girl's Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W1	Brick	White	Cracking	8	0.3	Negative
1	B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W2	Brick	White	Cracking	20	0.5	Negative
1	B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W3	Brick	White	Cracking	6	0.2	Negative
1	B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W4	Brick	White	Cracking	15	0.4	Negative
1	B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	Concrete	White	Cracking	20	0.17	Negative
1	B	Student Restrooms - Female (4-12)	Girl's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	Storage	Closet in Stairwell by Girl's Restroom	no	W1	Brick	Tan	Flaking	20	9.6	Positive
1	B	Storage	Closet in Stairwell by Girl's Restroom	no	W2	Brick	Tan	Flaking	35	7.3	Positive
1	B	Storage	Closet in Stairwell by Girl's Restroom	no	W3	Brick	Tan	Flaking	20	2.8	Positive
1	B	Storage	Closet in Stairwell by Girl's Restroom	no	W4	Brick	Tan	Flaking	10	5.5	Positive
1	B	Storage	Closet in Stairwell by Girl's Restroom	no	Ceiling	Concrete	Tan	Flaking	20	8.2	Positive
1	B	Storage	Closet in Stairwell by Girl's Restroom	no	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	Storage	Gym Storage	yes	W1	Brick	White	Partially Inaccessible	0	3.4	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	Storage	Gym Storage	yes	W2	Brick	White	Partially Inaccessible	10	6.8	Positive
1	B	Storage	Gym Storage	yes	W3	Brick	White	Flaking	2	7.5	Positive
1	B	Storage	Gym Storage	yes	W4	Brick	White	Flaking	6	6.5	Positive
1	B	Storage	Gym Storage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	Storage	Gym Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	Administrative Office	Gym Office	yes	W1	Brick	White	Chipping	1	6.1	Positive
1	B	Administrative Office	Gym Office	yes	W2	Brick	White	None	0	N/A	N/A
1	B	Administrative Office	Gym Office	yes	W3	Brick	White	None	0	N/A	N/A
1	B	Administrative Office	Gym Office	yes	W4	Brick	White	Flaking	3	6.1	Positive
1	B	Administrative Office	Gym Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	Administrative Office	Gym Office	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	yes	W1	Brick	Beige	None	0	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	Gymnasium - Intermediate Middle	Gym	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	yes	W2	Brick	Beige	None	0	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	YEs	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	yes	W3	Brick	Beige	None	0	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	Gymnasium - Intermediate Middle	Gym	yes	W4	Brick	Beige	None	0	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	yes	Ceiling	Plaster	White	Flaking, Efflorescence, Cracking	115	14.6	Positive
1	B	Gymnasium - Intermediate Middle	Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Gymnasium - Intermediate Middle	Gym	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Storage	Music Room Storage	yes	W1	Brick	Yellow	Chipping	1	2.8	Positive
1	B	Storage	Music Room Storage	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Storage	Music Room Storage	yes	W2	Brick	Yellow	Cracking	2	2.6	Positive
1	B	Storage	Music Room Storage	yes	W3	Brick	Yellow	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	Storage	Music Room Storage	yes	W4	Brick	Yellow	None	0	N/A	N/A
1	B	Storage	Music Room Storage	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	Storage	Music Room Storage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	Laundry Room	Laundry Room in Music Room	yes	W1	Brick	White	Wood	0	N/A	N/A
1	B	Laundry Room	Laundry Room in Music Room	yes	W2	Brick	White	Cracking	20	6.8	Positive
1	B	Laundry Room	Laundry Room in Music Room	yes	W3	Brick/Concrete	White	Cracking	60	6.5	Positive
1	B	Laundry Room	Laundry Room in Music Room	yes	W4	Brick/Concrete	White	Cracking	20	7.2	Positive
1	B	Laundry Room	Laundry Room in Music Room	yes	Ceiling	Concrete	White	Flaking	10	2.1	Positive
1	B	Laundry Room	Laundry Room in Music Room	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	Circulation (Hallway)	Hallway on Boy's Restroom side	yes	W1	Brick	White/Yellow	None	0	N/A	N/A
1	B	Circulation (Hallway)	Hallway on Boy's Restroom side	yes	W2	Brick	Yellow	Efflorescence	30	0.27	Negative
1	B	Circulation (Hallway)	Hallway on Boy's Restroom side	yes	W3	Brick	White	Cracking	4	6.6	Positive
1	B	Circulation (Hallway)	Hallway on Boy's Restroom side	yes	W4	Brick	White	Flaking	30	11	Positive
1	B	Circulation (Hallway)	Hallway on Boy's Restroom side	yes	Ceiling	Plaster	White	Flaking, Cracking, Damaged Plaster	200	11.5	Positive
1	B	Circulation (Hallway)	Hallway on Boy's Restroom side	yes	Ceiling	Concrete	White	Flaking	40	0.3	Negative
1	B	Circulation (Hallway)	Hallway on Boy's Restroom side	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Circulation (Hallway)	Hallway on Boy's Restroom side	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	Storage	Hallway Storage near Boy's Restroom	no	W1	Brick	White	Cracking	10	6	Positive
1	B	Storage	Hallway Storage near Boy's Restroom	no	W2	Brick	White	Cracking	10	18	Positive
1	B	Storage	Hallway Storage near Boy's Restroom	no	W3	Brick	White	Cracking	12	17.4	Positive
1	B	Storage	Hallway Storage near Boy's Restroom	no	W4	Brick	White	Cracking	8	16.1	Positive
1	B	Storage	Hallway Storage near Boy's Restroom	no	Ceiling	Concrete	White	Flaking	2	14.5	Positive
1	B	Storage	Hallway Storage near Boy's Restroom	no	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	Mechanical Room	Mechanical Closet in Hallway by Boy's Restroom	no	W1	Brick	White	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	Mechanical Room	Mechanical Closet in Hallway by Boy's Restroom	no	W2	Brick	White	None	0	N/A	N/A
1	B	Mechanical Room	Mechanical Closet in Hallway by Boy's Restroom	no	W3	Brick	White	None	0	N/A	N/A
1	B	Mechanical Room	Mechanical Closet in Hallway by Boy's Restroom	no	W4	Brick	White	None	0	N/A	N/A
1	B	Mechanical Room	Mechanical Closet in Hallway by Boy's Restroom	no	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	Mechanical Room	Mechanical Closet in Hallway by Boy's Restroom	no	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	Circulation (Hallway)	Hallway on Girl's Restroom side	yes	W1	Brick	White	Cracking	10	9.7	Positive
1	B	Circulation (Hallway)	Hallway on Girl's Restroom side	yes	W2	Brick	White	Cracking	25	11.7	Positive
1	B	Circulation (Hallway)	Hallway on Girl's Restroom side	yes	W3	Brick	White	Cracking	6	15.1	Positive
1	B	Circulation (Hallway)	Hallway on Girl's Restroom side	yes	W4	Brick	White	Cracking	20	11.1	Positive
1	B	Circulation (Hallway)	Hallway on Girl's Restroom side	yes	Ceiling	Concrete	White	Flaking, Damaged Plaster	40	7.1	Positive
1	B	Circulation (Hallway)	Hallway on Girl's Restroom side	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	Circulation (Hallway)	Hallway at Cafeteria	yes	W1	Concrete	White/Yellow	None	0	N/A	N/A
1	B	Circulation (Hallway)	Hallway at Cafeteria	yes	W2	Brick	White	None	0	N/A	N/A
1	B	Circulation (Hallway)	Hallway at Cafeteria	yes	W3	Brick	Yellow	Cracking	2	5.1	Positive
1	B	Circulation (Hallway)	Hallway at Cafeteria	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Circulation (Hallway)	Hallway at Cafeteria	yes	W4	Cinderblock	White	None	0	N/A	N/A
1	B	Circulation (Hallway)	Hallway at Cafeteria	yes	Ceiling	Concrete	White	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	Circulation (Hallway)	Hallway at Cafeteria	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	Circulation (Hallway)	Hallway at Gym	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
1	B	Circulation (Hallway)	Hallway at Gym	yes	W2	Plaster	Beige	Cracking	5	24.4	Positive
1	B	Circulation (Hallway)	Hallway at Gym	yes	W3	Plaster	Beige	Cracking	20	24.1	Positive
1	B	Circulation (Hallway)	Hallway at Gym	yes	W4	Plaster	Beige	Cracking, Efflorescence	10	23.6	Positive
1	B	Circulation (Hallway)	Hallway at Gym	yes	Ceiling	Concrete	Beige	None	0	N/A	N/A
1	B	Circulation (Hallway)	Hallway at Gym	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	Stairs	Stairwell on the right side of Gym	yes	W1	Plaster	Beige	Cracking	4	1.6	Positive
1	B	Stairs	Stairwell on the right side of Gym	yes	W2	Plaster	Beige	Cracking	8	18.5	Positive
1	B	Stairs	Stairwell on the right side of Gym	yes	W3	Plaster	Beige	Cracking	1	1	Positive
1	B	Stairs	Stairwell on the right side of Gym	yes	W4	Plaster	Beige	Cracking	20	23.7	Positive
1	B	Stairs	Stairwell on the right side of Gym	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairs	Stairwell on the right side of Gym	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairs	Stairwell on the right side of Gym	yes	Ceiling	Concrete	White	Cracking, Efflorescence	8	18.2	Positive
1	B	Stairs	Stairwell on the right side of Gym	yes	Ceiling	Plaster	White	Efflorescence	4	0.05	Negative
1	B	Stairs	Stairwell on the right side of Gym	yes	Floor	Concrete	Grey	Cracking	4	0.14	Negative
1	B	Stairs	Stairwell on the right side of Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairs	Stairwell on the right side of Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairs	Stairwell on the right side of Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairs	Stairwell on the left side of Gym	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	B	Stairs	Stairwell on the left side of Gym	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	B	Stairs	Stairwell on the left side of Gym	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	B	Stairs	Stairwell on the left side of Gym	yes	W4	Plaster	Beige	Cracking	5	20.7	Positive
1	B	Stairs	Stairwell on the left side of Gym	yes	Ceiling	Concrete	White	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
1	B	Stairs	Stairwell on the left side of Gym	yes	Floor	Concrete	Grey	None	0	N/A	N/A
2	B	Stairs	Stairwell on the left side of Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairs	Stairwell by Lunch Room 002	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	B	Stairs	Stairwell by Lunch Room 002	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	B	Stairs	Stairwell by Lunch Room 002	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	B	Stairs	Stairwell by Lunch Room 002	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	B	Stairs	Stairwell by Lunch Room 002	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	Stairs	Stairwell by Lunch Room 002	yes	Floor	Concrete	Grey	None	0	N/A	N/A
2	1	Primary	Classroom 110	yes	W1	Cinderblock	Beige	Chipping	2	0.17	Negative
2	1	Primary	Classroom 110	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 110	yes	W2	Cinderblock	Beige	Chipping	2	0.13	Negative
2	1	Primary	Classroom 110	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	1	Primary	Classroom 110	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 110	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 110	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 110	yes	W4	Cinderblock	Beige	Flaking	10	0.07	Negative
2	1	Primary	Classroom 110	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 110	yes	Ceiling	Concrete	White	Flaking	5	0.07	Negative
2	1	Primary	Classroom 110	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Storage	Classroom 110 Closet 1	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Storage	Classroom 110 Closet 1	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Storage	Classroom 110 Closet 1	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Storage	Classroom 110 Closet 1	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Storage	Classroom 110 Closet 1	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Storage	Classroom 110 Closet 1	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Storage	Classroom 110 Closet 2	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Storage	Classroom 110 Closet 2	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Storage	Classroom 110 Closet 2	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Storage	Classroom 110 Closet 2	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Storage	Classroom 110 Closet 2	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Storage	Classroom 110 Closet 2	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access



School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
2	1	Primary	Classroom 111	yes	W1	Cinderblock	Beige	Chipping	3	0.07	Negative
2	1	Primary	Classroom 111	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 111	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	1	Primary	Classroom 111	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 111	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 111	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	1	Primary	Classroom 111	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 111	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	1	Primary	Classroom 111	yes	Ceiling	Concrete	White	Flaking	4	0.06	Negative
2	1	Primary	Classroom 111	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Storage	Classroom 111 Closet 1	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 111 Closet 1	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 111 Closet 1	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 111 Closet 1	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 111 Closet 1	yes	Ceiling	Wood	White	None	0	N/A	N/A
2	1	Storage	Classroom 111 Closet 1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Storage	Classroom 111 Closet 2	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 111 Closet 2	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 111 Closet 2	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 111 Closet 2	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 111 Closet 2	yes	Ceiling	Wood	White	None	0	N/A	N/A
2	1	Storage	Classroom 111 Closet 2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 112	yes	W1	Cinderblock	Beige	Chipping	2	0.07	Negative
2	1	Primary	Classroom 112	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 112	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 112	yes	W2	Cinderblock	Beige	Flaking	12	0.05	Negative
2	1	Primary	Classroom 112	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	1	Primary	Classroom 112	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 112	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 112	yes	W4	Cinderblock	Beige	Flaking	4	0.09	Negative
2	1	Primary	Classroom 112	yes	Ceiling	Concrete	White	Chipping	4	0.03	Negative

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
2	1	Primary	Classroom 112	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Storage	Classroom 112 Closet 1	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 112 Closet 1	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 112 Closet 1	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 112 Closet 1	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 112 Closet 1	yes	Ceiling	Wood	White	None	0	N/A	N/A
2	1	Storage	Classroom 112 Closet 1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Storage	Classroom 112 Closet 2	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 112 Closet 2	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 112 Closet 2	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 112 Closet 2	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Storage	Classroom 112 Closet 2	yes	Ceiling	Wood	White	None	0	N/A	N/A
2	1	Storage	Classroom 112 Closet 2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Mechanical Room	Fan Room/Supply Room	no	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Mechanical Room	Fan Room/Supply Room	no	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Mechanical Room	Fan Room/Supply Room	no	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Mechanical Room	Fan Room/Supply Room	no	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Mechanical Room	Fan Room/Supply Room	no	Ceiling	Concrete	White	None	0	N/A	N/A
2	1	Mechanical Room	Fan Room/Supply Room	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 113	yes	W1	Plaster	Beige	None	0	N/A	N/A
2	1	Primary	Classroom 113	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 113	yes	W2	Plaster	Beige	None	0	N/A	N/A
2	1	Primary	Classroom 113	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 113	yes	W3	Plaster	Beige	None	0	N/A	N/A
2	1	Primary	Classroom 113	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 113	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
2	1	Primary	Classroom 113	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Primary	Classroom 113	yes	W4	Plaster	Beige	None	0	N/A	N/A
2	1	Primary	Classroom 113	yes	Ceiling	Concrete	White	Chipping	1	0.01	Negative
2	1	Primary	Classroom 113	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W1	Glazed Block	Tan	Friction	6	1.7	Positive
2	1	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W2	Glazed Block	Tan	Friction	5	2.6	Positive
2	1	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W3	Glazed Block	Tan	Friction	5	3	Positive
2	1	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W4	Glazed Block	Tan	Friction	3	3.2	Positive
2	1	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	Concrete	White	Flaking	15	0.28	Negative
2	1	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A
2	1	Circulation (Hallway)	Main Hallway	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Circulation (Hallway)	Main Hallway	yes	W2	Cinderblock	Yellow	Chipping	2	0.03	Negative
2	1	Circulation (Hallway)	Main Hallway	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Circulation (Hallway)	Main Hallway	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
2	1	Circulation (Hallway)	Main Hallway	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Circulation (Hallway)	Main Hallway	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Circulation (Hallway)	Main Hallway	yes	Ceiling	Conrete	White	Flaking	3	0.24	Negative
2	1	Circulation (Hallway)	Main Hallway	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Circulation (Hallway)	Hallway at Girl's Restroom	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Circulation (Hallway)	Hallway at Girl's Restroom	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Circulation (Hallway)	Hallway at Girl's Restroom	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Circulation (Hallway)	Hallway at Girl's Restroom	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Circulation (Hallway)	Hallway at Girl's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	1	Circulation (Hallway)	Hallway at Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Service Closets	Custodial Storage next to Girl's Restroom	no	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Service Closets	Custodial Storage next to Girl's Restroom	no	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Service Closets	Custodial Storage next to Girl's Restroom	no	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Service Closets	Custodial Storage next to Girl's Restroom	no	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	1	Service Closets	Custodial Storage next to Girl's Restroom	no	Ceiling	Concrete	White	Flaking	10	0.06	Negative
2	1	Service Closets	Custodial Storage next to Girl's Restroom	no	Floor	Concrete	Grey	None	0	N/A	N/A
2	1	Stairs	Stairwell by Rooms 111 & 112	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	1	Stairs	Stairwell by Rooms 111 & 112	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairs	Stairwell by Rooms 111 & 112	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	1	Stairs	Stairwell by Rooms 111 & 112	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	1	Stairs	Stairwell by Rooms 111 & 112	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	1	Stairs	Stairwell by Rooms 111 & 112	yes	Ceiling	Concrete	White	Flaking	4	0.1	Negative
2	1	Stairs	Stairwell by Rooms 111 & 112	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
2	1	Stairs	Stairwell by Rooms 111 & 112	yes	Floor	Concrete	Grey	None	0	N/A	N/A
2	1	Stairs	Stairwell by Room 113	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	1	Stairs	Stairwell by Room 113	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	1	Stairs	Stairwell by Room 113	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairs	Stairwell by Room 113	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	1	Stairs	Stairwell by Room 113	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stairs	Stairwell by Room 113	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	1	Stairs	Stairwell by Room 113	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	1	Stairs	Stairwell by Room 113	yes	Floor	Concrete	Grey	Chipping	4	0.04	Negative
2	1	Stairs	Stairwell by Room 113	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Primary	Classroom 213	yes	W1	Cinderblock	Beige	Chipping	2	0.14	Negative
2	2	Primary	Classroom 213	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Primary	Classroom 213	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	2	Primary	Classroom 213	yes	W3	Cinderblock	Beige	Chipping	2	0.09	Negative
2	2	Primary	Classroom 213	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	2	Primary	Classroom 213	yes	Ceiling	Concrete	White	Flaking	2	0.04	Negative
2	2	Primary	Classroom 213	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Teacher Lounge/Dining	Teacher Lounge	yes	W1	Cinderblock	Beige	Cracking	2	0.14	Negative
2	2	Teacher Lounge/Dining	Teacher Lounge	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Teacher Lounge/Dining	Teacher Lounge	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	2	Teacher Lounge/Dining	Teacher Lounge	yes	W3	Cinderblock	Beige	Cracking	2	0.09	Negative
2	2	Teacher Lounge/Dining	Teacher Lounge	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	2	Teacher Lounge/Dining	Teacher Lounge	yes	Ceiling	Concrete	White	Flaking	2	0.04	Negative
2	2	Teacher Lounge/Dining	Teacher Lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
2	2	Restrooms, Staff - Male/Female	Teacher Lounge Restroom	yes	W1	Glazed Block	N/A	None	0	N/A	N/A
2	2	Restrooms, Staff - Male/Female	Teacher Lounge Restroom	yes	W2	Glazed Block	N/A	None	0	2.3	Positive
2	2	Restrooms, Staff - Male/Female	Teacher Lounge Restroom	yes	W3	Glazed Block	N/A	None	0	N/A	N/A
2	2	Restrooms, Staff - Male/Female	Teacher Lounge Restroom	yes	W4	Glazed Block	N/A	None	0	N/A	N/A
2	2	Restrooms, Staff - Male/Female	Teacher Lounge Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	2	Restrooms, Staff - Male/Female	Teacher Lounge Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
2	2	Primary	Classroom 210	yes	W1	Cinderblock	Beige	Chipping	2	0.06	Negative
2	2	Primary	Classroom 210	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Primary	Classroom 210	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	2	Primary	Classroom 210	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	3	Primary	Classroom 210	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Primary	Classroom 210	yes	W4	Cinderblock	Beige	Chipping	2	0.08	Negative
2	2	Primary	Classroom 210	yes	Ceiling	Concrete	White	Chipping	4	0.02	Negative
2	2	Primary	Classroom 210	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Storage	Classroom 210 Closet 1	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 210 Closet 1	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 210 Closet 1	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 210 Closet 1	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 210 Closet 1	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 210 Closet 1	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 210 Closet 2	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 210 Closet 2	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 210 Closet 2	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 210 Closet 2	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 210 Closet 2	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 210 Closet 2	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
2	2	Primary	Classroom 211	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	2	Primary	Classroom 211	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Primary	Classroom 211	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	2	Primary	Classroom 211	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Primary	Classroom 211	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Primary	Classroom 211	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	2	Primary	Classroom 211	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	2	Primary	Classroom 211	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	2	Primary	Classroom 211	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Storage	Classroom 211 Closet 1	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 211 Closet 1	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 211 Closet 1	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 211 Closet 1	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 211 Closet 1	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 211 Closet 1	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 211 Closet 2	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 211 Closet 2	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 211 Closet 2	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 211 Closet 2	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 211 Closet 2	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 211 Closet 2	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Primary	Classroom 212	yes	W1	Cinderblock	Beige	Chipping	2	0.16	Negative
2	2	Primary	Classroom 212	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Primary	Classroom 212	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	2	Primary	Classroom 212	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	2	Primary	Classroom 212	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Primary	Classroom 212	yes	W4	Cinderblock	Beige	Chipping	2	0.19	Negative
2	2	Primary	Classroom 212	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Primary	Classroom 212	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	2	Primary	Classroom 212	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Storage	Classroom 212 Closet 1	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
2	2	Storage	Classroom 212 Closet 1	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 212 Closet 1	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 212 Closet 1	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 212 Closet 1	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 212 Closet 1	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 212 Closet 2	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 212 Closet 2	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 212 Closet 2	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 212 Closet 2	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 212 Closet 2	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage	Classroom 212 Closet 2	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Mechanical Room	Fan Room/Supply Room	no	W1	Cinderblock	Beige	None	0	N/A	N/A
2	2	Mechanical Room	Fan Room/Supply Room	no	W2	Cinderblock	Beige	None	0	N/A	N/A
2	2	Mechanical Room	Fan Room/Supply Room	no	W3	Cinderblock	Beige	None	0	N/A	N/A
2	2	Mechanical Room	Fan Room/Supply Room	no	W4	Cinderblock	Beige	None	0	N/A	N/A
2	2	Mechanical Room	Fan Room/Supply Room	no	Ceiling	Concrete	White	Flaking	4	0.06	Negative
2	2	Mechanical Room	Fan Room/Supply Room	no	Floor	Concrete	Grey	None	0	N/A	N/A
2	2	Service Closets	Custodial Storage	no	W1	Cinderblock	Beige	None	0	N/A	N/A
2	2	Service Closets	Custodial Storage	no	W2	Cinderblock	Beige	None	0	N/A	N/A
2	2	Service Closets	Custodial Storage	no	W3	Cinderblock	Beige	None	0	N/A	N/A
2	2	Service Closets	Custodial Storage	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Service Closets	Custodial Storage	no	W4	Cinderblock	Beige	None	0	N/A	N/A
2	2	Service Closets	Custodial Storage	no	Ceiling	Concrete	White	Cracking, Flaking	10	1.1	Positive
2	2	Service Closets	Custodial Storage	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A



School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
2	2	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	Glazed Block	N/A	None	0	N/A	N/A
2	2	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W2	Glazed Block	N/A	None	0	N/A	N/A
2	2	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W3	Glazed Block	N/A	None	0	N/A	N/A
2	2	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W4	Glazed Block	N/A	None	0	N/A	N/A
2	2	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	2	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A
2	2	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W1	Glazed Block	N/A	None	0	N/A	N/A
2	2	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W2	Glazed Block	N/A	None	0	N/A	N/A
2	2	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W3	Glazed Block	N/A	None	0	N/A	N/A
2	2	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W4	Glazed Block	N/A	None	0	N/A	N/A
2	2	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
2	2	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A
2	2	Circulation (Hallway)	Main Hallway	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	2	Circulation (Hallway)	Main Hallway	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	2	Circulation (Hallway)	Main Hallway	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	2	Circulation (Hallway)	Main Hallway	yes	W4	Cinderblock	Yellow	Cracking	2	0.07	Negative
2	2	Circulation (Hallway)	Main Hallway	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Circulation (Hallway)	Main Hallway	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	2	Circulation (Hallway)	Main Hallway	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Circulation (Hallway)	Hallway at Teacher Lounge	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	2	Circulation (Hallway)	Hallway at Teacher Lounge	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	2	Circulation (Hallway)	Hallway at Teacher Lounge	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	2	Circulation (Hallway)	Hallway at Teacher Lounge	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	2	Circulation (Hallway)	Hallway at Teacher Lounge	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	2	Circulation (Hallway)	Hallway at Teacher Lounge	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	2	Stairs	Stairwell by Rooms 211 & 212	yes	W1	Glazed Block	N/A	None	0	N/A	N/A
2	2	Stairs	Stairwell by Rooms 211 & 212	yes	W2	Glazed Block	N/A	None	0	N/A	N/A
2	2	Stairs	Stairwell by Rooms 211 & 212	yes	W3	Glazed Block	N/A	None	0	N/A	N/A
2	2	Stairs	Stairwell by Rooms 211 & 212	yes	W4	Glazed Block	N/A	None	0	N/A	N/A
2	2	Stairs	Stairwell by Rooms 211 & 212	yes	Ceiling	Concrete	White	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
2	2	Stairs	Stairwell by Rooms 211 & 212	yes	Floor	Concrete	Grey	None	0	N/A	N/A
2	3	Primary	Classroom 311	yes	W1	Cinderblock	Blue	None	0	N/A	N/A
2	3	Primary	Classroom 311	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Primary	Classroom 311	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Primary	Classroom 311	yes	W2	Cinderblock	Blue	None	0	N/A	N/A
2	3	Primary	Classroom 311	yes	W3	Cinderblock	Blue	None	0	N/A	N/A
2	3	Primary	Classroom 311	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Primary	Classroom 311	yes	W4	Cinderblock	Blue	None	0	N/A	N/A
2	3	Primary	Classroom 311	yes	Ceiling	Concrete	White	Chipping	5	0.02	Negative
2	3	Primary	Classroom 311	yes	Ceiling	Wood	Grey	Flaking	4	0.04	Negative
2	3	Primary	Classroom 311	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Storage	Classroom 311 Closet 1	yes	W1	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 311 Closet 1	yes	W2	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 311 Closet 1	yes	W3	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 311 Closet 1	yes	W4	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 311 Closet 1	yes	Ceiling	Wood	White	None	0	N/A	N/A
2	3	Storage	Classroom 311 Closet 1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Storage	Classroom 311 Closet 2	yes	W1	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 311 Closet 2	yes	W2	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 311 Closet 2	yes	W3	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 311 Closet 2	yes	W4	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 311 Closet 2	yes	Ceiling	Wood	White	None	0	N/A	N/A
2	3	Storage	Classroom 311 Closet 2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Primary	Classroom 312	yes	W1	Cinderblock	White	None	0	N/A	N/A
2	3	Primary	Classroom 312	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Primary	Classroom 312	yes	W2	Cinderblock	White	None	0	N/A	N/A
2	3	Primary	Classroom 312	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Primary	Classroom 312	yes	W3	Cinderblock	White	None	0	N/A	N/A
2	3	Primary	Classroom 312	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Primary	Classroom 312	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Primary	Classroom 312	yes	W4	Cinderblock	White	Chipping	5	0.06	Negative

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
2	3	Primary	Classroom 312	yes	Ceiling	Concrete	White	Flaking	5	1.4	Positive
2	3	Primary	Classroom 312	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Storage	Classroom 312 Closet 1	yes	W1	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 312 Closet 1	yes	W2	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 312 Closet 1	yes	W3	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 312 Closet 1	yes	W4	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 312 Closet 1	yes	Ceiling	Wood	White	None	0	N/A	N/A
2	3	Storage	Classroom 312 Closet 1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Storage	Classroom 312 Closet 2	yes	W1	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 312 Closet 2	yes	W2	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 312 Closet 2	yes	W3	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 312 Closet 2	yes	W4	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 312 Closet 2	yes	Ceiling	Wood	White	None	0	N/A	N/A
2	3	Storage	Classroom 312 Closet 2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Primary	Classroom 313	yes	W1	Cinderblock	White	Chipping	2	0.04	Negative
2	3	Primary	Classroom 313	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Primary	Classroom 313	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Primary	Classroom 313	yes	W2	Cinderblock	White	None	0	N/A	N/A
2	3	Primary	Classroom 313	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Primary	Classroom 313	yes	W3	Cinderblock	White	None	0	N/A	N/A
2	3	Primary	Classroom 313	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Primary	Classroom 313	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Primary	Classroom 313	yes	W4	Cinderblock	White	None	0	N/A	N/A
2	3	Primary	Classroom 313	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	3	Primary	Classroom 313	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Storage	Classroom 313 Closet 1	yes	W1	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 313 Closet 1	yes	W2	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 313 Closet 1	yes	W3	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 313 Closet 1	yes	W4	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 313 Closet 1	yes	Ceiling	Wood	White	None	0	N/A	N/A
2	3	Storage	Classroom 313 Closet 1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
2	3	Storage	Classroom 313 Closet 2	yes	W1	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 313 Closet 2	yes	W2	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 313 Closet 2	yes	W3	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 313 Closet 2	yes	W4	Cinderblock	White	None	0	N/A	N/A
2	3	Storage	Classroom 313 Closet 2	yes	Ceiling	Wood	White	None	0	N/A	N/A
2	3	Storage	Classroom 313 Closet 2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Mechanical Room	Fan Room/Supply Room	no	W1	Cinderblock	White	None	0	N/A	N/A
2	3	Mechanical Room	Fan Room/Supply Room	no	W2	Cinderblock	White	None	0	N/A	N/A
2	3	Mechanical Room	Fan Room/Supply Room	no	W3	Cinderblock	White	None	0	N/A	N/A
2	3	Mechanical Room	Fan Room/Supply Room	no	W4	Cinderblock	White	None	0	N/A	N/A
2	3	Mechanical Room	Fan Room/Supply Room	no	Ceiling	Concrete	White	Cracking	5	1.5	Positive
2	3	Mechanical Room	Fan Room/Supply Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Mechanical Room	Fan Room/Supply Room	no	Floor	Concrete	Grey	None	0	N/A	N/A
2	3	Service Closets	Custodial Storage next to Room 311C - Fan Room/Supply Room	no	W1	Cinderblock	White	None	0	N/A	N/A
2	3	Service Closets	Custodial Storage next to Room 311C - Fan Room/Supply Room	no	W2	Cinderblock	White	None	0	N/A	N/A
2	3	Service Closets	Custodial Storage next to Room 311C - Fan Room/Supply Room	no	W3	Cinderblock	White	None	0	N/A	N/A
2	3	Service Closets	Custodial Storage next to Room 311C - Fan Room/Supply Room	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Service Closets	Custodial Storage next to Room 311C - Fan Room/Supply Room	no	W4	Cinderblock	White	None	0	N/A	N/A
2	3	Service Closets	Custodial Storage next to Room 311C - Fan Room/Supply Room	no	Ceiling	Concrete	White	Flaking	1	1.5	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
2	3	Service Closets	Custodial Storage next to Room 311C - Fan Room/Supply Room	yes	Floor	Concrete	Grey	None	0	N/A	N/A
2	3	Primary	Classroom 314	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	3	Primary	Classroom 314	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	3	Primary	Classroom 314	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	3	Primary	Classroom 314	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	3	Primary	Classroom 314	yes	Ceiling	Wood	Yellow	None	0	N/A	N/A
2	3	Primary	Classroom 314	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Storage	Classroom 314 Closet	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	3	Storage	Classroom 314 Closet	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	3	Storage	Classroom 314 Closet	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	3	Storage	Classroom 314 Closet	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	3	Storage	Classroom 314 Closet	yes	Ceiling	Wood	Yellow	None	0	N/A	N/A
2	3	Storage	Classroom 314 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	Glazed Block	N/A	None	0	N/A	N/A
2	3	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W2	Glazed Block	N/A	None	0	N/A	N/A
2	3	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W3	Glazed Block	N/A	None	0	N/A	N/A
2	3	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W4	Glazed Block	N/A	None	0	N/A	N/A
2	3	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	3	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
2	3	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W1	Glazed Block	N/A	None	0	N/A	N/A
2	3	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W2	Glazed Block	N/A	None	0	N/A	N/A
2	3	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W3	Glazed Block	N/A	None	0	N/A	N/A
2	3	Student Restrooms - Female (4-12)	Girl's Restroom	yes	W4	Glazed Block	N/A	None	0	N/A	N/A
2	3	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	3	Student Restrooms - Female (4-12)	Girl's Restroom	yes	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A
2	3	Circulation (Hallway)	Main Hallway	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	3	Circulation (Hallway)	Main Hallway	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	3	Circulation (Hallway)	Main Hallway	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	3	Circulation (Hallway)	Main Hallway	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Circulation (Hallway)	Main Hallway	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	3	Circulation (Hallway)	Main Hallway	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Circulation (Hallway)	Main Hallway	yes	Ceiling	Concrete	White	Spalling	4	1.5	Positive
2	3	Circulation (Hallway)	Main Hallway	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
2	3	Circulation (Hallway)	Main Hallway	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairs	Stairwell by Rooms 312 & 313	yes	W1	Glazed Block	N/A	None	0	N/A	N/A
2	3	Stairs	Stairwell by Rooms 312 & 313	yes	W2	Glazed Block	N/A	None	0	N/A	N/A
2	3	Stairs	Stairwell by Rooms 312 & 313	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairs	Stairwell by Rooms 312 & 313	yes	W3	Glazed Block	N/A	None	0	N/A	N/A
2	3	Stairs	Stairwell by Rooms 312 & 313	yes	W4	Glazed Block	N/A	None	0	N/A	N/A
2	3	Stairs	Stairwell by Rooms 312 & 313	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Stairs	Stairwell by Rooms 312 & 313	yes	Ceiling	Concrete	White	Flaking	4	0.08	Negative
2	3	Stairs	Stairwell by Rooms 312 & 313	yes	Floor	Concrete	Grey	None	0	N/A	N/A
2	GD	Primary	Classroom G1	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Primary	Classroom G1	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Primary	Classroom G1	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Primary	Classroom G1	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Primary	Classroom G1	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	GD	Primary	Classroom G1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Storage	Classroom G1 Closet 1	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G1 Closet 1	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G1 Closet 1	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G1 Closet 1	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G1 Closet 1	yes	Ceiling	Wood	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G1 Closet 1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Storage	Classroom G1 Closet 2	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	GD	Storage	Classroom G1 Closet 2	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	GD	Storage	Classroom G1 Closet 2	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	GD	Storage	Classroom G1 Closet 2	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	GD	Storage	Classroom G1 Closet 2	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	GD	Storage	Classroom G1 Closet 2	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G1 Restroom	yes	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A



School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G1 Restroom	yes	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G1 Restroom	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G1 Restroom	yes	W4	Sheetrock	Beige	None	0	N/A	N/A
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G1 Restroom	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G1 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G1 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Primary	Classroom G2	yes	W1	Cinderblock	Beige	Flaking	2	0.04	Negative
2	GD	Primary	Classroom G2	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Primary	Classroom G2	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Primary	Classroom G2	yes	W2	Cinderblock	Beige	Flaking	5	0.09	Negative
2	GD	Primary	Classroom G2	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Primary	Classroom G2	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Primary	Classroom G2	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Primary	Classroom G2	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Primary	Classroom G2	yes	W4	Cinderblock	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
2	GD	Primary	Classroom G2	yes	Ceiling	Concrete	White	Flaking	3	1.1	Positive
2	GD	Primary	Classroom G2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Storage	Classroom G2 Closet 1	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G2 Closet 1	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G2 Closet 1	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G2 Closet 1	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G2 Closet 1	yes	Ceiling	Wood	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G2 Closet 1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Storage	Classroom G2 Closet 2	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G2 Closet 2	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G2 Closet 2	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G2 Closet 2	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G2 Closet 2	yes	Ceiling	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G2 Closet 2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G2 Restroom	yes	W1	Sheetrock	White	None	0	N/A	N/A
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G2 Restroom	yes	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G2 Restroom	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G2 Restroom	yes	W4	Sheetrock	White	N/A	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G2 Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G2 Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
2	GD	Primary	Classroom G3	yes	W1	Cinderblock	Purpe	None	0	N/A	N/A
2	GD	Primary	Classroom G3	yes	W2	Cinderblock	Blue	None	0	N/A	N/A
2	GD	Primary	Classroom G3	yes	W3	Cinderblock	Purple	None	0	N/A	N/A
2	GD	Primary	Classroom G3	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Primary	Classroom G3	yes	W4	Cinderblock	Blue	None	0	N/A	N/A
2	GD	Primary	Classroom G3	yes	Ceiling	Concrete	White	Cracking, Spalling	5	1.1	Positive
2	GD	Primary	Classroom G3	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Storage	Classroom G3 Closet 1	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G3 Closet 1	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G3 Closet 1	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G3 Closet 1	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G3 Closet 1	yes	Ceiling	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G3 Closet 1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Storage	Classroom G3 Closet 2	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G3 Closet 2	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G3 Closet 2	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G3 Closet 2	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G3 Closet 2	yes	Ceiling	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Storage	Classroom G3 Closet 2	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G3 Restroom	yes	W1	Sheetrock	Beige	Partially Inaccessible	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G3 Restroom	yes	W2	Sheetrock	Beige	Partially Inaccessible	0	N/A	N/A
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G3 Restroom	yes	W3	Glazed Block	N/A	Partially Inaccessible	0	N/A	N/A
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G3 Restroom	yes	W4	Glazed Block	N/A	Partially Inaccessible	0	N/A	N/A
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G3 Restroom	yes	Ceiling	Plaster	White	Partially Inaccessible	0	N/A	N/A
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G3 Restroom	yes	Floor	Ceramic	N/A	Partially Inaccessible	N/A	N/A	N/A
2	GD	Mechanical Room	Mechanical Room next to Classroom G3	no	W1	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Mechanical Room	Mechanical Room next to Classroom G3	no	W2	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Mechanical Room	Mechanical Room next to Classroom G3	no	W3	Cinderblock	Beige	Efflorescence	20	0.05	Negative
2	GD	Mechanical Room	Mechanical Room next to Classroom G3	no	W4	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Mechanical Room	Mechanical Room next to Classroom G3	no	Ceiling	Cinderblock	Beige	Flaking	15	0.06	Negative
2	GD	Mechanical Room	Mechanical Room next to Classroom G3	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Mechanical Room	Mechanical Room next to Classroom G3	no	Floor	Concrete	Grey	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
2	GD	Restrooms, Staff - Male/Female	Restroom in the Hallway across from Classroom G1	yes	W1	Glazed Block	N/A	Crack	1	2.5	Positive
2	GD	Restrooms, Staff - Male/Female	Restroom in the Hallway across from Classroom G1	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Restrooms, Staff - Male/Female	Restroom in the Hallway across from Classroom G1	yes	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A
2	GD	Restrooms, Staff - Male/Female	Restroom in the Hallway across from Classroom G1	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
2	GD	Restrooms, Staff - Male/Female	Restroom in the Hallway across from Classroom G1	yes	W4	Glazed Block	N/A	Crack	10	1.7	Positive
2	GD	Restrooms, Staff - Male/Female	Restroom in the Hallway across from Classroom G1	yes	Ceiling	Concrete	White	Flaking	10	0.05	Negative
2	GD	Restrooms, Staff - Male/Female	Restroom in the Hallway across from Classroom G1	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Service Closets	Custodial Storage next to Mechanical Room	no	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Service Closets	Custodial Storage next to Mechanical Room	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Service Closets	Custodial Storage next to Mechanical Room	no	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Service Closets	Custodial Storage next to Mechanical Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Service Closets	Custodial Storage next to Mechanical Room	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Service Closets	Custodial Storage next to Mechanical Room	no	W3	Cinderblock	Yellow	Cracking	10	0.4	Negative
2	GD	Service Closets	Custodial Storage next to Mechanical Room	no	W4	Cinderblock	Yellow	Cracking	10	0.3	Negative
2	GD	Service Closets	Custodial Storage next to Mechanical Room	no	Ceiling	Concrete	White	Flaking	3	0.06	Negative
2	GD	Service Closets	Custodial Storage next to Mechanical Room	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Service Closets	Custodial Storage next to Mechanical Room	no	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
2	GD	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male (4-12)	Boy's Restroom	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Ceiling	Concrete	White	Flaking	6	0.12	Negative
2	GD	Student Restrooms - Male (4-12)	Boy's Restroom	yes	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A
2	GD	Administrative Office	School Security Office	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Administrative Office	School Security Office	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Administrative Office	School Security Office	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Administrative Office	School Security Office	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Administrative Office	School Security Office	yes	Ceiling	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Administrative Office	School Security Office	yes	Floor	Cinderblock	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
2	GD	Restrooms, Staff - Male/Female	School Security Office Restroom	yes	W1	Glazed Block	N/A	N/A	N/A	N/A	N/A
2	GD	Restrooms, Staff - Male/Female	School Security Office Restroom	yes	W2	Glazed Block	N/A	N/A	N/A	N/A	N/A
2	GD	Restrooms, Staff - Male/Female	School Security Office Restroom	yes	W3	Glazed Block	N/A	N/A	N/A	N/A	N/A
2	GD	Restrooms, Staff - Male/Female	School Security Office Restroom	yes	W4	Glazed Block	N/A	N/A	N/A	N/A	N/A
2	GD	Restrooms, Staff - Male/Female	School Security Office Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	GD	Restrooms, Staff - Male/Female	School Security Office Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
2	GD	Circulation (Hallway)	Main Hallway	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Circulation (Hallway)	Main Hallway	yes	W2	Cinderblock	Yellow	Flaking	2	0.07	Negative
2	GD	Circulation (Hallway)	Main Hallway	yes	W3	Cinderblock	Yellow	Flaking	2	0.09	Negative
2	GD	Circulation (Hallway)	Main Hallway	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Circulation (Hallway)	Main Hallway	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Circulation (Hallway)	Main Hallway	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	GD	Circulation (Hallway)	Main Hallway	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Circulation (Hallway)	Hallway at Boy's Restroom	yes	W1	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Circulation (Hallway)	Hallway at Boy's Restroom	yes	W2	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Circulation (Hallway)	Hallway at Boy's Restroom	yes	W3	Cinderblock	Yellow	None	0	N/A	N/A
2	GD	Circulation (Hallway)	Hallway at Boy's Restroom	yes	W4	Cinderblock	Yellow	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
2	GD	Circulation (Hallway)	Hallway at Boy's Restroom	yes	Ceiling	Concrete	White	Flaking	2	0.15	Negative
2	GD	Circulation (Hallway)	Hallway at Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Stairs	Stairwell by Classrooms G2 & G3	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Stairs	Stairwell by Classrooms G2 & G3	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Stairs	Stairwell by Classrooms G2 & G3	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Stairs	Stairwell by Classrooms G2 & G3	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Stairs	Stairwell by Classrooms G2 & G3	yes	Ceiling	Concrete	White	None	0	N/A	N/A
2	GD	Stairs	Stairwell by Classrooms G2 & G3	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	GD	Stairs	Stairwell by Boy's Restroom	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Stairs	Stairwell by Boy's Restroom	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Stairs	Stairwell by Boy's Restroom	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Stairs	Stairwell by Boy's Restroom	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Stairs	Stairwell by Boy's Restroom	yes	Ceiling	Plaster	White	Efflorescence, Damaged Plaster	30	0.01	Negative
2	GD	Stairs	Stairwell by Boy's Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	GD	Stairs	Stairwell by Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	IMC (Library)	IMC Library	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	GD	IMC (Library)	IMC Library	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	GD	IMC (Library)	IMC Library	yes	W3	Cinderblock	Beige	Efflorescence	10	0	Negative
2	GD	IMC (Library)	IMC Library	yes	W4	Cinderblock	Beige	Efflorescence	40	0.01	Negative
2	GD	IMC (Library)	IMC Library	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	IMC (Library)	IMC Library	yes	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
2	GD	Administrative Office	Library Office/Kitchen	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Administrative Office	Library Office/Kitchen	yes	W2	Cinderblock	Beige	Efflorescence	20	0.01	Negative
2	GD	Administrative Office	Library Office/Kitchen	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Administrative Office	Library Office/Kitchen	yes	W4	Cinderblock	Beige	None	0	N/A	N/A



School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
2	GD	Administrative Office	Library Office/Kitchen	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Administrative Office	Library Office/Kitchen	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Administrative Office	Speech Room	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Administrative Office	Speech Room	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Administrative Office	Speech Room	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Administrative Office	Speech Room	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Administrative Office	Speech Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Administrative Office	Speech Room	yes	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
2	GD	Administrative Office	Home & School Office	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Administrative Office	Home & School Office	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Administrative Office	Home & School Office	yes	W3	Cinderblock	Beige	Efflorescence	100	0.01	Negative
2	GD	Administrative Office	Home & School Office	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Administrative Office	Home & School Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Administrative Office	Home & School Office	yes	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
2	GD	Restrooms, Staff - Male	Men's Restroom	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Restrooms, Staff - Male	Men's Restroom	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Restrooms, Staff - Male	Men's Restroom	yes	W3	Cinderblock	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)
2	GD	Restrooms, Staff - Male	Men's Restroom	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Restrooms, Staff - Male	Men's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Restrooms, Staff - Male	Men's Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
2	GD	Restrooms, Staff - Female	Women's Restroom	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Restrooms, Staff - Female	Women's Restroom	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Restrooms, Staff - Female	Women's Restroom	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Restrooms, Staff - Female	Women's Restroom	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Restrooms, Staff - Female	Women's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Restrooms, Staff - Female	Women's Restroom	yes	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
2	GD	Mechanical Room	Mechanical Room	no	W1	Cinderblock	N/A	N/A	N/A	N/A	N/A
2	GD	Mechanical Room	Mechanical Room	no	W2	Cinderblock	N/A	N/A	N/A	N/A	N/A
2	GD	Mechanical Room	Mechanical Room	no	W3	Cinderblock	N/A	N/A	N/A	N/A	N/A
2	GD	Mechanical Room	Mechanical Room	no	W4	Cinderblock	N/A	N/A	N/A	N/A	N/A
2	GD	Mechanical Room	Mechanical Room	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
2	GD	Mechanical Room	Mechanical Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	GD	Circulation (Hallway)	Hallway in front of Library	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Circulation (Hallway)	Hallway in front of Library	yes	W2	Cinderblock	Beige	None	0	N/A	N/A

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
2	GD	Circulation (Hallway)	Hallway in front of Library	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Circulation (Hallway)	Hallway in front of Library	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Circulation (Hallway)	Hallway in front of Library	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Circulation (Hallway)	Hallway in front of Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Circulation (Hallway)	Hallway at the Entrance	yes	W1	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Circulation (Hallway)	Hallway at the Entrance	yes	W2	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Circulation (Hallway)	Hallway at the Entrance	yes	W3	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Circulation (Hallway)	Hallway at the Entrance	yes	W4	Cinderblock	Beige	None	0	N/A	N/A
2	GD	Circulation (Hallway)	Hallway at the Entrance	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
2	GD	Circulation (Hallway)	Hallway at the Entrance	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Storage	Main Office Closet by the entrance	yes	W4	Plaster	Beige	Cracking	20	10.3	Positive
1	1	Storage	Teacher Lounge Right side Storage	yes	W1	Plaster	Beige	Flaking	4	8.9	Positive
1	1	Storage	Teacher Lounge Right side Storage	yes	W1	Plaster	Beige	Flaking, Cracking	4	8.4	Positive
1	1	Storage	Teacher Lounge Right side Storage	yes	W3	Plaster	Beige	Flaking, Cracking	5	10.1	Positive
1	1	Storage	Teacher Lounge Right side Storage	yes	W4	Plaster	Beige	Crack in plaster	6	7.8	Positive
1	1	Storage	Teacher Lounge Right side Storage	yes	Ceiling	Plaster	Beige	None	0	5.5	Positive
1	2	Storage	Classroom 202 Closet	yes	W4	Plaster	Beige	Efflorescence	10	7.7	Positive
1	2	Storage	Storage in Room 203A -School Psychologist's Office next to Room 203	yes	W1	Plaster	Beige	Chipping	10	0.01	Negative
1	2	Storage	Storage in Room 203A -School Psychologist's Office next to Room 203	yes	W2	Plaster	Beige	Chipping	10	0.8	Positive
1	2	Storage	Storage in Room 203A -School Psychologist's Office next to Room 203	yes	W3	Plaster	Beige	Chipping	10	0.9	Positive

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	Floor	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)
1	2	Storage	Storage in Room 203A -School Psychologist's Office next to Room 203	yes	W4	Plaster	Beige	Chipping	10	0.8	Positive
1	2	Storage	Classroom 206 Storage	yes	W4	Plaster	Beige	Efflorescence	10	0.8	Positive
1	3	Storage	Classroom 303 Closet	yes	W1	Plaster	Blue	Chipping	2	8.3	Positive
2	GD	Student Restrooms - Male/Female (Classroom)	Classroom G3 Restroom	yes	W1	Sheetrock	Beige	Cracking	5	0	Negative
1	3	Primary	Classroom 310	yes	W3	Plaster	Beige	Efflorescence	25	5.8	Positive
1	3	Storage	Classroom 310 Storage	yes	W4	Plaster	Beige	Efflorescence	15	12.2	Positive
2	3	Primary	Classroom 313	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	3	Primary	Classroom 313	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Primary	Classroom 306	yes	W2	Plaster	Beige	Efflorescence	40	12	Positive
1	1	Storage	Storage to the left of Stage	yes	W2	Plaster	Beige	Spalling, Efflorescence	6	8.8	Positive
1	1	Storage	Storage to the left of Stage	yes	W3	Plaster	Beige	Efflorescence	3	7.5	Positive
1	1	Storage	Storage to the left of Stage	yes	Ceiling	Plaster	Beige	Efflorescence, Flaking	4	12.4	Positive
1	1	Storage	Storage to the right of Stage	yes	W3	Plaster	Beige	Spalling, Efflorescence, Cracking	4	0.04	Negative
1	1	Storage	Storage to the right of Stage	yes	W4	Plaster	Beige	Spalling, Efflorescence, Cracking	12	0.14	Negative
1	1	Storage	Storage to the right of Stage	yes	Ceiling	Plaster	Beige	Efflorescence	2	11.5	Positive



# School District of Philadelphia

# Lead Safe Certification Inspection Report

# Martha Washington Elementary School

[illegible]







# School District of Philadelphia

# Lead Safe Certification Inspection Report

# Martha Washington Elementary School

[illegible]

School District of Philadelphia											
Lead Safe Certification Inspection Report											
Martha Washington Elementary School											
		Name of Inspector: Ananth K. Vinjamuri									
		Inspection Company: Criterion Labs, Inc.									
	F l o o r	Space Type	On-Site Room Name	Student Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/ negative)