



# THE SCHOOL DISTRICT OF PHILADELPHIA

## Operations Division

Office of Environmental Management and Services  
440 North Broad Street  
Philadelphia, Pennsylvania 19130  
215-400-4750

June 25, 2019

Dear Carver High School Community,

As part of the School District of Philadelphia's effort to provide students and staff with safe, accessible and appealing drinking water, your school's water was tested for lead on June 06, 2019. A trained technician collected samples from water outlets and the samples were sent to an accredited Pennsylvania laboratory for analysis. The action level used by the District is 10 parts per billion (ppb) of lead. If water exceeded this action level, the drinking water outlet was shut-off immediately and an action plan developed.

Federal studies indicate that children under the age of six are at the highest risk for harmful lead exposure, and children can be exposed to lead from a variety of sources, including paint, soil and even some consumer products. If you are concerned about your child's possible lead exposure risks, the Philadelphia Department of Public Health (PDPH) recommends contacting your pediatrician or neighborhood Health Center for testing. Additionally, PDPH's lead hotline can address any health-related questions you may have or help you in deciding whether to have your child tested; for questions or more information, please call (215) 685-2788. For additional information about lead and children you can visit [www.cdc.gov/lead](http://www.cdc.gov/lead).

There were 34 outlets tested at your school. Of those outlets, 29 outlets produced water that was below the action level of 10 ppb. Five (5) water outlets were found to have results above the water safety threshold and these outlets were immediately shut-off.

An action plan is being developed to determine the best way to address the outlet(s) that was shut-off (if applicable to your school), including replacing the outlet with a new hydration station or, if the outlet is not needed because another outlet is available nearby, the outlet may be permanently removed from the school. Once a decision is made, the Maintenance Department will perform the new installation or remove the existing outlet.

The School District will test the drinking water at your school every five years and share the results through a letter and also post the results on the District's website. If you wish to review the results from your school and for more information, you may visit the District's website at: [www.philasd.org/waterresults](http://www.philasd.org/waterresults).

Sincerely,

Francine Locke, MS  
Environmental Director



# THE SCHOOL DISTRICT OF PHILADELPHIA

## Operations Division

Office of Environmental Management and Services  
440 North Broad Street  
Philadelphia, Pennsylvania 19130  
215-400-4750

Sample Date	Floor	Outlet Number	Outlet Type	Outlet Description	Lead Result (ppb)	MDL	PQL	Action Limits
06/06/2019	1	1	FT	In health suite exam RM 126D	1.4	0.3	1	BA
06/06/2019	1	2	FT	In health suite exam RM 126G	2.1	0.3	1	BA
06/06/2019	1	3	FT	In health suite exam RM 126F	1.5	0.3	1	BA
06/06/2019	1	4	FT	In health suite exam RM 126E	1	0.3	1	BA
06/06/2019	1	7	FT	In training RM 139	<1.0	0.3	1	BA
06/06/2019	1	8	IM	In training RM 139	<1.0	0.3	1	BA
06/06/2019	1	9	HS	Outside gym	<1.0	0.3	1	BA
06/06/2019	1	10	WF	In boys locker room left	<1.0	0.3	1	BA
06/06/2019	1	11	WF	In boys locker room right	<1.0	0.3	1	BA
06/06/2019	1	12	WF	In girls locker room left	<1.0	0.3	1	BA
06/06/2019	1	14	WF	In girls locker room right	<1.0	0.3	1	BA
06/06/2019	1	17	HS	Outside RM 131 closet	<1.0	0.3	1	BA
06/06/2019	1	18	FT	In RM 145 left	22.7	0.3	1	AA
06/06/2019	1	19	FT	In RM 145 right	43.5	0.3	1	AA
06/06/2019	1	20	WF	In lunchroom left	<1.0	0.3	1	BA
06/06/2019	1	21	WF	In lunchroom right	<1.0	0.3	1	BA
06/06/2019	1	22	FT	In kitchen outside storage RM 101C left	<1.0	0.3	1	BA
06/06/2019	1	23	FT	In kitchen outside storage RM 101C right	1.5	0.3	1	BA
06/06/2019	1	24	FT	In kitchen next to pot washer	<1.0	0.3	1	BA
06/06/2019	1	25	FP	In kitchen next to freezer	299.8	0.3	1	AA
06/06/2019	1	26	FT	In kitchen by microwave oven	<1.0	0.3	1	BA
06/06/2019	1	27	HS	Outside RM 116 closet	<1.0	0.3	1	BA
06/06/2019	1	28	WF	Outside RM 123 left	<1.0	0.3	1	BA
06/06/2019	1	29	WF	Outside RM 123 right	<1.0	0.3	1	BA
06/06/2019	2	30	WF	Outside RM 204 right	2.7	0.3	1	BA
06/06/2019	2	31	WF	Outside RM 204 left	8.8	0.3	1	BA
06/06/2019	2	32	HS	Outside RM 229	<1.0	0.3	1	BA
06/06/2019	2	33	WF	Outside RM 221 left	<1.0	0.3	1	BA
06/06/2019	2	34	WF	Outside RM 221 right	<1.0	0.3	1	BA
06/06/2019	3	35	WF	Outside RM 327 left	<1.0	0.3	1	BA



# THE SCHOOL DISTRICT OF PHILADELPHIA

## Operations Division

Office of Environmental Management and Services  
440 North Broad Street  
Philadelphia, Pennsylvania 19130  
215-400-4750

Sample Date	Floor	Outlet Number	Outlet Type	Outlet Description	Lead Result (ppb)	MDL	PQL	Action Limits
06/06/2019	3	36	WF	Outside RM 327 right	<1.0	0.3	1	BA
06/06/2019	3	37	WF	Outside RM 304 left	37.9*	0.3	1	AA
06/06/2019	3	38	WF	Outside RM 304 right	13.3*	0.3	1	AA
06/06/2019	3	39	HS	Outside RM 320	<1.0	0.3	1	BA

### Notes:

AA = Above Action limit of 10 ppb

BA = Below Action limit of 10 ppb

MDL = Method Detection Limit

PQL = Practical Quantitation Limit

J = Result estimated below the PQL

< = not detected above PQL

ppb = parts per billion

\*Denotes an outlet location that has not been in use (the outlet was temporarily turned on for testing).

### Outlet Types:

WF=Water Fountain/Bubbler

HS=Hydration Station/Bottle Filling Station

FT=Faucet/Tap

FP - Food Prep/Pot-Filler/Kitchen Kettle

IM - Ice-Maker