

## **Operations Division**

Office of Environmental Management and Services
440 North Broad Street
Philadelphia, Pennsylvania 19130
215-400-4750

December 16, 2019

Dear Randolph High School Community,

As part of the School District of Philadelphia's effort to provide students and staff with safe, accessible and appealing drinking water, your school's water was tested for lead on June 18, 2019, June 19, 2019, June 20, 2019, and June 27, 2019. A trained technician collected samples from water outlets and the samples were sent to an accredited Pennsylvania laboratory for analysis. The action level used by the District is 10 parts per billion (ppb) of lead. If water exceeded this action level, the drinking water outlet was shut-off immediately and an action plan developed.

Federal studies indicate that children under the age of six are at the highest risk for harmful lead exposure, and children can be exposed to lead from a variety of sources, including paint, soil and even some consumer products. If you are concerned about your child's possible lead exposure risks, the Philadelphia Department of Public Health (PDPH) recommends contacting your pediatrician or neighborhood Health Center for testing. Additionally, PDPH's lead hotline can address any health-related questions you may have or help you in deciding whether to have your child tested; for questions or more information, please call (215) 685-2788. For additional information about lead and children you can visit www.cdc.gov/lead.

There were 33 outlets tested at your school. Of those outlets, 26 outlets produced water that was below the action level of 10 ppb. Seven (7) water outlets were found to have results above the water safety threshold and these outlets were immediately shut-off.

An action plan is being developed to determine the best way to address the outlet(s) that was shut-off (if applicable to your school), including replacing the outlet with a new hydration station or, if the outlet is not needed because another outlet is available nearby, the outlet may be permanently removed from the school. Once a decision is made, the Maintenance Department will perform the new installation or remove the existing outlet.

The School District will test the drinking water at your school every five years and share the results through a letter and also post the results on the District's website. If you wish to review the results from your school and for more information, you may visit the District's website at: www.philasd.org/waterresults.

Sincerely,

Brian Joseph Environmental Director



## **Operations Division**

Office of Environmental Management and Services
440 North Broad Street
Philadelphia, Pennsylvania 19130
215-400-4750

				<u></u>				
Sample Date	Floor	Outlet Number	Outlet Type	Outlet Description	Lead Result (ppb)	MDL	PQL	Action Limits
06/18/2019	1	1	WF	Outside building engineer office	1.0	0.3	1.0	BA
06/18/2019	1	2	HS	Outside school police office	<1.0	0.3	1.0	BA
06/18/2019	1	3	HS	In lunchroom	<1.0	0.3	1.0	BA
06/18/2019	1	4	IM	In kitchen outside food service office	<1.0	0.3	1.0	BA
06/18/2019	1	5	FT	In kitchen across from food service office left	3.0	0.3	1.0	BA
06/18/2019	1	6	FT	In kitchen across from food service office right	2.8	0.3	1.0	BA
06/18/2019	1	7	IM	In cutlery kitchen by walk in freezer	<1.0	0.3	1.0	BA
06/18/2019	1	8	FT	In cutlery kitchen by mixers	<1.0	0.3	1.0	BA
06/18/2019	1	9	FT	In cutlery kitchen outside chefs office	1.1	0.3	1.0	BA
06/18/2019	1	10	FT	In cutlery kitchen by pot washers	2.0	0.3	1.0	BA
06/18/2019	1	11	FP	In cutlery kitchen left	<1.0	0.3	1.0	BA
06/18/2019	1	12	FP	In cutlery kitchen right	2.4	0.3	1.0	BA
06/18/2019	1	13	FT	In nurses office	2.0	0.3	1.0	BA
06/18/2019	1	14	FT	In nurses restroom	3.3	0.3	1.0	BA
06/18/2019	1	15	FT	Outside nurses office in waiting RM	19.1	0.3	1.0	AA
06/19/2019	1	16	FT	In RM 38 (back wall left)	5.1	0.3	1.0	BA
06/19/2019	1	17	FT	In RM 38 (back wall center)	15.4	0.3	1.0	AA
06/19/2019	1	18	FT	In RM 38 (back wall right)	14.8	0.3	1.0	AA
06/19/2019	1	19	FT	In RM 38 by rear door	32.0	0.3	1.0	AA
06/19/2019	1	20	FT	In RM 38 (between 1+2 ops area)	<1.0	0.3	1.0	BA
06/19/2019	1	21	FT	In RM 38 (between 3+4 ops area)	1.7	0.3	1.0	BA
06/19/2019	1	22	FT	In RM 38 (between 4+5 ops area)	1.1	0.3	1.0	BA
06/19/2019	1	23	FT	In RM 38 (between 5+6 ops area)	2.0	0.3	1.0	BA
06/19/2019	1	24	FT	In RM 38 (dark room)	33.5	0.3	1.0	AA
06/19/2019	1	25	HS	Outside RM 73	<1.0	0.3	1.0	BA
06/19/2019	1	26	HS	In fire academy RM	<1.0	0.3	1.0	BA
06/19/2019	1	27	WF	In Auto shop by garage door AM-9	1.3	0.3	1.0	BA
06/19/2019	1	28	WF	In auto shop by garage door AM - 11	1.1	0.3	1.0	BA
06/19/2019	1	29	WF	In Gym	<1.0	0.3	1.0	BA
06/20/2019	1	30	WF	In welding shop outside boys BR	26.2*	0.3	1.0	AA
06/20/2019	1	31	WF	Outside welding shop	6.7	0.3	1.0	BA
06/20/2019	1	32	WF	In vendor shop	8.8	0.3	1.0	BA
06/27/2019	1	33	FT	In IMC office	28.4*	0.3	1.0	AA

## Notes:

AA = Above Action limit of 10 ppb

BA = Below Action limit of 10 ppb

MDL = Method Detection Limit

PQL = Practical Quantitation Limit

J = Result estimated below the PQL

< = not detected above PQL

ppb = parts per billion

Outlet Types:

WF=Water Fountain/Bubbler

HS=Hydration Station/Bottle Filling Station

FT=Faucet/Tap

FP - Food Prep/Pot-Filler/Kitchen Kettle

IM - Ice-Maker

<sup>\*</sup>Denotes an outlet location that has not been in use (the outlet was temporarily turned on for testing).