

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021              |   | School District of Philadelphia           |                    |        |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|---|--------------------|--------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794           |   | Lead Safe Certification Assessment Report |                    |        |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer   |   | Hackett School                            |                    |        |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component                                 | Substrate Material | Color  | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | 107C    | Gym  | Yes   | W1  | CMU                | Blue   | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 107C    | Gym  | Yes   | W2  | CMU                | Blue   | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 107C    | Gym  | Yes   | W3  | CMU                | Blue   | Flaking                  | 1                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 107C    | Gym  | Yes   | W4  | CMU                | Blue   | Flaking                  | 3                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 107C    | Gym  | Yes   | Ceiling                                   | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107C    | Gym  | Yes   | Floor                                     | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107C    | Gym  | Yes   | Duct                                      | Metal              | Silver | Flaking                  | 25                      | No Access               | No Access                      |
| 5300  | 1                               | 1                     | H120    | Circular Hallway Classroom 106 to Classroom 106                      | Yes   | W1  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120    | Circular Hallway Classroom 106 to Classroom 106                      | Yes   | W2  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120    | Circular Hallway Classroom 106 to Classroom 106                      | Yes   | W3  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120    | Circular Hallway Classroom 106 to Classroom 106                      | Yes   | W4  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120    | Circular Hallway Classroom 106 to Classroom 106                      | Yes   | Ceiling                                   | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120    | Circular Hallway Classroom 106 to Classroom 106                      | Yes   | Floor                                     | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H121    | Hallway Gym to Hall past Women's Restroom near Classroom 107 - Music | Yes   | W1  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H121    | Hallway Gym to Hall past Women's Restroom near Classroom 107 - Music | Yes   | W2  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H121    | Hallway Gym to Hall past Women's Restroom near Classroom 107 - Music | Yes   | W3  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H121    | Hallway Gym to Hall past Women's Restroom near Classroom 107 - Music | Yes   | W4  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H121    | Hallway Gym to Hall past Women's Restroom near Classroom 107 - Music | Yes   | Ceiling                                   | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H121    | Hallway Gym to Hall past Women's Restroom near Classroom 107 - Music | Yes   | Floor                                     | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H122    | Main Entrance Lobby  | Yes   | W1  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H122    | Main Entrance Lobby  | Yes   | W2  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H122    | Main Entrance Lobby  | Yes   | W3  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H122    | Main Entrance Lobby  | Yes   | W4  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H122    | Main Entrance Lobby  | Yes   | Ceiling                                   | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H122    | Main Entrance Lobby  | Yes   | Floor                                     | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H123    | Main Entrance Foyer  | Yes   | W1  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H123    | Main Entrance Foyer  | Yes   | W2  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H123    | Main Entrance Foyer  | Yes   | W3  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H123    | Main Entrance Foyer  | Yes   | W4  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H123    | Main Entrance Foyer  | Yes   | Ceiling                                   | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H123    | Main Entrance Foyer  | Yes   | Floor                                     | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S100    | Stairwell near Classroom 109   | Yes   | W1  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S100    | Stairwell near Classroom 109   | Yes   | W2  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S100    | Stairwell near Classroom 109   | Yes   | W3  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S100    | Stairwell near Classroom 109   | Yes   | W4  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S100    | Stairwell near Classroom 109   | Yes   | Ceiling                                   | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S100    | Stairwell near Classroom 109   | Yes   | Floor                                     | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S100    | Stairwell near Classroom 109   | Yes   | W1  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S100    | Stairwell near Classroom 109   | Yes   | W2  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S100    | Stairwell near Classroom 109   | Yes   | W3  | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021                           | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|---|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794                        | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer  | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name   | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | S100    | Stairwell near Classroom 109  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S100    | Stairwell near Classroom 109  | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S100    | Stairwell near Classroom 109  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S102    | Stairs next to Nurse Office that lead to Crawl Space and Elevator Mechanical Area | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S102    | Stairs next to Nurse Office that lead to Crawl Space and Elevator Mechanical Area | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S102    | Stairs next to Nurse Office that lead to Crawl Space and Elevator Mechanical Area | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S102    | Stairs next to Nurse Office that lead to Crawl Space and Elevator Mechanical Area | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S102    | Stairs next to Nurse Office that lead to Crawl Space and Elevator Mechanical Area | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S102    | Stairs next to Nurse Office that lead to Crawl Space and Elevator Mechanical Area | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100     | Main Office   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100     | Main Office   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100     | Main Office   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100     | Main Office   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100     | Main Office   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100     | Main Office   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100A    | Main Office Conference Room   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100A    | Main Office Conference Room   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100A    | Main Office Conference Room   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100A    | Main Office Conference Room   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100A    | Main Office Conference Room   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100A    | Main Office Conference Room   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100ACL  | Main Office Conference Room - Closet  | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100ACL  | Main Office Conference Room - Closet  | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100ACL  | Main Office Conference Room - Closet  | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100ACL  | Main Office Conference Room - Closet  | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100ACL  | Main Office Conference Room - Closet  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100ACL  | Main Office Conference Room - Closet  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100RR   | Conference Room Restroom  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100RR   | Conference Room Restroom  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100RR   | Conference Room Restroom  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100RR   | Conference Room Restroom  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100RR   | Conference Room Restroom  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100RR   | Conference Room Restroom  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100RR   | Conference Room Restroom  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100RR   | Conference Room Restroom  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100RR   | Conference Room Restroom  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100RR   | Conference Room Restroom  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100RR   | Conference Room Restroom  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100RR   | Conference Room Restroom  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100CL   | Main Office Rear Closet next to Counselor's Office                                | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | 100CL   | Main Office Rear Closet next to Counselor's Office         | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100CL   | Main Office Rear Closet next to Counselor's Office         | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100CL   | Main Office Rear Closet next to Counselor's Office         | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100CL   | Main Office Rear Closet next to Counselor's Office         | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100CL   | Main Office Rear Closet next to Counselor's Office         | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100B    | Rear Counselor's Office in Main Office                     | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100B    | Rear Counselor's Office in Main Office                     | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100B    | Rear Counselor's Office in Main Office                     | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100B    | Rear Counselor's Office in Main Office                     | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100B    | Rear Counselor's Office in Main Office                     | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100B    | Rear Counselor's Office in Main Office                     | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100C    | Middle Counselor's Office in Main Office                   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100C    | Middle Counselor's Office in Main Office                   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100C    | Middle Counselor's Office in Main Office                   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100C    | Middle Counselor's Office in Main Office                   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100C    | Middle Counselor's Office in Main Office                   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100C    | Middle Counselor's Office in Main Office                   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100D    | Vice Principal's Office in Main Office                     | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100D    | Vice Principal's Office in Main Office                     | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100D    | Vice Principal's Office in Main Office                     | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100D    | Vice Principal's Office in Main Office                     | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100D    | Vice Principal's Office in Main Office                     | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100D    | Vice Principal's Office in Main Office                     | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100H    | Main Office Copy/File Room                                 | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100H    | Main Office Copy/File Room                                 | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100H    | Main Office Copy/File Room                                 | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100H    | Main Office Copy/File Room                                 | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100H    | Main Office Copy/File Room                                 | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100H    | Main Office Copy/File Room                                 | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100E    | Principal's Office   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100E    | Principal's Office   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100E    | Principal's Office   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100E    | Principal's Office   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100E    | Principal's Office   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100E    | Principal's Office   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100F    | Nurse's Office Waiting Area                                | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100F    | Nurse's Office Waiting Area                                | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100F    | Nurse's Office Waiting Area                                | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100F    | Nurse's Office Waiting Area                                | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100F    | Nurse's Office Waiting Area                                | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100F    | Nurse's Office Waiting Area                                | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100G    | Nurse's Office Closet                                      | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100G    | Nurse's Office Closet                                      | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100G    | Nurse's Office Closet                                      | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100G    | Nurse's Office Closet                                      | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | 100G    | Nurse's Office Closet                                      | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100G    | Nurse's Office Closet                                      | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100K    | Nurse's Office Restroom                                    | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100K    | Nurse's Office Restroom                                    | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100K    | Nurse's Office Restroom                                    | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100K    | Nurse's Office Restroom                                    | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100K    | Nurse's Office Restroom                                    | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100K    | Nurse's Office Restroom                                    | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100I    | Nurse's Office   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100I    | Nurse's Office   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100I    | Nurse's Office   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100I    | Nurse's Office   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100I    | Nurse's Office   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 100I    | Nurse's Office   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 104     | IMC  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 104     | IMC  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 104     | IMC  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 104     | IMC  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 104     | IMC  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 104     | IMC  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 102     | IMC Rear Storage Room on Left Side                         | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 102     | IMC Rear Storage Room on Left Side                         | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 102     | IMC Rear Storage Room on Left Side                         | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 102     | IMC Rear Storage Room on Left Side                         | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 102     | IMC Rear Storage Room on Left Side                         | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 102     | IMC Rear Storage Room on Left Side                         | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 101     | IMC Rear Storage Room on Right Side (Computer Storage)     | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 101     | IMC Rear Storage Room on Right Side (Computer Storage)     | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 101     | IMC Rear Storage Room on Right Side (Computer Storage)     | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 101     | IMC Rear Storage Room on Right Side (Computer Storage)     | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 101     | IMC Rear Storage Room on Right Side (Computer Storage)     | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 101     | IMC Rear Storage Room on Right Side (Computer Storage)     | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105     | IMC Office   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105     | IMC Office   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105     | IMC Office   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105     | IMC Office   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105     | IMC Office   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105     | IMC Office   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105CL   | IMC Office Closet by Entrance                              | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105CL   | IMC Office Closet by Entrance                              | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021                 | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|---|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794              | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer  | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name   | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | 105CL   | IMC Office Closet by Entrance   | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105CL   | IMC Office Closet by Entrance   | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105CL   | IMC Office Closet by Entrance   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105CL   | IMC Office Closet by Entrance   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105A    | IMC Office Rear Storage Room  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105A    | IMC Office Rear Storage Room  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105A    | IMC Office Rear Storage Room  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105A    | IMC Office Rear Storage Room  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105A    | IMC Office Rear Storage Room  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 105A    | IMC Office Rear Storage Room  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S101    | Hallway to Boiler Room and Building Engineer's Office (includes Stairs) | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S101    | Hallway to Boiler Room and Building Engineer's Office (includes Stairs) | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S101    | Hallway to Boiler Room and Building Engineer's Office (includes Stairs) | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S101    | Hallway to Boiler Room and Building Engineer's Office (includes Stairs) | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S101    | Hallway to Boiler Room and Building Engineer's Office (includes Stairs) | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | S101    | Hallway to Boiler Room and Building Engineer's Office (includes Stairs) | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107B    | Building Engineer's Office  | No  | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107B    | Building Engineer's Office  | No  | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107B    | Building Engineer's Office  | No  | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107B    | Building Engineer's Office  | No  | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107B    | Building Engineer's Office  | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107B    | Building Engineer's Office  | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107N    | Building Engineer's Office - Restroom                                   | No  | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107N    | Building Engineer's Office - Restroom                                   | No  | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107N    | Building Engineer's Office - Restroom                                   | No  | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107N    | Building Engineer's Office - Restroom                                   | No  | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107N    | Building Engineer's Office - Restroom                                   | No  | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107N    | Building Engineer's Office - Restroom                                   | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC107N  | Pipe Chase in Building Engineer's Office - Restroom                     | No  | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC107N  | Pipe Chase in Building Engineer's Office - Restroom                     | No  | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC107N  | Pipe Chase in Building Engineer's Office - Restroom                     | No  | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC107N  | Pipe Chase in Building Engineer's Office - Restroom                     | No  | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC107N  | Pipe Chase in Building Engineer's Office - Restroom                     | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC107N  | Pipe Chase in Building Engineer's Office - Restroom                     | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107L    | Building Engineer's Office Supply Room                                  | No  | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107L    | Building Engineer's Office Supply Room                                  | No  | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107L    | Building Engineer's Office Supply Room                                  | No  | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107L    | Building Engineer's Office Supply Room                                  | No  | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107L    | Building Engineer's Office Supply Room                                  | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107L    | Building Engineer's Office Supply Room                                  | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021            | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794         | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | 106     | Classroom 106 - Art  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106     | Classroom 106 - Art  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106     | Classroom 106 - Art  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106     | Classroom 106 - Art  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106     | Classroom 106 - Art  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106     | Classroom 106 - Art  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106A    | Classroom 106 - Art - Rear Left Side Storage Room                  | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106A    | Classroom 106 - Art - Rear Left Side Storage Room                  | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106A    | Classroom 106 - Art - Rear Left Side Storage Room                  | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106A    | Classroom 106 - Art - Rear Left Side Storage Room                  | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106A    | Classroom 106 - Art - Rear Left Side Storage Room                  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106A    | Classroom 106 - Art - Rear Left Side Storage Room                  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106B    | Classroom 106 - Art - Rear Right Side Storage Room                 | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106B    | Classroom 106 - Art - Rear Right Side Storage Room                 | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106B    | Classroom 106 - Art - Rear Right Side Storage Room                 | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106B    | Classroom 106 - Art - Rear Right Side Storage Room                 | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106B    | Classroom 106 - Art - Rear Right Side Storage Room                 | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106B    | Classroom 106 - Art - Rear Right Side Storage Room                 | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106D    | Classroom 106 - Art - Storage Room next to Entrance                | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106D    | Classroom 106 - Art - Storage Room next to Entrance                | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106D    | Classroom 106 - Art - Storage Room next to Entrance                | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106D    | Classroom 106 - Art - Storage Room next to Entrance                | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106D    | Classroom 106 - Art - Storage Room next to Entrance                | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106D    | Classroom 106 - Art - Storage Room next to Entrance                | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106D    | Classroom 106 - Art - Storage Room next to Entrance                | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106D    | Classroom 106 - Art - Storage Room next to Entrance                | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106D    | Classroom 106 - Art - Storage Room next to Entrance                | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106D    | Classroom 106 - Art - Storage Room next to Entrance                | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106D    | Classroom 106 - Art - Storage Room next to Entrance                | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106D    | Classroom 106 - Art - Storage Room next to Entrance                | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106BB   | Storage Room across from Men's Restroom near Classroom 107 - Music | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106BB   | Storage Room across from Men's Restroom near Classroom 107 - Music | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106BB   | Storage Room across from Men's Restroom near Classroom 107 - Music | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106BB   | Storage Room across from Men's Restroom near Classroom 107 - Music | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106BB   | Storage Room across from Men's Restroom near Classroom 107 - Music | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106BB   | Storage Room across from Men's Restroom near Classroom 107 - Music | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106BB   | Storage Room across from Men's Restroom near Classroom 107 - Music | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106BB   | Storage Room across from Men's Restroom near Classroom 107 - Music | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021                             | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|---|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794                          | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer  | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name   | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | 106BB   | Storage Room across from Men's Restroom near Classroom 107 - Music                  | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106BB   | Storage Room across from Men's Restroom near Classroom 107 - Music                  | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106BB   | Storage Room across from Men's Restroom near Classroom 107 - Music                  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106BB   | Storage Room across from Men's Restroom near Classroom 107 - Music                  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106C    | Room adjacent to Storage Room across from Men's Restroom near Classroom 107 - Music | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106C    | Room adjacent to Storage Room across from Men's Restroom near Classroom 107 - Music | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106C    | Room adjacent to Storage Room across from Men's Restroom near Classroom 107 - Music | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106C    | Room adjacent to Storage Room across from Men's Restroom near Classroom 107 - Music | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106C    | Room adjacent to Storage Room across from Men's Restroom near Classroom 107 - Music | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 106C    | Room adjacent to Storage Room across from Men's Restroom near Classroom 107 - Music | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107     | Classroom 107-Music   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107     | Classroom 107-Music   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107     | Classroom 107-Music   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107     | Classroom 107-Music   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107     | Classroom 107-Music   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107     | Classroom 107-Music   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107A    | Classroom 107 - Band Storage  | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107A    | Classroom 107 - Band Storage  | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107A    | Classroom 107 - Band Storage  | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107A    | Classroom 107 - Band Storage  | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107A    | Classroom 107 - Band Storage  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107A    | Classroom 107 - Band Storage  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107DCL  | Classroom 107 Front Closet by Display   | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107DCL  | Classroom 107 Front Closet by Display   | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107DCL  | Classroom 107 Front Closet by Display   | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107DCL  | Classroom 107 Front Closet by Display   | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107DCL  | Classroom 107 Front Closet by Display   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107DCL  | Classroom 107 Front Closet by Display   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107D    | Gym Office  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107D    | Gym Office  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107D    | Gym Office  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107D    | Gym Office  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107D    | Gym Office  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107D    | Gym Office  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107M    | Gym Office Shower Area  | No  | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107M    | Gym Office Shower Area  | No  | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107M    | Gym Office Shower Area  | No  | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | 107M    | Gym Office Shower Area                                     | No  | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107M    | Gym Office Shower Area                                     | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107M    | Gym Office Shower Area                                     | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107K    | Gym Office Restroom  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107K    | Gym Office Restroom  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107K    | Gym Office Restroom  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107K    | Gym Office Restroom  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107K    | Gym Office Restroom  | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107K    | Gym Office Restroom  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107CL   | Gym Office Closet  | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107CL   | Gym Office Closet  | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107CL   | Gym Office Closet  | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107CL   | Gym Office Closet  | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107CL   | Gym Office Closet  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107CL   | Gym Office Closet  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107E    | Gym Storage next to Gym Office                             | Yes   | W1        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 107E    | Gym Storage next to Gym Office                             | Yes   | W2        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 107E    | Gym Storage next to Gym Office                             | Yes   | W3        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 107E    | Gym Storage next to Gym Office                             | Yes   | W4        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 107E    | Gym Storage next to Gym Office                             | Yes   | Ceiling   | Concrete           | Beige | Efflorescence            | 8                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 107E    | Gym Storage next to Gym Office                             | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107F    | Gym Girl's Restroom  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107F    | Gym Girl's Restroom  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107F    | Gym Girl's Restroom  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107F    | Gym Girl's Restroom  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107F    | Gym Girl's Restroom  | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107F    | Gym Girl's Restroom  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107G    | Gym Boy's Restroom   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107G    | Gym Boy's Restroom   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107G    | Gym Boy's Restroom   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107G    | Gym Boy's Restroom   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107G    | Gym Boy's Restroom   | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107G    | Gym Boy's Restroom   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC107G  | Pipe Chase in Gym Boy's Restroom                           | No  | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC107G  | Pipe Chase in Gym Boy's Restroom                           | No  | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC107G  | Pipe Chase in Gym Boy's Restroom                           | No  | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC107G  | Pipe Chase in Gym Boy's Restroom                           | No  | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC107G  | Pipe Chase in Gym Boy's Restroom                           | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC107G  | Pipe Chase in Gym Boy's Restroom                           | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107H    | Gym Storage between Boy's Restroom and Fan Room Stairs     | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107H    | Gym Storage between Boy's Restroom and Fan Room Stairs     | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107H    | Gym Storage between Boy's Restroom and Fan Room Stairs     | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |



|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |        |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|--------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |        |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |        |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color  | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | 107H    | Gym Storage between Boy's Restroom and Fan Room Stairs     | Yes   | W4        | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107H    | Gym Storage between Boy's Restroom and Fan Room Stairs     | Yes   | Ceiling   | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107H    | Gym Storage between Boy's Restroom and Fan Room Stairs     | Yes   | Floor     | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107I    | Gym Storage next to Girl's Restroom                        | Yes   | W1        | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107I    | Gym Storage next to Girl's Restroom                        | Yes   | W2        | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107I    | Gym Storage next to Girl's Restroom                        | Yes   | W3        | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107I    | Gym Storage next to Girl's Restroom                        | Yes   | W4        | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107I    | Gym Storage next to Girl's Restroom                        | Yes   | Ceiling   | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107I    | Gym Storage next to Girl's Restroom                        | Yes   | Floor     | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107I    | Gym Storage next to Girl's Restroom                        | Yes   | W1        | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107I    | Gym Storage next to Girl's Restroom                        | Yes   | W2        | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107I    | Gym Storage next to Girl's Restroom                        | Yes   | W3        | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107I    | Gym Storage next to Girl's Restroom                        | Yes   | W4        | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107I    | Gym Storage next to Girl's Restroom                        | Yes   | Ceiling   | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107I    | Gym Storage next to Girl's Restroom                        | Yes   | Floor     | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107J    | Gym Fan Room (including Stairs up to it)                   | No  | W1        | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107J    | Gym Fan Room (including Stairs up to it)                   | No  | W2        | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107J    | Gym Fan Room (including Stairs up to it)                   | No  | W3        | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107J    | Gym Fan Room (including Stairs up to it)                   | No  | W4        | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107J    | Gym Fan Room (including Stairs up to it)                   | No  | Ceiling   | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107J    | Gym Fan Room (including Stairs up to it)                   | No  | Floor     | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 107J    | Gym Fan Room (including Stairs up to it)                   | No  | Duct      | Metal              | Silver | Flaking                  | 1                       | 0.01                    | Negative                       |
| 5300  | 1                               | 1                     | 108     | Teacher's Lounge   | Yes   | W1        | CMU                | Beige  | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 108     | Teacher's Lounge   | Yes   | W2        | CMU                | Beige  | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 108     | Teacher's Lounge   | Yes   | W3        | CMU                | Beige  | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 108     | Teacher's Lounge   | Yes   | W4        | CMU                | Beige  | Flaking                  | 1                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 108     | Teacher's Lounge   | Yes   | Ceiling   | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108     | Teacher's Lounge   | Yes   | Floor     | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108CL   | Teacher's Lounge Closet                                    | Yes   | W1        | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108CL   | Teacher's Lounge Closet                                    | Yes   | W2        | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108CL   | Teacher's Lounge Closet                                    | Yes   | W3        | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108CL   | Teacher's Lounge Closet                                    | Yes   | W4        | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108CL   | Teacher's Lounge Closet                                    | Yes   | Ceiling   | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108CL   | Teacher's Lounge Closet                                    | Yes   | Floor     | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108B  | Pipe Chase in Girl's Restroom                              | No  | W1        | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108B  | Pipe Chase in Girl's Restroom                              | No  | W2        | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108B  | Pipe Chase in Girl's Restroom                              | No  | W3        | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108B  | Pipe Chase in Girl's Restroom                              | No  | W4        | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108B  | Pipe Chase in Girl's Restroom                              | No  | Ceiling   | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108B  | Pipe Chase in Girl's Restroom                              | No  | Floor     | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108A  | Pipe Chase in Boy's Restroom                               | No  | W1        | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108A  | Pipe Chase in Boy's Restroom                               | No  | W2        | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021                           | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|---|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794                        | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer  | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name   | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | PC108A  | Pipe Chase in Boy's Restroom  | No  | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108A  | Pipe Chase in Boy's Restroom  | No  | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108A  | Pipe Chase in Boy's Restroom  | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108A  | Pipe Chase in Boy's Restroom  | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108C    | Men's Restroom near Classroom 107 (Music)   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108C    | Men's Restroom near Classroom 107 (Music)   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108C    | Men's Restroom near Classroom 107 (Music)   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108C    | Men's Restroom near Classroom 107 (Music)   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108C    | Men's Restroom near Classroom 107 (Music)   | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108C    | Men's Restroom near Classroom 107 (Music)   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108D    | Women's Restroom near Classroom 107 (Music)                                       | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108D    | Women's Restroom near Classroom 107 (Music)                                       | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108D    | Women's Restroom near Classroom 107 (Music)                                       | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108D    | Women's Restroom near Classroom 107 (Music)                                       | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108D    | Women's Restroom near Classroom 107 (Music)                                       | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108D    | Women's Restroom near Classroom 107 (Music)                                       | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108E    | Custodial Storage Room and Lockers  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108E    | Custodial Storage Room and Lockers  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108E    | Custodial Storage Room and Lockers  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108E    | Custodial Storage Room and Lockers  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108E    | Custodial Storage Room and Lockers  | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108E    | Custodial Storage Room and Lockers  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108H    | Custodial Storage Room and Lockers - Restroom                                     | Yes   | W1        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 108H    | Custodial Storage Room and Lockers - Restroom                                     | Yes   | W2        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 108H    | Custodial Storage Room and Lockers - Restroom                                     | Yes   | W3        | CMU                | Beige | Flaking                  | 4                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 108H    | Custodial Storage Room and Lockers - Restroom                                     | Yes   | W4        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 1                     | 108H    | Custodial Storage Room and Lockers - Restroom                                     | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108H    | Custodial Storage Room and Lockers - Restroom                                     | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108F    | Storage Closet in Hallway between Faculty Lounge and Boy's Restroom               | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108F    | Storage Closet in Hallway between Faculty Lounge and Boy's Restroom               | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108F    | Storage Closet in Hallway between Faculty Lounge and Boy's Restroom               | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108F    | Storage Closet in Hallway between Faculty Lounge and Boy's Restroom               | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108F    | Storage Closet in Hallway between Faculty Lounge and Boy's Restroom               | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 108F    | Storage Closet in Hallway between Faculty Lounge and Boy's Restroom               | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108F  | Pipe Chase in Storage Closet in Hallway between Faculty Lounge and Boy's Restroom | No  | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108F  | Pipe Chase in Storage Closet in Hallway between Faculty Lounge and Boy's Restroom | No  | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108F  | Pipe Chase in Storage Closet in Hallway between Faculty Lounge and Boy's Restroom | No  | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021                           | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|---|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794                        | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer  | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name   | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | PC108F  | Pipe Chase in Storage Closet in Hallway between Faculty Lounge and Boy's Restroom | No  | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108F  | Pipe Chase in Storage Closet in Hallway between Faculty Lounge and Boy's Restroom | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | PC108F  | Pipe Chase in Storage Closet in Hallway between Faculty Lounge and Boy's Restroom | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109     | Classroom 109   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109     | Classroom 109   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109     | Classroom 109   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109     | Classroom 109   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109     | Classroom 109   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109     | Classroom 109   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109CL   | Classroom 109 Front Closet by Door  | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109CL   | Classroom 109 Front Closet by Door  | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109CL   | Classroom 109 Front Closet by Door  | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109CL   | Classroom 109 Front Closet by Door  | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109CL   | Classroom 109 Front Closet by Door  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109CL   | Classroom 109 Front Closet by Door  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109B    | Classroom 109 Coat Room/Lockers   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109B    | Classroom 109 Coat Room/Lockers   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109B    | Classroom 109 Coat Room/Lockers   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109B    | Classroom 109 Coat Room/Lockers   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109B    | Classroom 109 Coat Room/Lockers   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109B    | Classroom 109 Coat Room/Lockers   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109A    | Classroom 109 Restroom  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109A    | Classroom 109 Restroom  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109A    | Classroom 109 Restroom  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109A    | Classroom 109 Restroom  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109A    | Classroom 109 Restroom  | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109A    | Classroom 109 Restroom  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109C    | Classroom 109 rear Storage Room by Exit Door                                      | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109C    | Classroom 109 rear Storage Room by Exit Door                                      | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109C    | Classroom 109 rear Storage Room by Exit Door                                      | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109C    | Classroom 109 rear Storage Room by Exit Door                                      | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109C    | Classroom 109 rear Storage Room by Exit Door                                      | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109C    | Classroom 109 rear Storage Room by Exit Door                                      | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109H    | Rear Connection Hallway between Classrooms 109 and 110                            | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109H    | Rear Connection Hallway between Classrooms 109 and 110                            | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109H    | Rear Connection Hallway between Classrooms 109 and 110                            | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109H    | Rear Connection Hallway between Classrooms 109 and 110                            | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 109H    | Rear Connection Hallway between Classrooms 109 and 110                            | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | 109H    | Rear Connection Hallway between Classrooms 109 and 110     | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110     | Classroom 110  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110     | Classroom 110  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110     | Classroom 110  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110     | Classroom 110  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110     | Classroom 110  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110     | Classroom 110  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110CL   | Classroom 110 Front Closet                                 | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110CL   | Classroom 110 Front Closet                                 | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110CL   | Classroom 110 Front Closet                                 | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110CL   | Classroom 110 Front Closet                                 | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110CL   | Classroom 110 Front Closet                                 | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110CL   | Classroom 110 Front Closet                                 | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110B    | Classroom 110 Coat Room/Lockers                            | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110B    | Classroom 110 Coat Room/Lockers                            | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110B    | Classroom 110 Coat Room/Lockers                            | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110B    | Classroom 110 Coat Room/Lockers                            | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110B    | Classroom 110 Coat Room/Lockers                            | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110B    | Classroom 110 Coat Room/Lockers                            | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110A    | Classroom 110 Restroom                                     | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110A    | Classroom 110 Restroom                                     | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110A    | Classroom 110 Restroom                                     | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110A    | Classroom 110 Restroom                                     | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110A    | Classroom 110 Restroom                                     | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110A    | Classroom 110 Restroom                                     | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110C    | Classroom 110 Rear Closet                                  | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110C    | Classroom 110 Rear Closet                                  | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110C    | Classroom 110 Rear Closet                                  | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110C    | Classroom 110 Rear Closet                                  | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110C    | Classroom 110 Rear Closet                                  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 110C    | Classroom 110 Rear Closet                                  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111     | Classroom 111  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111     | Classroom 111  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111     | Classroom 111  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111     | Classroom 111  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111     | Classroom 111  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111     | Classroom 111  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111BB   | Classroom 111 Rear Closet by Exit                          | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111BB   | Classroom 111 Rear Closet by Exit                          | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111BB   | Classroom 111 Rear Closet by Exit                          | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111BB   | Classroom 111 Rear Closet by Exit                          | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111BB   | Classroom 111 Rear Closet by Exit                          | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111BB   | Classroom 111 Rear Closet by Exit                          | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111A    | Classrooms 111 and 112 Shared Restroom                     | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | 111A    | Classrooms 111 and 112 Shared Restroom                     | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111A    | Classrooms 111 and 112 Shared Restroom                     | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111A    | Classrooms 111 and 112 Shared Restroom                     | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111A    | Classrooms 111 and 112 Shared Restroom                     | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111A    | Classrooms 111 and 112 Shared Restroom                     | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111D    | Rear Connection Hall between Classrooms 111 and 112        | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111D    | Rear Connection Hall between Classrooms 111 and 112        | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111D    | Rear Connection Hall between Classrooms 111 and 112        | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111D    | Rear Connection Hall between Classrooms 111 and 112        | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111D    | Rear Connection Hall between Classrooms 111 and 112        | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111D    | Rear Connection Hall between Classrooms 111 and 112        | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111B    | Classroom 111 Closet next to Restroom                      | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111B    | Classroom 111 Closet next to Restroom                      | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111B    | Classroom 111 Closet next to Restroom                      | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111B    | Classroom 111 Closet next to Restroom                      | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111B    | Classroom 111 Closet next to Restroom                      | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111B    | Classroom 111 Closet next to Restroom                      | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111B    | Classroom 111 Closet next to Restroom                      | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111B    | Classroom 111 Closet next to Restroom                      | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111B    | Classroom 111 Closet next to Restroom                      | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111B    | Classroom 111 Closet next to Restroom                      | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111B    | Classroom 111 Closet next to Restroom                      | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111B    | Classroom 111 Closet next to Restroom                      | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111C    | Classroom 111 Middle Storage Room                          | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111C    | Classroom 111 Middle Storage Room                          | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111C    | Classroom 111 Middle Storage Room                          | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111C    | Classroom 111 Middle Storage Room                          | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111C    | Classroom 111 Middle Storage Room                          | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111C    | Classroom 111 Middle Storage Room                          | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111C    | Classroom 111 Middle Storage Room                          | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111C    | Classroom 111 Middle Storage Room                          | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111C    | Classroom 111 Middle Storage Room                          | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111C    | Classroom 111 Middle Storage Room                          | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111C    | Classroom 111 Middle Storage Room                          | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 111C    | Classroom 111 Middle Storage Room                          | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112     | Classroom 112  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112     | Classroom 112  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112     | Classroom 112  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112     | Classroom 112  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112     | Classroom 112  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | 112     | Classroom 112  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112A    | Classroom 112 Middle Storage Room                          | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112A    | Classroom 112 Middle Storage Room                          | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112A    | Classroom 112 Middle Storage Room                          | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112A    | Classroom 112 Middle Storage Room                          | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112A    | Classroom 112 Middle Storage Room                          | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112A    | Classroom 112 Middle Storage Room                          | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112B    | Classroom 112 Rear Closet                                  | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112B    | Classroom 112 Rear Closet                                  | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112B    | Classroom 112 Rear Closet                                  | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112B    | Classroom 112 Rear Closet                                  | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112B    | Classroom 112 Rear Closet                                  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112B    | Classroom 112 Rear Closet                                  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112AA   | Classroom 112 Closet next to Restroom                      | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112AA   | Classroom 112 Closet next to Restroom                      | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112AA   | Classroom 112 Closet next to Restroom                      | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112AA   | Classroom 112 Closet next to Restroom                      | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112AA   | Classroom 112 Closet next to Restroom                      | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112AA   | Classroom 112 Closet next to Restroom                      | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112AA   | Classroom 112 Closet next to Restroom                      | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112AA   | Classroom 112 Closet next to Restroom                      | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112AA   | Classroom 112 Closet next to Restroom                      | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112AA   | Classroom 112 Closet next to Restroom                      | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112AA   | Classroom 112 Closet next to Restroom                      | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 112AA   | Classroom 112 Closet next to Restroom                      | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114     | Kitchen  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114     | Kitchen  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114     | Kitchen  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114     | Kitchen  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114     | Kitchen  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114     | Kitchen  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114A    | Kitchen Office   | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114A    | Kitchen Office   | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114A    | Kitchen Office   | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114A    | Kitchen Office   | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114A    | Kitchen Office   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114A    | Kitchen Office   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114C    | Kitchen Storage Room                                       | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114C    | Kitchen Storage Room                                       | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114C    | Kitchen Storage Room                                       | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114C    | Kitchen Storage Room                                       | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114C    | Kitchen Storage Room                                       | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 114C    | Kitchen Storage Room                                       | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113     | Cafetorium   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113     | Cafetorium   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | 113     | Cafetorium   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113     | Cafetorium   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113     | Cafetorium   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113     | Cafetorium   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113C    | Cafetorium Storage Room                                    | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113C    | Cafetorium Storage Room                                    | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113C    | Cafetorium Storage Room                                    | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113C    | Cafetorium Storage Room                                    | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113C    | Cafetorium Storage Room                                    | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113C    | Cafetorium Storage Room                                    | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | Stage   | Cafetorium Stage   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | Stage   | Cafetorium Stage   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | Stage   | Cafetorium Stage   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | Stage   | Cafetorium Stage   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | Stage   | Cafetorium Stage   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | Stage   | Cafetorium Stage   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113G    | Stage Storage Room on Right                                | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113G    | Stage Storage Room on Right                                | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113G    | Stage Storage Room on Right                                | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113G    | Stage Storage Room on Right                                | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113G    | Stage Storage Room on Right                                | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113G    | Stage Storage Room on Right                                | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113F    | Stage Storage Room on Left                                 | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113F    | Stage Storage Room on Left                                 | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113F    | Stage Storage Room on Left                                 | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113F    | Stage Storage Room on Left                                 | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113F    | Stage Storage Room on Left                                 | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113F    | Stage Storage Room on Left                                 | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120A   | Hallway next to Stage to Cafetorium (Kitchen side)         | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120A   | Hallway next to Stage to Cafetorium (Kitchen side)         | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120A   | Hallway next to Stage to Cafetorium (Kitchen side)         | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120A   | Hallway next to Stage to Cafetorium (Kitchen side)         | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120A   | Hallway next to Stage to Cafetorium (Kitchen side)         | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120A   | Hallway next to Stage to Cafetorium (Kitchen side)         | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120A   | Hallway next to Stage to Cafetorium (Kitchen side)         | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120A   | Hallway next to Stage to Cafetorium (Kitchen side)         | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120A   | Hallway next to Stage to Cafetorium (Kitchen side)         | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120A   | Hallway next to Stage to Cafetorium (Kitchen side)         | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120A   | Hallway next to Stage to Cafetorium (Kitchen side)         | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120A   | Hallway next to Stage to Cafetorium (Kitchen side)         | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120B   | Hallway next to Stage to Cafetorium (Main Office side)     | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120B   | Hallway next to Stage to Cafetorium (Main Office side)     | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120B   | Hallway next to Stage to Cafetorium (Main Office side)     | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120B   | Hallway next to Stage to Cafetorium (Main Office side)     | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | H120B   | Hallway next to Stage to Cafetorium (Main Office side)     | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | H120B   | Hallway next to Stage to Cafetorium (Main Office side)     | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113E    | Home and School Program                                    | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113E    | Home and School Program                                    | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113E    | Home and School Program                                    | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113E    | Home and School Program                                    | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113E    | Home and School Program                                    | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113E    | Home and School Program                                    | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113F    | Women's Restroom near Main Office                          | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113F    | Women's Restroom near Main Office                          | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113F    | Women's Restroom near Main Office                          | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113F    | Women's Restroom near Main Office                          | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113F    | Women's Restroom near Main Office                          | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113F    | Women's Restroom near Main Office                          | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113MR   | Men's Restroom near Main Office                            | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113MR   | Men's Restroom near Main Office                            | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113MR   | Men's Restroom near Main Office                            | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113MR   | Men's Restroom near Main Office                            | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113MR   | Men's Restroom near Main Office                            | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113MR   | Men's Restroom near Main Office                            | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113J    | Custodial Closet across from Classroom 112                 | No  | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113J    | Custodial Closet across from Classroom 112                 | No  | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113J    | Custodial Closet across from Classroom 112                 | No  | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113J    | Custodial Closet across from Classroom 112                 | No  | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113J    | Custodial Closet across from Classroom 112                 | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113J    | Custodial Closet across from Classroom 112                 | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113B    | Maintenance Staff Storage Room across from Classroom 112   | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113B    | Maintenance Staff Storage Room across from Classroom 112   | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113B    | Maintenance Staff Storage Room across from Classroom 112   | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113B    | Maintenance Staff Storage Room across from Classroom 112   | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113B    | Maintenance Staff Storage Room across from Classroom 112   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113B    | Maintenance Staff Storage Room across from Classroom 112   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113A    | Storage Room (coats) across from Classrooms 111 and 112    | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113A    | Storage Room (coats) across from Classrooms 111 and 112    | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113A    | Storage Room (coats) across from Classrooms 111 and 112    | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113A    | Storage Room (coats) across from Classrooms 111 and 112    | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113A    | Storage Room (coats) across from Classrooms 111 and 112    | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |



|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021            | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794         | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 1                     | 113A    | Storage Room (coats) across from Classrooms 111 and 112            | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113A    | Storage Room (coats) across from Classrooms 111 and 112            | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113A    | Storage Room (coats) across from Classrooms 111 and 112            | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113A    | Storage Room (coats) across from Classrooms 111 and 112            | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113A    | Storage Room (coats) across from Classrooms 111 and 112            | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113A    | Storage Room (coats) across from Classrooms 111 and 112            | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113A    | Storage Room (coats) across from Classrooms 111 and 112            | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113H    | Storage Room (coats) across from Classrooms 111 and 112 - Restroom | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113H    | Storage Room (coats) across from Classrooms 111 and 112 - Restroom | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113H    | Storage Room (coats) across from Classrooms 111 and 112 - Restroom | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113H    | Storage Room (coats) across from Classrooms 111 and 112 - Restroom | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113H    | Storage Room (coats) across from Classrooms 111 and 112 - Restroom | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 1                     | 113H    | Storage Room (coats) across from Classrooms 111 and 112 - Restroom | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305A    | Book Storage "L" next to Classroom 305                             | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305A    | Book Storage "L" next to Classroom 305                             | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305A    | Book Storage "L" next to Classroom 305                             | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305A    | Book Storage "L" next to Classroom 305                             | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305A    | Book Storage "L" next to Classroom 305                             | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305A    | Book Storage "L" next to Classroom 305                             | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305     | Classroom 305  | Yes   | W1        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 305     | Classroom 305  | Yes   | W2        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 305     | Classroom 305  | Yes   | W3        | CMU                | Blue  | Efflorescence            | 1                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 305     | Classroom 305  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305     | Classroom 305  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305     | Classroom 305  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305CL   | Classroom 305 Front Closet   | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305CL   | Classroom 305 Front Closet   | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305CL   | Classroom 305 Front Closet   | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305CL   | Classroom 305 Front Closet   | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305CL   | Classroom 305 Front Closet   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305CL   | Classroom 305 Front Closet   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305B    | Book Storage "K" next to Classroom 305                             | Yes   | W1        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 305B    | Book Storage "K" next to Classroom 305                             | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305B    | Book Storage "K" next to Classroom 305                             | Yes   | W3        | CMU                | Beige | Efflorescence            | 2                       | 0                       | Negative                       |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 3                     | 305B    | Book Storage "K" next to Classroom 305                     | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305B    | Book Storage "K" next to Classroom 305                     | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 305B    | Book Storage "K" next to Classroom 305                     | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | S32     | Stairwell 2 near Classroom 306                             | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | S32     | Stairwell 2 near Classroom 306                             | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | S32     | Stairwell 2 near Classroom 306                             | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | S32     | Stairwell 2 near Classroom 306                             | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | S32     | Stairwell 2 near Classroom 306                             | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | S32     | Stairwell 2 near Classroom 306                             | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 306     | Classroom 306  | Yes   | W1        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 306     | Classroom 306  | Yes   | W2        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 306     | Classroom 306  | Yes   | W3        | CMU                | Blue  | Efflorescence            | 15                      | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 306     | Classroom 306  | Yes   | W4        | Drywall            | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 306     | Classroom 306  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 306     | Classroom 306  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 306A    | Classroom 306 Front Closet                                 | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 306A    | Classroom 306 Front Closet                                 | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 306A    | Classroom 306 Front Closet                                 | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 306A    | Classroom 306 Front Closet                                 | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 306A    | Classroom 306 Front Closet                                 | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 306A    | Classroom 306 Front Closet                                 | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 302     | Men's Restroom across from Classroom 306                   | Yes   | W1        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 302     | Men's Restroom across from Classroom 306                   | Yes   | W2        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 302     | Men's Restroom across from Classroom 306                   | Yes   | W3        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 302     | Men's Restroom across from Classroom 306                   | Yes   | W4        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 302     | Men's Restroom across from Classroom 306                   | Yes   | Ceiling   | Plaster            | Beige | Cracking                 | 1                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 302     | Men's Restroom across from Classroom 306                   | Yes   | Floor     | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 303     | Women's Restroom across from Classroom 306                 | Yes   | W1        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 303     | Women's Restroom across from Classroom 306                 | Yes   | W2        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 303     | Women's Restroom across from Classroom 306                 | Yes   | W3        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 303     | Women's Restroom across from Classroom 306                 | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 303     | Women's Restroom across from Classroom 306                 | Yes   | Ceiling   | Plaster            | Beige | Efflorescence            | 10                      | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 303     | Women's Restroom across from Classroom 306                 | Yes   | Floor     | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 307     | Classroom 307  | Yes   | W1        | CMU                | White | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 307     | Classroom 307  | Yes   | W2        | Drywall            | White | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 307     | Classroom 307  | Yes   | W3        | CMU                | Blue  | Efflorescence            | 10                      | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 307     | Classroom 307  | Yes   | W4        | Drywall            | White | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 307     | Classroom 307  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 307     | Classroom 307  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 307A    | Classroom 307 Front Closet                                 | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 307A    | Classroom 307 Front Closet                                 | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 307A    | Classroom 307 Front Closet                                 | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 307A    | Classroom 307 Front Closet                                 | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 307A    | Classroom 307 Front Closet                                 | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 307A    | Classroom 307 Front Closet                                 | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    |   | School District of Philadelphia           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|---|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 |   | Lead Safe Certification Assessment Report |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   |   | Hackett School                            |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component                                 | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 3                     | 308     | Classroom 308  | Yes   | W1  | CMU                | White | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 308     | Classroom 308  | Yes   | W2  | Drywall            | White | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 308     | Classroom 308  | Yes   | W3  | CMU                | Blue  | Efflorescence            | 5                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 308     | Classroom 308  | Yes   | W4  | CMU                | White | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 308     | Classroom 308  | Yes   | Ceiling                                   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 308     | Classroom 308  | Yes   | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 308A    | Classroom 308 Front Closet                                 | Yes   | W1  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 308A    | Classroom 308 Front Closet                                 | Yes   | W2  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 308A    | Classroom 308 Front Closet                                 | Yes   | W3  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 308A    | Classroom 308 Front Closet                                 | Yes   | W4  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 308A    | Classroom 308 Front Closet                                 | Yes   | Ceiling                                   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 308A    | Classroom 308 Front Closet                                 | Yes   | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 308D    | Classroom 308D   | Yes   | W1  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 308D    | Classroom 308D   | Yes   | W2  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 308D    | Classroom 308D   | Yes   | W3  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 308D    | Classroom 308D   | Yes   | W4  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 308D    | Classroom 308D   | Yes   | Ceiling                                   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 308D    | Classroom 308D   | Yes   | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | S33     | Stairwell next to Classroom 309                            | Yes   | W1  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | S33     | Stairwell next to Classroom 309                            | Yes   | W2  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | S33     | Stairwell next to Classroom 309                            | Yes   | W3  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | S33     | Stairwell next to Classroom 309                            | Yes   | W4  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | S33     | Stairwell next to Classroom 309                            | Yes   | Ceiling                                   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | S33     | Stairwell next to Classroom 309                            | Yes   | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 309A    | Storage Room "J" next to Classroom 309                     | Yes   | W1  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 309A    | Storage Room "J" next to Classroom 309                     | Yes   | W2  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 309A    | Storage Room "J" next to Classroom 309                     | Yes   | W3  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 309A    | Storage Room "J" next to Classroom 309                     | Yes   | W4  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 309A    | Storage Room "J" next to Classroom 309                     | Yes   | Ceiling                                   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 309A    | Storage Room "J" next to Classroom 309                     | Yes   | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 309     | Classroom 309  | Yes   | W1  | CMU                | White | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 309     | Classroom 309  | Yes   | W2  | CMU                | White | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 309     | Classroom 309  | Yes   | W3  | CMU                | Blue  | Flaking                  | 1                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 309     | Classroom 309  | Yes   | W4  | CMU                | White | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 3                     | 309     | Classroom 309  | Yes   | Ceiling                                   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 309     | Classroom 309  | Yes   | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 309CL   | Classroom 309 Front Closet                                 | Yes   | W1  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 309CL   | Classroom 309 Front Closet                                 | Yes   | W2  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 309CL   | Classroom 309 Front Closet                                 | Yes   | W3  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 309CL   | Classroom 309 Front Closet                                 | Yes   | W4  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 309CL   | Classroom 309 Front Closet                                 | Yes   | Ceiling                                   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | 309CL   | Classroom 309 Front Closet                                 | Yes   | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | H320    | 3rd Floor Hallway  | Yes   | W1  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | H320    | 3rd Floor Hallway  | Yes   | W2  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | H320    | 3rd Floor Hallway  | Yes   | W3  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    |   | School District of Philadelphia           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|---|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 |   | Lead Safe Certification Assessment Report |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   |   | Hackett School                            |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component                                 | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 3                     | H320    | 3rd Floor Hallway  | Yes   | W4  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | H320    | 3rd Floor Hallway  | Yes   | Ceiling                                   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 3                     | H320    | 3rd Floor Hallway  | Yes   | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 201     | Classroom 201  | Yes   | W1  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 201     | Classroom 201  | Yes   | W2  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 201     | Classroom 201  | Yes   | W3  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 201     | Classroom 201  | Yes   | W4  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 201     | Classroom 201  | Yes   | Ceiling                                   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 201     | Classroom 201  | Yes   | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 201A    | Classroom 201 Front Closet                                 | Yes   | W1  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 201A    | Classroom 201 Front Closet                                 | Yes   | W2  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 201A    | Classroom 201 Front Closet                                 | Yes   | W3  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 201A    | Classroom 201 Front Closet                                 | Yes   | W4  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 201A    | Classroom 201 Front Closet                                 | Yes   | Ceiling                                   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 201A    | Classroom 201 Front Closet                                 | Yes   | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 202     | Classroom 202  | Yes   | W1  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 202     | Classroom 202  | Yes   | W2  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 202     | Classroom 202  | Yes   | W3  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 202     | Classroom 202  | Yes   | W4  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 202     | Classroom 202  | Yes   | Ceiling                                   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 202     | Classroom 202  | Yes   | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 202A    | Classroom 202 Front Closet                                 | Yes   | W1  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 202A    | Classroom 202 Front Closet                                 | Yes   | W2  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 202A    | Classroom 202 Front Closet                                 | Yes   | W3  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 202A    | Classroom 202 Front Closet                                 | Yes   | W4  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 202A    | Classroom 202 Front Closet                                 | Yes   | Ceiling                                   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 202A    | Classroom 202 Front Closet                                 | Yes   | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 203     | Classroom 203  | Yes   | W1  | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 2L                    | 203     | Classroom 203  | Yes   | W2  | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 2L                    | 203     | Classroom 203  | Yes   | W3  | CMU                | Beige | Flaking                  | 5                       | 0                       | Negative                       |
| 5300  | 1                               | 2L                    | 203     | Classroom 203  | Yes   | W4  | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 2L                    | 203     | Classroom 203  | Yes   | Ceiling                                   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 203     | Classroom 203  | Yes   | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 203A    | Classroom 203 Front Closet                                 | Yes   | W1  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 203A    | Classroom 203 Front Closet                                 | Yes   | W2  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 203A    | Classroom 203 Front Closet                                 | Yes   | W3  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 203A    | Classroom 203 Front Closet                                 | Yes   | W4  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 203A    | Classroom 203 Front Closet                                 | Yes   | Ceiling                                   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 203A    | Classroom 203 Front Closet                                 | Yes   | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 204     | Classroom 204  | Yes   | W1  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 204     | Classroom 204  | Yes   | W2  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 204     | Classroom 204  | Yes   | W3  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 204     | Classroom 204  | Yes   | W4  | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 204     | Classroom 204  | Yes   | Ceiling                                   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 204     | Classroom 204  | Yes   | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 2L                    | 204A    | Classroom 204 Front Closet                                 | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 204A    | Classroom 204 Front Closet                                 | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 204A    | Classroom 204 Front Closet                                 | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 204A    | Classroom 204 Front Closet                                 | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 204A    | Classroom 204 Front Closet                                 | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 204A    | Classroom 204 Front Closet                                 | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205     | Classroom 205  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205     | Classroom 205  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205     | Classroom 205  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205     | Classroom 205  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205     | Classroom 205  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205     | Classroom 205  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205CL   | Classroom 205 Front Closet                                 | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205CL   | Classroom 205 Front Closet                                 | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205CL   | Classroom 205 Front Closet                                 | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205CL   | Classroom 205 Front Closet                                 | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205CL   | Classroom 205 Front Closet                                 | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205CL   | Classroom 205 Front Closet                                 | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205A    | Classroom 205A - Speech                                    | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205A    | Classroom 205A - Speech                                    | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205A    | Classroom 205A - Speech                                    | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205A    | Classroom 205A - Speech                                    | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205A    | Classroom 205A - Speech                                    | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205A    | Classroom 205A - Speech                                    | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205C    | Classroom 205A - Closet                                    | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205C    | Classroom 205A - Closet                                    | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205C    | Classroom 205A - Closet                                    | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205C    | Classroom 205A - Closet                                    | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205C    | Classroom 205A - Closet                                    | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205C    | Classroom 205A - Closet                                    | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205C    | Classroom 205A - Closet                                    | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205C    | Classroom 205A - Closet                                    | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205C    | Classroom 205A - Closet                                    | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205C    | Classroom 205A - Closet                                    | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205C    | Classroom 205A - Closet                                    | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 205C    | Classroom 205A - Closet                                    | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S22     | Stairwell next to Classroom 206                            | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S22     | Stairwell next to Classroom 206                            | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S22     | Stairwell next to Classroom 206                            | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S22     | Stairwell next to Classroom 206                            | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S22     | Stairwell next to Classroom 206                            | Yes   | Ceiling   | N/A                | N/A   | None                     | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S22     | Stairwell next to Classroom 206                            | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 206     | Classroom 206  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 206     | Classroom 206  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 206     | Classroom 206  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 206     | Classroom 206  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 206     | Classroom 206  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 206     | Classroom 206  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 206CL   | Classroom 206 Front Closet                                 | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 206CL   | Classroom 206 Front Closet                                 | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 206CL   | Classroom 206 Front Closet                                 | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |         |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|---------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |         |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |         |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color   | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 2L                    | 206CL   | Classroom 206 Front Closet                                 | Yes   | W4        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 206CL   | Classroom 206 Front Closet                                 | Yes   | Ceiling   | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 206CL   | Classroom 206 Front Closet                                 | Yes   | Floor     | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207     | Classroom 207 - Music                                      | Yes   | W1        | N/A                | N/A     | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207     | Classroom 207 - Music                                      | Yes   | W2        | N/A                | N/A     | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207     | Classroom 207 - Music                                      | Yes   | W3        | N/A                | N/A     | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207     | Classroom 207 - Music                                      | Yes   | W4        | N/A                | N/A     | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207     | Classroom 207 - Music                                      | Yes   | Ceiling   | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207     | Classroom 207 - Music                                      | Yes   | Floor     | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207CL   | Classroom 207 Closet                                       | Yes   | W1        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207CL   | Classroom 207 Closet                                       | Yes   | W2        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207CL   | Classroom 207 Closet                                       | Yes   | W3        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207CL   | Classroom 207 Closet                                       | Yes   | W4        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207CL   | Classroom 207 Closet                                       | Yes   | Ceiling   | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207CL   | Classroom 207 Closet                                       | Yes   | Floor     | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207CL   | Classroom 207 Closet                                       | Yes   | W1        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207CL   | Classroom 207 Closet                                       | Yes   | W2        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207CL   | Classroom 207 Closet                                       | Yes   | W3        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207CL   | Classroom 207 Closet                                       | Yes   | W4        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207CL   | Classroom 207 Closet                                       | Yes   | Ceiling   | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207CL   | Classroom 207 Closet                                       | Yes   | Floor     | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207A    | Boy's Restroom near Classroom 207                          | Yes   | W1        | N/A                | N/A     | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207A    | Boy's Restroom near Classroom 207                          | Yes   | W2        | N/A                | N/A     | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207A    | Boy's Restroom near Classroom 207                          | Yes   | W3        | N/A                | N/A     | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207A    | Boy's Restroom near Classroom 207                          | Yes   | W4        | N/A                | N/A     | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207A    | Boy's Restroom near Classroom 207                          | Yes   | Ceiling   | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207A    | Boy's Restroom near Classroom 207                          | Yes   | Floor     | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207A  | Pipe Chase in Boy's Restroom near Classroom 207            | No  | W1        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207A  | Pipe Chase in Boy's Restroom near Classroom 207            | No  | W2        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207A  | Pipe Chase in Boy's Restroom near Classroom 207            | No  | W3        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207A  | Pipe Chase in Boy's Restroom near Classroom 207            | No  | W4        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207A  | Pipe Chase in Boy's Restroom near Classroom 207            | No  | Ceiling   | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207A  | Pipe Chase in Boy's Restroom near Classroom 207            | No  | Floor     | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207AA   | Custodial Closet next to Boy's Restroom                    | No  | W1        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207AA   | Custodial Closet next to Boy's Restroom                    | No  | W2        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207AA   | Custodial Closet next to Boy's Restroom                    | No  | W3        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207AA   | Custodial Closet next to Boy's Restroom                    | No  | W4        | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207AA   | Custodial Closet next to Boy's Restroom                    | No  | Ceiling   | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207AA   | Custodial Closet next to Boy's Restroom                    | No  | Floor     | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207D    | Girl's Restroom near Classroom 207                         | Yes   | W1        | CMU                | Beige   | None                     | 0                       | 0.16                    | Negative                       |
| 5300  | 1                               | 2L                    | 207D    | Girl's Restroom near Classroom 207                         | Yes   | W2        | CMU                | Beige   | None                     | 0                       | 0.11                    | Negative                       |
| 5300  | 1                               | 2L                    | 207D    | Girl's Restroom near Classroom 207                         | Yes   | W3        | CMU                | Beige   | Efflorescence            | 1                       | 0.17                    | Negative                       |
| 5300  | 1                               | 2L                    | 207D    | Girl's Restroom near Classroom 207                         | Yes   | W4        | CMU                | Beige   | None                     | 0                       | 0.17                    | Negative                       |
| 5300  | 1                               | 2L                    | 207D    | Girl's Restroom near Classroom 207                         | Yes   | Ceiling   | Plaster            | Plaster | N/A                      | N/A                     | 0                       | Negative                       |
| 5300  | 1                               | 2L                    | 207D    | Girl's Restroom near Classroom 207                         | Yes   | Floor     | N/A                | N/A     | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 2L                    | PC207D  | Pipe Chase in Girl's Restroom near Classroom 207           | No  | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207D  | Pipe Chase in Girl's Restroom near Classroom 207           | No  | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207D  | Pipe Chase in Girl's Restroom near Classroom 207           | No  | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207D  | Pipe Chase in Girl's Restroom near Classroom 207           | No  | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207D  | Pipe Chase in Girl's Restroom near Classroom 207           | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207D  | Pipe Chase in Girl's Restroom near Classroom 207           | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207C    | Book Closet F near Classroom 207                           | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207C    | Book Closet F near Classroom 207                           | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207C    | Book Closet F near Classroom 207                           | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207C    | Book Closet F near Classroom 207                           | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207C    | Book Closet F near Classroom 207                           | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207C    | Book Closet F near Classroom 207                           | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207C  | Pipe Chase in Book Closet near Classroom 207               | No  | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207C  | Pipe Chase in Book Closet near Classroom 207               | No  | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207C  | Pipe Chase in Book Closet near Classroom 207               | No  | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207C  | Pipe Chase in Book Closet near Classroom 207               | No  | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207C  | Pipe Chase in Book Closet near Classroom 207               | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | PC207C  | Pipe Chase in Book Closet near Classroom 207               | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207B    | Men's Restroom near Classroom 207                          | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207B    | Men's Restroom near Classroom 207                          | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207B    | Men's Restroom near Classroom 207                          | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207B    | Men's Restroom near Classroom 207                          | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207B    | Men's Restroom near Classroom 207                          | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207B    | Men's Restroom near Classroom 207                          | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207E    | Women's Restroom near Classroom 207                        | Yes   | W1        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 2L                    | 207E    | Women's Restroom near Classroom 207                        | Yes   | W2        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 2L                    | 207E    | Women's Restroom near Classroom 207                        | Yes   | W3        | CMU                | White | Flaking                  | 4                       | 0                       | Negative                       |
| 5300  | 1                               | 2L                    | 207E    | Women's Restroom near Classroom 207                        | Yes   | W4        | CMU                | Beige | Flaking                  | 1                       | 0                       | Negative                       |
| 5300  | 1                               | 2L                    | 207E    | Women's Restroom near Classroom 207                        | Yes   | Ceiling   | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207E    | Women's Restroom near Classroom 207                        | Yes   | Floor     | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207H    | Hallway from Main Hall to Women's Restroom                 | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207H    | Hallway from Main Hall to Women's Restroom                 | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207H    | Hallway from Main Hall to Women's Restroom                 | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207H    | Hallway from Main Hall to Women's Restroom                 | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207H    | Hallway from Main Hall to Women's Restroom                 | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207H    | Hallway from Main Hall to Women's Restroom                 | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207F    | Teacher's Office next to Women's Restroom                  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207F    | Teacher's Office next to Women's Restroom                  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207F    | Teacher's Office next to Women's Restroom                  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207F    | Teacher's Office next to Women's Restroom                  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207F    | Teacher's Office next to Women's Restroom                  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207F    | Teacher's Office next to Women's Restroom                  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207G    | Copy Room for Teachers                                     | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207G    | Copy Room for Teachers                                     | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207G    | Copy Room for Teachers                                     | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 2L                    | 207G    | Copy Room for Teachers                                     | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207G    | Copy Room for Teachers                                     | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 207G    | Copy Room for Teachers                                     | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S23     | Stairwell near Classroom 208                               | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S23     | Stairwell near Classroom 208                               | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S23     | Stairwell near Classroom 208                               | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S23     | Stairwell near Classroom 208                               | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S23     | Stairwell near Classroom 208                               | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S23     | Stairwell near Classroom 208                               | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208     | Classroom 208  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208     | Classroom 208  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208     | Classroom 208  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208     | Classroom 208  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208     | Classroom 208  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208     | Classroom 208  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208B    | Classroom 208 Closet in Rear by Restroom                   | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208B    | Classroom 208 Closet in Rear by Restroom                   | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208B    | Classroom 208 Closet in Rear by Restroom                   | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208B    | Classroom 208 Closet in Rear by Restroom                   | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208B    | Classroom 208 Closet in Rear by Restroom                   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208B    | Classroom 208 Closet in Rear by Restroom                   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208A    | Classroom 208 Restroom                                     | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208A    | Classroom 208 Restroom                                     | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208A    | Classroom 208 Restroom                                     | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208A    | Classroom 208 Restroom                                     | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208A    | Classroom 208 Restroom                                     | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208A    | Classroom 208 Restroom                                     | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208A    | Classroom 208 Restroom                                     | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208A    | Classroom 208 Restroom                                     | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208A    | Classroom 208 Restroom                                     | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208A    | Classroom 208 Restroom                                     | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208A    | Classroom 208 Restroom                                     | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208A    | Classroom 208 Restroom                                     | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208C    | Classroom 208 Front Closet                                 | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208C    | Classroom 208 Front Closet                                 | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208C    | Classroom 208 Front Closet                                 | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208C    | Classroom 208 Front Closet                                 | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208C    | Classroom 208 Front Closet                                 | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 208C    | Classroom 208 Front Closet                                 | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209     | Classroom 209  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209     | Classroom 209  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209     | Classroom 209  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209     | Classroom 209  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209     | Classroom 209  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209     | Classroom 209  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |



|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 2L                    | 209B    | Classroom 209 Restroom                                     | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209B    | Classroom 209 Restroom                                     | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209B    | Classroom 209 Restroom                                     | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209B    | Classroom 209 Restroom                                     | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209B    | Classroom 209 Restroom                                     | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209B    | Classroom 209 Restroom                                     | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209A    | Classroom 209 Rear Closet by Restroom                      | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209A    | Classroom 209 Rear Closet by Restroom                      | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209A    | Classroom 209 Rear Closet by Restroom                      | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209A    | Classroom 209 Rear Closet by Restroom                      | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209A    | Classroom 209 Rear Closet by Restroom                      | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209A    | Classroom 209 Rear Closet by Restroom                      | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209C    | Classroom 209 Front Closet                                 | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209C    | Classroom 209 Front Closet                                 | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209C    | Classroom 209 Front Closet                                 | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209C    | Classroom 209 Front Closet                                 | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209C    | Classroom 209 Front Closet                                 | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 209C    | Classroom 209 Front Closet                                 | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 210     | Classroom 210  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 210     | Classroom 210  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 210     | Classroom 210  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 210     | Classroom 210  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 210     | Classroom 210  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 210     | Classroom 210  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 210A    | Classroom 210 Front Closet                                 | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 210A    | Classroom 210 Front Closet                                 | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 210A    | Classroom 210 Front Closet                                 | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 210A    | Classroom 210 Front Closet                                 | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 210A    | Classroom 210 Front Closet                                 | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 210A    | Classroom 210 Front Closet                                 | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 211     | Classroom 211  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 211     | Classroom 211  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 211     | Classroom 211  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 211     | Classroom 211  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 211     | Classroom 211  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 211     | Classroom 211  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 211A    | Classroom 211 Front Closet                                 | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 211A    | Classroom 211 Front Closet                                 | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 211A    | Classroom 211 Front Closet                                 | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 211A    | Classroom 211 Front Closet                                 | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 211A    | Classroom 211 Front Closet                                 | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 211A    | Classroom 211 Front Closet                                 | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212     | Classroom 212  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212     | Classroom 212  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212     | Classroom 212  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021       | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|---|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794    | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                      | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name   | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 2L                    | 212     | Classroom 212   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212     | Classroom 212   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212     | Classroom 212   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212CL   | Classroom 212 Front Closet                                    | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212CL   | Classroom 212 Front Closet                                    | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212CL   | Classroom 212 Front Closet                                    | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212CL   | Classroom 212 Front Closet                                    | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212CL   | Classroom 212 Front Closet                                    | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212CL   | Classroom 212 Front Closet                                    | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212B    | Psychologist's Office near Classroom 212                      | Yes   | W1        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 2L                    | 212B    | Psychologist's Office near Classroom 212                      | Yes   | W2        | CMU                | Beige | Flaking                  | 15                      | 0                       | Negative                       |
| 5300  | 1                               | 2L                    | 212B    | Psychologist's Office near Classroom 212                      | Yes   | W3        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 2L                    | 212B    | Psychologist's Office near Classroom 212                      | Yes   | W4        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 2L                    | 212B    | Psychologist's Office near Classroom 212                      | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212B    | Psychologist's Office near Classroom 212                      | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212G    | Psychologist's Office near Classroom 212 - Rear Closet        | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212G    | Psychologist's Office near Classroom 212 - Rear Closet        | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212G    | Psychologist's Office near Classroom 212 - Rear Closet        | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212G    | Psychologist's Office near Classroom 212 - Rear Closet        | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212G    | Psychologist's Office near Classroom 212 - Rear Closet        | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212G    | Psychologist's Office near Classroom 212 - Rear Closet        | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212A    | Psychologist's Office near Classroom 212 - Front Storage Room | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212A    | Psychologist's Office near Classroom 212 - Front Storage Room | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212A    | Psychologist's Office near Classroom 212 - Front Storage Room | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212A    | Psychologist's Office near Classroom 212 - Front Storage Room | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212A    | Psychologist's Office near Classroom 212 - Front Storage Room | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212A    | Psychologist's Office near Classroom 212 - Front Storage Room | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S21     | Stairwell 1 (York Street) next to Classroom 201               | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S21     | Stairwell 1 (York Street) next to Classroom 201               | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S21     | Stairwell 1 (York Street) next to Classroom 201               | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S21     | Stairwell 1 (York Street) next to Classroom 201               | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S21     | Stairwell 1 (York Street) next to Classroom 201               | Yes   | Ceiling   | N/A                | N/A   | None                     | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | S21     | Stairwell 1 (York Street) next to Classroom 201               | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | H225    | Hallway for Lower Level 2nd Floor                             | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | H225    | Hallway for Lower Level 2nd Floor                             | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021          | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794       | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 2L                    | H225    | Hallway for Lower Level 2nd Floor                                | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | H225    | Hallway for Lower Level 2nd Floor                                | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | H225    | Hallway for Lower Level 2nd Floor                                | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | H225    | Hallway for Lower Level 2nd Floor                                | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212F    | Fan Room across from Classroom 206                               | No  | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212F    | Fan Room across from Classroom 206                               | No  | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212F    | Fan Room across from Classroom 206                               | No  | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212F    | Fan Room across from Classroom 206                               | No  | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212F    | Fan Room across from Classroom 206                               | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212F    | Fan Room across from Classroom 206                               | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212E    | Storage Room across from Room 205A                               | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212E    | Storage Room across from Room 205A                               | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212E    | Storage Room across from Room 205A                               | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212E    | Storage Room across from Room 205A                               | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212E    | Storage Room across from Room 205A                               | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212E    | Storage Room across from Room 205A                               | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212D    | Storage Room "C" across from Classroom 202                       | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212D    | Storage Room "C" across from Classroom 202                       | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212D    | Storage Room "C" across from Classroom 202                       | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212D    | Storage Room "C" across from Classroom 202                       | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212D    | Storage Room "C" across from Classroom 202                       | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212D    | Storage Room "C" across from Classroom 202                       | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212C    | Fan Room 2 across from Classroom 211                             | No  | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212C    | Fan Room 2 across from Classroom 211                             | No  | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212C    | Fan Room 2 across from Classroom 211                             | No  | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212C    | Fan Room 2 across from Classroom 211                             | No  | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212C    | Fan Room 2 across from Classroom 211                             | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | 212C    | Fan Room 2 across from Classroom 211                             | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | H24     | Stairs up to 2nd Floor Upper Level near Classroom 207            | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | H24     | Stairs up to 2nd Floor Upper Level near Classroom 207            | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | H24     | Stairs up to 2nd Floor Upper Level near Classroom 207            | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | H24     | Stairs up to 2nd Floor Upper Level near Classroom 207            | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | H24     | Stairs up to 2nd Floor Upper Level near Classroom 207            | Yes   | Ceiling   | N/A                | N/A   | None                     | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2L                    | H24     | Stairs up to 2nd Floor Upper Level near Classroom 207            | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H34     | Stairs up to 3rd Floor from 2nd Floor Upper Level near Restrooms | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H34     | Stairs up to 3rd Floor from 2nd Floor Upper Level near Restrooms | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H34     | Stairs up to 3rd Floor from 2nd Floor Upper Level near Restrooms | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021          | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794       | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 2U                    | H34     | Stairs up to 3rd Floor from 2nd Floor Upper Level near Restrooms | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H34     | Stairs up to 3rd Floor from 2nd Floor Upper Level near Restrooms | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H34     | Stairs up to 3rd Floor from 2nd Floor Upper Level near Restrooms | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H34     | Stairs up to 3rd Floor from 2nd Floor Upper Level near Restrooms | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H34     | Stairs up to 3rd Floor from 2nd Floor Upper Level near Restrooms | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H34     | Stairs up to 3rd Floor from 2nd Floor Upper Level near Restrooms | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H34     | Stairs up to 3rd Floor from 2nd Floor Upper Level near Restrooms | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H34     | Stairs up to 3rd Floor from 2nd Floor Upper Level near Restrooms | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H34     | Stairs up to 3rd Floor from 2nd Floor Upper Level near Restrooms | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 223     | Custodial Closet next to Girl's Restroom                         | No  | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 223     | Custodial Closet next to Girl's Restroom                         | No  | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 223     | Custodial Closet next to Girl's Restroom                         | No  | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 223     | Custodial Closet next to Girl's Restroom                         | No  | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 223     | Custodial Closet next to Girl's Restroom                         | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 223     | Custodial Closet next to Girl's Restroom                         | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 222     | Girl's Restroom  | Yes   | W1        | CMU                | Beige | None                     | 0                       | 0.02                    | Negative                       |
| 5300  | 1                               | 2U                    | 222     | Girl's Restroom  | Yes   | W2        | CMU                | Beige | None                     | 0                       | 0.01                    | Negative                       |
| 5300  | 1                               | 2U                    | 222     | Girl's Restroom  | Yes   | W3        | CMU                | Beige | Flaking                  | 2                       | 0.06                    | Negative                       |
| 5300  | 1                               | 2U                    | 222     | Girl's Restroom  | Yes   | W4        | CMU                | Beige | None                     | 0                       | 0.04                    | Negative                       |
| 5300  | 1                               | 2U                    | 222     | Girl's Restroom  | Yes   | Ceiling   | Plaster            | Beige | Flaking                  | 30                      | 0                       | Negative                       |
| 5300  | 1                               | 2U                    | 222     | Girl's Restroom  | Yes   | Floor     | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 221     | Boy's Restroom   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 221     | Boy's Restroom   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 221     | Boy's Restroom   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 221     | Boy's Restroom   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 221     | Boy's Restroom   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 221     | Boy's Restroom   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H223    | Hallway from Boy's Restroom to Girl's Restroom                   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H223    | Hallway from Boy's Restroom to Girl's Restroom                   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H223    | Hallway from Boy's Restroom to Girl's Restroom                   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H223    | Hallway from Boy's Restroom to Girl's Restroom                   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H223    | Hallway from Boy's Restroom to Girl's Restroom                   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H223    | Hallway from Boy's Restroom to Girl's Restroom                   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | PCH223  | Pipe Chase in Hallway from Boy's Restroom to Girl's Restroom     | No  | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | PCH223  | Pipe Chase in Hallway from Boy's Restroom to Girl's Restroom     | No  | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021      | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794   | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                     | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 2U                    | PCH223  | Pipe Chase in Hallway from Boy's Restroom to Girl's Restroom | No  | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | PCH223  | Pipe Chase in Hallway from Boy's Restroom to Girl's Restroom | No  | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | PCH223  | Pipe Chase in Hallway from Boy's Restroom to Girl's Restroom | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | PCH223  | Pipe Chase in Hallway from Boy's Restroom to Girl's Restroom | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 216     | Classroom 216  | Yes   | W1        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 2U                    | 216     | Classroom 216  | Yes   | W2        | Drywall            | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 2U                    | 216     | Classroom 216  | Yes   | W3        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 2U                    | 216     | Classroom 216  | Yes   | W4        | CMU                | Beige | Flaking                  | 1                       | 0                       | Negative                       |
| 5300  | 1                               | 2U                    | 216     | Classroom 216  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 216     | Classroom 216  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 216A    | Classroom 216 Left Rear Closet                               | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 216A    | Classroom 216 Left Rear Closet                               | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 216A    | Classroom 216 Left Rear Closet                               | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 216A    | Classroom 216 Left Rear Closet                               | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 216A    | Classroom 216 Left Rear Closet                               | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 216A    | Classroom 216 Left Rear Closet                               | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 216B    | Classroom 216 Right Rear Closet                              | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 216B    | Classroom 216 Right Rear Closet                              | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 216B    | Classroom 216 Right Rear Closet                              | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 216B    | Classroom 216 Right Rear Closet                              | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 216B    | Classroom 216 Right Rear Closet                              | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 216B    | Classroom 216 Right Rear Closet                              | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 217     | Classroom 217  | Yes   | W1        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 2U                    | 217     | Classroom 217  | Yes   | W2        | CMU                | Beige | Flaking                  | 1                       | 0                       | Negative                       |
| 5300  | 1                               | 2U                    | 217     | Classroom 217  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 217     | Classroom 217  | Yes   | W4        | Drywall            | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 2U                    | 217     | Classroom 217  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 217     | Classroom 217  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 217A    | Classroom 217 Left Rear Closet                               | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 217A    | Classroom 217 Left Rear Closet                               | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 217A    | Classroom 217 Left Rear Closet                               | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 217A    | Classroom 217 Left Rear Closet                               | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 217A    | Classroom 217 Left Rear Closet                               | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 217A    | Classroom 217 Left Rear Closet                               | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 217B    | Classroom 217 Right Rear Closet                              | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 217B    | Classroom 217 Right Rear Closet                              | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 217B    | Classroom 217 Right Rear Closet                              | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 217B    | Classroom 217 Right Rear Closet                              | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 217B    | Classroom 217 Right Rear Closet                              | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 217B    | Classroom 217 Right Rear Closet                              | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 215     | Classroom 215  | Yes   | W1        | CMU                | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 2U                    | 215     | Classroom 215  | Yes   | W2        | Drywall            | Beige | None                     | 0                       | 0                       | Negative                       |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 2U                    | 215     | Classroom 215  | Yes   | W3        | CMU                | Beige | Efflorescence            | 5                       | 0                       | Negative                       |
| 5300  | 1                               | 2U                    | 215     | Classroom 215  | Yes   | W4        | Drywall            | Beige | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | 2U                    | 215     | Classroom 215  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 215     | Classroom 215  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 215A    | Classroom 215 Left Rear Closet                             | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 215A    | Classroom 215 Left Rear Closet                             | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 215A    | Classroom 215 Left Rear Closet                             | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 215A    | Classroom 215 Left Rear Closet                             | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 215A    | Classroom 215 Left Rear Closet                             | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 215A    | Classroom 215 Left Rear Closet                             | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 215B    | Classroom 215 Right Rear Closet                            | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 215B    | Classroom 215 Right Rear Closet                            | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 215B    | Classroom 215 Right Rear Closet                            | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 215B    | Classroom 215 Right Rear Closet                            | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 215B    | Classroom 215 Right Rear Closet                            | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 215B    | Classroom 215 Right Rear Closet                            | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218     | Classroom 218  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218     | Classroom 218  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218     | Classroom 218  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218     | Classroom 218  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218     | Classroom 218  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218     | Classroom 218  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218A    | Classroom 218 Left Rear Closet                             | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218A    | Classroom 218 Left Rear Closet                             | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218A    | Classroom 218 Left Rear Closet                             | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218A    | Classroom 218 Left Rear Closet                             | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218A    | Classroom 218 Left Rear Closet                             | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218A    | Classroom 218 Left Rear Closet                             | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218B    | Classroom 218 Right Rear Closet                            | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218B    | Classroom 218 Right Rear Closet                            | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218B    | Classroom 218 Right Rear Closet                            | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218B    | Classroom 218 Right Rear Closet                            | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218B    | Classroom 218 Right Rear Closet                            | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 218B    | Classroom 218 Right Rear Closet                            | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214     | Classroom 214  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214     | Classroom 214  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214     | Classroom 214  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214     | Classroom 214  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214     | Classroom 214  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214     | Classroom 214  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214A    | Classroom 214 Left Rear Closet                             | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214A    | Classroom 214 Left Rear Closet                             | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214A    | Classroom 214 Left Rear Closet                             | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214A    | Classroom 214 Left Rear Closet                             | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214A    | Classroom 214 Left Rear Closet                             | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021              | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794           | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 2U                    | 214A    | Classroom 214 Left Rear Closet                                       | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214B    | Classroom 214 Right Rear Closet                                      | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214B    | Classroom 214 Right Rear Closet                                      | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214B    | Classroom 214 Right Rear Closet                                      | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214B    | Classroom 214 Right Rear Closet                                      | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214B    | Classroom 214 Right Rear Closet                                      | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 214B    | Classroom 214 Right Rear Closet                                      | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219     | Classroom 219  | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219     | Classroom 219  | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219     | Classroom 219  | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219     | Classroom 219  | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219     | Classroom 219  | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219     | Classroom 219  | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219A    | Classroom 219 Left Rear Closet                                       | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219A    | Classroom 219 Left Rear Closet                                       | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219A    | Classroom 219 Left Rear Closet                                       | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219A    | Classroom 219 Left Rear Closet                                       | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219A    | Classroom 219 Left Rear Closet                                       | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219A    | Classroom 219 Left Rear Closet                                       | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219B    | Classroom 219 Right Rear Closet                                      | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219B    | Classroom 219 Right Rear Closet                                      | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219B    | Classroom 219 Right Rear Closet                                      | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219B    | Classroom 219 Right Rear Closet                                      | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219B    | Classroom 219 Right Rear Closet                                      | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219B    | Classroom 219 Right Rear Closet                                      | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219C    | Storage Room next to Classroom 219                                   | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219C    | Storage Room next to Classroom 219                                   | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219C    | Storage Room next to Classroom 219                                   | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219C    | Storage Room next to Classroom 219                                   | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219C    | Storage Room next to Classroom 219                                   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219C    | Storage Room next to Classroom 219                                   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219CL   | Closet within Storage Room next to Classroom 219                     | Yes   | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219CL   | Closet within Storage Room next to Classroom 219                     | Yes   | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219CL   | Closet within Storage Room next to Classroom 219                     | Yes   | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219CL   | Closet within Storage Room next to Classroom 219                     | Yes   | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219CL   | Closet within Storage Room next to Classroom 219                     | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219CL   | Closet within Storage Room next to Classroom 219                     | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219D    | Storage Room between Storage Room next to Classroom 219 and Elevator | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219D    | Storage Room between Storage Room next to Classroom 219 and Elevator | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219D    | Storage Room between Storage Room next to Classroom 219 and Elevator | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219D    | Storage Room between Storage Room next to Classroom 219 and Elevator | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021                | School District of Philadelphia             |           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-----------|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794             | Lead Safe Certification Assessment Report   |           |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer   | Hackett School                              |           |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | 2U                    | 219D    | Storage Room between Storage Room next to Classroom 219 and Elevator   | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | 219D    | Storage Room between Storage Room next to Classroom 219 and Elevator   | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | S220    | Stairs to 2nd Floor Lower Level near Elevator                          | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | S220    | Stairs to 2nd Floor Lower Level near Elevator                          | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | S220    | Stairs to 2nd Floor Lower Level near Elevator                          | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | S220    | Stairs to 2nd Floor Lower Level near Elevator                          | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | S220    | Stairs to 2nd Floor Lower Level near Elevator                          | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | S220    | Stairs to 2nd Floor Lower Level near Elevator                          | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H220    | Hallway for 2nd Floor Upper Level from Elevator to Stairs by Restrooms | Yes   | W1        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H220    | Hallway for 2nd Floor Upper Level from Elevator to Stairs by Restrooms | Yes   | W2        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H220    | Hallway for 2nd Floor Upper Level from Elevator to Stairs by Restrooms | Yes   | W3        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H220    | Hallway for 2nd Floor Upper Level from Elevator to Stairs by Restrooms | Yes   | W4        | N/A                | N/A   | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H220    | Hallway for 2nd Floor Upper Level from Elevator to Stairs by Restrooms | Yes   | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | 2U                    | H220    | Hallway for 2nd Floor Upper Level from Elevator to Stairs by Restrooms | Yes   | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | A                     | AT      | Attic  | No  | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | A                     | AT      | Attic  | No  | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | A                     | AT      | Attic  | No  | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | A                     | AT      | Attic  | No  | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | A                     | AT      | Attic  | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | A                     | AT      | Attic  | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 2       | Custodial Break Room (old office)                                      | No  | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 2       | Custodial Break Room (old office)                                      | No  | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 2       | Custodial Break Room (old office)                                      | No  | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 2       | Custodial Break Room (old office)                                      | No  | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 2       | Custodial Break Room (old office)                                      | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 2       | Custodial Break Room (old office)                                      | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 1       | Boiler Room  | No  | W1        | CMU                | Green | Flaking                  | 42                      | 0                       | Negative                       |
| 5300  | 1                               | B                     | 1       | Boiler Room  | No  | W2        | CMU                | Green | Flaking                  | 42                      | 0                       | Negative                       |
| 5300  | 1                               | B                     | 1       | Boiler Room  | No  | W3        | Concrete           | Green | Flaking                  | 42                      | 0                       | Negative                       |
| 5300  | 1                               | B                     | 1       | Boiler Room  | No  | W4        | Concrete           | Green | Flaking                  | 42                      | 0                       | Negative                       |
| 5300  | 1                               | B                     | 1       | Boiler Room  | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 1       | Boiler Room  | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 002A    | Custodial Break Room Restroom  | No  | W1        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 002A    | Custodial Break Room Restroom  | No  | W2        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 002A    | Custodial Break Room Restroom  | No  | W3        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 002A    | Custodial Break Room Restroom  | No  | W4        | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 002A    | Custodial Break Room Restroom  | No  | Ceiling   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 002A    | Custodial Break Room Restroom  | No  | Floor     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |



|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    | School District of Philadelphia             |             |                    |        |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|-------------|--------------------|--------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 | Lead Safe Certification Assessment Report   |             |                    |        |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   | Hackett School                              |             |                    |        |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component   | Substrate Material | Color  | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | B                     | 3       | Electrical Room  | No  | W1          | CMU                | Green  | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | B                     | 3       | Electrical Room  | No  | W2          | CMU                | Green  | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | B                     | 3       | Electrical Room  | No  | W3          | Concrete           | Green  | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | B                     | 3       | Electrical Room  | No  | W4          | Concrete           | Green  | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | B                     | 3       | Electrical Room  | No  | Ceiling     | Concrete           | Beige  | Flaking                  | 15                      | 0.15                    | Negative                       |
| 5300  | 1                               | B                     | 3       | Electrical Room  | No  | Floor       | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 4       | Storage Room in Boiler Room next to old Office             | No  | W1          | CMU                | Green  | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | B                     | 4       | Storage Room in Boiler Room next to old Office             | No  | W2          | CMU                | Green  | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | B                     | 4       | Storage Room in Boiler Room next to old Office             | No  | W3          | Concrete           | Green  | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | B                     | 4       | Storage Room in Boiler Room next to old Office             | No  | W4          | Concrete           | Green  | Flaking                  | 6                       | 0                       | Negative                       |
| 5300  | 1                               | B                     | 4       | Storage Room in Boiler Room next to old Office             | No  | Ceiling     | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 4       | Storage Room in Boiler Room next to old Office             | No  | Floor       | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 4       | Storage Room in Boiler Room next to old Office             | No  | Incinerator | Metal              | Silver | Flaking                  | 5                       | 0                       | Negative                       |
| 5300  | 1                               | B                     | S02     | Stairs to Boiler Room                                      | No  | W1          | CMU                | Green  | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | B                     | S02     | Stairs to Boiler Room                                      | No  | W2          | Concrete           | Green  | Flaking                  | 25                      | 0                       | Negative                       |
| 5300  | 1                               | B                     | S02     | Stairs to Boiler Room                                      | No  | W3          | CMU                | Green  | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | B                     | S02     | Stairs to Boiler Room                                      | No  | W4          | CMU                | Green  | None                     | 0                       | 0                       | Negative                       |
| 5300  | 1                               | B                     | S02     | Stairs to Boiler Room                                      | No  | Ceiling     | Concrete           | Green  | Flaking                  | 9                       | 0.02                    | Negative                       |
| 5300  | 1                               | B                     | S02     | Stairs to Boiler Room                                      | No  | Floor       | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 6       | Hallway from Crawlspace to Elevator Mechanical Room        | No  | W1          | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 6       | Hallway from Crawlspace to Elevator Mechanical Room        | No  | W2          | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 6       | Hallway from Crawlspace to Elevator Mechanical Room        | No  | W3          | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 6       | Hallway from Crawlspace to Elevator Mechanical Room        | No  | W4          | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 6       | Hallway from Crawlspace to Elevator Mechanical Room        | No  | Ceiling     | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 6       | Hallway from Crawlspace to Elevator Mechanical Room        | No  | Floor       | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 6A      | Elevator Mechanical Room                                   | No  | W1          | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 6A      | Elevator Mechanical Room                                   | No  | W2          | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 6A      | Elevator Mechanical Room                                   | No  | W3          | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 6A      | Elevator Mechanical Room                                   | No  | W4          | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 6A      | Elevator Mechanical Room                                   | No  | Ceiling     | N/A                | N/A    | None                     | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 6A      | Elevator Mechanical Room                                   | No  | Floor       | N/A                | N/A    | N/A                      | 0                       | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 5       | Unknown Room in Crawl Space                                | No  | W1          | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 5       | Unknown Room in Crawl Space                                | No  | W2          | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 5       | Unknown Room in Crawl Space                                | No  | W3          | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 5       | Unknown Room in Crawl Space                                | No  | W4          | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 5       | Unknown Room in Crawl Space                                | No  | Ceiling     | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | B                     | 5       | Unknown Room in Crawl Space                                | No  | Floor       | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | C                     | CS      | Crawl Space accessible by Mezz/Boiler Room                 | No  | W1          | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | C                     | CS      | Crawl Space accessible by Mezz/Boiler Room                 | No  | W2          | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | C                     | CS      | Crawl Space accessible by Mezz/Boiler Room                 | No  | W3          | N/A                | N/A    | N/A                      | N/A                     | N/A                     | N/A                            |

|       |                                 |                       |         | Inspection Dates: December 9, 2021 to December 13, 2021    |   | School District of Philadelphia           |                    |       |                          |                         |                         |                                |
|-------|---------------------------------|-----------------------|---------|--|---|---|--------------------|-------|--------------------------|-------------------------|-------------------------|--------------------------------|
|       |                                 |                       |         | Inspector Name and Certificate Number: Kevin Rumbol 006794 |   | Lead Safe Certification Assessment Report |                    |       |                          |                         |                         |                                |
|       |                                 |                       |         | Inspection Company: Acer                                   |   | Hackett School                            |                    |       |                          |                         |                         |                                |
| ULCS# | E<br>l<br>e<br>m<br>e<br>n<br>t | F<br>l<br>o<br>o<br>r | Space # | On-Site Room Name  | Student/<br>Teacher<br>Occupied<br>(yes/no) | Component                                 | Substrate Material | Color | Description of<br>Damage | Damage<br>Quantity (sf) | XRF Reading<br>(mg/cm2) | XRF<br>(positive/<br>negative) |
| 5300  | 1                               | C                     | CS      | Crawl Space accessible by Mezz/Boiler Room                 | No  | W4  | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | C                     | CS      | Crawl Space accessible by Mezz/Boiler Room                 | No  | Ceiling                                   | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |
| 5300  | 1                               | C                     | CS      | Crawl Space accessible by Mezz/Boiler Room                 | No  | Floor                                     | N/A                | N/A   | N/A                      | N/A                     | N/A                     | N/A                            |