

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	A	ATTIC1	Attic	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	A	ATTIC1	Attic	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	A	ATTIC1	Attic	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	A	ATTIC1	Attic	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	A	ATTIC1	Attic	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	A	ATTIC1	Attic	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	EX	Exterior	Exterior Play Deck	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	EX	Exterior	Exterior Play Deck	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	EX	Exterior	Exterior Play Deck	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	EX	Exterior	Exterior Play Deck	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	EX	Exterior	Exterior Play Deck	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	EX	Exterior	Exterior Play Deck	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	002B	Boiler Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	002B	Boiler Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	002B	Boiler Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	002B	Boiler Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	002B	Boiler Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	002B	Boiler Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Office 2 ( Main Office Area)	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Office 2 ( Main Office Area)	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Office 2 ( Main Office Area)	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Office 2 ( Main Office Area)	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Office 2 ( Main Office Area)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Office 2 ( Main Office Area)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C4	Classroom C-1	Yes	W1	DRYWALL	BEIGE	PEELING	5	0	Negative
5350	1	1	0C4	Classroom C-1	Yes	W2	DRYWALL	BEIGE	PEELING	5	0	Negative
5350	1	1	0C4	Classroom C-1	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C4	Classroom C-1	Yes	W4	DRYWALL	BEIGE	PEELING	5	0	Negative
5350	1	1	0C4	Classroom C-1	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C4	Classroom C-1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C4	Classroom C-1	Yes	DOOR CASING	METAL	BROWN	PEELING	5	0	Negative
5350	1	1	0C4	Classroom C-1	Yes	DOOR CASING	METAL	BEIGE	PEELING	5	0.14	Negative
5350	1	1	125	Gymnasium Storage	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	125	Gymnasium Storage	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	125	Gymnasium Storage	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	125	Gymnasium Storage	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	125	Gymnasium Storage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	125	Gymnasium Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	105	Custodial Storage Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	105	Custodial Storage Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	105	Custodial Storage Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	105	Custodial Storage Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	105	Custodial Storage Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	105	Custodial Storage Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	003	Classroom 3	Yes	W1	CMU	BEIGE	None	0	0	Negative

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	003	Classroom 3	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	003	Classroom 3	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	003	Classroom 3	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	003	Classroom 3	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	003	Classroom 3	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	003	Classroom 3	Yes	DOOR CASING	METAL	BROWN	None	0	0	Negative
5350	1	1	003	Classroom 3	Yes	DOOR	WOOD	BEIGE	None	0	0	Negative
5350	1	1	NP1	Classroom 3 Storage/ Kitchen	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP1	Classroom 3 Storage/ Kitchen	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP1	Classroom 3 Storage/ Kitchen	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP1	Classroom 3 Storage/ Kitchen	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP1	Classroom 3 Storage/ Kitchen	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP1	Classroom 3 Storage/ Kitchen	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05B	Rear Foyer	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05B	Rear Foyer	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05B	Rear Foyer	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05B	Rear Foyer	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05B	Rear Foyer	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05B	Rear Foyer	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05B	Rear Foyer	Yes	DOOR CASING1	METAL	BROWN	PEELING	2	0.01	Negative
5350	1	1	H05B	Rear Foyer	Yes	DOOR1	METAL	BROWN	PEELING	48	0	Negative
5350	1	1	H05B	Rear Foyer	Yes	DOOR3	METAL	BROWN	PEELING	48	0	Negative
5350	1	1	H05B	Rear Foyer	Yes	DOOR CASING3	METAL	BROWN	PEELING	2	0	Negative
5350	1	1	H05	Hallway at Auditorium	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05	Hallway at Auditorium	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05	Hallway at Auditorium	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05	Hallway at Auditorium	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05	Hallway at Auditorium	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05	Hallway at Auditorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	Lob1	Lobby	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	Lob1	Lobby	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	Lob1	Lobby	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	Lob1	Lobby	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	Lob1	Lobby	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	Lob1	Lobby	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	Lob1	Lobby	Yes	DOOR CASING1	METAL	BROWN	PEELING	2	0	Negative
5350	1	1	Lob1	Lobby	Yes	DOOR1	METAL	BROWN	PEELING	2	0	Negative
5350	1	1	Lob1	Lobby	Yes	DOOR3	METAL	BROWN	PEELING	2	0	Negative
5350	1	1	Lob1	Lobby	Yes	DOOR CASING3	METAL	BROWN	PEELING	2	0	Negative
5350	1	1	111A	Family Center	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	111A	Family Center	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	111A	Family Center	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	111A	Family Center	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	111A	Family Center	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	111A	Family Center	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	113A	Family Center Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	113A	Family Center Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	113A	Family Center Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	113A	Family Center Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	113A	Family Center Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	113A	Family Center Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	112A	Family Center Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	112A	Family Center Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	112A	Family Center Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	112A	Family Center Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	112A	Family Center Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	112A	Family Center Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	S101	Stairwell to Basement	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	S101	Stairwell to Basement	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	S101	Stairwell to Basement	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	S101	Stairwell to Basement	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	S101	Stairwell to Basement	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	S101	Stairwell to Basement	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H03	Hallway from Lobby to Music Room	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H03	Hallway from Lobby to Music Room	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H03	Hallway from Lobby to Music Room	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H03	Hallway from Lobby to Music Room	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H03	Hallway from Lobby to Music Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H03	Hallway from Lobby to Music Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H03	Hallway from Lobby to Music Room	Yes	DOOR CASING	METAL	BROWN	PEELING	2	0.1	Negative
5350	1	1	H03	Hallway from Lobby to Music Room	Yes	DOOR	METAL	BROWN	PEELING	2	1	Positive
5350	1	1	H13	Hallway from Library to Computer Room	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H13	Hallway from Library to Computer Room	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H13	Hallway from Library to Computer Room	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H13	Hallway from Library to Computer Room	Yes	W4	DRYWALL	ORANGE	PEELING	2	0	Negative
5350	1	1	H13	Hallway from Library to Computer Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H13	Hallway from Library to Computer Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	147	Boy's Restroom adjacent Hallway "D"	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	147	Boy's Restroom adjacent Hallway "D"	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	147	Boy's Restroom adjacent Hallway "D"	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	147	Boy's Restroom adjacent Hallway "D"	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	147	Boy's Restroom adjacent Hallway "D"	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	147	Boy's Restroom adjacent Hallway "D"	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	147	Boy's Restroom adjacent Hallway "D"	Yes	DOOR CASING	METAL	BROWN	PEELING	2	0.11	Negative
5350	1	1	149	Girl's Restroom adjacent Hallway "D"	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	149	Girl's Restroom adjacent Hallway "D"	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	149	Girl's Restroom adjacent Hallway "D"	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	149	Girl's Restroom adjacent Hallway "D"	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	149	Girl's Restroom adjacent Hallway "D"	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	149	Girl's Restroom adjacent Hallway "D"	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HD	Hallway "D"	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HD	Hallway "D"	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HD	Hallway "D"	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HD	Hallway "D"	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HD	Hallway "D"	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HD	Hallway "D"	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0D4	Classroom D-1	Yes	W1	DRYWALL	BEIGE	PEELING	6	0	Negative
5350	1	1	0D4	Classroom D-1	Yes	W1	DRYWALL	GRAY	PEELING	6	0	Negative
5350	1	1	0D4	Classroom D-1	Yes	W1	DRYWALL	PURPLE	PEELING	6	0	Negative
5350	1	1	0D4	Classroom D-1	Yes	W2	DRYWALL	PURPLE	None	0	0	Negative
5350	1	1	0D4	Classroom D-1	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0D4	Classroom D-1	Yes	W4	DRYWALL	GRAY	None	0	0	Negative
5350	1	1	0D4	Classroom D-1	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0D4	Classroom D-1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0D3	Classroom D-2	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0D3	Classroom D-2	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0D3	Classroom D-2	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0D3	Classroom D-2	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0D3	Classroom D-2	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0D3	Classroom D-2	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0D3	Classroom D-2	Yes	DOOR CASING	METAL	BROWN	PEELING	2	0	Negative
5350	1	1	0D2	Classroom D-3	Yes	W1	DRYWALL	PURPLE	PEELING	3	0	Negative
5350	1	1	0D2	Classroom D-3	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0D2	Classroom D-3	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0D2	Classroom D-3	Yes	W4	DRYWALL	PURPLE	None	0	0	Negative
5350	1	1	0D2	Classroom D-3	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0D2	Classroom D-3	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0D2	Classroom D-3	Yes	DOOR CASING	METAL	BROWN	PEELING	3	0	Negative
5350	1	1	0D2	Classroom D-3	Yes	DOOR CASING	METAL	BROWN	INTACT	N/A	0	Negative
5350	1	1	0D2	Classroom D-3	Yes	DOOR	METAL	BROWN	PEELING	8	0	Negative
5350	1	1	0D2	Classroom D-3	Yes	RADIATOR	METAL	BEIGE	PEELING	40	0.01	Negative
5350	1	1	0D1	Classroom D-4	Yes	W1	CMU	BEIGE	INTACT	N/A	0	Negative
5350	1	1	0D1	Classroom D-4	Yes	W1	DRYWALL	BEIGE	PEELING	2	0	Negative
5350	1	1	0D1	Classroom D-4	Yes	W2	DRYWALL	BEIGE	PEELING	2	0	Negative
5350	1	1	0D1	Classroom D-4	Yes	W3	CMU	BEIGE	PEELING	2	0.18	Negative
5350	1	1	0D1	Classroom D-4	Yes	W3	CMU	BEIGE	INTACT	N/A	0.16	Negative
5350	1	1	0D1	Classroom D-4	Yes	W4	DRYWALL	BEIGE	PEELING	2	0	Negative
5350	1	1	0D1	Classroom D-4	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0D1	Classroom D-4	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	0D1	Classroom D-4	Yes	DOOR CASING	METAL	BROWN	PEELING	6	0	Negative
5350	1	1	0D1	Classroom D-4	Yes	DOOR CASING	METAL	BEIGE	PEELING	6	0.2	Negative
5350	1	1	0D1	Classroom D-4	Yes	WINDOW CASING	METAL	BEIGE	PEELING	6	0.06	Negative
5350	1	1	152	Classroom D-4 Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	152	Classroom D-4 Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	152	Classroom D-4 Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	152	Classroom D-4 Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	152	Classroom D-4 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	152	Classroom D-4 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	151	Classroom D-0	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	151	Classroom D-0	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	151	Classroom D-0	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	151	Classroom D-0	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	151	Classroom D-0	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	151	Classroom D-0	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	153	Art Room (Currently Offices). CCTC Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	153	Art Room (Currently Offices). CCTC Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	153	Art Room (Currently Offices). CCTC Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	153	Art Room (Currently Offices). CCTC Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	153	Art Room (Currently Offices). CCTC Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	153	Art Room (Currently Offices). CCTC Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	153A	Art Room Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	153A	Art Room Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	153A	Art Room Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	153A	Art Room Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	153A	Art Room Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	153A	Art Room Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HB	Hallway "B"	Yes	W1	DRYWALL	BEIGE	None	0	0	Negative
5350	1	1	HB	Hallway "B"	Yes	W2	DRYWALL	BEIGE	None	0	0	Negative
5350	1	1	HB	Hallway "B"	Yes	W3	DRYWALL	BEIGE	None	0	0	Negative
5350	1	1	HB	Hallway "B"	Yes	W4	DRYWALL	BEIGE	None	0	0	Negative
5350	1	1	HB	Hallway "B"	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HB	Hallway "B"	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	155	Classroom B-0	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	155	Classroom B-0	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	155	Classroom B-0	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	155	Classroom B-0	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	155	Classroom B-0	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	155	Classroom B-0	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B4	Classroom B-1	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B4	Classroom B-1	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B4	Classroom B-1	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B4	Classroom B-1	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B4	Classroom B-1	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	0B4	Classroom B-1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B4	Classroom B-1	Yes	DOOR CASING	METAL	BLUE	PEELING	2	0	Negative
5350	1	1	0B4	Classroom B-1	Yes	DOOR CASING	METAL	BROWN	PEELING	2	0	Negative
5350	1	1	0B4	Classroom B-1	Yes	RADIATOR	METAL	BEIGE	None	0	0	Negative
5350	1	1	0B4	Classroom B-1	Yes	DOOR	METAL	BROWN	None	0	0.01	Negative
5350	1	1	154	Classroom B-1 Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	154	Classroom B-1 Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	154	Classroom B-1 Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	154	Classroom B-1 Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	154	Classroom B-1 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	154	Classroom B-1 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	154	Classroom B-1 Closet	Yes	DOOR CASING	METAL	BLUE	PEELING	2	0.13	Negative
5350	1	1	0B3	Classroom B-2	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B3	Classroom B-2	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B3	Classroom B-2	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B3	Classroom B-2	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B3	Classroom B-2	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B3	Classroom B-2	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B3	Classroom B-2	Yes	DOOR CASING1	METAL	BROWN	PEELING	2	0	Negative
5350	1	1	0B3	Classroom B-2	Yes	RADIATOR3	METAL	BEIGE	None	0	0	Negative
5350	1	1	0B3	Classroom B-2	Yes	DOOR4	METAL	BROWN	PEELING	8	0	Negative
5350	1	1	0B2	Classroom B-3	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B2	Classroom B-3	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B2	Classroom B-3	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B2	Classroom B-3	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B2	Classroom B-3	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B2	Classroom B-3	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0B2	Classroom B-3	Yes	DOOR CASING	METAL	BROWN	PEELING	2	0	Negative
5350	1	1	B4	Classroom B-4	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	B4	Classroom B-4	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	B4	Classroom B-4	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	B4	Classroom B-4	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	B4	Classroom B-4	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	B4	Classroom B-4	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	B4	Classroom B-4	Yes	DOOR CASING	METAL	BROWN	PEELING	2	0	Negative
5350	1	1	10	Classroom 10	Yes	W1	CMU	BEIGE	None	0	0	Negative
5350	1	1	10	Classroom 10	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	10	Classroom 10	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	10	Classroom 10	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	10	Classroom 10	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	10	Classroom 10	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	10	Classroom 10	Yes	DOOR CASING	METAL	BROWN	PEELING	2	0.11	Negative
5350	1	1	142	Women's Restroom adjacent Hallway "B"	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	142	Women's Restroom adjacent Hallway "B"	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	142	Women's Restroom adjacent Hallway "B"	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	142	Women's Restroom adjacent Hallway "B"	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	142	Women's Restroom adjacent Hallway "B"	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	142	Women's Restroom adjacent Hallway "B"	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	130	Cafeteria	Yes	W1	DRYWALL	ORANGE	PEELING	3	0	Negative
5350	1	1	130	Cafeteria	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	130	Cafeteria	Yes	W3	DRYWALL	YELLOW	PEELING	3	0	Negative
5350	1	1	130	Cafeteria	Yes	W4	DRYWALL	RED	PEELING	3	0	Negative
5350	1	1	130	Cafeteria	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	130	Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HA	Hallway "A"	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HA	Hallway "A"	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HA	Hallway "A"	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HA	Hallway "A"	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HA	Hallway "A"	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HA	Hallway "A"	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A4	Classroom A-1	Yes	W1	DRYWALL	BEIGE	PEELING	4	0	Negative
5350	1	1	0A4	Classroom A-1	Yes	W2	DRYWALL	BEIGE	None	0	0	Negative
5350	1	1	0A4	Classroom A-1	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A4	Classroom A-1	Yes	W4	DRYWALL	BEIGE	None	0	0	Negative
5350	1	1	0A4	Classroom A-1	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A4	Classroom A-1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A3	Classroom A-2	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A3	Classroom A-2	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A3	Classroom A-2	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A3	Classroom A-2	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A3	Classroom A-2	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A3	Classroom A-2	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A3	Classroom A-2	Yes	DOOR CASING	METAL	BROWN	None	0	0	Negative
5350	1	1	0A2	Classroom A-3	Yes	W1	DRYWALL	BEIGE	PEELING	10	0	Negative
5350	1	1	0A2	Classroom A-3	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A2	Classroom A-3	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A2	Classroom A-3	Yes	W4	DRYWALL	BEIGE	PEELING	1	0	Negative
5350	1	1	0A2	Classroom A-3	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A2	Classroom A-3	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A2	Classroom A-3	Yes	TRIM	DRYWALL	BEIGE	None	0	0	Negative
5350	1	1	0A2	Classroom A-3	Yes	DOOR CASING	METAL	BROWN	None	0	0	Negative
5350	1	1	0A1	Classroom A-4	Yes	W1	DRYWALL	BEIGE	PEELING	1	0	Negative
5350	1	1	0A1	Classroom A-4	Yes	W2	DRYWALL	BEIGE	PEELING	1	0	Negative
5350	1	1	0A1	Classroom A-4	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A1	Classroom A-4	Yes	W4	DRYWALL	BEIGE	PEELING	1	0	Negative
5350	1	1	0A1	Classroom A-4	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A1	Classroom A-4	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0A1	Classroom A-4	Yes	DOOR CASING	METAL	BROWN	PEELING	2	0	Negative

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	0A1	Classroom A-4	Yes	DOOR CASING	METAL	BEIGE	PEELING	2	0.23	Negative
5350	1	1	115	Classroom A-4 Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	115	Classroom A-4 Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	115	Classroom A-4 Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	115	Classroom A-4 Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	115	Classroom A-4 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	115	Classroom A-4 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	116	Classroom A-0	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	116	Classroom A-0	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	116	Classroom A-0	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	116	Classroom A-0	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	116	Classroom A-0	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	116	Classroom A-0	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	116	Classroom A-0	Yes	DOOR CASING	METAL	BROWN	PEELING	3	0.13	Negative
5350	1	1	HC	Hallway "C"	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HC	Hallway "C"	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HC	Hallway "C"	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HC	Hallway "C"	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HC	Hallway "C"	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	HC	Hallway "C"	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	111	Classroom C-0	Yes	W1	CMU	BROWN	PEELING	50	0.29	Negative
5350	1	1	111	Classroom C-0	Yes	W2	CMU	BROWN	PEELING	50	0.24	Negative
5350	1	1	111	Classroom C-0	Yes	W3	CMU	BROWN	PEELING	50	0.4	Negative
5350	1	1	111	Classroom C-0	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	111	Classroom C-0	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	111	Classroom C-0	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	111	Classroom C-0	Yes	DOOR CASING	METAL	BROWN	None	0	0.06	Negative
5350	1	1	112	Classroom C-1 Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	112	Classroom C-1 Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	112	Classroom C-1 Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	112	Classroom C-1 Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	112	Classroom C-1 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	112	Classroom C-1 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C3	Classroom C-2	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C3	Classroom C-2	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C3	Classroom C-2	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C3	Classroom C-2	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C3	Classroom C-2	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C3	Classroom C-2	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C2	Classroom C-3	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C2	Classroom C-3	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C2	Classroom C-3	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C2	Classroom C-3	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C2	Classroom C-3	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A



				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	0C2	Classroom C-3	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C2	Classroom C-3	Yes	DOOR CASING	METAL	BROWN	PEELING	2	0	Negative
5350	1	1	0C1	Classroom C-4	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C1	Classroom C-4	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C1	Classroom C-4	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C1	Classroom C-4	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C1	Classroom C-4	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0C1	Classroom C-4	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	109	Girl's Restroom adjacent Hallway "C"	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	109	Girl's Restroom adjacent Hallway "C"	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	109	Girl's Restroom adjacent Hallway "C"	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	109	Girl's Restroom adjacent Hallway "C"	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	109	Girl's Restroom adjacent Hallway "C"	Yes	Ceiling	PLASTER	WHITE	PEELING	20	0	Negative
5350	1	1	109	Girl's Restroom adjacent Hallway "C"	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107	Boy's Restroom adjacent Hallway "C"	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107	Boy's Restroom adjacent Hallway "C"	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107	Boy's Restroom adjacent Hallway "C"	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107	Boy's Restroom adjacent Hallway "C"	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107	Boy's Restroom adjacent Hallway "C"	Yes	Ceiling	PLASTER	WHITE	PEELING	10	0	Negative
5350	1	1	107	Boy's Restroom adjacent Hallway "C"	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	106	Kitchen Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	106	Kitchen Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	106	Kitchen Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	106	Kitchen Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	106	Kitchen Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	106	Kitchen Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102	Staff Lounge	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102	Staff Lounge	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102	Staff Lounge	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102	Staff Lounge	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102	Staff Lounge	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102	Staff Lounge	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Staff Restroom adjacent Staff Lounge ( Near Gymnasium)	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Staff Restroom adjacent Staff Lounge ( Near Gymnasium)	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Staff Restroom adjacent Staff Lounge ( Near Gymnasium)	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Staff Restroom adjacent Staff Lounge ( Near Gymnasium)	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Staff Restroom adjacent Staff Lounge ( Near Gymnasium)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Staff Restroom adjacent Staff Lounge ( Near Gymnasium)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	009	Classroom 9 (Art Studio)	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	009	Classroom 9 (Art Studio)	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	009	Classroom 9 (Art Studio)	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	009	Classroom 9 (Art Studio)	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	009	Classroom 9 (Art Studio)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	009	Classroom 9 (Art Studio)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	009	Classroom 9 (Art Studio)	Yes	DOOR CASING	METAL	BEIGE	PEELING	4	0.15	Negative
5350	1	1	008	Classroom 8 (Austic Support Room)	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	008	Classroom 8 (Austic Support Room)	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	008	Classroom 8 (Austic Support Room)	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	008	Classroom 8 (Austic Support Room)	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	008	Classroom 8 (Austic Support Room)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	008	Classroom 8 (Austic Support Room)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H14	Hallway from Auditorium to Custodial Storage Room	Yes	W1	CMU	BLUE	PEELING	1	0	Negative
5350	1	1	H14	Hallway from Auditorium to Custodial Storage Room	Yes	W2	DRYWALL	YELLOW	PEELING	1	0	Negative
5350	1	1	H14	Hallway from Auditorium to Custodial Storage Room	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H14	Hallway from Auditorium to Custodial Storage Room	Yes	W4	DRYWALL	ORANGE	PEELING	1	0	Negative
5350	1	1	H14	Hallway from Auditorium to Custodial Storage Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H14	Hallway from Auditorium to Custodial Storage Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	126	Gymnasium	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	126	Gymnasium	Yes	W2	WOOD	BLUE	PEELING	4	0	Negative
5350	1	1	126	Gymnasium	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	126	Gymnasium	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	126	Gymnasium	Yes	Ceiling	WOOD	BEIGE	None	0	0	Negative
5350	1	1	126	Gymnasium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	126	Gymnasium	Yes	BEAM1	METAL	RED	PEELING	50	0.01	Negative
5350	1	1	126	Gymnasium	Yes	BEAM3	METAL	RED	PEELING	50	0.03	Negative
5350	1	1	122	Gymnasium Boy's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	122	Gymnasium Boy's Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	122	Gymnasium Boy's Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	122	Gymnasium Boy's Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	122	Gymnasium Boy's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	122	Gymnasium Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	124	Physical Education Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	124	Physical Education Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	124	Physical Education Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	124	Physical Education Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	124	Physical Education Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	124	Physical Education Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	121	Gymnasium Girl's Room	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	121	Gymnasium Girl's Room	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	121	Gymnasium Girl's Room	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	121	Gymnasium Girl's Room	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	121	Gymnasium Girl's Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	121	Gymnasium Girl's Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	145	Computer Room 12	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	145	Computer Room 12	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	145	Computer Room 12	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	145	Computer Room 12	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	145	Computer Room 12	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	145	Computer Room 12	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	145	Computer Room 12	Yes	DOOR CASING	METAL	BROWN	PEELING	2	0.1	Negative
5350	1	1	H16A	IMC (Library)	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H16A	IMC (Library)	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H16A	IMC (Library)	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H16A	IMC (Library)	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H16A	IMC (Library)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H16A	IMC (Library)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	133	IMC (Library) Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	133	IMC (Library) Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	133	IMC (Library) Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	133	IMC (Library) Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	133	IMC (Library) Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	133	IMC (Library) Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	Ampitheater	IMC (Library) Ampitheater	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	Ampitheater	IMC (Library) Ampitheater	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	Ampitheater	IMC (Library) Ampitheater	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	Ampitheater	IMC (Library) Ampitheater	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	Ampitheater	IMC (Library) Ampitheater	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	Ampitheater	IMC (Library) Ampitheater	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	132A	IMC (Library) Office 1	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	132A	IMC (Library) Office 1	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	132A	IMC (Library) Office 1	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	132A	IMC (Library) Office 1	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	132A	IMC (Library) Office 1	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	132A	IMC (Library) Office 1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	132B	IMC (Library) Office 2	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	132B	IMC (Library) Office 2	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	132B	IMC (Library) Office 2	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	132B	IMC (Library) Office 2	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	132B	IMC (Library) Office 2	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	132B	IMC (Library) Office 2	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0M2	Classroom M-2	Yes	W1	CMU	BROWN	None	0	0	Negative
5350	1	1	0M2	Classroom M-2	Yes	W2	CMU	BROWN	None	0	0	Negative
5350	1	1	0M2	Classroom M-2	Yes	W3	CMU	BROWN	None	0	0	Negative
5350	1	1	0M2	Classroom M-2	Yes	W4	CMU	BROWN	PEELING	1	0	Negative
5350	1	1	0M2	Classroom M-2	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0M2	Classroom M-2	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	0M2	Classroom M-2	Yes	DOOR CASING	METAL	GRAY	PEELING	2	0.11	Negative
5350	1	1	0M2	Classroom M-2	Yes	DUCT	METAL	BEIGE	PEELING	1	0.04	Negative

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	097A	Office 7	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	097A	Office 7	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	097A	Office 7	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	097A	Office 7	Yes	W4	CMU	BEIGE	PEELING	2	0	Negative
5350	1	1	097A	Office 7	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	097A	Office 7	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	098A	Office 6	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	098A	Office 6	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	098A	Office 6	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	098A	Office 6	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	098A	Office 6	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	098A	Office 6	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	104A	Office 5	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	104A	Office 5	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	104A	Office 5	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	104A	Office 5	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	104A	Office 5	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	104A	Office 5	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	099A	Main Office Reception Area	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	099A	Main Office Reception Area	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	099A	Main Office Reception Area	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	099A	Main Office Reception Area	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	099A	Main Office Reception Area	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	099A	Main Office Reception Area	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	100A	Office 4	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	100A	Office 4	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	100A	Office 4	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	100A	Office 4	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	100A	Office 4	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	100A	Office 4	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	101A	Office 3 (Assistant Principals Office)	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	101A	Office 3 (Assistant Principals Office)	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	101A	Office 3 (Assistant Principals Office)	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	101A	Office 3 (Assistant Principals Office)	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	101A	Office 3 (Assistant Principals Office)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	101A	Office 3 (Assistant Principals Office)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Office 2 ( Main Office Area) School Police	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Office 2 ( Main Office Area) School Police	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Office 2 ( Main Office Area) School Police	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Office 2 ( Main Office Area) School Police	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Office 2 ( Main Office Area) School Police	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	102A	Office 2 ( Main Office Area) School Police	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	103A	Office 1	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	103A	Office 1	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	103A	Office 1	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	103A	Office 1	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	103A	Office 1	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	103A	Office 1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	108A	Main Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	108A	Main Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	108A	Main Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	108A	Main Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	108A	Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	108A	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	108A	Main Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	108A	Main Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	108A	Main Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	108A	Main Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	108A	Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	108A	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107A	Principal's Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107A	Principal's Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107A	Principal's Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107A	Principal's Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107A	Principal's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107A	Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107B	Principal's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107B	Principal's Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107B	Principal's Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107B	Principal's Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107B	Principal's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107B	Principal's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05A	Hallway from Classrooms 1 to 3	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05A	Hallway from Classrooms 1 to 3	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05A	Hallway from Classrooms 1 to 3	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05A	Hallway from Classrooms 1 to 3	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05A	Hallway from Classrooms 1 to 3	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H05A	Hallway from Classrooms 1 to 3	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP12	Women's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP12	Women's Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP12	Women's Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP12	Women's Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP12	Women's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP12	Women's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	001	Classroom 1	Yes	W1	CMU	BROWN	None	0	0.05	Negative
5350	1	1	001	Classroom 1	Yes	W2	CMU	BEIGE	None	0	0	Negative
5350	1	1	001	Classroom 1	Yes	W2	CMU	BROWN	None	0	-0.22	Negative
5350	1	1	001	Classroom 1	Yes	W3	CMU	BROWN	None	0	0.01	Negative

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	001	Classroom 1	Yes	W4	CMU	BROWN	PEELING	1	0.03	Negative
5350	1	1	001	Classroom 1	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	001	Classroom 1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	001	Classroom 1	Yes	HATCH4	METAL	BEIGE	None	0	0	Negative
5350	1	1	NP7	Classroom 1 Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP7	Classroom 1 Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP7	Classroom 1 Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP7	Classroom 1 Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP7	Classroom 1 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP7	Classroom 1 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP8	Classroom 1 Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP8	Classroom 1 Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP8	Classroom 1 Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP8	Classroom 1 Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP8	Classroom 1 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP8	Classroom 1 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	002	Classroom 2	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	002	Classroom 2	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	002	Classroom 2	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	002	Classroom 2	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	002	Classroom 2	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	002	Classroom 2	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP4	Classroom 2 Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP4	Classroom 2 Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP4	Classroom 2 Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP4	Classroom 2 Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP4	Classroom 2 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP4	Classroom 2 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP3	Classroom 2 Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP3	Classroom 2 Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP3	Classroom 2 Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP3	Classroom 2 Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP3	Classroom 2 Restroom	Yes	Ceiling	PLASTER	WHITE	None	0	0.02	Negative
5350	1	1	NP3	Classroom 2 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP10	Classroom 2 Storage	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP10	Classroom 2 Storage	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP10	Classroom 2 Storage	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP10	Classroom 2 Storage	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP10	Classroom 2 Storage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP10	Classroom 2 Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP9	Classroom 3 Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP9	Classroom 3 Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP9	Classroom 3 Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP9	Classroom 3 Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	NP9	Classroom 3 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP9	Classroom 3 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP2	Classroom 3 Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP2	Classroom 3 Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP2	Classroom 3 Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP2	Classroom 3 Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP2	Classroom 3 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP2	Classroom 3 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	004	Classroom 4	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	004	Classroom 4	Yes	W2	CMU	BROWN	None	0	0	Negative
5350	1	1	004	Classroom 4	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	004	Classroom 4	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	004	Classroom 4	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	004	Classroom 4	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP11	Classroom 4 Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP11	Classroom 4 Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP11	Classroom 4 Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP11	Classroom 4 Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP11	Classroom 4 Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP11	Classroom 4 Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP6	Classroom 4 Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP6	Classroom 4 Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP6	Classroom 4 Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP6	Classroom 4 Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP6	Classroom 4 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP6	Classroom 4 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP5	Classroom 4 Storage	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP5	Classroom 4 Storage	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP5	Classroom 4 Storage	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP5	Classroom 4 Storage	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP5	Classroom 4 Storage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	NP5	Classroom 4 Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H04	Hallway from Auditorium to Classroom 6	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H04	Hallway from Auditorium to Classroom 6	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H04	Hallway from Auditorium to Classroom 6	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H04	Hallway from Auditorium to Classroom 6	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H04	Hallway from Auditorium to Classroom 6	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	H04	Hallway from Auditorium to Classroom 6	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	005	Classroom 5	Yes	W1	CMU	BROWN	PEELING	3	0	Negative
5350	1	1	005	Classroom 5	Yes	W2	CMU	WHITE	None	0	0	Negative
5350	1	1	005	Classroom 5	Yes	W3	CMU	WHITE	PEELING	6	0	Negative
5350	1	1	005	Classroom 5	Yes	W4	CMU	WHITE	PEELING	200	0	Negative
5350	1	1	005	Classroom 5	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	005	Classroom 5	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	005	Classroom 5	Yes	CEILING HATCH	METAL	WHITE	None	0	0	Negative
5350	1	1	005	Classroom 5	Yes	DOOR CASING	METAL	BROWN	None	0	0.15	Negative
5350	1	1	006	Classroom 6	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	006	Classroom 6	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	006	Classroom 6	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	006	Classroom 6	Yes	W4	CMU	BEIGE	None	0	0	Negative
5350	1	1	006	Classroom 6	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	006	Classroom 6	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	006B	Classroom 6 Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	006B	Classroom 6 Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	006B	Classroom 6 Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	006B	Classroom 6 Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	006B	Classroom 6 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	006B	Classroom 6 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	005B	Classroom 5 Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	005B	Classroom 5 Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	005B	Classroom 5 Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	005B	Classroom 5 Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	005B	Classroom 5 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	005B	Classroom 5 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	OM1	Music Room 1	Yes	W1	CMU	BROWN	None	0	0	Negative
5350	1	1	OM1	Music Room 1	Yes	W2	CMU	BROWN	None	0	0	Negative
5350	1	1	OM1	Music Room 1	Yes	W3	CMU	BROWN	PEELING	1	0	Negative
5350	1	1	OM1	Music Room 1	Yes	W4	CMU	BROWN	None	0	0	Negative
5350	1	1	OM1	Music Room 1	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	OM1	Music Room 1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	OM1	Music Room 1	Yes	DOOR CASING	METAL	BROWN	PEELING	2	0.05	Negative
5350	1	1	095A	Auditorium	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	095A	Auditorium	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	095A	Auditorium	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	095A	Auditorium	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	095A	Auditorium	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	095A	Auditorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	095A	Auditorium	Yes	SOFFIT1	DRYWALL	BEIGE	PEELING	16	0	Negative
5350	1	1	095A	Auditorium	Yes	SOFFIT2	DRYWALL	BEIGE	PEELING	16	0	Negative
5350	1	1	095A	Auditorium	Yes	SOFFIT3	DRYWALL	BEIGE	PEELING	16	0	Negative
5350	1	1	095A	Auditorium	Yes	SOFFIT4	DRYWALL	BEIGE	PEELING	16	0	Negative
5350	1	1	095A	Auditorium	Yes	DOOR CASING1	METAL	BROWN	PEELING	2	0.08	Negative
5350	1	1	095A	Auditorium	Yes	DOOR CASING2	METAL	BROWN	PEELING	2	0.07	Negative
5350	1	1	095A	Auditorium	Yes	DOOR CASING3	METAL	BROWN	PEELING	2	0.07	Negative



				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	095A	Auditorium	Yes	DOOR CASING4	METAL	BROWN	PEELING	2	0.07	Negative
5350	1	B	006B	Electrical Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	006B	Electrical Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	006B	Electrical Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	006B	Electrical Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	006B	Electrical Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	006B	Electrical Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	S01	Boiler Room Stairs	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	S01	Boiler Room Stairs	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	S01	Boiler Room Stairs	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	S01	Boiler Room Stairs	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	S01	Boiler Room Stairs	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	S01	Boiler Room Stairs	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	S01	Boiler Room Stairs	Yes	DOOR1	METAL	BROWN	None	0	0	Negative
5350	1	B	S01	Boiler Room Stairs	Yes	DOOR CASING1	METAL	BROWN	None	0	0	Negative
5350	1	B	S01	Boiler Room Stairs	Yes	RADIATOR1	METAL	BROWN	None	0	0.12	Negative
5350	1	B	S01	Boiler Room Stairs	Yes	STAIRS RAILING1	METAL	BROWN	None	0	0.13	Negative
5350	1	B	S01	Boiler Room Stairs	Yes	STAIRS RAILING2	METAL	BROWN	None	0	0.3	Negative
5350	1	B	S01	Boiler Room Stairs	Yes	LADDER2	METAL	GRAY	None	0	0.06	Negative
5350	1	B	S01	Boiler Room Stairs	Yes	DOOR2	METAL	BROWN	None	0	0.04	Negative
5350	1	B	S01	Boiler Room Stairs	Yes	DOOR CASING2	METAL	BROWN	None	0	0.23	Negative
5350	1	B	S01	Boiler Room Stairs	Yes	STAIRS RAILING4	METAL	BROWN	None	0	0.25	Negative
5350	1	B	S01	Boiler Room Stairs	Yes	STAIRS NEWEL POST4	METAL	BROWN	None	0	0.14	Negative
5350	1	B	004B	Building Engineer's Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	004B	Building Engineer's Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	004B	Building Engineer's Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	004B	Building Engineer's Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	004B	Building Engineer's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	004B	Building Engineer's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	H01	Boiler Room Storage	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	H01	Boiler Room Storage	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	H01	Boiler Room Storage	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	H01	Boiler Room Storage	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	H01	Boiler Room Storage	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	H01	Boiler Room Storage	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	007B	Parking Garage	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	007B	Parking Garage	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	007B	Parking Garage	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	007B	Parking Garage	No	W4	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	B	007B	Parking Garage	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	007B	Parking Garage	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	H02	Garage Exit Ramp	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	H02	Garage Exit Ramp	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	H02	Garage Exit Ramp	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	H02	Garage Exit Ramp	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	H02	Garage Exit Ramp	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	H02	Garage Exit Ramp	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	S02	Boiler Stairs to Outdoors	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	S02	Boiler Stairs to Outdoors	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	S02	Boiler Stairs to Outdoors	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	S02	Boiler Stairs to Outdoors	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	S02	Boiler Stairs to Outdoors	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	B	S02	Boiler Stairs to Outdoors	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	063B	Nurse's Office	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	063B	Nurse's Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	063B	Nurse's Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	063B	Nurse's Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	063B	Nurse's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	063B	Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	063B	Nurse's Office	Yes	DOOR	METAL	BEIGE	PEELING	8	0	Negative
5350	1	1	063B	Nurse's Office	Yes	DOOR CASING	METAL	BEIGE	PEELING	2	0	Negative
5350	1	1	067A	Nurse's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	067A	Nurse's Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	067A	Nurse's Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	067A	Nurse's Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	067A	Nurse's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	067A	Nurse's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	067A	Nurse's Restroom	Yes	DOOR CASING	METAL	BROWN	PEELING	2	0	Negative
5350	1	1	067A	Nurse's Restroom	Yes	WALL HATCH	METAL	BEIGE	PEELING	2	0	Negative
5350	1	1	068A	Nurse's Examination Room	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	068A	Nurse's Examination Room	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	068A	Nurse's Examination Room	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	068A	Nurse's Examination Room	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	068A	Nurse's Examination Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	068A	Nurse's Examination Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	068A	Nurse's Examination Room	Yes	DOOR CASING	METAL	BEIGE	PEELING	2	0	Negative
5350	1	1	065A	Nurse's Closet	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	065A	Nurse's Closet	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	065A	Nurse's Closet	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	065A	Nurse's Closet	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	065A	Nurse's Closet	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	065A	Nurse's Closet	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	065A	Nurse's Closet	Yes	DOOR CASING	METAL	BEIGE	PEELING	2	0	Negative

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5350	1	1	063A	Nurse's Storage	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	063A	Nurse's Storage	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	063A	Nurse's Storage	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	063A	Nurse's Storage	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	063A	Nurse's Storage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	063A	Nurse's Storage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	063A	Nurse's Storage	Yes	DOOR CASING	METAL	BEIGE	PEELING	3	0	Negative
5350	1	1	064A	Nurse's Examination Room 2	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	064A	Nurse's Examination Room 2	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	064A	Nurse's Examination Room 2	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	064A	Nurse's Examination Room 2	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	064A	Nurse's Examination Room 2	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	064A	Nurse's Examination Room 2	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	064A	Nurse's Examination Room 2	Yes	DOOR CASING	METAL	BEIGE	PEELING	2	0	Negative
5350	1	1	064A	Nurse's Examination Room 2	Yes	DOOR CASING	METAL	BROWN	PEELING	2	0.02	Negative
5350	1	1	135	Men's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	135	Men's Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	135	Men's Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	135	Men's Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	135	Men's Restroom	Yes	Ceiling	PLASTER	WHITE	PEELING	120	0	Negative
5350	1	1	135	Men's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	135	Men's Restroom	Yes	STALL	METAL	BLUE	PEELING	5	0.23	Negative
5350	1	1	007	Teacher's Lounge	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	007	Teacher's Lounge	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	007	Teacher's Lounge	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	007	Teacher's Lounge	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	007	Teacher's Lounge	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	007	Teacher's Lounge	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	134	Custodial Closet outside Hallway A	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	134	Custodial Closet outside Hallway A	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	134	Custodial Closet outside Hallway A	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	134	Custodial Closet outside Hallway A	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	134	Custodial Closet outside Hallway A	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	134	Custodial Closet outside Hallway A	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	134	Custodial Closet outside Hallway A	No	HATCH	METAL	BEIGE	PEELING	4	0.01	Negative
5350	1	1	140	Custodial Closet outside Hallway B	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	140	Custodial Closet outside Hallway B	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	140	Custodial Closet outside Hallway B	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	140	Custodial Closet outside Hallway B	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	140	Custodial Closet outside Hallway B	No	Ceiling	PLASTER	WHITE	PEELING	4	0	Negative
5350	1	1	140	Custodial Closet outside Hallway B	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	140	Custodial Closet outside Hallway B	No	CEILING HATCH	METAL	WHITE	PEELING	4	0	Negative
5350	1	1	146	Men's Restroom adjacent Hallway D	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	146	Men's Restroom adjacent Hallway D	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/01/2021		School District of Philadelphia						
				Inspector Name and Certificate Number: Matthew DePalma, 005098		Lead Safe Certification Assessment Report						
				Inspection Company: ACER Associates LLC		McKinley School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
5350	1	1	146	Men's Restroom adjacent Hallway D	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	146	Men's Restroom adjacent Hallway D	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	146	Men's Restroom adjacent Hallway D	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	146	Men's Restroom adjacent Hallway D	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	148	Women's Restroom adjacent Hallway D	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	148	Women's Restroom adjacent Hallway D	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	148	Women's Restroom adjacent Hallway D	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	148	Women's Restroom adjacent Hallway D	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	148	Women's Restroom adjacent Hallway D	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	148	Women's Restroom adjacent Hallway D	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	148	Women's Restroom adjacent Hallway D	Yes	DOOR CASING	METAL	GRAY	None	0	0.1	Negative
5350	1	1	107A	Custodial Closet outside Hallway C ( Near Gymnasium)	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107A	Custodial Closet outside Hallway C ( Near Gymnasium)	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107A	Custodial Closet outside Hallway C ( Near Gymnasium)	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107A	Custodial Closet outside Hallway C ( Near Gymnasium)	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107A	Custodial Closet outside Hallway C ( Near Gymnasium)	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
5350	1	1	107A	Custodial Closet outside Hallway C ( Near Gymnasium)	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A