

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	S105	Stairwell by Classroom 105	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	S105	Stairwell by Classroom 105	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	S105	Stairwell by Classroom 105	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	S105	Stairwell by Classroom 105	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	S105	Stairwell by Classroom 105	Yes	Door	Metal	Blue	Chipping	2	Positive
8440	1	1	S105	Stairwell by Classroom 105	Yes	Door Frame	Metal	Blue	Chipping	1	Positive
8440	1	1	S105	Stairwell by Classroom 105	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	S105	Stairwell by Classroom 105	Yes	Ceiling	Metal	White	Moisture Damage	5	Negative
8440	1	1	S105	Stairwell by Classroom 105	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	S105	Stairwell by Classroom 105	Yes	Railing	Metal	White	Chipping	2	Negative
8440	1	1	S105	Stairwell by Classroom 105	Yes	Stair Riser	Concrete	Gray	Cracking, Chipping	6	Negative
8440	1	1	S117	Stairwell by IMC 117	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	S117	Stairwell by IMC 117	Yes	Door	Wood	Blue	Chipping	4	Negative
8440	1	1	S117	Stairwell by IMC 117	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	1	S117	Stairwell by IMC 117	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	S117	Stairwell by IMC 117	Yes	Baseboard	Concrete Masonry Unit	Gray	Chipping, Friction	10	Negative
8440	1	1	S117	Stairwell by IMC 117	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	S117	Stairwell by IMC 117	Yes	Door	Metal	Blue	Chipping	3	Positive
8440	1	1	S117	Stairwell by IMC 117	Yes	Door Frame	Metal	Blue	Chipping	2	Positive
8440	1	1	S117	Stairwell by IMC 117	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	S117	Stairwell by IMC 117	Yes	Ceiling	Metal	White	Moisture Damage, Chipping	5	Negative
8440	1	1	S117	Stairwell by IMC 117	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	S117	Stairwell by IMC 117	Yes	Railing	Metal	White	Chipping	2	Negative
8440	1	1	S117	Stairwell by IMC 117	Yes	Stair Stringer	Metal	White	Chipping, Friction	3	Negative
8440	1	1	S111	Stairwell by Classroom 111	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	S111	Stairwell by Classroom 111	Yes	Door	Metal	Blue	Chipping	1	Negative
8440	1	1	S111	Stairwell by Classroom 111	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	S111	Stairwell by Classroom 111	Yes	Baseboard	Concrete Masonry Unit	Gray	Chipping	10	Negative
8440	1	1	S111	Stairwell by Classroom 111	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	S111	Stairwell by Classroom 111	Yes	Door	Metal	Blue	Chipping	1	Positive
8440	1	1	S111	Stairwell by Classroom 111	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	S111	Stairwell by Classroom 111	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	S111	Stairwell by Classroom 111	Yes	Ceiling	Metal	White	Chipping, Flaking	4	Negative
8440	1	1	S111	Stairwell by Classroom 111	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	S111	Stairwell by Classroom 111	Yes	Stair Riser	Metal	Gray	Chipping	60	Negative
8440	1	1	S111	Stairwell by Classroom 111	Yes	Railing	Metal	White	Chipping	4	Negative
8440	1	1	S111	Stairwell by Classroom 111	Yes	Stair Stringer	Metal	White	Chipping	1	Negative
8440	1	1	S110	Stairwell by Classroom 110	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	S110	Stairwell by Classroom 110	Yes	Door	Metal	Blue	Chipping	5	Negative
8440	1	1	S110	Stairwell by Classroom 110	Yes	Door Frame	Metal	Blue	Chipping	2	Negative

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	S110	Stairwell by Classroom 110	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	S110	Stairwell by Classroom 110	Yes	Baseboard	Concrete Masonry Unit	Gray	Chipping, Flaking	5	Negative
8440	1	1	S110	Stairwell by Classroom 110	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	S110	Stairwell by Classroom 110	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	S110	Stairwell by Classroom 110	Yes	Ceiling	Metal	White	Chipping, Moisture Damage	10	Negative
8440	1	1	S110	Stairwell by Classroom 110	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	S110	Stairwell by Classroom 110	Yes	Railing	Metal	White	Chipping	5	Negative
8440	1	1	S110	Stairwell by Classroom 110	Yes	Stair Riser	Metal	Gray	Chipping	4	Negative
8440	1	1	S110	Stairwell by Classroom 110	Yes	Stair Stringer	Metal	Gray	Chipping	3	Negative
8440	1	1	S110X	Vestibule to Stairwell by Classroom 110	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	S110X	Vestibule to Stairwell by Classroom 110	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	S110X	Vestibule to Stairwell by Classroom 110	Yes	Door	Metal	Blue	Chipping	5	Negative
8440	1	1	S110X	Vestibule to Stairwell by Classroom 110	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	1	S110X	Vestibule to Stairwell by Classroom 110	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	S110X	Vestibule to Stairwell by Classroom 110	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	S110X	Vestibule to Stairwell by Classroom 110	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	S110X	Vestibule to Stairwell by Classroom 110	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	SPK1	Stairwell (to Pre-K A and B Sections)	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	SPK1	Stairwell (to Pre-K A and B Sections)	Yes	Door	Metal	Blue	Chipping	2	Negative
8440	1	1	SPK1	Stairwell (to Pre-K A and B Sections)	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	SPK1	Stairwell (to Pre-K A and B Sections)	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	SPK1	Stairwell (to Pre-K A and B Sections)	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	SPK1	Stairwell (to Pre-K A and B Sections)	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	SPK1	Stairwell (to Pre-K A and B Sections)	Yes	Door	Metal	Blue	Chipping	2	Positive
8440	1	1	SPK1	Stairwell (to Pre-K A and B Sections)	Yes	Door Frame	Metal	Blue	Chipping	1	Positive
8440	1	1	SPK1	Stairwell (to Pre-K A and B Sections)	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	SPK1	Stairwell (to Pre-K A and B Sections)	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	SPK1	Stairwell (to Pre-K A and B Sections)	Yes	Stair Riser	Concrete	Gray	Friction, Chipping	5	Negative
8440	1	1	SPK1	Stairwell (to Pre-K A and B Sections)	Yes	Stair Stringer	Metal	Gray	Chipping	1	Negative
8440	1	1	SPK1	Stairwell (to Pre-K A and B Sections)	Yes	Railing	Metal	White	Chipping	2	Negative
8440	1	1	SPK1	Stairwell (to Pre-K A and B Sections)	Yes	Stair Riser	Metal	Gray	Chipping	1	Positive
8440	1	1	100A	Girl's Restroom across from Classroom 100	Yes	W1	Concrete Masonry Unit	White, Blue	None	0	N/A
8440	1	1	100A	Girl's Restroom across from Classroom 100	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	100A	Girl's Restroom across from Classroom 100	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	100A	Girl's Restroom across from Classroom 100	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	100A	Girl's Restroom across from Classroom 100	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	100A	Girl's Restroom across from Classroom 100	Yes	Door	Metal	Gray	Chipping	1	Negative
8440	1	1	100A	Girl's Restroom across from Classroom 100	Yes	Door Frame	Metal	Blue	Moisture Damage, Chipping	10	Positive
8440	1	1	100A	Girl's Restroom across from Classroom 100	Yes	W4	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	100A	Girl's Restroom across from Classroom 100	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	100A	Girl's Restroom across from Classroom 100	Yes	Floor	Concrete	Gray	Chipping, Friction	4	Negative
8440	1	1	100A	Girl's Restroom across from Classroom 100	Yes	Stair Riser	Concrete	Gray	None	0	N/A
8440	1	1	100B	Boy's Restroom next to Classroom 101	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	100B	Boy's Restroom next to Classroom 101	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	100B	Boy's Restroom next to Classroom 101	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	100B	Boy's Restroom next to Classroom 101	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	100B	Boy's Restroom next to Classroom 101	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	100B	Boy's Restroom next to Classroom 101	Yes	Door	Metal	Blue	Moisture Damage, Friction, Chipping	20	Positive
8440	1	1	100B	Boy's Restroom next to Classroom 101	Yes	Door Frame	Metal	Blue	Moisture Damage, Friction, Chipping	5	Positive
8440	1	1	100B	Boy's Restroom next to Classroom 101	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	100B	Boy's Restroom next to Classroom 101	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	100B	Boy's Restroom next to Classroom 101	Yes	Floor	Concrete	Gray	Chipping, Friction	15	Negative
8440	1	1	100	Classroom 100	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	100	Classroom 100	Yes	Door	Wood	Blue	Chipping	5	Negative
8440	1	1	100	Classroom 100	Yes	Door Frame	Metal	Blue	Chipping	5	Negative
8440	1	1	100	Classroom 100	Yes	Door Panel	Wood	Blue	Chipping	3	Negative
8440	1	1	100	Classroom 100	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	100	Classroom 100	Yes	Sink Cabinet	Metal	Pink	Chipping	1	Negative
8440	1	1	100	Classroom 100	Yes	Coat Rack	Wood	White	Chipping	6	Negative
8440	1	1	100	Classroom 100	Yes	Shelf Support	Metal	White	Chipping	3	Negative
8440	1	1	100	Classroom 100	Yes	Support Post	Metal	Blue	Chipping	2	Positive
8440	1	1	100	Classroom 100	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	100	Classroom 100	Yes	Univent	Metal	Blue	Chipping	1	Negative
8440	1	1	100	Classroom 100	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	100	Classroom 100	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	100	Classroom 100	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	102	Classroom 102	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	102	Classroom 102	Yes	Door	Wood	Blue	Chipping	2	Negative
8440	1	1	102	Classroom 102	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	102	Classroom 102	Yes	Door Panel	Wood	Blue	Chipping	2	Negative
8440	1	1	102	Classroom 102	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	102	Classroom 102	Yes	Sink Cabinet	Metal	Pink	Chipping	1	Negative
8440	1	1	102	Classroom 102	Yes	Support Post	Metal	Blue	Chipping	1	Positive
8440	1	1	102	Classroom 102	Yes	Closet	Metal	Pink	Chipping	1	Negative
8440	1	1	102	Classroom 102	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	102	Classroom 102	Yes	Radiator	Metal	Blue	Chipping	1	Negative
8440	1	1	102	Classroom 102	Yes	Univent	Metal	Blue	Chipping	1	Negative
8440	1	1	102	Classroom 102	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	102	Classroom 102	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	102	Classroom 102	Yes	Floor	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	101	Classroom 101	Yes	W1	Drywall	White	Chipping	1	Negative
8440	1	1	101	Classroom 101	Yes	Door	Wood	Blue	Chipping	5	Negative
8440	1	1	101	Classroom 101	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	1	101	Classroom 101	Yes	Door Panel	Wood	Blue	Chipping	2	Negative
8440	1	1	101	Classroom 101	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	101	Classroom 101	Yes	Sink Cabinet	Metal	Pink	Chipping	1	Negative
8440	1	1	101	Classroom 101	Yes	Support Post	Metal	Tan	Chipping	1	Positive
8440	1	1	101	Classroom 101	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	101	Classroom 101	Yes	Radiator	Metal	Blue	Chipping	1	Negative
8440	1	1	101	Classroom 101	Yes	Univent	Metal	Blue	Chipping	3	Negative
8440	1	1	101	Classroom 101	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	101	Classroom 101	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	101	Classroom 101	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	101B	Classroom 101 Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	101B	Classroom 101 Restroom	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	101B	Classroom 101 Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	101B	Classroom 101 Restroom	Yes	W3	Drywall	White	Chipping	1	Negative
8440	1	1	101B	Classroom 101 Restroom	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	101B	Classroom 101 Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	101B	Classroom 101 Restroom	Yes	Floor	Concrete	Green	Friction, Chipping	4	Negative
8440	1	1	103	Classroom 103	Yes	W1	Drywall	Teal	Chipping	1	Negative
8440	1	1	103	Classroom 103	Yes	Door	Wood	Blue	Chipping	2	Negative
8440	1	1	103	Classroom 103	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	1	103	Classroom 103	Yes	Door Panel	Wood	Blue	Chipping	2	Negative
8440	1	1	103	Classroom 103	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	103	Classroom 103	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	103	Classroom 103	Yes	Univent	Metal	Blue	Chipping	2	Negative
8440	1	1	103	Classroom 103	Yes	Radiator	Metal	Blue	Chipping	2	Negative
8440	1	1	103	Classroom 103	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	103	Classroom 103	Yes	Sink Cabinet	Metal	Pink	Chipping	1	Negative
8440	1	1	103	Classroom 103	Yes	Coat Rack	Wood	White	Chipping	5	Negative
8440	1	1	103	Classroom 103	Yes	Shelf	Metal	White	Chipping	2	Negative
8440	1	1	103	Classroom 103	Yes	Shelf Support	Metal	White	Chipping	3	Negative
8440	1	1	103	Classroom 103	Yes	Support Post	Metal	Blue	Chipping	1	Positive
8440	1	1	103	Classroom 103	Yes	Closet Door	Metal	Pink	Chipping	2	Negative
8440	1	1	103	Classroom 103	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	103	Classroom 103	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	103B	Classroom 103 Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	103B	Classroom 103 Restroom	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	103B	Classroom 103 Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	103B	Classroom 103 Restroom	Yes	W3	Drywall	White	Flaking	1	Negative
8440	1	1	103B	Classroom 103 Restroom	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	103B	Classroom 103 Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	103B	Classroom 103 Restroom	Yes	Floor	Concrete	Green	Friction	4	Negative
8440	1	1	104	Classroom 104	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	104	Classroom 104	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	104	Classroom 104	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	104	Classroom 104	Yes	Door Panel	Wood	Blue	Chipping	1	Negative
8440	1	1	104	Classroom 104	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	104	Classroom 104	Yes	Support Post	Metal	Green	Chipping	1	Positive
8440	1	1	104	Classroom 104	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	104	Classroom 104	Yes	Radiator	Metal	Blue	Chipping	1	Negative
8440	1	1	104	Classroom 104	Yes	Univent	Metal	Blue	Chipping	1	Negative
8440	1	1	104	Classroom 104	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	104	Classroom 104	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	104	Classroom 104	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	104B	Hallway Storage adjacent to Classroom 104	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	104B	Hallway Storage adjacent to Classroom 104	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	104B	Hallway Storage adjacent to Classroom 104	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	1	104B	Hallway Storage adjacent to Classroom 104	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	104B	Hallway Storage adjacent to Classroom 104	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	104B	Hallway Storage adjacent to Classroom 104	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	104B	Hallway Storage adjacent to Classroom 104	Yes	Pipe	Metal	White	Chipping	1	Negative
8440	1	1	104B	Hallway Storage adjacent to Classroom 104	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	104B	Hallway Storage adjacent to Classroom 104	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	104A	Hallway Storage (Washer/Dryer)	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	104A	Hallway Storage (Washer/Dryer)	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	104A	Hallway Storage (Washer/Dryer)	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	104A	Hallway Storage (Washer/Dryer)	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	104A	Hallway Storage (Washer/Dryer)	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	104A	Hallway Storage (Washer/Dryer)	Yes	Pipes	Metal	Beige	Chipping	1	Negative
8440	1	1	104A	Hallway Storage (Washer/Dryer)	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	104A	Hallway Storage (Washer/Dryer)	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	104A	Hallway Storage (Washer/Dryer)	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	112	Classroom 112	Yes	W1	N/A	White	Chipping, Flaking	15	Negative
8440	1	1	112	Classroom 112	Yes	Sink Cabinet	Metal	Pink	Moisture Damage, Friction	2	Negative
8440	1	1	112	Classroom 112	Yes	W2	Concrete Masonry Unit	White	Chipping, Flaking	1	Negative
8440	1	1	112	Classroom 112	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	112	Classroom 112	Yes	Radiator	Metal	Blue	Chipping, Friction	4	Negative
8440	1	1	112	Classroom 112	Yes	Univent	Metal	Blue	Chipping, Friction	3	Negative
8440	1	1	112	Classroom 112	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	112	Classroom 112	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	112	Classroom 112	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	121	Nurse's Office	Yes	W1	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
8440	1	1	121	Nurse's Office	Yes	Door	Metal	Blue	Chipping	1	Negative
8440	1	1	121	Nurse's Office	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	121	Nurse's Office	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	121	Nurse's Office	Yes	Radiator	Metal	Blue	Chipping, Friction	1	Negative
8440	1	1	121	Nurse's Office	Yes	Univent	Metal	Blue	Chipping, Friction	1	Negative
8440	1	1	121	Nurse's Office	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	121	Nurse's Office	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	121	Nurse's Office	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	121XA	Bathroom in Nurse's Office	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	121XA	Bathroom in Nurse's Office	Yes	Door Frame	Metal	Tan	Chipping	1	Negative
8440	1	1	121XA	Bathroom in Nurse's Office	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	121XA	Bathroom in Nurse's Office	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	121XA	Bathroom in Nurse's Office	Yes	Radiator	Metal	Blue	Moisture Damage, Friction	3	Negative
8440	1	1	121XA	Bathroom in Nurse's Office	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	121XA	Bathroom in Nurse's Office	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	121XA	Bathroom in Nurse's Office	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	121XB	Storage Closet in Nurse's Office	Yes	W1	No Access	No Access	No Access	No Access	No Access
8440	1	1	121XB	Storage Closet in Nurse's Office	Yes	W2	No Access	No Access	No Access	No Access	No Access
8440	1	1	121XB	Storage Closet in Nurse's Office	Yes	W3	No Access	No Access	No Access	No Access	No Access
8440	1	1	121XB	Storage Closet in Nurse's Office	Yes	W4	No Access	No Access	No Access	No Access	No Access
8440	1	1	121XB	Storage Closet in Nurse's Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access
8440	1	1	121XB	Storage Closet in Nurse's Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access
8440	1	1	123A	Counselor Office #1 (Hallway Side)	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	123A	Counselor Office #1 (Hallway Side)	Yes	Door	Metal	Blue	Chipping	1	Negative
8440	1	1	123A	Counselor Office #1 (Hallway Side)	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	123A	Counselor Office #1 (Hallway Side)	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	123A	Counselor Office #1 (Hallway Side)	Yes	Radiator	Metal	Blue	Chipping	1	Negative
8440	1	1	123A	Counselor Office #1 (Hallway Side)	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	123A	Counselor Office #1 (Hallway Side)	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	123A	Counselor Office #1 (Hallway Side)	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	123B	Vice Principal's Office #1 (Hallway Side)	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	123B	Vice Principal's Office #1 (Hallway Side)	Yes	Door	Metal	Blue	Chipping	1	Negative
8440	1	1	123B	Vice Principal's Office #1 (Hallway Side)	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	123B	Vice Principal's Office #1 (Hallway Side)	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	123B	Vice Principal's Office #1 (Hallway Side)	Yes	Radiator	Metal	Blue	Chipping	1	Negative
8440	1	1	123B	Vice Principal's Office #1 (Hallway Side)	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	123B	Vice Principal's Office #1 (Hallway Side)	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	123B	Vice Principal's Office #1 (Hallway Side)	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	123C	Special Education Manager Office #3 (Closest to Nurse's Office)	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	123C	Special Education Manager Office #3 (Closest to Nurse's Office)	Yes	Door	Metal	Blue	Chipping	1	Negative

				2/7 - 2/16/22	<b>Lead Safe Certification Assessment Report</b>						
				Inspector Name and Certificate Number: Charles Rhodes 003542	<b>Loesche School</b>						
				Inspection Company: Batta	<b>595 Tomlinson Rd, Philadelphia, PA 19116</b>						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	123C	Special Education Manager Office #3 (Closest to Nurse's Office)	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	123C	Special Education Manager Office #3 (Closest to Nurse's Office)	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	123C	Special Education Manager Office #3 (Closest to Nurse's Office)	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	123C	Special Education Manager Office #3 (Closest to Nurse's Office)	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	123C	Special Education Manager Office #3 (Closest to Nurse's Office)	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	123	Main Office	Yes	W1	Drywall	Teal	Friction	3	Negative
8440	1	1	123	Main Office	Yes	Door	Metal	White	Chipping	2	Negative
8440	1	1	123	Main Office	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	123	Main Office	Yes	W3	Drywall	Yellow	Chipping, Flaking	1	Negative
8440	1	1	123	Main Office	Yes	Radiator	Metal	Blue	Chipping, Friction	1	Negative
8440	1	1	123	Main Office	Yes	Univent	Metal	Blue	Chipping, Friction	1	Negative
8440	1	1	123	Main Office	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	123	Main Office	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	123	Main Office	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	125B	Main Office Storage (IT MDF Room)	Yes	W1	No Access	No Access	No Access	No Access	No Access
8440	1	1	125B	Main Office Storage (IT MDF Room)	Yes	Door	Wood	Tan	Chipping	2	Negative
8440	1	1	125B	Main Office Storage (IT MDF Room)	Yes	Door Frame	Metal	Tan	Chipping	1	Negative
8440	1	1	125B	Main Office Storage (IT MDF Room)	Yes	W2	No Access	No Access	No Access	No Access	No Access
8440	1	1	125B	Main Office Storage (IT MDF Room)	Yes	W3	No Access	No Access	No Access	No Access	No Access
8440	1	1	125B	Main Office Storage (IT MDF Room)	Yes	W4	No Access	No Access	No Access	No Access	No Access
8440	1	1	125B	Main Office Storage (IT MDF Room)	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access
8440	1	1	125B	Main Office Storage (IT MDF Room)	Yes	Floor	No Access	No Access	No Access	No Access	No Access
8440	1	1	125	Principal's Office	Yes	W1	No Access	No Access	No Access	No Access	No Access
8440	1	1	125	Principal's Office	Yes	Door	Wood	Tan	Chipping	2	Negative
8440	1	1	125	Principal's Office	Yes	Door Frame	Metal	Tan	Chipping	2	Negative
8440	1	1	125	Principal's Office	Yes	W2	No Access	No Access	No Access	No Access	No Access
8440	1	1	125	Principal's Office	Yes	W3	No Access	No Access	No Access	No Access	No Access
8440	1	1	125	Principal's Office	Yes	W4	No Access	No Access	No Access	No Access	No Access
8440	1	1	125	Principal's Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access
8440	1	1	125	Principal's Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access
8440	1	1	125A	Principal's Office Restroom	Yes	W1	No Access	No Access	No Access	No Access	No Access
8440	1	1	125A	Principal's Office Restroom	Yes	W2	No Access	No Access	No Access	No Access	No Access
8440	1	1	125A	Principal's Office Restroom	Yes	W3	No Access	No Access	No Access	No Access	No Access
8440	1	1	125A	Principal's Office Restroom	Yes	W4	No Access	No Access	No Access	No Access	No Access
8440	1	1	125A	Principal's Office Restroom	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access
8440	1	1	125A	Principal's Office Restroom	Yes	Floor	No Access	No Access	No Access	No Access	No Access
8440	1	1	129	Men's Restroom across from Auditorium	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	129	Men's Restroom across from Auditorium	Yes	Door	Wood	Blue	Chipping	3	Negative
8440	1	1	129	Men's Restroom across from Auditorium	Yes	Door Frame	Metal	Blue	Chipping	2	Negative

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	129	Men's Restroom across from Auditorium	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	129	Men's Restroom across from Auditorium	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	129	Men's Restroom across from Auditorium	Yes	Radiator	Metal	Blue	Chipping	2	Negative
8440	1	1	129	Men's Restroom across from Auditorium	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	129	Men's Restroom across from Auditorium	Yes	Stalls	Metal	Green	Moisture Damage, Chipping	4	Negative
8440	1	1	129	Men's Restroom across from Auditorium	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	129	Men's Restroom across from Auditorium	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	129	Vestibule to Men's Restroom across from Auditorium	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	129	Vestibule to Men's Restroom across from Auditorium	Yes	Door	Metal	Blue	Chipping	2	Negative
8440	1	1	129	Vestibule to Men's Restroom across from Auditorium	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	129	Vestibule to Men's Restroom across from Auditorium	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	129	Vestibule to Men's Restroom across from Auditorium	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	129	Vestibule to Men's Restroom across from Auditorium	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	129	Vestibule to Men's Restroom across from Auditorium	Yes	Floor	Concrete	Gray	Chipping	1	Negative
8440	1	1	129A	Custodian Storage across from Auditorium	No	W1	No Access	No Access	No Access	No Access	No Access
8440	1	1	129A	Custodian Storage across from Auditorium	No	W2	No Access	No Access	No Access	No Access	No Access
8440	1	1	129A	Custodian Storage across from Auditorium	No	W3	No Access	No Access	No Access	No Access	No Access
8440	1	1	129A	Custodian Storage across from Auditorium	No	W4	No Access	No Access	No Access	No Access	No Access
8440	1	1	129A	Custodian Storage across from Auditorium	No	Ceiling	No Access	No Access	No Access	No Access	No Access
8440	1	1	129A	Custodian Storage across from Auditorium	No	Floor	No Access	No Access	No Access	No Access	No Access
8440	1	1	131	Women's Restroom across from Auditorium	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	131	Women's Restroom across from Auditorium	Yes	Door	Wood	Blue	Chipping	3	Negative
8440	1	1	131	Women's Restroom across from Auditorium	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	1	131	Women's Restroom across from Auditorium	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	131	Women's Restroom across from Auditorium	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	131	Women's Restroom across from Auditorium	Yes	Stalls	Metal	Yellow	Moisture Damage, Chipping	7	Negative
8440	1	1	131	Women's Restroom across from Auditorium	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	131	Women's Restroom across from Auditorium	Yes	Radiator	Metal	Blue	Chipping	1	Negative
8440	1	1	131	Women's Restroom across from Auditorium	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	131	Women's Restroom across from Auditorium	Yes	Floor	Concrete	Gray	Flaking	4	Negative
8440	1	1	140	Auditorium	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	140	Auditorium	Yes	Door	Wood	Gray, Blue	Chipping	1	Negative
8440	1	1	140	Auditorium	Yes	Door Frame	Metal	Gray, Blue	Chipping	1	Negative
8440	1	1	140	Auditorium	Yes	W2	Concrete	Tan	Friction, Chipping, Flaking	7	Negative
8440	1	1	140	Auditorium	Yes	Door	Metal	Blue	Chipping	5	Negative
8440	1	1	140	Auditorium	Yes	Door Frame	Metal	Blue	Chipping	5	Negative
8440	1	1	140	Auditorium	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	140	Auditorium	Yes	W4	Concrete	Tan	Friction, Chipping, Flaking	7	Negative
8440	1	1	140	Auditorium	Yes	Ceiling	Plaster	White	Efflorescence, Moisture Damage	3	Negative



				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	140	Auditorium	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	140XA	Auditorium Stage	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	140XA	Auditorium Stage	Yes	W2	Concrete Masonry Unit	Beige	Flaking	1	Negative
8440	1	1	140XA	Auditorium Stage	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	140XA	Auditorium Stage	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	140XA	Auditorium Stage	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	140XA	Auditorium Stage	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	140XB	Auditorium Stage Entrance - Left Side	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	140XB	Auditorium Stage Entrance - Left Side	Yes	Door	Wood	Beige	Chipping	1	Negative
8440	1	1	140XB	Auditorium Stage Entrance - Left Side	Yes	Door Frame	Metal	Beige	Chipping	1	Negative
8440	1	1	140XB	Auditorium Stage Entrance - Left Side	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	140XB	Auditorium Stage Entrance - Left Side	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	140XB	Auditorium Stage Entrance - Left Side	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	140XB	Auditorium Stage Entrance - Left Side	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	140XB	Auditorium Stage Entrance - Left Side	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	140XC	Auditorium Stage Entrance - Right Side	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	140XC	Auditorium Stage Entrance - Right Side	Yes	Door	Wood	Green	Chipping	1	Negative
8440	1	1	140XC	Auditorium Stage Entrance - Right Side	Yes	Door Frame	Metal	Green	Chipping	1	Negative
8440	1	1	140XC	Auditorium Stage Entrance - Right Side	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	140XC	Auditorium Stage Entrance - Right Side	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	140XC	Auditorium Stage Entrance - Right Side	Yes	Pipes	Metal	White	Chipping	1	Negative
8440	1	1	140XC	Auditorium Stage Entrance - Right Side	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	140XC	Auditorium Stage Entrance - Right Side	Yes	Ceiling	Concrete	White	Spalling	1	Negative
8440	1	1	140XC	Auditorium Stage Entrance - Right Side	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	140XD	Music Room	Yes	W1	No Access	No Access	No Access	No Access	No Access
8440	1	1	140XD	Music Room	Yes	Door	Wood	Gray	Chipping	1	Negative
8440	1	1	140XD	Music Room	Yes	Door Frame	Metal	Gray	Chipping	1	Negative
8440	1	1	140XD	Music Room	Yes	W2	No Access	No Access	No Access	No Access	No Access
8440	1	1	140XD	Music Room	Yes	W3	No Access	No Access	No Access	No Access	No Access
8440	1	1	140XD	Music Room	Yes	W4	No Access	No Access	No Access	No Access	No Access
8440	1	1	140XD	Music Room	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access
8440	1	1	140XD	Music Room	Yes	Floor	No Access	No Access	No Access	No Access	No Access
8440	1	1	120	Gymnasium	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	120	Gymnasium	Yes	Door	Wood	Blue	Chipping	8	Negative
8440	1	1	120	Gymnasium	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	1	120	Gymnasium	Yes	Access Panel	Metal	Blue	Chipping	1	Negative
8440	1	1	120	Gymnasium	Yes	Access Panel	Metal	Blue	Chipping	4	Negative
8440	1	1	120	Gymnasium	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	120	Gymnasium	Yes	Door	Metal	Blue	Chipping	4	Negative
8440	1	1	120	Gymnasium	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	120	Gymnasium	Yes	W3	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	120	Gymnasium	Yes	W4	Concrete Masonry Unit	White	Flaking, Chipping	4	Negative
8440	1	1	120	Gymnasium	Yes	Pipe	Metal	White	Chipping	1	Negative
8440	1	1	120	Gymnasium	Yes	Door	Wood	Blue	Chipping	5	Negative
8440	1	1	120	Gymnasium	Yes	Door Frame	Metal	Blue	Chipping, Friction	5	Negative
8440	1	1	120	Gymnasium	Yes	Ceiling	Metal	White	Flaking	5	Negative
8440	1	1	120	Gymnasium	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	122	Gym Storage Room adjacent to Attic/Air Handler Room	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	122	Gym Storage Room adjacent to Attic/Air Handler Room	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	122	Gym Storage Room adjacent to Attic/Air Handler Room	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	122	Gym Storage Room adjacent to Attic/Air Handler Room	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	122	Gym Storage Room adjacent to Attic/Air Handler Room	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	122	Gym Storage Room adjacent to Attic/Air Handler Room	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	122	Gym Storage Room adjacent to Attic/Air Handler Room	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	122	Gym Storage Room adjacent to Attic/Air Handler Room	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	124	Attic/Air Handler Room	no	W1	N/A	N/A	None	0	N/A
8440	1	1	124	Attic/Air Handler Room	no	Door	Metal	Blue, Green	Chipping	1	Negative
8440	1	1	124	Attic/Air Handler Room	no	Door Frame	Metal	Blue, Green	Chipping	2	Negative
8440	1	1	124	Attic/Air Handler Room	no	W2	N/A	N/A	None	0	N/A
8440	1	1	124	Attic/Air Handler Room	no	W3	N/A	N/A	None	0	N/A
8440	1	1	124	Attic/Air Handler Room	no	W4	N/A	N/A	None	0	N/A
8440	1	1	124	Attic/Air Handler Room	no	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	124	Attic/Air Handler Room	no	Floor	N/A	N/A	None	0	N/A
8440	1	1	126	Storage Room adjacent to Home and School Office	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	126	Storage Room adjacent to Home and School Office	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	126	Storage Room adjacent to Home and School Office	Yes	Door Frame	Metal	Blue	Chipping	3	Negative
8440	1	1	126	Storage Room adjacent to Home and School Office	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	126	Storage Room adjacent to Home and School Office	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	126	Storage Room adjacent to Home and School Office	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	126	Storage Room adjacent to Home and School Office	Yes	Ceiling	Concrete	White	Chipping	3	Negative
8440	1	1	126	Storage Room adjacent to Home and School Office	Yes	Duct	Metal	White	Friction, Chipping	2	Negative
8440	1	1	126	Storage Room adjacent to Home and School Office	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	128	Home and School Sunshine Office	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	128	Home and School Sunshine Office	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	128	Home and School Sunshine Office	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	128	Home and School Sunshine Office	Yes	Window Shield	Metal	Blue	Chipping	1	Negative

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	128	Home and School Sunshine Office	Yes	Window Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	128	Home and School Sunshine Office	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	128	Home and School Sunshine Office	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	128	Home and School Sunshine Office	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	128	Home and School Sunshine Office	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	128	Home and School Sunshine Office	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	130	Gym Storage Room adjacent to Stairwell	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	130	Gym Storage Room adjacent to Stairwell	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	130	Gym Storage Room adjacent to Stairwell	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	130	Gym Storage Room adjacent to Stairwell	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	130	Gym Storage Room adjacent to Stairwell	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	130	Gym Storage Room adjacent to Stairwell	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	132	Gym Storage adjacent to Boy's Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	132	Gym Storage adjacent to Boy's Restroom	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	132	Gym Storage adjacent to Boy's Restroom	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	132	Gym Storage adjacent to Boy's Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	132	Gym Storage adjacent to Boy's Restroom	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	132	Gym Storage adjacent to Boy's Restroom	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	132	Gym Storage adjacent to Boy's Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	132	Gym Storage adjacent to Boy's Restroom	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	134	Boy's Restroom in Gym	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	134	Boy's Restroom in Gym	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	134	Boy's Restroom in Gym	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	134	Boy's Restroom in Gym	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	134	Boy's Restroom in Gym	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	134	Boy's Restroom in Gym	Yes	Radiator	Metal	Tan	Chipping, Flaking, Moisture Damage	1	Negative
8440	1	1	134	Boy's Restroom in Gym	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	134	Boy's Restroom in Gym	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	134	Boy's Restroom in Gym	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	136	Girl's Restroom in Gym	yes	W1	N/A	N/A	None	0	N/A
8440	1	1	136	Girl's Restroom in Gym	yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	136	Girl's Restroom in Gym	yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	136	Girl's Restroom in Gym	yes	W2	N/A	N/A	None	0	N/A
8440	1	1	136	Girl's Restroom in Gym	yes	W3	N/A	N/A	None	0	N/A
8440	1	1	136	Girl's Restroom in Gym	yes	Stall	Metal	Pink	Chipping	1	Negative
8440	1	1	136	Girl's Restroom in Gym	yes	W4	N/A	N/A	None	0	N/A
8440	1	1	136	Girl's Restroom in Gym	yes	Radiator	Metal	Tan	Chipping	1	Negative
8440	1	1	136	Girl's Restroom in Gym	yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	136	Girl's Restroom in Gym	yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	138	Gym Office	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	138	Gym Office	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	138	Gym Office	Yes	Door Frame	Metal	Blue	Chipping	1	Negative

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	138	Gym Office	Yes	Window Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	138	Gym Office	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	138	Gym Office	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	138	Gym Office	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	138	Gym Office	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	138	Gym Office	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	138	Gym Office	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	138A	Gym Office Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	138A	Gym Office Restroom	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	138A	Gym Office Restroom	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	138A	Gym Office Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	138A	Gym Office Restroom	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	138A	Gym Office Restroom	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	138A	Gym Office Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	138A	Gym Office Restroom	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	138B	Gym Office Storage Room	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	138B	Gym Office Storage Room	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	138B	Gym Office Storage Room	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	138B	Gym Office Storage Room	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	138B	Gym Office Storage Room	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	138B	Gym Office Storage Room	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	H01	Hallway by Main Office/Auditorium/Gym	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	H01	Hallway by Main Office/Auditorium/Gym	Yes	Door	Metal	Blue	Friction	3	Positive
8440	1	1	H01	Hallway by Main Office/Auditorium/Gym	Yes	Door Frame	Metal	Blue	Chipping, Moisture Damage	3	Positive
8440	1	1	H01	Hallway by Main Office/Auditorium/Gym	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	H01	Hallway by Main Office/Auditorium/Gym	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	H01	Hallway by Main Office/Auditorium/Gym	Yes	W4	Concrete Masonry Unit	Blue	Chipping	1	Negative
8440	1	1	H01	Hallway by Main Office/Auditorium/Gym	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	H01	Hallway by Main Office/Auditorium/Gym	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	105	Classroom 105	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	105	Classroom 105	Yes	Door	Wood	Blue	Chipping	2	Negative
8440	1	1	105	Classroom 105	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	105	Classroom 105	Yes	Door Panel	Wood	Blue	Chipping	2	Negative
8440	1	1	105	Classroom 105	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	105	Classroom 105	Yes	Coat Rack	Wood	White	Chipping	8	Negative
8440	1	1	105	Classroom 105	Yes	Shelf	Metal	White	Chipping	2	Negative
8440	1	1	105	Classroom 105	Yes	Shelf Support	Metal	White	Chipping	6	Negative
8440	1	1	105	Classroom 105	Yes	Support Post	Metal	Tan	Chipping	2	Positive
8440	1	1	105	Classroom 105	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	105	Classroom 105	Yes	Radiator	Metal	Blue	Chipping	1	Negative

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	105	Classroom 105	Yes	Univent	Metal	Blue	Chipping, Moisture Damage	2	Negative
8440	1	1	105	Classroom 105	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	105	Classroom 105	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	105	Classroom 105	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	105A	Early Literacy Speech office across from Classroom 105	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	105A	Early Literacy Speech office across from Classroom 105	Yes	Door	Wood	Blue	Chipping	2	Negative
8440	1	1	105A	Early Literacy Speech office across from Classroom 105	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	105A	Early Literacy Speech office across from Classroom 105	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	105A	Early Literacy Speech office across from Classroom 105	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	105A	Early Literacy Speech office across from Classroom 105	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	105A	Early Literacy Speech office across from Classroom 105	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	105A	Early Literacy Speech office across from Classroom 105	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	106A	Building Engineer's Office	No	W1	Concrete Masonry Unit	White	Chipping	2	Negative
8440	1	1	106A	Building Engineer's Office	No	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	106A	Building Engineer's Office	No	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	106A	Building Engineer's Office	No	Pipe	Metal	White	Chipping	1	Negative
8440	1	1	106A	Building Engineer's Office	No	W2	N/A	N/A	None	0	N/A
8440	1	1	106A	Building Engineer's Office	No	W3	N/A	N/A	None	0	N/A
8440	1	1	106A	Building Engineer's Office	No	W4	N/A	N/A	None	0	N/A
8440	1	1	106A	Building Engineer's Office	No	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	106A	Building Engineer's Office	No	Floor	N/A	N/A	None	0	N/A
8440	1	1	106B	Bathroom in Building Engineer's Office	No	W1	N/A	N/A	None	0	N/A
8440	1	1	106B	Bathroom in Building Engineer's Office	No	Door Frame	Metal	Gray	Chipping	1	Negative
8440	1	1	106B	Bathroom in Building Engineer's Office	No	W2	N/A	N/A	None	0	N/A
8440	1	1	106B	Bathroom in Building Engineer's Office	No	W3	N/A	N/A	None	0	N/A
8440	1	1	106B	Bathroom in Building Engineer's Office	No	W4	N/A	N/A	None	0	N/A
8440	1	1	106B	Bathroom in Building Engineer's Office	No	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	106B	Bathroom in Building Engineer's Office	No	Floor	N/A	N/A	None	0	N/A
8440	1	1	106	Boiler Room	No	W1	Concrete Masonry Unit	White	Flaking, Chipping	10	Negative
8440	1	1	106	Boiler Room	No	Pipe	Metal	White	Chipping	2	Negative
8440	1	1	106	Boiler Room	No	Door	Metal	Blue	Chipping	5	Negative
8440	1	1	106	Boiler Room	No	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	1	106	Boiler Room	No	W2	N/A	N/A	None	0	N/A
8440	1	1	106	Boiler Room	No	Door	Wood	Gray, Red	Chipping	1	Negative

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	106	Boiler Room	No	Door Frame	Metal	Gray	Chipping	1	Negative
8440	1	1	106	Boiler Room	No	W3	Concrete Masonry Unit	White	Chipping	1	Negative
8440	1	1	106	Boiler Room	No	W4	N/A	N/A	None	0	N/A
8440	1	1	106	Boiler Room	No	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	106	Boiler Room	No	Floor	N/A	N/A	None	0	N/A
8440	1	1	107	Classroom 107	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	107	Classroom 107	Yes	Door	Wood	Blue	Chipping	2	Negative
8440	1	1	107	Classroom 107	Yes	Door Frame	Metal	Blue	Chipping	3	Negative
8440	1	1	107	Classroom 107	Yes	Door Panel	Wood	Blue	Chipping	2	Negative
8440	1	1	107	Classroom 107	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	107	Classroom 107	Yes	Coat Rack	Wood	White	Chipping	4	Negative
8440	1	1	107	Classroom 107	Yes	Shelf	Metal	White	Chipping	1	Negative
8440	1	1	107	Classroom 107	Yes	Shelf Support	Metal	White	Chipping	2	Negative
8440	1	1	107	Classroom 107	Yes	Closet Door	Metal	Pink	Chipping	2	Negative
8440	1	1	107	Classroom 107	Yes	Support Post	Metal	Tan	Chipping	2	Positive
8440	1	1	107	Classroom 107	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	107	Classroom 107	Yes	Univent	Metal	Blue	Chipping	2	Negative
8440	1	1	107	Classroom 107	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	107	Classroom 107	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	107	Classroom 107	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	109	Classroom 109	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	109	Classroom 109	Yes	Door	Wood	Blue	Chipping	2	Negative
8440	1	1	109	Classroom 109	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	109	Classroom 109	Yes	Door Panel	Wood	Blue	Chipping	1	Negative
8440	1	1	109	Classroom 109	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	109	Classroom 109	Yes	Coat Rack	Wood	White	Chipping	3	Negative
8440	1	1	109	Classroom 109	Yes	Shelf	Metal	White	Chipping	1	Negative
8440	1	1	109	Classroom 109	Yes	Shelf Support	Metal	White	Chipping	5	Negative
8440	1	1	109	Classroom 109	Yes	Support Post	Metal	Tan	Chipping	1	Positive
8440	1	1	109	Classroom 109	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	109	Classroom 109	Yes	Univent	Metal	Blue	Chipping	1	Negative
8440	1	1	109	Classroom 109	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	109	Classroom 109	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	109	Classroom 109	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	109A	Women's Restroom next to Classroom 109	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	109A	Women's Restroom next to Classroom 109	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	1	109A	Women's Restroom next to Classroom 109	Yes	Door	Wood	Blue	Chipping	3	Negative
8440	1	1	109A	Women's Restroom next to Classroom 109	Yes	Stalls	Metal	Yellow	Chipping, Moisture Damage	15	Negative
8440	1	1	109A	Women's Restroom next to Classroom 109	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	109A	Women's Restroom next to Classroom 109	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	109A	Women's Restroom next to Classroom 109	Yes	W4	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	109A	Women's Restroom next to Classroom 109	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	109A	Women's Restroom next to Classroom 109	Yes	Floor	Concrete	Gray	Chipping	3	Negative
8440	1	1	109B	Men's Restroom next to Classroom 109	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	109B	Men's Restroom next to Classroom 109	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	109B	Men's Restroom next to Classroom 109	Yes	Stalls	Metal	Green	Chipping	3	Negative
8440	1	1	109B	Men's Restroom next to Classroom 109	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	109B	Men's Restroom next to Classroom 109	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	109B	Men's Restroom next to Classroom 109	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	109B	Men's Restroom next to Classroom 109	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	109B	Men's Restroom next to Classroom 109	Yes	Floor	Concrete	Gray	Friction	3	Negative
8440	1	1	108A/B	Storage Room adjacent to IMC	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	108A/B	Storage Room adjacent to IMC	Yes	Door	Wood	Blue	Chipping	4	Negative
8440	1	1	108A/B	Storage Room adjacent to IMC	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	1	108A/B	Storage Room adjacent to IMC	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	108A/B	Storage Room adjacent to IMC	Yes	W3	Concrete Masonry Unit	White	Cracking	2	Negative
8440	1	1	108A/B	Storage Room adjacent to IMC	Yes	Pipe	Metal	Gray	Flaking	10	Negative
8440	1	1	108A/B	Storage Room adjacent to IMC	Yes	Door	Metal	Blue	Chipping	5	Negative
8440	1	1	108A/B	Storage Room adjacent to IMC	Yes	Door Frame	Metal	Blue	Chipping	3	Positive
8440	1	1	108A/B	Storage Room adjacent to IMC	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	108A/B	Storage Room adjacent to IMC	Yes	Storage Cages	Metal	Green	Chipping	5	Negative
8440	1	1	108A/B	Storage Room adjacent to IMC	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	108A/B	Storage Room adjacent to IMC	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	117	IMC	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	117	IMC	Yes	Door	Metal	Blue	Chipping	1	Negative
8440	1	1	117	IMC	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	117	IMC	Yes	Door	Metal	Blue	Chipping	1	Negative
8440	1	1	117	IMC	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	117	IMC	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	117	IMC	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	117	IMC	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	117	IMC	Yes	Radiator	Metal	Blue	Chipping	1	Negative
8440	1	1	117	IMC	Yes	Univent	Metal	Blue	Friction	1	Negative
8440	1	1	117	IMC	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	117	IMC	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	117A	IMC Office	Yes	W1	No Access	No Access	No Access	No Access	No Access
8440	1	1	117A	IMC Office	Yes	W2	No Access	No Access	No Access	No Access	No Access
8440	1	1	117A	IMC Office	Yes	W3	No Access	No Access	No Access	No Access	No Access
8440	1	1	117A	IMC Office	Yes	W4	No Access	No Access	No Access	No Access	No Access
8440	1	1	117A	IMC Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access
8440	1	1	117A	IMC Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access
8440	1	1	109D	Kitchen Staff Restroom Across from Kitchen	no	W1	No Access	No Access	No Access	No Access	No Access
8440	1	1	109D	Kitchen Staff Restroom Across from Kitchen	no	W2	No Access	No Access	No Access	No Access	No Access

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
8440	1	1	109D	Kitchen Staff Restroom Across from Kitchen	no	W3	No Access	No Access	No Access	No Access	No Access
8440	1	1	109D	Kitchen Staff Restroom Across from Kitchen	no	W4	No Access	No Access	No Access	No Access	No Access
8440	1	1	109D	Kitchen Staff Restroom Across from Kitchen	no	Ceiling	No Access	No Access	No Access	No Access	No Access
8440	1	1	109D	Kitchen Staff Restroom Across from Kitchen	no	Floor	No Access	No Access	No Access	No Access	No Access
8440	1	1	109E	Custodian Storage Room	No	W1	No Access	No Access	No Access	No Access	No Access
8440	1	1	109E	Custodian Storage Room	No	W2	No Access	No Access	No Access	No Access	No Access
8440	1	1	109E	Custodian Storage Room	No	W3	No Access	No Access	No Access	No Access	No Access
8440	1	1	109E	Custodian Storage Room	No	W4	No Access	No Access	No Access	No Access	No Access
8440	1	1	109E	Custodian Storage Room	No	Ceiling	No Access	No Access	No Access	No Access	No Access
8440	1	1	109E	Custodian Storage Room	No	Floor	No Access	No Access	No Access	No Access	No Access
8440	1	1	H02	Hallway from Classroom 100 to IMC	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	H02	Hallway from Classroom 100 to IMC	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	H02	Hallway from Classroom 100 to IMC	Yes	Fire Suppression Door Frame (Walls 2/4)	Metal	Blue	Chipping	1	Negative
8440	1	1	H02	Hallway from Classroom 100 to IMC	Yes	Fire Suppression Door (Walls 2/4)	Metal	Blue	Chipping	1	Negative
8440	1	1	H02	Hallway from Classroom 100 to IMC	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	H02	Hallway from Classroom 100 to IMC	Yes	Access Panel	Metal	White	Friction	1	Negative
8440	1	1	H02	Hallway from Classroom 100 to IMC	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	H02	Hallway from Classroom 100 to IMC	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	H02	Hallway from Classroom 100 to IMC	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	113	Cafeteria	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	113	Cafeteria	Yes	Vent	Metal	White	Chipping	1	Negative
8440	1	1	113	Cafeteria	Yes	W2	Concrete Masonry Unit	White, Blue	Chipping, Flaking	2	Negative
8440	1	1	113	Cafeteria	Yes	Door	Metal	Blue	Chipping	3	Positive
8440	1	1	113	Cafeteria	Yes	Door Frame	Metal	Blue	Chipping	3	Positive
8440	1	1	113	Cafeteria	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	113	Cafeteria	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	113	Cafeteria	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	113	Cafeteria	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	113	Cafeteria	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	113A	Air Handler Room in Cafeteria	No	W1	N/A	N/A	None	0	N/A
8440	1	1	113A	Air Handler Room in Cafeteria	No	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	113A	Air Handler Room in Cafeteria	No	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	113A	Air Handler Room in Cafeteria	No	W2	N/A	N/A	None	0	N/A
8440	1	1	113A	Air Handler Room in Cafeteria	No	W3	N/A	N/A	None	0	N/A
8440	1	1	113A	Air Handler Room in Cafeteria	No	W4	N/A	N/A	None	0	N/A
8440	1	1	113A	Air Handler Room in Cafeteria	No	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	113A	Air Handler Room in Cafeteria	No	Floor	N/A	N/A	None	0	N/A
8440	1	1	109C	Cafeteria Storage	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	109C	Cafeteria Storage	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	109C	Cafeteria Storage	Yes	Door Frame	Metal	Blue	Chipping	1	Negative



				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	109C	Cafeteria Storage	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	109C	Cafeteria Storage	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	109C	Cafeteria Storage	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	109C	Cafeteria Storage	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	109C	Cafeteria Storage	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	115	Kitchen by IMC	no	W1	N/A	N/A	None	0	N/A
8440	1	1	115	Kitchen by IMC	no	Door	Wood	Chipping	Blue, Green	1	Negative
8440	1	1	115	Kitchen by IMC	no	Door Frame	Metal	Chipping	Blue, Green	1	Negative
8440	1	1	115	Kitchen by IMC	no	W2	N/A	N/A	None	0	N/A
8440	1	1	115	Kitchen by IMC	no	Radiator	Metal	White	Chipping, Flaking	1	Negative
8440	1	1	115	Kitchen by IMC	no	W3	N/A	N/A	None	0	N/A
8440	1	1	115	Kitchen by IMC	no	W4	Concrete Masonry Unit	White	Chipping	2	Negative
8440	1	1	115	Kitchen by IMC	no	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	115	Kitchen by IMC	no	Floor	N/A	N/A	None	0	N/A
8440	1	1	117B	Kitchen Storage Room	no	W1	No Access	No Access	No Access	No Access	No Access
8440	1	1	117B	Kitchen Storage Room	no	Door	Wood	Green	Chipping	1	Negative
8440	1	1	117B	Kitchen Storage Room	no	Door Frame	Metal	Green	Chipping	1	Negative
8440	1	1	117B	Kitchen Storage Room	no	W2	No Access	No Access	No Access	No Access	No Access
8440	1	1	117B	Kitchen Storage Room	no	W3	No Access	No Access	No Access	No Access	No Access
8440	1	1	117B	Kitchen Storage Room	no	W4	No Access	No Access	No Access	No Access	No Access
8440	1	1	117B	Kitchen Storage Room	no	Ceiling	No Access	No Access	No Access	No Access	No Access
8440	1	1	117B	Kitchen Storage Room	no	Floor	No Access	No Access	No Access	No Access	No Access
8440	1	1	108	Classroom 108 (ART)	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	108	Classroom 108 (ART)	Yes	Door	Wood	Blue	Chipping	4	Negative
8440	1	1	108	Classroom 108 (ART)	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	108	Classroom 108 (ART)	Yes	Door Panel	Wood	Blue	Chipping	4	Negative
8440	1	1	108	Classroom 108 (ART)	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	108	Classroom 108 (ART)	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	108	Classroom 108 (ART)	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	108	Classroom 108 (ART)	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	108	Classroom 108 (ART)	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	108	Classroom 108 (ART)	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	108	Classroom 108 (ART)	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	110	Classroom 110 (MUSIC)	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	110	Classroom 110 (MUSIC)	Yes	Door	Wood	Blue	Chipping	2	Negative
8440	1	1	110	Classroom 110 (MUSIC)	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	1	110	Classroom 110 (MUSIC)	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	110	Classroom 110 (MUSIC)	Yes	Closet Door	Metal	Pink	Friction, Chipping	1	Negative
8440	1	1	110	Classroom 110 (MUSIC)	Yes	Sink Cabinet	Metal	Pink	Friction, Chipping	1	Negative
8440	1	1	110	Classroom 110 (MUSIC)	Yes	Support Post	Metal	Blue	Chipping	2	Positive
8440	1	1	110	Classroom 110 (MUSIC)	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	110	Classroom 110 (MUSIC)	Yes	Univent	Metal	Blue	Chipping	1	Negative

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	110	Classroom 110 (MUSIC)	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	110	Classroom 110 (MUSIC)	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	110	Classroom 110 (MUSIC)	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	110A	Boy's Restroom across from Classroom 110	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	110A	Boy's Restroom across from Classroom 110	Yes	Door	Wood	Blue	Chipping	3	Negative
8440	1	1	110A	Boy's Restroom across from Classroom 110	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	110A	Boy's Restroom across from Classroom 110	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	110A	Boy's Restroom across from Classroom 110	Yes	Vent	Metal	White	Chipping	1	Negative
8440	1	1	110A	Boy's Restroom across from Classroom 110	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	110A	Boy's Restroom across from Classroom 110	Yes	Door	Metal	Green	Chipping, Flaking	10	Negative
8440	1	1	110A	Boy's Restroom across from Classroom 110	Yes	Door Frame	Metal	Green	Chipping, Flaking	5	Positive
8440	1	1	110A	Boy's Restroom across from Classroom 110	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	110A	Boy's Restroom across from Classroom 110	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	110A	Boy's Restroom across from Classroom 110	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	110B	Girl's Restroom across from Classroom 110	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	110B	Girl's Restroom across from Classroom 110	Yes	Door	Wood	Blue	Chipping	5	Negative
8440	1	1	110B	Girl's Restroom across from Classroom 110	Yes	Door Frame	Metal	Blue	Chipping	3	Negative
8440	1	1	110B	Girl's Restroom across from Classroom 110	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	110B	Girl's Restroom across from Classroom 110	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	110B	Girl's Restroom across from Classroom 110	Yes	Door	Metal	Blue	Chipping	10	Positive
8440	1	1	110B	Girl's Restroom across from Classroom 110	Yes	Door Frame	Metal	Blue	Chipping, Flaking	3	Positive
8440	1	1	110B	Girl's Restroom across from Classroom 110	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	110B	Girl's Restroom across from Classroom 110	Yes	Stall	Metal	Peach	Chipping, Friction, Moisture Damage	15	Negative
8440	1	1	110B	Girl's Restroom across from Classroom 110	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	110B	Girl's Restroom across from Classroom 110	Yes	Floor	Concrete	Gray	Friction, Chipping	5	Negative
8440	1	1	111	Classroom 111	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	111	Classroom 111	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	1	111	Classroom 111	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	111	Classroom 111	Yes	Door Panel	Wood	Blue	Chipping	1	Negative
8440	1	1	111	Classroom 111	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	111	Classroom 111	Yes	Sink Cabinet	Metal	Pink	Chipping	1	Negative
8440	1	1	111	Classroom 111	Yes	Coat Rack	Wood	White	Chipping	2	Negative
8440	1	1	111	Classroom 111	Yes	Shelf	Metal	White	Chipping	1	Negative
8440	1	1	111	Classroom 111	Yes	Shelf Support	Metal	White	Chipping	3	Negative
8440	1	1	111	Classroom 111	Yes	Support Post	Metal	White	Chipping	2	Positive
8440	1	1	111	Classroom 111	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	111	Classroom 111	Yes	Univent	Metal	Blue	Chipping, Friction	2	Negative
8440	1	1	111	Classroom 111	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	111	Classroom 111	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	111	Classroom 111	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	H03	Hallway from Classrooms 108 to 110	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	H03	Hallway from Classrooms 108 to 110	Yes	W2	N/A	N/A	None	0	N/A

				2/7 - 2/16/22	<b>Lead Safe Certification Assessment Report</b>						
				Inspector Name and Certificate Number: Charles Rhodes 003542		<b>Loesche School</b>					
				Inspection Company: Batta		<b>595 Tomlinson Rd, Philadelphia, PA 19116</b>					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	H03	Hallway from Classrooms 108 to 110	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	H03	Hallway from Classrooms 108 to 110	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	H03	Hallway from Classrooms 108 to 110	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	H03	Hallway from Classrooms 108 to 110	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	H04A	Hallway from Classrooms A2 to A4	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	H04A	Hallway from Classrooms A2 to A4	Yes	Door	Metal	Blue	Flaking	1	Negative
8440	1	1	H04A	Hallway from Classrooms A2 to A4	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	H04A	Hallway from Classrooms A2 to A4	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	H04A	Hallway from Classrooms A2 to A4	Yes	Door Frame	Metal	Blue	Moisture Damage, Chipping	2	Negative
8440	1	1	H04A	Hallway from Classrooms A2 to A4	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	H04A	Hallway from Classrooms A2 to A4	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	H04A	Hallway from Classrooms A2 to A4	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	H05A	Hallway between A Section and B Section	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	H05A	Hallway between A Section and B Section	Yes	Door Frame	Metal	Red	Friction, Chipping	1	Negative
8440	1	1	H05A	Hallway between A Section and B Section	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	H05A	Hallway between A Section and B Section	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	H05A	Hallway between A Section and B Section	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	H05A	Hallway between A Section and B Section	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	H05A	Hallway between A Section and B Section	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	H05A	Hallway between A Section and B Section	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	H06A	Hallway from Classrooms B1 to B6	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	H06A	Hallway from Classrooms B1 to B6	Yes	W2	Concrete Masonry Unit	White	Spalling	1	Negative
8440	1	1	H06A	Hallway from Classrooms B1 to B6	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	H06A	Hallway from Classrooms B1 to B6	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	H06A	Hallway from Classrooms B1 to B6	Yes	Door	Metal	Blue	Chipping	1	Negative
8440	1	1	H06A	Hallway from Classrooms B1 to B6	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	H06A	Hallway from Classrooms B1 to B6	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	H06A	Hallway from Classrooms B1 to B6	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	H07A	Hallway before Stairwell to A and B Sections	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	H07A	Hallway before Stairwell to A and B Sections	Yes	Door Frame	Metal	Red, Blue	Moisture Damage, Cracked	1	Negative
8440	1	1	H07A	Hallway before Stairwell to A and B Sections	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	H07A	Hallway before Stairwell to A and B Sections	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	H07A	Hallway before Stairwell to A and B Sections	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	H07A	Hallway before Stairwell to A and B Sections	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	H07A	Hallway before Stairwell to A and B Sections	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	H07A	Hallway before Stairwell to A and B Sections	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	001A	Classroom A1	Yes	W1	Concrete Masonry Unit	White	None	0	N/A
8440	1	1	001A	Classroom A1	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	001A	Classroom A1	Yes	W2	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	001A	Classroom A1	Yes	Sink Cabinet	Wood	White	Chipping	4	Negative
8440	1	1	001A	Classroom A1	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	001A	Classroom A1	Yes	Radiator	Metal	Blue	Friction, Chipping	2	Negative
8440	1	1	001A	Classroom A1	Yes	Univent	Metal	White	Chipping	4	Negative
8440	1	1	001A	Classroom A1	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	001A	Classroom A1	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	001A	Classroom A1	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	A1A	Classroom A1 Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	A1A	Classroom A1 Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	A1A	Classroom A1 Restroom	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	A1A	Classroom A1 Restroom	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	A1A	Classroom A1 Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	A1A	Classroom A1 Restroom	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	002A	Classroom A2	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	002A	Classroom A2	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	002A	Classroom A2	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	002A	Classroom A2	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	002A	Classroom A2	Yes	Radiator	Metal	Blue	Friction, Chipping	1	Negative
8440	1	1	002A	Classroom A2	Yes	Univent	Metal	White	Chipping	1	Negative
8440	1	1	002A	Classroom A2	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	002A	Classroom A2	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	002A	Classroom A2	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	A2A	Classroom A2 Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	A2A	Classroom A2 Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	A2A	Classroom A2 Restroom	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	A2A	Classroom A2 Restroom	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	A2A	Classroom A2 Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	A2A	Classroom A2 Restroom	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	003A	Classroom A3	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	003A	Classroom A3	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	003A	Classroom A3	Yes	Former Coat Rack	Wood	White	Chipping	1	Negative
8440	1	1	003A	Classroom A3	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	003A	Classroom A3	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	003A	Classroom A3	Yes	Radiator	Metal	Blue	Friction	1	Negative
8440	1	1	003A	Classroom A3	Yes	Univent	Metal	Tan	Chipping	1	Negative
8440	1	1	003A	Classroom A3	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	003A	Classroom A3	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	003A	Classroom A3	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	004A	Classroom A4	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	004A	Classroom A4	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	004A	Classroom A4	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	004A	Classroom A4	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	004A	Classroom A4	Yes	Radiator	Metal	Blue	Chipping	1	Negative

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
8440	1	1	004A	Classroom A4	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	004A	Classroom A4	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	004A	Classroom A4	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	TEMP	Utility Closet	No	W1	No Access	No Access	No Access	No Access	No Access
8440	1	1	TEMP	Utility Closet	No	W2	No Access	No Access	No Access	No Access	No Access
8440	1	1	TEMP	Utility Closet	No	W3	No Access	No Access	No Access	No Access	No Access
8440	1	1	TEMP	Utility Closet	No	W4	No Access	No Access	No Access	No Access	No Access
8440	1	1	TEMP	Utility Closet	No	Ceiling	No Access	No Access	No Access	No Access	No Access
8440	1	1	TEMP	Utility Closet	No	Floor	No Access	No Access	No Access	No Access	No Access
8440	1	1	BR1	Teacher's Gender Neutral Bathroom	yes	W1	N/A	N/A	None	0	N/A
8440	1	1	BR1	Teacher's Gender Neutral Bathroom	yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	BR1	Teacher's Gender Neutral Bathroom	yes	W2	N/A	N/A	None	0	N/A
8440	1	1	BR1	Teacher's Gender Neutral Bathroom	yes	W3	N/A	N/A	None	0	N/A
8440	1	1	BR1	Teacher's Gender Neutral Bathroom	yes	W4	N/A	N/A	None	0	N/A
8440	1	1	BR1	Teacher's Gender Neutral Bathroom	yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	BR1	Teacher's Gender Neutral Bathroom	yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	BR2	Boy's Restroom near Classroom A2	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	BR2	Boy's Restroom near Classroom A2	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	BR2	Boy's Restroom near Classroom A2	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	BR2	Boy's Restroom near Classroom A2	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	BR2	Boy's Restroom near Classroom A2	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	BR2	Boy's Restroom near Classroom A2	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	BR2	Boy's Restroom near Classroom A2	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	A8A	Girl's Restroom near Classroom A2	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	A8A	Girl's Restroom near Classroom A2	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	A8A	Girl's Restroom near Classroom A2	Yes	Stall	Metal	Pink	Chipping, Friction	1	Negative
8440	1	1	A8A	Girl's Restroom near Classroom A2	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	A8A	Girl's Restroom near Classroom A2	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	A8A	Girl's Restroom near Classroom A2	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	A8A	Girl's Restroom near Classroom A2	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	A8A	Girl's Restroom near Classroom A2	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	TEMP2	Boy's Restroom (by Classroom B6)	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	TEMP2	Boy's Restroom (by Classroom B6)	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	TEMP2	Boy's Restroom (by Classroom B6)	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	TEMP2	Boy's Restroom (by Classroom B6)	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	TEMP2	Boy's Restroom (by Classroom B6)	Yes	Radiator	Metal	Blue	Chipping, Moisture Damage	1	Negative
8440	1	1	TEMP2	Boy's Restroom (by Classroom B6)	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	TEMP2	Boy's Restroom (by Classroom B6)	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	TEMP2	Boy's Restroom (by Classroom B6)	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	TEMP2	Girl's Restroom (by Classroom B6)	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	TEMP2	Girl's Restroom (by Classroom B6)	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	TEMP2	Girl's Restroom (by Classroom B6)	Yes	W2	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	TEMP2	Girl's Restroom (by Classroom B6)	Yes	Stall	Metal	Tan	Chipping, Moisture Damage	2	Negative
8440	1	1	TEMP2	Girl's Restroom (by Classroom B6)	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	TEMP2	Girl's Restroom (by Classroom B6)	Yes	Radiator	Metal	Blue	Chipping	1	Negative
8440	1	1	TEMP2	Girl's Restroom (by Classroom B6)	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	TEMP2	Girl's Restroom (by Classroom B6)	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	TEMP2	Girl's Restroom (by Classroom B6)	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	TEMP6	Staff Restroom (across from Classroom B6)	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	TEMP6	Staff Restroom (across from Classroom B6)	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	1	TEMP6	Staff Restroom (across from Classroom B6)	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	TEMP6	Staff Restroom (across from Classroom B6)	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	TEMP6	Staff Restroom (across from Classroom B6)	Yes	Pipe	Metal	White	Chipping	1	Negative
8440	1	1	TEMP6	Staff Restroom (across from Classroom B6)	Yes	W4	Concrete Masonry Unit	White	Chipping	1	Negative
8440	1	1	TEMP6	Staff Restroom (across from Classroom B6)	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	TEMP6	Staff Restroom (across from Classroom B6)	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	001B	Classroom B1	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	001B	Classroom B1	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	001B	Classroom B1	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	001B	Classroom B1	Yes	Built-In Lockers/Shelf	Wood	Blue	Chipping	1	Negative
8440	1	1	001B	Classroom B1	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	001B	Classroom B1	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	001B	Classroom B1	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	001B	Classroom B1	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	B1A	Classroom B1 Closet	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	B1A	Classroom B1 Closet	Yes	Door Frame	Metal	Blue, :White, Yellow	Chipping	1	Negative
8440	1	1	B1A	Classroom B1 Closet	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	B1A	Classroom B1 Closet	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	B1A	Classroom B1 Closet	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	B1A	Classroom B1 Closet	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	B1A	Classroom B1 Closet	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	B1B	Classroom B1 Boy's Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	B1B	Classroom B1 Boy's Restroom	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	B1B	Classroom B1 Boy's Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	B1B	Classroom B1 Boy's Restroom	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	B1B	Classroom B1 Boy's Restroom	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	B1B	Classroom B1 Boy's Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	B1B	Classroom B1 Boy's Restroom	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	B1C	Classroom B1 Girl's Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	B1C	Classroom B1 Girl's Restroom	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	B1C	Classroom B1 Girl's Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	B1C	Classroom B1 Girl's Restroom	Yes	W3	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	B1C	Classroom B1 Girl's Restroom	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	B1C	Classroom B1 Girl's Restroom	Yes	Pipe Fitting Cover	Plastic	White	Chipping	1	Positive
8440	1	1	B1C	Classroom B1 Girl's Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	B1C	Classroom B1 Girl's Restroom	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	002B	Classroom B2	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	002B	Classroom B2	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	002B	Classroom B2	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	002B	Classroom B2	Yes	Built-In Lockers/Shelf	Wood	Blue	Flaking	1	Negative
8440	1	1	002B	Classroom B2	Yes	W3	Concrete Masonry Unit	White	Chipping	1	Negative
8440	1	1	002B	Classroom B2	Yes	Radiator	Metal	Blue	Friction, Chipping	2	Negative
8440	1	1	002B	Classroom B2	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	002B	Classroom B2	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	002B	Classroom B2	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	B2A	Classroom B2 Closet	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	B2A	Classroom B2 Closet	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	B2A	Classroom B2 Closet	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	B2A	Classroom B2 Closet	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	B2A	Classroom B2 Closet	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	B2A	Classroom B2 Closet	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	B2A	Classroom B2 Closet	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	B2B	Classroom B2 Boy's Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	B2B	Classroom B2 Boy's Restroom	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	B2B	Classroom B2 Boy's Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	B2B	Classroom B2 Boy's Restroom	Yes	Pipe Fitting Cover	Plastic	White	Chipping	1	Negative
8440	1	1	B2B	Classroom B2 Boy's Restroom	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	B2B	Classroom B2 Boy's Restroom	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	B2B	Classroom B2 Boy's Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	B2B	Classroom B2 Boy's Restroom	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	B2C	Classroom B2 Girl's Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	B2C	Classroom B2 Girl's Restroom	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	B2C	Classroom B2 Girl's Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	B2C	Classroom B2 Girl's Restroom	Yes	Pipe Fitting Cover	Plastic	White	Chipping	1	Positive
8440	1	1	B2C	Classroom B2 Girl's Restroom	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	B2C	Classroom B2 Girl's Restroom	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	B2C	Classroom B2 Girl's Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	B2C	Classroom B2 Girl's Restroom	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	003B	Classroom B3	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	003B	Classroom B3	Yes	Door Frame	Metal	Blue	Chipping	1	Positive
8440	1	1	003B	Classroom B3	Yes	W2	Concrete Masonry Unit	White	Chipping	1	Negative
8440	1	1	003B	Classroom B3	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	003B	Classroom B3	Yes	W4	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	003B	Classroom B3	Yes	Built-In Lockers/Shelf	Wood	Blue	Chipping	1	Negative
8440	1	1	003B	Classroom B3	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	003B	Classroom B3	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	B3A	Classroom B3 Closet	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	B3A	Classroom B3 Closet	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	B3A	Classroom B3 Closet	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	B3A	Classroom B3 Closet	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	B3A	Classroom B3 Closet	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	B3A	Classroom B3 Closet	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	B3A	Classroom B3 Closet	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	B3B	Classroom B3 Boy's Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	B3B	Classroom B3 Boy's Restroom	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	B3B	Classroom B3 Boy's Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	B3B	Classroom B3 Boy's Restroom	Yes	Pipe Fitting Cover	Plastic	White	None	0	Positive
8440	1	1	B3B	Classroom B3 Boy's Restroom	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	B3B	Classroom B3 Boy's Restroom	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	B3B	Classroom B3 Boy's Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	B3B	Classroom B3 Boy's Restroom	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	B3C	Classroom B3 Girl's Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	B3C	Classroom B3 Girl's Restroom	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	B3C	Classroom B3 Girl's Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	B3C	Classroom B3 Girl's Restroom	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	B3C	Classroom B3 Girl's Restroom	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	B3C	Classroom B3 Girl's Restroom	Yes	Pipe Fitting Cover	Plastic	White	Chipping	1	Positive
8440	1	1	B3C	Classroom B3 Girl's Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	B3C	Classroom B3 Girl's Restroom	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	004B	Classroom B4	Yes	W1	Concrete Masonry Unit	White	Chipping	1	Negative
8440	1	1	004B	Classroom B4	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	004B	Classroom B4	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	004B	Classroom B4	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	004B	Classroom B4	Yes	Radiator	Metal	Blue	Fricition, Chipping	1	Negative
8440	1	1	004B	Classroom B4	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	004B	Classroom B4	Yes	Built-In Lockers/Shelf	Wood	Blue	Chipping	1	Negative
8440	1	1	004B	Classroom B4	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	004B	Classroom B4	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	B4A	Classroom B4 Closet	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	B4A	Classroom B4 Closet	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	B4A	Classroom B4 Closet	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	B4A	Classroom B4 Closet	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	B4A	Classroom B4 Closet	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	B4A	Classroom B4 Closet	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	B4A	Classroom B4 Closet	Yes	Floor	N/A	N/A	None	0	N/A



				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	B4B	Classroom B4 Boy's Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	B4B	Classroom B4 Boy's Restroom	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	B4B	Classroom B4 Boy's Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	B4B	Classroom B4 Boy's Restroom	Yes	Pipe Fitting Cover	Plastic	White	Flaking	1	Positive
8440	1	1	B4B	Classroom B4 Boy's Restroom	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	B4B	Classroom B4 Boy's Restroom	Yes	Pipe	Metal	White	Efflorescence, Chipping	1	Negative
8440	1	1	B4B	Classroom B4 Boy's Restroom	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	B4B	Classroom B4 Boy's Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	B4B	Classroom B4 Boy's Restroom	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	B4C	Classroom B4 Girl's Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	B4C	Classroom B4 Girl's Restroom	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	B4C	Classroom B4 Girl's Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	B4C	Classroom B4 Girl's Restroom	Yes	Pipe	Fiberglass Wrap	White	Flaking, Chipping	1	Negative
8440	1	1	B4C	Classroom B4 Girl's Restroom	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	B4C	Classroom B4 Girl's Restroom	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	B4C	Classroom B4 Girl's Restroom	Yes	Pipe Fitting Cover	Plastic	White	Chipping	1	Positive
8440	1	1	B4C	Classroom B4 Girl's Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	B4C	Classroom B4 Girl's Restroom	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	005B	Classroom B5	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	005B	Classroom B5	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	005B	Classroom B5	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	005B	Classroom B5	Yes	Built-In Locker/Shelf	Wood	Blue	Chipping	2	Negative
8440	1	1	005B	Classroom B5	Yes	W3	Concrete Masonry Unit	White	Chipping	1	Negative
8440	1	1	005B	Classroom B5	Yes	Radiator	Metal	Blue	Chipping, Friction	2	Negative
8440	1	1	005B	Classroom B5	Yes	Univent	Metal	Blue	Chipping	1	Negative
8440	1	1	005B	Classroom B5	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	005B	Classroom B5	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	005B	Classroom B5	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	B5A	Classroom B5 Closet	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	B5A	Classroom B5 Closet	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	B5A	Classroom B5 Closet	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	B5A	Classroom B5 Closet	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	B5A	Classroom B5 Closet	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	B5A	Classroom B5 Closet	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	B5A	Classroom B5 Closet	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	B5B	Classroom B5 Boy's Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	B5B	Classroom B5 Boy's Restroom	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	B5B	Classroom B5 Boy's Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	B5B	Classroom B5 Boy's Restroom	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	B5B	Classroom B5 Boy's Restroom	Yes	Pipe Fitting Cover	Plastic	White	Flaking	1	Positive
8440	1	1	B5B	Classroom B5 Boy's Restroom	Yes	W4	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	B5B	Classroom B5 Boy's Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	B5B	Classroom B5 Boy's Restroom	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	B5C	Classroom B5 Girl's Restroom	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	B5C	Classroom B5 Girl's Restroom	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	B5C	Classroom B5 Girl's Restroom	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	B5C	Classroom B5 Girl's Restroom	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	B5C	Classroom B5 Girl's Restroom	Yes	Pipe Fitting Cover	Plastic	White	Chipping	1	Positive
8440	1	1	B5C	Classroom B5 Girl's Restroom	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	B5C	Classroom B5 Girl's Restroom	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	B5C	Classroom B5 Girl's Restroom	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	020B	Mechanical Room adjacent to Classroom B6 (Roof Hatch Room in B Wing Entrance)	No	W1	No Access	No Access	No Access	No Access	No Access
8440	1	1	020B	Mechanical Room adjacent to Classroom B6 (Roof Hatch Room in B Wing Entrance)	No	W2	No Access	No Access	No Access	No Access	No Access
8440	1	1	020B	Mechanical Room adjacent to Classroom B6 (Roof Hatch Room in B Wing Entrance)	No	W3	No Access	No Access	No Access	No Access	No Access
8440	1	1	020B	Mechanical Room adjacent to Classroom B6 (Roof Hatch Room in B Wing Entrance)	No	W4	No Access	No Access	No Access	No Access	No Access
8440	1	1	020B	Mechanical Room adjacent to Classroom B6 (Roof Hatch Room in B Wing Entrance)	No	Ceiling	No Access	No Access	No Access	No Access	No Access
8440	1	1	020B	Mechanical Room adjacent to Classroom B6 (Roof Hatch Room in B Wing Entrance)	No	Floor	No Access	No Access	No Access	No Access	No Access
8440	1	1	018B	B-12	Yes	W1	Concrete Masonry Unit	Yellow	Spalling	1	Negative
8440	1	1	018B	B-12	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	018B	B-12	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	018B	B-12	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	018B	B-12	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	018B	B-12	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	018B	B-12	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	006B	Classroom B6	Yes	W1	Concrete Masonry Unit	White	Chipping	1	Negative
8440	1	1	006B	Classroom B6	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	1	006B	Classroom B6	Yes	Coat Rack	Wood	White	Chipping	1	Negative
8440	1	1	006B	Classroom B6	Yes	Shelf	Wood	White	Chipping	1	Negative
8440	1	1	006B	Classroom B6	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	006B	Classroom B6	Yes	W3	Concrete Masonry Unit	White	Efflorescence, Cracking, Chipping, Friction	2	Negative
8440	1	1	006B	Classroom B6	Yes	Radiator	Metal	Blue	Friction	1	Negative
8440	1	1	006B	Classroom B6	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	006B	Classroom B6	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	006B	Classroom B6	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	007B	Classroom B7	Yes	W1	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	007B	Classroom B7	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	1	007B	Classroom B7	Yes	Shelf	Wood	White	Chipping	1	Negative
8440	1	1	007B	Classroom B7	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	007B	Classroom B7	Yes	W3	Concrete Masonry Unit	White	Chipping, Spalling	1	Negative
8440	1	1	007B	Classroom B7	Yes	Radiator	Metal	Blue	Chipping	1	Negative
8440	1	1	007B	Classroom B7	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	007B	Classroom B7	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	007B	Classroom B7	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	008B	Classroom B8	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	008B	Classroom B8	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	1	008B	Classroom B8	Yes	W2	Concrete Masonry Unit	White	Chipping	1	Negative
8440	1	1	008B	Classroom B8	Yes	W3	Concrete Masonry Unit	White	Efflorescence, Flaking	4	Negative
8440	1	1	008B	Classroom B8	Yes	Radiator	Metal	Blue	Chipping	1	Negative
8440	1	1	008B	Classroom B8	Yes	Univent	Metal	Blue	Chipping	1	Negative
8440	1	1	008B	Classroom B8	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	008B	Classroom B8	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	008B	Classroom B8	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	009B	Classroom B9	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	009B	Classroom B9	Yes	Door Frame	Metal	Blue	Chipping	3	Negative
8440	1	1	009B	Classroom B9	Yes	Shelf	Wood	White	Chipping	1	Negative
8440	1	1	009B	Classroom B9	Yes	Coat Rack	Wood	White	Chipping	1	Negative
8440	1	1	009B	Classroom B9	Yes	W2	N/A	N/A	None	0	N/A
8440	1	1	009B	Classroom B9	Yes	W3	Concrete Masonry Unit	White	Flaking	4	Negative
8440	1	1	009B	Classroom B9	Yes	Radiator	Metal	Blue	Chipping, Friction	1	Negative
8440	1	1	009B	Classroom B9	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	009B	Classroom B9	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	009B	Classroom B9	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	BR3	Girl's Restroom near Classroom 216	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	BR3	Girl's Restroom near Classroom 216	Yes	Door	Wood	Blue	Chipping	5	Negative
8440	1	2	BR3	Girl's Restroom near Classroom 216	Yes	Door Frame	Metal	Blue	Chipping	8	Negative
8440	1	2	BR3	Girl's Restroom near Classroom 216	Yes	Stall	Metal	Peach, Blue	Chipping	20	Negative
8440	1	2	BR3	Girl's Restroom near Classroom 216	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	BR3	Girl's Restroom near Classroom 216	Yes	W3	Concrete Masonry Unit	White, Gray	Chipping, Friction	10	Negative
8440	1	2	BR3	Girl's Restroom near Classroom 216	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	BR3	Girl's Restroom near Classroom 216	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	BR3	Girl's Restroom near Classroom 216	Yes	Floor	Concrete	Gray	Chipping, Friction	10	Negative
8440	1	2	BR4	Boy's Restroom near Classroom 216	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	BR4	Boy's Restroom near Classroom 216	Yes	Door	Wood	Blue	Chipping	5	Negative
8440	1	2	BR4	Boy's Restroom near Classroom 216	Yes	Door Frame	Metal	Blue	Chipping	5	Negative

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	2	BR4	Boy's Restroom near Classroom 216	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	BR4	Boy's Restroom near Classroom 216	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	BR4	Boy's Restroom near Classroom 216	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	BR4	Boy's Restroom near Classroom 216	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	BR4	Boy's Restroom near Classroom 216	Yes	Floor	Concrete	Gray	Chipping, Friction	5	Negative
8440	1	2	SC216	Custodial Closet by Classroom 216	no	W1	N/A	N/A	None	0	N/A
8440	1	2	SC216	Custodial Closet by Classroom 216	no	Door	Wood	Blue	Chipping	10	Negative
8440	1	2	SC216	Custodial Closet by Classroom 216	no	Door Frame	Metal	Blue, Green	Chipping	5	Negative
8440	1	2	SC216	Custodial Closet by Classroom 216	no	W2	N/A	N/A	None	0	N/A
8440	1	2	SC216	Custodial Closet by Classroom 216	no	W3	N/A	N/A	None	0	N/A
8440	1	2	SC216	Custodial Closet by Classroom 216	no	W4	N/A	N/A	None	0	N/A
8440	1	2	SC216	Custodial Closet by Classroom 216	no	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	SC216	Custodial Closet by Classroom 216	no	Floor	N/A	N/A	None	0	N/A
8440	1	2	BR212	Women's Restroom (by Classroom 212)	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	BR212	Women's Restroom (by Classroom 212)	Yes	Door	Wood	Blue	Chipping	3	Negative
8440	1	2	BR212	Women's Restroom (by Classroom 212)	Yes	Door Frame	Metal	Blue	Chipping	4	Negative
8440	1	2	BR212	Women's Restroom (by Classroom 212)	Yes	Stall	Metal	Yellow	Moisture Damage, Chipping	5	Negative
8440	1	2	BR212	Women's Restroom (by Classroom 212)	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	BR212	Women's Restroom (by Classroom 212)	Yes	W3	Concrete Masonry Unit	White	Chipping	3	Negative
8440	1	2	BR212	Women's Restroom (by Classroom 212)	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	BR212	Women's Restroom (by Classroom 212)	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	BR212	Women's Restroom (by Classroom 212)	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	BR212A	Men's Restroom (by Classroom 212)	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	BR212A	Men's Restroom (by Classroom 212)	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	2	BR212A	Men's Restroom (by Classroom 212)	Yes	Door Frame	Metal	Blue	Chipping	4	Negative
8440	1	2	BR212A	Men's Restroom (by Classroom 212)	Yes	Stall	Metal	Green	Moisture Damage, Chipping	3	Negative
8440	1	2	BR212A	Men's Restroom (by Classroom 212)	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	BR212A	Men's Restroom (by Classroom 212)	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	2	BR212A	Men's Restroom (by Classroom 212)	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	BR212A	Men's Restroom (by Classroom 212)	Yes	W4	Concrete Masonry Unit	White	Spalling	1	Negative
8440	1	2	BR212A	Men's Restroom (by Classroom 212)	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	BR212A	Men's Restroom (by Classroom 212)	Yes	Floor	Concrete	Gray	Chipping	4	Negative
8440	1	1	HB12	Hallway next to B12	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	HB12	Hallway next to B12	Yes	Door	Metal	Blue	Chipping	1	Negative
8440	1	1	HB12	Hallway next to B12	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	HB12	Hallway next to B12	Yes	W2	Concrete Masonry Unit	White	Cracked	1	Negative
8440	1	1	HB12	Hallway next to B12	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	HB12	Hallway next to B12	Yes	Door Frame	Metal	Red	Friction, Chipping	1	Negative
8440	1	1	HB12	Hallway next to B12	Yes	W4	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	1	HB12	Hallway next to B12	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	HB12	Hallway next to B12	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	1	SCB12	Custodial Closet by B12	no	W1	N/A	N/A	None	0	N/A
8440	1	1	SCB12	Custodial Closet by B12	no	Door	Metal	Blue	Chipping	1	Negative
8440	1	1	SCB12	Custodial Closet by B12	no	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	1	SCB12	Custodial Closet by B12	no	W2	N/A	N/A	None	0	N/A
8440	1	1	SCB12	Custodial Closet by B12	no	W3	N/A	N/A	None	0	N/A
8440	1	1	SCB12	Custodial Closet by B12	no	W4	N/A	N/A	None	0	N/A
8440	1	1	SCB12	Custodial Closet by B12	no	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	SCB12	Custodial Closet by B12	no	Floor	N/A	N/A	None	0	N/A
8440	1	1	H11	Hallway from Classrooms B6 to B9	Yes	W1	N/A	N/A	None	0	N/A
8440	1	1	H11	Hallway from Classrooms B6 to B9	Yes	Door Frame	Metal	Blue	Chipping, Cracking	1	Negative
8440	1	1	H11	Hallway from Classrooms B6 to B9	Yes	W2	Concrete Masonry Unit	White	Chipping	2	Negative
8440	1	1	H11	Hallway from Classrooms B6 to B9	Yes	W3	N/A	N/A	None	0	N/A
8440	1	1	H11	Hallway from Classrooms B6 to B9	Yes	W4	N/A	N/A	None	0	N/A
8440	1	1	H11	Hallway from Classrooms B6 to B9	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	1	H11	Hallway from Classrooms B6 to B9	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	H201	Hallway from Classrooms 201 to 210	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	H201	Hallway from Classrooms 201 to 210	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	H201	Hallway from Classrooms 201 to 210	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	H201	Hallway from Classrooms 201 to 210	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	H201	Hallway from Classrooms 201 to 210	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	H201	Hallway from Classrooms 201 to 210	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	H212	Hallway outside Classroom 212	Yes	W1	Concrete Masonry Unit	White	Chipping	2	Negative
8440	1	2	H212	Hallway outside Classroom 212	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	H212	Hallway outside Classroom 212	Yes	Door	Metal	Blue	Chipping	1	Negative
8440	1	2	H212	Hallway outside Classroom 212	Yes	Door Frame	Metal	Blue	Chipping	3	Negative
8440	1	2	H212	Hallway outside Classroom 212	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	H212	Hallway outside Classroom 212	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	H212	Hallway outside Classroom 212	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	H212	Hallway outside Classroom 212	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	200	Classroom 200	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	200	Classroom 200	Yes	Door	Wood	Blue	Chipping	2	Negative
8440	1	2	200	Classroom 200	Yes	Door Frame	Metal	Blue	Chipping	4	Negative
8440	1	2	200	Classroom 200	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	200	Classroom 200	Yes	Coat Rack	Wood	White	Chipping	2	Negative
8440	1	2	200	Classroom 200	Yes	Shelf	Metal	White	Chipping	1	Negative
8440	1	2	200	Classroom 200	Yes	Shelf Support	Metal	White	Chipping	2	Negative
8440	1	2	200	Classroom 200	Yes	Support Post	Metal	Blue	Chipping	3	Positive
8440	1	2	200	Classroom 200	Yes	Closet Door	Metal	Pink	Chipping	1	Negative
8440	1	2	200	Classroom 200	Yes	W3	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	2	200	Classroom 200	Yes	Univent	Metal	Blue	Chipping	1	Negative
8440	1	2	200	Classroom 200	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	200	Classroom 200	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	200	Classroom 200	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	201	Classroom 201	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	201	Classroom 201	Yes	Door	Wood	Blue	Chipping	2	Negative
8440	1	2	201	Classroom 201	Yes	Door Frame	Metal	Blue	Chipping	3	Negative
8440	1	2	201	Classroom 201	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	201	Classroom 201	Yes	Coat Rack	Wood	White	Chipping	3	Negative
8440	1	2	201	Classroom 201	Yes	Shelf	Metal	White	Chipping	1	Negative
8440	1	2	201	Classroom 201	Yes	Shelf Support	Metal	White	Chipping	3	Negative
8440	1	2	201	Classroom 201	Yes	Support Post	Metal	Blue	Chipping	2	Positive
8440	1	2	201	Classroom 201	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	201	Classroom 201	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	201	Classroom 201	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	201	Classroom 201	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	202	Classroom 202	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	202	Classroom 202	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	2	202	Classroom 202	Yes	Door Frame	Metal	Blue	Chipping	4	Negative
8440	1	2	202	Classroom 202	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	202	Classroom 202	Yes	Coat Rack	Wood	White	Chipping	8	Negative
8440	1	2	202	Classroom 202	Yes	Shelf	Metal	White	Chipping	3	Negative
8440	1	2	202	Classroom 202	Yes	Shelf Support	Metal	White	Chipping	4	Negative
8440	1	2	202	Classroom 202	Yes	Support Post	Metal	Blue	Chipping	4	Positive
8440	1	2	202	Classroom 202	Yes	Door Frame	Metal	Pink	Chipping	1	Negative
8440	1	2	202	Classroom 202	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	202	Classroom 202	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	202	Classroom 202	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	202	Classroom 202	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	203	Classroom 203	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	203	Classroom 203	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	2	203	Classroom 203	Yes	Door Frame	Metal	Blue	Chipping	4	Negative
8440	1	2	203	Classroom 203	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	203	Classroom 203	Yes	Support Post	Metal	Tan	Chipping	1	Positive
8440	1	2	203	Classroom 203	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	203	Classroom 203	Yes	Univent	Metal	Blue	Chipping	1	Negative
8440	1	2	203	Classroom 203	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	203	Classroom 203	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	203	Classroom 203	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	204	Classroom 204	Yes	W1	N/A	White	None	0	N/A
8440	1	2	204	Classroom 204	Yes	Door	Wood	Blue	Chipping	2	Negative
8440	1	2	204	Classroom 204	Yes	Door Frame	Metal	Blue	Chipping	3	Negative

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	2	204	Classroom 204	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	204	Classroom 204	Yes	Support Post	Metal	Blue	Chipping	4	Positive
8440	1	2	204	Classroom 204	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	204	Classroom 204	Yes	Univent	Metal	Blue	Chipping	2	Negative
8440	1	2	204	Classroom 204	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	204	Classroom 204	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	204	Classroom 204	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	205	Classroom 205	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	205	Classroom 205	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	2	205	Classroom 205	Yes	Door Frame	Metal	Blue	Chipping	3	Negative
8440	1	2	205	Classroom 205	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	205	Classroom 205	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	205	Classroom 205	Yes	Univent	Metal	Blue	Chipping	2	Negative
8440	1	2	205	Classroom 205	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	205	Classroom 205	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	205	Classroom 205	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	206	Classroom 206	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	206	Classroom 206	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	2	206	Classroom 206	Yes	Shelf	Metal	White	Chipping	1	Negative
8440	1	2	206	Classroom 206	Yes	Shelf Support	Metal	White	Flaking	1	Negative
8440	1	2	206	Classroom 206	Yes	Closet Door	Metal	Pink	Chipping	1	Negative
8440	1	2	206	Classroom 206	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	206	Classroom 206	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	206	Classroom 206	Yes	Univent	Metal	Blue	Chipping, Friction	2	Negative
8440	1	2	206	Classroom 206	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	206	Classroom 206	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	206	Classroom 206	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	S24 (S2)	Stairwell between Classrooms 205 and 207	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	S24 (S2)	Stairwell between Classrooms 205 and 207	Yes	Door	Metal	Blue	Chipping	15	Negative
8440	1	2	S24 (S2)	Stairwell between Classrooms 205 and 207	Yes	Door Frame	Metal	Blue	Chipping	5	Negative
8440	1	2	S24 (S2)	Stairwell between Classrooms 205 and 207	Yes	W2	Concrete Masonry Unit	Green, White	Chipping	3	Negative
8440	1	2	S24 (S2)	Stairwell between Classrooms 205 and 207	Yes	Stair Railing	Metal	White	Chipping	5	Negative
8440	1	2	S24 (S2)	Stairwell between Classrooms 205 and 207	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	S24 (S2)	Stairwell between Classrooms 205 and 207	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	S24 (S2)	Stairwell between Classrooms 205 and 207	Yes	Baseboard	Metal	Gray	Chipping	1	Positive
8440	1	2	S24 (S2)	Stairwell between Classrooms 205 and 207	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	S24 (S2)	Stairwell between Classrooms 205 and 207	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	S24 (S2)	Stairwell between Classrooms 205 and 207	Yes	Stair Riser	Metal	Gray	Chipping	1	Positive
8440	1	2	S24 (S2)	Stairwell between Classrooms 205 and 207	Yes	Stair Stringer	Metal	White	Chipping	4	Negative
8440	1	2	S1	Stairwell by 201	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	S1	Stairwell by 201	Yes	Door	Metal	Blue	Chipping	10	Negative
8440	1	2	S1	Stairwell by 201	Yes	Door Frame	Metal	Blue	Chipping	1	Negative

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
8440	1	2	S1	Stairwell by 201	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	S1	Stairwell by 201	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	S1	Stairwell by 201	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	S1	Stairwell by 201	Yes	Baseboard	Metal	Gray	Chipping	15	Negative
8440	1	2	S1	Stairwell by 201	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	S1	Stairwell by 201	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	S1	Stairwell by 201	Yes	Stair Riser	Metal	Gray	Chipping	2	Positive
8440	1	2	S1	Stairwell by 201	Yes	Stair Stringer	Metal	Gray	Chipping	1	Negative
8440	1	2	S1	Stairwell by 201	Yes	Stair Railing	Metal	White	Chipping, Friction	10	Negative
8440	1	2	S3	Stairwell between Classrooms 212 and 214	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	S3	Stairwell between Classrooms 212 and 214	Yes	Door	Metal	Blue	Chipping	15	Negative
8440	1	2	S3	Stairwell between Classrooms 212 and 214	Yes	Door Frame	Metal	Blue	Chipping	7	Negative
8440	1	2	S3	Stairwell between Classrooms 212 and 214	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	S3	Stairwell between Classrooms 212 and 214	Yes	Stair Railing	Metal	White	Chipping	6	Negative
8440	1	2	S3	Stairwell between Classrooms 212 and 214	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	S3	Stairwell between Classrooms 212 and 214	Yes	Baseboard	Metal	Gray	Chipping	12	Positive
8440	1	2	S3	Stairwell between Classrooms 212 and 214	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	S3	Stairwell between Classrooms 212 and 214	Yes	Stair Stringer	Metal	White	Chipping	1	Negative
8440	1	2	S3	Stairwell between Classrooms 212 and 214	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	S3	Stairwell between Classrooms 212 and 214	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	S4	Stairwell by Classroom 221	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	S4	Stairwell by Classroom 221	Yes	Door	Metal	Blue	Chipping	10	Negative
8440	1	2	S4	Stairwell by Classroom 221	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	2	S4	Stairwell by Classroom 221	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	S4	Stairwell by Classroom 221	Yes	Stair Stringer	Metal	White	Chipping	2	Negative
8440	1	2	S4	Stairwell by Classroom 221	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	S4	Stairwell by Classroom 221	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	S4	Stairwell by Classroom 221	Yes	Baseboard	Metal	Gray	Friction	10	Positive
8440	1	2	S4	Stairwell by Classroom 221	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	S4	Stairwell by Classroom 221	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	S4	Stairwell by Classroom 221	Yes	Stair Railing	Metal	White	Chipping	5	Negative
8440	1	2	S4	Stairwell by Classroom 221	Yes	Stair Riser	Metal	Gray	Chipping, Moisture Damage	5	Negative
8440	1	2	S5	Stairwell by Classroom 224	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	S5	Stairwell by Classroom 224	Yes	Door	Metal	Blue	Chipping	10	Negative
8440	1	2	S5	Stairwell by Classroom 224	Yes	Door Frame	Metal	Blue	Chipping	5	Negative
8440	1	2	S5	Stairwell by Classroom 224	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	S5	Stairwell by Classroom 224	Yes	Baseboard	Metal	Gray	Chipping, Friction	10	Negative
8440	1	2	S5	Stairwell by Classroom 224	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	S5	Stairwell by Classroom 224	Yes	Door	Metal	Blue	Chipping	2	Positive
8440	1	2	S5	Stairwell by Classroom 224	Yes	Door Frame	Metal	Blue	Chipping	4	Negative
8440	1	2	S5	Stairwell by Classroom 224	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	S5	Stairwell by Classroom 224	Yes	Stair Railing	Metal	White	Chipping	5	Negative



				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	2	S5	Stairwell by Classroom 224	Yes	Stair Stringer	Metal	White	Chipping	5	Negative
8440	1	2	S5	Stairwell by Classroom 224	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	S5	Stairwell by Classroom 224	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	S5	Stairwell by Classroom 224	Yes	Stair Riser	Metal	Gray	Chipping, Moisture Damage	5	Negative
8440	1	2	207	Classroom 207	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	207	Classroom 207	Yes	Door	Wood	Blue	Chipping	3	Negative
8440	1	2	207	Classroom 207	Yes	Door Frame	Metal	Blue	Chipping	3	Negative
8440	1	2	207	Classroom 207	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	207	Classroom 207	Yes	Coat Rack	Wood	White	Chipping	7	Negative
8440	1	2	207	Classroom 207	Yes	Shelf	Metal	White	Chipping	2	Negative
8440	1	2	207	Classroom 207	Yes	Shelf Support	Metal	White	Chipping	4	Negative
8440	1	2	207	Classroom 207	Yes	Support Post	Metal	Blue	Chipping	3	Positive
8440	1	2	207	Classroom 207	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	207	Classroom 207	Yes	Univent	Metal	Blue	Chipping	4	Negative
8440	1	2	207	Classroom 207	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	207	Classroom 207	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	207	Classroom 207	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	208	Classroom 208	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	208	Classroom 208	Yes	Door Frame	Metal	Blue	Chipping	6	Negative
8440	1	2	208	Classroom 208	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	208	Classroom 208	Yes	Coat Rack	Wood	White	Chipping	2	Negative
8440	1	2	208	Classroom 208	Yes	Shelf	Metal	White	Chipping	1	Negative
8440	1	2	208	Classroom 208	Yes	Shelf Support	Metal	White	Chipping	2	Negative
8440	1	2	208	Classroom 208	Yes	Support Post	Metal	Blue	Chipping	5	Positive
8440	1	2	208	Classroom 208	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	208	Classroom 208	Yes	Univent	Metal	Blue	Chipping	2	Negative
8440	1	2	208	Classroom 208	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	208	Classroom 208	Yes	Pipe	Metal	White	Chipping	1	Negative
8440	1	2	208	Classroom 208	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	208	Classroom 208	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	209	Classroom 209	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	209	Classroom 209	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	2	209	Classroom 209	Yes	Door Frame	Metal	Blue	Chipping	6	Negative
8440	1	2	209	Classroom 209	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	209	Classroom 209	Yes	Coat Rack	Wood	White	Chipping	12	Negative
8440	1	2	209	Classroom 209	Yes	Shelf	Metal	White	Chipping	4	Negative
8440	1	2	209	Classroom 209	Yes	Shelf Support	Metal	White	Chipping	3	Negative
8440	1	2	209	Classroom 209	Yes	Support Post	Metal	Blue	Chipping	4	Positive
8440	1	2	209	Classroom 209	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	209	Classroom 209	Yes	Univent	Metal	Blue	Chipping	1	Negative
8440	1	2	209	Classroom 209	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	209	Classroom 209	Yes	Ceiling	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	2	209	Classroom 209	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	209XA	Room Across from Classroom 209	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	209XA	Room Across from Classroom 209	Yes	Door Frame	Metal	Blue	Chipping	4	Negative
8440	1	2	209XA	Room Across from Classroom 209	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	209XA	Room Across from Classroom 209	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	209XA	Room Across from Classroom 209	Yes	Univent	Metal	Blue	Chipping	3	Negative
8440	1	2	209XA	Room Across from Classroom 209	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	209XA	Room Across from Classroom 209	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	209XA	Room Across from Classroom 209	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	210	Classroom 210	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	210	Classroom 210	Yes	Door	Wood	Blue	Chipping	3	Negative
8440	1	2	210	Classroom 210	Yes	Door Frame	Metal	Blue	Chipping	6	Negative
8440	1	2	210	Classroom 210	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	210	Classroom 210	Yes	Coat Rack	Wood	White	Chipping	10	Negative
8440	1	2	210	Classroom 210	Yes	Shelf	Metal	White	Chipping	4	Negative
8440	1	2	210	Classroom 210	Yes	Shelf Support	Metal	White	Chipping	6	Negative
8440	1	2	210	Classroom 210	Yes	Support Post	Metal	Blue	Chipping	5	Positive
8440	1	2	210	Classroom 210	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	210	Classroom 210	Yes	W4	Concrete Masonry Unit	White	None	0	N/A
8440	1	2	210	Classroom 210	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	210	Classroom 210	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	210A	Classroom 210A	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	210A	Classroom 210A	yes	Door Frame	Metal	Green	Chipping	8	Negative
8440	1	2	210A	Classroom 210A	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	210A	Classroom 210A	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	210A	Classroom 210A	Yes	W4	Concrete Masonry Unit	White	None	0	N/A
8440	1	2	210A	Classroom 210A	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	210A	Classroom 210A	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	211	Classroom 211	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	211	Classroom 211	Yes	Door	Wood	Blue	Chipping	3	Negative
8440	1	2	211	Classroom 211	Yes	Door Frame	Metal	Blue	Chipping	5	Negative
8440	1	2	211	Classroom 211	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	211	Classroom 211	Yes	Coat Rack	Wood	White	Chipping	4	Negative
8440	1	2	211	Classroom 211	Yes	Shelf	Metal	White	Chipping	3	Negative
8440	1	2	211	Classroom 211	Yes	Shelf Support	Metal	White	Chipping	12	Negative
8440	1	2	211	Classroom 211	Yes	Support Post	Metal	Blue	Chipping	5	Positive
8440	1	2	211	Classroom 211	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	211	Classroom 211	Yes	Univent	Metal	Blue	Chipping	2	Negative
8440	1	2	211	Classroom 211	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	211	Classroom 211	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	211	Classroom 211	Yes	Floor	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
8440	1	2	212	Classroom 212	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	212	Classroom 212	Yes	Door	Wood	Blue	Chipping	3	Negative
8440	1	2	212	Classroom 212	Yes	Door Frame	Metal	Blue	Chipping	3	Negative
8440	1	2	212	Classroom 212	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	212	Classroom 212	Yes	Closet Door	Metal	Pink	Chipping	2	Negative
8440	1	2	212	Classroom 212	Yes	Coat Rack	Wood	White	Chipping	8	Negative
8440	1	2	212	Classroom 212	Yes	Shelf	Metal	White	Chipping	5	Negative
8440	1	2	212	Classroom 212	Yes	Shelf Support	Metal	White	Chipping	6	Negative
8440	1	2	212	Classroom 212	Yes	Support Post	Metal	Blue	Chipping	7	Positive
8440	1	2	212	Classroom 212	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	212	Classroom 212	Yes	Univent	Metal	Blue	Chipping	5	Negative
8440	1	2	212	Classroom 212	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	212	Classroom 212	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	212	Classroom 212	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	214	Classroom 214	Yes	W1	Concrete Masonry Unit	White	Spalling	5	Negative
8440	1	2	214	Classroom 214	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	2	214	Classroom 214	Yes	Door Frame	Metal	Blue	Chipping	4	Negative
8440	1	2	214	Classroom 214	Yes	Built-In Shelves	Wood	Red	Chipping	1	Negative
8440	1	2	214	Classroom 214	Yes	Built-In Shelves	Wood	White	Peeling, Chipping	3	Negative
8440	1	2	214	Classroom 214	Yes	Sink Cabinet	Metal	Pink	Chipping	5	Negative
8440	1	2	214	Classroom 214	Yes	W2	Concrete Masonry Unit	White	Chipping	2	Negative
8440	1	2	214	Classroom 214	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	214	Classroom 214	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	214	Classroom 214	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	214	Classroom 214	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	214A	Bathroom in Classroom 214	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	214A	Bathroom in Classroom 214	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	214A	Bathroom in Classroom 214	Yes	Door Frame	Metal	Gray	Chipping	1	Negative
8440	1	2	214A	Bathroom in Classroom 214	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	214A	Bathroom in Classroom 214	Yes	Stall	Metal	Pink	Chipping	1	Negative
8440	1	2	214A	Bathroom in Classroom 214	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	214A	Bathroom in Classroom 214	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	214A	Bathroom in Classroom 214	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	H214	Connector Rear Hallway between Classrooms 214 and 215	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	H214	Connector Rear Hallway between Classrooms 214 and 215	Yes	Door	Wood	Blue	Chipping	10	Positive
8440	1	2	H214	Connector Rear Hallway between Classrooms 214 and 215	Yes	Door Frame	Metal	Blue	Chipping	12	Positive
8440	1	2	H214	Connector Rear Hallway between Classrooms 214 and 215	Yes	W2	N/A	N/A	None	0	N/A

				2/7 - 2/16/22	<b>Lead Safe Certification Assessment Report</b>						
				Inspector Name and Certificate Number: Charles Rhodes 003542	<b>Loesche School</b>						
				Inspection Company: Batta	<b>595 Tomlinson Rd, Philadelphia, PA 19116</b>						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	2	H214	Connector Rear Hallway between Classrooms 214 and 215	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	H214	Connector Rear Hallway between Classrooms 214 and 215	Yes	Door Frame	Metal	Gray	Chipping	2	Negative
8440	1	2	H214	Connector Rear Hallway between Classrooms 214 and 215	Yes	W4	Concrete Masorny Unit	Yellow	Cracked	10	Negative
8440	1	2	H214	Connector Rear Hallway between Classrooms 214 and 215	Yes	Door Frame	Metal	Green	Chipping	5	Negative
8440	1	2	H214	Connector Rear Hallway between Classrooms 214 and 215	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	H214	Connector Rear Hallway between Classrooms 214 and 215	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	215	Classroom 215	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	215	Classroom 215	Yes	Door	Wood	Blue	Chipping	2	Negative
8440	1	2	215	Classroom 215	Yes	Door Frame	Metal	Blue	Chipping	2	Negative
8440	1	2	215	Classroom 215	Yes	Built-In Lockers	Wood	Blue	Chipping	8	Negative
8440	1	2	215	Classroom 215	Yes	Sink Cabinet	Metal	Pink	Chipping	3	Negative
8440	1	2	215	Classroom 215	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	215	Classroom 215	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	215	Classroom 215	Yes	Built-In Shelves	Wood	Green	Chipping	1	Negative
8440	1	2	215	Classroom 215	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	215	Classroom 215	Yes	Univent	Metal	Blue	Chipping	1	Negative
8440	1	2	215	Classroom 215	Yes	Radiator	Metal	Blue	Chipping	5	Negative
8440	1	2	215	Classroom 215	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	215	Classroom 215	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	215A	Bathroom in Classroom 215	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	215A	Bathroom in Classroom 215	Yes	Door	Wood	Blue	Chipping	1	Negative
8440	1	2	215A	Bathroom in Classroom 215	Yes	Door Frame	Metal	Blue	Chipping	1	Negative
8440	1	2	215A	Bathroom in Classroom 215	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	215A	Bathroom in Classroom 215	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	215A	Bathroom in Classroom 215	Yes	Radiator	Metal	Tan	Chipping, Moisture Damage	2	Negative
8440	1	2	215A	Bathroom in Classroom 215	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	215A	Bathroom in Classroom 215	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	215A	Bathroom in Classroom 215	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	216	Classroom 216	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	216	Classroom 216	Yes	Door	Wood	Blue	Chipping	5	Negative
8440	1	2	216	Classroom 216	Yes	Door Frame	Metal	Blue	Chipping	5	Negative
8440	1	2	216	Classroom 216	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	216	Classroom 216	Yes	Support Post	Metal	Blue	Chipping	5	Positive
8440	1	2	216	Classroom 216	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	216	Classroom 216	Yes	Univent	Metal	Blue	Chipping	2	Negative
8440	1	2	216	Classroom 216	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	216	Classroom 216	Yes	Ceiling	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	2	216	Classroom 216	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	217	Classroom 217	Yes	W1	Concrete Masonry Unit	White	Chipping	1	Negative
8440	1	2	217	Classroom 217	Yes	Door	Wood	Blue	Chipping	3	Negative
8440	1	2	217	Classroom 217	Yes	Door Frame	Metal	Blue	Chipping	15	Negative
8440	1	2	217	Classroom 217	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	217	Classroom 217	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	217	Classroom 217	Yes	Univent	Metal	Blue	Chipping	4	Negative
8440	1	2	217	Classroom 217	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	217	Classroom 217	Yes	Support Post	Metal	Blue	Chipping	10	Positive
8440	1	2	217	Classroom 217	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	217	Classroom 217	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	218	Classroom 218	Yes	W1	Concrete Masonry Unit	White	Spalling	1	Negative
8440	1	2	218	Classroom 218	Yes	Door	Wood	Blue	Chipping	3	Negative
8440	1	2	218	Classroom 218	Yes	Door Frame	Metal	Blue	Chipping	10	Negative
8440	1	2	218	Classroom 218	Yes	Door Panel	Wood	Blue	Chipping	3	Negative
8440	1	2	218	Classroom 218	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	218	Classroom 218	Yes	Coat Rack	Wood	White	Chipping	22	Negative
8440	1	2	218	Classroom 218	Yes	Shelf	Metal	White	Chipping	10	Negative
8440	1	2	218	Classroom 218	Yes	Shelf Support	Metal	White	Chipping	8	Negative
8440	1	2	218	Classroom 218	Yes	Support Post	Metal	Blue	Chipping	3	Positive
8440	1	2	218	Classroom 218	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	218	Classroom 218	Yes	Univent	Metal	Blue	Chipping	5	Negative
8440	1	2	218	Classroom 218	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	218	Classroom 218	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	218	Classroom 218	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	219	Classroom 219	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	219	Classroom 219	Yes	Door Frame	Metal	Blue	Chipping	10	Negative
8440	1	2	219	Classroom 219	Yes	Door	Wood	Blue	Chipping	3	Negative
8440	1	2	219	Classroom 219	Yes	Door Panel	Wood	Blue	Chipping	2	Negative
8440	1	2	219	Classroom 219	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	219	Classroom 219	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	219	Classroom 219	Yes	Univent	Metal	Blue	Flaking	3	Negative
8440	1	2	219	Classroom 219	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	219	Classroom 219	Yes	Closet Door	Metal	Pink	Friction	5	Negative
8440	1	2	219	Classroom 219	Yes	Coat Rack	Wood	White	Chipping	5	Negative
8440	1	2	219	Classroom 219	Yes	Shelf Support	Metal	White	Chipping	2	Negative
8440	1	2	219	Classroom 219	Yes	Shelf	Metal	White	Chipping	2	Negative
8440	1	2	219	Classroom 219	Yes	Support Post	Metal	Blue	Chipping	5	Positive
8440	1	2	219	Classroom 219	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	219	Classroom 219	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	220	Classroom 220	Yes	W1	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		Lead Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Charles Rhodes 003542		Loesche School					
				Inspection Company: Batta		595 Tomlinson Rd, Philadelphia, PA 19116					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	2	220	Classroom 220	Yes	Door Frame	Metal	Blue	Chipping	12	Negative
8440	1	2	220	Classroom 220	Yes	Door	Wood	Blue	Chipping	3	Negative
8440	1	2	220	Classroom 220	Yes	Door Panel	Wood	Blue	Chipping	1	Negative
8440	1	2	220	Classroom 220	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	220	Classroom 220	Yes	Coat Rack	Wood	White	Chipping	26	Negative
8440	1	2	220	Classroom 220	Yes	Shelf	Metal	White	Chipping	13	Negative
8440	1	2	220	Classroom 220	Yes	Shelf Support	Metal	White	Chipping	10	Negative
8440	1	2	220	Classroom 220	Yes	Support Post	Metal	Blue	Chipping	6	Positive
8440	1	2	220	Classroom 220	Yes	Sink Cabinet	Metal	Pink	Friction	2	Negative
8440	1	2	220	Classroom 220	Yes	W3	N/A	N/A	N/A	N/A	N/A
8440	1	2	220	Classroom 220	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	220	Classroom 220	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	220	Classroom 220	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	221	Classroom 221	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	221	Classroom 221	Yes	Door Frame	Metal	Blue	Chipping	12	Negative
8440	1	2	221	Classroom 221	Yes	Door	Wood	Blue	Chipping	3	Negative
8440	1	2	221	Classroom 221	Yes	Door Panel	Wood	Blue	Chipping	8	Negative
8440	1	2	221	Classroom 221	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	221	Classroom 221	Yes	Shelf Support	Metal	White	Chipping	8	Negative
8440	1	2	221	Classroom 221	Yes	Support Post	Metal	Blue	Chipping	6	Negative
8440	1	2	221	Classroom 221	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	221	Classroom 221	Yes	Univent	Metal	Blue	Chipping	4	Negative
8440	1	2	221	Classroom 221	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	221	Classroom 221	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	221	Classroom 221	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	222	Classroom 222	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	222	Classroom 222	Yes	Door Frame	Metal	Blue	Chipping	8	Negative
8440	1	2	222	Classroom 222	Yes	Door	Wood	Blue	Chipping	10	Negative
8440	1	2	222	Classroom 222	Yes	Door Panel	Wood	Blue	Chipping	5	Negative
8440	1	2	222	Classroom 222	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	222	Classroom 222	Yes	Coat Rack	Wood	White	Chipping	21	Negative
8440	1	2	222	Classroom 222	Yes	Shelf Support	Metal	White	Flaking	11	Negative
8440	1	2	222	Classroom 222	Yes	Support Post	Metal	Blue	Chipping	6	Positive
8440	1	2	222	Classroom 222	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	222	Classroom 222	Yes	Univent	Metal	Blue	Chipping	2	Negative
8440	1	2	222	Classroom 222	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	222	Classroom 222	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	222	Classroom 222	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	223	Classroom 223	Yes	W1	N/A	N/A	None	0	N/A
8440	1	2	223	Classroom 223	Yes	Door Frame	Metal	Blue	Chipping	13	Negative
8440	1	2	223	Classroom 223	Yes	Door	Wood	Blue	Chipping	8	Negative
8440	1	2	223	Classroom 223	Yes	Door Panel	Wood	Blue	Chipping	1	Negative
8440	1	2	223	Classroom 223	Yes	W2	N/A	N/A	None	0	N/A

				2/7 - 2/16/22		<b>Lead Safe Certification Assessment Report</b>					
				Inspector Name and Certificate Number: Charles Rhodes 003542		<b>Loesche School</b>					
				Inspection Company: Batta		<b>595 Tomlinson Rd, Philadelphia, PA 19116</b>					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
8440	1	2	223	Classroom 223	Yes	Sink Cabinet	Metal	Pink	Friction	3	Negative
8440	1	2	223	Classroom 223	Yes	Coat Rack	Wood	White	Flaking	8	Negative
8440	1	2	223	Classroom 223	Yes	Shelf Support	Metal	White	Flaking	6	Negative
8440	1	2	223	Classroom 223	Yes	Support Post	Metal	Blue	Chipping	7	Positive
8440	1	2	223	Classroom 223	Yes	Closet Door	Metal	Pink	Chipping	5	Negative
8440	1	2	223	Classroom 223	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	223	Classroom 223	Yes	Univent	Metal	Blue	Chipping	4	Negative
8440	1	2	223	Classroom 223	Yes	W4	Concrete Masonry Unit	White	Flaking	2	Negative
8440	1	2	223	Classroom 223	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	223	Classroom 223	Yes	Floor	N/A	N/A	None	0	N/A
8440	1	2	224	Classroom 224	Yes	W1	Concrete Masonry Unit	White	Chipping	3	Negative
8440	1	2	224	Classroom 224	Yes	Door Frame	Metal	Blue	Chipping	12	Negative
8440	1	2	224	Classroom 224	Yes	Door Panel	Wood	Blue	Chipping	2	Negative
8440	1	2	224	Classroom 224	Yes	W2	N/A	N/A	None	0	N/A
8440	1	2	224	Classroom 224	Yes	Coat Rack	Wood	Tan	Flaking	9	Negative
8440	1	2	224	Classroom 224	Yes	Shelf Support	Metal	Tan	Flaking	7	Negative
8440	1	2	224	Classroom 224	Yes	Closet Door	Metal	Pink	Flaking	3	Negative
8440	1	2	224	Classroom 224	Yes	W3	N/A	N/A	None	0	N/A
8440	1	2	224	Classroom 224	Yes	W4	N/A	N/A	None	0	N/A
8440	1	2	224	Classroom 224	Yes	Ceiling	N/A	N/A	None	0	N/A
8440	1	2	224	Classroom 224	Yes	Floor	N/A	N/A	None	0	N/A