

				Inspection Dates: 12/10-12/20/2021		School District of Philadelphia					
				Inspector Name and Certificate Number: Charles Rhodes, 003542		Lead Safe Certification Assessment Report					
				Inspection Company: Batta		Old Powell (swing space for SLA Beeber students) School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)	
1390	1	1	101	Classroom 101	Baseboard	Terracotta	Blue	Chipping	5	Negative	
1390	1	1	101	Classroom 101	Wire Shelf	Metal	White	Chipping	3	Positive	
1390	1	1	101	Classroom 101	Baseboard	Terracotta	Blue	Chipping	26	Negative	
1390	1	1	101	Classroom 101	Baseboard	Terracotta	Blue	Chipping	8	Negative	
1390	1	1	101	Classroom 101	Baseboard	Terracotta	Tan	Chipping	10	Negative	
1390	1	1	102	Classroom 102	Wire Shelf	Metal	White	Chipping	8	Positive	
1390	1	1	103	Classroom 103	Baseboard	Terracotta	Green	Chipping	31	Negative	
1390	1	1	108C	Principal's Office	Baseboard (W1-W4)	Terracotta	Green	Chipping	6	Negative	
1390	1	B	100A	Gym/Cafeteria 100A	Baseboard	Terracotta	Green	Chipping	28	Negative	
1390	1	B	100A	Gym/Cafeteria 100A	Baseboard	Terracotta	Green	Chipping	19	Negative	
1390	1	B	100A	Gym/Cafeteria 100A	Baseboard	Terracotta	Green	Chipping	24	Negative	
1390	1	B	100A	Gym/Cafeteria 100A	Conduit	Metal	White	Chipping	8	Positive	
1390	1	B	100A	Gym/Cafeteria 100A	Baseboard	Terracotta	Green	Chipping	8	Negative	
1390	1	B	1B	Boiler Room	W4	Concrete	White	Chipping	18	Positive	
1390	1	B	2B	Boiler Room Storage	Door Frame	Concrete	White	Flaking	10	Positive	
1390	1	1	103C	Classroom 103 Closet	W1	No Access	No Access	No Access	No Access	No Access	
1390	1	1	103C	Classroom 103 Closet	W2	No Access	No Access	No Access	No Access	No Access	
1390	1	1	103C	Classroom 103 Closet	W3	No Access	No Access	No Access	No Access	No Access	
1390	1	1	103C	Classroom 103 Closet	W4	No Access	No Access	No Access	No Access	No Access	
1390	1	1	103C	Classroom 103 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	
1390	1	1	103C	Classroom 103 Closet	Floor	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104	1st Floor Boy's Restroom	W1	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104	1st Floor Boy's Restroom	W2	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104	1st Floor Boy's Restroom	W3	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104	1st Floor Boy's Restroom	W4	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104	1st Floor Boy's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104	1st Floor Boy's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104A	Staff Restroom	W1	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104A	Staff Restroom	W2	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104A	Staff Restroom	W3	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104A	Staff Restroom	W4	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104A	Staff Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104A	Staff Restroom	Floor	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104A	Staff Restroom	W1	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104A	Staff Restroom	W2	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104A	Staff Restroom	W3	No Access	No Access	No Access	No Access	No Access	

				Inspection Dates: 12/10-12/20/2021		School District of Philadelphia					
				Inspector Name and Certificate Number: Charles Rhodes, 003542		Lead Safe Certification Assessment Report					
				Inspection Company: Batta		Old Powell (swing space for SLA Beeber students) School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)	
1390	1	1	TR-104A	Staff Restroom	W4	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104A	Staff Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	
1390	1	1	TR-104A	Staff Restroom	Floor	No Access	No Access	No Access	No Access	No Access	
1390	1	1	101	Classroom 101	W1	CMU	White	Chipping	3	Negative	
1390	1	1	101	Classroom 101	Conduit	Metal	White	Chipping	6	Negative	
1390	1	1	101	Classroom 101	Shelf Support	Metal	White/Blue	Chipping	2	Negative	
1390	1	1	101	Classroom 101	Coat Rack	Wood	White/Blue	Chipping	5	Negative	
1390	1	1	101	Classroom 101	Lockers	Metal	Blue	Chipping	30	Negative	
1390	1	1	101	Classroom 101	Doorframe	Metal	Blue	Chipping	3	Negative	
1390	1	1	101	Classroom 101	Metal Pole	Metal	Blue	Chipping	4	Negative	
1390	1	1	101	Classroom 101	W2	CMU	White	Chipping	2	Negative	
1390	1	1	101	Classroom 101	Chalkboard	Metal	Blue	Chipping	10	Negative	
1390	1	1	101	Classroom 101	Chalkboard	Wood	Blue	Chipping	12	Negative	
1390	1	1	101	Classroom 101	Pipe Cover	Metal	White	Chipping	4	Negative	
1390	1	1	101	Classroom 101	W3	CMU	White	Chipping	1	Negative	
1390	1	1	101	Classroom 101	Radiator	Metal	Blue	Chipping	24	Negative	
1390	1	1	101	Classroom 101	W4	CMU	White	Chipping	1	Negative	
1390	1	1	102	Classroom 102	W1	CMU	White	Chipping	5	Negative	
1390	1	1	102	Classroom 102	Shelf Support	Metal	White	Chipping	3	Negative	
1390	1	1	102	Classroom 102	Metal Pole	Metal	White	Chipping	5	Negative	
1390	1	1	102	Classroom 102	Conduit	Metal	White	Chipping	5	Negative	
1390	1	1	102	Classroom 102	Doorframe	Metal	Green	Chipping	5	Negative	
1390	1	1	102	Classroom 102	Lockers	Metal	Blue	Chipping	5	Negative	
1390	1	1	102	Classroom 102	Radiator	Metal	White	Chipping	6	Negative	
1390	1	1	102	Classroom 102	Pipe Cover	Metal	White	Chipping	5	Negative	
1390	1	1	103	Classroom 103	Doorframe	Metal	White	Chipping	9	Negative	
1390	1	1	103	Classroom 103	Loft/Ladder	Wood	Blue	Chipping	12	Negative	
1390	1	1	103	Classroom 103	Shelf	Wood	White	Flaking	4	Negative	
1390	1	1	103	Classroom 103	Window Frames	Metal	Grey	Friction	15	Negative	
1390	1	1	103	Classroom 103	Pipe Cover	Metal	White	Chipping	4	Negative	
1390	1	1	101A	Counselor's Office	Doorframe	Metal	White/Blue	Chipping	6	Negative	
1390	1	1	101A	Counselor's Office	Partition	Metal	White	Chipping	14	Negative	
1390	1	1	101A	Counselor's Office	Door	Metal	White	Chipping	7	Negative	
1390	1	1	101A	Counselor's Office	Stairs	Concrete	Grey	Friction	15	Negative	
1390	1	1	101A	Counselor's Office	Railing	Metal	Grey	Chipping	6	Negative	
1390	1	1	103A	Classroom 103 Restroom	Doorframe	Metal	Green	Chipping	5	Negative	
1390	1	1	103A	Classroom 103 Restroom	Floor	Concrete	Grey	Friction	10	Negative	

				Inspection Dates: 12/10-12/20/2021	School District of Philadelphia					
				Inspector Name and Certificate Number: Charles Rhodes, 003542	Lead Safe Certification Assessment Report					
				Inspection Company: Batta	Old Powell (swing space for SLA Beeber students) School					
ULCS#	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
1390	1	1	TR-105	1st Floor Girl's Restroom	Doorframe	Metal	Brown	Chipping	6	Negative
1390	1	1	TR-105	1st Floor Girl's Restroom	Floor	Concrete	Grey	Chipping	17	Negative
1390	1	1	108B	Main Office	W1	CMU	Yellow	Chipping	5	Negative
1390	1	1	108B	Main Office	Doorframe	Metal	White/Green	Chipping	6	Negative
1390	1	1	108B	Main Office	Doorframe	Metal	Brown	Chipping	4	Negative
1390	1	1	108B	Main Office	Radiator	Metal	Brown	Chipping	6	Negative
1390	1	1	108B	Main Office	Pipe Cover	Metal	White	Chipping	2	Negative
1390	1	1	108B	Main Office	Doorframe	Metal	Brown	Chipping	4	Negative
1390	1	1	108D	Nurse's Office	Radiator	Metal	White	Chipping	4	Negative
1390	1	1	108E	Nurse's Office Restroom	Doorframe	Metal	White	Chipping	5	Negative
1390	1	1	108E	Nurse's Office Restroom	Partition	Metal	Blue	Chipping	7	Negative
1390	1	1	108A	Telephone Room	Doorframe	Metal	Brown	Chipping	5	Negative
1390	1	1	108A	Telephone Room	Metal Panel	Metal	Green	Flaking	4	Negative
1390	1	1	108C	Principal's Office	Radiator	Metal	White	Chipping	4	Negative
1390	1	1	108F	Principal's Office Bathroom	Doorframe	Metal	White	Chipping	1	Negative
1390	1	1	108G	Principal's Office Closet	Door Frame	Metal	White	Chipping	5	Negative
1390	1	B	100A	Gym/Cafeteria 100A	W1	CMU	White	Chipping	1	Negative
1390	1	B	100A	Gym/Cafeteria 100A	Door Frame	Metal	Green	Chipping	14	Negative
1390	1	B	100A	Gym/Cafeteria 100A	W2	CMU	White	Chipping	1	Negative
1390	1	B	100A	Gym/Cafeteria 100A	Conduit	Metal	White	Chipping	2	Negative
1390	1	B	100A	Gym/Cafeteria 100A	W3	CMU	White	Chipping	1	Negative
1390	1	B	100A	Gym/Cafeteria 100A	Radiator	Metal	White	Chipping	3	Negative
1390	1	B	100A	Gym/Cafeteria 100A	Door Frame	Metal	Red	Chipping	12	Negative
1390	1	B	100A	Gym/Cafeteria 100A	W4	CMU	White	Chipping	1	Negative
1390	1	B	100B	Gym/Cafeteria Storage	Door Frame	Metal	White	Chipping	8	Negative
1390	1	B	100B	Gym/Cafeteria Storage	Pipe Covering	Metal	White	Chipping	7	Negative
1390	1	B	1B	Boiler Room	W1	CMU	White	Chipping	20	Negative
1390	1	B	1B	Boiler Room	Door	Metal	Grey	Chipping	6	Negative
1390	1	B	1B	Boiler Room	Door Frame	Metal	Grey	Chipping	8	Negative
1390	1	B	1B	Boiler Room	W2	CMU	White	Chipping	15	Negative
1390	1	B	1B	Boiler Room	Drain Pipe	Metal	Grey	Chipping	12	Negative
1390	1	B	1B	Boiler Room	Railing	Metal	Grey	Chipping	15	Negative
1390	1	B	1B	Boiler Room	W3	CMU	White	Chipping	15	Negative
1390	1	B	1B	Boiler Room	Door	Metal	Grey	Chipping	6	Negative
1390	1	B	1B	Boiler Room	Door Frame	Metal	Grey	Chipping	8	Negative
1390	1	B	1B	Boiler Room	Gas Line	Metal	Yellow	Chipping	9	Negative
1390	1	B	1B	Boiler Room	Cabinet	Metal	Grey	Chipping	8	Negative

				Inspection Dates: 12/10-12/20/2021		School District of Philadelphia				
				Inspector Name and Certificate Number: Charles Rhodes, 003542		Lead Safe Certification Assessment Report				
				Inspection Company: Batta		Old Powell (swing space for SLA Beeber students) School				
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
1390	1	B	2B	Boiler Room Storage	W1	Concrete	White	Chipping	8	Negative
1390	1	B	2B	Boiler Room Storage	W2	Concrete	White	Chipping	6	Negative
1390	1	B	2B	Boiler Room Storage	W3	Concrete	White	Chipping	8	Negative
1390	1	B	2B	Boiler Room Storage	W4	Concrete	White	Chipping	5	Negative
1390	1	B	3B	Boiler Room Office	W1	Concrete	White	Chipping	2	Negative
1390	1	B	3B	Boiler Room Office	Door Frame	Metal	Brown	Chipping	4	Negative
1390	1	B	3B	Boiler Room Office	Door Frame	Metal	White	Chipping	1	Negative
1390	1	B	3B	Boiler Room Office	W2	Concrete	White	Chipping	2	Negative
1390	1	B	3B	Boiler Room Office	W3	Concrete	White	Chipping	1	Negative
1390	1	B	3B	Boiler Room Office	W4	Concrete	White	Chipping	3	Negative
1390	1	B	3B	Boiler Room Office	Floor	Concrete	Grey	Chipping	15	Negative
1390	2	1	101	Library	Door Frame	Metal	Green	Chipping	7	Negative
1390	2	1	101	Library	Door	Metal	Green	Chipping	8	Negative
1390	2	1	101	Library	Door Frame	Metal	Grey	Chipping	9	Negative
1390	2	1	101	Library	Door	Metal	Grey	Chipping	7	Negative
1390	1	2	TR-209	2nd Floor Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A
1390	1	2	TR-209	2nd Floor Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A
1390	1	2	TR-209	2nd Floor Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A