



# THE SCHOOL DISTRICT OF PHILADELPHIA

## Operations Division

Office of Environmental Management and Services  
440 North Broad Street  
Philadelphia, Pennsylvania 19130  
215-400-4750

**December 30, 2021**

Dear **Fox Chase Elementary School** Community,

As a part of the School District of Philadelphia's effort to provide students and staff with safe, accessible and appealing drinking water, **34** water outlets at your school were initially tested for lead on **August 17, 2021**. Of those outlets, **Ten (10)** outlets produced water that was below the action level of 10 ppb. **24** water outlets were found to have results above the water safety threshold and these outlets were immediately shut-off.

Below outlines the confirmed corrective action steps that were taken for those **24** water outlets that tested above the action limit.

Sample Date	Floor	Outlet Number	Outlet Type	Outlet Description	Lead Result (ppb)	PQL (ppb)	Confirmed Corrective Action Description
08/17/2021	00	03	FT	In kitchen left	10	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
12/14/2021	00	03	FT	In kitchen left	4.1	1	Remediation Complete
08/17/2021	00	04	FT	In kitchen right	12	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	00	04	FT	In kitchen right	6.7	1	Remediation Complete
08/17/2021	01	07	FT	In esol RM BR special needs	100	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	07	FT	In esol RM BR special needs	4.4	1	Remediation Complete
08/17/2021	01	08	FT	In teachers lounge	40	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	08	FT	In teachers lounge	1.7	1	Remediation Complete
08/17/2021	01	09	FT	In teachers lounge BR	29	1	Posted signage. Made Handwash Sink Only.
08/17/2021	01	10	FT	In RM 103 K	610	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	10	FT	In RM 103 K	2.2	1	Remediation Complete



# THE SCHOOL DISTRICT OF PHILADELPHIA

## Operations Division

Office of Environmental Management and Services  
440 North Broad Street  
Philadelphia, Pennsylvania 19130  
215-400-4750

Sample Date	Floor	Outlet Number	Outlet Type	Outlet Description	Lead Result (ppb)	PQL (ppb)	Confirmed Corrective Action Description
08/17/2021	01	11	FT	In RM 103 left BR K	21	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	11	FT	In RM 103 left BR K	12 <1 <sup>1</sup>	1	Posted signage. Made Handwash Sink Only.
08/17/2021	01	12	FT	In RM 103 right BR K	23	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	12	FT	In RM 103 right BR K	2.9	1	Remediation Complete
08/17/2021	01	13	FT	In RM 102 K	46	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	13	FT	In RM 102 K	5.2	1	Remediation Complete
08/17/2021	01	15	FT	In RM 102 BR left K	36	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	15	FT	In RM 102 BR left K	2.3	1	Remediation Complete
08/17/2021	01	16	FT	In RM 102 BR right K	34	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	16	FT	In RM 102 BR right K	2.4	1	Remediation Complete
08/17/2021	01	17	FT	In RM 101 k	20	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	17	FT	In RM 101 k	9.2	1	Remediation Complete
08/17/2021	01	18	FT	In RM 104 k	46	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	18	FT	In RM 104 k	1	1	Remediation Complete
08/17/2021	01	20	FT	In RM 104 right BR k - right	66	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	20	FT	In RM 104 right BR k - right	4.4	1	Remediation Complete



# THE SCHOOL DISTRICT OF PHILADELPHIA

## Operations Division

Office of Environmental Management and Services  
440 North Broad Street  
Philadelphia, Pennsylvania 19130  
215-400-4750

Sample Date	Floor	Outlet Number	Outlet Type	Outlet Description	Lead Result (ppb)	PQL (ppb)	Confirmed Corrective Action Description
08/17/2021	01	22	FT	In RM 112 1st grade	230	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	22	FT	In RM 112 1st grade	3	1	Remediation Complete
08/17/2021	01	23	FT	In RM 112 right BR 1st grade	40	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	23	FT	In RM 112 right BR 1st grade	2.5	1	Remediation Complete
08/17/2021	01	24	FT	In RM 112 left BR 1st grade	17	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	24	FT	In RM 112 left BR 1st grade	3.8	1	Remediation Complete
08/17/2021	01	25	FT	In nurses office	17	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	25	FT	In nurses office	5	1	Remediation Complete
08/17/2021	01	26	FT	In nurses office BR	42	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	26	FT	In nurses office BR	4	1	Remediation Complete
08/17/2021	01	27	FT	In RM 107 nurses exam RM	93	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	27	FT	In RM 107 nurses exam RM	7.9	1	Remediation Complete
08/17/2021	01	28	FT	In RM 109 1st grade	17	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	28	FT	In RM 109 1st grade	1.8	1	Remediation Complete
08/17/2021	01	29	FT	In RM 111 1st grade	31	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	29	FT	In RM 111 1st grade	6.6	1	Remediation Complete



# THE SCHOOL DISTRICT OF PHILADELPHIA

## Operations Division

Office of Environmental Management and Services  
 440 North Broad Street  
 Philadelphia, Pennsylvania 19130  
 215-400-4750

Sample Date	Floor	Outlet Number	Outlet Type	Outlet Description	Lead Result (ppb)	PQL (ppb)	Confirmed Corrective Action Description
08/17/2021	01	30	FT	In RM 110 1st grade	64	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	01	30	FT	In RM 110 1st grade	2.6	1	Remediation Complete
08/17/2021	xx	34	FT	In special needs building BR	89	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/10/2021	xx	34	FT	In special needs building BR	4.3	1	Remediation Complete

**Notes:**

AA = Above Action limit of 10 ppb  
 BA = Below Action limit of 10 ppb  
 MDL = Method Detection Limit  
 PQL = Practical Quantitation Limit  
 J = Result estimated below the PQL  
 < = not detected above PQL  
 ppb = parts per billion  
 NA = Not Available  
 xx = Annex

**Outlet Types:**

WF = Water Fountain/Bubbler  
 HS = Hydration Station/Bottle Filling Station  
 FT = Faucet/Tap  
 FP = Food Prep/Pot-Filler/Kitchen Kettle  
 IM = Ice-Maker

<sup>1</sup>Indicates a follow-up flush sample result. Standard protocol when retesting AA outlets is to collect a follow-up flush sample.

The School District will test the drinking water at your school every five years and share the results through a letter and also post the results on the District's website. If you wish to review the results from your school and for more information, you may visit the District's website at: [www.philasd.org/waterresults](http://www.philasd.org/waterresults).

Sincerely,

**Steve Link**  
 Environmental Director