



# THE SCHOOL DISTRICT OF PHILADELPHIA

## Operations Division

Office of Environmental Management and Services  
440 North Broad Street  
Philadelphia, Pennsylvania 19130  
215-400-4750

**December 30, 2021**

Dear **LaBrum Campus** Community,

As a part of the School District of Philadelphia’s effort to provide students and staff with safe, accessible and appealing drinking water, **17** water outlets at your school were initially tested for lead on **August 19, 2021**. Of those outlets, **12** outlets produced water that was below the action level of 10 ppb. **Five (5)** water outlets were found to have results above the water safety threshold and these outlets were immediately shut-off.

Below outlines the confirmed corrective action steps that were taken for those **Five (5)** water outlets that tested above the action limit.

Sample Date	Floor	Outlet Number	Outlet Type	Outlet Description	Lead Result (ppb)	PQL (ppb)	Confirmed Corrective Action Description
08/19/2021	01	03	WF	In cafeteria	680	1	Replaced with Hydration Station <sup>1</sup>
11/24/2021	01	03	HS	In cafeteria	<1	1	Remediation Complete
08/19/2021	01	06	FT	In nurses office	130	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/24/2021	01	06	FT	In nurses office	2.9	1	Remediation Complete
08/19/2021	01	09	FT	In RM 103 life skills hall wall	15	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/24/2021	01	09	FT	In RM 103 life skills hall wall	3.8	1	Remediation Complete
08/19/2021	01	10	FT	In RM 103 life skills side wall left	11	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/24/2021	01	10	FT	In RM 103 life skills side wall left	3.7	1	Remediation Complete
08/19/2021	01	11	FT	In RM 103 life skills side wall center	11	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
11/24/2021	01	11	FT	In RM 103 life skills side wall center	1.5	1	Remediation Complete



# THE SCHOOL DISTRICT OF PHILADELPHIA

## Operations Division

Office of Environmental Management and Services  
440 North Broad Street  
Philadelphia, Pennsylvania 19130  
215-400-4750

### Notes:

AA = Above Action limit of 10 ppb

BA = Below Action limit of 10 ppb

MDL = Method Detection Limit

PQL = Practical Quantitation Limit

J = Result estimated below the PQL

< = not detected above PQL

ppb = parts per billion

### Outlet Types:

WF = Water Fountain/Bubbler

HS = Hydration Station/Bottle Filling Station

FT = Faucet/Tap

FP = Food Prep/Pot-Filler/Kitchen Kettle

IM = Ice-Maker

<sup>1</sup>Hydration Station has passed subsequent testing and is turned on for use. Hydration Stations offer filtered water and bottle filling stations that remove, on average, 99.3 percent of lead from drinking water. These filtered water bottle filling stations are more effective, efficient, and affordable than the alternatives to lead remediation.

The School District will test the drinking water at your school every five years and share the results through a letter and also post the results on the District's website. If you wish to review the results from your school and for more information, you may visit the District's website at:

[www.philasd.org/waterresults](http://www.philasd.org/waterresults).

Sincerely,

**Steve Link**

Environmental Director