



# THE SCHOOL DISTRICT OF PHILADELPHIA

## Operations Division

Office of Environmental Management and Services  
440 North Broad Street  
Philadelphia, Pennsylvania 19130  
215-400-4750

**December 30, 2021**

Dear **Solis Cohen Elementary School** Community,

As a part of the School District of Philadelphia's effort to provide students and staff with safe, accessible and appealing drinking water, **29** water outlets at your school were initially tested for lead on **August 04, 2021**. Of those outlets, **23** outlets produced water that was below the action level of 10 ppb. **Six (6)** water outlets were found to have results above the water safety threshold and these outlets were immediately shut-off.

Below outlines the confirmed corrective action steps that were taken for those **Six (6)** water outlets that tested above the action limit.

Sample Date	Floor	Outlet Number	Outlet Type	Outlet Description	Lead Result (ppb)	MDL (ppb)	PQL (ppb)	Confirmed Corrective Action Description
08/04/2021	1	2	FT	RM 102 BR K	47	NA	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
09/15/2021	1	2	FT	RM 102 BR K	1.5	NA	1	Remediation Complete
08/04/2021	1	3	FT	In RM 102 K	10	NA	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
09/15/2021	1	3	FT	In RM 102 K	1.3	NA	1	Remediation Complete
08/04/2021	1	6	FT	In RM 104 BR K	50	NA	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
09/15/2021	1	6	FT	In RM 104 BR K	<1	NA	1	Remediation Complete
08/04/2021	1	10	FT	In RM 106 BR K	130	NA	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
09/15/2021	1	10	FT	In RM 106 BR K	11 <1'	NA	1	Posted Signage. Made Handwash Sink Only.
08/04/2021	1	12	FT	In RM 107 BR K	13	NA	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
09/15/2021	1	12	FT	In RM 107 BR K	2.8	NA	1	Remediation Complete



# THE SCHOOL DISTRICT OF PHILADELPHIA

## Operations Division

Office of Environmental Management and Services  
 440 North Broad Street  
 Philadelphia, Pennsylvania 19130  
 215-400-4750

Sample Date	Floor	Outlet Number	Outlet Type	Outlet Description	Lead Result (ppb)	MDL (ppb)	PQL (ppb)	Confirmed Corrective Action Description
08/04/2021	1	15	FT	In RM 108 K	51	NA	1	Replaced fixture and any accessible lines, elbows back to the shutoff valve and retested
09/15/2021	1	15	FT	In RM 108 K	<1	NA	1	Remediation Complete

**Notes:**

AA = Above Action limit of 10 ppb  
 BA = Below Action limit of 10 ppb  
 MDL = Method Detection Limit  
 PQL = Practical Quantitation Limit  
 J = Result estimated below the PQL  
 < = not detected above PQL  
 ppb = parts per billion  
 NA = Not Available

**Outlet Types:**

WF = Water Fountain/Bubbler  
 HS = Hydration Station/Bottle Filling Station  
 FT = Faucet/Tap  
 FP = Food Prep/Pot-Filler/Kitchen Kettle  
 IM = Ice-Maker

^Indicates a follow-up flush sample result. Standard protocol when retesting AA outlets is to collect a follow-up flush sample.

The School District will test the drinking water at your school every five years and share the results through a letter and also post the results on the District's website. If you wish to review the results from your school and for more information, you may visit the District's website at:

[www.philasd.org/waterresults](http://www.philasd.org/waterresults).

Sincerely,

**Steve Link**

Environmental Director