

		Dates: 8/25/2022 - 8/26/2022	Lead-Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia HS Field House					
		Inspection Company: BATTA	1000 Bigler Street, Philadelphia, PA 19148					
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
1	1	Boy's Visitor Locker Room (JV Football)	Floor	Concrete	Green	Friction	200	Negative
1	1	Boy's Visitor Locker Room (JV Football)	W1	CMU	White	None	0	Negative
1	1	Boy's Visitor Locker Room (JV Football)	Doorframe	Metal	Green	Flaking	6	Negative
1	1	Boy's Visitor Locker Room (JV Football)	Door	Metal	Grey	None	0	Negative
1	1	Boy's Visitor Locker Room (JV Football)	W2	CMU	White	Cracking	5	Negative
1	1	Boy's Visitor Locker Room (JV Football)	Baseboard	CMU/Tile	Green	None	0	Negative
1	1	Boy's Visitor Locker Room (JV Football)	W3	CMU	White	None	0	Negative
1	1	Boy's Visitor Locker Room (JV Football)	Pipe Cover	Metal	White	None	0	Negative
1	1	Boy's Visitor Locker Room (JV Football)	Pipe Insulation	Fiberglass	White	None	0	Negative
1	1	Boy's Visitor Locker Room (JV Football)	W4	CMU	White	None	0	Negative
1	1	Boy's Visitor Locker Room (JV Football)	Divider	Metal	White	None	0	Negative
1	1	Boy's Visitor Locker Room (JV Football)	Bench	Wood	Grey	None	0	Negative
1	1	Boy's Visitor Locker Room (JV Football)	Ceiling	Concrete	White	None	0	Negative
1	1	Boy's Visitor Locker Restroom (JV Football)	Floor	Concrete	Green	Chipping	40	Negative
1	1	Boy's Visitor Locker Restroom (JV Football)	W1	CMU	White	None	0	Negative
1	1	Boy's Visitor Locker Restroom (JV Football)	Doorframe	Metal	Green	Chipping	1	Negative
1	1	Boy's Visitor Locker Restroom (JV Football)	Baseboard	CMU/Tile	Green	None	0	Negative
1	1	Boy's Visitor Locker Restroom (JV Football)	Radiator	Metal	White	None	0	Negative
1	1	Boy's Visitor Locker Restroom (JV Football)	Pipe Cover	Metal	White	Chipping	1	Negative
1	1	Boy's Visitor Locker Restroom (JV Football)	W2	CMU	White	Cracking	10	Negative
1	1	Boy's Visitor Locker Restroom (JV Football)	W3	CMU	White	None	0	Negative
1	1	Boy's Visitor Locker Restroom (JV Football)	Partition	Wood	Green	Chipping	3	Negative
1	1	Boy's Visitor Locker Restroom (JV Football)	W4	CMU	White	None	0	Negative
1	1	Boy's Visitor Locker Restroom (JV Football)	Conduit	Metal	White	None	0	Negative
1	1	Boy's Visitor Locker Restroom (JV Football)	Ceiling	Concrete	White	Cracking	10	Negative
1	1	Boy's Visitor Shower (JV Football)	Floor	Concrete	Green	None	0	Negative
1	1	Boy's Visitor Shower (JV Football)	W1	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Visitor Shower (JV Football)	W2	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Visitor Shower (JV Football)	W3	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Visitor Shower (JV Football)	W4	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Visitor Shower (JV Football)	Ceiling	Concrete	White	None	0	Negative

		Dates: 8/25/2022 - 8/26/2022	Lead-Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia HS Field House					
		Inspection Company: BATTA	1000 Bigler Street, Philadelphia, PA 19148					
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
1	1	Boy's Visitor Restroom (JV Football)	Floor	Concrete	Green	None	0	Negative
1	1	Boy's Visitor Restroom (JV Football)	W1	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Visitor Restroom (JV Football)	W2	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Visitor Restroom (JV Football)	W3	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Visitor Restroom (JV Football)	W4	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Visitor Restroom (JV Football)	Ceiling	Concrete	White	None	0	Negative
1	1	Boy's Home Locker (JV Football)	Floor	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Home Locker (JV Football)	W1	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Home Locker (JV Football)	W2	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Home Locker (JV Football)	W3	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Home Locker (JV Football)	W4	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Home Locker (JV Football)	Ceiling	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Home Restroom (JV Football)	Floor	Concrete	Green	Chipping	40	Negative
1	1	Boy's Home Restroom (JV Football)	W1	CMU	White	None	0	Negative
1	1	Boy's Home Restroom (JV Football)	Doorframe	Metal	Green	Chipping	1	Negative
1	1	Boy's Home Restroom (JV Football)	Baseboard	CMU/Tile	Green	None	0	Negative
1	1	Boy's Home Restroom (JV Football)	Radiator	Metal	White	None	0	Negative
1	1	Boy's Home Restroom (JV Football)	Pipe Cover	Metal	White	Chipping	1	Negative
1	1	Boy's Home Restroom (JV Football)	W2	CMU	White	Cracking	10	Negative
1	1	Boy's Home Restroom (JV Football)	W3	CMU	White	None	0	Negative
1	1	Boy's Home Restroom (JV Football)	Partition	Wood	Green	Chipping	3	Negative
1	1	Boy's Home Restroom (JV Football)	W4	CMU	White	None	0	Negative
1	1	Boy's Home Restroom (JV Football)	Conduit	Metal	White	None	0	Negative
1	1	Boy's Home Restroom (JV Football)	Ceiling	Concrete	White	Cracking	10	Negative
1	1	Boy's Home Locker Showers (JV Football)	Floor	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Home Locker Showers (JV Football)	W1	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Home Locker Showers (JV Football)	W2	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Home Locker Showers (JV Football)	W3	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Home Locker Showers (JV Football)	W4	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Home Locker Showers (JV Football)	Ceiling	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Home Locker Restroom (JV Football)	Floor	Concrete	Green	Chipping	40	Negative

		Dates: 8/25/2022 - 8/26/2022	Lead-Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia HS Field House					
		Inspection Company: BATTA	1000 Bigler Street, Philadelphia, PA 19148					
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
1	1	Boy's Home Locker Restroom (JV Football)	W1	CMU	White	None	0	Negative
1	1	Boy's Home Locker Restroom (JV Football)	Doorframe	Metal	Green	Chipping	1	Negative
1	1	Boy's Home Locker Restroom (JV Football)	Baseboard	CMU/Tile	Green	None	0	Negative
1	1	Boy's Home Locker Restroom (JV Football)	Radiator	Metal	White	None	0	Negative
1	1	Boy's Home Locker Restroom (JV Football)	Pipe Cover	Metal	White	Chipping	1	Negative
1	1	Boy's Home Locker Restroom (JV Football)	W2	CMU	White	Cracking	10	Negative
1	1	Boy's Home Locker Restroom (JV Football)	W3	CMU	White	None	0	Negative
1	1	Boy's Home Locker Restroom (JV Football)	Partition	Wood	Green	Chipping	3	Negative
1	1	Boy's Home Locker Restroom (JV Football)	W4	CMU	White	None	0	Negative
1	1	Boy's Home Locker Restroom (JV Football)	Conduit	Metal	White	None	0	Negative
1	1	Boy's Home Locker Restroom (JV Football)	Ceiling	Concrete	White	Cracking	10	Negative
1	1	Visitor's Coach's Office (JV Football)	Floor	N/A	N/A	N/A	N/A	N/A
1	1	Visitor's Coach's Office (JV Football)	W1	N/A	N/A	N/A	N/A	N/A
1	1	Visitor's Coach's Office (JV Football)	W2	N/A	N/A	N/A	N/A	N/A
1	1	Visitor's Coach's Office (JV Football)	W3	N/A	N/A	N/A	N/A	N/A
1	1	Visitor's Coach's Office (JV Football)	W4	N/A	N/A	N/A	N/A	N/A
1	1	Visitor's Coach's Office (JV Football)	Ceiling	N/A	N/A	N/A	N/A	N/A
1	1	Visitor's Coach's Office Storage (JV Football)	Floor	N/A	N/A	N/A	N/A	N/A
1	1	Visitor's Coach's Office Storage (JV Football)	W1	N/A	N/A	N/A	N/A	N/A
1	1	Visitor's Coach's Office Storage (JV Football)	W2	N/A	N/A	N/A	N/A	N/A
1	1	Visitor's Coach's Office Storage (JV Football)	W3	N/A	N/A	N/A	N/A	N/A
1	1	Visitor's Coach's Office Storage (JV Football)	W4	N/A	N/A	N/A	N/A	N/A
1	1	Visitor's Coach's Office Storage (JV Football)	Ceiling	N/A	N/A	N/A	N/A	N/A
1	1	Visitor's Coach's Restroom (JV Football)	Floor	Concrete	Green	Chipping	40	Negative
1	1	Visitor's Coach's Restroom (JV Football)	W1	CMU	White	None	0	Negative
1	1	Visitor's Coach's Restroom (JV Football)	Doorframe	Metal	Green	Chipping	1	Negative
1	1	Visitor's Coach's Restroom (JV Football)	Baseboard	CMU/Tile	Green	None	0	Negative
1	1	Visitor's Coach's Restroom (JV Football)	Radiator	Metal	White	None	0	Negative
1	1	Visitor's Coach's Restroom (JV Football)	Pipe Cover	Metal	White	Chipping	1	Negative
1	1	Visitor's Coach's Restroom (JV Football)	W2	CMU	White	Cracking	10	Negative
1	1	Visitor's Coach's Restroom (JV Football)	W3	CMU	White	None	0	Negative

		Dates: 8/25/2022 - 8/26/2022	Lead-Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia HS Field House					
		Inspection Company: BATTA	1000 Bigler Street, Philadelphia, PA 19148					
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
1	1	Visitor's Coach's Restroom (JV Football)	Partition	Wood	Green	Chipping	3	Negative
1	1	Visitor's Coach's Restroom (JV Football)	W4	CMU	White	None	0	Negative
1	1	Visitor's Coach's Restroom (JV Football)	Conduit	Metal	White	None	0	Negative
1	1	Visitor's Coach's Restroom (JV Football)	Ceiling	Concrete	White	Cracking	10	Negative
1	1	Varsity Coach's Office (Varsity Football)	Floor	N/A	N/A	N/A	N/A	N/A
1	1	Varsity Coach's Office (Varsity Football)	W1	N/A	N/A	N/A	N/A	N/A
1	1	Varsity Coach's Office (Varsity Football)	W2	N/A	N/A	N/A	N/A	N/A
1	1	Varsity Coach's Office (Varsity Football)	W3	N/A	N/A	N/A	N/A	N/A
1	1	Varsity Coach's Office (Varsity Football)	W4	N/A	N/A	N/A	N/A	N/A
1	1	Varsity Coach's Office (Varsity Football)	Ceiling	N/A	N/A	N/A	N/A	N/A
1	1	Varsity Coach's Office Storage	Floor	N/A	N/A	N/A	N/A	N/A
1	1	Varsity Coach's Office Storage	W1	N/A	N/A	N/A	N/A	N/A
1	1	Varsity Coach's Office Storage	W2	N/A	N/A	N/A	N/A	N/A
1	1	Varsity Coach's Office Storage	W3	N/A	N/A	N/A	N/A	N/A
1	1	Varsity Coach's Office Storage	W4	N/A	N/A	N/A	N/A	N/A
1	1	Varsity Coach's Office Storage	Ceiling	N/A	N/A	N/A	N/A	N/A
1	1	Visitor Locker Room (Varsity Football)	Floor	N/A	N/A	N/A	N/A	N/A
1	1	Visitor Locker Room (Varsity Football)	W1	N/A	N/A	N/A	N/A	N/A
1	1	Visitor Locker Room (Varsity Football)	W2	N/A	N/A	N/A	N/A	N/A
1	1	Visitor Locker Room (Varsity Football)	W3	N/A	N/A	N/A	N/A	N/A
1	1	Visitor Locker Room (Varsity Football)	W4	N/A	N/A	N/A	N/A	N/A
1	1	Visitor Locker Room (Varsity Football)	Floor	Concrete	Green	Chipping	40	Negative
1	1	Visitor Locker Restroom (Varsity Football)	W1	CMU	White	None	0	Negative
1	1	Visitor Locker Restroom (Varsity Football)	Doorframe	Metal	Green	Chipping	1	Negative
1	1	Visitor Locker Restroom (Varsity Football)	Baseboard	CMU/Tile	Green	None	0	Negative
1	1	Visitor Locker Restroom (Varsity Football)	Radiator	Metal	White	None	0	Negative
1	1	Visitor Locker Restroom (Varsity Football)	Pipe Cover	Metal	White	Chipping	1	Negative
1	1	Visitor Locker Restroom (Varsity Football)	W2	CMU	White	Cracking	10	Negative
1	1	Visitor Locker Restroom (Varsity Football)	W3	CMU	White	None	0	Negative
1	1	Visitor Locker Restroom (Varsity Football)	Partition	Wood	Green	Chipping	3	Negative
1	1	Visitor Locker Restroom (Varsity Football)	W4	CMU	White	None	0	Negative

		Dates: 8/25/2022 - 8/26/2022	Lead-Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia HS Field House					
		Inspection Company: BATTA	1000 Bigler Street, Philadelphia, PA 19148					
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
1	1	Visitor Locker Restroom (Varsity Football)	Conduit	Metal	White	None	0	Negative
1	1	Visitor Locker Restroom (Varsity Football)	Ceiling	Concrete	White	Cracking	10	Negative
1	1	Boy's Visitor Showers (Varsity Football)	Floor	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Visitor Showers (Varsity Football)	W1	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Visitor Showers (Varsity Football)	W2	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Visitor Showers (Varsity Football)	W3	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Visitor Showers (Varsity Football)	W4	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Visitor Showers (Varsity Football)	Ceiling	N/A	N/A	N/A	N/A	N/A
1	1	Boy's Home Locker (Varsity Football)	Floor	Concrete	Green	Friction	200	Negative
1	1	Boy's Home Locker (Varsity Football)	W1	CMU	White	None	0	Negative
1	1	Boy's Home Locker (Varsity Football)	Doorframe	Metal	Green	Flaking	6	Negative
1	1	Boy's Home Locker (Varsity Football)	Door	Metal	Grey	None	0	Negative
1	1	Boy's Home Locker (Varsity Football)	W2	CMU	White	Cracking	5	Negative
1	1	Boy's Home Locker (Varsity Football)	Baseboard	CMU/Tile	Green	None	0	Negative
1	1	Boy's Home Locker (Varsity Football)	W3	CMU	White	None	0	Negative
1	1	Boy's Home Locker (Varsity Football)	Pipe Cover	Metal	White	None	0	Negative
1	1	Boy's Home Locker (Varsity Football)	Pipe Insulation	Fiberglass	White	None	0	Negative
1	1	Boy's Home Locker (Varsity Football)	W4	CMU	White	None	0	Negative
1	1	Boy's Home Locker (Varsity Football)	Bench	Wood	Grey	None	0	Negative
1	1	Boy's Home Locker (Varsity Football)	Ceiling	Concrete	White	None	0	Negative
1	1	Boy's Home Locker (Varsity Football)	Divider	Metal	White	None	0	Negative
1	1	Boiler Room	Floor	N/A	N/A	N/A	N/A	N/A
1	1	Boiler Room	W1	N/A	N/A	N/A	N/A	N/A
1	1	Boiler Room	W2	N/A	N/A	N/A	N/A	N/A
1	1	Boiler Room	W3	N/A	N/A	N/A	N/A	N/A
1	1	Boiler Room	W4	N/A	N/A	N/A	N/A	N/A
1	1	Boiler Room	Ceiling	N/A	N/A	N/A	N/A	N/A
1	1	Garage - Field Attendant's Storage for Lawn Equipment	Floor	N/A	N/A	N/A	N/A	N/A
1	1	Garage - Field Attendant's Storage for Lawn Equipment	W1	N/A	N/A	N/A	N/A	N/A

		Dates: 8/25/2022 - 8/26/2022	Lead-Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia HS Field House					
		Inspection Company: BATTA	1000 Bigler Street, Philadelphia, PA 19148					
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
1	1	Garage - Field Attendant's Storage for Lawn Equipment	W2	N/A	N/A	N/A	N/A	N/A
1	1	Garage - Field Attendant's Storage for Lawn Equipment	W3	N/A	N/A	N/A	N/A	N/A
1	1	Garage - Field Attendant's Storage for Lawn Equipment	W4	N/A	N/A	N/A	N/A	N/A
1	1	Garage - Field Attendant's Storage for Lawn Equipment	Ceiling	N/A	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office	W1	CMU	White	None	0	Negative
1	1	Building Engineer's Office	Conduit	Metal	White	None	0	Negative
1	1	Building Engineer's Office	W2	CMU	White	None	0	Negative
1	1	Building Engineer's Office	Post	Wood	Grey	None	0	Negative
1	1	Building Engineer's Office	W3	CMU	White	None	0	Negative
1	1	Building Engineer's Office	W4	CMU	White	None	0	Negative
1	1	Building Engineer's Office	Ceiling	Concrete	White	None	0	Negative
1	2	Conference Room	Floor	N/A	N/A	N/A	N/A	N/A
1	2	Conference Room	W1	Plaster	White	None	0	Negative
1	2	Conference Room	W2	Plaster	White	None	0	Negative
1	2	Conference Room	W3	Plaster	White	None	0	Negative
1	2	Conference Room	W4	Plaster	White	None	0	Negative
1	2	Conference Room	Ceiling	Concrete	White	None	0	Negative
1	2	Kitchen	Floor	N/A	N/A	N/A	N/A	N/A
1	2	Kitchen	W1	Plaster	White	None	0	Negative
1	2	Kitchen	W2	Plaster	White	None	0	Negative
1	2	Kitchen	W3	Plaster	White	None	0	Negative
1	2	Kitchen	W4	Plaster	White	None	0	Negative
1	2	Kitchen	Ceiling	Concrete	White	None	0	Negative
1	2	Office 202	Floor	No Access	No Access	No Access	No Access	No Access
1	2	Office 202	W1	No Access	No Access	No Access	No Access	No Access
1	2	Office 202	W2	No Access	No Access	No Access	No Access	No Access
1	2	Office 202	W3	No Access	No Access	No Access	No Access	No Access

		Dates: 8/25/2022 - 8/26/2022	Lead-Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia HS Field House					
		Inspection Company: BATTA	1000 Bigler Street, Philadelphia, PA 19148					
Element	Floor	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
1	2	Office 202	W4	No Access	No Access	No Access	No Access	No Access
1	2	Office 202	Ceiling	No Access	No Access	No Access	No Access	No Access
1	2	Restroom	Floor	N/A	N/A	N/A	N/A	N/A
1	2	Restroom	W1	Plaster	White	None	0	Negative
1	2	Restroom	W2	Plaster	White	None	0	Negative
1	2	Restroom	W3	Plaster	White	None	0	Negative
1	2	Restroom	W4	Plaster	White	None	0	Negative
1	2	Restroom	Ceiling	Concrete	White	None	0	Negative
1	2	2nd Floor Hallway	Floor	N/A	N/A	N/A	N/A	N/A
1	2	2nd Floor Hallway	W1	Plaster	White	None	0	Negative
1	2	2nd Floor Hallway	W2	Plaster	White	None	0	Negative
1	2	2nd Floor Hallway	W3	Plaster	White	None	0	Negative
1	2	2nd Floor Hallway	W4	Plaster	White	None	0	Negative
1	2	2nd Floor Hallway	Ceiling	Concrete	White	None	0	Negative
1	2	Conference Room 203	Floor	N/A	N/A	N/A	N/A	N/A
1	2	Conference Room 203	W1	Plaster	White	None	0	Negative
1	2	Conference Room 203	W2	Plaster	White	None	0	Negative
1	2	Conference Room 203	W3	Plaster	White	None	0	Negative
1	2	Conference Room 203	W4	Plaster	White	None	0	Negative
1	2	Conference Room 203	Ceiling	Concrete	White	None	0	Negative
2	1	Boy's Visitor Restroom (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Restroom (Soccer)	W1	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Restroom (Soccer)	W2	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Restroom (Soccer)	W3	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Restroom (Soccer)	W4	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Restroom (Soccer)	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Restroom (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Restroom (Soccer)	W1	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Restroom (Soccer)	W2	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Restroom (Soccer)	W3	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Restroom (Soccer)	W4	N/A	N/A	N/A	N/A	N/A

		Dates: 8/25/2022 - 8/26/2022	Lead-Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia HS Field House					
		Inspection Company: BATTA	1000 Bigler Street, Philadelphia, PA 19148					
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
2	1	Girl's Visitor Restroom (Soccer)	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Restroom (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Restroom (Soccer)	W1	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Restroom (Soccer)	W2	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Restroom (Soccer)	W3	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Restroom (Soccer)	W4	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Restroom (Soccer)	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Locker Room (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Locker Room (Soccer)	W1	CMU	White	None	0	Negative
2	1	Boy's Visitor Locker Room (Soccer)	W2	CMU	White	None	0	Negative
2	1	Boy's Visitor Locker Room (Soccer)	W3	CMU	White	None	0	Negative
2	1	Boy's Visitor Locker Room (Soccer)	W4	CMU	White	None	0	Negative
2	1	Boy's Visitor Locker Room (Soccer)	Ceiling	Concrete	White	None	0	Negative
2	1	Boy's Visitor Showers (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Showers (Soccer)	W1	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Showers (Soccer)	W2	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Showers (Soccer)	W3	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Showers (Soccer)	W4	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Showers (Soccer)	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Locker Restroom (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Locker Restroom (Soccer)	W1	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Locker Restroom (Soccer)	W2	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Locker Restroom (Soccer)	W3	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Locker Restroom (Soccer)	W4	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Visitor Locker Restroom (Soccer)	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Locker Room (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Locker Room (Soccer)	W1	CMU	White	None	0	Negative
2	1	Girl's Visitor Locker Room (Soccer)	W2	CMU	White	None	0	Negative
2	1	Girl's Visitor Locker Room (Soccer)	W3	CMU	White	None	0	Negative
2	1	Girl's Visitor Locker Room (Soccer)	W4	CMU	White	None	0	Negative
2	1	Girl's Visitor Locker Room (Soccer)	Ceiling	Concrete	White	None	0	Negative

		Dates: 8/25/2022 - 8/26/2022	Lead-Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia HS Field House					
		Inspection Company: BATTA	1000 Bigler Street, Philadelphia, PA 19148					
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2	1	Girl's Visitor Showers (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Showers (Soccer)	W1	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Showers (Soccer)	W2	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Showers (Soccer)	W3	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Showers (Soccer)	W4	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Showers (Soccer)	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Locker Restroom (Soccer)	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Locker Restroom (Soccer)	W1	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Locker Restroom (Soccer)	W2	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Locker Restroom (Soccer)	W3	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Locker Restroom (Soccer)	W4	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Visitor Locker Restroom (Soccer)	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Locker Room Storage	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Locker Room Storage	W1	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Locker Room Storage	W2	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Locker Room Storage	W3	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Locker Room Storage	W4	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Locker Room Storage	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Coach's Office	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Coach's Office	W1	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Coach's Office	W2	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Coach's Office	W3	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Coach's Office	W4	N/A	N/A	N/A	N/A	N/A
2	1	Boy's Coach's Office	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Coach's Restroom	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Coach's Restroom	W1	N/A	N/A	N/A	N/A	N/A
2	1	Coach's Restroom	W2	N/A	N/A	N/A	N/A	N/A
2	1	Coach's Restroom	W3	N/A	N/A	N/A	N/A	N/A
2	1	Coach's Restroom	W4	N/A	N/A	N/A	N/A	N/A
2	1	Coach's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Locker Room Storage	Floor	N/A	N/A	N/A	N/A	N/A

		Dates: 8/25/2022 - 8/26/2022	Lead-Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia HS Field House					
		Inspection Company: BATTA	1000 Bigler Street, Philadelphia, PA 19148					
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2	1	Girl's Locker Room Storage	W1	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Locker Room Storage	W2	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Locker Room Storage	W3	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Locker Room Storage	W4	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Locker Room Storage	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Coach's Office	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Coach's Office	W1	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Coach's Office	W2	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Coach's Office	W3	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Coach's Office	W4	N/A	N/A	N/A	N/A	N/A
2	1	Girl's Coach's Office	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Home Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Home Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A
2	1	Home Girl's Restroom	W2	N/A	N/A	N/A	N/A	N/A
2	1	Home Girl's Restroom	W3	N/A	N/A	N/A	N/A	N/A
2	1	Home Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A
2	1	Home Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Girl's Restroom	W2	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Girl's Restroom	W3	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Home Showers Female	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Home Showers Female	W1	N/A	N/A	N/A	N/A	N/A
2	1	Home Showers Female	W2	N/A	N/A	N/A	N/A	N/A
2	1	Home Showers Female	W3	N/A	N/A	N/A	N/A	N/A
2	1	Home Showers Female	W4	N/A	N/A	N/A	N/A	N/A
2	1	Home Showers Female	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Showers Female	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Showers Female	W1	N/A	N/A	N/A	N/A	N/A

		Dates: 8/25/2022 - 8/26/2022	Lead-Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia HS Field House					
		Inspection Company: BATTA	1000 Bigler Street, Philadelphia, PA 19148					
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/ negative)
2	1	Visitor's Showers Female	W2	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Showers Female	W3	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Showers Female	W4	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Showers Female	Ceiling	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Showers Female	Floor	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Showers Female	W1	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Showers Female	W2	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Showers Female	W3	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Showers Female	W4	N/A	N/A	N/A	N/A	N/A
2	1	Visitor's Showers Female	Ceiling	N/A	N/A	N/A	N/A	N/A
3	1	Public Women's Restroom (Home)	Floor	N/A	N/A	N/A	N/A	N/A
3	1	Public Women's Restroom (Home)	W1	N/A	N/A	N/A	N/A	N/A
3	1	Public Women's Restroom (Home)	W2	N/A	N/A	N/A	N/A	N/A
3	1	Public Women's Restroom (Home)	W3	N/A	N/A	N/A	N/A	N/A
3	1	Public Women's Restroom (Home)	W4	N/A	N/A	N/A	N/A	N/A
3	1	Public Women's Restroom (Home)	Ceiling	N/A	N/A	N/A	N/A	N/A
3	1	Public Women's Restroom Storage Room	Floor	N/A	N/A	N/A	N/A	N/A
3	1	Public Women's Restroom Storage Room	W1	N/A	N/A	N/A	N/A	N/A
3	1	Public Women's Restroom Storage Room	W2	N/A	N/A	N/A	N/A	N/A
3	1	Public Women's Restroom Storage Room	W3	N/A	N/A	N/A	N/A	N/A
3	1	Public Women's Restroom Storage Room	W4	N/A	N/A	N/A	N/A	N/A
3	1	Public Women's Restroom Storage Room	Ceiling	N/A	N/A	N/A	N/A	N/A
3	1	Public Men's Restroom	Floor	N/A	N/A	N/A	N/A	N/A
3	1	Public Men's Restroom	W1	N/A	N/A	N/A	N/A	N/A
3	1	Public Men's Restroom	W2	N/A	N/A	N/A	N/A	N/A
3	1	Public Men's Restroom	W3	N/A	N/A	N/A	N/A	N/A
3	1	Public Men's Restroom	W4	N/A	N/A	N/A	N/A	N/A
3	1	Public Men's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A
3	1	Public Men's Restroom Storage Room	Floor	N/A	N/A	N/A	N/A	N/A
3	1	Public Men's Restroom Storage Room	W1	N/A	N/A	N/A	N/A	N/A
3	1	Public Men's Restroom Storage Room	W2	N/A	N/A	N/A	N/A	N/A

		Dates: 8/25/2022 - 8/26/2022	Lead-Safe Certification Assessment Report					
		Inspector Name and Certificate Number: Charles Rhodes 003542	South Philadelphia HS Field House					
		Inspection Company: BATTA	1000 Bigler Street, Philadelphia, PA 19148					
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF (positive/negative)
3	1	Public Men's Restroom Storage Room	W3	N/A	N/A	N/A	N/A	N/A
3	1	Public Men's Restroom Storage Room	W4	N/A	N/A	N/A	N/A	N/A
3	1	Public Men's Restroom Storage Room	Ceiling	N/A	N/A	N/A	N/A	N/A
4	1	Public Women's Restroom (Visitor)	Floor	N/A	N/A	N/A	N/A	N/A
4	1	Public Women's Restroom (Visitor)	W1	N/A	N/A	N/A	N/A	N/A
4	1	Public Women's Restroom (Visitor)	W2	N/A	N/A	N/A	N/A	N/A
4	1	Public Women's Restroom (Visitor)	W3	N/A	N/A	N/A	N/A	N/A
4	1	Public Women's Restroom (Visitor)	W4	N/A	N/A	N/A	N/A	N/A
4	1	Public Women's Restroom (Visitor)	Ceiling	N/A	N/A	N/A	N/A	N/A
5	1	Ticket Booth	Floor	N/A	N/A	N/A	N/A	N/A
5	1	Ticket Booth	W1	N/A	N/A	N/A	N/A	N/A
5	1	Ticket Booth	W2	N/A	N/A	N/A	N/A	N/A
5	1	Ticket Booth	W3	N/A	N/A	N/A	N/A	N/A
5	1	Ticket Booth	W4	N/A	N/A	N/A	N/A	N/A
5	1	Ticket Booth	Ceiling	N/A	N/A	N/A	N/A	N/A
1	A	Attic	Floor	No Access	No Access	No Access	No Access	No Access
1	A	Attic	W1	No Access	No Access	No Access	No Access	No Access
1	A	Attic	W2	No Access	No Access	No Access	No Access	No Access
1	A	Attic	W3	No Access	No Access	No Access	No Access	No Access
1	A	Attic	W4	No Access	No Access	No Access	No Access	No Access
1	A	Attic	Ceiling	No Access	No Access	No Access	No Access	No Access
1	A	Attic	Floor	No Access	No Access	No Access	No Access	No Access