

School District of Philadelphia

Lead Safe Certification Assessment Report

George Washington High School Bright Future Pre-K Program

Element	Floor	Name of Inspector: Ananth K. Vinjamuri																	Inspection Dates: 8/14/2019					Comments/ Description/ Notes	
		Inspection Company: Criterion Labs, Inc.																	ULCS# 8030						
		Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Primary Component	Substrate Material	Color	Description of Primary Damage	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component	Substrate Material	Color	Description of Paint and Plaster Damage	Additional Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Additional Component XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)		
1	GDE	406	Classroom 408	Yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	406	Classroom 408	Yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	406	Classroom 408	Yes	W3	Cinderblock	Yellow	Spalling	30	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	no	
1	GDE	406	Classroom 408	Yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	406	Classroom 408	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	406	Classroom 408	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	408	Classroom 410	Yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	408	Classroom 410	Yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	408	Classroom 410	Yes	W3	Cinderblock	Yellow	Spalling	30	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	no	
1	GDE	408	Classroom 410	Yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	408	Classroom 410	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	408	Classroom 410	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	409	Classroom 409	Yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	409	Classroom 409	Yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	409	Classroom 409	Yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	409	Classroom 409	Yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	409	Classroom 409	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	409	Classroom 409	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	414	Girl's Restroom	Yes	W1	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	414	Girl's Restroom	Yes	W2	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	414	Girl's Restroom	Yes	W3	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	414	Girl's Restroom	Yes	W4	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	414	Girl's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	414	Girl's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	413	Boy's Restroom	Yes	W1	Cinderblock	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	413	Boy's Restroom	Yes	W2	Cinderblock	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	413	Boy's Restroom	Yes	W3	Cinderblock	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	413	Boy's Restroom	Yes	W4	Cinderblock	White/Grey	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	413	Boy's Restroom	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	413	Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	415	Kitchen adjacent to Classroom 409	Yes	W1	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	415	Kitchen adjacent to Classroom 409	Yes	W2	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	415	Kitchen adjacent to Classroom 409	Yes	W3	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	415	Kitchen adjacent to Classroom 409	Yes	W4	Cinderblock	White/Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	415	Kitchen adjacent to Classroom 409	Yes	Ceiling	Concrete	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	415	Kitchen adjacent to Classroom 409	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	H413	Hallway Classroom 401-414	Yes	W1	Cinderblock	Yellow/Purple	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	H413	Hallway Classroom 401-414	Yes	W2	Cinderblock	Yellow	Spalling	10	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	no	
1	GDE	H413	Hallway Classroom 401-414	Yes	W3	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	H413	Hallway Classroom 401-414	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Blue	Friction	4	0	Negative	None	0	No	No	no	At Stairwell #16	
1	GDE	H413	Hallway Classroom 401-414	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Friction	3	0.24	Negative	None	0	No	No	no	At Stairwell #16	
1	GDE	H413	Hallway Classroom 401-414	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Blue	Friction	2	0	Negative	None	0	No	No	no	At Stairwell #17	
1	GDE	H413	Hallway Classroom 401-414	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Friction	4	0.28	Negative	None	0	No	No	no	At Stairwell #17	
1	GDE	H413	Hallway Classroom 401-414	Yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	H413	Hallway Classroom 401-414	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Ceiling Tile
1	GDE	H413	Hallway Classroom 401-414	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	Floor Tile
1	GDE	SB2	Stairwell #17 at Classroom 401	Yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	SB2	Stairwell #17 at Classroom 401	Yes	W2	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	SB2	Stairwell #17 at Classroom 401	Yes	W3	Cinderblock	Yellow	Spalling	3	0	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	Unknown	no	At the exit door
1	GDE	SB2	Stairwell #17 at Classroom 401	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door	Metal	Blue	Friction	2	0	Negative	None	0	No	No	no	Exit Door	
1	GDE	SB2	Stairwell #17 at Classroom 401	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	Door Frame	Metal	Blue	Friction	2	0	Negative	None	0	No	No	no	Exit Door	
1	GDE	SB2	Stairwell #17 at Classroom 401	Yes	W4	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	SB2	Stairwell #17 at Classroom 401	Yes	Ceiling	Concrete/Metal Deck	White	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	SB2	Stairwell #17 at Classroom 401	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	No Paint
1	GDE	SB2	Stairwell #17 at Classroom 401	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	Hand rails	Metal	Grey	Friction	20	0.21	Negative	None	0	No	No	no	No Paint	
1	GDE	SB1	Stairwell #16 at Classroom 411	Yes	W1	Cinderblock	Yellow	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	None	0	No	No	no	
1	GDE	SB1	Stairwell #16 at Classroom 41																						