


LEAD SAFE ASSESSMENT REPORT



E. Washington Rhodes Elementary School

2900 W. Clearfield Street
Philadelphia, Pennsylvania

August 12, 2021

Prepared For:



440 N. Broad Street
Philadelphia, PA 19130

Prepared by:



1012 Industrial Drive
West Berlin, NJ 08091

ACER Project Number: SDP040



TABLE OF CONTENTS

1.0 INTRODUCTION

2.0 SCOPE OF WORK

2.1 Building Description

3.0 FINDINGS & RECOMMENDATIONS

3.1 Inspection Findings

3.2 Recommendations

4.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

5.0 APPENDICES

Appendix A Lead Safe Certification Assessment



I.0 INTRODUCTION

Acer Associates, LLC (ACER) has prepared this report to summarize the findings of the Lead Safe Assessment at the E. Washington Rhodes Elementary School, located at 2900 W. Clearfield Street in Philadelphia, Pennsylvania. The purpose of the inspection was to identify and assess painted surfaces within the school.

The inspection was completed on May 18, 2021 – May 21, 2021, June 9, 2021, June 15, 2021, July 15, 2021, by Ms. Kristen Masotes of ACER. Ms. Masotes is a licensed Commonwealth of Pennsylvania Lead Risk Assessor (058358).

The lead survey was conducted in accordance with the requirements of Federal, State and local regulations pertaining to lead paint, including the U.S. Department of Housing and Urban Development (HUD) Guidelines for the Evaluation of Lead-Based Paint Hazards in Housing. The findings in this report are consistent with accepted principles and practices established and prescribed by the City of Philadelphia, Commonwealth of Pennsylvania, EPA, and HUD.

This report, and the supporting data, findings, conclusions, opinions, and the recommendations it contains, represents the result of ACER's efforts. This report is not an abatement specification and should not be used for specifying removal methods or techniques. The results, assessments, conclusions, and recommendations stated in this report are factually representative of the conditions observed at this location on the dates of the inspection. ACER cannot assume responsibility for any change in conditions that occurred after the inspection.

Any reliance on this report by a party other than The School District of Philadelphia shall be at the party's sole risk unless that party has written authorization from ACER to use this document. The purpose of this restriction is to attempt to protect the interest of parties to whom the report may not be appropriately directed.

END OF SECTION



2.0 INSPECTION

2.1 Building Description

E. Washington Rhodes Elementary School is a two (2) story building with a basement. Interior finishes surveyed included CMU walls, concrete ceilings, and a combination of wood, tile, and concrete floors.

Please Note: Direction “W1” corresponds to the entry wall of each room/location. Direction “W2” corresponds to the next adjacent wall in the clockwise directions and so forth for directions “W3” and “W4”.

A Viken Detection Pb200i X-ray fluorescence lead paint analyzer was used for determination of lead content in paint. Calibration checks of the PB200i were done in accordance with Performance Characteristic Sheets (PCS). Calibration checks were performed on this instrument at the beginning and end of each day’s testing and at intervals of every four (4) hours during the testing. Calibration checks consist of the average of three (3) readings taken of the nominal 1.0 mg/cm² paint film. If for any reason the instrument does not maintain a consistent reproducible calibration, it is immediately removed from active service and sent back to the manufacturer for examination, service and/or recalibration.

The inspection consisted of collecting test readings of all substrate types in a room as depicted above and described as follows. One (1) test point (reading) was taken for each testing combination, except for the walls where at least four (4) were tested, to determine the amount of lead contained in the paint for that substrate. A testing combination is characterized by the room equivalent (Room 102, Main Office, etc.), component type (door, window, wall, etc.) and substrate (metal, sheetrock, etc.). The resulting test readings are then classified as POSITIVE OR NEGATIVE according to the action level, which is set in accordance with the applicable action level of the governing municipality, county, or state. The lead safe certification assessment report for this inspection is provided in Appendix A.

END OF SECTION



3.0 FINDINGS & RECOMMENDATIONS

On May 18, 2021 – May 21, 2021, June 9, 2021, June 15, 2021, and July 15, 2021, ACER conducted an inspection for lead-based paint at E. Washington Rhodes Elementary School, located at 2900 W. Clearfield Street in Philadelphia, Pennsylvania.

3.1 Findings

In accordance with The Philadelphia Code, Chapter 6-800, lead-based paint is defined as greater than 0.7 mg/cm². ACER’s inspection identified lead-based paint associated with the following building components:

Component	Substrate	Color	Location(s)
Pipe	Metal	Yellow	Boiler Room
		Brown	Hallway/Loading Dock outside BE Office
Stair Components	Metal	Brown/Beige	Hallway/Vestibule outside Boiler Room
			Stairwell outside Art Room
			Stairwell inside Art Classroom
			Stairwell outside Building Engineers Office
			Front Entrance Vestibule Stairwell
			Hallway Connecting A & B Wings
			A Wing Lunchroom
			B Wing Lunchroom
			Stairwell Between A & B Wings
			Stairwell Behind B Wing Classroom B7
			Hallway Connecting C & D Wings
			D Wing Lunchroom
			C Wing Lunchroom
			Stairwell behind C Wing Classroom C7
			Stairwell behind D Wing Classroom D7
			Vestibule outside Police Office
			Stairwell behind A Wing Classroom A106
			Stairwell behind B Wing Classroom B106
Stairwell behind D Wing Classroom D106			
Stairwell behind C Wing Classroom C106			
Stairwell next to Classroom 126			
Stairwell next to Music Classrooms			



Component	Substrate	Color	Location(s)
Door Casing	Metal	Tan	Boy's Locker Room
		Blue	Boy's Gym Teacher Office
			Girl's Restroom next to Locker Room
		Beige	Girl's Gym Teacher Office
			Stairwell behind A Wing Classroom A106
		Blue	Classroom B106
			Classroom B103
			B Wing Men's Staff Restroom

3.2 Limitations

The inspection and sample procedures used to complete this inspection are consistent with prevalent environmental and industrial hygiene standards for lead-based paint. All reasonable efforts were made to identify the presence of lead-based paint within the inspected areas. Materials not identified in this report should be considered as not sampled. ACER cannot assume responsibility for any change in conditions that occurred after the inspection.

END OF SECTION



4.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONAL

Sincerely,
Acer Associates, LLC

Prepared By:

Kristen Masotes
Project Manager
PA Lead Risk Assessor #058358

Reviewed By:

Matthew J. DePalma
Vice President



5.0 APPENDICES



Appendix A
Lead Safe Certification Assessment Report

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
B	1	Boiler Room	Door Casing	Metal	Blue	None	0	0.5	Negative	None	0	N/A					
B	1	Boiler Room	Door	Metal	Blue	None	0	0	Negative	None	0	N/A					
B	1	Boiler Room	sink	ceramic	Gray	Flaking	0	0.3	Negative	None	0	N/A					
B	1	Boiler Room	Door	Metal	Blue	None	0	0	Negative	None	0	N/A					
B	1	Boiler Room	Door Casing	Metal	Blue	None	0	0.4	Negative	None	0	N/A					
B	1	Boiler Room	Pipe	Metal	Yellow	None	0	0.9	Positive	None	0	N/A					
B	1	Boiler Room	Pipe	Metal	Red	None	0	0.3	Negative	None	0	N/A					
B	S02	Boiler Room Stairs to Exterior	W1	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A					Not Painted
B	S02	Boiler Room Stairs to Exterior	W2	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A					Not Painted
B	S02	Boiler Room Stairs to Exterior	W3	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A					Not Painted
B	S02	Boiler Room Stairs to Exterior	W4	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A					Not Painted
B	S02	Boiler Room Stairs to Exterior	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A					Not Painted
B	S02	Boiler Room Stairs to Exterior	Floor	N/A	N/A	N/A	N/A	N/A	N/A	None	0	N/A					Not Painted
B	2	Incinerator Room	W1	CMU	Gray	None	0	0.1	Negative	None	0	N/A					
B	2	Incinerator Room	W2	Concrete	Gray	None	0	0.1	Negative	None	0	N/A					
B	2	Incinerator Room	W4	CMU	Gray	None	0	0.1	Negative	None	0	N/A					
B	2	Incinerator Room	Door	Metal	Purple	None	0	0	Negative	None	0	N/A					
B	2	Incinerator Room	Door Casing	Metal	Purple	None	0	0.1	Negative	None	0	N/A					
B	H01	Hallway/Vestibule outside Boiler Room	Stairs - Railing	Metal	Brown	None	0	1.2	Positive	None	0	N/A					
B	H01	Hallway/Vestibule outside Boiler Room	Door Casing	Metal	Blue	None	0	0.2	Negative	None	0	N/A					
B	H01	Hallway/Vestibule outside Boiler Room	Door	Metal	Blue	None	0	0.1	Negative	None	0	N/A					
B	H01	Hallway/Vestibule outside Boiler Room	machine	Metal	Gray	None	0	0	Negative	None	0	N/A					
B	S03	Stairwell to 1st Floor next to Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A								Included with Hallway/Vestibule outside Boiler Room
B	S03	Stairwell to 1st Floor next to Elevator	W2	N/A	N/A	N/A	N/A	N/A	N/A								Included with Hallway/Vestibule outside Boiler Room
B	S03	Stairwell to 1st Floor next to Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A								Included with Hallway/Vestibule outside Boiler Room
B	S03	Stairwell to 1st Floor next to Elevator	W4	N/A	N/A	N/A	N/A	N/A	N/A								Included with Hallway/Vestibule outside Boiler Room
B	S03	Stairwell to 1st Floor next to Elevator	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								Included with Hallway/Vestibule outside Boiler Room
B	S03	Stairwell to 1st Floor next to Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A								Included with Hallway/Vestibule outside Boiler Room
B	3	Storage Room below Stairwell to 1st Floor next to Elevator	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
B	3	Storage Room below Stairwell to 1st Floor next to Elevator	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
B	3	Storage Room below Stairwell to 1st Floor next to Elevator	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
B	3	Storage Room below Stairwell to 1st Floor next to Elevator	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
B	3	Storage Room below Stairwell to 1st Floor next to Elevator	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
B	3	Storage Room below Stairwell to 1st Floor next to Elevator	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
B	E01	Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
B	E01	Elevator	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
B	E01	Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
B	E01	Elevator	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
B	E01	Elevator	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
B	E01	Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
B	H015	Vestibule outside School Police Office	W1	CMU	Beige	None	0	0	Negative	None	0	N/A					
B	H015	Vestibule outside School Police Office	W2	CMU	Beige	None	0	0.5	Negative	None	0	N/A					
B	H015	Vestibule outside School Police Office	W3	CMU	Beige	None	0	0.2	Negative	None	0	N/A					
B	H015	Vestibule outside School Police Office	W4	CMU	Beige	None	0	0.2	Negative	None	0	N/A					
B	H015	Vestibule outside School Police Office	Door Casing	Metal	Beige	None	0	0.2	Negative	None	0	N/A					
B	H015	Vestibule outside School Police Office	Door	Metal	Beige	None	0	0	Negative	None	0	N/A					
B	H015	Vestibule outside School Police Office	Door	Metal	Blue	None	0	0.1	Negative	None	0	N/A					
B	H015	Vestibule outside School Police Office	Door Center Post	Metal	Blue	None	0	0.6	Negative	None	0	N/A					
B	H015	Vestibule outside School Police Office	Door Casing	Metal	Blue	None	0	0.3	Negative	None	0	N/A					
1	40	Main Office	W1	CMU	Orange	None	0	0.2	Negative	None	0	Positive					
1	40	Main Office	W2	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	40	Main Office	W4	CMU	Orange	None	0	0.1	Negative	None	0	Positive					
1	40	Main Office	W3	CMU	White	None	0	0.2	Negative	None	0	Positive					
1	40	Main Office	Door Casing	Metal	Brown	None	0	0.5	Negative	None	0	Negative					
1	40	Main Office	Door Casing	Metal	Brown	None	0	0.2	Negative	None	0	Negative					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	40	Main Office	Door Casing	Metal	Brown	None	0	0.2	Negative	None	0	Negative					
1	40	Main Office	Door Casing	Metal	Brown	None	0	0.3	Negative	None	0	Negative					
1	40	Main Office	Door	Wood	Tan	None	0	0.1	Negative	None	0	Negative					
1	40	Main Office	Door	Wood	Tan	None	0	0.1	Negative	None	0	Negative					
1	40	Main Office	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	42	Main Office Mail Room	W1	CMU	Beige	None	0	0.4	Negative	None	0	Positive					
1	42	Main Office Mail Room	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	42	Main Office Mail Room	W3	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	42	Main Office Mail Room	W4	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	42	Main Office Mail Room	Door Casing	Metal	Beige	None	0	0.4	Negative	None	0	Negative					
1	42	Main Office Mail Room	Door	Wood	Tan	None	0	0	Negative	None	0	Negative					
1	42	Main Office Mail Room	Door Casing	Metal	Brown	None	0	0.4	Negative	None	0	Negative					
1	39	Principal's Office	W1	CMU	White	None	0	0.2	Negative	None	0	Positive					
1	39	Principal's Office	W2	CMU	White	None	0	0.2	Negative	None	0	Positive					
1	39	Principal's Office	W3	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	39	Principal's Office	W4	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	39	Principal's Office	Door	Wood	Tan	None	0	0.1	Negative	None	0	Negative					
1	39	Principal's Office	Door Casing	Metal	Brown	None	0	0.3	Negative	None	0	Negative					
1	39	Principal's Office	Door Casing	Metal	Tan	None	0	0.4	Negative	None	0	Negative					
1	39	Principal's Office	Door	Metal	Tan	None	0	0	Negative	None	0	Negative					
1	39A	Principal's Office Restroom	Ceiling	Concrete	White	None	0	0	Negative	None	0	Negative					
1	39B	Principal's Office Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
1	39B	Principal's Office Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
1	39B	Principal's Office Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
1	39B	Principal's Office Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
1	39B	Principal's Office Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	39B	Principal's Office Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	38	Conference Room	W1	CMU	Blue	None	0	0.1	Negative	None	0	Positive					
1	38	Conference Room	W4	CMU	Blue	None	0	0.1	Negative	None	0	Positive					
1	38	Conference Room	W3	CMU	Blue	None	0	0.1	Negative	None	0	Positive					
1	38	Conference Room	W2	CMU	Blue	None	0	0.1	Negative	None	0	Positive					
1	38	Conference Room	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	38	Conference Room	Door Casing	Metal	Blue	None	0	0.5	Negative	None	0	Negative					
1	38	Conference Room	Univent	Metal	Blue	None	0	0	Negative	None	0	N/A					
1	37	Office next to Conference Room	W1	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	37	Office next to Conference Room	W4	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	37	Office next to Conference Room	W3	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	37	Office next to Conference Room	W2	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	37	Office next to Conference Room	Door	Wood	Tan	None	0	0	Negative	None	0	Negative					
1	37	Office next to Conference Room	Door Casing	Metal	White	None	0	0.2	Negative	None	0	Negative					
1	36	Main Office Copy Room	W1	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	36	Main Office Copy Room	W2	CMU	White	None	0	0	Negative	None	0	Positive					
1	36	Main Office Copy Room	W4	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	36	Main Office Copy Room	W3	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	35	Main Office Storage Closet	W1	CMU	Yellow	None	0	0.1	Negative	None	0	Positive					
1	35	Main Office Storage Closet	W4	CMU	Yellow	None	0	0	Negative	None	0	Positive					
1	35	Main Office Storage Closet	W3	CMU	Yellow	None	0	0	Negative	None	0	Positive					
1	35	Main Office Storage Closet	W2	CMU	Yellow	None	0	0.1	Negative	None	0	Positive					
1	35	Main Office Storage Closet	Door Casing	Metal	Brown	None	0	0.5	Negative	None	0	Negative					
1	35	Main Office Storage Closet	Door	Wood	Tan	None	0	0	Negative	None	0	Negative					
1	H01	Hallway from Main Office to Nurse's Suite	W1	CMU	Green	None	0	0.1	Negative	None	0	Positive					
1	H01	Hallway from Main Office to Nurse's Suite	W3	CMU	Green	None	0	0	Negative	None	0	Positive					
1	H01	Hallway from Main Office to Nurse's Suite	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	H01	Hallway from Main Office to Nurse's Suite	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	H01	Hallway from Main Office to Nurse's Suite	Door Center POS	Metal	Blue	None	0	0	Negative	None	0	Negative					
1	H01	Hallway from Main Office to Nurse's Suite	Door	Metal	Blue	None	0	0.1	Negative	None	0	Negative					
1	H01	Hallway from Main Office to Nurse's Suite	Door Casing	Metal	Blue	None	0	0.1	Negative	None	0	Negative					
1	H01	Hallway from Main Office to Nurse's Suite	Door Casing	Metal	Beige	None	0	0.2	Negative	None	0	Negative					
1	H01	Hallway from Main Office to Nurse's Suite	Door	Metal	Beige	None	0	0	Negative	None	0	Negative					
1	H01	Hallway from Main Office to Nurse's Suite	Door Center POS	Metal	Black	None	0	0	Negative	None	0	Negative					
1	H01	Hallway from Main Office to Nurse's Suite	Door Casing	Metal	Beige	None	0	0.1	Negative	None	0	Negative					
1	H01	Hallway from Main Office to Nurse's Suite	Door	Wood	Beige	None	0	0.1	Negative	None	0	Negative					
1	H01	Hallway from Main Office to Nurse's Suite	Univent	Metal	Beige	None	0	0	Negative	None	0	N/A					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report										Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21					
		E.W. Rhodes ES School										ULCS# 4150					
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	H07	Hallway from Main Office to 4 Administrative Offices	W1	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	H07	Hallway from Main Office to 4 Administrative Offices	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	H07	Hallway from Main Office to 4 Administrative Offices	W3	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	H07	Hallway from Main Office to 4 Administrative Offices	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	H07	Hallway from Main Office to 4 Administrative Offices	Door Casing	Metal	Blue	None	0	0.5	Negative	None	0	Negative					
1	H07	Hallway from Main Office to 4 Administrative Offices	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	H07	Hallway from Main Office to 4 Administrative Offices	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	H07	Hallway from Main Office to 4 Administrative Offices	Door Casing	Metal	Blue	None	0	0.4	Negative	None	0	Negative					
1	34	1st Right Administrative Office in Main Office Suite	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	34	1st Right Administrative Office in Main Office Suite	Door Casing	Metal	Blue	None	0	0.5	Negative	None	0	Negative					
1	34	1st Right Administrative Office in Main Office Suite	W1	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	34	1st Right Administrative Office in Main Office Suite	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	34	1st Right Administrative Office in Main Office Suite	W3	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	34	1st Right Administrative Office in Main Office Suite	W2	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	33	2nd Right Administrative Office in Main Office Suite	W1	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	33	2nd Right Administrative Office in Main Office Suite	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	33	2nd Right Administrative Office in Main Office Suite	W3	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	33	2nd Right Administrative Office in Main Office Suite	W2	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	33	2nd Right Administrative Office in Main Office Suite	Door Casing	Metal	Blue	None	0	0.2	Negative	None	0	Negative					
1	33	2nd Right Administrative Office in Main Office Suite	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	33	2nd Right Administrative Office in Main Office Suite	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	33	2nd Right Administrative Office in Main Office Suite	Door Casing	Metal	Blue	None	0	0.2	Negative	None	0	Negative					
1	32	Room between 2nd Right Administrative Office in Main Office Suite and Main Hallway outside Auditorium	Door Casing	Metal	Blue	None	0	0.3	Negative	None	0	Negative					
1	32	Room between 2nd Right Administrative Office in Main Office Suite and Main Hallway outside Auditorium	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	32	Room between 2nd Right Administrative Office in Main Office Suite and Main Hallway outside Auditorium	W1	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	32	Room between 2nd Right Administrative Office in Main Office Suite and Main Hallway outside Auditorium	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	32	Room between 2nd Right Administrative Office in Main Office Suite and Main Hallway outside Auditorium	W3	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	32	Room between 2nd Right Administrative Office in Main Office Suite and Main Hallway outside Auditorium	W4	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	041C	1st Left Administrative Office in Main Office Suite	Door	Wood	Black	None	0	0.1	Negative	None	0	Negative					
1	041C	1st Left Administrative Office in Main Office Suite	Door Casing	Metal	Black	None	0	0.2	Negative	None	0	Negative					
1	041C	1st Left Administrative Office in Main Office Suite	W1	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	041C	1st Left Administrative Office in Main Office Suite	W4	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	041C	1st Left Administrative Office in Main Office Suite	W3	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	041C	1st Left Administrative Office in Main Office Suite	W2	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	041A	2nd Left Administrative Office in Main Office Suite	W1	CMU	Blue	None	0	0	Negative	None	0	Positive					
1	041A	2nd Left Administrative Office in Main Office Suite	W4	CMU	Blue	None	0	0	Negative	None	0	Positive					
1	041A	2nd Left Administrative Office in Main Office Suite	W3	CMU	Blue	None	0	0.1	Negative	None	0	Positive					
1	041A	2nd Left Administrative Office in Main Office Suite	W2	CMU	Blue	None	0	0.2	Negative	None	0	Positive					
1	041A	2nd Left Administrative Office in Main Office Suite	Door Casing	Metal	Blue	None	0	0.1	Negative	None	0	Negative					
1	041A	2nd Left Administrative Office in Main Office Suite	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	31	Nurse's Suite - Open Area next to Main Office	Door Casing	Metal	Blue	None	0	0.3	Negative	None	0	Negative					
1	31	Nurse's Suite - Open Area next to Main Office	Door	Wood	Blue	None	0	0.2	Negative	None	0	Negative					
1	31	Nurse's Suite - Open Area next to Main Office	W1	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	31	Nurse's Suite - Open Area next to Main Office	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	31	Nurse's Suite - Open Area next to Main Office	W4	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	31	Nurse's Suite - Open Area next to Main Office	W3	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	30	Medical Supply Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	No Access
1	30	Medical Supply Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	No Access
1	30	Medical Supply Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	No Access
1	30	Medical Supply Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	No Access
1	30	Medical Supply Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	No Access
1	30	Medical Supply Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	No Access
1	29	Nurse's Office	W1	CMU	Yellow	None	0	0	Negative	None	0	Positive					
1	29	Nurse's Office	W2	CMU	Yellow	None	0	0	Negative	None	0	Positive					
1	29	Nurse's Office	W3	CMU	Yellow	None	0	0.1	Negative	None	0	Positive					
1	29	Nurse's Office	W4	CMU	Yellow	None	0	0	Negative	None	0	Positive					
1	29	Nurse's Office	Window Casing	Metal	Blue	None	0	0	Negative	None	0	Negative					
1	29	Nurse's Office	Window Casing	Metal	Blue	None	0	0.4	Negative	None	0	Negative					
1	29	Nurse's Office	Door Casing	Metal	Blue	None	0	0.1	Negative	None	0	Negative					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
		Name of Inspector: Kristen Masotes								Inspection Company: Acer Associates							
Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	29	Nurse's Office	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
1	29C	Nurse's Office Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
1	29C	Nurse's Office Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
1	29C	Nurse's Office Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
1	29C	Nurse's Office Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
1	29C	Nurse's Office Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	29C	Nurse's Office Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031D	Sound-Proof Room inside Nurse's Suite	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031D	Sound-Proof Room inside Nurse's Suite	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031D	Sound-Proof Room inside Nurse's Suite	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031D	Sound-Proof Room inside Nurse's Suite	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031D	Sound-Proof Room inside Nurse's Suite	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031D	Sound-Proof Room inside Nurse's Suite	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031A	Nurse's Suite Corner Exam Room	W1	CMU	Yellow	None	0	0	Negative	None	0	Positive					
1	031A	Nurse's Suite Corner Exam Room	W2	CMU	Yellow	None	0	0.1	Negative	None	0	Positive					
1	031A	Nurse's Suite Corner Exam Room	W3	CMU	Yellow	None	0	0.1	Negative	None	0	Positive					
1	031A	Nurse's Suite Corner Exam Room	W4	CMU	Yellow	None	0	0.1	Negative	None	0	Positive					
1	031A	Nurse's Suite Corner Exam Room	Door Casing	Metal	Blue	None	0	0.4	Negative	None	0	Negative					
1	031A	Nurse's Suite Corner Exam Room	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
1	031A2	Nurse's Suite Corner Exam Room Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031A2	Nurse's Suite Corner Exam Room Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031A2	Nurse's Suite Corner Exam Room Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031A2	Nurse's Suite Corner Exam Room Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031A2	Nurse's Suite Corner Exam Room Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031A2	Nurse's Suite Corner Exam Room Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031A1	Nurse's Suite Corner Exam Room Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A								No Paint
1	031A1	Nurse's Suite Corner Exam Room Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A								No Paint
1	031A1	Nurse's Suite Corner Exam Room Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A								No Paint
1	031A1	Nurse's Suite Corner Exam Room Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A								No Paint
1	031A1	Nurse's Suite Corner Exam Room Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	031A1	Nurse's Suite Corner Exam Room Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	031B	Nurse's Suite Middle Exam Room	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	031B	Nurse's Suite Middle Exam Room	Door Casing	Metal	Blue	None	0	0.4	Negative	None	0	Negative					
1	031B	Nurse's Suite Middle Exam Room	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	031B	Nurse's Suite Middle Exam Room	W3	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	031B	Nurse's Suite Middle Exam Room	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	031B2	Nurse's Suite Middle Exam Room Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031B2	Nurse's Suite Middle Exam Room Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031B2	Nurse's Suite Middle Exam Room Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031B2	Nurse's Suite Middle Exam Room Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031B2	Nurse's Suite Middle Exam Room Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031B2	Nurse's Suite Middle Exam Room Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031B1	Nurse's Suite Middle Exam Room Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A								No Paint
1	031B1	Nurse's Suite Middle Exam Room Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A								No Paint
1	031B1	Nurse's Suite Middle Exam Room Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A								No Paint
1	031B1	Nurse's Suite Middle Exam Room Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A								No Paint
1	031B1	Nurse's Suite Middle Exam Room Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	031B1	Nurse's Suite Middle Exam Room Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	AH-1	HVAC/Mechanical Room in Nurse's Suite	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
1	AH-1	HVAC/Mechanical Room in Nurse's Suite	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
1	AH-1	HVAC/Mechanical Room in Nurse's Suite	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
1	AH-1	HVAC/Mechanical Room in Nurse's Suite	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Positive	No Access	No Access	No Access	No Access	
1	AH-1	HVAC/Mechanical Room in Nurse's Suite	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	AH-1	HVAC/Mechanical Room in Nurse's Suite	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	031C	Nurse's Suite Waiting Room	W1	CMU	Beige	Flaking	3	0.1	Negative	None	0	Positive	No	Unknown	No	No	Minor Flaking
1	031C	Nurse's Suite Waiting Room	W2	CMU	Beige	Flaking	3	0	Negative	None	0	Positive	No	Unknown	No	No	Minor Flaking
1	031C	Nurse's Suite Waiting Room	W3	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	031C	Nurse's Suite Waiting Room	W4	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	031C	Nurse's Suite Waiting Room	Door Casing	Metal	Blue	None	0	0.4	Negative	None	0	Negative					
1	7	Custodial Storage Room across from Nurse's Suite	W4	Drywall	Beige	None	0	0.1	Negative	None	0	N/A					
1	7	Custodial Storage Room across from Nurse's Suite	Door Casing	Metal	Brown	None	0	0.1	Negative	None	0	Negative					
1	7	Custodial Storage Room across from Nurse's Suite	Door Casing	Metal	Blue	None	0	0.2	Negative	None	0	Negative					
1	7	Custodial Storage Room across from Nurse's Suite	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	H03	Hallway outside Main Office and Auditorium	W1	CMU	Blue	None	0	0.1	Negative	None	0	Positive					
1	H03	Hallway outside Main Office and Auditorium	W4	CMU	Blue	None	0	0.1	Negative	None	0	Positive					

		School District of Philadelphia																
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21								
		E.W. Rhodes ES School								ULCS# 4150								
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
																		W4
1	S023S	Shaft on landing between first and second floor	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	S023S	Shaft on landing between first and second floor	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	S023S	Shaft on landing between first and second floor	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	19	Art Classroom	Door Casing	Metal	Blue	Intact	0	0.5	Negative	None	0	Negative						
1	19	Art Classroom	Door	Wood	Blue	Intact	0	0	Negative	None	0	Negative						
1	19	Art Classroom	W1	CMU	Brown	Intact	0	0.1	Negative	None	0	Positive						
1	19	Art Classroom	W4	CMU	Brown	Intact	0	0	Negative	None	0	Positive						
1	19	Art Classroom	W3	CMU	Brown	Intact	0	0.1	Negative	None	0	Positive						
1	19	Art Classroom	W2	CMU	Brown	Intact	0	0.1	Negative	None	0	Positive						
1	19	Art Classroom	Duct	Metal	Beige	Flaking	3	0.1	Negative	None	0	Negative	No	No	No	No	Flaking	
1	S024	Stairwell inside Art Classroom to Upper HVAC/Mechanical Room	Stairs - Railing	Metal	Brown	Intact	0	0.4	Negative	None	0	Negative						
1	S024	Stairwell inside Art Classroom to Upper HVAC/Mechanical Room	Stairs - Stringer	Metal	Brown	Intact	0	1.6	Positive	None	0	Negative						
1	S024	Stairwell inside Art Classroom to Upper HVAC/Mechanical Room	Stairs - Riser	Metal	Brown	Intact	0	1.6	Positive	None	0	Negative						
1	23	Art Classroom Storage - Closer to Entrance	W1	CMU	Yellow	Intact	0	0.1	Negative	None	0	Positive						
1	23	Art Classroom Storage - Closer to Entrance	W2	CMU	Yellow	Intact	0	0.2	Negative	None	0	Positive						
1	23	Art Classroom Storage - Closer to Entrance	Door Casing	Metal	Blue	Intact	0	0.4	Negative	None	0	Negative						
1	23	Art Classroom Storage - Closer to Entrance	Door	Wood	Blue	Intact	0	0.1	Negative	None	0	Negative						
1	23	Art Classroom Storage - Closer to Entrance	Duct	Metal	Brown	Intact	0	0.4	Negative	None	0	Negative						
1	22	Art Classroom Office	Door	Wood	Blue	Intact	0	0	Negative	None	0	Negative						
1	22	Art Classroom Office	Door Casing	Metal	Blue	Intact	0	0.1	Negative	None	0	Negative						
1	22	Art Classroom Office	W1	CMU	Brown	Intact	0	0.1	Negative	None	0	Positive						
1	22	Art Classroom Office	W2	CMU	Brown	Intact	0	0	Negative	None	0	Positive						
1	22	Art Classroom Office	W3	CMU	Brown	Intact	0	0	Negative	None	0	Positive						
1	22	Art Classroom Office	W4	CMU	Brown	Intact	0	0.1	Negative	None	0	Positive						
1	22A	Storage inside Art Classroom Office	W1	CMU	Brown	Intact	0	0	Negative	None	0	Positive						
1	22A	Storage inside Art Classroom Office	Door Casing	Metal	Blue	Intact	0	0.1	Negative	None	0	Negative						
1	22A	Storage inside Art Classroom Office	Door	Wood	Blue	Intact	0	0	Negative	None	0	Negative						
1	22A	Storage inside Art Classroom Office	Duct	Metal	Brown	Intact	0	0.1	Negative	None	0	Negative						
1	20	Drying room next to Art Classroom Office	Duct	Metal	Yellow	Intact	0	0.1	Negative	None	0	Negative						
1	20	Drying room next to Art Classroom Office	W1	CMU	Yellow	Intact	0	0.1	Negative	None	0	Positive						
1	20	Drying room next to Art Classroom Office	W4	CMU	Yellow	Intact	0	0.1	Negative	None	0	Positive						
1	20	Drying room next to Art Classroom Office	W3	CMU	Yellow	Intact	0	0.1	Negative	None	0	Positive						
1	20	Drying room next to Art Classroom Office	W2	CMU	Yellow	Intact	0	0.1	Negative	None	0	Positive						
1	20	Drying room next to Art Classroom Office	Door Casing	Metal	Blue	Intact	0	0.4	Negative	None	0	Negative						
1	20	Drying room next to Art Classroom Office	Door	Wood	Blue	Intact	0	0.1	Negative	None	0	Negative						
1	21	Art Classroom Storage - Under stairs to Upper HVAC/Mechanical Room	W1	CMU	Brown	Intact	0	0	Negative	None	0	Positive						
1	21	Art Classroom Storage - Under stairs to Upper HVAC/Mechanical Room	Door Casing	Metal	Blue	Intact	0	0.4	Negative	None	0	Negative						
1	21	Art Classroom Storage - Under stairs to Upper HVAC/Mechanical Room	Door	Wood	Blue	Intact	0	0.1	Negative	None	0	Negative						
1	21	Art Classroom Storage - Under stairs to Upper HVAC/Mechanical Room	W2	CMU	Brown	Intact	0	0.1	Negative	None	0	Positive						
1	21	Art Classroom Storage - Under stairs to Upper HVAC/Mechanical Room	W3	CMU	Brown	Intact	0	0	Negative	None	0	Positive						
1	21	Art Classroom Storage - Under stairs to Upper HVAC/Mechanical Room	W4	CMU	Brown	Intact	0	0.1	Negative	None	0	Positive						
1	17	Backstage Area between Art Classroom and Auditorium	W1	CMU	Yellow	Intact	0	0.1	Negative	None	0	Positive						
1	17	Backstage Area between Art Classroom and Auditorium	W4	CMU	Yellow	Intact	0	0.1	Negative	None	0	Positive						
1	17	Backstage Area between Art Classroom and Auditorium	W3	CMU	Yellow	Intact	0	0.1	Negative	None	0	Positive						
1	17	Backstage Area between Art Classroom and Auditorium	W2	CMU	Yellow	Intact	0	0.1	Negative	None	0	Positive						
1	17	Backstage Area between Art Classroom and Auditorium	Duct	Metal	White	Flaking	10	0.2	Negative	None	0	Negative	No	No	No	No	Flaking	
1	17	Backstage Area between Art Classroom and Auditorium	Door Casing	Metal	Blue	Intact	0	0.2	Negative	None	0	Negative						
1	17	Backstage Area between Art Classroom and Auditorium	Door	Wood	Blue	Intact	0	0	Negative	None	0	Negative						
1	18	Auditorium Stage	W1	N/A	N/A	N/A	N/A	N/A	N/A			Positive					Part of the Auditorium	
1	18	Auditorium Stage	W2	N/A	N/A	N/A	N/A	N/A	N/A			Positive					Part of the Auditorium	
1	18	Auditorium Stage	W3	N/A	N/A	N/A	N/A	N/A	N/A			Positive					Part of the Auditorium	

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	18	Auditorium Stage	W4	N/A	N/A	N/A	N/A	N/A	N/A			Positive					Part of the Auditorium
1	11	Auditorium	W1	CMU	Brown	Intact	0	0.1	Negative	None	0	Positive					
1	11	Auditorium	W2	CMU	Brown	Intact	0	0.1	Negative	None	0	Positive					
1	11	Auditorium	Door Casing	Metal	Blue	Intact	0	0.2	Negative	None	0	Negative					
1	11	Auditorium	W3	CMU	Brown	Intact	0	0.1	Negative	None	0	Positive					
1	11	Auditorium	W3	Concrete	White	Flaking	10	0.1	Negative	None	0	Positive	No	No	No	No	On Half Wall
1	11	Auditorium	W4	Concrete	White	Intact	0	0.3	Negative	None	0	Positive					
1	11	Auditorium	W4	CMU	Brown	Intact	0	0.2	Negative	None	0	Positive					
1	11	Auditorium	Door Casing	Metal	Blue	Intact	0	0.5	Negative	None	0	Negative					
1	11	Auditorium	Door Casing	Metal	Blue	Intact	0	0.1	Negative	None	0	Negative					
1	11	Auditorium	Door Center POS	Metal	Tan	Intact	0	0.1	Negative	None	0	Negative					
1	11	Auditorium	Door	Wood	Blue	Intact	0	0.1	Negative	None	0	Negative					
1	H021	Hallway from Auditorium to Large Storage Area	W2	CMU	Beige	Intact	0	0	Negative	None	0	Positive					
1	H021	Hallway from Auditorium to Large Storage Area	W4	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	H021	Hallway from Auditorium to Large Storage Area	W3	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	H021	Hallway from Auditorium to Large Storage Area	Door	Wood	Beige	Intact	0	0.1	Negative	None	0	Negative					
1	H021	Hallway from Auditorium to Large Storage Area	Door Casing	Metal	Beige	Intact	0	0.3	Negative	None	0	Negative					
1	H021	Hallway from Auditorium to Large Storage Area	Column	Concrete	Beige	Intact	0	0.1	Negative	None	0	Negative					
1	S025	Stairwell outside Building Engineer's Office	W1	CMU	Beige	Intact	0	0	Negative	None	0	Positive					
1	S025	Stairwell outside Building Engineer's Office	W2	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	S025	Stairwell outside Building Engineer's Office	W3	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	S025	Stairwell outside Building Engineer's Office	W4	CMU	Beige	Intact	0	0.4	Negative	None	0	Positive					
1	S025	Stairwell outside Building Engineer's Office	Door Casing	Metal	Blue	Intact	0	0.3	Negative	None	0	Negative					
1	S025	Stairwell outside Building Engineer's Office	Door	Metal	Blue	Intact	0	0	Negative	None	0	Negative					
1	S025	Stairwell outside Building Engineer's Office	Door	Metal	Blue	Intact	0	0.1	Negative	None	0	Negative					
1	S025	Stairwell outside Building Engineer's Office	Door Casing	Metal	Blue	Intact	0	0.4	Negative	None	0	Negative					
1	S025	Stairwell outside Building Engineer's Office	Column	Concrete	Beige	Intact	0	0.2	Negative	None	0	Negative					
1	S025	Stairwell outside Building Engineer's Office	Stairs - Stringer	Metal	Brown	Intact	0	0.8	Positive	None	0	Negative					
1	S025	Stairwell outside Building Engineer's Office	Stairs - Railing	Metal	Brown	Intact	0	0.1	Negative	None	0	Negative					
1	S025	Stairwell outside Building Engineer's Office	Stairs - Riser	Metal	Brown	Intact	0	1	Positive	None	0	Negative					
1	12	Foyer outside Large Storage Area next to Art Classroom	W1	CMU	Beige	Intact	0	0	Negative	None	0	Positive					
1	12	Foyer outside Large Storage Area next to Art Classroom	W2	Drywall	Beige	Intact	0	0.2	Negative	None	0	N/A					
1	12	Foyer outside Large Storage Area next to Art Classroom	W3	Drywall	Beige	Intact	0	0	Negative	None	0	N/A					
1	12	Foyer outside Large Storage Area next to Art Classroom	W4	CMU	Beige	Intact	0	0	Negative	None	0	Negative					
1	012A	Storage Room outside Large Storage Area next to Art Classroom	W1	CMU	Blue	Intact	0	0	Negative	None	0	Positive	#REF!	#REF!	#REF!	#REF!	
1	012A	Storage Room outside Large Storage Area next to Art Classroom	W2	CMU	Blue	Intact	0	0.2	Negative	None	0	Positive	#REF!	#REF!	#REF!	#REF!	
1	012A	Storage Room outside Large Storage Area next to Art Classroom	W3	CMU	Blue	Intact	0	0	Negative	None	0	Positive	#REF!	#REF!	#REF!	#REF!	
1	012A	Storage Room outside Large Storage Area next to Art Classroom	W4	CMU	Blue	Intact	0	0.1	Negative	None	0	Positive	#REF!	#REF!	#REF!	#REF!	
1	012A	Storage Room outside Large Storage Area next to Art Classroom	Floor	Concrete	Brown	Intact	0	0.3	Negative	None	0	Negative	#REF!	#REF!	#REF!	#REF!	
1	012A	Storage Room outside Large Storage Area next to Art Classroom	Door Casing	Metal	Blue	Intact	0	0.2	Negative	None	0	Negative	#REF!	#REF!	#REF!	#REF!	
1	012A	Storage Room outside Large Storage Area next to Art Classroom	Door	Wood	Blue	Intact	0	0.1	Negative	None	0	Negative					
1	13	Large Storage Area Storage Room closer to Entrance	W1	CMU	Beige	Intact	0	0.2	Negative	None	0	Positive					
1	13	Large Storage Area Storage Room closer to Entrance	W2	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	13	Large Storage Area Storage Room closer to Entrance	W3	CMU	Beige	Intact	0	0.2	Negative	None	0	Positive					
1	13	Large Storage Area Storage Room closer to Entrance	Door	Wood	Blue	Intact	0	0	Negative	None	0	Negative					
1	13	Large Storage Area Storage Room closer to Entrance	Door Casing	Metal	Blue	Intact	0	0	Negative	None	0	Negative					
1	15	Large Storage Area Office toward Art Classroom	W1	CMU	Beige	Intact	0	0.2	Negative	None	0	Positive					
1	15	Large Storage Area Office toward Art Classroom	W2	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	15	Large Storage Area Office toward Art Classroom	W3	CMU	Beige	Intact	0	0.2	Negative	None	0	Positive					
1	15	Large Storage Area Office toward Art Classroom	Door	Wood	Blue	Intact	0	0	Negative	None	0	Negative					
1	15	Large Storage Area Office toward Art Classroom	Door Casing	Metal	Blue	Intact	0	0	Negative	None	0	Negative					
1	14	Large Storage Area Office Closet toward Art Classroom	Door Casing	Metal	Blue	Intact	0	0.4	Negative	None	0	Negative					
1	10	Large Storage Area next to Art Classroom	W1	Drywall	Beige	Intact	0	0.2	Negative	None	0	N/A					
1	10	Large Storage Area next to Art Classroom	W1	CMU	Beige	Intact	0	0	Negative	None	0	Positive					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report										Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21					
		E.W. Rhodes ES School										ULCS# 4150					
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	10	Large Storage Area next to Art Classroom	W2	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	10	Large Storage Area next to Art Classroom	W3	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	10	Large Storage Area next to Art Classroom	W4	Drywall	Beige	Intact	0	0.1	Negative	None	0	N/A					
1	10	Large Storage Area next to Art Classroom	W4	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	10	Large Storage Area next to Art Classroom	Column	Concrete	Beige	Intact	0	0.2	Negative	None	0	Negative					
1	10	Large Storage Area next to Art Classroom	Fan Unit	Metal	Beige	Intact	0	0.1	Negative	None	0	Negative					
1	10	Large Storage Area next to Art Classroom	Door Casing	Metal	Blue	Intact	0	0	Negative	None	0	Negative					
1	10	Large Storage Area next to Art Classroom	Door	Metal	Blue	Intact	0	0.1	Negative	None	0	Negative					
1	10	Large Storage Area next to Art Classroom	Door Center Post	Metal	Blue	Intact	0	0	Negative	None	0	Negative					
1	10	Large Storage Area next to Art Classroom	Door Casing	Metal	Blue	Intact	0	0.4	Negative	None	0	Negative					
1	10	Large Storage Area next to Art Classroom	Pipe	Metal	Beige	Intact	0	0.3	Negative	None	0	Negative					
1	10	Large Storage Area next to Art Classroom	Duct	Metal	Beige	Intact	0	0.1	Negative	None	0	Negative					
1	S013	Front Entrance Vestibule Stairwell	Stairs - Railing	Metal	Brown	Intact	0	0.3	Negative	None	0	Negative					
1	S013	Front Entrance Vestibule Stairwell	Stairs - Riser	Metal	Brown	Intact	0	0.7	Positive	None	0	Negative					
1	S013	Front Entrance Vestibule Stairwell	Stairs - Stringer	Metal	Brown	Intact	0	0.4	Negative	None	0	Negative					
1	S013	Front Entrance Vestibule Stairwell	W1	CMU	Beige	Intact	0	0.2	Negative	None	0	Positive					
1	S013	Front Entrance Vestibule Stairwell	W3	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	S013	Front Entrance Vestibule Stairwell	W2	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	S013	Front Entrance Vestibule Stairwell	Column	Concrete	Beige	Intact	0	0.1	Negative	None	0	Negative					
1	43	Men's Restroom next to Front Entrance	W1	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	43	Men's Restroom next to Front Entrance	W4	CMU	Beige	Intact	0	0	Negative	None	0	Positive					
1	43	Men's Restroom next to Front Entrance	W2	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	43	Men's Restroom next to Front Entrance	Ceiling	Concrete	Beige	Intact	0	0.1	Negative	None	0	Negative					
1	43	Men's Restroom next to Front Entrance	Door Casing	Metal	Blue	Intact	0	0.2	Negative	None	0	Negative					
1	43	Men's Restroom next to Front Entrance	Door	Wood	Blue	Intact	0	0.1	Negative	None	0	Negative					
1	44	Women's Restroom next to Front Entrance	W1	CMU	White	Intact	0	0.1	Negative	None	0	Positive					
1	44	Women's Restroom next to Front Entrance	W2	CMU	White	Intact	0	0.1	Negative	None	0	Positive					
1	44	Women's Restroom next to Front Entrance	W3	CMU	White	Intact	0	0	Negative	None	0	Positive					
1	44	Women's Restroom next to Front Entrance	Ceiling	Concrete	White	Intact	0	0	Negative	None	0	Negative					
1	44	Women's Restroom next to Front Entrance	Door Casing	Metal	Blue	Intact	0	0.4	Negative	None	0	Negative					
1	44	Women's Restroom next to Front Entrance	Door	Wood	Blue	Intact	0	0.1	Negative	None	0	Negative					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	W1	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	W2	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	DOOR CASING	Metal	BEIGE	INTACT	0	0.02	Negative	None	0	Negative					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	DOOR CENTER POST	METAL	BEIGE	INTACT	0	0	Negative	None	0	Negative					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	W3	CMU	YELLOW	INTACT	0	0	Negative	None	0	Positive					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	PIPE CHASE DOOR	METAL	BEIGE	INTACT	0	0	Negative	None	0	Negative					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	FIREHOSE DOOR	METAL	WHITE	INTACT	0	0	Negative	None	0	Negative					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	DOOR CASING	METAL	BEIGE	INTACT	0	0.04	Negative	None	0	Negative					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	DOOR	METAL	BEIGE	INTACT	0	0	Negative	None	0	Negative					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	W1	CMU	Beige	Intact	0	0	Negative	None	0	Positive					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	W3	CMU	Yellow	Intact	0	0.1	Negative	None	0	Positive					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	W2	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	Door	Metal	Beige	Intact	0	0.2	Negative	None	0	Negative					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	Door Casing	Metal	Beige	Intact	0	0.2	Negative	None	0	Negative					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	Pipe chase door	Metal	Beige	Intact	0	0.2	Negative	None	0	Negative					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	Door	Wood	Beige	Intact	0	0	Negative	None	0	Negative					
1	H013	Hallway between A and B Wings and Gymnasium/Pool	Door	Metal	Beige	Intact	0	0	Negative	None	0	Negative					
1	H09	Hallway outside A Wing Classrooms A1 -A7	W1	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	H09	Hallway outside A Wing Classrooms A1 -A7	W2	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	H09	Hallway outside A Wing Classrooms A1 -A7	W3	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	H09	Hallway outside A Wing Classrooms A1 -A7	W4	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	H09	Hallway outside A Wing Classrooms A1 -A7	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	H09	Hallway outside A Wing Classrooms A1 -A7	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	H09	Hallway outside A Wing Classrooms A1 -A7	DOOR	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	H09	Hallway outside A Wing Classrooms A1 -A7	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	H09	Hallway outside A Wing Classrooms A1 -A7	DOOR	WOOD	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	H09	Hallway outside A Wing Classrooms A1 -A7	SOFFIT	Plaster	CLEAR	INTACT	0	0	Negative	None	0	N/A					
1	H09	Hallway outside A Wing Classrooms A1 -A7	SOFFIT	Plaster	CLEAR	INTACT	0	0	Negative	None	0	N/A					
1	H09	Hallway outside A Wing Classrooms A1 -A7	SOFFIT	Plaster	CLEAR	INTACT	0	0	Negative	None	0	N/A					
1	H09C1	Custodial closet between Classrooms A7 and A6	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	H09C1	Custodial closet between Classrooms A7 and A6	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	H09C1	Custodial closet between Classrooms A7 and A6	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	H09C1	Custodial closet between Classrooms A7 and A6	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	H09C1	Custodial closet between Classrooms A7 and A6	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	H09C1	Custodial closet between Classrooms A7 and A6	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	H10	Hallway connecting A Wing and B Wing	W1	CMU	YELLOW	INTACT	0	0	Negative	None	0	Positive					
1	H10	Hallway connecting A Wing and B Wing	W4	CMU	YELLOW	INTACT	0	0	Negative	None	0	Positive					
1	H10	Hallway connecting A Wing and B Wing	W3	CMU	YELLOW	INTACT	0	0	Negative	None	0	Positive					
1	H10	Hallway connecting A Wing and B Wing	W2	CMU	YELLOW	INTACT	0	0	Negative	None	0	Positive					
1	H10	Hallway connecting A Wing and B Wing	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	H10	Hallway connecting A Wing and B Wing	DOOR	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	H10	Hallway connecting A Wing and B Wing	DOOR	METAL	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	H10	Hallway connecting A Wing and B Wing	DOOR CASING	METAL	BLUE	INTACT	0	0.09	Negative	None	0	Negative					
1	H10	Hallway connecting A Wing and B Wing	DOOR CASING	METAL	BLUE	INTACT	0	0.12	Negative	None	0	Negative					
1	H10	Hallway connecting A Wing and B Wing	DOOR	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	H10	Hallway connecting A Wing and B Wing	DOOR CENTER PANEL	METAL	BLUE	INTACT	0	0.11	Negative	None	0	Negative					
1	H10	Hallway connecting A Wing and B Wing	STAIRS RAILING	METAL	BROWN	INTACT	0	0	Negative	None	0	Negative					
1	H10	Hallway connecting A Wing and B Wing	STAIRS RISER	METAL	BROWN	INTACT	0	0.9	Positive	None	0	Negative					
1	H10	Hallway connecting A Wing and B Wing	STAIRS STRINGER	METAL	BROWN	INTACT	0	0.9	Positive	None	0	Negative					
1	H10	Hallway connecting A Wing and B Wing	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative	None	0	N/A					
1	H10	Hallway connecting A Wing and B Wing	DOOR TOP PANEL	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	H10	Hallway connecting A Wing and B Wing	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative	None	0	N/A					
1	H012	Hallway outside B Wing Classrooms B1 -B7	W1	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	H012	Hallway outside B Wing Classrooms B1 -B7	W4	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	H012	Hallway outside B Wing Classrooms B1 -B7	W4	CMU	TAN	INTACT	0	0	Negative	None	0	Positive					
1	H012	Hallway outside B Wing Classrooms B1 -B7	W3	CMU	TAN	INTACT	0	0	Negative	None	0	Positive					
1	H012	Hallway outside B Wing Classrooms B1 -B7	DOOR CASING	METAL	BLUE	INTACT	0	0.08	Negative	None	0	Negative					
1	H012	Hallway outside B Wing Classrooms B1 -B7	SOFFIT	Plaster	TAN	INTACT	0	0	Negative	None	0	N/A					
1	H012	Hallway outside B Wing Classrooms B1 -B7	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative	None	0	N/A					
1	H012	Hallway outside B Wing Classrooms B1 -B7	DOOR	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	H012	Hallway outside B Wing Classrooms B1 -B7	DOOR CASING	METAL	BLUE	INTACT	0	0.04	Negative	None	0	Negative					
1	H012	Hallway outside B Wing Classrooms B1 -B7	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	H012	Hallway outside B Wing Classrooms B1 -B7	VENT COVER	METAL	CLEAR	INTACT	0	0	Negative	None	0	Negative					
1	H012	Hallway outside B Wing Classrooms B1 -B7	VENT COVER	METAL	CLEAR	INTACT	0	0	Negative	None	0	Negative					
1	H012	Hallway outside B Wing Classrooms B1 -B7	W2	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	H012	Hallway outside B Wing Classrooms B1 -B7	DOOR	METAL	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	H012	Hallway outside B Wing Classrooms B1 -B7	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	H012	Hallway outside B Wing Classrooms B1 -B7	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative	None	0	N/A					
1	H012	Hallway outside B Wing Classrooms B1 -B7	DOOR	METAL	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	H012	Hallway outside B Wing Classrooms B1 -B7	DOOR CASING	METAL	BLUE	INTACT	0	0.03	Negative	None	0	Negative					
1	H012C	Custodial closet between Classrooms B6 and B7	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	H012C	Custodial closet between Classrooms B6 and B7	W2	N/A	N/A	N/A	N/A	N/A	N/A								
1	H012C	Custodial closet between Classrooms B6 and B7	W3	N/A	N/A	N/A	N/A	N/A	N/A								
1	H012C	Custodial closet between Classrooms B6 and B7	W4	N/A	N/A	N/A	N/A	N/A	N/A								
1	H012C	Custodial closet between Classrooms B6 and B7	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								
1	H012C	Custodial closet between Classrooms B6 and B7	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	H012C2	Storage closet in between boys and girls restroom in H012	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	H012C2	Storage closet in between boys and girls restroom in H012	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	H012C2	Storage closet in between boys and girls restroom in H012	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	H012C2	Storage closet in between boys and girls restroom in H012	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	H012C2	Storage closet in between boys and girls restroom in H012	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	H012C2	Storage closet in between boys and girls restroom in H012	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	H012PC	Pipe Chase in Storage closet in between boys and girls restroom in H012	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	H012PC	Pipe Chase in Storage closet in between boys and girls restroom in H012	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	H012PC	Pipe Chase in Storage closet in between boys and girls restroom in H012	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	H012PC	Pipe Chase in Storage closet in between boys and girls restroom in H012	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	H012PC	Pipe Chase in Storage closet in between boys and girls restroom in H012	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	H012PC	Pipe Chase in Storage closet in between boys and girls restroom in H012	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	LR-A	A Wing Lunch Room	DOOR CASING	METAL	BLUE	INTACT	0	0.02	Negative	None	0	Negative					
1	LR-A	A Wing Lunch Room	DOOR	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	LR-A	A Wing Lunch Room	W1	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	LR-A	A Wing Lunch Room	W2	CMU	ORANGE	INTACT	0	0	Negative	None	0	Positive					
1	LR-A	A Wing Lunch Room	W3	CMU	ORANGE	INTACT	0	0	Negative	None	0	Positive					
1	LR-A	A Wing Lunch Room	W4	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	LR-A	A Wing Lunch Room	WALL DIVIDER	FIBERBOARD	ORANGE	INTACT	0	0.13	Negative	None	0	Negative					
1	LR-A	A Wing Lunch Room	COLUMN	METAL	BEIGE	INTACT	0	0.05	Negative	None	0	Negative					
1	LR-A	A Wing Lunch Room	DIVIDER WALL	DRYWALL	BEIGE	INTACT	0	0	Negative	None	0	N/A					
1	LR-A	A Wing Lunch Room	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative	None	0	N/A					
1	LR-A	A Wing Lunch Room	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative	None	0	N/A					
1	LR-A	A Wing Lunch Room	CEILING	CONCRETE	BEIGE	INTACT	0	0	Negative	None	0	Negative					
1	LR-A	A Wing Lunch Room	STAIRS RISER	METAL	BROWN	INTACT	0	1.3	Positive	None	0	Negative					
1	LR-A	A Wing Lunch Room	STAIRS STRINGER	METAL	BROWN	INTACT	0	0.5	Negative	None	0	Negative					
1	LR-A	A Wing Lunch Room	STAIRS RAILING	METAL	BROWN	INTACT	0	0.13	Negative	None	0	Negative					
1	S014	Stairwell inside A Wing Lunch Room	W1	N/A	N/A	N/A	N/A	N/A	N/A								Included with A Wing Cafeteria
1	S014	Stairwell inside A Wing Lunch Room	W2	N/A	N/A	N/A	N/A	N/A	N/A								Included with A Wing Cafeteria
1	S014	Stairwell inside A Wing Lunch Room	W3	N/A	N/A	N/A	N/A	N/A	N/A								Included with A Wing Cafeteria
1	S014	Stairwell inside A Wing Lunch Room	W4	N/A	N/A	N/A	N/A	N/A	N/A								Included with A Wing Cafeteria
1	S014	Stairwell inside A Wing Lunch Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								Included with A Wing Cafeteria
1	S014	Stairwell inside A Wing Lunch Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A								Included with A Wing Cafeteria
1	LR-B	B Wing Lunch Room	W1	CMU	GREEN	INTACT	0	0.01	Negative	None	0	Positive					
1	LR-B	B Wing Lunch Room	W2	CMU	GREEN	INTACT	0	0.01	Negative	None	0	Positive					
1	LR-B	B Wing Lunch Room	COLUMN	CONCRETE	CLEAR	INTACT	0	0.02	Negative	None	0	Negative					
1	LR-B	B Wing Lunch Room	W2	CMU	BEIGE	INTACT	0	0.02	Negative	None	0	Positive					
1	LR-B	B Wing Lunch Room	DOOR	WOOD	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	LR-B	B Wing Lunch Room	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	LR-B	B Wing Lunch Room	COLUMN	CONCRETE	BEIGE	Flaking	5	0	Negative	None	0	Negative	No	No	No	No	At Stairs
1	LR-B	B Wing Lunch Room	W4	DRYWALL	BEIGE	INTACT	0	0	Negative	None	0	N/A					
1	LR-B	B Wing Lunch Room	W4	WOOD	BEIGE	INTACT	0	0	Negative	None	0	Negative					
1	LR-B	B Wing Lunch Room	COLUMN	METAL	BEIGE	INTACT	0	0.01	Negative	None	0	Negative					
1	LR-B	B Wing Lunch Room	VENT COVER	METAL	BEIGE	INTACT	0	0.01	Negative	None	0	Negative					
1	LR-B	B Wing Lunch Room	STAIRS RAILING	METAL	BROWN	INTACT	0	0.9	Positive	None	0	Negative					
1	LR-B	B Wing Lunch Room	STAIRS RISER	METAL	BROWN	INTACT	0	0.6	Negative	None	0	Negative					
1	LR-B	B Wing Lunch Room	STAIRS STRINGER	METAL	BROWN	INTACT	0	0.5	Negative	None	0	Negative					
1	LR-B	B Wing Lunch Room	CEILING	CONCRETE	BEIGE	INTACT	0	0	Negative	None	0	Negative					
1	LR-B	B Wing Lunch Room	DOOR CASING	PLASTER	BLUE	INTACT	0	0.01	Negative	None	0	N/A					
1	LR-B	B Wing Lunch Room	DOOR	METAL	BLUE	INTACT	0	0.04	Negative	None	0	Negative					
1	LR-B	B Wing Lunch Room	SOFFIT	METAL	BEIGE	INTACT	0	0	Negative	None	0	Negative					
1	LR-B	B Wing Lunch Room	SOFFIT	METAL	BEIGE	INTACT	0	0	Negative	None	0	Negative					
1	LR-B	B Wing Lunch Room	AIR RETURN COV	METAL	GREEN	INTACT	0	0	Negative	None	0	Negative					
1	S016	Stairwell inside B Wing Lunch Room	W1	N/A	N/A	N/A	N/A	N/A	N/A								Included with Cafeteria
1	S016	Stairwell inside B Wing Lunch Room	W2	N/A	N/A	N/A	N/A	N/A	N/A								Included with Cafeteria
1	S016	Stairwell inside B Wing Lunch Room	W3	N/A	N/A	N/A	N/A	N/A	N/A								Included with Cafeteria
1	S016	Stairwell inside B Wing Lunch Room	W4	N/A	N/A	N/A	N/A	N/A	N/A								Included with Cafeteria
1	S016	Stairwell inside B Wing Lunch Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								Included with Cafeteria
1	S016	Stairwell inside B Wing Lunch Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A								Included with Cafeteria
1	007A	Classroom A7	DIVIDER WALL	DRYWALL	WHITE	INTACT	0	0.01	Negative	None	0	N/A					Included with Cafeteria
1	007A	Classroom A7	DIVIDER WALL TR	WOOD	BEIGE	INTACT	0	0.03	Negative	None	0	Negative					
1	007A	Classroom A7	W2	CMU	BEIGE	INTACT	0	0.01	Negative	None	0	Positive					
1	007A	Classroom A7	W1	CMU	BEIGE	INTACT	0	0.01	Negative	None	0	Positive					
1	007A	Classroom A7	COLUMN	CONCRETE	BEIGE	INTACT	0	0.01	Negative	None	0	Negative					
1	007A	Classroom A7	DOOR CASING	METAL	BLUE	INTACT	0	0.02	Negative	None	0	Negative					
1	006A	Classroom A6	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	006A	Classroom A6	WALL BASEBOAR	CMU	BEIGE	INTACT	0	0.01	Negative	None	0	Positive					
1	006A	Classroom A6	WALL BASEBOAR	CMU	BEIGE	INTACT	0	0.01	Negative	None	0	Positive					
1	006A	Classroom A6	WALL BASEBOAR	CMU	BEIGE	INTACT	0	0.02	Negative	None	0	Positive					
1	006A	Classroom A6	WALL BASEBOAR	CMU	GRAY	INTACT	0	0.01	Negative	None	0	Positive					
1	006A	Classroom A6	COLUMN	CONCRETE	BEIGE	INTACT	0	0.01	Negative	None	0	Negative					
1	006A	Classroom A6	Ceiling	CONCRETE	BEIGE	INTACT	0	0.01	Negative	None	0	Negative					
1	006A	Classroom A6	DIVIDER WALL TR	WOOD	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	006A	Classroom A6	DIVIDER WALL	DRYWALL	BEIGE	INTACT	0	0	Negative	None	0	N/A					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	005A	Classroom A5	COLUMN	CONCRETE	YELLOW	INTACT	0	0	Negative	None	0	Negative					
1	005A	Classroom A5	W1	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	005A	Classroom A5	W2	CMU	WHITE	INTACT	0	0.03	Negative	None	0	Positive					
1	005A	Classroom A5	W3	CMU	YELLOW	INTACT	0	0.01	Negative	None	0	Positive					
1	005A	Classroom A5	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	005A	Classroom A5	DIVIDER WALL TR	WOOD	WHITE	INTACT	0	0.03	Negative	None	0	Negative					
1	005A	Classroom A5	DIVIDER WALL	DRYWALL	WHITE	INTACT	0	0.01	Negative	None	0	N/A					
1	005A	Classroom A5	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	005A	Classroom A5	DOOR	WOOD	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	004A	Classroom A4	DOOR CASING	METAL	BLUE	INTACT	0	0.02	Negative	None	0	Negative					
1	004A	Classroom A4	W1	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	004A	Classroom A4	W4	CMU	WHITE	INTACT	0	0.02	Negative	None	0	Positive					
1	004A	Classroom A4	W4	CMU	YELLOW	INTACT	0	0	Negative	None	0	Positive					
1	004A	Classroom A4	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	004A	Classroom A4	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	004A	Classroom A4	COLUMN	CONCRETE	WHITE	INTACT	0	0	Negative	None	0	Negative					
1	004A	Classroom A4	WALL DIVIDER TR	WOOD	WHITE	INTACT	0	0	Negative	None	0	Negative					
1	004A	Classroom A4	WALL DIVIDER	DRYWALL	WHITE	INTACT	0	0.01	Negative	None	0	N/A					
1	004A	Classroom A4	COLUMN	CONCRETE	YELLOW	INTACT	0	0.01	Negative	None	0	Negative					
1	003A	Classroom A3	DIVIDER WALL	DRYWALL	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	003A	Classroom A3	DIVIDER WALL TR	WOOD	WHITE	INTACT	0	0	Negative	None	0	Negative					
1	003A	Classroom A3	W1	CMU	WHITE	INTACT	0	0.02	Negative	None	0	Positive					
1	003A	Classroom A3	W2	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	003A	Classroom A3	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	003A	Classroom A3	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	003A	Classroom A3	WALL BASEBOAR	CMU	YELLOW	INTACT	0	0.03	Negative	None	0	Negative					
1	003A	Classroom A3	COLUMN	CONCRETE	YELLOW	INTACT	0	0	Negative	None	0	Negative					
1	003A	Classroom A3	DOOR CASING	METAL	BLUE	INTACT	0	0.05	Negative	None	0	Negative					
1	002A	Classroom A2	W1	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	002A	Classroom A2	W4	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	002A	Classroom A2	W3	CMU	YELLOW	INTACT	0	0.01	Negative	None	0	Positive					
1	002A	Classroom A2	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative	None	0	Negative					
1	002A	Classroom A2	DIVIDER WALL TR	WOOD	WHITE	INTACT	0	0	Negative	None	0	Negative					
1	002A	Classroom A2	DIVIDER WALL	DRYWALL	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	001A	Classroom A1	W1	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	001A	Classroom A1	W2	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	001A	Classroom A1	W4	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	001A	Classroom A1	W3	CMU	YELLOW	INTACT	0	0	Negative	None	0	Positive					
1	001A	Classroom A1	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	001A	Classroom A1	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	001A	Classroom A1	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	001A	Classroom A1	DOOR	WOOD	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	49	A Wing Boy's Restroom	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	49	A Wing Boy's Restroom	W1	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	49	A Wing Boy's Restroom	W4	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	49	A Wing Boy's Restroom	W3	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	49	A Wing Boy's Restroom	ceiling	Concrete	BEIGE	INTACT	0	0	Negative	None	0	Negative					
1	50	A Wing Girl's Restroom	W1	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	50	A Wing Girl's Restroom	W2	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	50	A Wing Girl's Restroom	W3	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	50	A Wing Girl's Restroom	W4	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	50	A Wing Girl's Restroom	CEILING	CONCRETE	BEIGE	INTACT	0	0	Negative	None	0	Negative					
1	50	A Wing Girl's Restroom	DOOR CASING	METAL	BLUE	INTACT	0	0.03	Negative	None	0	Negative					
1	S015	Stairwell between A and B Wings	W1	CMU	YELLOW	INTACT	0	0	Negative	None	0	Positive					
1	S015	Stairwell between A and B Wings	W4	CMU	YELLOW	INTACT	0	0	Negative	None	0	Positive					
1	S015	Stairwell between A and B Wings	W3	CMU	YELLOW	INTACT	0	0	Negative	None	0	Positive					
1	S015	Stairwell between A and B Wings	W2	CMU	YELLOW	Flaking	15	0	Negative	None	0	Positive	No	Unknown	no	Yes	Efflorescence
1	S015	Stairwell between A and B Wings	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	S015	Stairwell between A and B Wings	DOOR	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	S015	Stairwell between A and B Wings	DOOR	METAL	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	S015	Stairwell between A and B Wings	DOOR CASING	METAL	BLUE	INTACT	0	0.09	Negative	None	0	Negative					
1	S015	Stairwell between A and B Wings	DOOR CASING	METAL	BLUE	INTACT	0	0.12	Negative	None	0	Negative					
1	S015	Stairwell between A and B Wings	DOOR	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	S015	Stairwell between A and B Wings	DOOR CENTER PANEL	METAL	BLUE	INTACT	0	0.11	Negative	None	0	Negative					
1	S015	Stairwell between A and B Wings	STAIRS RAILING	METAL	BROWN	INTACT	0	0	Negative	None	0	Negative					
1	S015	Stairwell between A and B Wings	STAIRS RISER	METAL	BROWN	INTACT	0	0.9	Positive	None	0	Negative					
1	S015	Stairwell between A and B Wings	STAIRS STRINGER	METAL	BROWN	INTACT	0	0.9	Positive	None	0	Negative					
1	S015	Stairwell between A and B Wings	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative	None	0	N/A					
1	S015	Stairwell between A and B Wings	DOOR TOP PANEL	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	S015	Stairwell between A and B Wings	SOFFIT	Plaster	BEIGE	INTACT	0	0	Negative	None	0	N/A					
1	52	B Wing Girl's Restroom	W1	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	52	B Wing Girl's Restroom	W2	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	52	B Wing Girl's Restroom	W4	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	52	B Wing Girl's Restroom	W3	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	52	B Wing Girl's Restroom	Ceiling	Wood	WHITE	INTACT	0	0	Negative	None	0	Negative					
1	52	B Wing Girl's Restroom	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	53	B Wing Boy's Restroom	DOOR CASING	METAL	BLUE	INTACT	0	0.02	Negative	None	0	Negative					
1	53	B Wing Boy's Restroom	W1	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	53	B Wing Boy's Restroom	W2	CMU	BEIGE	INTACT	0	0.01	Negative	None	0	Positive					
1	53	B Wing Boy's Restroom	W3	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	53	B Wing Boy's Restroom	PIPE CHASE DOOR	METAL	BEIGE	INTACT	0	0	Negative	None	0	Negative					
1	53	B Wing Boy's Restroom	Ceiling	CONCRETE	BEIGE	INTACT	0	0	Negative	None	0	Negative					
1	53	B Wing Boy's Restroom	VENT COVER	METAL	BEIGE	INTACT	0	0	Negative	None	0	Negative					
1	H013C	Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	H013C	Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W2	N/A	N/A	N/A	N/A	N/A	N/A								
1	H013C	Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W3	N/A	N/A	N/A	N/A	N/A	N/A								
1	H013C	Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W4	N/A	N/A	N/A	N/A	N/A	N/A								
1	H013C	Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								
1	H013C	Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	H013C-PC	Pipe chase in Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W1	N/A	N/A	N/A	N/A	N/A	N/A								
1	H013C-PC	Pipe chase in Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W2	N/A	N/A	N/A	N/A	N/A	N/A								
1	H013C-PC	Pipe chase in Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W3	N/A	N/A	N/A	N/A	N/A	N/A								
1	H013C-PC	Pipe chase in Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	W4	N/A	N/A	N/A	N/A	N/A	N/A								
1	H013C-PC	Pipe chase in Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A								
1	H013C-PC	Pipe chase in Custodial Closet between B Wing Cafeteria and Stairwell behind B Wing Classroom B7	Floor	N/A	N/A	N/A	N/A	N/A	N/A								
1	S017	Stairwell behind B Wing Classroom B7	W1	Brick	Beige	Intact	0	0.1	Negative	None	0	N/A					
1	S017	Stairwell behind B Wing Classroom B7	W2	Brick	Beige	Intact	0	0.1	Negative	None	0	N/A					
1	S017	Stairwell behind B Wing Classroom B7	W4	Brick	Beige	Intact	0	0.2	Negative	None	0	N/A					
1	S017	Stairwell behind B Wing Classroom B7	Stairs - Railing	Metal	Beige	Intact	0	0.2	Negative	None	0	Negative					
1	S017	Stairwell behind B Wing Classroom B7	Stairs - Riser	Metal	Beige	Intact	0	1	Positive	None	0	Negative					
1	S017	Stairwell behind B Wing Classroom B7	Stairs - Stringer	Metal	Beige	Intact	0	0.7	Positive	None	0	Negative					
1	S017	Stairwell behind B Wing Classroom B7	W2	Drywall	Beige	Intact	0	0	Negative	None	0	N/A					
1	006B	Classrooms B6 + B7	W1	CMU	BEIGE	INTACT	0	0.03	Negative	None	0	Positive					
1	006B	Classrooms B6 + B7	W4	CMU	BEIGE	Efflorescence	7	0	Negative	None	0	Positive	No	Yes	No	yes	Efflorescence
1	006B	Classrooms B6 + B7	W3	CMU	BEIGE	INTACT	0	0.03	Negative	None	0	Positive					
1	006B	Classrooms B6 + B7	W2	CMU	BEIGE	INTACT	0	0.01	Negative	None	0	Positive					
1	006B	Classrooms B6 + B7	DIVIDER WALL TR	WOOD	BEIGE	INTACT	0	0.02	Negative	None	0	Negative					
1	006B	Classrooms B6 + B7	DIVIDER WALL	WOOD	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	006B	Classrooms B6 + B7	COLUMN	CONCRETE	WHITE	INTACT	0	0	Negative	None	0	Negative					
1	006B	Classrooms B6 + B7	COLUMN	CONCRETE	BEIGE	INTACT	0	0.01	Negative	None	0	Negative					
1	006B	Classrooms B6 + B7	UNIVENT	METAL	BEIGE	INTACT	0	0.14	Negative	None	0	N/A					
1	006B	Classrooms B6 + B7	SOFFIT	Plaster	BEIGE	Efflorescence	10	0	Negative	None	0	N/A	No	Yes	No	No	Efflorescence from Univent
1	006B-PC	Pipe Chase in Classrooms B6 + B7	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	006B-PC	Pipe Chase in Classrooms B6 + B7	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	006B-PC	Pipe Chase in Classrooms B6 + B7	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	006B-PC	Pipe Chase in Classrooms B6 + B7	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	
1	006B-PC	Pipe Chase in Classrooms B6 + B7	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access		No Access	No Access	No Access	No Access	

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	006B-PC	Pipe Chase in Classrooms B6 + B7	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	005B	Classroom B5	W1	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	005B	Classroom B5	W2	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	005B	Classroom B5	W3	CMU	ORANGE	Efflorescence	20	0.01	Negative	None	0	Positive	No	yes	no	yes	Efflorescence
1	005B	Classroom B5	SOFFIT	Plaster	WHITE	Efflorescence	10	0	Negative	None	0	N/A	No	yes	no	no	Efflorescence cause by univent
1	005B	Classroom B5	COLUMN	CONCRETE	ORANGE	INTACT	0	0	Negative	None	0	Negative					
1	005B	Classroom B5	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	005B	Classroom B5	DIVIDER WALL TR	WOOD	WHITE	INTACT	0	0.02	Negative	None	0	Negative					
1	005B	Classroom B5	DIVIDER WALL	WOOD	WHITE	INTACT	0	0	Negative	None	0	Negative					
1	005B	Classroom B5	CONDUIT	METAL	WHITE	INTACT	0	0.22	Negative	None	0	Negative					
1	004B	Classroom B4	WALL	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	004B	Classroom B4	WALL	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	004B	Classroom B4	W3	CMU	ORANGE	Flaking	10	0	Negative	None	0	Positive	No	No	No	Yes	Flaking
1	004B	Classroom B4	COLUMN	CONCRETE	ORANGE	INTACT	0	0	Negative	None	0	Negative					
1	004B	Classroom B4	COLUMN	CONCRETE	WHITE	INTACT	0	0.01	Negative	None	0	Negative					
1	004B	Classroom B4	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	004B	Classroom B4	WALL DIVIDER TR	WOOD	WHITE	INTACT	0	0	Negative	None	0	Negative					
1	004B	Classroom B4	DOOR	WOOD	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	003B	Classroom B3	W1	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	003B	Classroom B3	W4	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	003B	Classroom B3	W3	CMU	ORANGE	INTACT	0	0.01	Negative	None	0	Positive					
1	003B	Classroom B3	SOFFIT	Plaster	WHITE	Efflorescence	12	0	Negative	None	0	N/A	no	no	no	no	Efflorescence cause by univent
1	003B	Classroom B3	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	003B	Classroom B3	WALL DIVIDER TR	WOOD	WHITE	INTACT	0	0.01	Negative	None	0	Negative					
1	003B	Classroom B3	WALL DIVIDER	DRYWALL	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	003B	Classroom B3	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	002B	Classroom B2	W1	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	002B	Classroom B2	W2	CMU	WHITE	INTACT	0	0.02	Negative	None	0	Positive					
1	002B	Classroom B2	W3	CMU	ORANGE	INTACT	0	0.01	Negative	None	0	Positive					
1	002B	Classroom B2	SOFFIT	Plaster	WHITE	Efflorescence	2	0	Negative	None	0	N/A	No	no	no	no	Efflorescence cause by univent
1	002B	Classroom B2	WALL DIVIDER TR	WOOD	WHITE	INTACT	0	0	Negative	None	0	Negative					
1	002B	Classroom B2	WALL DIVIDER	DRYWALL	WHITE	INTACT	0	0.03	Negative	None	0	N/A					
1	002B	Classroom B2	DOOR CASING	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	002B	Classroom B2	W1	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	002B	Classroom B2	W2	CMU	BLUE	INTACT	0	0.01	Negative	None	0	Positive					
1	002B	Classroom B2	W3	CMU	ORANGE	INTACT	0	0	Negative	None	0	Positive					
1	002B	Classroom B2	W4	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	001B	Classroom B1	SOFFIT 3	Plaster	WHITE	Efflorescence	2	0	Negative	None	0	N/A	No	No	No	No	Efflorescence cause by univent
1	001B	Classroom B1	SOFFIT 2	Plaster	WHITE	Efflorescence	8	0	Negative	None	0	N/A	No	No	No	No	Efflorescence cause by univent
1	001B	Classroom B1	SOFFIT	Plaster	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	001B	Classroom B1	COLUMN	CONCRETE	ORANGE	INTACT	0	0	Negative	None	0	Negative					
1	001B	Classroom B1	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	001B	Classroom B1	DOOR	WOOD	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	51	Electrical Room between A and B Wings	W1	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	51	Electrical Room between A and B Wings	W2	CMU	WHITE	INTACT	0	0.02	Negative	None	0	Positive					
1	51	Electrical Room between A and B Wings	W3	CMU	WHITE	INTACT	0	0.02	Negative	None	0	Positive					
1	51	Electrical Room between A and B Wings	W4	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	51	Electrical Room between A and B Wings	DOOR CENTER PD	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	51	Electrical Room between A and B Wings	DOOR	METAL	BLUE	INTACT	0	0.02	Negative	None	0	Negative					
1	51	Electrical Room between A and B Wings	COLUMN	CONCRETE	WHITE	INTACT	0	0.02	Negative	None	0	Negative					
1	51	Electrical Room between A and B Wings	COLUMN	CONCRETE	WHITE	INTACT	0	0	Negative	None	0	Negative					
1	47	Special Education Classroom next to B Wing Lunch Room	W1	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	47	Special Education Classroom next to B Wing Lunch Room	W2	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	47	Special Education Classroom next to B Wing Lunch Room	W3	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	47	Special Education Classroom next to B Wing Lunch Room	W4	DRYWALL	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	47	Special Education Classroom next to B Wing Lunch Room	Ceiling	Concrete	WHITE	INTACT	0	0	Negative	None	0	Negative					
1	47	Special Education Classroom next to B Wing Lunch Room	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	47	Special Education Classroom next to B Wing Lunch Room	DUCT	METAL	WHITE	INTACT	0	0	Negative	None	0	Negative					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	047A	Restroom inside Special Education Classroom next to B Wing Lunch Room	W1	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	047A	Restroom inside Special Education Classroom next to B Wing Lunch Room	W4	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	047A	Restroom inside Special Education Classroom next to B Wing Lunch Room	W3	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	047A	Restroom inside Special Education Classroom next to B Wing Lunch Room	W2	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	047A	Restroom inside Special Education Classroom next to B Wing Lunch Room	CEILING	PLASTER	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	047A	Restroom inside Special Education Classroom next to B Wing Lunch Room	DOOR CASING	METAL	BLUE	INTACT	0	0.02	Negative	None	0	Negative					
1	047A	Restroom inside Special Education Classroom next to B Wing Lunch Room	DOOR	WOOD	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	46	Special Education Classroom next to Book Storage Room next to A Wing Lunch Room	W1	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	46	Special Education Classroom next to Book Storage Room next to A Wing Lunch Room	W4	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	46	Special Education Classroom next to Book Storage Room next to A Wing Lunch Room	W3	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	46	Special Education Classroom next to Book Storage Room next to A Wing Lunch Room	W4	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	46	Special Education Classroom next to Book Storage Room next to A Wing Lunch Room	W4	DRYWALL	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	46	Special Education Classroom next to Book Storage Room next to A Wing Lunch Room	CEILING	PLASTER	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	45	Book Storage Room next to A Wing Lunch Room	W1	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	45	Book Storage Room next to A Wing Lunch Room	W2	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	45	Book Storage Room next to A Wing Lunch Room	W3	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	45	Book Storage Room next to A Wing Lunch Room	W4	DRYWALL	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	45	Book Storage Room next to A Wing Lunch Room	WALL	DRYWALL	BLUE	INTACT	0	0	Negative	None	0	N/A					
1	45	Book Storage Room next to A Wing Lunch Room	SOFFIT	Plaster	BLUE	INTACT	0	0.01	Negative	None	0	N/A					
1	45	Book Storage Room next to A Wing Lunch Room	SOFFIT	Plaster	WHITE	Efflorescence	150	0.02	Negative	Floor	15	N/A	No	Unknown	Yes	No	
1	45	Book Storage Room next to A Wing Lunch Room	COLUMN	CONCRETE	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	45	Book Storage Room next to A Wing Lunch Room	COLUMN	CONCRETE	WHITE	INTACT	0	0.01	Negative	None	0	Negative					
1	45	Book Storage Room next to A Wing Lunch Room	DOOR CASING	METAL	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	H03C	Hallway between C and D Wings and Gymnasium/Pool	W1	CMU	PURPLE	INTACT	0	0	Negative	None	0	Positive					
1	H03C	Hallway between C and D Wings and Gymnasium/Pool	W3	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	H03C	Hallway between C and D Wings and Gymnasium/Pool	W2	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	H03C	Hallway between C and D Wings and Gymnasium/Pool	DOOR CASING	METAL	BEIGE	INTACT	0	0.01	Negative	None	0	Negative					
1	H03C	Hallway between C and D Wings and Gymnasium/Pool	DOOR	METAL	BEIGE	INTACT	0	0	Negative	None	0	Negative					
1	H03C	Hallway between C and D Wings and Gymnasium/Pool	DOOR CENTER PANEL	METAL	BROWN	INTACT	0	0	Negative	None	0	Negative					
1	H03C	Hallway between C and D Wings and Gymnasium/Pool	Pipe Chase Door	METAL	BEIGE	INTACT	0	0	Negative	None	0	Negative					
1	H03C	Men's Staff Restroom in hallway between C and D Wings	DOOR CASING	METAL	BLUE	INTACT	0	0.5	Negative	None	0	Negative					
1	H03C	Men's Staff Restroom in hallway between C and D Wings	W1	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	H03C	Men's Staff Restroom in hallway between C and D Wings	W4	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	H03C	Men's Staff Restroom in hallway between C and D Wings	W3	CMU	WHITE	INTACT	0	0	Negative	None	0	Positive					
1	H03C	Men's Staff Restroom in hallway between C and D Wings	W2	CMU	WHITE	INTACT	0	0.01	Negative	None	0	Positive					
1	H03C	Men's Staff Restroom in hallway between C and D Wings	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	H03C	Women's Staff Restroom in hallway between C and D Wings	W1	CMU	Purple	Intact	0	0.2	Negative	None	0	Positive					
1	H03C	Women's Staff Restroom in hallway between C and D Wings	W2	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	H03C	Women's Staff Restroom in hallway between C and D Wings	W3	CMU	Beige	Intact	0	0.1	Negative	None	0	Positive					
1	H03C	Women's Staff Restroom in hallway between C and D Wings	Door	Metal	Beige	Intact	0	0.1	Negative	None	0	Negative					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
		Name of Inspector: Kristen Masotes															
		Inspection Company: Acer Associates															
Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	H03C	Women's Staff Restroom in hallway between C and D Wings	Door Center POS	Metal	Brown	Intact	0	0	Negative	None	0	Negative					
1	H03C	Women's Staff Restroom in hallway between C and D Wings	Door Casing	Metal	Beige	Intact	0	0.2	Negative	None	0	Negative					
1	H03C	Women's Staff Restroom in hallway between C and D Wings	Door	Wood	White	Intact	0	0	Negative	None	0	Negative					
1	H03C	Women's Staff Restroom in hallway between C and D Wings	Door Casing	Metal	White	Intact	0	0.2	Negative	None	0	Negative					
1	H04	Hallway outside D Wing Classrooms D1 - D7	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with D Wing Cafeteria. One Big open Area.
1	H04	Hallway outside D Wing Classrooms D1 - D7	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with D Wing Cafeteria. One Big open Area.
1	H04	Hallway outside D Wing Classrooms D1 - D7	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with D Wing Cafeteria. One Big open Area.
1	H04	Hallway outside D Wing Classrooms D1 - D7	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with D Wing Cafeteria. One Big open Area.
1	H04	Hallway outside D Wing Classrooms D1 - D7	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with D Wing Cafeteria. One Big open Area.
1	H04	Hallway outside D Wing Classrooms D1 - D7	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with D Wing Cafeteria. One Big open Area.
1	H06	Hallway connecting C Wing and D Wing	W1	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	H06	Hallway connecting C Wing and D Wing	W4	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	H06	Hallway connecting C Wing and D Wing	DOOR CASING	METAL	BLUE	INTACT	0	0.15	Negative	None	0	Negative					
1	H06	Hallway connecting C Wing and D Wing	DOOR	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	H06	Hallway connecting C Wing and D Wing	DOOR CENTER POS	METAL	BLUE	INTACT	0	0.07	Negative	None	0	Negative					
1	H06	Hallway connecting C Wing and D Wing	W3	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	H06	Hallway connecting C Wing and D Wing	STAIRS RAILING	METAL	BROWN	INTACT	0	0	Negative	None	0	Negative					
1	H06	Hallway connecting C Wing and D Wing	STAIRS RISER	METAL	BROWN	INTACT	0	0.9	Positive	None	0	Negative					
1	H06	Hallway connecting C Wing and D Wing	STAIRS STRINGER	METAL	BROWN	INTACT	0	0.8	Positive	None	0	Negative					
1	H02	Hallway outside C Wing Classrooms C1 - C7	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with C Wing Cafeteria. One Big Open Area
1	H02	Hallway outside C Wing Classrooms C1 - C7	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with C Wing Cafeteria. One Big Open Area
1	H02	Hallway outside C Wing Classrooms C1 - C7	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with C Wing Cafeteria. One Big Open Area
1	H02	Hallway outside C Wing Classrooms C1 - C7	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with C Wing Cafeteria. One Big Open Area
1	H02	Hallway outside C Wing Classrooms C1 - C7	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with C Wing Cafeteria. One Big Open Area
1	H02	Hallway outside C Wing Classrooms C1 - C7	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with C Wing Cafeteria. One Big Open Area
1	H02C2	Custodial Closet in H02 between classrooms C6 and C7	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	H02C2	Custodial Closet in H02 between classrooms C6 and C7	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	H02C2	Custodial Closet in H02 between classrooms C6 and C7	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	H02C2	Custodial Closet in H02 between classrooms C6 and C7	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	H02C2	Custodial Closet in H02 between classrooms C6 and C7	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	H02C2	Custodial Closet in H02 between classrooms C6 and C7	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	LR-D	D Wing Lunch Room	W1	CMU	BEIGE	INTACT	0	0.05	Negative	None	0	Positive					
1	LR-D	D Wing Lunch Room	W2	CMU	BEIGE	INTACT	0	0.03	Negative	None	0	Positive					
1	LR-D	D Wing Lunch Room	W3	CMU	BEIGE	INTACT	0	0	Negative	None	0	Positive					
1	LR-D	D Wing Lunch Room	W4	CMU	BEIGE	INTACT	0	0.01	Negative	None	0	Positive					
1	LR-D	D Wing Lunch Room	COLUMN	CONCRETE	BEIGE	INTACT	0	0.02	Negative	None	0	Negative					
1	LR-D	D Wing Lunch Room	COLUMN	CONCRETE	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	LR-D	D Wing Lunch Room	COLUMN	CONCRETE	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	LR-D	D Wing Lunch Room	COLUMN	CONCRETE	BEIGE	INTACT	0	0.01	Negative	None	0	Negative					
1	LR-D	D Wing Lunch Room	DOOR CASING	METAL	BLUE	INTACT	0	0.05	Negative	None	0	Negative					
1	LR-D	D Wing Lunch Room	DOOR	WOOD	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	LR-D	D Wing Lunch Room	VENT COVER	METAL	BLUE	INTACT	0	0	Negative	None	0	Negative					
1	LR-D	D Wing Lunch Room	STAIRS RISER	METAL	BROWN	INTACT	0	0.7	Positive	None	0	Negative					
1	LR-D	D Wing Lunch Room	STAIRS STRINGER	METAL	BROWN	INTACT	0	0.5	Negative	None	0	Negative					
1	LR-D	D Wing Lunch Room	STAIRS RAILING	METAL	BROWN	INTACT	0	1	Positive	None	0	Negative					
1	LR-D	D Wing Lunch Room	CEILING	CONCRETE	WHITE	INTACT	0	0	Negative	None	0	N/A					
1	LR-D	D Wing Lunch Room	SOFFIT	Plaster	BLUE	INTACT	0	0	Negative	None	0	N/A					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	LR-D	D Wing Lunch Room	SOFFIT	Plaster	BLUE	INTACT	0	0	Negative	None	0	N/A					
1	079C	Storage Closet in D Wing Lunch Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	079C	Storage Closet in D Wing Lunch Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	079C	Storage Closet in D Wing Lunch Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	079C	Storage Closet in D Wing Lunch Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	079C	Storage Closet in D Wing Lunch Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	079C	Storage Closet in D Wing Lunch Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	S06	Stairwell inside D Wing Lunch Room	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with D Wing Cafeteria
1	S06	Stairwell inside D Wing Lunch Room	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with D Wing Cafeteria
1	S06	Stairwell inside D Wing Lunch Room	S06	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with D Wing Cafeteria
1	S06	Stairwell inside D Wing Lunch Room	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with D Wing Cafeteria
1	S06	Stairwell inside D Wing Lunch Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with D Wing Cafeteria
1	S06	Stairwell inside D Wing Lunch Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with D Wing Cafeteria
1	LR-C	C Wing Lunch Room	W1	CMU	BLUE	INTACT	0	0.01	Negative	None	0	Positive					
1	LR-C	C Wing Lunch Room	W2	CMU	BLUE	INTACT	0	0.01	Negative	None	0	Positive					
1	LR-C	C Wing Lunch Room	W3	CMU	BLUE	INTACT	0	0	Negative	None	0	Positive					
1	LR-C	C Wing Lunch Room	W4	CMU	BLUE	INTACT	0	0.01	Negative	None	0	Positive					
1	LR-C	C Wing Lunch Room	DOOR CASING	METAL	BLUE	INTACT	0	0.02	Negative	None	0	Negative					
1	LR-C	C Wing Lunch Room	DOOR	METAL	BLUE	INTACT	0	0.01	Negative	None	0	Negative					
1	LR-C	C Wing Lunch Room	SOFFIT	PLASTER	BEIGE	INTACT	0	0	Negative	None	0	N/A					
1	LR-C	C Wing Lunch Room	STAIRS RAILING	METAL	BROWN	INTACT	0	0.21	Negative	None	0	Negative					
1	LR-C	C Wing Lunch Room	STAIRS RISER	METAL	BROWN	INTACT	0	0.5	Negative	None	0	Negative					
1	LR-C	C Wing Lunch Room	STAIRS STRINGER	METAL	BROWN	INTACT	0	0.8	Positive	None	0	Negative					
1	LR-C	C Wing Lunch Room	CEILING	CONCRETE	WHITE	Flaking	15	0.03	Negative	None	0	N/A	No	No	NO	NO	Flaking
1	LR-C	C Wing Lunch Room	SOFFIT	PLASTER	BEIGE	INTACT	0	0	Negative	None	0	N/A					
1	LR-C	C Wing Lunch Room	SOFFIT	PLASTER	BEIGE	INTACT	0	0	Negative	None	0	N/A					
1	S05	Stairwell inside C Wing Lunch Room	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with C Wing Cafeteria
1	S05	Stairwell inside C Wing Lunch Room	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with C Wing Cafeteria
1	S05	Stairwell inside C Wing Lunch Room	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with C Wing Cafeteria
1	S05	Stairwell inside C Wing Lunch Room	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with C Wing Cafeteria
1	S05	Stairwell inside C Wing Lunch Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with C Wing Cafeteria
1	S05	Stairwell inside C Wing Lunch Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with C Wing Cafeteria
1	006D	Classroom D6 and D7	W1	CMU	WHITE	None	0	0	Negative	None	0	Positive					
1	006D	Classroom D6 and D7	W4	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	006D	Classroom D6 and D7	W2	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	006D	Classroom D6 and D7	W3	CMU	PURPLE	None	0	0	Negative	None	0	Positive					
1	006D	Classroom D6 and D7	W3	CMU	WHITE	None	0	0.02	Negative	None	0	Positive					
1	006D	Classroom D6 and D7	SOFFIT	Plaster	WHITE	None	0	0	Negative	None	0	N/A					
1	006D	Classroom D6 and D7	SOFFIT	Plaster	WHITE	None	0	0	Negative	None	0	N/A					
1	006D	Classroom D6 and D7	COLUMN	METAL	WHITE	None	0	0.01	Negative	None	0	Negative					
1	006D	Classroom D6 and D7	WALL DIVIDER TR	WOOD	WHITE	None	0	0	Negative	None	0	Negative					
1	006D	Classroom D6 and D7	CEILING COLUMN	CONCRETE	WHITE	None	0	0.01	Negative	None	0	Negative					
1	006D	Classroom D6 and D7	DOOR CASING	METAL	BEIGE	None	0	0.01	Negative	None	0	Negative					
1	006D	Classroom D6 and D7	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
1	005D	Classroom D5	DOOR CASING	METAL	BLUE	None	0	0	Negative	None	0	Negative					
1	005D	Classroom D5	DOOR	WOOD	BLUE	None	0	0	Negative	None	0	Negative					
1	005D	Classroom D5	W1	CMU	WHITE	None	0	0	Negative	None	0	Positive					
1	005D	Classroom D5	W4	CMU	WHITE	None	0	0.03	Negative	None	0	Positive					
1	005D	Classroom D5	W3	CMU	PURPLE	None	0	0.02	Negative	None	0	Positive					
1	005D	Classroom D5	SOFFIT	Plaster	WHITE	None	0	0	Negative	None	0	N/A					
1	005D	Classroom D5	COLUMN	CONCRETE	PURPLE	None	0	0.01	Negative	None	0	Negative					
1	005D	Classroom D5	WALL DIVIDER TR	WOOD	WHITE	None	0	0	Negative	None	0	Negative					
1	005D	Classroom D5	WALL DIVIDER TR	DRYWALL	WHITE	None	0	0	Negative	None	0	N/A					
1	004D	Classroom D4	WALL DIVIDER TR	DRYWALL	WHITE	None	0	0	Negative	None	0	N/A					
1	004D	Classroom D4	WALL DIVIDER TR	WOOD	WHITE	None	0	0	Negative	None	0	Negative					
1	004D	Classroom D4	W1	CMU	WHITE	None	0	0.02	Negative	None	0	Positive					
1	004D	Classroom D4	W2	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	004D	Classroom D4	W3	CMU	WHITE	None	0	0.02	Negative	None	0	Positive					
1	004D	Classroom D4	W3	CMU	PURPLE	None	0	0.05	Negative	None	0	Positive					
1	004D	Classroom D4	COLUMN	CONCRETE	PURPLE	None	0	0.01	Negative	None	0	Negative					
1	004D	Classroom D4	COLUMN	CONCRETE	WHITE	None	0	0	Negative	None	0	Negative					
1	004D	Classroom D4	SOFFIT 3	Plaster	WHITE	Efflorescence	3	0	Negative	None	0	N/A	No	Temperature Control	No	No	Efflorescence from Univent
1	004D	Classroom D4	SOFFIT	Plaster	WHITE	None	0	0.03	Negative	None	0	N/A					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
		Name of Inspector: Kristen Masotes								Inspection Company: Acer Associates							
Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	004D	Classroom D4	COLUMN	CONCRETE	WHITE	None	0	0.05	Negative	None	0	Negative					
1	003D	Classroom D3	W3	CMU	WHITE	None	0	0.04	Negative	None	0	Positive					
1	003D	Classroom D3	W4	CMU	WHITE	None	0	0	Negative	None	0	Positive					
1	003D	Classroom D3	W2	CMU	PURPLE	None	0	0.01	Negative	None	0	Positive					
1	003D	Classroom D3	UNIVENT	METAL	BEIGE	None	0	0	Negative	None	0	N/A					
1	003D	Classroom D3	SOFFIT	Plaster	WHITE	None	0	0.01	Negative	None	0	N/A					
1	003D	Classroom D3	SOFFIT	Plaster	WHITE	None	0	0.02	Negative	None	0	N/A					
1	003D	Classroom D3	DIVIDER WALL TR	WOOD	WHITE	None	0	0.01	Negative	None	0	Negative					
1	003D	Classroom D3	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative	None	0	N/A					
1	003D	Classroom D3	DOOR CENTER P	METAL	BEIGE	None	0	0.01	Negative	None	0	Negative					
1	002D	Classroom D2	DOOR CASING	METAL	BLACK	None	0	0.01	Negative	None	0	Negative					
1	002D	Classroom D2	W1	CMU	WHITE	None	0	0.03	Negative	None	0	Positive					
1	002D	Classroom D2	W2	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	002D	Classroom D2	W3	CMU	GREEN	None	0	0.01	Negative	None	0	Positive					
1	002D	Classroom D2	W3	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	002D	Classroom D2	SOFFIT	Plaster	WHITE	Efflorescence	6	0	Negative	None	0	N/A	No	Temperature Control	No	No	Efflorescence from Univent
1	002D	Classroom D2	UNIVENT	Metal	WHITE	None	0	0	Negative	None	0	N/A					
1	002D	Classroom D2	COLUMN	CONCRETE	GREEN	None	0	0.02	Negative	None	0	Negative					
1	002D	Classroom D2	DIVIDER WALL TR	WOOD	WHITE	None	0	0.01	Negative	None	0	Negative					
1	002D	Classroom D2	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative	None	0	Negative					
1	001D	Classroom D1	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
1	001D	Classroom D1	W1	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	001D	Classroom D1	W2	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	001D	Classroom D1	W4	CMU	WHITE	None	0	0.03	Negative	None	0	Positive					
1	001D	Classroom D1	W3	CMU	PURPLE	None	0	0.01	Negative	None	0	Positive					
1	001D	Classroom D1	COLUMN	METAL	PURPLE	None	0	0.01	Negative	None	0	Negative					
1	001D	Classroom D1	SOFFIT	Plaster	WHITE	None	0	0.02	Negative	None	0	N/A					
1	001D	Classroom D1	SOFFIT	Plaster	WHITE	None	0	0.03	Negative	None	0	N/A					
1	001D	Classroom D1	UNIVENT	METAL	WHITE	None	0	0	Negative	None	0	N/A					
1	78	D Wing Boy's Restroom	W1	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	78	D Wing Boy's Restroom	W2	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	78	D Wing Boy's Restroom	W3	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	78	D Wing Boy's Restroom	CEILING	CONCRETE	BEIGE	None	0	0	Negative	None	0	N/A					
1	78	D Wing Boy's Restroom	DOOR CASING	METAL	BLACK	None	0	0.11	Negative	None	0	Negative					
1	H02C1	Storage Closet in H02 between classrooms C6 and C7	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	H02C1	Storage Closet in H02 between classrooms C6 and C7	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	H02C1	Storage Closet in H02 between classrooms C6 and C7	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	H02C1	Storage Closet in H02 between classrooms C6 and C7	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	H02C1	Storage Closet in H02 between classrooms C6 and C7	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	H02C1	Storage Closet in H02 between classrooms C6 and C7	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	76	D Wing Girl's Restroom	DOOR CASING	METAL	BLACK	None	0	0.3	Negative	None	0	Negative					
1	76	D Wing Girl's Restroom	W1	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	76	D Wing Girl's Restroom	W2	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	76	D Wing Girl's Restroom	W3	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	76	D Wing Girl's Restroom	W4	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	76	D Wing Girl's Restroom	CEILING	Concrete	BEIGE	None	0	0	Negative	None	0	N/A					
1	S09	Stairwell between C and D Wings	W1	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	S09	Stairwell between C and D Wings	W4	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	S09	Stairwell between C and D Wings	DOOR CASING	METAL	BLUE	None	0	0.15	Negative	None	0	Negative					
1	S09	Stairwell between C and D Wings	DOOR	METAL	BLUE	None	0	0	Negative	None	0	Negative					
1	S09	Stairwell between C and D Wings	DOOR CENTER P	METAL	BLUE	None	0	0.07	Negative	None	0	Negative					
1	S09	Stairwell between C and D Wings	W3	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	S09	Stairwell between C and D Wings	STAIRS RAILING	METAL	BROWN	None	0	0	Negative	None	0	Negative					
1	S09	Stairwell between C and D Wings	STAIRS RISER	METAL	BROWN	None	0	0.9	Positive	None	0	Negative					
1	S09	Stairwell between C and D Wings	STAIRS STRINGER	METAL	BROWN	None	0	0.8	Positive	None	0	Negative					
1	71	C Wing Girl's Restroom	DOOR CASING	METAL	BLACK	None	0	0.15	Negative	None	0	Negative					
1	71	C Wing Girl's Restroom	W1	CMU	YELLOW	None	0	0	Negative	None	0	Positive					
1	71	C Wing Girl's Restroom	W2	CMU	YELLOW	None	0	0	Negative	None	0	Positive					
1	71	C Wing Girl's Restroom	W3	CMU	YELLOW	None	0	0	Negative	None	0	Positive					
1	71	C Wing Girl's Restroom	CEILING	CONCRETE	BEIGE	None	0	0	Negative	None	0	N/A					
1	70	C Wing Boy's Restroom	CEILING	CONCRETE	BEIGE	None	0	0	Negative	None	0	N/A					
1	70	C Wing Boy's Restroom	W1	CMU	BEIGE	None	0	0	Negative	None	0	Positive					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report										Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21					
		E.W. Rhodes ES School										ULCS# 4150					
		Name of Inspector: Kristen Masotes															
		Inspection Company: Acer Associates															
Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	70	C Wing Boy's Restroom	W4	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	70	C Wing Boy's Restroom	W3	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	70	C Wing Boy's Restroom	DOOR CASING	METAL	BLACK	None	0	0.21	Negative	None	0	Negative					
1	69	Storage Closet between boy's and girl's restrooms in C wing	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	69	Storage Closet between boy's and girl's restrooms in C wing	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	69	Storage Closet between boy's and girl's restrooms in C wing	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	69	Storage Closet between boy's and girl's restrooms in C wing	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	69	Storage Closet between boy's and girl's restrooms in C wing	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	69	Storage Closet between boy's and girl's restrooms in C wing	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	69PC	Pipe Chase in Storage Closet between boy's and girl's restrooms in C wing	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	69PC	Pipe Chase in Storage Closet between boy's and girl's restrooms in C wing	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	69PC	Pipe Chase in Storage Closet between boy's and girl's restrooms in C wing	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	69PC	Pipe Chase in Storage Closet between boy's and girl's restrooms in C wing	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	69PC	Pipe Chase in Storage Closet between boy's and girl's restrooms in C wing	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	69PC	Pipe Chase in Storage Closet between boy's and girl's restrooms in C wing	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	S04	Stairwell behind C Wing Classroom C7	W1	BRICK	BEIGE	None	0	0.01	Negative	None	0	N/A					
1	S04	Stairwell behind C Wing Classroom C7	W2	BRICK	BEIGE	None	0	0.01	Negative	None	0	N/A					
1	S04	Stairwell behind C Wing Classroom C7	W4	BRICK	BEIGE	None	0	0.01	Negative	None	0	N/A					
1	S04	Stairwell behind C Wing Classroom C7	W3	BRICK	BEIGE	None	0	0.03	Negative	None	0	N/A					
1	S04	Stairwell behind C Wing Classroom C7	W3	DRYWALL	BEIGE	None	0	0	Negative	None	0	N/A					
1	S04	Stairwell behind C Wing Classroom C7	STAIRS RISER	METAL	BEIGE	None	0	0.6	Negative	None	0	Negative					
1	S04	Stairwell behind C Wing Classroom C7	STAIRS STRINGER	METAL	BEIGE	None	0	1.2	Positive	None	0	Negative					
1	S04	Stairwell behind C Wing Classroom C7	STAIRS RAILING	METAL	BEIGE	None	0	0.02	Negative	None	0	Negative					
1	S04	Stairwell behind C Wing Classroom C7	STAIRS HALFVAL	WOOD	BEIGE	None	0	0	Negative	None	0	Negative					
1	S04	Stairwell behind C Wing Classroom C7	W3	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	S04	Stairwell behind C Wing Classroom C7	DOOR CASING	METAL	BEIGE	None	0	0	Negative	None	0	Negative					
1	S04	Stairwell behind C Wing Classroom C7	DOOR	METAL	BEIGE	None	0	0	Negative	None	0	Negative					
1	S04	Stairwell behind C Wing Classroom C7	DOOR CENTER P	METAL	BEIGE	None	0	0	Negative	None	0	Negative					
1	S04	Stairwell behind C Wing Classroom C7	UNIVENT	METAL	BEIGE	None	0	0.01	Negative	None	0	N/A					
1	S04	Stairwell behind C Wing Classroom C7	CEILING	CONCRETE	BEIGE	None	0	0.04	Negative	None	0	N/A					
1	007C	Classroom C7	DOOR CASING	METAL	BLUE	None	0	0.04	Negative	None	0	Negative					
1	007C	Classroom C7	DOOR	WOOD	BLUE	None	0	0	Negative	None	0	Negative					
1	007C	Classroom C7	W1	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	007C	Classroom C7	W2	CMU	WHITE	None	0	0.02	Negative	None	0	Positive					
1	007C	Classroom C7	W3	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	007C	Classroom C7	DIVIDER WALL TH	WOOD	WHITE	None	0	0	Negative	None	0	Negative					
1	007C	Classroom C7	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative	None	0	N/A					
1	006C	Classroom C6	DIVIDER WALL	DRYWALL	WHITE	None	0	0.01	Negative	None	0	N/A					
1	006C	Classroom C6	DIVIDER WALL TH	WOOD	WHITE	None	0	0.01	Negative	None	0	Negative					
1	006C	Classroom C6	W1	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	006C	Classroom C6	W4	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	006C	Classroom C6	W2	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	006C	Classroom C6	W3	CMU	GREEN	None	0	0.02	Negative	None	0	Positive					
1	006C	Classroom C6	SOFFIT	PLASTER	WHITE	None	0	0.05	Negative	None	0	N/A					
1	006C	Classroom C6	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative	None	0	N/A					
1	006C	Classroom C6	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
1	005C	Classroom C5	W1	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	005C	Classroom C5	W2	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	005C	Classroom C5	W3	CMU	WHITE	None	0	0	Negative	None	0	Positive					
1	005C	Classroom C5	SOFFIT	PLASTER	WHITE	None	0	0	Negative	None	0	N/A					
1	005C	Classroom C5	DIVIDER WALL TH	WOOD	WHITE	None	0	0.01	Negative	None	0	Negative					
1	005C	Classroom C5	DIVIDER WALL	DRYWALL	WHITE	None	0	0.01	Negative	None	0	N/A					
1	004C	Classroom C4	SOFFIT	Plaster	WHITE	None	0	0.02	Negative	None	0	N/A					
1	004C	Classroom C4	SOFFIT	Plaster	WHITE	None	0	0.01	Negative	None	0	N/A					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
		Name of Inspector: Kristen Masotes															
		Inspection Company: Acer Associates															
Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	004C	Classroom C4	W1	CMU	WHITE	None	0	0.02	Negative	None	0	Positive					
1	004C	Classroom C4	W4	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	004C	Classroom C4	W3	CMU	GREEN	None	0	0.01	Negative	None	0	Positive					
1	004C	Classroom C4	COLUMN	METAL	GREEN	None	0	0.01	Negative	None	0	Negative					
1	004C	Classroom C4	COLUMN	METAL	WHITE	None	0	0.01	Negative	None	0	Negative					
1	004C	Classroom C4	DIVIDER WALL TR	WOOD	WHITE	None	0	0.05	Negative	None	0	Negative					
1	004C	Classroom C4	DIVIDER WALL	DRYWALL	WHITE	None	0	0.02	Negative	None	0	N/A					
1	004C	Classroom C4	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
1	004C	Classroom C4	DOOR	WOOD	BLUE	None	0	0	Negative	None	0	Negative					
1	003C	Classroom C3	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative	None	0	N/A					
1	003C	Classroom C3	DIVIDER WALL TR	WOOD	WHITE	None	0	0	Negative	None	0	Negative					
1	003C	Classroom C3	W1	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	003C	Classroom C3	W2	CMU	WHITE	None	0	0.03	Negative	None	0	Positive					
1	003C	Classroom C3	W3	CMU	GREEN	None	0	0.01	Negative	None	0	Positive					
1	003C	Classroom C3	SOFFIT	Plaster	WHITE	None	0	0.02	Negative	None	0	N/A					
1	003C	Classroom C3	SOFFIT	Plaster	WHITE	None	0	0.01	Negative	None	0	N/A					
1	002C	Classroom C2	SOFFIT	Plaster	WHITE	None	0	0.02	Negative	None	0	N/A					
1	002C	Classroom C2	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Positive					
1	002C	Classroom C2	DOOR CASING	METAL	BLUE	None	0	0.09	Negative	None	0	Negative					
1	002C	Classroom C2	W4	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	002C	Classroom C2	W3	CMU	GREEN	None	0	0.01	Negative	None	0	Positive					
1	002C	Classroom C2	SOFFIT	Plaster	WHITE	None	0	0.01	Negative	None	0	N/A					
1	002C	Classroom C2	DIVIDER WALL TR	WOOD	WHITE	None	0	0	Negative	None	0	Negative					
1	002C	Classroom C2	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative	None	0	N/A					
1	002C	Classroom C2	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative	None	0	N/A					
1	001C	Classroom C1	W1	CMU	WHITE	None	0	0.02	Negative	None	0	Positive					
1	001C	Classroom C1	W4	CMU	WHITE	None	0	0	Negative	None	0	Positive					
1	001C	Classroom C1	W3	CMU	WHITE	None	0	0.03	Negative	None	0	Positive					
1	001C	Classroom C1	W2	CMU	GREEN	None	0	0.01	Negative	None	0	Positive					
1	001C	Classroom C1	COLUMN	METAL	GREEN	None	0	0.02	Negative	None	0	Negative					
1	001C	Classroom C1	SOFFIT	Plaster	WHITE	None	0	0.02	Negative	None	0	N/A					
1	001C	Classroom C1	W2	CMU	WHITE	None	0	0.01	Negative	None	0	Positive					
1	001C	Classroom C1	SOFFIT	Plaster	WHITE	None	0	0.02	Negative	None	0	N/A					
1	74	Kitchen	W1	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	74	Kitchen	W2	CMU	BEIGE	None	0	0.01	Negative	None	0	Positive					
1	74	Kitchen	W3	CMU	BEIGE	None	0	0.02	Negative	None	0	Positive					
1	74	Kitchen	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Positive					
1	74	Kitchen	DOOR	WOOD	BLUE	None	0	0.03	Negative	None	0	Negative					
1	74	Kitchen	DOOR CASING	METAL	BLUE	None	0	0.03	Negative	None	0	Negative					
1	74	Kitchen	COLUMN	METAL	BEIGE	None	0	0.01	Negative	None	0	Negative					
1	74	Kitchen	W4	CMU	WHITE	None	0	0	Negative	None	0	Positive					
1	74	Kitchen	DOOR CASING	METAL	BLUE	None	0	0.03	Negative	None	0	Negative					
1	74	Kitchen	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
1	074A	Kitchen Locker Room	DOOR	WOOD	BLUE	None	0	0.06	Negative	None	0	Negative					
1	074A	Kitchen Locker Room	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
1	074A	Kitchen Locker Room	W1	CMU	YELLOW	None	0	0	Negative	None	0	Positive					
1	074A	Kitchen Locker Room	W2	CMU	YELLOW	None	0	0	Negative	None	0	Positive					
1	074A	Kitchen Locker Room	W4	CMU	YELLOW	None	0	0.04	Negative	None	0	Positive					
1	074A	Kitchen Locker Room	W3	CMU	YELLOW	None	0	0.01	Negative	None	0	Positive					
1	074B	Kitchen Custodial Closet near C Cafeteria	W1	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	074B	Kitchen Custodial Closet near C Cafeteria	W1	DRYWALL	BEIGE	None	0	0	Negative	None	0	Positive					
1	074B	Kitchen Custodial Closet near C Cafeteria	DOOR CENTER PC	METAL	BLUE	None	0	0.09	Negative	None	0	Negative					
1	074B	Kitchen Custodial Closet near C Cafeteria	W2	CMU	BEIGE	None	0	0.01	Negative	None	0	Positive					
1	074B	Kitchen Custodial Closet near C Cafeteria	W3	CMU	BEIGE	None	0	0.02	Negative	None	0	Positive					
1	074B	Kitchen Custodial Closet near C Cafeteria	W4	CMU	BEIGE	None	0	0.03	Negative	None	0	Positive					
1	75	Kitchen Lounge	DOOR	WOOD	BLUE	None	0	0.06	Negative	None	0	Negative					
1	75	Kitchen Lounge	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
1	75	Kitchen Lounge	W1	CMU	YELLOW	None	0	0	Negative	None	0	Positive					
1	75	Kitchen Lounge	W2	CMU	YELLOW	None	0	0	Negative	None	0	Positive					
1	75	Kitchen Lounge	W4	CMU	YELLOW	None	0	0.04	Negative	None	0	Positive					
1	75	Kitchen Lounge	W3	CMU	YELLOW	None	0	0.01	Negative	None	0	Positive					
1	075A	Kitchen Lounge Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	075A	Kitchen Lounge Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	075A	Kitchen Lounge Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	075A	Kitchen Lounge Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	075A	Kitchen Lounge Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	075A	Kitchen Lounge Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	69	Dietician's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	69	Dietician's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	69	Dietician's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	69	Dietician's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	69	Dietician's Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	69	Dietician's Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	72	Storage Room next to C Wing Lunch Room	W1	CONCRETE	WHITE	None	0	0	Negative	None	0	Positive					
1	72	Storage Room next to C Wing Lunch Room	W4	CMU	WHITE	None	0	0	Negative	None	0	Positive					
1	72	Storage Room next to C Wing Lunch Room	W2	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	72	Storage Room next to C Wing Lunch Room	FLOOR	METAL	GRAY	None	0	0	Negative	None	0	Negative					
1	72	Storage Room next to C Wing Lunch Room	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
1	72	Storage Room next to C Wing Lunch Room	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
1	73	Walk in Freezer Room	W1	CONCRETE	WHITE	None	0	0	Negative	None	0	Positive					
1	73	Walk in Freezer Room	W4	CMU	WHITE	None	0	0	Negative	None	0	Positive					
1	73	Walk in Freezer Room	W2	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	73	Walk in Freezer Room	FLOOR	METAL	GRAY	None	0	0	Negative	None	0	Negative					
1	73	Walk in Freezer Room	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
1	73	Walk in Freezer Room	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
1	80	Food Storage Room next to D Wing Lunch Room	W1	CONCRETE	WHITE	None	0	0	Negative	None	0	Positive					
1	80	Food Storage Room next to D Wing Lunch Room	W4	CMU	WHITE	None	0	0	Negative	None	0	Positive					
1	80	Food Storage Room next to D Wing Lunch Room	W2	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	80	Food Storage Room next to D Wing Lunch Room	FLOOR	METAL	GRAY	None	0	0	Negative	None	0	Negative					
1	80	Food Storage Room next to D Wing Lunch Room	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
1	80	Food Storage Room next to D Wing Lunch Room	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
1	080A	Closet inside Food Storage Room next to D Wing Lunch Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	080A	Closet inside Food Storage Room next to D Wing Lunch Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	080A	Closet inside Food Storage Room next to D Wing Lunch Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	080A	Closet inside Food Storage Room next to D Wing Lunch Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	080A	Closet inside Food Storage Room next to D Wing Lunch Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	080A	Closet inside Food Storage Room next to D Wing Lunch Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	S07	Stairwell next to D Wing Classroom D7	W1	BRICK	BEIGE	None	0	0.01	Negative	None	0	N/A					
1	S07	Stairwell next to D Wing Classroom D7	W2	BRICK	BEIGE	None	0	0.01	Negative	None	0	N/A					
1	S07	Stairwell next to D Wing Classroom D7	W4	BRICK	BEIGE	None	0	0.01	Negative	None	0	N/A					
1	S07	Stairwell next to D Wing Classroom D7	W3	BRICK	BEIGE	None	0	0.03	Negative	None	0	N/A					
1	S07	Stairwell next to D Wing Classroom D7	W3	DRYWALL	BEIGE	None	0	0	Negative	None	0	N/A					
1	S07	Stairwell next to D Wing Classroom D7	STAIRS RISER	METAL	BEIGE	None	0	0.6	Negative	None	0	Negative					
1	S07	Stairwell next to D Wing Classroom D7	STAIRS STRINGER	METAL	BEIGE	None	0	1.2	Positive	None	0	Negative					
1	S07	Stairwell next to D Wing Classroom D7	STAIRS RAILING	METAL	BEIGE	None	0	0.02	Negative	None	0	Negative					
1	S07	Stairwell next to D Wing Classroom D7	STAIRS HALFVAL	WOOD	BEIGE	None	0	0	Negative	None	0	Negative					
1	S07	Stairwell next to D Wing Classroom D7	W3	CMU	BEIGE	None	0	0	Negative	None	0	Positive					
1	S07	Stairwell next to D Wing Classroom D7	DOOR CASING	METAL	BEIGE	None	0	0	Negative	None	0	Negative					
1	S07	Stairwell next to D Wing Classroom D7	DOOR	METAL	BEIGE	None	0	0	Negative	None	0	Negative					
1	S07	Stairwell next to D Wing Classroom D7	DOOR CENTER P	METAL	BEIGE	None	0	0	Negative	None	0	Negative					
1	S07	Stairwell next to D Wing Classroom D7	UNIVENT	METAL	BEIGE	None	0	0.01	Negative	None	0	N/A					
1	S07	Stairwell next to D Wing Classroom D7	CEILING	CONCRETE	BEIGE	None	0	0.04	Negative	None	0	N/A					
1	83	Men's Restroom behind D Wing Stairwell	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Padlocked
1	83	Men's Restroom behind D Wing Stairwell	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Padlocked
1	83	Men's Restroom behind D Wing Stairwell	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Padlocked
1	83	Men's Restroom behind D Wing Stairwell	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Padlocked
1	83	Men's Restroom behind D Wing Stairwell	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Padlocked
1	83	Men's Restroom behind D Wing Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Padlocked
1	84	Women's Restroom behind D Wing Stairwell	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Padlocked
1	84	Women's Restroom behind D Wing Stairwell	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Padlocked
1	84	Women's Restroom behind D Wing Stairwell	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Padlocked
1	84	Women's Restroom behind D Wing Stairwell	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Padlocked

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	84	Women's Restroom behind D Wing Stairwell	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Padlocked
1	84	Women's Restroom behind D Wing Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Padlocked
1	67	Pool Area (closed)	W1	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	67	Pool Area (closed)	W4	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	67	Pool Area (closed)	W3	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	67	Pool Area (closed)	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	67	Pool Area (closed)	Door Casing	Metal	Brown	None	0	0	Negative	None	0	Negative					
1	67	Pool Area (closed)	Door	Metal	Brown	None	0	0.1	Negative	None	0	Negative					
1	67	Pool Area (closed)	Door	Metal	Brown	None	0	0.1	Negative	None	0	Negative					
1	67	Pool Area (closed)	Door Casing	Metal	Brown	None	0	0.1	Negative	None	0	Negative					
1	67	Pool Area (closed)	Door Casing	Metal	Brown	None	0	0.1	Negative	None	0	Negative					
1	67	Pool Area (closed)	Door	Wood	Brown	None	0	0	Negative	None	0	Negative					
1	64	Storage/Pool Pump Room	W2	CMU	Yellow	None	0	0.1	Negative	None	0	Positive					
1	64	Storage/Pool Pump Room	W4	CMU	Yellow	None	0	0.2	Negative	None	0	Positive					
1	64	Storage/Pool Pump Room	W3	CMU	Yellow	None	0	0.3	Negative	None	0	Positive					
1	64	Storage/Pool Pump Room	Column	Concrete	Yellow	None	0	0.2	Negative	None	0	Negative					
1	63	Pool Equipment Storage Room	W1	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	63	Pool Equipment Storage Room	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	66	Pool Office	W1	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	66	Pool Office	W4	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	66	Pool Office	W3	CMU	White	None	0	0	Negative	None	0	Positive					
1	66	Pool Office	W2	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	057B	Boy's Locker Room Restroom and Showers	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	057B	Boy's Locker Room Restroom and Showers	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	057B	Boy's Locker Room Restroom and Showers	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	057B	Boy's Locker Room Restroom and Showers	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	057B	Boy's Locker Room Restroom and Showers	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	057B	Boy's Locker Room Restroom and Showers	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	057C	Boy's Locker Room Changing Booth	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	057C	Boy's Locker Room Changing Booth	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	057C	Boy's Locker Room Changing Booth	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	057C	Boy's Locker Room Changing Booth	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	057C	Boy's Locker Room Changing Booth	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	057C	Boy's Locker Room Changing Booth	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	BLRH	Boy's Locker Room Hallway	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Boy's Locker Room
1	BLRH	Boy's Locker Room Hallway	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Boy's Locker Room
1	BLRH	Boy's Locker Room Hallway	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Boy's Locker Room
1	BLRH	Boy's Locker Room Hallway	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Boy's Locker Room
1	BLRH	Boy's Locker Room Hallway	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Boy's Locker Room
1	BLRH	Boy's Locker Room Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Boy's Locker Room
1	57	Boy's Locker Room - Main Area	W1	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	57	Boy's Locker Room - Main Area	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	57	Boy's Locker Room - Main Area	W3	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	57	Boy's Locker Room - Main Area	W4	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	57	Boy's Locker Room - Main Area	Door Casing	Metal	Tan	None	0	0.7	Positive	None	0	Negative					
1	57	Boy's Locker Room - Main Area	Door	Wood	Tan	None	0	0.1	Negative	None	0	Negative					
1	57	Boy's Locker Room - Main Area	Door	Wood	Tan	None	0	0.1	Negative	None	0	Negative					
1	57	Boy's Locker Room - Main Area	Door Casing	Metal	Tan	None	0	0.7	Positive	None	0	Negative					
1	57	Boy's Locker Room - Main Area	Door Casing	Metal	Tan	None	0	0.6	Negative	None	0	Negative					
1	057A	Boy's Locker Room Shower Area	W2	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	057A	Boy's Locker Room Shower Area	W3	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	057A	Boy's Locker Room Shower Area	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	055C	Storage Closet inside Boy's Locker Room Main Area	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	055C	Storage Closet inside Boy's Locker Room Main Area	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	055C	Storage Closet inside Boy's Locker Room Main Area	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	055C	Storage Closet inside Boy's Locker Room Main Area	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	055C	Storage Closet inside Boy's Locker Room Main Area	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	055C	Storage Closet inside Boy's Locker Room Main Area	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	055B	Boy's Restroom next to Locker Room Main Area	Door Casing	Metal	Blue	None	0	0.3	Negative	None	0	Negative					
1	055B	Boy's Restroom next to Locker Room Main Area	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	055B	Boy's Restroom next to Locker Room Main Area	W1	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	055B	Boy's Restroom next to Locker Room Main Area	W2	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	055B	Boy's Restroom next to Locker Room Main Area	W3	CMU	White	None	0	0	Negative	None	0	Positive					
1	055B	Boy's Restroom next to Locker Room Main Area	W4	CMU	White	None	0	0.1	Negative	None	0	Positive					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	055B	Boy's Restroom next to Locker Room Main Area	Ceiling	Concrete	White	None	0	0.1	Negative	None	0	N/A					
1	055D	Custodial Closet next to Boy's Locker Room Main Area	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	055D	Custodial Closet next to Boy's Locker Room Main Area	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	055D	Custodial Closet next to Boy's Locker Room Main Area	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	055D	Custodial Closet next to Boy's Locker Room Main Area	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	055D	Custodial Closet next to Boy's Locker Room Main Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	055D	Custodial Closet next to Boy's Locker Room Main Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	055D-PC	Pipe Chase Custodial Closet next to Boy's Locker Room Main Area	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	055D-PC	Pipe Chase Custodial Closet next to Boy's Locker Room Main Area	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	055D-PC	Pipe Chase Custodial Closet next to Boy's Locker Room Main Area	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	055D-PC	Pipe Chase Custodial Closet next to Boy's Locker Room Main Area	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	055D-PC	Pipe Chase Custodial Closet next to Boy's Locker Room Main Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	055D-PC	Pipe Chase Custodial Closet next to Boy's Locker Room Main Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	055A	Boy's Gym Teacher's Restroom Gym Office	W1	CMU	Blue	None	0	0.1	Negative	None	0	Positive					
1	055A	Boy's Gym Teacher's Restroom Gym Office	W4	CMU	Blue	None	0	0.1	Negative	None	0	Positive					
1	055A	Boy's Gym Teacher's Restroom Gym Office	W3	CMU	Blue	None	0	0.2	Negative	None	0	Positive					
1	055A	Boy's Gym Teacher's Restroom Gym Office	W2	CMU	Blue	None	0	0.2	Negative	None	0	Positive					
1	55	Boy's Gym Teacher's Office	W1	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	55	Boy's Gym Teacher's Office	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	55	Boy's Gym Teacher's Office	W3	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	55	Boy's Gym Teacher's Office	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	55	Boy's Gym Teacher's Office	Door Casing	Metal	Blue	None	0	0.7	Positive	None	0	Negative					
1	55	Boy's Gym Teacher's Office	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	55	Boy's Gym Teacher's Office	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	55	Boy's Gym Teacher's Office	Door Casing	Metal	Blue	None	0	0.6	Negative	None	0	Negative					
1	55	Boy's Gym Teacher's Office	Door Casing	Wood	Blue	None	0	0	Negative	None	0	Negative					
1	55	Boy's Gym Teacher's Office	Door Casing	Metal	Blue	None	0	0.5	Negative	None	0	Negative					
1	56	Boy's Gym Storage Room across from the Gym Teacher's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
1	56	Boy's Gym Storage Room across from the Gym Teacher's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
1	56	Boy's Gym Storage Room across from the Gym Teacher's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
1	56	Boy's Gym Storage Room across from the Gym Teacher's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
1	56	Boy's Gym Storage Room across from the Gym Teacher's Office	Duct	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
1	56A	Storage room across from boy's changing booths	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
1	56A	Storage room across from boy's changing booths	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
1	56A	Storage room across from boy's changing booths	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
1	56A	Storage room across from boy's changing booths	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
1	56A	Storage room across from boy's changing booths	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
1	56A	Storage room across from boy's changing booths	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
1	54	Gymnasium	W1	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	54	Gymnasium	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	54	Gymnasium	W3	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	54	Gymnasium	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	54	Gymnasium	Door Casing	Metal	Blue	None	0	0.2	Negative	None	0	Negative					
1	54	Gymnasium	Door Center POS	Metal	Blue	None	0	0	Negative	None	0	Negative					
1	54	Gymnasium	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
1	S011	Stairwell in Boy's Side Gymnasium to Upper Weight Room	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Gym
1	S011	Stairwell in Boy's Side Gymnasium to Upper Weight Room	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Gym
1	S011	Stairwell in Boy's Side Gymnasium to Upper Weight Room	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Gym
1	S011	Stairwell in Boy's Side Gymnasium to Upper Weight Room	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Gym
1	S011	Stairwell in Boy's Side Gymnasium to Upper Weight Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Gym
1	S011	Stairwell in Boy's Side Gymnasium to Upper Weight Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Gym

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
		Name of Inspector: Kristen Masotes															
		Inspection Company: Acer Associates															
Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	S012	Stairwell in Girl's Side Gymnasium to Upper Weight Room	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Gym
1	S012	Stairwell in Girl's Side Gymnasium to Upper Weight Room	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Gym
1	S012	Stairwell in Girl's Side Gymnasium to Upper Weight Room	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Gym
1	S012	Stairwell in Girl's Side Gymnasium to Upper Weight Room	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Gym
1	S012	Stairwell in Girl's Side Gymnasium to Upper Weight Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Gym
1	S012	Stairwell in Girl's Side Gymnasium to Upper Weight Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Gym
2	122E	Upper Weight Room above Locker Rooms	W1	CMU	Blue	None	0	0	Negative	None	0	Positive					
2	122E	Upper Weight Room above Locker Rooms	W4	CMU	Blue	None	0	0.1	Negative	None	0	Positive					
2	122E	Upper Weight Room above Locker Rooms	W3	CMU	Blue	None	0	0.1	Negative	None	0	Positive					
2	122E	Upper Weight Room above Locker Rooms	W2	CMU	Blue	None	0	0.1	Negative	None	0	Positive					
2	122E	Upper Weight Room above Locker Rooms	W2	CMU	Yellow	None	0	0.1	Negative	None	0	Positive					
2	122E	Upper Weight Room above Locker Rooms	W1	CMU	Yellow	None	0	0.1	Negative	None	0	Positive					
2	122E	Upper Weight Room above Locker Rooms	W3	CMU	Yellow	None	0	0	Negative	None	0	Positive					
2	122E	Upper Weight Room above Locker Rooms	W4	CMU	Yellow	None	0	0.2	Negative	None	0	Positive					
2	122E	Upper Weight Room above Locker Rooms	Door Casing	Metal	Blue	None	0	0.2	Negative	None	0	Negative					
2	122E	Upper Weight Room above Locker Rooms	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	058A	Girl's Locker Room Restroom	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	058A	Girl's Locker Room Restroom	W3	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	058A	Girl's Locker Room Restroom	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	61	Girl's Locker Room Changing Booth	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Locker Room
1	61	Girl's Locker Room Changing Booth	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Locker Room
1	61	Girl's Locker Room Changing Booth	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Locker Room
1	61	Girl's Locker Room Changing Booth	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Locker Room
1	61	Girl's Locker Room Changing Booth	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Locker Room
1	61	Girl's Locker Room Changing Booth	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with Locker Room
1	58	Girl's Locker Room - Main Area	W1	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	58	Girl's Locker Room - Main Area	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	58	Girl's Locker Room - Main Area	W2	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	58	Girl's Locker Room - Main Area	W3	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	58	Girl's Locker Room - Main Area	Door Casing	Metal	Beige	None	0	0.5	Negative	None	0	Negative					
1	58	Girl's Locker Room - Main Area	Door Casing	Metal	Tan	None	0	0.6	Negative	None	0	Negative					
1	58	Girl's Locker Room - Main Area	Door Casing	Metal	Tan	None	0	0.5	Negative	None	0	Negative					
1	058B	Girl's Locker Room Shower Area	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	058B	Girl's Locker Room Shower Area	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	058B	Girl's Locker Room Shower Area	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	058B	Girl's Locker Room Shower Area	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	058B	Girl's Locker Room Shower Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	058B	Girl's Locker Room Shower Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	058C	Storage Closet inside Girl's Locker Room Main Area	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	058C	Storage Closet inside Girl's Locker Room Main Area	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	058C	Storage Closet inside Girl's Locker Room Main Area	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	058C	Storage Closet inside Girl's Locker Room Main Area	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	058C	Storage Closet inside Girl's Locker Room Main Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	058C	Storage Closet inside Girl's Locker Room Main Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	060B	Girl's Restroom next to Locker Room Main Area	W1	CMU	White	None	0	0.1	Negative	None	0	Positive					
1	060B	Girl's Restroom next to Locker Room Main Area	W2	CMU	White	None	0	0	Negative	None	0	Positive					
1	060B	Girl's Restroom next to Locker Room Main Area	W3	CMU	White	None	0	0	Negative	None	0	Positive					
1	060B	Girl's Restroom next to Locker Room Main Area	W4	CMU	White	None	0	0.2	Negative	None	0	Positive					
1	060B	Girl's Restroom next to Locker Room Main Area	Ceiling	Concrete	White	None	0	0	Negative	None	0	N/A					
1	060B	Girl's Restroom next to Locker Room Main Area	Door Casing	Metal	Blue	None	0	0.7	Positive	None	0	Negative					
1	060B	Girl's Restroom next to Locker Room Main Area	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
1	060C	Custodial Closet next to Girl's Locker Room Main Area	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	060C	Custodial Closet next to Girl's Locker Room Main Area	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	060C	Custodial Closet next to Girl's Locker Room Main Area	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	060C	Custodial Closet next to Girl's Locker Room Main Area	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	060C	Custodial Closet next to Girl's Locker Room Main Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	060C	Custodial Closet next to Girl's Locker Room Main Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	060PC	Pipe Chase in Custodial Closet next to Girl's Locker Room Main Area	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	060PC	Pipe Chase in Custodial Closet next to Girl's Locker Room Main Area	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	060PC	Pipe Chase in Custodial Closet next to Girl's Locker Room Main Area	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	060PC	Pipe Chase in Custodial Closet next to Girl's Locker Room Main Area	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	060PC	Pipe Chase in Custodial Closet next to Girl's Locker Room Main Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	060PC	Pipe Chase in Custodial Closet next to Girl's Locker Room Main Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
1	060A	Girl's Gym Teacher's Restroom Gym Office	W1	CMU	Yellow	None	0	0.1	Negative	None	0	Positive					
1	060A	Girl's Gym Teacher's Restroom Gym Office	W2	CMU	Yellow	None	0	0.1	Negative	None	0	Positive					
1	060A	Girl's Gym Teacher's Restroom Gym Office	W3	CMU	Yellow	None	0	0	Negative	None	0	Positive					
1	060A	Girl's Gym Teacher's Restroom Gym Office	W4	CMU	Yellow	None	0	0.4	Negative	None	0	Positive					
1	060A	Girl's Gym Teacher's Restroom Gym Office	Door Casing	Metal	Blue	None	0	0.5	Negative	None	0	Negative					
1	060A	Girl's Gym Teacher's Restroom Gym Office	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
1	60	Girl's Gym Teacher's Office	W1	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	60	Girl's Gym Teacher's Office	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	60	Girl's Gym Teacher's Office	W3	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	60	Girl's Gym Teacher's Office	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	60	Girl's Gym Teacher's Office	Door Casing	Metal	Beige	None	0	0.7	Positive	None	0	Negative					
1	60	Girl's Gym Teacher's Office	Door Casing	Metal	Beige	None	0	0.8	Positive	None	0	Negative					
1	60	Girl's Gym Teacher's Office	Door	Wood	Beige	None	0	0.1	Negative	None	0	Negative					
1	60	Girl's Gym Teacher's Office	Door Casing	Metal	Beige	None	0	0.6	Negative	None	0	Negative					
1	59	Girl's Gym Storage Room across from the Gym Teacher's Office	W1	CMU	Brown	Flaking	60	0.1	Negative	None	0	Positive		Yes	No	No	
1	59	Girl's Gym Storage Room across from the Gym Teacher's Office	W2	CMU	Brown	None	0	0	Negative	None	0	Positive					
1	59	Girl's Gym Storage Room across from the Gym Teacher's Office	W3	CMU	Brown	None	0	0.1	Negative	None	0	Positive					
1	59	Girl's Gym Storage Room across from the Gym Teacher's Office	W4	CMU	Brown	None	0	0.2	Negative	None	0	Positive					
1	59	Girl's Gym Storage Room across from the Gym Teacher's Office	Duct	Metal	Brown	None	0	0.1	Negative	None	0	Negative					
1	H015	Vestibule outside School Police Office	Stairs - Railing	Metal	Brown	None	0	0.3	Negative	None	0	Negative					
1	H015	Vestibule outside School Police Office	Stairs - Stringer	Metal	Brown	None	0	1.5	Positive	None	0	Negative					
1	H015	Vestibule outside School Police Office	Stairs - Riser	Metal	Brown	None	0	1.5	Positive	None	0	Negative					
1	8	School Police Office	W1	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	8	School Police Office	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	8	School Police Office	W3	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	8	School Police Office	W4	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	8	School Police Office	Soffit	Plaster	Beige	Efflorescence	31	0.1	Negative	Uni-vent	2	N/A	No	Temperature Control	yes	No	Efflorescence 26 SF/Plaster Crumbling 5 SF/Plaster Missing over Uni-vent 12 SF
1	008A	School Police Office Holding Cell	W1	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	008A	School Police Office Holding Cell	W2	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	008A	School Police Office Holding Cell	W3	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	008A	School Police Office Holding Cell	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	008A	School Police Office Holding Cell	Column	Concrete	Beige	None	0	0.1	Negative	None	0	Negative					
1	008A	School Police Office Holding Cell	Window Casing	Metal	Blue	None	0	0.2	Negative	None	0	Negative					
1	008A	School Police Office Holding Cell	Door Casing	Metal	Blue	None	0	0	Negative	None	0	Negative					
1	008A	School Police Office Holding Cell	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
1	9	Principal's Storage Room next to School Police Office	W1	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	9	Principal's Storage Room next to School Police Office	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	9	Principal's Storage Room next to School Police Office	W3	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	9	Principal's Storage Room next to School Police Office	W2	CMU	Blue	None	0	0	Negative	None	0	Positive					
1	9	Principal's Storage Room next to School Police Office	Door Casing	Metal	Blue	None	0	0.4	Negative	None	0	Negative					
1	9	Principal's Storage Room next to School Police Office	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
1	9	Principal's Storage Room next to School Police Office	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	9	Principal's Storage Room next to School Police Office	Door Casing	Metal	Blue	None	0	0	Negative	None	0	Negative					
1	9	Principal's Storage Room next to School Police Office	Window Casing	Metal	Blue	None	0	0	Negative	None	0	Negative					
1	H40A	Main Entrance Foyer	W1	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	H40A	Main Entrance Foyer	W3	CMU	Beige	None	0	0.2	Negative	None	0	Positive					
1	H40A	Main Entrance Foyer	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	H40A	Main Entrance Foyer	Door Casing	Metal	Blue	None	0	0.4	Negative	None	0	Negative					
1	H40A	Main Entrance Foyer	Door Center Post	Metal	Blue	None	0	0.3	Negative	None	0	Negative					
1	H40A	Main Entrance Foyer	Door	Metal	Blue	None	0	0.1	Negative	None	0	Negative					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	H40A	Main Entrance Foyer	Door	Metal	Beige	None	0	0	Negative	None	0	Negative					
1	H40A	Main Entrance Foyer	Door Casing	Metal	Beige	None	0	0.1	Negative	None	0	Negative					
1	009A	Storage Closet inside Principal's Storage Room next to School Police Office	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Inaccessible due to computer items stored
1	009A	Storage Closet inside Principal's Storage Room next to School Police Office	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Inaccessible due to computer items stored
1	009A	Storage Closet inside Principal's Storage Room next to School Police Office	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Inaccessible due to computer items stored
1	009A	Storage Closet inside Principal's Storage Room next to School Police Office	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Inaccessible due to computer items stored
1	009A	Storage Closet inside Principal's Storage Room next to School Police Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Inaccessible due to computer items stored
1	009A	Storage Closet inside Principal's Storage Room next to School Police Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Inaccessible due to computer items stored
1	H014	Hallway/Loading Dock outside Building Engineer's Office	W1	CMU	Blue	None	0	0.1	Negative	None	0	Positive					
1	H014	Hallway/Loading Dock outside Building Engineer's Office	W3	CMU	Blue	None	0	0.1	Negative	None	0	Positive					
1	H014	Hallway/Loading Dock outside Building Engineer's Office	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	H014	Hallway/Loading Dock outside Building Engineer's Office	Door Casing	Metal	Beige	None	0	0.4	Negative	None	0	Negative					
1	H014	Hallway/Loading Dock outside Building Engineer's Office	Door	Wood	Beige	None	0	0.1	Negative	None	0	Negative					
1	H014	Hallway/Loading Dock outside Building Engineer's Office	Column	Concrete	Beige	None	0	0.3	Negative	None	0	Negative					
1	H014	Hallway/Loading Dock outside Building Engineer's Office	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	H014	Hallway/Loading Dock outside Building Engineer's Office	W1	CMU	Brown	None	0	0.1	Negative	None	0	Positive					
1	H014	Hallway/Loading Dock outside Building Engineer's Office	W2	CMU	Brown	None	0	0	Negative	None	0	Positive					
1	H014	Hallway/Loading Dock outside Building Engineer's Office	W3	CMU	Brown	None	0	0.5	Negative	None	0	Positive					
1	H014	Hallway/Loading Dock outside Building Engineer's Office	W4	CMU	Brown	None	0	0	Negative	None	0	Positive					
1	H014	Hallway/Loading Dock outside Building Engineer's Office	Column	Concrete	Brown	None	0	0.3	Negative	None	0	Negative					
1	H014	Hallway/Loading Dock outside Building Engineer's Office	Pipe	Metal	Brown	None	0	0.8	Positive	None	0	Negative					
1	H014	Hallway/Loading Dock outside Building Engineer's Office	Door	Wood	Brown	None	0	0.1	Negative	None	0	Negative					
1	H014	Hallway/Loading Dock outside Building Engineer's Office	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
1	4	Men's Restroom next to Building Engineer's Office	W2	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	4	Men's Restroom next to Building Engineer's Office	W1	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	4	Men's Restroom next to Building Engineer's Office	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	4	Men's Restroom next to Building Engineer's Office	W3	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	4	Men's Restroom next to Building Engineer's Office	Door Casing	Metal	Blue	None	0	0.5	Negative	None	0	Negative					
1	4	Men's Restroom next to Building Engineer's Office	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
1	3	Building Engineer's Office	W1	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	3	Building Engineer's Office	W2	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	3	Building Engineer's Office	W3	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	3	Building Engineer's Office	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	3	Building Engineer's Office	Window Casing	Metal	Blue	None	0	0.1	Negative	None	0	Negative					
1	3	Building Engineer's Office	Door Casing	Metal	Blue	None	0	0.3	Negative	None	0	Negative					
1	3	Building Engineer's Office	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
1	3-PC	Pipe Chase in Building Engineer's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	3-PC	Pipe Chase in Building Engineer's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	3-PC	Pipe Chase in Building Engineer's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	3-PC	Pipe Chase in Building Engineer's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	3-PC	Pipe Chase in Building Engineer's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	3-PC	Pipe Chase in Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	5	Office next to Building Engineer's Office	W1	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	5	Office next to Building Engineer's Office	W2	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	5	Office next to Building Engineer's Office	W3	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	5	Office next to Building Engineer's Office	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	5	Office next to Building Engineer's Office	Door Casing	Metal	Beige	None	0	0.2	Negative	None	0	Negative					
1	5	Office next to Building Engineer's Office	Door	Wood	Beige	None	0	0.1	Negative	None	0	Negative					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	5-PC	Pipe Chase in Office next to Building Engineer's Office	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	5-PC	Pipe Chase in Office next to Building Engineer's Office	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	5-PC	Pipe Chase in Office next to Building Engineer's Office	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	5-PC	Pipe Chase in Office next to Building Engineer's Office	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	5-PC	Pipe Chase in Office next to Building Engineer's Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	5-PC	Pipe Chase in Office next to Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Not Painted
1	16	Women's Restroom next to Building Engineer's Office	W1	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	16	Women's Restroom next to Building Engineer's Office	W2	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	16	Women's Restroom next to Building Engineer's Office	W3	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	16	Women's Restroom next to Building Engineer's Office	W4	CMU	Beige	None	0	0	Negative	None	0	Positive					
1	16	Women's Restroom next to Building Engineer's Office	Door Casing	Metal	Blue	None	0	0.4	Negative	None	0	Negative					
1	16	Women's Restroom next to Building Engineer's Office	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
1	7	Storage Room next to Loading Dock Entrance	W1	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	7	Storage Room next to Loading Dock Entrance	W4	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	7	Storage Room next to Loading Dock Entrance	W3	CMU	Beige	None	0	0.1	Negative	None	0	Positive					
1	7	Storage Room next to Loading Dock Entrance	W2	CMU	Black	None	0	0.1	Negative	None	0	Positive					
1	S018	Stairwell next to Elevator	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with H01
1	S018	Stairwell next to Elevator	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with H01
1	S018	Stairwell next to Elevator	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with H01
1	S018	Stairwell next to Elevator	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with H01
1	S018	Stairwell next to Elevator	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with H01
1	S018	Stairwell next to Elevator	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					Included with H01
2	S113	Stairwell behind A Wing Classroom A106	W1	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	S113	Stairwell behind A Wing Classroom A106	W2	CMU	Beige	None	0	0	Negative	None	0	Negative					
2	S113	Stairwell behind A Wing Classroom A106	W4	CMU	Beige	None	0	0	Negative	None	0	Negative					
2	S113	Stairwell behind A Wing Classroom A106	Stairs - Railing	Metal	Brown	None	0	0	Negative	None	0	Negative					
2	S113	Stairwell behind A Wing Classroom A106	Stairs - Stringer	Metal	Brown	None	0	1.1	Positive	None	0	Negative					
2	S113	Stairwell behind A Wing Classroom A106	Stairs - Riser	Metal	Brown	None	0	0.9	Positive	None	0	Negative					
2	S113	Stairwell behind A Wing Classroom A106	Door Casing	Metal	Beige	None	0	0.7	Positive	None	0	Negative					
2	S113	Stairwell behind A Wing Classroom A106	Door	Metal	Beige	None	0	0	Negative	None	0	Negative					
2	106A	Classroom A106	W1	CMU	Blue	Flaking	15	0.1	Negative	None	0	Negative	No	No	No	No	Flaking
2	106A	Classroom A106	W2	CMU	Blue	None	0	0.1	Negative	None	0	Negative					
2	106A	Classroom A106	W3	CMU	Blue	None	0	0	Negative	None	0	Negative					
2	106A	Classroom A106	W4	Concrete	Blue	None	0	0.1	Negative	None	0	Negative					
2	106A	Classroom A106	Soffit	Plaster	Beige	None	0	0	Negative	None	0	N/A					
2	106A	Classroom A106	Door Casing	Metal	Blue	None	0	0.8	Positive	None	0	Negative					
2	106A	Classroom A106	Soffit	Plaster	Beige	None	0	0.3	Negative	None	0	N/A					
2	106A	Classroom A106	W1	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	105A	Classroom A105	W1	CMU	White	None	0	0.1	Negative	None	0	Negative					
2	105A	Classroom A105	W2	CMU	White	None	0	0	Negative	None	0	Negative					
2	105A	Classroom A105	W3	CMU	Yellow	None	0	0	Negative	None	0	Negative					
2	105A	Classroom A105	Soffit	Plaster	White	Efflorescence	2	0.3	Negative	Uni-vent	1	N/A	No	Temperature Control	No	No	Efflorescence from Univent
2	105A	Classroom A105	Column	Concrete	White	None	0	0.2	Negative	None	0	Negative					
2	105A	Classroom A105	Divider Wall Trac	Wood	White	None	0	0.2	Negative	None	0	Negative					
2	105A	Classroom A105	Divider Wall	Drywall	White	None	0	0.2	Negative	None	0	N/A					
2	105A	Classroom A105	Door Casing	Metal	Blue	None	0	0.3	Negative	None	0	Negative					
2	105A	Classroom A105	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
2	104A	Classroom A104	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
2	104A	Classroom A104	Door Casing	Metal	Blue	None	0	0.4	Negative	None	0	Negative					
2	104A	Classroom A104	Divider Wall Trac	Wood	White	None	0	0.1	Negative	None	0	Negative					
2	104A	Classroom A104	Divider Wall Trac	Wood	White	None	0	0	Negative	None	0	Negative					
2	104A	Classroom A104	Divider Wall	Drywall	White	None	0	0.1	Negative	None	0	N/A					
2	104A	Classroom A104	Divider Wall	Drywall	White	None	0	0.1	Negative	None	0	N/A					
2	104A	Classroom A104	W3	Concrete	Yellow	None	0	0	Negative	None	0	Negative					
2	104A	Classroom A104	Soffit	Plaster	White	Efflorescence	10	0.1	Negative	Uni-vent	2	N/A	No	Temperature Control	No	No	Efflorescence from Univent
2	103A	Classroom A103	W1	Concrete	White	None	0	0.1	Negative	None	0	Negative					
2	103A	Classroom A103	W4	Concrete	White	None	0	0	Negative	None	0	Negative					
2	103A	Classroom A103	W3	Concrete	Yellow	None	0	0.1	Negative	None	0	Negative					
2	103A	Classroom A103	Soffit	Plaster	White	None	0	0.2	Negative	None	0	N/A					
2	103A	Classroom A103	Divider Wall Trac	Wood	White	None	0	0	Negative	None	0	Negative					
2	103A	Classroom A103	Divider Wall	Drywall	White	None	0	0.1	Negative	None	0	N/A					
2	103A	Classroom A103	Door Casing	Metal	Blue	None	0	0.1	Negative	None	0	Negative					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	102A	Classroom A102	Door Casing	Metal	Blue	None	0	0.2	Negative	None	0	Negative					
2	102A	Classroom A102	W1	CMU	White	None	0	0.1	Negative	None	0	Negative					
2	102A	Classroom A102	W2	CMU	White	None	0	0.1	Negative	None	0	Negative					
2	102A	Classroom A102	W3	CMU	Yellow	None	0	0.1	Negative	None	0	Negative					
2	102A	Classroom A102	Soffit	Plaster	White	None	0	0.1	Negative	None	0	N/A					
2	102A	Classroom A102	Divider Wall Trac	Wood	White	None	0	0.1	Negative	None	0	Negative					
2	102A	Classroom A102	Divider Wall	Drywall	White	None	0	0	Negative	None	0	N/A					
2	101A	Classroom A101	W1	CMU	WHITE	None	0	0.02	Negative	None	0	Negative					
2	101A	Classroom A101	W4	CMU	WHITE	None	0	0.02	Negative	None	0	Negative					
2	101A	Classroom A101	W3	CMU	YELLOW	None	0	0.01	Negative	None	0	Negative					
2	101A	Classroom A101	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative	None	0	N/A					
2	101A	Classroom A101	DIVIDER WALL TR	WOOD	WHITE	None	0	0.01	Negative	None	0	Negative					
2	101A	Classroom A101	DIVIDER WALL	DRYWALL	WHITE	None	0	0.01	Negative	None	0	N/A					
2	101A	Classroom A101	DOOR CASING	METAL	BLUE	None	0	0	Negative	None	0	Negative					
2	101A	Classroom A101	Divider Wall	Drywall	White	None	0	0.1	Negative	None	0	N/A					
2	101A	Classroom A101	Divider Wall Trac	Wood	White	None	0	0.1	Negative	None	0	Negative					
2	101A	Classroom A101	W1	CMU	White	None	0	0.1	Negative	None	0	Negative					
2	101A	Classroom A101	W4	CMU	White	None	0	0.1	Negative	None	0	Negative					
2	101A	Classroom A101	W3	CMU	Yellow	None	0	0.1	Negative	None	0	Negative					
2	101A	Classroom A101	Soffit	Plaster	White	None	0	0.1	Negative	None	0	N/A					
2	116A	A Wing Boy's Restroom	W1	CMU	Beige	None	0	0	Negative	None	0	Negative					
2	116A	A Wing Boy's Restroom	W4	CMU	Beige	None	0	0	Negative	None	0	Negative					
2	116A	A Wing Boy's Restroom	W3	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	116A	A Wing Boy's Restroom	Door Casing	Metal	Blue	None	0	0.3	Negative	None	0	Negative					
2	116A	A Wing Boy's Restroom	Ceiling	Concrete	Beige	None	0	0.1	Negative	None	0	N/A					
2	117A	A Wing Men's Staff Restroom	Ceiling	Concrete	White	None	0	0.1	Negative	None	0	N/A					
2	117A	A Wing Men's Staff Restroom	Door Casing	Metal	Blue	None	0	0.4	Negative	None	0	Negative					
2	117A	A Wing Men's Staff Restroom	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
2	117A	A Wing Men's Staff Restroom	W1	CMU	White	None	0	0.1	Negative	None	0	Negative					
2	117A	A Wing Men's Staff Restroom	W4	CMU	White	None	0	0	Negative	None	0	Negative					
2	117A	A Wing Men's Staff Restroom	W3	CMU	White	None	0	0	Negative	None	0	Negative					
2	118A	A Wing Women's Staff Restroom	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
2	118A	A Wing Women's Staff Restroom	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
2	118A	A Wing Women's Staff Restroom	W1	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	118A	A Wing Women's Staff Restroom	W2	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	118A	A Wing Women's Staff Restroom	W3	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	118A	A Wing Women's Staff Restroom	CEILING	CONCRETE	WHITE	None	0	0	Negative	None	0	N/A					
2	118A	A Wing Women's Staff Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.03	Negative	None	0	N/A					
2	118A	A Wing Women's Staff Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.03	Negative	None	0	N/A					
2	118A	A Wing Women's Staff Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.08	Negative	None	0	N/A					
2	119A	A Wing Girl's Restroom	Door Casing	Metal	Blue	None	0	0.4	Negative	None	0	Negative					
2	119A	A Wing Girl's Restroom	W1	CMU	Pink	None	0	0	Negative	None	0	Negative					
2	119A	A Wing Girl's Restroom	W2	CMU	Pink	None	0	0.1	Negative	None	0	Negative					
2	119A	A Wing Girl's Restroom	W4	CMU	Pink	None	0	0.1	Negative	None	0	Negative					
2	119A	A Wing Girl's Restroom	Ceiling	Concrete	Beige	None	0	0	Negative	None	0	N/A					
2	H132	Hallway outside A Wing Classrooms A101 - A106	W1	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	H132	Hallway outside A Wing Classrooms A101 - A106	W2	CMU	Beige	None	0	0	Negative	None	0	Negative					
2	H132	Hallway outside A Wing Classrooms A101 - A106	W2	CMU	Green	None	0	0	Negative	None	0	Negative					
2	H132	Hallway outside A Wing Classrooms A101 - A106	W4	CMU	Beige	None	0	0	Negative	None	0	Negative					
2	H132	Hallway outside A Wing Classrooms A101 - A106	W3	CMU	Brown	None	0	0.1	Negative	None	0	Negative					
2	H132	Hallway outside A Wing Classrooms A101 - A106	W1	CMU	Green	None	0	0	Negative	None	0	Negative					
2	H132	Hallway outside A Wing Classrooms A101 - A106	Door Casing	Metal	Green	None	0	0.1	Negative	None	0	Negative					
2	H132	Hallway outside A Wing Classrooms A101 - A106	Door Casing	Metal	Beige	None	0	0.4	Negative	None	0	Negative					
2	H132	Hallway outside A Wing Classrooms A101 - A106	Door Casing	Metal	Beige	None	0	0.4	Negative	None	0	Negative					
2	H132	Hallway outside A Wing Classrooms A101 - A106	Door Casing	Metal	Beige	None	0	0.5	Negative	None	0	Negative					
2	H132	Hallway outside A Wing Classrooms A101 - A106	Door Casing	Metal	Brown	None	0	0.4	Negative	None	0	Negative					
2	H132	Hallway outside A Wing Classrooms A101 - A106	Soffit	Plaster	Brown	None	0	0	Negative	None	0	N/A					
2	H132	Hallway outside A Wing Classrooms A101 - A106	Soffit	Plaster	Beige	None	0	0	Negative	None	0	N/A					
2	H132	Hallway outside A Wing Classrooms A101 - A106	Soffit	Plaster	Beige	None	0	0	Negative	None	0	N/A					
2	H132C	Custodial Closet Hallway between Classrooms 106A & 105A	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H132C	Custodial Closet Hallway between Classrooms 106A & 105A	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	H132C	Custodial Closet Hallway between Classrooms 106A & 105A	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H132C	Custodial Closet Hallway between Classrooms 106A & 105A	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H132C	Custodial Closet Hallway between Classrooms 106A & 105A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H132C	Custodial Closet Hallway between Classrooms 106A & 105A	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	S117	Stairwell behind B Wing Classroom B106	W1	Brick	Beige	None	0	0.1	Negative	None	0	N/A					
2	S117	Stairwell behind B Wing Classroom B106	W2	Brick	Beige	None	0	0.1	Negative	None	0	N/A					
2	S117	Stairwell behind B Wing Classroom B106	W4	Brick	Beige	None	0	0.2	Negative	None	0	N/A					
2	S117	Stairwell behind B Wing Classroom B106	Stairs - Railing	Metal	Beige	None	0	0.2	Negative	None	0	Negative					
2	S117	Stairwell behind B Wing Classroom B106	Stairs - Riser	Metal	Beige	None	0	1	Positive	None	0	Negative					
2	S117	Stairwell behind B Wing Classroom B106	Stairs - Stringer	Metal	Beige	None	0	0.7	Positive	None	0	Negative					
2	S117	Stairwell behind B Wing Classroom B106	W2	Drywall	Beige	None	0	0	Negative	None	0	N/A					
2	106B	Classroom B106	Soffit	Plaster	White	None	0	0.1	Negative	None	0	N/A					
2	106B	Classroom B106	Soffit	Plaster	White	None	0	0	Negative	None	0	N/A					
2	106B	Classroom B106	Door Casing	Metal	Blue	None	0	0.7	Positive	None	0	Negative					
2	106B	Classroom B106	W1	CMU	White	None	0	0.1	Negative	None	0	Negative					
2	106B	Classroom B106	W2	CMU	White	None	0	0.1	Negative	None	0	Negative					
2	105B	Classroom B105	Divider Wall Trac	Wood	White	None	0	0.1	Negative	None	0	Negative					
2	105B	Classroom B105	Divider Wall	Drywall	White	None	0	0.1	Negative	None	0	N/A					
2	105B	Classroom B105	Door Casing	Metal	Blue	None	0	0.6	Negative	None	0	Negative					
2	105B	Classroom B105	W1	CMU	White	None	0	0.1	Negative	None	0	Negative					
2	105B	Classroom B105	W4	CMU	White	None	0	0	Negative	None	0	Negative					
2	105B	Classroom B105	W3	CMU	Orange	None	0	0.1	Negative	None	0	Negative					
2	105B	Classroom B105	Soffit	Plaster	White	None	0	0	Negative	None	0	N/A					
2	104B	Classroom B104	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
2	104B	Classroom B104	Door Casing	Metal	Blue	None	0	0.5	Negative	None	0	Negative					
2	104B	Classroom B104	W1	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	104B	Classroom B104	W2	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	104B	Classroom B104	W3	CMU	Beige	None	0	0	Negative	None	0	Negative					
2	104B	Classroom B104	Soffit	Plaster	White	None	0	0	Negative	None	0	N/A					
2	104B	Classroom B104	Divider Wall	Drywall	White	None	0	0.1	Negative	None	0	N/A					
2	104B	Classroom B104	Divider Wall Trac	Wood	White	None	0	0.1	Negative	None	0	Negative					
2	104B	Classroom B104	Divider Wall Trac	Wood	White	None	0	0.1	Negative	None	0	Negative					
2	103B	Classroom B103	Divider Wall Trac	Wood	White	None	0	0	Negative	None	0	Negative					
2	103B	Classroom B103	Divider Wall	Drywall	White	None	0	0.1	Negative	None	0	N/A					
2	103B	Classroom B103	W1	CMU	White	None	0	0.1	Negative	None	0	Negative					
2	103B	Classroom B103	W2	CMU	White	None	0	0.1	Negative	None	0	Negative					
2	103B	Classroom B103	W3	CMU	Orange	None	0	0.6	Negative	None	0	Negative					
2	103B	Classroom B103	Soffit	Plaster	White	None	0	0	Negative	None	0	N/A					
2	103B	Classroom B103	Door Casing	Metal	Blue	None	0	0.7	Positive	None	0	Negative					
2	103B	Classroom B103	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
2	102B	Classroom B102	Door Casing	Metal	Blue	None	0	0.4	Negative	None	0	Negative					
2	102B	Classroom B102	Door	Wood	Blue	None	0	0.1	Negative	None	0	Negative					
2	102B	Classroom B102	W1	CMU	White	None	0	0.2	Negative	None	0	Negative					
2	102B	Classroom B102	W4	CMU	White	None	0	0.1	Negative	None	0	Negative					
2	102B	Classroom B102	W3	CMU	Orange	None	0	0	Negative	None	0	Negative					
2	102B	Classroom B102	Soffit	Plaster	White	Efflorescence	3	0	Negative	None	0	N/A	No	Temperature Control	No	No	Efflorescence from Univent
2	102B	Classroom B102	Divider Wall	Drywall	White	None	0	0.1	Negative	None	0	N/A					
2	102B	Classroom B102	Divider Wall Trac	Wood	White	None	0	0.1	Negative	None	0	Negative					
2	101B	Classroom B101	W1	Concrete	Beige	None	0	0.1	Negative	None	0	Negative					
2	101B	Classroom B101	W2	Concrete	Beige	Flaking	3	0.1	Negative	None	0	Negative	No	Unknown	No	No	Efflorescence
2	101B	Classroom B101	W3	Concrete	Blue	None	0	0.1	Negative	None	0	Negative					
2	101B	Classroom B101	Soffit	Plaster	White	Efflorescence	1	0.1	Negative	None	0	N/A	No	Temperature Control	No	NO	Efflorescence from Univent
2	101B	Classroom B101	Divider Wall	Drywall	White	None	0	0.2	Negative	None	0	N/A					
2	101B	Classroom B101	Divider Wall Trac	Wood	White	None	0	0.1	Negative	None	0	Negative					
2	101B	Classroom B101	Door Casing	Metal	Blue	None	0	0.4	Negative	None	0	Negative					
2	116B	B Wing Boy's Restroom	Ceiling	CMU	Beige	None	0	0	Negative	None	0	N/A					
2	116B	B Wing Boy's Restroom	W1	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	116B	B Wing Boy's Restroom	W2	CMU	Beige	None	0	0	Negative	None	0	Negative					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	116B	B Wing Boy's Restroom	W3	CMU	Beige	None	0	0	Negative	None	0	Negative					
2	116B	B Wing Boy's Restroom	Floor	Tile	Gray	None	0	0.2	Negative	None	0	Negative					
2	116B	B Wing Boy's Restroom	Wall - Baseboard	Tile	Gray	None	0	0	Negative	None	0	N/A					
2	116B	B Wing Boy's Restroom	Wall - Baseboard	Tile	Gray	None	0	0	Negative	None	0	N/A					
2	116B	B Wing Boy's Restroom	Wall - Baseboard	Tile	Gray	None	0	0.4	Negative	None	0	N/A					
2	116B	B Wing Boy's Restroom	Wall - Baseboard	Tile	Gray	None	0	0	Negative	None	0	N/A					
2	116B	B Wing Boy's Restroom	Door Casing	Metal	Blue	None	0	0.6	Negative	None	0	Negative					
2	117B	B Wing Men's Staff Restroom	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
2	117B	B Wing Men's Staff Restroom	Door Casing	Metal	Blue	None	0	0.7	Positive	None	0	Negative					
2	117B	B Wing Men's Staff Restroom	Door Casing	Metal	Blue	None	0	0.5	Negative	None	0	Negative					
2	117B	B Wing Men's Staff Restroom	W1	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	117B	B Wing Men's Staff Restroom	W2	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	117B	B Wing Men's Staff Restroom	W3	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	117B	B Wing Men's Staff Restroom	Floor	Tile	Gray	None	0	0.2	Negative	None	0	N/A					
2	117B	B Wing Men's Staff Restroom	Wall - Baseboard	Tile	Gray	None	0	0.1	Negative	None	0	N/A					
2	117B	B Wing Men's Staff Restroom	Wall - Baseboard	Tile	Gray	None	0	0.1	Negative	None	0	N/A					
2	117B	B Wing Men's Staff Restroom	Wall - Baseboard	Tile	Gray	None	0	0	Negative	None	0	N/A					
2	117B	B Wing Men's Staff Restroom	Ceiling	Concrete	Beige	None	0	0.1	Negative	None	0	N/A					
2	118B	B Wing Women's Staff Restroom	Wall - Baseboard	Tile	Gray	None	0	0	Negative	None	0	N/A					
2	118B	B Wing Women's Staff Restroom	Wall - Baseboard	Tile	Gray	None	0	0.1	Negative	None	0	N/A					
2	118B	B Wing Women's Staff Restroom	Wall - Baseboard	Tile	Gray	None	0	0.1	Negative	None	0	N/A					
2	118B	B Wing Women's Staff Restroom	Floor	Tile	Gray	None	0	0.3	Negative	None	0	N/A					
2	118B	B Wing Women's Staff Restroom	W1	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	118B	B Wing Women's Staff Restroom	W2	CMU	Beige	None	0	0.2	Negative	None	0	Negative					
2	118B	B Wing Women's Staff Restroom	W3	CMU	Beige	None	0	0.6	Negative	None	0	Negative					
2	118B	B Wing Women's Staff Restroom	Ceiling	Concrete	Beige	None	0	0.1	Negative	None	0	N/A					
2	118B	B Wing Women's Staff Restroom	Door Casing	Metal	Blue	None	0	0.5	Negative	None	0	Negative					
2	118B	B Wing Women's Staff Restroom	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
2	119B	B Wing Girl's Restroom	Door Casing	Metal	Blue	None	0	0.5	Negative	None	0	Negative					
2	119B	B Wing Girl's Restroom	W2	CMU	Beige	None	0	0	Negative	None	0	Negative					
2	119B	B Wing Girl's Restroom	W1	CMU	Beige	None	0	0	Negative	None	0	Negative					
2	119B	B Wing Girl's Restroom	W3	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	119B	B Wing Girl's Restroom	W4	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	119B	B Wing Girl's Restroom	Ceiling	Concrete	Beige	None	0	0.1	Negative	None	0	N/A					
2	119B	B Wing Girl's Restroom	Floor	Tile	Gray	None	0	0.2	Negative	None	0	N/A					
2	119B	B Wing Girl's Restroom	Wall - Baseboard	Tile	Gray	None	0	0.1	Negative	None	0	N/A					
2	119B	B Wing Girl's Restroom	Wall - Baseboard	Tile	Gray	None	0	0.5	Negative	None	0	N/A					
2	119B	B Wing Girl's Restroom	Wall - Baseboard	Tile	Gray	None	0	0.1	Negative	None	0	N/A					
2	119B	B Wing Girl's Restroom	Wall - Baseboard	Tile	Gray	None	0	0.2	Negative	None	0	N/A					
2	H134	Hallway outside B Wing Classrooms B101 - B106	W1	CMU	Tan	None	0	0.1	Negative	None	0	Negative					
2	H134	Hallway outside B Wing Classrooms B101 - B106	W2	CMU	Tan	None	0	0.1	Negative	None	0	Negative					
2	H134	Hallway outside B Wing Classrooms B101 - B106	W3	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	H134	Hallway outside B Wing Classrooms B101 - B106	W4	CMU	Green	None	0	0.1	Negative	None	0	Negative					
2	H134	Hallway outside B Wing Classrooms B101 - B106	Door Casing	Metal	Beige	None	0	0.4	Negative	None	0	Negative					
2	H134	Hallway outside B Wing Classrooms B101 - B106	Door	Wood	Beige	None	0	0.1	Negative	None	0	Negative					
2	H134	Hallway outside B Wing Classrooms B101 - B106	Door	Metal	Beige	None	0	0	Negative	None	0	Negative					
2	H134	Hallway outside B Wing Classrooms B101 - B106	Door Casing	Metal	Beige	None	0	0.5	Negative	None	0	Negative					
2	H134	Hallway outside B Wing Classrooms B101 - B106	Soffit	Plaster	Beige	None	0	0.1	Negative	None	0	N/A					
2	H134	Hallway outside B Wing Classrooms B101 - B106	Soffit	Plaster	Beige	None	0	0	Negative	None	0	N/A					
2	H134	Hallway outside B Wing Classrooms B101 - B106	W3	CMU	Green	None	0	0	Negative	None	0	Negative					
2	H134	Hallway outside B Wing Classrooms B101 - B106	Soffit	Plaster	Beige	None	0	0.1	Negative	None	0	N/A					
2	H134	Hallway outside B Wing Classrooms B101 - B106	W4	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	H134	Hallway outside B Wing Classrooms B101 - B106	Door Casing	Metal	Beige	None	0	0.4	Negative	None	0	Negative					
2	H134	Hallway outside B Wing Classrooms B101 - B106	Door	Metal	Blue	None	0	0	Negative	None	0	Negative					
2	H134C	Custodial closet in hallway between 106B & 105B	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H134C	Custodial closet in hallway between 106B & 105B	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H134C	Custodial closet in hallway between 106B & 105B	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H134C	Custodial closet in hallway between 106B & 105B	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H134C	Custodial closet in hallway between 106B & 105B	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H134C	Custodial closet in hallway between 106B & 105B	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H135	Music Classrooms Hallway	W1	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	H135	Music Classrooms Hallway	W3	CMU	Beige	None	0	0	Negative	None	0	Negative					
2	H135	Music Classrooms Hallway	W4	CMU	Beige	None	0	0.1	Negative	None	0	Negative					

		School District of Philadelphia																
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21								
		E.W. Rhodes ES School								ULCS# 4150								
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
2	H135	Music Classrooms Hallway	Door	Wood	Beige	None	0	0.1	Negative	None	0	Negative						
2	H135	Music Classrooms Hallway	Door Casing	Metal	Beige	None	0	0.1	Negative	None	0	Negative						
2	H135	Music Classrooms Hallway	Soffit	Plaster	Beige	None	0	0.1	Negative	None	0	N/A						
2	107A	Large Library Reading Area in A Wing	W1	CMU	GREEN	None	0	0.03	Negative	None	0	Negative						
2	107A	Large Library Reading Area in A Wing	W4	CMU	GREEN	None	0	0.01	Negative	None	0	Negative						
2	107A	Large Library Reading Area in A Wing	W3	CMU	GREEN	None	0	0.02	Negative	None	0	Negative						
2	107A	Large Library Reading Area in A Wing	W2	CMU	GREEN	None	0	0.01	Negative	None	0	Negative						
2	107A	Large Library Reading Area in A Wing	W2	CMU	LIGHT GREEN	None	0	0.02	Negative	None	0	Negative						
2	107A	Large Library Reading Area in A Wing	W1	CMU	LIGHT GREEN	Efflorescence	5	0.01	Negative	None	0	Negative	No	Window	No	NO		Efflorescence from Window
2	107A	Large Library Reading Area in A Wing	W3	CMU	LIGHT GREEN	None	0	0.03	Negative	None	0	Negative						
2	107A	Large Library Reading Area in A Wing	W2	CMU	LIGHT GREEN	None	0	0.01	Negative	None	0	Negative						
2	107A	Large Library Reading Area in A Wing	COLUMN	CONCRETE	WHITE	Flaking	10	0	Negative	None	0	Negative	No	No	NO	NO		Flaking
2	107A	Large Library Reading Area in A Wing	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative	None	0	N/A						
2	107A	Large Library Reading Area in A Wing	DOOR CASING	METAL	BLUE	None	0	0.26	Negative	None	0	Negative						
2	107A	Large Library Reading Area in A Wing	DOOR CASING	METAL	BLUE	None	0	0.6	Negative	None	0	Negative						
2	107A	Large Library Reading Area in A Wing	DOOR	WOOD	BLUE	None	0	0	Negative	None	0	Negative						
2	107A	Large Library Reading Area in A Wing	DOOR	WOOD	BLUE	None	0	0	Negative	None	0	Negative						
2	S114	A Wing Large Library Reading Area Stairwell	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with A Wing Cafeteria
2	S114	A Wing Large Library Reading Area Stairwell	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with A Wing Cafeteria
2	S114	A Wing Large Library Reading Area Stairwell	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with A Wing Cafeteria
2	S114	A Wing Large Library Reading Area Stairwell	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with A Wing Cafeteria
2	S114	A Wing Large Library Reading Area Stairwell	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with A Wing Cafeteria
2	S114	A Wing Large Library Reading Area Stairwell	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with A Wing Cafeteria
2	S115	Stairwell between A and B Wings	W2	Concrete	Yellow	None	0	0.2	Negative	None	0	Negative						
2	S115	Stairwell between A and B Wings	W3	Concrete	Beige	None	0	0.1	Negative	None	0	Negative						
2	S115	Stairwell between A and B Wings	W4	Concrete	Beige	None	0	0.1	Negative	None	0	Negative						
2	S115	Stairwell between A and B Wings	Door	Metal	Blue	None	0	0.1	Negative	None	0	Negative						
2	S115	Stairwell between A and B Wings	Door Casing	Metal	Beige	None	0	0.4	Negative	None	0	Negative						
2	S115	Stairwell between A and B Wings	Stairs - Railing	Metal	Brown	None	0	0.1	Negative	None	0	Negative						
2	S115	Stairwell between A and B Wings	Stairs - Riser	Metal	Brown	None	0	1.9	Positive	None	0	Negative						
2	S115	Stairwell between A and B Wings	Stairs - Stringer	Metal	Brown	None	0	1.2	Positive	None	0	Negative						
2	112A	Lounge between A Wing Large Library Reading Area and A Wing Hallway	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	112A	Lounge between A Wing Large Library Reading Area and A Wing Hallway	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	112A	Lounge between A Wing Large Library Reading Area and A Wing Hallway	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	112A	Lounge between A Wing Large Library Reading Area and A Wing Hallway	W2	CMU	YELLOW	None	0	0.01	Negative	None	0	Negative						
2	112A	Lounge between A Wing Large Library Reading Area and A Wing Hallway	W1	CMU	YELLOW	None	0	0.02	Negative	None	0	Negative						
2	112A	Lounge between A Wing Large Library Reading Area and A Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.3	Negative	None	0	Negative						
2	112A	Lounge between A Wing Large Library Reading Area and A Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.3	Negative	None	0	Negative						
2	112A	Lounge between A Wing Large Library Reading Area and A Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.23	Negative	None	0	Negative						
2	112A	Lounge between A Wing Large Library Reading Area and A Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.4	Negative	None	0	Negative						
2	112A	Lounge between A Wing Large Library Reading Area and A Wing Hallway	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative						
2	112A	Lounge between A Wing Large Library Reading Area and A Wing Hallway	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative						
2	112A	Lounge between A Wing Large Library Reading Area and A Wing Hallway	DOOR	WOOD	BLUE	None	0	0.02	Negative	None	0	Negative						
2	113A	Office behind A Wing Stairwell	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative						
2	113A	Office behind A Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.22	Negative	None	0	Negative						
2	113A	Office behind A Wing Stairwell	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	113A	Office behind A Wing Stairwell	W2	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	113A	Office behind A Wing Stairwell	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	113A	Office behind A Wing Stairwell	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	115A	Office between 121A and A Wing Faculty Lounge	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative						
2	115A	Office between 121A and A Wing Faculty Lounge	DOOR CENTER PANEL	METAL	BLUE	None	0	0.25	Negative	None	0	Negative						
2	115A	Office between 121A and A Wing Faculty Lounge	DOOR CASING	METAL	BLUE	None	0	0.28	Negative	None	0	Negative						
2	115A	Office between 121A and A Wing Faculty Lounge	DOOR	WOOD	BLUE	None	0	0.02	Negative	None	0	Negative						
2	115A	Office between 121A and A Wing Faculty Lounge	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	115A	Office between 121A and A Wing Faculty Lounge	W4	CMU	BEIGE	None	0	0.03	Negative	None	0	Negative					
2	115A	Office between 121A and A Wing Faculty Lounge	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	115A	Office between 121A and A Wing Faculty Lounge	W2	CMU	BEIGE	None	0	0.03	Negative	None	0	Negative					
2	121A	Office next to A Wing Stairwell	W2	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	121A	Office next to A Wing Stairwell	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	121A	Office next to A Wing Stairwell	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	121A	Office next to A Wing Stairwell	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	121A	Office next to A Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.4	Negative	None	0	Negative					
2	121A	Office next to A Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.26	Negative	None	0	Negative					
2	114A	Office across from Classroom A103	W4	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	114A	Office across from Classroom A103	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	114A	Office across from Classroom A103	W2	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	114A	Office across from Classroom A103	W1	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	114A	Office across from Classroom A103	DOOR CASING	METAL	BLUE	None	0	0.5	Negative	None	0	Negative					
2	114A	Office across from Classroom A103	DOOR CASING	METAL	BLUE	None	0	0.25	Negative	None	0	Negative					
2	114A	Office across from Classroom A103	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
2	114A	Office across from Classroom A103	DOOR	WOOD	BLUE	None	0	0.02	Negative	None	0	Negative					
2	108A	A Wing Large Storage Room	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	108A	A Wing Large Storage Room	W2	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	108A	A Wing Large Storage Room	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	108A	A Wing Large Storage Room	W4	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	108A	A Wing Large Storage Room	WINDOW CASING	METAL	BROWN	None	0	0.4	Negative	None	0	Negative					
2	108A	A Wing Large Storage Room	WINDOW CASING	METAL	BROWN	None	0	0.23	Negative	None	0	Negative					
2	108A	A Wing Large Storage Room	WINDOW CASING	METAL	BROWN	None	0	0.25	Negative	None	0	Negative					
2	108A	A Wing Large Storage Room	DOOR CASING	METAL	BROWN	None	0	0.4	Negative	None	0	Negative					
2	108A	A Wing Large Storage Room	DOOR	WOOD	BROWN	None	0	0.01	Negative	None	0	Negative					
2	108A	A Wing Large Storage Room	DOOR	WOOD	BROWN	None	0	0.01	Negative	None	0	Negative					
2	108A	A Wing Large Storage Room	DOOR CASING	METAL	BROWN	None	0	0.25	Negative	None	0	Negative					
2	108A	A Wing Large Storage Room	COLUMN	CONCRETE	BEIGE	None	0	0.04	Negative	None	0	Negative					
2	109A	A Wing Small Storage Room	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	109A	A Wing Small Storage Room	W2	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	109A	A Wing Small Storage Room	W3	CMU	BEIGE	None	0	0.03	Negative	None	0	Negative					
2	109A	A Wing Small Storage Room	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	109A	A Wing Small Storage Room	DOOR CASING	METAL	BLUE	None	0	0.18	Negative	None	0	Negative					
2	109A	A Wing Small Storage Room	DOOR	WOOD	BLUE	None	0	0.1	Negative	None	0	Negative					
2	110A	Small Office inside A Wing Large Library Reading Area	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
2	110A	Small Office inside A Wing Large Library Reading Area	DOOR CASING	METAL	BLUE	None	0	0.4	Negative	None	0	Negative					
2	110A	Small Office inside A Wing Large Library Reading Area	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	110A	Small Office inside A Wing Large Library Reading Area	W2	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	110A	Small Office inside A Wing Large Library Reading Area	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	110A	Small Office inside A Wing Large Library Reading Area	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	111A	A Wing Storage Room next to HVAC/Mechanical Room 1	W4	CMU	BEIGE	None	0	0.03	Negative	None	0	Negative					
2	111A	A Wing Storage Room next to HVAC/Mechanical Room 1	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	111A	A Wing Storage Room next to HVAC/Mechanical Room 1	W2	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	111A	A Wing Storage Room next to HVAC/Mechanical Room 1	W3	CMU	BEIGE	None	0	0.11	Negative	None	0	Negative					
2	111A	A Wing Storage Room next to HVAC/Mechanical Room 1	DOOR CASING	METAL	BLUE	None	0	0.25	Negative	None	0	Negative					
2	111A	A Wing Storage Room next to HVAC/Mechanical Room 1	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
2	120A	HVAC/Mechanical Room 1 between A and B Wings	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	120A	HVAC/Mechanical Room 1 between A and B Wings	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	120A	HVAC/Mechanical Room 1 between A and B Wings	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	120A	HVAC/Mechanical Room 1 between A and B Wings	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	120A	HVAC/Mechanical Room 1 between A and B Wings	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	120A	HVAC/Mechanical Room 1 between A and B Wings	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	107B	Large Library Reading Area in B Wing	W1	CMU	BLUE	None	0	0.01	Negative	None	0	Negative					
2	107B	Large Library Reading Area in B Wing	W1	CMU	LIGHT BLUE	None	0	0.02	Negative	None	0	Negative					
2	107B	Large Library Reading Area in B Wing	W2	CMU	LIGHT BLUE	None	0	0.02	Negative	None	0	Negative					
2	107B	Large Library Reading Area in B Wing	W4	CMU	LIGHT BLUE	None	0	0.01	Negative	None	0	Negative					
2	107B	Large Library Reading Area in B Wing	W3	CMU	LIGHT BLUE	None	0	0.01	Negative	None	0	Negative					
2	107B	Large Library Reading Area in B Wing	W3	CMU	BLUE	None	0	0.01	Negative	None	0	Negative					

		School District of Philadelphia																	
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21									
		E.W. Rhodes ES School								ULCS# 4150									
F l o o r	Space #	Name of Inspector: Kristen Masotes	Inspection Company: Acer Associates	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
		Name of Inspector: Kristen Masotes	Inspection Company: Acer Associates	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	107B	Large Library Reading Area in B Wing	W4	CMU	BLUE	None	None	0	0.03	Negative	None	0	Negative						
2	107B	Large Library Reading Area in B Wing	W2	CMU	BLUE	None	None	0	0	Negative	None	0	Negative						
2	107B	Large Library Reading Area in B Wing	COLUMN	CONCRETE	BLUE	None	None	0	0	Negative	None	0	Negative						
2	107B	Large Library Reading Area in B Wing	W2	DRYWALL	WHITE	None	None	0	0	Negative	None	0	N/A						
2	107B	Large Library Reading Area in B Wing	SOFFIT	PLASTER	WHITE	None	None	0	0	Negative	None	0	N/A						
2	107B	Large Library Reading Area in B Wing	DOOR CASING	METAL	BEIGE	None	None	0	0.21	Negative	None	0	Negative						
2	107B	Large Library Reading Area in B Wing	DOOR	WOOD	BEIGE	None	None	0	0	Negative	None	0	Negative						
2	107B	Large Library Reading Area in B Wing	DOOR CENTER P	WOOD	BEIGE	None	None	0	0	Negative	None	0	Negative						
2	107B	Large Library Reading Area in B Wing	DOOR CASING	METAL	BLUE	None	None	0	0.26	Negative	None	0	Negative						
2	107B	Large Library Reading Area in B Wing	DOOR	WOOD	BLUE	None	None	0	0	Negative	None	0	Negative						
2	107B	Large Library Reading Area in B Wing	DOOR	WOOD	BLACK	None	None	0	0.01	Negative	None	0	Negative						
2	107B	Large Library Reading Area in B Wing	DOOR CASING	METAL	BLACK	None	None	0	0.3	Negative	None	0	Negative						
2	S116	B Wing Large Library Reading Area Stairwell	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included wih Cafeteria
2	S116	B Wing Large Library Reading Area Stairwell	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included wih Cafeteria
2	S116	B Wing Large Library Reading Area Stairwell	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included wih Cafeteria
2	S116	B Wing Large Library Reading Area Stairwell	W4	N/A	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included wih Cafeteria
2	S116	B Wing Large Library Reading Area Stairwell	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included wih Cafeteria
2	S116	B Wing Large Library Reading Area Stairwell	Floor	N/A	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included wih Cafeteria
2	112B	Lounge between B Wing Large Library Reading Area and B Wing Hallway	DOOR CASING	METAL	BLACK	None	None	0	0.24	Negative	None	0	Negative	#REF!	#REF!	#REF!	#REF!		
2	112B	Lounge between B Wing Large Library Reading Area and B Wing Hallway	DOOR	WOOD	BLACK	None	None	0	0	Negative	None	0	Negative	#REF!	#REF!	#REF!	#REF!		
2	112B	Lounge between B Wing Large Library Reading Area and B Wing Hallway	W2	CMU	BEIGE	None	None	0	0.03	Negative	None	0	Negative	#REF!	#REF!	#REF!	#REF!		
2	112B	Lounge between B Wing Large Library Reading Area and B Wing Hallway	W3	CMU	BEIGE	None	None	0	0.01	Negative	None	0	Negative	#REF!	#REF!	#REF!	#REF!		
2	112B	Lounge between B Wing Large Library Reading Area and B Wing Hallway	W4	CMU	BEIGE	None	None	0	0.02	Negative	None	0	Negative	#REF!	#REF!	#REF!	#REF!		
2	112B	Lounge between B Wing Large Library Reading Area and B Wing Hallway	W3	CMU	GREEN	None	None	0	0.02	Negative	None	0	Negative	#REF!	#REF!	#REF!	#REF!		
2	112B	Lounge between B Wing Large Library Reading Area and B Wing Hallway	W2	CMU	GREEN	None	None	0	0.01	Negative	None	0	Negative						
2	112B	Lounge between B Wing Large Library Reading Area and B Wing Hallway	W1	CMU	GREEN	None	None	0	0.01	Negative	None	0	Negative						
2	113B	Office behind B Wing Stairwell	DOOR	WOOD	BLACK	None	None	0	0.05	Negative	None	0	Negative						
2	113B	Office behind B Wing Stairwell	DOOR CASING	METAL	BLACK	None	None	0	0.4	Negative	None	0	Negative						
2	113B	Office behind B Wing Stairwell	DOOR CASING	METAL	BLACK	None	None	0	0.3	Negative	None	0	Negative						
2	113B	Office behind B Wing Stairwell	DOOR	WOOD	BLACK	None	None	0	0.01	Negative	None	0	Negative						
2	113B	Office behind B Wing Stairwell	W1	CMU	BEIGE	None	None	0	0.02	Negative	None	0	Negative						
2	113B	Office behind B Wing Stairwell	W2	CMU	BEIGE	None	None	0	0.07	Negative	None	0	Negative						
2	113B	Office behind B Wing Stairwell	W4	CMU	BEIGE	None	None	0	0.02	Negative	None	0	Negative						
2	113B	Office behind B Wing Stairwell	W3	CMU	BEIGE	Flaking	Flaking	2	0.03	Negative	None	0	Negative	No	No	NO	No		Flaking
2	113B	Office behind B Wing Stairwell	COLUMN	CONCRETE	BEIGE	None	None	0	0	Negative	None	0	Negative						
2	115B	Office between 121B and B Wing Faculty Lounge	W4	CMU	BEIGE	None	None	0	0.02	Negative	None	0	Negative						
2	115B	Office between 121B and B Wing Faculty Lounge	W3	CMU	BEIGE	None	None	0	0.01	Negative	None	0	Negative						
2	115B	Office between 121B and B Wing Faculty Lounge	W1	CMU	BEIGE	None	None	0	0.02	Negative	None	0	Negative						
2	115B	Office between 121B and B Wing Faculty Lounge	W2	CMU	BEIGE	None	None	0	0.02	Negative	None	0	Negative						
2	115B	Office between 121B and B Wing Faculty Lounge	DOOR CASING	METAL	BLACK	None	None	0	0.16	Negative	None	0	Negative						
2	115B	Office between 121B and B Wing Faculty Lounge	DOOR	WOOD	BLACK	None	None	0	0.01	Negative	None	0	Negative						
2	121B	Office next to B Wing Stairwell	DOOR	WOOD	BLUE	None	None	0	0.01	Negative	None	0	Negative						
2	121B	Office next to B Wing Stairwell	DOOR CASING	METAL	BLUE	None	None	0	0.21	Negative	None	0	Negative						
2	121B	Office next to B Wing Stairwell	DOOR CASING	METAL	BLUE	None	None	0	0.5	Negative	None	0	Negative						
2	121B	Office next to B Wing Stairwell	DOOR	WOOD	BLUE	None	None	0	0.01	Negative	None	0	Negative						
2	121B	Office next to B Wing Stairwell	W1	CMU	BEIGE	None	None	0	0.01	Negative	None	0	Negative						
2	121B	Office next to B Wing Stairwell	W2	CMU	BEIGE	Flaking	Flaking	5	0.01	Negative	None	0	Negative	No	No	No	No		Flaking
2	121B	Office next to B Wing Stairwell	W3	CMU	BEIGE	None	None	0	0.02	Negative	None	0	Negative						
2	121B	Office next to B Wing Stairwell	W4	CMU	BEIGE	None	None	0	0.01	Negative	None	0	Negative						
2	114B	Office across from Classroom B103	W1	CMU	BEIGE	None	None	0	0.02	Negative	None	0	Negative						
2	114B	Office across from Classroom B103	W2	CMU	BEIGE	None	None	0	0.06	Negative	None	0	Negative						
2	114B	Office across from Classroom B103	W3	CMU	BEIGE	None	None	0	0.02	Negative	None	0	Negative						
2	114B	Office across from Classroom B103	W4	CMU	BEIGE	None	None	0	0.01	Negative	None	0	Negative						
2	114B	Office across from Classroom B103	DOOR CASING	METAL	BLACK	None	None	0	0.3	Negative	None	0	Negative						
2	114B	Office across from Classroom B103	DOOR CASING	METAL	BLUE	None	None	0	0.28	Negative	None	0	Negative						
2	114B	Office across from Classroom B103	DOOR	WOOD	BLUE	None	None	0	0.01	Negative	None	0	Negative						
2	114B	Office across from Classroom B103	DOOR	WOOD	BLACK	None	None	0	0.01	Negative	None	0	Negative						

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
		Name of Inspector: Kristen Masotes	Inspection Company: Acer Associates														
2	108B	B Wing Small Storage Room	DOOR CASING	METAL	BLUE	None	0	0.3	Negative	None	0	Negative					
2	108B	B Wing Small Storage Room	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	108B	B Wing Small Storage Room	W2	CMU	BEIGE	Flaking	3	0.02	Negative	None	0	Negative	No	No	No	No	Flaking
2	108B	B Wing Small Storage Room	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	108B	B Wing Small Storage Room	W4	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	108B	B Wing Small Storage Room	COLUMN	CONCRETE	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	109B	Small Office inside B Wing Large Library Reading Area	W2	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	109B	Small Office inside B Wing Large Library Reading Area	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	109B	Small Office inside B Wing Large Library Reading Area	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	109B	Small Office inside B Wing Large Library Reading Area	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	109B	Small Office inside B Wing Large Library Reading Area	DOOR CASING	METAL	BLUE	None	0	0.26	Negative	None	0	Negative					
2	109B	Small Office inside B Wing Large Library Reading Area	DOOR CASING	METAL	BLUE	None	0	0.3	Negative	None	0	Negative					
2	109B	Small Office inside B Wing Large Library Reading Area	Door	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
2	109B	Small Office inside B Wing Large Library Reading Area	DOOR CASING	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
2	110B	B Wing Storage Room next to HVAC/Mechanical Room 1	DOOR CASING	METAL	BLACK	None	0	0.01	Negative	None	0	Negative					
2	110B	B Wing Storage Room next to HVAC/Mechanical Room 1	DOOR	WOOD	BLACK	None	0	0.01	Negative	None	0	Negative					
2	110B	B Wing Storage Room next to HVAC/Mechanical Room 1	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	110B	B Wing Storage Room next to HVAC/Mechanical Room 1	W4	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	110B	B Wing Storage Room next to HVAC/Mechanical Room 1	W3	CMU	BEIGE	None	0	0.03	Negative	None	0	Negative					
2	110B	B Wing Storage Room next to HVAC/Mechanical Room 1	W2	CMU	BEIGE	None	0	0.04	Negative	None	0	Negative					
2	S17	Stairwell behind D Wing Classroom D106	W1	BRICK	BEIGE	None	0	0.01	Negative	None	0	N/A					
2	S17	Stairwell behind D Wing Classroom D106	W2	BRICK	BEIGE	None	0	0.01	Negative	None	0	N/A					
2	S17	Stairwell behind D Wing Classroom D106	W4	BRICK	BEIGE	None	0	0.01	Negative	None	0	N/A					
2	S17	Stairwell behind D Wing Classroom D106	W3	BRICK	BEIGE	None	0	0.03	Negative	None	0	N/A					
2	S17	Stairwell behind D Wing Classroom D106	W3	DRYWALL	BEIGE	None	0	0	Negative	None	0	N/A					
2	S17	Stairwell behind D Wing Classroom D106	STAIRS RISER	METAL	BEIGE	None	0	0.6	Negative	None	0	Negative					
2	S17	Stairwell behind D Wing Classroom D106	STAIRS STRINGER	METAL	BEIGE	None	0	1.2	Positive	None	0	Negative					
2	S17	Stairwell behind D Wing Classroom D106	STAIRS RAILING	METAL	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	S17	Stairwell behind D Wing Classroom D106	STAIRS HALF WALL	WOOD	BEIGE	None	0	0	Negative	None	0	Negative					
2	S17	Stairwell behind D Wing Classroom D106	W3	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	S17	Stairwell behind D Wing Classroom D106	DOOR CASING	METAL	BEIGE	None	0	0	Negative	None	0	Negative					
2	S17	Stairwell behind D Wing Classroom D106	DOOR	METAL	BEIGE	None	0	0	Negative	None	0	Negative					
2	S17	Stairwell behind D Wing Classroom D106	DOOR CENTER PANEL	METAL	BEIGE	None	0	0	Negative	None	0	Negative					
2	S17	Stairwell behind D Wing Classroom D106	UNIVENT	METAL	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	S17	Stairwell behind D Wing Classroom D106	CEILING	CONCRETE	BEIGE	None	0	0.04	Negative	None	0	Negative					
2	106D	Classroom D106	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
2	106D	Classroom D106	DOOR CASING	WOOD	BLUE	None	0	0	Negative	None	0	Negative					
2	106D	Classroom D106	W1	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	106D	Classroom D106	W2	CMU	WHITE	None	0	0.02	Negative	None	0	Negative					
2	106D	Classroom D106	W4	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	106D	Classroom D106	W3	CMU	WHITE	None	0	0.02	Negative	None	0	Negative					
2	106D	Classroom D106	WALL	CMU	PURPLE	None	0	0.01	Negative	None	0	Negative					
2	106D	Classroom D106	CEILING	PLASTER	WHITE	None	0	0.01	Negative	None	0	N/A					
2	105D	Classroom D105	W1	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	105D	Classroom D105	W4	CMU	WHITE	None	0	0.02	Negative	None	0	Negative					
2	105D	Classroom D105	W3	CMU	PURPLE	None	0	0.01	Negative	None	0	Negative					
2	105D	Classroom D105	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative	None	0	N/A					
2	105D	Classroom D105	DIVIDER WALL TOP	WOOD	WHITE	None	0	0	Negative	None	0	Negative					
2	105D	Classroom D105	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative	None	0	N/A					
2	104D	Classroom D104	DIVIDER WALL	DRYWALL	WHITE	None	0	0	Negative	None	0	N/A					
2	104D	Classroom D104	DIVIDER WALL TOP	WOOD	WHITE	None	0	0	Negative	None	0	Negative					
2	104D	Classroom D104	W1	CMU	WHITE	None	0	0	Negative	None	0	Negative					
2	104D	Classroom D104	DIVIDER WALL TOP	WOOD	WHITE	None	0	0.03	Negative	None	0	Negative					
2	104D	Classroom D104	DIVIDER WALL	PLASTER	WHITE	None	0	0.01	Negative	None	0	N/A					
2	104D	Classroom D104	W2	CMU	WHITE	None	0	0.02	Negative	None	0	Negative					
2	104D	Classroom D104	W3	CMU	PURPLE	None	0	0.01	Negative	None	0	Negative					
2	104D	Classroom D104	COLUMN	CONCRETE	WHITE	None	0	0.01	Negative	None	0	Negative					
2	104D	Classroom D104	SOFFIT	PLASTER	WHITE	Efflorescence	2	0.01	Negative	None	0	N/A	No	Temperature Control	No	No	Efflorescence from Univent

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	103D	Classroom D103	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative	None	0	N/A					
2	103D	Classroom D103	W3	CMU	PURPLE	None	0	0.02	Negative	None	0	Negative					
2	103D	Classroom D103	W2	CMU	WHITE	None	0	0	Negative	None	0	Negative					
2	103D	Classroom D103	W1	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	103D	Classroom D103	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
2	103D	Classroom D103	DIVIDER WALL TH	WOOD	WHITE	None	0	0.02	Negative	None	0	Negative					
2	103D	Classroom D103	DIVIDER WALL	WOOD	WHITE	None	0	0.01	Negative	None	0	Negative					
2	102D	Classroom D102	DIVIDER WALL	WOOD	WHITE	None	0	0.02	Negative	None	0	Negative					
2	102D	Classroom D102	DIVIDER WALL TH	WOOD	WHITE	None	0	0.02	Negative	None	0	Negative					
2	102D	Classroom D102	W1	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	102D	Classroom D102	W4	CMU	WHITE	None	0	0.02	Negative	None	0	Negative					
2	102D	Classroom D102	W3	CMU	PURPLE	None	0	0.01	Negative	None	0	Negative					
2	102D	Classroom D102	SOFFIT	PLASTER	WHITE	None	0	0	Negative	None	0	N/A					
2	101D	Classroom D101	SOFFIT	PLASTER	WHITE	None	0	0.04	Negative	None	0	N/A					
2	101D	Classroom D101	W1	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	101D	Classroom D101	W2	CMU	WHITE	None	0	0.02	Negative	None	0	Negative					
2	101D	Classroom D101	W3	CMU	PURPLE	None	0	0	Negative	None	0	Negative					
2	101D	Classroom D101	DIVIDER WALL TH	WOOD	WHITE	None	0	0.01	Negative	None	0	Negative					
2	101D	Classroom D101	DIVIDER WALL	PLASTER	WHITE	None	0	0.02	Negative	None	0	N/A					
2	116D	D Wing Boy's Restroom	DOOR CASING	METAL	BLACK	None	0	0.03	Negative	None	0	Negative					
2	116D	D Wing Boy's Restroom	W1	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	116D	D Wing Boy's Restroom	W3	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	116D	D Wing Boy's Restroom	W2	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	116D	D Wing Boy's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0	Negative	None	0	N/A					
2	116D	D Wing Boy's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0	Negative	None	0	N/A					
2	116D	D Wing Boy's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0	Negative	None	0	N/A					
2	116D	D Wing Boy's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0	Negative	None	0	N/A					
2	116D	D Wing Boy's Restroom	CEILING	CONCRETE	BEIGE	None	0	0	Negative	None	0	N/A					
2	117D	D Wing Men's Staff Restroom	CEILING	CONCRETE	WHITE	None	0	0	Negative	None	0	N/A					
2	117D	D Wing Men's Staff Restroom	WALL BASEBOAR	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	117D	D Wing Men's Staff Restroom	WALL BASEBOAR	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	117D	D Wing Men's Staff Restroom	WALL BASEBOAR	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	117D	D Wing Men's Staff Restroom	DOOR CASING	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
2	117D	D Wing Men's Staff Restroom	DOOR	WOOD	BLUE	None	0	0.09	Negative	None	0	Negative					
2	118D	D Wing Women's Staff Restroom	DOOR CASING	METAL	BLUE	None	0	0.02	Negative	None	0	Negative					
2	118D	D Wing Women's Staff Restroom	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
2	118D	D Wing Women's Staff Restroom	W1	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	118D	D Wing Women's Staff Restroom	W4	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	118D	D Wing Women's Staff Restroom	W3	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	118D	D Wing Women's Staff Restroom	CEILING	CONCRETE	WHITE	None	0	0	Negative	None	0	N/A					
2	119D	D Wing Girl's Restroom	CEILING	CONCRETE	BEIGE	None	0	0	Negative	None	0	N/A					
2	119D	D Wing Girl's Restroom	FLOOR	CONCRETE	GRAY	None	0	0	Negative	None	0	N/A					
2	119D	D Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.03	Negative	None	0	N/A					
2	119D	D Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.02	Negative	None	0	N/A					
2	119D	D Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.01	Negative	None	0	N/A					
2	119D	D Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.02	Negative	None	0	N/A					
2	119D	D Wing Girl's Restroom	W3	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	119D	D Wing Girl's Restroom	W2	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	119D	D Wing Girl's Restroom	W1	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	119D	D Wing Girl's Restroom	DOOR CASING	METAL	BLACK	None	0	0.05	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	W1	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	W4	CMU	BEIGE	None	0	0.05	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	DOOR CASING	METAL	BLACK	None	0	0.03	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	DOOR	METAL	BLUE	None	0	0	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	W2	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	SOFFIT	Plaster	BEIGE	None	0	0	Negative	None	0	N/A					
2	H124	Hallway outside D Wing Classrooms D101 - D106	SOFFIT	Plaster	BEIGE	None	0	0	Negative	None	0	N/A					
2	H124	Hallway outside D Wing Classrooms D101 - D106	W1	CMU	Blue	None	0	0.1	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	W1	CMU	Green	None	0	0.2	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	W3	CMU	Green	None	0	0	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	W3	CMU	Blue	None	0	0.1	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	W2	CMU	Blue	None	0	0.2	Negative	None	0	Negative					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	H124	Hallway outside D Wing Classrooms D101 - D106	W2	CMU	Green	None	0	0.1	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	W4	CMU	Green	None	0	0.1	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	W4	CMU	Blue	None	0	0.1	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	Door	Wood	Beige	None	0	0.1	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	Door Casing	Metal	Blue	None	0	0.4	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	Door	Wood	Beige	None	0	0.1	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	Door Casing	Metal	Beige	None	0	0.1	Negative	None	0	Negative					
2	H124	Hallway outside D Wing Classrooms D101 - D106	Soffit	Plaster	Beige	None	0	0.5	Negative	None	0	N/A					
2	H124	Hallway outside D Wing Classrooms D101 - D106	Soffit	Plaster	Beige	None	0	0.1	Negative	None	0	N/A					
2	H124C	Custodial Closet in hallway between D106 & D105	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H124C	Custodial Closet in hallway between D106 & D105	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H124C	Custodial Closet in hallway between D106 & D105	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H124C	Custodial Closet in hallway between D106 & D105	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H124C	Custodial Closet in hallway between D106 & D105	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H124C	Custodial Closet in hallway between D106 & D105	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	S14	Stairwell behind C Wing Classroom 106C	W1	BRICK	BEIGE	None	0	0.01	Negative	None	0	N/A					
2	S14	Stairwell behind C Wing Classroom 106C	W2	BRICK	BEIGE	None	0	0.01	Negative	None	0	N/A					
2	S14	Stairwell behind C Wing Classroom 106C	W4	BRICK	BEIGE	None	0	0.01	Negative	None	0	N/A					
2	S14	Stairwell behind C Wing Classroom 106C	W3	BRICK	BEIGE	None	0	0.03	Negative	None	0	N/A					
2	S14	Stairwell behind C Wing Classroom 106C	W3	DRYWALL	BEIGE	None	0	0	Negative	None	0	N/A					
2	S14	Stairwell behind C Wing Classroom 106C	STAIRS RISER	METAL	BEIGE	None	0	0.6	Negative	None	0	Negative					
2	S14	Stairwell behind C Wing Classroom 106C	STAIRS STRINGER	METAL	BEIGE	None	0	1.2	Positive	None	0	Negative					
2	S14	Stairwell behind C Wing Classroom 106C	STAIRS RAILING	METAL	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	S14	Stairwell behind C Wing Classroom 106C	STAIRS HALFVAL	WOOD	BEIGE	None	0	0	Negative	None	0	Negative					
2	S14	Stairwell behind C Wing Classroom 106C	W3	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	S14	Stairwell behind C Wing Classroom 106C	DOOR CASING	METAL	BEIGE	None	0	0	Negative	None	0	Negative					
2	S14	Stairwell behind C Wing Classroom 106C	DOOR	METAL	BEIGE	None	0	0	Negative	None	0	Negative					
2	S14	Stairwell behind C Wing Classroom 106C	DOOR CENTER P	METAL	BEIGE	None	0	0	Negative	None	0	Negative					
2	S14	Stairwell behind C Wing Classroom 106C	UNIVENT	METAL	BEIGE	None	0	0.01	Negative	None	0	N/A					
2	S14	Stairwell behind C Wing Classroom 106C	CEILING	CONCRETE	BEIGE	None	0	0.04	Negative	None	0	N/A					
2	106C	Classroom C106	W1	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	106C	Classroom C106	W2	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	106C	Classroom C106	W3	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	106C	Classroom C106	W3	CMU	GREEN	None	0	0.01	Negative	None	0	Negative					
2	106C	Classroom C106	W4	CMU	GREEN	None	0	0.01	Negative	None	0	Negative					
2	106C	Classroom C106	SOFFIT	PLASTER	WHITE	None	0	0	Negative	None	0	N/A					
2	106C	Classroom C106	SOFFIT	PLASTER	WHITE	None	0	0	Negative	None	0	N/A					
2	106C	Classroom C106	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
2	106C	Classroom C106	DOOR	WOOD	BLUE	None	0	0	Negative	None	0	Negative					
2	105C	Classroom C105	DOOR CASING	METAL	BLUE	None	0	0.06	Negative	None	0	Negative					
2	105C	Classroom C105	W1	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	105C	Classroom C105	W2	CMU	WHITE	None	0	0.02	Negative	None	0	Negative					
2	105C	Classroom C105	W3	CMU	GREEN	None	0	0.01	Negative	None	0	Negative					
2	105C	Classroom C105	SOFFIT	PLASTER	WHITE	Efflorescence	4	0	Negative	None	0	N/A	No	Temperature Control	No	No	Efflorescence from Univent
2	105C	Classroom C105	WALL DIVIDER TH	WOOD	WHITE	None	0	0	Negative	None	0	Negative					
2	105C	Classroom C105	WALL DIVIDER	DRYWALL	WHITE	None	0	0	Negative	None	0	N/A					
2	104C	Classroom C104	WALL DIVIDER TH	WOOD	WHITE	None	0	0.01	Negative	None	0	N/A					
2	104C	Classroom C104	WALL DIVIDER TH	WOOD	WHITE	None	0	0.02	Negative	None	0	Negative					
2	104C	Classroom C104	W1	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	104C	Classroom C104	W4	CMU	WHITE	None	0	0.04	Negative	None	0	Negative					
2	104C	Classroom C104	W3	CMU	GREEN	None	0	0.04	Negative	None	0	Negative					
2	104C	Classroom C104	DIVIDER WALL	DRYWALL	WHITE	None	0	0.01	Negative	None	0	N/A					
2	104C	Classroom C104	DIVIDER WALL TH	WOOD	WHITE	None	0	0	Negative	None	0	Negative					
2	104C	Classroom C104	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative	None	0	N/A					
2	103C	Classroom C103	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative	None	0	N/A					
2	103C	Classroom C103	W1	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	103C	Classroom C103	W4	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	103C	Classroom C103	W3	CMU	GREEN	None	0	0.05	Negative	None	0	Negative					
2	103C	Classroom C103	W2	CMU	WHITE	None	0	0.02	Negative	None	0	Negative					
2	103C	Classroom C103	WALL DIVIDER TH	WOOD	WHITE	None	0	0.01	Negative	None	0	Negative					
2	103C	Classroom C103	WALL DIVIDER	DRYWALL	WHITE	None	0	0.01	Negative	None	0	N/A					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	103C	Classroom C103	DOOR CASING	METAL	BLUE	None	0	0	Negative	None	0	Negative					
2	102C	Classroom C102	DOOR CASING	METAL	BLUE	None	0	0.02	Negative	None	0	Negative					
2	102C	Classroom C102	DOOR	WOOD	BLUE	None	0	0	Negative	None	0	Negative					
2	102C	Classroom C102	W1	CMU	WHITE	None	0	0.02	Negative	None	0	Negative					
2	102C	Classroom C102	W2	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	102C	Classroom C102	W3	CMU	GREEN	None	0	0.05	Negative	None	0	Negative					
2	102C	Classroom C102	SOFFIT	PLASTER	WHITE	None	0	0.01	Negative	None	0	N/A					
2	102C	Classroom C102	WALL DIVIDER TH	WOOD	WHITE	None	0	0.01	Negative	None	0	Negative					
2	102C	Classroom C102	WALL DIVIDER	DRYWALL	WHITE	None	0	0.02	Negative	None	0	Negative					
2	102C	Classroom C102	COLUMN	CONCRETE	WHITE	None	0	0	Negative	None	0	Negative					
2	101C	Classroom C101	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
2	101C	Classroom C101	W1	CMU	WHITE	None	0	0.03	Negative	None	0	Negative					
2	101C	Classroom C101	W4	CMU	WHITE	None	0	0.05	Negative	None	0	Negative					
2	101C	Classroom C101	W3	CMU	GREEN	None	0	0.02	Negative	None	0	Negative					
2	101C	Classroom C101	SOFFIT	PLASTER	WHITE	None	0	0.02	Negative	None	0	N/A					
2	101C	Classroom C101	DIVIDER WALL TH	WOOD	WHITE	None	0	0.01	Negative	None	0	Negative					
2	101C	Classroom C101	DIVIDER WALL	DRYWALL	WHITE	None	0	0.01	Negative	None	0	N/A					
2	119C	C Wing Boy's Restroom	DOOR CASING	METAL	BLACK	None	0	0.03	Negative	None	0	Negative					
2	119C	C Wing Boy's Restroom	W1	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	119C	C Wing Boy's Restroom	W4	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	119C	C Wing Boy's Restroom	W2	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	119C	C Wing Boy's Restroom	W3	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	119C	C Wing Boy's Restroom	CEILING	CONCRETE	BEIGE	None	0	0	Negative	None	0	N/A					
2	119C	C Wing Boy's Restroom	FLOOR	CONCRETE	GRAY	None	0	0	Negative	None	0	N/A					
2	119C	C Wing Boy's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.02	Negative	None	0	N/A					
2	119C	C Wing Boy's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.01	Negative	None	0	N/A					
2	119C	C Wing Boy's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0	Negative	None	0	N/A					
2	119C	C Wing Boy's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.04	Negative	None	0	N/A					
2	118C	C Wing Men's Staff Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	118C	C Wing Men's Staff Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	118C	C Wing Men's Staff Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	118C	C Wing Men's Staff Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	118C	C Wing Men's Staff Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	118C	C Wing Men's Staff Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	117C	C Wing Women's Staff Restroom	W1	CMU	WHITE	None	0	0	Negative	None	0	Negative					
2	117C	C Wing Women's Staff Restroom	W4	CMU	WHITE	None	0	0	Negative	None	0	Negative					
2	117C	C Wing Women's Staff Restroom	W3	CMU	WHITE	None	0	0	Negative	None	0	Negative					
2	117C	C Wing Women's Staff Restroom	CEILING	CONCRETE	WHITE	None	0	0	Negative	None	0	N/A					
2	116C	C Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.05	Negative	None	0	N/A					
2	116C	C Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.01	Negative	None	0	N/A					
2	116C	C Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.04	Negative	None	0	N/A					
2	116C	C Wing Girl's Restroom	WALL BASEBOAR	TILE	GRAY	None	0	0.07	Negative	None	0	N/A					
2	116C	C Wing Girl's Restroom	W1	CMU	PINK	None	0	0	Negative	None	0	Negative					
2	116C	C Wing Girl's Restroom	W4	CMU	PINK	None	0	0	Negative	None	0	Negative					
2	116C	C Wing Girl's Restroom	W3	CMU	PINK	None	0	0	Negative	None	0	Negative					
2	116C	C Wing Girl's Restroom	CEILING	CONCRETE	BEIGE	None	0	0	Negative	None	0	N/A					
2	116C	C Wing Girl's Restroom	FLOOR	CONCRETE	GRAY	None	0	0	Negative	None	0	N/A					
2	116C	C Wing Girl's Restroom	DOOR CASING	METAL	BLACK	None	0	0.01	Negative	None	0	Negative					
2	H126	Hallway outside C Wing Classrooms C101 - C106	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
2	H126	Hallway outside C Wing Classrooms C101 - C106	DOOR	METAL	BLUE	None	0	0	Negative	None	0	Negative					
2	H126	Hallway outside C Wing Classrooms C101 - C106	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	H126	Hallway outside C Wing Classrooms C101 - C106	W2	CMU	PURPLE	None	0	0.04	Negative	None	0	Negative					
2	H126	Hallway outside C Wing Classrooms C101 - C106	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	H126	Hallway outside C Wing Classrooms C101 - C106	W3	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	H126	Hallway outside C Wing Classrooms C101 - C106	W1	CMU	PURPLE	None	0	0.01	Negative	None	0	Negative					
2	H126	Hallway outside C Wing Classrooms C101 - C106	DOOR CASING	METAL	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	H126	Hallway outside C Wing Classrooms C101 - C106	DOOR CASING	METAL	BEIGE	None	0	0.06	Negative	None	0	Negative					
2	H126	Hallway outside C Wing Classrooms C101 - C106	SOFFIT	PLASTER	BEIGE	None	0	0.01	Negative	None	0	N/A					
2	H126	Hallway outside C Wing Classrooms C101 - C106	SOFFIT	PLASTER	BEIGE	None	0	0.01	Negative	None	0	N/A					
2	H126C	Custodial Closet in H126 between classrooms C105 & C106	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
2	H126C	Custodial Closet in H126 between classrooms C105 & C106	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					

		School District of Philadelphia																
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21								
		E.W. Rhodes ES School								ULCS# 4150								
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
2	H126C	Custodial Closet in H126 between classrooms C105 & C106	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A						
2	H126C	Custodial Closet in H126 between classrooms C105 & C106	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A						
2	H126C	Custodial Closet in H126 between classrooms C105 & C106	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A						
2	H126C	Custodial Closet in H126 between classrooms C105 & C106	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A						
2	107D	Large Library Reading Area in D Wing	W1	CMU	BLUE	None	0	0.01	Negative	None	0	Negative						
2	107D	Large Library Reading Area in D Wing	W2	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative						
2	107D	Large Library Reading Area in D Wing	W1	CMU	BEIGE	Flaking	25	0.03	Negative	None	0	Negative	No	Window	No	No		Under Window
2	107D	Large Library Reading Area in D Wing	DOOR CASING	METAL	BLUE	None	0	0.15	Negative	None	0	Negative						
2	107D	Large Library Reading Area in D Wing	DOOR	METAL	BLUE	None	0	0.06	Negative	None	0	Negative						
2	107D	Large Library Reading Area in D Wing	W4	CMU	BLUE	None	0	0.01	Negative	None	0	Negative						
2	107D	Large Library Reading Area in D Wing	DOOR CASING	METAL	BLUE	None	0	0.28	Negative	None	0	Negative						
2	107D	Large Library Reading Area in D Wing	DOOR	METAL	BLUE	None	0	0	Negative	None	0	Negative						
2	107D	Large Library Reading Area in D Wing	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	107D	Large Library Reading Area in D Wing	COLUMN	CONCRETE	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	107D	Large Library Reading Area in D Wing	CEILING	PLASTER	WHITE	None	0	0	Negative	None	0	N/A						
2	S16	D Wing Large Library Reading Area Stairwell	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with Cafeteria
2	S16	D Wing Large Library Reading Area Stairwell	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with Cafeteria
2	S16	D Wing Large Library Reading Area Stairwell	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with Cafeteria
2	S16	D Wing Large Library Reading Area Stairwell	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with Cafeteria
2	S16	D Wing Large Library Reading Area Stairwell	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with Cafeteria
2	S16	D Wing Large Library Reading Area Stairwell	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with Cafeteria
2	112D	Lounge between D Wing Large Library Reading Area and D Wing Hallway	W1	CMU	Grey	None	0	0.01	Negative	None	0	Negative						
2	112D	Lounge between D Wing Large Library Reading Area and D Wing Hallway	W3	CMU	PURPLE	None	0	0	Negative	None	0	Negative						
2	112D	Lounge between D Wing Large Library Reading Area and D Wing Hallway	W4	CMU	PINK	None	0	0.02	Negative	None	0	Negative						
2	112D	Lounge between D Wing Large Library Reading Area and D Wing Hallway	W2	CMU	PINK	None	0	0.01	Negative	None	0	Negative						
2	112D	Lounge between D Wing Large Library Reading Area and D Wing Hallway	DOOR CASING	METAL	PURPLE	None	0	0.02	Negative	None	0	Negative						
2	112D	Lounge between D Wing Large Library Reading Area and D Wing Hallway	DOOR CASING	METAL	PURPLE	None	0	0.01	Negative	None	0	Negative						
	112D	Lounge between D Wing Large Library Reading Area and D Wing Hallway	DOOR	WOOD	PINK	None	0	0	Negative	None	0	Negative						
2	112D	Lounge between D Wing Large Library Reading Area and D Wing Hallway	DOOR	WOOD	PURPLE	None	0	0.01	Negative	None	0	Negative						
2	112D-PC	Pipe Chase in Lounge between D Wing Large Library Reading Area and D Wing Hallway	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A						
2	112D-PC	Pipe Chase in Lounge between D Wing Large Library Reading Area and D Wing Hallway	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A						
2	112D-PC	Pipe Chase in Lounge between D Wing Large Library Reading Area and D Wing Hallway	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A						
2	112D-PC	Pipe Chase in Lounge between D Wing Large Library Reading Area and D Wing Hallway	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A						
2	112D-PC	Pipe Chase in Lounge between D Wing Large Library Reading Area and D Wing Hallway	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A						
2	113D	Office behind D Wing Stairwell	W1	CMU	PURPLE	None	0	0.01	Negative	None	0	Negative						
2	113D	Office behind D Wing Stairwell	W3	CMU	PURPLE	None	0	0	Negative	None	0	Negative						
2	113D	Office behind D Wing Stairwell	W4	CMU	PINK	None	0	0.02	Negative	None	0	Negative						
2	113D	Office behind D Wing Stairwell	W2	CMU	PINK	None	0	0.01	Negative	None	0	Negative						
2	113D	Office behind D Wing Stairwell	DOOR CASING	METAL	PURPLE	None	0	0.02	Negative	None	0	Negative						
2	113D	Office behind D Wing Stairwell	DOOR CASING	METAL	PURPLE	None	0	0.01	Negative	None	0	Negative						
2	113D	Office behind D Wing Stairwell	DOOR	WOOD	PINK	None	0	0	Negative	None	0	Negative						
2	113D	Office behind D Wing Stairwell	DOOR	WOOD	PURPLE	None	0	0.01	Negative	None	0	Negative						
2	115D	Office next to D Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative						
2	115D	Office next to D Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative						
2	115D	Office next to D Wing Stairwell	DOOR	WOOD	BLUE	None	0	0.02	Negative	None	0	Negative						
2	115D	Office next to D Wing Stairwell	W1	CMU	BEIGE	None	0	0	Negative	None	0	Negative						
2	115D	Office next to D Wing Stairwell	W2	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative						
2	115D	Office next to D Wing Stairwell	W3	CMU	BEIGE	None	0	0	Negative	None	0	Negative						
2	115D	Office next to D Wing Stairwell	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	115D	Office next to D Wing Stairwell	COLUMN	CONCRETE	BEIGE	None	0	0.02	Negative	None	0	Negative						
2	114D	Office across from Classroom D103	W1	CMU	BLUE	None	0	0.01	Negative	None	0	Negative						

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	114D	Office across from Classroom D103	W3	CMU	BLUE	None	0	0.01	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	W2	CMU	PURPLE	None	0	0.02	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	W4	CMU	PURPLE	None	0	0.01	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	DOOR CASING	METAL	BLUE	None	0	0.03	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	DOOR	WOOD	BLUE	None	0	0.05	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	DOOR	WOOD	BLUE	None	0	0.02	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	W1	CMU	WHITE	None	0	0.05	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	W1	CMU	BLUE	None	0	0	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	W2	CMU	GRAY	None	0	0.02	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	W3	CMU	GRAY	None	0	0.01	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	W3	CMU	BLUE	None	0	0.01	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	W3	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	W4	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	W4	CMU	GRAY	None	0	0.01	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	DOOR CASING	METAL	BLUE	None	0	0.02	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	DOOR	METAL	BLUE	None	0	0	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	DOOR CASING	METAL	BLUE	None	0	0.03	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	DOOR CASING	METAL	BLUE	None	0	0.02	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
2	114D	Office across from Classroom D103	DOOR CASING	METAL	BLUE	None	0	0	Negative	None	0	Negative					
2	108D	D Wing End Storage Room	W1	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	108D	D Wing End Storage Room	W4	CMU	BEIGE	None	0	0	Negative	None	0	Negative					
2	108D	D Wing End Storage Room	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	108D	D Wing End Storage Room	W2	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	108D	D Wing End Storage Room	DOOR CASING	METAL	BLUE	None	0	0.16	Negative	None	0	Negative					
2	108D	D Wing End Storage Room	DOOR	WOOD	BLUE	None	0	0.05	Negative	None	0	Negative					
2	109D	D Wing Small Storage Room	DOOR	WOOD	BLUE	None	0	0.04	Negative	None	0	Negative					
2	109D	D Wing Small Storage Room	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
2	109D	D Wing Small Storage Room	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	109D	D Wing Small Storage Room	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	109D	D Wing Small Storage Room	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	109D	D Wing Small Storage Room	W2	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	109D	D Wing Small Storage Room	COLUMN	CONCRETE	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	110D	Small Office inside D Wing Large Library Reading Area	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	110D	Small Office inside D Wing Large Library Reading Area	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	110D	Small Office inside D Wing Large Library Reading Area	W2	CMU	BEIGE	None	0	0.03	Negative	None	0	Negative					
2	110D	Small Office inside D Wing Large Library Reading Area	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative					
2	110D	Small Office inside D Wing Large Library Reading Area	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
2	111D	D Wing Storage Room next to HVAC/Mechanical Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	111D	D Wing Storage Room next to HVAC/Mechanical Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	111D	D Wing Storage Room next to HVAC/Mechanical Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	111D	D Wing Storage Room next to HVAC/Mechanical Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	111D	D Wing Storage Room next to HVAC/Mechanical Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	111D	D Wing Storage Room next to HVAC/Mechanical Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	120C	HVAC/Mechanical Room between C and D Wings	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	120C	HVAC/Mechanical Room between C and D Wings	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	120C	HVAC/Mechanical Room between C and D Wings	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	120C	HVAC/Mechanical Room between C and D Wings	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	120C	HVAC/Mechanical Room between C and D Wings	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	120C	HVAC/Mechanical Room between C and D Wings	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	107C	Large Library Reading Area in C Wing	W1	CMU	YELLOW	Flaking	28	0.05	Negative	None	0	Negative	No	Window	No	No	Flaking under Window
2	107C	Large Library Reading Area in C Wing	W1	CMU	WHITE	None	0	0.02	Negative	None	0	Negative					
2	107C	Large Library Reading Area in C Wing	W2	DRYWALL	BEIGE	None	0	0	Negative	None	0	N/A					

		School District of Philadelphia																
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21								
		E.W. Rhodes ES School								ULCS# 4150								
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
2	107C	Large Library Reading Area in C Wing	W2	CMU	YELLOW	None	0	0.01	Negative	None	0	Negative						
2	107C	Large Library Reading Area in C Wing	W3	CMU	YELLOW	None	0	0.01	Negative	None	0	Negative						
2	107C	Large Library Reading Area in C Wing	W4	CMU	YELLOW	None	0	0.01	Negative	None	0	Negative						
2	107C	Large Library Reading Area in C Wing	COLUMN	Concrete	BEIGE	None	0	0	Negative	None	0	Negative						
2	107C	Large Library Reading Area in C Wing	CEILING	PLASTER	BEIGE	None	0	0.01	Negative	None	0	N/A						
2	S15	C Wing Large Library Reading Area Stairwell	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with Cafeteria
2	S15	C Wing Large Library Reading Area Stairwell	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with Cafeteria
2	S15	C Wing Large Library Reading Area Stairwell	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with Cafeteria
2	S15	C Wing Large Library Reading Area Stairwell	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with Cafeteria
2	S15	C Wing Large Library Reading Area Stairwell	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with Cafeteria
2	S15	C Wing Large Library Reading Area Stairwell	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A						Included with Cafeteria
2	112C	Lounge between C Wing Large Library Reading Area and C Wing Hallway	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	112C	Lounge between C Wing Large Library Reading Area and C Wing Hallway	W1	CMU	PURPLE	None	0	0.01	Negative	None	0	Negative						
2	112C	Lounge between C Wing Large Library Reading Area and C Wing Hallway	W2	CMU	PURPLE	None	0	0	Negative	None	0	Negative						
2	112C	Lounge between C Wing Large Library Reading Area and C Wing Hallway	W3	CMU	PURPLE	None	0	0.03	Negative	None	0	Negative						
2	112C	Lounge between C Wing Large Library Reading Area and C Wing Hallway	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	112C	Lounge between C Wing Large Library Reading Area and C Wing Hallway	W2	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	112C	Lounge between C Wing Large Library Reading Area and C Wing Hallway	W1	CMU	PINK	None	0	0.01	Negative	None	0	Negative						
2	112C	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative						
2	112C	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.05	Negative	None	0	Negative						
2	112C	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.02	Negative	None	0	Negative						
2	112C	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR CASING	METAL	BLUE	None	0	0.04	Negative	None	0	Negative						
2	112C	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR	METAL	BLUE	None	0	0	Negative	None	0	Negative						
2	112C	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative						
2	112C	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative						
2	112C	Lounge between C Wing Large Library Reading Area and C Wing Hallway	DOOR	WOOD	BLUE	None	0	-0.09	Negative	None	0	Negative						
2	112-PC	Pipe Chase in 112C Lounge	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A						
2	112-PC	Pipe Chase in 112C Lounge	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A						
2	112-PC	Pipe Chase in 112C Lounge	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A						
2	112-PC	Pipe Chase in 112C Lounge	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A						
2	112-PC	Pipe Chase in 112C Lounge	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A						
2	112-PC	Pipe Chase in 112C Lounge	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A						
2	113C	Office behind C Wing Stairwell	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access	No Access
2	113C	Office behind C Wing Stairwell	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access	No Access
2	113C	Office behind C Wing Stairwell	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access	No Access
2	113C	Office behind C Wing Stairwell	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access	No Access
2	113C	Office behind C Wing Stairwell	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access	No Access
2	113C	Office behind C Wing Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access	No Access
2	115C	Office next to C Wing Stairwell	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	115C	Office next to C Wing Stairwell	W2	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	115C	Office next to C Wing Stairwell	W4	CMU	BEIGE	None	0	0.04	Negative	None	0	Negative						
2	115C	Office next to C Wing Stairwell	W3	CMU	BEIGE	None	0	0	Negative	None	0	Negative						
2	115C	Office next to C Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.02	Negative	None	0	Negative						
2	115C	Office next to C Wing Stairwell	DOOR CASING	METAL	BLUE	None	0	0.13	Negative	None	0	Negative						
2	115C	Office next to C Wing Stairwell	DOOR	WOOD	BLUE	None	0	0.04	Negative	None	0	Negative						
2	114C	Office across from Classroom C103	W1	CMU	BEIGE	None	0	0	Negative	None	0	Negative						
2	114C	Office across from Classroom C103	W2	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	114C	Office across from Classroom C103	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative						
2	114C	Office across from Classroom C103	W3	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative						
2	114C	Office across from Classroom C103	DOOR CASING	METAL	BLUE	None	0	0.02	Negative	None	0	Negative						
2	114C	Office across from Classroom C103	DOOR	WOOD	BLUE	None	0	0	Negative	None	0	Negative						
2	114C	Office across from Classroom C103	DOOR	WOOD	BLUE	None	0	0	Negative	None	0	Negative						
2	114C	Office across from Classroom C103	DOOR CASING	METAL	BLUE	None	0	0.01	Negative	None	0	Negative						

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	108C	C Wing End Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	108C	C Wing End Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	108C	C Wing End Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	108C	C Wing End Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	108C	C Wing End Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	108C	C Wing End Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	109C	C Wing Small Storage Room	DOOR	WOOD	BLUE	None	0	0.01	Negative	None	0	Negative					
2	109C	C Wing Small Storage Room	DOOR CASING	METAL	BLUE	None	0	0.04	Negative	None	0	Negative					
2	109C	C Wing Small Storage Room	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	109C	C Wing Small Storage Room	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	109C	C Wing Small Storage Room	W3	CMU	BEIGE	None	0	0.04	Negative	None	0	Negative					
2	109C	C Wing Small Storage Room	W2	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	110C	Small Office inside C Wing Large Library Reading Area	W2	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	110C	Small Office inside C Wing Large Library Reading Area	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	110C	Small Office inside C Wing Large Library Reading Area	W4	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	110C	Small Office inside C Wing Large Library Reading Area	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	110C	Small Office inside C Wing Large Library Reading Area	DOOR CASING	METAL	BLUE	None	0	0.02	Negative	None	0	Negative					
2	110C	Small Office inside C Wing Large Library Reading Area	DOOR	WOOD	BLUE	None	0	0.05	Negative	None	0	Negative					
2	111C	C Wing Storage Room next to HVAC/Mechanical Room 1	DOOR	WOOD	BLUE	None	0	0.04	Negative	None	0	Negative					
2	111C	C Wing Storage Room next to HVAC/Mechanical Room 1	DOOR CASING	METAL	BLUE	None	0	0.05	Negative	None	0	Negative					
2	111C	C Wing Storage Room next to HVAC/Mechanical Room 1	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	111C	C Wing Storage Room next to HVAC/Mechanical Room 1	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	111C	C Wing Storage Room next to HVAC/Mechanical Room 1	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	111C	C Wing Storage Room next to HVAC/Mechanical Room 1	W2	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	IMC	IMC (Library)	W1	CMU	BEIGE	Flaking	15	0.01	Negative	None	0	Negative	No	Window	No	No	Efflorescence Adj Windows
2	IMC	IMC (Library)	COLUMN	CONCRETE	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	IMC	IMC (Library)	COLUMN	CONCRETE	WHITE	None	0	0.02	Negative	None	0	Negative					
2	IMC	IMC (Library)	W3	CMU	WHITE	None	0	0.01	Negative	None	0	Negative					
2	IMC	IMC (Library)	W4	DRYWALL	WHITE	None	0	0	Negative	None	0	N/A					
2	IMC	IMC (Library)	W4	CMU	BEIGE	None	0	0.04	Negative	None	0	Negative					
2	IMC	IMC (Library)	W2	CMU	BEIGE	Flaking	25	0.02	Negative	None	0	Negative	No	Window	No	No	Efflorescence Adj Windows
2	IMC	IMC (Library)	W2	DRYWALL	BEIGE	None	0	0	Negative	None	0	N/A					
2	IMC	IMC (Library)	SOFFIT	PLASTER	BEIGE	None	0	0.02	Negative	None	0	N/A					
2	IMC	IMC (Library)	WINDOW CASING	METAL	BROWN	None	0	0.4	Negative	None	0	Negative					
2	IMC	IMC (Library)	DOOR CASING	METAL	BROWN	None	0	0.4	Negative	None	0	Negative					
2	IMC	IMC (Library)	DOOR	WOOD	BROWN	None	0	0.03	Negative	None	0	Negative					
2	IMC	IMC (Library)	DOOR	WOOD	BROWN	None	0	0.01	Negative	None	0	Negative					
2	IMC	IMC (Library)	DOOR CASING	METAL	BROWN	None	0	0.4	Negative	None	0	Negative					
2	IMCO	IMC Office	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	IMCO	IMC Office	W2	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	IMCO	IMC Office	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	IMCO	IMC Office	W4	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	IMCO	IMC Office	WINDOW CASING	METAL	BROWN	None	0	0.4	Negative	None	0	Negative					
2	IMCO	IMC Office	WINDOW CASING	METAL	BROWN	None	0	0.23	Negative	None	0	Negative					
2	IMCO	IMC Office	WINDOW CASING	METAL	BROWN	None	0	0.25	Negative	None	0	Negative					
2	IMCO	IMC Office	DOOR CASING	METAL	BROWN	None	0	0.4	Negative	None	0	Negative					
2	IMCO	IMC Office	DOOR	WOOD	BROWN	None	0	0.01	Negative	None	0	Negative					
2	IMCO	IMC Office	DOOR	WOOD	BROWN	None	0	0.01	Negative	None	0	Negative					
2	IMCO	IMC Office	DOOR CASING	METAL	BROWN	None	0	0.25	Negative	None	0	Negative					
2	120E	Small office in IMC	DOOR CASING	METAL	BROWN	None	0	0.5	Negative	None	0	Negative					
2	120E	Small office in IMC	DOOR CASING	METAL	BROWN	None	0	0.4	Negative	None	0	Negative					
2	120E	Small office in IMC	DOOR CASING	WOOD	BROWN	None	0	0.01	Negative	None	0	Negative					
2	120E	Small office in IMC	DOOR CASING	WOOD	BROWN	None	0	0	Negative	None	0	Negative					
2	120E	Small office in IMC	W1	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	120E	Small office in IMC	W2	CMU	BEIGE	None	0	0.03	Negative	None	0	Negative					
2	120E	Small office in IMC	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	120E	Small office in IMC	W3	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	121E	IMC Office/Data Room	W1	CMU	BEIGE	None	0	0.03	Negative	None	0	Negative					
2	121E	IMC Office/Data Room	W4	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	121E	IMC Office/Data Room	W3	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	121E	IMC Office/Data Room	W2	CMU	BEIGE	None	0	0.04	Negative	None	0	Negative					
2	121E	IMC Office/Data Room	DOOR CASING	METAL	BROWN	None	0	0.28	Negative	None	0	Negative					
2	121E	IMC Office/Data Room	DOOR	METAL	BROWN	None	0	0.02	Negative	None	0	Negative					
2	123E	IMC Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	123E	IMC Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	123E	IMC Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	123E	IMC Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	123E	IMC Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	123E	IMC Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	H129	Hallway from D Wing Library Reading Room to Computer Classroom E131	W1	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	H129	Hallway from D Wing Library Reading Room to Computer Classroom E131	W3	CMU	Beige	None	0	0	Negative	None	0	Negative					
2	H129	Hallway from D Wing Library Reading Room to Computer Classroom E131	W4	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	H129	Hallway from D Wing Library Reading Room to Computer Classroom E131	Door	Wood	Beige	None	0	0.1	Negative	None	0	Negative					
2	H129	Hallway from D Wing Library Reading Room to Computer Classroom E131	Door Casing	Metal	Beige	None	0	0.1	Negative	None	0	Negative					
2	H129	Hallway from D Wing Library Reading Room to Computer Classroom E131	Soffit	Plaster	Beige	None	0	0.1	Negative	None	0	N/A					
2	H130	Hallway between Library and Auditorium	W2	CMU	Purple	None	0	0.1	Negative	None	0	Negative					
2	H130	Hallway between Library and Auditorium	W2	CMU	Pink	None	0	0.1	Negative	None	0	Negative					
2	H130	Hallway between Library and Auditorium	W2	CMU	Blue	None	0	0.3	Negative	None	0	Negative					
2	H130	Hallway between Library and Auditorium	W2	CMU	Green	None	0	0.2	Negative	None	0	Negative					
2	H130	Hallway between Library and Auditorium	W2	CMU	Red	None	0	0.1	Negative	None	0	Negative					
2	H130	Hallway between Library and Auditorium	W2	CMU	Orange	None	0	0.1	Negative	None	0	Negative					
2	H130	Hallway between Library and Auditorium	W4	CMU	Orange	None	0	0	Negative	None	0	Negative					
2	H130	Hallway between Library and Auditorium	W4	CMU	Pink	None	0	0.1	Negative	None	0	Negative					
2	H130	Hallway between Library and Auditorium	W4	CMU	Purple	None	0	0.1	Negative	None	0	Negative					
2	H130	Hallway between Library and Auditorium	W4	CMU	Blue	None	0	0.1	Negative	None	0	Negative					
2	H130	Hallway between Library and Auditorium	W4	CMU	Green	None	0	0	Negative	None	0	Negative					
2	H130	Hallway between Library and Auditorium	W4	CMU	Red	None	0	0.1	Negative	None	0	Negative					
2	H131	Hallway from Library to Classroom 126	W1	CMU	Yellow	None	0	0.1	Negative	None	0	Negative					
2	H131	Hallway from Library to Classroom 126	W1	CMU	Green	None	0	0.1	Negative	None	0	Negative					
2	H131	Hallway from Library to Classroom 126	W1	CMU	Purple	None	0	0.1	Negative	None	0	Negative					
2	H131	Hallway from Library to Classroom 126	W1	CMU	Blue	None	0	0	Negative	None	0	Negative					
2	H131	Hallway from Library to Classroom 126	W1	CMU	Navy	None	0	0.1	Negative	None	0	Negative					
2	H131	Hallway from Library to Classroom 126	W3	CMU	Navy	None	0	0.1	Negative	None	0	Negative					
2	H131	Hallway from Library to Classroom 126	W3	CMU	Blue	None	0	0.1	Negative	None	0	Negative					
2	H131	Hallway from Library to Classroom 126	W3	CMU	Green	None	0	0.1	Negative	None	0	Negative					
2	H131	Hallway from Library to Classroom 126	W3	CMU	Yellow	None	0	0	Negative	None	0	Negative					
2	H131	Hallway from Library to Classroom 126	W4	CMU	Beige	None	0	0.2	Negative	None	0	Negative					
2	H131	Hallway from Library to Classroom 126	Door Casing	Metal	Beige	None	0	0.1	Negative	None	0	Negative					
2	H131	Hallway from Library to Classroom 126	Door Casing	Metal	Beige	None	0	0.3	Negative	None	0	Negative					
2	H131	Hallway from Library to Classroom 126	Door	Metal	Beige	None	0	0	Negative	None	0	Negative					
2	H131	Hallway from Library to Classroom 126	Door	Metal	Beige	None	0	0	Negative	None	0	Negative					
2	H131	Hallway from Library to Classroom 126	Door Casing	Metal	Beige	None	0	0.3	Negative	None	0	Negative					
2	131E	Computer Classroom E131	W1	Concrete	White	None	0	0.2	Negative	None	0	Negative					
2	131E	Computer Classroom E131	W2	Concrete	White	None	0	0.1	Negative	None	0	Negative					
2	131E	Computer Classroom E131	W3	Concrete	White	None	0	0.1	Negative	None	0	Negative					
2	131E	Computer Classroom E131	W4	Concrete	White	None	0	0	Negative	None	0	Negative					
2	131E	Computer Classroom E131	Column	Concrete	White	None	0	0.2	Negative	None	0	Negative					
2	131E	Computer Classroom E131	Ceiling	Concrete	White	None	0	0.2	Negative	None	0	Negative					
2	131E	Computer Classroom E131	Duct	Metal	White	None	0	0.1	Negative	None	0	Negative					
2	131E	Computer Classroom E131	Closet - Door	Wood	Brown	None	0	0.1	Negative	None	0	Negative					
2	131E	Computer Classroom E131	Door Casing	Metal	Brown	None	0	0.5	Negative	None	0	Negative					
2	131E	Computer Classroom E131	Column	Concrete	White	None	0	0.2	Negative	None	0	Negative					
2	131E	Computer Classroom E131	Window Casing	Metal	Brown	None	0	0	Negative	None	0	Negative					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	126A	Classroom 126 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	126A	Classroom 126 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	126A	Classroom 126 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	126A	Classroom 126 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	126A	Classroom 126 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
2	S126	Stairwell next to Classroom 126	Door Casing	Metal	Beige	None	0	0.5	Negative	None	0	Negative					
2	S126	Stairwell next to Classroom 126	Door	Metal	Beige	None	0	0	Negative	None	0	Negative					
2	S126	Stairwell next to Classroom 126	W1	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	S126	Stairwell next to Classroom 126	W2	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	S126	Stairwell next to Classroom 126	W3	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	S126	Stairwell next to Classroom 126	W4	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	S126	Stairwell next to Classroom 126	Stairs - Railing	Metal	Beige	None	0	0.3	Negative	None	0	Negative					
2	S126	Stairwell next to Classroom 126	Stairs - Stringer	Metal	Beige	None	0	0.6	Negative	None	0	Negative					
2	S126	Stairwell next to Classroom 126	Stairs - Riser	Metal	Beige	None	0	0.7	Positive	None	0	Negative					
2	126E	Classroom at End of Hall next to Computer Classroom E131, Left Door	W1	DRYWALL	BEIGE	None	0	0	Negative	None	0	N/A					
2	126E	Classroom at End of Hall next to Computer Classroom E131, Left Door	W2	DRYWALL	BEIGE	None	0	0	Negative	None	0	N/A					
2	126E	Classroom at End of Hall next to Computer Classroom E131, Left Door	W3	CMU	BEIGE	None	0	0.02	Negative	None	0	Negative					
2	126E	Classroom at End of Hall next to Computer Classroom E131, Left Door	W4	CMU	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	126E	Classroom at End of Hall next to Computer Classroom E131, Left Door	DUCT	METAL	BEIGE	None	0	0.01	Negative	None	0	Negative					
2	126E	Classroom at End of Hall next to Computer Classroom E131, Left Door	CEILING	CONCRETE	BEIGE	None	0	0.02	Negative	None	0	N/A					
2	127E	Large HVAC/Mechanical Room next to Computer Classroom E131	Fan Unit	Metal	Beige	Flaking	20	0.1	Negative	None	0	Negative	No	No	No	No	Flaking
2	127E	Large HVAC/Mechanical Room next to Computer Classroom E131	Duct	Metal	Beige	None	0	0.1	Negative	None	0	Negative					
2	127E	Large HVAC/Mechanical Room next to Computer Classroom E131	Larger Fan Unit	Metal	Beige	None	0	0	Negative	None	0	Negative					
2	132E	Classroom at End of Hall next to Computer Classroom E131, Right Door	W4	CMU	Beige	None	0	0.3	Negative	None	0	Negative					
2	132E	Classroom at End of Hall next to Computer Classroom E131, Right Door	W3	CMU	Beige	None	0	0	Negative	None	0	Negative					
2	132E	Classroom at End of Hall next to Computer Classroom E131, Right Door	W2	CMU	Beige	None	0	0.1	Negative	None	0	Negative					
2	132E	Classroom at End of Hall next to Computer Classroom E131, Right Door	W1	Drywall	Beige	None	0	0.1	Negative	None	0	N/A					
2	132E	Classroom at End of Hall next to Computer Classroom E131, Right Door	W4	Drywall	Beige	None	0	0.1	Negative	None	0	N/A					
2	132E	Classroom at End of Hall next to Computer Classroom E131, Right Door	Ceiling	Concrete	Beige	None	0	0.2	Negative	None	0	N/A					
2	132E	Classroom at End of Hall next to Computer Classroom E131, Right Door	Column	Concrete	Beige	None	0	0.2	Negative	None	0	Negative					
2	132E	Classroom at End of Hall next to Computer Classroom E131, Right Door	Duct	Metal	Beige	None	0	0.2	Negative	None	0	Negative					
2	132E	Classroom at End of Hall next to Computer Classroom E131, Right Door	Door	Metal	Brown	None	0	0	Negative	None	0	Negative					
2	132E	Classroom at End of Hall next to Computer Classroom E131, Right Door	Door Casing	Metal	Brown	None	0	0	Negative	None	0	Negative					
2	132E	Classroom at End of Hall next to Computer Classroom E131, Right Door	W4	Drywall	Beige	None	0	0.1	Negative	None	0	Negative					
2	132E	Classroom at End of Hall next to Computer Classroom E131, Right Door	Door	Metal	Brown	None	0	0	Negative	None	0	Negative					
2	132E	Classroom at End of Hall next to Computer Classroom E131, Right Door	Door Casing	Metal	Brown	None	0	0.5	Negative	None	0	Negative					
2	131C	Closet between Two Classrooms at End of Hall next to Computer Classroom E131	W1	CMU	Purple	None	0	0.2	Negative	None	0	Negative					
2	131C	Closet between Two Classrooms at End of Hall next to Computer Classroom E131	W2	CMU	Purple	None	0	0.2	Negative	None	0	Negative					
2	131C	Closet between Two Classrooms at End of Hall next to Computer Classroom E131	W3	CMU	Purple	None	0	0.1	Negative	None	0	Negative					
2	131C	Closet between Two Classrooms at End of Hall next to Computer Classroom E131	W4	CMU	Purple	None	0	0.1	Negative	None	0	Negative					
2	131C	Closet between Two Classrooms at End of Hall next to Computer Classroom E131	Pipe	Metal	Purple	None	0	0.3	Negative	None	0	N/A					
2	131C	Closet between Two Classrooms at End of Hall next to Computer Classroom E131	Door Casing	Metal	Blue	None	0	0.3	Negative	None	0	Negative					

		School District of Philadelphia															
		Lead Safe Certification Assessment Report								Inspection Dates: 5/18/21 - 5/21/21, 6/9/21, 6/15/21 & 7/15/21							
		E.W. Rhodes ES School								ULCS# 4150							
F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
2	139E	Soundproof Room F inside Music Classroom next to Stairwell	W2	CMU	Yellow	None	0	0.1	Negative	None	0	Negative					
2	139E	Soundproof Room F inside Music Classroom next to Stairwell	W3	CMU	Yellow	None	0	0.1	Negative	None	0	Negative					
2	139E	Soundproof Room F inside Music Classroom next to Stairwell	W4	CMU	Yellow	None	0	0.1	Negative	None	0	Negative					
2	139E	Soundproof Room F inside Music Classroom next to Stairwell	Door Casing	Metal	Blue	None	0	0.2	Negative	None	0	Negative					
2	139E	Soundproof Room F inside Music Classroom next to Stairwell	Door	Wood	Blue	None	0	0	Negative	None	0	Negative					
2	135E	Smaller Music Classroom	W1	CMU	YELLOW	None	0	0.01	Negative	None	0	Negative					
2	135E	Smaller Music Classroom	W4	CMU	YELLOW	None	0	0.01	Negative	None	0	Negative					
2	135E	Smaller Music Classroom	W3	CMU	YELLOW	None	0	0.01	Negative	None	0	Negative					
2	135E	Smaller Music Classroom	W2	CMU	YELLOW	None	0	0.04	Negative	None	0	Negative					
2	135E	Smaller Music Classroom	COLUMN 1	CONCRETE	YELLOW	Flaking	15	0.02	Negative	None	0	Negative	No	No	No	No	Flaking
2	135E	Smaller Music Classroom	COLUMN 4	CONCRETE	YELLOW	Flaking	10	0.01	Negative	None	0	Negative	No	no	no	No	Flaking
2	133E	Office inside Smaller Music Classroom	W1	CMU	YELLOW	None	0	0.01	Negative	None	0	Negative					
2	133E	Office inside Smaller Music Classroom	W2	CMU	YELLOW	None	0	0.01	Negative	None	0	Negative					
2	133E	Office inside Smaller Music Classroom	W3	CMU	YELLOW	None	0	0.01	Negative	None	0	Negative					
2	133E	Office inside Smaller Music Classroom	W4	CMU	YELLOW	None	0	0.01	Negative	None	0	Negative					
2	133E	Office inside Smaller Music Classroom	DOOR CASING	METAL	BLUE	None	0	0	Negative	None	0	Negative					
2	133E	Office inside Smaller Music Classroom	DOOR	WOOD	BLUE	None	0	0.02	Negative	None	0	Negative					
2	133E	Office inside Smaller Music Classroom	DOOR	WOOD	BLUE	None	0	0.06	Negative	None	0	Negative					
2	133E	Office inside Smaller Music Classroom	DOOR CASING	METAL	BLUE	None	0	0	Negative	None	0	Negative					
2	135A	Soundproof Room A inside Smaller Music Classroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135A	Soundproof Room A inside Smaller Music Classroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135A	Soundproof Room A inside Smaller Music Classroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135A	Soundproof Room A inside Smaller Music Classroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135A	Soundproof Room A inside Smaller Music Classroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135A	Soundproof Room A inside Smaller Music Classroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135B	Soundproof Room B inside Smaller Music Classroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135B	Soundproof Room B inside Smaller Music Classroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135B	Soundproof Room B inside Smaller Music Classroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135B	Soundproof Room B inside Smaller Music Classroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135B	Soundproof Room B inside Smaller Music Classroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135B	Soundproof Room B inside Smaller Music Classroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135C	Soundproof Room C inside Smaller Music Classroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135C	Soundproof Room C inside Smaller Music Classroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135C	Soundproof Room C inside Smaller Music Classroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135C	Soundproof Room C inside Smaller Music Classroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135C	Soundproof Room C inside Smaller Music Classroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
2	135C	Soundproof Room C inside Smaller Music Classroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	No Access
AT	AT	Attic - None	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
AT	AT	Attic - None	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
AT	AT	Attic - None	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
AT	AT	Attic - None	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
AT	AT	Attic - None	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
AT	AT	Attic - None	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
CS	CS1	Crawl Space Under the Pool	W1	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
CS	CS1	Crawl Space Under the Pool	W2	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
CS	CS1	Crawl Space Under the Pool	W3	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
CS	CS1	Crawl Space Under the Pool	W4	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
CS	CS1	Crawl Space Under the Pool	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A			N/A					
CS	CS1	Crawl Space Under the Pool	Floor	N/A	N/A	N/A	N/A	N/A	N/A			N/A					