

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Name of Inspector: Kristen Masotes		Lingelbach Elementary School								Inspection Dates: 8/17/21 - 8/19/21						
Inspection Company: Acer Associates		ULCS# 6440																	
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	R	Roof	No	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	R	Roof	No	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	R	Roof	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	R	Roof	No	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	R	Roof	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	R	Roof	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	Stairwell 4	Yes	W1	CMU/Concrete	Beige	None	0	0.2	Negative		0	Negative						
1	2	Stairwell 4	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative						
1	2	Stairwell 4	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative						
1	2	Stairwell 4	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative						
1	2	Stairwell 4	Yes	Ceiling	Concrete	White	None	0	0	Negative		0	Negative						
1	2	Stairwell 4	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	Stairwell 4	Yes	Door	Metal	Gray	None	0	0	Negative		0	N/A						
1	2	Stairwell 4	Yes	Door Casing	Metal	Gray	None	0	0.2	Negative		0	N/A						
1	2	Stairwell 4	Yes	Radiator	Metal	Gray	None	0	0.2	Negative		0	N/A						
1	2	Boy's Restroom behind IMC	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	
1	2	Boy's Restroom behind IMC	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	
1	2	Boy's Restroom behind IMC	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	
1	2	Boy's Restroom behind IMC	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	
1	2	Boy's Restroom behind IMC	Yes	Ceiling	Plaster	White	None	0	0.3	Negative		0	N/A						
1	2	Boy's Restroom behind IMC	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	Boy's Restroom behind IMC	Yes	Door Casing	Metal	Gray	None	0	0	Negative		0	N/A						
1	2	Pipe Chase between Boy's and Girl's Restroom behind IMC	No	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	2	Pipe Chase between Boy's and Girl's Restroom behind IMC	No	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	2	Pipe Chase between Boy's and Girl's Restroom behind IMC	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	2	Pipe Chase between Boy's and Girl's Restroom behind IMC	No	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	2	Pipe Chase between Boy's and Girl's Restroom behind IMC	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	Pipe Chase between Boy's and Girl's Restroom behind IMC	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	Girl's Restroom behind IMC	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	
1	2	Girl's Restroom behind IMC	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	
1	2	Girl's Restroom behind IMC	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	
1	2	Girl's Restroom behind IMC	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	
1	2	Girl's Restroom behind IMC	Yes	Ceiling	Plaster	White	None	0	0.3	Negative		0	N/A						
1	2	Girl's Restroom behind IMC	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	Girl's Restroom behind IMC	Yes	Door Casing	Metal	Gray	None	0	0	Negative		0	N/A						
1	2	Hallway from IMC to Stairwell 4	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative						
1	2	Hallway from IMC to Stairwell 4	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative						
1	2	Hallway from IMC to Stairwell 4	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative						
1	2	Hallway from IMC to Stairwell 4	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative						
1	2	Hallway from IMC to Stairwell 4	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	Hallway from IMC to Stairwell 4	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	Hallway from IMC to Stairwell 4	Yes	Window Sill	Concrete	Gray	None	0	0.2	Negative		0	N/A						
1	2	Hallway from IMC to Stairwell 4	Yes	Door Casing	Metal	Gray	None	0	0	Negative		0	N/A						
1	2	Hallway from IMC to Stairwell 4	Yes	Door Casing	Metal	Gray	None	0	0	Negative		0	N/A						
1	2	Hallway from IMC to Stairwell 4	Yes	Door	Metal	Gray	None	0	0	Negative		0	N/A						
1	2	IMC	Yes	W1	CMU	Beige	None	0	0.1	Negative		0	Negative						
1	2	IMC	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative						
1	2	IMC	Yes	W3	CMU	Beige	None	0	0.1	Negative		0	Negative						
1	2	IMC	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative						
1	2	IMC	Yes	Ceiling	Plaster	White	None	0	0.1	Negative		0	N/A						
1	2	IMC	Yes	Ceiling	Acoustical Plaster	White	None	0	0.1	Negative		0	N/A						
1	2	IMC	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	IMC	Yes	Column	Concrete	Beige	None	0	0.3	Negative		0	Negative						
1	2	IMC	Yes	Door Casing	Metal	Gray	None	0	0.4	Negative		0	N/A						
1	2	IMC	Yes	Window Casing	Metal	Blue	None	0	0	Negative		0	N/A						
1	2	IMC	Yes	Door Casing	Metal	Blue	None	0	0.1	Negative		0	N/A						
1	2	IMC	Yes	Door Casing	Metal	Blue	None	0	0.3	Negative		0	N/A						
1	2	Hallway from IMC to Main Hallway	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	2	Hallway from IMC to Main Hallway	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	2	Hallway from IMC to Main Hallway	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	2	Hallway from IMC to Main Hallway	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	2	Hallway from IMC to Main Hallway	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	Hallway from IMC to Main Hallway	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	IMC Office	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Inaccessible. No one had the key	
1	2	IMC Office	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Inaccessible. No one had the key	
1	2	IMC Office	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Inaccessible. No one had the key	

			School District of Philadelphia																	
			Lead Safe Certification Assessment Report																	
			Name of Inspector: Kristen Masotes		Lingelbach Elementary School								Inspection Dates: 8/17/21 - 8/19/21							
Inspection Company: Acer Associates										ULCS# 6440										
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
1	2	IMC Office	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Inaccessible. No one had the key		
1	2	IMC Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Inaccessible. No one had the key		
1	2	IMC Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Inaccessible. No one had the key		
1	2	Classroom 300	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative							
1	2	Classroom 300	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative							
1	2	Classroom 300	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative							
1	2	Classroom 300	Yes	W4	CMU	Beige	None	0	0.5	Negative		0	Negative							
1	2	Classroom 300	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	2	Classroom 300	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	2	Classroom 301	Yes	W1	Concrete/CMU	Black/Beige	None	0	0	Negative		0	Negative							
1	2	Classroom 301	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative							
1	2	Classroom 301	Yes	W3	CMU	Beige	None	0	0.1	Negative		0	Negative							
1	2	Classroom 301	Yes	W4	CMU	Beige	None	0	0.1	Negative		0	Negative							
1	2	Classroom 301	Yes	Ceiling	Plaster	White	None	0	0.1	Negative		0	N/A							
1	2	Classroom 301	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	2	Classroom 301	Yes	Closet Door	Wood	Green	None	0	0.1	Negative		0	N/A							
1	2	Classroom 301	Yes	Closet Door	Wood	Green	None	0	0.1	Negative		0	N/A							
1	2	Classroom 301	Yes	Column	Concrete	Beige	None	0	0	Negative		0	Negative							
1	2	Classroom 302	Yes	W1	CMU	Beige	None	0	0.1	Negative		0	Negative							
1	2	Classroom 302	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative							
1	2	Classroom 302	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative							
1	2	Classroom 302	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative							
1	2	Classroom 302	Yes	Ceiling	Plaster	White	None	0	0.1	Negative		0	N/A							
1	2	Classroom 302	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	2	Classroom 302	Yes	Closet Door	Wood	Black	None	0	0.1	Negative		0	N/A							
1	2	Classroom 302	Yes	Closet Door	Wood	Black	None	0	0.1	Negative		0	N/A							
1	2	Classroom 302	Yes	Column	Concrete	Black	None	0	0.2	Negative		0	Negative							
1	2	Classroom 303	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative							
1	2	Classroom 303	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative							
1	2	Classroom 303	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative							
1	2	Classroom 303	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative							
1	2	Classroom 303	Yes	Ceiling	Plaster	White	None	0	0.1	Negative		0	N/A							
1	2	Classroom 303	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	2	Classroom 303	Yes	Closet Door	Wood	Green	None	0	0.2	Negative		0	N/A							
1	2	Classroom 303	Yes	Closet Door	Wood	Green	None	0	0.1	Negative		0	N/A							
1	2	2nd Floor Women's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile		
1	2	2nd Floor Women's Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile		
1	2	2nd Floor Women's Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile		
1	2	2nd Floor Women's Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile		
1	2	2nd Floor Women's Restroom	Yes	Ceiling	Plaster	White	None	0	0.3	Negative		0	N/A							
1	2	2nd Floor Women's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	2	2nd Floor Women's Restroom	Yes	Radiator	Metal	Gray	None	0	0.2	Negative		0	N/A							
1	2	2nd Floor Women's Restroom	Yes	Door Casing	Metal	Gray	None	0	0.1	Negative		0	N/A							
1	2	Pipe Chase between 2nd Floor Men's and Women's Restrooms	No	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative							
1	2	Pipe Chase between 2nd Floor Men's and Women's Restrooms	No	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative							
1	2	Pipe Chase between 2nd Floor Men's and Women's Restrooms	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative							
1	2	Pipe Chase between 2nd Floor Men's and Women's Restrooms	No	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative							
1	2	Pipe Chase between 2nd Floor Men's and Women's Restrooms	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	2	Pipe Chase between 2nd Floor Men's and Women's Restrooms	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	2	2nd Floor Men's Restroom	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile		
1	2	2nd Floor Men's Restroom	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile		
1	2	2nd Floor Men's Restroom	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile		
1	2	2nd Floor Men's Restroom	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile		
1	2	2nd Floor Men's Restroom	Yes	Ceiling	Plaster	White	Flaking	1	0.3	Negative	None	0	N/A	No	No	No	No			
1	2	2nd Floor Men's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	2	2nd Floor Men's Restroom	Yes	Door Casing	Metal	Gray	None	0	0.1	Negative		0	N/A							
1	2	2nd Floor Men's Restroom	Yes	Radiator	Metal	Gray	None	0	0.1	Negative		0	N/A							
1	2	Teacher's Lounge 303A	Yes	W1	CMU	Green	None	0	0	Negative		0	Negative							
1	2	Teacher's Lounge 303A	Yes	W1	Drywall	Green	None	0	0.1	Negative		0	Negative							
1	2	Teacher's Lounge 303A	Yes	W2	CMU	Green	None	0	0	Negative		0	Negative							
1	2	Teacher's Lounge 303A	Yes	W3	CMU	Beige	Flaking	1	0	Negative	None	0	Negative	No	No	No	No			
1	2	Teacher's Lounge 303A	Yes	W4	CMU	Green	None	0	0	Negative		0	Negative							
1	2	Teacher's Lounge 303A	Yes	W4	Drywall	Green	None	0	0.1	Negative		0	Negative							
1	2	Teacher's Lounge 303A	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	2	Teacher's Lounge 303A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	2	Teacher's Lounge 303A	Yes	Door Casing	Metal	Gray	None	0	0.4	Negative		0	N/A							

Element		Floor		School District of Philadelphia														
				Lead Safe Certification Assessment Report														
				Name of Inspector: Kristen Masotes			Lingelbach Elementary School							Inspection Dates: 8/17/21 - 8/19/21				
Inspection Company: Acer Associates										ULCS# 6440								
		On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	2	Teacher's Lounge 303A	Yes	Door Transom	Concrete	Green	None	0	0.1	Negative		0	N/A					
1	2	Teacher's Lounge 303A	Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A					
1	2	Teacher's Lounge 303A	Yes	Door Casing	Metal	Brown	None	0	0	Negative		0	N/A					
1	2	Teacher's Lounge 303A Telecommunication Equipment Room	No	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
1	2	Teacher's Lounge 303A Telecommunication Equipment Room	No	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
1	2	Teacher's Lounge 303A Telecommunication Equipment Room	No	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
1	2	Teacher's Lounge 303A Telecommunication Equipment Room	No	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
1	2	Teacher's Lounge 303A Telecommunication Equipment Room	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	2	Teacher's Lounge 303A Telecommunication Equipment Room	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	2	Classroom 304	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative					
1	2	Classroom 304	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative					
1	2	Classroom 304	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative					
1	2	Classroom 304	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative					
1	2	Classroom 304	Yes	Ceiling	Concrete	White	cracks	3	0.4	Negative	None	0	Negative	No	No	No	No	
1	2	Classroom 304	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	2	Classroom 304	Yes	Door Casing	Metal	Gray	None	0	0.4	Negative		0	N/A					
1	2	Classroom 305	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative					
1	2	Classroom 305	Yes	W2	CMU	Beige	None	0	0.1	Negative		0	Negative					
1	2	Classroom 305	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative					
1	2	Classroom 305	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative					
1	2	Classroom 305	Yes	Ceiling	Plaster	White	None	0	0	Negative		0	N/A					
1	2	Classroom 305	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	2	Classroom 306	Yes	W1	Concrete	Beige/Black	None	0	0	Negative		0	Negative					
1	2	Classroom 306	Yes	W2	CMU	Beige	None	0	0.1	Negative		0	Negative					
1	2	Classroom 306	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative					
1	2	Classroom 306	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative					
1	2	Classroom 306	Yes	Ceiling	Concrete	White	None	0	0.3	Negative		0	Negative					
1	2	Classroom 306	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	2	Classroom 306	Yes	Door Transom	Concrete	White	None	0	0.4	Negative		0	N/A					
1	2	Classroom 306	Yes	Door Casing	Metal	Gray	None	0	0.4	Negative		0	N/A					
1	2	Storage Room adjacent to 2nd Floor Fan Room - Roof Drain	No	W1	CMU	Tan	None	0	0.1	Negative		0	Negative					
1	2	Storage Room adjacent to 2nd Floor Fan Room - Roof Drain	No	W2	Brick	Tan	Flaking	8	0.2	Negative	None	0	Negative	No	No	No	No	
1	2	Storage Room adjacent to 2nd Floor Fan Room - Roof Drain	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	2	Storage Room adjacent to 2nd Floor Fan Room - Roof Drain	No	W4	CMU	Tan	None	0	0	Negative		0	Negative					
1	2	Storage Room adjacent to 2nd Floor Fan Room - Roof Drain	No	Ceiling	Concrete	White	None	0	0.2	Negative		0	Negative					
1	2	Storage Room adjacent to 2nd Floor Fan Room - Roof Drain	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	2	Storage Room adjacent to 2nd Floor Fan Room	No	W1	CMU	Tan	None	0	0.1	Negative		0	Negative					
1	2	Storage Room adjacent to 2nd Floor Fan Room	No	W2	Brick	Tan	None	0	0.2	Negative		0	Negative					
1	2	Storage Room adjacent to 2nd Floor Fan Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	2	Storage Room adjacent to 2nd Floor Fan Room	No	W4	CMU	Tan	None	0	0	Negative		0	Negative					
1	2	Storage Room adjacent to 2nd Floor Fan Room	No	Ceiling	Concrete	White	None	0	0.2	Negative		0	Negative					
1	2	Storage Room adjacent to 2nd Floor Fan Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	2	Storage Room adjacent to 2nd Floor Fan Room	No	Pipe	Metal	Tan	None	0	0.4	Negative		0	N/A					
1	2	Storage Room adjacent to 2nd Floor Fan Room	No	Column	Concrete	Tan	None	0	0.2	Negative		0	Negative					
1	2	Boy's Restroom across from Classroom 306	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	2	Boy's Restroom across from Classroom 306	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	2	Boy's Restroom across from Classroom 306	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	2	Boy's Restroom across from Classroom 306	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	2	Boy's Restroom across from Classroom 306	Yes	Ceiling	Plaster	White	None	0	0.4	Negative		0	N/A					
1	2	Boy's Restroom across from Classroom 306	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	2	Boy's Restroom across from Classroom 306	Yes	Pipe Chase Door	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	2	Boy's Restroom across from Classroom 306	Yes	Stall door Support	Metal	Blue	None	0	0.2	Negative		0	N/A					
1	2	Boy's Restroom across from Classroom 306	Yes	Radiator	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	2	Boy's Restroom across from Classroom 306	Yes	Mirror Casing	Wood	Gray	None	0	0.3	Negative		0	N/A					
1	2	Boy's Restroom across from Classroom 306	Yes	Door Casing	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	2	Girl's Restroom across from Classroom 306	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	2	Girl's Restroom across from Classroom 306	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	2	Girl's Restroom across from Classroom 306	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	2	Girl's Restroom across from Classroom 306	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	2	Girl's Restroom across from Classroom 306	Yes	Ceiling	Plaster	White	Flaking	1	0.3	Negative	None	0	N/A	No	No	No	No	

			School District of Philadelphia																
			Lead Safe Certification Assessment Report													Inspection Dates: 8/17/21 - 8/19/21			
			Lingelbach Elementary School																
Name of Inspector: Kristen Masotes			Inspection Company: Acer Associates									ULCS# 6440							
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	2	Girl's Restroom across from Classroom 306	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	Girl's Restroom across from Classroom 306	Yes	Door Casing	Metal	Gray	None	0	0	Negative		0	N/A						
1	2	Girl's Restroom across from Classroom 306	Yes	Stall door Support	Metal	Green	None	0	0.3	Negative		0	N/A						
1	2	Girl's Restroom across from Classroom 306	Yes	Radiator	Metal	Gray	None	0	0.2	Negative		0	N/A						
1	2	Girl's Restroom across from Classroom 306	Yes	Mirror Casing	Wood	Gray	None	0	0	Negative		0	N/A						
1	2	Girl's Restroom across from Classroom 306 Pipe Chase	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	2	Girl's Restroom across from Classroom 306 Pipe Chase	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	2	Girl's Restroom across from Classroom 306 Pipe Chase	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	2	Girl's Restroom across from Classroom 306 Pipe Chase	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	2	Girl's Restroom across from Classroom 306 Pipe Chase	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	Girl's Restroom across from Classroom 306 Pipe Chase	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	2nd Floor Fan Room across from Classrooms 305 & 306	No	W1	CMU	Yellow	None	0	0	Negative		0	Negative						
1	2	2nd Floor Fan Room across from Classrooms 305 & 306	No	W2	Brick	Yellow	None	0	0	Negative		0	Negative						
1	2	2nd Floor Fan Room across from Classrooms 305 & 306	No	W3	Concrete	Yellow	Efflorescence	16	0	Negative	None	0	Negative	No	Unknown	No	No		
1	2	2nd Floor Fan Room across from Classrooms 305 & 306	No	W4	CMU	Yellow	None	0	0.5	Negative		0	Negative						
1	2	2nd Floor Fan Room across from Classrooms 305 & 306	No	Ceiling	Concrete	White	None	0	0.4	Negative		0	Negative						
1	2	2nd Floor Fan Room across from Classrooms 305 & 306	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	2nd Floor Fan Room across from Classrooms 305 & 306	No	Door	Metal	Brown	None	0	0.1	Negative		0	N/A						
1	2	2nd Floor Fan Room across from Classrooms 305 & 306	No	Door Casing	Metal	Brown	None	0	0.4	Negative		0	N/A						
1	2	2nd Floor Fan Room across from Classrooms 305 & 306	No	Fan Unit	Metal	Yellow	None	0	0.1	Negative		0	N/A						
1	2	2nd Floor Fan Room across from Classrooms 305 & 306	No	Pipe	Metal	Yellow	None	0	0	Negative		0	N/A						
1	1	Stairwell 1	Yes	W1	CMU	Beige	None	0	0.1	Negative		0	Negative						
1	1	Stairwell 1	Yes	W2	CMU	Beige	None	0	0.1	Negative		0	Negative						
1	1	Stairwell 1	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative						
1	1	Stairwell 1	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative						
1	1	Stairwell 1	Yes	Ceiling	Plaster	White	Flaking	11	0.4	Negative	None	0	N/A	No	No	No	No		
1	1	Stairwell 1	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	1	Stairwell 1	Yes	Stairs - Newell Post	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1	Stairwell 1	Yes	Stairs - Stringer	Metal	Gray	None	0	0.2	Negative		0	N/A						
1	1	Stairwell 1	Yes	Stairs - Riser	Metal	Gray	None	0	0.2	Negative		0	N/A						
1	1	Stairwell 1	Yes	Univent	Metal	Gray	None	0	0	Negative		0	N/A						
1	1	Stairwell 1	Yes	Pipe Jacket	Metal	Beige	None	0	0.1	Negative		0	N/A						
1	1	Stairwell 1	Yes	Door	Metal	Gray	None	0	0.2	Negative		0	N/A						
1	2	Hallway outside Classrooms 301-306	Yes	Window Sill	Concrete	Gray	None	0	0.2	Negative		0	N/A						
1	2	Hallway outside Classrooms 301-306	Yes	W2	CMU	Purple	None	0	0.1	Negative		0	Negative						
1	2	Hallway outside Classrooms 301-306	Yes	W3	CMU	Purple	None	0	0	Negative		0	Negative						
1	2	Hallway outside Classrooms 301-306	Yes	W4	CMU	Purple	None	0	0	Negative		0	Negative						
1	2	Hallway outside Classrooms 301-306	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	Hallway outside Classrooms 301-306	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	2	Hallway outside Classrooms 301-306	Yes	Door Casing	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	2	Hallway outside Classrooms 301-306	Yes	Door	Metal	Gray	None	0	0	Negative		0	N/A						
1	2	Hallway outside Classrooms 301-306	Yes	Door	Metal	Gray	None	0	0.4	Negative		0	N/A						
1	2	Hallway outside Classrooms 301-306	Yes	Radiator	Metal	Gray	None	0	0.2	Negative		0	N/A						
1	2	Hallway outside Classrooms 301-306	Yes	Door	Metal	Gray	None	0	0	Negative		0	N/A						
1	2	Hallway outside Classrooms 301-306	Yes	Door Casing	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1	Stairwell 2	Yes	W1	CMU	Beige	Efflorescence	20	0	Negative	None	0	Negative	No	Unknown	No	No		
1	1	Stairwell 2	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative						
1	1	Stairwell 2	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative						
1	1	Stairwell 2	Yes	W4	CMU	Beige	Efflorescence	20	0.1	Negative	None	0	Negative	No	Unknown	No	No		
1	1	Stairwell 2	Yes	Ceiling	Plaster	White	None	0	0	Negative		0	N/A						
1	1	Stairwell 2	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	1	Stairwell 2	Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A						
1	1	Stairwell 2	Yes	Door	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1	Stairwell 2	Yes	Stairs - Newell Post	Metal	Gray	None	0	0.2	Negative		0	N/A						
1	1	Stairwell 2	Yes	Stairs - Stringer	Metal	Gray	None	0	0.2	Negative		0	N/A						
1	1	Stairwell 2	Yes	Stairs - Riser	Metal	Gray	None	0	0.2	Negative		0	N/A						

			School District of Philadelphia																	
			Lead Safe Certification Assessment Report									Inspection Dates: 8/17/21 - 8/19/21								
			Lingelbach Elementary School									ULCS# 6440								
E l e m e n t	F l o o r		On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1		Stairwell 2	Yes	Univent	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Stairwell 2	Yes	Pipe Jacket	Metal	Beige	None	0	0.2	Negative		0	N/A						
1	1		Stairwell 2	Yes	Stairs - Riser	Metal	Gray	None	0	0	Negative		0	N/A						
1	1		Stairwell 2	Yes	Stairs - Stringer	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Stairwell 3	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Stairwell 3	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Stairwell 3	Yes	W3	CMU	Beige	Flaking	2	0.1	Negative	None	0	Negative	No	No	No	No		
1	1		Stairwell 3	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Stairwell 3	Yes	Ceiling	Plaster	White	None	0	0	Negative		0	N/A						
1	1		Stairwell 3	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	1		Stairwell 3	Yes	Stairs - Stringer	Metal	Gray	None	0	0.2	Negative		0	N/A						
1	1		Stairwell 3	Yes	Stairs - Riser	Metal	Gray	None	0	0.4	Negative		0	N/A						
1	1		Stairwell 3	Yes	Door	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Stairwell 3	Yes	Univent	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Stairwell 3	Yes	Stairs - Railing	Metal	Gray	None	0	0.2	Negative		0	N/A						
1	1		Classroom 200	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 200	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 200	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 200	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	1		Classroom 200	Yes	Ceiling	Concrete	White	None	0	0.3	Negative		0	Negative						
1	1		Classroom 200	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	1		Classroom 200	Yes	Column	Concrete	Beige	None	0	0.2	Negative		0	Negative						
1	1		Classroom 200	Yes	Column	Concrete	Beige	Flaking	1	0	Negative	None	0	Negative	No	No	No	No		
1	1		Classroom 200	Yes	Column	Concrete	Beige	Flaking	3	0.1	Negative	None	0	Negative	No	No	No	No		
1	1		Classroom 200	Yes	Column	Concrete	Beige	None	0	0.2	Negative		0	Negative						
1	1		Classroom 200	Yes	Univent	Metal	Gray	None	0	0	Negative		0	N/A						
1	1		Classroom 200	Yes	Door Casing	Wood	Gray	None	0	0.1	Negative		0	N/A						
1	1		Classroom 200A	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 200A	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 200A	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 200A	Yes	W4	CMU	Beige	None	0	0.2	Negative		0	Negative						
1	1		Classroom 200A	Yes	Ceiling	Concrete	White	None	0	0.3	Negative		0	Negative						
1	1		Classroom 200A	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	1		Classroom 200A	Yes	Column	Concrete	Beige	None	0	0.3	Negative		0	Negative						
1	1		Classroom 200A	Yes	Column	Concrete	Beige	None	0	0.1	Negative		0	Negative						
1	1		Classroom 200A	Yes	Door	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Classroom 200A	Yes	Door Casing	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Classroom 200A	Yes	Door Casing	Metal	Gray	None	0	0.4	Negative		0	N/A						
1	1		Classroom 200A	Yes	Door	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Classroom 200A	Yes	Door	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Classroom 200A Teacher Restroom	Yes	W1	CMU	Beige	None	0	0.1	Negative		0	Negative						
1	1		Classroom 200A Teacher Restroom	Yes	W2	CMU	Beige	None	0	0.4	Negative		0	Negative						
1	1		Classroom 200A Teacher Restroom	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 200A Teacher Restroom	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 200A Teacher Restroom	Yes	Ceiling	Concrete	White	None	0	0.1	Negative		0	Negative						
1	1		Classroom 200A Teacher Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	1		Classroom 200A Teacher Restroom	Yes	Shelf	Wood	Green	None	0	1.2	Positive		0	N/A						
1	1		Classroom 200A Teacher Restroom	Yes	Door Casing	Metal	Gray	None	0	0.4	Negative		0	N/A						
1	1		Classroom 200/200A Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access		
1	1		Classroom 200/200A Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access		
1	1		Classroom 200/200A Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access		
1	1		Classroom 200/200A Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access		
1	1		Classroom 200/200A Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access		
1	1		Classroom 200/200A Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access		
1	1		Classroom 200/200A Restroom	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 200/200A Restroom	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 200/200A Restroom	Yes	W3	CMU	Beige/Gray	None	0	0.3	Negative		0	Negative						
1	1		Classroom 200/200A Restroom	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 200/200A Restroom	Yes	Ceiling	Concrete	White	None	0	0.4	Negative		0	Negative						
1	1		Classroom 200/200A Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	1		Classroom 200/200A Restroom	Yes	Door Casing	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Classroom 200/200A Restroom	Yes	Door Casing	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Classroom 200/200A Restroom	Yes	Pipe	Metal	White	None	0	0	Negative		0	N/A						
1	1		Classroom 200/200A Restroom	Yes	Radiator	Metal	Gray	None	0	0.2	Negative		0	N/A						
1	1		Classroom 200/200A Restroom	Yes	Pipe Jacket	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Classroom 200/200A Restroom	Yes	Duct	Metal	Beige	None	0	0.1	Negative		0	N/A						
1	1		Classroom 201	Yes	W1	CMU	Beige	None	0	0.4	Negative		0	Negative						
1	1		Classroom 201	Yes	W2	CMU	Beige	None	0	0.4	Negative		0	Negative						
1	1		Classroom 201	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	1		Classroom 201	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 201	Yes	Ceiling	Concrete	White	None	0	0	Negative		0	Negative						

			School District of Philadelphia																	
			Lead Safe Certification Assessment Report									Inspection Dates: 8/17/21 - 8/19/21								
			Lingelbach Elementary School									ULCS# 6440								
Element	Floor		On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	1		Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	1		Classroom 201	Yes	Column	Concrete	Beige	None	0	0.2	Negative		0	Negative						
1	1		Classroom 201	Yes	Column	Concrete	Beige	None	0	0.3	Negative		0	Negative						
1	1		Classroom 201	Yes	Column	Concrete	Beige	None	0	0.3	Negative		0	Negative						
1	1		Classroom 201	Yes	Univent	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Classroom 201	Yes	Door Casing	Wood	Gray	None	0	0.4	Negative		0	N/A						
1	1		Classroom 202	Yes	W1	CMU	Beige	None	0	0.3	Negative		0	Negative						
1	1		Classroom 202	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 202	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	1		Classroom 202	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 202	Yes	Ceiling	Concrete	White	None	0	0	Negative		0	Negative						
1	1		Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	1		Classroom 202	Yes	Column	Concrete	Beige	None	0	0.1	Negative		0	Negative						
1	1		Classroom 202	Yes	Column	Concrete	Beige	None	0	0.1	Negative		0	Negative						
1	1		Classroom 202	Yes	Column	Concrete	Beige	None	0	0.1	Negative		0	Negative						
1	1		Classroom 202	Yes	Univent	Metal	Gray	None	0	0	Negative		0	N/A						
1	1		Classroom 203	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 203	Yes	W2	CMU	Beige	None	0	0.4	Negative		0	Negative						
1	1		Classroom 203	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	1		Classroom 203	Yes	W4	CMU	Beige	None	0	0.4	Negative		0	Negative						
1	1		Classroom 203	Yes	Ceiling	Concrete	White	None	0	0.2	Negative		0	Negative						
1	1		Classroom 203	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	1		Classroom 203	Yes	Column	Concrete	Beige	None	0	0.3	Negative		0	Negative						
1	1		Classroom 203	Yes	Column	Concrete	Beige	None	0	0.2	Negative		0	Negative						
1	1		Classroom 203	Yes	Column	Concrete	Beige	None	0	0.2	Negative		0	Negative						
1	1		Classroom 203	Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A						
1	1		Classroom 203	Yes	Univent	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Classroom 204	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 204	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 204	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	1		Classroom 204	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 204	Yes	Ceiling	Concrete	White	None	0	0.4	Negative		0	Negative						
1	1		Classroom 204	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	1		Classroom 204	Yes	Column	Concrete	Beige	None	0	0.2	Negative		0	Negative						
1	1		Classroom 204	Yes	Column	Concrete	Beige	Flaking	2	0.3	Negative	None	0	Negative	No	No	No	No		
1	1		Classroom 204	Yes	Column	Concrete	Beige	Flaking	3	0.2	Negative	None	0	Negative	No	No	No	No		
1	1		Classroom 205	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 205	Yes	W2	CMU	Beige	None	0	0.4	Negative		0	Negative						
1	1		Classroom 205	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	1		Classroom 205	Yes	W4	CMU	Pink/Beige	None	0	0.2	Negative		0	Negative						
1	1		Classroom 205	Yes	Ceiling	Concrete	White	None	0	0.4	Negative		0	Negative						
1	1		Classroom 205	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	1		Classroom 205	Yes	Column	Concrete	Beige	None	0	0.2	Negative		0	Negative						
1	1		Classroom 205	Yes	Column	Concrete	Pink	Chipping	2	0.1	Negative	None	0	Negative	No	No	No	No		
1	1		Classroom 205	Yes	Column	Concrete	Pink	Chipping	2	0.1	Negative	None	0	Negative	No	No	No	No		
1	1		Classroom 205	Yes	Univent	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Classroom 205	Yes	Door Casing	Metal	Gray	None	0	0.4	Negative		0	N/A						
1	1		Classroom 206	Yes	W1	CMU	Beige	None	0	0.4	Negative		0	Negative						
1	1		Classroom 206	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative						
1	1		Classroom 206	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	1		Classroom 206	Yes	W4	CMU	Beige	None	0	0.4	Negative		0	Negative						
1	1		Classroom 206	Yes	Ceiling	Plaster	White	None	0	0.3	Negative		0	N/A						
1	1		Classroom 206	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	1		Classroom 206	Yes	Column	Concrete	Beige	Flaking	1	0.3	Negative	None	0	Negative	No	No	No	No		
1	1		Classroom 206	Yes	Column	Concrete	Beige	Flaking	5	0.3	Negative	None	0	Negative	No	No	No	No		
1	1		Classroom 206	Yes	Door Casing	Metal	Gray	None	0	0.3	Negative		0	N/A						
1	1		Classroom 206	Yes	Univent	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Girl's Restroom across from Classroom 206	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	
1	1		Girl's Restroom across from Classroom 206	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	
1	1		Girl's Restroom across from Classroom 206	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	
1	1		Girl's Restroom across from Classroom 206	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	
1	1		Girl's Restroom across from Classroom 206	Yes	Ceiling	Plaster	White	Flaking	5	0.2	Negative	None	0	N/A	No	No	No	No		
1	1		Girl's Restroom across from Classroom 206	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	1		Girl's Restroom across from Classroom 206	Yes	Radiator	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Girl's Restroom across from Classroom 206	Yes	Stall Wall	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	1		Girl's Restroom across from Classroom 206	Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A						
1	1		Girl's Restroom across from Classroom 206	Yes	Door	Wood	Gray	None	0	0	Negative		0	N/A						
1	1		Boy's Restroom outside Gym/Cafeteria	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	
1	1		Boy's Restroom outside Gym/Cafeteria	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	
1	1		Boy's Restroom outside Gym/Cafeteria	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	
1	1		Boy's Restroom outside Gym/Cafeteria	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile	

			School District of Philadelphia																			
			Lead Safe Certification Assessment Report																Inspection Dates: 8/17/21 - 8/19/21			
			Lingelbach Elementary School																ULCS# 6440			
Element	Floor	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes				
1	1	Boy's Restroom outside Gym/Cafeteria	Yes	Ceiling	Plaster	White	None	0	0	Negative		0	N/A									
1	1	Boy's Restroom outside Gym/Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A									
1	1	Boy's Restroom outside Gym/Cafeteria	Yes	Door	Wood	Gray	None	0	0.1	Negative		0	N/A									
1	1	Boy's Restroom outside Gym/Cafeteria	Yes	Door Casing	Metal	Gray	None	0	0.1	Negative		0	N/A									
1	1	Boy's Restroom outside Gym/Cafeteria	Yes	Pipe Shaft Door	Metal	Blue	rusting	10	0	Negative	None	0	N/A	No	No	No	No					
1	1	Boy's Restroom outside Gym/Cafeteria	Yes	Stall Wall	Metal	Gray	None	0	0	Negative		0	N/A									
1	1	Boy's Restroom outside Gym/Cafeteria	Yes	Radiator	Metal	Gray	None	0	0.1	Negative		0	N/A									
1	1	Boy's Restroom outside Gym/Cafeteria	Yes	Pipe Jacket	Metal	White	None	0	0.1	Negative		0	N/A									
1	1	Boy's Restroom outside Gym/Cafeteria Pipe Chase	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative									
1	1	Boy's Restroom outside Gym/Cafeteria Pipe Chase	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative									
1	1	Boy's Restroom outside Gym/Cafeteria Pipe Chase	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative									
1	1	Boy's Restroom outside Gym/Cafeteria Pipe Chase	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative									
1	1	Boy's Restroom outside Gym/Cafeteria Pipe Chase	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A									
1	1	Boy's Restroom outside Gym/Cafeteria Pipe Chase	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A									
1	1	Storage Room across from Boy's Restroom outside Cafetorium	No	W1	CMU	Yellow	None	0	0	Negative		0	Negative									
1	1	Storage Room across from Boy's Restroom outside Cafetorium	No	W2	CMU	Yellow	None	0	0.3	Negative		0	Negative									
1	1	Storage Room across from Boy's Restroom outside Cafetorium	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative									
1	1	Storage Room across from Boy's Restroom outside Cafetorium	No	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative									
1	1	Storage Room across from Boy's Restroom outside Cafetorium	No	Ceiling	Concrete	White	None	0	0.6	Negative		0	Negative									
1	1	Storage Room across from Boy's Restroom outside Cafetorium	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A									
1	1	Storage Room across from Boy's Restroom outside Cafetorium	No	Column	Concrete	Yellow	None	0	0.2	Negative		0	Negative									
1	1	Storage Room across from Boy's Restroom outside Cafetorium	No	Column	Concrete	Yellow	None	0	0	Negative		0	Negative									
1	1	Storage Room across from Boy's Restroom outside Cafetorium	No	Column	Concrete	Yellow	None	0	0	Negative		0	Negative									
1	1	Gym/Cafeteria	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative									
1	1	Gym/Cafeteria	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative									
1	1	Gym/Cafeteria	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative									
1	1	Gym/Cafeteria	Yes	W4	CMU	Beige	None	0	0.4	Negative		0	Negative									
1	1	Gym/Cafeteria	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A									
1	1	Gym/Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A									
1	1	Gym/Cafeteria	Yes	Door	Wood	Gray	None	0	0	Negative		0	N/A									
1	1	Gym/Cafeteria	Yes	Door Casing	Metal	Gray	None	0	0.6	Negative		0	N/A									
1	1	Gym/Cafeteria	Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A									
1	1	Gym/Cafeteria	Yes	Door	Wood	Gray	None	0	0.1	Negative		0	N/A									
1	1	Gym/Cafeteria	Yes	Vent	Metal	Gray	None	0	0.1	Negative		0	N/A									
1	1	Gym/Cafeteria	Yes	Lunch Table Hideaway Casing	Metal	Gray	None	0	0.4	Negative		0	N/A									
1	1	Gym/Cafeteria	Yes	Lunch Table Hideaway Casing	Metal	Gray	None	0	0.4	Negative		0	N/A									
1	1	Gym Office	Yes	W1	CMU	Beige	None	0	0.4	Negative		0	Negative									
1	1	Gym Office	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative									
1	1	Gym Office	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Inaccessible due to items stored				
1	1	Gym Office	Yes	W4	CMU	Beige	None	0	0.4	Negative		0	Negative									
1	1	Gym Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					Inaccessible due to items stored				
1	1	Gym Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					Floor Tile				
1	1	School Psychologist Office adjacent to Entrances to Gym and Stage	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access					
1	1	School Psychologist Office adjacent to Entrances to Gym and Stage	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access					
1	1	School Psychologist Office adjacent to Entrances to Gym and Stage	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access					
1	1	School Psychologist Office adjacent to Entrances to Gym and Stage	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access					
1	1	School Psychologist Office adjacent to Entrances to Gym and Stage	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access					
1	1	School Psychologist Office adjacent to Entrances to Gym and Stage	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access					
1	1	Kitchen	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile				
1	1	Kitchen	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile				
1	1	Kitchen	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile				
1	1	Kitchen	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile				
1	1	Kitchen	Yes	Ceiling	Concrete	White	None	0	0.2	Negative		0	Negative									
1	1	Kitchen	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A									
1	1	Kitchen	Yes	Door	Metal	Gray	None	0	0.4	Negative		0	N/A									
1	1	Kitchen	Yes	Door Casing	Metal	Gray	None	0	0.1	Negative		0	N/A									

		School District of Philadelphia																	
		Lead Safe Certification Assessment Report									Inspection Dates: 8/17/21 - 8/19/21								
		Lingelbach Elementary School									ULCS# 6440								
Element	Floor			Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
		On-Site Room Name																	
1	1	Kitchen Office		Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	1	Kitchen Office		Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	1	Kitchen Office		Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	1	Kitchen Office		Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	1	Kitchen Office		Yes	Ceiling	Concrete	White	None	0	0.4	Negative		0	Negative					
1	1	Kitchen Office		Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Storage Room adjacent to Kitchen and Gym/Cafeteria		No	W1	CMU	Beige	None	0	0.1	Negative		0	Negative					
1	1	Storage Room adjacent to Kitchen and Gym/Cafeteria		No	W2	Brick	Beige	None	0	0.2	Negative		0	Negative					
1	1	Storage Room adjacent to Kitchen and Gym/Cafeteria		No	W3	CMU	Beige	None	0	0	Negative		0	Negative					
1	1	Storage Room adjacent to Kitchen and Gym/Cafeteria		No	W4	CMU	Beige	None	0	0.1	Negative		0	Negative					
1	1	Storage Room adjacent to Kitchen and Gym/Cafeteria		No	Ceiling	Concrete	White	None	0	0.1	Negative		0	Negative					
1	1	Storage Room adjacent to Kitchen and Gym/Cafeteria		No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Storage Room adjacent to Kitchen and Gym/Cafeteria		No	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A					
1	1	Storage Room adjacent to Kitchen and Gym/Cafeteria		No	Door Casing	Metal	Gray	None	0	0.2	Negative		0	N/A					
1	1	Storage Room adjacent to Kitchen and Gym/Cafeteria		No	W1- Baseboard	Vinyl	Gray	None	0	0	Negative		0	N/A					
1	1	Storage Room adjacent to Kitchen and Gym/Cafeteria		No	W2- Baseboard	Vinyl	Gray	None	0	0.1	Negative		0	N/A					
1	1	Storage Room adjacent to Kitchen and Gym/Cafeteria		No	W3- Baseboard	Vinyl	Gray	None	0	0	Negative		0	N/A					
1	1	Storage Room adjacent to Kitchen and Gym/Cafeteria		No	W4- Baseboard	Vinyl	Gray	None	0	0	Negative		0	N/A					
1	1	Auditorium		Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Auditorium		Yes	W2	CMU	White	None	0	0	Negative		0	Negative					
1	1	Auditorium		Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Auditorium		Yes	W4	CMU	White	None	0	0.4	Negative		0	Negative					
1	1	Auditorium		Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Auditorium		Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Auditorium		Yes	Door Casing	Metal	Gray	None	0	0.2	Negative		0	N/A					
1	1	Auditorium Stage		Yes	W1	CMU	White	None	0	0.2	Negative		0	Negative					
1	1	Auditorium Stage		Yes	W2	CMU	White	None	0	0.4	Negative		0	Negative					
1	1	Auditorium Stage		Yes	W3	CMU	White	None	0	0.3	Negative		0	Negative					
1	1	Auditorium Stage		Yes	W4	CMU	White	None	0	0.3	Negative		0	Negative					
1	1	Auditorium Stage		Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Auditorium Stage		Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Auditorium Stage		Yes	Door	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	1	Auditorium Stage		Yes	Door	Metal	Gray	None	0	0	Negative		0	N/A					
1	1	Auditorium Stage		Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A					
1	1	Auditorium Stage		Yes	Door Casing	Metal	Gray	None	0	0.3	Negative		0	N/A					
1	1	Auditorium Stage		Yes	Door	Metal	Gray	None	0	0	Negative		0	N/A					
1	1	Auditorium Stage		Yes	W1- Baseboard	Metal	Gray	None	0	0	Negative		0	N/A					
1	1	Auditorium Stage		Yes	W2- Baseboard	Metal	Gray	None	0	0	Negative		0	N/A					
1	1	Auditorium Stage		Yes	W3- Baseboard	Metal	Gray	None	0	0.3	Negative		0	N/A					
1	1	Auditorium Stage		Yes	W4- Baseboard	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	1	Custodial Closet adjacent to Men's Restroom across from Stage Entrance		No	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Custodial Closet adjacent to Men's Restroom across from Stage Entrance		No	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Custodial Closet adjacent to Men's Restroom across from Stage Entrance		No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Custodial Closet adjacent to Men's Restroom across from Stage Entrance		No	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Custodial Closet adjacent to Men's Restroom across from Stage Entrance		No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Custodial Closet adjacent to Men's Restroom across from Stage Entrance		No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Men's Restroom across from Stage Entrance		Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative					
1	1	Men's Restroom across from Stage Entrance		Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative					
1	1	Men's Restroom across from Stage Entrance		Yes	W3	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	1	Men's Restroom across from Stage Entrance		Yes	W4	CMU	Beige	None	0	0.3	Negative		0	Negative					
1	1	Men's Restroom across from Stage Entrance		Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Couldn't bring a ladder into room because of items stored
1	1	Men's Restroom across from Stage Entrance		Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Men's Restroom across from Stage Entrance		Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A					
1	1	MDF Computer Equipment Room adjacent to Reading Room		No	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
1	1	MDF Computer Equipment Room adjacent to Reading Room		No	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
1	1	MDF Computer Equipment Room adjacent to Reading Room		No	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
1	1	MDF Computer Equipment Room adjacent to Reading Room		No	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
1	1	MDF Computer Equipment Room adjacent to Reading Room		No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	1	MDF Computer Equipment Room adjacent to Reading Room		No	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	1	Reading Room		Yes	W1	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	1	Reading Room		Yes	W2	CMU	Beige	None	0	0.4	Negative		0	Negative					



			School District of Philadelphia																	
			Name of Inspector: Kristen Masotes		Lead Safe Certification Assessment Report								Inspection Dates: 8/17/21 - 8/19/21							
			Inspection Company: Acer Associates		Lingelbach Elementary School								ULCS# 6440							
Element	Floor		Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes		
		On-Site Room Name																		
1	1	Reading Room	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative							
1	1	Reading Room	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative							
1	1	Reading Room	Yes	Ceiling	Concrete	White	None	0	0	Negative		0	Negative							
1	1	Reading Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	1	Women's Restroom adjacent to Main Office	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative							
1	1	Women's Restroom adjacent to Main Office	Yes	W2	CMU	Beige	None	0	0.1	Negative		0	Negative							
1	1	Women's Restroom adjacent to Main Office	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative							
1	1	Women's Restroom adjacent to Main Office	Yes	W4	CMU	Beige	None	0	0.3	Negative		0	Negative							
1	1	Women's Restroom adjacent to Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	1	Women's Restroom adjacent to Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	1	Women's Restroom adjacent to Main Office	Yes	Door Casing	Metal	Gray	None	0	0.2	Negative		0	N/A							
1	1	Counselor's Office	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative							
1	1	Counselor's Office	Yes	W2	CMU	Beige	None	0	0.4	Negative		0	Negative							
1	1	Counselor's Office	Yes	W3	CMU	Beige	None	0	0.1	Negative		0	Negative							
1	1	Counselor's Office	Yes	W4	CMU	Beige	None	0	0.4	Negative		0	Negative							
1	1	Counselor's Office	Yes	Ceiling	Concrete	White	None	0	0.3	Negative		0	Negative							
1	1	Counselor's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	1	Counselor's Office	Yes	Radiator	Metal	Gray	None	0	0.1	Negative		0	N/A							
1	1	Counselor's Office	Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A							
1	1	Counselor's Office Closet	No	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access			
1	1	Counselor's Office Closet	No	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access			
1	1	Counselor's Office Closet	No	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access			
1	1	Counselor's Office Closet	No	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access			
1	1	Counselor's Office Closet	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access			
1	1	Counselor's Office Closet	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access			
1	1	Main Office Waiting Area	Yes	W1	CMU	Beige	None	0	0.3	Negative		0	Negative							
1	1	Main Office Waiting Area	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative							
1	1	Main Office Waiting Area	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative							
1	1	Main Office Waiting Area	Yes	W4	CMU	Beige	None	0	0.4	Negative		0	Negative							
1	1	Main Office Waiting Area	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	1	Main Office Waiting Area	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	1	Main Office Waiting Area	Yes	Column	Concrete	Beige	None	0	0.2	Negative		0	Negative							
1	1	Main Office Waiting Area	Yes	Window Casing	Metal	Gray	None	0	0.5	Negative		0	N/A							
1	1	Main Office Secretary Area	Yes	W1	CMU	Beige	None	0	0.3	Negative		0	Negative							
1	1	Main Office Secretary Area	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative							
1	1	Main Office Secretary Area	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative							
1	1	Main Office Secretary Area	Yes	W4	CMU	Beige	None	0	0.4	Negative		0	Negative							
1	1	Main Office Secretary Area	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	1	Main Office Secretary Area	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A							
1	1	Main Office Secretary Area	Yes	Column	Concrete	Beige	None	0	0.2	Negative		0	Negative							
1	1	Main Office Secretary Area	Yes	Window Casing	Metal	Gray	None	0	0.5	Negative		0	N/A							
1	1	Main Office Large Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access			
1	1	Main Office Large Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access			
1	1	Main Office Large Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access			
1	1	Main Office Large Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access			
1	1	Main Office Large Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access			
1	1	Main Office Large Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access			
1	1	Main Office Small Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access			
1	1	Main Office Small Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access			
1	1	Main Office Small Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access			
1	1	Main Office Small Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access			
1	1	Main Office Small Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access			
1	1	Main Office Small Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access			
1	1	Principal's Office	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection		
1	1	Principal's Office	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection		
1	1	Principal's Office	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection		
1	1	Principal's Office	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection		
1	1	Principal's Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection		
1	1	Principal's Office	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection		
1	1	Principal's Office Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection		
1	1	Principal's Office Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection		
1	1	Principal's Office Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection		
1	1	Principal's Office Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection		

			School District of Philadelphia																
			Lead Safe Certification Assessment Report																
			Lingelbach Elementary School																
			Name of Inspector: Kristen Masotes										Inspection Dates: 8/17/21 - 8/19/21						
			Inspection Company: Acer Associates										ULCS# 6440						
E l e m e n t	F l o o r		On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	1		Principal's Office Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection
1	1		Principal's Office Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection
1	1		Principal's Office Restroom	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection
1	1		Principal's Office Restroom	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection
1	1		Principal's Office Restroom	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection
1	1		Principal's Office Restroom	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection
1	1		Principal's Office Restroom	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection
1	1		Principal's Office Restroom	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	Principal was in meetings and on Zoom Calls during the inspection
1	1		Women's Restroom adjacent to Nurse's Office	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative					
1	1		Women's Restroom adjacent to Nurse's Office	Yes	W2	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	1		Women's Restroom adjacent to Nurse's Office	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative					
1	1		Women's Restroom adjacent to Nurse's Office	Yes	W4	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	1		Women's Restroom adjacent to Nurse's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1		Women's Restroom adjacent to Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1		Women's Restroom adjacent to Nurse's Office	Yes	Stall Wall	Transite	Silver	None	0	0.1	Negative		0	N/A					
1	1		Nurse's Office	Yes	W1	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	1		Nurse's Office	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative					
1	1		Nurse's Office	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative					
1	1		Nurse's Office	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative					
1	1		Nurse's Office	Yes	Ceiling	Concrete	White	Flaking	5	0.3	Negative	None	0	Negative	No	No	No	No	
1	1		Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1		Nurse's Office	Yes	Door Casing	Metal	Gray	None	0	0.6	Negative		0	N/A					
1	1		Nurse's Office	Yes	Radiator	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	1		Nurse's Office Room behind Men's Restroom	Yes	W1	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	1		Nurse's Office Room behind Men's Restroom	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative					
1	1		Nurse's Office Room behind Men's Restroom	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative					
1	1		Nurse's Office Room behind Men's Restroom	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative					
1	1		Nurse's Office Room behind Men's Restroom	Yes	Ceiling	Concrete	white	Flaking	10	0.3	Negative	None	0	Negative	No	No	No	No	
1	1		Nurse's Office Room behind Men's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1		Nurse's Office Room behind Men's Restroom	Yes	Radiator	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	1		Nurse's Office Room behind Men's Restroom	Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A					
1	1		Nurse's Office Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
1	1		Nurse's Office Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
1	1		Nurse's Office Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
1	1		Nurse's Office Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Negative	No Access	No Access	No Access	No Access	
1	1		Nurse's Office Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	1		Nurse's Office Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	N/A	No Access	No Access	No Access	No Access	
1	1		Nurse's Office Restroom	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative					
1	1		Nurse's Office Restroom	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative					
1	1		Nurse's Office Restroom	Yes	W3	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	1		Nurse's Office Restroom	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative					
1	1		Nurse's Office Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1		Nurse's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1		Nurse's Office Restroom	Yes	Door Casing	Metal	Gray	None	0	0.3	Negative		0	N/A					
1	1		Men's Restroom adjacent to Nurse's Office	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative					
1	1		Men's Restroom adjacent to Nurse's Office	Yes	W2	CMU	Beige	None	0	0	Negative		0	Negative					
1	1		Men's Restroom adjacent to Nurse's Office	Yes	W3	CMU	Beige	None	0	0	Negative		0	Negative					
1	1		Men's Restroom adjacent to Nurse's Office	Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative					
1	1		Men's Restroom adjacent to Nurse's Office	Yes	Ceiling	Concrete	White	Flaking	2	0.4	Negative	None	0	Negative	No	No	No	No	
1	1		Men's Restroom adjacent to Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1		Men's Restroom adjacent to Nurse's Office	Yes	Radiator	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	1		Men's Restroom adjacent to Nurse's Office	Yes	Door Casing	Metal	Gray	None	0	0.3	Negative		0	N/A					
1	1		Hallway outside Classrooms 201-206	Yes	W1	CMU	Yellow/White	None	0	0.4	Negative		0	Negative					
1	1		Hallway outside Classrooms 201-206	Yes	W2	CMU	Yellow	None	0	0.3	Negative		0	Negative					
1	1		Hallway outside Classrooms 201-206	Yes	W3	CMU	Yellow	None	0	0	Negative		0	Negative					
1	1		Hallway outside Classrooms 201-206	Yes	W4	CMU	Yellow	None	0	0.1	Negative		0	Negative					
1	1		Hallway outside Classrooms 201-206	Yes	Ceiling	Concrete	White	None	0	0	Negative		0	Negative					
1	1		Hallway outside Classrooms 201-206	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1		Hallway outside Classrooms 201-206	Yes	Door Casing	Metal	Gray	None	0	0.2	Negative		0	N/A					
1	1		Hallway outside Classrooms 201-206	Yes	Radiator	Metal	Gray	None	0	0.3	Negative		0	N/A					
1	1		Hallway outside Classrooms 201-206	Yes	Pipe Shaft Door Casing	Metal	Gray	None	0	0.2	Negative		0	N/A					
1	1		Hallway outside Classrooms 201-206	Yes	Vent	Metal	White	None	0	0	Negative		0	N/A					
1	1		Hallway outside Classrooms 201-206	Yes	Door	Metal	Gray	None	0	0	Negative		0	N/A					
1	1		Hallway outside Classrooms 201-206	Yes	Door Casing	Metal	Gray	None	0	0.3	Negative		0	N/A					

		School District of Philadelphia																	
		Lead Safe Certification Assessment Report									Inspection Dates: 8/17/21 - 8/19/21								
		Lingelbach Elementary School									ULCS# 6440								
Element	Floor			Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
		On-Site Room Name																	
1	1	Hallway from Main Entrance to Hallway outside Classrooms 201-206		Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Hallway from Main Entrance to Hallway outside Classrooms 201-206		Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Hallway from Main Entrance to Hallway outside Classrooms 201-206		Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Hallway from Main Entrance to Hallway outside Classrooms 201-206		Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Hallway from Main Entrance to Hallway outside Classrooms 201-206		Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Hallway from Main Entrance to Hallway outside Classrooms 201-206		Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Lobby outside Auditorium		Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Lobby outside Auditorium		Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Lobby outside Auditorium		Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Lobby outside Auditorium		Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Lobby outside Auditorium		Yes	Ceiling	Concrete	White	Flaking	5	0.4	Negative	None	0	Negative	No	No	No	No	
1	1	Lobby outside Auditorium		Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Lobby outside Auditorium		Yes	Column	Concrete	Yellow	None	0	0.3	Negative		0	Negative					
1	1	Lobby outside Auditorium		Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A					
1	1	Lobby outside Auditorium		Yes	Radiator	Metal	Gray	None	0	0	Negative		0	N/A					
1	1	Hallway outside Boy's Restroom and Gym/Cafeteria		Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Hallway outside Boy's Restroom and Gym/Cafeteria		Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Hallway outside Boy's Restroom and Gym/Cafeteria		Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Hallway outside Boy's Restroom and Gym/Cafeteria		Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Hallway outside Boy's Restroom and Gym/Cafeteria		Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Hallway outside Boy's Restroom and Gym/Cafeteria		Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Hallway outside Boy's Restroom and Gym/Cafeteria		Yes	Univent	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	1	Hallway from Gym/Cafeteria to Exterior Entrance		Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Hallway from Gym/Cafeteria to Exterior Entrance		Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Hallway from Gym/Cafeteria to Exterior Entrance		Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Hallway from Gym/Cafeteria to Exterior Entrance		Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Hallway from Gym/Cafeteria to Exterior Entrance		Yes	Ceiling	Concrete	White	None	0	0.2	Negative		0	Negative					
1	1	Hallway from Gym/Cafeteria to Exterior Entrance		Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Hallway from Gym/Cafeteria to Exterior Entrance		Yes	Door	Metal	Gray	None	0	0.5	Negative		0	N/A					
1	1	Hallway from Gym/Cafeteria to Exterior Entrance		Yes	Door Center Post	Metal	Tan	None	0	0.1	Negative		0	N/A					
1	1	Hallway from Gym/Cafeteria to Exterior Entrance		Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A					
1	1	Hallway from Gym/Cafeteria to Exterior Entrance		Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A					
1	1	Storage Room behind Classroom 200 (Exterior Access Only)		No	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Storage Room behind Classroom 200 (Exterior Access Only)		No	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Storage Room behind Classroom 200 (Exterior Access Only)		No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Storage Room behind Classroom 200 (Exterior Access Only)		No	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	1	Storage Room behind Classroom 200 (Exterior Access Only)		No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	1	Storage Room behind Classroom 200 (Exterior Access Only)		No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	B	Classroom 101		Yes	W1	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	B	Classroom 101		Yes	W2	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	B	Classroom 101		Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	B	Classroom 101		Yes	W4	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	B	Classroom 101		Yes	Ceiling	Concrete	White	Flaking	20	0.4	Negative	None	0	Negative	No	No	No	No	
1	B	Classroom 101		Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	B	Classroom 101		Yes	Column	Concrete	Beige	None	0	0.2	Negative		0	Negative					
1	B	Classroom 101		Yes	Column	Concrete	Beige	None	0	0.2	Negative		0	Negative					
1	B	Classroom 101		Yes	Univent	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	B	Classroom 101		Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A					
1	B	Classroom 101		Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A					
1	B	Classroom 102		Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative					
1	B	Classroom 102		Yes	W2	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	B	Classroom 102		Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	B	Classroom 102		Yes	W4	CMU	Beige	None	0	0	Negative		0	Negative					
1	B	Classroom 102		Yes	Ceiling	Concrete	White	Flaking	13	0.3	Negative	None	0	Negative	No	No	No	No	
1	B	Classroom 102		Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	B	Classroom 102		Yes	Column	Concrete	Beige	None	0	0.2	Negative		0	Negative					
1	B	Classroom 102		Yes	Column	Concrete	Beige	None	0	0.3	Negative		0	Negative					
1	B	Classroom 102		Yes	Univent	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	B	Classroom 102		Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A					
1	B	Classroom 103		Yes	W1	Wall	CMU	None	0	0	Negative		0	Negative					
1	B	Classroom 103		Yes	W2	Wall	CMU	None	0	0.4	Negative		0	Negative					

			School District of Philadelphia															
			Lead Safe Certification Assessment Report															
			Lingelbach Elementary School															
Name of Inspector: Kristen Masotes			Inspection Dates: 8/17/21 - 8/19/21															
Inspection Company: Acer Associates			ULCS# 6440															
E l e m e n t	F l o o r	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	B	Classroom 103	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	B	Classroom 103	Yes	W4	Wall	CMU	None	0	0	Negative		0	Negative					
1	B	Classroom 103	Yes	Ceiling	Concrete	White	Flaking	10	0.3	Negative	None	0	Negative	No	No	No	No	
1	B	Classroom 103	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	B	Classroom 103	Yes	Column	Concrete	Beige	None	0	0.1	Negative		0	Negative					
1	B	Classroom 103	Yes	Column	Concrete	Beige	None	0	0.2	Negative		0	Negative					
1	B	Classroom 103	Yes	Door Casing	Metal	Gray	None	0	0.7	Positive		0	N/A					
1	B	Classroom 103	Yes	Univent	Metal	Gray	None	0	0.2	Negative		0	N/A					
1	B	Classroom 103	Yes	Univent	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	B	Classroom 104	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative					
1	B	Classroom 104	Yes	W2	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	B	Classroom 104	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	B	Classroom 104	Yes	W4	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	B	Classroom 104	Yes	Ceiling	Concrete	White	None	0	0.3	Negative		0	Negative					
1	B	Classroom 104	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	B	Classroom 104	Yes	Column	Concrete	Beige	Flaking	2	0.2	Negative	None	0	Negative	No	No	No	No	
1	B	Classroom 104	Yes	Univent	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	B	Classroom 104	Yes	Univent	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	B	Classroom 104	Yes	Door Casing	Metal	Gray	None	0	0.7	Positive		0	N/A					
1	B	Classroom 105	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative					
1	B	Classroom 105	Yes	W2	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	B	Classroom 105	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	B	Classroom 105	Yes	W4	CMU	Beige	None	0	0.3	Negative		0	Negative					
1	B	Classroom 105	Yes	Ceiling	Concrete	White	Flaking	5	0.3	Negative	None	0	Negative	No	No	No	No	
1	B	Classroom 105	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	B	Classroom 105	Yes	Column	Concrete	Beige	None	0	0.2	Negative		0	Negative					
1	B	Classroom 105	Yes	Column	Concrete	Beige	None	0	0.1	Negative		0	Negative					
1	B	Classroom 105	Yes	Door Casing	Metal	Green	None	0	0.7	Positive		0	N/A					
1	B	Classroom 105	Yes	Univent	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	B	Classroom 106	Yes	W1	CMU	Beige	None	0	0	Negative		0	Negative					
1	B	Classroom 106	Yes	W2	CMU	Beige	Flaking	1	0.3	Negative	None	0	Negative	No	No	No	No	
1	B	Classroom 106	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	B	Classroom 106	Yes	W4	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	B	Classroom 106	Yes	Ceiling	Concrete	White	None	0	0.3	Negative		0	Negative					
1	B	Classroom 106	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	B	Classroom 106	Yes	Column	Concrete	Beige	None	0	0.1	Negative		0	Negative					
1	B	Classroom 106	Yes	Univent	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	B	Classroom 106	Yes	Door Casing	Metal	Green	None	0	0	Negative		0	N/A					
1	B	Girl's Restroom across from Classroom 106	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	B	Girl's Restroom across from Classroom 106	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	B	Girl's Restroom across from Classroom 106	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	B	Girl's Restroom across from Classroom 106	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	B	Girl's Restroom across from Classroom 106	Yes	Ceiling	Concrete	White	Flaking	15	0.3	Negative	None	0	Negative	No	No	No	No	
1	B	Girl's Restroom across from Classroom 106	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	B	Girl's Restroom across from Classroom 106	Yes	Stall Door	Metal	Green	None	0	0	Negative		0	N/A					
1	B	Girl's Restroom across from Classroom 106	Yes	Radiator	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	B	Girl's Restroom across from Classroom 106	Yes	Stall Wall	Transite	Gray	None	0	0.2	Negative		0	N/A					
1	B	Girl's Restroom across from Classroom 106	Yes	Door Casing	Metal	Gray	None	0	0	Negative		0	N/A					
1	B	Girl's Restroom across from Classroom 106	Yes	Door	Metal	Gray	None	0	0	Negative		0	N/A					
1	B	Boy's Restroom across from Classroom 106	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	B	Boy's Restroom across from Classroom 106	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	B	Boy's Restroom across from Classroom 106	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	B	Boy's Restroom across from Classroom 106	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Ceramic Tile
1	B	Boy's Restroom across from Classroom 106	Yes	Ceiling	Concrete	White	Flaking	15	0.2	Negative	None	0	Negative	No	No	No	No	
1	B	Boy's Restroom across from Classroom 106	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	B	Boy's Restroom across from Classroom 106	Yes	Door	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	B	Boy's Restroom across from Classroom 106	Yes	Door Casing	Metal	Gray	None	0	0.4	Negative		0	N/A					
1	B	Boy's Restroom across from Classroom 106	Yes	Pipe Shaft Door	Wood	Gray	None	0	0.1	Negative		0	N/A					
1	B	Boy's Restroom across from Classroom 106	Yes	Pipe Shaft Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A					
1	B	Boy's Restroom across from Classroom 106	Yes	Pipe	Metal	White	None	0	0.1	Negative		0	N/A					
1	B	Boy's Restroom across from Classroom 106	Yes	Stall Wall	Transite	Gray	None	0	0.1	Negative		0	N/A					
1	B	Boy's Restroom across from Classroom 106	Yes	Radiator	Metal	Gray	None	0	0.1	Negative		0	N/A					
1	B	Boy's Restroom across from Classroom 106 Pipe Chase	No	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	B	Boy's Restroom across from Classroom 106 Pipe Chase	No	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	B	Boy's Restroom across from Classroom 106 Pipe Chase	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	B	Boy's Restroom across from Classroom 106 Pipe Chase	No	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					

Element		Floor		School District of Philadelphia														
				Lead Safe Certification Assessment Report														
				Name of Inspector: Kristen Masotes			Lingelbach Elementary School							Inspection Dates: 8/17/21 - 8/19/21				
Inspection Company: Acer Associates										ULCS# 6440								
		On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/ negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes
1	B	Boy's Restroom across from Classroom 106 Pipe Chase	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	B	Boy's Restroom across from Classroom 106 Pipe Chase	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	B	Boiler Room	No	W1	CMU	Beige	None	0	0.1	Negative		0	Negative					
1	B	Boiler Room	No	W1	Concrete	Beige	Flaking	5	0.4	Negative	None	0	Negative	No	No	No	No	
1	B	Boiler Room	No	W2	Brick	Beige	None	0	0.1	Negative		0	Negative					
1	B	Boiler Room	No	W2	Concrete	Beige	Flaking	5	0.3	Negative	None	0	Negative	No	No	No	No	
1	B	Boiler Room	No	W3	Concrete	Beige	None	0	0.2	Negative		0	Negative					
1	B	Boiler Room	No	W4	Concrete	Beige	None	0	0.3	Negative		0	Negative					
1	B	Boiler Room	No	W4	CMU	Beige	None	0	0.4	Negative		0	Negative					
1	B	Boiler Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					Height of Ceiling is too High
1	B	Boiler Room	No	Floor	Concrete	Gray	None	0	0.4	Negative		0	N/A					
1	B	Boiler Room	No	Stairs - Tread	Concrete	Gray	None	0	0.1	Negative		0	N/A					
1	B	Boiler Room	No	Stairs - Railing	Metal	Gray	None	0	0.5	Negative		0	N/A					
1	B	Boiler Room	No	Door Casing	Metal	Gray	None	0	0.7	Positive		0	N/A					Height of Ceiling is too High
1	B	Boiler Room	No	Door	Metal	Gray	None	0	0	Negative		0	N/A					
1	B	Water Softner Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Not Painted
1	B	Water Softner Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Not Painted
1	B	Water Softner Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Not Painted
1	B	Water Softner Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Not Painted
1	B	Water Softner Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					Not Painted
1	B	Water Softner Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					Not Painted
1	B	Former Coal Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Not Painted
1	B	Former Coal Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Not Painted
1	B	Former Coal Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Not Painted
1	B	Former Coal Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					Not Painted
1	B	Former Coal Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					Not Painted
1	B	Former Coal Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					Not Painted
1	B	Electrical Room	No	W1	CMU	Gray	None	0	0	Negative		0	Negative					
1	B	Electrical Room	No	W2	Concrete	Gray	Flaking	50	0.2	Negative	None	0	Negative	No	No	No	No	
1	B	Electrical Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	B	Electrical Room	No	W4	CMU	Gray	None	0	0	Negative		0	Negative					
1	B	Electrical Room	No	Ceiling	Concrete	Gray	Flaking	135	0.3	Negative	None	0	Negative	No	No	No	No	
1	B	Electrical Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	B	Electrical Room	No	Wallboard	Wood	Gray	None	0	0.1	Negative		0	N/A					
1	B	Electrical Room	No	Electrical Panel	Metal	Gray	None	0	0.2	Negative		0	N/A					
1	B	Storage Room adjacent to Boiler Room	No	W1	CMU	Yellow	None	0	0	Negative		0	Negative					
1	B	Storage Room adjacent to Boiler Room	No	W2	CMU	Yellow	None	0	0.4	Negative		0	Negative					
1	B	Storage Room adjacent to Boiler Room	No	W3	CMU	Yellow	None	0	0.1	Negative		0	Negative					
1	B	Storage Room adjacent to Boiler Room	No	W4	Concrete	Yellow	None	0	0.4	Negative		0	Negative					
1	B	Storage Room adjacent to Boiler Room	No	Ceiling	Concrete	White	Flaking	10	0.2	Negative	None	0	Negative	No	No	No	No	
1	B	Storage Room adjacent to Boiler Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	B	Storage Room adjacent to Boiler Room	No	Door Casing	Metal	Green	None	0	0.7	Positive		0	N/A					
1	B	Storage Room adjacent to Hearing and Speech Therapy	No	W1	CMU	Yellow	None	0	0.4	Negative		0	Negative					
1	B	Storage Room adjacent to Hearing and Speech Therapy	No	W2	CMU	Yellow	None	0	0	Negative		0	Negative					
1	B	Storage Room adjacent to Hearing and Speech Therapy	No	W3	CMU	Yellow	None	0	0.4	Negative		0	Negative					
1	B	Storage Room adjacent to Hearing and Speech Therapy	No	W4	CMU	Yellow	None	0	0	Negative		0	Negative					
1	B	Storage Room adjacent to Hearing and Speech Therapy	No	Ceiling	Concrete	White	Flaking	15	0.3	Negative	None	0	Negative	No	No	No	No	
1	B	Storage Room adjacent to Hearing and Speech Therapy	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	B	Storage Room adjacent to Hearing and Speech Therapy	No	Column	Concrete	Yellow	None	0	0.2	Negative		0	Negative					
1	B	Storage Room adjacent to Hearing and Speech Therapy	No	Door Casing	Metal	Gray	None	0	0.2	Negative		0	N/A					
1	B	Storage Room adjacent to Hearing and Speech Therapy	No	Duct	Metal	White	None	0	0.1	Negative		0	N/A					
1	B	Hearing and Speach Therapy	Yes	W1	CMU	Purple/Yellow	None	0	0	Negative		0	Negative					
1	B	Hearing and Speach Therapy	Yes	W2	CMU	Purple	None	0	0.4	Negative		0	Negative					
1	B	Hearing and Speach Therapy	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	B	Hearing and Speach Therapy	Yes	W4	CMU	Yellow	None	0	0.3	Negative		0	Negative					
1	B	Hearing and Speach Therapy	Yes	Ceiling	Concrete	White	Flaking	10	0.6	Negative	None	0	Negative	No	No	No	No	
1	B	Hearing and Speach Therapy	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A					
1	B	Hearing and Speach Therapy	Yes	Door Casing	Metal	Gray	None	0	0.3	Negative		0	N/A					
1	B	Women's Restroom across from Classroom 104	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	B	Women's Restroom across from Classroom 104	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	B	Women's Restroom across from Classroom 104	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					
1	B	Women's Restroom across from Classroom 104	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative					

Element		Floor		School District of Philadelphia															
				Lead Safe Certification Assessment Report															
				Name of Inspector: Kristen Masotes		Lingelbach Elementary School								Inspection Dates: 8/17/21 - 8/19/21					
Inspection Company: Acer Associates										ULCS# 6440									
		On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	Debris Present (describe location)	Quantity (sf)	Asbestos Paint sampled (positive/negative)	Contents Need to be Moved	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no)	Comments/ Description/ Notes	
1	B	Women's Restroom across from Classroom 104	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	B	Women's Restroom across from Classroom 104	Yes	Ceiling	Concrete	White	None	0	0.3	Negative		0	Negative						
1	B	Women's Restroom across from Classroom 104	Yes	Door Casing	Metal	Gray	None	0	0.4	Negative		0	N/A						
1	B	Women's Restroom across from Classroom 104	Yes	Pipe Jacket	Metal	Gray	None	0	0.2	Negative		0	N/A						
1	B	Building Engineer's Office	No	W1	CMU	Beige	None	0	0	Negative		0	Negative						
1	B	Building Engineer's Office	No	W2	CMU	Beige	None	0	0.3	Negative		0	Negative						
1	B	Building Engineer's Office	No	W2	Concrete	Beige	Flaking	3	0.2	Negative	None	0	Negative	No	No	No	No		
1	B	Building Engineer's Office	No	W3	Concrete	Beige	Flaking	20	0.3	Negative	None	0	Negative	No	No	No	No		
1	B	Building Engineer's Office	No	W4	CMU	Beige	Flaking	15	0.4	Negative	None	0	Negative	No	No	No	No		
1	B	Building Engineer's Office	No	Ceiling	Concrete	White	Flaking	15	0.3	Negative	None	0	Negative	No	No	No	No		
1	B	Building Engineer's Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	B	Building Engineer's Office	No	Column	Concrete	Beige	None	0	0.3	Negative		0	Negative						
1	B	Building Engineer's Office	No	Door Casing	Metal	White	None	0	0.5	Negative		0	N/A						
1	B	Building Engineer's Office	No	Radiator	Metal	Beige	None	0	0.2	Negative		0	N/A						
1	B	Building Engineer's Office	No	Crawlspace Door	Metal	Beige	None	0	0.1	Negative		0	N/A						
1	B	Building Engineer's Office	No	Ladder	Metal	Beige	None	0	0.1	Negative		0	N/A						
1	B	Building Engineer's Office	No	Crawlspace Door	Metal	Beige	None	0	0.1	Negative		0	N/A						
1	B	Building Engineer's Office Restroom	No	W1	CMU	Beige	None	0	0.4	Negative		0	Negative						
1	B	Building Engineer's Office Restroom	No	W2	CMU	Beige	None	0	0.3	Negative		0	Negative						
1	B	Building Engineer's Office Restroom	No	W3	CMU	Beige	None	0	0.4	Negative		0	Negative						
1	B	Building Engineer's Office Restroom	No	W4	CMU	Beige	None	0	0.4	Negative		0	Negative						
1	B	Building Engineer's Office Restroom	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	B	Building Engineer's Office Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	B	Building Engineer's Office Restroom	No	Door Casing	Metal	Gray	None	0	0.4	Negative		0	N/A						
1	B	Building Engineer's Office Restroom	No	Door	Wood	Gray	None	0	0.1	Negative		0	N/A						
1	B	Building Engineer's Office Closet	No	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	B	Building Engineer's Office Closet	No	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	B	Building Engineer's Office Closet	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	B	Building Engineer's Office Closet	No	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	B	Building Engineer's Office Closet	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	B	Building Engineer's Office Closet	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	B	Hallway outside Classrooms 101-106	Yes	W1	CMU	Green	None	0	0	Negative		0	Negative						
1	B	Hallway outside Classrooms 101-106	Yes	W2	CMU	Green	None	0	0	Negative		0	Negative						
1	B	Hallway outside Classrooms 101-106	Yes	W3	CMU	Green	None	0	0	Negative		0	Negative						
1	B	Hallway outside Classrooms 101-106	Yes	W4	CMU	Green	None	0	0.4	Negative		0	Negative						
1	B	Hallway outside Classrooms 101-106	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	B	Hallway outside Classrooms 101-106	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	B	Hallway outside Classrooms 101-106	Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A						
1	B	Hallway outside Classrooms 101-106	Yes	Door	Metal	Gray	None	0	0	Negative		0	N/A						
1	B	Hallway outside Classrooms 101-106	Yes	Door	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	B	Hallway outside Classrooms 101-106	Yes	Door Casing	Metal	Gray	None	0	0.5	Negative		0	N/A						
1	B	Hallway outside Classrooms 101-106	Yes	Door Casing	Metal	Gray	None	0	0.8	Positive		0	N/A						
1	B	Hallway outside Classrooms 101-106	Yes	Door	Metal	Gray	None	0	0.1	Negative		0	N/A						
1	A	Attic	No	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	A	Attic	No	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	A	Attic	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	A	Attic	No	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	A	Attic	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	A	Attic	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	C	Crawlspace near Building Engineer Office	No	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	C	Crawlspace near Building Engineer Office	No	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	C	Crawlspace near Building Engineer Office	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	C	Crawlspace near Building Engineer Office	No	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	C	Crawlspace near Building Engineer Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	C	Crawlspace near Building Engineer Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	C	Crawlspace near Boiler Room Wall	No	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	C	Crawlspace near Boiler Room Wall	No	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	C	Crawlspace near Boiler Room Wall	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	C	Crawlspace near Boiler Room Wall	No	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	C	Crawlspace near Boiler Room Wall	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	C	Crawlspace near Boiler Room Wall	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	C	Crawlspace near Boiler Room	No	W1	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	C	Crawlspace near Boiler Room	No	W2	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	C	Crawlspace near Boiler Room	No	W3	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	C	Crawlspace near Boiler Room	No	W4	N/A	N/A	N/A	N/A	N/A	N/A		0	Negative						
1	C	Crawlspace near Boiler Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						
1	C	Crawlspace near Boiler Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A		0	N/A						