

Alain Locke ES
Scope of Work

Task ID	ULCS#	Elimination	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Debris or and/or Existing Materials located
1	1470	1	3	300A	Storage	Book Storage adjacent to Classroom 300	W4	Flaking paint at conduits	5	N	Flaking paint at conduits
2	1470	1	3	311A	Storage	Book Storage adjacent to Classroom 313	Ceiling	Flaking paint at ceiling and duct	50	N	Flaking paint at ceiling and duct
3	1470	1	3	300	Computer - Intermediate Middle	Classroom 300	Ceiling	Flaking paint by windows	5	N	Flaking paint by windows
4	1470	1	3	300	Computer - Intermediate Middle	Classroom 300	W1	Flaking paint in closet by ceiling, chipped paint at door casing.	15	N	Flaking paint in closet by ceiling, chipped paint at door casing.
5	1470	1	3	301	Primary	Classroom 301	Ceiling	Flaking paint	15	N	Flaking paint
6	1470	1	3	301	Primary	Classroom 301	W1	Flaking paint at closet pole, door casing, and cracking paint near	30	N	Flaking paint at closet pole, door casing, and cracking paint near
7	1470	1	3	301	Primary	Classroom 301	W3	Flaking paint at column by windows	1	N	Flaking paint at column by windows
8	1470	1	3	301	Primary	Classroom 301	W4	Cracking paint	1	N	Cracking paint
9	1470	1	3	302	Primary	Classroom 302	Ceiling	Flaking paint	15	N	Flaking paint
10	1470	1	3	302	Primary	Classroom 302	W1	Flaking paint at closet pole and door casing	10	N	Flaking paint at closet pole and door casing
11	1470	1	3	302	Primary	Classroom 302	W2	Flaking paint near ceiling	10	N	Flaking paint near ceiling
12	1470	1	3	302	Primary	Classroom 302	W4	Flaking paint near ceiling	10	N	Flaking paint near ceiling
13	1470	1	3	303	Primary	Classroom 303	Ceiling	Flaking paint in closet, by W4 and by windows	5	N	Flaking paint in closet, by W4 and by windows
14	1470	1	3	303	Primary	Classroom 303	W1	Flaking paint by entrance, closet pole, and door casing	20	N	Flaking paint by entrance, closet pole, and door casing
15	1470	1	3	303	Primary	Classroom 303	W3	Flaking paint by blinds	5	N	Flaking paint by blinds
16	1470	1	3	303	Primary	Classroom 303	W4	Flaking paint by entrance and by	10	N	Flaking paint by entrance and by
17	1470	1	3	304	Primary	Classroom 304	Ceiling	Flaking paint in closet	5	N	Flaking paint in closet
18	1470	1	3	304	Primary	Classroom 304	W1	Flaking paint at closet pole and door casing	10	N	Flaking paint at closet pole and door casing
19	1470	1	3	304	Primary	Classroom 304	W2	Flaking paint near ceiling	1	N	Flaking paint near ceiling
20	1470	1	3	304	Primary	Classroom 304	W3	Flaking paint below window sill	2	N	Flaking paint below window sill
21	1470	1	3	305	Primary	Classroom 305	Ceiling	Flaking paint	50	N	Flaking paint
22	1470	1	3	305	Primary	Classroom 305	W1	Flaking paint at door casing, closet pole, and side of bulletin board	15	N	Flaking paint at door casing, closet pole, and side of bulletin board
23	1470	1	3	305	Primary	Classroom 305	W2	Cracked paint at ceiling	5	N	Cracked paint at ceiling
24	1470	1	3	305	Primary	Classroom 305	W3	Flaking paint by bulletin board	5	N	Flaking paint by bulletin board
25	1470	1	3	308	Primary	Classroom 308	Ceiling	Flaking paint	10	N	Flaking paint
26	1470	1	3	308	Primary	Classroom 308	W1	Flaking paint at closet pole and door casing	10	N	Flaking paint at closet pole and door casing
27	1470	1	3	308	Primary	Classroom 308	W2	Cracked paint near ceiling	2	N	Cracked paint near ceiling
28	1470	1	3	308	Primary	Classroom 308	W3	Flaking paint at column by windows	5	N	Flaking paint at column by windows
29	1470	1	3	309	Primary	Classroom 309	Ceiling	Flaking paint throughout and in closet	30	N	Flaking paint throughout and in closet
30	1470	1	3	309	Primary	Classroom 309	W1	Flaking paint at closet pole and door casing	10	N	Flaking paint at closet pole and door casing
31	1470	1	3	309	Primary	Classroom 309	W2	Flaking paint by ceiling	2	N	Flaking paint by ceiling

Alain Locke ES
Scope of Work

Task ID	ULCS#	Elimination	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Debris or and/or Existing Materials located
40	1470	1	3	312	Primary	Classroom 312	Ceiling	Flaking paint throughout and in closet	30	N	
41	1470	1	3	312	Primary	Classroom 312	W1	Flaking paint at door casing, baseboard, and closet pole	20	N	
42	1470	1	3	312	Primary	Classroom 312	W2	Cracked paint near ceiling	5	N	
43	1470	1	3	312	Primary	Classroom 312	W3	Flaking paint at column by windows	5	N	
44	1470	1	3	312	Primary	Classroom 312	W4	Flaking paint above blackboard	20	N	
45	1470	1	3	313	Primary	Classroom 313	Ceiling	Flaking paint	20	N	
46	1470	1	3	313	Primary	Classroom 313	W1	Flaking paint at door casing, baseboard, and closet pole	20	N	
47	1470	1	3	313	Primary	Classroom 313	W3	Flaking paint at column between windows	5	N	
48	1470	1	3	313	Primary	Classroom 313	W4	Cracked paint	5	N	
49	1470	1	3	H37	Circulation (Hallway)	Hallway Classrooms 300-313	Ceiling	Flaking paint	40	N	
50	1470	1	3	H37	Circulation (Hallway)	Hallway Classrooms 300-313	W1	Flaking paint	10	N	
51	1470	1	3	H37	Circulation (Hallway)	Hallway Classrooms 300-313	W3	Flaking paint at wall, and at stairwell doors and door casings	50	N	
52	1470	1	3	S32	Stairs	Stairway adjacent to Classroom 300	Ceiling	Flaking paint at landing ceiling	10	Y	
53	1470	1	3	S32	Stairs	Stairway adjacent to Classroom 300	W1	Flaking paint at doors	15	N	
54	1470	1	3	S33	Stairs	Stairway adjacent to Classroom 312	Ceiling	Flaking paint	20	N	
55	1470	1	3	S33	Stairs	Stairway adjacent to Classroom 312	W1	Flaking paint at doors	15	N	
56	1470	1	2	200A	Storage	Book Storage adjacent to Classroom 200	Ceiling	Flaking paint	50	N	
57	1470	1	2	200A	Storage	Book Storage adjacent to Classroom 200	W4	Flaking paint at conduits	10	N	Flk
58	1470	1	2	212A	Storage	Book Storage adjacent to Classroom 212	Ceiling	Flaking paint	50	N	
59	1470	1	2	212A	Storage	Book Storage adjacent to Classroom 212	W1	Flaking paint at conduit	10		Flk
60	1470	1	2	204A	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Flaking paint	50	N	
61	1470	1	2	200	Primary	Classroom 200	Ceiling	Flaking paint	10	N	
62	1470	1	2	200	Primary	Classroom 200	W1	Flaking paint at closet pole	5	N	
63	1470	1	2	200	Primary	Classroom 200	W2	Flaking paint near ceiling	10	N	
64	1470	1	2	200	Primary	Classroom 200	W3	Flaking paint at column	2	N	
65	1470	1	2	201	Primary	Classroom 201	Ceiling	Flaking paint	20	N	
66	1470	1	2	201	Primary	Classroom 201	W1	Flaking paint at door casing and closet pole	10	N	
67	1470	1	2	201	Primary	Classroom 201	W2	Flaking paint at conduit	2	N	

Alain Locke ES
Scope of Work

Task ID	ULCS#	Elimination	For	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Debris or and/or Electrical Materials located
75	1470	1	2	203	Primary	Classroom 203	W1	Flaking paint at door casing and closet pole	10	N	
76	1470	1	2	203	Primary	Classroom 203	W2	Flaking paint	2	N	
77	1470	1	2	203	Primary	Classroom 203	W3	Flaking paint at column	2	N	
78	1470	1	2	203	Primary	Classroom 203	W4	Flaking paint at conduit	5	N	
79	1470	1	2	204	Primary	Classroom 204	Ceiling	Flaking paint in closet and by W4	15	N	
80	1470	1	2	204	Primary	Classroom 204	W1	Flaking paint at door casing and closet pole	10	N	
81	1470	1	2	204	Primary	Classroom 204	W3	Flaking paint by windows	2	N	
82	1470	1	2	204	Primary	Classroom 204	W4	Flaking paint at conduit	5	N	
83	1470	1	2	208	Primary	Classroom 208	Ceiling	Flaking paint	20	N	
84	1470	1	2	208	Primary	Classroom 208	W1	Flaking paint at door casing and wall	20	N	
85	1470	1	2	208	Primary	Classroom 208	W2	Flaking paint at wall and conduit	5	N	
86	1470	1	2	208	Primary	Classroom 208	W3	Flaking paint by bulletin board	5	N	
87	1470	1	2	208	Primary	Classroom 208	W4	Flaking paint	5	N	
88	1470	1	2	209	Primary	Classroom 209	Ceiling	Flaking paint	20	N	
89	1470	1	2	209	Primary	Classroom 209	W1	Flaking paint at closet pole	5	N	
90	1470	1	2	209	Primary	Classroom 209	W3	Cracked paint by window sill	1	N	
91	1470	1	2	210	Primary	Classroom 210	Ceiling	Flaking paint in closet	5	N	
92	1470	1	2	210	Primary	Classroom 210	W1	Flaking paint	10	N	
93	1470	1	2	210	Primary	Classroom 210	W3	Flaking paint	5	N	
94	1470	1	2	210	Primary	Classroom 210	W4	Flaking paint	10	N	
95	1470	1	2	211	Primary	Classroom 211	Ceiling	Flaking paint in closet and throughout	40	N	
96	1470	1	2	211	Primary	Classroom 211	W1	Flaking paint at door casing, closet pole, and wall	15	N	
97	1470	1	2	211	Primary	Classroom 211	W2	Flaking paint by W3	2	N	
98	1470	1	2	211	Primary	Classroom 211	W3	Flaking paint by bulletin board	10	N	
99	1470	1	2	212	Primary	Classroom 212	Ceiling	Flaking paint	25	N	
100	1470	1	2	212	Primary	Classroom 212	W1	Flaking paint at door casing	5	N	
101	1470	1	2	212	Primary	Classroom 212	W3	Flaking paint at radiator and column	15	N	
102	1470	1	2	212	Primary	Classroom 212	W4	Flaking paint near ceiling	10	N	
103	1470	1	2	213	Primary	Classroom 213	Ceiling	Flaking paint in closet and throughout	25	N	
104	1470	1	2	213	Primary	Classroom 213	W1	Flaking paint at door casing, closet pole, and at wall by W2	15	N	
105	1470	1	2	213	Primary	Classroom 213	W3	Flaking paint by W2, by ceiling, and at radiator	15	N	
106	1470	1	2	207	Administrative Office	Counselor's Office	W1	Flaking paint	5	N	
107	1470	1	2	208A	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Flaking paint	50	N	
108	1470	1	2	H26	Circulation (Hallway)	Hallway Classrooms 200-213	W1	Flaking paint	10	N	
109	1470	1	2	H26	Circulation (Hallway)	Hallway Classrooms 200-213	W3	Flaking paint at wall, and at stairwell doors and door casings	50	N	

Alain Locke ES
Scope of Work

Task ID	ULCS#	Elimination	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Debris or and/or Existing Materials located
115	1470	1	2	S23	Stairs	Stairs adjacent to Classroom 212	W1	Flaking paint at doors	15	N	
116	1470	1	2	201A	Storage	Storage Room adjacent to Classroom 201	Ceiling	Flaking paint	5	N	
117	1470	1	2	201A	Storage	Storage Room adjacent to Classroom 201	W2	Flaking paint	2	N	
118	1470	1	1	AUD	Auditorium	Auditorium	W2	Flaking paint	80	Y	
119	1470	1	1	AUD	Auditorium	Auditorium	W4	Flaking paint	20	N	
120	1470	1	1	STAGE	Stage	Auditorium Stage	W3	Flaking paint	30	Y	
121	1470	1	1	101A	Storage	Book Storage adjacent to Classroom 101	Ceiling	Flaking paint	10	N	
122	1470	1	1	112A	Storage	Book Storage adjacent to Classroom 112	Ceiling	Flaking paint	20	N	
123	1470	1	1	112A	Storage	Book Storage adjacent to Classroom 112	W2	Flaking paint at conduits	20	N	Flaking paint at conduits
124	1470	1	1	102C	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Flaking paint	20	N	
125	1470	1	1	100	Primary	Classroom 100	Ceiling	Flaking paint by W3, W4 and window	10	N	
126	1470	1	1	100	Primary	Classroom 100	W3	Flaking paint by window	5	N	
127	1470	1	1	101	Primary	Classroom 101	Ceiling	Flaking paint throughout and at support beam in closet	30	N	
128	1470	1	1	102	Primary	Classroom 102	Ceiling	Flaking paint	20	N	
129	1470	1	1	102	Primary	Classroom 102	W3	Flaking paint by window 1 and by bulletin board	15	N	
130	1470	1	1	103	Primary	Classroom 103	W1	Flaking paint by ceiling	10	N	
131	1470	1	1	105	Music	Classroom 105	Ceiling	Flaking paint	20	N	
132	1470	1	1	105	Music	Classroom 105	W1	Flaking paint by closet	5	N	
133	1470	1	1	109	Primary	Classroom 109	Ceiling	Flaking paint	30	N	
134	1470	1	1	111	Primary	Classroom 111	Ceiling	Flaking paint	20	N	
135	1470	1	1	111	Primary	Classroom 111	W3	Flaking paint above window 7	5	N	
136	1470	1	1	112	Primary	Classroom 112	Ceiling	Flaking paint	20	N	
137	1470	1	1	112	Primary	Classroom 112	W1	Cracked paint at door	1	N	
138	1470	1	1	115	Primary	Classroom 115	Ceiling	Flaking paint	10	N	
139	1470	1	1	115	Primary	Classroom 115	W3	Flaking paint by bulletin board and column	10	N	
140	1470	1	1	117	Primary	Classroom 117	Ceiling	Flaking paint	25	N	
141	1470	1	1	117	Primary	Classroom 117	W2	Flaking paint at door casing	5	N	
142	1470	1	1	117	Primary	Classroom 117	W3	Flaking paint by window 5	2	N	
143	1470	1	1	117A	Storage	Classroom 117 Closet	Ceiling	Flaking paint	10	N	
144	1470	1	1	116A	Administrative Office	Copy Room in Main Office (next to Nurse's Office)	W4	Cracked paint	2	N	
145	1470	1	1	116A	Administrative Office	Copy Room in Main Office (next to Nurse's Office)	W1	Flaking paint at door casing	5	N	

Alain Locke ES
Scope of Work

Task ID	ULCS#	Elimination	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Debris or and/or Existing Materials located
149	1470	1	1	123GRR	Student Restrooms - Female (4-12) (Hallway)	Gymnasium/Cafeteria Girl's Restroom	W2	Flaking paint	10	N	
150	1470	1	1	H11	Circulation (Hallway)	Hallway Classroom 103 to Stage	W2	Flaking paint	20	N	
151	1470	1	1	H11	Circulation (Hallway)	Hallway Classroom 103 to Stage	W4	Flaking paint	10	N	
152	1470	1	1	H13	Circulation (Hallway)	Hallway Classroom 111 to Gym	W2	Flaking paint	30	N	
153	1470	1	1	H13	Circulation (Hallway)	Hallway Classroom 111 to Gym	W4	Flaking paint	30	N	
154	1470	1	1	H14	Circulation (Hallway)	Hallway Classrooms 100-112	W1	Flaking paint	20	N	
155	1470	1	1	H14	Circulation (Hallway)	Hallway Classrooms 100-112	W3	Flaking paint at wall and stairwell doors	70	N	
156	1470	1	1	H15	Circulation (Hallway)	Hallway Gym to Stage	W1	Flaking paint at baseboards	20	N	
157	1470	1	1	H16	Circulation (Hallway)	Hallway Teacher's Lounge to just past Women's Restroom	W2	Flaking paint	20	N	
158	1470	1	1	H16	Circulation (Hallway)	Hallway Teacher's Lounge to just past Women's Restroom	W4	Flaking paint	20	N	
159	1470	1	1	108/110	IMC (Library)	IMC	W1	Flaking paint at walls and door	20	N	
160	1470	1	1	108/110	IMC (Library)	IMC	W2	Flaking paint	5	N	
161	1470	1	1	108/110	IMC (Library)	IMC	W3	Flaking paint	10	N	
162	1470	1	1	108D	Administrative Office	IMC Office	W1	Flaking paint at door casing	10	N	
163	1470	1	1	108D	Administrative Office	IMC Office	W3	Flaking paint at soap dispenser	1	N	
164	1470	1	1	108D	Administrative Office	IMC Office	W4	Flaking paint by window	1	N	
165	1470	1	1	121C	Kitchen	Kitchen	Ceiling	Flaking paint	10	N	
166	1470	1	1	121C	Kitchen	Kitchen	W3	Flaking paint	10	N	
167	1470	1	1	121C	Kitchen	Kitchen	W1	Flaking paint	10	N	
168	1470	1	1	121A	Storage	Kitchen Storage	W1	Flaking paint at door casings	10	N	
169	1470	1	1	H15B	Circulation (Hallway)	Main Entrance Foyer	Ceiling	Flaking paint	5	N	
170	1470	1	1	H15B	Circulation (Hallway)	Main Entrance Foyer	W3	Flaking paint	5	N	
171	1470	1	1	H15B	Circulation (Hallway)	Main Entrance Foyer	W4	Flaking paint	5	N	
172	1470	1	1	H15A	Circulation (Hallway)	Main Lobby	Ceiling	Flaking paint	30	N	
173	1470	1	1	H15A	Circulation	Main Lobby	W1	Flaking paint at baseboards	5	N	

Alain Locke ES
Scope of Work

Task ID	ULCS#	Elimination	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Debris or and/or Existing Materials located
179	1470	1	1	118A	Restrooms, Staff - Male	Men's Restroom	Ceiling	Flaking paint	10	N	
180	1470	1	1	118A	Restrooms, Staff - Male	Men's Restroom	W1	Flaking paint	40	N	
181	1470	1	1	118A	Restrooms, Staff - Male	Men's Restroom	W2	Flaking paint	20	N	
182	1470	1	1	118A	Restrooms, Staff - Male	Men's Restroom	W3	Flaking paint at wall and radiator	20	N	
183	1470	1	1	118A	Restrooms, Staff - Male	Men's Restroom	W4	Flaking paint	10	N	
184	1470	1	1	105A	Administrative Office	Music Room 105 - Office	Ceiling	Flaking paint	10	N	
185	1470	1	1	114	Administrative Office	Nurse's Office	W3	Flaking paint	10	Y	
186	1470	1	1	116D	Administrative Office	Principal's Office	W2	Flaking paint by window	1	N	
187	1470	1	1	116RR	Restrooms, Staff - Female	Principal's Office Restroom	Ceiling	Flaking paint	3	N	
188	1470	1	1	114B	Administrative Office	Psychologist/Speech Room in Nurse's Office	W3	Flaking paint	5	Y	
189	1470	1	1	116SR	Central Security	Security Room in Main Office	W1	Flaking paint on conduit	5	N	
190	1470	1	1	116SR	Central Security	Security Room in Main Office	W4	Flaking paint on conduit	2	N	
191	1470	1	1	114C	Restrooms, Staff - Female	Staff Female Restroom in Nurse's Office	W1	Flaking paint	2	N	
192	1470	1	1	S-12	Stairs	Stairs adjacent to Classroom 100	W1	Flaking paint at doors	15	N	
193	1470	1	1	S13	Stairs	Stairs adjacent to Classroom 112	Ceiling	Flaking paint	10	N	
194	1470	1	1	S13	Stairs	Stairs adjacent to Classroom 112	W1	Flaking paint at doors	15	N	
195	1470	1	1	113	Storage	Storage Room next to Principal's Office (former Classroom 113)	Ceiling	Flaking paint	20	Y	
196	1470	1	1	113	Storage	Storage Room next to Principal's Office (former Classroom 113)	W1	Flaking paint at door casing	5	N	
197	1470	1	1	107	Teacher Lounge/Dining	Teacher's Lounge	W1	Flaking paint at door casings	10	N	
198	1470	1	1	107	Teacher Lounge/Dining	Teacher's Lounge	W3	Flaking paint near exit door	10	N	
199	1470	1	1	107	Teacher Lounge/Dining	Teacher's Lounge	W4	Flaking paint near window	1	N	
200	1470	1	1	108C	Administrative	Visual Aid Office next to	W1	Flaking paint at door casing	10	N	