

Task ID	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surface and/or Educational Materials (describe location)
1	3	330	Student Restrooms - Male (4-12)	Boy's Restroom	Floor	Chipped paint at floor	200	N	
2	3	330	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Flaking paint at radiator cover	5	N	
3	3	301	Primary	Classroom 301	Ceiling	Flaking paint at ceiling	100	Y	
4	3	301	Primary	Classroom 301	W3	Flaking paint around windows	50	Y	Floor, sill
5	3	301	Primary	Classroom 301	W4	Flaking paint at wall	10	N	
6	3	301A	Storage	Classroom 301 Closet	W1	Damaged plaster	10	N	
7	3	301A	Storage	Classroom 301 Closet	W2	Damaged plaster	10	N	
8	3	301A	Storage	Classroom 301 Closet	W3	Damaged plaster	10	N	
9	3	301A	Storage	Classroom 301 Closet	W4	Damaged plaster	10	N	
10	3	303	Primary	Classroom 303	W1	Flaking paint on door. Cracking paint to the right of the blackboard	22	N	
11	3	303	Primary	Classroom 303	W2	Flaking paint at closet doors. Cracking paint by closet	10	N	
12	3	303	Primary	Classroom 303	W3	Flaking paint around windows, at trim below windows, and by radiator	35	Y	
13	3	331A	Storage	Classroom 303 Closet	W1	Flaking paint at door and damaged plaster	40	N	
14	3	331A	Storage	Classroom 303 Closet	W2	Flaking paint at wall	1	N	
15	3	331A	Storage	Classroom 303 Closet	W3	Damaged plaster	40	N	
						Flaking paint at blackboard			

20	3	304A	Storage	Classroom 304 Closet	W1	Damaged plaster	30	N	
21	3	304A	Storage	Classroom 304 Closet	W3	Damaged plaster at windows	5	N	
22	3	305	Primary	Classroom 305	W3	Flaking paint at sides of windows, below window 3, and at riser by window 3.	5	N	
23	3	305A	Primary	Classroom 305 Closet	Ceiling	Flaking paint at ceiling	2	N	
24	3	305A	Primary	Classroom 305 Closet	W1	Flaking paint at wall and door	15	N	
25	3	305A	Primary	Classroom 305 Closet	W2	Flaking paint at wall	50	N	
26	3	305A	Primary	Classroom 305 Closet	W3	Flaking paint at wall	20	N	
27	3	305A	Primary	Classroom 305 Closet	W4	Flaking paint at wall and door	160	N	
28	3	307	Primary	Classroom 307	W2	Flaking paint debris on bulletin board sill and floor	5	N	Bulletin board sill floor
29	3	307	Primary	Classroom 307	W3	Flaking paint debris by radiator	5	N	Floor
30	3	307A	Storage	Classroom 307 Closet	Ceiling	Flaking paint	20	N	
31	3	307A	Storage	Classroom 307 Closet	W1	Flaking paint	5	N	
32	3	307A	Storage	Classroom 307 Closet	W2	Flaking paint	50	N	

35	3	308	Primary	Classroom 308	W2	Flaking paint debris on bulletin board sill and floor	5	N	Bulletin board sill floor
36	3	308	Primary	Classroom 308	W3	Flaking paint at window trims and debris by radiator	15	Y	Floor
37	3	308A	Storage	Classroom 308 Closet	W1	Flaking paint at door	5	N	
38	3	308A	Storage	Classroom 308 Closet	W2	Flaking paint at baseboards	5	N	
39	3	308A	Storage	Classroom 308 Closet	W3	Flaking paint at baseboards	5	N	
40	3	308A	Storage	Classroom 308 Closet	W4	Flaking paint at baseboards	5	N	
41	3	309	Primary	Classroom 309	W3	Flaking paint at radiator and debris below window 1	5	N	Floor, sill
42	3	309A	Storage	Classroom 309 Closet	Ceiling	Flaking paint	100	N	
43	3	309A	Storage	Classroom 309 Closet	Floor	Flaking paint debris	50	N	Floor
44	3	309A	Storage	Classroom 309 Closet	W1	Flaking paint	5	N	
45	3	309A	Storage	Classroom 309 Closet	W2	Flaking paint	20	N	
46	3	309A	Storage	Classroom 309 Closet	W3	Flaking paint	20	N	
47	3	309A	Storage	Classroom 309 Closet	W4	Flaking paint	50	N	
48	3	310	Primary	Classroom 310	W3	Flaking paint debris by radiator	2	N	Floor
49	3	310A	Storage	Classroom 310 Closet	W3	Flaking paint at pipe and radiator, damaged plaster	30	N	
50	3	311A	Primary	Classroom 311 Closet	W3	Flaking paint at pipe and radiator, damaged plaster	30	N	

57	3	313	Primary	Classroom 313	W3	Flaking paint	100	N	
58	3	313A	Storage	Classroom 313 Closet	Ceiling	Flaking paint	10	N	
59	3	313A	Storage	Classroom 313 Closet	W1	Flaking paint	20	N	
60	3	313A	Storage	Classroom 313 Closet	W2	Flaking paint	10	N	
61	3	313A	Storage	Classroom 313 Closet	W3	Flaking paint	30	N	
62	3	313A	Storage	Classroom 313 Closet	W4	Flaking paint	10	N	
63	3	S31	Stairs, Fire Tower	Fire Tower near Classroom 302	Ceiling	Damaged plaster	40	N	
64	3	S36	Stairs, Fire Tower	Fire Tower near Classroom 312	Ceiling	Damaged plaster	20	N	
65	3	331	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Flaking paint at exhaust fan	5	N	
66	3	331	Student Restrooms - Female (4-12)	Girl's Restroom	Floor	Flaking paint debris at pipe by W3	5	N	Floor
67	3	H320	Circulation (Hallway)	Hallway outside Classrooms 301 to 303	W3	Flaking paint behind radiator	20	N	
68	3	H319	Circulation (Hallway)	Hallway outside Classrooms 311 to 313	W1	Flaking paint behind radiator	20	N	
69	3	H318	Circulation (Hallway)	Hallway to Fire Tower near Classroom 302	W1	Flaking paint at door	15	N	
70	3	H318	Circulation (Hallway)	Hallway to Fire Tower near Classroom 302	W2	Flaking paint at door	15	N	
71	3	H317	Circulation (Hallway)	Hallway to Fire Tower near Classroom 312	W2	Flaking paint at door	15	N	
72	3	H317	Circulation (Hallway)	Hallway to Fire Tower near Classroom 312	W3	Flaking paint at door	15	N	
73	3	329	Administrative Office	Office 313A	W1	Damaged plaster	10	N	
74	3	329	Administrative Office	Office 313A	W3	Flaking paint	30	N	

78	3	332A	Restrooms, Staff - Male/Female	Teacher' Lounge adjacent to Classroom 301 Restroom	W2	Flaking paint at pipe	2	N	
79	3	332A	Restrooms, Staff - Male/Female	Teacher' Lounge adjacent to Classroom 301 Restroom	W3	Flaking paint at sill	5	N	
80	3	332A	Restrooms, Staff - Male/Female	Teacher' Lounge adjacent to Classroom 301 Restroom	W4	Flaking paint at wall in copy room by radiator	5	N	Floor
81	2	H214	Circulation (Hallway)	2nd Floor Hallway outside Auditorium	W2	Flaking paint behind radiator	20	N	
82	2	217	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Flaking paint at pipes	10	N	
83	2	203	Primary	Classroom 203	Ceiling	Flaking paint, damaged plaster near windows	15	Y	
84	2	203	Primary	Classroom 203	W1	Flaking paint above closet door. Plaster damage	10	N	
85	2	203	Primary	Classroom 203	W3	Flaking paint at window trim. Plaster damage	10	N	
86	2	203B	Storage	Classroom 203 Closet	Ceiling	Flaking paint	20	N	
87	2	203B	Storage	Classroom 203 Closet	W1	Flaking paint	10	N	
88	2	203B	Storage	Classroom 203 Closet	W2	Flaking paint	20	N	
89	2	203B	Storage	Classroom 203 Closet	W3	Flaking paint	10	N	
90	2	203B	Storage	Classroom 203 Closet	W4	Flaking paint	10	N	
91	2	205	Primary	Classroom 205	W1	Flaking paint at wall and doors	20	N	
						Flaking paint below bulletin			

96	2	205B	Storage	Classroom 205 Closet	W2	Damaged plaster	5	N	
97	2	205B	Storage	Classroom 205 Closet	W3	Flaking paint and pipe and radiator. Damaged plaster	30	N	
98	2	205B	Storage	Classroom 205 Closet	W4	Damaged plaster	5	N	
99	2	206A	Storage	Classroom 206 Closet	W1	Flaking paint at wall	10	N	
100	2	206A	Storage	Classroom 206 Closet	W3	Flaking paint at wall	20	N	
101	2	206A	Storage	Classroom 206 Closet	W4	Flaking paint at wall	20	N	
102	2	207	Primary	Classroom 207	Ceiling	Flaking paint near windows	100	Y	
103	2	207	Primary	Classroom 207	W1	Flaking paint by entrance, and above blackboard	5	N	
104	2	207	Primary	Classroom 207	W2	Flaking paint on wall by computers	2	N	
105	2	207	Primary	Classroom 207	W3	Flaking paint above and below windows	80	Y	
106	2	207	Primary	Classroom 207	W4	Flaking paint at wall around bulletin board and on baseboard	20	N	Window 2 Sill
107	2	209	Primary	Classroom 209	W3	Flaking paint behind pipe at window 4	2	Y	
108	2	209	Primary	Classroom 209	W4	Flaking paint at wall	2	N	
109	2	209B	Storage	Classroom 209 Closet	W1	Flaking paint at door	1	N	
110	2	209B	Storage	Classroom 209 Closet	W3	Flaking paint at walls and pipe	40	N	
111	2	210	Administrative Office	Counselor's Office 206A	W1	Flaking at wall and baseboards	25	N	
112	2	210	Administrative Office	Counselor's Office 206A	W2	Flaking at wall and baseboards	25	N	
113	2	210	Administrative Office	Counselor's Office 206A	W3	Flaking at wall and baseboards	35	N	
114	2	210	Administrative Office	Counselor's Office 206A	W4	Flaking at wall and baseboards	50	N	
115	2	S21	Stairs, Fire Tower	Fire Tower near Classroom 202	Ceiling	Damaged plaster	40	N	
116	2	220	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Flaking paint at pipe	3	N	

120	2	H211	Circulation (Hallway)	Hallway to Fire Tower near Classroom 208	W3	Flaking paint at door	15	N	
121	2	H211	Circulation (Hallway)	Hallway to Fire Tower near Classroom 208	W4	Flaking paint at door	15	N	
122	2	201	IMC (Library)	Library 201	Ceiling	Flaking paint near windows	30	Y	
123	2	201	IMC (Library)	Library 201	W1	Flaking paint at baseboards	20	N	
124	2	201	IMC (Library)	Library 201	W2	Flaking paint at baseboards	20	N	
125	2	201	IMC (Library)	Library 201	W3	Flaking paint debris on sills. Flaking paint at baseboards	35	Y	Window sills
126	2	201	IMC (Library)	Library 201	W4	Flaking paint at baseboards	20	N	
127	2	202	IMC (Library)	Library 202	Ceiling	Flaking paint near windows	30	Y	
128	2	202	IMC (Library)	Library 202	W1	Flaking paint at baseboards	20	N	
129	2	202	IMC (Library)	Library 202	W2	Flaking paint at baseboards	20	N	
130	2	202	IMC (Library)	Library 202	W3	Flaking paint debris on sills. Flaking paint at baseboards	35	Y	Window sills
131	2	202	IMC (Library)	Library 202	W4	Flaking paint at baseboards	20	N	
132	2	204A	Administrative Office	Nurse's Office	W1	Flaking paint on pipe in bathroom	1	N	
133	2	204A	Administrative Office	Nurse's Office	W3	Flaking paint debris on floor and on pipe.	5	Y	Floor
134	2	205A	Administrative Office	Office 205A	W1	Flaking paint at door	10	N	
135	2	205A	Administrative Office	Office 205A	W3	Flaking paint at wall	5	N	
136	2	205A	Administrative Office	Office 205A	W4	Flaking paint at wall	5	N	
137	2	209A	Administrative Office	Office 209A	Ceiling	Flaking paint and plaster damage	50	N	
138	2	209A	Administrative Office	Office 209A	W1	Flaking paint and plaster damage	12	N	
139	2	209A	Administrative Office	Office 209A	W2	Flaking paint and plaster damage	30	N	
140	2	209A	Administrative Office	Office 209A	W3	Flaking paint and plaster damage	30	N	
141	2	209A	Administrative Office	Office 209A	W4	Flaking paint and plaster damage	30	N	
142	2	201C	Administrative Office	Office between Library 201 Closet and Speech Pathologist Office	W1	Flaking paint at wall	5	N	

143	2	201C	Administrative Office	Office between Library 201 Closet and Speech Pathologist Office 201A (access from Speech Pathologist Office only)	W4	Flaking paint at wall	15	N	
144	2	201A	Administrative Office	Speech Pathologist Office 201A	W1	Flaking paint at door.	5	N	
145	2	201A	Administrative Office	Speech Pathologist Office 201A	W4	Flaking paint at baseboards	15	N	
146	2	201D	Restrooms, Staff - Male/Female	Speech Pathologist Office 201A Restroom	Ceiling	Flaking paint near windows	5	Y	
147	2	201D	Restrooms, Staff - Male/Female	Speech Pathologist Office 201A Restroom	W2	Flaking paint debris on sill and floor.	3	Y	Floor, sill
148	2	201E	Storage	Speech Pathologist Office 201A Storage Room	Ceiling	Flaking paint	50	Y	
149	2	201E	Storage	Speech Pathologist Office 201A Storage Room	Floor	Flaking paint debris	40	Y	
150	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W1	Flaking paint	50	Y	
151	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W2	Flaking paint	50	Y	
152	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W3	Flaking paint	50	Y	
153	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W4	Flaking paint	50	Y	

157	2	220A	Storage	Storage Closet near Girl's Restroom	Ceiling	No access			
158	2	220A	Storage	Storage Closet near Girl's Restroom	Floor	No access			
159	2	220A	Storage	Storage Closet near Girl's Restroom	W1	No access			
160	2	220A	Storage	Storage Closet near Girl's Restroom	W2	No access			
161	2	220A	Storage	Storage Closet near Girl's Restroom	W3	No access			
162	2	220A	Storage	Storage Closet near Girl's Restroom	W4	No access			
163	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	Ceiling	Flaking paint at ceiling	20	N	
164	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	W2	Flaking paint	2	N	
165	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	W3	Flaking paint below window	5	N	
166	2	204B	Restrooms, Staff - Male/Female	Teacher's Lounge 204 Restroom	W1	Flaking paint at door	5	N	
167	1	102	Administrative Office	Assistant Principal's Office 102	Ceiling	Flaking paint at ceiling	50	N	
168	1	102	Administrative Office	Assistant Principal's Office 102	W1	Flaking paint at wall and doors	30	N	
169	1	102	Administrative Office	Assistant Principal's Office 102	W2	Flaking paint at wall	5	N	
170	1	102	Administrative Office	Assistant Principal's Office 102	W3	Flaking paint around windows and behind radiator	40	N	
171	1	102	Administrative Office	Assistant Principal's Office 102	W4	Flaking and chipping paint at wall.	20	N	
172	1	102	Administrative Office	Assistant Principal's Office 102	W4	Flaking paint and damaged	20	N	

179	1	104A	Administrative Office	BET Office	Ceiling	Flaking paint at ceiling	20	N	
180	1	104A	Administrative Office	BET Office	W1	Flaking paint on and near door.	6	N	
181	1	104A	Administrative Office	BET Office	W2	Flaking paint at wall	10	N	
182	1	104A	Administrative Office	BET Office	W3	Flaking paint at wall	5	N	
183	1	104A	Administrative Office	BET Office	W4	Flaking paint at wall	10	N	
184	1	101A	Storage	Classroom 101 Closet	Ceiling	Flaking paint.	15	N	
185	1	101A	Storage	Classroom 101 Closet	W1	Flaking paint.	20	N	
186	1	101A	Storage	Classroom 101 Closet	W2	Flaking paint.	5	N	
187	1	101A	Storage	Classroom 101 Closet	W3	Flaking paint.	20	N	
188	1	101A	Storage	Classroom 101 Closet	W4	Flaking paint.	5	N	
189	1	101	Primary	Classroom 101	Ceiling	Damaged plaster at ceiling.	20	N	
190	1	101	Primary	Classroom 101	W1	Flaking paint above and below blackboard and on door.	20	N	
191	1	101	Primary	Classroom 101	W3	Flaking paint around windows.	20	Y	
192	1	101	Primary	Classroom 101	W4	Flaking paint above and below blackboard.	20	N	
193	1	103	Primary	Classroom 103	Ceiling	Flaking paint at ceiling	40	N	
194	1	103	Primary	Classroom 103	W1	Flaking paint near entrance and above white board.	15	N	
195	1	103	Primary	Classroom 103	W2	Flaking paint above and below bulletin board	20	N	
196	1	103	Primary	Classroom 103	W3	Flaking paint around windows	40	Y	
197	1	103	Primary	Classroom 103	W4	Flaking paint at wall	5	N	

200	1	103A	Storage	Classroom 103 Closet	W2	Flaking paint	5	N	
201	1	103A	Storage	Classroom 103 Closet	W3	Flaking paint	20	N	
202	1	103A	Storage	Classroom 103 Closet	W4	Flaking paint	10	Y	
203	1	104	Primary	Classroom 104	Ceiling	Flaking paint near windows	20	Y	
204	1	104	Primary	Classroom 104	W1	Flaking paint above and below blackboard, on door, and baseboards	30	N	
205	1	104	Primary	Classroom 104	W2	Flaking paint at wall and door.	15	N	
206	1	104	Primary	Classroom 104	W3	Flaking paint around windows.	10	Y	
207	1	104B	Storage	Classroom 104 Closet	Ceiling	Flaking paint at ceiling	20	N	
208	1	104B	Storage	Classroom 104 Closet	W1	Flaking paint at wall	20	N	
209	1	104B	Storage	Classroom 104 Closet	W3	Flaking paint at wall.	30	N	
210	1	104B	Storage	Classroom 104 Closet	W4	Flaking paint on pipe.	5	N	Floor
211	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	Ceiling	Flaking paint	20	N	
212	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W1	Flaking paint	20	N	
213	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W2	Flaking paint	20	N	
214	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W3	Flaking paint	20	N	

216	1	106	Primary	Classroom 106	W1	Flaking paint on door, above door, and above blackboard	15	N	
217	1	106	Primary	Classroom 106	W3	Flaking paint around windows and on trim	10	Y	
218	1	106	Primary	Classroom 106	W4	Flaking paint above bulletin board	10	N	
219	1	106A	Storage	Classroom 106 Closet	Ceiling	Flaking paint at ceiling	30	Y	
220	1	106A	Storage	Classroom 106 Closet	W2	Flaking paint at wall	20	Y	
221	1	107	Primary	Classroom 107	Ceiling	Damages plaster	10	N	
222	1	107	Primary	Classroom 107	W1	Flaking paint on doors	20	N	
223	1	107	Primary	Classroom 107	W3	Flaking paint on baseboards and behind radiator	20	N	
224	1	108	Primary	Classroom 108	W1	Flaking paint on wall and door	10	N	
225	1	108	Primary	Classroom 108	W2	Flaking paint on baseboard	15	N	
226	1	108	Primary	Classroom 108	W3	Flaking paint below windows and behind radiator	30	Y	
227	1	108B	Storage	Classroom 108 Closet	Ceiling	Cracking paint at ceiling	100	N	
228	1	108B	Storage	Classroom 108 Closet	W3	Flaking paint	5	N	
229	1	108B	Storage	Classroom 108 Closet	W4	Flaking paint on pipe	2	N	
230	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	Ceiling	Flaking paint at ceiling	10	N	
231	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W1	Flaking paint at wall and door	20	N	
232	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W3	Flaking paint at wall and door	5	N	

235	1	111	Storage	Closet at rear of Auditorium	Floor	No access		
236	1	111	Storage	Closet at rear of Auditorium	W1	No access		
237	1	111	Storage	Closet at rear of Auditorium	W2	No access		
238	1	111	Storage	Closet at rear of Auditorium	W3	No access		
239	1	111	Storage	Closet at rear of Auditorium	W4	No access		
240	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	Ceiling	Flaking paint	40	Y
241	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W1	Flaking paint	10	N
242	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W2	Flaking paint	10	N
243	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W3	Flaking paint	20	N
244	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W4	Flaking paint	20	N
245	1	S16	Stairs, Fire Tower	Fire Tower near Classroom 107	Ceiling	Damaged plaster at ceiling	20	N
246	1	114	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Flaking paint at ceiling	15	Y
247	1	114	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Flaking paint at wall.	20	Y
248	1	H16	Circulation (Hallway)	Hallway from Classroom 104 to Teacher's Lounge	W2	Flaking paint behind radiators	20	N
249	1	H18	Circulation (Hallway)	Hallway outside Classrooms 101 to 104	Ceiling	Cracking paint at ceiling.	20	N

253	1	H17	Circulation (Hallway)	Hallway to BET Office	W1	Flaking paint at wall	200	N	
254	1	H17	Circulation (Hallway)	Hallway to BET Office	W3	Flaking paint at wall	30	N	
255	1	115	Administrative Office	Main Office	Ceiling	Flaking paint near windows.	15	Y	
256	1	115	Administrative Office	Main Office	W3	Flaking paint near desk and behind radiator.	20	N	
257	1	108A	Restrooms, Staff - Male	Men's Restroom 109	W3	Flaking paint behind radiator	5	N	
258	1	108A	Restrooms, Staff - Male	Men's Restroom 109	W4	Flaking paint	5	N	
259	1	115B	Administrative Office	Principal's Office	W3	Flaking paint at window sill.	2	N	
260	1	115C	Restrooms, Staff - Male/Female	Principal's Office Restroom	W1	Cracking paint	5	N	
261	1	115C	Restrooms, Staff - Male/Female	Principal's Office Restroom	W2	Cracking paint	5	N	
262	1	S13	Stairs	Stairwell adjacent Classroom 103	W1	Spalling paint from ongoing steam leak.	50	Y	Floor, radiator co
263	1	S13	Stairs	Stairwell adjacent Classroom 103	W2	Flaking paint	40	Y	
264	1	S14	Stairs	Stairwell adjacent to Classroom 106	W1	Flaking paint at wall toward basement	50	Y	
265	1	S17	Stairs	Stairwell near Classroom 108	Ceiling	Flaking paint near Exit.	10	Y	
266	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W1	Flaking paint	10	N	
267	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W2	Flaking paint	5	N	
268	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W3	Flaking paint	20	N	
269	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W4	Flaking paint	5	N	
270	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	Ceiling	Flaking paint	100	Y	
271	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to	W1	Flaking paint	100	Y	

274	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W4	Flaking paint	100	Y	
275	1	119	Restrooms, Staff - Female	Women's Restroom 100	Ceiling	Flaking paint and plaster damage	15	N	
276	0	0B3	Primary	Art Room	Ceiling	Flaking paint at ceiling, pipes, and ducts.	800	N	
277	0	0B3	Primary	Art Room	W2	Flaking paint around windows & trim.	20	Y	
278	0	001	Student Restrooms - Male (4-12)	Basement Boy's Restroom	Ceiling	Flaking paint at ceiling and pipe	200	Y	
279	0	001	Student Restrooms - Male (4-12)	Basement Boy's Restroom	W1	Flaking paint on pipe.	10	N	
280	0	012	Student Restrooms - Female (4-12)	Basement Girl's Restroom	Ceiling	Flaking paint	50	Y	
281	0	012	Student Restrooms - Female (4-12)	Basement Girl's Restroom	W4	Flaking paint at pipe	5	N	
282	0	001A	Storage	Classroom 0B1 Large Closet	Ceiling	Flaking paint	40	Y	
283	0	001A	Storage	Classroom 0B1 Large Closet	W1	Flaking paint	10	N	
284	0	001A	Storage	Classroom 0B1 Large Closet	W2	Flaking paint	10	N	
285	0	001A	Storage	Classroom 0B1 Large Closet	W3	Flaking paint	20	N	
286	0	001A	Storage	Classroom 0B1 Large Closet	W4	Flaking paint	20	Y	
287	0	0B2B	Storage	Classroom 0B2 Large Closet	W1	Flaking paint	20	Y	
288	0	0B2A	Storage	Classroom 0B2 Small Closet	W1	Flaking paint at wall and door.	10	N	
289	0	0B1	Primary	Classroom B1	W1	Flaking paint at closet doors	10	N	
290	0	0B1	Primary	Classroom B1	W2	Damaged plaster	5	N	
291	0	0B1	Primary	Classroom B1	W3	Flaking paint near windows	5	N	
292	0	0B1	Primary	Classroom B1	W4	Damaged plaster	5	N	
293	0	001B	Storage	Classroom B1 Small Closet	Ceiling	Cracking paint	10	N	
294	0	001B	Storage	Classroom B1	W4	Damaged plaster	5	N	

300	0	0B4	Gymnasium - Intermediate Middle	Gym	Ceiling	Flaking paint at ceiling and ducts	500	N	
301	0	0B4	Gymnasium - Intermediate Middle	Gym	W3	Flaking paint at window trim and pipes	30	Y	
302	0	008B	Administrative Office	Gym Office	Ceiling	Flaking paint at ceiling near windows	5	Y	
303	0	008B	Administrative Office	Gym Office	W2	Flaking paint at window trim	5	Y	
304	0	008A	Storage	Gym Storage Room	W1	Flaking paint at door	10	N	
305	0	H01	Circulation (Hallway)	Hallway outside Classrooms B1-B2	Ceiling	Flaking paint on ceiling above ductwork and near Start S17	100	N	
306	0	H02	Circulation (Hallway)	Hallway outside Gym	Ceiling	Flaking paint on deck above ductwork	500	N	
307	0	H02	Circulation (Hallway)	Hallway outside Gym	W1	Flaking paint at pipe.	5	N	
308	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	Ceiling	Flaking paint at ceiling by exit to outdoors	25	Y	
309	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	W2	Flaking paint at wall across from Girls Restroom	10	Y	Floor
310	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	W3	Flaking paint at wall across from Girls Restroom and at window trim.	15	Y	Floor
311	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	W4	Flaking paint at pipe by exit to outdoors	5	N	
312	0	011A	Kitchen	Kitchen	W3	Flaking paint near window behind freezer	10	Y	
313	0	011B	Administrative Office	Kitchen Office	Ceiling	Flaking paint	50	N	
314	0	011B	Administrative Office	Kitchen Office	W2	Flaking paint	15	N	
315	0	011B	Administrative Office	Kitchen Office	W3	Flaking paint	20	N	
316	0	011B	Administrative Office	Kitchen Office	W4	Flaking paint	20	N	
317	0	011B	Cafeteria	Kitchen Office	Ceiling	Spalling paint at concrete	5	Y	

[illegible]