

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	4	401	Primary	Classroom 401	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	4	401	Primary	Classroom 401	yes	W2	Plaster	Pink	None	0	N/A	N/A
1	4	401	Primary	Classroom 401	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	4	401	Primary	Classroom 401	yes	Radiator (W3)	Metal	Grey	Chipping	10	1.9	Positive
1	4	401	Primary	Classroom 401	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	4	401	Primary	Classroom 401	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	401	Primary	Classroom 401	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	401A	Storage	Classroom 401 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	4	401A	Storage	Classroom 401 Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	21.4	Positive
1	4	401A	Storage	Classroom 401 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	4	401A	Storage	Classroom 401 Closet	yes	Radiator (W3)	Metal	Grey	Chipping	2	0.8	Positive
1	4	401A	Storage	Classroom 401 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	4	401A	Storage	Classroom 401 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	401A	Storage	Classroom 401 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	402	Primary	Classroom 402	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	4	402	Primary	Classroom 402	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	4	402	Primary	Classroom 402	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	4	402	Primary	Classroom 402	yes	Radiator (W3)	Metal	Grey	Chipping	10	1	Positive
1	4	402	Primary	Classroom 402	yes	W4	Plaster	White	None	0	N/A	N/A
1	4	402	Primary	Classroom 402	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	402	Primary	Classroom 402	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	402A	Storage	Classroom 402 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	4	402A	Storage	Classroom 402 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	4	402A	Storage	Classroom 402 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	4	402A	Storage	Classroom 402 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	4	402A	Storage	Classroom 402 Closet	yes	Radiator (W4)	Plaster	Beige	None	0	N/A	N/A
1	4	402A	Storage	Classroom 402 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	402A	Storage	Classroom 402 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	403	Primary	Classroom 403	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	4	403	Primary	Classroom 403	yes	W2	Plaster	White	None	0	N/A	N/A
1	4	403	Primary	Classroom 403	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	4	403	Primary	Classroom 403	yes	Radiator (W3)	Metal	Grey	Chipping	10	2.8	Positive
1	4	403	Primary	Classroom 403	yes	W4	Plaster	Beige	Spalling, Efflorescence	3	0	Negative
1	4	403	Primary	Classroom 403	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	403	Primary	Classroom 403	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	403A	Storage	Classroom 403 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	4	403A	Storage	Classroom 403 Closet	yes	W2	Plaster	Beige	Damaged Plaster	4	35.8	Positive
1	4	403A	Storage	Classroom 403 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	4	403A	Storage	Classroom 403 Closet	yes	Radiator (W3)	Metal	Grey	Chipping	4	0.11	Negative
1	4	403A	Storage	Classroom 403 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	4	403A	Storage	Classroom 403 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	403A	Storage	Classroom 403 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	403B	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	yes	W1	Ceramic/Plaster	N/A	N/A	N/A	N/A	N/A
1	4	403B	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	yes	W2	Ceramic/Plaster	N/A	N/A	N/A	N/A	N/A
1	4	403B	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	yes	W3	Ceramic/Plaster	N/A	N/A	N/A	N/A	N/A
1	4	403B	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	yes	Radiator (W3)	Metal	Grey	Chipping	4	0.4	Negative
1	4	403B	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	yes	W4	Ceramic/Plaster	N/A	N/A	N/A	N/A	N/A
1	4	403B	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	403B	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	4	404	Primary	Classroom 404	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	4	404	Primary	Classroom 404	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	4	404	Primary	Classroom 404	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	4	404	Primary	Classroom 404	yes	Radiator (W3)	Metal	Grey	Chipping	10	1.9	Positive
1	4	404	Primary	Classroom 404	yes	W4	Plaster	Green	None	0	N/A	N/A
1	4	404	Primary	Classroom 404	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	404	Primary	Classroom 404	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	404A	Storage	Classroom 404 Closet	yes	W1	Plaster	White	None	0	N/A	N/A
1	4	404A	Storage	Classroom 404 Closet	yes	W2	Plaster	White	None	0	N/A	N/A
1	4	404A	Storage	Classroom 404 Closet	yes	W3	Plaster	White	None	0	N/A	N/A
1	4	404A	Storage	Classroom 404 Closet	yes	W4	Plaster	White	None	0	N/A	N/A
1	4	404A	Storage	Classroom 404 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	404A	Storage	Classroom 404 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	405	Primary	Classroom 405	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	4	405	Primary	Classroom 405	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	4	405	Primary	Classroom 405	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	4	405	Primary	Classroom 405	yes	Radiator (W3)	Metal	Grey	Chipping	10	1.2	Positive
1	4	405	Primary	Classroom 405	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	4	405	Primary	Classroom 405	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	405	Primary	Classroom 405	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	405A	Storage	Classroom 405 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	4	405A	Storage	Classroom 405 Closet	yes	W2	Plaster	Beige	Chipping	4	1.8	Positive

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	4	405A	Storage	Classroom 405 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	4	405A	Storage	Classroom 405 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	4	405A	Storage	Classroom 405 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	405A	Storage	Classroom 405 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	406	Computer - Intermediate Middle	Classroom 406	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	4	406	Computer - Intermediate Middle	Classroom 406	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	4	406	Computer - Intermediate Middle	Classroom 406	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	4	406	Computer - Intermediate Middle	Classroom 406	yes	Radiator (W3)	Metal	Grey	Chipping	10	1.4	Positive
1	4	406	Computer - Intermediate Middle	Classroom 406	yes	W4	Plaster	Purple	None	0	N/A	N/A
1	4	406	Computer - Intermediate Middle	Classroom 406	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	406	Computer - Intermediate Middle	Classroom 406	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	406B	Storage	Classroom 406 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	4	406B	Storage	Classroom 406 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	4	406B	Storage	Classroom 406 Closet	yes	W3	Plaster	Beige	Efflorescence, Flaking	5	26.7	Positive
1	4	406B	Storage	Classroom 406 Closet	yes	Radiator (W3)	Metal	Grey	Chipping	10	1	Positive
1	4	406B	Storage	Classroom 406 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	4	406B	Storage	Classroom 406 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	406B	Storage	Classroom 406 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	406A	Administrative Office	Room 404A Office Adjacent to Classroom 405	yes	W1	Plaster	White	None	0	N/A	N/A
1	4	406A	Administrative Office	Room 404A Office Adjacent to Classroom 405	yes	W2	Plaster	White	None	0	N/A	N/A
1	4	406A	Administrative Office	Room 404A Office Adjacent to Classroom 405	yes	W3	Plaster	White	Efflorescence	1	0	Negative
1	4	406A	Administrative Office	Room 404A Office Adjacent to Classroom 405	yes	Radiator (W3)	Metal	Grey	Chipping	4	0.05	Negative
1	4	406A	Administrative Office	Room 404A Office Adjacent to Classroom 405	yes	W4	Plaster	Purple	None	0	N/A	N/A
1	4	406A	Administrative Office	Room 404A Office Adjacent to Classroom 405	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	406A	Administrative Office	Room 404A Office Adjacent to Classroom 405	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	4	406AB	Restrooms, Staff - Male/Female	Restroom in Room 404A Office Adjacent to Classroom 405	yes	W1	Ceramic/Plaster	Beige	None	0	N/A	N/A
1	4	406AB	Restrooms, Staff - Male/Female	Restroom in Room 404A Office Adjacent to Classroom 405	yes	W2	Ceramic/Plaster	Beige	None	0	N/A	N/A
1	4	406AB	Restrooms, Staff - Male/Female	Restroom in Room 404A Office Adjacent to Classroom 405	yes	W3	Ceramic/Plaster	Beige	None	0	N/A	N/A
1	4	406AB	Restrooms, Staff - Male/Female	Restroom in Room 404A Office Adjacent to Classroom 405	yes	W4	Ceramic/Plaster	Beige	None	0	N/A	N/A
1	4	406AB	Restrooms, Staff - Male/Female	Restroom in Room 404A Office Adjacent to Classroom 405	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	406AB	Restrooms, Staff - Male/Female	Restroom in Room 404A Office Adjacent to Classroom 405	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	407	IMC (Library)	Library (Rooms 407 and 408)	yes	W1	Plaster	Purple	None	0	N/A	N/A
1	4	407	IMC (Library)	Library (Rooms 407 and 408)	yes	W2	Plaster	Orange	None	0	N/A	N/A
1	4	407	IMC (Library)	Library (Rooms 407 and 408)	yes	W3	Plaster	Beige	Efflorescence, Spalling	5	0.02	Negative
1	4	407	IMC (Library)	Library (Rooms 407 and 408)	yes	Radiator (W3)	Metal	Grey	Chipping	6	2	Positive
1	4	407	IMC (Library)	Library (Rooms 407 and 408)	yes	W4	Plaster	Orange	None	0	N/A	N/A
1	4	407	IMC (Library)	Library (Rooms 407 and 408)	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	407	IMC (Library)	Library (Rooms 407 and 408)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	407A	Storage	Library (Room 407 Side Closet)	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	4	407A	Storage	Library (Room 407 Side Closet)	yes	W2	Plaster	Beige	Flaking	1	24.8	Positive
1	4	407A	Storage	Library (Room 407 Side Closet)	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	4	407A	Storage	Library (Room 407 Side Closet)	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	4	407A	Storage	Library (Room 407 Side Closet)	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	4	407A	Storage	Library (Room 407 Side Closet)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	408A	Storage	Library (Room 408 Side Closet)	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	4	408A	Storage	Library (Room 408 Side Closet)	yes	W2	Plaster	Beige	Plaster debris	40	8.2	Positive
1	4	408A	Storage	Library (Room 408 Side Closet)	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	4	408A	Storage	Library (Room 408 Side Closet)	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	4	408A	Storage	Library (Room 408 Side Closet)	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	4	408A	Storage	Library (Room 408 Side Closet)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	4	409	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 406	yes	W1	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	4	409	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 406	yes	W2	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	4	409	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 406	yes	W3	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	4	409	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 406	yes	Radiator (W3)	Metal	Grey	Chipping	3	1.1	Positive

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	4	409	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 406	yes	W4	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	4	409	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 406	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	409	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 406	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	4	409A	Service Closets	Custodial Closet next to Girl's Restroom	no	W1						
1	4	409A	Service Closets	Custodial Closet next to Girl's Restroom	no	W2						
1	4	409A	Service Closets	Custodial Closet next to Girl's Restroom	no	W3						
1	4	409A	Service Closets	Custodial Closet next to Girl's Restroom	no	W4						
1	4	409A	Service Closets	Custodial Closet next to Girl's Restroom	no	Ceiling						
1	4	409A	Service Closets	Custodial Closet next to Girl's Restroom	no	Floor						
1	4	H415	Circulation (Hallway)	Hallway along IMC	yes	W1	Plaster	White/Grey	None	0	N/A	N/A
1	4	H415	Circulation (Hallway)	Hallway along IMC	yes	W2	Plaster	White/Grey	None	0	N/A	N/A
1	4	H415	Circulation (Hallway)	Hallway along IMC	yes	Radiator (W2)	Metal	Grey	Chipping	10	4.6	Positive
1	4	H415	Circulation (Hallway)	Hallway along IMC	yes	W3	Plaster	White/Grey	None	0	N/A	N/A
1	4	H415	Circulation (Hallway)	Hallway along IMC	yes	W4	Plaster	White/Grey	None	0	N/A	N/A
1	4	H415	Circulation (Hallway)	Hallway along IMC	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	H415	Circulation (Hallway)	Hallway along IMC	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	H416	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	W1	Plaster	Yellow/Grey	None	0	N/A	N/A
1	4	H416	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	W2	Plaster	Yellow/Grey	None	0	N/A	N/A
1	4	H416	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	W3	Plaster	Yellow	Efflorescence, Spalling	5	11.6	Positive
1	4	H416	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	W3	Plaster	Grey	Efflorescence, Spalling	7	21.7	Positive
1	4	H416	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	Radiator (W3)	Metal	Grey	Chipping	10	2.1	Positive
1	4	H416	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	W4	Plaster	Yellow/Grey	None	0	N/A	N/A
1	4	H416	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	H416	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	H417	Circulation (Hallway)	Hallway from Room 401 to Room 402	yes	W1	Plaster	White/Grey	None	0	N/A	N/A
1	4	H417	Circulation (Hallway)	Hallway from Room 401 to Room 402	yes	W2	Plaster	White	Partially Inaccessible	0	32.8	Positive
1	4	H417	Circulation (Hallway)	Hallway from Room 401 to Room 402	yes	W2	Plaster	Grey	Partially Inaccessible	0	23.5	Positive

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	4	H417	Circulation (Hallway)	Hallway from Room 401 to Room 402	yes	W3	Plaster	White/Grey	None	0	N/A	N/A
1	4	H417	Circulation (Hallway)	Hallway from Room 401 to Room 402	yes	W4	Plaster	White	Efflorescence	10	24	Positive
1	4	H417	Circulation (Hallway)	Hallway from Room 401 to Room 402	yes	W4	Plaster	Grey	Efflorescence	5	1.3	Positive
1	4	H417	Circulation (Hallway)	Hallway from Room 401 to Room 402	yes	Radiator (W4)	Metal	Grey	Chipping	10	1.5	Positive
1	4	H417	Circulation (Hallway)	Hallway from Room 401 to Room 402	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	H417	Circulation (Hallway)	Hallway from Room 401 to Room 402	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	S41	Stairs	4th Floor Stairwell Across from Classroom 406	yes	W1	Plaster	White/Green	None	0	N/A	N/A
1	4	S41	Stairs	4th Floor Stairwell Across from Classroom 406	yes	W2	Plaster	White/Green	None	0	N/A	N/A
1	4	S41	Stairs	4th Floor Stairwell Across from Classroom 406	yes	W3	Plaster	White/Green	None	0	N/A	N/A
1	4	S41	Stairs	4th Floor Stairwell Across from Classroom 406	yes	Radiator (W3)	Metal	Grey	Chipping	10	2.3	Positive
1	4	S41	Stairs	4th Floor Stairwell Across from Classroom 406	yes	W4	Plaster	White/Green	None	0	N/A	N/A
1	4	S41	Stairs	4th Floor Stairwell Across from Classroom 406	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	S41	Stairs	4th Floor Stairwell Across from Classroom 406	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	S42	Stairs	4th Floor Stairwell Across from Classroom 404	yes	W1	Plaster	White/Blue	None	0	N/A	N/A
1	4	S42	Stairs	4th Floor Stairwell Across from Classroom 404	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
1	4	S42	Stairs	4th Floor Stairwell Across from Classroom 404	yes	W3	Plaster	White/Blue	None	0	N/A	N/A
1	4	S42	Stairs	4th Floor Stairwell Across from Classroom 404	yes	Radiator (W3)	Metal	Grey	Chipping	10	2.1	Positive
1	4	S42	Stairs	4th Floor Stairwell Across from Classroom 404	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
1	4	S42	Stairs	4th Floor Stairwell Across from Classroom 404	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	S42	Stairs	4th Floor Stairwell Across from Classroom 404	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	S43A	Circulation (Hallway)	Walkway in 4th Floor Fire Tower near Classroom 401	yes	W1	Brick	White	None	0	N/A	N/A
1	4	S43A	Circulation (Hallway)	Walkway in 4th Floor Fire Tower near Classroom 401	yes	W2	Brick	White	None	0	N/A	N/A
1	4	S43A	Circulation (Hallway)	Walkway in 4th Floor Fire Tower near Classroom 401	yes	W3	Brick	White	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	4	S43A	Circulation (Hallway)	Walkway in 4th Floor Fire Tower near Classroom 401	yes	Drain Pipe (W3)	Metal	Grey	Flaking	5	9.1	Positive
1	4	S43A	Circulation (Hallway)	Walkway in 4th Floor Fire Tower near Classroom 401	yes	Window sill/Grates (W3/W4)	Metal	Grey	Flaking	50	6.7	Positive
1	4	S43A	Circulation (Hallway)	Walkway in 4th Floor Fire Tower near Classroom 401	yes	W4	Brick	White	None	0	N/A	N/A
1	4	S43A	Circulation (Hallway)	Walkway in 4th Floor Fire Tower near Classroom 401	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	4	S43A	Circulation (Hallway)	Walkway in 4th Floor Fire Tower near Classroom 401	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	S43	Stairs	4th Floor Fire Tower near Classroom 401	yes	W1	Brick	White	None	0	N/A	N/A
1	4	S43	Stairs	4th Floor Fire Tower near Classroom 401	yes	W2	Brick	White	None	0	N/A	N/A
1	4	S43	Stairs	4th Floor Fire Tower near Classroom 401	yes	W3	Brick	White	None	0	N/A	N/A
1	4	S43	Stairs	4th Floor Fire Tower near Classroom 401	yes	W4	Brick	White	Efflorescence, Spalling	80	2.7	Positive
1	4	S43	Stairs	4th Floor Fire Tower near Classroom 401	yes	Ceiling	Concrete	White	Crack, loose pieces hanging	10	1.7	Positive
1	4	S43	Stairs	4th Floor Fire Tower near Classroom 401	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	S44A	Circulation (Hallway)	Walkway in 4th Floor Fire Tower near IMC (Room 408)	yes	W1	Brick	White	None	0	N/A	N/A
1	4	S44A	Circulation (Hallway)	Walkway in 4th Floor Fire Tower near IMC (Room 408)	yes	W2	Brick	White	None	0	N/A	N/A
1	4	S44A	Circulation (Hallway)	Walkway in 4th Floor Fire Tower near IMC (Room 408)	yes	W3	Brick	White	None	0	N/A	N/A
1	4	S44A	Circulation (Hallway)	Walkway in 4th Floor Fire Tower near IMC (Room 408)	yes	Window sill/Grates (W3/W4)	Metal	Grey	Flaking	50	9.7	Positive
1	4	S44A	Circulation (Hallway)	Walkway in 4th Floor Fire Tower near IMC (Room 408)	yes	W4	Brick	White	None	0	N/A	N/A
1	4	S44A	Circulation (Hallway)	Walkway in 4th Floor Fire Tower near IMC (Room 408)	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	4	S44A	Circulation (Hallway)	Walkway in 4th Floor Fire Tower near IMC (Room 408)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	S44	Stairs	4th Floor Fire Tower near IMC (Room 408)	yes	W1	Brick	White	None	0	N/A	N/A
1	4	S44	Stairs	4th Floor Fire Tower near IMC (Room 408)	yes	W2	Brick	White	Efflorescence, Flaking	50	5.6	Positive
1	4	S44	Stairs	4th Floor Fire Tower near IMC (Room 408)	yes	W3	Brick	White	None	0	N/A	N/A
1	4	S44	Stairs	4th Floor Fire Tower near IMC (Room 408)	yes	W4	Brick	White	None	0	N/A	N/A
1	4	S44	Stairs	4th Floor Fire Tower near IMC (Room 408)	yes	Ceiling	Concrete	White	Spalling, Crack in ceiling	6	2	Positive
1	4	S44	Stairs	4th Floor Fire Tower near IMC (Room 408)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	S31	Stairs	3rd Floor Stairwell near Classroom 306	yes	W1	Plaster	White/Green	None	0	N/A	N/A
1	3	S31	Stairs	3rd Floor Stairwell near Classroom 306	yes	W2	Plaster	White/Green	None	0	N/A	N/A
1	3	S31	Stairs	3rd Floor Stairwell near Classroom 306	yes	W3	Plaster	White/Green	None	0	N/A	N/A
1	3	S31	Stairs	3rd Floor Stairwell near Classroom 306	yes	Radiator (W3)	Metal	Grey	Chipping	6	0.14	Negative
1	3	S31	Stairs	3rd Floor Stairwell near Classroom 306	yes	W4	Plaster	White/Green	None	0	N/A	N/A
1	3	S31	Stairs	3rd Floor Stairwell near Classroom 306	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	S31	Stairs	3rd Floor Stairwell near Classroom 306	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	S32	Stairs	3rd Floor Stairwell across from Classroom 304	yes	W1	Plaster	White/Blue	None	0	N/A	N/A
1	3	S32	Stairs	3rd Floor Stairwell across from Classroom 304	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
1	3	S32	Stairs	3rd Floor Stairwell across from Classroom 304	yes	W3	Plaster	White/Blue	None	0	N/A	N/A
1	3	S32	Stairs	3rd Floor Stairwell across from Classroom 304	yes	Radiator (W3)	Metal	Grey	Chipping	6	0.19	Negative
1	3	S32	Stairs	3rd Floor Stairwell across from Classroom 304	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
1	3	S32	Stairs	3rd Floor Stairwell across from Classroom 304	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	S32	Stairs	3rd Floor Stairwell across from Classroom 304	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	S33A	Circulation (Hallway)	Walkway in 3rd Floor Fire Tower near Classroom 301	yes	W1	Brick	White	None	0	N/A	N/A
1	3	S33A	Circulation (Hallway)	Walkway in 3rd Floor Fire Tower near Classroom 301	yes	W2	Brick	White	None	0	N/A	N/A
1	3	S33A	Circulation (Hallway)	Walkway in 3rd Floor Fire Tower near Classroom 301	yes	W3	Brick	White	Flaking	6	27.9	Positive
1	3	S33A	Circulation (Hallway)	Walkway in 3rd Floor Fire Tower near Classroom 301	yes	Window sill/Grates (W3/W4)	Metal	Grey	Chipping, Flaking	50	5.1	Positive
1	3	S33A	Circulation (Hallway)	Walkway in 3rd Floor Fire Tower near Classroom 301	yes	W4	Brick	White	Flaking	10	3.8	Positive
1	3	S33A	Circulation (Hallway)	Walkway in 3rd Floor Fire Tower near Classroom 301	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	S33A	Circulation (Hallway)	Walkway in 3rd Floor Fire Tower near Classroom 301	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	S33	Stairs	3rd Floor Fire Tower near Classroom 301	yes	W1	Brick	White	None	0	N/A	N/A
1	3	S33	Stairs	3rd Floor Fire Tower near Classroom 301	yes	W2	Brick	White	None	0	N/A	N/A
1	3	S33	Stairs	3rd Floor Fire Tower near Classroom 301	yes	W3	Brick	White	None	0	N/A	N/A
1	3	S33	Stairs	3rd Floor Fire Tower near Classroom 301	yes	W4	Brick	White	Flaking	10	3.8	Positive
1	3	S33	Stairs	3rd Floor Fire Tower near Classroom 301	yes	Ceiling	Concrete	White	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	S33	Stairs	3rd Floor Fire Tower near Classroom 301	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	S34A	Circulation (Hallway)	Walkway in 3rd Floor Fire Tower near Classroom 308	yes	W1	Brick	White	None	0	N/A	N/A
1	3	S34A	Circulation (Hallway)	Walkway in 3rd Floor Fire Tower near Classroom 308	yes	W2	Brick	White	None	0	N/A	N/A
1	3	S34A	Circulation (Hallway)	Walkway in 3rd Floor Fire Tower near Classroom 308	yes	W3	Brick	White	None	0	N/A	N/A
1	3	S34A	Circulation (Hallway)	Walkway in 3rd Floor Fire Tower near Classroom 308	yes	Window sill/Grates (W3/W4)	Metal	Grey	Chipping, Flaking	50	7.2	Positive
1	3	S34A	Circulation (Hallway)	Walkway in 3rd Floor Fire Tower near Classroom 308	yes	W4	Brick	White	None	0	N/A	N/A
1	3	S34A	Circulation (Hallway)	Walkway in 3rd Floor Fire Tower near Classroom 308	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	S34A	Circulation (Hallway)	Walkway in 3rd Floor Fire Tower near Classroom 308	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	S34	Stairs	3rd Floor Fire Tower near Classroom 308	yes	W1	Brick	White	None	0	N/A	N/A
1	3	S34	Stairs	3rd Floor Fire Tower near Classroom 308	yes	W2	Brick	White	None	0	N/A	N/A
1	3	S34	Stairs	3rd Floor Fire Tower near Classroom 308	yes	W3	Brick	White	None	0	N/A	N/A
1	3	S34	Stairs	3rd Floor Fire Tower near Classroom 308	yes	W4	Brick	White	None	0	N/A	N/A
1	3	S34	Stairs	3rd Floor Fire Tower near Classroom 308	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	S34	Stairs	3rd Floor Fire Tower near Classroom 308	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	300	Teacher Lounge/Dining	Room 305A Former Teacher's Lounge	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	300	Teacher Lounge/Dining	Room 305A Former Teacher's Lounge	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	300	Teacher Lounge/Dining	Room 305A Former Teacher's Lounge	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	300	Teacher Lounge/Dining	Room 305A Former Teacher's Lounge	yes	Radiator (W3)	Metal	Grey	Chipping	6	0.03	Negative
1	3	300	Teacher Lounge/Dining	Room 305A Former Teacher's Lounge	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	300	Teacher Lounge/Dining	Room 305A Former Teacher's Lounge	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	300	Teacher Lounge/Dining	Room 305A Former Teacher's Lounge	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	300A	Satellite Kitchen	Room 305A Teacher's Lounge Former Kitchenette	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	300A	Satellite Kitchen	Room 305A Teacher's Lounge Former Kitchenette	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	300A	Satellite Kitchen	Room 305A Teacher's Lounge Former Kitchenette	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	300A	Satellite Kitchen	Room 305A Teacher's Lounge Former Kitchenette	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	300A	Satellite Kitchen	Room 305A Teacher's Lounge Former Kitchenette	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	300A	Satellite Kitchen	Room 305A Teacher's Lounge Former Kitchenette	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	301	Primary	Classroom 301	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	301	Primary	Classroom 301	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	301	Primary	Classroom 301	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	301	Primary	Classroom 301	yes	Radiator (W3)	Metal	Grey	Chipping	8	0.06	Negative
1	3	301	Primary	Classroom 301	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	301	Primary	Classroom 301	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301	Primary	Classroom 301	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	301A	Storage	Classroom 301 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	301A	Storage	Classroom 301 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	301A	Storage	Classroom 301 Closet	yes	Radiator (W2)	Metal	Grey	Chipping	6	0.5	Negative
1	3	301A	Storage	Classroom 301 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	301A	Storage	Classroom 301 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	301A	Storage	Classroom 301 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301A	Storage	Classroom 301 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	302	Primary	Classroom 302	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	302	Primary	Classroom 302	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	302	Primary	Classroom 302	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	302	Primary	Classroom 302	yes	Radiator (W3)	Metal	Grey	Chipping	10	2	Positive
1	3	302	Primary	Classroom 302	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	302	Primary	Classroom 302	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	302	Primary	Classroom 302	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	302A	Storage	Classroom 302 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	302A	Storage	Classroom 302 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	302A	Storage	Classroom 302 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	302A	Storage	Classroom 302 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	302A	Storage	Classroom 302 Closet	yes	Radiator (W4)	Metal	Grey	Chipping	4	0.23	Negative
1	3	302A	Storage	Classroom 302 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	302A	Storage	Classroom 302 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	303	Primary	Classroom 303	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	303	Primary	Classroom 303	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	303	Primary	Classroom 303	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	303	Primary	Classroom 303	yes	Radiator (W3)	Metal	Grey	Chipping	12	0.17	Negative
1	3	303	Primary	Classroom 303	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	303	Primary	Classroom 303	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303	Primary	Classroom 303	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	303B	Storage	Classroom 303 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	303B	Storage	Classroom 303 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	303B	Storage	Classroom 303 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	303B	Storage	Classroom 303 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	303B	Storage	Classroom 303 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	303B	Storage	Classroom 303 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	303A	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	yes	W1	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	3	303A	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	yes	W2	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	3	303A	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	yes	W3	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	3	303A	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	yes	Radiator (W3)	Metal	Grey	Chipping	6	0.11	Negative
1	3	303A	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	yes	W4	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	3	303A	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	303A	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	304	Primary	Classroom 304	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	304	Primary	Classroom 304	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	304	Primary	Classroom 304	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	304	Primary	Classroom 304	yes	Column (W3)	Plaster	Beige	Chipping	1	24.6	Positive
1	3	304	Primary	Classroom 304	yes	Radiator (W3)	Metal	Grey	Chipping	12	0.7	Positive
1	3	304	Primary	Classroom 304	yes	W4	Plaster	Purple	None	0	N/A	N/A
1	3	304	Primary	Classroom 304	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	304	Primary	Classroom 304	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	304A	Storage	Classroom 304 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	304A	Storage	Classroom 304 Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	21.5	Positive
1	3	304A	Storage	Classroom 304 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	304A	Storage	Classroom 304 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	304A	Storage	Classroom 304 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	304A	Storage	Classroom 304 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	305	Primary	Classroom 305	yes	W1	Plaster	Purple	None	0	N/A	N/A
1	3	305	Primary	Classroom 305	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	305	Primary	Classroom 305	yes	W3	Plaster	Beige	Spalling	1	0.07	Negative
1	3	305	Primary	Classroom 305	yes	Radiator (W3)	Metal	Grey	Chipping	6	2.6	Positive
1	3	305	Primary	Classroom 305	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	305	Primary	Classroom 305	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	305	Primary	Classroom 305	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	305A	Storage	Classroom 305 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	305A	Storage	Classroom 305 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	305A	Storage	Classroom 305 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	305A	Storage	Classroom 305 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	305A	Storage	Classroom 305 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	305A	Storage	Classroom 305 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	306	Primary	Classroom 306	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	306	Primary	Classroom 306	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	306	Primary	Classroom 306	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	306	Primary	Classroom 306	yes	Radiator (W3)	Metal	Grey	Chipping	12	0.29	Negative
1	3	306	Primary	Classroom 306	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	3	306	Primary	Classroom 306	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306	Primary	Classroom 306	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	306A	Storage	Classroom 306 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	306A	Storage	Classroom 306 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	306A	Storage	Classroom 306 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	306A	Storage	Classroom 306 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	306A	Storage	Classroom 306 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306A	Storage	Classroom 306 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	307	Primary	Classroom 307	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	307	Primary	Classroom 307	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	307	Primary	Classroom 307	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	307	Primary	Classroom 307	yes	Radiator (W3)	Metal	Grey	Chipping	12	0.19	Negative
1	3	307	Primary	Classroom 307	yes	W4	Plaster	Grey	None	0	N/A	N/A
1	3	307	Primary	Classroom 307	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307	Primary	Classroom 307	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	307A	Storage	Classroom 307 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	307A	Storage	Classroom 307 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	307A	Storage	Classroom 307 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	3	307A	Storage	Classroom 307 Closet	yes	Radiator (W3)	Metal	Grey	Chipping	12	0.27	Negative
1	3	307A	Storage	Classroom 307 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	3	307A	Storage	Classroom 307 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307A	Storage	Classroom 307 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	308	Primary	Classroom 308	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	308	Primary	Classroom 308	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	3	308	Primary	Classroom 308	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	308	Primary	Classroom 308	yes	Radiator (W3)	Metal	Grey	Chipping	12	0.11	Negative
1	3	308	Primary	Classroom 308	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	3	308	Primary	Classroom 308	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	308	Primary	Classroom 308	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	308A	Storage	Classroom 308 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	3	308A	Storage	Classroom 308 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	308A	Storage	Classroom 308 Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	36.7	Positive
1	3	308A	Storage	Classroom 308 Closet	yes	Radiator (W3)	Metal	Grey	Chipping	12	0.12	Negative
1	3	308A	Storage	Classroom 308 Closet	yes	W4	Plaster	Beige	Partially Inaccessible	0	30.1	Positive
1	3	308A	Storage	Classroom 308 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	308A	Storage	Classroom 308 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	309	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	yes	W1	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	3	309	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	yes	W2	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	3	309	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	yes	W3	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	3	309	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	yes	Radiator (W3)	Metal	Grey	Chipping	4	0.26	Negative
1	3	309	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	yes	W4	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	3	309	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	3	309	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	yes	Floor	Concrete	White	None	0	N/A	N/A
1	3	309A	Service Closets	Custodial Closet next to Girl's Restroom	no	W1						
1	3	309A	Service Closets	Custodial Closet next to Girl's Restroom	no	W2						
1	3	309A	Service Closets	Custodial Closet next to Girl's Restroom	no	W3						
1	3	309A	Service Closets	Custodial Closet next to Girl's Restroom	no	W4						
1	3	309A	Service Closets	Custodial Closet next to Girl's Restroom	no	Ceiling						
1	3	309A	Service Closets	Custodial Closet next to Girl's Restroom	no	Floor						
1	3	H313	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	W1	Plaster	White/Purple	None	0	N/A	N/A
1	3	H313	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	W2	Plaster	White/Purple	None	0	N/A	N/A
1	3	H313	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	W3	Plaster	White/Purple	None	0	N/A	N/A
1	3	H313	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	W4	Plaster	White/Purple	None	0	N/A	N/A
1	3	H313	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	H313	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	H312	Circulation (Hallway)	Hallway along Classrooms 307 and 308	yes	W1	Plaster	White/Blue	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	H312	Circulation (Hallway)	Hallway along Classrooms 307 and 308	yes	W2	Plaster	Blue	Spalling	3	14.9	Positive
1	3	H312	Circulation (Hallway)	Hallway along Classrooms 307 and 308	yes	W3	Plaster	White/Blue	None	0	N/A	N/A
1	3	H312	Circulation (Hallway)	Hallway along Classrooms 307 and 308	yes	Radiator (W3)	Metal	Grey	Chipping	12	2.3	Positive
1	3	H312	Circulation (Hallway)	Hallway along Classrooms 307 and 308	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
1	3	H312	Circulation (Hallway)	Hallway along Classrooms 307 and 308	yes	Ceiling	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	H312	Circulation (Hallway)	Hallway along Classrooms 307 and 308	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	H314	Circulation (Hallway)	Hallway along Classrooms 301 and 302	yes	W1	Plaster	White/Blue	None	0	N/A	N/A
1	3	H314	Circulation (Hallway)	Hallway along Classrooms 301 and 302	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
1	3	H314	Circulation (Hallway)	Hallway along Classrooms 301 and 302	yes	W3	Plaster	White/Blue	None	0	N/A	N/A
1	3	H314	Circulation (Hallway)	Hallway along Classrooms 301 and 302	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
1	3	H314	Circulation (Hallway)	Hallway along Classrooms 301 and 302	yes	Radiator (W4)	Metal	Grey	Chipping	12	0.9	Positive
1	3	H314	Circulation (Hallway)	Hallway along Classrooms 301 and 302	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H314	Circulation (Hallway)	Hallway along Classrooms 301 and 302	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	200	Student Restrooms - Male (4-12)	Boy's Restroom near Elevator	yes	W1	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	2	200	Student Restrooms - Male (4-12)	Boy's Restroom near Elevator	yes	W2	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	2	200	Student Restrooms - Male (4-12)	Boy's Restroom near Elevator	yes	W3	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	2	200	Student Restrooms - Male (4-12)	Boy's Restroom near Elevator	yes	W4	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	2	200	Student Restrooms - Male (4-12)	Boy's Restroom near Elevator	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	200	Student Restrooms - Male (4-12)	Boy's Restroom near Elevator	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	201	Primary	Classroom 201	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	201	Primary	Classroom 201	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	201	Primary	Classroom 201	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	201	Primary	Classroom 201	yes	Radiator (W3)	Metal	Grey	Chipping	10	1.2	Positive
1	2	201	Primary	Classroom 201	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	2	201	Primary	Classroom 201	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Primary	Classroom 201	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	201A	Storage	Classroom 201 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	201A	Storage	Classroom 201 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	201A	Storage	Classroom 201 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	201A	Storage	Classroom 201 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	201A	Storage	Classroom 201 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201A	Storage	Classroom 201 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	202	Primary	Classroom 202	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	202	Primary	Classroom 202	yes	W2	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	202	Primary	Classroom 202	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	202	Primary	Classroom 202	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	202	Primary	Classroom 202	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Primary	Classroom 202	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	202A	Student Restrooms - Male/Female (Classroom)	Classroom 202 Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	202A	Student Restrooms - Male/Female (Classroom)	Classroom 202 Restroom	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	202A	Student Restrooms - Male/Female (Classroom)	Classroom 202 Restroom	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	202A	Student Restrooms - Male/Female (Classroom)	Classroom 202 Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	202A	Student Restrooms - Male/Female (Classroom)	Classroom 202 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202A	Student Restrooms - Male/Female (Classroom)	Classroom 202 Restroom	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	202B	Storage	Classroom 202 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	202B	Storage	Classroom 202 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	202B	Storage	Classroom 202 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	202B	Storage	Classroom 202 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	202B	Storage	Classroom 202 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202B	Storage	Classroom 202 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	203	ESE Full Time	Classroom 203	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	203	ESE Full Time	Classroom 203	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	203	ESE Full Time	Classroom 203	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	203	ESE Full Time	Classroom 203	yes	W4	Plaster	Beige	Efflorescence, Spalling	5	25.1	Positive
1	2	203	ESE Full Time	Classroom 203	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	ESE Full Time	Classroom 203	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	203A	Student Restrooms - Male/Female (Classroom)	Classroom 203 Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	203A	Student Restrooms - Male/Female (Classroom)	Classroom 203 Restroom	yes	W2	Plaster	Beige	Partially Inaccessible	0	13	Positive
1	2	203A	Student Restrooms - Male/Female (Classroom)	Classroom 203 Restroom	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	203A	Student Restrooms - Male/Female (Classroom)	Classroom 203 Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	203A	Student Restrooms - Male/Female (Classroom)	Classroom 203 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	203A	Student Restrooms - Male/Female (Classroom)	Classroom 203 Restroom	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	203B	Data Processing Equipment	Computer Server Room next to Classroom 203	no	W1						
1	2	203B	Data Processing Equipment	Computer Server Room next to Classroom 203	no	W2						
1	2	203B	Data Processing Equipment	Computer Server Room next to Classroom 203	no	W3						
1	2	203B	Data Processing Equipment	Computer Server Room next to Classroom 203	no	W4						
1	2	203B	Data Processing Equipment	Computer Server Room next to Classroom 203	no	Ceiling						
1	2	203B	Data Processing Equipment	Computer Server Room next to Classroom 203	no	Floor						
1	2	204	Administrative Office	Room 204 Teacher's Office	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	204	Administrative Office	Room 204 Teacher's Office	yes	W2	Plaster	Beige	Partially Inaccessible	0	0	Negative
1	2	204	Administrative Office	Room 204 Teacher's Office	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	204	Administrative Office	Room 204 Teacher's Office	yes	Radiator (W3)	Metal	Grey	Chipping	10	1	Positive
1	2	204	Administrative Office	Room 204 Teacher's Office	yes	W4	Plaster	Beige	Partially Inaccessible	0	31.2	Positive
1	2	204	Administrative Office	Room 204 Teacher's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204	Administrative Office	Room 204 Teacher's Office	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	204A	Administrative Office	Office Adjacent to Teacher's Lounge	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	204A	Administrative Office	Office Adjacent to Teacher's Lounge	yes	W2	Plaster	Beige	Partially Inaccessible	0	0	Negative
1	2	204A	Administrative Office	Office Adjacent to Teacher's Lounge	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	204A	Administrative Office	Office Adjacent to Teacher's Lounge	yes	Radiator (W3)	Metal	Grey	Chipping	2	2.1	Positive
1	2	204A	Administrative Office	Office Adjacent to Teacher's Lounge	yes	W4	Plaster	Beige	Partially Inaccessible	0	0	Negative
1	2	204A	Administrative Office	Office Adjacent to Teacher's Lounge	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204A	Administrative Office	Office Adjacent to Teacher's Lounge	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	204B	Storage	Room 204 Teacher's Office Rear Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	204B	Storage	Room 204 Teacher's Office Rear Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	204B	Storage	Room 204 Teacher's Office Rear Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	204B	Storage	Room 204 Teacher's Office Rear Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	204B	Storage	Room 204 Teacher's Office Rear Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204B	Storage	Room 204 Teacher's Office Rear Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	204C	Storage	Room 204A Office Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	204C	Storage	Room 204A Office Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	204C	Storage	Room 204A Office Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	204C	Storage	Room 204A Office Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	204C	Storage	Room 204A Office Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204C	Storage	Room 204A Office Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	205	Administrative Office	Room 205 Counselor's Office	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	205	Administrative Office	Room 205 Counselor's Office	yes	W2	Plaster	Beige	Partially Inaccessible	0	0	Negative
1	2	205	Administrative Office	Room 205 Counselor's Office	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	205	Administrative Office	Room 205 Counselor's Office	yes	W4	Plaster	Yellow	Partially Inaccessible	0	0	Negative
1	2	205	Administrative Office	Room 205 Counselor's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	Administrative Office	Room 205 Counselor's Office	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	205A	Teacher Lounge/Dining	Room 204 A Teacher's Lounge	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	205A	Teacher Lounge/Dining	Room 204 A Teacher's Lounge	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	205A	Teacher Lounge/Dining	Room 204 A Teacher's Lounge	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	205A	Teacher Lounge/Dining	Room 204 A Teacher's Lounge	yes	Radiator (W3)	Metal	Grey	Chipping	6	1.1	Positive
1	2	205A	Teacher Lounge/Dining	Room 204 A Teacher's Lounge	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	205A	Teacher Lounge/Dining	Room 204 A Teacher's Lounge	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205A	Teacher Lounge/Dining	Room 204 A Teacher's Lounge	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	205B	Storage	Storage in Room 205 Counselor's Office	yes	W1	Plaster	Beige	Partially Inaccessible	0	13	Positive
1	2	205B	Storage	Storage in Room 205 Counselor's Office	yes	W2	Plaster	Beige	Partially Inaccessible	0	13.3	Positive
1	2	205B	Storage	Storage in Room 205 Counselor's Office	yes	W3	Plaster	Beige	Partially Inaccessible	0	12.5	Positive
1	2	205B	Storage	Storage in Room 205 Counselor's Office	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	205B	Storage	Storage in Room 205 Counselor's Office	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	2	205B	Storage	Storage in Room 205 Counselor's Office	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	206	Primary	Classroom 206	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	206	Primary	Classroom 206	yes	W2	Plaster	Beige	Partially Inaccessible	0	34.1	Positive
1	2	206	Primary	Classroom 206	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	206	Primary	Classroom 206	yes	W4	Plaster	Green	Partially Inaccessible	0	25	Positive
1	2	206	Primary	Classroom 206	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Primary	Classroom 206	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	206C	Storage	Classroom 206 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	206C	Storage	Classroom 206 Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	22.5	Positive
1	2	206C	Storage	Classroom 206 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	206C	Storage	Classroom 206 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	206C	Storage	Classroom 206 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206C	Storage	Classroom 206 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	206B	Circulation (Hallway)	Hallway between Rooms 205 and 206A	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	206B	Circulation (Hallway)	Hallway between Rooms 205 and 206A	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	206B	Circulation (Hallway)	Hallway between Rooms 205 and 206A	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	206B	Circulation (Hallway)	Hallway between Rooms 205 and 206A	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	206B	Circulation (Hallway)	Hallway between Rooms 205 and 206A	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206B	Circulation (Hallway)	Hallway between Rooms 205 and 206A	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	206A	Administrative Office	Room 206A Counselor's Office	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	206A	Administrative Office	Room 206A Counselor's Office	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	206A	Administrative Office	Room 206A Counselor's Office	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	206A	Administrative Office	Room 206A Counselor's Office	yes	Radiator (W3)	Metal	Grey	Chipping	6	0.9	Positive
1	2	206A	Administrative Office	Room 206A Counselor's Office	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	206A	Administrative Office	Room 206A Counselor's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206A	Administrative Office	Room 206A Counselor's Office	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	207	Primary	Classroom 207	yes	W1	Plaster	Beige	Partially Inaccessible	0	34.5	Positive
1	2	207	Primary	Classroom 207	yes	W2	Plaster	Beige	Partially Inaccessible	0	0	Negative
1	2	207	Primary	Classroom 207	yes	W3	Plaster	Blue	Partially Inaccessible	0	4.6	Positive
1	2	207	Primary	Classroom 207	yes	Radiator (W3)	Metal	Grey	Chipping	10	1.9	Positive
1	2	207	Primary	Classroom 207	yes	W4	Plaster	Blue	Partially Inaccessible	0	32.5	Positive
1	2	207	Primary	Classroom 207	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Primary	Classroom 207	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	207A	Storage	Classroom 207 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	207A	Storage	Classroom 207 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	207A	Storage	Classroom 207 Closet	yes	Radiator (W2)	Metal	Grey	Chipping	2	1.5	Positive
1	2	207A	Storage	Classroom 207 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	207A	Storage	Classroom 207 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	207A	Storage	Classroom 207 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	Storage	Classroom 207 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	207B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 206	yes	W1	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	2	207B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 206	yes	W2	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	2	207B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 206	yes	W3	Plaster/Ceramic	Beige	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	207B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 206	yes	Radiator Cover (W3)	Metal	Brown	Chipping	1	0	Negative
1	2	207B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 206	yes	W4	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	2	207B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 206	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	207B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 206	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	207C	Service Closets	Custodial Closet next to Girl's Restroom	no	W1						
1	2	207C	Service Closets	Custodial Closet next to Girl's Restroom	no	W2						
1	2	207C	Service Closets	Custodial Closet next to Girl's Restroom	no	W3						
1	2	207C	Service Closets	Custodial Closet next to Girl's Restroom	no	W4						
1	2	207C	Service Closets	Custodial Closet next to Girl's Restroom	no	Ceiling						
1	2	207C	Service Closets	Custodial Closet next to Girl's Restroom	no	Floor						
1	2	208A	Student Restrooms - Male/Female (Classroom)	Classroom 208 Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	208A	Student Restrooms - Male/Female (Classroom)	Classroom 208 Restroom	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	208A	Student Restrooms - Male/Female (Classroom)	Classroom 208 Restroom	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	208A	Student Restrooms - Male/Female (Classroom)	Classroom 208 Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	208A	Student Restrooms - Male/Female (Classroom)	Classroom 208 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208A	Student Restrooms - Male/Female (Classroom)	Classroom 208 Restroom	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	208B	Storage	Classroom 208 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	208B	Storage	Classroom 208 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	208B	Storage	Classroom 208 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	208B	Storage	Classroom 208 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	208B	Storage	Classroom 208 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208B	Storage	Classroom 208 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	208	Administrative Office	Room 208 ESOL Office	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	208	Administrative Office	Room 208 ESOL Office	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	208	Administrative Office	Room 208 ESOL Office	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	208	Administrative Office	Room 208 ESOL Office	yes	W4	Plaster	Purple	None	0	N/A	N/A
1	2	208	Administrative Office	Room 208 ESOL Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Administrative Office	Room 208 ESOL Office	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	222	Storage	Storage Room across from the Teacher's Lounge	yes	W1	Plaster	White	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
			Name of Inspector: Ananth K. Vinjamuri									
			Inspection Company: Criterion Laboratories, Inc.									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	222	Storage	Storage Room across from the Teacher's Lounge	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	222	Storage	Storage Room across from the Teacher's Lounge	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	222	Storage	Storage Room across from the Teacher's Lounge	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	222	Storage	Storage Room across from the Teacher's Lounge	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	222	Storage	Storage Room across from the Teacher's Lounge	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	S21	Stairs	2nd Floor Stairwell across from Classroom 206	yes	W1	Plaster	White/Green	None	0	N/A	N/A
1	2	S21	Stairs	2nd Floor Stairwell across from Classroom 206	yes	W2	Plaster	White/Green	None	0	N/A	N/A
1	2	S21	Stairs	2nd Floor Stairwell across from Classroom 206	yes	W3	Plaster	White/Green	None	0	N/A	N/A
1	2	S21	Stairs	2nd Floor Stairwell across from Classroom 206	yes	Radiator (W3)	Metal	Grey	Chipping	10	1.5	Positive
1	2	S21	Stairs	2nd Floor Stairwell across from Classroom 206	yes	W4	Plaster	White/Green	None	0	N/A	N/A
1	2	S21	Stairs	2nd Floor Stairwell across from Classroom 206	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	S21	Stairs	2nd Floor Stairwell across from Classroom 206	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	S21	Stairs	2nd Floor Stairwell across from Classroom 206	yes	Newel Post	Metal	Grey	Friction	1	0.01	Negative
1	2	S22	Stairs	2nd Floor Stairwell across from Classroom 204	yes	W1	Plaster	White/Blue	None	0	N/A	N/A
1	2	S22	Stairs	2nd Floor Stairwell across from Classroom 204	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
1	2	S22	Stairs	2nd Floor Stairwell across from Classroom 204	yes	W3	Plaster	White/Blue	None	0	N/A	N/A
1	2	S22	Stairs	2nd Floor Stairwell across from Classroom 204	yes	Radiator (W3)	Metal	Grey	Chipping	10	1.8	Positive
1	2	S22	Stairs	2nd Floor Stairwell across from Classroom 204	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
1	2	S22	Stairs	2nd Floor Stairwell across from Classroom 204	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	S22	Stairs	2nd Floor Stairwell across from Classroom 204	yes	Floor	Concrete	Grey	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
			Name of Inspector: Ananth K. Vinjamuri									
			Inspection Company: Criterion Laboratories, Inc.									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	S23A	Circulation (Hallway)	Walkway in 2nd Floor Fire Tower near Classroom 201	yes	W1	Brick	White	None	0	N/A	N/A
1	2	S23A	Circulation (Hallway)	Walkway in 2nd Floor Fire Tower near Classroom 201	yes	W2	Brick	White	None	0	N/A	N/A
1	2	S23A	Circulation (Hallway)	Walkway in 2nd Floor Fire Tower near Classroom 201	yes	W3	Brick	White	None	0	N/A	N/A
1	2	S23A	Circulation (Hallway)	Walkway in 2nd Floor Fire Tower near Classroom 201	yes	Window sill/Grates (W3/W4)	Metal	Grey	Chipping	50	9.8	Positive
1	2	S23A	Circulation (Hallway)	Walkway in 2nd Floor Fire Tower near Classroom 201	yes	W4	Brick	White	None	0	N/A	N/A
1	2	S23A	Circulation (Hallway)	Walkway in 2nd Floor Fire Tower near Classroom 201	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	S23A	Circulation (Hallway)	Walkway in 2nd Floor Fire Tower near Classroom 201	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	S23	Stairs	2nd Floor Fire Tower near Classroom 201	yes	W1	Brick	White	None	0	N/A	N/A
1	2	S23	Stairs	2nd Floor Fire Tower near Classroom 201	yes	W2	Brick	White	None	0	N/A	N/A
1	2	S23	Stairs	2nd Floor Fire Tower near Classroom 201	yes	W3	Brick	White	None	0	N/A	N/A
1	2	S23	Stairs	2nd Floor Fire Tower near Classroom 201	yes	W4	Brick	White	None	0	N/A	N/A
1	2	S23	Stairs	2nd Floor Fire Tower near Classroom 201	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	S23	Stairs	2nd Floor Fire Tower near Classroom 201	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	S24A	Circulation (Hallway)	Walkway in 2nd Floor Fire Tower near Classroom 208	yes	W1	Brick	White	None	0	N/A	N/A
1	2	S24A	Circulation (Hallway)	Walkway in 2nd Floor Fire Tower near Classroom 208	yes	W2	Brick	White	None	0	N/A	N/A
1	2	S24A	Circulation (Hallway)	Walkway in 2nd Floor Fire Tower near Classroom 208	yes	W3	Brick	White	None	0	N/A	N/A
1	2	S24A	Circulation (Hallway)	Walkway in 2nd Floor Fire Tower near Classroom 208	yes	Window sill/Grates (W3/W4)	Metal	Grey	Chipping	50	24.1	Positive
1	2	S24A	Circulation (Hallway)	Walkway in 2nd Floor Fire Tower near Classroom 208	yes	W4	Brick	White	None	0	N/A	N/A
1	2	S24A	Circulation (Hallway)	Walkway in 2nd Floor Fire Tower near Classroom 208	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	S24A	Circulation (Hallway)	Walkway in 2nd Floor Fire Tower near Classroom 208	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	S24	Stairs	2nd Floor Fire Tower near Classroom 208	yes	W1	Brick	White	None	0	N/A	N/A
1	2	S24	Stairs	2nd Floor Fire Tower near Classroom 208	yes	W2	Brick	White	None	0	N/A	N/A
1	2	S24	Stairs	2nd Floor Fire Tower near Classroom 208	yes	W3	Brick	White	None	0	N/A	N/A
1	2	S24	Stairs	2nd Floor Fire Tower near Classroom 208	yes	W4	Brick	White	None	0	N/A	N/A
1	2	S24	Stairs	2nd Floor Fire Tower near Classroom 208	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	S24	Stairs	2nd Floor Fire Tower near Classroom 208	yes	Floor	Concrete	Grey	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	H210	Circulation (Hallway)	Hallway along Classrooms 201 and 202	yes	W1	Plaster	White/Green	None	0	N/A	N/A
1	2	H210	Circulation (Hallway)	Hallway along Classrooms 201 and 202	yes	W2	Plaster	White/Green	None	0	N/A	N/A
1	2	H210	Circulation (Hallway)	Hallway along Classrooms 201 and 202	yes	W3	Plaster	White/Green	None	0	N/A	N/A
1	2	H210	Circulation (Hallway)	Hallway along Classrooms 201 and 202	yes	W4	Plaster	White/Green	None	0	N/A	N/A
1	2	H210	Circulation (Hallway)	Hallway along Classrooms 201 and 202	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H210	Circulation (Hallway)	Hallway along Classrooms 201 and 202	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	H211	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	W1	Plaster	White/Green	Partially Inaccessible	0	28.7	Positive
1	2	H211	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	W2	Plaster	White/Green	Partially Inaccessible	0	31.9	Positive
1	2	H211	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	W3	Plaster	White/Green	Partially Inaccessible	0	29.6	Positive
1	2	H211	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	W4	Plaster	White/Green	Partially Inaccessible	0	32.2	Positive
1	2	H211	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H211	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	H209	Circulation (Hallway)	Hallway along Classrooms 207 and 208	yes	W1	Plaster	White/Green	None	0	N/A	N/A
1	2	H209	Circulation (Hallway)	Hallway along Classrooms 207 and 208	yes	W2	Plaster	Green	Flaking	1	20.9	Positive
1	2	H209	Circulation (Hallway)	Hallway along Classrooms 207 and 208	yes	W3	Plaster	White/Green	None	0	N/A	N/A
1	2	H209	Circulation (Hallway)	Hallway along Classrooms 207 and 208	yes	W4	Plaster	White/Green	None	0	N/A	N/A
1	2	H209	Circulation (Hallway)	Hallway along Classrooms 207 and 208	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H209	Circulation (Hallway)	Hallway along Classrooms 207 and 208	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	S26A		Stairs to Storage Area above Stage Right	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	S26A		Stairs to Storage Area above Stage Right	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	S26A		Stairs to Storage Area above Stage Right	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	S26A		Stairs to Storage Area above Stage Right	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	S26A		Stairs to Storage Area above Stage Right	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	S26A		Stairs to Storage Area above Stage Right	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	S26	Storage	Storage Area above Stage Right	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	S26	Storage	Storage Area above Stage Right	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	S26	Storage	Storage Area above Stage Right	yes	W3	Plaster	Beige	Spalling	4	13.9	Positive
1	2	S26	Storage	Storage Area above Stage Right	yes	Radiator (W3)	Metal	Grey	Chipping	4	5.7	Positive
1	2	S26	Storage	Storage Area above Stage Right	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	S26	Storage	Storage Area above Stage Right	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	2	S26	Storage	Storage Area above Stage Right	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	S26B		Storage Area above Stage Right Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	S26B		Storage Area above Stage Right Closet	yes	W2	Plaster	Beige	Spalling	6	16	Positive
1	2	S26B		Storage Area above Stage Right Closet	yes	Radiator (W2)	Metal	Grey	Chipping	4	3.5	Positive

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	S26B		Storage Area above Stage Right Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	S26B		Storage Area above Stage Right Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	S26B		Storage Area above Stage Right Closet	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	2	S26B		Storage Area above Stage Right Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	S27A		Stairs to Storage Area above Stage Left	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	S27A		Stairs to Storage Area above Stage Left	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	S27A		Stairs to Storage Area above Stage Left	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	S27A		Stairs to Storage Area above Stage Left	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	S27A		Stairs to Storage Area above Stage Left	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	S27A		Stairs to Storage Area above Stage Left	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	S27	Storage	Storage Area above Stage Left	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	S27	Storage	Storage Area above Stage Left	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	S27	Storage	Storage Area above Stage Left	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	S27	Storage	Storage Area above Stage Left	yes	Radiator (W3)	Metal	Grey	Chipping	4	2.8	Positive
1	2	S27	Storage	Storage Area above Stage Left	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	S27	Storage	Storage Area above Stage Left	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	2	S27	Storage	Storage Area above Stage Left	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	S27B		Storage Area above Stage Left Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	S27B		Storage Area above Stage Left Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	S27B		Storage Area above Stage Left Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	S27B		Storage Area above Stage Left Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	S27B		Storage Area above Stage Left Closet	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	2	S27B		Storage Area above Stage Left Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	100	Auditorium	Auditorium	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	100	Auditorium	Auditorium	yes	W2	Plaster	Beige	Partially Inaccessible	0	10.1	Positive
1	1	100	Auditorium	Auditorium	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	100	Auditorium	Auditorium	yes	W4	Plaster	Beige	Partially Inaccessible	0	13.6	Positive
1	1	100	Auditorium	Auditorium	yes	Ceiling	No Access	Beige	Partially Inaccessible	5		
1	1	100	Auditorium	Auditorium	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	100A Stage	Stage	Stage	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	100A Stage	Stage	Stage	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	100A Stage	Stage	Stage	yes	W3	Plaster	Beige	Flaking	10	13.7	Positive
1	1	100A Stage	Stage	Stage	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	100A Stage	Stage	Stage	yes	Ceiling	Plaster	Beige	Flaking	5	11.8	Positive
1	1	100A Stage	Stage	Stage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	S16	Stairs	Stage Right Stair Area	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	S16	Stairs	Stage Right Stair Area	yes	W2	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	S16	Stairs	Stage Right Stair Area	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	S16	Stairs	Stage Right Stair Area	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	S16	Stairs	Stage Right Stair Area	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	1	S16	Stairs	Stage Right Stair Area	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	S17	Stairs	Stage Left Stair Area	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	S17	Stairs	Stage Left Stair Area	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	S17	Stairs	Stage Left Stair Area	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	S17	Stairs	Stage Left Stair Area	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	S17	Stairs	Stage Left Stair Area	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	1	S17	Stairs	Stage Left Stair Area	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	101	Administrative Office	CATCH Program	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	101	Administrative Office	CATCH Program	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	101	Administrative Office	CATCH Program	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	101	Administrative Office	CATCH Program	yes	Radiator (W3)	Metal	Grey	Chipping	4	0.08	Negative
1	1	101	Administrative Office	CATCH Program	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	101	Administrative Office	CATCH Program	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101	Administrative Office	CATCH Program	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	102	Primary	Classroom 102 Kindergarten	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	102	Primary	Classroom 102 Kindergarten	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	102	Primary	Classroom 102 Kindergarten	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	102	Primary	Classroom 102 Kindergarten	yes	W4	Plaster	Beige	Partially Inaccessible	0	16.9	Positive
1	1	102	Primary	Classroom 102 Kindergarten	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102	Primary	Classroom 102 Kindergarten	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	102 B	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	102 B	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	102 B	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	102 B	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	102 B	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102 B	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	102C	Storage	Classroom 102 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	102C	Storage	Classroom 102 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	102C	Storage	Classroom 102 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	102C	Storage	Classroom 102 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	102C	Storage	Classroom 102 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102C	Storage	Classroom 102 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	103	Primary	Classroom 103	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	103	Primary	Classroom 103	yes	W2	Plaster	Beige	Partially Inaccessible	0	24.3	Positive
1	1	103	Primary	Classroom 103	yes	W3	Plaster	Beige	Flaking	3	3.2	Positive
1	1	103	Primary	Classroom 103	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	103	Primary	Classroom 103	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Primary	Classroom 103	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	103B	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	103B	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	103B	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	103B	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	103B	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103B	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	103A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 103	yes	W1	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	1	103A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 103	yes	W2	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	1	103A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 103	yes	W3	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	1	103A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 103	yes	W4	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	1	103A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 103	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	103A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 103	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	104	Primary	Classroom 104	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	104	Primary	Classroom 104	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	104	Primary	Classroom 104	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	104	Primary	Classroom 104	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	104	Primary	Classroom 104	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Primary	Classroom 104	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	104B	Storage	Classroom 104 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	104B	Storage	Classroom 104 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	104B	Storage	Classroom 104 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	104B	Storage	Classroom 104 Closet	yes	W4	Plaster	Beige	Damaged plaster	2	11.1	Positive
1	1	104B	Storage	Classroom 104 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104B	Storage	Classroom 104 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	105	Primary	Classroom 105	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	105	Primary	Classroom 105	yes	W2	Plaster	Beige	Partially Inaccessible	0	29.6	Positive
1	1	105	Primary	Classroom 105	yes	W3	Plaster	Beige	Flaking	1	0	Negative
1	1	105	Primary	Classroom 105	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	105	Primary	Classroom 105	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105	Primary	Classroom 105	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	105B	Storage	Classroom 105 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	105B	Storage	Classroom 105 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	105B	Storage	Classroom 105 Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	19.2	Positive
1	1	105B	Storage	Classroom 105 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	105B	Storage	Classroom 105 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105B	Storage	Classroom 105 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	106	Primary	Classroom 106	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	106	Primary	Classroom 106	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	106	Primary	Classroom 106	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	106	Primary	Classroom 106	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	106	Primary	Classroom 106	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106	Primary	Classroom 106	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	yes	W2	Plaster	Beige	Partially Inaccessible	0	1.3	Positive
1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	yes	W3	Plaster	Beige	Spalling, Cracking	4	9.5	Positive
1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	yes	W4	Sheetrock	Beige	Spalling, Efflorescence	2	0	Negative
1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	106B	Storage	Classroom 106 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	106B	Storage	Classroom 106 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	106B	Storage	Classroom 106 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	106B	Storage	Classroom 106 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	106B	Storage	Classroom 106 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106B	Storage	Classroom 106 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	107	Primary	Classroom 107	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	107	Primary	Classroom 107	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	107	Primary	Classroom 107	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	107	Primary	Classroom 107	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	107	Primary	Classroom 107	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107	Primary	Classroom 107	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	107A	Storage	Classroom 107 Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	107A	Storage	Classroom 107 Closet	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	107A	Storage	Classroom 107 Closet	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	107A	Storage	Classroom 107 Closet	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	107A	Storage	Classroom 107 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	107A	Storage	Classroom 107 Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	W4	Plaster	Beige	Partially Inaccessible	0	21.6	Positive
1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	108	Administrative Office	Principal's Office	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	108	Administrative Office	Principal's Office	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	108	Administrative Office	Principal's Office	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	108	Administrative Office	Principal's Office	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	108	Administrative Office	Principal's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108	Administrative Office	Principal's Office	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	108A	Restrooms, Staff - Female	Principal's Office Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	108A	Restrooms, Staff - Female	Principal's Office Restroom	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	108A	Restrooms, Staff - Female	Principal's Office Restroom	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	108A	Restrooms, Staff - Female	Principal's Office Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	108A	Restrooms, Staff - Female	Principal's Office Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108A	Restrooms, Staff - Female	Principal's Office Restroom	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	108B	Storage	Principal's Office Closet	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	108B	Storage	Principal's Office Closet	yes	W2	Plaster	Beige	Partially Inaccessible	0	10.1	Positive
1	1	108B	Storage	Principal's Office Closet	yes	W3	Plaster	Beige	Partially Inaccessible	0	8.4	Positive
1	1	108B	Storage	Principal's Office Closet	yes	W4	Plaster	Beige	Partially Inaccessible	0	7.8	Positive
1	1	108B	Storage	Principal's Office Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108B	Storage	Principal's Office Closet	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	109	Administrative Office	Main Office	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	109	Administrative Office	Main Office	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	109	Administrative Office	Main Office	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	109	Administrative Office	Main Office	yes	Radiator (W3)	Metal	Grey	Chipping	6	1.5	Positive
1	1	109	Administrative Office	Main Office	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	109	Administrative Office	Main Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	109	Administrative Office	Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109A	Storage	Main Office Closet on Right	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	109A	Storage	Main Office Closet on Right	yes	W2	Plaster	Beige	Partially Inaccessible	0	3.8	Positive
1	1	109A	Storage	Main Office Closet on Right	yes	W3	Plaster	Beige	Partially Inaccessible	0	3.6	Positive
1	1	109A	Storage	Main Office Closet on Right	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	109A	Storage	Main Office Closet on Right	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	1	109A	Storage	Main Office Closet on Right	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	109C	Storage	Main Office Closet on Left	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	109C	Storage	Main Office Closet on Left	yes	W2	Plaster	Beige	Partially Inaccessible	0	3.9	Positive
1	1	109C	Storage	Main Office Closet on Left	yes	W3	Plaster	Beige	Partially Inaccessible	0	2	Positive
1	1	109C	Storage	Main Office Closet on Left	yes	W4	Plaster	Beige	Partially Inaccessible	0	2.3	Positive
1	1	109C	Storage	Main Office Closet on Left	yes	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	1	109C	Storage	Main Office Closet on Left	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	109B	Restrooms, Staff - Female	Women's Restroom	yes	W1	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	1	109B	Restrooms, Staff - Female	Women's Restroom	yes	W2	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	1	109B	Restrooms, Staff - Female	Women's Restroom	yes	W3	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	1	109B	Restrooms, Staff - Female	Women's Restroom	yes	W4	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	1	109B	Restrooms, Staff - Female	Women's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	109B	Restrooms, Staff - Female	Women's Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	110	Administrative Office	Nurse's Office	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	110	Administrative Office	Nurse's Office	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	110	Administrative Office	Nurse's Office	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	110	Administrative Office	Nurse's Office	yes	Radiator (W3)	Metal	Grey	Chipping	4	0.04	Negative
1	1	110	Administrative Office	Nurse's Office	yes	W4	Plaster	Beige	Friction	4	24.7	Positive
1	1	110	Administrative Office	Nurse's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	Administrative Office	Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110A	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	yes	W1	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	1	110A	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	yes	W2	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	1	110A	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	yes	W3	Plaster/Ceramic	Beige	None	0	N/A	N/A
1	1	110A	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	yes	W4	Plaster/Ceramic	Beige	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	110A	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	110A	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	112	Service Closets	Custodial Closet next to Women's Restroom	no	W1						
1	1	112	Service Closets	Custodial Closet next to Women's Restroom	no	W2						
1	1	112	Service Closets	Custodial Closet next to Women's Restroom	no	W3						
1	1	112	Service Closets	Custodial Closet next to Women's Restroom	no	W4						
1	1	112	Service Closets	Custodial Closet next to Women's Restroom	no	Ceiling						
1	1	112	Service Closets	Custodial Closet next to Women's Restroom	no	Floor						
1	1	H14	Circulation (Hallway)	Hallway along Classrooms 106 and 107	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	H14	Circulation (Hallway)	Hallway along Classrooms 106 and 107	yes	W2	Plaster	Grey	Efflorescence	2	14.9	Positive
1	1	H14	Circulation (Hallway)	Hallway along Classrooms 106 and 107	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	H14	Circulation (Hallway)	Hallway along Classrooms 106 and 107	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	H14	Circulation (Hallway)	Hallway along Classrooms 106 and 107	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	Circulation (Hallway)	Hallway along Classrooms 106 and 107	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	H17	Circulation (Hallway)	Hallway along Classrooms 101 and 102	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	1	H17	Circulation (Hallway)	Hallway along Classrooms 101 and 102	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	1	H17	Circulation (Hallway)	Hallway along Classrooms 101 and 102	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	H17	Circulation (Hallway)	Hallway along Classrooms 101 and 102	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	H17	Circulation (Hallway)	Hallway along Classrooms 101 and 102	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H17	Circulation (Hallway)	Hallway along Classrooms 101 and 102	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	H18	Circulation (Hallway)	Hallway from Women's Restroom to Nurse's Office	yes	W1	Plaster	White	Partially Inaccessible	0	27	Positive
1	1	H18	Circulation (Hallway)	Hallway from Women's Restroom to Nurse's Office	yes	W1	Plaster	Blue	Partially Inaccessible	1	14.6	Positive
1	1	H18	Circulation (Hallway)	Hallway from Women's Restroom to Nurse's Office	yes	W2	Plaster	White	Partially Inaccessible	0	27.6	Positive
1	1	H18	Circulation (Hallway)	Hallway from Women's Restroom to Nurse's Office	yes	W2	Plaster	Blue	Partially Inaccessible	0	18.7	Positive
1	1	H18	Circulation (Hallway)	Hallway from Women's Restroom to Nurse's Office	yes	W3	Plaster	White	Partially Inaccessible	0	24.3	Positive
1	1	H18	Circulation (Hallway)	Hallway from Women's Restroom to Nurse's Office	yes	W3	Plaster	Blue	Partially Inaccessible	0	15.8	Positive

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
			Name of Inspector: Ananth K. Vinjamuri									
			Inspection Company: Criterion Laboratories, Inc.									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	H18	Circulation (Hallway)	Hallway from Women's Restroom to Nurse's Office	yes	W4	Plaster	White	Partially Inaccessible	0	33.3	Positive
1	1	H18	Circulation (Hallway)	Hallway from Women's Restroom to Nurse's Office	yes	W4	Plaster	Blue	Partially Inaccessible	0	15.8	Positive
1	1	H18	Circulation (Hallway)	Hallway from Women's Restroom to Nurse's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H18	Circulation (Hallway)	Hallway from Women's Restroom to Nurse's Office	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	S12	Stairs	1st Floor Stairwell across from Classroom 104	yes	W1	Plaster	White/Blue	None	0	N/A	N/A
1	1	S12	Stairs	1st Floor Stairwell across from Classroom 104	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
1	1	S12	Stairs	1st Floor Stairwell across from Classroom 104	yes	W3	Plaster	White/Blue	Chipping	1	1.1	Positive
1	1	S12	Stairs	1st Floor Stairwell across from Classroom 104	yes	W4	Plaster	White/Blue	None	0	N/A	N/A
1	1	S12	Stairs	1st Floor Stairwell across from Classroom 104	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	S12	Stairs	1st Floor Stairwell across from Classroom 104	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	S11	Stairs	1st Floor Stairwell across from Principal's Office	yes	W1	Plaster	White/Green	None	0	N/A	N/A
1	1	S11	Stairs	1st Floor Stairwell across from Principal's Office	yes	W2	Plaster	White/Green	None	0	N/A	N/A
1	1	S11	Stairs	1st Floor Stairwell across from Principal's Office	yes	W3	Plaster	White/Green	None	0	N/A	N/A
1	1	S11	Stairs	1st Floor Stairwell across from Principal's Office	yes	W4	Plaster	White/Green	None	0	N/A	N/A
1	1	S11	Stairs	1st Floor Stairwell across from Principal's Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	S11	Stairs	1st Floor Stairwell across from Principal's Office	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	S18	Stairs	1st Floor Stairwell next to Main Office (Main Entrance)	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	S18	Stairs	1st Floor Stairwell next to Main Office (Main Entrance)	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	S18	Stairs	1st Floor Stairwell next to Main Office (Main Entrance)	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	S18	Stairs	1st Floor Stairwell next to Main Office (Main Entrance)	yes	W4	Plaster	White	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
			Name of Inspector: Ananth K. Vinjamuri									
			Inspection Company: Criterion Laboratories, Inc.									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	S18	Stairs	1st Floor Stairwell next to Main Office (Main Entrance)	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	S18	Stairs	1st Floor Stairwell next to Main Office (Main Entrance)	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	S13A	Circulation (Hallway)	Walkway in 1st Floor Fire Tower near Room 101	yes	W1	Brick	White	None	0	N/A	N/A
1	1	S13A	Circulation (Hallway)	Walkway in 1st Floor Fire Tower near Room 101	yes	W2	Brick	White	None	0	N/A	N/A
1	1	S13A	Circulation (Hallway)	Walkway in 1st Floor Fire Tower near Room 101	yes	W3	Brick	White	None	0	N/A	N/A
1	1	S13A	Circulation (Hallway)	Walkway in 1st Floor Fire Tower near Room 101	yes	Window sill/Grates (W3/W4))	Metal	Grey	Chipping	50	7.9	Positive
1	1	S13A	Circulation (Hallway)	Walkway in 1st Floor Fire Tower near Room 101	yes	W4	Brick	White	None	0	N/A	N/A
1	1	S13A	Circulation (Hallway)	Walkway in 1st Floor Fire Tower near Room 101	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	S13A	Circulation (Hallway)	Walkway in 1st Floor Fire Tower near Room 101	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	S13	Stairs	1st Floor Fire Tower near Room 101	yes	W1	Brick	White	None	0	N/A	N/A
1	1	S13	Stairs	1st Floor Fire Tower near Room 101	yes	W2	Brick	White	None	0	N/A	N/A
1	1	S13	Stairs	1st Floor Fire Tower near Room 101	yes	W3	Brick	White	None	0	N/A	N/A
1	1	S13	Stairs	1st Floor Fire Tower near Room 101	yes	W4	Brick	White	None	0	N/A	N/A
1	1	S13	Stairs	1st Floor Fire Tower near Room 101	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	S13	Stairs	1st Floor Fire Tower near Room 101	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	S14A	Circulation (Hallway)	Walkway in 1st Floor Fire Tower near Room 107	yes	W1	Brick	White	None	0	N/A	N/A
1	1	S14A	Circulation (Hallway)	Walkway in 1st Floor Fire Tower near Room 107	yes	W2	Brick	White	None	0	N/A	N/A
1	1	S14A	Circulation (Hallway)	Walkway in 1st Floor Fire Tower near Room 107	yes	W3	Brick	White	None	0	N/A	N/A
1	1	S14A	Circulation (Hallway)	Walkway in 1st Floor Fire Tower near Room 107	yes	Window sill/Grates (W3/W4))	Metal	Grey	Chipping	50	10.6	Positive
1	1	S14A	Circulation (Hallway)	Walkway in 1st Floor Fire Tower near Room 107	yes	Pipe (W3)	Metal	Grey	Chipping	5	4.7	Positive
1	1	S14A	Circulation (Hallway)	Walkway in 1st Floor Fire Tower near Room 107	yes	W4	Brick	White	None	0	N/A	N/A
1	1	S14A	Circulation (Hallway)	Walkway in 1st Floor Fire Tower near Room 107	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	S14A	Circulation (Hallway)	Walkway in 1st Floor Fire Tower near Room 107	yes	Floor	Concrete	Grey	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	S14	Stairs	1st Floor Fire Tower near Room 107	yes	W1	Brick	White	None	0	N/A	N/A
1	1	S14	Stairs	1st Floor Fire Tower near Room 107	yes	W2	Brick	White	None	0	N/A	N/A
1	1	S14	Stairs	1st Floor Fire Tower near Room 107	yes	W3	Brick	White	None	0	N/A	N/A
1	1	S14	Stairs	1st Floor Fire Tower near Room 107	yes	W4	Brick	White	None	0	N/A	N/A
1	1	S14	Stairs	1st Floor Fire Tower near Room 107	yes	Ceiling	Concrete	White	Efflorescence	6	2.2	Positive
1	1	S14	Stairs	1st Floor Fire Tower near Room 107	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	E1	Elevators, Passenger	Elevator	yes	W1	Metal	Blue	None	0	N/A	N/A
1	B	E1	Elevators, Passenger	Elevator	yes	W2	Metal	Blue	None	0	N/A	N/A
1	B	E1	Elevators, Passenger	Elevator	yes	W3	Metal	Blue	None	0	N/A	N/A
1	B	E1	Elevators, Passenger	Elevator	yes	W4	Metal	Blue	None	0	N/A	N/A
1	B	E1	Elevators, Passenger	Elevator	yes	Ceiling	Metal	Blue	None	0	N/A	N/A
1	B	E1	Elevators, Passenger	Elevator	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	B1	Primary	Classroom B1 (Art)	yes	W1	Plaster	Beige	Partially Inaccessible	0	19	Positive
1	B	B1	Primary	Classroom B1 (Art)	yes	W2	Plaster	Blue	Partially Inaccessible	0	20.9	Positive
1	B	B1	Primary	Classroom B1 (Art)	yes	W3	Plaster	Blue	Partially Inaccessible	0	27.6	Positive
1	B	B1	Primary	Classroom B1 (Art)	yes	W4	Plaster	Beige	Partially Inaccessible	0	21.1	Positive
1	B	B1	Primary	Classroom B1 (Art)	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	B1	Primary	Classroom B1 (Art)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	B1A	Student Restrooms - Male/Female (Classroom)	Classroom B1 (Art) Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	B	B1A	Student Restrooms - Male/Female (Classroom)	Classroom B1 (Art) Restroom	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	B	B1A	Student Restrooms - Male/Female (Classroom)	Classroom B1 (Art) Restroom	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	B	B1A	Student Restrooms - Male/Female (Classroom)	Classroom B1 (Art) Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	B	B1A	Student Restrooms - Male/Female (Classroom)	Classroom B1 (Art) Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	B1A	Student Restrooms - Male/Female (Classroom)	Classroom B1 (Art) Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010B	Administrative Office	Classroom B1 (Art) Rear Storage Area	yes	W1	Plaster	Beige	Partially Inaccessible	0	11.9	Positive
1	B	010B	Administrative Office	Classroom B1 (Art) Rear Storage Area	yes	W2	Plaster	Beige	Flaking	15	2	Positive
1	B	010B	Administrative Office	Classroom B1 (Art) Rear Storage Area	yes	W3	Plaster	Beige	Partially Inaccessible	0	16.4	Positive

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
			Name of Inspector: Ananth K. Vinjamuri									
			Inspection Company: Criterion Laboratories, Inc.									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	010B	Administrative Office	Classroom B1 (Art) Rear Storage Area	yes	W4	Plaster	Beige	Partially Inaccessible	0	15.7	Positive
1	B	010B	Administrative Office	Classroom B1 (Art) Rear Storage Area	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	010B	Administrative Office	Classroom B1 (Art) Rear Storage Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010BB	Storage	Classroom B1 (Art) Closet within Rear Storage Area	yes	W1	Plaster	White	None	0	N/A	N/A
1	B	010BB	Storage	Classroom B1 (Art) Closet within Rear Storage Area	yes	W2	Plaster	White	Damaged Plaster	6	0.01	Negative
1	B	010BB	Storage	Classroom B1 (Art) Closet within Rear Storage Area	yes	W3	Plaster	White	None	0	N/A	N/A
1	B	010BB	Storage	Classroom B1 (Art) Closet within Rear Storage Area	yes	W4	Plaster	White	None	0	N/A	N/A
1	B	010BB	Storage	Classroom B1 (Art) Closet within Rear Storage Area	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	010BB	Storage	Classroom B1 (Art) Closet within Rear Storage Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	004D	Service Closets	Custodial Closet with Restroom near Exit Doors (Art Room Side of Basement)	no	W1						
1	B	004D	Service Closets	Custodial Closet with Restroom near Exit Doors (Art Room Side of Basement)	no	W2						
1	B	004D	Service Closets	Custodial Closet with Restroom near Exit Doors (Art Room Side of Basement)	no	W3						
1	B	004D	Service Closets	Custodial Closet with Restroom near Exit Doors (Art Room Side of Basement)	no	W4						
1	B	004D	Service Closets	Custodial Closet with Restroom near Exit Doors (Art Room Side of Basement)	no	Ceiling						
1	B	004D	Service Closets	Custodial Closet with Restroom near Exit Doors (Art Room Side of Basement)	no	Floor						
1	B	004E	Storage	Storage Room In the Custodial Closet with Restroom near Exit Doors (Art Room Side of Basement) - Under Fire Tower Stairs	no	W1						
1	B	004E	Storage	Storage Room In the Custodial Closet with Restroom near Exit Doors (Art Room Side of Basement) - Under Fire Tower Stairs	no	W2						
1	B	004E	Storage	Storage Room In the Custodial Closet with Restroom near Exit Doors (Art Room Side of Basement) - Under Fire Tower Stairs	no	W3						
1	B	004E	Storage	Storage Room In the Custodial Closet with Restroom near Exit Doors (Art Room Side of Basement) - Under Fire Tower Stairs	no	W4						

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
			Name of Inspector: Ananth K. Vinjamuri									
			Inspection Company: Criterion Laboratories, Inc.									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	004E	Storage	Storage Room In the Custodial Closet with Restroom near Exit Doors (Art Room Side of Basement) - Under Fire Tower Stairs	no	Ceiling						
1	B	004E	Storage	Storage Room In the Custodial Closet with Restroom near Exit Doors (Art Room Side of Basement) - Under Fire Tower Stairs	no	Floor						
1	B	004C	Storage	Storage Room between Custodial Closet with Restroom near Exit Doors and the Boy's Restroom	no	W1						
1	B	004C	Storage	Storage Room between Custodial Closet with Restroom near Exit Doors and the Boy's Restroom	no	W2						
1	B	004C	Storage	Storage Room between Custodial Closet with Restroom near Exit Doors and the Boy's Restroom	no	W3						
1	B	004C	Storage	Storage Room between Custodial Closet with Restroom near Exit Doors and the Boy's Restroom	no	W4						
1	B	004C	Storage	Storage Room between Custodial Closet with Restroom near Exit Doors and the Boy's Restroom	no	Ceiling						
1	B	004C	Storage	Storage Room between Custodial Closet with Restroom near Exit Doors and the Boy's Restroom	no	Floor						
	B	PC004C	Pipe Chase	Pipe Chase in Storage Room between Custodial Closet with Restroom near Exit Doors and the Boy's Restroom	no	W1						
	B	PC004C	Pipe Chase	Pipe Chase in Storage Room between Custodial Closet with Restroom near Exit Doors and the Boy's Restroom	no	W2						
	B	PC004C	Pipe Chase	Pipe Chase in Storage Room between Custodial Closet with Restroom near Exit Doors and the Boy's Restroom	no	W3						
	B	PC004C	Pipe Chase	Pipe Chase in Storage Room between Custodial Closet with Restroom near Exit Doors and the Boy's Restroom	no	W4						
	B	PC004C	Pipe Chase	Pipe Chase in Storage Room between Custodial Closet with Restroom near Exit Doors and the Boy's Restroom	no	Ceiling						

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
	B	PC004C	Pipe Chase	Pipe Chase in Storage Room between Custodial Closet with Restroom near Exit Doors and the Boy's Restroom	no	Floor						
1	B	004B	Student Restrooms - Male (4-12)	Boy's Restroom near B1 Art Room	yes	W1	Brick	White	None	0	N/A	N/A
1	B	004B	Student Restrooms - Male (4-12)	Boy's Restroom near B1 Art Room	yes	W2	Brick	White	Flaking	2	7.3	Positive
1	B	004B	Student Restrooms - Male (4-12)	Boy's Restroom near B1 Art Room	yes	W3	Brick	White	None	0	N/A	N/A
1	B	004B	Student Restrooms - Male (4-12)	Boy's Restroom near B1 Art Room	yes	W4	Brick	White	None	0	N/A	N/A
1	B	004B	Student Restrooms - Male (4-12)	Boy's Restroom near B1 Art Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	004B	Student Restrooms - Male (4-12)	Boy's Restroom near B1 Art Room	yes	Floor	Concrete	Grey	None	0	N/A	N/A
	B	PC004B	Pipe Chase	Pipe Chase in Boy's Restroom near B1 Art Room	no	W1						
	B	PC004B	Pipe Chase	Pipe Chase in Boy's Restroom near B1 Art Room	no	W2						
	B	PC004B	Pipe Chase	Pipe Chase in Boy's Restroom near B1 Art Room	no	W3						
	B	PC004B	Pipe Chase	Pipe Chase in Boy's Restroom near B1 Art Room	no	W4						
	B	PC004B	Pipe Chase	Pipe Chase in Boy's Restroom near B1 Art Room	no	Ceiling						
	B	PC004B	Pipe Chase	Pipe Chase in Boy's Restroom near B1 Art Room	no	Floor						
1	B	H01	Circulation (Hallway)	Hallway from B1 Art Room to Custodial Closet with Restroom by Exit Doors	yes	W1	Brick	White	None	0	N/A	N/A
1	B	H01	Circulation (Hallway)	Hallway from B1 Art Room to Custodial Closet with Restroom by Exit Doors	yes	W2	Brick	White	None	0	N/A	N/A
1	B	H01	Circulation (Hallway)	Hallway from B1 Art Room to Custodial Closet with Restroom by Exit Doors	yes	W3	Brick	White	None	0	N/A	N/A
1	B	H01	Circulation (Hallway)	Hallway from B1 Art Room to Custodial Closet with Restroom by Exit Doors	yes	W4	Brick	White	None	0	N/A	N/A
1	B	H01	Circulation (Hallway)	Hallway from B1 Art Room to Custodial Closet with Restroom by Exit Doors	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	H01	Circulation (Hallway)	Hallway from B1 Art Room to Custodial Closet with Restroom by Exit Doors	yes	Floor	Concrete	Grey	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	015A	Circulation (Hallway)	Hallway Area between Building Engineer's Office and Gym	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	B	015A	Circulation (Hallway)	Hallway Area between Building Engineer's Office and Gym	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	B	015A	Circulation (Hallway)	Hallway Area between Building Engineer's Office and Gym	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	B	015A	Circulation (Hallway)	Hallway Area between Building Engineer's Office and Gym	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	B	015A	Circulation (Hallway)	Hallway Area between Building Engineer's Office and Gym	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	015A	Circulation (Hallway)	Hallway Area between Building Engineer's Office and Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001B	Service Closets	Custodial Closet with Restroom near Exit Doors (Girl's Restroom Side of Basement)	no	W1						
1	B	001B	Service Closets	Custodial Closet with Restroom near Exit Doors (Girl's Restroom Side of Basement)	no	W2						
1	B	001B	Service Closets	Custodial Closet with Restroom near Exit Doors (Girl's Restroom Side of Basement)	no	W3						
1	B	001B	Service Closets	Custodial Closet with Restroom near Exit Doors (Girl's Restroom Side of Basement)	no	W4						
1	B	001B	Service Closets	Custodial Closet with Restroom near Exit Doors (Girl's Restroom Side of Basement)	no	Ceiling						
1	B	001B	Service Closets	Custodial Closet with Restroom near Exit Doors (Girl's Restroom Side of Basement)	no	Floor						
1	B	001A		Storage Room between Custodial Closet with Restroom near Exit Doors and the Girl's Restroom	no	W1						
1	B	001A	Storage	Storage Room between Custodial Closet with Restroom near Exit Doors and the Girl's Restroom	no	W2						
1	B	001A	Storage	Storage Room between Custodial Closet with Restroom near Exit Doors and the Girl's Restroom	no	W3						
1	B	001A	Storage	Storage Room between Custodial Closet with Restroom near Exit Doors and the Girl's Restroom	no	W4						
1	B	001A	Storage	Storage Room between Custodial Closet with Restroom near Exit Doors and the Girl's Restroom	no	Ceiling						

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	001A	Storage	Storage Room between Custodial Closet with Restroom near Exit Doors and the Girl's Restroom	no	Floor						
1	B	PC001A	Pipe Chase	Pipe Chase in Boy's Restroom near B1 Art Room	no	W1						
1	B	PC001A	Pipe Chase	Pipe Chase in Boy's Restroom near B1 Art Room	no	W2						
1	B	PC001A	Pipe Chase	Pipe Chase in Boy's Restroom near B1 Art Room	no	W3						
1	B	PC001A	Pipe Chase	Pipe Chase in Boy's Restroom near B1 Art Room	no	W4						
1	B	PC001A	Pipe Chase	Pipe Chase in Boy's Restroom near B1 Art Room	no	Ceiling						
1	B	PC001A	Pipe Chase	Pipe Chase in Boy's Restroom near B1 Art Room	no	Floor						
1	B	H03	Circulation (Hallway)	Hallway from Kitchen to Custodial Closet with Restroom by Exit Doors	yes	W1	Brick	White	None	0	N/A	N/A
1	B	H03	Circulation (Hallway)	Hallway from Kitchen to Custodial Closet with Restroom by Exit Doors	yes	W2	Brick	White	None	0	N/A	N/A
1	B	H03	Circulation (Hallway)	Hallway from Kitchen to Custodial Closet with Restroom by Exit Doors	yes	W3	Brick	White	None	0	N/A	N/A
1	B	H03	Circulation (Hallway)	Hallway from Kitchen to Custodial Closet with Restroom by Exit Doors	yes	W4	Brick	White	None	0	N/A	N/A
1	B	H03	Circulation (Hallway)	Hallway from Kitchen to Custodial Closet with Restroom by Exit Doors	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	H03	Circulation (Hallway)	Hallway from Kitchen to Custodial Closet with Restroom by Exit Doors	yes	Floor	Concrete	White	None	0	N/A	N/A
1	B	001	Student Restrooms - Female (4-12)	Girl's Restroom near Kitchen	yes	W1	Brick	White	Chipping	10	8.6	Positive
1	B	001	Student Restrooms - Female (4-12)	Girl's Restroom near Kitchen	yes	W2	Brick	White	Chipping	4	7.4	Positive
1	B	001	Student Restrooms - Female (4-12)	Girl's Restroom near Kitchen	yes	W3	Brick	White	None	0	N/A	N/A
1	B	001	Student Restrooms - Female (4-12)	Girl's Restroom near Kitchen	yes	W4	Brick	White	None	0	N/A	N/A
1	B	001	Student Restrooms - Female (4-12)	Girl's Restroom near Kitchen	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	001	Student Restrooms - Female (4-12)	Girl's Restroom near Kitchen	yes	Floor	Concrete	Grey	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
	B	PC001	Pipe Chase	Pipe Chase in Girl's Restroom near Kitchen	no	W1						
	B	PC001	Pipe Chase	Pipe Chase in Girl's Restroom near Kitchen	no	W2						
	B	PC001	Pipe Chase	Pipe Chase in Girl's Restroom near Kitchen	no	W3						
	B	PC001	Pipe Chase	Pipe Chase in Girl's Restroom near Kitchen	no	W4						
	B	PC001	Pipe Chase	Pipe Chase in Girl's Restroom near Kitchen	no	Ceiling						
	B	PC001	Pipe Chase	Pipe Chase in Girl's Restroom near Kitchen	no	Floor						
1	B	034	Kitchen	Kitchen	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	B	034	Kitchen	Kitchen	yes	Pipe (W1)	Metal	Beige	Chipping	2	14.6	Positive
1	B	034	Kitchen	Kitchen	yes	Pipe (W1)	Metal	Grey	Chipping	2	15.2	Positive
1	B	034	Kitchen	Kitchen	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	B	034	Kitchen	Kitchen	yes	W3	Plaster	Beige	Efflorescence	10	13	Positive
1	B	034	Kitchen	Kitchen	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	B	034	Kitchen	Kitchen	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	034	Kitchen	Kitchen	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
	B	PC034	Pipe Chase	Pipe Chase in Kitchen	no	W1						
	B	PC034	Pipe Chase	Pipe Chase in Kitchen	no	W2						
	B	PC034	Pipe Chase	Pipe Chase in Kitchen	no	W3						
	B	PC034	Pipe Chase	Pipe Chase in Kitchen	no	W4						
	B	PC034	Pipe Chase	Pipe Chase in Kitchen	no	Ceiling						
	B	PC034	Pipe Chase	Pipe Chase in Kitchen	no	Floor						
	B	034A	Storage	Kitchen Office/Storage	yes	W1	Plaster	Beige	None	0	N/A	N/A
	B	034A	Storage	Kitchen Office/Storage	yes	W2	Plaster	Beige	None	0	N/A	N/A
	B	034A	Storage	Kitchen Office/Storage	yes	Pipe (W2)	Metal	Grey	Flaking	3	22	Positive
	B	034A	Storage	Kitchen Office/Storage	yes	W3	Plaster	Beige	Efflorescence	10	20.5	Positive
	B	034A	Storage	Kitchen Office/Storage	yes	W4	Plaster	Beige	Efflorescence	4	0	Negative
	B	034A	Storage	Kitchen Office/Storage	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
	B	034A	Storage	Kitchen Office/Storage	yes	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	H02	Circulation (Hallway)	Hallway from near Elevator to Boiler Room	no	W1						
1	B	H02	Circulation (Hallway)	Hallway from near Elevator to Boiler Room	no	W2						
1	B	H02	Circulation (Hallway)	Hallway from near Elevator to Boiler Room	no	W3						
1	B	H02	Circulation (Hallway)	Hallway from near Elevator to Boiler Room	no	W4						
1	B	H02	Circulation (Hallway)	Hallway from near Elevator to Boiler Room	no	Ceiling						
1	B	H02	Circulation (Hallway)	Hallway from near Elevator to Boiler Room	no	Floor						

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
			Name of Inspector: Ananth K. Vinjamuri									
			Inspection Company: Criterion Laboratories, Inc.									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	011B	Storage	Boiler Room Storage Area (near Building Engineer's Office Side of Building)	no	W1						
1	B	011B	Storage	Boiler Room Storage Area (near Building Engineer's Office Side of Building)	no	W2						
1	B	011B	Storage	Boiler Room Storage Area (near Building Engineer's Office Side of Building)	no	W3						
1	B	011B	Storage	Boiler Room Storage Area (near Building Engineer's Office Side of Building)	no	W4						
1	B	011B	Storage	Boiler Room Storage Area (near Building Engineer's Office Side of Building)	no	Ceiling						
1	B	011B	Storage	Boiler Room Storage Area (near Building Engineer's Office Side of Building)	no	Floor						
1	B	009B	Mechanical	Boiler Room Area	no	W1						
1	B	009B	Mechanical	Boiler Room Area	no	W2						
1	B	009B	Mechanical	Boiler Room Area	no	W3						
1	B	009B	Mechanical	Boiler Room Area	no	W4						
1	B	009B	Mechanical	Boiler Room Area	no	Ceiling						
1	B	009B	Mechanical	Boiler Room Area	no	Floor						
1	B	008B	Storage	Boiler Room Storage Area with Transformer (near Kitchen Side of Building)	no	W1						
1	B	008B	Storage	Boiler Room Storage Area with Transformer (near Kitchen Side of Building)	no	W2						
1	B	008B	Storage	Boiler Room Storage Area with Transformer (near Kitchen Side of Building)	no	W3						
1	B	008B	Storage	Boiler Room Storage Area with Transformer (near Kitchen Side of Building)	no	W4						
1	B	008B	Storage	Boiler Room Storage Area with Transformer (near Kitchen Side of Building)	no	Ceiling						
1	B	008B	Storage	Boiler Room Storage Area with Transformer (near Kitchen Side of Building)	no	Floor						
1	B	008BA	Storage	Boiler Room Storage Area adjacent to Storage area with Transformer	no	W1						
1	B	008BA	Storage	Boiler Room Storage Area adjacent to Storage area with Transformer	no	W2						

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	008BA	Storage	Boiler Room Storage Area adjacent to Storage area with Transformer	no	W3						
1	B	008BA	Storage	Boiler Room Storage Area adjacent to Storage area with Transformer	no	W4						
1	B	008BA	Storage	Boiler Room Storage Area adjacent to Storage area with Transformer	no	Ceiling						
1	B	008BA	Storage	Boiler Room Storage Area adjacent to Storage area with Transformer	no	Floor						
1	B	012B	Mechanical	Fan Room near Kitchen	no	W1						
1	B	012B	Mechanical	Fan Room near Kitchen	no	W2						
1	B	012B	Mechanical	Fan Room near Kitchen	no	W3						
1	B	012B	Mechanical	Fan Room near Kitchen	no	W4						
1	B	012B	Mechanical	Fan Room near Kitchen	no	Ceiling						
1	B	012B	Mechanical	Fan Room near Kitchen	no	Floor						
1	B	006C	Storage	Lunch Table Storage Room between Kitchen and Gym	yes	W1	Brick	White	None	0	N/A	N/A
1	B	006C	Storage	Lunch Table Storage Room between Kitchen and Gym	yes	W2	Brick	White	None	0	N/A	N/A
1	B	006C	Storage	Lunch Table Storage Room between Kitchen and Gym	yes	W3	Brick	White	None	0	N/A	N/A
1	B	006C	Storage	Lunch Table Storage Room between Kitchen and Gym	yes	W4	Brick	White	None	0	N/A	N/A
1	B	006C	Storage	Lunch Table Storage Room between Kitchen and Gym	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	006C	Storage	Lunch Table Storage Room between Kitchen and Gym	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	006D	Circulation (Hallway)	Hallway Area between Lunch Table Storage Room and Gym	yes	W1	Plaster	White	None	0	N/A	N/A
1	B	006D	Circulation (Hallway)	Hallway Area between Lunch Table Storage Room and Gym	yes	W2	Plaster	White	None	0	N/A	N/A
1	B	006D	Circulation (Hallway)	Hallway Area between Lunch Table Storage Room and Gym	yes	W3	Plaster	White	None	0	N/A	N/A
1	B	006D	Circulation (Hallway)	Hallway Area between Lunch Table Storage Room and Gym	yes	W4	Plaster	White	None	0	N/A	N/A
1	B	006D	Circulation (Hallway)	Hallway Area between Lunch Table Storage Room and Gym	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	006D	Circulation (Hallway)	Hallway Area between Lunch Table Storage Room and Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	003B	Gymnasium - Intermediate Middle	Gym/Cafe	yes	W1	Brick	White	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
		Name of Inspector: Ananth K. Vinjamuri										
		Inspection Company: Criterion Laboratories, Inc.										
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	003B	Gymnasium - Intermediate Middle	Gym/Cafe	yes	W2	Brick	White	Flaking	6	0.07	Negative
1	B	003B	Gymnasium - Intermediate Middle	Gym/Cafe	yes	W2	Plaster	White	Efflorescence	4	18	Positive
1	B	003B	Gymnasium - Intermediate Middle	Gym/Cafe	yes	W3	Brick	White	Flaking	2	2	Positive
1	B	003B	Gymnasium - Intermediate Middle	Gym/Cafe	yes	W4	Brick	White	None	0	N/A	N/A
1	B	003B	Gymnasium - Intermediate Middle	Gym/Cafe	yes	Ceiling	Plaster	White	Damaged Plaster	1	20.4	Positive
1	B	003B	Gymnasium - Intermediate Middle	Gym/Cafe	yes	Pipe (Ceiling)	Metal	White	Flaking	20	0.08	Negative
1	B	003B	Gymnasium - Intermediate Middle	Gym/Cafe	yes	Radiator (Ceiling)	Metal	White	Flaking	15	0.02	Negative
1	B	003B	Gymnasium - Intermediate Middle	Gym/Cafe	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	006B	Administrative Office	Gym Office	yes	W1	Brick	White	Friction	3	8.8	Positive
1	B	006B	Administrative Office	Gym Office	yes	W2	Brick	White	Friction	2	9.6	Positive
1	B	006B	Administrative Office	Gym Office	yes	W3	Brick	White	None	0	N/A	N/A
1	B	006B	Administrative Office	Gym Office	yes	Column (W3)	Concrete	White	Flaking	6	7.2	Positive
1	B	006B	Administrative Office	Gym Office	yes	W4	Brick	White	Friction	5	9.6	Positive
1	B	006B	Administrative Office	Gym Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	006B	Administrative Office	Gym Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	007B	Storage	Gym Storage (Now Kitchen)	yes	W1	Brick	White	Friction	4	8.3	Positive
1	B	007B	Storage	Gym Storage (Now Kitchen)	yes	W2	Brick	White	Friction	10	5.6	Positive
1	B	007B	Storage	Gym Storage (Now Kitchen)	yes	W3	Brick	White	Friction	5	10.1	Positive
1	B	007B	Storage	Gym Storage (Now Kitchen)	yes	W4	Brick	White	Friction	3	14.4	Positive
1	B	007B	Storage	Gym Storage (Now Kitchen)	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	007B	Storage	Gym Storage (Now Kitchen)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	015	Administrative Office	Building Engineer's Office	no	W1						
1	B	015	Administrative Office	Building Engineer's Office	no	W2						
1	B	015	Administrative Office	Building Engineer's Office	no	W3						
1	B	015	Administrative Office	Building Engineer's Office	no	W4						
1	B	015	Administrative Office	Building Engineer's Office	no	Ceiling						
1	B	015	Administrative Office	Building Engineer's Office	no	Floor						
1	B	S01	Stairs	Basement Stairwell between Building Engineer's Office and Art Room	yes	W1	Plaster	White/Green	None	0	N/A	N/A
1	B	S01	Stairs	Basement Stairwell between Building Engineer's Office and Art Room	yes	W2	Plaster	White	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
			Name of Inspector: Ananth K. Vinjamuri									
			Inspection Company: Criterion Laboratories, Inc.									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	S01	Stairs	Basement Stairwell between Building Engineer's Office and Art Room	yes	W2	Plaster	Green	Friction	2	1.2	Positive
1	B	S01	Stairs	Basement Stairwell between Building Engineer's Office and Art Room	yes	W3	Plaster	White/Green	None	0	N/A	N/A
1	B	S01	Stairs	Basement Stairwell between Building Engineer's Office and Art Room	yes	W4	Plaster	White/Green	None	0	N/A	N/A
1	B	S01	Stairs	Basement Stairwell between Building Engineer's Office and Art Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	S01	Stairs	Basement Stairwell between Building Engineer's Office and Art Room	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	S02	Stairs	Basement Stairwell Between Kitchen and Gym	yes	W1	Plaster	White/Blue	None	0	N/A	N/A
1	B	S02	Stairs	Basement Stairwell Between Kitchen and Gym	yes	W2	Plaster	White/Blue	None	0	N/A	N/A
1	B	S02	Stairs	Basement Stairwell Between Kitchen and Gym	yes	W3	Plaster	White/Blue	None	0	N/A	N/A
1	B	S02	Stairs	Basement Stairwell Between Kitchen and Gym	yes	W4	Plaster	White	None	0	N/A	N/A
1	B	S02	Stairs	Basement Stairwell Between Kitchen and Gym	yes	W4	Plaster	Blue	Friction	2	19.6	Positive
1	B	S02	Stairs	Basement Stairwell Between Kitchen and Gym	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	S02	Stairs	Basement Stairwell Between Kitchen and Gym	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	S04	Stairs	Basement Stairwell next to Custodial Closet with Restroom (Art Room Side of Building)	yes	W1	Brick	White	None	0	N/A	N/A
1	B	S04	Stairs	Basement Stairwell next to Custodial Closet with Restroom (Art Room Side of Building)	yes	W2	Brick	White	None	0	N/A	N/A
1	B	S04	Stairs	Basement Stairwell next to Custodial Closet with Restroom (Art Room Side of Building)	yes	W3	Brick	White	None	0	N/A	N/A
1	B	S04	Stairs	Basement Stairwell next to Custodial Closet with Restroom (Art Room Side of Building)	yes	W4	Brick	White	None	0	N/A	N/A
1	B	S04	Stairs	Basement Stairwell next to Custodial Closet with Restroom (Art Room Side of Building)	yes	Ceiling	Concrete	White	None	0	N/A	N/A

School District of Philadelphia												
Lead Safe Certification Assessment Report												
Nebinger Elementary School												
			Name of Inspector: Ananth K. Vinjamuri									
			Inspection Company: Criterion Laboratories, Inc.									
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	S04	Stairs	Basement Stairwell next to Custodial Closet with Restroom (Art Room Side of Building)	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	S05	Stairs	Basement Stairwell next to Custodial Closet with Restroom (Kitchen Side of Building)	yes	W1	Brick	White	None	0	N/A	N/A
1	B	S05	Stairs	Basement Stairwell next to Custodial Closet with Restroom (Kitchen Side of Building)	yes	W2	Brick	White	None	0	N/A	N/A
1	B	S05	Stairs	Basement Stairwell next to Custodial Closet with Restroom (Kitchen Side of Building)	yes	W3	Brick	White	None	0	N/A	N/A
1	B	S05	Stairs	Basement Stairwell next to Custodial Closet with Restroom (Kitchen Side of Building)	yes	W4	Brick	White	None	0	N/A	N/A
1	B	S05	Stairs	Basement Stairwell next to Custodial Closet with Restroom (Kitchen Side of Building)	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	S05	Stairs	Basement Stairwell next to Custodial Closet with Restroom (Kitchen Side of Building)	yes	Floor	Concrete	Grey	None	0	N/A	N/A