

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	6450	1	3	302	IMC (Library)	IMC	Ceiling	Flaking	4	N	N	0	N	N	ACT
2	6450	1	3	302	IMC (Library)	IMC	W1	Flaking	16	N	N	0	Y - 140 SF Bulletin Boards, Desks, Book Cases	N	5 Areas - Additional Cracking, Chipping, Gouges, Holes
3	6450	1	3	302	IMC (Library)	IMC	W2	Flaking	3	N	N	0	Y- 120 SF Book Cases	N	2 Areas - Cracking
4	6450	1	3	302	IMC (Library)	IMC	W3/Windows	Flaking/Flaking	19	N/N	N/Y	0/15	N/N	N	2 Areas - Flaking on Window Lintels 1,2,3,5,6,8; Debris on Window Sills 5,6
5	6450	1	3	303	Intermediate/Middle -- Science Lab	Classroom 303/304	W1	Flaking	8	N	N	0	Y - 240 SF Cabinet, Bulletin Board, Posters	N	3 Areas - Additional Cracks
6	6450	1	3	303	Intermediate/Middle -- Science Lab	Classroom 303/304	W2	Flaking	8	N	N	0	Y - 80 SF Bulletin Boards, Posters	N	2 Areas - Additional Cracks
7	6450	1	3	303	Intermediate/Middle -- Science Lab	Classroom 303/304	W3/Windows	Flaking/None	20	N/N	N/N	0/0	Y - 28 SF Bookcase, Posters/N	N/N	3 Areas/None
8	6450	1	3	303	Intermediate/Middle -- Science Lab	Classroom 303/304	W4	Cracking	2	N	N	0	Y - 70 SF Posters, White Board, Bulletin Board	N	
9	6450	1	3	305	Teacher Lounge/Dining	Teacher Lounge	W1	Cracking	18	N	N	0	N	N	
10	6450	1	3	305	Teacher Lounge/Dining	Teacher Lounge	W2	Flaking	6	N	N	0	N	Y - 2 SF	2 Areas - Additional Cracks
11	6450	1	3	305	Teacher Lounge/Dining	Teacher Lounge	W3/Windows	Flaking/None	2	N/N	N/Y	0/1	Y - 8 SF Bulletin Board/N	N	
12	6450	1	3	305	Teacher Lounge/Dining	Teacher Lounge	W4	Cracking	3	N	N	0	Y - 42 SF Cabinets	N	Wall & Pipe
13	6450	1	3	306	Medium Education Laboratory	Classroom 307	W1	Flaking	86	N	N	0	Y - 180 SF Bulletin Board, White Board, Posters	N	Additional Cracking
14	6450	1	3	306	Medium Education Laboratory	Classroom 307	W2	Flaking	8	N	N	0	Y - 32 SF Bulletin Board	N	Additional Cracking
15	6450	1	3	306	Medium Education Laboratory	Classroom 307	W3/Windows	Flaking	42	N/Y	N/Y	0/6	N/N	N	Walls & Pipes, Additional Cracking/Debris on Window Sills 4 & 7, Efflorescence on Window Lintil
16	6450	1	3	306	Medium Education Laboratory	Classroom 307	W4	Flaking	120	N	N	0	N	N	Additional Cracking
17	6450	1	3	308	Primary	Classroom 308	W1	Flaking	34	N	N	0	Y - 80 SF Bulletin Boards, Posters	N	Additional Cracking
18	6450	1	3	308	Primary	Classroom 308	W2	Flaking	8	N	N	0	Y - 100 SF White Board, Posters	N	
19	6450	1	3	308	Primary	Classroom 308	W3	Flaking	26	N	N	0	Y - 8 SF File Cabinets, Bookcase	N	Additional Cracking
20	6450	1	3	308	Primary	Classroom 308	W4	Flaking	10	N	N	0	Y - 60 SF Bulletins Board, Posters	N	Additional Cracking
21	6450	1	3	309	Primary	Classroom 309	W3/Windows	None/None	0	N/N	N/Y	10	Y - 8 SF Posters	N	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
22	6450	1	3	313	Primary	Classroom 313	W1	Cracking	4	N	N	0	Y - 100 SF Bulletin Boards, Bookcases, Posters	N	Holes
23	6450	1	3	313	Primary	Classroom 313	W2	Flaking	16	N	Y	2	Y - 40 SF Bulletin Boards, Posters	N	2 Areas, Additional Gouges; Debris on Radiator
24	6450	1	3	313	Primary	Classroom 313	W3/Windows	Cracking/Efflorescence	24	N/Y	N/Y	3	Y - Futon/Y - 6 SF Bulletin Boards	N/Y	Holes/Window Lentil & Sill Debris
25	6450	1	3	318	Student Restrooms - Male (4-12)	3rd Floor Boy's Restroom	Ceiling	Flaking	5	N	N	0	N	Y	Additional Cracking & 5 Duct Hanger Penetrations
26	6450	1	3	302B	IMC (Library)	IMC Reading Room	W1	Flaking	44	N	N	0	Y - 120 SF Posters	N	302A&B On Drawing; 2 Areas - Flaking includes door; additional cracking
27	6450	1	3	302B	IMC (Library)	IMC Reading Room	W2	Cracking	3	N	N	0	Y - 60 SF Posters	N	302A&B On Drawing
28	6450	1	3	302B	IMC (Library)	IMC Reading Room	W4	None/Flaking	4	N/N	N/Y	0/4	N/N	N/N	302A&B On Drawing; Window Lentils & Sills 1,2
29	6450	1	3	302D	Primary	Classroom 302 adjacent to IMC	W1	Flaking	1	N	N	0	N	N	Room @ End of H31
30	6450	1	3	302D	Primary	Classroom 302 adjacent to IMC	W2	Flaking	33	N	N	0	Y - 16 SF Bookcases & Posters	Y	Room @ End of H31; Additional Cracking & Holes
31	6450	1	3	302D	Primary	Classroom 302 adjacent to IMC	W3	Flaking	60	Y	N	0	Y - 24 SF White Board	Y	Room @ End of H31; Additional Cracking & Holes; Significant Water Damage
32	6450	1	3	302D	Primary	Classroom 302 adjacent to IMC	W4	Flaking	70	Y	N	0	Y - 32 SF Bookcases	N	Room @ End of H31; Significant Water Damage
33	6450	1	3	303A	Storage	Classroom 303 Closet	W2	Flaking	12	N	N	0	Y - 12 SF Lockers & Crates	Y - 12 SF	Additional Cracks
34	6450	1	3	304A	Storage	Classroom 304 Closet	W1	Cracking	2	N	N	0	Y - 20 SF Boxes	N	
35	6450	1	3	304A	Storage	Classroom 304 Closet	W2	Cracking	20	N	N	0	Y - 12 SF Boxes	N	
36	6450	1	3	304A	Storage	Classroom 304 Closet	W3	Flaking	24	N	N	0	Y - 160 SF Bookcases	N	2 Areas - Additional Cracking
37	6450	1	3	304A	Storage	Classroom 304 Closet	W4	Cracking	8	N	N	0	Y - 45 SF Bookcase & Boxes	N	
38	6450	1	3	305A	Kitchen	Teacher Lounge Kitchen	W1	Cracking	16	Y	N	0	Y - 12 SF Desks	N	Stained ACT Above
39	6450	1	3	305A	Kitchen	Teacher Lounge Kitchen	W2	Cracking	6	N	N	0	N	N	
40	6450	1	3	305A	Kitchen	Teacher Lounge Kitchen	W3	Flaking	10	N	N	0	Y - 42 SF Cabinets	N	Wall & Pipe by Sink
41	6450	1	3	305A	Kitchen	Teacher Lounge Kitchen	W4	Cracking	10	N	N	0	Y - 18 SF Tables	N	
42	6450	1	3	305B	Storage	Teacher Lounge Closet	Ceiling	Cracking	2	N	N	0	N	N	
43	6450	1	3	305B	Storage	Teacher Lounge Closet	W1	Cracking	2	N	N	0	Y - 14 SF Bookcases	N	
44	6450	1	3	305B	Storage	Teacher Lounge Closet	W2	Cracking	2	N	N	0	Y - 14 SF Bookcases	N	
45	6450	1	3	305B	Storage	Teacher Lounge Closet	W3	Cracking	16	N	N	0	Y - 42 SF Bookcases	Y - 16 SF	
46	6450	1	3	305B	Storage	Teacher Lounge Closet	W4	Cracking	2	N	N	0	Y - 14 SF Bookcases	N	
47	6450	1	3	306A	Storage	Classroom 307 Left Closet	W1	Flaking	36	N	N	0	Y - 32 SF Cabinets	N	Additional Cracking
48	6450	1	3	306A	Storage	Classroom 307 Left Closet	W2	Cracking	2	N	N	0	Y - 32 SF Cabinets	N	
49	6450	1	3	306B	Storage	Classroom 307 Center Closet	W1	Flaking	18	N	N	0	N		Additional Cracking

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
50	6450	1	3	306B	Storage	Classroom 307 Center Closet	W3	Flaking	8	N	N	0	Y - 60 SF Cabinets		Additional Cracking
51	6450	1	3	306B	Storage	Classroom 307 Center Closet	W4	Flaking	36	N	N	0	N	Y - 2 SF	Additional Cracking
52	6450	1	3	306C	Storage	Classroom 307 Right Closet	Ceiling	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
53	6450	1	3	306C	Storage	Classroom 307 Right Closet	Floor	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
54	6450	1	3	306C	Storage	Classroom 307 Right Closet	W1	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
55	6450	1	3	306C	Storage	Classroom 307 Right Closet	W2	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
56	6450	1	3	306C	Storage	Classroom 307 Right Closet	W3	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
57	6450	1	3	306C	Storage	Classroom 307 Right Closet	W4	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
58	6450	1	3	306D	Medium Education Laboratory	Classroom 307 Cabinet Area	W1	Flaking	48	N	N	0	Y - 30 SF File Cabinets, Sink, Shelves	N	Additional Cracking
59	6450	1	3	306D	Medium Education Laboratory	Classroom 307 Cabinet Area	W2	Flaking	18	N	N	0	Y - 18 SF Desks & Cabinets	N	Additional Cracking
60	6450	1	3	306D	Medium Education Laboratory	Classroom 307 Cabinet Area	W3/Windows	Flaking/None	96	N	N/Y	0/2	Y - 12 SF File Cabinets/N	N	Additional Cracking/None
61	6450	1	3	306E	Storage	Classroom 307 Space at Rear Entrance	W3	Flaking	24	N	N	0	Y - 54 SF Counter	N	Pipe & Wall
62	6450	1	3	306E	Storage	Classroom 307 Space at Rear Entrance	W4	Flaking	60	N	N	0	N	Y - 36 SF	Additional Cracking
63	6450	1	3	308A	Storage	Classroom 308 Large Closet	W4	Cracking	20	N	N	0	N	N	
64	6450	1	3	308C	Storage	Classroom 308 Small Closet	W1	Cracking	8	N	N	0	Y - 28 SF Bookcases	N	
65	6450	1	3	308C	Storage	Classroom 308 Small Closet	W2	Flaking	24	N	N	0	Y - 42 SF Bookcases	N	
66	6450	1	3	308C	Storage	Classroom 308 Small Closet	W3	Flaking	24	N	N	0	Y - 42 SF Bookcases	N	
67	6450	1	3	309A	Storage	Classroom 309 Large Closet	W1	Cracking	8	N	N	0	N	N	
68	6450	1	3	309A	Storage	Classroom 309 Large Closet	W2	Cracking	2	N	N	0	Y - 13 SF Boxes, File Cabinets	N	
69	6450	1	3	309A	Storage	Classroom 309 Large Closet	W3	Cracking	30	N	N	0	Y - 20 SF File Cabinets	N	
70	6450	1	3	309A	Storage	Classroom 309 Large Closet	W4	Flaking	12	N	N	0	Y - 6 SF Radiators	N	Pipe Paint
71	6450	1	3	309B	Storage	Classroom 309 Small Closet	W3	Cracking	16	N	N	0	Y - 21 SF Bookcases		
72	6450	1	3	309B	Storage	Classroom 309 Small Closet	W4	Flaking	20	N	N	0	N	Y - 2 SF	
73	6450	1	3	310A	Storage	Storage Room adjacent to 3rd Floor Faculty Restroom	Ceiling	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
74	6450	1	3	310A	Storage	Storage Room adjacent to 3rd Floor Faculty Restroom	Floor	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
75	6450	1	3	310A	Storage	Storage Room adjacent to 3rd Floor Faculty Restroom	W1	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
76	6450	1	3	310A	Storage	Storage Room adjacent to 3rd Floor Faculty Restroom	W2	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
77	6450	1	3	310A	Storage	Storage Room adjacent to 3rd Floor Faculty Restroom	W3	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
78	6450	1	3	310A	Storage	Storage Room adjacent to 3rd Floor Faculty Restroom	W4	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
79	6450	1	3	313A	Storage	Right Closet outside Classroom 313	Ceiling	Cracking	44	N	N	0	Y - 8 SF Light	N	Additional Cracking
80	6450	1	3	313A	Storage	Right Closet outside Classroom 313	W1	Flaking	10	N	N	0	Y - 21 SF Bookcases	N	
81	6450	1	3	313A	Storage	Right Closet outside Classroom 313	W2	Flaking	47	N	N	0	Y - 77 SF Bookcases	N	2 Areas

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
82	6450	1	3	313A	Storage	Right Closet outside Classroom 313	W3	Flaking	20	N	N	0	Y - 35 SF Bookcases	N	2 Areas
83	6450	1	3	313A	Storage	Right Closet outside Classroom 313	W4	Flaking	44	N	N	0	Y - 72 SF Bookcases	N	
84	6450	1	3	313B	Storage	Left Closet outside Classroom 313	Ceiling	Cracking	44	N	N	0	Y - 8 SF Light	N	
85	6450	1	3	313B	Storage	Left Closet outside Classroom 313	W1	Flaking	20	N	N	0	Y - 21 SF Bookcases	N	
86	6450	1	3	313B	Storage	Left Closet outside Classroom 313	W2	Flaking	44	N	N	0	Y - 77 SF Bookcases	N	
87	6450	1	3	313B	Storage	Left Closet outside Classroom 313	W3	Flaking	28	N	N	0	Y - 35 SF Bookcases	N	
88	6450	1	3	313B	Storage	Left Closet outside Classroom 313	W4	Cracking	0	N	N	0	Y - 77 SF Bookcases	N	
89	6450	1	3	313C	Storage	Classroom 313 Coat Closet	W1	Cracking	8	N	N	0	N	N	
90	6450	1	3	313C	Storage	Classroom 313 Coat Closet	W2	Cracking	72	N	Y	0	Y - 64 SF Coats	N	Coat Rack Rails
91	6450	1	3	313C	Storage	Classroom 313 Coat Closet	W3/Windows	Cracking/Flaking	60	N	N/Y	0/4	Y - 42 SF Storage	N	
92	6450	1	3	313C	Storage	Classroom 313 Coat Closet	W4	Flaking	45	Y	N	0	Y - 90 SF Bookcases, Storage	N	2 Areas; Stained ACT Above/Window Lentil & Sill Debris
93	6450	1	3	313D	Storage	Classroom 313 Closet adjacent to Coat Closet	Ceiling	Cracking	4	N	N	0	Y - 8 SF Light	N	
94	6450	1	3	313D	Storage	Classroom 313 Closet adjacent to Coat Closet	W1	Flaking	14	N	N	0	Y - 21 SF Bookcases	N	2 Areas
95	6450	1	3	313D	Storage	Classroom 313 Closet adjacent to Coat Closet	W4	Cracking	8	N	N	0	Y - 35 SF Bookcases	N	
96	6450	1	3	313E	Storage	Classroom 313 Closet to left of Entrance	Ceiling	Flaking	10	N	N	0	N	N	
97	6450	1	3	313E	Storage	Classroom 313 Closet to left of Entrance	W1	Cracking	2	N	N	0	Y - 70 SF Bookcases	N	Whole Wall Obstructed
98	6450	1	3	333A	Storage	Left Closet across from Classroom 303/304	Ceiling	Flaking	16	N	N	0	N	Y - 4 SF	3 Areas (Space Above Closet)
99	6450	1	3	333A	Storage	Left Closet across from Classroom 303/304	W2	Cracking	14	N	N	0	Y - 14 SF Bookcases	N	
100	6450	1	3	333A	Storage	Left Closet across from Classroom 303/304	W4	Flaking	14	N	N	0	Y - 13 SF Bookcases	N	
101	6450	1	3	333B	Storage	Center Closet across from Classroom 303/304	Ceiling	Flaking	32	Y	N	0	N	N	3 Areas; Efflorescence, Cracking (Space Above Closet)
102	6450	1	3	333B	Storage	Center Closet across from Classroom 303/304	W2	Flaking	14	N	N	0	Y - 14 SF Bookcases	N	
103	6450	1	3	333C	Storage	Right Closet across from Classroom 303/304	Ceiling	Cracking	18	N	N	0	N	N	Efflorescence, Cracking (Space Above Closet)
104	6450	1	3	333C	Storage	Right Closet across from Classroom 303/304	W4	Flaking	7	N	N	0	Y - 14 SF Bookcases	N	Pipe Paint
105	6450	1	3	333D	Storage	Left Closet across from Classroom 307	Ceiling	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
106	6450	1	3	333D	Storage	Left Closet across from Classroom 307	Floor	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
107	6450	1	3	333D	Storage	Left Closet across from Classroom 307	W1	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
108	6450	1	3	333D	Storage	Left Closet across from Classroom 307	W2	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
109	6450	1	3	333D	Storage	Left Closet across from Classroom 307	W3	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
110	6450	1	3	333D	Storage	Left Closet across from Classroom 307	W4	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
111	6450	1	3	333E	Storage	Center Closet across from Classroom 307	W4	Flaking	20	Y	Y - On Shelves & Books	20	Y - 15 SF Bookcases	Y - 20 SF	Additional Cracking & Efflorescence
112	6450	1	3	333F	Storage	Right Closet across from Classroom 307	Ceiling	Flaking	20	Y	N	0	N	Y	3 Areas; Efflorescence & Cracking (Space Above Closet)
113	6450	1	3	333F	Storage	Right Closet across from Classroom 307	W2	Cracking	6	N	N	0	Y - 64 SF Bookcases	N	
114	6450	1	3	333F	Storage	Right Closet across from Classroom 307	W4	Cracking	6	N	N	0	Y - 32 SF Boxes & Desks	N	
115	6450	1	3	H31	Circulation (Hallway)	Hallway outside IMC	W2	Gouges	1	N	N	0	N	Y	
116	6450	1	3	H31	Circulation (Hallway)	Hallway outside IMC	W3	Cracking	1	N	N	0	N	N	
117	6450	1	3	H32	Circulation (Hallway)	Hallway outside Classrooms 308-309	W2/Windows	Efflorescence/Flaking	16	Y/Y	N	0	N/Y	N	Additional Efflorescence & Cracking on Window Lentils 1,2,3,4
118	6450	1	3	H32	Circulation (Hallway)	Hallway outside Classrooms 308-309	W3	Flaking	8	N	N	0	N	N	Additional Cracking
119	6450	1	3	H32	Circulation (Hallway)	Hallway outside Classrooms 308-309	W4	Flaking	240	N	N	0	Y - 30 SF Papers	N	Additional Cracking
120	6450	1	3	H33	Circulation (Hallway)	Hallway outside Classrooms 303-307	W1	Flaking	37	N	N	0	Y - 80 SF Posters	N	11 Areas; Additional Cracking & Holes
121	6450	1	3	H33	Circulation (Hallway)	Hallway outside Classrooms 303-307	W2	Chipping	1	N	N	0	N	N	
122	6450	1	3	H33	Circulation (Hallway)	Hallway outside Classrooms 303-307	W3	Flaking	25	N	N	0	Y - 6 SF Posters	N	7 Areas; Additional Cracking
123	6450	1	3	H33	Circulation (Hallway)	Hallway outside Classrooms 303-307	W4	Flaking	15	N	N	0	N	N	5 Areas
124	6450	1	3	S32	Stairs	Boy's Side Stairwell	W1	Cracking	10	N	N	0	N	N	
125	6450	1	3	S32	Stairs	Boy's Side Stairwell	W3	Flaking	30	Y	N	0	N	Y	Additional Cracking & Efflorescence
126	6450	1	3	S32	Stairs	Boy's Side Stairwell	W4	Flaking	5	Y	N	0	N	N	
127	6450	1	3	S35	Stairs	Girl's Side Stairwell	W1	Cracking	40	N	N	0	N	N	
128	6450	1	3	S35	Stairs	Girl's Side Stairwell	W3	Flaking	1	N	N	0	N	N	
129	6450	1	2	201	Music	Classroom 201	W1	Cracking	12	N	N	0	Y - 72 SF Bulletin Board	N	
130	6450	1	2	201	Music	Classroom 201	W3/Windows	Flaking/Chipping	32	N/N	Y/N	5/0	Y - 10 SF Cabinets/N	Y- 5 SF/N	Additional Cracking and Spalling, Under Window Sill, Including Pipe/ Chipping on Window Lentils 2,4
131	6450	1	2	201	Music	Classroom 201	W4	Cracking	7	N	N	0	Y - 42 SF Bulletin Board, File Cabinets	N	
132	6450	1	2	202	Music	Classroom 202	W1	Cracking	23	N	N	0	Y - 96 SF White Board	N	Additional Holes
133	6450	1	2	202	Music	Classroom 202	W2	Cracking	3	N	N	0	Y - 110 SF File Cabinets, Bookcases	N	2 Areas; Additional Gouges
134	6450	1	2	202	Music	Classroom 202	W3/Windows	Flaking/Chipping	14	N/N	N/N	0	Y - 60 SF Cabinets, Furniture/N	N/N	2 Areas; Cracking Pipe/2 Areas; Window Lentils 1,5
135	6450	1	2	203	Primary	Classroom 203	W1	Cracking	1	N	N	0	Y - 112 SF Bulletin Boards, Posters	N	
136	6450	1	2	203	Primary	Classroom 203	W3/Windows	Flaking/Chipping	17	N/N	N/N	0	Y - 22 SF Bookcases, Posters/N	N	5 Areas Including Pipe
137	6450	1	2	204	Primary	Classroom 204	W2	Cracking	2	N	N	0	Y - 50 SF Bulletin Boards, Bookcases	N	
138	6450	1	2	204	Primary	Classroom 204	W3/Windows	Flaking/None	3	N/N	Y/N	0/2	Y - 48 SF Bookcases/ N	N/N	Debris on Window Sill 2,4

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
139	6450	1	2	204	Primary	Classroom 204	W4	Holes	14	N	N	0	Y - 84 SF White Board	Y - 2 SF	Additional Cracking
140	6450	1	2	205	Administrative Office	Office 205	W1	Holes	10	N	N	0	Y - 32 SF Bulletin Boards, File Cabinets	N	
141	6450	1	2	205	Administrative Office	Office 205	W2	Holes	1	N	N	0	Y - 60 SF Bookcases	N	
142	6450	1	2	205	Administrative Office	Office 205	W3/Windows	None/Flaking	4	N/N	N/N	0/0	N/N	N/N	None/Flaking on Window Lentil 1,2
143	6450	1	2	206	Primary	Classroom 206	W1	Flaking	13	N	N	0	Y - 142 SF Bulletin Board, Bookcases	N	3 Locations; Additional Holes
144	6450	1	2	206	Primary	Classroom 206	W2	Chipping	1	N	N	0	Y - 80 SF White Board, Posters	N	
145	6450	1	2	206	Primary	Classroom 206	W3/Windows	Flaking/None	8	N/N	N/N	0/0	Y - 37 SF Bookcases/N	N/N	
146	6450	1	2	206	Primary	Classroom 206	W4	Cracking	3	N	N	0	Y - 27 SF Bulletin Board	N	
147	6450	1	2	207	Primary	Classroom 207	W3	Chipping	1/2	N/N	N/N	0	Y - 24 SF Bookcase/N	N/N	Chipping on Window Lentils 3,5
148	6450	1	2	207	Primary	Classroom 207	W4	Gouges	1	N	N	0	Y - 240 SF Bulletin Board, Bookcase	N	
149	6450	1	2	208	Primary	Classroom 208	W1	Chipping	4	N	N	0	Y - 105 SF Bulletin Board	N	
150	6450	1	2	208	Primary	Classroom 208	W3/Windows	Flaking/Flaking	1/12	N/N	N/Y	0/3	Y - 20 SF File Cabinets, Bookcases/N	N/Y - 3 SF	3 Locations; Flaking on Window Lentils 1,2,3,4,5 & Debris on Window Sill 4
151	6450	1	2	209	Primary	Classroom 209	W1	Flaking	1	N	N	0	Y - 84 SF White Board	N	
152	6450	1	2	209	Primary	Classroom 209	W3/Windows	None/Flaking	4	N/N	N/Y	0/2	N/N	N/Y - 2 SF	2 Locations; Cracking on Window Lentils 2,3 & Debris on Window Sills 2,3
153	6450	1	2	210	Administrative Office	Counselor's Office 210	W1	Flaking	2	N	N	0	Y - 15 SF File Cabinets	Y - 1 SF	
154	6450	1	2	210	Administrative Office	Counselor's Office 210	W2/Windows	Flaking/None	15	N/N	Y/N	5/0	Y - 30 SF Radiator, Bookcases, Posters/NY - 30 SF Bookcases	N/N	Debris On Window Sill 2
155	6450	1	2	210	Administrative Office	Counselor's Office 210	W3	Cracking	4	N	N	0	N	N	
156	6450	1	2	210	Administrative Office	Counselor's Office 210	W4	Flaking	2	N	N	0	N	N	Including Pipe
157	6450	1	2	211	Student Restrooms - Female (4-12)	2nd Floor Girl's Restroom	Ceiling	Holes	3	N	N	0	N	N	
158	6450	1	2	201A	Storage	Classroom 201 Large Closet	W1	Cracking	6	N	N	0	Y - 9 SF Bookcases, Crates	N	
159	6450	1	2	201A	Storage	Classroom 201 Large Closet	W3	Cracking	4	N	N	0	Y - 30 SF File Cabinets, Furniture	N	
160	6450	1	2	201A	Storage	Classroom 201 Large Closet	W4	Cracking	24	N	N	0	Y - 12 SF File Cabinets	N	
161	6450	1	2	201B	Storage	Classroom 201 Small Closet	W2	Cracking	16	N	N	0	Y - 14 SF Bookcases	N	
162	6450	1	2	201B	Storage	Classroom 201 Small Closet	W3	Cracking	24	N	N	0	Y - 28 SF Bookcases	N	
163	6450	1	2	202A	Storage	Classroom 202 Large Closet	W1	Cracking	24	N	N	0	Y - 10 SF Contents	N	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
164	6450	1	2	202A	Storage	Classroom 202 Large Closet	W2	Cracking	6	N	N	0	Y - 6 SF File Cabinets	N	
165	6450	1	2	202B	Storage	Classroom 202 Small Closet	W1	Cracking	2	N	N	0	Y - 28 SF Bookcase	N	
166	6450	1	2	202B	Storage	Classroom 202 Small Closet	W3	Cracking	20	N	N	0	Y - 35 SF Bookcase	N	
167	6450	1	2	202B	Storage	Classroom 202 Small Closet	W4	Cracking	4	N	N	0	Y - 42 SF Bookcase	N	
168	6450	1	2	203B	Storage	Classroom 203 Small Closet	Ceiling	Cracking	9	N	N	0	N	N	
169	6450	1	2	203B	Storage	Classroom 203 Small Closet	W1	Cracking	2	N	N	0	Y - 14 SF Bookcase	N	
170	6450	1	2	204A	Storage	Classroom 204 Large Closet	W1	Holes	10	N	N	0	N	N	Holes from Coat Racks
171	6450	1	2	205A	Restrooms, Staff - Male/Female	Office 205 Restroom	Ceiling	Cracking	4	N	N	0	N	N	
172	6450	1	2	205A	Restrooms, Staff - Male/Female	Office 205 Restroom	W2	Holes	2	N	N	0	N	Y - 2SF	2 Areas; Additional Cracking
173	6450	1	2	205B	Storage	Closet adjacent to Office 205	Ceiling	Cracking	10	N	N	0	N	N	
174	6450	1	2	205B	Storage	Closet adjacent to Office 205	W1	Flaking	16	N	N	0	N	N	2 Areas; Additional Cracking and Holes
175	6450	1	2	205B	Storage	Closet adjacent to Office 205	W2	Cracking	5	N	N	0	Y - 35 SF Bookcase	N	
176	6450	1	2	205B	Storage	Closet adjacent to Office 205	W3	Cracking	4	N	N	0	Y - 42 SF Bookcase	N	
177	6450	1	2	205B	Storage	Closet adjacent to Office 205	W4	Cracking	8	N	N	0	Y - 35 SF Bookcase	N	
178	6450	1	2	206A	Storage	Classroom 206 Large Closet	W1	Flaking	6	N	N	0	Y - 14 SF Cabinets	N	3 Areas; Additional Cracking
179	6450	1	2	206A	Storage	Classroom 206 Large Closet	W2	Gouges	1	N	N	0	N	N	
180	6450	1	2	206B	Storage	Classroom 206 Small Closet	W3	Cracking	10	N	N	0	Y - 48 SF Bookcase	N	
181	6450	1	2	207A	Storage	Classroom 207 Large Closet	W1	Holes	10	N	N	0	Y - 6 SF File Cabinet	N	Coat Rack Holes
182	6450	1	2	207A	Storage	Classroom 207 Large Closet	W4	Chipping	9	N	N	0	N	N	
183	6450	1	2	207B	Storage	Classroom 207 Small Closet	Ceiling	Cracking	3	N	N	0	N	N	
184	6450	1	2	207B	Storage	Classroom 207 Small Closet	W1	Cracking	3	N	N	0	Y - 14 SF Bookcase	N	
185	6450	1	2	207B	Storage	Classroom 207 Small Closet	W2	Cracking	4	N	N	0	Y - 48 SF Bookcase	N	2 Areas; Additional Chipping
186	6450	1	2	207B	Storage	Classroom 207 Small Closet	W3	Cracking	3	N	N	0	Y - 48 SF Bookcase	N	
187	6450	1	2	208A	Storage	Classroom 208 Large Closet	W1	Chipping	1	N	N	0	N	N	
188	6450	1	2	208A	Storage	Classroom 208 Large Closet	W3	Chipping	1	N	N	0	N	N	
189	6450	1	2	208B	Storage	Classroom 208 Small Closet	W1	Cracking	2	N	N	0	Y - 14 SF Bulletin Board	N	
190	6450	1	2	208B	Storage	Classroom 208 Small Closet	W2	Cracking	2	N	N	0	Y - 48 SF Bookcases	N	
191	6450	1	2	208B	Storage	Classroom 208 Small Closet	W3	Cracking	2	N	N	0	Y - 48 SF Bookcases	N	
192	6450	1	2	209A	Storage	Classroom 209 Large Closet	W2	Cracking	16	N	N	0	N	N	
193	6450	1	2	209A	Storage	Classroom 209 Large Closet	W3	Cracking	20	N	N	0	Y - 24 SF File Cabinets	N	
194	6450	1	2	209B	Storage	Classroom 209 Small Closet	W3	Flaking	10	N	N	0	Y - 28 SF Shelves	N	2 Areas; Including Pipe
195	6450	1	2	209B	Storage	Classroom 209 Small Closet	W4	Cracking	18	N	N	0	Y - 14 SF Shelves	N	2 Areas
196	6450	1	2	222A	Storage	Right Closet across from Classroom 206	Ceiling	Cracking	2	Y	N	0	N	N	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
197	6450	1	2	222A	Storage	Right Closet across from Classroom 206	W2	Cracking	4	Y	N	0	Y - 20 SF Bookcases	N	Stained Walls
198	6450	1	2	222A	Storage	Right Closet across from Classroom 206	W3	Significant Moisture Damage	50	Y	N	0	Y - 50 SF Bookcases	N	Stained Walls
199	6450	1	2	222A	Storage	Right Closet across from Classroom 206	W4	Cracking	6	Y	N	0	Y - 20 SF Bookcases	N	Stained Walls
200	6450	1	2	222B	Storage	Center Closet across from Classroom 206	Ceiling	Significant Moisture Damage	50	Y	N	0	N	N	Stained Ceiling
201	6450	1	2	222B	Storage	Center Closet across from Classroom 206	W2	Cracking	8	Y	N	0	Y - 20 SF Bookcases	N	Stained Walls
202	6450	1	2	222B	Storage	Center Closet across from Classroom 206	W3	Significant Moisture Damage	50	Y	N	0	Y - 50 SF Bookcases	N	Stained Walls
203	6450	1	2	222B	Storage	Center Closet across from Classroom 206	W4	Flaking	8	Y	N	0	Y - 20 SF Bookcases	Y - 1 SF	Stained Walls
204	6450	1	2	222C	Storage	Left Closet across from Classroom 206	Ceiling	Significant Moisture Damage	148	Y	N	0	Y - 35 SF Desks	N	Stained Ceiling
205	6450	1	2	222C	Storage	Left Closet across from Classroom 206	W2	Flaking	16	Y	Y	16	Y - 20 SF Bookcases	N	Stained Walls
206	6450	1	2	222C	Storage	Left Closet across from Classroom 206	W3	Significant Moisture Damage	50	Y	N	0	Y - 50 SF Bookcases	N	Stained Walls
207	6450	1	2	222C	Storage	Left Closet across from Classroom 206	W4	Significant Moisture Damage	25	Y	N	0	Y - 20 SF Bookcases	N	Stained Walls
208	6450	1	2	222D	Storage	Right Closet across from Classroom 204	Ceiling	Flaking	5	Y	N	0	N	N	Stained Ceiling
209	6450	1	2	222D	Storage	Right Closet across from Classroom 204	W2	Cracking	2	Y	N	0	Y - 20 SF Bookcases	N	Stained Walls
210	6450	1	2	222D	Storage	Right Closet across from Classroom 204	W4	Flaking	12	Y	N	0	Y - 20 SF Bookcases	Y - 1 SF	2 Areas; Stained Walls; Including Pipe
211	6450	1	2	222E	Storage	Center Closet across from Classroom 204	Ceiling	Significant Moisture Damage	0	N	N	0	N	N	
212	6450	1	2	222E	Storage	Center Closet across from Classroom 204	W2	Cracking	1	N	N	0	Y - 20 SF Crates, Boxes	N	
213	6450	1	2	222E	Storage	Center Closet across from Classroom 204	W3	Significant Moisture Damage	15	Y	N	0	Y - 50 SF Bookcases	N	Stained Walls
214	6450	1	2	222E	Storage	Center Closet across from Classroom 204	W4	Cracking	4	Y	N	0	Y - 20 SF Bookcases & Crates	N	Stained Walls
215	6450	1	2	222F	Storage	Left Closet across from Classroom 204	Ceiling	Significant Moisture Damage	140	N	N	0	Y - 35 SF Desks	N	Stained Walls
216	6450	1	2	222F	Storage	Left Closet across from Classroom 204	W2	Cracking	2	Y	N	0	Y - 20 SF Bookcases	N	
217	6450	1	2	222F	Storage	Left Closet across from Classroom 204	W3	Significant Moisture Damage	15	N	N	0	Y - 50 SF Bookcases	N	Stained Walls
218	6450	1	2	222F	Storage	Left Closet across from Classroom 204	W4	Cracking	3	Y	N	0	Y - 20 SF Bookcases & Crates	N	
219	6450	1	2	H21	Circulation (Hallway)	Hallway outside Classrooms 201-202	W2	Flaking	20	N	N	0	Y - 50 SF Posters	N	Additional Cracking
220	6450	1	2	H21	Circulation (Hallway)	Hallway outside Classrooms 201-202	W3	Cracking	3	N	N	0	N	N	
221	6450	1	2	H21	Circulation (Hallway)	Hallway outside Classrooms 201-202	W4/Windows	Flaking/Flaking	60	N/N	N/Y	0/8	N/N	N	Debris on Window Sills 3,4; Flaking on Window Lentils 1,2,3,4,7; Cracking on Walls & Radiator
222	6450	1	2	H22	Circulation (Hallway)	Hallway outside Classrooms 208-209	W2/Windows	Flaking/Flaking	14	N/N	N/Y	16	N/N	N	Debris on Window Sills 1,2,3,4; Flaking on Window Lentils 1,2; Additional Cracking



Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
223	6450	1	2	H22	Circulation (Hallway)	Hallway outside Classrooms 208-209	W3	Flaking	6	N	N	0	Y - 20 SF Posters	N	
224	6450	1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 203-207	W1	Flaking	35	N	N	0	Y - 110 SF Bulletin Board & Posters	N	Additional Cracking
225	6450	1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 203-207	W2	Flaking	1	N	N	0	N	N	
226	6450	1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 203-207	W3	Flaking	55	N	N	0	Y - 35 SF Posters	N	Additional Cracking
227	6450	1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 203-207	W4	Flaking	2	N	N	0	Y - 12 SF Posters	N	Additional Cracking
228	6450	1	2	S22	Stairs	Boy's Side Stairwell	Floor	Chipping	10	N	N	0	N	N	
229	6450	1	2	S22	Stairs	Boy's Side Stairwell	W1	Cracking	12	N	N	0	N	N	
230	6450	1	2	S22	Stairs	Boy's Side Stairwell	W3	Flaking/Flaking	32	N/N	N/Y	16	N/N	N	Debris on Window Sill 2; Additional Cracking
231	6450	1	2	S22	Stairs	Boy's Side Stairwell	W4	Chipping	36	N	N	0	N	N	Including Pipe; Additional Cracking
232	6450	1	2	S25	Stairs	Girl's Side Stairwell	Floor	Chipping	10	N	N	0	N	N	
233	6450	1	2	S25	Stairs	Girl's Side Stairwell	W1	Flaking	32	N	N	0	N	N	Additional Cracking
234	6450	1	2	S25	Stairs	Girl's Side Stairwell	W3/Windows	Cracking/Flaking	1/8	N/N	N/N	0/0	N/N	N/N	N/Window Frames 3-8
235	6450	1	1	100	Administrative Office	School Psychologist Office	W2	Flaking	40	N	N	0	Y - 24 SF Posters	N	
236	6450	1	1	100	Administrative Office	School Psychologist Office	W3/Windows	Cracking	12	N	N	0	Y - 20 SF Posters	N	
237	6450	1	1	100	Administrative Office	School Psychologist Office	W4	Flaking	20	N	N	0	Y - 10 SF File Cabinets & Paper	Y - 4 SF	Additional Cracks & Holes
238	6450	1	1	101	Primary	Classroom 101	W1	Cracking	6	N	N	0	Y - 230 SF Bulletin Board & Posters	N	
239	6450	1	1	101	Primary	Classroom 101	W3/Windows	Flaking/Flaking	36	N/N	Y/Y	12/16	N/N	N/N	Behind Radiators and on Pipe Opposite Restrooms/Flaking and Debris on Window Lentils & Sills 1,2,3,8
240	6450	1	1	101	Primary	Classroom 101	W4	Cracking	18	N	N	0	N	N	
241	6450	1	1	103	Primary	Classroom 103	W1	Cracking	16	N	N	0	N	N	2 Locations; Additional Chipping
242	6450	1	1	103	Primary	Classroom 103	W3/Windows	Flaking/None	20	N/N	N/N	0/0	Y - 8 SF Posters/N	N	4 Locations; Including Pipe
243	6450	1	1	103	Primary	Classroom 103	W4	Flaking	18	N	N	0	Y - 6 SF File Cabinets	N	
244	6450	1	1	104	Primary	Classroom 104	W1	Cracking	26	N	N	0	Y - 169 SF Bulletin Boards & Posters	N	6 Locations; Additional Chipping
245	6450	1	1	104	Primary	Classroom 104	W2	Cracking	27	N	N	0	Y - 26 SF Bulletin Boards & Posters	N	2 Locations
246	6450	1	1	104	Primary	Classroom 104	W3/Windows	Cracking/None	5	N/N	N/N	0/0	Y - 100 SF Bulletin Boards & Posters/N	N/N	
247	6450	1	1	105	Administrative Office	Main Office	W1	Cracking	4	N	N	0	Y - 14 SF File Cabinets	N	2 Locations; Additional Chipping
248	6450	1	1	105	Administrative Office	Main Office	W2	Cracking	5	N	N	0	Y - 48 SF Bookcase	N	2 Locations
249	6450	1	1	105	Administrative Office	Main Office	W3	Flaking	1	N	N	0	Y - 64 SF Desks	N	Flaking on Pipe
250	6450	1	1	105	Administrative Office	Main Office	W4	Holes	1	N	N	0	Y - 30 SF Bulletin Boards & Posters	N	
251	6450	1	1	106	ESE Full Time	Classroom 106	W1	Flaking	11	N	N	0	N	N	4 Locations; Additional Cracking & Chipping
252	6450	1	1	106	ESE Full Time	Classroom 106	W2	Flaking	13	N	N	0	N	N	4 Locations; Additional Cracking & Chipping

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
253	6450	1	1	106	ESE Full Time	Classroom 106	W3/Windows	Flaking/Flaking	35	N/N	N/Y	0/16	Y - 16 SF Bookcases/N	Y - 1 SF/ Y - 2 SF	6 Locations; Additional Cracking & Chipping Including Pipe; Window Lentils & Sills 2,3,4,5
254	6450	1	1	106	ESE Full Time	Classroom 106	W4	Flaking	16	N	N	0	N	N	2 Locations; Additional Cracking
255	6450	1	1	107	Primary	Classroom 107	W1	Flaking	27	N	N	0	Y - 96 SF Bulletin Boards	N	3 Locations; Additional Cracking
256	6450	1	1	107	Primary	Classroom 107	W3/Windows	Flaking/None	33	N/N	N/N	0/0	Y - 20 SF Posters/N	N/N	5 Locations Including Pipe; Additional Cracking
257	6450	1	1	107	Primary	Classroom 107	W4	Cracking	1	N	N	0	N	N	
258	6450	1	1	108	Primary	Classroom 108	W1	Flaking	6	N	N	0	Y - 6 SF Posters	Y - 1 SF	3 Locations; Additional Cracking
259	6450	1	1	108	Primary	Classroom 108	W2	Cracking	3	N	N	0	N	N	2 Locations
260	6450	1	1	108	Primary	Classroom 108	W3/Windows	Flaking/Flaking	27	N/N	N/Y	0/16	Y - 45 SF File Cabinets/N	N/N	5 Locations; Additional Cracking & Holes; Debris and Flaking on Window Lentils & Sills 1,2,3,4
261	6450	1	1	109	Administrative Office	Office 109 adjacent to Women's Room	W1	Cracking	2	N	N	0	N	N	2 Locations
262	6450	1	1	109	Administrative Office	Office 109 adjacent to Women's Room	W2/Windows	Cracking/None	10	N/N	N/N	0/0	Y - 12 SF Bookcase/N	N/N	2 Locations/
263	6450	1	1	109	Administrative Office	Office 109 adjacent to Women's Room	W3	Cracking	6	N	N	0	N	N	
264	6450	1	1	109	Administrative Office	Office 109 adjacent to Women's Room	W4	Flaking	6	N	N	0	Y - 12 SF Desks	N	Additional Cracking
265	6450	1	1	111	Student Restrooms - Female (4-12)	1st Floor Girl's Restroom	Ceiling	Flaking	4	N	N	0	N	N	4 Locations
266	6450	1	1	113	Auditorium	Auditorium	Ceiling	Flaking	160	N	N	0	N	N	5 Locations; Additional Cracks & Holes
267	6450	1	1	113	Auditorium	Auditorium	W1	Flaking	7	N	Y	2	N	N	3 Locations; Additional Cracks
268	6450	1	1	113	Auditorium	Auditorium	W2/Windows	Flaking/None	44	N/N	Y	4	N/Y - Curtains	N/N	9 Locations; Debris on Floor Behind Radiator; Additional Cracks, Chips, Holes
269	6450	1	1	113	Auditorium	Auditorium	W3	Flaking	38	N	N	0	N	N	7 Locations; Additional Cracks, Chips, Holes
270	6450	1	1	113	Auditorium	Auditorium	W4/Windows	Flaking/Flaking	40	N/N	N	0	N/Y - Curtains	N/Y - 4 SF	2 Locations/4 Locations; Window Lentils & Frames 1,4
271	6450	1	1	116	Student Restrooms - Male (4-12)	1st Floor Boy's Restroom	Ceiling	Flaking	1	N	N	0	N	N	6 Areas; Additional Holes
272	6450	1	1	101A	Student Restrooms - Male (4-12)	Classroom 101 Boy's Restroom	Ceiling	Cracking	25	N	N	0	N	N	
273	6450	1	1	101B	Storage	Classroom 101 Small Closet	Ceiling	Cracking	36	N	N	0	N	N	
274	6450	1	1	101B	Storage	Classroom 101 Small Closet	W1	Cracking	4	N	N	0	N	N	
275	6450	1	1	101B	Storage	Classroom 101 Small Closet	W3/Windows	Cracking/None	12	N/N	N/N	0/0	Y - 24 SF Bookcase/N	N/N	
276	6450	1	1	101B	Storage	Classroom 101 Small Closet	W4	Cracking	36	N	N	0	Y - 48 SF Bookcase	N	
277	6450	1	1	101C	Storage	Classroom 101 Large Closet	W1	Chipping	1	N	N	0	Y - 24 SF Coats	N	
278	6450	1	1	101C	Storage	Classroom 101 Large Closet	W2	Cracking	10	N	N	0	Y - 45 SF Coats	N	
279	6450	1	1	101C	Storage	Classroom 101 Large Closet	W4	Cracking	36	N	N	0	N	N	
280	6450	1	1	101D	Student Restrooms - Female (4-12)	Classroom 101 Girl's Restroom	Ceiling	Cracking	10	N	N	0	N	N	
281	6450	1	1	103A	Storage	Classroom 103 Large Closet	W1	Cracking	110	N	N	0	N	N	3 Locations; Including Pipe
282	6450	1	1	103A	Storage	Classroom 103 Large Closet	W2	Cracking	16	N	N	0	N	N	
283	6450	1	1	103A	Storage	Classroom 103 Large Closet	W3	Cracking	120	N	N	0	N	N	
284	6450	1	1	103A	Storage	Classroom 103 Large Closet	W4	Cracking	40	N	N	0	N	N	
285	6450	1	1	103B	Storage	Classroom 103 Small Closet	Ceiling	Cracking	30	N	N	0	Y - 40 SF Bookcases	N	
286	6450	1	1	103B	Storage	Classroom 103 Small Closet	W1	Cracking	5	N	N	0	Y - 35 SF Bookcases	N	
287	6450	1	1	103B	Storage	Classroom 103 Small Closet	W2	Cracking	5	N	N	0	Y - 40 SF Bookcases	N	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
288	6450	1	1	103B	Storage	Classroom 103 Small Closet	W3	Cracking	5	N	N	0	Y - 35 SF Bookcases	N	
289	6450	1	1	103B	Storage	Classroom 103 Small Closet	W4	Cracking	5	N	N	0	Y - 40 SF Bookcases	N	
290	6450	1	1	104A	Storage	Classroom 104 Large Closet	W1	Cracking	8	N	N	0	Y - 24 SF Carts	N	
291	6450	1	1	104A	Storage	Classroom 104 Large Closet	W2	Cracking	16	N	N	0	Y - 24 SF Bookcases	N	
292	6450	1	1	104A	Storage	Classroom 104 Large Closet	W3	Cracking	24	N	N	0	N	N	
293	6450	1	1	104B	Storage	Classroom 104 Small Closet	Ceiling	Cracking	42	N	N	0	N	N	
294	6450	1	1	105A	Storage	Main Office Large Closet	W2	Cracking	3	N	N	0	Y - 48 SF Bookcases	N	
295	6450	1	1	105A	Storage	Main Office Large Closet	W3	Flaking	35	N	N	0	Y - 120 SF Bookcases	N	2 Locations; Additional Cracking
296	6450	1	1	105A	Storage	Main Office Large Closet	W4	Cracking	3	N	N	0	Y - 12 SF Contents	N	
297	6450	1	1	105B	Administrative Office	Principal's Office	W1	Cracking	3	N	N	0	Y - 120 SF Bulletin Boards, Posters, Bookcases	N	
298	6450	1	1	105B	Administrative Office	Principal's Office	W3/Windows	Flaking/None	4	N/N	N/N	0/0	Y - 126 SF Bulletin Boards, Desks, File Cabinets/N	N/N	Flaking on Pipe
299	6450	1	1	105B	Administrative Office	Principal's Office	W4	Cracking	10	N	N	0	N	N	
300	6450	1	1	105D	Storage	Main Office Small Closet	Ceiling	Cracking	8	N	N	0	N	N	
301	6450	1	1	105D	Storage	Main Office Small Closet	W2	Cracking	7	N	N	0	Y - 10 SF Bookcase	N	
302	6450	1	1	105D	Storage	Main Office Small Closet	W4	Cracking	5	N	N	0	Y - 10 SF Bookcase	N	
303	6450	1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	Ceiling	Flaking	12	N	Y	12	N	N	2 Locations
304	6450	1	1	106B	Laundry/Towel Distribution	Classroom 106 Laundry Room	W1	Cracking	6	N	N	0	N	N	
305	6450	1	1	106B	Laundry/Towel Distribution	Classroom 106 Laundry Room	W2	Cracking	15	N	N	0	N	N	
306	6450	1	1	106B	Laundry/Towel Distribution	Classroom 106 Laundry Room	W3	Cracking	4	N	N	0	Y - 18 SF Washer/Dryer	N	
307	6450	1	1	106C	Storage	Classroom 106 Closet	Ceiling	Cracking	24	N	N	0	Y - 42 SF Bookcase	N	
308	6450	1	1	107A	Storage	Classroom 107 Large Closet	W1	Cracking	6	N	N	0	N	N	
309	6450	1	1	107A	Storage	Classroom 107 Large Closet	W3	Cracking	12	N	N	0	Y - 90 SF Boxes	N	
310	6450	1	1	107A	Storage	Classroom 107 Large Closet	W4	Cracking	15	N	N	0	Y - 15 SF Cabinets	N	
311	6450	1	1	107B	Storage	Classroom 107 Small Closet	Ceiling	Cracking	20	N	N	0	N	N	
312	6450	1	1	108A	Storage	Classroom 108 Large Closet	W1	Cracking	24	N	N	0	N	N	
313	6450	1	1	108A	Storage	Classroom 108 Large Closet	W2	Cracking	8	N	N	0	Y - 18 SF Bookcases	N	
314	6450	1	1	108A	Storage	Classroom 108 Large Closet	W4	Cracking	12	N	N	0	N	N	
315	6450	1	1	108B	Storage	Classroom 108 Small Closet	W1	Cracking	2	N	N	0	Y - 8 SF Bookcase	N	
316	6450	1	1	108B	Storage	Classroom 108 Small Closet	W2	Cracking	4	N	N	0	Y - 42 SF Bookcase	N	
317	6450	1	1	108B	Storage	Classroom 108 Small Closet	W3	Flaking	7	N	N	0	Y - 21 SF Bookcase	N	Pipe
318	6450	1	1	108B	Storage	Classroom 108 Small Closet	W4	Cracking	48	N	N	0	Y - 6 SF Bookcase	N	
319	6450	1	1	111A	Storage	Left Closet across from Classroom 104	Ceiling	Cracking	3	N	N	0	Y - 35 SF Desks	N	2 Locations; Additional Chipping

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
320	6450	1	1	111A	Storage	Left Closet across from Classroom 104	W2	Cracking	4	N	N	0	Y - 10 SF Bookcase	N	
321	6450	1	1	111A	Storage	Left Closet across from Classroom 104	W4	Cracking	2	N	N	0	Y - 10 SF Bookcase	N	
322	6450	1	1	111B	Storage	Center Closet across from Classroom 104	W2	Cracking	35	N	N	0	Y - 10 SF Bookcase	N	
323	6450	1	1	111B	Storage	Center Closet across from Classroom 104	W4	Cracking	3	N	N	0	Y - 10 SF Bookcase	N	
324	6450	1	1	111C	Storage	Right Closet across from Classroom 104	Ceiling	Cracking	4	N	N	0	Y - 35 SF Desks	N	
325	6450	1	1	111C	Storage	Right Closet across from Classroom 104	W2	Cracking	3	N	N	0	Y - 10 SF Bookcase	N	
326	6450	1	1	111D	Storage	Left Closet across from Classroom 106	Ceiling	Flaking	5	N	N	0	Y - 35 SF Desks	Y - 1 SF	Pipe Paint; Additional Holes
327	6450	1	1	111D	Storage	Left Closet across from Classroom 106	W2	Flaking	31	N	N	0	Y - 10 SF Bookcase	N	Pipe Paint; Additional Cracking
328	6450	1	1	111E	Storage	Center Closet across from Classroom 106	W4	Cracking	6	N	N	0	Y - 10 SF Bookcase	N	
329	6450	1	1	111F	Storage	Right Closet across from Classroom 106	W2	Cracking	4	N	N	0	Y - 10 SF Bookcase	N	
330	6450	1	1	111F	Storage	Right Closet across from Classroom 106	W4	Cracking	2	N	N	0	Y - 10 SF Bookcase	N	
331	6450	1	1	113A	Storage	Auditorium Storage Room to Left of Stage	W1	Chipping	1	N	N	0	N	N	
332	6450	1	1	113A	Storage	Auditorium Storage Room to Left of Stage	W2	Chipping	3	N	N	0	N	N	2 Locations
333	6450	1	1	113C	Stage	Auditorium Stage	W1	Significant Moisture Damage	4	N	N	0	N	Y - 4 SF	
334	6450	1	1	113C	Stage	Auditorium Stage	W2	Flaking	8	N	N	0	N	N	
335	6450	1	1	113C	Stage	Auditorium Stage	W3	Chipping	1	N	N	0	N	N	
336	6450	1	1	113C	Stage	Auditorium Stage	W4	Chipping	1	N	N	0	N	N	
337	6450	1	1	113D	Storage	Auditorium Storage Room to Right of Stage	Ceiling	Flaking	7	Y	N	0	N	N	2 Locations; Additional Efflorescence & Cracking
338	6450	1	1	113D	Storage	Auditorium Storage Room to Right of Stage	W3	Cracking	12	N	N	0	N	N	
339	6450	1	1	113D	Storage	Auditorium Storage Room to Right of Stage	W4	Chipping	4	N	N	0	N	N	
340	6450	1	1	H11	Circulation (Hallway)	Hallway outside Classroom 101	Floor	Flaking	4	N	N	0	N	N	Floor Paint
341	6450	1	1	H11	Circulation (Hallway)	Hallway outside Classroom 101	W2	Flaking	70	N	N	0	Y - 115 SF Posters, Pictures	N	Additional Cracking & Chipping
342	6450	1	1	H11	Circulation (Hallway)	Hallway outside Classroom 101	W3	Cracking	5	N	N	0	N	N	Additional Gouges
343	6450	1	1	H11	Circulation (Hallway)	Hallway outside Classroom 101	W4/Windows	Flaking/Flaking	68	N/N	N/Y	0/8	Y - 20 SF Pictures/N	N	Additional Cracking & Chipping; Flaking & Debris on Window Lintels & Sills 3 & 4
344	6450	1	1	H12	Circulation (Hallway)	Hallway outside Classrooms 107-108	W2/Windows	Flaking/Flaking	115	N/N	N/N	0/0	Y - 20 SF Pictures/N	N/N	
345	6450	1	1	H12	Circulation (Hallway)	Hallway outside Classrooms 107-108	W3	Cracking	7	N	N	0	N	N	Additional Cracking & Chipping
346	6450	1	1	H12	Circulation (Hallway)	Hallway outside Classrooms 107-108	W4	Flaking	86	N	N	0	Y - 64 SF Pictures & Posters	Y - 3 SF	
347	6450	1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 103-106	W1	Flaking	112	N	N	0	Y - 190 SF Pictures	N	Additional Cracking, Chipping, Holes
348	6450	1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 103-106	W2	Flaking	12	N	N	0	Y - 12 SF Bulletin Board	Y -1 SF	Additional Cracking

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
349	6450	1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 103-106	W3	Flaking	44	N	N	0	Y - 20 SF Bulletin Board, Pictures	N	Additional Cracking & Chipping
350	6450	1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 103-106	W4	Cracking	9	N	N	0	Y - 15 SF Bulletin Board, Posters	N	
351	6450	1	1	H13A	Circulation (Hallway)	Main Entrance	Ceiling	Cracking	144	N	N	0	N	N	
352	6450	1	1	H13A	Circulation (Hallway)	Main Entrance	W1	Flaking	18	N	N	0	N	N	Additional Cracking
353	6450	1	1	H13A	Circulation (Hallway)	Main Entrance	W2	Spalling	45	N	N	0	N	N	
354	6450	1	1	H13A	Circulation (Hallway)	Main Entrance	W4	Cracking	40	N	N	0	N	N	
355	6450	1	1	H13B	Storage	Closet adjacent to Main Entrance	W2	Cracking	6	N	N	0	Y - 16 SF Bookcase	N	
356	6450	1	1	H13B	Storage	Closet adjacent to Main Entrance	W3	Cracking	10	N	N	0	Y - 80 SF Bookcase	N	
357	6450	1	1	S12	Stairs	Boy's Side Stairwell	Floor	Chipping	20	N	N	0	N	N	
358	6450	1	1	S12	Stairs	Boy's Side Stairwell	W1	Chipping	4	N	N	0	N	N	Additional Cracking
359	6450	1	1	S12	Stairs	Boy's Side Stairwell	W3/Windows	Cracking/None	3	N/N	N/N	0/0	N/N	N/N	
360	6450	1	1	S15	Stairs	Girl's Side Stairwell	Floor	Chipping	12	N	N	0	N	N	Floor Paint
361	6450	1	1	S15	Stairs	Girl's Side Stairwell	W1	Cracking	48	N	N	0	N	N	
362	6450	1	0	001	Student Restrooms - Male (4-12)	Basement Boy's Restroom	Ceiling	Flaking	55	N	N	0	N	N	Flaking Pipe Paint; Additional Cracking
363	6450	1	0	002	Cafeteria (Dining Area)	Small Cafeteria	Floor	Chipping	26	N	N	0	N	N	Around Perimeter
364	6450	1	0	002	Cafeteria (Dining Area)	Small Cafeteria	W1	Flaking	100	N	N	0	Y - 52 SF Bulletin Boards, Shelves	N	Additional Cracking
365	6450	1	0	002	Cafeteria (Dining Area)	Small Cafeteria	W2	Cracking	16	N	N	0	Y - 40 SF Bulletin Boards	N	
366	6450	1	0	002	Cafeteria (Dining Area)	Small Cafeteria	W3/Windows	Flaking/Flaking	82	N/N	N/Y	0/1	Y - 27 SF Shelving	N/N	Additional Cracking/Debris on Window Sill 5
367	6450	1	0	002	Cafeteria (Dining Area)	Small Cafeteria	W4	Flaking	30	N	N	0	Y - 96 SF Shelving	N	Additional Cracking
368	6450	1	0	003	Cafeteria (Dining Area)	Large Cafeteria	Ceiling	Flaking	24	N	N	0	N	N	1' x 1' Ceiling Tile, 24 SF Plaster Ceiling Near Windows
369	6450	1	0	003	Cafeteria (Dining Area)	Large Cafeteria	Floor	Chipping	8	N	N	0	N	N	Around Perimeter
370	6450	1	0	003	Cafeteria (Dining Area)	Large Cafeteria	W1	Flaking	186	N	N	0	Y - 186 SF Contents	N	Additional Cracking
371	6450	1	0	003	Cafeteria (Dining Area)	Large Cafeteria	W2	Flaking	64	N	N	0	Y - 60 SF Bulletin Board & Posters	N	Additional Cracking
372	6450	1	0	003	Cafeteria (Dining Area)	Large Cafeteria	W3	Flaking	144	N	N	0	Y - 100 SF File Cabinets & Posters	N	Additional Cracking
373	6450	1	0	003	Cafeteria (Dining Area)	Large Cafeteria	W4	Flaking	76	N	N	0	Y - 72 SF File Cabinets & Posters	N	Additional Cracking
374	6450	1	0	007	Student Restrooms - Female (4-12)	Basement Girl's Restroom	Ceiling	Cracking	40	N	N	0	N	N	4 Locations
375	6450	1	0	009	Gymnasium - Intermediate Middle	Gym	Ceiling	Cracking	22	N	N	0	N	N	
376	6450	1	0	009	Gymnasium - Intermediate Middle	Gym	W1	Flaking	20	N	N	0	N	N	Additional Cracking
377	6450	1	0	009	Gymnasium - Intermediate Middle	Gym	W3	Flaking	50	N	N	0	N	N	
378	6450	1	0	009	Gymnasium - Intermediate Middle	Gym	W4	Flaking	26	N	N	0	N	N	Additional Spalling
379	6450	1	0	009B	Administrative Office	Gym Office	Ceiling	Cracking	10	N	N	0	N	N	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
380	6450	1	0	009C	Storage	Gym Storage Closet	Ceiling	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
381	6450	1	0	009C	Storage	Gym Storage Closet	Floor	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
382	6450	1	0	009C	Storage	Gym Storage Closet	W1	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
383	6450	1	0	009C	Storage	Gym Storage Closet	W2	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
384	6450	1	0	009C	Storage	Gym Storage Closet	W3	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
385	6450	1	0	009C	Storage	Gym Storage Closet	W4	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
386	6450	1	0	H01	Circulation (Hallway)	Hallway outside Basement Boy's Restroom	Ceiling	Flaking	50	N	N	0	Y - 300 SF Ductwork	N	
387	6450	1	0	H01	Circulation (Hallway)	Hallway outside Basement Boy's Restroom	Floor	Flaking	48	N	N	0	N	N	Flaking Between Water Fountain and Stairs; Additional Cracking
388	6450	1	0	H01	Circulation (Hallway)	Hallway outside Basement Boy's Restroom	W3	Efflorescence	3	N	N	0	N	N	Additional Cracking
389	6450	1	0	H01	Circulation (Hallway)	Hallway outside Basement Boy's Restroom	W4	Flaking	62	N	N	0	N	Y - 10 SF	
390	6450	1	0	H02	Circulation (Hallway)	Hallway outside Basement Girl's Restroom	Ceiling	Flaking	42	N	N	0	Y - 300 SF Ductwork	N	
391	6450	1	0	H02	Circulation (Hallway)	Hallway outside Basement Girl's Restroom	Floor	Cracking	64	N	N	0	N	N	
392	6450	1	0	H02	Circulation (Hallway)	Hallway outside Basement Girl's Restroom	W2	Flaking	90	N	N	0	N	N	Including Paint on Pipe; Additional Cracking
393	6450	1	0	H02	Circulation (Hallway)	Hallway outside Basement Girl's Restroom	W3	Cracking	6	N	N	0	N	N	
394	6450	1	0	H02	Circulation (Hallway)	Hallway outside Basement Girl's Restroom	W4	Flaking	4	N	N	0	N	N	
395	6450	1	0	H03	Circulation (Hallway)	Hallway outside Large Cafeteria and Boiler Room	Ceiling	Flaking	400	N	N	0	Y - 500 SF Ductwork	N	Additional Cracking
396	6450	1	0	H03	Circulation (Hallway)	Hallway outside Large Cafeteria and Boiler Room	W1	Flaking	18	N	N	0	N	N	Additional Cracking
397	6450	1	0	H03	Circulation (Hallway)	Hallway outside Large Cafeteria and Boiler Room	W2	Flaking	16	N	N	0	N	N	Additional Cracking
398	6450	1	0	H03	Circulation (Hallway)	Hallway outside Large Cafeteria and Boiler Room	W3	Flaking	33	N	N	0	N	N	Additional Cracking
399	6450	1	0	H03	Circulation (Hallway)	Hallway outside Large Cafeteria and Boiler Room	W4	Flaking	4	N	N	0	N	N	
400	6450	1	0	S02	Stairs	Boy's Side Stairwell	Floor	Flaking	12	N	N	0	N	N	
401	6450	1	0	S02	Stairs	Boy's Side Stairwell	W1	Flaking	154	N	N	0	N	N	3 Locations; Flaking on Pipe and on Wall above Granite; Additional Cracking
402	6450	1	0	S02	Stairs	Boy's Side Stairwell	W2	Cracking	12	N	N	0	N	N	
403	6450	1	0	S02	Stairs	Boy's Side Stairwell	W3/Windows	Flaking/Flaking	26	N/N	N/N	0/2	N/N	N/N	2 Locations/Debris on Window Sill 1
404	6450	1	0	S02	Stairs	Boy's Side Stairwell	W4	Cracking	12	N	N	0	N	N	
405	6450	1	0	S02A	Storage	Boy's Side Stairwell Recess Equipment Closet	Ceiling	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
406	6450	1	0	S02A	Storage	Boy's Side Stairwell Recess Equipment Closet	Floor	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
407	6450	1	0	S02A	Storage	Boy's Side Stairwell Recess Equipment Closet	W1	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
408	6450	1	0	S02A	Storage	Boy's Side Stairwell Recess Equipment Closet	W2	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
409	6450	1	0	S02A	Storage	Boy's Side Stairwell Recess Equipment Closet	W3	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
410	6450	1	0	S02A	Storage	Boy's Side Stairwell Recess Equipment Closet	W4	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
411	6450	1	0	S02B	Storage	Boy's Side Stairwell Closet below Stairs	Ceiling	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	
412	6450	1	0	S02B	Storage	Boy's Side Stairwell Closet below Stairs	Floor	Not Accessible	N/A	N/A	N/A	N/A	N/A	N/A	

