

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Boiler Room	W1	Brick	White	Flaking	800	36.8	Positive
1	B	Boiler Room	W1	Concrete	White	Flaking	400	22.7	Positive
1	B	Boiler Room	W2	Brick	White	Flaking	1100	21.1	Positive
1	B	Boiler Room	W2	Concrete	White	Flaking	500	41.3	Positive
1	B	Boiler Room	W3	Brick	White	Flaking	750	21.4	Positive
1	B	Boiler Room	W3	Concrete	White	Flaking	100	41	Positive
1	B	Boiler Room	W4	Brick	White	Flaking	450	23.2	Positive
1	B	Boiler Room	W4	Concrete	White	Flaking	200	37.5	Positive
1	B	Boiler Room	Pillar	Concrete	Blue	Flaking	500	23.3	Positive
1	B	Boiler Room	Ceiling	Concrete	White	Flaking	750	29.4	Positive
1	B	Boiler Room	Conduit Pipe	Metal	Grey	None	0	0	Negative
1	B	Boiler Room	Pipe	Metal	White	Flaking	70	10.3	Positive
1	B	Boiler Room	Engine Pedastal	Concrete	White	None	0	0.11	Negative
1	B	Boiler Room	Door Casing	Metal	Grey	None	0	0	Negative
1	B	Boiler Room	Door	Metal	Grey	None	0	0	Negative
1	B	Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Boiler Room Staff Restroom	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Boiler Room Staff Restroom	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Boiler Room Staff Restroom	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Boiler Room Staff Restroom	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Boiler Room Staff Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Boiler Room Staff Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Fire Exit Stairwell near Boiler Room	W1	Brick	Grey	Flaking	30	52.7	Positive
1	B	Fire Exit Stairwell near Boiler Room	W2	Brick	Grey	Flaking	140	56	Positive
1	B	Fire Exit Stairwell near Boiler Room	W3	Brick	Grey	Flaking	15	51.4	Positive
1	B	Fire Exit Stairwell near Boiler Room	W4	Brick	Grey	Flaking	150	53.9	Positive
1	B	Fire Exit Stairwell near Boiler Room	Ceiling	Concrete	White	Flaking	75	2.7	Positive
1	B	Fire Exit Stairwell near Boiler Room	Floor	Concrete	Grey	Friction	60	2.5	Positive
1	B	Electrical/Fan Room next to Boiler Room	W1	Brick	White	Flaking	300	1.2	Positive
1	B	Electrical/Fan Room next to Boiler Room	W1	Concrete	White	Flaking	40	0.03	Negative
1	B	Electrical/Fan Room next to Boiler Room	W2	Brick	White	Flaking	400	31.8	Positive
1	B	Electrical/Fan Room next to Boiler Room	W2	Concrete	White	Flaking	25	42.7	Positive
1	B	Electrical/Fan Room next to Boiler Room	W3	Brick	White	Flaking	250	32.4	Positive
1	B	Electrical/Fan Room next to Boiler Room	W3	Concrete	White	Flaking	50	38.5	Positive
1	B	Electrical/Fan Room next to Boiler Room	W4	Brick	White	Flaking	500	44.8	Positive

		<b>Dates: 3/16/23-3/31/23</b>	<b>Lead-Safe Certification Assessment Report</b>						
		<b>Inspector Name and Certificate Number: Christopher Karoly 006424</b>	<b>The U School @ Ferguson Elementary School School</b>						
		<b>Inspection Company: Criterion Laboratories</b>	<b>2000 N.7th Street, Philadelphia, PA 19122</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	B	Electrical/Fan Room next to Boiler Room	W4	Concrete	White	Flaking	25	30.2	Positive
1	B	Electrical/Fan Room next to Boiler Room	Fan Unit	Metal	White	Flaking	2000	10.4	Positive
1	B	Electrical/Fan Room next to Boiler Room	Conduit	Metal	White	None	0	0	Negative
1	B	Electrical/Fan Room next to Boiler Room	Ceiling	Concrete	White	Flaking	500	10.1	Positive
1	B	Electrical/Fan Room next to Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Staff Shower next to Fan/Electrical Room	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Staff Shower next to Fan/Electrical Room	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Staff Shower next to Fan/Electrical Room	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Staff Shower next to Fan/Electrical Room	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Staff Shower next to Fan/Electrical Room	Duct	Metal	White	Flaking	4	24.6	Positive
1	B	Staff Shower next to Fan/Electrical Room	Pipe	Metal	White	Flaking	5	29.3	Positive
1	B	Staff Shower next to Fan/Electrical Room	Ceiling	Plaster	White	Flaking	10	15.7	Positive
1	B	Staff Shower next to Fan/Electrical Room	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Small Storage next to Boiler Room	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Small Storage next to Boiler Room	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Small Storage next to Boiler Room	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Small Storage next to Boiler Room	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Small Storage next to Boiler Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Small Storage next to Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Storage Room off the stairwell across from Boys Restroom	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Storage Room off the stairwell across from Boys Restroom	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Storage Room off the stairwell across from Boys Restroom	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Storage Room off the stairwell across from Boys Restroom	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Storage Room off the stairwell across from Boys Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Storage Room off the stairwell across from Boys Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Large Storage Room next to Boiler Room	W1	Brick	White	Flaking	40	23.1	Positive
1	B	Large Storage Room next to Boiler Room	W2	Brick	White	Flaking	60	20.7	Positive
1	B	Large Storage Room next to Boiler Room	W3	Brick	White	Flaking	10	24.6	Positive
1	B	Large Storage Room next to Boiler Room	W4	Brick	White	Flaking	20	24.7	Positive
1	B	Large Storage Room next to Boiler Room	Ceiling	Concrete	White	Flaking	200	28.2	Positive

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Large Storage Room next to Boiler Room	Pipe	Metal	Grey	Flaking	10	1.5	Positive
1	B	Large Storage Room next to Boiler Room	Door	Wood	grey	none	0	0.05	Negative
1	B	Large Storage Room next to Boiler Room	Door Casing	Wood	Grey	none	0	0.17	Negative
1	B	Large Storage Room next to Boiler Room	Duct	Metal	White	Flaking	10	24.3	Positive
1	B	Large Storage Room next to Boiler Room	Radiator W2	Metal	Grey	Flaking	5	6.3	Positive
1	B	Large Storage Room next to Boiler Room	Radiator W3	Metal	Grey	Flaking	5	10.1	Positive
1	B	Large Storage Room next to Boiler Room	Floor	Concrete	Grey	None	0	0.01	Negative
1	B	Girl's Restroom near Kitchen	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Girl's Restroom near Kitchen	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Girl's Restroom near Kitchen	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Girl's Restroom near Kitchen	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Girl's Restroom near Kitchen	Ceiling	Plaster	White	Flaking	10	8.2	Positive
1	B	Girl's Restroom near Kitchen	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Custodial Closet near Kitchen	W1	Plaster	White	Flaking	40	25.6	Positive
1	B	Custodial Closet near Kitchen	W2	Plaster	White	Flaking	60	26.5	Positive
1	B	Custodial Closet near Kitchen	W3	Plaster	White	Flaking	50	21.3	Positive
1	B	Custodial Closet near Kitchen	W4	Plaster	White	Flaking	70	34.3	Positive
1	B	Custodial Closet near Kitchen	Ceiling	Plaster	White	Flaking	200	23.8	Positive
1	B	Custodial Closet near Kitchen	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Service Room next to 006	W1	Ceramic tile	unpainted	N/A	N/A	N/A	N/A
1	B	Service Room next to 006	W2	Ceramic tile	unpainted	N/A	N/A	N/A	N/A
1	B	Service Room next to 006	W3	Ceramic tile	unpainted	N/A	N/A	N/A	N/A
1	B	Service Room next to 006	W4	Ceramic tile	unpainted	N/A	N/A	N/A	N/A
1	B	Service Room next to 006	Ceiling	Plaster	White	Flaking	5	21.4	Positive
1	B	Service Room next to 006	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Kitchen	W1	Plaster	White	Flaking	50	12.6	Positive
1	B	Kitchen	W2	Plaster	White	Flaking	100	14.7	Positive
1	B	Kitchen	W3	Plaster	White	Flaking	60	3.4	Positive
1	B	Kitchen	Door Casing	Wood	Brown	None	0	0.04	Negative
1	B	Kitchen	Riser Door	Metal	Yellow	None	0	0.4	Negative
1	B	Kitchen	pipe	Metal	White	Flaking	10	15.6	Positive
1	B	Kitchen	W4	Plaster	White	Flaking	200	13.2	Positive
1	B	Kitchen	Ceiling	Plaster	White	Flaking	65	11.7	Positive
1	B	Kitchen	Duct	Metal	White	Flaking	2	10.2	Positive
1	B	Kitchen	Grate	Metal	Black	Friction	10	0.08	Negative

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Kitchen	Baseboard	Wood	Brown	Friction	20	0.02	Negative
1	B	Kitchen	Floor	Concrete	Black	Friction	400	0	Negative
1	B	Kitchen Storage Walk- in Refrigerators	W1	Plaster	White	Flaking	150	35.4	Positive
1	B	Kitchen Storage Walk- in Refrigerators	W2	Plaster	White	Flaking	5	No Access	No Access
1	B	Kitchen Storage Walk- in Refrigerators	W3	Plaster	White	Flaking	50	37.6	Positive
1	B	Kitchen Storage Walk- in Refrigerators	W4	Plaster	White	Flaking	50	37.1	Positive
1	B	Kitchen Storage Walk- in Refrigerators	Radiator	Metal	Grey	Flaking	5	0.03	Negative
1	B	Kitchen Storage Walk- in Refrigerators	Pipe	Metal	White	None	0	0.01	Negative
1	B	Kitchen Storage Walk- in Refrigerators	Ceiling	Plaster	White	Flaking	3	9.3	Positive
1	B	Kitchen Storage Walk- in Refrigerators	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Kitchen Office	W1	Plaster	White	Flaking	20	25.5	Positive
1	B	Kitchen Office	W1	Concrete	White	None	0	0	Negative
1	B	Kitchen Office	W2	Plaster	White	None	0	32.6	Positive
1	B	Kitchen Office	W2	Concrete	White	None	0	0	Negative
1	B	Kitchen Office	W3	Plaster	White	None	0	40.9	Positive
1	B	Kitchen Office	W4	Plaster	White	None	0	23.5	Positive
1	B	Kitchen Office	Ceiling	Plaster	White	None	0	3.5	Positive
1	B	Kitchen Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Kitchen Office Closet	W1	Plaster	White	Flaking	10	2.1	Positive
1	B	Kitchen Office Closet	W2	Plaster	White	Flaking	100	1.9	Positive
1	B	Kitchen Office Closet	W3	Plaster	White	Flaking	50	1.6	Positive
1	B	Kitchen Office Closet	W4	Plaster	White	Flaking	100	2	Positive
1	B	Kitchen Office Closet	Ceiling	Plaster	White	Flaking	20	2.9	Positive
1	B	Kitchen Office Closet	Pipe	Metal	White	Flaking	20	27.6	Positive
1	B	Kitchen Office Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Kitchen Staff Restroom	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Kitchen Staff Restroom	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Kitchen Staff Restroom	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Kitchen Staff Restroom	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Kitchen Staff Restroom	Ceiling	Plaster	White	Flaking	5	10.3	Positive
1	B	Kitchen Staff Restroom	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Kitchen Storage next to Bathroom	W1	Plaster	White	Flaking	4	13.6	Positive
1	B	Kitchen Storage next to Bathroom	W2	Plaster	White	Flaking	3	12.5	Positive
1	B	Kitchen Storage next to Bathroom	W3	Plaster	White	Flaking	12	4	Positive
1	B	Kitchen Storage next to Bathroom	W4	Plaster	White	None	0	10.2	Positive

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Kitchen Storage next to Bathroom	Ceiling	Plaster	White	None	0	10.1	Positive
1	B	Kitchen Storage next to Bathroom	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B	Hallway next to Kitchen	W1	Brick	White	Flaking	750	20.9	Positive
1	B	Hallway next to Kitchen	W2	Brick	White	Flaking	50	17.2	Positive
1	B	Hallway next to Kitchen	W3	Brick	White	Flaking	200	4.4	Positive
1	B	Hallway next to Kitchen	W4	Brick	White	Flaking	150	0.9	Positive
1	B	Hallway next to Kitchen	Duct	Metal	White	Flaking	2000	26.1	Positive
1	B	Hallway next to Kitchen	Pipe	Metal	White	Flaking	200	12.9	Positive
1	B	Hallway next to Kitchen	Window Frame W3	Metal	Brown	Flaking	15	16.4	Positive
1	B	Hallway next to Kitchen	Stringer	Concrete	Grey	Flaking	10	8.3	Positive
1	B	Hallway next to Kitchen	Riser	Concrete	Grey	Flaking	8	2.6	Positive
1	B	Hallway next to Kitchen	Door Casing	Metal	Brown	None	0	0	Negative
1	B	Hallway next to Kitchen	Stair Treads	Concrete	Grey	Friction	10	0.7	Positive
1	B	Hallway next to Kitchen	Door W4	Metal	Grey	None	0	0	Negative
1	B	Hallway next to Kitchen	Door Casing W3	Metal	White	None	0	0.03	Negative
1	B	Hallway next to Kitchen	Door W1	Metal	Brown	None	0	0	Negative
1	B	Hallway next to Kitchen	Door Casing W1	Metal	Brown	None	0	0	Negative
1	B	Hallway next to Kitchen	Door W1	Metal	Brown	Friction	5	1.7	Positive
1	B	Hallway next to Kitchen	Door Casing W3	Metal	Brown	Friction	5	2.4	Positive
1	B	Hallway next to Kitchen	Ceiling	Concrete	White	Flaking	1000	5.1	Positive
1	B	Hallway next to Kitchen	Floor	Concrete	Black	None	0	0.04	Negative
1	B	Building Engineer's Office	W1	Plaster	Yellow	Flaking	20	23.7	Positive
1	B	Building Engineer's Office	W2	Plaster	Yellow	Flaking	30	31.6	Positive
1	B	Building Engineer's Office	W3	Plaster	Yellow	Flaking	100	33.7	Positive
1	B	Building Engineer's Office	W4	Plaster	Yellow	Flaking	40	31.3	Positive
1	B	Building Engineer's Office	Ceiling	Plaster	Yellow	Flaking	600	24.7	Positive
1	B	Building Engineer's Office	Radiator	Metal	Grey	Flaking	2	2.1	Positive
1	B	Building Engineer's Office	Pipe	Metal	White	None	0	0	Negative
1	B	Building Engineer's Office	Vent	Metal	Yellow	Flaking	5	42	Positive
1	B	Building Engineer's Office	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B	Building Engineer's Office Storage at Window	W1	Plaster	White	Flaking	200	31.5	Positive

		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>							
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>							
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	B	Building Engineer's Office Storage at Window	W2	Plaster	White	Flaking	100	37.2	Positive	
1	B	Building Engineer's Office Storage at Window	W3	Plaster	White	Flaking	250	42.8	Positive	
1	B	Building Engineer's Office Storage at Window	W4	Plaster	White	Flaking	50	36.5	Positive	
1	B	Building Engineer's Office Storage at Window	Ceiling	Plaster	White	Flaking	250	29.2	Positive	
1	B	Building Engineer's Office Storage at Window	Radiator	Metal	Grey	Flaking	4	1.7	Positive	
1	B	Building Engineer's Office Storage at Window	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B	Building Engineer's Office Storage near Entrance	W1	Plaster	White	Flaking	70	34.1	Positive	
1	B	Building Engineer's Office Storage near Entrance	W2	Plaster	White	Flaking	40	29.4	Positive	
1	B	Building Engineer's Office Storage near Entrance	W3	Plaster	White	Flaking	120	36.9	Positive	
1	B	Building Engineer's Office Storage near Entrance	W4	Plaster	White	Flaking	80	28.5	Positive	
1	B	Building Engineer's Office Storage near Entrance	Ceiling	Plaster	White	Flaking	100	29.8	Positive	
1	B	Building Engineer's Office Storage near Entrance	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B	Cafeteria Room 004A	W1	Brick	White	Flaking	100	4.6	Positive	
1	B	Cafeteria Room 004A	W2	Brick	White	Flaking	50	1.7	Positive	
1	B	Cafeteria Room 004A	W3	Brick	White	Flaking	100	2.2	Positive	
1	B	Cafeteria Room 004A	W4	Brick	White	Flaking	50	1.4	Positive	
1	B	Cafeteria Room 004A	Ceiling	No Access	No Access	Flaking	1000	No Access	No Access	
1	B	Cafeteria Room 004A	Duct	Metal	White	Flaking	500	No Access	No Access	
1	B	Cafeteria Room 004A	Radiator	Metal	Grey	Flaking	40	No Access	No Access	
1	B	Cafeteria Room 004A	Fire Extinguisher Post	Wood	Blue	Flaking	2	0.7	Positive	
1	B	Cafeteria Room 004A	pipe	Metal	White	None	0	0.2	Negative	
1	B	Cafeteria Room 004A	Door	Wood	Blue	None	0	0	Negative	
1	B	Cafeteria Room 004A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B	Cafeteria Storage next to Entrance	W1	Brick	White	Flaking	100	13.1	Positive	
1	B	Cafeteria Storage next to Entrance	W2	Brick	White	Flaking	100	10.3	Positive	
1	B	Cafeteria Storage next to Entrance	W3	Brick	White	Flaking	100	9.5	Positive	
1	B	Cafeteria Storage next to Entrance	W4	Brick	White	Flaking	60	10.2	Positive	
1	B	Cafeteria Storage next to Entrance	Ceiling	Concrete	White	Flaking	50	7.1	Positive	
1	B	Cafeteria Storage next to Entrance	Pipe	Metal	White	Flaking	10	9.8	Positive	
1	B	Cafeteria Storage next to Entrance	Duct	Metal	White	Flaking	800	14.8	Positive	
1	B	Cafeteria Storage next to Entrance	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B	Cafeteria Storage next to Windows	W1	Brick	Yellow	Flaking	100	9.9	Positive	
1	B	Cafeteria Storage next to Windows	W2	Brick	Yellow	Flaking	100	13.2	Positive	

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Cafeteria Storage next to Windows	W3	Brick	Yellow	Flaking	50	1.3	Positive
1	B	Cafeteria Storage next to Windows	W4	Brick	Yellow	Flaking	50	4.4	Positive
1	B	Cafeteria Storage next to Windows	Ceiling	Plaster	White	Flaking	50	11.4	Positive
1	B	Cafeteria Storage next to Windows	Radiator	Metal	Grey	Flaking	5	1.2	Positive
1	B	Cafeteria Storage next to Windows	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Custodial Storage next to Classroom 3	W1	Brick	White	None	0	0.02	Negative
1	B	Custodial Storage next to Classroom 3	W2	Brick	White	None	0	0.01	Negative
1	B	Custodial Storage next to Classroom 3	W2	Brick	Glazed	None	0	0.02	Negative
1	B	Custodial Storage next to Classroom 3	W3	Brick	White	None	0	0.03	Negative
1	B	Custodial Storage next to Classroom 3	W4	Brick	White	None	0	0.01	Negative
1	B	Custodial Storage next to Classroom 3	Ceiling	Plaster	White	None	0	0.04	Negative
1	B	Custodial Storage next to Classroom 3	Duct	Metal	White	None	0	15.7	Positive
1	B	Custodial Storage next to Classroom 3	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Hallway next to Gymnasium	W2	Brick	Yellow	Flaking	350	9.9	Positive
1	B	Hallway next to Gymnasium	Stair tread	Metal	Red	Friction	5	1.4	Positive
1	B	Hallway next to Gymnasium	W4	Brick	Yellow	Flaking	400	20.4	Positive
1	B	Hallway next to Gymnasium	Duct	Metal	White	Flaking	1500	24.8	Positive
1	B	Hallway next to Gymnasium	Ceiling	Concrete	White	Flaking	250	8.2	Positive
1	B	Hallway next to Gymnasium	Floor	Concrete	Black	None	0	0.04	Negative
1	B	Room 4 Storage/Actual Cafe	W1	Brick	White	Cracking	100	21.4	Positive
1	B	Room 4 Storage/Actual Cafe	W2	Brick	White	Cracking	120	25.7	Positive
1	B	Room 4 Storage/Actual Cafe	W3	Brick	White	Cracking	80	23.8	Positive
1	B	Room 4 Storage/Actual Cafe	W4	Brick	White	Cracking	25	24.6	Positive
1	B	Room 4 Storage/Actual Cafe	Ceiling	Concrete	White	Flaking	600	19.2	Positive
1	B	Room 4 Storage/Actual Cafe	Radiator	Metal	White	Flaking	15	1.7	Positive
1	B	Room 4 Storage/Actual Cafe	Duct	Metal	White	Flaking	20	16.2	Positive
1	B	Room 4 Storage/Actual Cafe	Floor	Concrete	Grey	None	0	0	Negative
1	B	Stairwell next to Room 4	W1	Plaster	Yellow	Flaking	80	42.9	Positive
1	B	Stairwell next to Room 4	W2	Plaster	Yellow	Flaking	50	39.8	Positive
1	B	Stairwell next to Room 4	W3	Plaster	Yellow	None	0	41.7	Positive
1	B	Stairwell next to Room 4	W4	Plaster	Yellow	Flaking	20	43.6	Positive
1	B	Stairwell next to Room 4	Ceiling	Plaster	White	Flaking	100	1.6	Positive
1	B	Stairwell next to Room 4	Radiator	Metal	Grey	Flaking	2	1.1	Positive
1	B	Stairwell next to Room 4	Door	Metal	Brown	None	0	0	Negative
1	B	Stairwell next to Room 4	Door Casing	Metal	Brown	None	0	0	Negative

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Stairwell next to Room 4	Stringer	Concrete	Brown	Flaking	50	14.2	Positive
1	B	Stairwell next to Room 4	Balluster	Metal	Brown	Friction	80	9.8	Positive
1	B	Stairwell next to Room 4	Newel	Metal	Brown	Friction	10	10.7	Positive
1	B	Stairwell next to Room 4	Stairs	Concrete	Brown	Friction	40	2.5	Positive
1	B	Stairwell next to Room 4	Floor	Concrete	Brown	None	0	0.02	Negative
1	B	Classroom 5 Electrical Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Classroom 5 Electrical Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Classroom 5 Electrical Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Classroom 5 Electrical Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Classroom 5 Electrical Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Classroom 5 Electrical Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Classroom 5	W1	Plaster	Grey	Flaking	10	31	Positive
1	B	Classroom 5	W2	Plaster	Grey	Flaking	10	26.1	Positive
1	B	Classroom 5	W3	Plaster	Grey	Flaking	5	27.6	Positive
1	B	Classroom 5	W4	Plaster	Grey	Flaking	10	22.2	Positive
1	B	Classroom 5	Ceiling	Plaster	White	Flaking	200	31.2	Positive
1	B	Classroom 5	Radiator	Metal	Grey	Flaking	3	1.9	Positive
1	B	Classroom 5	Pipe	Metal	White	Flaking	4	1.1	Positive
1	B	Classroom 5	Vent Cover	Metal	Grey	Flaking	2	30.3	Positive
1	B	Classroom 5	Vent	Metal	Black	None	0	0.04	Negative
1	B	Classroom 5	Duct	Metal	White	Flaking	10	29.3	Positive
1	B	Classroom 5	Trim	Wood	Brown	None	0	0.07	Negative
1	B	Classroom 5	Baseboard	Wood	Brown	None	0	0	Negative
1	B	Classroom 5	Door Jam	Wood	Brown	None	0	0	Negative
1	B	Classroom 5	Floor	N/A	unpainted	N/A	N/A	N/A	N/A
1	B	Classroom 6	W1	Plaster	White	Flaking	40	25.6	Positive
1	B	Classroom 6	W2	Plaster	White	Flaking	60	26.5	Positive
1	B	Classroom 6	W3	Plaster	White	Flaking	50	21.3	Positive
1	B	Classroom 6	W4	Plaster	White	Flaking	70	34.3	Positive
1	B	Classroom 6	Ceiling	Plaster	White	Flaking	200	23.8	Positive
1	B	Classroom 6	Baseboard	Wood	Brown	None	0	0.04	Negative
1	B	Classroom 6	Vent Hood	Metal	White	Flaking	5	51.3	Positive
1	B	Classroom 6	Radiator	Metal	Grey	Flaking	5	1.1	Positive
1	B	Classroom 6	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Classroom 6 Pipe Chase Closet	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A



		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Classroom 6 Pipe Chase Closet	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Classroom 6 Pipe Chase Closet	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Classroom 6 Pipe Chase Closet	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Classroom 6 Pipe Chase Closet	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Classroom 6 Pipe Chase Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Boy's Restroom next to Classroom 6	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Boy's Restroom next to Classroom 6	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Boy's Restroom next to Classroom 6	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Boy's Restroom next to Classroom 6	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Boy's Restroom next to Classroom 6	Duct	Metal	White	Flaking	10	13.8	Positive
1	B	Boy's Restroom next to Classroom 6	Ceiling	Plaster	White	Flaking	10	14.2	Positive
1	B	Boy's Restroom next to Classroom 6	Floor	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Custodial Closet to left of Classroom 6	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Custodial Closet to left of Classroom 6	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Custodial Closet to left of Classroom 6	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Custodial Closet to left of Classroom 6	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Custodial Closet to left of Classroom 6	Ceiling	Plaster	White	Flaking	10	15.3	Positive
1	B	Custodial Closet to left of Classroom 6	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Custodial Storage across from Classroom 6	W1	Brick	White	None	0	0.01	Negative
1	B	Custodial Storage across from Classroom 6	W2	Brick	White	None	0	0.01	Negative
1	B	Custodial Storage across from Classroom 6	W3	Brick	White	None	0	0	Negative
1	B	Custodial Storage across from Classroom 6	W4	Brick	White	None	0	0.05	Negative
1	B	Custodial Storage across from Classroom 6	Ceiling	Concrete	White	None	0	0.02	Negative
1	B	Custodial Storage across from Classroom 6	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Stairwell to Right of Boiler Room	W2	Concrete	White	None	0	0	Negative
1	B	Stairwell to Right of Boiler Room	W3	Concrete	White	None	0	0	Negative
1	B	Stairwell to Right of Boiler Room	W4	Concrete	White	None	0	0	Negative
1	B	Stairwell to Right of Boiler Room	Stair Riser	Concrete	Brown	None	0	0.03	Negative
1	B	Stairwell to Right of Boiler Room	Stair Tread	Concrete	Brown	None	0	0.18	Negative
1	B	Stairwell to Right of Boiler Room	Ceiling	Plaster	White	None	0	0.01	Negative
1	B	Stairwell to Right of Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Hallway next to Classrooms 5 and 6	W1	Brick	Yellow	Flaking	100	4.6	Positive
1	B	Hallway next to Classrooms 5 and 6	Door Casing W1	Metal	Brown	Flaking	5	3.1	Positive
1	B	Hallway next to Classrooms 5 and 6	Door W1	Metal	Brown	Flaking	5	2.3	Positive

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	Hallway next to Classrooms 5 and 6	W2	Brick	Yellow	Flaking	20	1.4	Positive
1	B	Hallway next to Classrooms 5 and 6	Electrical Box	Metal	Yellow	None	0	0.4	Negative
1	B	Hallway next to Classrooms 5 and 6	Door Casing W3	Metal	Brown	None	0	0	Negative
1	B	Hallway next to Classrooms 5 and 6	Door W3	Metal	Brown	None	0	0	Negative
1	B	Hallway next to Classrooms 5 and 6	Pipe W3	Metal	Yellow	Flaking	10	3.5	Positive
1	B	Hallway next to Classrooms 5 and 6	Extinguisher Holder	Wood	Yellow	None	0	0.01	Negative
1	B	Hallway next to Classrooms 5 and 6	W3	Brick	Yellow	Flaking	100	12.9	Positive
1	B	Hallway next to Classrooms 5 and 6	Ceiling	Concrete	White	Flaking	100	5.6	Positive
1	B	Hallway next to Classrooms 5 and 6	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Pipe Chase by Boy's Bathroom	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Pipe Chase by Boy's Bathroom	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Pipe Chase by Boy's Bathroom	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Pipe Chase by Boy's Bathroom	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Pipe Chase by Boy's Bathroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Pipe Chase by Boy's Bathroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 100	W1	Plaster	Yellow	Flaking	75	45.4	Positive
1	1	Classroom 100	W2	Sheetrock	Brown	None	0	0	Negative
1	1	Classroom 100	W3	Plaster	Yellow	Efflorescence	250	46.7	Positive
1	1	Classroom 100	W4	Plaster	Yellow	Flaking	100	54.3	Positive
1	1	Classroom 100	Ceiling	Plaster	White	Flaking	200	36.1	Positive
1	1	Classroom 100	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 100 Coat Closet	W1	Plaster	White	Flaking	50	41	Positive
1	1	Classroom 100 Coat Closet	W2	Plaster	White	Flaking	10	45.7	Positive
1	1	Classroom 100 Coat Closet	W3	Plaster	White	Flaking	150	42.2	Positive
1	1	Classroom 100 Coat Closet	W4	Plaster	White	Flaking	120	40.7	Positive
1	1	Classroom 100 Coat Closet	Radiator	Metal	Grey	Flaking	2	2.3	Positive
1	1	Classroom 100 Coat Closet	Ceiling	Plaster	White	Flaking	200	31.3	Positive
1	1	Classroom 100 Coat Closet	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Student Restrooms adjacent to Classroom 100	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Student Restrooms adjacent to Classroom 100	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Student Restrooms adjacent to Classroom 100	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Student Restrooms adjacent to Classroom 100	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Student Restrooms adjacent to Classroom 100	Pipe	Metal	White	Flaking	10	16.4	Positive

		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>							
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>							
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Student Restrooms adjacent to Classroom 100	Ceiling	Plaster	White	Flaking	25	13.7	Positive	
1	1	Student Restrooms adjacent to Classroom 100	Floor	Brick	Unpainted	N/A	N/A	N/A	N/A	
1	1	Stairwell next to Classroom 100 leading to Basement	W2	Plaster	Yellow	Flaking	10	25.7	Positive	
1	1	Stairwell next to Classroom 100 leading to Basement	W3	Plaster	Yellow	Flaking	2	22.3	Positive	
1	1	Stairwell next to Classroom 100 leading to Basement	W4	Plaster	Yellow	Flaking	60	24.9	Positive	
1	1	Stairwell next to Classroom 100 leading to Basement	Ceiling	Concrete	White	Flaking	10	23.6	Positive	
1	1	Stairwell next to Classroom 100 leading to Basement	Door	Metal	Brown	None	0	0.09	Negative	
1	1	Stairwell next to Classroom 100 leading to Basement	Door Casing	Metal	Brown	None	0	0.3	Negative	
1	1	Stairwell next to Classroom 100 leading to Basement	Stairs	Concrete	Brown	Friction	15	2.8	Positive	
1	1	Stairwell next to Classroom 100 leading to Basement	Stringer	Concrete	Brown	Cracking	10	10.3	Positive	
1	1	Stairwell next to Classroom 100 leading to Basement	Newel	Concrete	Brown	Friction	5	9.7	Positive	
1	1	Stairwell next to Classroom 100 leading to Basement	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 101	W1	Plaster	Yellow	Flaking	25	26.2	Positive	
1	1	Classroom 101	W2	Plaster	Yellow	None	0	24.1	Positive	
1	1	Classroom 101	W3	Plaster	Yellow	Flaking	110	28.7	Positive	
1	1	Classroom 101	W4	Plaster	Yellow	Flaking	10	22.3	Positive	
1	1	Classroom 101	Ceiling	Plaster	White	Flaking	60	29.8	Positive	
1	1	Classroom 101	Radiator	Metal	Grey	Flaking	6	2.7	Positive	
1	1	Classroom 101	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	1	1st Floor Fire Escape Stairwell across from Classroom 101	W1	Brick	White	Cracking	10	24.1	Positive	
1	1	1st Floor Fire Escape Stairwell across from Classroom 101	W2	Brick	White	Cracking	5	16.7	Positive	
1	1	1st Floor Fire Escape Stairwell across from Classroom 101	W3	Brick	White	Cracking	10	22.1	Positive	
1	1	1st Floor Fire Escape Stairwell across from Classroom 101	W4	Brick	White	Cracking	20	18.6	Positive	
1	1	1st Floor Fire Escape Stairwell across from Classroom 101	Ceiling	Concrete	White	Flaking	50	10.1	Positive	
1	1	<b>1st Floor Fire Escape Stairwell across from Classroom 101</b>	Bars	Metal	Black	Flaking	150	13.4	Positive	
1	1	1st Floor Fire Escape Stairwell across from Classroom 101	Floor	Concrete	Grey	None	0	0	Negative	
1	1	Classroom 102	W1	Sheetrock	White	None	0	0	Negative	
1	1	Classroom 102	W2	Sheetrock	White	None	0	0	Negative	
1	1	Classroom 102	W3	Plaster	White	Flaking	10	32.4	Positive	

		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>							
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>							
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Classroom 102	W4	Plaster	White	Flaking	5	31.6	Positive	
1	1	Classroom 102	Ceiling	Plaster	White	Flaking	100	32.4	Positive	
1	1	Classroom 102	Floor	Brick	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 102 Coat Closet	W1	Plaster	White	Flaking	20	26.4	Positive	
1	1	Classroom 102 Coat Closet	W2	Plaster	White	Flaking	15	20.9	Positive	
1	1	Classroom 102 Coat Closet	W3	Plaster	White	Flaking	45	23.7	Positive	
1	1	Classroom 102 Coat Closet	W4	Plaster	White	Flaking	50	24.9	Positive	
1	1	Classroom 102 Coat Closet	Ceiling	Plaster	White	Flaking	25	26.2	Positive	
1	1	Classroom 102 Coat Closet	Radiator	Metal	Grey	Flaking	4	2.7	Positive	
1	1	Classroom 102 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	1	Advisor's Office next to 103A Lobby	W1	Plaster	White	Flaking	10	21.4	Positive	
1	1	Advisor's Office next to 103A Lobby	W2	Plaster	White	Flaking	6	26.9	Positive	
1	1	Advisor's Office next to 103A Lobby	W3	Sheetrock	White	None	0	0	Negative	
1	1	Advisor's Office next to 103A Lobby	W4	Sheetrock	White	None	0	0	Negative	
1	1	Advisor's Office next to 103A Lobby	Ceiling	Plaster	White	Flaking	5	21.7	Positive	
1	1	Advisor's Office next to 103A Lobby	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	1	Office to Left of Advisor's Office	W1	Plaster	White	Flaking	4	10.6	Positive	
1	1	Office to Left of Advisor's Office	W2	Sheetrock	White	None	0	0	Negative	
1	1	Office to Left of Advisor's Office	W3	Plaster	White	Flaking	15	13.7	Positive	
1	1	Office to Left of Advisor's Office	W4	Plaster	White	Flaking	5	12.3	Positive	
1	1	Office to Left of Advisor's Office	Ceiling	Plaster	White	Flaking	25	26.1	Positive	
1	1	Office to Left of Advisor's Office	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	1	Advisor's Office Restroom	W1	Plaster	White	Flaking	20	34.5	Positive	
1	1	Advisor's Office Restroom	W2	Plaster	White	Flaking	15	36.2	Positive	
1	1	Advisor's Office Restroom	W3	Sheetrock	White	None	0	0	Negative	
1	1	Advisor's Office Restroom	W4	Sheetrock	White	None	0	0	Negative	
1	1	Advisor's Office Restroom	Ceiling	Plaster	White	Flaking	100	35.1	Positive	
1	1	Advisor's Office Restroom	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Restroom in Rear of Advisor Suites	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Restroom in Rear of Advisor Suites	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Restroom in Rear of Advisor Suites	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Restroom in Rear of Advisor Suites	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Restroom in Rear of Advisor Suites	Ceiling	Plaster	White	Flaking	15	1.5	Positive	
1	1	Restroom in Rear of Advisor Suites	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Restroom in School Officer Office	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	

		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>							
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>							
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Restroom in School Officer Office	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Restroom in School Officer Office	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Restroom in School Officer Office	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Restroom in School Officer Office	Ceiling	Plaster	White	Flaking	10	11.8	Positive	
1	1	Restroom in School Officer Office	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	School Officer Office	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	School Officer Office	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	School Officer Office	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	School Officer Office	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	School Officer Office	Ceiling	Plaster	White	Flaking	25	13.1	Positive	
1	1	School Officer Office	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Right service closet adjacent to 103	W1	Plaster	White	Flaking	5	11.7	Positive	
1	1	Right service closet adjacent to 103	W2	Plaster	White	Flaking	10	10.6	Positive	
1	1	Right service closet adjacent to 103	W3	Plaster	White	Flaking	2	11.9	Positive	
1	1	Right service closet adjacent to 103	W4	Plaster	White	Flaking	30	9.6	Positive	
1	1	Right service closet adjacent to 103	Ceiling	Plaster	White	None	0	14.3	Positive	
1	1	Right service closet adjacent to 103	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	1	Left service closet adjacent to 103	W1	Plaster	White	Flaking	2	11.5	Positive	
1	1	Left service closet adjacent to 103	W2	Plaster	White	Flaking	5	15.4	Positive	
1	1	Left service closet adjacent to 103	W3	Plaster	White	Flaking	10	10.2	Positive	
1	1	Left service closet adjacent to 103	W4	Plaster	White	Flaking	5	12.6	Positive	
1	1	Left service closet adjacent to 103	Ceiling	Plaster	White	None	0	15.2	Positive	
1	1	Left service closet adjacent to 103	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	1	Hallway next to Classrooms 100 through 102	W1	Plaster	Yellow	Flaking	200	4.5	Positive	
1	1	Hallway next to Classrooms 100 through 102	W2	Plaster	Yellow	Flaking	100	48.3	Positive	
1	1	Hallway next to Classrooms 100 through 102	W3	Plaster	Yellow	Flaking	100	45.4	Positive	
1	1	Hallway next to Classrooms 100 through 102	W4	Plaster	Yellow	Flaking	20	53	Positive	
1	1	Hallway next to Classrooms 100 through 102	Door	Metal	Brown	Friction	5	1.5	Positive	
1	1	Hallway next to Classrooms 100 through 102	Ceiling	Plaster	White	Flaking	700	37.1	Positive	
1	1	Hallway next to Classrooms 100 through 102	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	1	Stairwell adjacent to Principal's Office	W1	Plaster	Yellow	Flaking	60	42.9	Positive	
1	1	Stairwell adjacent to Principal's Office	W2	Plaster	Yellow	Flaking	30	39.4	Positive	
1	1	Stairwell adjacent to Principal's Office	W3	Plaster	Yellow	Flaking	15	40.1	Positive	
1	1	Stairwell adjacent to Principal's Office	W4	Plaster	Yellow	Flaking	50	39.2	Positive	
1	1	Stairwell adjacent to Principal's Office	Ceiling	Plaster	White	Flaking	110	2.3	Positive	

		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>						
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>						
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Stairwell adjacent to Principal's Office	Radiator	Metal	Grey	Flaking	3	1.2	Positive
1	1	Stairwell adjacent to Principal's Office	Stringer	Concrete	Brown	Friction	50	13.7	Positive
1	1	Stairwell adjacent to Principal's Office	Balluster	Metal	Brown	Friction	60	9.1	Positive
1	1	Stairwell adjacent to Principal's Office	Newel	Metal	Brown	Friction	10	9.6	Positive
1	1	Stairwell adjacent to Principal's Office	Stairs	Concrete	Brown	Friction	20	2.9	Positive
1	1	Stairwell adjacent to Principal's Office	Floor	Concrete	Brown	None	0	0.01	Negative
1	B	Stairwell by Kitchen	W1	Plaster	Yellow	Flaking	50	37.6	Positive
1	B	Stairwell by Kitchen	W2	Plaster	Yellow	Flaking	20	41.4	Positive
1	B	Stairwell by Kitchen	W3	Plaster	Yellow	Flaking	15	43.8	Positive
1	B	Stairwell by Kitchen	W4	Plaster	Yellow	Flaking	30	37.4	Positive
1	B	Stairwell by Kitchen	Ceiling	Plaster	White	Efflorescence	100	3.4	Positive
1	B	Stairwell by Kitchen	Radiator	Metal	Grey	Flaking	3	1.7	Positive
1	B	Stairwell by Kitchen	Stringer	Concrete	Brown	Friction	80	13.6	Positive
1	B	Stairwell by Kitchen	Balluster	Metal	Brown	Friction	70	8.9	Positive
1	B	Stairwell by Kitchen	Newel	Metal	Brown	Friction	10	9.3	Positive
1	B	Stairwell by Kitchen	Stairs	Concrete	Brown	Friction	35	4	Positive
1	B	Stairwell by Kitchen	Gate	Metal	Black	None	0	0.11	Negative
1	B	Stairwell by Kitchen	Door	Metal	Brown	None	0	0.02	Negative
1	B	Stairwell by Kitchen	Door Casing	Metal	Brown	None	0	0	Negative
1	B	Stairwell by Kitchen	Floor	Concrete	Brown	None	0	0	Negative
1	1	Girl's Restroom next to Principal's Office	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Restroom next to Principal's Office	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Restroom next to Principal's Office	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Restroom next to Principal's Office	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Restroom next to Principal's Office	Ceiling	Plaster	White	Flaking	200	23.1	Positive
1	1	Girl's Restroom next to Principal's Office	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Room 103	W1	Plaster	Blue	Flaking	10	50.1	Positive
1	1	Room 103	W2	Plaster	Blue	Flaking	40	34.5	Positive
1	1	Room 103	W3	Plaster	Blue	Flaking	100	36.5	Positive
1	1	Room 103	W4	Sheetrock	Blue	None	0	0	Negative
1	1	Room 103	Chalkboard	Wood	Tan	None	0	0.16	Negative
1	1	Room 103	Door Casing W1	Wood	Tan	None	0	0.12	Negative
1	1	Room 103	Door Casing W2	Wood	Tan	None	0	0.04	Negative

		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>							
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Room 103	Ceiling	Plaster	White	None	0	13.2	Positive	
1	1	Room 103	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Room 103 Coat Closet	W1	Plaster	White	Flaking	50	42.4	Positive	
1	1	Room 103 Coat Closet	W2	Plaster	White	Flaking	10	54.3	Positive	
1	1	Room 103 Coat Closet	W3	Plaster	White	None	0	45.5	Positive	
1	1	Room 103 Coat Closet	W4	Plaster	White	Flaking	30	48.2	Positive	
1	1	Room 103 Coat Closet	Radiator	Metal	Grey	Flaking	5	1.4	Positive	
1	1	Room 103 Coat Closet	Ceiling	Plaster	White	None	0	31.5	Positive	
1	1	Room 103 Coat Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	1	Room 103 Closet to the right of door	W1	Plaster	White	Flaking	5	40.9	Positive	
1	1	Room 103 Closet to the right of door	W2	Plaster	White	Flaking	2	55.9	Positive	
1	1	Room 103 Closet to the right of door	W3	Plaster	White	Flaking	30	50.1	Positive	
1	1	Room 103 Closet to the right of door	W4	Plaster	White	Flaking	2	37.4	Positive	
1	1	Room 103 Closet to the right of door	Radiator	Metal	Grey	Flaking	4	1.9	Positive	
1	1	Room 103 Closet to the right of door	Ceiling	Plaster	White	Flaking	6	32.5	Positive	
1	1	Room 103 Closet to the right of door	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	1	Room 103 Restroom	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Room 103 Restroom	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Room 103 Restroom	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Room 103 Restroom	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Room 103 Restroom	Ceiling	Plaster	White	Flaking	25	25.1	Positive	
1	1	Room 103 Restroom	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Auditorium	W1	Plaster	White	Flaking	300	13.2	Positive	
1	1	Auditorium	Paneling	Wood	White	Flaking	550	34.1	Positive	
1	1	Auditorium	W2	Plaster	White	Flaking	1200	2.6	Positive	
1	1	Auditorium	W3	Plaster	White	Flaking	150	3.2	Positive	
1	1	Auditorium	W4	Plaster	White	Flaking	500	21.4	Positive	
1	1	Auditorium	Door Casing	Wood	White	Friction	20	30.4	Positive	
1	1	Auditorium	Door	Wood	White	Flaking	40	20.6	Positive	
1	1	Auditorium	Vent	Metal	White	Flaking	10	15.8	Positive	
1	1	Auditorium	Baseboard	Wood	Brown	Friction	40	21.4	Positive	
1	1	Auditorium	Ceiling	No Access	White	Flaking	1000	No Access	No Access	
1	1	Auditorium	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	1	Storage in Rear of Stage	W1	Plaster	White	Flaking	20	36.2	Positive	
1	1	Storage in Rear of Stage	W2	Plaster	White	Flaking	10	26.1	Positive	

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	Storage in Rear of Stage	W3	Plaster	White	Flaking	40	31.7	Positive
1	1	Storage in Rear of Stage	W4	Plaster	White	Flaking	10	3.8	Positive
1	1	Storage in Rear of Stage	Door Casing	Metal	White	Friction	5	38.5	Positive
1	1	Storage in Rear of Stage	Door	Wood	White	None	0	0	Negative
1	1	Storage in Rear of Stage	Baseboard	Wood	White	Friction	10	20.3	Positive
1	1	Storage in Rear of Stage	Ceiling	Plaster	White	Flaking	40	23.8	Positive
1	1	Storage in Rear of Stage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stage	W2	Plaster	White	Flaking	300	15.1	Positive
1	1	Stage	W3	Plaster	White	Flaking	100	16.7	Positive
1	1	Stage	W4	Plaster	White	Flaking	200	12.3	Positive
1	1	Stage	Chair-rail W1	Wood	Brown	Friction	50	34.1	Positive
1	1	Stage	Decorative Trim	Plaster	White	Flaking	100	15.5	Positive
1	1	Stage	Baseboard	Wood	Brown	Friction	50	31.3	Positive
1	1	Stage	Chair-rail	Wood	White	Flaking	400	36.2	Positive
1	1	Stage	Ceiling	No Access	No Access	No Access	500	No Access	No Access
1	1	Stage	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet by 103C	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet by 103C	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet by 103C	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet by 103C	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet by 103C	Ceiling	Plaster	White	Flaking	50	13.7	Positive
1	1	Custodial Closet by 103C	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway next to Auditorium	W2	Plaster	Yellow	Flaking	150	42.8	Positive
1	1	Hallway next to Auditorium	W4	Plaster	Yellow	Flaking	180	48.4	Positive
1	1	Hallway next to Auditorium	Radiator	Metal	Grey	Friction	5	1.5	Positive
1	1	Hallway next to Auditorium	Ceiling	Plaster	White	Flaking	250	31.4	Positive
1	1	Hallway next to Auditorium	Floor/Stairs	Concrete	black	cracking	10	3.5	Positive
1	1	Climate Manager Office	W1	Plaster	Yellow	Flaking	5	32.4	Positive
1	1	Climate Manager Office	W2	Plaster	Yellow	Flaking	10	33.5	Positive
1	1	Climate Manager Office	W3	Plaster	Yellow	Flaking	15	34.6	Positive
1	1	Climate Manager Office	W4	Plaster	Yellow	Flaking	2	35.1	Positive
1	1	Climate Manager Office	Ceiling	Plaster	White	Flaking	100	36.2	Positive
1	1	Climate Manager Office	Desk	Wood	Orange	None	0	0.02	Negative
1	1	Climate Manager Office	Radiator	Metal	Grey	Flaking	5	0.9	Positive
1	1	Climate Manager Office	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A



		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>							
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>							
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Climate Manager Coat Closet	W1	Plaster	White	Flaking	20	34.1	Positive	
1	1	Climate Manager Coat Closet	W2	Plaster	White	Flaking	15	33.2	Positive	
1	1	Climate Manager Coat Closet	W3	Plaster	White	Flaking	30	34.5	Positive	
1	1	Climate Manager Coat Closet	W4	Plaster	White	Flaking	20	35.6	Positive	
1	1	Climate Manager Coat Closet	Ceiling	Plaster	Yellow	Flaking	30	34.5	Positive	
1	1	Climate Manager Coat Closet	Radiator	Metal	Grey	Flaking	5	1.4	Positive	
1	1	Climate Manager Coat Closet	Pipe Jacket	Metal	Yellow	Friction	10	4.4	Positive	
1	1	Climate Manager Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	1	Gender Neutral Restroom	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Gender Neutral Restroom	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Gender Neutral Restroom	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Gender Neutral Restroom	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Gender Neutral Restroom	Pipe	Metal	White	Flaking	20	42	Positive	
1	1	Gender Neutral Restroom	Ceiling	Plaster	White	None	0	14.8	Positive	
1	1	Gender Neutral Restroom	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Stairwell next to Building 21 Main Office	W1	Plaster	Yellow	Flaking	30	37.6	Positive	
1	1	Stairwell next to Building 21 Main Office	W2	Plaster	Yellow	Flaking	40	41.2	Positive	
1	1	Stairwell next to Building 21 Main Office	W3	Plaster	Yellow	Flaking	60	39	Positive	
1	1	Stairwell next to Building 21 Main Office	W4	Plaster	Yellow	Flaking	10	40.7	Positive	
1	1	Stairwell next to Building 21 Main Office	Ceiling	Plaster	White	Flaking	60	2.9	Positive	
1	1	Stairwell next to Building 21 Main Office	Radiator	Metal	Grey	Flaking	6	2.3	Positive	
1	1	Stairwell next to Building 21 Main Office	Stringer	Concrete	Brown	Flaking	75	9.3	Positive	
1	1	Stairwell next to Building 21 Main Office	Balluster	Metal	Brown	Friction	50	9.6	Positive	
1	1	Stairwell next to Building 21 Main Office	Newel	Metal	Brown	Friction	10	9.1	Positive	
1	1	Stairwell next to Building 21 Main Office	Stairs	Concrete	Brown	Friction	60	2.7	Positive	
1	1	Stairwell next to Building 21 Main Office	Floor	Concrete	Brown	None	0	0.03	Negative	
1	1	Custodial Closet near Main Office	W1	Plaster	White	None	0	33.7	Positive	
1	1	Custodial Closet near Main Office	W2	Plaster	White	Flaking	10	11.4	Positive	
1	1	Custodial Closet near Main Office	W3	Plaster	White	None	0	16.7	Positive	
1	1	Custodial Closet near Main Office	W4	Plaster	White	None	0	32.4	Positive	
1	1	Custodial Closet near Main Office	Pipe W2	Metal	White	None	0	0.2	Negative	
1	1	Custodial Closet near Main Office	Ceiling	Plaster	White	None	0	10.2	Positive	
1	1	Custodial Closet near Main Office	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 105	W1	Plaster	Yellow	Flaking	25	1.6	Positive	
1	1	Classroom 105	W2	Sheetrock	Yellow	None	0	0	Negative	

		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>							
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>							
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Classroom 105	W3	Plaster	Yellow	Efflorescence	50	4.5	Positive	
1	1	Classroom 105	W4	Plaster	Yellow	Flaking	20	45.4	Positive	
1	1	Classroom 105	Radiator	Metal	Grey	Flaking	5	1.9	Positive	
1	1	Classroom 105	Ceiling	Plaster	White	None	0	31.7	Positive	
1	1	Classroom 105	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 105 Coat Closet	W1	Plaster	Yellow	Flaking	10	1.6	Positive	
1	1	Classroom 105 Coat Closet	W2	Plaster	Yellow	Flaking	25	22.6	Positive	
1	1	Classroom 105 Coat Closet	W3	Plaster	Yellow	Flaking	50	45.8	Positive	
1	1	Classroom 105 Coat Closet	W4	Plaster	Yellow	Flaking	10	55	Positive	
1	1	Classroom 105 Coat Closet	Radiator	Metal	Grey	Flaking	3	2.1	Positive	
1	1	Classroom 105 Coat Closet	Ceiling	Plaster	Yellow	Flaking	3	34.8	Positive	
1	1	Classroom 105 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	1	1st Floor Fire Escape Stairwell across from Classroom 105	W1	Brick	White	Cracking	10	20.4	Positive	
1	1	1st Floor Fire Escape Stairwell across from Classroom 105	W2	Brick	White	Cracking	20	21.9	Positive	
1	1	1st Floor Fire Escape Stairwell across from Classroom 105	W3	Brick	White	Cracking	25	23.2	Positive	
1	1	1st Floor Fire Escape Stairwell across from Classroom 105	W4	Brick	White	Cracking	15	20.1	Positive	
1	1	1st Floor Fire Escape Stairwell across from Classroom 105	Ceiling	Concrete	White	Flaking	35	10.5	Positive	
1	1	1st Floor Fire Escape Stairwell across from Classroom 105	Bars	Metal	Black	Flaking	150	11.1	Positive	
1	1	1st Floor Fire Escape Stairwell across from Classroom 105	Floor	Concrete	Grey	None	0	0	Negative	
1	1	Classroom 106	W1	Plaster	Yellow	Flaking	30	27.3	Positive	
1	1	Classroom 106	W2	Partition Wall	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 106	W3	Plaster	Yellow	Flaking	20	40.1	Positive	
1	1	Classroom 106	W4	Plaster	Yellow	Flaking	10	56.5	Positive	
1	1	Classroom 106	Radiator	Metal	Grey	Flaking	4	1.7	Positive	
1	1	Classroom 106	Ceiling	Plaster	White	Flaking	20	11.7	Positive	
1	1	Classroom 106	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 107	W1	Plaster	Yellow	Flaking	30	51.4	Positive	
1	1	Classroom 107	W2	Plaster	Yellow	Flaking	10	46.1	Positive	
1	1	Classroom 107	W3	Plaster	Yellow	Flaking	100	3	Positive	

		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>							
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>							
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	Classroom 107	W4	Plaster	Yellow	Flaking	10	51.4	Positive	
1	1	Classroom 107	Radiator	Metal	Grey	Flaking	5	2.3	Positive	
1	1	Classroom 107	Pipe	Metal	Yellow	Flaking	5	24.1	Positive	
1	1	Classroom 107	Ceiling	Plaster	White	Flaking	10	31.6	Positive	
1	1	Classroom 107	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 107 Storage	W1	Plaster	White	Flaking	35	22.6	Positive	
1	1	Classroom 107 Storage	W2	Plaster	White	Flaking	20	24.1	Positive	
1	1	Classroom 107 Storage	W3	Plaster	White	Flaking	80	25.9	Positive	
1	1	Classroom 107 Storage	W4	Plaster	White	Flaking	15	28.1	Positive	
1	1	Classroom 107 Storage	Ceiling	Plaster	White	Flaking	25	23.5	Positive	
1	1	Classroom 107 Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	1	Hallway near Classrooms 105 through 107	W1	Plaster	Yellow	Flaking	250	44.2	Positive	
1	1	Hallway near Classrooms 105 through 107	W2	Plaster	Yellow	Flaking	20	54.3	Positive	
1	1	Hallway near Classrooms 105 through 107	W3	Plaster	Yellow	Flaking	500	55.8	Positive	
1	1	Hallway near Classrooms 105 through 107	Radiator	Metal	Grey	Flaking	20	2.1	Positive	
1	1	Hallway near Classrooms 105 through 107	Pipe	Plaster	Yellow	Cracking	5	4.8	Positive	
1	1	Hallway near Classrooms 105 through 107	Door	Metal	Brown	Friction	10	1.9	Positive	
1	1	Hallway near Classrooms 105 through 107	Ceiling	Plaster	White	Flaking	1200	39.4	Positive	
1	1	Hallway near Classrooms 105 through 107	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	1	Stairwell next to Classroom 107	W2	Concrete	White	None	0	0.07	Negative	
1	1	Stairwell next to Classroom 107	W4	Concrete	White	None	0	0.06	Negative	
1	1	Stairwell next to Classroom 107	Ceiling	Concrete	White	None	0	0.01	Negative	
1	1	Stairwell next to Classroom 107	Floor	Concrete	Brown	None	0	0.09	Negative	
1	2	Classroom 201 and 200 (IMC)	W1	Plaster	Purple	Flaking	20	39.1	Positive	
1	2	Classroom 201 and 200 (IMC)	W2	Plaster	Purple	Flaking	10	32.4	Positive	
1	2	Classroom 201 and 200 (IMC)	W3	Plaster	Purple	Flaking	60	33.1	Positive	
1	2	Classroom 201 and 200 (IMC)	W3	Sheetrock	Purple	None	0	0	Negative	
1	2	Classroom 201 and 200 (IMC)	W4	Plaster	Purple	Flaking	20	32.1	Positive	
1	2	Classroom 201 and 200 (IMC)	Ceiling	Plaster	White	Flaking	10	33.4	Positive	
1	2	Classroom 201 and 200 (IMC)	Radiator	Metal	Grey	Flaking	2	2.9	Positive	
1	2	Classroom 201 and 200 (IMC)	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	
1	2	Classroom 201 (IMC) Coat Closet	W1	Plaster	White	Flaking	20	32.4	Positive	
1	2	Classroom 201 (IMC) Coat Closet	W2	Plaster	White	Flaking	10	32.5	Positive	
1	2	Classroom 201 (IMC) Coat Closet	W3	Plaster	White	Flaking	60	33.2	Positive	
1	2	Classroom 201 (IMC) Coat Closet	W4	Plaster	White	Flaking	20	42.1	Positive	

		<b>Dates: 3/16/23-3/31/23</b>	<b>Lead-Safe Certification Assessment Report</b>						
		<b>Inspector Name and Certificate Number: Christopher Karoly 006424</b>	<b>The U School @ Ferguson Elementary School School</b>						
		<b>Inspection Company: Criterion Laboratories</b>	<b>2000 N.7th Street, Philadelphia, PA 19122</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	2	Classroom 201 (IMC) Coat Closet	Ceiling	Plaster	White	Flaking	10	34.2	Positive
1	2	Classroom 201 (IMC) Coat Closet	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 208A	W1	Plaster	White	Flaking	10	32.4	Positive
1	2	Classroom 208A	W2	Plaster	White	Flaking	30	43.5	Positive
1	2	Classroom 208A	W3	Plaster	White	Flaking	5	33.8	Positive
1	2	Classroom 208A	W4	Plaster	White	Flaking	20	32.7	Positive
1	2	Classroom 208A	Ceiling	Plaster	White	Flaking	100	45.7	Positive
1	2	Classroom 208A	Window Casing	Wood	White	Friction	2	18.8	Positive
1	2	Classroom 208A	Door casing	Wood	White	Friction	5	11.7	Positive
1	2	Classroom 208A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom in Office 208A	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom in Office 208A	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom in Office 208A	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom in Office 208A	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom in Office 208A	Ceiling	Plaster	White	Flaking	20	10.2	Positive
1	2	Restroom in Office 208A	Door casing	Wood	White	Flaking	12	11.4	Positive
1	2	Restroom in Office 208A	Window Casing	Wood	White	Flaking	20	18.1	Positive
1	2	Restroom in Office 208A	Pipe Jacket	Metal	Grey	Friction	5	14.5	Positive
1	2	Restroom in Office 208A	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	2nd Floor Fire Escape Stairwell next to Classroom 201 and 200	W1	Brick	White	Cracking	20	20.3	Positive
1	2	2nd Floor Fire Escape Stairwell next to Classroom 201 and 200	W2	Brick	White	Cracking	25	21.5	Positive
1	2	2nd Floor Fire Escape Stairwell next to Classroom 201 and 200	W3	Brick	White	Cracking	10	19.7	Positive
1	2	2nd Floor Fire Escape Stairwell next to Classroom 201 and 200	W4	Brick	White	Cracking	45	23.1	Positive
1	2	2nd Floor Fire Escape Stairwell next to Classroom 201 and 200	Ceiling	Concrete	White	Flaking	75	10.3	Positive
1	2	2nd Floor Fire Escape Stairwell next to Classroom 201 and 200	Bars	Metal	Black	Flaking	150	11.8	Positive
1	2	2nd Floor Fire Escape Stairwell next to Classroom 201 and 200	Floor	Concrete	Grey	None	0	0	Negative
1	2	Main Office Restroom	W1	Plaster	White	Flaking	2	32.4	Positive
1	2	Main Office Restroom	W2	Plaster	White	Flaking	10	31.2	Positive
1	2	Main Office Restroom	W3	Plaster	White	Flaking	5	33.4	Positive

		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>							
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>							
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	2	Main Office Restroom	W4	Plaster	White	Flaking	5	32.5	Positive	
1	2	Main Office Restroom	Ceiling	Plaster	White	Flaking	5	33.2	Positive	
1	2	Main Office Restroom	Floor	Brick	Unpainted	N/A	N/A	N/A	N/A	
1	2	Main Office	W1	Plaster	White	Flaking	15	32.4	Positive	
1	2	Main Office	W2	Plaster	White	Flaking	5	34.5	Positive	
1	2	Main Office	W3	Plaster	White	Flaking	18	32.1	Positive	
1	2	Main Office	W4	Plaster	White	Flaking	20	33.4	Positive	
1	2	Main Office	Ceiling	Plaster	White	Flaking	100	32.5	Positive	
1	2	Main Office	Pipe	Metal	White	Friction	5	14.2	Positive	
1	2	Main Office	Door casing	Wood	Brown	Friction	10	23.3	Positive	
1	2	Main Office	Window Casing	Wood	White	None	0	0.09	Negative	
1	2	Main Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	Main Office Kitchen	W1	Plaster	Yellow	Flaking	5	33.5	Positive	
1	2	Main Office Kitchen	W2	Plaster	Yellow	Flaking	10	32.5	Positive	
1	2	Main Office Kitchen	W3	Plaster	Yellow	Flaking	15	32.6	Positive	
1	2	Main Office Kitchen	W4	Plaster	Yellow	Flaking	5	33.7	Positive	
1	2	Main Office Kitchen	Ceiling	Plaster	White	Flaking	15	31.5	Positive	
1	2	Main Office Kitchen	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	Classroom 202	W1	Plaster	Purple	Flaking	5	33.1	Positive	
1	2	Classroom 202	W2	Sheetrock	Purple	None	0	0	Negative	
1	2	Classroom 202	W3	Plaster	Purple	Flaking	20	34.5	Positive	
1	2	Classroom 202	W4	Plaster	Purple	Flaking	30	33.7	Positive	
1	2	Classroom 202	Ceiling	Plaster	White	Flaking	100	34.6	Positive	
1	2	Classroom 202	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	Stairwell adjacent to Classroom 203	W1	Plaster	Yellow	Flaking	15	40.8	Positive	
1	2	Stairwell adjacent to Classroom 203	W2	Plaster	Yellow	Flaking	60	39.6	Positive	
1	2	Stairwell adjacent to Classroom 203	W3	Plaster	Yellow	Flaking	35	44.1	Positive	
1	2	Stairwell adjacent to Classroom 203	W4	Plaster	Yellow	Flaking	10	43.1	Positive	
1	2	Stairwell adjacent to Classroom 203	Ceiling	Plaster	White	Flaking	75	2.9	Positive	
1	2	Stairwell adjacent to Classroom 203	Radiator	Metal	Grey	Flaking	2	1.1	Positive	
1	2	Stairwell adjacent to Classroom 203	Stringer	Concrete	Brown	Friction	60	15.3	Positive	
1	2	Stairwell adjacent to Classroom 203	Balluster	Metal	Brown	Friction	70	10.7	Positive	
1	2	Stairwell adjacent to Classroom 203	Newel	Metal	Brown	Friction	10	9.2	Positive	
1	2	Stairwell adjacent to Classroom 203	Stairs	Concrete	Brown	Friction	25	4.2	Positive	
1	2	Stairwell adjacent to Classroom 203	Floor	Concrete	Brown	None	0	0.01	Negative	

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Girl's Restroom next to Classroom 203	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom next to Classroom 203	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom next to Classroom 203	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom next to Classroom 203	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom next to Classroom 203	Ceiling	Plaster	White	Flaking	200	34.5	Positive
1	2	Girl's Restroom next to Classroom 203	Pipe	Metal	White	Friction	30	14.4	Positive
1	2	Girl's Restroom next to Classroom 203	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway near Room 200A	W1	Plaster	Yellow	Flaking	120	32.4	Positive
1	2	Hallway near Room 200A	W2	Plaster	Yellow	Flaking	5	32.1	Positive
1	2	Hallway near Room 200A	W3	Plaster	Yellow	Flaking	60	34	Positive
1	2	Hallway near Room 200A	W4	Plaster	Yellow	Flaking	5	35.6	Positive
1	2	Hallway near Room 200A	Ceiling	Plaster	White	Flaking	400	36.9	Positive
1	2	Hallway near Room 200A	Pipe	Metal	Yellow	Friction	10	20.2	Positive
1	2	Hallway near Room 200A	Radiator	Metal	Grey	Flaking	3	1.5	Positive
1	2	Hallway near Room 200A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 203	W1	Plaster	Blue	Flaking	10	33.7	Positive
1	2	Classroom 203	W2	Plaster	Blue	Flaking	20	34.5	Positive
1	2	Classroom 203	W3	Plaster	Blue	Flaking	30	45.3	Positive
1	2	Classroom 203	W4	Plaster	Blue	Flaking	80	33.8	Positive
1	2	Classroom 203	Ceiling	Plaster	White	Flaking	100	37.8	Positive
1	2	Classroom 203	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 203 Coat Closet	W1	Plaster	Blue	Flaking	15	31.4	Positive
1	2	Classroom 203 Coat Closet	W2	Plaster	Blue	Flaking	5	29.3	Positive
1	2	Classroom 203 Coat Closet	W3	Plaster	Blue	Flaking	5	31.9	Positive
1	2	Classroom 203 Coat Closet	W4	Plaster	Blue	Flaking	10	30.1	Positive
1	2	Classroom 203 Coat Closet	Ceiling	Plaster	White	Flaking	25	11.4	Positive
1	2	Classroom 203 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Men's Restroom	W1	Plaster	Yellow	None	0	34.6	Positive
1	2	Men's Restroom	W2	Plaster	Yellow	Flaking	10	33.8	Positive
1	2	Men's Restroom	W3	Plaster	Yellow	Flaking	8	33.6	Positive
1	2	Men's Restroom	W4	Plaster	Yellow	Flaking	5	34.9	Positive
1	2	Men's Restroom	Radiator	Metal	Grey	Flaking	1	1.2	Positive
1	2	Men's Restroom	Ceiling	Plaster	White	Flaking	100	35.9	Positive
1	2	Men's Restroom	Floor	Ceramic	unpainted	N/A	N/A	N/A	N/A
1	2	Storage Closet across from Classroom 203	W1	No Access	No Access	No Access	No Access	No Access	No Access

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Storage Closet across from Classroom 203	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage Closet across from Classroom 203	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage Closet across from Classroom 203	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage Closet across from Classroom 203	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Storage Closet across from Classroom 203	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Hallway between Classroom 204 and 203	W2	Plaster	Yellow	Flaking	30	34.5	Positive
1	2	Hallway between Classroom 204 and 203	W4	Plaster	Yellow	Flaking	150	36.7	Positive
1	2	Hallway between Classroom 204 and 203	Ceiling	Plaster	White	Flaking	300	34.1	Positive
1	2	Hallway between Classroom 204 and 203	Radiator	Metal	Grey	Flaking	3	1.8	Positive
1	2	Hallway between Classroom 204 and 203	Door	Metal	Brown	Friction	5	34.7	Positive
1	2	Hallway between Classroom 204 and 203	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 204A	W1	Plaster	Yellow	Flaking	5	34.5	Positive
1	2	Office 204A	W2	Plaster	Yellow	Flaking	30	35.7	Positive
1	2	Office 204A	W3	Plaster	Yellow	Flaking	20	32.6	Positive
1	2	Office 204A	W4	Plaster	Yellow	Flaking	30	33.5	Positive
1	2	Office 204A	Ceiling	Plaster	White	Flaking	50	33.9	Positive
1	2	Office 204A	Radiator	Metal	Gray	Flaking	2	2.3	Positive
1	2	Office 204A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 204	W1	Plaster	Blue	Flaking	20	34.7	Positive
1	2	Classroom 204	W2	Plaster	Grey	Flaking	50	38.9	Positive
1	2	Classroom 204	W3	Plaster	Grey	Flaking	100	34.5	Positive
1	2	Classroom 204	W4	Plaster	Blue	Flaking	40	32.5	Positive
1	2	Classroom 204	Ceiling	Plaster	White	Flaking	100	32.9	Positive
1	2	Classroom 204	Baseboard	Wood	White	None	0	0.06	Negative
1	2	Classroom 204	Door Casing	Metal	White	None	0	0.04	Negative
1	2	Classroom 204	Chalkboard	Wood	White	None	0	0.07	Negative
1	2	Classroom 204	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Women's Restroom next to Stairwell	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Women's Restroom next to Stairwell	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Women's Restroom next to Stairwell	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Women's Restroom next to Stairwell	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Women's Restroom next to Stairwell	Pipe Jacket	Metal	Gray	No Access	No Access	No Access	No Access
1	2	Women's Restroom next to Stairwell	Ceiling	Plaster	Yellow	Flaking	40	34.6	Positive
1	2	Women's Restroom next to Stairwell	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell next to Classroom 205	W1	Plaster	Yellow	Flaking	15	43.4	Positive

		<b>Dates: 3/16/23-3/31/23</b>	<b>Lead-Safe Certification Assessment Report</b>						
		<b>Inspector Name and Certificate Number: Christopher Karoly 006424</b>	<b>The U School @ Ferguson Elementary School School</b>						
		<b>Inspection Company: Criterion Laboratories</b>	<b>2000 N.7th Street, Philadelphia, PA 19122</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	2	Stairwell next to Classroom 205	W2	Plaster	Yellow	Flaking	40	39.3	Positive
1	2	Stairwell next to Classroom 205	W3	Plaster	Yellow	Flaking	6	41.8	Positive
1	2	Stairwell next to Classroom 205	W4	Plaster	Yellow	Flaking	35	41.6	Positive
1	2	Stairwell next to Classroom 205	Ceiling	Plaster	White	Flaking	60	3.4	Positive
1	2	Stairwell next to Classroom 205	Radiator	Metal	Grey	Flaking	3	1.1	Positive
1	2	Stairwell next to Classroom 205	Stringer	Concrete	Brown	Flaking	35	9.7	Positive
1	2	Stairwell next to Classroom 205	Balluster	Metal	Brown	Friction	60	9.8	Positive
1	2	Stairwell next to Classroom 205	Newel	Metal	Brown	Friction	5	11.5	Positive
1	2	Stairwell next to Classroom 205	Stairs	Concrete	Brown	Friction	30	2.6	Positive
1	2	Stairwell next to Classroom 205	Floor	Concrete	Brown	None	0	0.03	Negative
1	2	Custodial Closet near Classroom 204	W1	Plaster	White	Flaking	5	34.1	Positive
1	2	Custodial Closet near Classroom 204	W2	Plaster	White	Flaking	10	32.6	Positive
1	2	Custodial Closet near Classroom 204	W3	Plaster	White	Flaking	5	35.2	Positive
1	2	Custodial Closet near Classroom 204	W4	Plaster	White	Flaking	5	33.6	Positive
1	2	Custodial Closet near Classroom 204	Ceiling	Plaster	White	Flaking	5	32.1	Positive
1	2	Custodial Closet near Classroom 204	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 205	W1	Plaster	Yellow	Flaking	20	34.5	Positive
1	2	Classroom 205	W2	Plaster	Yellow	Flaking	120	36.7	Positive
1	2	Classroom 205	W3	Plaster	Yellow	Flaking	30	31.2	Positive
1	2	Classroom 205	W4	Plaster	Yellow	Flaking	20	33.7	Positive
1	2	Classroom 205	Ceiling	Plaster	White	Flaking	100	34.9	Positive
1	2	Classroom 205	Radiator	Metal	Grey	Flaking	5	1.3	Positive
1	2	Classroom 205	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 205 Coat Closet	W1	Plaster	White	Flaking	5	33.5	Positive
1	2	Classroom 205 Coat Closet	W2	Plaster	White	Flaking	10	32.5	Positive
1	2	Classroom 205 Coat Closet	W3	Plaster	White	Flaking	30	32.7	Positive
1	2	Classroom 205 Coat Closet	W4	Plaster	White	Flaking	10	32.8	Positive
1	2	Classroom 205 Coat Closet	Ceiling	Plaster	White	Flaking	15	35.7	Positive
1	2	Classroom 205 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 206	W1	Plaster	Yellow	Flaking	60	33.4	Positive
1	2	Classroom 206	W2	Plaster	Yellow	Flaking	30	32.6	Positive
1	2	Classroom 206	W3	Plaster	Yellow	Flaking	100	33.9	Positive
1	2	Classroom 206	W4	Plaster	Yellow	Flaking	5	32.6	Positive
1	2	Classroom 206	Radiator	Concrete	Gray	Flaking	5	1.5	Positive
1	2	Classroom 206	Ceiling	Plaster	White	Flaking	250	34.5	Positive



		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>						
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>						
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	Classroom 206	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 207	W1	Plaster	White	Flaking	15	33.9	Positive
1	2	Classroom 207	W2	Plaster	White	Flaking	90	32.5	Positive
1	2	Classroom 207	W3	Plaster	White	Flaking	20	33.6	Positive
1	2	Classroom 207	W4	Plaster	White	Flaking	15	32.7	Positive
1	2	Classroom 207	Ceiling	Plaster	White	Flaking	200	34.6	Positive
1	2	Classroom 207	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 207 Storage	W1	Plaster	White	Flaking	5	34.8	Positive
1	2	Classroom 207 Storage	W2	Plaster	White	Flaking	20	36.7	Positive
1	2	Classroom 207 Storage	W3	Plaster	White	Flaking	15	33.8	Positive
1	2	Classroom 207 Storage	W4	Plaster	White	Flaking	20	32.5	Positive
1	2	Classroom 207 Storage	Ceiling	Plaster	White	Flaking	50	33.7	Positive
1	2	Classroom 207 Storage	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell next to Classroom 207	W2	Concrete	Yellow	None	0	0.01	Negative
1	2	Stairwell next to Classroom 207	W4	Concrete	Yellow	None	0	0.02	Negative
1	2	Stairwell next to Classroom 207	Ceiling	Concrete	White	None	0	0.05	Negative
1	2	Stairwell next to Classroom 207	Floor	Concrete	Brown	None	0	0.03	Negative
1	2	Hallway next to Classrooms 207 and 205	W1	Concrete	Yellow	None	0	0.12	Negative
1	2	Hallway next to Classrooms 207 and 205	W2	Concrete	Yellow	None	0	0.08	Negative
1	2	Hallway next to Classrooms 207 and 205	W3	Concrete	Yellow	None	0	0.09	Negative
1	2	Hallway next to Classrooms 207 and 205	W4	Concrete	Yellow	None	0	0.07	Negative
1	2	Hallway next to Classrooms 207 and 205	Pipe	Metal	Yellow	Friction	3	14.2	Positive
1	2	Hallway next to Classrooms 207 and 205	Door	Metal	Red	None	0	0.06	Negative
1	2	Hallway next to Classrooms 207 and 205	Ceiling	Concrete	White	None	0	0.1	Negative
1	2	Hallway next to Classrooms 207 and 205	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Fire Escape Stairwell next to Classroom 207	W1	Brick	White	Cracking	15	24.1	Positive
1	2	Fire Escape Stairwell next to Classroom 207	W2	Brick	White	Cracking	10	21.5	Positive
1	2	Fire Escape Stairwell next to Classroom 207	W3	Brick	White	Cracking	35	22.7	Positive
1	2	Fire Escape Stairwell next to Classroom 207	W4	Brick	White	Cracking	15	19.4	Positive
1	2	Fire Escape Stairwell next to Classroom 207	Ceiling	Concrete	White	Flaking	60	10.2	Positive
1	2	Fire Escape Stairwell next to Classroom 207	Bars	Metal	Black	Flaking	150	11.6	Positive
1	2	Fire Escape Stairwell next to Classroom 207	Floor	Concrete	Grey	None	0	0	Negative
1	3	Classroom 300	W1	Plaster	Yellow	Flaking	40	44.6	Positive
1	3	Classroom 300	W2	Plaster	Yellow	Flaking	5	45.8	Positive
1	3	Classroom 300	W3	Plaster	Yellow	Efflorescence	120	43	Positive

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 300	W4	Plaster	Yellow	Flaking	15	54.6	Positive
1	3	Classroom 300	Ceiling	Plaster	Yellow	Flaking	100	28.5	Positive
1	3	Classroom 300	Radiator	Metal	Grey	Flaking	3	1.5	Positive
1	3	Classroom 300	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 300 Coat Closet	W1	Plaster	Yellow	Flaking	40	44.2	Positive
1	3	Classroom 300 Coat Closet	W2	Plaster	Yellow	Flaking	20	31.6	Positive
1	3	Classroom 300 Coat Closet	W3	Plaster	Yellow	Efflorescence	200	2.7	Positive
1	3	Classroom 300 Coat Closet	W4	Plaster	Yellow	Flaking	20	37.8	Positive
1	3	Classroom 300 Coat Closet	Ceiling	Plaster	Yellow	Flaking	25	29.6	Positive
1	3	Classroom 300 Coat Closet	Radiator	Metal	Grey	Flaking	2	1.4	Positive
1	3	Classroom 300 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Restrooms, Staff - Male	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	Restrooms, Staff - Male	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	Restrooms, Staff - Male	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	Restrooms, Staff - Male	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	Restrooms, Staff - Male	Ceiling	Plaster	White	Flaking	30	27.2	Positive
1	3	Restrooms, Staff - Male	Floor	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 301	W1	Plaster	Yellow	Flaking	50	38.7	Positive
1	3	Classroom 301	W2	Plaster	Yellow	Flaking	10	41.4	Positive
1	3	Classroom 301	W3	Plaster	Yellow	Flaking	100	36	Positive
1	3	Classroom 301	W4	Plaster	Yellow	Flaking	3	37.9	Positive
1	3	Classroom 301	Ceiling	Plaster	White	Flaking	300	30.1	Positive
1	3	Classroom 301	Radiator	Metal	Grey	Flaking	5	1.1	Positive
1	3	Classroom 301	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 302	W1	Plaster	Yellow	Flaking	40	39.3	Positive
1	3	Classroom 302	W2	Plaster	Yellow	Flaking	30	35.7	Positive
1	3	Classroom 302	W3	Plaster	Yellow	Efflorescence	120	45.1	Positive
1	3	Classroom 302	W4	Plaster	Yellow	Flaking	5	41.9	Positive
1	3	Classroom 302	Ceiling	Plaster	Yellow	Flaking	150	28.8	Positive
1	3	Classroom 302	Radiator	Metal	Grey	Flaking	3	1	Positive
1	3	Classroom 302	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classrooms 301 and 302 Coat Closet	W1	Plaster	Yellow	Flaking	15	32.6	Positive
1	3	Classrooms 301 and 302 Coat Closet	W2	Plaster	Yellow	Flaking	30	31.4	Positive
1	3	Classrooms 301 and 302 Coat Closet	W3	Plaster	Yellow	Flaking	5	38.7	Positive
1	3	Classrooms 301 and 302 Coat Closet	W4	Plaster	Yellow	Flaking	25	46.2	Positive

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classrooms 301 and 302 Coat Closet	Ceiling	Plaster	Yellow	Flaking	60	30.2	Positive
1	3	Classrooms 301 and 302 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	3rd Floor Fire Escape Stairwell across from Room 301	W1	Brick	White	Cracking	5	22.4	Positive
1	3	3rd Floor Fire Escape Stairwell across from Room 301	W2	Brick	White	Cracking	4	20.6	Positive
1	3	3rd Floor Fire Escape Stairwell across from Room 301	W3	Brick	White	Cracking	2	24.8	Positive
1	3	3rd Floor Fire Escape Stairwell across from Room 301	W4	Brick	White	Cracking	6	21.7	Positive
1	3	3rd Floor Fire Escape Stairwell across from Room 301	Ceiling	Concrete	White	Flaking	50	11.5	Positive
1	3	3rd Floor Fire Escape Stairwell across from Room 301	Bars	Metal	Black	Flaking	100	10.5	Positive
1	3	3rd Floor Fire Escape Stairwell across from Room 301	Floor	Concrete	Grey	None	0	0	Negative
1	3	3rd Floor Fire Escape Stairwell across from Room 301	Pipe	Metal	Grey	Cracking	8	0.8	Positive
1	3	3rd Floor Custodial Closet beside Classrooms 301 and 302 - Stair to Roof and Main Attic	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	3	3rd Floor Custodial Closet beside Classrooms 301 and 302 - Stair to Roof and Main Attic	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	3	3rd Floor Custodial Closet beside Classrooms 301 and 302 - Stair to Roof and Main Attic	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	3	3rd Floor Custodial Closet beside Classrooms 301 and 302 - Stair to Roof and Main Attic	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	3	3rd Floor Custodial Closet beside Classrooms 301 and 302 - Stair to Roof and Main Attic	stairs	Concrete	White	Friction	20	1.7	Positive
1	3	3rd Floor Custodial Closet beside Classrooms 301 and 302 - Stair to Roof and Main Attic	pipe	Metal	White	Cracking	5	37.2	Positive
1	3	3rd Floor Custodial Closet beside Classrooms 301 and 302 - Stair to Roof and Main Attic	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	3rd Floor Custodial Closet beside Classrooms 301 and 302 - Stair to Roof and Main Attic	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairwell next to U School Main Office	W1	Plaster	Yellow	Flaking	20	41.9	Positive
1	3	Stairwell next to U School Main Office	W2	Plaster	Yellow	Flaking	110	42.5	Positive
1	3	Stairwell next to U School Main Office	W3	Plaster	Yellow	Flaking	40	37.8	Positive
1	3	Stairwell next to U School Main Office	W4	Plaster	Yellow	Flaking	160	37.4	Positive
1	3	Stairwell next to U School Main Office	Ceiling	Plaster	White	Flaking	100	2.1	Positive
1	3	Stairwell next to U School Main Office	Radiator	Metal	Grey	Flaking	4	1.8	Positive
1	3	Stairwell next to U School Main Office	Stringer	Concrete	Brown	Friction	50	14.8	Positive
1	3	Stairwell next to U School Main Office	Balluster	Metal	Brown	Friction	80	9.3	Positive
1	3	Stairwell next to U School Main Office	Newel	Metal	Brown	Friction	10	10.5	Positive
1	3	Stairwell next to U School Main Office	Stairs	Concrete	Brown	Friction	15	4.8	Positive

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Stairwell next to U School Main Office	Floor	Concrete	Brown	None	0	0.02	Negative
1	3	Girl's Restroom next to U School Main Office	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom next to U School Main Office	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom next to U School Main Office	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom next to U School Main Office	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom next to U School Main Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom next to U School Main Office	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 303	W1	Plaster	Yellow	Flaking	25	41.8	Positive
1	3	Classroom 303	W2	Plaster	Yellow	Flaking	2	39.7	Positive
1	3	Classroom 303	W3	Plaster	Yellow	Flaking	40	38.4	Positive
1	3	Classroom 303	W4	Plaster	Yellow	Flaking	20	45.6	Positive
1	3	Classroom 303	Ceiling	Plaster	White	Flaking	100	27.4	Positive
1	3	Classroom 303	Radiator	Metal	Grey	Flaking	4	2.1	Positive
1	3	Classroom 303	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 303 Coat Closet	W1	Plaster	Yellow	Flaking	20	39	Positive
1	3	Classroom 303 Coat Closet	W2	Plaster	Yellow	Flaking	25	44.2	Positive
1	3	Classroom 303 Coat Closet	W3	Plaster	Yellow	Flaking	100	38.3	Positive
1	3	Classroom 303 Coat Closet	W4	Plaster	Yellow	Flaking	50	42.5	Positive
1	3	Classroom 303 Coat Closet	Ceiling	Plaster	White	Flaking	150	26.7	Positive
1	3	Classroom 303 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway at Classrooms 300 to 303	W1	Plaster	Yellow	Flaking	270	52.5	Positive
1	3	Hallway at Classrooms 300 to 303	W3	Plaster	Yellow	Flaking	180	48.7	Positive
1	3	Hallway at Classrooms 300 to 303	W4	Plaster	Yellow	Flaking	50	49.8	Positive
1	3	Hallway at Classrooms 300 to 303	Ceiling	Plaster	White	Flaking	450	39.4	Positive
1	3	Hallway at Classrooms 300 to 303	Radiator	Metal	Grey	Flaking	4	1.5	Positive
1	3	Hallway at Classrooms 300 to 303	Door W1	Metal	Brown	None	0	0.01	Negative
1	3	Hallway at Classrooms 300 to 303	Door W3	Metal	Brown	Friction	10	1.7	Positive
1	3	Hallway at Classrooms 300 to 303	Pipe	Metal	Yellow	Cracking	5	42.1	Positive
1	3	Hallway at Classrooms 300 to 303	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 318	W1	Plaster	Yellow	Flaking	50	47.8	Positive
1	3	Classroom 318	W2	Plaster	Yellow	Flaking	30	43.2	Positive
1	3	Classroom 318	W3	Plaster	Yellow	Flaking	80	39.1	Positive
1	3	Classroom 318	W4	Plaster	Yellow	Flaking	35	40.5	Positive
1	3	Classroom 318	Ceiling	Plaster	Yellow	Flaking	100	27.9	Positive
1	3	Classroom 318	Pipe	Metal	Yellow	Flaking	20	58.4	Positive

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 318	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 318 Closet	W1	Plaster	Yellow	Flaking	20	33.9	Positive
1	3	Classroom 318 Closet	W2	Plaster	Yellow	Flaking	2	35.6	Positive
1	3	Classroom 318 Closet	W3	Plaster	Yellow	Flaking	5	32	Positive
1	3	Classroom 318 Closet	W4	Plaster	Yellow	Flaking	20	30.1	Positive
1	3	Classroom 318 Closet	Ceiling	Plaster	Yellow	Flaking	10	28.2	Positive
1	3	Classroom 318 Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 317	W1	Plaster	Yellow	Flaking	50	37.8	Positive
1	3	Classroom 317	W2	Plaster	Yellow	Flaking	35	32.1	Positive
1	3	Classroom 317	W3	Plaster	Yellow	Efflorescence	125	29.7	Positive
1	3	Classroom 317	W4	Plaster	Yellow	Flaking	40	36.4	Positive
1	3	Classroom 317	Ceiling	Plaster	White	Flaking	100	29.8	Positive
1	3	Classroom 317	Radiator	Metal	Grey	Flaking	5	2.5	Positive
1	3	Classroom 317	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 317 Coat Closet	W1	Plaster	Yellow	Flaking	35	37.2	Positive
1	3	Classroom 317 Coat Closet	W2	Plaster	Yellow	Flaking	30	39.9	Positive
1	3	Classroom 317 Coat Closet	W3	Plaster	Yellow	Flaking	30	42.1	Positive
1	3	Classroom 317 Coat Closet	W4	Plaster	Yellow	Flaking	25	36.5	Positive
1	3	Classroom 317 Coat Closet	Ceiling	Plaster	Yellow	Flaking	25	28.4	Positive
1	3	Classroom 317 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 319	W1	Plaster	Yellow	Flaking	50	48.7	Positive
1	3	Classroom 319	W2	Plaster	Yellow	Flaking	30	43.2	Positive
1	3	Classroom 319	W3	Plaster	Yellow	Efflorescence	110	40.9	Positive
1	3	Classroom 319	W4	Plaster	Yellow	Flaking	30	47.4	Positive
1	3	Classroom 319	Ceiling	Plaster	White	Flaking	250	34.2	Positive
1	3	Classroom 319	Radiator	Metal	Grey	Flaking	2	4.1	Positive
1	3	Classroom 319	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 319 Coat Closet	W1	Plaster	Yellow	Flaking	5	38.7	Positive
1	3	Classroom 319 Coat Closet	W2	Plaster	Yellow	Flaking	10	33.5	Positive
1	3	Classroom 319 Coat Closet	W3	Plaster	Yellow	Flaking	2	35.9	Positive
1	3	Classroom 319 Coat Closet	W4	Plaster	Yellow	None	0	29.8	Positive
1	3	Classroom 319 Coat Closet	Ceiling	Plaster	Yellow	Flaking	20	26.3	Positive
1	3	Classroom 319 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 320	W1	Plaster	Yellow	Flaking	30	42.5	Positive
1	3	Classroom 320	W2	Plaster	Black	Flaking	100	39.8	Positive

		<b>Dates: 3/16/23-3/31/23</b>	<b>Lead-Safe Certification Assessment Report</b>						
		<b>Inspector Name and Certificate Number: Christopher Karoly 006424</b>	<b>The U School @ Ferguson Elementary School School</b>						
		<b>Inspection Company: Criterion Laboratories</b>	<b>2000 N.7th Street, Philadelphia, PA 19122</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative)</b>
1	3	Classroom 320	W3	Plaster	Yellow	Efflorescence	120	44.9	Positive
1	3	Classroom 320	W4	Plaster	Blue	Flaking	40	37.7	Positive
1	3	Classroom 320	Ceiling	Plaster	White	Flaking	200	32.1	Positive
1	3	Classroom 320	Radiator	Metal	Grey	Flaking	5	1.1	Positive
1	3	Classroom 320	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 320 Coat Closet	W1	Plaster	Yellow	Flaking	5	46.1	Positive
1	3	Classroom 320 Coat Closet	W2	Plaster	Yellow	Flaking	20	42.8	Positive
1	3	Classroom 320 Coat Closet	W3	Plaster	Yellow	Efflorescence	10	39.9	Positive
1	3	Classroom 320 Coat Closet k	W4	Plaster	Yellow	Flaking	25	44	Positive
1	3	Classroom 320 Coat Closet	Ceiling	Plaster	White	Flaking	80	32.4	Positive
1	3	Classroom 320 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 316	W1	Plaster	Yellow	Flaking	35	45.2	Positive
1	3	Classroom 316	W2	Plaster	Yellow	Flaking	50	40.6	Positive
1	3	Classroom 316	W3	Plaster	Yellow	Flaking	100	37.9	Positive
1	3	Classroom 316	W4	Plaster	Yellow	Flaking	35	41.4	Positive
1	3	Classroom 316	Ceiling	Plaster	Yellow	Flaking	75	24.7	Positive
1	3	Classroom 316	Radiator	Metal	Grey	Flaking	5	1.5	Positive
1	3	Classroom 316	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 316 Coat Closet	W1	Plaster	Yellow	Flaking	100	39.4	Positive
1	3	Classroom 316 Coat Closet	W2	Plaster	Yellow	Flaking	15	36	Positive
1	3	Classroom 316 Coat Closet	W3	Plaster	Yellow	Flaking	80	34.2	Positive
1	3	Classroom 316 Coat Closet	W4	Plaster	Yellow	Flaking	40	35.7	Positive
1	3	Classroom 316 Coat Closet	Ceiling	Plaster	Yellow	Flaking	50	27.8	Positive
1	3	Classroom 316 Coat Closet	Radiator	Metal	Grey	Flaking	2	1.2	Positive
1	3	Classroom 316 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway next to Classroom 319	W2	Plaster	Yellow	Flaking	120	56.4	Positive
1	3	Hallway next to Classroom 319	W4	Plaster	Yellow	Flaking	160	52.7	Positive
1	3	Hallway next to Classroom 319	Ceiling	Plaster	White	Flaking	375	48.6	Positive
1	3	Hallway next to Classroom 319	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 304	W1	Plaster	Yellow	Flaking	55	37.2	Positive
1	3	Classroom 304	W2	Plaster	Yellow	Flaking	80	42.9	Positive
1	3	Classroom 304	W3	Plaster	Yellow	Efflorescence	150	44.1	Positive
1	3	Classroom 304	W4	Plaster	Yellow	Flaking	20	46.4	Positive
1	3	Classroom 304	Ceiling	Plaster	White	Flaking	200	32.1	Positive
1	3	Classroom 304	Radiator	Metal	Grey	Flaking	3	0.9	Positive

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 304	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 304 Coat Closet	W1	Plaster	Yellow	Flaking	40	41.2	Positive
1	3	Classroom 304 Coat Closet	W2	Plaster	Yellow	Flaking	80	37.4	Positive
1	3	Classroom 304 Coat Closet	W3	Plaster	Yellow	Efflorescence	125	39.5	Positive
1	3	Classroom 304 Coat Closet	W4	Plaster	Yellow	Flaking	40	38.1	Positive
1	3	Classroom 304 Coat Closet	Ceiling	Plaster	White	Flaking	25	30.7	Positive
1	3	Classroom 304 Coat Closet	Radiator	Metal	Grey	Flaking	5	2.1	Positive
1	3	Classroom 304 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	3rd Floor Fire Escape Stairwell across from Room 304	W1	Brick	White	Cracking	15	13.5	Positive
1	3	3rd Floor Fire Escape Stairwell across from Room 304	W2	Brick	White	Cracking	30	18.3	Positive
1	3	3rd Floor Fire Escape Stairwell across from Room 304	W3	Brick	White	Cracking	10	19.1	Positive
1	3	3rd Floor Fire Escape Stairwell across from Room 304	W4	Brick	White	Cracking	40	13.8	Positive
1	3	3rd Floor Fire Escape Stairwell across from Room 304	Ceiling	Concrete	White	Flaking	35	10.7	Positive
1	3	3rd Floor Fire Escape Stairwell across from Room 304	Bars	Metal	Black	Flaking	150	11.9	Positive
1	3	3rd Floor Fire Escape Stairwell across from Room 304	Floor	Concrete	Grey	None	0	0	Negative
1	3	Boy's Restroom adjacent to Classroom 320	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom adjacent to Classroom 320	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom adjacent to Classroom 320	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom adjacent to Classroom 320	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom adjacent to Classroom 320	Ceiling	Plaster	White	Flaking	30	34.7	Positive
1	3	Boy's Restroom adjacent to Classroom 320	pipe	Metal	White	Flaking	25	52.8	Positive
1	3	Boy's Restroom adjacent to Classroom 320	Hatch	Metal	White	None	0	0	Negative
1	3	Boy's Restroom adjacent to Classroom 320	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairwell next to Classroom 305 and 306	W1	Plaster	Yellow	Flaking	15	41.8	Positive
1	3	Stairwell next to Classroom 305 and 306	W2	Plaster	Yellow	Flaking	85	43.7	Positive
1	3	Stairwell next to Classroom 305 and 306	W3	Plaster	Yellow	Flaking	60	41.4	Positive
1	3	Stairwell next to Classroom 305 and 306	W4	Plaster	Yellow	Flaking	75	37.9	Positive
1	3	Stairwell next to Classroom 305 and 306	Ceiling	Plaster	White	Flaking	200	3.4	Positive
1	3	Stairwell next to Classroom 305 and 306	Radiator	Metal	Grey	Flaking	3	1.2	Positive
1	3	Stairwell next to Classroom 305 and 306	Stringer	Concrete	Brown	Friction	50	9.9	Positive
1	3	Stairwell next to Classroom 305 and 306	Balluster	Metal	Brown	Friction	70	10.7	Positive
1	3	Stairwell next to Classroom 305 and 306	Newel	Metal	Brown	Friction	10	9.1	Positive
1	3	Stairwell next to Classroom 305 and 306	Stair	Concrete	Brown	Friction	25	2.5	Positive
1	3	Stairwell next to Classroom 305 and 306	Floor	Concrete	Brown	None	0	0.01	Negative
1	3	Electrical Panel Room near Classroom 304	W1	Plaster	Yellow	None	0	40.7	Positive

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Electrical Panel Room near Classroom 304	W2	Plaster	Yellow	None	0	38.6	Positive
1	3	Electrical Panel Room near Classroom 304	W3	Plaster	Yellow	Flaking	10	37.9	Positive
1	3	Electrical Panel Room near Classroom 304	W4	Plaster	Yellow	Flaking	25	43.8	Positive
1	3	Electrical Panel Room near Classroom 304	Ceiling	Plaster	White	None	0	34.1	Positive
1	3	Electrical Panel Room near Classroom 304	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 305	W1	Plaster	Yellow	Flaking	15	42	Positive
1	3	Classroom 305	W2	Plaster	Yellow	Partially Inaccessible	150	37.9	Positive
1	3	Classroom 305	W3	Plaster	Yellow	Flaking	110	36.4	Positive
1	3	Classroom 305	W4	Plaster	Yellow	Partially Inaccessible	250	39.5	Positive
1	3	Classroom 305	Ceiling	Plaster	Yellow	Flaking	100	27.6	Positive
1	3	Classroom 305	Radiator	Metal	Grey	Flaking	4	1.1	Positive
1	3	Classroom 305	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 305 Coat Closet	W1	Plaster	Yellow	Flaking	60	39.7	Positive
1	3	Classroom 305 Coat Closet	W2	Plaster	Yellow	Flaking	80	36.3	Positive
1	3	Classroom 305 Coat Closet	W3	Plaster	Yellow	Flaking	60	41	Positive
1	3	Classroom 305 Coat Closet	W4	Plaster	Yellow	Flaking	10	38.4	Positive
1	3	Classroom 305 Coat Closet	Ceiling	Plaster	Yellow	Flaking	20	30.2	Positive
1	3	Classroom 305 Coat Closet	Radiator	Metal	Grey	Flaking	4	1.9	Positive
1	3	Classroom 305 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 306	W1	Plaster	Yellow	Flaking	30	39.4	Positive
1	3	Classroom 306	W2	Plaster	Yellow	None	0	39.7	Positive
1	3	Classroom 306	W3	Plaster	Yellow	Flaking	150	36.2	Positive
1	3	Classroom 306	W4	Plaster	Yellow	Flaking	5	42	Positive
1	3	Classroom 306	Ceiling	Plaster	White	Flaking	110	26.5	Positive
1	3	Classroom 306	Radiator	Metal	Grey	Flaking	5	1.5	Positive
1	3	Classroom 306	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 307	W1	Plaster	Yellow	Flaking	35	36.8	Positive
1	3	Classroom 307	W2	Plaster	Yellow	Flaking	25	32.5	Positive
1	3	Classroom 307	W3	Plaster	Yellow	Flaking	50	40.2	Positive
1	3	Classroom 307	W4	Plaster	Yellow	Flaking	4	35.4	Positive
1	3	Classroom 307	Ceiling	Plaster	White	Flaking	25	29.6	Positive
1	3	Classroom 307	Radiator	Metal	Grey	Flaking	2	4.2	Positive
1	3	Classroom 307	Pipe	Metal	Yellow	Flaking	10	24.7	Positive
1	3	Classroom 307	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 307 Coat Closet	W1	Plaster	Yellow	Flaking	30	37.6	Positive



		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	Classroom 307 Coat Closet	W2	Plaster	Yellow	Flaking	15	36.8	Positive
1	3	Classroom 307 Coat Closet	W3	Plaster	Yellow	Efflorescence	120	40.9	Positive
1	3	Classroom 307 Coat Closet	W4	Plaster	Yellow	Flaking	80	36.3	Positive
1	3	Classroom 307 Coat Closet	Ceiling	Plaster	Yellow	Flaking	60	32.4	Positive
1	3	Classroom 307 Coat Closet	Pipe	Metal	Yellow	Flaking	2	22.6	Positive
1	3	Classroom 307 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	3rd Floor Fire Escape Stair near Classroom 307	W1	Brick	White	Cracking	20	21.4	Positive
1	3	3rd Floor Fire Escape Stair near Classroom 307	W2	Brick	White	Cracking	35	25.1	Positive
1	3	3rd Floor Fire Escape Stair near Classroom 307	W3	Brick	White	Cracking	50	19.7	Positive
1	3	3rd Floor Fire Escape Stair near Classroom 307	W4	Brick	White	Cracking	10	15.6	Positive
1	3	3rd Floor Fire Escape Stair near Classroom 307	Ceiling	Concrete	White	Flaking	45	12.6	Positive
1	3	3rd Floor Fire Escape Stair near Classroom 307	Bars	Metal	Black	Flaking	150	9.1	Positive
1	3	3rd Floor Fire Escape Stair near Classroom 307	Floor	Concrete	Grey	None	0	0	Negative
1	3	Hallway next to Classrooms 305 to 307	W1	Plaster	Yellow	Flaking	200	39.7	Positive
1	3	Hallway next to Classrooms 305 to 307	W3	Plaster	Yellow	Flaking	600	37.6	Positive
1	3	Hallway next to Classrooms 305 to 307	Ceiling	Plaster	White	Flaking	500	29.4	Positive
1	3	Hallway next to Classrooms 305 to 307	Radiator	Metal	Grey	Flaking	3	1.4	Positive
1	3	Hallway next to Classrooms 305 to 307	Pipe	Metal	Yellow	Flaking	10	20.2	Positive
1	3	Hallway next to Classrooms 305 to 307	Door	Metal	Brown	Friction	10	1.5	Positive
1	3	Hallway next to Classrooms 305 to 307	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	B	Stairwell to left of Building Engineer Office	W1	Concrete	Yellow	None	0	0	Negative
2	B	Stairwell to left of Building Engineer Office	W2	Concrete	Yellow	None	0	0	Negative
2	B	Stairwell to left of Building Engineer Office	W3	Concrete	Yellow	None	0	0	Negative
2	B	Stairwell to left of Building Engineer Office	W4	Concrete	Yellow	None	0	0	Negative
2	B	Stairwell to left of Building Engineer Office	Door	Metal	White	None	0	0	Negative
2	B	Stairwell to left of Building Engineer Office	Door Casing	Metal	White	None	0	0.18	Negative
2	B	Stairwell to left of Building Engineer Office	Univent	Metal	White	None	0	0.06	Negative
2	B	Stairwell to left of Building Engineer Office	Ceiling	Concrete	White	None	0	0.05	Negative
2	B	Stairwell to left of Building Engineer Office	Floor	Concrete	Brown	None	0	0	Negative
2	B	Stairwell to Right of Classroom 10	W1	Concrete	Blue	None	0	0.01	Negative
2	B	Stairwell to Right of Classroom 10	W2	Concrete	Pink	None	0	0.03	Negative
2	B	Stairwell to Right of Classroom 10	W3	Concrete	Pink	None	0	0.04	Negative
2	B	Stairwell to Right of Classroom 10	W4	Concrete	Pink	None	0	0.03	Negative
2	B	Stairwell to Right of Classroom 10	Door Casing W1	Metal	Brown	None	0	0	Negative

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	B	Stairwell to Right of Classroom 10	Door	Metal	Brown	None	0	0.01	Negative
2	B	Stairwell to Right of Classroom 10	Univent	Metal	Blue	None	0	0.1	Negative
2	B	Stairwell to Right of Classroom 10	W4	Concrete	Pink	None	0	0.03	Negative
2	B	Stairwell to Right of Classroom 10	Ceiling	Concrete	White	None	0	0	Negative
2	B	Stairwell to Right of Classroom 10	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	B	Girl's Restroom to left of Building Engineer's Office	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Girl's Restroom to left of Building Engineer's Office	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Girl's Restroom to left of Building Engineer's Office	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Girl's Restroom to left of Building Engineer's Office	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Girl's Restroom to left of Building Engineer's Office	Door Casing	Metal	Tan	None	0	0.06	Negative
2	B	Girl's Restroom to left of Building Engineer's Office	Door	Wood	Red	None	0	0.01	Negative
2	B	Girl's Restroom to left of Building Engineer's Office	Ceiling	Concrete	White	None	0	0.04	Negative
2	B	Girl's Restroom to left of Building Engineer's Office	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	B	Staff Restroom near Classroom 10	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Staff Restroom near Classroom 10	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Staff Restroom near Classroom 10	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Staff Restroom near Classroom 10	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Staff Restroom near Classroom 10	Ceiling	Concrete	White	None	0	0	Negative
2	B	Staff Restroom near Classroom 10	Floor	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Service closet at corner of S03 and H01	W1	Concrete	White	None	0	0.16	Negative
2	B	Service closet at corner of S03 and H01	W2	Concrete	White	None	0	0	Negative
2	B	Service closet at corner of S03 and H01	W3	Concrete	White	None	0	0.01	Negative
2	B	Service closet at corner of S03 and H01	W4	Concrete	White	None	0	0.01	Negative
2	B	Service closet at corner of S03 and H01	Ceiling	Concrete	White	None	0	0	Negative
2	B	Service closet at corner of S03 and H01	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	B	Service closet at corner of S03 and H01	Duct	Metal	White	None	0	0.03	Negative
2	B	Service closet at corner of S03 and H01	Pipe W1	Metal	White	None	0	0.13	Negative
2	B	Service closet at corner of S03 and H01	Door W1	Metal	Red	None	0	0.24	Negative
2	B	Custodial Closet next to Staff Restroom	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	B	Custodial Closet next to Staff Restroom	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	B	Custodial Closet next to Staff Restroom	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	B	Custodial Closet next to Staff Restroom	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	B	Custodial Closet next to Staff Restroom	Riser Door	Metal	White	None	0	0	Negative
2	B	Custodial Closet next to Staff Restroom	Ceiling	Concrete	White	None	0	0.13	Negative
2	B	Custodial Closet next to Staff Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	B	Custodial closet next to S04	W1	Concrete	White	None	0	0	Negative
2	B	Custodial closet next to S04	W2	Concrete	White	None	0	0	Negative
2	B	Custodial closet next to S04	W3	Concrete	White	None	0	0	Negative
2	B	Custodial closet next to S04	W4	Concrete	White	None	0	0	Negative
2	B	Custodial closet next to S04	Ceiling	Concrete	White	None	0	0.03	Negative
2	B	Custodial closet next to S04	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	B	Custodial closet next to S04	Pipe	Metal	White	None	0	0	Negative
2	B	Custodial closet next to S04	door casing W1	Metal	Brown	None	0	0.12	Negative
2	B	Custodial closet next to S04	door	Wood	Brown	None	0	0.09	Negative
2	B	Principial's Office	W1	Concrete	White	None	0	0	Negative
2	B	Principial's Office	W2	Concrete	White	None	0	0	Negative
2	B	Principial's Office	W3	Concrete	White	None	0	0	Negative
2	B	Principial's Office	W4	Concrete	White	None	0	0	Negative
2	B	Principial's Office	Ceiling	Concrete	White	None	0	0.09	Negative
2	B	Principial's Office	Radiator	Metal	Tan	None	0	0.01	Negative
2	B	Principial's Office	Door Casing W1	Metal	Yellow	None	0	0.13	Negative
2	B	Principial's Office	Door Casing W2	Metal	Yellow	None	0	0.02	Negative
2	B	Principial's Office	Vent	Metal	White	None	0	0	Negative
2	B	Principial's Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	B	Principal's Restroom	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Principal's Restroom	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Principal's Restroom	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Principal's Restroom	Pipe W3	Metal	White	None	0	0	Negative
2	B	Principal's Restroom	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Principal's Restroom	Ceiling	Concrete	White	None	0	0	Negative
2	B	Principal's Restroom	Floor	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Principal's Office Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	B	Principal's Office Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	B	Principal's Office Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	B	Principal's Office Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	B	Principal's Office Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	B	Principal's Office Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	B	Classroom 10	W1	Concrete	White	None	0	0	Negative

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	B	Classroom 10	W2	Concrete	White	None	0	0	Negative
2	B	Classroom 10	W3	Concrete	White	None	0	0	Negative
2	B	Classroom 10	W4	Concrete	White	None	0	0	Negative
2	B	Classroom 10	Ceiling	Concrete	White	None	0	0	Negative
2	B	Classroom 10	Pole W1	Metal	White	Friction	3	1.6	Positive
2	B	Classroom 10	Door Casing	Metal	Yellow	None	0	0	Negative
2	B	Classroom 10	Univent	Metal	Yellow	None	0	0	Negative
2	B	Classroom 10	Univent Cover	Metal	Tan	None	0	0	Negative
2	B	Classroom 10	Louver	Metal	Black	None	0	0.06	Negative
2	B	Classroom 10	Door	Wood	Yellow	None	0	0	Negative
2	B	Classroom 10	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
2	B	Former Building 21 Main Office	W1	Concrete	Yellow	None	0	0.04	Negative
2	B	Former Building 21 Main Office	W2	Concrete	Yellow	None	0	0	Negative
2	B	Former Building 21 Main Office	W3	Concrete	Black	None	0	0	Negative
2	B	Former Building 21 Main Office	Window Frame	Metal	Yellow	None	0	0.11	Negative
2	B	Former Building 21 Main Office	W4	Concrete	Black	None	0	0	Negative
2	B	Former Building 21 Main Office	Ceiling	Spline Ceiling Tile	Unpainted	N/A	N/A	N/A	N/A
2	B	Former Building 21 Main Office	Door Casing	Metal	Yellow	None	0	0.24	Negative
2	B	Former Building 21 Main Office	Univent	Metal	Pink	None	0	0	Negative
2	B	Former Building 21 Main Office	Desk	Metal	Black	None	0	0.01	Negative
2	B	Former Building 21 Main Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
2	B	Classroom 11	W1	Concrete	White	None	0	0	Negative
2	B	Classroom 11	W2	Concrete	White	None	0	0	Negative
2	B	Classroom 11	W3	Concrete	White	None	0	0	Negative
2	B	Classroom 11	W4	Concrete	White	None	0	0	Negative
2	B	Classroom 11	Ceiling	Concrete	White	None	0	0.16	Negative
2	B	Classroom 11	Pole W1	Metal	White	Friction	10	1.2	Positive
2	B	Classroom 11	Window Louver	Metal	White	None	0	0.11	Negative
2	B	Classroom 11	Univent vents	Metal	Pink	None	0	0	Negative
2	B	Classroom 11	Univent	Metal	Pink	None	0	0	Negative
2	B	Classroom 11	Locker	Metal	Brown	None	0	0.02	Negative
2	B	Classroom 11	Door Casing	Metal	Yellow	None	0	0.24	Negative
2	B	Classroom 11	Door	Wood	Yellow	None	0	0	Negative
2	B	Classroom 11	Floor	N/A	unpainted	N/A	N/A	N/A	N/A

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	B	Counselor's Office 1	W1	Concrete	Yellow	None	0	0	Negative
2	B	Counselor's Office 1	W2	Concrete	Yellow	None	0	0	Negative
2	B	Counselor's Office 1	W3	Concrete	Yellow	None	0	0	Negative
2	B	Counselor's Office 1	W4	Concrete	Yellow	None	0	0	Negative
2	B	Counselor's Office 1	Ceiling	Spline Ceiling Tile	Unpainted	N/A	N/A	N/A	N/A
2	B	Counselor's Office 1	Floor	N/A	unpainted	N/A	N/A	N/A	N/A
2	B	Counselor's Office 2	W1	Concrete	Yellow	None	0	0	Negative
2	B	Counselor's Office 2	W2	Concrete	Yellow	None	0	0	Negative
2	B	Counselor's Office 2	W3	Concrete	Yellow	None	0	0	Negative
2	B	Counselor's Office 2	W4	Concrete	Yellow	None	0	0	Negative
2	B	Counselor's Office 2	Ceiling	Spline Ceiling	Unpainted	N/A	N/A	N/A	N/A
2	B	Counselor's Office 2	Floor	N/A	unpainted	N/A	N/A	N/A	N/A
2	B	Counselor's Office 3	W1	Concrete	Yellow	None	0	0	Negative
2	B	Counselor's Office 3	W2	Concrete	Yellow	None	0	0	Negative
2	B	Counselor's Office 3	W3	Concrete	Yellow	None	0	0	Negative
2	B	Counselor's Office 3	W4	Concrete	Yellow	None	0	0	Negative
2	B	Counselor's Office 3	Window Casing	Metal	Yellow	None	0	0.1	Negative
2	B	Counselor's Office 3	Ceiling	Spline Ceiling	Unpainted	N/A	N/A	N/A	N/A
2	B	Counselor's Office 3	Floor	N/A	unpainted	N/A	N/A	N/A	N/A
2	B	Classroom 12	W1	Concrete	Yellow	None	0	0	Negative
2	B	Classroom 12	W1	Sheetrock	Yellow	None	0	0	Negative
2	B	Classroom 12	W1	Concrete	Yellow	None	0	0	Negative
2	B	Classroom 12	W2	Concrete	Yellow	None	0	0	Negative
2	B	Classroom 12	W3	Concrete	Yellow	None	0	0	Negative
2	B	Classroom 12	W4	Concrete	Yellow	None	0	0	Negative
2	B	Classroom 12	W4	Sheetrock	Yellow	None	0	0	Negative
2	B	Classroom 12	Pole W1	Metal	White/yellow	Friction	5	1.5	Positive
2	B	Classroom 12	Univent vent	Metal	Pink	None	0	0	Negative
2	B	Classroom 12	Univent	Metal	Yellow	None	0	0	Negative
2	B	Classroom 12	Door Casing	Metal	Yellow	None	0	0.23	Negative
2	B	Classroom 12	Door	Wood	Yellow	None	0	0	Negative
2	B	Classroom 12	Locker	Metal	Brown	None	0	0.01	Negative
2	B	Classroom 12	Ceiling	Concrete	White	None	0	0	Negative
2	B	Classroom 12	Floor	N/A	unpainted	N/A	N/A	N/A	N/A
2	B	Nurse Office Room 13	W1	Concrete	Yellow	None	0	0	Negative

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	B	Nurse Office Room 13	W2	Concrete	Yellow	None	0	0	Negative
2	B	Nurse Office Room 13	W3	Concrete	Yellow	None	0	0	Negative
2	B	Nurse Office Room 13	W4	Concrete	Yellow	None	0	0	Negative
2	B	Nurse Office Room 13	Ceiling	Concrete	White	None	0	0	Negative
2	B	Nurse Office Room 13	Floor	N/A	unpainted	N/A	N/A	N/A	N/A
2	B	Nurse's Restroom	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Nurse's Restroom	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Nurse's Restroom	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Nurse's Restroom	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Nurse's Restroom	Ceiling	Concrete	White	None	0	0	Negative
2	B	Nurse's Restroom	Floor	Brick	Unpainted	N/A	N/A	N/A	N/A
2	B	Nurse's Office Storage	W1	Sheetrock	White	None	0	0	Negative
2	B	Nurse's Office Storage	W2	Sheetrock	White	None	0	0	Negative
2	B	Nurse's Office Storage	W3	Concrete	White	None	0	0	Negative
2	B	Nurse's Office Storage	W4	Concrete	White	None	0	0	Negative
2	B	Nurse's Office Storage	Ceiling	Concrete	White	None	0	0	Negative
2	B	Nurse's Office Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	B	Hallway next to Classrooms 10 and 12	W1	Brick	Yellow	None	0	0.03	Negative
2	B	Hallway next to Classrooms 10 and 12	W2	Brick	Yellow	None	0	0.03	Negative
2	B	Hallway next to Classrooms 10 and 12	W3	Brick	Yellow	None	0	0.04	Negative
2	B	Hallway next to Classrooms 10 and 12	W4	Brick	Yellow	None	0	0.03	Negative
2	B	Hallway next to Classrooms 10 and 12	Door Casing	Metal	Brown	None	0	0.01	Negative
2	B	Hallway next to Classrooms 10 and 12	Door	Metal	Brown	None	0	0.02	Negative
2	B	Hallway next to Classrooms 10 and 12	Riser Door	Metal	Yellow	Cracking	<1	2.1	Positive
2	B	Hallway next to Classrooms 10 and 12	Ceiling	Concrete	White	None	0	0	Negative
2	B	Hallway next to Classrooms 10 and 12	Intercom Box	Metal	White	None	0	0.07	Negative
2	B	Hallway next to Classrooms 10 and 12	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	B	Stairs next to Room 13	W1	Concrete	Yellow	None	0	0.04	Negative
2	B	Stairs next to Room 13	W2	Concrete	Yellow	None	0	0.02	Negative
2	B	Stairs next to Room 13	W3	Concrete	Yellow	None	0	0	Negative
2	B	Stairs next to Room 13	W4	Concrete	Yellow	None	0	0	Negative
2	B	Stairs next to Room 13	Ceiling	Concrete	White	None	0	0.01	Negative
2	B	Stairs next to Room 13	Door W1	Metal	Brown	None	0	0.04	Negative
2	B	Stairs next to Room 13	Door Casing W1	Metal	Brown	None	0	0.28	Negative

		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>						
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>						
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	B	Stairs next to Room 13	Door W3	Metal	Brown	None	0	0	Negative
2	B	Stairs next to Room 13	Door Casing W3	Metal	Brown	None	0	0	Negative
2	B	Stairs next to Room 13	Univent	Metal	Brown	None	0	0.1	Negative
2	B	Stairs next to Room 13	Floor	Concrete	Brown	None	0	0	Negative
2	1	Boy's Restroom next to Classroom 110	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Boy's Restroom next to Classroom 110	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Boy's Restroom next to Classroom 110	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Boy's Restroom next to Classroom 110	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Boy's Restroom next to Classroom 110	Ceiling	Concrete	White	None	0	0	Negative
2	1	Boy's Restroom next to Classroom 110	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Custodial Closet next to Classroom 110	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Custodial Closet next to Classroom 110	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Custodial Closet next to Classroom 110	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Custodial Closet next to Classroom 110	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Custodial Closet next to Classroom 110	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Custodial Closet next to Classroom 110	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	1	IT Room	W1	Concrete	White	None	0	0	Negative
2	1	IT Room	W2	Concrete	White	None	0	0	Negative
2	1	IT Room	W3	Concrete	White	None	0	0	Negative
2	1	IT Room	W4	Concrete	White	None	0	0	Negative
2	1	IT Room	Pipe	Metal	White	Flaking	2	0.7	Positive
2	1	IT Room	Door Casing	Metal	White	none	0	0.02	Negative
2	1	IT Room	Ceiling	Concrete	White	None	0	0	Negative
2	1	IT Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Staff Restroom next to Classroom 110	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Staff Restroom next to Classroom 110	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Staff Restroom next to Classroom 110	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Staff Restroom next to Classroom 110	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Staff Restroom next to Classroom 110	Ceiling	Concrete	White	None	0	0	Negative
2	1	Staff Restroom next to Classroom 110	Floor	Brick	Unpainted	N/A	N/A	N/A	N/A
2	1	Hallway at Staff Restroom	W1	Concrete	White	None	0	0	Negative
2	1	Hallway at Staff Restroom	W2	Concrete	White	None	0	0	Negative
2	1	Hallway at Staff Restroom	W3	Concrete	White	None	0	0	Negative
2	1	Hallway at Staff Restroom	W4	Concrete	White	None	0	0	Negative

		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>						
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>						
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	1	Hallway at Staff Restroom	Ceiling	Concrete	White	None	0	0	Negative
2	1	Hallway at Staff Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Control Room in Hallway at Staff Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Control Room in Hallway at Staff Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Control Room in Hallway at Staff Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Control Room in Hallway at Staff Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Control Room in Hallway at Staff Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Control Room in Hallway at Staff Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	1	Girl's Restroom next to Classroom 115	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Girl's Restroom next to Classroom 115	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Girl's Restroom next to Classroom 115	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Girl's Restroom next to Classroom 115	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Girl's Restroom next to Classroom 115	Pipe	Metal	White	None	0	0.13	Negative
2	1	Girl's Restroom next to Classroom 115	Ceiling	Concrete	White	None	0	0	Negative
2	1	Girl's Restroom next to Classroom 115	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Classroom 115	W1	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 115	W2	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 115	W3	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 115	W4	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 115	Pole	Metal	Green	Friction	5	0.8	Positive
2	1	Classroom 115	Univent	Metal	Blue	None	0	0	Negative
2	1	Classroom 115	locker	Metal	Green	None	0	0	Negative
2	1	Classroom 115	pipe jacket	Metal	Yellow	None	0	0	Negative
2	1	Classroom 115	Ceiling	Concrete	White	None	0	0	Negative
2	1	Classroom 115	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Classroom 115 Storage	W1	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 115 Storage	W2	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 115 Storage	W3	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 115 Storage	W4	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 115 Storage	Ceiling	Concrete	White	None	0	0	Negative
2	1	Classroom 115 Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Classroom 110	W1	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 110	W2	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 110	W3	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 110	W4	Concrete	Yellow	None	0	0	Negative



		<b>Dates: 3/16/23-3/31/23</b>	<b>Lead-Safe Certification Assessment Report</b>						
		<b>Inspector Name and Certificate Number: Christopher Karoly 006424</b>	<b>The U School @ Ferguson Elementary School School</b>						
		<b>Inspection Company: Criterion Laboratories</b>	<b>2000 N.7th Street, Philadelphia, PA 19122</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/ negative)</b>
2	1	Classroom 110	Ceiling	Concrete	White	None	0	0	Negative
2	1	Classroom 110	Pole	Metal	Yellow	Friction	3	1.2	Positive
2	1	Classroom 110	Pipe jacket	Metal	Yellow	None	0	0	Negative
2	1	Classroom 110	Door Casing	Metal	Tan	None	0	0	Negative
2	1	Classroom 110	Door	Wood	Tan	None	0	0	Negative
2	1	Classroom 110	Window Casing	Metal	Yellow	None	0	0	Negative
2	1	Classroom 110	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Classroom 111	W1	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 111	W2	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 111	W3	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 111	W4	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 111	pole	Metal	Yellow	Friction	<1	1.9	Positive
2	1	Classroom 111	univent	Metal	Tan	None	0	0	Negative
2	1	Classroom 111	door casing	Metal	Tan	None	0	0	Negative
2	1	Classroom 111	door	Wood	Tan	None	0	0	Negative
2	1	Classroom 111	Jacket	Metal	Yellow	None	0	0	Negative
2	1	Classroom 111	Transite Panel W1	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 111	Ceiling	Concrete	White	None	0	0	Negative
2	1	Classroom 111	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Classroom 114/113	W1	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 114/113	W2	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 114/113	W3	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 114/113	W4	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 114/113	Ceiling	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 114/113	Ceiling	Concrete	White	None	0	0	Negative
2	1	Classroom 114/113	pole	Metal	Yellow	Friction	5	1	positive
2	1	Classroom 114/113	Door Casing	Metal	Tan	None	0	0.4	Negative
2	1	Classroom 114/113	Door	Wood	Tan	None	0	0	Negative
2	1	Classroom 114/113	Locker	Metal	Grey	None	0	0.01	Negative
2	1	Classroom 114/113	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Classroom 112	W1	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 112	W2	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 112	W3	Concrete	Yellow	None	0	0	Negative
2	1	Classroom 112	W4	Concrete	Yellow	None	0	0	Negative

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	1	Classroom 112	Door Casing	Metal	White	None	0	0.04	Negative
2	1	Classroom 112	Pipe	Metal	Yellow	None	0	0.02	Negative
2	1	Classroom 112	Univent	Metal	Tan	None	0	0	Negative
2	1	Classroom 112	Pole	Metal	Yellow	Friction	8	1.6	Positive
2	1	Classroom 112	Ceiling	Concrete	White	None	0	0	Negative
2	1	Classroom 112	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Hallway next to Classrooms 110 through 115	W1	Concrete	Black	None	0	0	Negative
2	1	Hallway next to Classrooms 110 through 115	W2	Concrete	Black	None	0	0	Negative
2	1	Hallway next to Classrooms 110 through 115	W3	Concrete	Black	None	0	0	Negative
2	1	Hallway next to Classrooms 110 through 115	W4	Concrete	Black	None	0	0	Negative
2	1	Hallway next to Classrooms 110 through 115	Ceiling	Concrete	White	None	0	0	Negative
2	1	Hallway next to Classrooms 110 through 115	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
2	1	Stairwell next to Classroom 113	W1	Concrete	Yellow	None	0	0	Negative
2	1	Stairwell next to Classroom 113	W2	Concrete	Yellow	None	0	0	Negative
2	1	Stairwell next to Classroom 113	W3	Concrete	Yellow	None	0	0.01	Negative
2	1	Stairwell next to Classroom 113	W4	Concrete	Yellow	None	0	0	Negative
2	1	Stairwell next to Classroom 113	Ceiling	Concrete	White	None	0	0.01	Negative
2	1	Stairwell next to Classroom 113	Door	Metal	Brown	None	0	0.27	Negative
2	1	Stairwell next to Classroom 113	Door Casing	Metal	Brown	None	0	0.3	Negative
2	1	Stairwell next to Classroom 113	Floor	Concrete	Brown	None	0	0	Negative
2	2	Staff Women's Lounge next to Classroom 210	W1	Concrete	Yellow	None	0	0	Negative
2	2	Staff Women's Lounge next to Classroom 210	W2	Concrete	Yellow	None	0	0	Negative
2	2	Staff Women's Lounge next to Classroom 210	W3	Concrete	Yellow	None	0	0	Negative
2	2	Staff Women's Lounge next to Classroom 210	W4	Concrete	Yellow	None	0	0	Negative
2	2	Staff Women's Lounge next to Classroom 210	Ceiling	Concrete	White	None	0	0	Negative
2	2	Staff Women's Lounge next to Classroom 210	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
2	2	Restroom in Staff Women's Lounge	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Restroom in Staff Women's Lounge	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Restroom in Staff Women's Lounge	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Restroom in Staff Women's Lounge	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Restroom in Staff Women's Lounge	Ceiling	Concrete	White	None	0	0	Negative
2	2	Restroom in Staff Women's Lounge	Floor	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Storage Room in Hallway at Staff Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage Room in Hallway at Staff Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage Room in Hallway at Staff Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	2	Storage Room in Hallway at Staff Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage Room in Hallway at Staff Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Storage Room in Hallway at Staff Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	2	Boy's Restroom next to Classroom 210	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Boy's Restroom next to Classroom 210	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Boy's Restroom next to Classroom 210	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Boy's Restroom next to Classroom 210	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Boy's Restroom next to Classroom 210	Ceiling	Concrete	White	None	0	0	Negative
2	2	Boy's Restroom next to Classroom 210	Floor	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Pipe Chase in Boy's Restroom	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	2	Pipe Chase in Boy's Restroom	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	2	Pipe Chase in Boy's Restroom	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	2	Pipe Chase in Boy's Restroom	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	2	Pipe Chase in Boy's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	2	Pipe Chase in Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	2	Custodial Closet next to Classroom 210	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Custodial Closet next to Classroom 210	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Custodial Closet next to Classroom 210	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Custodial Closet next to Classroom 210	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Custodial Closet next to Classroom 210	Ceiling	Concrete	White	None	0	0	Negative
2	2	Custodial Closet next to Classroom 210	Floor	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Classroom 215 Storage Closet	W1	Concrete	Yellow	None	0	0.12	Negative
2	2	Classroom 215 Storage Closet	W2	Concrete	Yellow	None	0	0.14	Negative
2	2	Classroom 215 Storage Closet	W3	Concrete	Yellow	None	0	0.15	Negative
2	2	Classroom 215 Storage Closet	W4	Concrete	Yellow	None	0	0.19	Negative
2	2	Classroom 215 Storage Closet	Ceiling	Concrete	White	None	0	0.46	Negative
2	2	Classroom 215 Storage Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	2	Girl's Restroom next to Classroom 215	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Girl's Restroom next to Classroom 215	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Girl's Restroom next to Classroom 215	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Girl's Restroom next to Classroom 215	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Girl's Restroom next to Classroom 215	Ceiling	Concrete	White	None	0	0	Negative
2	2	Girl's Restroom next to Classroom 215	Floor	Brick	Unpainted	N/A	N/A	N/A	N/A
2	2	Stairwell next to Classroom 215	W1	Concrete	White	None	0	0	Negative
2	2	Stairwell next to Classroom 215	W2	Concrete	White	None	0	0	Negative

		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>						
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>						
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	2	Stairwell next to Classroom 215	W3	Concrete	White	None	0	0	Negative
2	2	Stairwell next to Classroom 215	W4	Concrete	White	None	0	0	Negative
2	2	Stairwell next to Classroom 215	Ceiling	Concrete	White	None	0	0	Negative
2	2	Stairwell next to Classroom 215	Floor	Concrete	Brown	None	0	0	Negative
2	2	Stairwell next to Classroom 215	Door	Metal	Brown	None	0	0.04	Negative
2	2	Stairwell next to Classroom 215	Door Casing	Metal	Brown	None	0	0.09	Negative
2	2	Classroom 215	W1	Concrete	Blue	None	0	0.12	Negative
2	2	Classroom 215	W2	Concrete	Blue	None	0	0.32	Negative
2	2	Classroom 215	W3	Concrete	Blue	None	0	0.41	Negative
2	2	Classroom 215	W4	Concrete	Blue	None	0	0.56	Negative
2	2	Classroom 215	Ceiling	Concrete	White	Flaking	100	0.34	Negative
2	2	Classroom 215	Univent	Metal	Blue	None	0	0.15	Negative
2	2	Classroom 215	Pole	Metal	Blue	Friction	4	2.3	Positive
2	2	Classroom 215	Door casing	Metal	Tan	None	0	0.3	Negative
2	2	Classroom 215	Door	Wood	Tan	None	0	0.45	Negative
2	2	Classroom 215	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
2	2	Classroom 210	W1	Concrete	Yellow	None	0	0.12	Negative
2	2	Classroom 210	W2	Concrete	Yellow	None	0	0.14	Negative
2	2	Classroom 210	W3	Concrete	Yellow	None	0	0.34	Negative
2	2	Classroom 210	W4	Concrete	Yellow	None	0	0.49	Negative
2	2	Classroom 210	Ceiling	Concrete	White	Flaking	100	0.17	Negative
2	2	Classroom 210	Pole	Metal	Yellow	Friction	5	1.9	Positive
2	2	Classroom 210	Univent	Metal	Brown	None	0	0.13	Negative
2	2	Classroom 210	Door casing	Metal	Brown	None	0	0.5	Negative
2	2	Classroom 210	Door	Wood	Brown	None	0	0.19	Negative
2	2	Classroom 210	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
2	2	Classroom 211	W1	Concrete	Blue	None	0	0.45	Negative
2	2	Classroom 211	W2	Concrete	Blue	None	0	0.12	Negative
2	2	Classroom 211	W3	Concrete	Blue	None	0	0.42	Negative
2	2	Classroom 211	W4	Concrete	Blue	None	0	0.17	Negative
2	2	Classroom 211	Ceiling	Concrete	White	Flaking	150	0.17	Negative
2	2	Classroom 211	Pole	Metal	Blue	Friction	4	1.9	Positive
2	2	Classroom 211	Univent	Metal	Orange	None	0	0.19	Negative
2	2	Classroom 211	Door	Wood	Tan	None	0	0.2	Negative
2	2	Classroom 211	Door casing	Metal	Tan	None	0	0.12	Negative

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	2	Classroom 211	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
2	2	Classrooms 213 and 214	W1	Concrete	Yellow	None	0	0.15	Negative
2	2	Classrooms 213 and 214	W2	Concrete	Yellow	None	0	0.43	Negative
2	2	Classrooms 213 and 214	W3	Concrete	Yellow	None	0	0.19	Negative
2	2	Classrooms 213 and 214	W4	Concrete	Yellow	None	0	0.4	Negative
2	2	Classrooms 213 and 214	Ceiling	Concrete	White	Flaking	100	0.34	Negative
2	2	Classrooms 213 and 214	Univent	Metal	Green	None	0	0.19	Negative
2	2	Classrooms 213 and 214	Pole	Metal	Green	Friction	2	2.5	Positive
2	2	Classrooms 213 and 214	Door casing	Metal	Tan	None	0	0.1	Negative
2	2	Classrooms 213 and 214	Door	Wood	Tan	None	0	0.5	Negative
2	2	Classrooms 213 and 214	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
2	2	Classroom 212	W1	Concrete	Yellow	None	0	0.12	Negative
2	2	Classroom 212	W2	Concrete	Yellow	None	0	0.19	Negative
2	2	Classroom 212	W3	Concrete	Yellow	None	0	0.18	Negative
2	2	Classroom 212	W4	Concrete	Yellow	None	0	0.09	Negative
2	2	Classroom 212	Ceiling	Concrete	White	Flaking	100	0.43	Negative
2	2	Classroom 212	Pole	Metal	Yellow	Friction	5	1.9	Positive
2	2	Classroom 212	Univent	Metal	Purple	None	0	0.18	Negative
2	2	Classroom 212	Door casing	Metal	Tan	None	0	0.12	Negative
2	2	Classroom 212	Door	Wood	Tan	None	0	0.14	Negative
2	2	Classroom 212	Floor	N/A	unpainted	N/A	N/A	N/A	N/A
2	2	Hallway next to Classrooms 213 and 215	W2	Concrete	White	None	0	0.6	Negative
2	2	Hallway next to Classrooms 213 and 215	W3	Concrete	White	None	0	0.6	Negative
2	2	Hallway next to Classrooms 213 and 215	W4	Concrete	White	None	0	0.6	Negative
2	2	Hallway next to Classrooms 213 and 215	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	2	Hallway next to Classrooms 213 and 215	Door Casing	Metal	Red	N/A	N/A	0.2	Negative
2	2	Hallway next to Classrooms 213 and 215	Door	Wood	Brown	N/A	N/A	0.04	Negative
2	2	Hallway next to Classrooms 213 and 215	Door Casing	Metal	Brown	N/A	N/A	0.07	Negative
2	2	Hallway next to Classrooms 213 and 215	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	2	Stairwell next to Classroom 213	W1	Concrete	Yellow	None	0	0.01	Negative
2	2	Stairwell next to Classroom 213	W2	Concrete	Yellow	None	0	0.02	Negative
2	2	Stairwell next to Classroom 213	W3	Concrete	Yellow	None	0	0	Negative
2	2	Stairwell next to Classroom 213	W4	Concrete	Yellow	None	0	0.01	Negative
2	2	Stairwell next to Classroom 213	Ceiling	Concrete	White	None	0	0.02	Negative
2	2	Stairwell next to Classroom 213	Door	Metal	Red	None	0	0.3	Negative

		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	2	Stairwell next to Classroom 213	Door Casing	Metal	Red	None	0	0.24	Negative
2	2	Stairwell next to Classroom 213	Floor	Concrete	Brown	None	0	0	Negative
2	3	Boy's Restroom near Classroom 310	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
2	3	Boy's Restroom near Classroom 310	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
2	3	Boy's Restroom near Classroom 310	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
2	3	Boy's Restroom near Classroom 310	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
2	3	Boy's Restroom near Classroom 310	Ceiling	Concrete	White	Flaking	50	0.15	Negative
2	3	Boy's Restroom near Classroom 310	Floor	Ceramic Tile	unpainted	N/A	N/A	N/A	N/A
2	3	Custodial Closet next to Boys Restroom	W1	Ceramic Tile	unpainted	N/A	N/A	N/A	N/A
2	3	Custodial Closet next to Boys Restroom	W2	Ceramic Tile	unpainted	N/A	N/A	N/A	N/A
2	3	Custodial Closet next to Boys Restroom	W3	Ceramic Tile	unpainted	N/A	N/A	N/A	N/A
2	3	Custodial Closet next to Boys Restroom	W4	Ceramic Tile	unpainted	N/A	N/A	N/A	N/A
2	3	Custodial Closet next to Boys Restroom	Ceiling	Concrete	White	Flaking	50	0.13	Negative
2	3	Custodial Closet next to Boys Restroom	Floor	Ceramic Tile	unpainted	N/A	N/A	N/A	N/A
2	3	Staff Lounge next to Classroom 310	W1	Concrete	Yellow	None	0	0.08	Negative
2	3	Staff Lounge next to Classroom 310	W2	Concrete	Yellow	None	0	0.19	Negative
2	3	Staff Lounge next to Classroom 310	W3	Concrete	Yellow	None	0	0.21	Negative
2	3	Staff Lounge next to Classroom 310	W4	Concrete	Yellow	None	0	0.23	Negative
2	3	Staff Lounge next to Classroom 310	Ceiling	Concrete	White	Flaking	100	0.4	Negative
2	3	Staff Lounge next to Classroom 310	Floor	N/A	unpainted	N/A	N/A	N/A	N/A
2	3	Girl's Restroom across from 310	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
2	3	Girl's Restroom across from 310	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
2	3	Girl's Restroom across from 310	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
2	3	Girl's Restroom across from 310	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
2	3	Girl's Restroom across from 310	Ceiling	Concrete	White	Flaking	50	0.09	Negative
2	3	Girl's Restroom across from 310	Floor	Ceramic Brick	Unpainted	N/A	N/A	N/A	N/A
2	3	Pipe Chase in Girl's Restroom	W1	Concrete	White	None	0	0.08	Negative
2	3	Pipe Chase in Girl's Restroom	W2	Concrete	White	None	0	0.08	Negative
2	3	Pipe Chase in Girl's Restroom	W3	Concrete	White	None	0	0.12	Negative
2	3	Pipe Chase in Girl's Restroom	W4	Concrete	White	None	0	0.14	Negative
2	3	Pipe Chase in Girl's Restroom	Ceiling	Concrete	White	None	0	0.43	Negative
2	3	Pipe Chase in Girl's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	3	Classroom 315	W1	Concrete	Blue	None	0	0.12	Negative
2	3	Classroom 315	W2	Concrete	Blue	None	0	0.09	Negative
2	3	Classroom 315	W3	Concrete	Blue	None	0	0.06	Negative

		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>						
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>						
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	3	Classroom 315	W4	Concrete	Blue	None	0	0.09	Negative
2	3	Classroom 315	Univent	Metal	Tan	None	0	0.12	Negative
2	3	Classroom 315	Pole	Metal	Blue	Friction	4	1.6	Positive
2	3	Classroom 315	Door casing	Metal	Tan	None	0	0.34	Negative
2	3	Classroom 315	Door	Wood	Tan	None	0	0.15	Negative
2	3	Classroom 315	Ceiling	Concrete	White	Flaking	100	0.34	Negative
2	3	Classroom 315	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A
2	3	Classroom 315 Storage	W1	Concrete	Blue	None	0	0.17	Negative
2	3	Classroom 315 Storage	W2	Concrete	Blue	None	0	0.46	Negative
2	3	Classroom 315 Storage	W3	Concrete	Blue	None	0	0.31	Negative
2	3	Classroom 315 Storage	W4	Concrete	Blue	None	0	0.15	Negative
2	3	Classroom 315 Storage	Ceiling	Concrete	White	Friction	50	0.2	Negative
2	3	Classroom 315 Storage	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A
2	3	Classroom 310	W1	Concrete	Blue	None	0	0.09	Negative
2	3	Classroom 310	W2	Concrete	Blue	None	0	0.1	Negative
2	3	Classroom 310	W3	Concrete	Blue	None	0	0.08	Negative
2	3	Classroom 310	W4	Concrete	Blue	None	0	0.07	Negative
2	3	Classroom 310	Ceiling	Concrete	White	None	0	0.06	Negative
2	3	Classroom 310	Pole	Metal	Blue	Friction	3	1.5	Positive
2	3	Classroom 310	Univent	Metal	Tan	None	0	0.07	Negative
2	3	Classroom 310	Door casing	Metal	Tan	None	0	0.14	Negative
2	3	Classroom 310	Door	Wood	Tan	None	0	0.16	Negative
2	3	Classroom 310	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A
2	3	Hallway next to Classrooms 315 and 310	W1	Concrete	Yellow	None	0	0.09	Negative
2	3	Hallway next to Classrooms 315 and 310	W2	Concrete	Yellow	None	0	0.02	Negative
2	3	Hallway next to Classrooms 315 and 310	W3	Concrete	Yellow	None	0	0.1	Negative
2	3	Hallway next to Classrooms 315 and 310	W4	Concrete	Yellow	None	0	0.3	Negative
2	3	Hallway next to Classrooms 315 and 310	Ceiling	Concrete	White	Flaking	100	0.17	Negative
2	3	Hallway next to Classrooms 315 and 310	Door	Metal	Red	None	0	0.16	Negative
2	3	Hallway next to Classrooms 315 and 310	Door casing	Metal	Red	None	0	0.16	Negative
2	3	Hallway next to Classrooms 315 and 310	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	3	Stairs near Classroom 310	W1	Concrete	White	None	0	0	Negative
2	3	Stairs near Classroom 310	W2	Concrete	White	None	0	0	Negative
2	3	Stairs near Classroom 310	W3	Concrete	White	None	0	0	Negative
2	3	Stairs near Classroom 310	W4	Concrete	White	None	0	0	Negative

		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>						
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>						
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
		2	3	Stairs near Classroom 310	Ceiling	Concrete	White	None	0
2	3	Stairs near Classroom 310	Floor	Concrete	Brown	None	0	0	Negative
2	3	Stairs near Classroom 310	Door	Metal	Brown	None	0	0.1	Negative
2	3	Stairs near Classroom 310	Door Casing	Metal	Brown	None	0	0.27	Negative
2	3	Classroom 311	W1	Concrete	Yellow	None	0	0.09	Negative
2	3	Classroom 311	W2	Concrete	Yellow	None	0	0.1	Negative
2	3	Classroom 311	W3	Concrete	Yellow	None	0	0.08	Negative
2	3	Classroom 311	Pole	Metal	Yellow	Friction	2	1.5	Positive
2	3	Classroom 311	Door	Wood	Tan	None	0	0.09	Negative
2	3	Classroom 311	Door casing	Metal	Tan	None	0	0.1	Negative
2	3	Classroom 311	Univent	Metal	Tan	None	0	0.12	Negative
2	3	Classroom 311	W4	Concrete	Yellow	None	0	0.07	Negative
2	3	Classroom 311	Ceiling	Concrete	White	None	0	0.1	Negative
2	3	Classroom 311	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A
2	3	Classroom 313	W1	Concrete	Yellow	None	0	0.08	Negative
2	3	Classroom 313	W2	Sheetrock	Yellow	None	0	0	Negative
2	3	Classroom 313	W3	Concrete	Yellow	None	0	0.06	Negative
2	3	Classroom 313	W4	Concrete	Yellow	None	0	0.07	Negative
2	3	Classroom 313	Ceiling	Concrete	White	None	0	0.09	Negative
2	3	Classroom 313	Univent	Metal	Tan	None	0	0.12	Negative
2	3	Classroom 313	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A
2	3	Classroom 313 Storage Closet near windows	W1	Sheetrock	Yellow	None	0	0	Negative
2	3	Classroom 313 Storage Closet near windows	W2	Concrete	Yellow	None	0	0.09	Negative
2	3	Classroom 313 Storage Closet near windows	W3	Concrete	Yellow	None	0	0.08	Negative
2	3	Classroom 313 Storage Closet near windows	W4	Sheetrock	Yellow	None	0	0	Negative
2	3	Classroom 313 Storage Closet near windows	Pole	Metal	Yellow	Friction	5	1.3	Positive
2	3	Classroom 313 Storage Closet near windows	Ceiling	Concrete	White	None	0	0.09	Negative
2	3	Classroom 313 Storage Closet near windows	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A
2	3	Classroom 313 Storage Closet at Hallway side of room	W1	Sheetrock	Yellow	None	0	0	Negative
2	3	Classroom 313 Storage Closet at Hallway side of room	W2	Concrete	Yellow	None	0	0.08	Negative
2	3	Classroom 313 Storage Closet at Hallway side of room	W3	Concrete	Yellow	None	0	0.07	Negative
2	3	Classroom 313 Storage Closet at Hallway side of room	W4	Sheetrock	Yellow	None	0	0	Negative
2	3	Classroom 313 Storage Closet at Hallway side of room	Ceiling	Concrete	White	None	0	0.1	Negative
2	3	Classroom 313 Storage Closet at Hallway side of room	Pole	Metal	Yellow	Friction	5	1.9	Positive
2	3	Classroom 313 Storage Closet at Hallway side of room	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A



		Dates: 3/16/23-3/31/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Christopher Karoly 006424	The U School @ Ferguson Elementary School School						
		Inspection Company: Criterion Laboratories	2000 N.7th Street, Philadelphia, PA 19122						
Element	Floor	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	3	Classroom 312	W1	Concrete	Yellow	None	0	0.03	Negative
2	3	Classroom 312	W2	Concrete	Yellow	None	0	0.05	Negative
2	3	Classroom 312	W3	Concrete	Yellow	None	0	0.08	Negative
2	3	Classroom 312	W4	Concrete	Yellow	None	0	0.08	Negative
2	3	Classroom 312	Univent	Metal	Tan	None	0	0.09	Negative
2	3	Classroom 312	Door Casing	Metal	Tan	None	0	0.06	Negative
2	3	Classroom 312	Door	Wood	Tan	None	0	0.07	Negative
2	3	Classroom 312	Pole	Metal	Yellow	Friction	5	1.8	Positive
2	3	Classroom 312	Ceiling	Concrete	White	None	0	0.03	Negative
2	3	Classroom 312	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A
2	3	Stairwell next to Classrooms 312 and 313	W1	Concrete	Yellow	None	0	0.02	Negative
2	3	Stairwell next to Classrooms 312 and 313	W2	Concrete	Yellow	None	0	0.01	Negative
2	3	Stairwell next to Classrooms 312 and 313	W3	Concrete	Yellow	None	0	0.01	Negative
2	3	Stairwell next to Classrooms 312 and 313	W4	Concrete	Yellow	None	0	0.01	Negative
2	3	Stairwell next to Classrooms 312 and 313	Ceiling	Concrete	White	None	0	0.03	Negative
2	3	Stairwell next to Classrooms 312 and 313	Door Casing W1	Metal	Tan	None	0	0.26	Negative
2	3	Stairwell next to Classrooms 312 and 313	Door W1	Metal	Tan	None	0	0.14	Negative
2	3	Stairwell next to Classrooms 312 and 313	Floor	Concrete	Brown	None	0	0.02	Negative
1	AT	Main Attic - Entrance through 318A (3rd Floor Custodial Closet beside Classrooms 301 and 302)	W1	N/A	Unpainted	N/A	N/A	N/A	N/A
1	AT	Main Attic - Entrance through 318A (3rd Floor Custodial Closet beside Classrooms 301 and 302)	W2	N/A	Unpainted	N/A	N/A	N/A	N/A
1	AT	Main Attic - Entrance through 318A (3rd Floor Custodial Closet beside Classrooms 301 and 302)	W3	N/A	Unpainted	N/A	N/A	N/A	N/A
1	AT	Main Attic - Entrance through 318A (3rd Floor Custodial Closet beside Classrooms 301 and 302)	W4	N/A	Unpainted	N/A	N/A	N/A	N/A
1	AT	Main Attic - Entrance through 318A (3rd Floor Custodial Closet beside Classrooms 301 and 302)	Ceiling	N/A	Unpainted	N/A	N/A	N/A	N/A
1	AT	Main Attic - Entrance through 318A (3rd Floor Custodial Closet beside Classrooms 301 and 302)	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawl Space in Basement Restroom	W1	N/A	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawl Space in Basement Restroom	W2	N/A	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawl Space in Basement Restroom	W3	N/A	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawl Space in Basement Restroom	W4	N/A	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawl Space in Basement Restroom	Ceiling	N/A	Unpainted	N/A	N/A	N/A	N/A

		Dates: 3/16/23-3/31/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Christopher Karoly 006424	<b>The U School @ Ferguson Elementary School School</b>							
		Inspection Company: Criterion Laboratories	<b>2000 N.7th Street, Philadelphia, PA 19122</b>							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
		1	CS	Crawl Space in Basement Restroom	Floor	N/A	Unpainted	N/A	N/A	N/A
1	CS	Crawl Space in Basement Stairwell	W1	N/A	Unpainted	N/A	N/A	N/A	N/A	
1	CS	Crawl Space in Basement Stairwell	W2	N/A	Unpainted	N/A	N/A	N/A	N/A	
1	CS	Crawl Space in Basement Stairwell	W3	N/A	Unpainted	N/A	N/A	N/A	N/A	
1	CS	Crawl Space in Basement Stairwell	W4	N/A	Unpainted	N/A	N/A	N/A	N/A	
1	CS	Crawl Space in Basement Stairwell	Ceiling	N/A	Unpainted	N/A	N/A	N/A	N/A	
1	CS	Crawl Space in Basement Stairwell	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A	
1	CS	Crawl Space in Boiler Room	W1	N/A	Unpainted	N/A	N/A	N/A	N/A	
1	CS	Crawl Space in Boiler Room	W2	N/A	Unpainted	N/A	N/A	N/A	N/A	
1	CS	Crawl Space in Boiler Room	W3	N/A	Unpainted	N/A	N/A	N/A	N/A	
1	CS	Crawl Space in Boiler Room	W4	N/A	Unpainted	N/A	N/A	N/A	N/A	
1	CS	Crawl Space in Boiler Room	Ceiling	N/A	Unpainted	N/A	N/A	N/A	N/A	
1	CS	Crawl Space in Boiler Room	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A	