

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	1250	1	3	307A	Primary	Classroom 300A	Ceiling	Flaking	120	N	N	0	N	Y - 12	Additional Efflorescence, Cracking
2	1250	1	3	307A	Primary	Classroom 300A	W1	Flaking	8	N	N	0	Y - 14 SF File Cabinets	N	2 Locations; Additional Cracking, Gouges
3	1250	1	3	307A	Primary	Classroom 300A	W2	Flaking	5	N	N	0	N	N	2 Locations; Additional Cracking
4	1250	1	3	307A	Primary	Classroom 300A	W3	Flaking	15	N	Y - On Window Sill	1 SF	N	Y - 1 SF	3 Locations; Additional Chipping, Holes; Damage @ Radiator & Window Frame
5	1250	1	3	301	Primary	Classroom 301	W1	Chipping	3	N	N	0	N/A	N	
6	1250	1	3	301	Primary	Classroom 301	W3	Flaking	2	N	N	0	Y - 68 SF Desks, Contents	N	Flaking @ Radiator Grate
7	1250	1	3	301	Primary	Classroom 301	W4	Partially Inaccessible		N	N	0	Y - 48 SF Desks	N	
8	2510	1	3	301C	Storage	Classroom 301 Left Side Storage Closet	Ceiling	Inaccessible							
9	2510	1	3	301C	Storage	Classroom 301 Left Side Storage Closet	Floor	Inaccessible							
10	2510	1	3	301C	Storage	Classroom 301 Left Side Storage Closet	W4	Inaccessible							
11	2510	1	3	301B	Storage	Classroom 301 Right Side Storage Closet	Ceiling	Inaccessible							
12	2510	1	3	301B	Storage	Classroom 301 Right Side Storage Closet	Floor	Inaccessible							
13	2510	1	3	301B	Storage	Classroom 301 Right Side Storage Closet	W1	Inaccessible							
14	2510	1	3	301B	Storage	Classroom 301 Right Side Storage Closet	W2	Inaccessible							
15	2510	1	3	301B	Storage	Classroom 301 Right Side Storage Closet	W3	Inaccessible							
16	2510	1	3	301B	Storage	Classroom 301 Right Side Storage Closet	W4	Inaccessible							
17	2510	1	3	301C	Storage	Classroom 301 Left Side Storage Closet	W1	Inaccessible							
18	2510	1	3	301C	Storage	Classroom 301 Left Side Storage Closet	W2	Inaccessible							
19	2510	1	3	301C	Storage	Classroom 301 Left Side Storage Closet	W3	Inaccessible							
20	1250	1	3	302	Primary	Classroom 302	Ceiling	Holes	1	N	N	0	N	N	
21	1250	1	3	302	Primary	Classroom 302	W1	Chipping	6	N	N	0	N	N	2 Locations
22	1250	1	3	302	Primary	Classroom 302	W3	Flaking	3	N	N	0	N	N	2 Locations; Additional Chipping
23	1250	1	3	303	Primary	Classroom 303	Ceiling	Flaking	7	N	N	0	N	N	2 Locations; Additional Cracking
24	1250	1	3	303	Primary	Classroom 303	W3	Flaking	2	N	Y - Windows 3 & 4	2	N	N	Flaking @ Radiator
25	1250	1	3	304	Primary	Classroom 304	W1	Cracking	2	N	N	0	Y - 10 SF Posters		
26	1250	1	3	304	Primary	Classroom 304	W2	Chipping	1	N	N	0	Y - 16 SF Posters		
27	1250	1	3	304	Primary	Classroom 304	W3	Flaking	2	Y	N	0	Y - 15 SF Contents, Posters	Y - 1 SF	Additional Spalling; Flaking @ Radiator Grate; Spalling under Window 5
28	1250	1	3	304	Primary	Classroom 304	W4	Partially Inaccessible		N	N	0	Y - 84 SF Bookcases, File Cabinets, Desks		
29	2510	1	3	305A	Storage	Classroom 305 Coat Closet Area	W3	Partially Inaccessible		N	N	0	Y - 180 SF Contents	N	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
30	1250	1	3	306	Primary	Classroom 306	W1	Cracking	6	N	N	0	Y - 120 SF Shelves, Contents	N	
31	1250	1	3	306	Primary	Classroom 306	W2	Cracking	25	N	N	0	Y - 22 SF Desks	N	2 Locations
32	1250	1	3	306	Primary	Classroom 306	W3	Flaking	4	N	N	0	Y - 96 SF File Cabinets, Tables, Desks, Contents	N	2 Locations; Additional Cracking; Damage Includes ACPI
33	1250	1	3	306B	Storage	Classroom 306 Center Closet	Ceiling	Flaking	12	N	N	0	N	N/A	Additional Cracking
34	1250	1	3	306B	Storage	Classroom 306 Center Closet	W1	Cracking	1	N	N	0	Y - 24 SF Shelves	N/A	
35	1250	1	3	306B	Storage	Classroom 306 Center Closet	W2	Partially Inaccessible		N	N	0	Y - 64 SF Shelves	N/A	
36	1250	1	3	306B	Storage	Classroom 306 Center Closet	W3	Partially Inaccessible		N	N	0	Y - 80 SF Shelves	N/A	
37	1250	1	3	306B	Storage	Classroom 306 Center Closet	W4	Cracking	7	N	N	0	Y - 48 SF Shelves	N/A	
38	1250	1	3	306A	Storage	Classroom 306 Closet adjacent to Hallway	Ceiling	Flaking	8	N	N	0	N	N	Additional Cracking
39	1250	1	3	306A	Storage	Classroom 306 Closet adjacent to Hallway	W2	Partially Inaccessible		N	N	0	Y - 64 SF Shelves	N	
40	1250	1	3	306A	Storage	Classroom 306 Closet adjacent to Hallway	W3	Partially Inaccessible		N	N	0	Y - 64 SF Shelves	N	
41	1250	1	3	306A	Storage	Classroom 306 Closet adjacent to Hallway	W4	Cracking	4	N	N	0	N	N	
42	1250	1	3	307	Primary	Classroom 307	W2	Flaking	3	N	N	0	Y - 40 SF Bookcases, Desks, Posters	N	Additional Gouges
43	1250	1	3	307	Primary	Classroom 307	W3	Chipping	4	N	N	0	Y - 36 SF Bookcases, Posters	N	2 Locations
44	1250	1	3	307	Primary	Classroom 307	W4	Flaking	3	N	N	0	Y - 48 SF Bookcases, Posters	N	Additional Gouges
45	2510	1	3	307A	Storage	Classroom 307 Coat Closet Area	W3	Chipping	1	N	N	0	Y - 120 SF Contents	N	
46	1250	1	3	308	Primary	Classroom 308	Ceiling	Flaking	5	N	N	0	N	N	2 Locations; Additional Cracking; Damage @ Window Lintel 3 @ ACPI
47	1250	1	3	308	Primary	Classroom 308	W1	Chipping	4	N	N	0	N	N	2 Locations
48	1250	1	3	308	Primary	Classroom 308	W3	Flaking	2	N	N	0	Y - 42 SF Bookcases, Posters	N	Flaking @ Radiator Grate
49	1250	1	3	308	Primary	Classroom 308	W4	Chipping	2	N	N	0	Y - 64 SF Bookcases, Desks, Posters	N	
50	2510	1	3	NP13	Storage	Classroom 308 Book Closet	Ceiling	Inaccessible							
51	2510	1	3	NP13	Storage	Classroom 308 Book Closet	Floor	Inaccessible							
52	2510	1	3	NP13	Storage	Classroom 308 Book Closet	W1	Inaccessible							
53	2510	1	3	NP13	Storage	Classroom 308 Book Closet	W2	Inaccessible							
54	2510	1	3	NP13	Storage	Classroom 308 Book Closet	W3	Inaccessible							
55	2510	1	3	NP13	Storage	Classroom 308 Book Closet	W4	Inaccessible							
56	2510	1	3	308A	Storage	Classroom 308 Coat Closet Area	W3	Holes	2	N	N	0	N	N	
57	1250	1	3	309	Primary	Classroom 309	Ceiling	Flaking	1	N	N	0	N	N	
58	1250	1	3	309	Primary	Classroom 309	W1	Cracking	2	N	N	0	N	N	
59	1250	1	3	309	Primary	Classroom 309	W3	Flaking	8	N	N	0	N	N	2 Locations; Additional Chipping
60	1250	1	3	309A	Primary	Classroom 309 Closet	Ceiling	Flaking	6	N	N	0	N	Y - 6 SF	Additional Cracking
61	1250	1	3	309A	Primary	Classroom 309 Closet	W2	Partially Inaccessible		N	N	0	Y - 14 SF Shelves	N	
62	1250	1	3	309A	Primary	Classroom 309 Closet	W3	Partially Inaccessible		N	N	0	Y - 42 SF Shelves	N	
63	1250	1	3	309A	Primary	Classroom 309 Closet	W4	Partially Inaccessible		N	N	0	Y - 14 SF Shelves	N	
64	1250	1	3	310	Primary	Classroom 310	Ceiling	Efflorescence	1	N	N	0	N	Y - 1 SF	Damage @ Window Lintel 1
65	1250	1	3	310	Primary	Classroom 310	W1	Cracking	3	N	N	0	Y - 10 SF Posters	N	2 Locations
66	1250	1	3	310	Primary	Classroom 310	W3	Flaking	3	N	N	0	Y - 40 SF Bookcases, Desks, Posters	N	2 Locations; Additional Chipping

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
67	1250	1	3	310	Primary	Classroom 310	W4	Chipping	8	N	N	0	N	N	
68	1250	1	3	311	Primary	Classroom 311	Ceiling	Flaking	6	N	N	0	N	Y - 2 SF	4 Locations; Additional Efflorescence, Cracking
69	1250	1	3	311	Primary	Classroom 311	W1	Partially Inaccessible		N	N	0	Y - 160 SF Posters, Contents	N	
70	1250	1	3	311	Primary	Classroom 311	W2	Partially Inaccessible		N	N	0	Y - 72 SF Bookcases, Desks, Posters	N	
71	1250	1	3	311	Primary	Classroom 311	W3	Flaking	5	N	N	0	Y - 30 SF Posters	N	3 Locations; Additional Cracking; Flaking @ Radiator
72	1250	1	3	311	Primary	Classroom 311	W4	Cracking	5	N	N	0	Y - 48 SF Bookcases, Desks, Contents	N	Additional Chipping
73	2510	1	3	S310	Stairs	Fire Tower Stairs	Ceiling	Inaccessible							
74	2510	1	3	S310	Stairs	Fire Tower Stairs	Floor	Inaccessible							
75	2510	1	3	S310	Stairs	Fire Tower Stairs	W1	Inaccessible							
76	2510	1	3	S310	Stairs	Fire Tower Stairs	W2	Inaccessible							
77	2510	1	3	S310	Stairs	Fire Tower Stairs	W3	Inaccessible							
78	2510	1	3	S310	Stairs	Fire Tower Stairs	W4	Inaccessible							
79	1250	1	3	306C	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	Ceiling	Inaccessible							
80	1250	1	3	306C	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	Floor	Inaccessible							
81	1250	1	3	306C	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	W1	Inaccessible							
82	1250	1	3	306C	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	W2	Inaccessible							
83	1250	1	3	306C	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	W3	Inaccessible							
84	1250	1	3	306C	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	W4	Inaccessible							
85	1250	1	3	H37	Circulation (Hallway)	Hallway from Boy's Restroom 300B to Classroom 310	W1	Cracking	6	N	N	0	N	N	
86	1250	1	3	H37	Circulation (Hallway)	Hallway from Boy's Restroom 300B to Classroom 310	W2	Flaking	76	N	N	0	Y - 12 SF Posters	N	6 Locations; Additional Cracking Chipping; Flaking on ACPI & Radiators
87	1250	1	3	H37	Circulation (Hallway)	Hallway from Boy's Restroom 300B to Classroom 310	W3	Cracking	11	N	N	0	N	N	2 Locations
88	1250	1	3	H37	Circulation (Hallway)	Hallway from Boy's Restroom 300B to Classroom 310	W4	Flaking	14	N	N	0	N	N	4 Locations; Additional Cracking, Chipping; Flaking on Radiator
89	1250	1	3	H38	Circulation (Hallway)	Hallway outside Classrooms 301-305	Ceiling	Cracking	2	N	N	0	N	N	
90	1250	1	3	H38	Circulation (Hallway)	Hallway outside Classrooms 301-305	W1	Cracking	30	N	N	0	Y - 41 SF Posters	N	6 Locations; Additional Chipping
91	1250	1	3	H38	Circulation (Hallway)	Hallway outside Classrooms 301-305	W3	Flaking	60	N	N	0	Y - 18 SF Bulletin Boards	N	9 Locations Additional Cracking, Chipping; Flaking on Radiator 1
92	1250	1	3	H38	Circulation (Hallway)	Hallway outside Classrooms 301-305	W4	Cracking	13	N	N	0	N	N	2 Locations; Additional Chipping
93	1250	1	3	301D	Circulation (Hallway)	Hallway to Classroom 300A	Ceiling	Cracking	10	N	N	0	N	N	2 Locations
94	1250	1	3	311D	Circulation (Hallway)	Hallway to Program Support Teacher's Office	W1	Cracking	2	N	N	0	N	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
95	1250	1	3	311D	Circulation (Hallway)	Hallway to Program Support Teacher's Office	W2	Cracking	20	N	N	0	N	Y - 10 SF	2 Locations; Additional Efflorescence
96	1250	1	3	311D	Circulation (Hallway)	Hallway to Program Support Teacher's Office	W3	Cracking	2	N	N	0	N	N	
97	1250	1	3	311D	Circulation (Hallway)	Hallway to Program Support Teacher's Office	W4	Gouges	1	N	N	0	N	N	
98	1250	1	3	305	IMC (Library)	IMC 305	W1	Cracking	1	N	N	0	Y - 27 SF Bookcases, Desks	N	
99	1250	1	3	305	IMC (Library)	IMC 305	W2	Partially Inaccessible		N	N	0	Y - 30 SF Bookcases	N	
100	1250	1	3	305	IMC (Library)	IMC 305	W3	Flaking	5	N	N	0	N	N	3 Locations; Additional Cracking, Chipping; Flaking @ Radiator Grate; Chipping @ ACPI
101	2510	1	3	310	IMC (Library)	IMC/Library	Ceiling	Efflorescence	1	Y	N	0	N	Y - 1 SF	Damage @ Window Lintel 1
102	2510	1	3	310	IMC (Library)	IMC/Library	W1	Cracking	3	N	N	0	Y - 10 SF Posters	N	2 Locations
103	2510	1	3	310	IMC (Library)	IMC/Library	W3	Flaking	3	N	N	0	Y - 40 SF Bookcases, Desks	N	2 Locations; Additional Chipping
104	2510	1	3	310	IMC (Library)	IMC/Library	W4	Chipping	2	N	N	0	Y - 8 SF Posters	N	
105	2510	1	3	310A	Storage	IMC/Library Middle Storage Closet	W2	Partially Inaccessible		N	N	0	Y - 7 SF Shelves	N	
106	2510	1	3	310A	Storage	IMC/Library Middle Storage Closet	W3	Partially Inaccessible		N	N	0	Y - 42 SF Shelves	N	
107	2510	1	3	310A	Storage	IMC/Library Middle Storage Closet	W4	Partially Inaccessible		N	N	0	Y - 7 SF Shelves	N	
108	1250	1	3	311A	Administrative Office	Program Support Teacher's Office	Ceiling	Cracking	1	N	N	0	N	N	
109	1250	1	3	311A	Administrative Office	Program Support Teacher's Office	W2	Partially Inaccessible		N	N	0	Y - 24 SF Desks, Cabinets	N	
110	1250	1	3	311A	Administrative Office	Program Support Teacher's Office	W3	Flaking	4	N	N	0	N	Y - 2 SF	Additional Efflorescence, Cracking; Damage @ Window Frames 1, 2
111	2510	1	3	304B	Administrative Office	Room 304-A Counselor's Office	W2	Partially Inaccessible		N	N	0	Y - 7 SF Shelves	N	
112	2510	1	3	304B	Administrative Office	Room 304-A Counselor's Office	W3	Partially Inaccessible		N	N	0	Y - 42 SF Shelves	N	
113	2510	1	3	304B	Administrative Office	Room 304-A Counselor's Office	W4	Partially Inaccessible		N	N	0	Y - 7 SF Shelves	N	
114	2510	1	3	304D	Restrooms, Staff - Female	Room 304-A Counselor's Office Women's Restroom	Ceiling	Inaccessible							
115	2510	1	3	304D	Restrooms, Staff - Female	Room 304-A Counselor's Office Women's Restroom	Floor	Inaccessible							
116	2510	1	3	304D	Restrooms, Staff - Female	Room 304-A Counselor's Office Women's Restroom	W1	Inaccessible							
117	2510	1	3	304D	Restrooms, Staff - Female	Room 304-A Counselor's Office Women's Restroom	W2	Inaccessible							
118	2510	1	3	304D	Restrooms, Staff - Female	Room 304-A Counselor's Office Women's Restroom	W3	Inaccessible							
119	2510	1	3	304D	Restrooms, Staff - Female	Room 304-A Counselor's Office Women's Restroom	W4	Inaccessible							
120	2510	1	3	304C	Storage	Room 304-A Storage Closet	W3	Flaking	1	N	N	0	N	N	
121	1250	1	3	S32	Stairs	Stairwell across from Classroom 302	Ceiling	Flaking	2	N	N	0	N	N	Flaking above Door
122	1250	1	3	S32	Stairs	Stairwell across from Classroom 302	Center Banister	Chipping	96	N	N	0	N	N	
123	1250	1	3	S32	Stairs	Stairwell across from Classroom 302	W1	Chipping	4	N	N	0	N	N	Chipping @ Doors

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
124	1250	1	3	S32	Stairs	Stairwell across from Classroom 302	W2	Cracking	5	N	N	0	N	N	
125	1250	1	3	S32	Stairs	Stairwell across from Classroom 302	W3	Flaking	10	N	N	0	N	N	2 Locations; Additional Chipping; Flaking @ Window Frame; Chipping @ ACPI
126	2510	1	3	S36	Stairs	Stairwell next to Classroom 301	Ceiling	Inaccessible							
127	2510	1	3	S36	Stairs	Stairwell next to Classroom 301	Floor	Inaccessible							
128	2510	1	3	S36	Stairs	Stairwell next to Classroom 301	W1	Inaccessible							
129	2510	1	3	S36	Stairs	Stairwell next to Classroom 301	W2	Inaccessible							
130	2510	1	3	S36	Stairs	Stairwell next to Classroom 301	W3	Inaccessible							
131	2510	1	3	S36	Stairs	Stairwell next to Classroom 301	W4	Inaccessible							
132	1250	1	3	S31	Stairs	Stairwell next to Classroom 304	Ceiling	Flaking	6	N	N	0	N	N	Additional Cracking
133	1250	1	3	S31	Stairs	Stairwell next to Classroom 304	W1	Flaking	64	N	N	0	N	N	Additional Cracking
134	1250	1	3	S31	Stairs	Stairwell next to Classroom 304	W3	Flaking	48	N	N	0	N	N	Additional Chipping
135	1250	1	3	S31	Stairs	Stairwell next to Classroom 304	W4	Flaking	1	N	N	0	N	N	Flaking @ Window
136	1250	1	3	S33	Stairs	Stairwell next to Classroom 309	W3	Cracking	2	N	N	0	N	N	2 Locations
137	2510	1	3	301A	Storage	Storage Closet next to Classroom 301	Ceiling	Inaccessible							
138	2510	1	3	301A	Storage	Storage Closet next to Classroom 301	Floor	Inaccessible							
139	2510	1	3	301A	Storage	Storage Closet next to Classroom 301	W1	Inaccessible							
140	2510	1	3	301A	Storage	Storage Closet next to Classroom 301	W2	Inaccessible							
141	2510	1	3	301A	Storage	Storage Closet next to Classroom 301	W3	Inaccessible							
142	2510	1	3	301A	Storage	Storage Closet next to Classroom 301	W4	Inaccessible							
143	1250	1	3	301A	Storage	Storage Room across from Classroom 301	Ceiling	Flaking	8	Y	N	0	N	N	Additional Gouges
144	1250	1	3	301A	Storage	Storage Room across from Classroom 301	W1	Cracking	12	N	N	0	Y - 24 SF Shelves	N	2 Locations
145	1250	1	3	301A	Storage	Storage Room across from Classroom 301	W2	Partially Inaccessible		N	N	0	Y - 96 SF Shelves	N	
146	1250	1	3	301A	Storage	Storage Room across from Classroom 301	W3	Partially Inaccessible		N	N	0	Y - 112 SF Shelves	N	
147	1250	1	3	301A	Storage	Storage Room across from Classroom 301	W4	Cracking	6	N	N	0	Y - 96 SF Cabinets, Shelves	N	2 Locations; Additional Chipping
148	2510	1	3	310B	Storage	Storage Room in IMC/Library	Ceiling	Inaccessible							
149	2510	1	3	310B	Storage	Storage Room in IMC/Library	Floor	Inaccessible							
150	2510	1	3	310B	Storage	Storage Room in IMC/Library	W1	Inaccessible							
151	2510	1	3	310B	Storage	Storage Room in IMC/Library	W2	Inaccessible							
152	2510	1	3	310B	Storage	Storage Room in IMC/Library	W3	Inaccessible							
153	2510	1	3	310B	Storage	Storage Room in IMC/Library	W4	Inaccessible							
154	1250	1	3	311B	Restrooms, Staff - Female	Women's Restroom adjacent to Program Support Teacher's Office	W1	Flaking	9	N	N	0	N	N	Additional Cracking; Damage @ Door Frame
155	1250	1	2	201	Primary	Classroom 201	Ceiling	Cracking	1	N	N	0	N	N	
156	1250	1	2	201	Primary	Classroom 201	W1	Flaking	13	N	N	0	N	N	
157	1250	1	2	201	Primary	Classroom 201	W3	Flaking	2	N	N	0	Y - 26 SF Bookcases, Posters	N	
158	1250	1	2	201	Primary	Classroom 201	W4	Chipping	3	N	N	0	Y - 24 SF Desks	N	
159	1250	1	2	202	Primary	Classroom 202	W1	Chipping	4	N	N	0	N	N	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
160	1250	1	2	202	Primary	Classroom 202	W3	Flaking	2	N	N	0	Y - 48 SF File Cabinets, Desks, Contents	N	
161	1250	1	2	203	Primary	Classroom 203	W1	Partially Inaccessible		N	N	0	Y - 60 SF Contents	N	
162	1250	1	2	203	Primary	Classroom 203	W2	Gouges	2	N	N	0	Y - 52 SF Desks, Contents	N	
163	1250	1	2	203	Primary	Classroom 203	W3	Flaking	3	N	N	0	Y - 48 SF Bookcases	N	Additional Chipping; Damage @ Radiator
164	1250	1	2	204	Primary	Classroom 204	W1	Chipping	1	N	N	0	Y - 12 SF File Cabinets	N	Chipping above Closet
165	1250	1	2	204	Primary	Classroom 204	W2	Cracking	3	N	N	0	Y - 56 SF Tables, Bookcases	N	2 Locations; Additional Chipping
166	1250	1	2	204	Primary	Classroom 204	W3	Flaking	2	N	N	0	Y - 90 SF Bookcases, Posters	N	Flaking @ Radiator
167	1250	1	2	204	Primary	Classroom 204	W4	Partially Inaccessible		N	N	0	Y - 64 SF Tables, Smartboard, Posters	N	
168	1250	1	2	205	Primary	Classroom 205	W2	Flaking	1	N	N	0	Y - 32 SF Bookcases	Y - 1 SF	Additional Gouges
169	1250	1	2	205	Primary	Classroom 205	W3	Flaking	3	N	N	0	Y - 16 SF Posters	N	Additional Chipping; Damage @ Radiator Grate
170	1250	1	2	205	Primary	Classroom 205	W4	Chipping	18	N	N	0	Y - 24 SF Bookcases, Desks	N	Additional Holes
171	1250	1	2	206	Primary	Classroom 206	W2	Flaking	1	N	N	0	N	N	
172	1250	1	2	206	Primary	Classroom 206	W3	Flaking	5	N	N	0	N	N	Flaking @ Radiator Grate
173	1250	1	2	206	Primary	Classroom 206	W4	Flaking	1	N	N	0	N	N	
174	1250	1	2	206C	Storage	Classroom 206 Center Closet	Ceiling	Inaccessible							
175	1250	1	2	206C	Storage	Classroom 206 Center Closet	Floor	Inaccessible							
176	1250	1	2	206C	Storage	Classroom 206 Center Closet	W1	Inaccessible							
177	1250	1	2	206C	Storage	Classroom 206 Center Closet	W2	Inaccessible							
178	1250	1	2	206C	Storage	Classroom 206 Center Closet	W3	Inaccessible							
179	1250	1	2	206C	Storage	Classroom 206 Center Closet	W4	Inaccessible							
180	1250	1	2	207	Primary	Classroom 207	W3	Partially Inaccessible		N	N	0	Y - 32 SF Bookcases, File Cabinets, Posters	N	
181	1250	1	2	207	Primary	Classroom 207	W4	Partially Inaccessible		N	N	0	Y - 22 SF Desks, Posters	N	
182	1250	1	2	208	Primary	Classroom 208	W1	Partially Inaccessible		N	N	0	Y - 48 SF Posters	N	
183	1250	1	2	208	Primary	Classroom 208	W2	Cracking	3	N	N	0	N	N	
184	1250	1	2	208	Primary	Classroom 208	W3	Chipping	4	N	N	0	N	N	Chipping @ Radiator
185	1250	1	2	208	Primary	Classroom 208	W4	Partially Inaccessible		N	N	0	Y - 60 SF Bookcases, Desks, Contents	N	
186	1250	1	2	209	Primary	Classroom 209	W1	Partially Inaccessible		N	N	0	Y - 200 SF Boxes, Contents, Posters	N	
187	1250	1	2	209	Primary	Classroom 209	W2	Partially Inaccessible		N	N	0	Y - 80 SF Bulletin Boards, Posters, Contents	N	
188	1250	1	2	209	Primary	Classroom 209	W3	Partially Inaccessible		N	N	0	Y - 72 SF Bookcases, Posters, Contents	N	
189	1250	1	2	209	Primary	Classroom 209	W4	Partially Inaccessible		N	N	0	Y - 100 SF Smartboard, Desks, Posters, Contents	N	
190	1250	1	2	210	Primary	Classroom 210	W1	Partially Inaccessible		N	N	0	Y - 60 SF Posters, Contents	N	Room Previously Abated
191	1250	1	2	210	Primary	Classroom 210	W3	Flaking	1	N	N	0	Y - 60 SF Bookcases, Shelves, Contents	N	Flaking Between Windows 4 & 5
192	1250	1	2	210	Primary	Classroom 210	W4	Partially Inaccessible		N	N	0	Y - 45 SF Desks, Tables	N	
193	1250	1	2	211	Primary	Classroom 211	W1	Chipping	2	N	N	0	N	N	
194	1250	1	2	211	Primary	Classroom 211	W2	Chipping	2	N	N	0	N	N	2 Locations

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
195	1250	1	2	211	Primary	Classroom 211	W3	Flaking	6	Y	N	0	N	Y - 1 SF	2 Locations; Additional Efflorescence; Damage @ Radiator and Window 1
196	1250	1	2	211	Primary	Classroom 211	W4	Chipping	3	N	N	0	Y - 48 SF Desks	N	
197	2510	1	2	S210	Stairs	Fire Tower Stairs	Ceiling	Inaccessible							
198	2510	1	2	S210	Stairs	Fire Tower Stairs	Floor	Inaccessible							
199	2510	1	2	S210	Stairs	Fire Tower Stairs	W1	Inaccessible							
200	2510	1	2	S210	Stairs	Fire Tower Stairs	W2	Inaccessible							
201	2510	1	2	S210	Stairs	Fire Tower Stairs	W3	Inaccessible							
202	2510	1	2	S210	Stairs	Fire Tower Stairs	W4	Inaccessible							
203	1250	1	2	H25	Circulation (Hallway)	Hallway from Teacher's Lounge to Classroom 210	Ceiling	Cracking	10	N	N	0	N	N	
204	1250	1	2	H25	Circulation (Hallway)	Hallway from Teacher's Lounge to Classroom 210	W2	Flaking	25	N	N	0	Y - 40 SF Posters	N	9 Locations; Additional Chipping
205	1250	1	2	H25	Circulation (Hallway)	Hallway from Teacher's Lounge to Classroom 210	W3	Chipping	2	N	N	0	N	N	Chipping @ Door
206	1250	1	2	H25	Circulation (Hallway)	Hallway from Teacher's Lounge to Classroom 210	W4	Cracking	5	N	N	0	Y - 24 SF Posters	N	2 Locations
207	1250	1	2	H26	Circulation (Hallway)	Hallway outside Classrooms 201-205	W1	Cracking	6	N	N	0	N	N	2 Locations
208	1250	1	2	H26	Circulation (Hallway)	Hallway outside Classrooms 201-205	W3	Cracking	10	N	N	0	N	N	5 Locations; Additional Chipping; Chipping on ACPI
209	1250	1	2	H26	Circulation (Hallway)	Hallway outside Classrooms 201-205	W4	Chipping	3	N	N	0	N	N	Chipping @ Door Frame
210	1250	1	2	207C	Circulation (Hallway)	Hallway to Office 207A	W2	Cracking	3	N	N	0	N	N	
211	1250	1	2	207A	Administrative Office	Office 207A	W3	Flaking	4	N	N	0	Y - 18 SF Cabinets, Tables	N	2 Locations; Additional Chipping; Damage @ Radiator & Wall
212	1250	1	2	S22	Stairs	Stairwell across from Classroom 202	Ceiling	Chipping	1	N	N	0	N	N	
213	1250	1	2	S22	Stairs	Stairwell across from Classroom 202	Center Banister	Chipping	96	N	N	0	N	N	
214	1250	1	2	S22	Stairs	Stairwell across from Classroom 202	W1	Chipping	4	N	N	0	N	N	
215	1250	1	2	S22	Stairs	Stairwell across from Classroom 202	W3	Chipping	6	N	N	0	N	N	3 Locations; Chipping @ Windows & ACPI
216	1250	1	2	S21	Stairs	Stairwell next to Classroom 204	W1	Flaking	30	N	N	0	N	N	3 Locations; Additional Cracking, Chipping; Damage Includes ACPI
217	1250	1	2	S21	Stairs	Stairwell next to Classroom 204	W3	Cracking	8	N	N	0	N	N	
218	1250	1	2	S23	Stairs	Stairwell next to Classroom 209	Ceiling	Cracking	3	N	N	0	N	N	
219	1250	1	2	S23	Stairs	Stairwell next to Classroom 209	W2	Cracking	8	N	N	0	N	N	
220	1250	1	2	S23	Stairs	Stairwell next to Classroom 209	W3	Cracking	6	N	N	0	N	N	Additional Chipping; Damage @ Window Frame
221	1250	1	2	S23	Stairs	Stairwell next to Classroom 209	W4	Cracking	4	N	N	0	N	N	
222	1250	1	2	206B	Storage	Storage Room 206B	W1	Chipping	1	N	N	0	Y - 36 SF Contents	N	
223	1250	1	2	206B	Storage	Storage Room 206B	W2	Partially Inaccessible		N	N	0	Y - 64 SF Shelves, Contents	N	
224	1250	1	2	206B	Storage	Storage Room 206B	W3	Flaking	2	N	N	0	Y - 72 SF Cabinets, Contents	N	Additional Chipping
225	1250	1	2	206B	Storage	Storage Room 206B	W4	Flaking	1	N	N	0	Y - 18 SF Tables, Boxes	N	Additional Gouges

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
226	1250	1	2	206F	Telecommunication Equipment Room	Storage Room 206B Telecommunication Equipment Room	Ceiling	Inaccessible							
227	1250	1	2	206F	Telecommunication Equipment Room	Storage Room 206B Telecommunication Equipment Room	Floor	Inaccessible							
228	1250	1	2	206F	Telecommunication Equipment Room	Storage Room 206B Telecommunication Equipment Room	W1	Inaccessible							
229	1250	1	2	206F	Telecommunication Equipment Room	Storage Room 206B Telecommunication Equipment Room	W2	Inaccessible							
230	1250	1	2	206F	Telecommunication Equipment Room	Storage Room 206B Telecommunication Equipment Room	W3	Inaccessible							
231	1250	1	2	206F	Telecommunication Equipment Room	Storage Room 206B Telecommunication Equipment Room	W4	Inaccessible							
232	1250	1	2	200	Teacher Lounge/Dining	Teacher's Lounge	Ceiling	Flaking	25	N	N	0	N	Y - 25 SF	Additional Holes; Suspended Ceiling
233	1250	1	2	200A	Kitchen	Teacher's Lounge Kitchen	W3	Cracking	1	N	N	0	Y - 16 SF Contents	N	
234	1250	1	1	110	Auditorium	Auditorium	Ceiling	Flaking	10	Y	N	0	N	Y - 4 SF	4 Locations; Additional Efflorescence, Cracking
235	1250	1	1	110	Auditorium	Auditorium	Floor	Flaking	30	N	Y - Around Perimeter	48	N	N	Additional Chipping; Damage around Perimeter
236	1250	1	1	110	Auditorium	Auditorium	W1	Flaking	34	N	N	0	N	Y - 1 SF	6 Locations; Additional Cracking
237	1250	1	1	110	Auditorium	Auditorium	W2	Flaking	4	N	N	0	N	Y - 1 SF	2 Locations - Additional Cracking, Holes
238	1250	1	1	110	Auditorium	Auditorium	W3	Flaking	14	Y	Y - Window Sill 1	2	N	Y - 2 SF	6 Locations; Additional Efflorescence, Cracking
239	1250	1	1	110	Auditorium	Auditorium	W4	Cracking	12	N	N	0	N	N	4 Locations
240	1250	1	1	107A	Student Restrooms - Male (4-12)	Boy's Restroom between Classrooms 106 and 107	W4	Flaking	1	N	N	0	N	N	Additional Holes
241	1250	1	1	102	Primary	Classroom 102	W2	Flaking	4	N	N	0	Y - 32 SF Shelves	N	2 Locations
242	1250	1	1	102	Primary	Classroom 102	W3	Flaking	2	N	N	0	Y - 28 SF Bookcases, Desks	N	Flaking @ Radiator Grate
243	1250	1	1	103	Primary	Classroom 103	W1	Partially Inaccessible		N	N	0	Y - 28 SF Posters	N	
244	1250	1	1	103	Primary	Classroom 103	W2	Partially Inaccessible		N	N	0	Y - 36 SF Desks, Contents	N	
245	1250	1	1	103	Primary	Classroom 103	W3	Flaking	5	N	N	0	None	Y - 2 SF Behind Mirror	Flaking @ Radiator
246	1250	1	1	103	Primary	Classroom 103	W4	Flaking	8	N	N	0	Y - 35 SF Posters	N	2 Locations; Additional Chipping; Teacher Says Additional Flaking/Chipping behind Wall Decals
247	1250	1	1	103A	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	W3	Cracking	4	N	N	0	N	N	2 Locations; Additional Chipping



Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
248	1250	1	1	104	Primary	Classroom 104	W1	Cracking	8	N	N	0	Y - 52 SF Cabinets, Posters	N	Flaking on ACPI
249	1250	1	1	104	Primary	Classroom 104	W2	Partially Inaccessible		N	N	0	Y - 105 SF - Bulletin Boards, Posters	N	
250	1250	1	1	104	Primary	Classroom 104	W3	Flaking	1	N	N	0	Y - 60 SF Bookcases, Contents	N	
251	1250	1	1	104	Primary	Classroom 104	W4	Chipping	1	N	N	0	Y - 52 SF Desks, Tables, Posters	N	
252	1250	1	1	105	Primary	Classroom 105	Ceiling	Cracking	8	N	N	0	N	N	2 Locations
253	1250	1	1	105	Primary	Classroom 105	W1	Chipping	2	N	N	0	Y - 32 SF Bookcases, Posters, Contents	N	Chipping @ Door
254	1250	1	1	105	Primary	Classroom 105	W3	Flaking	4	N	N	0	Y - 90 SF Bookcases, Desks	N	2 Locations; Flaking @ Radiator Grates
255	1250	1	1	105	Primary	Classroom 105	W4	Partially Inaccessible		N	N	0	Y - 96 SF Cabinets, Kitchen Appliances	N	
256	1250	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W2	Flaking	1	N	N	0	N	N	Flaking on ACPI
257	1250	1	1	106	Primary	Classroom 106	W1	Partially Inaccessible		N	N	0	Y - 48 SF Bookcases, Desks, Posters	N	
258	1250	1	1	106	Primary	Classroom 106	W2	Chipping	2	N	N	0	Y - 20 SF File Cabinets, Posters	N	
259	1250	1	1	106	Primary	Classroom 106	W3	Flaking	4	N	N	0	Y - 60 SF Desks, Tables	N	2 Locations; Including Radiators
260	1250	1	1	106	Primary	Classroom 106	W4	Chipping	1	N	N	0	Y - 55 SF Bookcases, Posters	N	
261	1250	1	1	107	Primary	Classroom 107	Ceiling	Flaking	3	N	N	0	N	N	2 Locations
262	1250	1	1	107	Primary	Classroom 107	W1	Flaking	8	N	N	0	Y - 18 SF Posters	N	Additional Cracking, Chipping
263	1250	1	1	107	Primary	Classroom 107	W2	Partially Inaccessible		N	N	0	Y - 48 SF Bookcases, Desks, Posters	N	
264	1250	1	1	107	Primary	Classroom 107	W3	Flaking	8	N	Y - Window Sill 1	1	N	N	4 Locations; Additional Chipping
265	1250	1	1	107	Primary	Classroom 107	W4	Gouges	1	N	N	0	N	N	
266	1250	1	1	108	Primary	Classroom 108	W1	Partially Inaccessible		N	N	0	Y - 102 SF Posters, Contents	N	
267	1250	1	1	108	Primary	Classroom 108	W2	Cracking	6	N	N	0	Y - 48 SF Posters, Contents	N	2 Locations
268	1250	1	1	108	Primary	Classroom 108	W3	Flaking	4	N	N	0	N	N	2 Locations; Including Radiator
269	1250	1	1	108	Primary	Classroom 108	W4	Partially Inaccessible		N	N	0	Y - 48 SF Posters, Contents	N	
270	1250	1	1	108A	Administrative Office	Dean of Students Office	W2	Partially Inaccessible		N	N	0	Y - 68 SF Cabinets, Contents		
271	1250	1	1	108A	Administrative Office	Dean of Students Office	W3	Partially Inaccessible		N	N	0	Y - 48 SF Desk, Cabinets		
272	1250	1	1	108A	Administrative Office	Dean of Students Office	W4	Partially Inaccessible		N	N	0	Y - 72 SF Posters, Cabinets, Contents		
273	1250	1	1	108J	Restrooms, Staff - Male/Female	Faculty Restroom adjacent to Counselor's Office	Ceiling	Flaking	16	N	N	0	N	Y - 16 SF	
274	1250	1	1	H13	Circulation (Hallway)	Hallway from Main Entrance to Classroom 108	Ceiling	Cracking	30	N	N	0	N	N	
275	1250	1	1	H13	Circulation (Hallway)	Hallway from Main Entrance to Classroom 108	W2	Cracking	28	N	N	0	N	N	Additional Chipping

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
276	1250	1	1	H13	Circulation (Hallway)	Hallway from Main Entrance to Classroom 108	W4	Cracking	8	N	N	0	N	N	
277	1250	1	1	H14	Circulation (Hallway)	Hallway from Main Office to Classroom 104	Ceiling	Flaking	16	N	N	0	N	N	3 Locations; Additional Cracking
278	1250	1	1	H14	Circulation (Hallway)	Hallway from Main Office to Classroom 104	W3	Cracking	6	N	N	0	N	N	2 Locations; Additional Chipping; Damage @ Wall & Door
279	1250	1	1	H14	Circulation (Hallway)	Hallway from Main Office to Classroom 104	W4	Chipping	3	N	N	0	N	N	
280	1250	1	1	106A	Circulation (Hallway)	Hallway outside Restrooms between Classrooms 106 and 107	W2	Flaking	3	N	N	0	N	Y - 1 SF	
281	1250	1	1	H13A	Circulation (Hallway)	Main Entrance Vestibule	W1	Cracking	2	N	N	0	N	N	
282	1250	1	1	H13A	Circulation (Hallway)	Main Entrance Vestibule	W4	Cracking	2	N	N	0	N	N	
283	1250	1	1	101	Administrative Office	Main Office	W1	Cracking	3	N	N	0	N	N	2 Locations; Additional Chipping
284	1250	1	1	101	Administrative Office	Main Office	W3	Flaking	3	N	N	0	N	N	Flaking @ Radiator Grate
285	1250	1	1	101	Administrative Office	Main Office	W4	Cracking	6	N	N	0	N	N	
286	1250	1	1	108B	Administrative Office	Nurse's Office	Ceiling	Flaking	12	N	N	0	N	N	2 Locations; Additional Cracking
287	1250	1	1	108B	Administrative Office	Nurse's Office	W2	Flaking	5	N	N	0	Y - 24 SF Cabinets	Y - 1 SF	3 Locations; Additional Cracking, Chipping
288	1250	1	1	108B	Administrative Office	Nurse's Office	W3	Cracking	2	N	N	0	N	N	
289	1250	1	1	108F	Student Restrooms - Male/Female	Nurse's Office Restroom	Ceiling	Flaking	4	N	N	0	N	N	Additional Cracking
290	1250	1	1	108F	Student Restrooms - Male/Female	Nurse's Office Restroom	W1	Cracking	2	N	N	0	N	N	
291	1250	1	1	108F	Student Restrooms - Male/Female	Nurse's Office Restroom	W2	Cracking	1	N	N	0	N	N	
292	1250	1	1	108F	Student Restrooms - Male/Female	Nurse's Office Restroom	W4	Chipping	1	N	N	0	N	N	
293	1250	1	1	100B	Conference Room	Principal's Conference Room	W1	Cracking	4	N	N	0	N	N	
294	1250	1	1	100B	Conference Room	Principal's Conference Room	W2	Partially Inaccessible		N	N	0	N	N	
295	1250	1	1	100B	Conference Room	Principal's Conference Room	W3	Cracking	6	N	N	0	N	N	Cracking on ACPI
296	1250	1	1	100B	Conference Room	Principal's Conference Room	W4	Cracking	5	N	N	0	Y - 20 SF Posters	N	
297	1250	1	1	100H	Storage	Principal's Conference Room Closet	Ceiling	Inaccessible							
298	1250	1	1	100H	Storage	Principal's Conference Room Closet	Floor	Inaccessible							
299	1250	1	1	100H	Storage	Principal's Conference Room Closet	W1	Inaccessible							
300	1250	1	1	100H	Storage	Principal's Conference Room Closet	W2	Inaccessible							
301	1250	1	1	100H	Storage	Principal's Conference Room Closet	W3	Inaccessible							
302	1250	1	1	100H	Storage	Principal's Conference Room Closet	W4	Inaccessible							
303	1250	1	1	100C	Restrooms, Staff - Male/Female	Principal's Conference Room Restroom	Ceiling	Inaccessible							
304	1250	1	1	100C	Restrooms, Staff - Male/Female	Principal's Conference Room Restroom	Floor	Inaccessible							
305	1250	1	1	100C	Restrooms, Staff - Male/Female	Principal's Conference Room Restroom	W1	Inaccessible							
306	1250	1	1	100C	Restrooms, Staff - Male/Female	Principal's Conference Room Restroom	W2	Inaccessible							

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
307	1250	1	1	100C	Restrooms, Staff - Male/Female	Principal's Conference Room Restroom	W3	Inaccessible							
308	1250	1	1	100C	Restrooms, Staff - Male/Female	Principal's Conference Room Restroom	W4	Inaccessible							
309	1250	1	1	100	Administrative Office	Principal's Office	Ceiling	Cracking	1	N	N	0	N	N	Cracking @ Window Lintel 2
310	1250	1	1	100	Administrative Office	Principal's Office	W3	Chipping	1	N	N	0	N	N	Chipping on ACPI
311	1250	1	1	100F	Storage	Principal's Office Closet adjacent to Hallway Junction	Ceiling	Inaccessible							
312	1250	1	1	100F	Storage	Principal's Office Closet adjacent to Hallway Junction	Floor	Inaccessible							
313	1250	1	1	100F	Storage	Principal's Office Closet adjacent to Hallway Junction	W1	Inaccessible							
314	1250	1	1	100F	Storage	Principal's Office Closet adjacent to Hallway Junction	W2	Inaccessible							
315	1250	1	1	100F	Storage	Principal's Office Closet adjacent to Hallway Junction	W3	Inaccessible							
316	1250	1	1	100F	Storage	Principal's Office Closet adjacent to Hallway Junction	W4	Inaccessible							
317	1250	1	1	100G	Storage	Principal's Office Closet closest to Main Office	Ceiling	Inaccessible							
318	1250	1	1	100G	Storage	Principal's Office Closet closest to Main Office	Floor	Inaccessible							
319	1250	1	1	100G	Storage	Principal's Office Closet closest to Main Office	W1	Inaccessible							
320	1250	1	1	100G	Storage	Principal's Office Closet closest to Main Office	W2	Inaccessible							
321	1250	1	1	100G	Storage	Principal's Office Closet closest to Main Office	W3	Inaccessible							
322	1250	1	1	100G	Storage	Principal's Office Closet closest to Main Office	W4	Inaccessible							
323	1250	1	1	100A	Storage	Principal's Office Large Closet adjacent to Main Entrance	Ceiling	Inaccessible							
324	1250	1	1	100A	Storage	Principal's Office Large Closet adjacent to Main Entrance	Floor	Inaccessible							
325	1250	1	1	100A	Storage	Principal's Office Large Closet adjacent to Main Entrance	W1	Inaccessible							
326	1250	1	1	100A	Storage	Principal's Office Large Closet adjacent to Main Entrance	W2	Inaccessible							
327	1250	1	1	100A	Storage	Principal's Office Large Closet adjacent to Main Entrance	W3	Inaccessible							
328	1250	1	1	100A	Storage	Principal's Office Large Closet adjacent to Main Entrance	W4	Inaccessible							
329	1250	1	1	100E	Storage	Principal's Office Small Closet adjacent to Main Entrance	Ceiling	Inaccessible							
330	1250	1	1	100E	Storage	Principal's Office Small Closet adjacent to Main Entrance	Floor	Inaccessible							
331	1250	1	1	100E	Storage	Principal's Office Small Closet adjacent to Main Entrance	W1	Inaccessible							
332	1250	1	1	100E	Storage	Principal's Office Small Closet adjacent to Main Entrance	W2	Inaccessible							
333	1250	1	1	100E	Storage	Principal's Office Small Closet adjacent to Main Entrance	W3	Inaccessible							
334	1250	1	1	100E	Storage	Principal's Office Small Closet adjacent to Main Entrance	W4	Inaccessible							

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
335	1250	1	1	110A	Stage	Stage	Ceiling	Flaking	13	N	N	0	N	N	2 Locations
336	1250	1	1	110A	Stage	Stage	Floor	Flaking	5	N	N	0	N	N	2 Locations; Additional Chipping
337	1250	1	1	110A	Stage	Stage	W2	Cracking	12	N	N	0	Y - 35 SF Contents	N	
338	1250	1	1	110A	Stage	Stage	W3	Cracking	30	N	N	0	N	N	
339	1250	1	1	110A	Stage	Stage	W4	Cracking	6	N	N	0	N	N	Additional Chipping
340	1250	1	1	S12	Stairs	Stairwell across from Main Office	Center Banister	Cracking	96	N	N	0	N	N	
341	1250	1	1	S12	Stairs	Stairwell across from Main Office	W2	Flaking	6	N	N	0	N	N	2 Locations
342	1250	1	1	S12	Stairs	Stairwell across from Main Office	W3	Chipping	7	N	N	0	N	N	2 Locations
343	1250	1	1	S12	Stairs	Stairwell across from Main Office	W4	Cracking	4	N	N	0	N	N	
344	1250	1	1	S11	Stairs	Stairwell next to Classroom 103	W1	Cracking	16	N	N	0	N	N	2 Locations; Additional Cracking
345	1250	1	1	S11	Stairs	Stairwell next to Classroom 103	W3	Flaking	14	N	N	0	N	N	Additional Cracking, Chipping; Damage on Wall & ACPI
346	1250	1	1	S11	Stairs	Stairwell next to Classroom 103	W4	Flaking	8	N	N	0	N	N	Additional Cracking; Damage Includes ACPI
347	1250	1	1	S13	Stairs	Stairwell next to Classroom 108	Ceiling	Cracking	8	N	N	0	N	N	
348	1250	1	1	S13	Stairs	Stairwell next to Classroom 108	W1	Cracking	2	N	N	0	N	N	
349	1250	1	1	S13	Stairs	Stairwell next to Classroom 108	W2	Flaking	10	N	N	0	N	N	3 Locations; Additional Cracking
350	1250	1	1	S13	Stairs	Stairwell next to Classroom 108	W3	Flaking	5	N	N	0	N	N	2 Locations; Additional Cracking, Chipping
351	1250	1	1	S13	Stairs	Stairwell next to Classroom 108	W4	Cracking	8	N	N	0	N	N	
352	1250	1	1	100D	Storage	Storage Room Across from Main Office	W1	Flaking	6	N	N	0	Y - 120 SF Shelves, Boxes	N	2 Locations
353	1250	1	1	100D	Storage	Storage Room Across from Main Office	W2	Partially Inaccessible		N	N	0	Y - 150 SF Shelves, Cabinets, Contents	N	
354	1250	1	1	100D	Storage	Storage Room Across from Main Office	W3	Partially Inaccessible		N	N	0	Y - 160 SF Shelves, Contents	N	
355	1250	1	1	100D	Storage	Storage Room Across from Main Office	W4	Holes	1	N	N	0	Y - 80 SF Shelves, Contents	N	
356	1250	1	1	107C	Storage	Storage Room between Classrooms 106 and 107	W1	Gouges	1	N	N	0	N	N	
357	1250	1	1	107C	Storage	Storage Room between Classrooms 106 and 107	W2	Partially Inaccessible		N	N	0	Y - 64 SF Shelves, Contents	N	
358	1250	1	1	107C	Storage	Storage Room between Classrooms 106 and 107	W3	Partially Inaccessible		N	N	0	Y - 64 SF Shelves, Contents	N	
359	1250	1	1	107C	Storage	Storage Room between Classrooms 106 and 107	W4	Partially Inaccessible		N	N	0	Y - 64 SF Shelves, Contents	N	
360	1250	1	0	H01A	Student Restrooms - Male (4-12)	Boy's Restroom across from Fan Room	Ceiling	Flaking	12	N	N	0	N	N	Additional Cracking
361	1250	1	0	H01A	Student Restrooms - Male (4-12)	Boy's Restroom across from Fan Room	W1	Chipping	4	N	N	0	N	N	Chipping @ Door
362	1250	1	0	002B	Cafeteria (Dining Area)	Cafeteria	Ceiling	Cracking	40	N	N	0	N	N	2 Locations
363	1250	1	0	002B	Cafeteria (Dining Area)	Cafeteria	W3	Cracking	16	N	N	0	N	N	
364	1250	1	0	015B	Storage	Cafeteria Storage Room	W2	Cracking	1	N	N	0	N	Y - 1 SF	
365	1250	1	0	015B	Storage	Cafeteria Storage Room	W3	Partially Inaccessible		N	N	0	N	N	
366	1250	1	0	015B	Storage	Cafeteria Storage Room	W4	Partially Inaccessible		N	N	0	N	N	
367	1250	1	0	001B	Gymnasium - Intermediate Middle	Gymnasium	Floor	Chipping	240	N	N	0	N	N	Around Perimeter
368	1250	1	0	001B	Gymnasium - Intermediate Middle	Gymnasium	W1	Flaking	4	N	N	0	N	N	2 Locations

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
369	1250	1	0	001B	Gymnasium - Intermediate Middle	Gymnasium	W2	Flaking	4	N	N	0	N	N	2 Locations; Flaking on Radiator Grates
370	1250	1	0	001B	Gymnasium - Intermediate Middle	Gymnasium	W3	Flaking	6	N	N	0	N	N	2 Locations; Flaking on Radiator Grates
371	1250	1	0	001B	Gymnasium - Intermediate Middle	Gymnasium	W4	Flaking	22	N	N	0	N	N	6 Locations; Additional Chipping; Damage on Radiators & ACPI
372	1250	1	0	001C	Administrative Office	Gymnasium Office/Equipment Storage	Ceiling	Inaccessible							
373	1250	1	0	001C	Administrative Office	Gymnasium Office/Equipment Storage	Floor	Inaccessible							
374	1250	1	0	001C	Administrative Office	Gymnasium Office/Equipment Storage	W1	Inaccessible							
375	1250	1	0	001C	Administrative Office	Gymnasium Office/Equipment Storage	W2	Inaccessible							
376	1250	1	0	001C	Administrative Office	Gymnasium Office/Equipment Storage	W3	Inaccessible							
377	1250	1	0	001C	Administrative Office	Gymnasium Office/Equipment Storage	W4	Inaccessible							
378	1250	1	0	H01	Circulation (Hallway)	Hallway from Boiler Room to Emergency Generator Room	Ceiling	Flaking	35	N	N	0	N	N	4 Locations; Additional Cracking
379	1250	1	0	H01	Circulation (Hallway)	Hallway from Boiler Room to Emergency Generator Room	Floor	Chipping	36	N	N	0	N	N	Chipping around Perimeter
380	1250	1	0	H01	Circulation (Hallway)	Hallway from Boiler Room to Emergency Generator Room	W2	Flaking	9	N	N	0	N	N	2 Locations; Additional Chipping; Damage @ Radiator & Door
381	1250	1	0	H01	Circulation (Hallway)	Hallway from Boiler Room to Emergency Generator Room	W3	Cracking	5	N	N	0	N	N	
382	1250	1	0	H01	Circulation (Hallway)	Hallway from Boiler Room to Emergency Generator Room	W4	Chipping	2	N	N	0	N	N	Chipping @ Door
383	1250	1	0	H02	Circulation (Hallway)	Hallway from Gym to Cafeteria	Ceiling	Cracking	30	N	N	0	N	N	3 Locations
384	1250	1	0	H02	Circulation (Hallway)	Hallway from Gym to Cafeteria	W1	Cracking	3	N	N	0	N	N	2 Locations
385	1250	1	0	H02A	Music	Music Room	Ceiling	Flaking	8	N	N	0	None	N	2 Locations
386	1250	1	0	H02A	Music	Music Room	W1	Cracking	12	N	N	0	Y - 72 SF Shelves	N	2 Locations
387	1250	1	0	H02A	Music	Music Room	W2	Cracking	4	N	N	0	Y - 65 SF Desks, Cabinets, Contents	N	
388	1250	1	0	H02A	Music	Music Room	W3	Flaking	16	N	N	0	N	N	2 Locations; Additional Cracking; Damage @ Duct & ACPI
389	1250	1	0	H02A	Music	Music Room	W4	Partially Inaccessible		N	N	0	Y - 24 SF Desks, Bookcases, Contents	N	
390	1250	1	0	S02	Stairs	Stairwell across from Cafeteria	Center Banister	Chipping	96	N	N	0	N	N	
391	1250	1	0	S02	Stairs	Stairwell across from Cafeteria	W1	Cracking	6	N	N	0	N	N	
392	1250	1	0	S02	Stairs	Stairwell across from Cafeteria	W2	Cracking	10	N	N	0	N	N	
393	1250	1	0	S02	Stairs	Stairwell across from Cafeteria	W4	Cracking	4	N	N	0	N	N	
394	1250	1	0	005B	Storage	Stairwell across from Cafeteria Storage Room	Ceiling	Inaccessible							
395	1250	1	0	005B	Storage	Stairwell across from Cafeteria Storage Room	Floor	Inaccessible							
396	1250	1	0	005B	Storage	Stairwell across from Cafeteria Storage Room	W1	Inaccessible							
397	1250	1	0	005B	Storage	Stairwell across from Cafeteria Storage Room	W2	Inaccessible							
398	1250	1	0	005B	Storage	Stairwell across from Cafeteria Storage Room	W3	Inaccessible							

