

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|--------------------------------|--|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------|
| 1 | 1470 | 1 | 3 | 300A | Storage | Book Storage adjacent to Classroom 300 | W4 | Flaking paint at conduits | 5 | N | Floor | 2 | | N | |
| 2 | 1470 | 1 | 3 | 311A | Storage | Book Storage adjacent to Classroom 313 | Ceiling | Flaking paint at ceiling and duct | 50 | N | | | | N | |
| 3 | 1470 | 1 | 3 | 300 | Computer - Intermediate Middle | Classroom 300 | Ceiling | Flaking paint by windows | 5 | N | | | | N | |
| 4 | 1470 | 1 | 3 | 300 | Computer - Intermediate Middle | Classroom 300 | W1 | Flaking paint in closet by ceiling, chipped paint at door casing. | 15 | N | | | | N | |
| 5 | 1470 | 1 | 3 | 301 | Primary | Classroom 301 | Ceiling | Flaking paint | 15 | N | | | | N | |
| 6 | 1470 | 1 | 3 | 301 | Primary | Classroom 301 | W1 | Flaking paint at closet pole, door casing, and cracking paint near ceiling. | 30 | N | | | | N | |
| 7 | 1470 | 1 | 3 | 301 | Primary | Classroom 301 | W3 | Flaking paint at column by windows | 1 | N | | | | N | |
| 8 | 1470 | 1 | 3 | 301 | Primary | Classroom 301 | W4 | Cracking paint | 1 | N | | | | N | |
| 9 | 1470 | 1 | 3 | 302 | Primary | Classroom 302 | Ceiling | Flaking paint | 15 | N | | | | N | |
| 10 | 1470 | 1 | 3 | 302 | Primary | Classroom 302 | W1 | Flaking paint at closet pole and door casing | 10 | N | | | | N | |
| 11 | 1470 | 1 | 3 | 302 | Primary | Classroom 302 | W2 | Flaking paint near ceiling | 10 | N | | | | N | |
| 12 | 1470 | 1 | 3 | 302 | Primary | Classroom 302 | W4 | Flaking paint near ceiling | 10 | N | | | | N | |
| 13 | 1470 | 1 | 3 | 303 | Primary | Classroom 303 | Ceiling | Flaking paint in closet, by W4 and by windows | 5 | N | | | | N | |
| 14 | 1470 | 1 | 3 | 303 | Primary | Classroom 303 | W1 | Flaking paint by entrance, closet pole, and door casing | 20 | N | | | | N | |
| 15 | 1470 | 1 | 3 | 303 | Primary | Classroom 303 | W3 | Flaking paint by blinds | 5 | N | | | | N | |
| 16 | 1470 | 1 | 3 | 303 | Primary | Classroom 303 | W4 | Flaking paint by entrance and by ceiling | 10 | N | | | | N | |
| 17 | 1470 | 1 | 3 | 304 | Primary | Classroom 304 | Ceiling | Flaking paint in closet | 5 | N | | | | N | |
| 18 | 1470 | 1 | 3 | 304 | Primary | Classroom 304 | W1 | Flaking paint at closet pole and door casing | 10 | N | | | | N | |
| 19 | 1470 | 1 | 3 | 304 | Primary | Classroom 304 | W2 | Flaking paint near ceiling | 1 | N | | | | N | |
| 20 | 1470 | 1 | 3 | 304 | Primary | Classroom 304 | W3 | Flaking paint below window sill | 2 | N | | | | N | |
| 21 | 1470 | 1 | 3 | 305 | Primary | Classroom 305 | Ceiling | Flaking paint | 50 | N | | | | N | |
| 22 | 1470 | 1 | 3 | 305 | Primary | Classroom 305 | W1 | Flaking paint at door casing, closet pole, and side of bulletin board | 15 | N | | | | N | |
| 23 | 1470 | 1 | 3 | 305 | Primary | Classroom 305 | W2 | Cracked paint at ceiling | 5 | N | | | | N | |
| 24 | 1470 | 1 | 3 | 305 | Primary | Classroom 305 | W3 | Flaking paint by bulletin board | 5 | N | | | | N | |
| 25 | 1470 | 1 | 3 | 308 | Primary | Classroom 308 | Ceiling | Flaking paint | 10 | N | | | | N | |
| 26 | 1470 | 1 | 3 | 308 | Primary | Classroom 308 | W1 | Flaking paint at closet pole and door casing | 10 | N | | | | N | |
| 27 | 1470 | 1 | 3 | 308 | Primary | Classroom 308 | W2 | Cracked paint near ceiling | 2 | N | | | | N | |

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|-----------------------|------------------------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------|
| 28 | 1470 | 1 | 3 | 308 | Primary | Classroom 308 | W3 | Flaking paint at column by windows | 5 | N | | | | N | |
| 29 | 1470 | 1 | 3 | 309 | Primary | Classroom 309 | Ceiling | Flaking paint throughout and in closet | 30 | N | | | | N | |
| 30 | 1470 | 1 | 3 | 309 | Primary | Classroom 309 | W1 | Flaking paint at closet pole and door casing | 10 | N | | | | N | |
| 31 | 1470 | 1 | 3 | 309 | Primary | Classroom 309 | W2 | Flaking paint by ceiling | 2 | N | | | | N | |
| 32 | 1470 | 1 | 3 | 309 | Primary | Classroom 309 | W3 | Flaking paint above window | 5 | N | | | | N | |
| 33 | 1470 | 1 | 3 | 309 | Primary | Classroom 309 | W4 | Cracked paint near ceiling | 2 | N | | | | N | |
| 34 | 1470 | 1 | 3 | 310 | Primary | Classroom 310 | Ceiling | Flaking paint throughout and in closet | 10 | N | | | | N | |
| 35 | 1470 | 1 | 3 | 310 | Primary | Classroom 310 | W1 | Flaking paint at closet pole and door casing | 10 | N | | | | N | |
| 36 | 1470 | 1 | 3 | 310 | Primary | Classroom 310 | W3 | Flaking paint at columns and behind blind | 10 | N | | | | N | |
| 37 | 1470 | 1 | 3 | 311 | Primary | Classroom 311 | Ceiling | Flaking paint throughout and in closet | 50 | N | | | | N | |
| 38 | 1470 | 1 | 3 | 311 | Primary | Classroom 311 | W1 | Flaking paint at closet pole and door casing | 10 | N | | | | N | |
| 39 | 1470 | 1 | 3 | 311 | Primary | Classroom 311 | W3 | Flaking paint to right of bulletin board | 2 | N | | | | N | |
| 40 | 1470 | 1 | 3 | 312 | Primary | Classroom 312 | Ceiling | Flaking paint throughout and in closet | 30 | N | | | | N | |
| 41 | 1470 | 1 | 3 | 312 | Primary | Classroom 312 | W1 | Flaking paint at door casing, baseboard, and closet pole | 20 | N | | | | N | |
| 42 | 1470 | 1 | 3 | 312 | Primary | Classroom 312 | W2 | Cracked paint near ceiling | 5 | N | | | | N | |
| 43 | 1470 | 1 | 3 | 312 | Primary | Classroom 312 | W3 | Flaking paint at column by windows | 5 | N | | | Stickers | N | |
| 44 | 1470 | 1 | 3 | 312 | Primary | Classroom 312 | W4 | Flaking paint above blackboard | 20 | N | | | | N | |
| 45 | 1470 | 1 | 3 | 313 | Primary | Classroom 313 | Ceiling | Flaking paint | 20 | N | | | | N | |
| 46 | 1470 | 1 | 3 | 313 | Primary | Classroom 313 | W1 | Flaking paint at door casing, baseboard, and closet pole | 20 | N | | | | N | |
| 47 | 1470 | 1 | 3 | 313 | Primary | Classroom 313 | W3 | Flaking paint at column between windows | 5 | N | | | | N | |
| 48 | 1470 | 1 | 3 | 313 | Primary | Classroom 313 | W4 | Cracked paint | 5 | N | | | | N | |
| 49 | 1470 | 1 | 3 | H37 | Circulation (Hallway) | Hallway Classrooms 300-313 | Ceiling | Flaking paint | 40 | N | | | | N | |
| 50 | 1470 | 1 | 3 | H37 | Circulation (Hallway) | Hallway Classrooms 300-313 | W1 | Flaking paint | 10 | N | | | | N | |
| 51 | 1470 | 1 | 3 | H37 | Circulation (Hallway) | Hallway Classrooms 300-313 | W3 | Flaking paint at wall, and at stairwell doors and door casings | 50 | N | | | Posters | N | |
| 52 | 1470 | 1 | 3 | S32 | Stairs | Stairway adjacent to Classroom 300 | Ceiling | Flaking paint at landing ceiling | 10 | Y | | | | N | |

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|---------------------------------|--|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------|
| 53 | 1470 | 1 | 3 | S32 | Stairs | Stairway adjacent to Classroom 300 | W1 | Flaking paint at doors | 15 | N | | | | N | |
| 54 | 1470 | 1 | 3 | S33 | Stairs | Stairway adjacent to Classroom 312 | Ceiling | Flaking paint | 20 | N | | | | N | |
| 55 | 1470 | 1 | 3 | S33 | Stairs | Stairway adjacent to Classroom 312 | W1 | Flaking paint at doors | 15 | N | | | | N | |
| 56 | 1470 | 1 | 2 | 200A | Storage | Book Storage adjacent to Classroom 200 | Ceiling | Flaking paint | 50 | N | | | | N | |
| 57 | 1470 | 1 | 2 | 200A | Storage | Book Storage adjacent to Classroom 200 | W4 | Flaking paint at conduits | 10 | N | Floor | 5 | | N | |
| 58 | 1470 | 1 | 2 | 212A | Storage | Book Storage adjacent to Classroom 212 | Ceiling | Flaking paint | 50 | N | | | | N | |
| 59 | 1470 | 1 | 2 | 212A | Storage | Book Storage adjacent to Classroom 212 | W1 | Flaking paint at conduit | 10 | | Floor | 5 | Boxes | N | |
| 60 | 1470 | 1 | 2 | 204A | Student Restrooms - Male (4-12) | Boy's Restroom | Ceiling | Flaking paint | 50 | N | | | | N | |
| 61 | 1470 | 1 | 2 | 200 | Primary | Classroom 200 | Ceiling | Flaking paint | 10 | N | | | | N | |
| 62 | 1470 | 1 | 2 | 200 | Primary | Classroom 200 | W1 | Flaking paint at closet pole | 5 | N | | | | N | |
| 63 | 1470 | 1 | 2 | 200 | Primary | Classroom 200 | W2 | Flaking paint near ceiling | 10 | N | | | | N | |
| 64 | 1470 | 1 | 2 | 200 | Primary | Classroom 200 | W3 | Flaking paint at column | 2 | N | | | | N | |
| 65 | 1470 | 1 | 2 | 201 | Primary | Classroom 201 | Ceiling | Flaking paint | 20 | N | | | | N | |
| 66 | 1470 | 1 | 2 | 201 | Primary | Classroom 201 | W1 | Flaking paint at door casing and closet pole | 10 | N | | | | N | |
| 67 | 1470 | 1 | 2 | 201 | Primary | Classroom 201 | W2 | Flaking paint at conduit | 2 | N | | | | N | |
| 68 | 1470 | 1 | 2 | 201 | Primary | Classroom 201 | W3 | Cracked paint below window sill | 3 | N | | | | N | |
| 69 | 1470 | 1 | 2 | 201 | Primary | Classroom 201 | W4 | Flaking paint | 5 | N | | | Bookshelf, posters | N | |
| 70 | 1470 | 1 | 2 | 202 | Primary | Classroom 202 | Ceiling | Flaking paint in closet | 10 | N | | | | N | |
| 71 | 1470 | 1 | 2 | 202 | Primary | Classroom 202 | W1 | Flaking paint at door casing and closet pole | 10 | N | | | | N | |
| 72 | 1470 | 1 | 2 | 202 | Primary | Classroom 202 | W2 | Flaking paint above blackboard | 10 | N | | | Posters | N | |
| 73 | 1470 | 1 | 2 | 202 | Primary | Classroom 202 | W3 | Flaking paint above windows and at column | 15 | N | | | | N | |
| 74 | 1470 | 1 | 2 | 202 | Primary | Classroom 202 | W4 | Flaking paint | 5 | N | | | | N | |
| 75 | 1470 | 1 | 2 | 203 | Primary | Classroom 203 | W1 | Flaking paint at door casing and closet pole | 10 | N | | | | N | |
| 76 | 1470 | 1 | 2 | 203 | Primary | Classroom 203 | W2 | Flaking paint | 2 | N | | | | N | |
| 77 | 1470 | 1 | 2 | 203 | Primary | Classroom 203 | W3 | Flaking paint at column | 2 | N | | | Posters | N | |
| 78 | 1470 | 1 | 2 | 203 | Primary | Classroom 203 | W4 | Flaking paint at conduit | 5 | N | | | | N | |
| 79 | 1470 | 1 | 2 | 204 | Primary | Classroom 204 | Ceiling | Flaking paint in closet and by W4 | 15 | N | | | | N | |
| 80 | 1470 | 1 | 2 | 204 | Primary | Classroom 204 | W1 | Flaking paint at door casing and closet pole | 10 | N | | | | N | |
| 81 | 1470 | 1 | 2 | 204 | Primary | Classroom 204 | W3 | Flaking paint by windows | 2 | N | | | Posters | N | |

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|-----------------------------------|----------------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------|
| 82 | 1470 | 1 | 2 | 204 | Primary | Classroom 204 | W4 | Flaking paint at conduit | 5 | N | | | | N | |
| 83 | 1470 | 1 | 2 | 208 | Primary | Classroom 208 | Ceiling | Flaking paint | 20 | N | | | | N | |
| 84 | 1470 | 1 | 2 | 208 | Primary | Classroom 208 | W1 | Flaking paint at door casing and wall | 20 | N | | | | N | |
| 85 | 1470 | 1 | 2 | 208 | Primary | Classroom 208 | W2 | Flaking paint at wall and conduit | 5 | N | | | | N | |
| 86 | 1470 | 1 | 2 | 208 | Primary | Classroom 208 | W3 | Flaking paint by bulletin board | 5 | N | | | | N | |
| 87 | 1470 | 1 | 2 | 208 | Primary | Classroom 208 | W4 | Flaking paint | 5 | N | | | | N | |
| 88 | 1470 | 1 | 2 | 209 | Primary | Classroom 209 | Ceiling | Flaking paint | 20 | N | | | | N | |
| 89 | 1470 | 1 | 2 | 209 | Primary | Classroom 209 | W1 | Flaking paint at closet pole | 5 | N | | | | N | |
| 90 | 1470 | 1 | 2 | 209 | Primary | Classroom 209 | W3 | Cracked paint by window sill | 1 | N | | | | N | |
| 91 | 1470 | 1 | 2 | 210 | Primary | Classroom 210 | Ceiling | Flaking paint in closet | 5 | N | | | | N | |
| 92 | 1470 | 1 | 2 | 210 | Primary | Classroom 210 | W1 | Flaking paint | 10 | N | | | | N | |
| 93 | 1470 | 1 | 2 | 210 | Primary | Classroom 210 | W3 | Flaking paint | 5 | N | | | | N | |
| 94 | 1470 | 1 | 2 | 210 | Primary | Classroom 210 | W4 | Flaking paint | 10 | N | | | | N | |
| 95 | 1470 | 1 | 2 | 211 | Primary | Classroom 211 | Ceiling | Flaking paint in closet and throughout | 40 | N | | | | N | |
| 96 | 1470 | 1 | 2 | 211 | Primary | Classroom 211 | W1 | Flaking paint at door casing, closet pole, and wall | 15 | N | | | | N | |
| 97 | 1470 | 1 | 2 | 211 | Primary | Classroom 211 | W2 | Flaking paint by W3 | 2 | N | | | | N | |
| 98 | 1470 | 1 | 2 | 211 | Primary | Classroom 211 | W3 | Flaking paint by bulletin board | 10 | N | | | | N | |
| 99 | 1470 | 1 | 2 | 212 | Primary | Classroom 212 | Ceiling | Flaking paint | 25 | N | | | | N | |
| 100 | 1470 | 1 | 2 | 212 | Primary | Classroom 212 | W1 | Flaking paint at door casing | 5 | N | | | | N | |
| 101 | 1470 | 1 | 2 | 212 | Primary | Classroom 212 | W3 | Flaking paint at radiator and column | 15 | N | | | | N | |
| 102 | 1470 | 1 | 2 | 212 | Primary | Classroom 212 | W4 | Flaking paint near ceiling | 10 | N | | | | N | |
| 103 | 1470 | 1 | 2 | 213 | Primary | Classroom 213 | Ceiling | Flaking paint in closet and throughout | 25 | N | | | | N | |
| 104 | 1470 | 1 | 2 | 213 | Primary | Classroom 213 | W1 | Flaking paint at door casing, closet pole, and at wall by W2 | 15 | N | | | | N | |
| 105 | 1470 | 1 | 2 | 213 | Primary | Classroom 213 | W3 | Flaking paint by W2, by ceiling, and at radiator | 15 | N | | | | N | |
| 106 | 1470 | 1 | 2 | 207 | Administrative Office | Counselor's Office | W1 | Flaking paint | 5 | N | | | | N | |
| 107 | 1470 | 1 | 2 | 208A | Student Restrooms - Female (4-12) | Girl's Restroom | Ceiling | Flaking paint | 50 | N | | | | N | |
| 108 | 1470 | 1 | 2 | H26 | Circulation (Hallway) | Hallway Classrooms 200-213 | W1 | Flaking paint | 10 | N | | | | N | |
| 109 | 1470 | 1 | 2 | H26 | Circulation (Hallway) | Hallway Classrooms 200-213 | W3 | Flaking paint at wall, and at stairwell doors and door casings | 50 | N | | | Posters | N | |
| 110 | 1470 | 1 | 2 | 205 | Administrative Office | Room 205 School Police | Ceiling | Flaking paint in closet | 20 | N | | | | N | |
| 111 | 1470 | 1 | 2 | 205 | Administrative Office | Room 205 School Police | W1 | Flaking paint at door casing and closet pole | 10 | N | | | | N | |

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|---------------------------------|--|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------|
| 112 | 1470 | 1 | 2 | 205 | Administrative Office | Room 205 School Police | W3 | Cracked paint below sill | 5 | N | | | | N | |
| 113 | 1470 | 1 | 2 | 205 | Administrative Office | Room 205 School Police | W4 | Flaking paint at conduit | 5 | N | | | Desks, Bookshelves | N | |
| 114 | 1470 | 1 | 2 | S22 | Stairs | Stairs adjacent to Classroom 200 | W1 | Flaking paint at doors | 15 | N | | | | N | |
| 115 | 1470 | 1 | 2 | S23 | Stairs | Stairs adjacent to Classroom 212 | W1 | Flaking paint at doors | 15 | N | | | | N | |
| 116 | 1470 | 1 | 2 | 201A | Storage | Storage Room adjacent to Classroom 201 | Ceiling | Flaking paint | 5 | N | | | | N | |
| 117 | 1470 | 1 | 2 | 201A | Storage | Storage Room adjacent to Classroom 201 | W2 | Flaking paint | 2 | N | | | Cabinet | N | |
| 118 | 1470 | 1 | 1 | AUD | Auditorium | Auditorium | W2 | Flaking paint | 80 | Y | | | | N | |
| 119 | 1470 | 1 | 1 | AUD | Auditorium | Auditorium | W4 | Flaking paint | 20 | N | | | | N | |
| 120 | 1470 | 1 | 1 | STAGE | Stage | Auditorium Stage | W3 | Flaking paint | 30 | Y | | | | N | |
| 121 | 1470 | 1 | 1 | 101A | Storage | Book Storage adjacent to Classroom 101 | Ceiling | Flaking paint | 10 | N | | | | N | |
| 122 | 1470 | 1 | 1 | 112A | Storage | Book Storage adjacent to Classroom 112 | Ceiling | Flaking paint | 20 | N | | | | N | |
| 123 | 1470 | 1 | 1 | 112A | Storage | Book Storage adjacent to Classroom 112 | W2 | Flaking paint at conduits | 20 | N | Floor | 5 | | N | |
| 124 | 1470 | 1 | 1 | 102C | Student Restrooms - Male (4-12) | Boy's Restroom | Ceiling | Flaking paint | 20 | N | | | | N | |
| 125 | 1470 | 1 | 1 | 100 | Primary | Classroom 100 | Ceiling | Flaking paint by W3, W4 and window | 10 | N | | | | N | |
| 126 | 1470 | 1 | 1 | 100 | Primary | Classroom 100 | W3 | Flaking paint by window | 5 | N | | | | N | |
| 127 | 1470 | 1 | 1 | 101 | Primary | Classroom 101 | Ceiling | Flaking paint throughout and at support beam in closet | 30 | N | | | | N | |
| 128 | 1470 | 1 | 1 | 102 | Primary | Classroom 102 | Ceiling | Flaking paint | 20 | N | | | | N | |
| 129 | 1470 | 1 | 1 | 102 | Primary | Classroom 102 | W3 | Flaking paint by window 1 and by bulletin board | 15 | N | | | | N | |
| 130 | 1470 | 1 | 1 | 103 | Primary | Classroom 103 | W1 | Flaking paint by ceiling | 10 | N | | | | N | |
| 131 | 1470 | 1 | 1 | 105 | Music | Classroom 105 | Ceiling | Flaking paint | 20 | N | | | | N | |
| 132 | 1470 | 1 | 1 | 105 | Music | Classroom 105 | W1 | Flaking paint by closet | 5 | N | | | | N | |
| 133 | 1470 | 1 | 1 | 109 | Primary | Classroom 109 | Ceiling | Flaking paint | 30 | N | | | | N | |
| 134 | 1470 | 1 | 1 | 111 | Primary | Classroom 111 | Ceiling | Flaking paint | 20 | N | | | | N | |
| 135 | 1470 | 1 | 1 | 111 | Primary | Classroom 111 | W3 | Flaking paint above window 7 | 5 | N | | | | N | |
| 136 | 1470 | 1 | 1 | 112 | Primary | Classroom 112 | Ceiling | Flaking paint | 20 | N | | | | N | |
| 137 | 1470 | 1 | 1 | 112 | Primary | Classroom 112 | W1 | Cracked paint at door | 1 | N | | | | N | |
| 138 | 1470 | 1 | 1 | 115 | Primary | Classroom 115 | Ceiling | Flaking paint | 10 | N | | | | N | |

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------------------------------|--|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------|
| 139 | 1470 | 1 | 1 | 115 | Primary | Classroom 115 | W3 | Flaking paint by bulletin board and column | 10 | N | | | | N | |
| 140 | 1470 | 1 | 1 | 117 | Primary | Classroom 117 | Ceiling | Flaking paint | 25 | N | | | | N | |
| 141 | 1470 | 1 | 1 | 117 | Primary | Classroom 117 | W2 | Flaking paint at door casing | 5 | N | | | | N | |
| 142 | 1470 | 1 | 1 | 117 | Primary | Classroom 117 | W3 | Flaking paint by window 5 | 2 | N | | | | N | |
| 143 | 1470 | 1 | 1 | 117A | Storage | Classroom 117 Closet | Ceiling | Flaking paint | 10 | N | | | | N | |
| 144 | 1470 | 1 | 1 | 116A | Administrative Office | Copy Room in Main Office (next to Nurse's Office) | W4 | Cracked paint | 2 | N | | | | N | |
| 145 | 1470 | 1 | 1 | 116A | Administrative Office | Copy Room in Main Office (next to Nurse's Office) | W1 | Flaking paint at door casing | 5 | N | | | | N | |
| 146 | 1470 | 1 | 1 | 108B | Student Restrooms - Female (4-12) | Girl's Restroom | Ceiling | Flaking paint | 20 | N | | | | N | |
| 147 | 1470 | 1 | 1 | GYM/CAF | Cafeterium (Cafeteria / Gymnasium) | Gymnasium/Cafeteria | W1 | Flaking paint at door casings | 10 | N | | | | N | |
| 148 | 1470 | 1 | 1 | 123 | Student Restrooms - Male (4-12) | Gymnasium/Cafeteria Boy's Restroom | W2 | Flaking paint at pipe chase door | 10 | N | | | | N | |
| 149 | 1470 | 1 | 1 | 123GRR | Student Restrooms - Female (4-12) | Gymnasium/Cafeteria Girl's Restroom | W2 | Flaking paint | 10 | N | | | | N | |
| 150 | 1470 | 1 | 1 | H11 | Circulation (Hallway) | Hallway Classroom 103 to Stage | W2 | Flaking paint | 20 | N | | | | N | |
| 151 | 1470 | 1 | 1 | H11 | Circulation (Hallway) | Hallway Classroom 103 to Stage | W4 | Flaking paint | 10 | N | | | | N | |
| 152 | 1470 | 1 | 1 | H13 | Circulation (Hallway) | Hallway Classroom 111 to Gym | W2 | Flaking paint | 30 | N | | | | N | |
| 153 | 1470 | 1 | 1 | H13 | Circulation (Hallway) | Hallway Classroom 111 to Gym | W4 | Flaking paint | 30 | N | | | | N | |
| 154 | 1470 | 1 | 1 | H14 | Circulation (Hallway) | Hallway Classrooms 100-112 | W1 | Flaking paint | 20 | N | | | | N | |
| 155 | 1470 | 1 | 1 | H14 | Circulation (Hallway) | Hallway Classrooms 100-112 | W3 | Flaking paint at wall and stairwell doors | 70 | N | | | | N | |
| 156 | 1470 | 1 | 1 | H15 | Circulation (Hallway) | Hallway Gym to Stage | W1 | Flaking paint at baseboards | 20 | N | | | | N | |
| 157 | 1470 | 1 | 1 | H16 | Circulation (Hallway) | Hallway Teacher's Lounge to just past Women's Restroom | W2 | Flaking paint | 20 | N | | | | N | |
| 158 | 1470 | 1 | 1 | H16 | Circulation (Hallway) | Hallway Teacher's Lounge to just past Women's Restroom | W4 | Flaking paint | 20 | N | | | | N | |

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|-------------------------|--------------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------|
| 159 | 1470 | 1 | 1 | 108/110 | IMC (Library) | IMC | W1 | Flaking paint at walls and door casings | 20 | N | | | | N | |
| 160 | 1470 | 1 | 1 | 108/110 | IMC (Library) | IMC | W2 | Flaking paint | 5 | N | | | | N | |
| 161 | 1470 | 1 | 1 | 108/110 | IMC (Library) | IMC | W3 | Flaking paint | 10 | N | | | | N | |
| 162 | 1470 | 1 | 1 | 108D | Administrative Office | IMC Office | W1 | Flaking paint at door casing | 10 | N | | | | N | |
| 163 | 1470 | 1 | 1 | 108D | Administrative Office | IMC Office | W3 | Flaking paint at soap dispenser | 1 | N | | | | N | |
| 164 | 1470 | 1 | 1 | 108D | Administrative Office | IMC Office | W4 | Flaking paint by window | 1 | N | | | | N | |
| 165 | 1470 | 1 | 1 | 121C | Kitchen | Kitchen | Ceiling | Flaking paint | 10 | N | | | | N | |
| 166 | 1470 | 1 | 1 | 121C | Kitchen | Kitchen | W3 | Flaking paint | 10 | N | | | | N | |
| 167 | 1470 | 1 | 1 | 121C | Kitchen | Kitchen | W1 | Flaking paint | 10 | N | | | | N | |
| 168 | 1470 | 1 | 1 | 121A | Storage | Kitchen Storage | W1 | Flaking paint at door casings | 10 | N | | | | N | |
| 169 | 1470 | 1 | 1 | H15B | Circulation (Hallway) | Main Entrance Foyer | Ceiling | Flaking paint | 5 | N | | | | N | |
| 170 | 1470 | 1 | 1 | H15B | Circulation (Hallway) | Main Entrance Foyer | W3 | Flaking paint | 5 | N | | | | N | |
| 171 | 1470 | 1 | 1 | H15B | Circulation (Hallway) | Main Entrance Foyer | W4 | Flaking paint | 5 | N | | | | N | |
| 172 | 1470 | 1 | 1 | H15A | Circulation (Hallway) | Main Lobby | Ceiling | Flaking paint | 30 | N | | | | N | |
| 173 | 1470 | 1 | 1 | H15A | Circulation (Hallway) | Main Lobby | W1 | Flaking paint at baseboards | 5 | N | | | | N | |
| 174 | 1470 | 1 | 1 | H15A | Circulation (Hallway) | Main Lobby | W2 | Flaking paint at baseboards and wall | 10 | N | | | | N | |
| 175 | 1470 | 1 | 1 | H15A | Circulation (Hallway) | Main Lobby | W4 | Flaking paint at baseboards and wall | 10 | N | | | | N | |
| 176 | 1470 | 1 | 1 | 116 | Administrative Office | Main Office | W1 | Flaking paint at door casings, wall, and on reception desk | 30 | N | | | | N | |
| 177 | 1470 | 1 | 1 | 116F | Storage | Main Office Storage Room | W1 | Flaking paint | 10 | N | | | | N | |
| 178 | 1470 | 1 | 1 | 116F | Storage | Main Office Storage Room | W2 | Flaking paint | 10 | N | | | | N | |
| 179 | 1470 | 1 | 1 | 118A | Restrooms, Staff - Male | Men's Restroom | Ceiling | Flaking paint | 10 | N | | | | N | |
| 180 | 1470 | 1 | 1 | 118A | Restrooms, Staff - Male | Men's Restroom | W1 | Flaking paint | 40 | N | | | | N | |
| 181 | 1470 | 1 | 1 | 118A | Restrooms, Staff - Male | Men's Restroom | W2 | Flaking paint | 20 | N | | | | N | |
| 182 | 1470 | 1 | 1 | 118A | Restrooms, Staff - Male | Men's Restroom | W3 | Flaking paint at wall and radiator | 20 | N | | | | N | |
| 183 | 1470 | 1 | 1 | 118A | Restrooms, Staff - Male | Men's Restroom | W4 | Flaking paint | 10 | N | | | | N | |

