

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	8160	1	UL	204	Intermediate/Middle		W1	Chipping	4	N	N	0	N	N	
2	8160	1	UL	204	Intermediate/Middle		W2	Flaking	16	N	N	0	N	N	Chipping @ Door Frame
3	8160	1	UL	204	Intermediate/Middle		W4	Partially Inaccessible	0	N	N	0	Y - 72 SF Desks, Computers, Cabinets	N	Inspection Required
4	8160	1	UL	204	Intermediate/Middle		W5	Partially Inaccessible	0	N	N	0	Y - 98 SF Cabinets, Boxes, Contents	N	Inspection Required
5	8160	1	UL	A200	Administrative Office		W1	Cracking	10	N	N	0	N	N	
6	8160	1	UL	A200	Administrative Office		W2	Cracking	8	N	N	0	N	N	
7	8160	1	UL	A200	Administrative Office		W3	Cracking	10	N	N	0	N	N	
8	8160	1	UL	A200	Administrative Office		W4	Cracking	8	N	N	0	N	N	
9	8160	1	UL	A200A	Storage		W2	Cracking	8	N	N	0	N	N	Cracking @ Corners
10	8160	1	UL	A200A	Storage		W3	Cracking	8	N	N	0	N	N	Cracking @ Corners
11	8160	1	UL	A200A	Storage		W4	Cracking	8	N	N	0	N	N	Cracking @ Corners
12	8160	1	UL	A200B	Storage		W2	Cracking	8	N	N	0	N	N	Cracking @ Corners
13	8160	1	UL	A200B	Storage		W3	Cracking	8	N	N	0	N	N	Cracking @ Corners
14	8160	1	UL	A200B	Storage		W4	Cracking	8	N	N	0	N	N	Cracking @ Corners
15	8160	1	UL	A201	Intermediate/Middle		W1	Flaking	12	N	N	0	N	N	
16	8160	1	UL	A201	Intermediate/Middle		W2	Flaking	16	N	N	0	N	N	
17	8160	1	UL	A201	Intermediate/Middle		W3	Flaking	20	N	N	0	N	N	
18	8160	1	UL	A201	Intermediate/Middle		W4	Flaking	48	N	N	0	N	N	
19	8160	1	UL	A201	Intermediate/Middle		W5	Flaking	36	N	N	0	N	N	
20	8160	1	UL	A202	Intermediate/Middle		W1	Flaking	24	N	N	0	N	N	
21	8160	1	UL	A202	Intermediate/Middle		W2	Flaking	16	N	N	0	N	N	
22	8160	1	UL	A202	Intermediate/Middle		W3	Flaking	40	N	N	0	N	N	
23	8160	1	UL	A202	Intermediate/Middle		W4	Flaking	90	N	N	0	N	N	
24	8160	1	UL	A202	Intermediate/Middle		W5	Flaking	50	N	N	0	N	N	
25	8160	1	UL	A204	Student Restrooms - Female (4-12)		Ceiling	Flaking	24	N	N	0	N	N	Additional Cracking
26	8160	1	UL	A205	Restrooms, Staff - Male		Ceiling	Cracking	16	N	N	0	N	N	
27	8160	1	UL	A206	Student Restrooms - Male (4-12)		Ceiling	Cracking	8	N	N	0	N	N	

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
28	8160	1	UL	A207	General Administrative Space		W4	Flaking	4	N	N	0	Y - 40 SF Bookcases, Cabinets, Contents	N	Additional Chipping
29	8160	1	UL	A207	General Administrative Space		W2	Partially Inaccessible	0	N	N	0	Y - 24 SF Desks, Contents	N	Inspection Required
30	8160	1	UL	A207	General Administrative Space		W3	Partially Inaccessible	0	N	N	0	Y - 20 SF Posters	N	Inspection Required
31	8160	1	UL	A208	Administrative Office		W4	Flaking	80	N	N	0	N	N	
32	8160	1	UL	A208A	Student Restrooms - Male/Female		W2	Cracking	8	N	N	0	N	N	
33	8160	1	UL	A208A	Student Restrooms - Male/Female		W3	Cracking	8	N	N	0	N	N	
34	8160	1	UL	A210	Administrative Office		W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
35	8160	1	UL	A210	Administrative Office		W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
36	8160	1	UL	A210	Administrative Office		W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
37	8160	1	UL	A210	Administrative Office		W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
38	8160	1	UL	A210	Administrative Office		Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
39	8160	1	UL	A210	Administrative Office		Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
40	8160	1	UL	A211	Administrative Office		W1	Flaking	10	N	N	0	N	N	
41	8160	1	UL	A211	Administrative Office		W2	Flaking	32	N	N	0	N	N	
42	8160	1	UL	A211	Administrative Office		W3	Flaking	24	N	N	0	N	N	
43	8160	1	UL	A211	Administrative Office		W4	Flaking	16	N	N	0	N	N	
44	8160	1	UL	A212	Administrative Office		W1	Flaking	30	N	N	0	N	N	
45	8160	1	UL	A212	Administrative Office		W2	Flaking	90	N	N	0	N	N	
46	8160	1	UL	A212	Administrative Office		W3	Flaking	45	N	N	0	N	N	
47	8160	1	UL	A216	Administrative Office		W1	Chipping	8	N	N	0	Y - 24 SF Desks, Bookcases, Contents	N	
48	8160	1	UL	A216	Administrative Office		W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks, Contents	N	Inspection Required

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
49	8160	1	UL	A216	Administrative Office		W3	Partially Inaccessible	0	N	N	0	Y - 36 SF Desks, Bookcases, Contents	N	Inspection Required
50	8160	1	UL	A216	Administrative Office		W4	Partially Inaccessible	0	N	N	0	Y - 24 SF Desks, Bookcases, Contents	N	Inspection Required
51	8160	1	UL	A218	Administrative Office		W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
52	8160	1	UL	A218	Administrative Office		W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
53	8160	1	UL	A218	Administrative Office		W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
54	8160	1	UL	A218	Administrative Office		W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
55	8160	1	UL	A218	Administrative Office		Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
56	8160	1	UL	A218	Administrative Office		Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
57	8160	1	UL	A220	Restrooms, Staff - Male/Female		W4	Chipping	4	N	N	0	N	N	
58	8160	1	UL	A222	Administrative Office		W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
59	8160	1	UL	A222	Administrative Office		W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
60	8160	1	UL	A222	Administrative Office		W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
61	8160	1	UL	A222	Administrative Office		W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
62	8160	1	UL	A222	Administrative Office		Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
63	8160	1	UL	A222	Administrative Office		Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
64	8160	1	UL	A240	Intermediate/Middle		W4	Chipping	4	N	N	0	N	N	
65	8160	1	UL	A240A	Storage		W5	Cracking	8	N	N	0	N	N	
66	8160	1	UL	A240A	Storage		W1	Partially Inaccessible	0	N	N	0	Y - 16 SF Shelves, Contents	N	Inspection Required
67	8160	1	UL	A240A	Storage		W2	Partially Inaccessible	0	N	N	0	Y - 24 SF Shelves, Contents	N	Inspection Required
68	8160	1	UL	A240A	Storage		W3	Partially Inaccessible	0	N	N	0	Y - 32 SF Contents	N	Inspection Required
69	8160	1	UL	A240A	Storage		W4	Partially Inaccessible	0	N	N	0	Y - 16 SF Shelves, Contents	N	Inspection Required
70	8160	1	UL	H117	Circulation (Hallway)		W1	Chipping	10	N	N	0	N	N	Chipping Near Floor & On Columns
71	8160	1	UL	H117	Circulation (Hallway)		W3	Chipping	12	N	N	0	N	N	Chipping Near Floor & On Columns
72	8160	1	UL	H118	Circulation (Hallway)		W1	Chipping	10	N	N	0	N	N	Chipping Near Floor & On Columns

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
73	8160	1	UL	H118	Circulation (Hallway)		W3	Chipping	12	N	N	0	N	N	Chipping Near Floor & On Columns
74	8160	1	UL	S112	Stairs		Center Banister	Chipping	20	N	N	0	N	N	
75	8160	1	UL	S112	Stairs		W2	Cracking	8	N	N	0	N	N	
76	8160	1	UL	S112	Stairs		W1	Flaking	16	Y	N	0	N	N	Ceiling Leaks
77	8160	1	UL	S112	Stairs		Ceiling	Flaking	0	Y	N	0	N	N	
78	8160	1	UL	S113	Stairs		W2	Cracking	8	N	N	0	N	N	
79	8160	1	UL	S113	Stairs		W4	Holes	1	N	N	0	N	N	
80	8160	1	UL	S114	Stairs		Center Banister	Chipping	20	N	N	0	N	N	
81	8160	1	UL	S114	Stairs		W1	Cracking	16	Y	N	0	N	N	
82	8160	1	UL	S114	Stairs		W2	Cracking	10	N	N	0	N	N	
83	8160	1	UL	S114	Stairs		W3	Cracking	8	N	N	0	N	N	
84	8160	1	UL	S114	Stairs		W4	Cracking	20	N	N	0	N	N	
85	8160	1	UL	S114	Stairs		Ceiling	Cracking	40	N	N	0	N	N	Ceiling Leaks
86	8160	1	ML	A102	Student Restrooms - Female (4-12)		W2	Flaking	12	N	N	0	N	N	
87	8160	1	ML	A117	Music		W1	Flaking	40	N	N	0	N	N	Additional Cracking, Chipping
88	8160	1	ML	A117	Music		W2	Flaking	16	N	N	0	N	N	Additional Cracking, Chipping
89	8160	1	ML	A117	Music		W3	Flaking	50	N	N	0	N	N	Additional Cracking, Chipping
90	8160	1	ML	A117	Music		W4	Flaking	12	N	N	0	N	N	Additional Cracking, Chipping
91	8160	1	ML	A118	Music		W1	Chipping	16	N	N	0	N	N	
92	8160	1	ML	A118	Music		W3	Chipping	12	N	N	0	N	N	
93	8160	1	ML	A118	Music		W2	Cracking	10	N	N	0	N	N	
94	8160	1	ML	A118	Music		W4	Cracking	16	N	N	0	N	N	
95	8160	1	ML	A120	Music		W3	Flaking	5	Y	N	0	N	N	Additional Efflorescence
96	8160	1	ML	A126	Computer - Intermediate Middle		W3	Chipping	20	N	N	0	N	N	
97	8160	1	ML	A126	Computer - Intermediate Middle		W1	Flaking	28	N	N	0	N	N	
98	8160	1	ML	A126	Computer - Intermediate Middle		W2	Flaking	20	N	N	0	N	N	
99	8160	1	ML	A127	Computer - Intermediate Middle		W1	Cracking	28	N	N	0	Y - 28 SF Contents, Desks, Computers	N	
100	8160	1	ML	A127	Computer - Intermediate Middle		W2	Cracking	36	N	N	0	Y - 32 SF Contents, Desks, Computers	N	
101	8160	1	ML	A127	Computer - Intermediate Middle		W3	Cracking	10	N	N	0	Y - 40 SF Contents, Desks, Computers	N	

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
102	8160	1	ML	A127	Computer - Intermediate Middle		W4	Cracking	20	N	N	0	N	N	
103	8160	1	ML	A128	Computer - Intermediate Middle		W2	Flaking	280	N	N	0	N	N	Additional Cracking, Chipping
104	8160	1	ML	A128	Computer - Intermediate Middle		W4	Flaking	100	N	N	0	N	N	
105	8160	1	ML	A140	Administrative Office		W3	Flaking	12	N	N	0	N	N	
106	8160	1	ML	A140	Administrative Office		W4	Flaking	10	N	N	0	N	N	
107	8160	1	ML	A141	Administrative Office		W2	Flaking	8	N	N	0	N	N	
108	8160	1	ML	A141	Administrative Office		W3	Flaking	12	N	N	0	N	N	
109	8160	1	ML	A143	Storage		W2	Partially Inaccessible	0	N	N	0	Y - 24 SF Shelves, Contents	N	Inspection Required
110	8160	1	ML	A143	Storage		W3	Partially Inaccessible	0	N	N	0	Y - 28 SF Shelves, Contents	N	Inspection Required
111	8160	1	ML	A143	Storage		W4	Partially Inaccessible	0	N	N	0	Y - 24 SF Shelves, Contents	N	Inspection Required
112	8160	1	ML	A146	Auditorium		W2	Flaking	500	N	N	0	N	N	Additional Cracking, Chipping
113	8160	1	ML	A146	Auditorium		W4	Flaking	500	N	N	0	N	N	Additional Cracking, Chipping
114	8160	1	ML	A146 STAGE	Stage		W2	Flaking	80	N	N	0	N	N	
115	8160	1	ML	A146 STAGE	Stage		W3	Flaking	600	N	N	0	N	N	
116	8160	1	ML	A146 STAGE	Stage		W4	Flaking	50	N	N	0	N	N	
117	8160	1	ML	B101	Intermediate/Middle -- Science Lab		W1	Chipping	10	N	N	0	N	N	Chipping @ Door Frame
118	8160	1	ML	B101	Intermediate/Middle -- Science Lab		W2	Flaking	4	N	N	0	N	N	Additional Chipping
119	8160	1	ML	B101	Intermediate/Middle -- Science Lab		W3	Flaking	30	N	N	0	N	N	
120	8160	1	ML	B101	Intermediate/Middle -- Science Lab		W4	Flaking	120	N	N	0	N	N	Additional Cracking, Chipping
121	8160	1	ML	B101A	Storage		W1	Flaking	20	N	N	0	N	N	
122	8160	1	ML	B101A	Storage		W2	Flaking	30	N	N	0	Y - 20 SF Contents	N	
123	8160	1	ML	B101A	Storage		W3	Flaking	45	N	N	0	Y - 30 SF Contents	N	

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
124	8160	1	ML	B101A	Storage		W4	Flaking	30	N	N	0	Y - 20 SF Contents	N	
125	8160	1	ML	B102	Intermediate/Middle		W1	Chipping	4	N	N	0	N	N	
126	8160	1	ML	B102	Intermediate/Middle		W3	Flaking	40	N	N	0	Y - 120 SF Desks, Posters	N	Additional Chipping
127	8160	1	ML	B102	Intermediate/Middle		W4	Flaking	35	N	N	0	Y - 80 SF Posters	N	Additional Chipping
128	8160	1	ML	B103	Intermediate/Middle		W1	Flaking	15	N	N	0	N	N	Additional Chipping
129	8160	1	ML	B103	Intermediate/Middle		W2	Flaking	10	N	N	0	N	N	Additional Chipping
130	8160	1	ML	B103	Intermediate/Middle		W4	Flaking	100	N	N	0	N	N	Additional Chipping
131	8160	1	ML	B104	Intermediate/Middle		W1	Chipping	6	N	N	0	N	N	
132	8160	1	ML	B104	Intermediate/Middle		W2	Chipping	8	N	N	0	N	N	
133	8160	1	ML	B104	Intermediate/Middle		W3	Flaking	8	N	N	0	N	N	Additional Chipping
134	8160	1	ML	B105	Intermediate/Middle		W1	Chipping	6	N	N	0	N	N	
135	8160	1	ML	B105	Intermediate/Middle		W2	Chipping	200	N	N	0	N	N	
136	8160	1	ML	B105	Intermediate/Middle		W3	Partially Inaccessible	0	N	N	0	Y - 120 SF Desks, Tables, Posters	N	Inspection Required
137	8160	1	ML	B105	Intermediate/Middle		W4	Partially Inaccessible	0	N	N	0	Y - 100 SF Desks, Tables, Posters	N	Inspection Required
138	8160	1	ML	C105	Restrooms, Staff - Male/Female		Ceiling	Flaking	12	N	N	0	N	N	
139	8160	1	ML	C113	Student Restrooms - Male (4-12)		Ceiling	Flaking	25	N	N	0	N	N	
140	8160	1	ML	C114	Restrooms, Staff - Male		W1	Chipping	8	N	N	0	N	N	
141	8160	1	ML	C114	Restrooms, Staff - Male		W2	Chipping	5	N	N	0	N	N	
142	8160	1	ML	C114	Restrooms, Staff - Male		W3	Chipping	6	N	N	0	N	N	
143	8160	1	ML	C114	Restrooms, Staff - Male		W4	Chipping	10	N	N	0	N	N	
144	8160	1	ML	C117	Student Restrooms - Female (4-12)		Ceiling	Flaking	12	N	N	0	N	N	
145	8160	1	ML	C118	Restrooms, Staff - Female		Ceiling	Flaking	15	N	N	0	N	N	
146	8160	1	ML	C120	Art - Intermediate Middle		W1	Partially Inaccessible	0	N	N	0	Y - 30 SF Desks, Contents	N	Inspection Required

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
147	8160	1	ML	C120	Art - Intermediate Middle		W2	Partially Inaccessible	0	N	N	0	Y - 38 SF Desks, Posters, Contents	N	Inspection Required
148	8160	1	ML	C120	Art - Intermediate Middle		W3	Partially Inaccessible	0	N	N	0	Y - 32 SF Desks, Tables, Posters Contents	N	Inspection Required
149	8160	1	ML	C120	Art - Intermediate Middle		W4	Partially Inaccessible	0	N	N	0	Y - 36 SF Desks, Contents	N	Inspection Required
150	8160	1	ML	C136	Storage		W2	Partially Inaccessible	0	N	N	0	Y - 20 SF Shelves, Contents	N	Inspection Required
151	8160	1	ML	C136	Storage		W3	Partially Inaccessible	0	N	N	0	Y - 18 SF Shelves, Contents	N	Inspection Required
152	8160	1	ML	C136	Storage		W4	Partially Inaccessible	0	N	N	0	Y - 26 SF Shelves, Contents	N	Inspection Required
153	8160	1	ML	C137	Storage		W2	Partially Inaccessible	0	N	N	0	Y - 24 SF Shelves, Contents	N	Inspection Required
154	8160	1	ML	C137	Storage		W3	Partially Inaccessible	0	N	N	0	Y - 28 SF Shelves, Contents	N	Inspection Required
155	8160	1	ML	C137	Storage		W4	Partially Inaccessible	0	N	N	0	Y - 24 SF Shelves, Contents	N	Inspection Required
156	8160	1	ML	G101	Intermediate/Middle -- Science Lab		W1	Partially Inaccessible	0	N	N	0	Y - 40 SF Contents	N	Inspection Required
157	8160	1	ML	G101	Intermediate/Middle -- Science Lab		W2	Partially Inaccessible	0	N	N	0	Y - 36 SF Desks, Posters	N	Inspection Required
158	8160	1	ML	G101	Intermediate/Middle -- Science Lab		W3	Partially Inaccessible	0	N	N	0	Y - 20 SF Desks	N	Inspection Required
159	8160	1	ML	G101	Intermediate/Middle -- Science Lab		W4	Partially Inaccessible	0	N	N	0	Y - 45 SF Desks, Contents	N	Inspection Required
160	8160	1	ML	G101	Intermediate/Middle -- Science Lab		W5	Partially Inaccessible	0	N	N	0	Y - 45 SF Desks, Contents	N	Inspection Required
161	8160	1	ML	G102	Intermediate/Middle		W1	Flaking	150	N	N	0	N	N	Additional Chipping
162	8160	1	ML	G102	Intermediate/Middle		W2	Flaking	20	N	N	0	N	N	Additional Chipping
163	8160	1	ML	G103	Intermediate/Middle		W1	Chipping	18	N	N	0	N	N	
164	8160	1	ML	G103	Intermediate/Middle		W2	Chipping	15	N	N	0	N	N	

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
165	8160	1	ML	G103	Intermediate/Middle		W4	Chipping	20	N	N	0	N	N	
166	8160	1	ML	G103	Intermediate/Middle		W5	Chipping	18	N	N	0	N	N	
167	8160	1	ML	G103	Intermediate/Middle		W3	Flaking	18	N	N	0	N	N	Additional Cracking, Chipping
168	8160	1	ML	G104	Intermediate/Middle		W1	Chipping	20	N	N	0	N	N	
169	8160	1	ML	G104	Intermediate/Middle		W3	Chipping	20	N	N	0	N	N	
170	8160	1	ML	G105	Intermediate/Middle		W1	Chipping	5	N	N	0	N	N	
171	8160	1	ML	G105	Intermediate/Middle		W4	Chipping	12	N	N	0	N	N	
172	8160	1	ML	G105	Intermediate/Middle		W3	Cracking	18	N	N	0	N	N	Additional Chipping
173	8160	1	ML	H101	Intermediate/Middle		W1	Chipping	8	N	N	0	Y - 12 SF Posters	N	
174	8160	1	ML	H101	Intermediate/Middle		W2	Partially Inaccessible	0	N	N	0	Y - 36 SF Bookcases, Contents	N	Inspection Required
175	8160	1	ML	H101	Intermediate/Middle		W3	Partially Inaccessible	0	N	N	0	N	N	Inspection Required
176	8160	1	ML	H122A	Circulation (Hallway)		Ceiling	Flaking	16	N	N	0	N	N	Suspended Ceiling; Flaking @ Window Lintel
177	8160	1	ML	H122B	Circulation (Hallway)		W2	Chipping	10	N	N	0	N	N	
178	8160	1	ML	H122B	Circulation (Hallway)		Ceiling	Flaking	16	N	N	0	N	N	Suspended Ceiling; Flaking @ Window Lintel
179	8160	1	ML	H123	Circulation (Hallway)		W2	Chipping	14	N	N	0	N	N	Chipping @ Classroom Door Frames
180	8160	1	ML	H123	Circulation (Hallway)		W4	Chipping	18	N	N	0	N	N	Chipping @ Classroom Door Frames
181	8160	1	ML	H123A	Circulation (Hallway)		W1	Chipping	18	N	N	0	N	N	Chipping @ Classroom Door Frames
182	8160	1	ML	H123A	Circulation (Hallway)		W3	Chipping	20	N	N	0	N	N	Chipping @ Classroom Door Frames
183	8160	1	ML	H125	Circulation (Hallway)		W1	Chipping	14	N	N	0	N	N	Chipping @ Classroom Door Frames
184	8160	1	ML	H125	Circulation (Hallway)		W3	Chipping	10	N	N	0	N	N	Chipping @ Classroom Door Frames
185	8160	1	ML	H125A	Circulation (Hallway)		W2	Chipping	12	N	N	0	N	N	Chipping @ Classroom Door Frames
186	8160	1	ML	H125A	Circulation (Hallway)		W4	Chipping	16	N	N	0	N	N	Chipping @ Classroom Door Frames
187	8160	1	ML	H146	Kitchen		W1	Chipping	8	N	N	0	N	N	
188	8160	1	ML	H146	Kitchen		W2	Chipping	8	N	N	0	N	N	
189	8160	1	ML	H148	Cafeteria (Dining Area) - Yellow		W3	Chipping	60	N	N	0	N	N	
190	8160	1	ML	H148	Cafeteria (Dining Area) - Yellow		W1	Flaking	300	N	N	0	N	N	
191	8160	1	ML	H148	Cafeteria (Dining Area) - Yellow		W2	Flaking	40	N	N	0	N	N	

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
192	8160	1	ML	H148	Cafeteria (Dining Area) - Yellow		W4	Flaking	16	N	N	0	N	N	
193	8160	1	ML	H148	Cafeteria (Dining Area) - Yellow		Ceiling	Flaking	800	N	N	0	N	N	
194	8160	1	ML	H151	Cafeteria (Dining Area) - Green		W3	Chipping	30	N	N	0	N	N	
195	8160	1	ML	H151	Cafeteria (Dining Area) - Green		W1	Flaking	350	N	N	0	N	N	
196	8160	1	ML	H151	Cafeteria (Dining Area) - Green		Ceiling	Flaking	800	N	N	0	N	N	
197	8160	1	ML	H155	Cafeteria (Dining Area) - Blue		W1	Chipping	20	N	N	0	N	N	
198	8160	1	ML	H155	Cafeteria (Dining Area) - Blue		W2	Chipping	40	N	N	0	N	N	
199	8160	1	ML	H155	Cafeteria (Dining Area) - Blue		W3	Chipping	30	N	N	0	N	N	
200	8160	1	ML	H155	Cafeteria (Dining Area) - Blue		W4	Chipping	20	N	N	0	N	N	
201	8160	1	ML	H155	Cafeteria (Dining Area) - Blue		Ceiling	Chipping	40	N	N	0	N	N	
202	8160	1	ML	H158	Cafeteria (Dining Area) - Orange		W3	Chipping	30	N	N	0	N	N	
203	8160	1	ML	H158	Cafeteria (Dining Area) - Orange		W1	Flaking	40	N	N	0	N	N	
204	8160	1	ML	H158	Cafeteria (Dining Area) - Orange		W2	Flaking	30	N	N	0	N	N	
205	8160	1	ML	H158	Cafeteria (Dining Area) - Orange		W4	Flaking	50	N	N	0	N	N	
206	8160	1	ML	H158	Cafeteria (Dining Area) - Orange		Ceiling	Flaking	500	N	N	0	N	N	
207	8160	1	ML	O101	Intermediate/Middle -- Science Lab		W3	Cracking	30	N	N	0	N	N	Additional Chipping
208	8160	1	ML	O101	Intermediate/Middle -- Science Lab		W1	Flaking	12	N	N	0	N	N	Additional Chipping
209	8160	1	ML	O101	Intermediate/Middle -- Science Lab		W4	Flaking	40	N	N	0	Y - 40 SF Posters	N	
210	8160	1	ML	O101	Intermediate/Middle -- Science Lab		W2	Partially Inaccessible	0	N	N	0	Y - 30 SF Posters	N	Inspection Required
211	8160	1	ML	O101A	Storage		W1	Partially Inaccessible	0	N	N	0	N	N	Inspection Required
212	8160	1	ML	O101A	Storage		W2	Partially Inaccessible	0	N	N	0	N	N	Inspection Required
213	8160	1	ML	O101A	Storage		W3	Partially Inaccessible	0	N	N	0	N	N	Inspection Required
214	8160	1	ML	O101A	Storage		W4	Partially Inaccessible	0	N	N	0	N	N	Inspection Required
215	8160	1	ML	O102	Intermediate/Middle		W4	Cracking	40	N	N	0	Y - 60 SF Posters	N	Additional Chipping
216	8160	1	ML	O102	Intermediate/Middle		W1	Flaking	30	N	N	0	N	N	Additional Cracking, Chipping
217	8160	1	ML	O102	Intermediate/Middle		W2	Flaking	2	N	N	0	N	N	Flaking Behind Column
218	8160	1	ML	O103	Intermediate/Middle		W1	Flaking	20	N	N	0	N	N	Additional Chipping

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
219	8160	1	ML	O103	Intermediate/Middle		W3	Flaking	16	N	N	0	N	N	
220	8160	1	ML	O104	Intermediate/Middle		W1	Chipping	4	N	N	0	N	N	
221	8160	1	ML	O104	Intermediate/Middle		W3	Cracking	26	N	N	0	N	N	Additional Chipping
222	8160	1	ML	O105	Intermediate/Middle		W1	Chipping	8	N	N	0	N	N	
223	8160	1	ML	O105	Intermediate/Middle		W4	Cracking	80	N	N	0	N	N	
224	8160	1	ML	O105	Intermediate/Middle		W3	Flaking	100	N	N	0	N	N	
225	8160	1	ML	S118	Stairs		W1	Chipping	8	N	N	0	N	N	
226	8160	1	ML	S118	Stairs		W2	Chipping	8	N	N	0	N	N	
227	8160	1	ML	S118	Stairs		W3	Chipping	8	N	N	0	N	N	
228	8160	1	ML	S118	Stairs		W4	Chipping	8	N	N	0	N	N	
229	8160	1	ML	Y101	Intermediate/Middle -- Science Lab		W1	Chipping	8	N	N	0	N	N	
230	8160	1	ML	Y101	Intermediate/Middle -- Science Lab		W2	Partially Inaccessible	0	N	N	0	Y - 120 SF Desks, Posters Contents	N	Inspection Required
231	8160	1	ML	Y101	Intermediate/Middle -- Science Lab		W3	Partially Inaccessible	0	N	N	0	Y - 100 SF Desks, Posters Contents	N	Inspection Required
232	8160	1	ML	Y101	Intermediate/Middle -- Science Lab		W4	Partially Inaccessible	0	N	N	0	Y - 50 SF Desks, Posters Contents	N	Inspection Required
233	8160	1	ML	Y101	Intermediate/Middle -- Science Lab		W5	Partially Inaccessible	0	N	N	0	Y - 120 SF Desks, Posters Contents	N	Inspection Required
234	8160	1	ML	Y101A	Storage		W1	Flaking	8	N	N	0	N	N	
235	8160	1	ML	Y101A	Storage		W2	Flaking	22	N	N	0	Y - 20 SF Contents	N	
236	8160	1	ML	Y101A	Storage		W3	Flaking	14	N	N	0	Y - 30 SF Contents	N	
237	8160	1	ML	Y101A	Storage		W4	Flaking	20	N	N	0	Y - 20 SF Contents	N	
238	8160	1	ML	Y102	Intermediate/Middle		W1	Chipping	6	N	N	0	N	N	
239	8160	1	ML	Y102	Intermediate/Middle		W4	Chipping	15	N	N	0	N	N	
240	8160	1	ML	Y102	Intermediate/Middle		W2	Flaking	30	N	N	0	N	N	
241	8160	1	ML	Y102	Intermediate/Middle		W3	Flaking	30	N	N	0	N	N	Additional Chipping
242	8160	1	ML	Y102	Intermediate/Middle		W5	Flaking	20	N	N	0	N	N	
243	8160	1	ML	Y102	Intermediate/Middle		Ceiling	Flaking	8	Y	N	0	N	N	Additional Efflorescence, Cracking

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
244	8160	1	ML	Y103	Intermediate/Middle		W1	Cracking	10	N	N	0	N	N	Additional Chipping
245	8160	1	ML	Y103	Intermediate/Middle		W3	Cracking	14	N	N	0	N	N	Additional Chipping
246	8160	1	ML	Y103	Intermediate/Middle		W5	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
247	8160	1	ML	Y104	Intermediate/Middle		W1	Chipping	5	N	N	0	N	N	
248	8160	1	ML	Y104	Intermediate/Middle		W5	Chipping	20	N	N	0	N	N	
249	8160	1	ML	Y104	Intermediate/Middle		W2	Cracking	20	N	N	0	Y - 20 SF Contents, Posters	N	
250	8160	1	ML	Y104	Intermediate/Middle		W3	Cracking	16	N	N	0	Y - 18 SF Desks, Posters	N	
251	8160	1	ML	Y104	Intermediate/Middle		W4	Cracking	12	N	N	0	Y - 48 SF Desks, Posters	N	
252	8160	1	ML	Y105	Intermediate/Middle		W1	Chipping	8	N	N	0	N	N	Chipping @ Door Frame
253	8160	1	ML	Y105	Intermediate/Middle		W4	Chipping	40	N	N	0	N	N	
254	8160	1	ML	Y105	Intermediate/Middle		W5	Chipping	10	N	N	0	N	N	
255	8160	1	ML	Y105	Intermediate/Middle		W2	Flaking	8	N	N	0	N	N	Additional Chipping
256	8160	1	ML	Y105	Intermediate/Middle		W3	Flaking	30	N	N	0	N	N	Additional Cracking, Chipping
257	8160	1	LL	B1	Intermediate/Middle -- Science Lab		W1	Flaking	32	N	N	0	N	N	Additional Chipping
258	8160	1	LL	B1	Intermediate/Middle -- Science Lab		W2	Flaking	120	N	N	0	N	N	Additional Cracking, Chipping
259	8160	1	LL	B1	Intermediate/Middle -- Science Lab		W3	Flaking	140	N	N	0	N	N	
260	8160	1	LL	B1	Intermediate/Middle -- Science Lab		W4	Flaking	16	N	N	0	N	N	Additional Chipping
261	8160	1	LL	B1	Intermediate/Middle -- Science Lab		W5	Flaking	10	N	N	0	Y - 72 SF Cabinets, Contents	N	Additional Chipping
262	8160	1	LL	B11	Storage		W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
263	8160	1	LL	B11	Storage		W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
264	8160	1	LL	B11	Storage		W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
265	8160	1	LL	B11	Storage		W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
266	8160	1	LL	B11	Storage		Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
267	8160	1	LL	B11	Storage		Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
268	8160	1	LL	B12	Administrative Office		W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
269	8160	1	LL	B12	Administrative Office		W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
270	8160	1	LL	B12	Administrative Office		W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
271	8160	1	LL	B12	Administrative Office		W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
272	8160	1	LL	B12	Administrative Office		Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
273	8160	1	LL	B12	Administrative Office		Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
274	8160	1	LL	B14	Administrative Office		W1	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
275	8160	1	LL	B14	Administrative Office		W2	Flaking	16	N	N	0	N	N	Additional Cracking, Chipping
276	8160	1	LL	B14	Administrative Office		W3	Flaking	30	N	N	0	N	N	Additional Cracking, Chipping
277	8160	1	LL	B1A	Storage		W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Padlocked
278	8160	1	LL	B1A	Storage		W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
279	8160	1	LL	B1A	Storage		W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
280	8160	1	LL	B1A	Storage		W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
281	8160	1	LL	B1A	Storage		Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
282	8160	1	LL	B1A	Storage		Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
283	8160	1	LL	B2	Intermediate/Middle		W5	Cracking	60	N	N	0	N	N	Additional Chipping
284	8160	1	LL	B2	Intermediate/Middle		W1	Flaking	36	N	N	0	N	N	Additional Cracking, Chipping
285	8160	1	LL	B2	Intermediate/Middle		W4	Flaking	72	N	N	0	N	N	
286	8160	1	LL	B2	Intermediate/Middle		W2	Partially Inaccessible	0	N	N	0	Y - 12 SF Desks	N	Inspection Required
287	8160	1	LL	B3	Intermediate/Middle		W4	Cracking	12	N	N	0	Y - 72 SF Desks, File Cabinets, Contents	N	Additional Chipping
288	8160	1	LL	B3	Intermediate/Middle		W1	Flaking	14	N	N	0	N	N	Additional Chipping
289	8160	1	LL	B4	Intermediate/Middle		W2	Chipping	7	N	N	0	N	N	
290	8160	1	LL	B4	Intermediate/Middle		W3	Flaking	12	N	N	0	N	N	Additional Cracking
291	8160	1	LL	B4	Intermediate/Middle		W4	Flaking	22	N	N	0	N	N	Additional Cracking
292	8160	1	LL	B5	Intermediate/Middle		W5	Chipping	140	N	N	0	N	N	
293	8160	1	LL	B5	Intermediate/Middle		W1	Flaking	40	N	N	0	N	N	Additional Cracking, Chipping
294	8160	1	LL	B5	Intermediate/Middle		W3	Flaking	6	N	N	0	N	N	Additional Chipping; Damage @ Column & Pipe
295	8160	1	LL	B5	Intermediate/Middle		W4	Flaking	80	N	N	0	N	N	Additional Cracking, Chipping
296	8160	1	LL	C1	Lockers - Female		W1	Partially Inaccessible	0	N	Y	80	N	N	Inspection Required
297	8160	1	LL	C1	Lockers - Female		W2	Partially Inaccessible	0	N	Y	120	N	N	Inspection Required
298	8160	1	LL	C1	Lockers - Female		W3	Partially Inaccessible	0	N	Y	100	N	N	Inspection Required
299	8160	1	LL	C1	Lockers - Female		W4	Partially Inaccessible	0	N	Y	60	N	N	Inspection Required

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
300	8160	1	LL	C12	Other Physical Education Space		W1	Cracking	8	N	N	0	N	N	
301	8160	1	LL	C20	Lockers - Male		W1	Chipping	6	N	N	0	Y - 80 SF Boxes, Contents	N	
302	8160	1	LL	C20	Lockers - Male		W4	Chipping	16	N	N	0	Y - 48 SF Contents	N	
303	8160	1	LL	C20	Lockers - Male		Ceiling	Cracking	30	N	N	0	N	N	Additional Chipping
304	8160	1	LL	C20	Lockers - Male		W3	Flaking	40	N	N	0	Y - 160 SF Contents	N	Additional Chipping
305	8160	1	LL	C20	Lockers - Male		W2	Partially Inaccessible	0	N	N	0	Y - 90 SF Contents	N	Inspection Required
306	8160	1	LL	C20A	Storage		W1	Chipping	3	N	N	0	N	N	Chipping @ Door Frame
307	8160	1	LL	C29	Restrooms, Staff - Female		Ceiling	Cracking	6	N	N	0	N	N	
308	8160	1	LL	G1	Intermediate/Middle -- Science Lab		W1	Flaking	200	N	N	0	N	N	Additional Chipping
309	8160	1	LL	G1	Intermediate/Middle -- Science Lab		W4	Flaking	400	N	N	0	Y - 200 SF Cabinets, Desks	N	Additional Cracking, Chipping
310	8160	1	LL	G1	Intermediate/Middle -- Science Lab		W5	Flaking	20	N	N	0	N	N	Additional Chipping
311	8160	1	LL	G18A	Student Restrooms - Male/Female (Classroom)		Ceiling	Cracking	12	N	N	0	N	N	
312	8160	1	LL	G1A	Storage		W1	Cracking	10	N	N	0	N	N	
313	8160	1	LL	G1A	Storage		W2	Cracking	10	N	N	0	N	N	
314	8160	1	LL	G1A	Storage		Ceiling	Flaking	45	N	N	0	N	N	
315	8160	1	LL	G1A	Storage		W4	Partially Inaccessible	0	N	N	0	Y - 64 SF Cabinets, Contents	N	Inspection Required
316	8160	1	LL	G2	Intermediate/Middle		W1	Cracking	20	N	N	0	N	N	Additional Chipping; Damage @ Door Frame & Wall
317	8160	1	LL	G2	Intermediate/Middle		W2	Cracking	100	N	N	0	N	N	Additional Chipping
318	8160	1	LL	G2	Intermediate/Middle		W5	Cracking	4	N	N	0	N	N	
319	8160	1	LL	G2	Intermediate/Middle		W3	Flaking	18	N	N	0	N	N	Additional Cracking, Chipping
320	8160	1	LL	G3	Intermediate/Middle		W3	Partially Inaccessible	0	N	N	0	Y - 80 SF Desks, Bookcases, Posters	N	Inspection Required
321	8160	1	LL	G3	Intermediate/Middle		W4	Partially Inaccessible	0	N	N	0	Y - 40 SF Bookcases, Posters	N	Inspection Required
322	8160	1	LL	G4	Intermediate/Middle		W4	Cracking	20	N	N	0	N	N	Additional Chipping
323	8160	1	LL	G4	Intermediate/Middle		W1	Flaking	6	N	N	0	N	N	

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
324	8160	1	LL	G4	Intermediate/Middle		W3	Partially Inaccessible	0	N	N	0	Y - 60 SF Bookcases, Contents, Posters	N	Inspection Required
325	8160	1	LL	G5	Intermediate/Middle		W3	Cracking	30	N	N	0	Y - 100 SF Desks, Contents	N	Additional Chipping
326	8160	1	LL	G5	Intermediate/Middle		W1	Flaking	16	N	N	0	N	N	Additional Chipping
327	8160	1	LL	G5	Intermediate/Middle		W2	Flaking	40	N	N	0	N	N	Additional Cracking, Chipping
328	8160	1	LL	H010	Circulation (Hallway)		W1	Chipping	3	N	N	0	N	N	
329	8160	1	LL	H012	Circulation (Hallway)		W2	Flaking	0	N	N	0	N	N	Additional Chipping; Damage Near Floor
330	8160	1	LL	H012	Circulation (Hallway)		W4	Flaking	0	N	N	0	N	N	Additional Chipping; Damage Near Floor
331	8160	1	LL	H013	Circulation (Hallway)		W1	Flaking	18	N	N	0	N	N	Additional Chipping; Damage Near Floor
332	8160	1	LL	H013	Circulation (Hallway)		W3	Flaking	14	N	N	0	N	N	Additional Chipping; Damage Near Floor
333	8160	1	LL	H014	Circulation (Hallway)		W1	Flaking	8	N	N	0	N	N	Additional Chipping; Damage Near Floor
334	8160	1	LL	H014	Circulation (Hallway)		W3	Flaking	12	N	N	0	N	N	Additional Chipping; Damage Near Floor
335	8160	1	LL	H015	Circulation (Hallway)		W1	Flaking	10	N	N	0	N	N	Additional Chipping; Damage Near Floor
336	8160	1	LL	H015	Circulation (Hallway)		W3	Flaking	10	N	N	0	N	N	Additional Chipping; Damage Near Floor
337	8160	1	LL	H07	Circulation (Hallway)		W1	Flaking	20	Y	N	0	N	N	Additional Efflorescence
338	8160	1	LL	H07	Circulation (Hallway)		Floor	None	0	N	Y - @ Perimeter	6	N	N	
339	8160	1	LL	H09	Circulation (Hallway)		W3	Chipping	4	N	N	0	N	N	
340	8160	1	LL	H1	Intermediate/Middle -- Open Plan		W1	Chipping	0	N	N	0	Y - 32 SF Desks, Computers, Bookcases	N	Chipping Near Floor
341	8160	1	LL	H1	Intermediate/Middle -- Open Plan		W2	Chipping	0	N	N	0	Y - 20 SF Desks, Computers, Bookcases	N	Chipping Near Floor
342	8160	1	LL	H1	Intermediate/Middle -- Open Plan		W3	Chipping	0	N	N	0	Y - 28 SF Desks, Computers, Bookcases	N	Chipping Near Floor
343	8160	1	LL	H1	Intermediate/Middle -- Open Plan		W4	Chipping	0	N	N	0	N	N	Chipping Near Floor
344	8160	1	LL	H26	Administrative Office		W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
345	8160	1	LL	H26	Administrative Office		W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
346	8160	1	LL	H26	Administrative Office		W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
347	8160	1	LL	H26	Administrative Office		W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
348	8160	1	LL	H26	Administrative Office		Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
349	8160	1	LL	H26	Administrative Office		Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
350	8160	1	LL	H80	Student Restrooms - Female (4-12)		Ceiling	Flaking	8	N	N	0	N	N	
351	8160	1	LL	O1	Intermediate/Middle -- Science Lab		W2	Cracking	6	N	N	0	N	N	Additional Chipping
352	8160	1	LL	O1	Intermediate/Middle -- Science Lab		W3	Cracking	24	N	N	0	N	N	Additional Chipping
353	8160	1	LL	O1	Intermediate/Middle -- Science Lab		W4	Cracking	10	N	N	0	N	N	
354	8160	1	LL	O1	Intermediate/Middle -- Science Lab		W5	Cracking	16	N	N	0	N	N	
355	8160	1	LL	O10	Storage		Ceiling	Flaking	36	N	N	0	N	N	
356	8160	1	LL	O1A	Storage		W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
357	8160	1	LL	O1A	Storage		W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
358	8160	1	LL	O1A	Storage		W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
359	8160	1	LL	O1A	Storage		W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
360	8160	1	LL	O1A	Storage		Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
361	8160	1	LL	O1A	Storage		Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
362	8160	1	LL	O2	Intermediate/Middle		W1	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
363	8160	1	LL	O2	Intermediate/Middle		W3	Flaking	30	N	N	0	N	N	Additional Cracking, Chipping
364	8160	1	LL	O2	Intermediate/Middle		W4	Flaking	260	N	N	0	N	N	Additional Cracking, Chipping
365	8160	1	LL	O2	Intermediate/Middle		W5	Flaking	60	N	N	0	N	N	Additional Cracking, Chipping
366	8160	1	LL	O3	Intermediate/Middle		W1	Flaking	16	N	N	0	N	N	
367	8160	1	LL	O3	Intermediate/Middle		W3	Partially Inaccessible	0	N	N	0	Y - 28 SF Posters, Contents	N	Inspection Required
368	8160	1	LL	O3	Intermediate/Middle		W5	Flaking	36	N	N	0	N	N	Additional Cracking, Chipping
369	8160	1	LL	O3	Intermediate/Middle		W6	Flaking	36	N	N	0	N	N	
370	8160	1	LL	O4	Intermediate/Middle		W1	Chipping	8	N	N	0	N	N	
371	8160	1	LL	O4	Intermediate/Middle		W2	Flaking	16	N	N	0	N	N	
372	8160	1	LL	O4	Intermediate/Middle		W3	Flaking	10	N	N	0	Y - 30 SF Posters	N	Additional Cracking, Chipping

Baldi -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
373	8160	1	LL	O5	Intermediate/Middle		W4	Cracking	4	N	N	0	N	N	
374	8160	1	LL	O5	Intermediate/Middle		W1	Flaking	40	N	N	0	N	N	Additional Chipping
375	8160	1	LL	O5	Intermediate/Middle		W2	Flaking	30	N	N	0	N	N	Additional Chipping
376	8160	1	LL	O5	Intermediate/Middle		W3	Flaking	180	N	N	0	N	N	Additional Cracking, Chipping
377	8160	1	LL	S010	Stairs		W3	Flaking	4	N	N	0	N	N	Flaking Above Exit
378	8160	1	LL	S021	Stairs		W1	Flaking	20	N	N	0	N	N	
379	8160	1	LL	S021	Stairs		W2	Flaking	30	N	N	0	N	N	
380	8160	1	LL	S021	Stairs		W3	Flaking	60	N	N	0	N	N	
381	8160	1	LL	S021	Stairs		W4	Flaking	40	N	N	0	N	N	
382	8160	1	LL	S021	Stairs		Ceiling	Flaking	30	N	N	0	N	N	
383	8160	1	LL	Y1	Intermediate/Middle -- Science Lab		W1	Flaking	72	N	N	0	N	N	Additional Cracking, Chipping
384	8160	1	LL	Y1	Intermediate/Middle -- Science Lab		W2	Flaking	128	N	N	0	N	N	Additional Cracking, Chipping
385	8160	1	LL	Y1	Intermediate/Middle -- Science Lab		W3	Flaking	45	N	N	0	N	N	Additional Cracking, Chipping
386	8160	1	LL	Y1	Intermediate/Middle -- Science Lab		W4	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
387	8160	1	LL	Y2	Intermediate/Middle		W1	Flaking	72	N	N	0	N	N	Additional Cracking, Chipping
388	8160	1	LL	Y2	Intermediate/Middle		W2	Flaking	128	N	N	0	N	N	Additional Cracking, Chipping
389	8160	1	LL	Y2	Intermediate/Middle		W3	Flaking	45	N	N	0	N	N	Additional Cracking, Chipping
390	8160	1	LL	Y2	Intermediate/Middle		W4	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
391	8160	1	LL	Y3	Intermediate/Middle		W1	Chipping	6	N	N	0	N	N	Chipping @ Door Frame
392	8160	1	LL	Y3	Intermediate/Middle		W4	Cracking	18	N	N	0	N	N	Additional Chipping
393	8160	1	LL	Y3	Intermediate/Middle		W2	Flaking	50	N	N	0	N	N	Additional Cracking, Chipping
394	8160	1	LL	Y4	Intermediate/Middle		W5	Cracking	24	N	N	0	N	N	Additional Chipping
395	8160	1	LL	Y4	Intermediate/Middle		W1	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
396	8160	1	LL	Y5	Intermediate/Middle		W1	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
397	8160	1	LL	Y5	Intermediate/Middle		W5	Flaking	36	N	N	0	N	N	Additional Chipping
398	8160	1	LL	Y5	Intermediate/Middle		W4	Partially Inaccessible	0	N	N	0	Y - 36 SF Desks, Computers	N	Inspection Required