

Summary of Paint & Plaster Stabilization Activities

AT:

**#6300– Logan Elementary School
1700 Lindley Avenue
Philadelphia, PA 19141**

PREPARED FOR:

**Ms. Francine Locke, M.S.
Environmental Services Director**

**Mr. Jerry Junod
Environmental Services Manager**

**School District of Philadelphia
Office of Environmental Management & Services
440 North Broad Street
3rd Floor – Portal C
Philadelphia, PA 19130**

PREPARED BY:

**Mr. Steven A. Vena, CIH
Project Manager**

**Criterion Laboratories, Inc.
January 17, 2019**

**Project Number: 181676
Project Dates: July 30 – December 13, 2018**

Summary of Paint and Plaster Stabilization Activities
School Name: Logan Elementary School
Address: 1700 Lindley Avenue
Philadelphia, PA 19141
UCLS #: 6300

TABLE OF CONTENTS

- I. Introduction**

- II. Methods Executive Summary**
 - A. Preliminary Steps**
 - i. Parent and Staff Notifications**
 - ii. Decluttering**
 - iii. Wall Hangings**
 - iv. Swing Space**
 - v. Facilities Building Cleaning Staff Training**
 - B. Pre-Cleaning**
 - C. Paint & Plaster Stabilization Procedures**
 - i. Work Practices**
 - ii. Oversight**
 - D. Cleanup & Completion**
 - i. Cleanup**
 - ii. Testing**

- III. Oversight**
 - A. Scope of Work**
 - B. EPA Checklist**
 - C. Oversight**
 - D. Sample Results**

Appendix A. Scope of Work Table

Appendix B. EPA Checklist Table

Appendix C. Oversight Table

Appendix D. Sample Results Table

Appendix E. Photographs

Appendix F. Environmental Firm Certification Documentation of Training

Appendix G. Paint Contractor Certifications or Documentation of Training

Appendix H. Documentation of Parent and Staff Notifications

I. INTRODUCTION

Criterion Laboratories, Inc. (Criterion), was requested by the School District of Philadelphia's Office of Environmental Management Services (OEMS) to perform oversight and clearance testing during a paint and plaster stabilization project being performed by the School District Painters at Logan Elementary School located at 1700 Lindley Avenue in Philadelphia, PA (the "School"). The purpose of the oversight was to document that all parts of the US Environmental Protection Agency (EPA) Lead Renovation, Repair and Painting rules were being followed and documented.

II. METHODS EXECUTIVE SUMMARY

A. Preliminary Steps

i. Parent and Staff Notifications

Parents and staff were notified of the paint and plaster project by mail several weeks prior to the commencement of the project. Additionally, prior to the start of the project, parent and staff meetings were held by OEMS, Maintenance, and Operations to explain the process of the paint and plaster projects and to field any questions or concerns.

ii. Decluttering

Classrooms, closets and other storage areas were decluttered prior to the commencement of stabilization work. Coordination of the decluttering activities was made between teachers and facilities staff to ensure that outdated and unneeded academic materials were discarded, and that resources were provided to assist in the decluttering tasks such as support staff for heavy lifting and/or moving large furniture and additional recycling dumpsters.

iii. Wall Hangings

Posters, bulletin boards, framed art and other wall hangings were removed prior to the commencement of the paint stabilization project. This was coordinated with teachers by the Operations Division at the kick-off meeting, and during the phasing of the project, with the help of the Principal.

iv. Swing Space

Swing space was identified prior to the commencement of stabilization work to ensure that classrooms were available during the school year. A plan was created on a school-by-school basis to relocate students and teachers from classrooms during the course of this work. All work areas were scheduled for cleaning by facilities staff after the paint stabilization work was completed by Maintenance Painting Staff.

v. Facilities Building Cleaning Staff Training

Facilities Building Cleaning Staff were provided with information about this project and expectations for post-cleaning, including use of wet-wipes and HEPA vacuums.

B. Pre-Cleaning

On an as-needed basis, for areas such as cluttered storage closets, that required extensive movement of materials, HEPA vacuuming, and wet-wiping prior to paint and plaster stabilization, the Maintenance Environmental staff performed a pre-cleaning in advance of stabilization work. The intent of this task was to provide a clean work area prior to decluttering and stabilization.

Additionally, post-cleaning was conducted by facilities staff after paint and plaster stabilization was completed. This included the HEPA vacuuming and wet-wiping of all horizontal surfaces and polishing floors.

C. Paint & Plaster Stabilization Procedures

Paint and plaster stabilization work complied with the EPA's Lead RRP rule. All staff conducting this work were trained and/or certified as Lead RRP workers.

The following procedures were followed:

i. Work Practices

- Isolate work areas to restrict dust from impacting adjacent areas.
- Post signs/notifications as per EPA Lead RRP.
- Place "walk-off" pads at all access points into/out of work area.
- Seal all openings [windows, doors, and HVAC system registers/grilles] inside work areas as per direction from on-site environmental monitors and consistent with the EPA Lead RRP rules & guidelines.
- Workers are to wear disposable clothing and foot coverings while inside work areas and will not leave work areas wearing disposable clothing.
- Move/cover all remaining objects in work area to protect them. Including all open bins, shelves and boxes in the classroom.
- Employ/Erect "portable" dust containment barrier systems to limit the size of work areas requiring post-cleaning and limit testing and exposure.
- Place plastic floor coverings to extend at least 6 feet out from vertical surfaces being stabilized unless utilizing vertical barriers/containment systems.
- Perform all paint stabilization work in compliance with the EPA Lead RRP rules & guidelines and as per the directions of on-site environmental monitors to minimize dust contamination.
- Take all steps necessary to ensure that no dust or debris leaves the work area while the work is being performed.
- Use precautions to ensure that all employees, tools, and other items, including the exteriors of waste containers, are free of dust and debris before leaving the work area.

- Collect all paint chips & debris, fold up plastic floor coverings and any other plastic sheeting used on horizontal surfaces, without dispersing dust or debris and dispose of the material in heavy duty plastic waste bags.
- Do not use power tools.
- Do not use dry sweeping with brooms.
- Do use water/misting during stabilization to minimize dust.
- Do use HEPA vacuums and wet wiping/cleaning techniques.

ii. Oversight

The environmental technician will oversee paint and plaster stabilization work to ensure compliance with lead safe work practices. An oversight report will be completed at the end of every shift to record the work areas that were stabilized. The following tasks will be verified and recorded:

- Pre-cleaning
- Contents moved
- Work area prepped
- Surfaces stabilized
- Contents back in place
- Final inspection approval and photos

D. Cleanup & Completion

The following clean-up and completion procedures were performed for each work area following the completion of stabilization work:

i. Cleanup

- There should be no signs of loose, peeling, flaking, bubbling or crumbling paint or plaster visible on walls or ceilings or on any other painted surfaces.
- There should be no visible signs of paint chips, debris or dust of any kind on surfaces within “contained” and isolated work areas NOR outside of the contained and isolated work areas.
- Window sills, floors, baseboards, shelving units, tops of cabinets, desks, chairs, tables and all other horizontal surfaces must be free of any visible signs of paint and plaster dust and/or debris.
- There must be absolutely no visible signs of paint chips, and/or paint/plaster dust or debris on academic/educational materials, including books, bins, toys, desks, chairs, carpets, papers, etc., after each work shift and to allow for re-occupancy the next day,
- Any remaining paint and plaster must be tightly adhered to wall and ceiling surfaces such that it cannot be further damaged, pried off or disturbed by “simple fingernail pressure” otherwise work will not be considered to be successfully completed.
- Newly painted surfaces should match the aesthetics of the area in total and should cover the entirety of the wall or ceiling area that was addressed through this work. No visible “patches” of paint should be observed.

ii. Testing

The District and the PFT's Environmental Consultant worked closely to develop an agreed upon approach to verify that stabilization work was performed in accordance with lead safe work practices, and that classrooms would be safe for re-occupancy by children and staff. This approach exceeds the EPA Lead RRP rule requirements in terms of the types of, and amounts of, testing performed. Testing will take place in work areas. The areas will be cleaned by general cleaners after the stabilization work is completed and the clearance testing is performed.

Qualitative testing methods, i.e., EPA RRP verification wipe testing and colorimetric wipe testing, will be compared with the quantitative testing method of Atomic Absorption Spectrophotometry (AAS) as indicated in the testing protocol below. If the comparison testing is consistently correlated, only qualitative testing will continue for the duration of the project.

a. Testing Protocol

Step 1 -- EPA RRP Verification Wipes and Colorimetric Wipes

The environmental consultant and painter foreman will coordinate the EPA RRP Verification Test Wipe in rooms/areas that have been stabilized and cleaned, and where plastic work area coverings have been removed and visual inspection conducted. After EPA RRP verification wipes pass the cleanliness standard for any surface and/or a 40 square feet (SF) section, the colorimetric testing will be conducted by the environmental consultant.

The colorimetric wipe tests will occur in "child-occupied areas" on approximately 10% of surfaces considered "clean" following the use of the verification wipes. These surfaces may include floors, window sills, or the tops of any other immovable objects that were covered and cleaned in each work area (e.g. CUVs, immovable bookshelves). Additional colorimetric wipes may be collected on surfaces that had been moved and covered and placed outside of the work area. These surfaces may include desks, chairs, bookshelves, etc.

"Child-occupied areas" will include: classrooms, restrooms, cafeterias, gymnasiums, and auditoriums that are routinely used by children in PK-1st grade classrooms. Common areas that children in PK-1st grade classrooms only pass through, such as hallways, stairways, and garages are not included. "Child-occupied areas" will be identified by the Principal of each school.

Step 2 -- Response to Failed Tests

If colorimetric testing "fails," then the 40 SF area will be re-wiped by EPA RRP Wipes. The process will continue until both testing methods confirm a "pass."

Step 3 -- Flame Atomic Absorption Spectrophotometry (FAAS)

Flame Atomic Absorption Spectrophotometry (FAAS) will be used to verify and confirm the results of the colorimetric testing. FAAS will be used as a quality assurance/quality control for the colorimetric samples. Approximately 10% of the colorimetric samples should be submitted for FAAS analysis.

Step 4 -- Release Spaces Back to School/Operations

If EPA RRP wipes and colorimetric wipes are both acceptable, as determined on site, and if work was completed in accordance with this procedure, the room will be turned over to the District's Operations team for "deep cleaning" and for re-occupancy.

Step 5 -- Ongoing Review

All sampling and testing data, information and results will be readily available and accessible for review by school staff, parents and members of the Oversight Advisory Committee and will be reviewed on a regular basis. Any suggested modifications, changes or other revisions will be considered by the School District of Philadelphia.

The three testing methods were conducted as follows:

Type of Clearance Tests	Building Component	Number of Sample Locations within Work Area	Type of Testing	Testing Specifications/Limitations
EPA RRP Cleaning Verification Wipe	Floors, Countertops, Desks, Tables, Window Sills	One (1) wipe every 40 square feet (ft ²) or entire surface of component if surface area is less than 40ft ² One (1) wipe for every window sill	Qualitative	<ul style="list-style-type: none"> ● Qualitative testing based on cleanliness (white glove test) ● According to RRP, the areas pass after the 3rd cleaning, regardless of verification
Colorimetric Wipe SKC, Inc. Full Disclosure® Instant Wipes	Floors, Countertops, Desks, Tables, Window Sills, Etc.	10% of surfaces considered "clean" following the use of EPA RRP Cleaning Verification Wipes	Qualitative	<ul style="list-style-type: none"> ● Qualitative testing based on colorimetric visual comparison ● Lower Limit of Visual Detection is 18µg of lead ● False positive and false negative interferences from silver, cadmium, barium, mercury, and titanium (percentages unknown) ● Involves field preparation of sampling media using reagents

<p>Flame Atomic Absorption Spectrophotometry (AAS)</p>	<p>Analyze Colorimetric Wipes from locations listed above</p>	<p>A minimum of one and a maximum of 10% of colorimetric wipes will also be subjected to laboratory analysis by FAAS for verification. This testing method will be used on a periodic basis to validate the the accuracy of qualitative methods above.</p>	<p>Quantitative</p>	<ul style="list-style-type: none"> ● Interior Floors and Desks: < 20 µg/ft² This is based upon a District and PFT agreement. This is half the current HUD and EPA standard. This is tied to the detection level for the colorimetric wipe which is 18µg per wipe. ● Window Sills: < 100 µg/ft² per HUD
--	---	--	---------------------	--

III. OVERSIGHT

A. Scope of Work

A scope of work was developed for Logan Elementary School following a room-by-room inspection of the school. During the inspection, the location and quantity of damaged paint and plaster, along with any associated debris and whether the damage was the result of an on-going moisture intrusion, were noted. This information was entered into a scope of work spreadsheet, which was provided to the School District Painting Department in order to create a schedule for the work to be completed.

During the paint and plaster stabilization project, additional areas of damage were found behind wall hangings, inside of closets that had now been decluttered, and behind furniture once it had been moved. These additional areas of work were added to the scope of work as they were observed.

The scope of work for Logan Elementary School is included in the Appendix A of this report.

B. EPA Checklist

Throughout the paint and plaster stabilization project, Criterion's on-site inspector observed, documented, and signed-off on tasks required by the EPA RRP. Additional notes were added to the EPA Checklist to document different oversight tasks that took place. These included documenting that warning signs were posted at the entrance to the work area, that the work area had been contained to prevent the spread of dust and debris, that all objects in the work area had been removed or covered, that all HVAC ducts in the work area were closed and covered, that windows in the work area were closed, that doors in the work area were closed and sealed, that doors that must be used in the work area were covered to allow passage but prevent the spread of dust, that floors in the work area were covered with taped-down plastic, that waste was being contained while on-site and while being transported, that the work site was properly cleaned after the renovations, that all paint chips and debris were picked up and that the protective sheeting was misted, folded dirty-side inward, and taped for removal, that the work area surfaces and objects were cleaned using HEPA vacuums and/or wet-wiping or mopping, that a certified renovator performed the post-renovation cleaning verification, a description of the post-renovation cleaning verification, including the number of wet and dry cloths used, and if the dust clearance testing was performed.

The EPA Checklist for Logan Elementary School is included in the Appendix B of this report.

C. Oversight

Throughout the paint and plaster stabilization project, Criterion's on-site inspector documented the day-to-day tasks performed for each work area. These tasks included the dates of pre-cleaning, the moving of the contents of the room, the prepping of the work area, the stabilization of the painted surfaces, and the final inspection.

The Oversight Table for Logan Elementary School is included in the Appendix C of this report.

D. Sample Results

Throughout the paint and plaster stabilization project, Criterion's on-site inspector documented all sampling results for each work area location. This included all RRP verification wipes, colorimetric wipes, and wipes to be submitted for Flame AAS analysis.

The Sample Results Table for Logan Elementary School is included in the Appendix D of this report.

Appendix A. Scope of Work Table

Task ID	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	3	330	Student Restrooms - Male (4-12)	Boy's Restroom	Floor	Chipped paint at floor	200	N			N		
2	3	330	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Flaking paint at radiator cover	5	N			N		
3	3	301	Primary	Classroom 301	Ceiling	Flaking paint at ceiling	100	Y			N	Posters, cabinets	
4	3	301	Primary	Classroom 301	W3	Flaking paint around windows	50	Y	Floor, sill	20	Y	Posters, cabinets	
5	3	301	Primary	Classroom 301	W4	Flaking paint at wall	10	N			N	Posters, cabinets	
6	3	301A	Storage	Classroom 301 Closet	W1	Damaged plaster	10	N			Y		
7	3	301A	Storage	Classroom 301 Closet	W2	Damaged plaster	10	N			Y		
8	3	301A	Storage	Classroom 301 Closet	W3	Damaged plaster	10	N			Y		
9	3	301A	Storage	Classroom 301 Closet	W4	Damaged plaster	10	N			Y		
10	3	303	Primary	Classroom 303	W1	Flaking paint on door. Cracking paint to the right of the blackboard	22	N			N		
11	3	303	Primary	Classroom 303	W2	Flaking paint at closet doors. Cracking paint by closet	10	N			N		
12	3	303	Primary	Classroom 303	W3	Flaking paint around windows, at trim below windows, and by radiator	35	Y			Y		
13	3	331A	Storage	Classroom 303 Closet	W1	Flaking paint at door and damaged plaster	40	N			Y		
14	3	331A	Storage	Classroom 303 Closet	W2	Flaking paint at wall	1	N			N		
15	3	331A	Storage	Classroom 303 Closet	W3	Damaged plaster	40	N			Y		
16	3	304	Primary	Classroom 304	W1	Flaking paint at blackboard trim, at doors, and at baseboards	65	N			N		
17	3	304	Primary	Classroom 304	W2	Flaking paint near closet and W1, and at baseboards	75	N			N		
18	3	304	Primary	Classroom 304	W3	Flaking paint at wall and baseboards	35	N			N		
19	3	304	Primary	Classroom 304	W4	Flaking paint at blackboard trim and baseboards	45	N			N		

20	3	304A	Storage	Classroom 304 Closet	W1	Damaged plaster	30	N			N		
21	3	304A	Storage	Classroom 304 Closet	W3	Damaged plaster at windows	5	N			N		
22	3	305	Primary	Classroom 305	W3	Flaking paint at sides of windows, below window 3, and at riser by window 3.	5	N			N	Posters	
23	3	305A	Primary	Classroom 305 Closet	Ceiling	Flaking paint at ceiling	2	N			N	Supplies, Cabinet, Bookshelf, Table	
24	3	305A	Primary	Classroom 305 Closet	W1	Flaking paint at wall and door	15	N			N	Supplies, Cabinet, Bookshelf, Table	
25	3	305A	Primary	Classroom 305 Closet	W2	Flaking paint at wall	50	N			N	Supplies, Cabinet, Bookshelf, Table	
26	3	305A	Primary	Classroom 305 Closet	W3	Flaking paint at wall	20	N			N	Supplies, Cabinet, Bookshelf, Table	
27	3	305A	Primary	Classroom 305 Closet	W4	Flaking paint at wall and door	160	N			N	Supplies, Cabinet, Bookshelf, Table	
28	3	307	Primary	Classroom 307	W2	Flaking paint debris on bulletin board sill and floor	5	N	Bulletin board sill and floor	5	N		
29	3	307	Primary	Classroom 307	W3	Flaking paint debris by radiator	5	N	Floor	5	N		
30	3	307A	Storage	Classroom 307 Closet	Ceiling	Flaking paint	20	N			N	Books, desks, supplies, boxes	
31	3	307A	Storage	Classroom 307 Closet	W1	Flaking paint	5	N			N	Books, desks, supplies, boxes	
32	3	307A	Storage	Classroom 307 Closet	W2	Flaking paint	50	N			N	Books, desks, supplies, boxes	
33	3	307A	Storage	Classroom 307 Closet	W3	Flaking paint	20	N			N	Books, desks, supplies, boxes	
34	3	307A	Storage	Classroom 307 Closet	W4	Flaking paint	100	N			N	Books, desks, supplies, boxes	

35	3	308	Primary	Classroom 308	W2	Flaking paint debris on bulletin board sill and floor	5	N	Bulletin board sill and floor	5	N		
36	3	308	Primary	Classroom 308	W3	Flaking paint at window trims and debris by radiator	15	Y	Floor	5	N		
37	3	308A	Storage	Classroom 308 Closet	W1	Flaking paint at door	5	N			N		
38	3	308A	Storage	Classroom 308 Closet	W2	Flaking paint at baseboards	5	N			N		
39	3	308A	Storage	Classroom 308 Closet	W3	Flaking paint at baseboards	5	N			N		
40	3	308A	Storage	Classroom 308 Closet	W4	Flaking paint at baseboards	5	N			N		
41	3	309	Primary	Classroom 309	W3	Flaking paint at radiator and debris below window 1	5	N	Floor, sill	5	N		
42	3	309A	Storage	Classroom 309 Closet	Ceiling	Flaking paint	100	N			N	Many books, supplies, boxes	
43	3	309A	Storage	Classroom 309 Closet	Floor	Flaking paint debris	50	N	Floor	50	N	Many books, supplies, boxes	
44	3	309A	Storage	Classroom 309 Closet	W1	Flaking paint	5	N			N	Many books, supplies, boxes	
45	3	309A	Storage	Classroom 309 Closet	W2	Flaking paint	20	N			N	Many books, supplies, boxes	
46	3	309A	Storage	Classroom 309 Closet	W3	Flaking paint	20	N			N	Many books, supplies, boxes	
47	3	309A	Storage	Classroom 309 Closet	W4	Flaking paint	50	N			N	Many books, supplies, boxes	
48	3	310	Primary	Classroom 310	W3	Flaking paint debris by radiator	2	N	Floor	2	N		
49	3	310A	Storage	Classroom 310 Closet	W3	Flaking paint at pipe and radiator, damaged plaster	30	N			Y		
50	3	311	Primary	Classroom 311	W3	Flaking paint debris by radiator	1	N	Floor	1	N		
51	3	311A	Storage	Classroom 311 Closet	W1	Damaged plaster	5	N			Y		
52	3	311A	Storage	Classroom 311 Closet	W3	Damaged plaster	5	N			Y		
53	3	312	Primary	Classroom 312	W3	Flaking paint behind radiator	10	N			N		
54	3	313	Primary	Classroom 313	Ceiling	Flaking paint	20	Y			N		
55	3	313	Primary	Classroom 313	W1	Flaking paint	50	N			N	Posters	
56	3	313	Primary	Classroom 313	W2	Flaking paint	40	N			N	Posters	

57	3	313	Primary	Classroom 313	W3	Flaking paint	100	N			N	Posters	
58	3	313A	Storage	Classroom 313 Closet	Ceiling	Flaking paint	10	N			N	Many supplies	
59	3	313A	Storage	Classroom 313 Closet	W1	Flaking paint	20	N			N	Many supplies	
60	3	313A	Storage	Classroom 313 Closet	W2	Flaking paint	10	N			N	Many supplies	
61	3	313A	Storage	Classroom 313 Closet	W3	Flaking paint	30	N			N	Many supplies	
62	3	313A	Storage	Classroom 313 Closet	W4	Flaking paint	10	N			N	Many supplies	
63	3	S31	Stairs, Fire Tower	Fire Tower near Classroom 302	Ceiling	Damaged plaster	40	N			Y		
64	3	S36	Stairs, Fire Tower	Fire Tower near Classroom 312	Ceiling	Damaged plaster	20	N			Y		
65	3	331	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Flaking paint at exhaust fan	5	N			N		
66	3	331	Student Restrooms - Female (4-12)	Girl's Restroom	Floor	Flaking paint debris at pipe by W3	5	N	Floor	5	N		
67	3	H320	Circulation (Hallway)	Hallway outside Classrooms 301 to 303	W3	Flaking paint behind radiator	20	N			N		
68	3	H319	Circulation (Hallway)	Hallway outside Classrooms 311 to 313	W1	Flaking paint behind radiator	20	N			N		
69	3	H318	Circulation (Hallway)	Hallway to Fire Tower near Classroom 302	W1	Flaking paint at door	15	N			N		
70	3	H318	Circulation (Hallway)	Hallway to Fire Tower near Classroom 302	W2	Flaking paint at door	15	N			N		
71	3	H317	Circulation (Hallway)	Hallway to Fire Tower near Classroom 312	W2	Flaking paint at door	15	N			N		
72	3	H317	Circulation (Hallway)	Hallway to Fire Tower near Classroom 312	W3	Flaking paint at door	15	N			N		
73	3	329	Administrative Office	Office 313A	W1	Damaged plaster	10	N			Y		
74	3	329	Administrative Office	Office 313A	W3	Flaking paint	30	N			N		
75	3	S34	Stairs	Stairwell near Classroom 311	W1	Flaking paint above door	3	N			N		
76	3	S34	Stairs	Stairwell near Classroom 311	W2	Cracking paint	15	N			N		
77	3	S34	Stairs	Stairwell near Classroom 311	W3	Flaking paint	40	N			N		

78	3	332A	Restrooms, Staff - Male/Female	Teacher' Lounge adjacent to Classroom 301 Restroom	W2	Flaking paint at pipe	2	N			N		
79	3	332A	Restrooms, Staff - Male/Female	Teacher' Lounge adjacent to Classroom 301 Restroom	W3	Flaking paint at sill	5	N			N		
80	3	332A	Restrooms, Staff - Male/Female	Teacher' Lounge adjacent to Classroom 301 Restroom	W4	Flaking paint at wall in copy room by radiator	5	N	Floor	1	N		
81	2	H214	Circulation (Hallway)	2nd Floor Hallway outside Auditorium	W2	Flaking paint behind radiator	20	N			N		
82	2	217	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Flaking paint at pipes	10	N			N		
83	2	203	Primary	Classroom 203	Ceiling	Flaking paint, damaged plaster near windows	15	Y			Y		
84	2	203	Primary	Classroom 203	W1	Flaking paint above closet door. Plaster damage	10	N			Y		
85	2	203	Primary	Classroom 203	W3	Flaking paint at window trim. Plaster damage	10	N			Y		
86	2	203B	Storage	Classroom 203 Closet	Ceiling	Flaking paint	20	N			N	Bookshelves, many supplies	
87	2	203B	Storage	Classroom 203 Closet	W1	Flaking paint	10	N			N	Bookshelves, many supplies	
88	2	203B	Storage	Classroom 203 Closet	W2	Flaking paint	20	N			N	Bookshelves, many supplies	
89	2	203B	Storage	Classroom 203 Closet	W3	Flaking paint	10	N			N	Bookshelves, many supplies	
90	2	203B	Storage	Classroom 203 Closet	W4	Flaking paint	10	N			N	Bookshelves, many supplies	
91	2	205	Primary	Classroom 205	W1	Flaking paint at wall and doors	20	N			N	Bookshelves, posters, supplies	
92	2	205	Primary	Classroom 205	W2	Flaking paint below bulletin board, on closet doors, and baseboards	20	N			N	Bookshelves, posters, supplies	
93	2	205	Primary	Classroom 205	W3	Flaking paint above windows	25	Y	Sill, Floor	3	Y	Bookshelves, posters, supplies	
94	2	205B	Storage	Classroom 205 Closet	Ceiling	Damaged plaster	5	N			Y		
95	2	205B	Storage	Classroom 205 Closet	W1	Flaking paint at pipe and wall	10	N			Y		

96	2	205B	Storage	Classroom 205 Closet	W2	Damaged plaster	5	N			Y		
97	2	205B	Storage	Classroom 205 Closet	W3	Flaking paint and pipe and radiator. Damaged plaster	30	N			Y		
98	2	205B	Storage	Classroom 205 Closet	W4	Damaged plaster	5	N			Y		
99	2	206A	Storage	Classroom 206 Closet	W1	Flaking paint at wall	10	N			N	Bookshelves, supplies	
100	2	206A	Storage	Classroom 206 Closet	W3	Flaking paint at wall	20	N			N	Bookshelves, supplies	
101	2	206A	Storage	Classroom 206 Closet	W4	Flaking paint at wall	20	N			N	Bookshelves, supplies	
102	2	207	Primary	Classroom 207	Ceiling	Flaking paint near windows	100	Y			N	Posters, bookshelves	
103	2	207	Primary	Classroom 207	W1	Flaking paint by entrance, and above blackboard	5	N			N	Posters, bookshelves	
104	2	207	Primary	Classroom 207	W2	Flaking paint on wall by computers	2	N			N	Posters, bookshelves	
105	2	207	Primary	Classroom 207	W3	Flaking paint above and below windows	80	Y			N	Posters, bookshelves	
106	2	207	Primary	Classroom 207	W4	Flaking paint at wall around bulletin board and on baseboard	20	N			N	Posters, bookshelves	
107	2	209	Primary	Classroom 209	W3	Flaking paint behind pipe at window 4	2	Y	Window 2 Sill	2	N	Posters	
108	2	209	Primary	Classroom 209	W4	Flaking paint at wall	2	N			N	Posters	
109	2	209B	Storage	Classroom 209 Closet	W1	Flaking paint at door	1	N			N	Bookshelves and supplies	
110	2	209B	Storage	Classroom 209 Closet	W3	Flaking paint at walls and pipe	40	N			N	Bookshelves and supplies	
111	2	210	Administrative Office	Counselor's Office 206A	W1	Flaking at wall and baseboards	25	N			Y	Posters	
112	2	210	Administrative Office	Counselor's Office 206A	W2	Flaking at wall and baseboards	25	N			Y	Posters	
113	2	210	Administrative Office	Counselor's Office 206A	W3	Flaking at wall and baseboards	35	N			Y	Posters	
114	2	210	Administrative Office	Counselor's Office 206A	W4	Flaking at wall and baseboards	50	N			Y	Posters	
115	2	S21	Stairs, Fire Tower	Fire Tower near Classroom 202	Ceiling	Damaged plaster	40	N			Y		
116	2	220	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Flaking paint at pipe	3	N			N		
117	2	H215	Circulation (Hallway)	Hallway outside Classrooms 201 to 203	W3	Flaking paint behind radiator	20	N			N		
118	2	H213	Circulation (Hallway)	Hallway outside Classrooms 207 to 209	W1	Flaking paint behind radiator	20	N			N		
119	2	H212	Circulation (Hallway)	Hallway to Fire Tower near Classroom 202	W1	Flaking paint at door	15	N			N		

120	2	H211	Circulation (Hallway)	Hallway to Fire Tower near Classroom 208	W3	Flaking paint at door	15	N			N		
121	2	H211	Circulation (Hallway)	Hallway to Fire Tower near Classroom 208	W4	Flaking paint at door	15	N			N		
122	2	201	IMC (Library)	Library 201	Ceiling	Flaking paint near windows	30	Y			N	Desks	
123	2	201	IMC (Library)	Library 201	W1	Flaking paint at baseboards	20	N			N	Desks	
124	2	201	IMC (Library)	Library 201	W2	Flaking paint at baseboards	20	N			N	Desks	
125	2	201	IMC (Library)	Library 201	W3	Flaking paint debris on sills. Flaking paint at baseboards	35	Y	Window sills	15	N	Desks	
126	2	201	IMC (Library)	Library 201	W4	Flaking paint at baseboards	20	N			N	Desks	
127	2	202	IMC (Library)	Library 202	Ceiling	Flaking paint near windows	30	Y			N	Desks	
128	2	202	IMC (Library)	Library 202	W1	Flaking paint at baseboards	20	N			N	Desks	
129	2	202	IMC (Library)	Library 202	W2	Flaking paint at baseboards	20	N			N	Desks	
130	2	202	IMC (Library)	Library 202	W3	Flaking paint debris on sills. Flaking paint at baseboards	35	Y	Window sills	15	N	Desks	
131	2	202	IMC (Library)	Library 202	W4	Flaking paint at baseboards	20	N			N	Desks	
132	2	204A	Administrative Office	Nurse's Office	W1	Flaking paint on pipe in bathroom	1	N			N		
133	2	204A	Administrative Office	Nurse's Office	W3	Flaking paint debris on floor and on pipe.	5	Y	Floor	5	N		
134	2	205A	Administrative Office	Office 205A	W1	Flaking paint at door	10	N			N		
135	2	205A	Administrative Office	Office 205A	W3	Flaking paint at wall	5	N			N		
136	2	205A	Administrative Office	Office 205A	W4	Flaking paint at wall	5	N			N		
137	2	209A	Administrative Office	Office 209A	Ceiling	Flaking paint and plaster damage	50	N			Y		
138	2	209A	Administrative Office	Office 209A	W1	Flaking paint and plaster damage	12	N			Y		
139	2	209A	Administrative Office	Office 209A	W2	Flaking paint and plaster damage	30	N			Y		
140	2	209A	Administrative Office	Office 209A	W3	Flaking paint and plaster damage	30	N			Y		
141	2	209A	Administrative Office	Office 209A	W4	Flaking paint and plaster damage	30	N			Y		
142	2	201C	Administrative Office	Office between Library 201 Closet and Speech Pathologist Office 201A (access from Speech Pathologist Office only)	W1	Flaking paint at wall	5	N			N		

143	2	201C	Administrative Office	Office between Library 201 Closet and Speech Pathologist Office 201A (access from Speech Pathologist Office only)	W4	Flaking paint at wall	15	N			N		
144	2	201A	Administrative Office	Speech Pathologist Office 201A	W1	Flaking paint at door.	5	N			N		
145	2	201A	Administrative Office	Speech Pathologist Office 201A	W4	Flaking paint at baseboards	15	N			N		
146	2	201D	Restrooms, Staff - Male/Female	Speech Pathologist Office 201A Restroom	Ceiling	Flaking paint near windows	5	Y			N	Many supplies	
147	2	201D	Restrooms, Staff - Male/Female	Speech Pathologist Office 201A Restroom	W2	Flaking paint debris on sill and floor.	3	Y	Floor, sill	3	N	Many supplies	
148	2	201E	Storage	Speech Pathologist Office 201A Storage Room	Ceiling	Flaking paint	50	Y			N	Many supplies	
149	2	201E	Storage	Speech Pathologist Office 201A Storage Room	Floor	Flaking paint debris	40	Y			N	Many supplies	
150	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W1	Flaking paint	50	Y			N	Many supplies	
151	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W2	Flaking paint	50	Y			N	Many supplies	
152	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W3	Flaking paint	50	Y			N	Many supplies	
153	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W4	Flaking paint	50	Y			N	Many supplies	
154	2	S24	Stairs	Stairwell near Classroom 207	W1	Flaking paint around door	10	N			N		
155	2	S24	Stairs	Stairwell near Classroom 207	W3	Flaking paint behind pipe	10	Y			N		
156	2	S24	Stairs	Stairwell near Classroom 207	W4	Flaking paint near ceiling	10	N			N		

157	2	220A	Storage	Storage Closet near Girl's Restroom	Ceiling	No access							
158	2	220A	Storage	Storage Closet near Girl's Restroom	Floor	No access							
159	2	220A	Storage	Storage Closet near Girl's Restroom	W1	No access							
160	2	220A	Storage	Storage Closet near Girl's Restroom	W2	No access							
161	2	220A	Storage	Storage Closet near Girl's Restroom	W3	No access							
162	2	220A	Storage	Storage Closet near Girl's Restroom	W4	No access							
163	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	Ceiling	Flaking paint at ceiling	20	N			N		
164	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	W2	Flaking paint	2	N			N		
165	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	W3	Flaking paint below window	5	N			N	Bookshelves	
166	2	204B	Restrooms, Staff - Male/Female	Teacher's Lounge 204 Restroom	W1	Flaking paint at door	5	N			N		
167	1	102	Administrative Office	Assistant Principal's Office 102	Ceiling	Flaking paint at ceiling	50	N			N		
168	1	102	Administrative Office	Assistant Principal's Office 102	W1	Flaking paint at wall and doors	30	N			N	Posters	
169	1	102	Administrative Office	Assistant Principal's Office 102	W2	Flaking paint at wall	5	N			N	Posters	
170	1	102	Administrative Office	Assistant Principal's Office 102	W3	Flaking paint around windows and behind radiator	40	N			N	Posters	
171	1	102	Administrative Office	Assistant Principal's Office 102	W4	Flaking and chipping paint at wall.	20	N			N	Posters	
172	1	112	Auditorium	Auditorium	W1	Flaking paint and damaged plaster	30	N			Y		
173	1	112	Auditorium	Auditorium	W2	Flaking paint and damaged plaster	30	N			Y		
174	1	112	Auditorium	Auditorium	W3	Flaking paint and damaged plaster	35	N			Y		
175	1	112	Auditorium	Auditorium	W4	Damaged plaster	20	N			Y		
176	1	112A	Auditorium	Auditorium Stage	Ceiling	Flaking paint at ceiling	20	N			N		
177	1	112A	Auditorium	Auditorium Stage	W3	Flaking paint near ceiling	10	N			N		
178	1	112A	Auditorium	Auditorium Stage	W4	Flaking paint	5	N			N		

179	1	104A	Administrative Office	BET Office	Ceiling	Flaking paint at ceiling	20	N			N		
180	1	104A	Administrative Office	BET Office	W1	Flaking paint on and near door.	6	N			N		
181	1	104A	Administrative Office	BET Office	W2	Flaking paint at wall	10	N			N		
182	1	104A	Administrative Office	BET Office	W3	Flaking paint at wall	5	N			N	Posters, desks	
183	1	104A	Administrative Office	BET Office	W4	Flaking paint at wall	10	N			N		
184	1	101A	Storage	Classroom 101 Closet	Ceiling	Flaking paint.	15	N			N		
185	1	101A	Storage	Classroom 101 Closet	W1	Flaking paint.	20	N			N		
186	1	101A	Storage	Classroom 101 Closet	W2	Flaking paint.	5	N			N		
187	1	101A	Storage	Classroom 101 Closet	W3	Flaking paint.	20	N			N		
188	1	101A	Storage	Classroom 101 Closet	W4	Flaking paint.	5	N			N		
189	1	101	Primary	Classroom 101	Ceiling	Damaged plaster at ceiling.	20	N			Y		
190	1	101	Primary	Classroom 101	W1	Flaking paint above and below blackboard and on door.	20	N			N		
191	1	101	Primary	Classroom 101	W3	Flaking paint around windows.	20	Y			N	Many posters, bookshelves, desks.	
192	1	101	Primary	Classroom 101	W4	Flaking paint above and below blackboard.	20	N			N		
193	1	103	Primary	Classroom 103	Ceiling	Flaking paint at ceiling	40	N			N		
194	1	103	Primary	Classroom 103	W1	Flaking paint near entrance and above white board.	15	N			N	Many supplies and posters	
195	1	103	Primary	Classroom 103	W2	Flaking paint above and below bulletin board	20	N			N	Many supplies and posters	
196	1	103	Primary	Classroom 103	W3	Flaking paint around windows	40	Y			N	Many supplies and posters	
197	1	103	Primary	Classroom 103	W4	Flaking paint at wall	5	N			N	Many supplies and posters	
198	1	103A	Storage	Classroom 103 Closet	Ceiling	Flaking paint	10	N			N	Many supplies, cabinets, shelving.	
199	1	103A	Storage	Classroom 103 Closet	W1	Flaking paint	2	N			N	Many supplies, cabinets, shelving.	

200	1	103A	Storage	Classroom 103 Closet	W2	Flaking paint	5	N			N	Many supplies, cabinets, shelving.
201	1	103A	Storage	Classroom 103 Closet	W3	Flaking paint	20	N			N	Many supplies, cabinets, shelving.
202	1	103A	Storage	Classroom 103 Closet	W4	Flaking paint	10	Y			N	Many supplies, cabinets, shelving.
203	1	104	Primary	Classroom 104	Ceiling	Flaking paint near windows	20	Y			N	
204	1	104	Primary	Classroom 104	W1	Flaking paint above and below blackboard, on door, and baseboards	30	N			N	
205	1	104	Primary	Classroom 104	W2	Flaking paint at wall and door.	15	N			N	
206	1	104	Primary	Classroom 104	W3	Flaking paint around windows.	10	Y			N	
207	1	104B	Storage	Classroom 104 Closet	Ceiling	Flaking paint at ceiling	20	N			N	
208	1	104B	Storage	Classroom 104 Closet	W1	Flaking paint at wall	20	N			N	
209	1	104B	Storage	Classroom 104 Closet	W3	Flaking paint at wall.	30	N			N	
210	1	104B	Storage	Classroom 104 Closet	W4	Flaking paint on pipe.	5	N	Floor	2	N	
211	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	Ceiling	Flaking paint	20	N			N	
212	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W1	Flaking paint	20	N			N	
213	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W2	Flaking paint	20	N			N	
214	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W3	Flaking paint	20	N			N	
215	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W4	Flaking paint	20	N			N	

216	1	106	Primary	Classroom 106	W1	Flaking paint on door, above door, and above blackboard	15	N			N	Many posters, desks, bookshelves, toys.	
217	1	106	Primary	Classroom 106	W3	Flaking paint around windows and on trim	10	Y			N	Many posters, desks, bookshelves, toys.	
218	1	106	Primary	Classroom 106	W4	Flaking paint above bulletin board	10	N			N	Many posters, desks, bookshelves, toys.	
219	1	106A	Storage	Classroom 106 Closet	Ceiling	Flaking paint at ceiling	30	Y			Y	Cabinets, supplies	
220	1	106A	Storage	Classroom 106 Closet	W2	Flaking paint at wall	20	Y			Y	Cabinets, supplies	
221	1	107	Primary	Classroom 107	Ceiling	Damages plaster	10	N			Y		
222	1	107	Primary	Classroom 107	W1	Flaking paint on doors	20	N			N		
223	1	107	Primary	Classroom 107	W3	Flaking paint on baseboards and behind radiator	20	N			N	Desks, bookshelves	
224	1	108	Primary	Classroom 108	W1	Flaking paint on wall and door	10	N			N		
225	1	108	Primary	Classroom 108	W2	Flaking paint on baseboard	15	N			N		
226	1	108	Primary	Classroom 108	W3	Flaking paint below windows and behind radiator	30	Y			N		
227	1	108B	Storage	Classroom 108 Closet	Ceiling	Cracking paint at ceiling	100	N			N	Many supplies	
228	1	108B	Storage	Classroom 108 Closet	W3	Flaking paint	5	N			N	Many supplies	
229	1	108B	Storage	Classroom 108 Closet	W4	Flaking paint on pipe	2	N			N	Many supplies	
230	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	Ceiling	Flaking paint at ceiling	10	N			N		
231	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W1	Flaking paint at wall and door	20	N			N		
232	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W2	Flaking paint at wall	5	N			N		
233	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W3	Flaking paint at wall	30	N			N		
234	1	111	Storage	Closet at rear of Auditorium	Ceiling	No access							

235	1	111	Storage	Closet at rear of Auditorium	Floor	No access								
236	1	111	Storage	Closet at rear of Auditorium	W1	No access								
237	1	111	Storage	Closet at rear of Auditorium	W2	No access								
238	1	111	Storage	Closet at rear of Auditorium	W3	No access								
239	1	111	Storage	Closet at rear of Auditorium	W4	No access								
240	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	Ceiling	Flaking paint	40	Y			Y		Cleaning supplies, shelves, locker.	
241	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W1	Flaking paint	10	N			N		Cleaning supplies, shelves, locker.	
242	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W2	Flaking paint	10	N			N		Cleaning supplies, shelves, locker.	
243	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W3	Flaking paint	20	N			N		Cleaning supplies, shelves, locker.	
244	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W4	Flaking paint	20	N			N		Cleaning supplies, shelves, locker.	
245	1	S16	Stairs, Fire Tower	Fire Tower near Classroom 107	Ceiling	Damaged plaster at ceiling	20	N			Y			
246	1	114	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Flaking paint at ceiling	15	Y			N			
247	1	114	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Flaking paint at wall.	20	Y			N			
248	1	H16	Circulation (Hallway)	Hallway from Classroom 104 to Teacher's Lounge	W2	Flaking paint behind radiators	20	N			N			
249	1	H18	Circulation (Hallway)	Hallway outside Classrooms 101 to 103	Ceiling	Cracking paint at ceiling.	20	N			N			
250	1	H18	Circulation (Hallway)	Hallway outside Classrooms 101 to 103	W3	Flaking paint at pipe near S15 and behind radiators	25	N			Y			
251	1	H15	Circulation (Hallway)	Hallway outside Classrooms 106 to 108	W1	Flaking paint behind radiators	20	N			N			
252	1	H17	Circulation (Hallway)	Hallway to BET Office	Ceiling	Flaking paint at ceiling	10	N			N			

253	1	H17	Circulation (Hallway)	Hallway to BET Office	W1	Flaking paint at wall	200	N			N		
254	1	H17	Circulation (Hallway)	Hallway to BET Office	W3	Flaking paint at wall	30	N			N	Poster	
255	1	115	Administrative Office	Main Office	Ceiling	Flaking paint near windows.	15	Y			N		
256	1	115	Administrative Office	Main Office	W3	Flaking paint near desk and behind radiator.	20	N			N	Desk.	
257	1	108A	Restrooms, Staff - Male	Men's Restroom 109	W3	Flaking paint behind radiator	5	N			N		
258	1	108A	Restrooms, Staff - Male	Men's Restroom 109	W4	Flaking paint	5	N			N		
259	1	115B	Administrative Office	Principal's Office	W3	Flaking paint at window sill.	2	N			N	Curtains	
260	1	115C	Restrooms, Staff - Male/Female	Principal's Office Restroom	W1	Cracking paint	5	N			N		
261	1	115C	Restrooms, Staff - Male/Female	Principal's Office Restroom	W2	Cracking paint	5	N			N		
262	1	S13	Stairs	Stairwell adjacent Classroom 103	W1	Spalling paint from ongoing steam leak.	50	Y	Floor, radiator cover	10	N		
263	1	S13	Stairs	Stairwell adjacent Classroom 103	W2	Flaking paint	40	Y			N		
264	1	S14	Stairs	Stairwell adjacent to Classroom 106	W1	Flaking paint at wall toward basement	50	Y			N		
265	1	S17	Stairs	Stairwell near Classroom 108	Ceiling	Flaking paint near Exit.	10	Y			N		
266	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W1	Flaking paint	10	N			N		
267	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W2	Flaking paint	5	N			N		
268	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W3	Flaking paint	20	N			N		
269	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W4	Flaking paint	5	N			N		
270	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	Ceiling	Flaking paint	100	Y			N	Many supplies	
271	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W1	Flaking paint	100	Y			N	Many supplies	
272	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W2	Flaking paint	100	Y			N	Many supplies	
273	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W3	Flaking paint	100	Y			N	Many supplies	

274	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W4	Flaking paint	100	Y			N	Many supplies	
275	1	119	Restrooms, Staff - Female	Women's Restroom 100	Ceiling	Flaking paint and plaster damage	15	N			Y		
276	0	0B3	Primary	Art Room	Ceiling	Flaking paint at ceiling, pipes, and ducts.	800	N			N	Desks	
277	0	0B3	Primary	Art Room	W2	Flaking paint around windows & trim.	20	Y			N	Bookshelves, posters	
278	0	001	Student Restrooms - Male (4-12)	Basement Boy's Restroom	Ceiling	Flaking paint at ceiling and pipe	200	Y			N		
279	0	001	Student Restrooms - Male (4-12)	Basement Boy's Restroom	W1	Flaking paint on pipe.	10	N			N		
280	0	012	Student Restrooms - Female (4-12)	Basement Girl's Restroom	Ceiling	Flaking paint	50	Y			N		
281	0	012	Student Restrooms - Female (4-12)	Basement Girl's Restroom	W4	Flaking paint at pipe	5	N			N		
282	0	001A	Storage	Classroom 0B1 Large Closet	Ceiling	Flaking paint	40	Y			N	Many supplies	
283	0	001A	Storage	Classroom 0B1 Large Closet	W1	Flaking paint	10	N			N	Many supplies	
284	0	001A	Storage	Classroom 0B1 Large Closet	W2	Flaking paint	10	N			N	Many supplies	
285	0	001A	Storage	Classroom 0B1 Large Closet	W3	Flaking paint	20	N			N	Many supplies	
286	0	001A	Storage	Classroom 0B1 Large Closet	W4	Flaking paint	20	Y			N	Many supplies	
287	0	0B2B	Storage	Classroom 0B2 Large Closet	W1	Flaking paint	20	Y			N	Many supplies	
288	0	0B2A	Storage	Classroom 0B2 Small Closet	W1	Flaking paint at wall and door.	10	N			N	Many supplies	
289	0	0B1	Primary	Classroom B1	W1	Flaking paint at closet doors	10	N			N		
290	0	0B1	Primary	Classroom B1	W2	Damaged plaster	5	N			N		
291	0	0B1	Primary	Classroom B1	W3	Flaking paint near windows	5	N			N		
292	0	0B1	Primary	Classroom B1	W4	Damaged plaster	5	N			N		
293	0	001B	Storage	Classroom B1 Small Closet	Ceiling	Cracking paint	10	N			N		
294	0	001B	Storage	Classroom B1 Small Closet	W1	Damaged plaster	5	N			Y	Supplies	
295	0	0B2	Primary	Classroom B2	Ceiling	Flaking paint	10	N			N		
296	0	0B2	Primary	Classroom B2	W1	Flaking paint	5	N			N		
297	0	0B2	Primary	Classroom B2	W2	Flaking paint	5	N			N		
298	0	0B2	Primary	Classroom B2	W3	Flaking paint at windows and columns	20	Y			N		
299	0	0B2	Primary	Classroom B2	W4	Flaking paint	10	N			N		

300	0	0B4	Gymnasium - Intermediate Middle	Gym	Ceiling	Flaking paint at ceiling and ducts	500	N			N		
301	0	0B4	Gymnasium - Intermediate Middle	Gym	W3	Flaking paint at window trim and pipes	30	Y			N		
302	0	008B	Administrative Office	Gym Office	Ceiling	Flaking paint at ceiling near windows	5	Y			N		
303	0	008B	Administrative Office	Gym Office	W2	Flaking paint at window trim	5	Y			N		
304	0	008A	Storage	Gym Storage Room	W1	Flaking paint at door	10	N			N		
305	0	H01	Circulation (Hallway)	Hallway outside Classrooms B1-B2	Ceiling	Flaking paint on ceiling above ductwork and near Start S17	100	N			N		
306	0	H02	Circulation (Hallway)	Hallway outside Gym	Ceiling	Flaking paint on deck above ductwork	500	N			N		
307	0	H02	Circulation (Hallway)	Hallway outside Gym	W1	Flaking paint at pipe.	5	N			N		
308	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	Ceiling	Flaking paint at ceiling by exit to outdoors	25	Y			N		
309	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	W2	Flaking paint at wall across from Girls Restroom	10	Y	Floor	5	N		
310	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	W3	Flaking paint at wall across from Girls Restroom and at window trim.	15	Y	Floor	5	N		
311	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	W4	Flaking paint at pipe by exit to outdoors	5	N			N		
312	0	011A	Kitchen	Kitchen	W3	Flaking paint near window behind freezer	10	Y			N	Freezer	
313	0	011B	Administrative Office	Kitchen Office	Ceiling	Flaking paint	50	N			N	Supplies, Cabinets, Shelves	
314	0	011B	Administrative Office	Kitchen Office	W2	Flaking paint	15	N			N	Supplies, Cabinets, Shelves	
315	0	011B	Administrative Office	Kitchen Office	W3	Flaking paint	20	N			N	Supplies, Cabinets, Shelves	
316	0	011B	Administrative Office	Kitchen Office	W4	Flaking paint	20	N			N	Supplies, Cabinets, Shelves	
317	0	0B5	Cafeteria (Dining Area)	Logan Cafe 2	Ceiling	Spalling paint at concrete ceiling beam	5	Y			N		
318	0	0B5	Cafeteria (Dining Area)	Logan Cafe 2	W2	Spalling paint near wall 3	10	Y			N		
319	0	0B5	Cafeteria (Dining Area)	Logan Cafe 2	W3	Flaking paint	10	Y			N		
320	0	010	Storage	Logan Cafe 2 Small Closet	Ceiling	Damaged plaster	10	N			Y		
321	0	010	Storage	Logan Cafe 2 Small Closet	W1	Flaking paint behind pipe	5	N			N		

Appendix B. EPA Checklist Table

Task ID	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
1	3	330	Student Restrooms - Male (4-12)	Boy's Restroom	Floor	Chipped paint at floor	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	3 RRP, 1 Colormetric		Jackie Neiman, Industrial Hygienist	10/1/18
2	3	330	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Flaking paint at radiator cover	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/1/18
3	3	301	Primary	Classroom 301	Ceiling	Flaking paint at ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	8 RRP, 1 Colormetric		Jackie Neiman, Industrial Hygienist	11/13/18
4	3	301	Primary	Classroom 301	W3	Flaking paint around windows	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	11/13/18
5	3	301	Primary	Classroom 301	W4	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	11/13/18
6	3	301A	Storage	Classroom 301 Closet	W1	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	2 RRP, 1 Colormetric		Jackie Neiman, Industrial Hygienist	11/13/18
7	3	301A	Storage	Classroom 301 Closet	W2	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	11/13/18
8	3	301A	Storage	Classroom 301 Closet	W3	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	11/13/18
9	3	301A	Storage	Classroom 301 Closet	W4	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	11/13/18
10	3	303	Primary	Classroom 303	W1	Flaking paint on door. Cracking paint to the right of the blackboard	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	10 RRP, 1 Colormetric		Jackie Neiman, Industrial Hygienist	10/4/18
11	3	303	Primary	Classroom 303	W2	Flaking paint at closet doors. Cracking paint by closet	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/4/18
12	3	303	Primary	Classroom 303	W3	Flaking paint around windows, at trim below windows, and by radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/4/18
13	3	331A	Storage	Classroom 303 Closet	W1	Flaking paint at door and damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	10 RRP, 1 Colormetric		Jackie Neiman, Industrial Hygienist	10/4/18
14	3	331A	Storage	Classroom 303 Closet	W2	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/4/18
15	3	331A	Storage	Classroom 303 Closet	W3	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/4/18
16	3	304	Primary	Classroom 304	W1	Flaking paint at blackboard trim, at doors, and at baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	11 RRP, 1 Colormetric		Jackie Neiman, Industrial Hygienist	10/1/18
17	3	304	Primary	Classroom 304	W2	Flaking paint near closet and W1, and at baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/1/18
18	3	304	Primary	Classroom 304	W3	Flaking paint at wall and baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/1/18
19	3	304	Primary	Classroom 304	W4	Flaking paint at blackboard trim and baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/1/18
20	3	304A	Storage	Classroom 304 Closet	W1	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	8 RRP, 1 Colormetric		Jackie Neiman, Industrial Hygienist	10/4/18
21	3	304A	Storage	Classroom 304 Closet	W3	Damaged plaster at windows	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/4/18
22	3	305	Primary	Classroom 305	W3	Flaking paint at sides of windows, below window 3, and at riser by window 3.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	2 RRP, 1 Colormetric		Jackie Neiman, Industrial Hygienist	10/4/18
23	3	305A	Primary	Classroom 305 Closet	Ceiling	Flaking paint at ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	3 RRP, Colormetric		Jackie Neiman, Industrial Hygienist	10/4/18
24	3	305A	Primary	Classroom 305 Closet	W1	Flaking paint at wall and door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/4/18
25	3	305A	Primary	Classroom 305 Closet	W2	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/4/18
26	3	305A	Primary	Classroom 305 Closet	W3	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/4/18
27	3	305A	Primary	Classroom 305 Closet	W4	Flaking paint at wall and door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/4/18
28	3	307	Primary	Classroom 307	W2	Flaking paint debris on bulletin board sill and floor	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	6 RRP, 1 Colormetric		Jackie Neiman, Industrial Hygienist	10/9/18
29	3	307	Primary	Classroom 307	W3	Flaking paint debris by radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/9/18
30	3	307A	Storage	Classroom 307 Closet	Ceiling	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	3 RRP, 1 Colormetric		Jackie Neiman, Industrial Hygienist	10/9/18
31	3	307A	Storage	Classroom 307 Closet	W1	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/9/18
32	3	307A	Storage	Classroom 307 Closet	W2	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/9/18
33	3	307A	Storage	Classroom 307 Closet	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/9/18
34	3	307A	Storage	Classroom 307 Closet	W4	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/9/18
35	3	308	Primary	Classroom 308	W2	Flaking paint debris on bulletin board sill and floor	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	6 RRP, 1 Colormetric		Jackie Neiman, Industrial Hygienist	10/11/18
36	3	308	Primary	Classroom 308	W3	Flaking paint at window trims and debris by radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/11/18
37	3	308A	Storage	Classroom 308 Closet	W1	Flaking paint at door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	11 RRP, 1 Colormetric		Jackie Neiman, Industrial Hygienist	10/11/18
38	3	308A	Storage	Classroom 308 Closet	W2	Flaking paint at baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/11/18
39	3	308A	Storage	Classroom 308 Closet	W3	Flaking paint at baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/11/18
40	3	308A	Storage	Classroom 308 Closet	W4	Flaking paint at baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above		Jackie Neiman, Industrial Hygienist	10/11/18

41	3	309	Primary	Classroom 309	W3	Flaking paint at radiator and debris below window 1	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	2 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/12/18
42	3	309A	Storage	Classroom 309 Closet	Ceiling	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	3 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/12/18
43	3	309A	Storage	Classroom 309 Closet	Floor	Flaking paint debris	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/12/18
44	3	309A	Storage	Classroom 309 Closet	W1	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/12/18
45	3	309A	Storage	Classroom 309 Closet	W2	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/12/18
46	3	309A	Storage	Classroom 309 Closet	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/12/18
47	3	309A	Storage	Classroom 309 Closet	W4	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/12/18
48	3	310	Primary	Classroom 310	W3	Flaking paint debris by radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	2 RRP, 2 Colormetric	Jackie Neiman, Industrial Hygienist	10/17/18
49	3	310A	Storage	Classroom 310 Closet	W3	Flaking paint at pipe and radiator, damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 2 Colormetric	Jackie Neiman, Industrial Hygienist	10/17/18
50	3	311	Primary	Classroom 311	W3	Flaking paint debris by radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	2 RRP, 2 Colormetric	Jackie Neiman, Industrial Hygienist	10/23/18
51	3	311A	Storage	Classroom 311 Closet	W1	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/23/18
52	3	311A	Storage	Classroom 311 Closet	W3	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/23/18
53	3	312	Primary	Classroom 312	W3	Flaking paint behind radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	1 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/16/18
54	3	313	Primary	Classroom 313	Ceiling	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	8 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/16/18
55	3	313	Primary	Classroom 313	W1	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18
56	3	313	Primary	Classroom 313	W2	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18
57	3	313	Primary	Classroom 313	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18
58	3	313A	Storage	Classroom 313 Closet	Ceiling	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/19/18
59	3	313A	Storage	Classroom 313 Closet	W1	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/19/18
60	3	313A	Storage	Classroom 313 Closet	W2	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/19
61	3	313A	Storage	Classroom 313 Closet	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/19/18
62	3	313A	Storage	Classroom 313 Closet	W4	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	
63	3	S31	Stairs, Fire Tower	Fire Tower near Classroom 302	Ceiling	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	1 RRP	Jackie Neiman, Industrial Hygienist	10/1/18
64	3	S36	Stairs, Fire Tower	Fire Tower near Classroom 312	Ceiling	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	1 RRP	Jackie Neiman, Industrial Hygienist	10/1/18
65	3	331	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Flaking paint at exhaust fan	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	2 RRP	Jackie Neiman, Industrial Hygienist	10/2/18
66	3	331	Student Restrooms - Female (4-12)	Girl's Restroom	Floor	Flaking paint debris at pipe by W3	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/2/18
67	3	H320	Circulation (Hallway)	Hallway outside Classrooms 301 to 303	W3	Flaking paint behind radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	3 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	9/14/18
68	3	H319	Circulation (Hallway)	Hallway outside Classrooms 311 to 313	W1	Flaking paint behind radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/14/18
69	3	H318	Circulation (Hallway)	Hallway to Fire Tower near Classroom 302	W1	Flaking paint at door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/14/18
70	3	H318	Circulation (Hallway)	Hallway to Fire Tower near Classroom 302	W2	Flaking paint at door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/14/18
71	3	H317	Circulation (Hallway)	Hallway to Fire Tower near Classroom 312	W2	Flaking paint at door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/14/18
72	3	H317	Circulation (Hallway)	Hallway to Fire Tower near Classroom 312	W3	Flaking paint at door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/14/18
73	3	329	Administrative Office	Office 313A	W1	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/22/18
74	3	329	Administrative Office	Office 313A	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/22/18
75	3	S34	Stairs	Stairwell near Classroom 311	W1	Flaking paint above door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	5 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/9/18
76	3	S34	Stairs	Stairwell near Classroom 311	W2	Cracking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/9/18
77	3	S34	Stairs	Stairwell near Classroom 311	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/9/18
78	3	332A	Restrooms, Staff - Male/Female	Teacher Lounge adjacent to Classroom 301 Restroom	W2	Flaking paint at pipe	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	12 RRP, 2 Colormetric	Jackie Neiman, Industrial Hygienist	10/4/18
79	3	332A	Restrooms, Staff - Male/Female	Teacher Lounge adjacent to Classroom 301 Restroom	W3	Flaking paint at sill	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/4/18
80	3	332A	Restrooms, Staff - Male/Female	Teacher Lounge adjacent to Classroom 301 Restroom	W4	Flaking paint at wall in copy room by radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/4/18
81	2	H214	Circulation (Hallway)	2nd Floor Hallway outside Auditorium	W2	Flaking paint behind radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	1 RRP	Jackie Neiman, Industrial Hygienist	8/23/18

82	2	217	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Flaking paint at pipes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	3 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	8/23/18
83	2	203	Primary	Classroom 203	Ceiling	Flaking paint, damaged plaster near windows	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	13 RRP, 2 Colormetric	Jackie Neiman, Industrial Hygienist	8/23/18
84	2	203	Primary	Classroom 203	W1	Flaking paint above closet door. Plaster damage	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/23/18
85	2	203	Primary	Classroom 203	W3	Flaking paint at window trim. Plaster damage	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/23/18
86	2	203B	Storage	Classroom 203 Closet	Ceiling	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	3 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	8/23/18
87	2	203B	Storage	Classroom 203 Closet	W1	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/23/18
88	2	203B	Storage	Classroom 203 Closet	W2	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/23/18
89	2	203B	Storage	Classroom 203 Closet	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/23/18
90	2	203B	Storage	Classroom 203 Closet	W4	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/23/18
91	2	205	Primary	Classroom 205	W1	Flaking paint at wall and doors	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	8/21/18
92	2	205	Primary	Classroom 205	W2	Flaking paint below bulletin board, on closet doors, and baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	2 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	8/21/18
93	2	205	Primary	Classroom 205	W3	Flaking paint above windows	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP	Jackie Neiman, Industrial Hygienist	8/21/18
94	2	205B	Storage	Classroom 205 Closet	Ceiling	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	2 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	8/21/18
95	2	205B	Storage	Classroom 205 Closet	W1	Flaking paint at pipe and wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/21/18
96	2	205B	Storage	Classroom 205 Closet	W2	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/21/18
97	2	205B	Storage	Classroom 205 Closet	W3	Flaking paint and pipe and radiator. Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/21/18
98	2	205B	Storage	Classroom 205 Closet	W4	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/21/18
99	2	206A	Storage	Classroom 206 Closet	W1	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	9 RRP, 1 Colormetric	Isa Haj, Industrial Hygienist	8/18/18
100	2	206A	Storage	Classroom 206 Closet	W3	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/18/18
101	2	206A	Storage	Classroom 206 Closet	W4	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/18/18
102	2	207	Primary	Classroom 207	Ceiling	Flaking paint near windows	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	13 RRP, 2 Colormetric	Jackie Neiman, Industrial Hygienist	8/27/18
103	2	207	Primary	Classroom 207	W1	Flaking paint by entrance, and above blackboard	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/27/18
104	2	207	Primary	Classroom 207	W2	Flaking paint on wall by computers	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/27/18
105	2	207	Primary	Classroom 207	W3	Flaking paint above and below windows	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/27/18
106	2	207	Primary	Classroom 207	W4	Flaking paint at wall around bulletin board and on baseboard	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/27/18
107	2	209	Primary	Classroom 209	W3	Flaking paint behind pipe at window 4	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	8/23/18
108	2	209	Primary	Classroom 209	W4	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/23/18
109	2	209B	Storage	Classroom 209 Closet	W1	Flaking paint at door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	8 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	8/23/18
110	2	209B	Storage	Classroom 209 Closet	W3	Flaking paint at walls and pipe	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/23/18
111	2	210	Administrative Office	Counselor's Office 206A	W1	Flaking at wall and baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	12 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/1/18
112	2	210	Administrative Office	Counselor's Office 206A	W2	Flaking at wall and baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/1/18
113	2	210	Administrative Office	Counselor's Office 206A	W3	Flaking at wall and baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/1/18
114	2	210	Administrative Office	Counselor's Office 206A	W4	Flaking at wall and baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/1/18
115	2	S21	Stairs, Fire Tower	Fire Tower near Classroom 202	Ceiling	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/27/18
116	2	220	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Flaking paint at pipe	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	1 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	8/23/18
117	2	H215	Circulation (Hallway)	Hallway outside Classrooms 201 to 203	W3	Flaking paint behind radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	5 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	8/27/18
118	2	H213	Circulation (Hallway)	Hallway outside Classrooms 207 to 209	W1	Flaking paint behind radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/27/18
119	2	H212	Circulation (Hallway)	Hallway to Fire Tower near Classroom 202	W1	Flaking paint at door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/27/18
120	2	H211	Circulation (Hallway)	Hallway to Fire Tower near Classroom 208	W3	Flaking paint at door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/27/18
121	2	H211	Circulation (Hallway)	Hallway to Fire Tower near Classroom 208	W4	Flaking paint at door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/27/18
122	2	201	IMC (Library)	Library 201	Ceiling	Flaking paint near windows	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	16 RRP, 2 Colormetric	Jackie Neiman, Industrial Hygienist	8/31/18
123	2	201	IMC (Library)	Library 201	W1	Flaking paint at baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/31/18
124	2	201	IMC (Library)	Library 201	W2	Flaking paint at baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/31/18
125	2	201	IMC (Library)	Library 201	W3	Flaking paint debris on sills. Flaking paint at baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/31/18

126	2	201	IMC (Library)	Library 201	W4	Flaking paint at baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/31/18
127	2	202	IMC (Library)	Library 202	Ceiling	Flaking paint near windows	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/31/18
128	2	202	IMC (Library)	Library 202	W1	Flaking paint at baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/31/18
129	2	202	IMC (Library)	Library 202	W2	Flaking paint at baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/31/18
130	2	202	IMC (Library)	Library 202	W3	Flaking paint debris on sills. Flaking paint at baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/31/18
131	2	202	IMC (Library)	Library 202	W4	Flaking paint at baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman		Jackie Neiman, Industrial Hygienist	8/31/18
132	2	204A	Administrative Office	Nurse's Office	W1	Flaking paint on pipe in bathroom	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	8/23/18
133	2	204A	Administrative Office	Nurse's Office	W3	Flaking paint debris on floor and on pipe.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/23/18
134	2	205A	Administrative Office	Office 205A	W1	Flaking paint at door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	12 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	9/18/18
135	2	205A	Administrative Office	Office 205A	W3	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/18/18
136	2	205A	Administrative Office	Office 205A	W4	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/18/18
137	2	209A	Administrative Office	Office 209A	Ceiling	Flaking paint and plaster damage	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	7 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	9/13/18
138	2	209A	Administrative Office	Office 209A	W1	Flaking paint and plaster damage	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/13/18
139	2	209A	Administrative Office	Office 209A	W2	Flaking paint and plaster damage	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/13/18
140	2	209A	Administrative Office	Office 209A	W3	Flaking paint and plaster damage	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/13/18
141	2	209A	Administrative Office	Office 209A	W4	Flaking paint and plaster damage	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/13/18
142	2	201C	Administrative Office	Office between Library 201 Closet and Speech Pathologist Office 201A (access from Speech Pathologist Office only)	W1	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/26/18
143	2	201C	Administrative Office	Office between Library 201 Closet and Speech Pathologist Office 201A (access from Speech Pathologist Office only)	W4	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/26/18
144	2	201A	Administrative Office	Speech Pathologist Office 201A	W1	Flaking paint at door.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	6 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/26/18
145	2	201A	Administrative Office	Speech Pathologist Office 201A	W4	Flaking paint at baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/26/18
146	2	201D	Restrooms, Staff - Male/Female	Speech Pathologist Office 201A Restroom	Ceiling	Flaking paint near windows	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	6 RRP, 3 Colormetric	Jackie Neiman, Industrial Hygienist	11/5/18
147	2	201D	Restrooms, Staff - Male/Female	Speech Pathologist Office 201A Restroom	W2	Flaking paint debris on sill and floor.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/5/18
148	2	201E	Storage	Speech Pathologist Office 201A Storage Room	Ceiling	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	3 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/5/18
149	2	201E	Storage	Speech Pathologist Office 201A Storage Room	Floor	Flaking paint debris	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/5/18
150	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W1	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/5/18
151	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W2	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/5/18
152	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/5/18
153	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W4	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/5/18
154	2	S24	Stairs	Stairwell near Classroom 207	W1	Flaking paint around door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	5 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/9/18
155	2	S24	Stairs	Stairwell near Classroom 207	W3	Flaking paint behind pipe	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/9/18
156	2	S24	Stairs	Stairwell near Classroom 207	W4	Flaking paint near ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/9/18
157	2	220A	Storage	Storage Closet near Girl's Restroom	Ceiling	No access	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	1 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	9/13/18
158	2	220A	Storage	Storage Closet near Girl's Restroom	Floor	No access	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/13/18
159	2	220A	Storage	Storage Closet near Girl's Restroom	W1	No access	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/13/18
160	2	220A	Storage	Storage Closet near Girl's Restroom	W2	No access	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/13/18
161	2	220A	Storage	Storage Closet near Girl's Restroom	W3	No access	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/13/18
162	2	220A	Storage	Storage Closet near Girl's Restroom	W4	No access	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/13/18
163	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	Ceiling	Flaking paint at ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	9/14/18

164	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	W2	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/14/18
165	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	W3	Flaking paint below window	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/14/18
166	2	204B	Restrooms, Staff-Male/Female	Teacher's Lounge 204 Restroom	W1	Flaking paint at door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	1 RRP, 1 Colorimetric	Jackie Neiman, Industrial Hygienist	9/14/18
167	1	102	Administrative Office	Assistant Principal's Office 102	Ceiling	Flaking paint at ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	8 RRP, 1 Colorimetric	Jackie Neiman, Industrial Hygienist	11/7/18
168	1	102	Administrative Office	Assistant Principal's Office 102	W1	Flaking paint at wall and doors	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/7/18
169	1	102	Administrative Office	Assistant Principal's Office 102	W2	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/7/18
170	1	102	Administrative Office	Assistant Principal's Office 102	W3	Flaking paint around windows and behind radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/7/18
171	1	102	Administrative Office	Assistant Principal's Office 102	W4	Flaking and chipping paint at wall.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/7/18
172	1	112	Auditorium	Auditorium	W1	Flaking paint and damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of Below	Jackie Neiman, Industrial Hygienist	9/17/18
173	1	112	Auditorium	Auditorium	W2	Flaking paint and damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colorimetric	Jackie Neiman, Industrial Hygienist	9/17/18
174	1	112	Auditorium	Auditorium	W3	Flaking paint and damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/17/18
175	1	112	Auditorium	Auditorium	W4	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/17/18
176	1	112A	Auditorium	Auditorium Stage	Ceiling	Flaking paint at ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colorimetric	Jackie Neiman, Industrial Hygienist	9/17/18
177	1	112A	Auditorium	Auditorium Stage	W3	Flaking paint near ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/17/18
178	1	112A	Auditorium	Auditorium Stage	W4	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/17/18
179	1	104A	Administrative Office	BET Office	Ceiling	Flaking paint at ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colorimetric	Jackie Neiman, Industrial Hygienist	11/1/18
180	1	104A	Administrative Office	BET Office	W1	Flaking paint on and near door.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/1/18
181	1	104A	Administrative Office	BET Office	W2	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/1/18
182	1	104A	Administrative Office	BET Office	W3	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/1/18
183	1	104A	Administrative Office	BET Office	W4	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/1/18
184	1	101A	Storage	Classroom 101 Closet	Ceiling	Flaking paint.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	9 RRP, 1 Colorimetric	Isa Haj, Industrial Hygienist	8/13/18
185	1	101A	Storage	Classroom 101 Closet	W1	Flaking paint.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/13/18
186	1	101A	Storage	Classroom 101 Closet	W2	Flaking paint.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/13/18
187	1	101A	Storage	Classroom 101 Closet	W3	Flaking paint.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/13/18
188	1	101A	Storage	Classroom 101 Closet	W4	Flaking paint.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/13/18
189	1	101	Primary	Classroom 101	Ceiling	Damaged plaster at ceiling.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	13 RRP	Jackie Neiman, Industrial Hygienist	7/31/18
190	1	101	Primary	Classroom 101	W1	Flaking paint above and below blackboard and on door.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	7/31/18
191	1	101	Primary	Classroom 101	W3	Flaking paint around windows.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	7/31/18
192	1	101	Primary	Classroom 101	W4	Flaking paint above and below blackboard.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colorimetric	Jackie Neiman, Industrial Hygienist	7/31/18
193	1	103	Primary	Classroom 103	Ceiling	Flaking paint at ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	13 RRP, 1 Colorimetric	Jackie Neiman, Industrial Hygienist	8/6/18
194	1	103	Primary	Classroom 103	W1	Flaking paint near entrance and above white board.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/6/18
195	1	103	Primary	Classroom 103	W2	Flaking paint above and below bulletin board	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/6/18
196	1	103	Primary	Classroom 103	W3	Flaking paint around windows	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/6/18
197	1	103	Primary	Classroom 103	W4	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/6/18
198	1	103A	Storage	Classroom 103 Closet	Ceiling	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of below	Jackie Neiman, Industrial Hygienist	8/6/18
199	1	103A	Storage	Classroom 103 Closet	W1	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colorimetric	Jackie Neiman, Industrial Hygienist	8/6/18
200	1	103A	Storage	Classroom 103 Closet	W2	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	1 RRP	Jackie Neiman, Industrial Hygienist	8/6/18
201	1	103A	Storage	Classroom 103 Closet	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP	Jackie Neiman, Industrial Hygienist	8/6/18
202	1	103A	Storage	Classroom 103 Closet	W4	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	1 RRP	Jackie Neiman, Industrial Hygienist	8/6/18
203	1	104	Primary	Classroom 104	Ceiling	Flaking paint near windows	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	36 RRP, 3 Colorimetric	Isa Haj, Industrial Hygienist	8/16/18
204	1	104	Primary	Classroom 104	W1	Flaking paint above and below blackboard, on door, and baseboards	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/16/18
205	1	104	Primary	Classroom 104	W2	Flaking paint at wall and door.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/16/18
206	1	104	Primary	Classroom 104	W3	Flaking paint around windows.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/16/18
207	1	104B	Storage	Classroom 104 Closet	Ceiling	Flaking paint at ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	6 RRP, 1 Colorimetric	Isa Haj, Industrial Hygienist	8/16/18
208	1	104B	Storage	Classroom 104 Closet	W1	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/16/18
209	1	104B	Storage	Classroom 104 Closet	W3	Flaking paint at wall.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/16/18
210	1	104B	Storage	Classroom 104 Closet	W4	Flaking paint on pipe.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/16/18

211	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	Ceiling	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	3 RRP, 1 Colorimetric	Isa Haj, Industrial Hygienist	8/16/18
212	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W1	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/16/18
213	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W2	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/16/18
214	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/16/18
215	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W4	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/16/18
216	1	106	Primary	Classroom 106	W1	Flaking paint on door, above door, and above blackboard	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	11 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	8/9/18
217	1	106	Primary	Classroom 106	W3	Flaking paint around windows and on trim	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/9/18
218	1	106	Primary	Classroom 106	W4	Flaking paint above bulletin board	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/9/18
219	1	106A	Storage	Classroom 106 Closet	Ceiling	Flaking paint at ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman/Isa Haj	9 RRP, 1 Colorimetric	Jackie Neiman & Isa Haj, Industrial Hygienist	8/14/18
220	1	106A	Storage	Classroom 106 Closet	W2	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman/Isa Haj	Part of Above	Jackie Neiman & Isa Haj, Industrial Hygienist	8/14/18
221	1	107	Primary	Classroom 107	Ceiling	Damages plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	8 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/13/18
222	1	107	Primary	Classroom 107	W1	Flaking paint on doors	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/13/18
223	1	107	Primary	Classroom 107	W3	Flaking paint on baseboards and behind radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/13/18
224	1	108	Primary	Classroom 108	W1	Flaking paint on wall and door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	36 RRP, 3 Colorimetric	Isa Haj, Industrial Hygienist	8/18/18
225	1	108	Primary	Classroom 108	W2	Flaking paint on baseboard	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/18/18
226	1	108	Primary	Classroom 108	W3	Flaking paint below windows and behind radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/18/18
227	1	108B	Storage	Classroom 108 Closet	Ceiling	Cracking paint at ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	9 RRP, 1 Colorimetric	Isa Haj, Industrial Hygienist	8/18/18
228	1	108B	Storage	Classroom 108 Closet	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/18/18
229	1	108B	Storage	Classroom 108 Closet	W4	Flaking paint on pipe	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/18/18
230	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	Ceiling	Flaking paint at ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	0	Isa Haj, Industrial Hygienist	8/18/18
231	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W1	Flaking paint at wall and door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/18/18
232	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W2	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/18/18
233	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W3	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Isa Haj	Part of above	Isa Haj, Industrial Hygienist	8/18/18
234	1	111	Storage	Closet at rear of Auditorium	Ceiling	No access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Jackie Neiman	0	Jackie Neiman, Industrial Hygienist	11/16/18
235	1	111	Storage	Closet at rear of Auditorium	Floor	No access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18
236	1	111	Storage	Closet at rear of Auditorium	W1	No access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16
237	1	111	Storage	Closet at rear of Auditorium	W2	No access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18
238	1	111	Storage	Closet at rear of Auditorium	W3	No access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18
239	1	111	Storage	Closet at rear of Auditorium	W4	No access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18
240	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	Ceiling	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	1 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/12/18
241	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W1	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/12/18
242	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W2	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/12/18
243	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/12/18
244	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W4	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/12/18
245	1	S16	Stairs, Fire Tower	Fire Tower near Classroom 107	Ceiling	Damaged plaster at ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	1 RRP	Jackie Neiman, Industrial Hygienist	10/4/18

246	1	114	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Flaking paint at ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	3 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/9/18
247	1	114	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Flaking paint at wall.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/9/18
248	1	H16	Circulation (Hallway)	Hallway from Classroom 104 to Teacher's Lounge	W2	Flaking paint behind radiators	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	2 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/13/18
249	1	H18	Circulation (Hallway)	Hallway outside Classrooms 101 to 103	Ceiling	Cracking paint at ceiling.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/13/18
250	1	H18	Circulation (Hallway)	Hallway outside Classrooms 101 to 103	W3	Flaking paint at pipe near S15 and behind radiators	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/13/18
251	1	H15	Circulation (Hallway)	Hallway outside Classrooms 106 to 108	W1	Flaking paint behind radiators	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/13/18
252	1	H17	Circulation (Hallway)	Hallway to BET Office	Ceiling	Flaking paint at ceiling	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/13/18
253	1	H17	Circulation (Hallway)	Hallway to BET Office	W1	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/13/18
254	1	H17	Circulation (Hallway)	Hallway to BET Office	W3	Flaking paint at wall	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/13/18
255	1	115	Administrative Office	Main Office	Ceiling	Flaking paint near windows.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	8 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/30/18
256	1	115	Administrative Office	Main Office	W3	Flaking paint near desk and behind radiator.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/30/18
257	1	108A	Restrooms, Staff - Male	Men's Restroom 109	W3	Flaking paint behind radiator	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	6 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/19/18
258	1	108A	Restrooms, Staff - Male	Men's Restroom 109	W4	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/19/18
259	1	115B	Administrative Office	Principal's Office	W3	Flaking paint at window sill.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/30/18
260	1	115C	Restrooms, Staff - Male/Female	Principal's Office Restroom	W1	Cracking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	2 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/16/18
261	1	115C	Restrooms, Staff - Male/Female	Principal's Office Restroom	W2	Cracking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18
262	1	S13	Stairs	Stairwell adjacent Classroom 103	W1	Spalling paint from ongoing steam leak.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	3 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/9/18
263	1	S13	Stairs	Stairwell adjacent Classroom 103	W2	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/9/18
264	1	S14	Stairs	Stairwell adjacent to Classroom 106	W1	Flaking paint at wall toward basement	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	1 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/9/18
265	1	S17	Stairs	Stairwell near Classroom 108	Ceiling	Flaking paint near Exit.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	2 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/9/18
266	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W1	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	14 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/1/18
267	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W2	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/1/18
268	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/1/18
269	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W4	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/1/18
270	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	Ceiling	Flaking paint	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Jackie Neiman	Room turned over to Environmental Services	Jackie Neiman, Industrial Hygienist	11/16/18
271	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W1	Flaking paint	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18
272	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W2	Flaking paint	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18
273	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W3	Flaking paint	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18
274	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W4	Flaking paint	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18
275	1	119	Restrooms, Staff - Female	Women's Restroom 100	Ceiling	Flaking paint and plaster damage	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	3 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/24/18
276	0	0B3	Primary	Art Room	Ceiling	Flaking paint at ceiling, pipes, and ducts.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	9 RRP, 2 Colormetric	Jackie Neiman, Industrial Hygienist	9/13/18
277	0	0B3	Primary	Art Room	W2	Flaking paint around windows & trim.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	9/13/18
278	0	001	Student Restrooms - Male (4-12)	Basement Boy's Restroom	Ceiling	Flaking paint at ceiling and pipe	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	5 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	8/27/18
279	0	001	Student Restrooms - Male (4-12)	Basement Boy's Restroom	W1	Flaking paint on pipe.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/27/18
280	0	012	Student Restrooms - Female (4-12)	Basement Girl's Restroom	Ceiling	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	5 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/12/18
281	0	012	Student Restrooms - Female (4-12)	Basement Girl's Restroom	W4	Flaking paint at pipe	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/12/18
282	0	001A	Storage	Classroom 0B1 Large Closet	Ceiling	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	2 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	8/10/18

283	0	001A	Storage	Classroom 0B1 Large Closet	W1	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/10/18	
284	0	001A	Storage	Classroom 0B1 Large Closet	W2	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/10/18	
285	0	001A	Storage	Classroom 0B1 Large Closet	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/10/18	
286	0	001A	Storage	Classroom 0B1 Large Closet	W4	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/10/18	
287	0	0B2B	Storage	Classroom 0B2 Large Closet	W1	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/15/18	
288	0	0B2A	Storage	Classroom 0B2 Small Closet	W1	Flaking paint at wall and door.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/15/18	
289	0	0B1	Primary	Classroom B1	W1	Flaking paint at closet doors	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP	Jackie Neiman, Industrial Hygienist	8/2/18	
290	0	0B1	Primary	Classroom B1	W2	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	1 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	8/2/18	
291	0	0B1	Primary	Classroom B1	W3	Flaking paint near windows	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	3 RRP	Jackie Neiman, Industrial Hygienist	8/2/18	
292	0	0B1	Primary	Classroom B1	W4	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP	Jackie Neiman, Industrial Hygienist	8/2/18	
293	0	001B	Storage	Classroom B1 Small Closet	Ceiling	Cracking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	3 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	8/10/18	
294	0	001B	Storage	Classroom B1 Small Closet	W1	Damaged plaster	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/10/18	
295	0	0B2	Primary	Classroom B2	Ceiling	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/10/18	
296	0	0B2	Primary	Classroom B2	W1	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/10/18	
297	0	0B2	Primary	Classroom B2	W2	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/10/18	
298	0	0B2	Primary	Classroom B2	W3	Flaking paint at windows and columns	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/10/18	
299	0	0B2	Primary	Classroom B2	W4	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	8/10/18	
300	0	0B4	Gymnasium - Intermediate Middle	Gym	Ceiling	Flaking paint at ceiling and ducts	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	50 RRP, 5 colormetric	Jackie Neiman, Industrial Hygienist	10/24/18	
301	0	0B4	Gymnasium - Intermediate Middle	Gym	W3	Flaking paint at window trim and pipes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/24/18	
302	0	008B	Administrative Office	Gym Office	Ceiling	Flaking paint at ceiling near windows	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	3 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/24/18	
303	0	008B	Administrative Office	Gym Office	W2	Flaking paint at window trim	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/24/18	
304	0	008A	Storage	Gym Storage Room	W1	Flaking paint at door	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/24/18	
305	0	H01	Circulation (Hallway)	Hallway outside Classrooms B1-B2	Ceiling	Flaking paint on ceiling above ductwork and near Start S17	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman/Julie Mui	Area was turned over to Environmental Services. Final testing was not completed. (Aea cleaned on 12/13/2018 - JM)	Jackie Neiman, Industrial Hygienist/Julie Mui, Industrial Hygienist	11/16/18 (12/13/2018-JM)	
306	0	H02	Circulation (Hallway)	Hallway outside Gym	Ceiling	Flaking paint on deck above ductwork	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman/Julie Mui	Part of above	Jackie Neiman, Industrial Hygienist/Julie Mui, Industrial Hygienist	11/16/18 (12/13/2018-JM)	
307	0	H02	Circulation (Hallway)	Hallway outside Gym	W1	Flaking paint at pipe.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18	
308	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	Ceiling	Flaking paint at ceiling by exit to outdoors	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman/Julie Mui	Area was turned over to Environmental Services. Final testing was not completed. (Aea cleaned on 12/13/2018 - JM)	Jackie Neiman, Industrial Hygienist/Julie Mui, Industrial Hygienist	11/16/18 (12/13/2018-JM)	
309	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	W2	Flaking paint at wall across from Girls Restroom	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18	
310	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	W3	Flaking paint at wall across from Girls Restroom and at window trim.	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18	
311	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	W4	Flaking paint at pipe by exit to outdoors	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/16/18	
312	0	011A	Kitchen	Kitchen	W3	Flaking paint near window behind freezer	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	4 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/13/18	
313	0	011B	Administrative Office	Kitchen Office	Ceiling	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	2 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/20/18	
314	0	011B	Administrative Office	Kitchen Office	W2	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/20/18	
315	0	011B	Administrative Office	Kitchen Office	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/20/18	
316	0	011B	Administrative Office	Kitchen Office	W4	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/20/18	
317	0	0B5	Cafeteria (Dining Area)	Logan Cafe 2	Ceiling	Spalling paint at concrete ceiling beam	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	5 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	10/24/18	
318	0	0B5	Cafeteria (Dining Area)	Logan Cafe 2	W2	Spalling paint near wall 3	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/24/18	
319	0	0B5	Cafeteria (Dining Area)	Logan Cafe 2	W3	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/24/18	
320	0	010	Storage	Logan Cafe 2 Small Closet	Ceiling	Damaged plaster	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Jackie Neiman	None	Closet will be cleaned by Environmental Services	Jackie Neiman, Industrial Hygienist	11/15/18
321	0	010	Storage	Logan Cafe 2 Small Closet	W1	Flaking paint behind pipe	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/15/18	
322	0	010	Storage	Logan Cafe 2 Small Closet	W2	Flaking paint where pipes enter wall	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	10/24/18	
323	0	S01	Stairs	Stairwell adjacent to Boiler Room Restroom	Ceiling	Flaking paint	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	2 RRP, 1 Colormetric	Jackie Neiman, Industrial Hygienist	11/9/18	
324	0	S01	Stairs	Stairwell adjacent to Boiler Room Restroom	Floor	Flaking paint debris	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Jackie Neiman	Part of above	Jackie Neiman, Industrial Hygienist	11/9/18	

Appendix C. Oversight Table

Task ID	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
1	3	330	Student Restrooms - Male (4-12)	Boy's Restroom	Floor	Chipped paint at floor	N/A	Prior	9/24/18	10/1/18	N/A	10/1/18	84	3	1	1	<20 ug/ft2	
2	3	330	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Flaking paint at radiator cover	N/A	Prior	9/24/18	10/1/18	N/A	10/1/18	40	Part of above	Part of above	Part of above		
3	3	301	Primary	Classroom 301	Ceiling	Flaking paint at ceiling	N/A	Prior	11/6/18	11/15/18	N/A	11/15/18	300	8	1	1	< 20 ug/ft2	
4	3	301	Primary	Classroom 301	W3	Flaking paint around windows	N/A	Prior	11/6/18	11/15/18	N/A	11/15/18	Part of above	Part of above	Part of above	Part of above		
5	3	301	Primary	Classroom 301	W4	Flaking paint at wall	N/A	Prior	11/6/18	11/15/18	N/A	11/15/18	Part of above	Part of above	Part of above	Part of above		
6	3	301A	Storage	Classroom 301 Closet	W1	Damaged plaster	N/A	Prior	11/6/18	11/15/18	N/A	11/15/18	72	2	1	0		
7	3	301A	Storage	Classroom 301 Closet	W2	Damaged plaster	N/A	Prior	11/6/18	11/15/18	N/A	11/15/18	150	4	Part of above	Part of above		
8	3	301A	Storage	Classroom 301 Closet	W3	Damaged plaster	N/A	Prior	11/6/18	11/15/18	N/A	11/15/18	72	2	Part of above	Part of above		
9	3	301A	Storage	Classroom 301 Closet	W4	Damaged plaster	N/A	Prior	11/6/18	11/15/18	N/A	11/15/18	150	4	Part of above	Part of above		
10	3	303	Primary	Classroom 303	W1	Flaking paint on door. Cracking paint to the right of the blackboard	N/A	Prior	9/20/18	10/4/18	N/A	10/4/18	150	4	1	0		
11	3	303	Primary	Classroom 303	W2	Flaking paint at closet doors. Cracking paint by closet	N/A	Prior	9/20/18	10/4/18	N/A	10/4/18	150	4	Part of above	Part of above		
12	3	303	Primary	Classroom 303	W3	Flaking paint around windows, at trim below windows, and by radiator	N/A	Prior	9/20/18	10/4/18	N/A	10/4/18	72	2	Part of above	Part of above		
13	3	331A	Storage	Classroom 303 Closet	W1	Flaking paint at door and damaged plaster	N/A	Prior	9/20/18	10/4/18	N/A	10/4/18	150	4	1	0		
14	3	331A	Storage	Classroom 303 Closet	W2	Flaking paint at wall	N/A	Prior	9/20/18	10/4/18	N/A	10/4/18	72	2	Part of above	Part of above		
15	3	331A	Storage	Classroom 303 Closet	W3	Damaged plaster	N/A	Prior	9/20/18	10/4/18	N/A	10/4/18	150	4	Part of above	Part of above		
16	3	304	Primary	Classroom 304	W1	Flaking paint at blackboard trim, at doors, and at baseboards	N/A	Prior	9/18/18	10/1/18	N/A	10/1/18	156	4	1	1	<20 ug/ft2	
17	3	304	Primary	Classroom 304	W2	Flaking paint near closet and W1, and at baseboards	N/A	Prior	9/18/18	10/1/18	N/A	10/1/18	40	1	Part of above	Part of above		
18	3	304	Primary	Classroom 304	W3	Flaking paint at wall and baseboards	N/A	Prior	9/18/18	10/1/18	N/A	10/1/18	96	3	Part of above	Part of above		
19	3	304	Primary	Classroom 304	W4	Flaking paint at blackboard trim and baseboards	N/A	Prior	9/18/18	10/1/18	N/A	10/1/18	126	3	Part of above	Part of above		
20	3	304A	Storage	Classroom 304 Closet	W1	Damaged plaster	N/A	Prior	9/18	10/4/18	N/A	10/4/18	150	4	1	0		
21	3	304A	Storage	Classroom 304 Closet	W3	Damaged plaster at windows	N/A	Prior	9/18/18	10/4/18	N/A	10/4/18	150	4	Part of above	Part of above		
22	3	305	Primary	Classroom 305	W3	Flaking paint at sides of windows, below window 3, and at riser by window 3.	N/A	Prior	9/28/18	10/4/18	N/A	10/4/18	72	2	1	0		

23	3	305A	Primary	Classroom 305 Closet	Ceiling	Flaking paint at ceiling	N/A	Prior	9/28/18	10/4/18	N/A	10/4/18	84	3	1	0		
24	3	305A	Primary	Classroom 305 Closet	W1	Flaking paint at wall and door	N/A	Prior	9/28/18	10/4/18	N/A	10/4/18	Part of above	Part of above	Part of above	Part of above		
25	3	305A	Primary	Classroom 305 Closet	W2	Flaking paint at wall	N/A	Prior	9/28/18	10/4/18	N/A	10/4/18	Part of above	Part of above	Part of above	Part of above		
26	3	305A	Primary	Classroom 305 Closet	W3	Flaking paint at wall	N/A	Prior	9/28/18	10/4/18	N/A	10/4/18	Part of above	Part of above	Part of above	Part of above		
27	3	305A	Primary	Classroom 305 Closet	W4	Flaking paint at wall and door	N/A	Prior	9/28/18	10/4/18	N/A	10/4/18	Part of above	Part of above	Part of above	Part of above		
28	3	307	Primary	Classroom 307	W2	Flaking paint debris on bulletin board sill and floor	N/A	Prior	10/3/18	10/9/18	N/A	10/9/18	150	4	1	1	< 20 ug/ft2	
29	3	307	Primary	Classroom 307	W3	Flaking paint debris by radiator	N/A	Prior	10/3/18	10/9/18	N/A	10/9/18	72	2	Part of above	Part of above		
30	3	307A	Storage	Classroom 307 Closet	Ceiling	Flaking paint	N/A	Prior	10/3/18	10/9/18	N/A	10/9/18	84	3	1	1	< 20 ug/ft2	
31	3	307A	Storage	Classroom 307 Closet	W1	Flaking paint	N/A	Prior	10/3/18	10/9/18	N/A	10/9/18	Part of above	Part of above	Part of above	Part of above		
32	3	307A	Storage	Classroom 307 Closet	W2	Flaking paint	N/A	Prior	10/3/18	10/9/18	N/A	10/9/18	Part of above	Part of above	Part of above	Part of above		
33	3	307A	Storage	Classroom 307 Closet	W3	Flaking paint	N/A	Prior	10/3/18	10/9/18	N/A	10/9/18	Part of above	Part of above	Part of above	Part of above		
34	3	307A	Storage	Classroom 307 Closet	W4	Flaking paint	N/A	Prior	10/3/18	10/9/18	N/A	10/9/18	Part of above	Part of above	Part of above	Part of above		
35	3	308	Primary	Classroom 308	W2	Flaking paint debris on bulletin board sill and floor	N/A	Prior	10/8/18	10/11/18	N/A	10/11/18	150	4	1	0		
36	3	308	Primary	Classroom 308	W3	Flaking paint at window trims and debris by radiator	N/A	Prior	10/8/18	10/11/18	N/A	10/11/18	72	2	Part of above	Part of above		
37	3	308A	Storage	Classroom 308 Closet	W1	Flaking paint at door	N/A	Prior	10/8/18	10/11/18	N/A	10/11/18	40	1	1	0		
38	3	308A	Storage	Classroom 308 Closet	W2	Flaking paint at baseboards	N/A	Prior	10/8/18	10/11/18	N/A	10/11/18	150	4	Part of above	Part of above		
39	3	308A	Storage	Classroom 308 Closet	W3	Flaking paint at baseboards	N/A	Prior	10/8/18	10/11/18	N/A	10/11/18	72	2	Part of above	Part of above		
40	3	308A	Storage	Classroom 308 Closet	W4	Flaking paint at baseboards	N/A	Prior	10/8/18	10/11/18	N/A	10/11/18	150	4	Part of above	Part of above		
41	3	309	Primary	Classroom 309	W3	Flaking paint at radiator and debris below window 1	N/A	Prior	10/9/18	10/12/18	N/A	10/12/18	72	2	1	1	< 20 ug/ft2	
42	3	309A	Storage	Classroom 309 Closet	Ceiling	Flaking paint	N/A	Prior	10/9/18	10/12/18	N/A	10/12/18	84	3	1	0		
43	3	309A	Storage	Classroom 309 Closet	Floor	Flaking paint debris	N/A	Prior	10/9/18	10/12/18	N/A	10/12/18	Part of above	Part of above	Part of above	0		
44	3	309A	Storage	Classroom 309 Closet	W1	Flaking paint	N/A	Prior	10/9/18	10/12/18	N/A	10/12/18	Part of above	Part of above	Part of above	Part of above		
45	3	309A	Storage	Classroom 309 Closet	W2	Flaking paint	N/A	Prior	10/9/18	10/12/18	N/A	10/12/18	Part of above	Part of above	Part of above	Part of above		
46	3	309A	Storage	Classroom 309 Closet	W3	Flaking paint	N/A	Prior	10/9/18	10/12/18	N/A	10/12/18	Part of above	Part of above	Part of above	Part of above		
47	3	309A	Storage	Classroom 309 Closet	W4	Flaking paint	N/A	Prior	10/9/18	10/12/18	N/A	10/12/18	Part of above	Part of above	Part of above	Part of above		
48	3	310	Primary	Classroom 310	W3	Flaking paint debris by radiator	N/A	Prior	10/12/18	10/17/18	N/A	10/17/18	72	2	2	0		
49	3	310A	Storage	Classroom 310 Closet	W3	Flaking paint at pipe and radiator, damaged plaster	N/A	Prior	10/12/18	10/17/18	N/A	10/17/18	150	4	2	0		
50	3	311	Primary	Classroom 311	W3	Flaking paint debris by radiator	N/A	Prior	10/12/18	10/23/18	N/A	10/23/18	72	2	2	1	< 20 ug/ft2	
51	3	311A	Storage	Classroom 311 Closet	W1	Damaged plaster	N/A	Prior	10/12/18	10/23/18	N/A	10/23/18	150	4	1	1	< 20 ug/ft2	

52	3	311A	Storage	Classroom 311 Closet	W3	Damaged plaster	N/A	Prior	10/12/18	10/23/18	N/A	10/23/18	150	4	Part of above	Part of above		
53	3	312	Primary	Classroom 312	W3	Flaking paint behind radiator	N/A	Prior	10/12/18	10/16/18	N/A	10/16/18	20	1	1	0		
54	3	313	Primary	Classroom 313	Ceiling	Flaking paint	N/A	Prior	11/5/18	11/16/18	N/A	11/16/18	300	8	1	0		
55	3	313	Primary	Classroom 313	W1	Flaking paint	N/A	Prior	11/5/18	11/16/18	N/A	11/16/18	Part of above	Part of above	Part of above	Part of above		
56	3	313	Primary	Classroom 313	W2	Flaking paint	N/A	Prior	11/5/18	11/16/18	N/A	11/16/18	Part of above	Part of above	Part of above	Part of above		
57	3	313	Primary	Classroom 313	W3	Flaking paint	N/A	Prior	11/5/18	11/16/18	N/A	11/16/18	Part of above	Part of above	Part of above	Part of above		
58	3	313A	Storage	Classroom 313 Closet	Ceiling	Flaking paint	N/A	Prior	11/5/18	11/19/18	N/A	11/19/18	150	4	1	0		
59	3	313A	Storage	Classroom 313 Closet	W1	Flaking paint	N/A	Prior	11/5/18	11/19/18	N/A	11/19/18	Part of above	Part of above	Part of above	Part of above		
60	3	313A	Storage	Classroom 313 Closet	W2	Flaking paint	N/A	Prior	11/5/18	11/19/18	N/A	11/19/18	Part of above	Part of above	Part of above	Part of above		
61	3	313A	Storage	Classroom 313 Closet	W3	Flaking paint	N/A	Prior	11/5/18	11/19/18	N/A	11/19/18	Part of above	Part of above	Part of above	Part of above		
62	3	313A	Storage	Classroom 313 Closet	W4	Flaking paint	N/A	Prior	11/5/18	11/19/18	N/A	11/19/18	Part of above	Part of above	Part of above	Part of above		
63	3	S31	Stairs, Fire Tower	Fire Tower near Classroom 302	Ceiling	Damaged plaster	N/A	Prior	9/28/18	10/1/18	N/A	10/1/18	40	1	0	0		
64	3	S36	Stairs, Fire Tower	Fire Tower near Classroom 312	Ceiling	Damaged plaster	N/A	Prior	9/28/18	10/1/18	N/A	10/1/18	40	1	0	0		
65	3	331	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Flaking paint at exhaust fan	N/A	Prior	10/1/18	10/2/18	N/A	10/2/18	90	2	0	0		Floor was painted
66	3	331	Student Restrooms - Female (4-12)	Girl's Restroom	Floor	Flaking paint debris at pipe by W3	N/A	Prior	10/1/18	10/2/18	N/A	10/2/18	Part of above	Part of above	Part of above	Part of above		
67	3	H320	Circulation (Hallway)	Hallway outside Classrooms 301 to 303	W3	Flaking paint behind radiator	N/A	Prior	8/27/18	9/14/18	N/A	9/14/18	20	1	1	0		
68	3	H319	Circulation (Hallway)	Hallway outside Classrooms 311 to 313	W1	Flaking paint behind radiator	N/A	Prior	8/27/18	9/14/18	N/A	9/14/18	20	1	Part of above	Part of above		
69	3	H318	Circulation (Hallway)	Hallway to Fire Tower near Classroom 302	W1	Flaking paint at door	N/A	Prior	8/27/18	9/14/18	N/A	9/14/18	20	1	Part of above	Part of above		
70	3	H318	Circulation (Hallway)	Hallway to Fire Tower near Classroom 302	W2	Flaking paint at door	N/A	Prior	8/27/18	9/14/18	N/A	9/14/18	20	1	Part of above	Part of above		
71	3	H317	Circulation (Hallway)	Hallway to Fire Tower near Classroom 312	W2	Flaking paint at door	N/A	Prior	8/27/18	9/14/18	N/A	9/14/18	20	1	Part of above	Part of above		
72	3	H317	Circulation (Hallway)	Hallway to Fire Tower near Classroom 312	W3	Flaking paint at door	N/A	Prior	8/27/18	9/14/18	N/A	9/14/18	20	1	Part of above	Part of above		
73	3	329	Administrative Office	Office 313A	W1	Damaged plaster	N/A	Prior	10/17/18	10/22/18	N/A	10/22/18	72	2	1	0		
74	3	329	Administrative Office	Office 313A	W3	Flaking paint	N/A	Prior	10/17/18	10/22/18	N/A	10/22/18	72	2	Part of above	Part of above		
75	3	S34	Stairs	Stairwell near Classroom 311	W1	Flaking paint above door	N/A	Prior	11/2/18	11/9/18	N/A	11/9/18	40	1	1	0		
76	3	S34	Stairs	Stairwell near Classroom 311	W2	Cracking paint	N/A	Prior	11/2/18	11/9/18	N/A	11/9/18	72	2	Part of above	Part of above		
77	3	S34	Stairs	Stairwell near Classroom 311	W3	Flaking paint	N/A	Prior	11/2/18	11/9/18	N/A	11/9/18	72	2	Part of above	Part of above		

78	3	332A	Restrooms, Staff - Male/Female	Teacher' Lounge adjacent to Classroom 301 Restroom	W2	Flaking paint at pipe	N/A	Prior	10/1/18	10/4/18	N/A	10/4/18	200	5	1	0		
79	3	332A	Restrooms, Staff - Male/Female	Teacher' Lounge adjacent to Classroom 301 Restroom	W3	Flaking paint at sill	N/A	Prior	10/1/18	10/4/18	N/A	10/4/18	72	2	0	0		
80	3	332A	Restrooms, Staff - Male/Female	Teacher' Lounge adjacent to Classroom 301 Restroom	W4	Flaking paint at wall in copy room by radiator	N/A	Prior	10/1/18	10/4/18	N/A	10/4/18	200	5	1	No		
81	2	H214	Circulation (Hallway)	2nd Floor Hallway outside Auditorium	W2	Flaking paint behind radiator	N/A	Prior	8/22/18	8/23/18	N/A	8/23/18	20	0	0	0		
82	2	217	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Flaking paint at pipes	N/A	Prior	8/22/18	8/23/18	N/A	8/23/18	95	3	1	1	<20 ug/ft2	
83	2	203	Primary	Classroom 203	Ceiling	Flaking paint, damaged plaster near windows	N/A	Prior	8/20/18	8/23/18	N/A	8/23/18	546	13	2	1	<20 ug/ft2	
84	2	203	Primary	Classroom 203	W1	Flaking paint above closet door. Plaster damage	N/A	Prior	8/20/18	8/23/18	N/A	8/23/18	Part of above	Part of above	Part of above	Part of above		
85	2	203	Primary	Classroom 203	W3	Flaking paint at window trim. Plaster damage	N/A	Prior	8/20/18	8/23/18	N/A	8/23/18	Part of above	Part of above	Part of above	Part of above		
86	2	203B	Storage	Classroom 203 Closet	Ceiling	Flaking paint	N/A	Prior	8/20/18	8/23/18	N/A	8/23/18	95	3	1	0		
87	2	203B	Storage	Classroom 203 Closet	W1	Flaking paint	N/A	Prior	8/20/18	8/23/18	N/A	8/23/18	Part of above	Part of above	Part of above	Part of above		
88	2	203B	Storage	Classroom 203 Closet	W2	Flaking paint	N/A	Prior	8/20/18	8/23/18	N/A	8/23/18	Part of above	Part of above	Part of above	Part of above		
89	2	203B	Storage	Classroom 203 Closet	W3	Flaking paint	N/A	Prior	8/20/18	8/23/18	N/A	8/23/18	Part of above	Part of above	Part of above	Part of above		
90	2	203B	Storage	Classroom 203 Closet	W4	Flaking paint	N/A	Prior	8/20/18	8/23/18	N/A	8/23/18	Part of above	Part of above	Part of above	Part of above		
91	2	205	Primary	Classroom 205	W1	Flaking paint at wall and doors	N/A	Prior	8/15/18	8/21/18	N/A	8/21/18	150	4	1	0		
92	2	205	Primary	Classroom 205	W2	Flaking paint below bulletin board, on closet doors, and baseboards	N/A	Prior	8/15/18	8/21/18	N/A	8/21/18	72	2	1	0		
93	2	205	Primary	Classroom 205	W3	Flaking paint above windows	N/A	Prior	8/15/18	8/21/18	N/A	8/21/18	150	4	0	0		
94	2	205B	Storage	Classroom 205 Closet	Ceiling	Damaged plaster	N/A	Prior	8/15/18	8/21/18	N/A	8/21/18	84	2	1	0		
95	2	205B	Storage	Classroom 205 Closet	W1	Flaking paint at pipe and wall	N/A	Prior	8/15/18	8/21/18	N/A	8/21/18	Part of above	Part of above	Part of above	Part of above		
96	2	205B	Storage	Classroom 205 Closet	W2	Damaged plaster	N/A	Prior	8/15/18	8/21/18	N/A	8/21/18	Part of above	Part of above	Part of above	Part of above		
97	2	205B	Storage	Classroom 205 Closet	W3	Flaking paint and pipe and radiator. Damaged plaster	N/A	Prior	8/15/18	8/21/18	N/A	8/21/18	Part of above	Part of above	Part of above	Part of above		
98	2	205B	Storage	Classroom 205 Closet	W4	Damaged plaster	N/A	Prior	8/15/18	8/21/18	N/A	8/21/18	Part of above	Part of above	Part of above	Part of above		
99	2	206A	Storage	Classroom 206 Closet	W1	Flaking paint at wall	N/A	Prior	8/18/18	8/18/18	N/A	8/18/18	95	12	1	0		
100	2	206A	Storage	Classroom 206 Closet	W3	Flaking paint at wall	N/A	Prior	8/18/18	8/18/18	N/A	8/18/18	Part of Above	Part of Above	Part of Above	Part of Above		
101	2	206A	Storage	Classroom 206 Closet	W4	Flaking paint at wall	N/A	Prior	8/18/18	8/18/18	N/A	8/18/18	Part of Above	Part of Above	Part of Above	Part of Above		
102	2	207	Primary	Classroom 207	Ceiling	Flaking paint near windows	N/A	Prior	8/20/18	8/23/18	N/A	8/27/18	546	13	2	1	<20 ug/ft2	

103	2	207	Primary	Classroom 207	W1	Flaking paint by entrance, and above blackboard	N/A	Prior	8/20/18	8/23/18	N/A	8/27/18	Part of above	Part of above	Part of above	Part of above		
104	2	207	Primary	Classroom 207	W2	Flaking paint on wall by computers	N/A	Prior	8/20/18	8/23/18	N/A	8/27/18	Part of above	Part of above	Part of above	Part of above		
105	2	207	Primary	Classroom 207	W3	Flaking paint above and below windows	N/A	Prior	8/20/18	8/23/18	N/A	8/27/18	Part of above	Part of above	Part of above	Part of above		
106	2	207	Primary	Classroom 207	W4	Flaking paint at wall around bulletin board and on baseboard	N/A	Prior	8/20/18	8/23/18	N/A	8/27/18	Part of above	Part of above	Part of above	Part of above		
107	2	209	Primary	Classroom 209	W3	Flaking paint behind pipe at window 4	N/A	Prior	8/20/18	8/23/18	N/A	8/23/18	72	2	1	0		
108	2	209	Primary	Classroom 209	W4	Flaking paint at wall	N/A	Prior	8/20/18	8/23/18	N/A	8/23/18	72	2	Part of above	Part of above		
109	2	209B	Storage	Classroom 209 Closet	W1	Flaking paint at door	N/A	Prior	8/20/18	8/23/18	N/A	8/23/18	150	4	1	2	8/23/18 Fail, Retest 8/27/18 <20 ug/ft2	
110	2	209B	Storage	Classroom 209 Closet	W3	Flaking paint at walls and pipe	N/A	Prior	8/20/18	8/23/18	N/A	8/23/18	150	4	Part of above	Part of above		
111	2	210	Administrative Office	Counselor's Office 206A	W1	Flaking at wall and baseboards	N/A	Prior	9/14/18	10/1/18	N/A	10/1/18	40	1	1	0		
112	2	210	Administrative Office	Counselor's Office 206A	W2	Flaking at wall and baseboards	N/A	Prior	9/14/18	10/1/18	N/A	10/1/18	200	5	Part of above	Part of above		
113	2	210	Administrative Office	Counselor's Office 206A	W3	Flaking at wall and baseboards	N/A	Prior	9/14/18	10/1/18	N/A	10/1/18	40	1	Part of above	Part of above		
114	2	210	Administrative Office	Counselor's Office 206A	W4	Flaking at wall and baseboards	N/A	Prior	9/14/18	10/1/18	N/A	10/1/18	200	5	Part of above	Part of above		
115	2	S21	Stairs, Fire Tower	Fire Tower near Classroom 202	Ceiling	Damaged plaster	N/A	Prior	9/13/18	9/14/18	N/A	9/14/18	40	1	Part of above	0		
116	2	220	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Flaking paint at pipe	N/A	Prior	8/22/18	8/23/18	N/A	8/23/18	40	1	1	0		
117	2	H215	Circulation (Hallway)	Hallway outside Classrooms 201 to 203	W3	Flaking paint behind radiator	N/A	Prior	8/23/18	8/24/18	N/A	8/27/18	40	1	1	0		
118	2	H213	Circulation (Hallway)	Hallway outside Classrooms 207 to 209	W1	Flaking paint behind radiator	N/A	Prior	8/23/18	8/24/18	N/A	8/27/18	40	1	Part of above	Part of above		
119	2	H212	Circulation (Hallway)	Hallway to Fire Tower near Classroom 202	W1	Flaking paint at door	N/A	Prior	8/23/18	8/24/18	N/A	8/27/18	40	1	Part of above	Part of above		
120	2	H211	Circulation (Hallway)	Hallway to Fire Tower near Classroom 208	W3	Flaking paint at door	N/A	Prior	8/23/18	8/24/18	N/A	8/27/18	40	1	Part of above	Part of above		
121	2	H211	Circulation (Hallway)	Hallway to Fire Tower near Classroom 208	W4	Flaking paint at door	N/A	Prior	8/23/18	8/24/18	N/A	8/27/18	40	1	Part of above	Part of above		
122	2	201	IMC (Library)	Library 201	Ceiling	Flaking paint near windows	N/A	Prior	8/27/18	8/31/18	N/A	8/31/18	650	16	2	1	<20 ug/ft2	
123	2	201	IMC (Library)	Library 201	W1	Flaking paint at baseboards	N/A	Prior	8/27/18	8/31/18	N/A	8/31/18	Part of above	Part of above	Part of above	Part of above		
124	2	201	IMC (Library)	Library 201	W2	Flaking paint at baseboards	N/A	Prior	8/27/18	8/31/18	N/A	8/31/18	Part of above	Part of above	Part of above	Part of above		
125	2	201	IMC (Library)	Library 201	W3	Flaking paint debris on sills. Flaking paint at baseboards	N/A	Prior	8/27/18	8/31/18	N/A	8/31/18	Part of above	Part of above	Part of above	Part of above		
126	2	201	IMC (Library)	Library 201	W4	Flaking paint at baseboards	N/A	Prior	8/27/18	8/31/18	N/A	8/31/18	Part of above	Part of above	Part of above	Part of above		
127	2	202	IMC (Library)	Library 202	Ceiling	Flaking paint near windows	N/A	Prior	8/27/18	8/31/18	N/A	8/31/18	Part of above	Part of above	Part of above	Part of above		

128	2	202	IMC (Library)	Library 202	W1	Flaking paint at baseboards	N/A	Prior	8/27/18	8/31/18	N/A	8/31/18	Part of above	Part of above	Part of above	Part of above		
129	2	202	IMC (Library)	Library 202	W2	Flaking paint at baseboards	N/A	Prior	8/27/18	8/31/18	N/A	8/31/18	Part of above	Part of above	Part of above	Part of above		
130	2	202	IMC (Library)	Library 202	W3	Flaking paint debris on sills. Flaking paint at baseboards	N/A	Prior	8/27/18	8/31/18	N/A	8/31/18	Part of above	Part of above	Part of above	Part of above		
131	2	202	IMC (Library)	Library 202	W4	Flaking paint at baseboards	N/A	Prior	8/27/18	8/31/18	N/A	8/31/18	Part of above	Part of above	Part of above	Part of above		
132	2	204A	Administrative Office	Nurse's Office	W1	Flaking paint on pipe in bathroom	N/A	Prior	8/22/18	8/23/18	N/A	8/23/18	72	2	1	1	<20 ug/ft2	
133	2	204A	Administrative Office	Nurse's Office	W3	Flaking paint debris on floor and on pipe.	N/A	Prior	8/22/18	8/23/18	N/A	8/23/18	72	2	Part of above	Part of above		
134	2	205A	Administrative Office	Office 205A	W1	Flaking paint at door	N/A	Prior	9/14/18	9/18/18	N/A	9/18	200	5	1	0		
135	2	205A	Administrative Office	Office 205A	W3	Flaking paint at wall	N/A	Prior	9/14/18	9/18/18	N/A	9/18/18	72	2	Part of above	Part of above		
136	2	205A	Administrative Office	Office 205A	W4	Flaking paint at wall	N/A	Prior	9/14/18	9/18/18	N/A	9/18/18	200	5	Part of above	Part of above		
137	2	209A	Administrative Office	Office 209A	Ceiling	Flaking paint and plaster damage	N/A	Prior	8/27/18	9/13/18	N/A	9/13/18	270	7	1	0		
138	2	209A	Administrative Office	Office 209A	W1	Flaking paint and plaster damage	N/A	Prior	8/20/18	9/13/18	N/A	9/13/18	Part of above	Part of above	Part of above	Part of above		
139	2	209A	Administrative Office	Office 209A	W2	Flaking paint and plaster damage	N/A	Prior	8/27/18	9/13/18	N/A	9/13/18	Part of above	Part of above	Part of above	Part of above		
140	2	209A	Administrative Office	Office 209A	W3	Flaking paint and plaster damage	N/A	Prior	8/27/18	9/13/18	N/A	9/13/18	Part of above	Part of above	Part of above	Part of above		
141	2	209A	Administrative Office	Office 209A	W4	Flaking paint and plaster damage	N/A	Prior	8/27/18	9/13/18	N/A	9/13/18	Part of above	Part of above	Part of above	Part of above		
142	2	201C	Administrative Office	Office between Library 201 Closet and Speech Pathologist Office 201A (access from Speech Pathologist Office only)	W1	Flaking paint at wall	N/A	Prior	10/22/18	10/26/18	N/A	10/26/18	72	2	1	0		
143	2	201C	Administrative Office	Office between Library 201 Closet and Speech Pathologist Office 201A (access from Speech Pathologist Office only)	W4	Flaking paint at wall	N/A	Prior	10/22/18	10/26/18	N/A	10/26/18	72	2	Part of above	Part of above		
144	2	201A	Administrative Office	Speech Pathologist Office 201A	W1	Flaking paint at door.	N/A	Prior	10/22/18	10/26/18	N/A	10/26/18	72	2	1	No		
145	2	201A	Administrative Office	Speech Pathologist Office 201A	W4	Flaking paint at baseboards	N/A	Prior	10/22/18	10/26/18	N/A	10/26/18	150	4	Part of above	Part of above		
146	2	201D	Restrooms, Staff - Male/Female	Speech Pathologist Office 201A Restroom	Ceiling	Flaking paint near windows	N/A	Prior	10/22/18	11/5/18	N/A	11/5/18	60	2	3	No		

147	2	201D	Restrooms, Staff - Male/Female	Speech Pathologist Office 201A Restroom	W2	Flaking paint debris on sill and floor.	N/A	Prior	10/22/18	11/5/18	N/A	11/5/18	Part of above	Part of above	Part of above	Part of above		
148	2	201E	Storage	Speech Pathologist Office 201A Storage Room	Ceiling	Flaking paint	N/A	Prior	10/22/18	11/5/18	N/A	11/5/18	120	3	1	0		
149	2	201E	Storage	Speech Pathologist Office 201A Storage Room	Floor	Flaking paint debris	N/A	Prior	10/22/18	11/5/18	N/A	11/5/18	Part of above	Part of above	Part of above	Part of above		
150	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W1	Flaking paint	N/A	Prior	10/22/18	11/5/18	N/A	11/5/18	Part of above	Part of above	Part of above	Part of above		
151	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W2	Flaking paint	N/A	Prior	10/22/18	11/5/18	N/A	11/5/18	Part of above	Part of above	Part of above	Part of above		
152	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W3	Flaking paint	N/A	Prior	10/22/18	11/5/18	N/A	11/5/18	Part of above	Part of above	Part of above	Part of above		
153	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W4	Flaking paint	N/A	Prior	10/22/18	11/5/18	N/A	11/5/18	Part of above	Part of above	Part of above	Part of above		
154	2	S24	Stairs	Stairwell near Classroom 207	W1	Flaking paint around door	N/A	Prior	11/2/18	11/9/18	N/A	11/9/18	40	1	1	0		
155	2	S24	Stairs	Stairwell near Classroom 207	W3	Flaking paint behind pipe	N/A	Prior	11/2/18	11/9/18	N/A	11/9/18	72	2	Part of above	Part of above		
156	2	S24	Stairs	Stairwell near Classroom 207	W4	Flaking paint near ceiling	N/A	Prior	11/2/18	11/9/18	N/A	11/9/18	72	2	Part of above	Part of above		
157	2	220A	Storage	Storage Closet near Girl's Restroom	Ceiling	No access	N/A	Prior	9/11	9/13/18	N/A	9/13/18	30	1	1	0		
158	2	220A	Storage	Storage Closet near Girl's Restroom	Floor	No access	N/A	Prior	9/11/18	9/13/18	N/A	9/13/18	Part of above	Part of above	Part of above	Part of above		
159	2	220A	Storage	Storage Closet near Girl's Restroom	W1	No access	N/A	Prior	9/11/18	9/13/18	N/A	9/13/18	Part of above	Part of above	Part of above	Part of above		
160	2	220A	Storage	Storage Closet near Girl's Restroom	W2	No access	N/A	Prior	9/11/18	9/13/18	N/A	9/13/18	Part of above	Part of above	Part of above	Part of above		
161	2	220A	Storage	Storage Closet near Girl's Restroom	W3	No access	N/A	Prior	9/11/18	9/13/18	N/A	9/13/18	Part of above	Part of above	Part of above	Part of above		
162	2	220A	Storage	Storage Closet near Girl's Restroom	W4	No access	N/A	Prior	9/11/18	9/13/18	N/A	9/13/18	Part of above	Part of above	Part of above	Part of above		
163	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	Ceiling	Flaking paint at ceiling	N/A	Prior	9/12/18	9/14/18	N/A	9/14/18	130	4	1	0		
164	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	W2	Flaking paint	N/A	Prior	9/12/18	9/14/18	N/A	9/14/18	Part of above	Part of above	Part of above	Part of above		
165	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	W3	Flaking paint below window	N/A	Prior	9/12/18	9/14/18	N/A	9/14/18	Part of above	Part of above	Part of above	Part of above		

166	2	204B	Restrooms, Staff - Male/Female	Teacher's Lounge 204 Restroom	W1	Flaking paint at door	N/A	Prior	9/12/18	9/14/18	N/A	9/14/18	72	1	1	0		
167	1	102	Administrative Office	Assistant Principal's Office 102	Ceiling	Flaking paint at ceiling	N/A	Prior	10/30/18	11/7/18	N/A	11/7/18	300	8	1	0		
168	1	102	Administrative Office	Assistant Principal's Office 102	W1	Flaking paint at wall and doors	N/A	Prior	10/30/18	11/7/18	N/A	11/7/18	Part of above	Part of above	Part of above	Part of above		
169	1	102	Administrative Office	Assistant Principal's Office 102	W2	Flaking paint at wall	N/A	Prior	10/30/18	11/7/18	N/A	11/7/18	Part of above	Part of above	Part of above	Part of above		
170	1	102	Administrative Office	Assistant Principal's Office 102	W3	Flaking paint around windows and behind radiator	N/A	Prior	10/30/18	11/7/18	N/A	11/7	Part of above	Part of above	Part of above	Part of above		
171	1	102	Administrative Office	Assistant Principal's Office 102	W4	Flaking and chipping paint at wall.	N/A	Prior	10/30/18	11/7/18	N/A	11/7/18	Part of above	Part of above	Part of above	Part of above		
172	1	112	Auditorium	Auditorium	W1	Flaking paint and damaged plaster	N/A	Prior	9/11/18	9/17/18	N/A	9/17/18	40	1	Part of below	Part of below		
173	1	112	Auditorium	Auditorium	W2	Flaking paint and damaged plaster	N/A	Prior	9/11/18	9/17/18	N/A	9/17/18	150	4	1	2	9/17/18 Fail, Retest 9/18/18 <20ug/ft2	
174	1	112	Auditorium	Auditorium	W3	Flaking paint and damaged plaster	N/A	Prior	9/11/18	9/17/18	N/A	9/17/18	150	4	Part of above	Part of above		
175	1	112	Auditorium	Auditorium	W4	Damaged plaster	N/A	Prior	9/11/18	9/17/18	N/A	9/17	40	1	Part of above	Part of above		
176	1	112A	Auditorium	Auditorium Stage	Ceiling	Flaking paint at ceiling	N/A	Prior	9/11/18	9/17/18	N/A	9/17/18	160	4	1	0		
177	1	112A	Auditorium	Auditorium Stage	W3	Flaking paint near ceiling	N/A	Prior	9/11/18	9/17/18	N/A	9/17/18	Part of above	Part of above	Part of above	Part of above		
178	1	112A	Auditorium	Auditorium Stage	W4	Flaking paint	N/A	Prior	9/11/18	9/17/18	N/A	9/17/18	Part of above	Part of above	Part of above	Part of above		
179	1	104A	Administrative Office	BET Office	Ceiling	Flaking paint at ceiling	N/A	Prior	10/24/18	11/1/18	N/A	11/1/18	160	4	1	0		
180	1	104A	Administrative Office	BET Office	W1	Flaking paint on and near door.	N/A	Prior	10/24/18	11/1/18	N/A	11/1/18	Part of above	Part of above	Part of above	Part of above		
181	1	104A	Administrative Office	BET Office	W2	Flaking paint at wall	N/A	Prior	10/24/18	11/1/18	N/A	11/1/18	Part of above	Part of above	Part of above	Part of above		
182	1	104A	Administrative Office	BET Office	W3	Flaking paint at wall	N/A	Prior	10/24/18	11/1/18	N/A	11/1/18	Part of above	Part of above	Part of above	Part of above		
183	1	104A	Administrative Office	BET Office	W4	Flaking paint at wall	N/A	Prior	10/24/18	11/1/18	N/A	11/1/18	Part of above	Part of above	Part of above	Part of above		
184	1	101A	Storage	Classroom 101 Closet	Ceiling	Flaking paint.	N/A	Prior	8/10/18	8/13/18	N/A	8/13/18	95	9	1	0		
185	1	101A	Storage	Classroom 101 Closet	W1	Flaking paint.	N/A	Prior	8/10/18	8/13/18	N/A	8/13/18	Part of Above	Part of Above	Part of Above	Part of above		
186	1	101A	Storage	Classroom 101 Closet	W2	Flaking paint.	N/A	Prior	8/10/18	8/13/18	N/A	8/13/18	Part of Above	Part of Above	Part of Above	Part of above		
187	1	101A	Storage	Classroom 101 Closet	W3	Flaking paint.	N/A	Prior	8/10/18	8/13/18	N/A	8/13/18	Part of Above	Part of Above	Part of Above	Part of above		
188	1	101A	Storage	Classroom 101 Closet	W4	Flaking paint.	N/A	Prior	8/10/18	8/13/18	N/A	8/13/18	Part of Above	Part of Above	Part of Above	Part of above		
189	1	101	Primary	Classroom 101	Ceiling	Damaged plaster at ceiling.	N/A	Prior	7/30/18	7/31/18	N/A	7/31/18	546	13	0	1	<20 ug/ft2	
190	1	101	Primary	Classroom 101	W1	Flaking paint above and below blackboard and on door.	N/A	Prior	7/30/18	7/31/18	N/A	7/31/18	156	Part of above	Part of above	Part of above		

191	1	101	Primary	Classroom 101	W3	Flaking paint around windows.	N/A	Prior	7/30/18	7/31/18	N/A	7/31/18	96	Part of above	Part of above	Part of above		
192	1	101	Primary	Classroom 101	W4	Flaking paint above and below blackboard.	N/A	Prior	7/30/18	7/31/18	N/A	7/31/18	126	4	1	1	<20 ug/ft2	
193	1	103	Primary	Classroom 103	Ceiling	Flaking paint at ceiling	N/A	Prior	8/2/18	8/6/18	N/A	8/6/18	546	13	2	2	8/6/18 Fail, Retest 8/9 <20 ug/ft2	
194	1	103	Primary	Classroom 103	W1	Flaking paint near entrance and above white board.	N/A	Prior	8/2/18	8/6/18	N/A	8/6/18	156	Part of above	Part of above	Part of above		
195	1	103	Primary	Classroom 103	W2	Flaking paint above and below bulletin board	N/A	Prior	8/2/18	8/6/18	N/A	8/6/18	42	Part of above	Part of above	Part of above		
196	1	103	Primary	Classroom 103	W3	Flaking paint around windows	N/A	Prior	8/2/18	8/6/18	N/A	8/6/18	96	Part of above	Part of above	Part of above		
197	1	103	Primary	Classroom 103	W4	Flaking paint at wall	N/A	Prior	8/2/18	8/6/18	N/A	8/6/18	126	Part of above	Part of above	Part of above		
198	1	103A	Storage	Classroom 103 Closet	Ceiling	Flaking paint	N/A	Prior	8/2/18	8/6/18	N/A	8/6/18	84	Part of below	Part of below	Part of below		
199	1	103A	Storage	Classroom 103 Closet	W1	Flaking paint	N/A	Prior	8/2/18	8/6/18	N/A	8/6/18	150	4	1	0		
200	1	103A	Storage	Classroom 103 Closet	W2	Flaking paint	N/A	Prior	8/2/18	8/6/18	N/A	8/6/18	72	2	Part of above	Part of above		
201	1	103A	Storage	Classroom 103 Closet	W3	Flaking paint	N/A	Prior	8/2/18	8/6/18	N/A	8/6/18	150	4	Part of above	Part of above		
202	1	103A	Storage	Classroom 103 Closet	W4	Flaking paint	N/A	Prior	8/2/18	8/6/18	N/A	8/6/18	72	2	Part of above	Part of above		
203	1	104	Primary	Classroom 104	Ceiling	Flaking paint near windows	N/A	Prior	8/8/18	8/16/18	N/A	8/16/18	720	36	3	2	8/16/18 - 43 ug/ft2 Fail, Retest 8/23/18 <20 ug/ft2	1 colorimetric on floor, 1 colorimetric on Windowsill, & 1 colorimetric outside work area on desktop
204	1	104	Primary	Classroom 104	W1	Flaking paint above and below blackboard, on door, and baseboards	N/A	Prior	8/8/18	8/16/18	N/A	8/16/18	Part of Above	Part of Above	Part of Above	Part of Above		
205	1	104	Primary	Classroom 104	W2	Flaking paint at wall and door.	N/A	Prior	8/8/18	8/16/18	N/A	8/16/18	Part of Above	Part of Above	Part of Above	Part of Above		
206	1	104	Primary	Classroom 104	W3	Flaking paint around windows.	N/A	Prior	8/8/18	8/16/18	N/A	8/16/18	Part of Above	Part of Above	Part of Above	Part of Above		
207	1	104B	Storage	Classroom 104 Closet	Ceiling	Flaking paint at ceiling	N/A	Prior	8/8/18	8/16/18	N/A	8/16/18	65	6	1	0		
208	1	104B	Storage	Classroom 104 Closet	W1	Flaking paint at wall	N/A	Prior	8/8/18	8/16/18	N/A	8/16/18	Part of Above	Part of Above	Part of Above	Part of Above		
209	1	104B	Storage	Classroom 104 Closet	W3	Flaking paint at wall.	N/A	Prior	8/8/18	8/16/18	N/A	8/16/18	Part of Above	Part of Above	Part of Above	Part of Above		
210	1	104B	Storage	Classroom 104 Closet	W4	Flaking paint on pipe.	N/A	Prior	8/8/18	8/16/18	N/A	8/16/18	Part of Above	Part of Above	Part of Above	Part of Above		
211	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	Ceiling	Flaking paint	N/A	Prior	8/8/18	8/16/18	N/A	8/16/18	40	3	1	0		
212	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W1	Flaking paint	N/A	Prior	8/8/18	8/16/18	N/A	8/16/18	Part of Above	Part of Above	Part of Above	Part of Above		
213	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W2	Flaking paint	N/A	Prior	8/8/18	8/16/18	N/A	8/16/18	Part of Above	Part of Above	Part of Above	Part of Above		

235	1	111	Storage	Closet at rear of Auditorium	Floor	No access	N/A	Prior	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
236	1	111	Storage	Closet at rear of Auditorium	W1	No access	N/A	Prior	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
237	1	111	Storage	Closet at rear of Auditorium	W2	No access	N/A	Prior	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
238	1	111	Storage	Closet at rear of Auditorium	W3	No access	N/A	Prior	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
239	1	111	Storage	Closet at rear of Auditorium	W4	No access	N/A	Prior	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
240	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	Ceiling	Flaking paint	N/A	Prior	10/9/18	10/12/18	N/A	10/12/18	40	1	1	0		
241	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W1	Flaking paint	N/A	Prior	10/9/18	10/12/18	N/A	10/12/18	Part of above	Part of above	Part of above	Part of above		
242	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W2	Flaking paint	N/A	Prior	10/9/18	10/12/18	N/A	10/12/18	Part of above	Part of above	Part of above	Part of above		
243	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W3	Flaking paint	N/A	Prior	10/9/18	10/12/18	N/A	10/12/18	Part of above	Part of above	Part of above	Part of above		
244	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W4	Flaking paint	N/A	Prior	10/9/18	10/12/18	N/A	10/12/18	Part of above	Part of above	Part of above	Part of above		
245	1	S16	Stairs, Fire Tower	Fire Tower near Classroom 107	Ceiling	Damaged plaster at ceiling	N/A	Prior	10/4/18	10/4/18	N/A	10/4/18	40	1	0	0		
246	1	114	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Flaking paint at ceiling	N/A	Prior	11/7/18	11/9/18	N/A	11/9/18	90	3	1	0		
247	1	114	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Flaking paint at wall.	N/A	Prior	11/7/18	11/9/18	N/A	11/19/18	Part of above	Part of above	Part of above	Part of above		
248	1	H16	Circulation (Hallway)	Hallway from Classroom 104 to Teacher's Lounge	W2	Flaking paint behind radiators	N/A	Prior	10/24/18	11/13/18	N/A	11/13/18	72	2	1	2	11/13/15 Fail, Retest 11/15 < 20 ug/ft2	
249	1	H18	Circulation (Hallway)	Hallway outside Classrooms 101 to 103	Ceiling	Cracking paint at ceiling.	N/A	Prior	10/24/18	11/13/18	N/A	11/13/18	150	4	1	1	<20 ug/ft2	
250	1	H18	Circulation (Hallway)	Hallway outside Classrooms 101 to 103	W3	Flaking paint at pipe near S15 and behind radiators	N/A	Prior	10/24/18	11/13/18	N/A	11/13/18	Part of above	Part of above	Part of above	Part of above		
251	1	H15	Circulation (Hallway)	Hallway outside Classrooms 106 to 108	W1	Flaking paint behind radiators	N/A	Prior	10/24/18	11/13/18	N/A	11/13/18	Part of above	Part of above	Part of above	Part of above		
252	1	H17	Circulation (Hallway)	Hallway to BET Office	Ceiling	Flaking paint at ceiling	N/A	Prior	10/24/18	11/13/18	N/A	11/13/18	150	4	1	1	< 20 ug/ft2	
253	1	H17	Circulation (Hallway)	Hallway to BET Office	W1	Flaking paint at wall	N/A	Prior	10/24/18	11/13/18	N/A	11/13/18	Part of above	Part of above	Part of above	Part of above		
254	1	H17	Circulation (Hallway)	Hallway to BET Office	W3	Flaking paint at wall	N/A	Prior	10/24/18	11/13/18	N/A	11/13/18	Part of above	Part of above	Part of above	Part of above		
255	1	115	Administrative Office	Main Office	Ceiling	Flaking paint near windows.	N/A	Prior	10/26/18	10/30/18	N/A	10/30/18	300	8	1	1	<20 ug/ft2	
256	1	115	Administrative Office	Main Office	W3	Flaking paint near desk and behind radiator.	N/A	Prior	10/26/18	10/30/18	N/A	10/30/18	Part of above	Part of above	Part of above	Part of above		
257	1	108A	Restrooms, Staff - Male	Men's Restroom 109	W3	Flaking paint behind radiator	N/A	Prior	10/12/18	10/19/18	N/A	10/19/18	72	2	1	0		

258	1	108A	Restrooms, Staff - Male	Men's Restroom 109	W4	Flaking paint	N/A	Prior	10/12/18	10/19/18	N/A	10/19/18	150	4	Part of above	Part of above		
259	1	115B	Administrative Office	Principal's Office	W3	Flaking paint at window sill.	N/A	Prior	10/24/18	10/30/18	N/A	10/30/18	150	4	1	0		
260	1	115C	Restrooms, Staff - Male/Female	Principal's Office Restroom	W1	Cracking paint	N/A	Prior	10/24/18	11/16/18	N/A	11/16/18	72	2	1	0		
261	1	115C	Restrooms, Staff - Male/Female	Principal's Office Restroom	W2	Cracking paint	N/A	Prior	10/24/18	11/16/18	N/A	11/16/18	72	2	Part of above	Part of above		
262	1	S13	Stairs	Stairwell adjacent Classroom 103	W1	Spalling paint from ongoing steam leak.	N/A	Prior	11/2/18	11/9/18	N/A	11/9/18	40	1	1	0		
263	1	S13	Stairs	Stairwell adjacent Classroom 103	W2	Flaking paint	N/A	Prior	11/2/18	11/9/18	N/A	11/9/18	72	2	Part of above	Part of above		
264	1	S14	Stairs	Stairwell adjacent to Classroom 106	W1	Flaking paint at wall toward basement	N/A	Prior	11/2/18	11/9/18	N/A	11/9/18	40	1	1	0		
265	1	S17	Stairs	Stairwell near Classroom 108	Ceiling	Flaking paint near Exit.	N/A	Prior	11/2/18	11/9/18	N/A	11/9/18	72	2	1	0		
266	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W1	Flaking paint	N/A	Prior	10/22/18	11/1/18	N/A	11/1/18	150	4	1	1	< 20 ug/ft2	
267	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W2	Flaking paint	N/A	Prior	10/22/18	11/1/18	N/A	11/1/18	150	4	Part of above	Part of above		
268	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W3	Flaking paint	N/A	Prior	10/22/18	11/1/18	N/A	11/1/18	72	2	Part of above	Part of above		
269	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W4	Flaking paint	N/A	Prior	10/22/18	11/1/18	N/A	11/1/18	150	4	Part of above	Part of above		
270	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	Ceiling	Flaking paint	N/A	Prior	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		Painters are turning this room over to Environmental Services
271	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W1	Flaking paint	N/A	Prior	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
272	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W2	Flaking paint	N/A	Prior	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
273	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W3	Flaking paint	N/A	Prior	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
274	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W4	Flaking paint	N/A	Prior	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
275	1	119	Restrooms, Staff - Female	Women's Restroom 100	Ceiling	Flaking paint and plaster damage	N/A	Prior	10/18/18	10/24/18	N/A	10/24/18	100	3	1	0		
276	0	0B3	Primary	Art Room	Ceiling	Flaking paint at ceiling, pipes, and ducts.	N/A	Prior	8/27/18	9/13/18	N/A	9/13/18	360	9	1	2	9/13/2018 Fail, Retest 9/17/18 <20 ug/ft2	
277	0	0B3	Primary	Art Room	W2	Flaking paint around windows & trim.	N/A	Prior	8/27/18	9/13/18	N/A	9/13/18	Part of above	Part of above	Part of above	Part of above		

278	0	001	Student Restrooms - Male (4-12)	Basement Boy's Restroom	Ceiling	Flaking paint at ceiling and pipe	N/A	Prior	8/23/18	8/24/18	N/A	8/27/18	180	5	1	1	<20ug/ft2	
279	0	001	Student Restrooms - Male (4-12)	Basement Boy's Restroom	W1	Flaking paint on pipe.	N/A	Prior	8/23/18	8/24/18	N/A	8/27/18	Part of above	Part of above	Part of above	Part of above		
280	0	012	Student Restrooms - Female (4-12)	Basement Girl's Restroom	Ceiling	Flaking paint	N/A	Prior	10/9/18	10/12/18	N/A	10/12/18	180	5	1	0		
281	0	012	Student Restrooms - Female (4-12)	Basement Girl's Restroom	W4	Flaking paint at pipe	N/A	Prior	10/9/18	10/12/18	N/A	10/12/18	Part of above	Part of above	Part of above	Part of above		
282	0	001A	Storage	Classroom 0B1 Large Closet	Ceiling	Flaking paint	N/A	Prior	8/6/18	8/10/18	N/A	8/10/18	72	2	1	0		
283	0	001A	Storage	Classroom 0B1 Large Closet	W1	Flaking paint	N/A	Prior	8/6/18	8/10/18	N/A	8/10/18	Part of above	Part of above	Part of above	Part of above		
284	0	001A	Storage	Classroom 0B1 Large Closet	W2	Flaking paint	N/A	Prior	8/6/18	8/10/18	N/A	8/10/18	Part of above	Part of above	Part of above	Part of above		
285	0	001A	Storage	Classroom 0B1 Large Closet	W3	Flaking paint	N/A	Prior	8/6/18	8/10/18	N/A	8/10/18	Part of above	Part of above	Part of above	Part of above		
286	0	001A	Storage	Classroom 0B1 Large Closet	W4	Flaking paint	N/A	Prior	8/6/18	8/10/18	N/A	8/10/18	Part of above	Part of above	Part of above	Part of above		
287	0	0B2B	Storage	Classroom 0B2 Large Closet	W1	Flaking paint	N/A	Prior	11/6/18	11/15/18	N/A	11/15/18	150	4	1	0		
288	0	0B2A	Storage	Classroom 0B2 Small Closet	W1	Flaking paint at wall and door.	N/A	Prior	11/6/18	11/15/18	N/A	11/15/18	150	4	1	0		
289	0	0B1	Primary	Classroom B1	W1	Flaking paint at closet doors	N/A	Prior	7/30/18	8/2/18	N/A	8/2/18	156	4	0	0		
290	0	0B1	Primary	Classroom B1	W2	Damaged plaster	N/A	Prior	7/30/18	8/2/18	N/A	8/2/18	42	1	1	Part of above		
291	0	0B1	Primary	Classroom B1	W3	Flaking paint near windows	N/A	Prior	7/30/18	8/2/18	N/A	8/2/18	96	1	0	Part of above		
292	0	0B1	Primary	Classroom B1	W4	Damaged plaster	N/A	Prior	7/30/18	8/2/18	N/A	8/2/18	126	4	0	Part of above		
293	0	001B	Storage	Classroom B1 Small Closet	Ceiling	Cracking paint	N/A	Prior	8/6/18	8/10/18	N/A	8/10/18	95	3	1	0		
294	0	001B	Storage	Classroom B1 Small Closet	W1	Damaged plaster	N/A	Prior	8/6/18	8/10/18	N/A	8/10/18	Part of above	Part of above	Part of above	Part of above		
295	0	0B2	Primary	Classroom B2	Ceiling	Flaking paint	N/A	Prior	11/6/18	11/15/18	N/A	11/15/18	300	8	1	1	< 20 ug/ft2	
296	0	0B2	Primary	Classroom B2	W1	Flaking paint	N/A	Prior	11/6/18	11/15/18	N/A	11/15/18	Part of above	Part of above	Part of above	Part of above		
297	0	0B2	Primary	Classroom B2	W2	Flaking paint	N/A	Prior	11/6/18	11/15/18	N/A	11/15/18	Part of above	Part of above	Part of above	Part of above		
298	0	0B2	Primary	Classroom B2	W3	Flaking paint at windows and columns	N/A	Prior	11/6/18	11/15/18	N/A	11/15/18	Part of above	Part of above	Part of above	Part of above		
299	0	0B2	Primary	Classroom B2	W4	Flaking paint	N/A	Prior	11/6/18	11/15/18	N/A	11/15/18	Part of above	Part of above	Part of above	Part of above		
300	0	0B4	Gymnasium - Intermediate Middle	Gym	Ceiling	Flaking paint at ceiling and ducts	N/A	Prior	10/1/18	10/24/18	N/A	10/24/18	2,000	50	5	3	Fail 10/24/18, Retest 11/5/18 <20 ug/ft2	
301	0	0B4	Gymnasium - Intermediate Middle	Gym	W3	Flaking paint at window trim and pipes	N/A	Prior	10/1/18	10/24/18	N/A	10/24/18	Part of above	Part of above	Part of above	Part of above		
302	0	008B	Administrative Office	Gym Office	Ceiling	Flaking paint at ceiling near windows	N/A	Prior	10/1/18	10/24/18	N/A	10/24/18	150	3	1	0		
303	0	008B	Administrative Office	Gym Office	W2	Flaking paint at window trim	N/A	Prior	10/1/18	10/24/18	N/A	10/24/18	Part of above	Part of above	Part of above	Part of above		

304	0	008A	Storage	Gym Storage Room	W1	Flaking paint at door	N/A	Prior	10/1/18	10/24/18	N/A	10/24/18	Part of above	Part of above	Part of above	Part of above		
305	0	H01	Circulation (Hallway)	Hallway outside Classrooms B1-B2	Ceiling	Flaking paint on ceiling above ductwork and near Start S17	N/A	Prior	8/21/18 (12/13/2018)	8/23/18 (12/13/2018)	N/A	8/23/18 (12/13/2018)	300	8	1 (Additional Sample Collected on 12/13/2018)	0		Additional Cleaning Above Duct Work Completed on 12/13/2018 (JM)
306	0	H02	Circulation (Hallway)	Hallway outside Gym	Ceiling	Flaking paint on deck above ductwork	N/A	Prior	9/18/18 (12/13/2018)	#####	N/A	12/13/2018	300	8	1	0		There was flaking and debris above the vent work in the basement. The hallway was turned over to Environmental Services and will have to be tested at a later date. (12/13/2018)
307	0	H02	Circulation (Hallway)	Hallway outside Gym	W1	Flaking paint at pipe.	N/A	Prior	9/18/18		N/A							
308	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	Ceiling	Flaking paint at ceiling by exit to outdoors	N/A	Prior	12/12/18	12/12/18	N/A	12/12/18	500	13	2	0		
309	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	W2	Flaking paint at wall across from Girls Restroom	N/A	Prior	10/8/18		N/A							
310	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	W3	Flaking paint at wall across from Girls Restroom and at window trim.	N/A	Prior	10/8/18		N/A							
311	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	W4	Flaking paint at pipe by exit to outdoors	N/A	Prior	10/8/18		N/A							
312	0	011A	Kitchen	Kitchen	W3	Flaking paint near window behind freezer	N/A	Prior	11/6/18	11/13/18	N/A	11/13/18	150	4	1	2	Fail 11/13/18, Retest 11/15 <20 ug/ft2	
313	0	011B	Administrative Office	Kitchen Office	Ceiling	Flaking paint	N/A	Prior	11/6/18	11/20/18	N/A	11/20/18	72	2	1	0		
314	0	011B	Administrative Office	Kitchen Office	W2	Flaking paint	N/A	Prior	11/6/18	11/20/18	N/A	11/20/18	Part of above	Part of above	Part of above	Part of above		
315	0	011B	Administrative Office	Kitchen Office	W3	Flaking paint	N/A	Prior	11/6/18	11/20/18	N/A	11/20/18	Part of above	Part of above	Part of above	Part of above		
316	0	011B	Administrative Office	Kitchen Office	W4	Flaking paint	N/A	Prior	11/6/28	11/20/18	N/A	11/20/18	Part of above	Part of above	Part of above	Part of above		
317	0	0B5	Cafeteria (Dining Area)	Logan Cafe 2	Ceiling	Spalling paint at concrete ceiling beam	N/A	Prior	10/15/18	10/24/18	N/A	10/24/18	230	5	1	1	<20 ug/ft2	
318	0	0B5	Cafeteria (Dining Area)	Logan Cafe 2	W2	Spalling paint near wall 3	N/A	Prior	10/15/18	10/24/18	N/A	10/24/18	Part of above	Part of above	Part of above	Part of above		
319	0	0B5	Cafeteria (Dining Area)	Logan Cafe 2	W3	Flaking paint	N/A	Prior	10/15/18	10/24/18	N/A	10/24/18	Part of above	Part of above	Part of above	Part of above		
320	0	010	Storage	Logan Cafe 2 Small Closet	Ceiling	Damaged plaster	N/A	Prior	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		Closet will be cleaned by Environmental Services
321	0	010	Storage	Logan Cafe 2 Small Closet	W1	Flaking paint behind pipe	N/A	Prior	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
322	0	010	Storage	Logan Cafe 2 Small Closet	W2	Flaking paint where pipes enter wall	N/A	Prior	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
323	0	S01	Stairs	Stairwell adjacent to Boiler Room Restroom	Ceiling	Flaking paint	N/A	Prior	11/2/18	11/16/18	N/A	11/16/18	150	4	1	0		
324	0	S01	Stairs	Stairwell adjacent to Boiler Room Restroom	Floor	Flaking paint debris	N/A	Prior	11/2/18	11/16/18	N/A	11/16/18	Part of above	Part of above	Part of above	Part of above		

Appendix D. Sample Results Table

Task ID	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
1	3	330	Student Restrooms - Male (4-12)	Boy's Restroom	Floor	Chipped paint at floor	1	1	<20 ug/ft2	
2	3	330	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Flaking paint at radiator cover	Part of above	Part of above		
3	3	301	Primary	Classroom 301	Ceiling	Flaking paint at ceiling	1	1	< 20 ug/ft2	
4	3	301	Primary	Classroom 301	W3	Flaking paint around windows	Part of above	Part of above		
5	3	301	Primary	Classroom 301	W4	Flaking paint at wall	Part of above	Part of above		
6	3	301A	Storage	Classroom 301 Closet	W1	Damaged plaster	1	0		
7	3	301A	Storage	Classroom 301 Closet	W2	Damaged plaster	Part of above	Part of above		
8	3	301A	Storage	Classroom 301 Closet	W3	Damaged plaster	Part of above	Part of above		
9	3	301A	Storage	Classroom 301 Closet	W4	Damaged plaster	Part of above	Part of above		
10	3	303	Primary	Classroom 303	W1	Flaking paint on door. Cracking paint to the right of the blackboard	1	0		
11	3	303	Primary	Classroom 303	W2	Flaking paint at closet doors. Cracking paint by closet	Part of above	Part of above		
12	3	303	Primary	Classroom 303	W3	Flaking paint around windows, at trim below windows, and by radiator	Part of above	Part of above		
13	3	331A	Storage	Classroom 303 Closet	W1	Flaking paint at door and damaged plaster	1	0		
14	3	331A	Storage	Classroom 303 Closet	W2	Flaking paint at wall	Part of above	Part of above		
15	3	331A	Storage	Classroom 303 Closet	W3	Damaged plaster	Part of above	Part of above		
16	3	304	Primary	Classroom 304	W1	Flaking paint at blackboard trim, at doors, and at baseboards	1	1	<20 ug/ft2	
17	3	304	Primary	Classroom 304	W2	Flaking paint near closet and W1, and at baseboards	Part of above	Part of above		

18	3	304	Primary	Classroom 304	W3	Flaking paint at wall and baseboards	Part of above	Part of above		
19	3	304	Primary	Classroom 304	W4	Flaking paint at blackboard trim and baseboards	Part of above	Part of above		
20	3	304A	Storage	Classroom 304 Closet	W1	Damaged plaster	1	0		
21	3	304A	Storage	Classroom 304 Closet	W3	Damaged plaster at windows	Part of above	Part of above		
22	3	305	Primary	Classroom 305	W3	Flaking paint at sides of windows, below window 3, and at riser by window 3.	1	0		
23	3	305A	Primary	Classroom 305 Closet	Ceiling	Flaking paint at ceiling	1	0		
24	3	305A	Primary	Classroom 305 Closet	W1	Flaking paint at wall and door	Part of above	Part of above		
25	3	305A	Primary	Classroom 305 Closet	W2	Flaking paint at wall	Part of above	Part of above		
26	3	305A	Primary	Classroom 305 Closet	W3	Flaking paint at wall	Part of above	Part of above		
27	3	305A	Primary	Classroom 305 Closet	W4	Flaking paint at wall and door	Part of above	Part of above		
28	3	307	Primary	Classroom 307	W2	Flaking paint debris on bulletin board sill and floor	1	1	< 20 ug/ft2	
29	3	307	Primary	Classroom 307	W3	Flaking paint debris by radiator	Part of above	Part of above		
30	3	307A	Storage	Classroom 307 Closet	Ceiling	Flaking paint	1	1	< 20 ug/ft2	
31	3	307A	Storage	Classroom 307 Closet	W1	Flaking paint	Part of above	Part of above		
32	3	307A	Storage	Classroom 307 Closet	W2	Flaking paint	Part of above	Part of above		
33	3	307A	Storage	Classroom 307 Closet	W3	Flaking paint	Part of above	Part of above		
34	3	307A	Storage	Classroom 307 Closet	W4	Flaking paint	Part of above	Part of above		
35	3	308	Primary	Classroom 308	W2	Flaking paint debris on bulletin board sill and floor	1	0		
36	3	308	Primary	Classroom 308	W3	Flaking paint at window trims and debris by radiator	Part of above	Part of above		
37	3	308A	Storage	Classroom 308 Closet	W1	Flaking paint at door	1	0		
38	3	308A	Storage	Classroom 308 Closet	W2	Flaking paint at baseboards	Part of above	Part of above		
39	3	308A	Storage	Classroom 308 Closet	W3	Flaking paint at baseboards	Part of above	Part of above		
40	3	308A	Storage	Classroom 308 Closet	W4	Flaking paint at baseboards	Part of above	Part of above		

41	3	309	Primary	Classroom 309	W3	Flaking paint at radiator and debris below window 1	1	1	< 20 ug/ft2	
42	3	309A	Storage	Classroom 309 Closet	Ceiling	Flaking paint	1	0		
43	3	309A	Storage	Classroom 309 Closet	Floor	Flaking paint debris	Part of above	0		
44	3	309A	Storage	Classroom 309 Closet	W1	Flaking paint	Part of above	Part of above		
45	3	309A	Storage	Classroom 309 Closet	W2	Flaking paint	Part of above	Part of above		
46	3	309A	Storage	Classroom 309 Closet	W3	Flaking paint	Part of above	Part of above		
47	3	309A	Storage	Classroom 309 Closet	W4	Flaking paint	Part of above	Part of above		
48	3	310	Primary	Classroom 310	W3	Flaking paint debris by radiator	2	0		
49	3	310A	Storage	Classroom 310 Closet	W3	Flaking paint at pipe and radiator, damaged plaster	2	0		
50	3	311	Primary	Classroom 311	W3	Flaking paint debris by radiator	2	1	< 20 ug/ft2	
51	3	311A	Storage	Classroom 311 Closet	W1	Damaged plaster	1	1	< 20 ug/ft2	
52	3	311A	Storage	Classroom 311 Closet	W3	Damaged plaster	Part of above	Part of above		
53	3	312	Primary	Classroom 312	W3	Flaking paint behind radiator	1	0		
54	3	313	Primary	Classroom 313	Ceiling	Flaking paint	1	0		
55	3	313	Primary	Classroom 313	W1	Flaking paint	Part of above	Part of above		
56	3	313	Primary	Classroom 313	W2	Flaking paint	Part of above	Part of above		
57	3	313	Primary	Classroom 313	W3	Flaking paint	Part of above	Part of above		
58	3	313A	Storage	Classroom 313 Closet	Ceiling	Flaking paint	1	0		
59	3	313A	Storage	Classroom 313 Closet	W1	Flaking paint	Part of above	Part of above		
60	3	313A	Storage	Classroom 313 Closet	W2	Flaking paint	Part of above	Part of above		
61	3	313A	Storage	Classroom 313 Closet	W3	Flaking paint	Part of above	Part of above		
62	3	313A	Storage	Classroom 313 Closet	W4	Flaking paint	Part of above	Part of above		
63	3	S31	Stairs, Fire Tower	Fire Tower near Classroom 302	Ceiling	Damaged plaster	0	0		
64	3	S36	Stairs, Fire Tower	Fire Tower near Classroom 312	Ceiling	Damaged plaster	0	0		

65	3	331	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Flaking paint at exhaust fan	0	0		Floor was painted
66	3	331	Student Restrooms - Female (4-12)	Girl's Restroom	Floor	Flaking paint debris at pipe by W3	Part of above	Part of above		
67	3	H320	Circulation (Hallway)	Hallway outside Classrooms 301 to 303	W3	Flaking paint behind radiator	1	0		
68	3	H319	Circulation (Hallway)	Hallway outside Classrooms 311 to 313	W1	Flaking paint behind radiator	Part of above	Part of above		
69	3	H318	Circulation (Hallway)	Hallway to Fire Tower near Classroom 302	W1	Flaking paint at door	Part of above	Part of above		
70	3	H318	Circulation (Hallway)	Hallway to Fire Tower near Classroom 302	W2	Flaking paint at door	Part of above	Part of above		
71	3	H317	Circulation (Hallway)	Hallway to Fire Tower near Classroom 312	W2	Flaking paint at door	Part of above	Part of above		
72	3	H317	Circulation (Hallway)	Hallway to Fire Tower near Classroom 312	W3	Flaking paint at door	Part of above	Part of above		
73	3	329	Administrative Office	Office 313A	W1	Damaged plaster	1	0		
74	3	329	Administrative Office	Office 313A	W3	Flaking paint	Part of above	Part of above		
75	3	S34	Stairs	Stairwell near Classroom 311	W1	Flaking paint above door	1	0		
76	3	S34	Stairs	Stairwell near Classroom 311	W2	Cracking paint	Part of above	Part of above		
77	3	S34	Stairs	Stairwell near Classroom 311	W3	Flaking paint	Part of above	Part of above		
78	3	332A	Restrooms, Staff - Male/Female	Teacher' Lounge adjacent to Classroom 301 Restroom	W2	Flaking paint at pipe	1	0		
79	3	332A	Restrooms, Staff - Male/Female	Teacher' Lounge adjacent to Classroom 301 Restroom	W3	Flaking paint at sill	0	0		
80	3	332A	Restrooms, Staff - Male/Female	Teacher' Lounge adjacent to Classroom 301 Restroom	W4	Flaking paint at wall in copy room by radiator	1	No		

81	2	H214	Circulation (Hallway)	2nd Floor Hallway outside Auditorium	W2	Flaking paint behind radiator	0	0		
82	2	217	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Flaking paint at pipes	1	1	<20 ug/ft2	
83	2	203	Primary	Classroom 203	Ceiling	Flaking paint, damaged plaster near windows	2	1	<20 ug/ft2	
84	2	203	Primary	Classroom 203	W1	Flaking paint above closet door. Plaster damage	Part of above	Part of above		
85	2	203	Primary	Classroom 203	W3	Flaking paint at window trim. Plaster damage	Part of above	Part of above		
86	2	203B	Storage	Classroom 203 Closet	Ceiling	Flaking paint	1	0		
87	2	203B	Storage	Classroom 203 Closet	W1	Flaking paint	Part of above	Part of above		
88	2	203B	Storage	Classroom 203 Closet	W2	Flaking paint	Part of above	Part of above		
89	2	203B	Storage	Classroom 203 Closet	W3	Flaking paint	Part of above	Part of above		
90	2	203B	Storage	Classroom 203 Closet	W4	Flaking paint	Part of above	Part of above		
91	2	205	Primary	Classroom 205	W1	Flaking paint at wall and doors	1	0		
92	2	205	Primary	Classroom 205	W2	Flaking paint below bulletin board, on closet doors, and baseboards	1	0		
93	2	205	Primary	Classroom 205	W3	Flaking paint above windows	0	0		
94	2	205B	Storage	Classroom 205 Closet	Ceiling	Damaged plaster	1	0		
95	2	205B	Storage	Classroom 205 Closet	W1	Flaking paint at pipe and wall	Part of above	Part of above		
96	2	205B	Storage	Classroom 205 Closet	W2	Damaged plaster	Part of above	Part of above		
97	2	205B	Storage	Classroom 205 Closet	W3	Flaking paint and pipe and radiator. Damaged plaster	Part of above	Part of above		
98	2	205B	Storage	Classroom 205 Closet	W4	Damaged plaster	Part of above	Part of above		
99	2	206A	Storage	Classroom 206 Closet	W1	Flaking paint at wall	1	0		
100	2	206A	Storage	Classroom 206 Closet	W3	Flaking paint at wall	Part of Above	Part of Above		
101	2	206A	Storage	Classroom 206 Closet	W4	Flaking paint at wall	Part of Above	Part of Above		
102	2	207	Primary	Classroom 207	Ceiling	Flaking paint near windows	2	1	<20 ug/ft2	

103	2	207	Primary	Classroom 207	W1	Flaking paint by entrance, and above blackboard	Part of above	Part of above		
104	2	207	Primary	Classroom 207	W2	Flaking paint on wall by computers	Part of above	Part of above		
105	2	207	Primary	Classroom 207	W3	Flaking paint above and below windows	Part of above	Part of above		
106	2	207	Primary	Classroom 207	W4	Flaking paint at wall around bulletin board and on baseboard	Part of above	Part of above		
107	2	209	Primary	Classroom 209	W3	Flaking paint behind pipe at window 4	1	0		
108	2	209	Primary	Classroom 209	W4	Flaking paint at wall	Part of above	Part of above		
109	2	209B	Storage	Classroom 209 Closet	W1	Flaking paint at door	1	2	8/23/18 Fail, Retest 8/27/18 <20 ug/ft2	
110	2	209B	Storage	Classroom 209 Closet	W3	Flaking paint at walls and pipe	Part of above	Part of above		
111	2	210	Administrative Office	Counselor's Office 206A	W1	Flaking at wall and baseboards	1	0		
112	2	210	Administrative Office	Counselor's Office 206A	W2	Flaking at wall and baseboards	Part of above	Part of above		
113	2	210	Administrative Office	Counselor's Office 206A	W3	Flaking at wall and baseboards	Part of above	Part of above		
114	2	210	Administrative Office	Counselor's Office 206A	W4	Flaking at wall and baseboards	Part of above	Part of above		
115	2	S21	Stairs, Fire Tower	Fire Tower near Classroom 202	Ceiling	Damaged plaster	Part of above	0		
116	2	220	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Flaking paint at pipe	1	0		
117	2	H215	Circulation (Hallway)	Hallway outside Classrooms 201 to 203	W3	Flaking paint behind radiator	1	0		
118	2	H213	Circulation (Hallway)	Hallway outside Classrooms 207 to 209	W1	Flaking paint behind radiator	Part of above	Part of above		
119	2	H212	Circulation (Hallway)	Hallway to Fire Tower near Classroom 202	W1	Flaking paint at door	Part of above	Part of above		
120	2	H211	Circulation (Hallway)	Hallway to Fire Tower near Classroom 208	W3	Flaking paint at door	Part of above	Part of above		
121	2	H211	Circulation (Hallway)	Hallway to Fire Tower near Classroom 208	W4	Flaking paint at door	Part of above	Part of above		

122	2	201	IMC (Library)	Library 201	Ceiling	Flaking paint near windows	2	1	<20 ug/ft2	
123	2	201	IMC (Library)	Library 201	W1	Flaking paint at baseboards	Part of above	Part of above		
124	2	201	IMC (Library)	Library 201	W2	Flaking paint at baseboards	Part of above	Part of above		
125	2	201	IMC (Library)	Library 201	W3	Flaking paint debris on sills. Flaking paint at baseboards	Part of above	Part of above		
126	2	201	IMC (Library)	Library 201	W4	Flaking paint at baseboards	Part of above	Part of above		
127	2	202	IMC (Library)	Library 202	Ceiling	Flaking paint near windows	Part of above	Part of above		
128	2	202	IMC (Library)	Library 202	W1	Flaking paint at baseboards	Part of above	Part of above		
129	2	202	IMC (Library)	Library 202	W2	Flaking paint at baseboards	Part of above	Part of above		
130	2	202	IMC (Library)	Library 202	W3	Flaking paint debris on sills. Flaking paint at baseboards	Part of above	Part of above		
131	2	202	IMC (Library)	Library 202	W4	Flaking paint at baseboards	Part of above	Part of above		
132	2	204A	Administrative Office	Nurse's Office	W1	Flaking paint on pipe in bathroom	1	1	<20 ug/ft2	
133	2	204A	Administrative Office	Nurse's Office	W3	Flaking paint debris on floor and on pipe.	Part of above	Part of above		
134	2	205A	Administrative Office	Office 205A	W1	Flaking paint at door	1	0		
135	2	205A	Administrative Office	Office 205A	W3	Flaking paint at wall	Part of above	Part of above		
136	2	205A	Administrative Office	Office 205A	W4	Flaking paint at wall	Part of above	Part of above		
137	2	209A	Administrative Office	Office 209A	Ceiling	Flaking paint and plaster damage	1	0		
138	2	209A	Administrative Office	Office 209A	W1	Flaking paint and plaster damage	Part of above	Part of above		
139	2	209A	Administrative Office	Office 209A	W2	Flaking paint and plaster damage	Part of above	Part of above		
140	2	209A	Administrative Office	Office 209A	W3	Flaking paint and plaster damage	Part of above	Part of above		
141	2	209A	Administrative Office	Office 209A	W4	Flaking paint and plaster damage	Part of above	Part of above		

142	2	201C	Administrative Office	Office between Library 201 Closet and Speech Pathologist Office 201A (access from Speech Pathologist Office only)	W1	Flaking paint at wall	1	0		
143	2	201C	Administrative Office	Office between Library 201 Closet and Speech Pathologist Office 201A (access from Speech Pathologist Office only)	W4	Flaking paint at wall	Part of above	Part of above		
144	2	201A	Administrative Office	Speech Pathologist Office 201A	W1	Flaking paint at door.	1	No		
145	2	201A	Administrative Office	Speech Pathologist Office 201A	W4	Flaking paint at baseboards	Part of above	Part of above		
146	2	201D	Restrooms, Staff - Male/Female	Speech Pathologist Office 201A Restroom	Ceiling	Flaking paint near windows	3	No		
147	2	201D	Restrooms, Staff - Male/Female	Speech Pathologist Office 201A Restroom	W2	Flaking paint debris on sill and floor.	Part of above	Part of above		
148	2	201E	Storage	Speech Pathologist Office 201A Storage Room	Ceiling	Flaking paint	1	0		
149	2	201E	Storage	Speech Pathologist Office 201A Storage Room	Floor	Flaking paint debris	Part of above	Part of above		
150	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W1	Flaking paint	Part of above	Part of above		

151	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W2	Flaking paint	Part of above	Part of above		
152	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W3	Flaking paint	Part of above	Part of above		
153	2	201E	Storage	Speech Pathologist Office 201A Storage Room	W4	Flaking paint	Part of above	Part of above		
154	2	S24	Stairs	Stairwell near Classroom 207	W1	Flaking paint around door	1	0		
155	2	S24	Stairs	Stairwell near Classroom 207	W3	Flaking paint behind pipe	Part of above	Part of above		
156	2	S24	Stairs	Stairwell near Classroom 207	W4	Flaking paint near ceiling	Part of above	Part of above		
157	2	220A	Storage	Storage Closet near Girl's Restroom	Ceiling	No access	1	0		
158	2	220A	Storage	Storage Closet near Girl's Restroom	Floor	No access	Part of above	Part of above		
159	2	220A	Storage	Storage Closet near Girl's Restroom	W1	No access	Part of above	Part of above		
160	2	220A	Storage	Storage Closet near Girl's Restroom	W2	No access	Part of above	Part of above		
161	2	220A	Storage	Storage Closet near Girl's Restroom	W3	No access	Part of above	Part of above		
162	2	220A	Storage	Storage Closet near Girl's Restroom	W4	No access	Part of above	Part of above		
163	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	Ceiling	Flaking paint at ceiling	1	0		
164	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	W2	Flaking paint	Part of above	Part of above		
165	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	W3	Flaking paint below window	Part of above	Part of above		
166	2	204B	Restrooms, Staff - Male/Female	Teacher's Lounge 204 Restroom	W1	Flaking paint at door	1	0		

167	1	102	Administrative Office	Assistant Principal's Office 102	Ceiling	Flaking paint at ceiling	1	0		
168	1	102	Administrative Office	Assistant Principal's Office 102	W1	Flaking paint at wall and doors	Part of above	Part of above		
169	1	102	Administrative Office	Assistant Principal's Office 102	W2	Flaking paint at wall	Part of above	Part of above		
170	1	102	Administrative Office	Assistant Principal's Office 102	W3	Flaking paint around windows and behind radiator	Part of above	Part of above		
171	1	102	Administrative Office	Assistant Principal's Office 102	W4	Flaking and chipping paint at wall.	Part of above	Part of above		
172	1	112	Auditorium	Auditorium	W1	Flaking paint and damaged plaster	Part of below	Part of below		
173	1	112	Auditorium	Auditorium	W2	Flaking paint and damaged plaster	1	2	9/17/18 Fail, Retest 9/18/18 <20ug/ft2	
174	1	112	Auditorium	Auditorium	W3	Flaking paint and damaged plaster	Part of above	Part of above		
175	1	112	Auditorium	Auditorium	W4	Damaged plaster	Part of above	Part of above		
176	1	112A	Auditorium	Auditorium Stage	Ceiling	Flaking paint at ceiling	1	0		
177	1	112A	Auditorium	Auditorium Stage	W3	Flaking paint near ceiling	Part of above	Part of above		
178	1	112A	Auditorium	Auditorium Stage	W4	Flaking paint	Part of above	Part of above		
179	1	104A	Administrative Office	BET Office	Ceiling	Flaking paint at ceiling	1	0		
180	1	104A	Administrative Office	BET Office	W1	Flaking paint on and near door.	Part of above	Part of above		
181	1	104A	Administrative Office	BET Office	W2	Flaking paint at wall	Part of above	Part of above		
182	1	104A	Administrative Office	BET Office	W3	Flaking paint at wall	Part of above	Part of above		
183	1	104A	Administrative Office	BET Office	W4	Flaking paint at wall	Part of above	Part of above		
184	1	101A	Storage	Classroom 101 Closet	Ceiling	Flaking paint.	1	0		
185	1	101A	Storage	Classroom 101 Closet	W1	Flaking paint.	Part of Above	Part of above		
186	1	101A	Storage	Classroom 101 Closet	W2	Flaking paint.	Part of Above	Part of above		

187	1	101A	Storage	Classroom 101 Closet	W3	Flaking paint.	Part of Above	Part of above		
188	1	101A	Storage	Classroom 101 Closet	W4	Flaking paint.	Part of Above	Part of above		
189	1	101	Primary	Classroom 101	Ceiling	Damaged plaster at ceiling.	0	1	<20 ug/ft2	
190	1	101	Primary	Classroom 101	W1	Flaking paint above and below blackboard and on door.	Part of above	Part of above		
191	1	101	Primary	Classroom 101	W3	Flaking paint around windows.	Part of above	Part of above		
192	1	101	Primary	Classroom 101	W4	Flaking paint above and below blackboard.	1	1	<20 ug/ft2	
193	1	103	Primary	Classroom 103	Ceiling	Flaking paint at ceiling	2	2	8/6/18 Fail, Retest 8/9 <20 ug/ft2	
194	1	103	Primary	Classroom 103	W1	Flaking paint near entrance and above white board.	Part of above	Part of above		
195	1	103	Primary	Classroom 103	W2	Flaking paint above and below bulletin board	Part of above	Part of above		
196	1	103	Primary	Classroom 103	W3	Flaking paint around windows	Part of above	Part of above		
197	1	103	Primary	Classroom 103	W4	Flaking paint at wall	Part of above	Part of above		
198	1	103A	Storage	Classroom 103 Closet	Ceiling	Flaking paint	Part of below	Part of below		
199	1	103A	Storage	Classroom 103 Closet	W1	Flaking paint	1	0		
200	1	103A	Storage	Classroom 103 Closet	W2	Flaking paint	Part of above	Part of above		
201	1	103A	Storage	Classroom 103 Closet	W3	Flaking paint	Part of above	Part of above		
202	1	103A	Storage	Classroom 103 Closet	W4	Flaking paint	Part of above	Part of above		
203	1	104	Primary	Classroom 104	Ceiling	Flaking paint near windows	3	2	8/16/18 - 43 ug/ft2 Fail, Retest 8/23/18 <20 ug/ft2	1 colorimetric on floor, 1 colorimetric on Windowsill, & 1 colorimetric outside work area on desktop
204	1	104	Primary	Classroom 104	W1	Flaking paint above and below blackboard, on door, and baseboards	Part of Above	Part of Above		
205	1	104	Primary	Classroom 104	W2	Flaking paint at wall and door.	Part of Above	Part of Above		
206	1	104	Primary	Classroom 104	W3	Flaking paint around windows.	Part of Above	Part of Above		
207	1	104B	Storage	Classroom 104 Closet	Ceiling	Flaking paint at ceiling	1	0		

208	1	104B	Storage	Classroom 104 Closet	W1	Flaking paint at wall	Part of Above	Part of Above		
209	1	104B	Storage	Classroom 104 Closet	W3	Flaking paint at wall.	Part of Above	Part of Above		
210	1	104B	Storage	Classroom 104 Closet	W4	Flaking paint on pipe.	Part of Above	Part of Above		
211	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	Ceiling	Flaking paint	1	0		
212	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W1	Flaking paint	Part of Above	Part of Above		
213	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W2	Flaking paint	Part of Above	Part of Above		
214	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W3	Flaking paint	Part of Above	Part of Above		
215	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W4	Flaking paint	Part of Above	Part of Above		
216	1	106	Primary	Classroom 106	W1	Flaking paint on door, above door, and above blackboard	1	No		
217	1	106	Primary	Classroom 106	W3	Flaking paint around windows and on trim	0	Part of Above		
218	1	106	Primary	Classroom 106	W4	Flaking paint above bulletin board	1	Part of Above		
219	1	106A	Storage	Classroom 106 Closet	Ceiling	Flaking paint at ceiling	1	0		
220	1	106A	Storage	Classroom 106 Closet	W2	Flaking paint at wall	Part of Above	Part of Above		
221	1	107	Primary	Classroom 107	Ceiling	Damages plaster	1	1	< 20 ug/ft2	
222	1	107	Primary	Classroom 107	W1	Flaking paint on doors	Part of above	Part of Above		
223	1	107	Primary	Classroom 107	W3	Flaking paint on baseboards and behind radiator	Part of above	Part of Above		

224	1	108	Primary	Classroom 108	W1	Flaking paint on wall and door	3	1	< 20 ug/ft2	1 colorimetric on floor, 1 colorimetric on Windowsill, & 1 colorimetric outside work area on desktop
225	1	108	Primary	Classroom 108	W2	Flaking paint on baseboard	Part of Above	Part of Above		
226	1	108	Primary	Classroom 108	W3	Flaking paint below windows and behind radiator	Part of Above	Part of Above		
227	1	108B	Storage	Classroom 108 Closet	Ceiling	Cracking paint at ceiling	1	0		
228	1	108B	Storage	Classroom 108 Closet	W3	Flaking paint	Part of Above	Part of Above		
229	1	108B	Storage	Classroom 108 Closet	W4	Flaking paint on pipe	Part of Above	Part of Above		
230	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	Ceiling	Flaking paint at ceiling	0	No		Floor was painted
231	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W1	Flaking paint at wall and door	Part of Above	Part of Above		
232	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W2	Flaking paint at wall	Part of Above	Part of Above		
233	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W3	Flaking paint at wall	Part of Above	Part of Above		
234	1	111	Storage	Closet at rear of Auditorium	Ceiling	No access	N/A	N/A		
235	1	111	Storage	Closet at rear of Auditorium	Floor	No access	N/A	N/A		
236	1	111	Storage	Closet at rear of Auditorium	W1	No access	N/A	N/A		
237	1	111	Storage	Closet at rear of Auditorium	W2	No access	N/A	N/A		
238	1	111	Storage	Closet at rear of Auditorium	W3	No access	N/A	N/A		
239	1	111	Storage	Closet at rear of Auditorium	W4	No access	N/A	N/A		
240	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	Ceiling	Flaking paint	1	0		

241	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W1	Flaking paint	Part of above	Part of above		
242	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W2	Flaking paint	Part of above	Part of above		
243	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W3	Flaking paint	Part of above	Part of above		
244	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W4	Flaking paint	Part of above	Part of above		
245	1	S16	Stairs, Fire Tower	Fire Tower near Classroom 107	Ceiling	Damaged plaster at ceiling	0	0		
246	1	114	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Flaking paint at ceiling	1	0		
247	1	114	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Flaking paint at wall.	Part of above	Part of above		
248	1	H16	Circulation (Hallway)	Hallway from Classroom 104 to Teacher's Lounge	W2	Flaking paint behind radiators	1	2	11/13/15 Fail, Retest 11/15 < 20 ug/ft2	
249	1	H18	Circulation (Hallway)	Hallway outside Classrooms 101 to 103	Ceiling	Cracking paint at ceiling.	1	1	<20 ug/ft2	
250	1	H18	Circulation (Hallway)	Hallway outside Classrooms 101 to 103	W3	Flaking paint at pipe near S15 and behind radiators	Part of above	Part of above		
251	1	H15	Circulation (Hallway)	Hallway outside Classrooms 106 to 108	W1	Flaking paint behind radiators	Part of above	Part of above		
252	1	H17	Circulation (Hallway)	Hallway to BET Office	Ceiling	Flaking paint at ceiling	1	1	< 20 ug/ft2	
253	1	H17	Circulation (Hallway)	Hallway to BET Office	W1	Flaking paint at wall	Part of above	Part of above		
254	1	H17	Circulation (Hallway)	Hallway to BET Office	W3	Flaking paint at wall	Part of above	Part of above		
255	1	115	Administrative Office	Main Office	Ceiling	Flaking paint near windows.	1	1	<20 ug/ft2	
256	1	115	Administrative Office	Main Office	W3	Flaking paint near desk and behind radiator.	Part of above	Part of above		
257	1	108A	Restrooms, Staff - Male	Men's Restroom 109	W3	Flaking paint behind radiator	1	0		
258	1	108A	Restrooms, Staff - Male	Men's Restroom 109	W4	Flaking paint	Part of above	Part of above		

259	1	115B	Administrative Office	Principal's Office	W3	Flaking paint at window sill.	1	0		
260	1	115C	Restrooms, Staff - Male/Female	Principal's Office Restroom	W1	Cracking paint	1	0		
261	1	115C	Restrooms, Staff - Male/Female	Principal's Office Restroom	W2	Cracking paint	Part of above	Part of above		
262	1	S13	Stairs	Stairwell adjacent Classroom 103	W1	Spalling paint from ongoing steam leak.	1	0		
263	1	S13	Stairs	Stairwell adjacent Classroom 103	W2	Flaking paint	Part of above	Part of above		
264	1	S14	Stairs	Stairwell adjacent to Classroom 106	W1	Flaking paint at wall toward basement	1	0		
265	1	S17	Stairs	Stairwell near Classroom 108	Ceiling	Flaking paint near Exit.	1	0		
266	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W1	Flaking paint	1	1	< 20 ug/ft2	
267	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W2	Flaking paint	Part of above	Part of above		
268	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W3	Flaking paint	Part of above	Part of above		
269	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W4	Flaking paint	Part of above	Part of above		
270	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	Ceiling	Flaking paint	N/A	N/A		Painters are turning this room over to Environmental Services
271	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W1	Flaking paint	N/A	N/A		
272	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W2	Flaking paint	N/A	N/A		
273	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W3	Flaking paint	N/A	N/A		
274	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W4	Flaking paint	N/A	N/A		

275	1	119	Restrooms, Staff - Female	Women's Restroom 100	Ceiling	Flaking paint and plaster damage	1	0		
276	0	0B3	Primary	Art Room	Ceiling	Flaking paint at ceiling, pipes, and ducts.	1	2	9/13/2018 Fail, Retest 9/17/18 <20 ug/ft2	
277	0	0B3	Primary	Art Room	W2	Flaking paint around windows & trim.	Part of above	Part of above		
278	0	001	Student Restrooms - Male (4-12)	Basement Boy's Restroom	Ceiling	Flaking paint at ceiling and pipe	1	1	<20ug/ft2	
279	0	001	Student Restrooms - Male (4-12)	Basement Boy's Restroom	W1	Flaking paint on pipe.	Part of above	Part of above		
280	0	012	Student Restrooms - Female (4-12)	Basement Girl's Restroom	Ceiling	Flaking paint	1	0		
281	0	012	Student Restrooms - Female (4-12)	Basement Girl's Restroom	W4	Flaking paint at pipe	Part of above	Part of above		
282	0	001A	Storage	Classroom 0B1 Large Closet	Ceiling	Flaking paint	1	0		
283	0	001A	Storage	Classroom 0B1 Large Closet	W1	Flaking paint	Part of above	Part of above		
284	0	001A	Storage	Classroom 0B1 Large Closet	W2	Flaking paint	Part of above	Part of above		
285	0	001A	Storage	Classroom 0B1 Large Closet	W3	Flaking paint	Part of above	Part of above		
286	0	001A	Storage	Classroom 0B1 Large Closet	W4	Flaking paint	Part of above	Part of above		
287	0	0B2B	Storage	Classroom 0B2 Large Closet	W1	Flaking paint	1	0		
288	0	0B2A	Storage	Classroom 0B2 Small Closet	W1	Flaking paint at wall and door.	1	0		
289	0	0B1	Primary	Classroom B1	W1	Flaking paint at closet doors	0	0		
290	0	0B1	Primary	Classroom B1	W2	Damaged plaster	1	Part of above		
291	0	0B1	Primary	Classroom B1	W3	Flaking paint near windows	0	Part of above		
292	0	0B1	Primary	Classroom B1	W4	Damaged plaster	0	Part of above		
293	0	001B	Storage	Classroom B1 Small Closet	Ceiling	Cracking paint	1	0		
294	0	001B	Storage	Classroom B1 Small Closet	W1	Damaged plaster	Part of above	Part of above		
295	0	0B2	Primary	Classroom B2	Ceiling	Flaking paint	1	1	< 20 ug/ft2	

296	0	0B2	Primary	Classroom B2	W1	Flaking paint	Part of above	Part of above		
297	0	0B2	Primary	Classroom B2	W2	Flaking paint	Part of above	Part of above		
298	0	0B2	Primary	Classroom B2	W3	Flaking paint at windows and columns	Part of above	Part of above		
299	0	0B2	Primary	Classroom B2	W4	Flaking paint	Part of above	Part of above		
300	0	0B4	Gymnasium - Intermediate Middle	Gym	Ceiling	Flaking paint at ceiling and ducts	5	3	Fail 10/24/18, Retest 11/5/18 <20 ug/ft2	
301	0	0B4	Gymnasium - Intermediate Middle	Gym	W3	Flaking paint at window trim and pipes	Part of above	Part of above		
302	0	008B	Administrative Office	Gym Office	Ceiling	Flaking paint at ceiling near windows	1	0		
303	0	008B	Administrative Office	Gym Office	W2	Flaking paint at window trim	Part of above	Part of above		
304	0	008A	Storage	Gym Storage Room	W1	Flaking paint at door	Part of above	Part of above		
305	0	H01	Circulation (Hallway)	Hallway outside Classrooms B1-B2	Ceiling	Flaking paint on ceiling above ductwork and near Start S17	1 (Additional Sample Collected on 12/13/2018)	0		Additonal Cleaning Above Duct Work Completed on 12/13/2018 (JM)
306	0	H02	Circulation (Hallway)	Hallway outside Gym	Ceiling	Flaking paint on deck above ductwork	1	0		There was flaking and debris above the vent work in the basement. The hallway was turned over to Environmental Services and will have to be tested at a later date. (12/13/2018)
307	0	H02	Circulation (Hallway)	Hallway outside Gym	W1	Flaking paint at pipe.				
308	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	Ceiling	Flaking paint at ceiling by exit to outdoors	2	0		
309	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	W2	Flaking paint at wall across from Girls Restroom				
310	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	W3	Flaking paint at wall across from Girls Restroom and at window trim.				
311	0	H03	Circulation (Hallway)	Hallway outside Logan Cafe 1	W4	Flaking paint at pipe by exit to outdoors				

312	0	011A	Kitchen	Kitchen	W3	Flaking paint near window behind freezer	1	2	Fail 11/13/18, Retest 11/15 <20 ug/ft2	
313	0	011B	Administrative Office	Kitchen Office	Ceiling	Flaking paint	1	0		
314	0	011B	Administrative Office	Kitchen Office	W2	Flaking paint	Part of above	Part of above		
315	0	011B	Administrative Office	Kitchen Office	W3	Flaking paint	Part of above	Part of above		
316	0	011B	Administrative Office	Kitchen Office	W4	Flaking paint	Part of above	Part of above		
317	0	0B5	Cafeteria (Dining Area)	Logan Cafe 2	Ceiling	Spalling paint at concrete ceiling beam	1	1	<20 ug/ft2	
318	0	0B5	Cafeteria (Dining Area)	Logan Cafe 2	W2	Spalling paint near wall 3	Part of above	Part of above		
319	0	0B5	Cafeteria (Dining Area)	Logan Cafe 2	W3	Flaking paint	Part of above	Part of above		
320	0	010	Storage	Logan Cafe 2 Small Closet	Ceiling	Damaged plaster	N/A	N/A		Closet will be cleaned by Environmental Services
321	0	010	Storage	Logan Cafe 2 Small Closet	W1	Flaking paint behind pipe	N/A	N/A		
322	0	010	Storage	Logan Cafe 2 Small Closet	W2	Flaking paint where pipes enter wall	N/A	N/A		
323	0	S01	Stairs	Stairwell adjacent to Boiler Room Restroom	Ceiling	Flaking paint	1	0		
324	0	S01	Stairs	Stairwell adjacent to Boiler Room Restroom	Floor	Flaking paint debris	Part of above	Part of above		
325	0	S01	Stairs	Stairwell adjacent to Boiler Room Restroom	W1	Flaking paint	Part of above	Part of above		
326	0	S01	Stairs	Stairwell adjacent to Boiler Room Restroom	W2	Flaking paint	Part of above	Part of above		
327	0	S01	Stairs	Stairwell adjacent to Boiler Room Restroom	W3	Flaking paint	Part of above	Part of above		

Appendix E. Photographs



Prior to stabilization.



Prior to stabilization.



Prior to stabilization.



Following stabilization



Following stabilization



Following stabilization

***Appendix F. Environmental Firm Certification Documentation of
Training***

Documentation of Criterion Employees Assigned to Site with EPA RRP & Dust Sampling Technician Training

First Name	Last Name	Course Description	Course End Date	Expiration Date
Julie	Mui	EPA-Lead Renovator Initial	4/8/2016	4/8/2021
Julie	Mui	Dust Sampling Technician Initial	1/8/2018	1/8/2023
Isa	Haj	EPA-Lead Renovator Initial	11/20/2015	11/20/2020
Isa	Haj	Dust Sampling Technician Initial	1/8/2018	1/8/2023
Mary Anne	Lerro	EPA-Lead Renovator Initial	9/10/2015	9/10/2020
Mary Anne	Lerro	Dust Sampling Technician Initial	1/8/2018	1/8/2023
Alyssa	Cartagena	EPA-Lead Renovator Initial	6/11/2018	6/11/2023
Alyssa	Cartagena	Dust Sampling Technician Initial	11/2/2016	11/2/2021
Gina	Fernandes	EPA-Lead Renovator Initial	12/3/2018	12/3/2023
Gina	Fernandes	Dust Sampling Technician Initial	11/20/2018	11/20/2023
Cristopher	Karoly	EPA-Lead Renovator Initial	12/17/2018	12/17/2023
Cristopher	Karoly	Dust Sampling Technician Initial	11/20/2018	11/20/2023
Jackie	Neiman	EPA-Lead Renovator Initial	6/11/2018	6/11/2023
Jackie	Neiman	Dust Sampling Technician Initial	6/14/2018	6/14/2023

***Appendix G. Painting Contractor Certifications or Documentation of
Training***

Comprehensive List of Philadelphia School District Employees with EPA RRP Training

First Name	Last Name	Course Description	Course End Date	Expiration Date
Kyle	Adami	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Marcel	Allen	EPA-Lead Renovator Refresher	28-Apr-15	28-Apr-20
James	Archie	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Demetrius	Atwell	EPA-Lead Renovator Initial	17-Nov-17	17-Nov-22
Samuel	Atwell	EPA-Lead Renovator Initial	17-Nov-17	17-Nov-22
Shawn	Baldwin	EPA-Lead Renovator Initial	01-Apr-15	01-Apr-20
Michael	Baranek	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Chris	Bartella	EPA-Lead Renovator Refresher	21-May-15	21-May-20
Chris	Bendig	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Michael	Bennett	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Gino	Berardinucci	EPA-Lead Renovator Refresher	21-May-15	21-May-20
Jessica	Binda-Rischow	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
Terrence	Blocker	EPA-Lead Renovator Initial	01-Apr-15	01-Apr-20
Damian	Boninfante	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
James	Borie	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Joe	Bowes	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Rhett	Boykins	EPA-Lead Renovator Initial	03-Nov-17	03-Nov-22
Robert	Broadnax	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
Philip	Burton	EPA-Lead Renovator Refresher	02-Apr-15	02-Apr-20
Randy	Bushnell	EPA-Lead Renovator Refresher	02-Apr-15	02-Apr-20
Okang	Cambridge	EPA-Lead Renovator Initial	17-Nov-17	17-Nov-22
Michael	Cancelliere	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Anthony	Carruth	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Thomas	Casey	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Gabrielle	Cecala	EPA-Lead Renovator Initial	17-Nov-17	17-Nov-22
Anthony	Cecala	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Brian	Chambers	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Suzette	Christian	EPA-Lead Renovator Initial	17-Nov-17	17-Nov-22
Rich	Ciuckis	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Michael	Clark	EPA-Lead Renovator Initial	01-Apr-15	01-Apr-20
Harold	Clark, Jr.	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Joseph	Clemson	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Brian	Cook	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Jeff	Cook	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Kevin	Courtney	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
Jahmai	Crawley	EPA-Lead Renovator Initial	03-Nov-17	03-Nov-22
Timothy	Creighton	EPA-Lead Renovator Initial	17-Nov-17	17-Nov-22
Steven	Creighton	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Joe	Curran	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Kevin	Curry	EPA-Lead Renovator Refresher	28-Apr-15	28-Apr-20
Demetrius	Dancey	EPA-Lead Renovator Initial	01-Apr-15	01-Apr-20

Fran	Davis	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
James	Davis (diff emp.)	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Edmund	Davis, Jr.	EPA-Lead Renovator Initial	20-Mar-18	20-Mar-23
Anthony	Devlin	EPA-Lead Renovator Refresher	02-Apr-15	02-Apr-20
Ken	Dickson	EPA-Lead Renovator Initial	11-Aug-14	11-Aug-19
Mark	DiGiambattista	EPA-Lead Renovator Initial	01-Apr-15	01-Apr-20
Steve	Dolan	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Stephen	DuBan	EPA-Lead Renovator Refresher	20-Mar-15	20-Mar-20
James	Dugan	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Mark	Dugan	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Donald	Eife	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
George	Faccenda	EPA-Lead Renovator Refresher	20-Mar-15	20-Mar-20
Anthony	Fiore	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Bill	Flanigan	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Michael	Flannery Sr.	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Joseph	Flannery, Jr.	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
David	Foster	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Anthony	Gajdowski	EPA-Lead Renovator Initial	30-Jul-14	30-Jul-19
Joseph	Gallagher	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Stephen	Gallagher	EPA-Lead Renovator Initial	11-Aug-14	11-Aug-19
Harold	Ganskopp, Jr.	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Ralph	Garcia	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
James	Garofolo	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
John	Genovese	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Joe	George	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
Thomas	Gibson	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
John	Gidzinski	EPA-Lead Renovator Initial	01-Apr-15	01-Apr-20
James	Gillice	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Melvin	Goins	EPA-Lead Renovator Initial	17-Nov-17	17-Nov-22
Damon	Gonzaga	EPA-Lead Renovator Initial	11-Aug-14	11-Aug-19
Raynaldo	Gonzalez	EPA-Lead Renovator Initial	17-Nov-17	17-Nov-22
John	Gordon	EPA-Lead Renovator Initial	01-Apr-15	01-Apr-20
Frank	Gosciminski	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Kwamie	Grove	EPA-Lead Renovator Initial	11-Aug-14	11-Aug-19
Ron	Hackimer	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Richard	Hagenbuch	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
James	Hall	EPA-Lead Renovator Initial	11-Jul-18	11-Jul-23
David	Hampton Jr.	EPA-Lead Renovator Refresher	21-May-15	21-May-20
Gerard	Harkins	EPA-Lead Renovator Refresher	02-Apr-15	02-Apr-20
Erica	Hickey	EPA-Lead Renovator Initial	20-Mar-18	3/20/2023
Wayne	Hogeland	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Timothy	Holman	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Durelle	Holmes	EPA-Lead Renovator Initial	20-Mar-18	20-Mar-23
Richard	Houck	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20

Alfred	Howard	EPA-Lead Renovator Initial	20-Mar-18	20-Mar-23
Wayne	Howard	EPA-Lead Renovator Initial	01-Apr-15	01-Apr-20
Timothy	Humes	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Lance	Jackson	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Eric	Johnson	EPA-Lead Renovator Refresher	28-Apr-15	28-Apr-20
James	Johnson	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Jimmie	Johnson	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Walter	Johnson	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Donald	Johnson Jr.	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Jesse	Jones	EPA-Lead Renovator Initial	11-Aug-14	11-Aug-19
Gerald	Joniec	EPA-Lead Renovator Refresher	21-May-15	21-May-20
Brian	Joseph	EPA-Lead Renovator Refresher	28-Apr-15	28-Apr-20
Anthony	Jubilee	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Gerald	Junod	EPA-Lead Renovator Refresher	28-Apr-15	28-Apr-20
Joe	Kehoe	EPA-Lead Renovator Initial	01-Apr-15	01-Apr-20
John	Kenney	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Mary	Koehler	EPA-Lead Renovator Refresher	02-Apr-15	02-Apr-20
Richard	Kovacs	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
John	Krol	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Michael	Leone	EPA-Lead Renovator Refresher	02-Apr-15	02-Apr-20
George	Leone	EPA-Lead Renovator Initial	11-Aug-14	11-Aug-19
Richard	Lepore	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
Walter	Lipski	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
David	Loftus	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Eloy	Lopez Jr.	EPA-Lead Renovator Refresher	20-Mar-15	20-Mar-20
Augustus	Lover, III	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
Michael	Lowe	EPA-Lead Renovator Refresher	21-May-15	21-May-20
Harry	Lowe, Jr.	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
Kenneth	Mack	EPA-Lead Renovator Initial	01-Apr-15	01-Apr-20
Thomas	Malkowski	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Thomas	Malkowski, Jr.	EPA-Lead Renovator Initial	03-Nov-17	03-Nov-22
Kevin	Malone	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Dante	Mancini	EPA-Lead Renovator Refresher	28-Apr-15	28-Apr-20
Stephen	Manna	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
Charles	Markey	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Derrick	Matthews	EPA-Lead Renovator Initial	01-Apr-15	01-Apr-20
Benedict	Matthews	EPA-Lead Renovator Refresher	20-Mar-15	20-Mar-20
Kevin	McAfee	EPA-Lead Renovator Initial	30-Jul-14	30-Jul-19
Gerard	McAnena	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Jim	McBride	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
John	McFarlane	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Mikkel	McKinnie	EPA-Lead Renovator Initial	01-Apr-15	01-Apr-20
Patrick	McMahon	EPA-Lead Renovator Refresher	02-Apr-15	02-Apr-20
Pat	McMahon	EPA-Lead Renovator Initial	11-Aug-14	11-Aug-19

Matthew	Melady	EPA-Lead Renovator Refresher	28-Apr-15	28-Apr-20
Joe	Mellina Jr.	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Harry	Milbourne	EPA-Lead Renovator Initial	30-Jul-14	30-Jul-19
Christopher	Moore	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Mike	Moore	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Mike	Moore	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Earl	Morris	EPA-Lead Renovator Refresher	20-Mar-15	20-Mar-20
William	Muller	EPA-Lead Renovator Refresher	20-Mar-15	20-Mar-20
Jorge	Naveiro	EPA-Lead Renovator Initial	17-Nov-17	17-Nov-22
Richard	Nedorost	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Ernest	Neven	EPA-Lead Renovator Initial	20-Mar-18	20-Mar-23
Scott	Ovington	EPA-Lead Renovator Refresher	28-Apr-15	28-Apr-20
Benjamin	Pak	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
Vernon	Palmer	EPA-Lead Renovator Initial	01-Apr-15	01-Apr-20
Derek	Parker	EPA-Lead Renovator Refresher	20-Mar-15	20-Mar-20
Percy	Payno	EPA-Lead Renovator Initial	01-Apr-15	01-Apr-20
Jose	Perez	EPA-Lead Renovator Refresher	20-Mar-15	20-Mar-20
Edward	Perks	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Salvatore	Perrone	EPA-Lead Renovator Refresher	20-Mar-15	20-Mar-20
John	Pilotti	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Alfred	Pizzo	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
James	Pizzo	EPA-Lead Renovator Initial	20-Mar-18	20-Mar-23
Ernest	Purvis	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Kevin	Quigley	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Luke	Quinn	EPA-Lead Renovator Refresher	20-Mar-15	20-Mar-20
Fred	Raskay	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
Frank	Ratka, II	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
Pat	Raynor	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Jim	Reick	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Michael	Reilly	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Eric	Ricchezza	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Shawn	Robinson	EPA-Lead Renovator Initial	01-Apr-15	01-Apr-20
Joseph	Ryan	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Salvatore	Sansone	EPA-Lead Renovator Refresher	20-Mar-15	20-Mar-20
William	Savage	EPA-Lead Renovator Initial	20-Mar-18	20-Mar-23
Bruce	Savage	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Ricky	Scarbrough, Sr.	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Jeff	Schillig	EPA-Lead Renovator Refresher	20-Mar-15	20-Mar-20
Steven	Schmidt	EPA-Lead Renovator Refresher	02-Apr-15	02-Apr-20
Harry	Schmitt	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Jeff	Scott	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Tom	Sharer	EPA-Lead Renovator Refresher	20-Mar-15	20-Mar-20
David	Sienko	EPA-Lead Renovator Initial	17-Nov-17	17-Nov-22
Frank	Sienko	EPA-Lead Renovator Refresher	02-Apr-15	02-Apr-20

Gregory	Smith	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
William	Soda	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
Raymond	Solley	EPA-Lead Renovator Refresher	20-Mar-15	20-Mar-20
Lukose	Solomon	EPA-Lead Renovator Refresher	21-May-15	21-May-20
Joseph	Stewart	EPA-Lead Renovator Refresher	21-May-15	21-May-20
Frank	Stramitis	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Mario	Tamborello	EPA-Lead Renovator Initial	11-Aug-14	11-Aug-19
Christopher	Taylor	EPA-Lead Renovator Initial	30-Jul-14	30-Jul-19
Harry	Thomson	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Ray	Tierney	EPA-Lead Renovator Refresher	02-Apr-15	02-Apr-20
Vincent	Tonelli	EPA-Lead Renovator Initial	17-Nov-17	17-Nov-22
Vincent	Trasatti	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
Richard	Tremonte	EPA-Lead Renovator Refresher	20-Mar-15	20-Mar-20
Nicholas	Umile	EPA-Lead Renovator Initial	17-Nov-17	17-Nov-22
Gerald	Watson	EPA-Lead Renovator Refresher	19-Mar-15	19-Mar-20
Tim	Weicker	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
Stephen	Weiss	EPA-Lead Renovator Initial	17-Nov-17	17-Nov-22
George	Weissman	EPA-Lead Renovator Initial	17-Nov-17	17-Nov-22
Lee	White, II	EPA-Lead Renovator Initial	20-Apr-18	20-Apr-23
William	Wilson	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Timothy	Witczak	EPA-Lead Renovator Refresher	09-Mar-15	09-Mar-20
Denice	Witkowski	EPA-Lead Renovator Initial	17-Nov-17	17-Nov-22
Robert	Yerkov	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Tim	Yust	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20
Eric	Zeoli	EPA-Lead Renovator Refresher	10-Mar-15	10-Mar-20

Appendix H. Documentation of Parent and Staff Notification



LOGAN SCHOOL
1700 Lindley Ave.
Philadelphia, PA 19141

Chuanika Sanders
Principal

Phone: 215 - 400 - 3670

Notice of Paint and Plaster Stabilization Work and Meeting

Dear School Families;

The School District of Philadelphia works daily to ensure that our students and staff have a safe, healthy environment in which to learn and work. I am writing to share information with you about plans for renovation to remove loose and peeling paint in our school building. **We understand that you likely will have additional questions, and we will work to address those promptly. The School District will host a meeting for families to share an overview of the renovations and to answer questions on August 6, 2018 in the school auditorium.**

The School District has begun paint and plaster stabilization work in school buildings constructed prior to 1978 that are likely to contain lead-based paint. Paint stabilization involves removing loose, peeling, flaking and crumbling paint and plaster under controlled conditions. The goal of the work is to enhance classroom environments and remove the risk of lead exposure to children in our school community. Our school has been selected for this work because paint damage was documented in occupied spaces such as classrooms and classroom closets, administrative offices, cafeteria, auditorium, bathrooms, kitchen, hallways, and emergency exit stairways.

With student safety our main priority, work is being completed by individuals who are trained and certified in United States Environmental Protection Agency (EPA) lead-based paint renovation, repair and painting work practices. These work practices ensure that classrooms and other areas are free of paint chips, dust and debris after the project is completed.

Upon completion, loose, flaking, peeling and crumbling paint and plaster will be removed from ceilings and walls. The areas will also be patched, repainted and cleaned. A quality control assessment will also take place after the work is completed in each area to ensure that the spaces are ready for students and staff to safely occupy.

A full report of scope and frequently asked questions will be made available in the school's main office and provided to the School Advisory Council and Home and School Association in the near future. For more information about lead, please contact the Lead Prevention Unit of the Philadelphia Department of Health at (215) 685-2788 or visit <http://www.phila.gov/health/childhoodlead>.

Thank you for your attention to this matter.

Sincerely,
Principal Sanders



Logan School Community

SCHOOL MEETING NOTIFICATION

SUBJECT: **Paint and Plaster Stabilization Project at the Logan**

DATE: **August 6, 2018**

TIME: **3:00 to 4:30 PM**

LOCATION: **Logan - Room 107**

The School District will host a meeting for families to share an overview of the renovations and to answer questions on August 6 at 3:00 PM in Room 107.

We understand that you likely will have questions, and we will work to address those promptly.

Thank you.

Sincerely,

Principal Sanders